HALEY ALDRICH

www.haleyaldrich.com

REPORT ON

ASTM PHASE I ENVIRONMENTAL SITE ASSESSMENT
296 4TH AVENUE DEVELOPMENT
296 4TH AVENUE
BROOKLYN, NEW YORK

by
Haley & Aldrich of New York
New York, New York

[redacted]

File No. 0206616
October 2022

HALEY & ALDRICH OF NEW YORK
237 W 35th Street
16th Floor
New York, NY 10001
646.277.5685

4 October 2022
File No. 0206616

[redacted]

Subject: ASTM Phase I Environmental Site Assessment
296 4th Avenue
Brooklyn, New York

Ladies and Gentlemen:

The enclosed report presents the results of a Phase I Environmental Site Assessment (Phase I) conducted at the above-referenced property, located at 296 4th Avenue, in Brooklyn, New York (herein referred to as the "subject property"). This work was performed by Haley & Aldrich of New York (Haley & Aldrich), in accordance with our proposal to [redacted]. This Phase I was conducted in conformance with the scope and limitations of the ASTM International (ASTM) E1527-13 and E1527-21 Standard Practice for Environmental Site Assessments.[1]

The objective of a Phase I is to assess whether known and suspect "recognized environmental conditions" (RECs), controlled RECs (CRECs), or historical RECs (HRECs) are associated with the subject property, as defined in the ASTM E1527-13 and E1527-21 Standards.

[1] The ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E1527 13 Standard) as referenced in 40 CFR Part 312 (the All Appropriate Inquiries [AAI] Rule). Additionally, Haley & Aldrich's Phase I Environmental Site Assessments incorporated the procedures set forth in ASTM E1527-21, which have not yet been approved by the U.S. Environmental Protection Agency (EPA) to meet the requirements of 40 CFR 312, AAI.

Thank you for the opportunity to perform these services for you. Please do not hesitate to contact us if you have any questions or comments.

Sincerely yours,
HALEY & ALDRICH OF NEW YORK

Zachary Simmel
Senior Engineer

Mari Cate Conlon, P.G.
Senior Project Manager

James M. Bellew
Principal

Enclosures

Executive Summary

Haley & Aldrich of New York (Haley & Aldrich) has performed a Phase I Environmental Site Assessment (Phase I) of the 296 4th Avenue property in Brooklyn, New York, (herein referred to as the "subject property"). [redacted]
This Phase I was performed for [redacted] This Phase I was performed in conformance with the scope and limitations of the ASTM International (ASTM) E1527-13 and E1527-21 Standards and All Appropriate Inquiries (AAI) Rule.

SUBJECT PROPERTY DESCRIPTION

The subject property is located within an urban area characterized by multi-story commercial and residential buildings, and low-rising industrial buildings. The subject property, identified as Block 456, Lots 1, 6, 32, and 34 on the New York City tax map is located in the Special Gowanus Mixed-Use zoning district, is 28,818 square feet (sq ft), and is currently improved with a one-story commercial building used as a car wash and associated store (Lot 1), a two-story vacant building (Lot 32), and an on-grade parking lot (Lot 6). Lot 34 is an undeveloped cement-capped lot. The subject property is bound to the north by commercial and residential buildings; to the east by 4th Avenue followed by a multi-story mixed-use building and commercial buildings; to the south by 1st Street followed by a large commercial building and parking lot operated by Con Edison; and to the west by Denton Street followed by a school and church.

It is assumed that the subject property redevelopment will remain consistent with the current zoning.

OBJECTIVE

The objective of a Phase I is to assess whether "recognized environmental conditions" (RECs), controlled RECs (CRECs), or historical RECs (HRECs) are associated with the subject property. Our conclusions are intended to help the user evaluate the "business environmental risk" associated with the subject property. Our opinion regarding a REC's potential impact on the subject property is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, our experience evaluating similar sites, and on our understanding of the client's intention to purchase and redevelop the site for residential use.

SIGNIFICANT DATA GAPS

Our ability to identify and evaluate RECs at the subject property is conditioned upon significant data gaps identified as part of this Phase I. The ASTM E1527-21 Standard defines a significant data gap as a data gap that affects the ability of the environmental professional to identify a REC.

We identified the following data gaps in association with this Phase I. The sources of information that were consulted to address the data gap and their significance relative to our ability to identify RECs are described below.

- Lack of access to Lot 32 – While access was not granted to the interior of the vacant building on Lot 32, Haley & Aldrich personnel viewed the structure from the exterior and viewed the remainder of the subject property's interior. Further, with the availability of the historic

resources for the subject property, including Lot 32, this data gap is not considered significant relative to our ability to identify RECs at the subject property.

RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a REC as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

The following RECs listed below were identified in connection with the subject property.

REC #1: Former use of the Subject Property and Upgradient Properties for Industrial, Manufacturing, and Auto-Related Purposes

The subject property was historically used for industrial, manufacturing, and auto-related purposes. According to historical records, Lot 1 was historically operated by the Fulton Smelting & Refining Works, Inc., a service station, auto repair facility, and auto detailing center. Lot 6 was used for residential purposes and a parking lot. Lot 32 was operated by a bottle storage facility and auto repair use, and lot 34 was operated by an auto repair facility. The hydraulically upgradient property addressed 275 4th Avenue (Block 964, Lot 7505) was historically operated by a gasoline service station from the early 1970s to late 1980s and was listed in the Petroleum Bulk Storage (PBS) database for multiple gasoline underground and aboveground storage tanks.

Manufacturing and auto-related facilities commonly utilize hazardous materials including petroleum products and chlorinated solvents. The historical use of the subject property and upgradient properties is considered a REC, as potential or undocumented releases of petroleum products, solvents, and/or other hazardous materials may have adversely affected groundwater, soil, and/or soil vapor at the subject property.

REC #2: Documented Contamination in Soil, Groundwater & Soil Vapor on Lot 34

A Remedial Investigation performed by RSK in December 2021 identified contamination in soil (including heavy metals and semi-volatile organic compounds [SVOCs]), in groundwater (including heavy metals and SVOCs), and soil vapor (specifically petroleum-related compounds and chlorinated volatile organic compounds [VOCs]) beneath Lot 34, located on the eastern boundary of the subject property. The contamination in urban fill was widely distributed throughout the Lot 34 to depths up to 12 feet below ground surface (bgs) and is consistent with characteristics of urban fill found throughout the New York City area. Analytical results indicated elevated concentrations of metals and SVOCs in groundwater samples. Soil vapor analytical results identified petroleum-related VOCs and chlorinated VOCs in several samples. RSK concluded that soil vapor contamination beneath the subject property is likely associated from historic on-site operations, a former underground storage tank (UST), and a former gasoline filling station located hydraulically upgradient of the subject property. According to available records, remedial action has not been implemented on the subject property; therefore, the documented contamination on Lot 34 is considered a REC.

REC #3: Documented Contamination in Soil, Groundwater & Soil Vapor on Lot 6

A Remedial Investigation performed by RSK in July 2022 identified contamination in soil (including metals, semi-volatile organic compounds [SVOCs], and volatile organic compounds [VOCs]), in groundwater (including metals, SVOCs, and VOCs), and soil vapor (specifically petroleum-related compounds and chlorinated VOCs) beneath Lot 6, the northwest portion of the subject property. The contamination in urban fill was widely distributed throughout Lot 6 subject property to depths up to 8 feet bgs and is consistent with characteristics of urban fill found throughout the New York City area. Analytical results indicated elevated concentrations of metals and SVOCs in groundwater samples. Soil vapor analytical results identified petroleum-related VOCs and chlorinated VOCs in several samples. According to available records, remedial action has not been implemented on the subject property; therefore, the documented contamination is considered a REC.

REC #4: Former Gasoline Storage Tanks at the Subject Property

One gasoline storage tank on Lot 32 is indicated on Sanborn Fire Insurance Maps from 1926 to 1950. One gasoline storage tank on Lot 34 is indicated on Sanborn Fire Insurance Maps from 1926 to 2007. Four gasoline storage tanks on Lot 1 are indicated on Sanborn Fire Insurance Maps from 1951 to 1965. There are no records of the installation or removal of these tanks with the New York State Department of Environmental Conservation (NYSDEC). A geophysical survey performed by RSK in December 2021 on Lot 34 detected a metallic anomaly in the northeastern side of the building measuring 6 feet by 4 feet. RSK was not able to identify any other discernable features in this area. Without proper documentation, it is unknown if these tanks were underground, the close-out status of the tanks, or if residual contamination remains in the former tank areas. Due to the dates of installation and duration of usage at the subject property, the former storage tanks are considered a REC.

CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a CREC as a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

CRECs were not identified in connection with the subject property.

HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines an HREC as a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. A historical recognized environmental condition is not a recognized environmental condition.

HRECs were not identified in connection with the subject property.

DE MINIMIS CONDITIONS

The ASTM E1527-21 Standard defines *de minimis* conditions as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not

be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. The ASTM E1527-21 Standard notes that conditions determined to be *de minimis* are not recognized environmental conditions.

The following *de minimis* condition listed below was identified in connection with the subject property.

***De minimis* Condition #1:** Improper Storage of Petroleum Products and Minor Staining

Vehicle maintenance and repair products and chemicals were observed inside of the Lot 1 subject property building. Products used for vehicle repair, such as motor oil, were typically stored on shelves in sealed containers, whereas products intended for maintaining the exteriors of vehicles were typically stored in drums on the ground with no secondary containment. Minor staining was observed on the slab beneath the chemical storage containers and floor drains were observed near the locations where these products and chemicals were stored.

OTHER FINDINGS

ASTM does not define the term "other finding"; however, Haley & Aldrich utilizes the category to indicate conditions of potential risk that are not clearly defined in the ASTM standard. While not considered RECs, Haley & Aldrich identified the following other findings:

Other Finding #1: New York City E-Designation

The subject property was identified as an E-Designation site by the New York City Office of Environmental Remediation (NYCOER). The subject property was assigned E-601 – Gowanus Neighborhood Plan Rezoning Action as a result of a City Environmental Quality Review (CEQR) effective 23 November 2021 (CEQR #19DCP157K). The requirements under the E-Designation program are satisfaction of the requirements for hazardous materials, noise (window wall attenuation and alternative means of ventilation), and air quality (HVAC limited to natural gas and exhaust stack location limitations) with the NYCOER. The air quality component for this E-Designation for new developers is the exclusive use of natural gas for heating with the stack location at the highest tier (at least 158 feet above grade). The noise requirement states future residential/commercial must provide a closed-window condition with a minimum of 31 dBA window/wall attenuation on all façades in order to maintain an interior noise level not greater than 45 dBA for residential and community facility uses or not greater than 50 dBA for commercial office spaces. To maintain a closed-window condition, an alternate means of ventilation must also be provided. Alternate means of ventilation includes, but is not limited to, air conditioning.

SUMMARY

In summary, we identified four RECs were identified in connection with the subject property during this Phase I.

The remainder of this report contains additional information regarding the Phase I, the resulting findings summarized above, and limitations affecting this report.

Continued Viability of Environmental Site Assessment

In accordance with the ASTM E1527-21 Standard, the following components of the Phase I Report must be conducted or updated within 180 days prior to the date of acquisition or prior to the date of the transaction:

1. Interviews with owners, operators, and occupants. Completed on: 28 September 2022
2. Searches for recorded environmental cleanup liens (a user responsibility). Completed on: 20 September 2022
3. Reviews of federal, tribal, state, and local government records. Completed on: 22 September 2022
4. Visual inspections of the subject property and of adjoining properties. Completed on: 28 September 2022
5. The declaration by the environmental professional responsible for the assessment or update (refer to Section 9). Completed on 4 October 2022

\\haleyaldrich.com\share\CF\Projects\0206616\Deliverables\1. Phase I ESA\2022-1004-HANY-296 4th Avenue-Phase I ESA-F.docx

Table of Contents

		Page
Executive Summary		**i**
Continued Viability of Environmental Site Assessment		**v**
List of Figures		**viii**
List of Appendices		**viii**
1.	**Introduction**	**1**
1.1	OBJECTIVE	1
1.2	SCOPE OF SERVICES	1
1.3	NON-SCOPE CONSIDERATIONS	1
1.4	LIMITING CONDITIONS/DEVIATIONS	2
1.5	USER RESPONSIBILITIES	2
2.	**Site Description**	**3**
2.1	SITE OWNERSHIP, LOCATION, AND VICINITY DESCRIPTION	3
2.2	PHYSICAL SETTING	4
3.	**Previous Reports**	**6**
4.	**Subject Property History**	**11**
4.1	SUBJECT PROPERTY	11
4.2	ADJOINING PROPERTIES	12
5.	**Environmental Records Review**	**14**
5.1	ENVIRONMENTAL DATABASE RECORDS SEARCH	14
5.2	ADDITIONAL ENVIRONMENTAL RECORDS OR FILE REVIEW	15
5.3	DETAILED DESCRIPTION OF RELEVANT INFORMATION	16
5.3.1	Subject Property	16
5.3.2	Nearby Sites	16
5.4	VAPOR MIGRATION	21
6.	**Subject Property Reconnaissance and Key Personnel Interview(s)**	**22**
	CURRENT USE OF THE SUBJECT PROPERTY	22
	GENERAL DESCRIPTION OF STRUCTURES	22
	USE, STORAGE, AND DISPOSAL OF PETROLEUM PRODUCTS AND HAZARDOUS MATERIALS	22
	OTHER SUBJECT PROPERTY OBSERVATIONS	26
6.1	ADJOINING PROPERTY OBSERVATIONS	27
6.2	USER RESPONSIBILITIES	27

TABLE OF CONTENTS (cont'd)

Page

7. Findings and Opinions 29

7.1 SIGNIFICANT DATA GAPS 29
7.2 RECOGNIZED ENVIRONMENTAL CONDITIONS 29
7.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS 31
7.4 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS 31
7.5 DE MINIMIS CONDITIONS 31
7.6 OTHER FINDINGS 31

8. Conclusions 33

9. Environmental Professional Certification 34

10. Credentials 35

11. Glossary and Other Descriptions 36

11.1 GLOSSARY 36
11.2 DESCRIPTIONS OF DATABASES SEARCHED 37

12. References 39

List of Figures

Figure No.	Title
1	Project Locus
2	Site Plan

List of Appendices

Appendix	Title
A	Phase I Environmental Site Assessment Limitations
B	Previous Reports
C	Historical Research Documentation
D	Regulatory Records Documentation
E	Site Photographs

1. Introduction

This report presents the results of an ASTM International (ASTM) Phase I Environmental Site Assessment (Phase I) conducted at 296 4th Avenue in Brooklyn, New York, (herein referred to as the "subject property"). The approximately 29,818-square-foot (0.685-acre) subject property is composed of four tax parcels improved with a one-story commercial building, a two-story mixed-use building, and an on-grade parking lot. The subject property is shown on the Project Locus, Figure 1. This Phase I was conducted in consideration of [redacted]

1.1 OBJECTIVE

The objective of a Phase I is to assess whether "recognized environmental conditions" (RECs), controlled RECs (CRECs), or historical RECs (HRECs) are associated with the subject property by evaluating site history, interviews, existing observable conditions, current site use, and current and former uses of adjoining properties as well as potential releases at surrounding properties that may impact the subject property. Our conclusions are intended to help the user evaluate the "business environmental risk" associated with the subject property.

The ASTM E1527-21 Standard defines a REC as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. The definitions of RECs, CRECs, and HRECs are included in the Glossary section of this report.

1.2 SCOPE OF SERVICES

This Phase I was performed by Haley & Aldrich of New York (Haley & Aldrich) in conformance with the scope and limitations of the ASTM E1527-13 Standard and All Appropriate Inquiries (AAI) Rule and in accordance with our proposal dated 13 September 2022 ("Agreement") as authorized on 20 September 2022. The Phase I limitations are attached hereto as Appendix A.

As part of this Phase I, Haley & Aldrich conducted visual observations of site conditions and of abutting property use and interviewed a key site manager and applicable tenant representatives (site reconnaissance); reviewed federal, state, tribal, and local environmental database information, federal and state environmental files, previous reports (if identified and provided), and site historical use records; and formulated conclusions regarding the potential presence and impact of RECs.

1.3 NON-SCOPE CONSIDERATIONS

The ASTM E1527-13 and E1527-21 Standards include the following list of "additional issues" that are non-scope considerations outside of the scope of the ASTM Phase I practice: asbestos-containing materials, biological agents, cultural and historic resources, ecological resources, endangered species, health and safety, indoor air quality related to release of hazardous substances or petroleum products into the environment, industrial hygiene, lead-based paint unrelated to releases into the environment, lead in drinking water, mold or microbial growth conditions, polychlorinated biphenyl (PCB)-containing materials, naturally occurring radon, regulatory compliance, substances not defined as hazardous

substances (emerging compounds[2]), and wetlands. These items were not included in this Phase I of the subject property.

Note that PCBs may be present in miscellaneous building materials such as caulking, sealants, insulation and sound dampening materials, paint, gaskets, roofing and siding materials, waterproofing compounds, enamel coatings, and other chemical products manufactured prior to 1979. Evaluating the subject property building for potential PCB-containing building materials and possible PCB-containing materials other than "electrical or hydraulic equipment known or likely to contain PCBs" was outside the scope of this Phase I.

1.4 LIMITING CONDITIONS/DEVIATIONS

Haley & Aldrich completed this Phase I in substantial conformance with the ASTM E1527-13 and E1527-21 Standards. With the exception of lacking access to Lot 32 at the subject property, in our opinion, no additions were made to, or deviations and deletions made from the ASTM work scope in completing this Phase I.

1.5 USER RESPONSIBILITIES

The completion of this Phase I is only one component of the process required to satisfy the AAI Rule. In addition, the user must adhere to a set of user responsibilities as defined by the ASTM E1527-13 Standard and the AAI Rule. User responsibilities are discussed in Section 6.6 of this report. A user seeking protection from Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) liability as an innocent landowner, bona fide prospective purchaser, or contiguous property owner must complete all components of the AAI process in addition to meeting ongoing obligations. AAI components, CERCLA liability relief, and ongoing obligations are discussed in the AAI Rule and in Appendix XI of the ASTM E1527-13 Standard.

[2] Per- and polyfluoroalkyl substances (PFAS) are examples of emerging compounds.

2. Site Description

A description of the subject property is detailed in the sections below. Refer to Figure 1 for a Project Locus and Figure 2 for a Site Plan showing relevant subject property features and adjacent properties.

2.1 SITE OWNERSHIP, LOCATION, AND VICINITY DESCRIPTION

Site Description		
Owner	Lot 1: VJN Real Estate Corp. 296th 4th Avenue Brooklyn, New York Lot 6: 2123 Denton LLC 529 Brooklyn Avenue, Suite 3B Brooklyn, New York	Lot 32: LT 284 Gowanus LLC 105 Mulberry Street, Suite 202 New York, New York Lot 34: Crown 286 4th Avenue LLC 286-290 4th Avenue Brooklyn, New York
Occupant/Operator	27 Denton Place (Block 456, Lot 1) is occupied by Golden Touch Car Care Center, an auto detailing center and car wash. 21 Denton Place (Block 456, Lot 6) is improved with an on-grade parking lot. The building at 284 4th Avenue (Block 456, Lot 32) is currently vacant. 290 4th Avenue (Block 456, Lot 34) is currently an undeveloped lot.	
Current Subject Property Use	Commercial	
Size	29,818 sq ft (0.685 acres)	
Building Square Footage	Lot 1, one-story commercial building: 10,960 sq ft Lot 32, one-story commercial building: 5,880 sq ft	
USGS 7.5 Minute Topographic Map	Brooklyn, 2019	
Site County	Kings County	
Zoning	Manufacturing MW-4/C4/R6B, Special Gowanus Mixed-Use District	
Parcel Information	New York City, Borough of Brooklyn Block 456, Lots 1, 6, 32 & 34	
Utilities	Water:	City of New York
	Sewerage:	New York Department of Environmental Protection
	Electricity:	Consolidated Edison
	Gas/Oil/LPG:	Natural Gas - Consolidated Edison
Heating/Cooling System	Heating: Natural Gas Cooling: Central Air	

Site Vicinity Description		
General Area Description	The area surrounding the subject property predominantly consists of manufacturing/industrial, residential, and commercial-use properties.	
Adjoining Property Description	North:	Commercial and residential buildings.
	East:	4th Avenue followed by a multi-story mixed-use building and commercial buildings.
	South:	1st Street followed by a large commercial building operated by Con Edison.
	West:	Denton Place followed by public school P.S. 372 – The Children's School and Our Lady of Peace church.

2.2 PHYSICAL SETTING

Environmental investigations were previously performed by others at portions of the subject property to investigation the physical setting and subsurface conditions. Pertinent issues identified in those reports are summarized in Section 3 of this report and relevant excerpts from these reports are included in Appendix B.

Physical Setting		Source
Topography Summary	The subject property is generally flat.	1
Subject Property Elevation	The elevation of the property is 23 feet above mean sea level.	2
Overburden Soils	Subsurface soils consist historic fill materials including brown to dark brown sand with varying amounts of brick, concrete, and slag from grade to approximately 8 to 20 feet below ground surface (bgs).	5, 6
Bedrock Formation	Bedrock geology is unknown and is overlain by glacial and alluvial deposits.	4
Depth to Bedrock	Greater than 100 feet bgs.	4
Depth to Groundwater	Approximately 11 to 12 feet bgs.	5
Surface Water Flow Direction	Surface water appears to flow toward the west-southwest based on observed surface topography.	1
Regional Groundwater Flow Direction	Regional groundwater flow appears to flow to the west-southwest toward the Gowanus Canal, located about 0.22-mile west of the subject property.	1, 5
Nearest Surface Water Body	The Gowanus Canal is located approximately 0.22-mile west of the subject property.	1

Physical Setting		Source

***Sources**:*

1. *Brooklyn 2019 USGS 7.5 Minute Topographic Map.*
2. *EDR Radius Map report with Geocheck – Inquiry Number 07124126.2r, 20 September 2022.*
3. *Site Visit conducted by Haley & Aldrich of New York, 20 September 2022.*
4. *USGS Bedrock Map of New York.*
5. *Remedial Investigation Report prepared by RSK Environmental Group, LLC, July 2022 (Lot 6 only).*
6. *Remedial Investigation Report prepared by RSK Environmental Group, LLC, March 2022 (Lot 34 only).*
7. *Geotechnical Report prepared by Soil Mechanics Drilling Corp., 19 September 2017 (Lot 34 only).*

Environmentally Sensitive Areas		Source
Floodplain	No	1, 2
Mapped Wetlands	No	1, 3
Aquifer Protection Area/District	No	1
Watershed Protection District	No	1
Natural Resources Protection District	No	1

***Sources**:*

1. *EDR Radius Map with Geocheck – Inquiry Number 07124126.2r, 20 September 2022.*
2. *FEMA Flood Map Service Center – http://msc.fema.gov/portal/home, accessed 22 September 202.2*
3. *National Wetlands Inventory Map – http://www.fws.gov/wetlands/data/mapper.html, accessed 22 September 2022.*

3. Previous Reports

The following reports previously prepared for the subject property were provided and reviewed for this Phase I.

- Phase I Environmental Site Assessment Report (Singer Environmental Group, LTD, 12 April 2018) [Lot 34]
- Phase I Environmental Site Assessment Report (RSK Environmental Group, LLC, March 2022) [Lot 6]
- Remedial Investigation Report (RSK Environmental Group, LLC, March 2022) [Lot 34]
- Remedial Investigation Report (RSK Environmental Group, LLC, July 2022) [Lot 6]
- Remedial Action Work Plan (RSK Environmental Group, LLC, July 2022) [Lot 34]

Pertinent issues identified in those reports are summarized below and relevant excerpts from these reports are included in Appendix B.

Phase I Environmental Site Assessment Report (Singer Environmental Group, LTD, 12 April 2018)

A Phase I Environmental Site Assessment was conducted for Lot 34 by Singer Environmental Group, LTD (Singer) in April 2018. The assessment revealed no evidence of RECs in connection with the property; however, Singer noted the following:

- Based on available records, historic site operations included use as a garage in the 1920s and as an auto repair shop from the 1950s to 1990s.
- A gasoline tank was depicted on historic Sanborn maps dated from the 1920s to 1990s. A site inspection of the interior of the building was not performed for this assessment. No vent or fill was observed on the exterior of the building.
- According to a New York City (NYC) Department of Buildings (DOB) permit dated 20 September 2006, a paint spray booth and gas line from spray booth to the new gas meter were installed.

Phase I Environmental Site Assessment Report (RSK Environmental Group, LLC, 30 March 2022)

A Phase I Environmental Site Assessment was conducted for Lot 6 by RSK Environmental Group, LLC (RSK) in March 2022. The assessment revealed evidence of two RECs and are summarized below:

- The site was formerly improved with residential structures circa 1906 to 1951. The presence of a buried tank/anomaly is likely, which may pose as a threat to impact the subsurface.
- Based on the proximity of historic buried tanks and spill sites, a vapor encroachment condition exists for the site.

Remedial Investigation Report (RSK Environmental Group, LLC, March 2022)

RSK performed a Remedial Investigation (RI) at Lot 34 in December 2021 to provide information sufficient for establishing remedial action objectives, evaluating remedial actions, and selecting a

remedy. The investigation included a geophysical survey, installation of six soil borings, three temporary groundwater monitoring wells, and eight soil vapor probes, and collection of twelve soil samples, three groundwater samples, and eight soil vapor samples. As part of an additional round of sampling, three groundwater samples were collected for metals analysis. Soil samples were analyzed for VOCs, SVOCs, total metals, pesticides, PCBs, 1,4-dioxane, and PFAS. Groundwater samples were analyzed for VOCs, SVOCs, total metals, pesticides, PCBs, 1,4-dioxane, and PFAS. Soil vapor samples were analyzed for VOCs.

Field observations and laboratory analytical results are summarized below:

- The stratigraphy of the site, from the surface down, consists of brown sandy soil and historic fill materials with varying amounts of brick and slag extending to a depth of 10 feet bgs. Groundwater was encountered at depths ranging from 13.24 to 13.54 feet bgs. Groundwater flow was generally from east to west beneath the site.
- Soil results are summarized as follows:
  - No VOCs were detected exceeding New York City Department of Environmental Protection (NYCDEC) Part 375 Unrestricted Use Soil Cleanup Objectives (UUSCOs).
  - Four (4) SVOCs including 2-methylphenol (max. of 1,250 micrograms per kilogram [µg/kg]), acenaphthene (max. of 60,400 µg/kg), fluorene (max. of 64,100 µg/kg), and naphthalene (max. of 46,500 µg/kg) were detected exceeding UUSCOs in shallow and deep soil samples across the site. Eleven (11) SVOCs including anthracene (max. of 126,000 µg/kg), benzo(a)anthracene (max. of 1,430,000 µg/kg), benzo(a)pyrene (max. of 158,000 µg/kg), benzo(b)fluoranthene (max. of 121,000 µg/kg), benzo(k)fluoranthene (max. of 131,000 µg/kg), chrysene (max. of 1,300,000 µg/kg), dibenzo(a,h)anthracene (max. of 28,600 µg/kg), fluoranthene (max. of 4,000,000 µg/kg), indeno(1,2,3-cd)pyrene (max. of 88,000 µg/kg), phenanthrene (max. of 4,030,000 µg/kg), and pyrene (max. of 88,000 µg/kg) were detected exceeding the Restricted Residential Soil Cleanup Objectives (RRSCOs) in shallow and deep soil samples across the site.
  - Three (3) metals including chromium (max. of 88.2 mg/kg), nickel (max. of 145 mg/kg), and zinc (max. of 818 mg/kg) were detected exceeding UUSCOs in shallow and deep samples across the site. Five (5) metals including arsenic (max. of 70.1 mg/kg), barium (max. of 407 mg/kg), copper (max. of 284 mg/kg), lead (max. of 14,500), and mercury (max. of 4.05 mg/kg) were detected exceeding RRSCOs in shallow and deep samples across the site.
  - Perfluorotetradecanoic acid (PFTA) was detected in SB-1 S4 at 0.810 µg/kg and Perfluoro-n-butanoic acid (PFBA) was detected in SB-2 S4 at 0.396 µg/kg.
  - No pesticides, PCBs, or 1,4-dioxane were detected above UUSCOs or RRSCOs.
- Groundwater results are summarized below:
  - No VOCs were detected exceeding the New York State 6NYCRR Part 703.5 Class GA Groundwater Quality Standards (GQS).
  - Five (5) SVOCs, including benzo(a)anthracene (max. of 1.74 micrograms per liter [µg/L]), benzo(b)fluoranthene (max. of 1.55 µg/L), benzo(k)fluoranthene (max. of 1.54 µg/L), chrysene (max. of 1.92 µg/L), and indeno(1,2,3-cd)pyrene (max. of 1.09 µg/L) were detected above GQS in all three groundwater samples.

- Fourteen (14) metals (unfiltered), including aluminum (max. 421 milligrams per liter [mg/L]), antimony (max. of 0.00769 mg/L), arsenic (max. of 0.308 mg/L), barium (max. of 9.40 mg/L), chromium (max. of 0.741 mg/L), copper (max. of 1.78 mg/L), iron (max. of 681 mg/L), lead (max. of 10.7 mg/L), magnesium (max. of 142 mg/L), manganese (max. of 25.0 mg/L), nickel (max. of 1.32 mg/L), sodium (max. of 797 mg/L), zinc (max. of 7.10 mg/L), and mercury (max. 0.4761) were detected above GQS in groundwater samples analyzed. Three (3) dissolved metals including magnesium (max. of 142 mg/L), manganese (max. of 2.07 mg/L), and sodium (max. of 905 mg/L) were detected above GQS.
- Four (4) PFAS compounds, primarily perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS), were detected at a maximum concentration of 53.5 nanograms per liter (ng/L) and 12.5 ng/L, respectively, for all three groundwater samples.
- No pesticides, PCBs, or 1,4-dioxane were detected above GQS in any groundwater sample.
- An additional round of groundwater sampling was performed in February 2022. Resampling results showed fourteen (14) metals exceeding the GQS in the unfiltered groundwater samples analyzed. Four (4) dissolved metals including iron, magnesium, manganese, and sodium were detected exceeding GQS in groundwater samples analyzed.

- Soil vapor results are summarized below:
  - Total petroleum-related VOCs (benzene, toluene, ethylbenzene, and xylenes [BTEX]) concentrations ranged from 62 micrograms per cubic meter (µg/m^3) in sample SV-3 (2') to 366.9 µg/m^3 in sample SV1 (10'). Chlorinated VOCs including 1,1,1-trichloroethane and methylene chloride were not detected in any soil vapor samples. The chlorinated VOC 1,1-dichloroethane was detected in soil vapor sample SV-4 (10') at a concentration of 2.49 µg/m^3 and carbon tetrachloride was detected in soil vapor samples SV-3 (2' and 10') and SV-4 (10') at a maximum concentration of 0.47 µg/m^3. The chlorinated VOC cis-1,2-dichloroethylene was detected in soil vapor samples SV-2 (10'), SV-3 (2' and 10'), and SV-4 (10') at a maximum concentration of 180 µg/m^3; tetrachloroethene (PCE) was detected in all eight soil vapor samples at a maximum concentration of 2,950 µg/m^3; trichloroethene (TCE) was detected in all eight soil vapor samples except SV-2 (2') at a maximum concentration of 6,820 µg/m^3; and vinyl chloride was detected in all the deepest soil vapor samples (i.e., at 10 ft), at a maximum concentration of 166 µg/m^3.

Based on the findings of the RI, RSK identified four areas of concern (AOCs) for the site including the possible presence of a buried tank/anomaly, historic fill materials beneath the building slab, groundwater impact by polycyclic aromatic hydrocarbons (PAHs), and the presence of soil vapors associated with gasoline products and chlorinated VOCs.

Remedial Investigation Report (RSK Environmental Group, LLC, July 2022)

RSK performed a RI at Lot 6 in July 2022 to provide information sufficient for establishing remedial action objectives, evaluating remedial actions, and selecting a remedy. The investigation included a geophysical survey, installation of five (5) soil borings to collect ten samples, three (3) groundwater monitoring wells to collect three samples, and five (5) soil vapor probes to collect five samples. Soil samples were analyzed for VOCs, SVOCs, total metals, pesticides, PCBs, 1,4-dioxane, and PFAS.

Groundwater samples were analyzed for VOCs, SVOCs, total metals, PCBs, 1,4-dioxane, and PFAS. Soil vapor samples were analyzed for VOCs.

Field observations and laboratory analytical results are summarized below:

- The stratigraphy from the site, from the surface down, consists of 8 feet of dark brown, sandy soil and historic fill material consisting of crushed red brick and concrete. This material is underlain by 4 feet of silty clay soil. The depth to bedrock is beyond 20 feet, as it was not encountered during the RI. The depth to groundwater at the site ranges between 11 and 12 feet and generally flows from east to west beneath the site.
- Soil results are summarized below:
  - One (1) VOC was detected exceeding NYCDEC Part 375 UUSCOs, TCE (max. of 3,900 µg/kg).
  - Four (4) SVOCs including acenaphthene (max. of 66,000 µg/kg), fluorene (max. of 56,000 µg/kg), dibenzofuran (max of 31,000 µg/kg), and naphthalene (max. of 35,000 µg/kg) were detected exceeding UUSCOs.
  - Ten (10) SVOCs including anthracene (130,000 µg/kg), benzo(a)pyrene (max. of 240,000 µg/kg), benzo(b)fluoranthene (max. of 210,000 µg/kg), benzo(k)fluoranthene (max. of 210,000 µg/kg), chrysene (280,000 µg/kg), dibenzo(a,h)anthracene (max of 39,000 µg/kg), fluoranthene (max. of 510,000 µg/kg), indeno(1,2,3-cd)pyrene (max. of 160,000 µg/kg), phenanthrene (max. of 530,000 µg/kg), and pyrene (max. of 410,000 µg/kg) were detected exceeding RRSCOs in samples between 0 and 4 feet bgs.
  - Three (3) heavy metals including chromium (max. of 57.7 mg/kg), copper (max. of 263 mg/kg), and zinc (max. of 960 mg/kg) were detected exceeding UUSCOs.
  - Five (5) heavy metals including arsenic (max. of 20 mg/kg), barium (max. of 797 mg/kg), lead (max. of 15,300 mg/kg), mercury (max of 5.69 mg/kg), and cadmium (max. of 6.11 mg/kg) were detected exceeding RRSCOs.
  - Five (5) pesticides including, 4,4'-DDD (max. of 9.4 µg/kg), 4,4-DDE (max. of 350 µg/kg), 4,4'-DDT (max. of 840 µg/kg), a-Chlordane (max of 230 µg/kg), and g-chlordane (max. of µg/kg) were detected exceeding UUSCOs.
  - No PCBs, PFAS, or 1,4-dioxane were detected above UUSCOs.
- Groundwater results are summarized below:
  - One (1) VOC, naphthalene (max. 420 µg/L) was detected exceeding the New York State 6NYCRR Part 703.5 Class GA GQS.
  - Ten (10) SVOCs including 2-methylnaphalene (max. 84 µg/L), acenaphthene (max. 69 µg/L), naphthalene (max. 70 µg/L), phenanthrene (max. 70 µg/L), benz(a)anthracene (max. 0.97 µg/L), benzo(a)pyrene (max. 0.25 µg/L), benzo(b)fluoranthene (max. 0.53 µg/L), benzo(k)fluoranthene (max. 0.4 µg/L), chrysene (max. of 1.7 µg/L), indeno (1,2,3-cd)pyrene (max. of 0.28 µg/L) were detected exceeding the GQS.
  - Six (6) heavy metals including aluminum (max. of 12.2 mg/L), arsenic (max. of 0.093 mg/L), iron (max. of 52.3 mg/L), lead (max. of 0.0577 mg/L), manganese (max. of 1.39 mg/L), and sodium (max. of 1.7 mg/L) were detected exceeding the GQS.

- PFAS compounds ranging from concentration of 2.09 to 152 ng/L were detected in all groundwater samples.
- No PCBs or pesticides were detected above the GQS.

- Soil vapor results are summarized below:
  - Total petroleum-related VOCs (BTEX) concentrations ranged from 5.38 to 1,700 (µg/m^3). The chlorinated VOC carbon tetrachloride was detected in samples SV-2 through SV-5 at a maximum concentration of 0.52 µg/m^3, methylene chloride was detected in SV-2 at a concentration of 15.5 µg/m^3; tetrachloroethylene (PCE) was detected in samples SV-1 through SV-4 at a maximum concentration of 16.8 µg/m^3; and vinyl chloride was detected in SV 2 at a concentration of 0.43 µg/m^3, all of which were detected below monitoring level ranges as established by the New York State Department of Health (NYSDOH) matrices. The chlorinated VOCs cis-1,2-dichloroethylnee was detected in samples SV-1 and SV-2 at a max concentration of 23.3 µg/m^3 and TCE was detected in samples SV-1 through SV4 at a max concentration of 1,980 µg/m^3, both of which are above the monitoring level range requiring mitigation as established by the NYSDOH soil vapor guidance matrices.

Based on the findings of the RI, RSK identified two AOCs for the site including the possible presence of a buried tank/anomaly on the site and the proximity of off-site buried tanks, spill sies, and E-Designated sites which could lead to a vapor encroachment condition (VEC).

Remedial Action Work Plan (RSK Environmental Group, LLC, July 2022)

A Remedial Action Work Plan (RAWP) for Lot 34 was prepared by RSK under the Office of Environmental Remediation (OER) Voluntary Cleanup Program (VCP). The remedial action described in the RAWP provides for the protection of public health and the environment consisted with the proposed mixed-use commercial and residential development. The proposed redevelopment of the site consists of a fourteen-story mixed-use commercial and residential building with a partial cellar. For development purposes, soil beneath the site was planned to be excavated to 11.5 feet bgs for the partial cellar. To facilitate development, RSK proposed excavation and removal of soil/fill exceeding Track 4 Site-Specific SCOs. Proposed engineering controls included installation of a composite cover system consisting of 6-inch-thick concrete building slab underlain by compacted crushed stone, and the installation of a vapor barrier system consisting of vapor barrier beneath the building cellar slab and outside of sub-grade foundation walls to grade of the building. Additionally, a sub-slab depressurization system (SSDS) was proposed and would consist of two separate systems with an extensive network of piping beneath the building slab. The RAWP included provisions to establish institutional controls and prepare a Site Management Plan (SMP). The SMP would provide for long-term management of residual contamination and include plans for the operation, maintenance, monitoring, and inspection certification requirements of the engineering and institutional controls.

4. Subject Property History

Haley & Aldrich assessed past usage of the subject property and adjoining properties through a review of:

- Sanborn Fire Insurance Maps dated 1886, 1888, 1904, 1906, 1915, 1921, 1922, 1926, 1928, 1938, 1950, 1951, 1965, 1969, 1977, 1978, 1979, 1980, 1981, 1982, 1985, 1986, 1987, 1988, 1991, 1992, 1993, 1994, 1995, 1996, 2001, 2022, 2003, 2004, 2005, 2006, and 2007;
- Topographic Maps dated 1897, 1898, 1900, 1947, 1955, 1967, 1979, 1995, 2014, 2016, and 2019;
- Aerial Photographs dated 1924, 1943, 1951, 1954, 1961, 1966, 1971, 1974, 1980, 1984, 1994, 2006, 2009, 2013, and 2017;
- City Directories dated 1928, 1934, 1940, 1945, 1949, 1960, 1965, 1970, 1973, 1976, 1980, 1985, 1992, 1994, 1997, 1999, 2000, 2004, 2005, 2009, 2015, and 2017;
- Municipal records;
- Previous Reports; and
- Interviews with subject property personnel.

Copies of information obtained from historical references reviewed are included in Appendix C. Unless otherwise noted below, per the ASTM standard, sources were reviewed dating back to the late 1800s or first developed use, whichever is earlier, and at 5-year intervals if the use of the property has changed within the time period.

4.1 SUBJECT PROPERTY

Earliest records from the late 1800s identify the subject property as undeveloped and divided into three separate parcels.

Lot 1 was developed in the early 1900s with a wagon shed and smaller structures, uses of which were not reported. By the early to mid-1920s, the lot was improved with a large industrial building operated by Fulton Smelting & Refining Works, Inc., and a two-story and three-story dwelling in the northwestern corner (formerly addressed 25 Denton Street). Certificates of Occupancy indicate the metal smelting plant continued operation through the 1940s. By 1951, the northwestern dwellings were razed and converted into a building labeled as “scrap metal” with four gasoline tanks depicted in the southeastern corner along 4th Avenue. In the mid-1960s, Lot 1 was labeled as “wholesale linoleum” before being converted into auto body/repair in the late 1970s. From the 1970s to 2007, Lot 1 remained unchanged before being converted into its current use as an auto detailing, transmission service, and car wash facility.

Lot 6 was developed in the early 1900s with multiple dwellings. By 1951, the dwellings in the northwestern portion of the lot were razed and from the mid-1960s to present Lot 6 has operated as a parking lot.

Lots 32 and 34 were developed in the early 1900s with bottle rack storage areas, before being converted into garages in the early to mid-1920s. By the early 1950s, Lots 32 and 34 were used for auto repair

shops with gasoline tanks depicted along 4th Avenue. The 1965 Certificate of Occupancy for Lot 32 indicates the lot was used for sales and shipping of oil burner parts and the 1968 Certificate of Occupancy indicates the lot was operated as an auto repair shop. Lots 32 and 34 remained relatively unchanged from the mid-1960s until 2007. From 2007, Lot 32 has operated as a burner and heating supply company until vacated circa 2021. From 2007, Lot 34 has operated as an auto center until razed in 2022.

The table below provides a detailed summary of pertinent information from the historical sources reviewed:

Dates	Description of Subject Property	Sources
Late 1800s to Late 1930s	The 1906 Sanborn map shows the subject property as improved with multiple dwellings on Lot 6, a wagon shed and smaller structures on Lot 1, and bottle racks/storage on Lots 32 and 34. By the early to mid-1920s, Lot 1 was improved with a large industrial building operated by Fulton Smelting & Refining Works Inc. and a two-story and three-story dwelling. Lots 32 and 34 were depicted as garages and Lot 6 was improved with dwellings. A 1928 City Directory listing for Lot 1 includes Keller A Rubber Metals.	Sanborn Maps, Aerial Photographs, City Directories
Late 1930s to Mid-1960s	In the early 1940s, City Directories indicate Lot 1 was operated by a service station). By 1951, the dwellings on Lot 1 were razed and the building was identified as "scrap metal." Four gasoline tanks were depicted in the southeastern corner of Lot 1 on Sanborn maps from 1951 to 1965. The garages on Lots 32 and 34 were identified as auto repair shops with a gasoline tank depicted along 4th Avenue, and the dwellings on the northern portion of Lot 6 was razed.	Sanborn Maps, Aerial Photographs, City Directories
Mid-1960s to Mid-2000s	By the mid-1960s, Lot 6 was converted into a parking lot, Lot 1 was identified as "wholesale linoleum," and the auto repair shops on Lots 32 and 34 remained unchanged. By the late 1970s, the entire subject property, except for Lot 6, was used for auto body/repair use. The gasoline tanks in the southeast corner of Lot 1 were no longer depicted after 1965. City Directory listings during this interval include MAACO Auto Painting & Body works, AAMCO Automatic Transmissions, and Great Bear Auto Center.	Sanborn Maps, Aerial Photographs, City Directories
2007 to present	Lot 1 operated as an auto detailing facility, transmission service, and car wash; Lot 32 as a burner and heating supply company before vacating circa 2021; Lot 34 as an auto center until the building was razed in 2022; and Lot 6 as a parking lot. The subject property remains relatively unchanged today.	Sanborn Maps, Aerial Photographs, City Directories

4.2 ADJOINING PROPERTIES

The table below provides a summary of pertinent information from the historical sources reviewed regarding adjacent properties:

Dates	Description of Adjacent Properties	Sources
Late 1800s to Late 1930s	North: Residential dwellings and stores. The 1926 Sanborn map depicts a garage on the northeast corner of Carroll Place and 4th Avenue with two gasoline tanks. South: 1st Street followed by the Washington Park Brooklyn Ball Club field and dwellings. By 1915, the baseball field was converted into a public storage warehouse and the dwellings converted into the Consumers Pie & Baking Corp. East: 4th Avenue followed by dwellings and stores. West: Denton Street followed by stores, a school, and church.	Sanborn Maps, Aerial Photographs
Late 1930s to Mid-1960s	North: Low-rise stores, an auto repair garage and filling station on Carroll Place, and buildings used for bottle storage and wastepaper. South: The 1951 Sanborn map shows the property across 1st Street as a filling station with five gasoline tanks. The other portion of the property is operated by Con Edison. Properties further south are operated by the Wagner Baking Company. By 1965, the filling station is not present and converted into a parking lot. East: 4th Avenue followed by a filling station on southwestern corner of 1st Street and 4th Avenue and an auto repair shop further north. West: Denton Street followed by a school and church.	Sanborn Maps, Aerial Photographs
Mid-1960s to present	North: Low-rising dwellings, stores, and garages. The 1978 Sanborn map depicts an NYC Transit substation immediately north of Lot 32 along 4th Avenue. The filling station on the corner of Carroll Place and 4th Avenue is no longer present. South: 1st Street followed by a large building and parking lot operated by Con Ed and the Peerless Paper Box Co. In the 1995 Sanborn Map, the paper box company is no longer depicted. East: 4th Avenue followed by a filling station on southwestern corner of 1st Street and 4th Avenue and stores. In the 1988 Sanborn map, the filling station is no longer shown and converted to auto repair use. West: Denton Street followed by a school and church.	Sanborn Maps, Aerial Photographs

5. Environmental Records Review

5.1 ENVIRONMENTAL DATABASE RECORDS SEARCH

Haley & Aldrich used an electronic database service[3], to complete the environmental records review. The database search was used to identify properties that may be listed in the referenced agency records, located within the ASTM-specified approximate minimum search distances as shown in the table below. A description of each database searched is in Section 11.2 of this report. The complete environmental database report is provided in Appendix C. Pertinent information obtained from the database is summarized in Section 5.3 below.

Database Searched	Approximate Minimum Search Distance	Subject Property Listed?	Number of Sites within Search Distance[1]
1. NPL Sites	1 mile	No	1
2. Delisted NPL Sites	0.5 mile	No	0
3. CERCLIS/SEMs[2] Sites	0.5 mile	No	1
4. CERCLIS-NFRAP/SEMs[2] Sites	0.5 mile	No	3
5. Federal ERNS	Site only	No	Not Applicable
6. RCRA non-CORRACTS TSD Facilities	0.5 mile	No	0
7. RCRA CORRACTS TSD Facilities	1 mile	No	2
8. RCRA Generators	Site & Adjoining	No	1
9. Federal Institutional/Engineering Controls	Site Only	No	Not Applicable
10. State/Tribal Equivalent NPL Sites	1 mile	No	0
11. State/Tribal Equivalent CERCLIS[2] Sites	0.5 mile	No	7
12. State/Tribal Registered Storage Tanks	Site & Adjoining	No	19
13. State/Tribal Landfills and Solid Waste Disposal Sites	0.5 mile	No	14
14. State/Tribal Leaking Storage Tanks	0.5 mile	No	42
15. State/Tribal Institutional Controls/Engineering Controls	Site Only	No	Not Applicable
16. State/Tribal Voluntary Cleanup Sites	0.5 mile	No	13
17. State/Tribal Brownfield Sites	0.5 mile	No	25
18. Orphan Site List[3]	Site & Adjoining	No	0

Notes:

1. *Some sites may be included on multiple databases.*
2. *The US EPA retired the CERCLIS database in October 2013. In January 2016, the Superfund Enterprise Management System (SEMS), which replaces the CERCLIS database, became active. The CERCLIS database records search included as part of this assessment includes currently ascertainable data from the SEMS and SEMS-Archive databases as reported through the database vendor.*
3. *Haley & Aldrich also searched the Orphan Site List provided in the database report for the subject property and sites adjoining the subject property. Orphan sites are those that, due to incorrect or incomplete addresses, could not be mapped.*
4. *If applicable, other relevant databases, not specifically required by ASTM were included in the database review.*

[3] Examples of electronic database services are EDR/Lightbox and ERIS.

5.2 ADDITIONAL ENVIRONMENTAL RECORDS OR FILE REVIEW

To supplement the environmental record search, we contacted the following state and local government agencies and searched applicable online databases. If copies of the documents reviewed were obtained, pertinent material is included in Appendix C. Relevant information obtained is included in the appropriate sections of the report and/or discussed in Section 5.3 below. Adjacent properties were also included in requests for additional information if a significant incident or release was identified. Those adjacent properties reviewed for this assessment include:

- 267 4th Avenue
- 269-271 4th Avenue

Agency	Request Sent or Files Searched		Files Exist and are Available for Review	Files Reviewed
	Subject Property	Adjoining Properties		
New York State Department of Environmental Conservation[2]	Yes	No	No	N/A
New York State Department of Finance City Registry[3]	Yes	No	Yes	Yes (online)
New York City Department of Buildings[4]	Yes	No	Yes	Yes (online)
New York City Department of Health[5,1]	Yes	No	No	N/A
Fire Department of New York[6,1]	Yes	No	No	N/A
New York City Department of Environmental Protection[7,1]	Yes	No	No	N/A
New York City Office of Environmental Remediation[8]	Yes	No	No	N/A

***Notes**:*

1. *To date, no responses have been received from the Freedom of Information Act (FOIA) requests noted above. Based on the information obtained through our interviews with key site personnel, and our review of other records, it does not appear that responses to the FOIA requests should affect our conclusions regarding RECs on the subject property. However, when a response is received, it will be forwarded to* [redacted] *and, if it affects our conclusions regarding the subject property,* [redacted] *will be informed.*
2. *The New York Department of Environmental Conservation maintains information regarding spills, petroleum bulk storage (PBS), including underground storage tanks (USTs) and aboveground storage tanks (ASsT) and investigation/remediations overseen by New York State regulatory programs.*
3. *The New York City Department of Finance City Register maintains information regarding property transactions, including deeds, lease, and mortgage documents. Records were reviewed in the online database.*
4. *The New York City Department of Buildings maintains information regarding violations, complaints, certificates of occupancy, elevator records, asbestos assessments, and permits. Records were reviewed in the online database, which included several Certificate of Occupancy records for the subject property.*
5. *The New York City Department of Health maintains information regarding environmental concerns for public health. A response has not yet been received by the NYSDOH.*
6. *The Fire Department of New York maintains information regarding USTs and emergencies/fire episodes. A response has not yet been received by the FDNY.*
7. *The New York City Department of Environmental Protection maintains information regarding wastewater discharge and boilers. A response has not yet been received by the NYCDEP.*
8. *The New York City Office of Environmental Remediation maintains information regarding investigation/remediations, manages the New York City Voluntary Cleanup Program, and assists with guidance through all the City Environmental Quality Review (CEQR) requirements. Records were reviewed in the online database.*

5.3 DETAILED DESCRIPTION OF RELEVANT INFORMATION

5.3.1 Subject Property

Listing	Description	Potential Impact
US AIRS, FINDS, ECHO	296 4th Avenue (Lot 1) – Maaco Auto Painting is listed in the FINDS and ECHO databases. No violations are associated with these listings. 296 4th Avenue (Lot 1) is listed in the US AIRS database as part of the State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards under Programmatic ID AIR NY0000002610300124 and Facility Registry ID 110001593339. The case is in the inspection/evaluation and compliance monitoring phase.	A listing in these databases do not necessarily indicate an environmental concern.
EDR Historic Auto	296 4th (Lot 1) Avenue is listed in the EDR Historic Auto database from 1979 to 2005 and operated as an automotive repair shop. 296 4th Avenue was operated as "Jen Jay Transmission Inc" from 1979 to 1993" and then operated as "Affordable Motor Collision" from 2002 through 2005.	A listing on this database does not necessarily indicate an environmental concern; however, in conjunction with other former site uses and gasoline tanks with undocumented closure status as noted in historical resources, this is considered a REC.
RCRA NonGen/NLR NY Manifest	296 4th Avenue (Lot 1) is listed in the RCRA NonGen/NLR database under EPA ID NYD986925642, for the former generation of hazardous waste at the site including non-halogenated solvents (F003 and F005) by Maaco Auto Painting and Bodyworks Inc. in 1998, 1999, 2000, and 2007. 296 4th Avenue (Lot 1) is also listed in the NY Manifest database for the transportation of hazardous materials associated with Maaco Auto Painting & Bodyworks, Inc.	Due to the lack of reported violations associated with this listing, it is not anticipated to adversely affect the subject property.
NY Manifest – Con Edison	292 4th Avenue (Lot 1) is listed multiple times in the NY Manifest data for the transportation of hazardous materials (D008) from the site in 2014.	Due to the lack of reported violations and releases associated with this listing, it is not anticipated to adversely affect the subject property.

5.3.2 Nearby Sites

Several sites were listed in the database report within the applicable search radii or identified in regulatory records reviews. Due to their location with respect to the subject property (on the opposite side of a hydrogeologic barrier, distance from the site, location of the site relative to inferred groundwater flow, subsurface utilities and building levels, etc.), or their status (closed out release, etc.), several of the sites are not likely to adversely affect the subject property and are not discussed herein.

Only those sites adjacent to the subject property and sites with a potential to have impacted the subject property are discussed below. The complete database report and relevant records review information is included in Appendix C.

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
Street 1st Street/4th Avenue (0.011 miles southeast)	NY Spills	Spill #0404988 was reported at the intersection of 1st Street and 4th Avenue on 6 August 2004 due to a release of approximately 1.5 gallons of antifreeze from a vehicular accident. It was reported that the spill was cleaned using oil absorbents and the spill case was closed by NYSDEC on 6 August 2004.	Since this case has achieved regulatory closure, it is not anticipated to adversely affect the subject property.
North Petroleum Corp 275 4th Avenue (0.026 miles east)	RCRA LQG UST AST NY Manifest VCP EDR Historic Auto	This property is listed in the RCRA database as a large quantity generator (LQG) of multiple hazardous wastes including ignitable waste and lead by the operator "Spartan Petroleum." No violations are associated with this listing. This property is listed in the UST database under PBS ID 2-241849 for 14 550-gallon gasoline USTs that were installed in November 1967 and closed prior to March 1991. This property is also listed in the AST database for two 550-gallon ASTs containing gasoline that were closed and removed on 1 May 1994. This property is listed multiple times in the NY Manifest database for the transportation of hazardous waste (D006) from the property in 2015. This property is listed in the New York City Voluntary Cleanup Program (VCP) under site IDs 14TMP0054K, 14EHAZ054K, 14CVCP240K. According to available records, cleanup at the site was performed in 2014 to 2015 and the site achieved Track 4 Residential Soil Cleanup Objectives (SCOs). The property employs the use of protective environmental systems (composite cover system and vapor barrier system) prevent exposure to residual contamination beneath the property. This property is listed in the EDR Historic Auto database for the former use as a gasoline service station from 1974 to 1987. Previous operators include "Dana Fuel Corp" from 1974 to 1979, "M&P Service Station" from 1977 to 1979, and "Zoya Diagnostic Inc." from 1982 to 1987.	While this property has been remediated through the VCP and engineering controls have been implemented to address the residual petroleum contamination, due to the proximity of the site and located hydraulically upgradient to the subject property, impacted soil vapor and/or groundwater may have migrated and be present at the subject property.

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
269-271 4th Avenue (0.026 miles east)	VCP NY Spills E-Designation	This property is listed in the VCP under site ID 14TMP0455K, 14EHAZ455K, and 14CVCP250K. According to available records, cleanup at the site was performed in 2018 and the site achieved Track 4 Residential Soil Cleanup Objectives (SCOs). The property employs the use of protective environmental systems (composite cover system, vapor barrier system, and active sub-slab depressurization system) prevent exposure to residual contamination beneath the property. Spill #0501021 was reported at this property on 25 April 2005 when contaminated soil and groundwater was encountered during a site investigation. Results of the soil and groundwater investigation were not included in the spill report. However, contamination was assumed to be coming from the south adjoining property, 275 4th Avenue. Remediation efforts were not detailed in the spill case and NYSDEC administratively closed the case on 20 February 2006. This property is listed with an environmental E-Designation (E-113) for hazardous materials, resulting from a City Environmental Quality Review (CEQR) effective 30 April 2003 (CEQR # 03DCP030K).	While this property has been remediated through the VCP and engineering controls have been implemented to address the residual contamination, due to the proximity of the site and located hydraulically upgradient to the subject property, impacted soil vapor and/or groundwater may have migrated and be present at the subject property.
Construction Site 267 4th Avenue (0.023 miles east)	NY Spills	Spill #0912838 was reported at this property on 10 March 2010 due to a complaint received by a neighbor that the construction site was filled with water that had a gasoline-like odor. Investigation into this incident was not included in the spill report and NYSDEC administratively closed the spill case on 11 March 2010.	Since this case has achieved regulatory closure, it is not anticipated to adversely affect the subject property.
3rd Ave Yard 1st Street and 4th Avenue (0.018 miles southeast)	NY Spills	Spill #0002643 was reported at the intersection of 1st Street and 4th Avenue on 2 June 2000 due to a transformer that was removed from a vault and placed on a containment pad that began to leak. The containment was cleaned with an oil absorbent and waste was placed in barrels for disposal. NYSDEC administratively closed this spill case on 25 September 2001.	Since this case has achieved regulatory closure, it is not anticipated to adversely affect the subject property.
4th Avenue/Garfield Street (0.20 miles northeast)	NY Spills	Spill #8404005 was reported on 17 December 1984 related to the investigation of eight spills along 4th Avenue running from 6th Street to Pacific Street that involve feeders that run	Since this case has achieved regulatory closure, it is not anticipated to

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
		along the top of the subway line along 4th Avenue. An investigation was conducted involving the installation of 56 soil borings and collection of 112 soil samples in order to delineate the extent of dielectric fluid impacts in the area, and installation of up to 8 groundwater monitoring wells to assess potential impacts to groundwater and potential migration pathways to surface water receptors. Results of the investigation were not detailed in the spill report, however, Con Edison recommended closure of the spill case due to the shallow depth of the subway tunnel and associated infrastructure at the spill location, and the absence of evidence of residual dielectric fluid at the time of the release. The NYSDEC closed the spill on 29 April 2020.	adversely affect the subject property.
Con Edison 222 1st Street (0.031 miles south)	NY Spills	Spill #0604245 was reported at the property on 28 June 2006 associated with a previous spill. Con Edison personnel were unable to give details on the spill but directed NYSDEC to a large pit in the floor of a loading bay where vehicle repairs may have been made in the past. No further information was available and it was indicated that further investigation and remediation would be conducted under the BCP. NYSDEC administratively closed the spill case on 8 June 2017. Spill #0705772 was reported at the property on 20 August 2007 due to a release of 6 gallons of hydraulic oil in a concrete containment pit. This case achieved regulatory closure on 8 November 2007. Spill #0512797 was reported at the property on 2 April 2006 due to a vactor that leaked approximately 1 gallon of hydraulic fluid onto concrete. The spill was contained with an oil absorbent and cleanup was completed. The case achieved regulatory closure on 12 April 2006. Spill #9501055 was reported at the property on 25 April 1995 due to a leak of gasoline from a vehicle. Approximately 15 gallons of gasoline leaked from the vehicle and the spill was cleaned with pads and non-combustible	Since this property is located hydraulically downgradient of the subject property and the spill case has received regulatory closure, it is not anticipated to adversely affect the subject property.

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
		absorbent. This case achieved regulatory closure on 16 July 2004. Spill #0505767 was reported at the property on 10 August 2005 due to a spill of approximately 1 gallon of hydraulic oil that leaked from a lift being used by a contractor for building renovations. The spill was in the process of being cleaned and this case achieved regulatory closure on 11 August 2005.	
McDonalds 245 1st Street (0.008 miles west)	NY Spills	Spill #0551768 was reported at the property on 1 February 2006 when an investigation was conducted at the property which indicated VOC impacts to groundwater and soil. Remediation efforts were conducted at the property including injection of oxygen release compounds (ORC) to reduce VOCs in groundwater. In 2013 a Supplemental Subsurface Investigation was conducted at the site and VOCs were detected slightly above the standards in groundwater samples. Based on the analytical results, it was requested that NYSDEC close the spill case and the case achieved regulatory closure on 7 October 2013.	Since this property is located hydraulically downgradient of the subject property and the spill case has received regulatory closure, it is not anticipated to adversely affect the subject property.
Con Edison 221 1st Street (0.027 miles west)	NY Spills NY Manifest RCRA NonGen/NLR	Spill #9911979 was reported at the property on 17 January 2000 when a hose broke on a Con Edison vehicle resulting in the release of approximately 2 quarts of antifreeze. The spill was cleaned with absorbents and this case achieved regulatory closure on 23 February 2000. This property is listed in the RCRA database as a Non-Generator/No Longer Regulated under EPA ID NYP004772869 and NYP004837696 for formerly generating hazardous waste as a large quantity generator in 2015 and 2016. This property is listed multiple times in the NY Manifest database for the transportation of hazardous waste (B002 and D007) from the property in 2015.	Since the property is located hydraulically downgradient of the subject property, the spill case has achieved regulatory closure, and no violations are listed with the NonGen/NLR listing, it is not anticipated to adversely affect the subject property.
MTA NYCT 276 4th Avenue (0.019 mile ENE)	RCRA SQG	This property is listed in the RCRA database as a Small Quantity Generator under EPA ID NYR000250654 for formerly generating hazardous waste.	Since no violations are listed with the SQG listing, it is not anticipated to

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
			adversely affect the subject property.

5.4 VAPOR MIGRATION

The ASTM E1527-13 and E1527-21 Standards state that "for the purposes of this practice, “migrate” and “migration” refer to the movement of hazardous substances or petroleum products in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." Thus, this section specifies whether or not we perceive a risk of vapor migration to the subject property.

To assess a vapor migration risk we conducted a detailed review and analysis of the site-specific environmental database report and/or other reasonably ascertainable records to assess whether:

1. Off-site properties have documented chlorinated VOC contamination located within 100 feet of the subject property, or
2. Off-site properties have documented volatile petroleum hydrocarbon contamination within 30 feet of the subject property.

Based on our records review, we have identified and assessed the following potential sources for vapor migration:

Adjacent properties in the surrounding area were historically used for industrial/manufacturing purposes and were formerly operated as filling stations. Frequently, industrial/manufacturing facilities use hazardous chemicals such as lubricants and/or cleaning agents, and petroleum constituents as well as chlorinated solvents for equipment maintenance.

If improperly disposed, the abovementioned hazardous chemicals related to current and/or historical operations at nearby properties have the potential to impact soil and groundwater beneath the surface. If present in groundwater, VOCs, typical of products used in auto-related, manufacturing, and dismantling facilities, could volatilize into soil vapor.

6. Subject Property Reconnaissance and Key Personnel Interview(s)

A site visit to observe subject property conditions was conducted by Elizabeth Scheuerman and Nicole Mooney of Haley & Aldrich, on 28 September 2022. Access to the subject property was provided by [redacted]

Haley & Aldrich personnel observed accessible interior areas of the subject property building(s), including common areas, basement areas, mechanical spaces, and tenant spaces. Haley & Aldrich also observed the exterior portions of the subject property, including the property boundaries, and observed adjoining property conditions from the subject property boundaries and/or public thoroughfares. No weather-related conditions that would limit our ability to observe the subject property or adjoining properties occurred during our site visit; however, there was no access to the subject property building on Lot 32.

An interview with Gus Monogioudis of Golden Touch Car Care Center, the key site manager, was performed in conjunction with the site visit. Per the ASTM Standard, past owners, operators, and occupants of the subject property who are likely to have material information regarding the potential for contamination at the subject property shall be contacted to the extent that they can be identified and that the information likely to be obtained is not duplicative of information already obtained from other sources. Haley & Aldrich was not provided with contact information in order to interview past owners and/or operators at the subject property. Based upon historical data collected from other sources, this potential data gap is not expected to adversely impact the results of this assessment.

The findings of the site visit and interviews are discussed below. Subject property photographs are included in Appendix E.

ASTM E1527-13 and E1527-21 Standards Section 10.8 requires that, prior to the site visit, the current subject property owner or key site manager and user, if different from the current owner or key site manager, be asked if there are any helpful documents that can be made available for review. Documents were provided and are discussed in Section 3.

6.1 CURRENT USE OF THE SUBJECT PROPERTY

The current subject property use is commercial and vacant. Lot 1 is occupied by Golden Touch Car Care Center, an auto detailing center and car wash. Lot 6 is improved with an on-grade parking lot. Lot 32 is improved with a vacant building. Lot 34 is a vacant undeveloped lot capped with cement upon which there are small piles of construction debris, brick, and refuse.

6.2 GENERAL DESCRIPTION OF STRUCTURES

Lot 1 is comprised of a one-story commercial building covering approximately 10,960 sq ft. The building at Lot 32 is currently vacant and covers approximately 5,880 sq ft.

6.3 USE, STORAGE, AND DISPOSAL OF PETROLEUM PRODUCTS AND HAZARDOUS MATERIALS

Petroleum products and/or hazardous materials were observed or reported to be used, stored, and/or disposed of at the subject property as described below.

The following bulk storage tanks were depicted on the Sanborn fire insurance maps from the 1920s through the 1960s but not observed at the subject property during the site reconnaissance:

Tank #	AST/ UST	Contents	Capacity	Location[1]	Use	Closure Status
1	Unknown	Gasoline	Unknown	Lot 32	Unknown	Unknown
2	Unknown	Gasoline	Unknown	Lot 34	Unknown	Unknown
3, 4, 5, 6	Unknown	Gasoline	Unknown	Lot 1	Unknown	Unknown

***Notes**:*
1. *Approximate tank locations are shown in Sanborn fire insurance maps in Appendix C.*

Other petroleum/hazardous materials observed at the subject property included:

Petroleum Product or Hazardous Substances	Quantity Stored & Container	Storage Location	Use	Disposal	Observations/ Evidence of release
Synthetic Motor Oil	Approximately 10 4.5-quart containers, 8 5-gallon dispensers, and 1 55-gallon drum	Lot 1, inside subject property building on shelves located near northwest wall and inside office near north corner of building. Dispensers and 55-gallon drum located near northeast wall, next to electric vehicle lift.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment for 55-gallon drum. Floor drains noted nearby.
Solvent-Free Engine Cleaner	Approximately 35 1-gallon containers	Lot 1, inside subject property building under shelves in northwest corner of building. Also located inside of storage room/office on northeast side of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Power Steering Service Fluid	Approximately 30 2-quart containers	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Synthetic Oil Stabilizer	Approximately 170 1-quart bottles	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A

Petroleum Product or Hazardous Substances	Quantity Stored & Container	Storage Location	Use	Disposal	Observations/ Evidence of release
Cooling System Protector	Approximately 25 15-Fl.-Oz. containers	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Oil System Service	Approximately 78 15-Fl.-Oz. plastic bottles (39 kits - kits include 2 bottles each).	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Emission System Cleaner	Approximately 48 15-Fl.-Oz. cans (16 kits - kits include 3 cans each).	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Fuel Injection System Cleaner	Approximately 11 15-Fl.-Oz. cans	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Engine Tune-Up Fluid	Approximately 55 11-Fl.-Oz. cans	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Engine Stop-Leak	1 15-Fl.-Oz. can	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Automatic Transmission Conditioner	8 15-Fl.-Oz. cans	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Oil Treatment	25 15-Fl.-Oz. cans	Lot 1, inside subject property building on shelf located in northwest portion of building.	Vehicle Maintenance/ Auto Repair	Unknown	N/A
Wipe & Shine Detailer	Approximately 2 5-gallon containers	Lot 1 inside subject property building, on shelf in northeast corner of building, on shelf in center of building in front of store.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.

Petroleum Product or Hazardous Substances	Quantity Stored & Container	Storage Location	Use	Disposal	Observations/ Evidence of release
Kleens All Purpose Cleaner	Approximately 3 55-gallon drums	Lot 1 inside subject property building, 2 containers located near center of northwest wall; 1 container located in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.
Yellow Foaming Polish	3 30-gallon containers	Lot 1 inside subject property building, located along northeast wall and in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.
Carolina Hi-Gloss	1 55-gallon drum	Lot 1, inside subject property building in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.
Bell Chemical Corp Glass Cleaner	1 30-gallon container	Lot 1, inside subject property building near southwest wall.	Vehicle Maintenance/ Auto Repair	Unknown	1 empty container observed.
Dirt Buster	2 55-gallon drums	Lot 1, inside subject property building in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.
Drip & Shine	1 55-gallon drum	Lot 1, inside subject property building in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.
Braker	1 30-gallon container	Lot 1, inside subject property building in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.
Winter Presoak	1 15-gallon container	Lot 1, inside subject property building in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.

Petroleum Product or Hazardous Substances	Quantity Stored & Container	Storage Location	Use	Disposal	Observations/ Evidence of release
Gasoline	1 5-gallon gas can	Lot 1, inside subject property building in northeast corner.	Vehicle Maintenance/ Auto Repair	Unknown	Improper storage - no secondary containment. Floor drains noted nearby.

Vehicle maintenance and repair products and chemicals were observed inside of the Lot 1 subject property building. Products used for vehicle repair, such as motor oil, were typically stored on shelves in sealed containers, whereas products intended for maintaining the exteriors of vehicles were typically stored in drums on the ground with no secondary containment. Minor staining was observed on the floor beneath the chemical storage containers. Floor drains were observed near the locations where these chemicals were stored.

6.4 OTHER SUBJECT PROPERTY OBSERVATIONS

The table below summarizes items that were observed and/or reported at the subject property during the site visit other than those items related to use, storage, and disposal of petroleum or hazardous materials (described in Section 6.3 above). If items were observed or reported, they are further described either in the table or below.

Description	Observed or Reported at Time of Site Visit	Observations/Comments
Potable Water Supply	N/A	
Nearest Drinking Water Source	No	
Sewage Disposal System	No	
Septic System	No	
Unidentified Storage Containers	Yes	Unlabeled storage containers or storage containers with obstructed view of labels were observed in various locations inside of the Lot 1 subject property building.
Wastewater Discharge	No	
Stormwater Discharge	No	
Odors	Yes	Lot 1 subject property building – autobody-related odors.
PCBs Associated with Electrical or Hydraulic Equipment	No	
Elevators (Traction or Hydraulic)	No	
Vehicle Maintenance Lifts	Yes	Lot 1 subject property building – electric-powered aboveground vehicle maintenance lift.
Emergency Generators	No	
Sprinkler System Pumps	No	

Description	Observed or Reported at Time of Site Visit	Observations/Comments
Heating System	Yes	Lot 1 subject property building - HVAC system located on roof.
Cooling System	Yes	Lot 1 subject property building - 4 active and 1 inactive gas-powered cooling systems.
Stains or Corrosion on Floors, Walls, or Ceilings	Yes	Lot 1 subject property building – minor staining observed on slab beneath drums stored without secondary containment.
Floor Drains	Yes	Lot 1 subject property building – floor drains observed along the southeast wing of the building.
Sumps	Yes	Lot 1 subject property building - sump observed in north corner of cellar.
Catch Basins	No	
Pits, Ponds, Lagoons, and Pools of Liquid	No	
Stained Soil or Pavement	Yes	
Stressed Vegetation	No	
Solid Waste and Evidence of Waste Filling	No	
Dry Wells	No	
Monitoring Wells	No	
Water Supply Wells	No	
Irrigation Wells	No	
Injection Wells	No	
Abandoned Wells	Yes	Lot 6 – abandoned well observed near center of southwest wall. Purge water stored in one 55-gallon drum was observed near the center of the southeast wall under scaffolding.

***Notes**:*

1. *N/A items are those that were not observed or reported and/or not anticipated to be present given the nature of the subject property (e.g., building features not present on an undeveloped property).*

6.5 ADJOINING PROPERTY OBSERVATIONS

Low-rising dwellings, stores, and garages were observed to the north. 1st Street, followed by a large building and parking lot operated by Con Ed were observed to the south. 4th Avenue, followed by high-rising apartment complexes and stores were observed to the east. Denton Place followed by a school and church were observed to the west. Construction was also noted northeast of Lot 32. Conditions at the adjoining properties likely do not have the potential to adversely impact the subject property.

6.6 USER RESPONSIBILITIES

The AAI Rule requires that the User of the report consider the following:

- Whether the user has specialized knowledge about previous ownership or uses of the subject property that may be material to identifying RECs;
- Whether the user has determined that the subject property's Title contains environmental liens or other information related to the environmental condition of the property, including

engineering and institutional controls and Activity and Use Limitations (AULs), as defined by ASTM;

- Whether the user is aware of commonly known or reasonably ascertainable information about the subject property including whether or not the presence of contamination is likely on the subject property and to what degree it can be detected; and
- Whether the user has prior knowledge that the price of the subject property has been reduced for environmentally related reasons.

While such information is not required to be provided by the environmental professional(s), the information can assist the environmental professional in identifying recognized environmental conditions. The "All Appropriate Inquiries" Final Rule (40 CFR Part 312) requires that these tasks be performed by or on behalf of a party seeking to qualify for an LLP to CERCLA liability.

Haley & Aldrich provided the user with a responsibilities questionnaire; however, a completed questionnaire was not received. The absence of such information is not considered significant to our conclusions.

7. Findings and Opinions

7.1 SIGNIFICANT DATA GAPS

Our ability to identify and evaluate RECs at the subject property is conditioned upon significant data gaps identified as part of this Phase I. The ASTM E1527-21 Standard defines a significant data gap as a data gap that affects the ability of the environmental professional to identify a REC.

No significant data gaps were identified during the performance of this Phase I. Thus, it is our opinion that sufficient information was obtained to identify subject property conditions indicative of releases or threatened releases of hazardous substances and petroleum hydrocarbons. Our opinion is limited by the conditions prevailing at the time our work is performed and the applicable regulatory requirements in effect.

We identified the following data gaps in association with this Phase I. The sources of information that were consulted to address the data gap and their significance relative to our ability to identify RECs are described below.

- Lack of access to Lot 32 – While access was not granted to the interior of the vacant building on Lot 32 Haley & Aldrich personnel viewed the structure from the exterior and viewed the remainder of the subject property's interior. Further, with the availability of the historic resources for the subject property including Lot 32 this data gap is not considered significant relative to our ability to identify RECs at the subject property.

7.2 RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a REC as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

Our opinion regarding a REC's potential impact on the subject property is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, our experience evaluating similar sites, and on our understanding of the client's intended use for the subject property.

The following RECs listed below were identified in connection with the subject property.

REC #1: Former use of the Subject Property and Upgradient Properties for Industrial, Manufacturing, and Auto-Related Purposes

The subject property was historically used for industrial, manufacturing, and auto-related purposes. According to historical records, Lot 1 was historically operated by the Fulton Smelting & Refining Works, Inc., a service station, auto repair facility, and auto detailing center. Lot 6 was used for residential purposes and a parking lot. Lot 32 was operated by a bottle storage facility and auto repair use and lot

34 was operated by an auto repair facility. The hydraulically upgradient property addressed 275 4th Avenue (Block 964, Lot 7505) was historically operated by a gasoline service station from the early 1970s to late 1980s and was listed in the Petroleum Bulk Storage (PBS) database for multiple gasoline underground and ASTs.

Manufacturing and auto-related facilities commonly utilize hazardous materials including petroleum products and chlorinated solvents. The historical use of the subject property and upgradient properties is considered a REC as potential or undocumented releases of petroleum products, solvents, and/or other hazardous materials may have adversely affected groundwater, soil, and/or soil vapor at the subject property.

REC #2: Documented Contamination in Soil, Groundwater, & Soil Vapor on Lot 34

A Remedial Investigation performed by RSK in December 2021 identified contamination in soil (including heavy metals and SVOCs), in groundwater (including heavy metals and SVOCs), and soil vapor (specifically petroleum-related compounds and chlorinated VOCs) beneath Lot 34, located on the eastern boundary of the subject property. The contamination in urban fill was widely distributed throughout the Lot 34 subject property to depths up to 12 feet bgs and is consistent with characteristics of urban fill found throughout the New York City area. Analytical results indicated elevated concentrations of metals and SVOCs in groundwater samples. Soil vapor analytical results identified petroleum-related VOCs and chlorinated VOCs in several samples. RSK concluded that soil vapor contamination beneath the subject property is likely associated from historic on-site operations, a former UST, and a former gasoline filling station located hydraulically upgradient of the subject property. According to available records, remedial action has not been implemented on the subject property; therefore, the documented contamination on Lot 34 is considered a REC.

REC #3: Documented Contamination in Soil, Groundwater, & Soil Vapor on Lot 6

A Remedial Investigation performed by RSK in July 2022 identified contamination in soil (including metals, SVOCs, and VOCs), in groundwater (including metals, SVOCs, and VOCs), and soil vapor (specifically petroleum-related compounds and chlorinated VOCs) beneath Lot 6, the northwest portion of the subject property. The contamination in urban fill was widely distributed throughout Lot 6 subject property to depths up to 8 feet bgs and is consistent with characteristics of urban fill found throughout the New York City area. Analytical results indicated elevated concentrations of metals and SVOCs in groundwater samples. Soil vapor analytical results identified petroleum-related VOCs and chlorinated VOCs in several samples. According to available records, remedial action has not been implemented on the subject property; therefore, the documented contamination is considered a REC.

REC #4: Former Gasoline Storage Tanks at the Subject Property

One gasoline storage tank on Lot 32 is indicated on Sanborn Fire Insurance Maps from 1926 to 1950. One gasoline storage tank on Lot 34 is indicated on Sanborn Fire Insurance Maps from 1926 to 2007. Four gasoline storage tanks on Lot 1 are indicated on Sanborn Fire Insurance Maps from 1951 to 1965. There are no records of the installation or removal of these tanks with the NYSDEC. A geophysical survey performed by RSK in December 2021 on Lot 34 detected a metallic anomaly in the northeastern side of the building measuring 6 feet by 4 feet. RSK was not ablet to identify any other discernable features in this area. Without proper documentation, it is unknown if these tanks were underground, the close-out status of the tanks or if residual contamination remains in the former tank areas. Due to the dates of

installation and duration of usage at the subject property, the former storage tanks are considered a REC.

7.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a CREC as a recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

CRECs were not identified in connection with the subject property.

7.4 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines an HREC as "a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. A historical recognized environmental condition is not a recognized environmental condition.

HRECs were not identified in connection with the subject property.

7.5 DE MINIMIS CONDITIONS

The ASTM E1527-21 Standard defines a *de minimis* condition as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. The ASTM E1527-21 Standard notes that conditions determined to be *de minimis* are not recognized environmental conditions.

The following *de minimis* condition listed below was identified in connection with the subject property.

***De minimis* Condition #1:** Improper Storage of Petroleum Products and Minor Staining

Vehicle maintenance and repair products and chemicals were observed inside of the Lot 1 subject property building. Products used for vehicle repair, such as motor oil, were typically stored on shelves in sealed containers, whereas products intended for maintaining the exteriors of vehicles were typically stored in drums on the ground with no secondary containment. Minor staining was observed on the slab beneath the chemical storage containers and floor drains were observed near the locations where these products and chemicals were stored.

7.6 OTHER FINDINGS

ASTM does not define the term "other finding"; however, Haley & Aldrich utilizes the category to indicate conditions of potential risk that are not clearly defined in the ASTM standard. While not considered RECs, Haley & Aldrich identified the following other findings:

Other Finding #1: New York City E-Designation

The subject property was identified in the as an E-Designation site by the NYCOER. The subject property was assigned E-601 – Gowanus Neighborhood Plan Rezoning Action as a result of a CEQR effective 23 November 2021 (CEQR #19DCP157K). The requirements under the E-Designation program are satisfaction of the requirements for hazardous materials, noise (window wall attenuation and alternative means of ventilation), and air quality (HVAC limited to natural gas and exhaust stack location limitations) with the NYCOER. The air quality component for this E-Designation for new developers is the exclusive use of natural gas for heating with the stack location at the highest tier (at least 158 feet above grade). The noise requirement states future residential/commercial must provide a closed-window condition with a minimum of 31 dBA window/wall attenuation on all façades in order to maintain an interior noise level not greater than 45 dBA for residential and community facility uses or not greater than 50 dBA for commercial office spaces. To maintain a closed-window condition, an alternate means of ventilation must also be provided. Alternate means of ventilation includes, but is not limited to, air conditioning.

8. Conclusions

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of the ASTM Practice E 1527 of 296 4th Avenue, the subject property. Any exceptions to or deletions from, this practice are described in Section 1.4 of this report.

This assessment has revealed evidence of four RECs in connection with the subject property.

9. Environmental Professional Certification

The undersigned declare the following:

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in §312.10 of 40 CFR Part 312; and

We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Zachary Simmel
Senior Engineer



Mari Cate Conlon, P.G.
Senior Project Manager

10. Credentials

This Phase I report was prepared by Zachary Simmel, under the direct supervision of Mari Cate Conlon, who served as the Environmental Professional(s) for this project. Qualification information for the project personnel is provided below.

Zachary Simmel is a Senior Engineer at Haley & Aldrich with strong environmental background and 5 years of experience in soil and groundwater investigation, and experience conducting environmental investigations, including Phase I Environmental Site Assessments.

Mari Cate Conlon is a Senior Project Manager at Haley & Aldrich and a licensed Professional Geologist in the state of New York with more than seven years of experience conducting Phase I and Phase II Environmental Site Assessments.

11. Glossary and Other Descriptions

11.1 GLOSSARY

All Appropriate Inquiry (AAI) — that inquiry constituting "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined in CERCLA, 42 U.S.C. §9601(35)(B), that will qualify a party to a commercial real estate transaction for one of threshold criteria for satisfying the LLPs to CERCLA liability (42 U.S.C. §9601(35)(A) & (B), §9607(b)(3), §9607(q); and §9607(r)), assuming compliance with other elements of the defense.

Business Environmental Risk — a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice. Consideration of business environmental risk issues may involve addressing one or more non-scope considerations.

Controlled Recognized Environmental Condition (CREC) — as a recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

Significant Data Gap — a data gap that affects the ability of the environmental professional to identify a recognized environmental condition.

De Minimis Conditions — a condition related to a release that generally does not present those conditions which "do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies." The ASTM E1527-21 Standard notes that conditions determined to be de minimis are not recognized environmental conditions.

Environmental Professional — a person meeting the education, training, and experience requirements as set forth in 40 CFR §312.10(b).

Historical Recognized Environmental Condition (HREC) — a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. A historical recognized environmental condition is not a recognized environmental condition.

Key Site Manager — the person identified by the owner or operator of a subject property as having good knowledge of the uses and physical characteristics of the subject property.

Material Threat —an obvious threat which is likely to lead to a release and that, in the opinion of the environmental professional, would likely result in impact to public health or the environment.

Orphan Site — (not ASTM E1527-21 definition) — sites that could not be mapped due to poor or inadequate address information.

Recognized Environmental Condition (REC) — (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. *De minimis* conditions are not RECs.

11.2 DESCRIPTIONS OF DATABASES SEARCHED

Numerous regulatory databases were searched during this Phase I. Each database reviewed is described in the database report presented in Appendix D. Those databases required by the ASTM E1527-13 and E1527-21 Standards are identified below.

1. **NPL Sites:** The National Priorities List (NPL) is a list of contaminated sites that are considered the highest priority for cleanup by the U.S. Environmental Protection Agency (USEPA).
2. **Delisted NPL Sites:** The Delisted National Priorities List (NPL) is a list of formal NPL sites formerly considered the highest priority for cleanup by the USEPA that met the criteria of the National Oil and Hazardous Substances Pollution Contingency Plan (NCP) for deletion from the NPL because a no further response was appropriate.
3. **CERCLIS Sites:** The Comprehensive Environmental Response, Compensation, and Liability Act Information System (CERCLIS) list identifies sites which are suspected to have contamination and require additional investigation to assess whether they should be considered for inclusion on the NPL.
4. **CERCLIS-NFRAP Sites:** CERCLIS-NFRAP status indicates that a site was once on the CERCLIS List but has No Further Response Actions Planned (NFRAP). Sites on the CERCLIS-NFRAP List were removed from the CERCLIS List in February 1995 because, after an initial investigation was performed, no contamination was found, contamination was removed quickly, or the contamination was not significant enough to warrant NPL status.
5. **Federal ERNS:** The Federal Emergency Response Notification System (ERNS) list tracks information on reported releases of oil and hazardous materials.
6. **RCRA non-CORRACTS TSD facilities:** The Resource Conservation and Recovery Act (RCRA) non-CORRACTS TSD Facilities List tracks facilities which treat, store, or dispose of hazardous waste and are not associated with corrective action activity.
7. **RCRA CORRACTS TSD facilities:** The RCRA CORRACTS TSD Facilities list catalogues facilities that treat, store, or dispose of hazardous waste and have been associated with corrective action activity.
8. **RCRA Generators:** The RCRA Generator list is maintained by the USEPA to track facilities that generate hazardous waste.
9. **Federal Institutional Controls/Engineering Controls:** The Federal Institutional Control list and Engineering Control list are maintained by the USEPA. Some Institutional Control and Engineering Control information may not be made publicly available and therefore will not be included on this registry.

10. **State and Tribal Equivalent NPL/CERCLIS Sites:** The (ASTM E1527-13 and E1527-21 Standards) requires searching "State and Tribal Equivalent NPL Sites." In New York, the equivalent NPL is the Inactive Hazardous Waste Disposal Sites, which is maintained by the NYSDEC.
11. **State and Tribal Registered Storage Tanks:** The NYSDEC maintains a list of aboveground and underground storage tanks registered with the NYSDEC Petroleum Bulk Storage program.
12. **State and Tribal Landfills and Solid Waste Disposal Sites:** The NYSDEC maintains a list of regulated waste disposal sites.
13. **State and Tribal Leaking Storage Tanks:** The NYSDEC maintains a list of Leaking Storage Tanks (LUST/LAST). The LUST/LAST lists are a listing of release sites that have an Underground or Aboveground Storage Tank listed as the source.
14. **State and Tribal Institutional Controls/Engineering Controls:** The NYSDEC maintains a list of sites with Institutional controls or Engineering controls in place.
15. **State and Tribal Voluntary Cleanup Sites:** The NYSDEC maintains a list of Voluntary Cleanup sites.
16. **State and Tribal Brownfield Sites:** The NYSDEC maintains a list of Brownfield sites which includes properties where redevelopment or re-use may be compromised by the presence or presumed presence of hazardous materials or petroleum.

12. References

1. Aerial Photographs dated 1924, 1943, 1951, 1954, 1961, 1966, 1971, 1974, 1980, 1984, 1994, 2006, 2009, 2013, 2017.

2. City Directories dated 1928, 1934, 1940, 1945, 1949, 1960, 1965, 1970, 1973, 1976, 1980, 1985, 1992, 1994, 1997, 1999, 2000, 2004, 2005, 2009, 2015, 2017.

3. EDR Inquiry No. 07124126.2r, Database Report, dated 20 September 2022.

4. Gus Monogioudis of Golden Touch Car Care Center, interview with Haley & Aldrich, 29 September 2022.

5. Haley & Aldrich of New York, site visit conducted by Elizabeth Scheuerman and Nicole Mooney on 29 September 2022.

6. Phase I Environmental Site Assessment Report, 12 April 2022, Singer Environmental Group, LTD.

7. Phase I Environmental Site Assessment Report, March 2022, RSK Environmental Group, LLC.

8. Remedial Action Work Plan, July 2022, RSK Environmental Group, LLC.

9. Remedial Investigation Report, July 2022, RSK Environmental Group, LLC.

10. Remedial Investigation Report, March 2022, RSK Environmental Group, LLC.

11. Sanborn Fire Maps dated 1886, 1888, 1904, 1906, 1915, 1921, 1922, 1926, 1928, 1938, 1950, 1951, 1965, 1969, 1977, 1978, 1979, 1980, 1981, 1982, 1985, 1986, 1987, 1988, 1991, 1992, 1993, 1994, 1995, 1996, 2001, 2022, 2003, 2004, 2005, 2006, 2007.

12. Topographic Map, Brooklyn, United States Geological Survey 7.5-minute series, 2019.

13. Topographic Maps dated 1897, 1898, 1900, 1947, 1955, 1967, 1979, 1995, 2014, 2016, 2019.

FIGURES





MAP SOURCE: USGS
SITE COORDINATES: 40°40'32"N, 73°59'5"W

HALEY ALDRICH

296 4TH AVENUE
BROOKLYN, NEW YORK

PROJECT LOCUS

APPROXIMATE SCALE: 1 IN = 2000 FT
SEPTEMBER 2022

FIGURE 1

GIS FILE PATH: \\haleyaldrich.com\share\CF\Groups\nyc\GIS\Maps\2022_09_206616206616_000_0001_PROJECT_LOCUS.mxd — USER: hwachholz — LAST SAVED: 9/22/2022 12:07:43 PM



LEGEND

PARCEL BOUNDARY

SITE BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.

2. ASSESSOR PARCEL DATA SOURCE: NYC DEPARTMENT OF CITY PLANNING

3. AERIAL IMAGERY SOURCE: NEARMAP, 19 JULY 2022

N

0 30 60

SCALE IN FEET

HALEY ALDRICH

296 4TH AVENUE
BROOKLYN, NEW YORK

SITE PLAN

SEPTEMBER 2022

FIGURE 2

GIS FILE PATH: \\haleyaldrich.com\share\CF\Groups\nyc\GIS\Maps\2022_09_206616\206616_000_0002_SITE_PLAN.mxd — USER: hwachholz — LAST SAVED: 9/22/2022 2:43:49 PM

APPENDIX A
Limitations

APPENDIX A

Haley & Aldrich of New York Limitations

Environmental site assessment (Phase I Environmental Site Assessment) reports prepared by Haley & Aldrich are for the sole and exclusive use of its Client. Haley & Aldrich represents that the Phase I Environmental Site Assessment was prepared in accordance with the ASTM International (ASTM) Standards E1527-13 and E1527-21 entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (ASTM E1527-13 and E1527-21). The findings, opinions, conclusions, and information contained in the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment are limited to, and solely based upon, information reasonably ascertainable by Haley & Aldrich at the time the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment was completed.

All users of this ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment are bound to the terms and conditions and limitations contained in the accompanying Proposal, Terms and Conditions, and Limitations for this ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment. The findings, opinions, conclusions, and information contained in this report are based solely on the Scope of Services provided pursuant to the Proposal and its attachments and the information reasonably ascertainable by Haley & Aldrich at the time the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment was completed. Haley & Aldrich has not performed any additional observations, investigations, studies, or other testing not specified in the Scope of Services. Haley & Aldrich shall not be liable for the existence of any condition the discovery of which would have required the performance of services not authorized under the Scope of Services.

This ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment is prepared for the exclusive use of Haley & Aldrich's client in connection with the subject property for the purpose of assessing the potential or existing environmental contamination liabilities associated with the subject property. There are no intended beneficiaries other than Haley & Aldrich's client. Haley & Aldrich shall owe no duty whatsoever to any other person or entity by issuing the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment. Use of this ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment by any person or entity, including by Haley & Aldrich's client, for a purpose other than for the purpose of assessing the potential or existing environmental contamination liabilities associated with the subject property is expressly prohibited unless such person or entity obtains written authorization from Haley & Aldrich indicating that the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment is adequate for such other use. Use of this ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment by any person or entity for such other purpose without written authorization by Haley & Aldrich shall be at such person's or entity's sole risk and shall be without legal exposure or liability to Haley & Aldrich.

Haley & Aldrich may authorize third-party reliance on the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment by providing reliance letters to third party(ies) provided that the third party(ies) agree: (1) to use the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment only for the purpose of assessing the potential or existing environmental contamination liabilities associated with real property; (2) to be bound by the terms and conditions and limitations contained in the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment report and the proposal and its Attachments, Terms and Conditions, and Limitations; (3) to accept the form and substance of Haley & Aldrich's reliance letter; and (4) to deliver to Haley & Aldrich a signed copy of a reliance letter by an

authorized representative of the relying party, within thirty (30) days after said reliance letter is provided to the relying party, signifying the relying party's acceptance of the aforementioned conditions. Upon Haley & Aldrich's receipt of the signed reliance letter by the relying party(ies), the relying party(ies) will be authorized to rely on Haley & Aldrich's ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment for the limited purpose of identifying potential or existing environmental contamination liabilities associated with the subject property. The relying party(ies) agree(s) to bind each of its respective successors and assigns to the aforementioned Terms and Conditions.

This ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment reflects subject property conditions observed and described by records available to Haley & Aldrich as of the date of ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment preparation. The passage of time may result in significant changes in subject property conditions, technology, or economic conditions, which could alter the findings and/or recommendations of the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment. Accordingly, Haley & Aldrich's client and any other party to whom the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment is provided recognize and agree that Haley & Aldrich shall bear no liability for deviations from observed conditions or available records after the time of ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment preparation. Haley & Aldrich makes no express or implied representation that the information contained in the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment has continued viability after 180 days of the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment's completion date, and any use or reliance on the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment after 180 days of the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment's completion date by Haley & Aldrich's client or any other authorized person or entity will be at that party's sole risk and without liability to Haley & Aldrich.

Notwithstanding anything contained herein, Haley & Aldrich shall not be liable for any claim or damage arising from environmental contamination liabilities that occurred on the subject property after the effective date of the ASTM E1527-13 and E1527-21 Phase I Environmental Site Assessment. Likewise, Haley & Aldrich shall not be liable for any existing or future property owner's failure to satisfy any continuing obligation for CERCLA liability protection or under the Federal Environmental Protection Agency's All Appropriate Inquiries rule..

APPENDIX B
Previous Reports

APPENDIX C
Historical Research Documentation

296 4th Avenue

296 4th Avenue

Brooklyn, NY 11215

Inquiry Number: 7124126.3

September 21, 2022

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

09/21/22

Site Name:

296 4th Avenue
296 4th Avenue
Brooklyn, NY 11215
EDR Inquiry # 7124126.3

Client Name:

Haley & Aldrich, Inc.
299 Cherry Hill Road
Parsippany, NJ 07054
Contact: Sarah Commisso

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Haley & Aldrich, Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 2334-4FD6-9353

PO # 0206616

Project 296 4th Avenue

Maps Provided:

2007	1995	1985	1965
2006	1994	1982	1951
2005	1993	1981	1950
2004	1992	1980	1938
2003	1991	1979	1928
2002	1988	1978	1926
2001	1987	1977	1922
1996	1986	1969	1921

1915	
1906	
1904	
1888	
1886	

Sanborn® Library search results
Certification #: 2334-4FD6-9353

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Haley & Aldrich, Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets



Volume 6, Sheet 25
2007

Volume 6, Sheet 26
2007

2006 Source Sheets

Volume 6, Sheet 26
2006



Volume 6, Sheet 25
2006

2005 Source Sheets



Volume 6, Sheet 25
2005

Volume 6, Sheet 26
2005

2004 Source Sheets



Volume 6, Sheet 25
2004

Volume 6, Sheet 26
2004

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets



Volume 6, Sheet 25
2003

Volume 6, Sheet 26
2003

2002 Source Sheets



Volume 6, Sheet 25
2002

Volume 6, Sheet 26
2002

2001 Source Sheets



Volume 6, Sheet 25
2001

Volume 6, Sheet 26
2001

1995 Source Sheets

Volume 5, Sheet 26
1995-Jan

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1995 Source Sheets



Volume 6, Sheet 25
1995

Volume 6, Sheet 26
1995

1994 Source Sheets



Volume 6, Sheet 25
1994

1993 Source Sheets



Volume 6, Sheet 25
1993

Volume 6, Sheet 26
1993

1992 Source Sheets



Volume 6, Sheet 25
1992

Volume 6, Sheet 26
1992

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1991 Source Sheets



Volume 6, Sheet 25
1991

Volume 6, Sheet 26
1991

1988 Source Sheets



Volume 6, Sheet 25
1988

Volume 6, Sheet 26
1988

1987 Source Sheets



Volume 6, Sheet 25
1987

Volume 6, Sheet 26
1987

1985 Source Sheets



Volume 6, Sheet 25
1985



Volume 6, Sheet 26
1985

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1982 Source Sheets



Volume 6, Sheet 25
1982

Volume 6, Sheet 26
1982

1980 Source Sheets



Volume 6, Sheet 25
1980



Volume 6, Sheet 26
1980



Volume 6, Sheet 25
1980

Volume 6, Sheet 26
1980

1979 Source Sheets



Volume 6, Sheet 25
1979

Volume 6, Sheet 26
1979

1978 Source Sheets

Volume 6, Sheet 26
1978



Volume 6, Sheet 25
1978

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1965 Source Sheets



Volume 6, Sheet 25
1965



Volume 6, Sheet 26
1965

1951 Source Sheets



Volume 6, Sheet 25
1951

Volume 6, Sheet 26
1951

1926 Source Sheets



Volume 6, Sheet 25
1926



Volume 6, Sheet 26
1926

1922 Source Sheets



Volume Pier Maps, Sheet 41
1922

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1921 Source Sheets



Volume Atlas Maps, Sheet b-12
1921

1906 Source Sheets



Volume 6, Sheet 38
1906



Volume 6, Sheet 39
1906

1888 Source Sheets

Volume 6, Sheet 137
1888



Volume 6, Sheet 138
1888



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 25
Volume 6, Sheet 26

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 26
Volume 6, Sheet 25

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 26
Volume 6, Sheet 25

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25
Volume 5, Sheet 26

0 Feet 150 300 600

N



©1994 Sanborn Co., EDR Sanborn, Inc.

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	1994



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 26
Volume 6, Sheet 25

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 26
Volume 6, Sheet 25

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 26
Volume 6, Sheet 25

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





N

Certified Sanborn® Map

1985



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1985

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 26
Volume 6, Sheet 25

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1981

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25
Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 25
Volume 6, Sheet 26

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1969

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1938

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	1928

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #:	2334-4FD6-9353
Copyright	1926

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 26
Volume 6, Sheet 25

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1922

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume Pier Maps, Sheet 41

0 Feet 150 300 600

N

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright 1921



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume Atlas Maps, Sheet b-12

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	1915

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	1906

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6, Sheet 39
Volume 6, Sheet 38

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright 1904

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name:	296 4th Avenue
Address:	296 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11215
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	7124126.3
Order Date:	09/21/2022
Certification #	2334-4FD6-9353
Copyright	1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 6, Sheet 138
Volume 6, Sheet 137

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2334-4FD6-9353

Site Name: 296 4th Avenue
Address: 296 4th Avenue
City, ST, ZIP: Brooklyn, NY 11215
Client: Haley & Aldrich, Inc.
EDR Inquiry: 7124126.3
Order Date: 09/21/2022
Certification #: 2334-4FD6-9353
Copyright: 1886

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

N

296 4th Avenue

296 4th Avenue

Brooklyn, NY 11215

Inquiry Number: 7124126.8

September 22, 2022

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

09/22/22

Site Name:

296 4th Avenue
296 4th Avenue
Brooklyn, NY 11215
EDR Inquiry # 7124126.8

Client Name:

Haley & Aldrich, Inc.
299 Cherry Hill Road
Parsippany, NJ 07054
Contact: Sarah Commisso

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2013	1"=500'	Flight Year: 2013	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 04, 1994	USGS/DOQQ
1984	1"=500'	Flight Date: March 26, 1984	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1974	1"=500'	Flight Date: October 19, 1974	NOAA
1971	1"=500'	Flight Date: April 15, 1971	NOAA
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: April 12, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 18, 1954	USGS
1951	1"=500'	Flight Date: April 07, 1951	EDR Proprietary Aerial Viewpoint
1943	1"=500'	Flight Date: December 23, 1943	USC&GS
1924	1"=500'	Flight Date: July 01, 1924	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 7124126.8

YEAR: 2017

= 500'

N

EDR


INQUIRY #: 7124126.8
YEAR: 2013
= 500'
N
EDR



INQUIRY #: 7124126.8

YEAR: 2009

= 500'

N

EDR



INQUIRY #: 7124126.8

YEAR: 2006

= 500'

N

EDR



INQUIRY #: 7124126.8

YEAR: 1994

= 500'

N

EDR


INQUIRY #: 7124126.8
YEAR: 1984
= 500'
N
EDR

INQUIRY #: 7124126.8

YEAR: 1980

= 500'

N

EDR

INQUIRY #: 7124126.8
YEAR: 1974
= 500'
N
EDR

INQUIRY #: 7124126.8
YEAR: 1971
= 500'
N
EDR

INQUIRY #: 7124126.8

YEAR: 1966

= 500'

N

EDR

INQUIRY #: 7124126.8

YEAR: 1961

= 500'

N

EDR

INQUIRY #: 7124126.8

YEAR: 1954

= 500'

N

EDR

INQUIRY #: 7124126.8

YEAR: 1951

= 500'

N

EDR

INQUIRY #: 7124126.8

YEAR: 1943

= 500'

N

EDR

INQUIRY #: 7124126.8

YEAR: 1924

= 500'

N

EDR

296 4th Avenue

296 4th Avenue

Brooklyn, NY 11215

Inquiry Number: 7124126.4

September 20, 2022

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

09/20/22

Site Name:

296 4th Avenue
296 4th Avenue
Brooklyn, NY 11215
EDR Inquiry # 7124126.4

Client Name:

Haley & Aldrich, Inc.
299 Cherry Hill Road
Parsippany, NJ 07054
Contact: Sarah Commisso

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Haley & Aldrich, Inc. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 0206616
Project: 296 4th Avenue

Coordinates:

Latitude:	40.675577 40° 40' 32" North
Longitude:	-73.985041 -73° 59' 6" West
UTM Zone:	Zone 18 North
UTM X Meters:	585777.46
UTM Y Meters:	4503239.26
Elevation:	23.00' above sea level

Maps Provided:

2019	1900
2016	1898
2014, 2013	1897
1995	
1979, 1981	
1967	
1955, 1956	
1947	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Brooklyn
2019
7.5-minute, 24000

Jersey City
2019
7.5-minute, 24000

2016 Source Sheets



Brooklyn
2016
7.5-minute, 24000

Jersey City
2016
7.5-minute, 24000

2014, 2013 Source Sheets

Jersey City
2014
7.5-minute, 24000



Brooklyn
2013
7.5-minute, 24000

1995 Source Sheets

Brooklyn
1995
7.5-minute, 24000
Aerial Photo Revised 1977

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979, 1981 Source Sheets



Brooklyn
1979
7.5-minute, 24000
Aerial Photo Revised 1977

Jersey City
1981
7.5-minute, 24000
Aerial Photo Revised 1976

1967 Source Sheets

Brooklyn
1967
7.5-minute, 24000
Aerial Photo Revised 1966

Jersey City
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1955, 1956 Source Sheets

Jersey City
1955
7.5-minute, 24000
Aerial Photo Revised 1954



Brooklyn
1956
7.5-minute, 24000

1947 Source Sheets

Brooklyn
1947
7.5-minute, 24000
Aerial Photo Revised 1940

Jersey City
1947
7.5-minute, 24000
Aerial Photo Revised 1940

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets

Brooklyn
1900
15-minute, 62500

Staten Island
1900
15-minute, 62500

1898 Source Sheets

Brooklyn
1898
15-minute, 62500

Staten Island
1898
15-minute, 62500

1897 Source Sheets

Brooklyn
1897
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2019, 7.5-minute
W, Jersey City, 2019, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2016, 7.5-minute
W, Jersey City, 2016, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N

Historical Topo Map

2014, 2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2013, 7.5-minute
W, Jersey City, 2014, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1995, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1979, 7.5-minute
W, Jersey City, 1981, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1967, 7.5-minute
W, Jersey City, 1967, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N

Historical Topo Map

1955, 1956



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1956, 7.5-minute
W, Jersey City, 1955, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1947, 7.5-minute
W, Jersey City, 1947, 7.5-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1900, 15-minute
SW, Staten Island, 1900, 15-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1898, 15-minute
SW, Staten Island, 1898, 15-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1897, 15-minute

SITE NAME: 296 4th Avenue
ADDRESS: 296 4th Avenue
Brooklyn, NY 11215
CLIENT: Haley & Aldrich, Inc.

N

296 4th Avenue
296 4th Avenue
Brooklyn, NY 11215

Inquiry Number: 7124126.5
September 21, 2022

The EDR-City Directory Abstract

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2017. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2017	Cole Information Services	X	X	X	-
2014	Cole Information Services	X	X	X	-
2009	Cole Information Services	X	X	X	-
2005	Hill-Donnelly Corporation	-	X	X	-
	Hill-Donnelly Corporation	X	X	X	-
2004	Cole Information Services	X	X	X	-
2000	Cole Information Services	-	X	X	-
1999	Cole Information Services	X	X	X	-
1997	NYNEX	-	X	X	-
	NYNEX	X	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1994	Cole Information Services	X	X	X	-
1992	NYNEX Informantion Resource Co.	-	X	X	-
	NYNEX Informantion Resource Co.	X	X	X	-
1985	NYNEX Information Resources Company	-	X	X	-
	NYNEX Information Resources Company	X	X	X	-
1980	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1976	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1973	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1970	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1965	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1960	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1945	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1940	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1928	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
27 Denton Place	Client Entered	
21 Denton Place	Client Entered	
290 4th Avenue	Client Entered	X
284 4th Avenue	Client Entered	X

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

296 4th Avenue
Brooklyn, NY 11215

FINDINGS DETAIL

Target Property research detail.

4TH AVE

284 4TH AVE

Year	*Uses*	*Source*
2017	4 AVENUE BURNER & HEATING	Cole Information Services
2014	4 AVENUE BURNER & HEATING	Cole Information Services
	BENJAMIN KEENE	Cole Information Services
2009	4TH AVE BURNER & HEATING SUPS	Cole Information Services
	BENJAMIN KEENE	Cole Information Services
2005	4 Avenue Burner & Heating Supl	Hill-Donnelly Corporation
2004	4TH AVE BURNER	Cole Information Services
	4TH AVENUE BURNER & HTR SPLY	Cole Information Services
	KARA JANECZKO	Cole Information Services
	M RAYMOND	Cole Information Services
1999	4 AVENUE BURNER & HEATING SUPPLIES INCORPORATED	Cole Information Services
1997	SEEHUSEN Richard	NYNEX
1994	4 AVENUE BURNER & HEATING SUPPLIES INC	Cole Information Services
	SEEHAUSEN, RICHARD	Cole Information Services
1992	4 AVENUE BURNER & HEATING SUPPLIES INC	NYNEX Informantion Resource Co.
	SEEHAUSEN RICHARD	NYNEX Informantion Resource Co.
1985	4 AVENUE BURNER & HEATING SUPPLIES INC	NYNEX Information Resources Company
1976	UNION BURNER SUPLS	New York Telephone
1973	Union Burner Supls	New York Telephone
1970	Square Fuel Corp	New York Telephone
	Union Burner Supls	New York Telephone
1965	Square Fuel Corp	New York Telephone

FINDINGS

Year	Uses	Source
1965	Union Burner Supls	New York Telephone
1960	BURMAR CHEMCL CORP	New York Telephone
	BURTON MARINE CORP	New York Telephone
	BURMAR CHEMCL CORP	New York Telephone Company
	BURTON MARINE CORP	New York Telephone Company
1949	Cody Mfg Co	New York Telephone Company

290 4TH AVE

Year	Uses	Source
2009	AUTOBODY & PAINTING BY PRIDE	Cole Information Services
	GRAFAM INC	Cole Information Services
	GREAT BEAR AUTO CENTER	Cole Information Services
2005	Great Bear Auto Ctr	Hill-Donnelly Corporation
2004	JERRY GRAY	Cole Information Services
1999	GREAT BEAR AUTO CENTER	Cole Information Services
1997	Great Bear Auto Center	NYNEX
1994	GREAT BEAR AUTO CENTER	Cole Information Services
1992	GREAT BEAR AUTO CENTER	NYNEX Informantion Resource Co.
1985	GREAT BEAR	NYNEX Information Resources Company
	TIRE WORLD DISCOUNT CENTER	NYNEX Information Resources Company
1976	GREAT BEAR AUTO CENTERS	New York Telephone
1973	A & S Auto Supply Co	New York Telephone
	Gowanus Auto Glass	New York Telephone
1970	Chaley Nat Doors Inc	New York Telephone
1965	Sabre Parts Distribtrs Inc	New York Telephone
1960	UNION AUTOMTV PARTS INC	New York Telephone
	UNION AUTOMTV PARTS INC	New York Telephone Company
1949	Automotive Maintenance Co	New York Telephone Company
1945	Automotive Maintenance Co	New York Telephone
1928	MATCOVICH PHILIP IRON WKS	New York Telephone

296 4TH AVE

Year	Uses	Source
2017	GOLDEN TOUCH CAR WASH	Cole Information Services

FINDINGS

Year	Uses	Source
2017	WALKIN COOLERS REPAIR NYC	Cole Information Services
2014	GOLDEN TOUCH CAR WASH	Cole Information Services
	LEE MYLES TRANSMISSIONS & AUTOCARE	Cole Information Services
2009	GOLDEN TOUCH CAR WASH INC	Cole Information Services
2005	1ST ST	Hill-Donnelly Corporation
	Golden Touch Car Wash Inc	Hill-Donnelly Corporation
	Lee Myles Transmissions	Hill-Donnelly Corporation
2004	FARRAJ HAMDOU	Cole Information Services
1999	MAACO AUTO PAINTING & BODYWORKS	Cole Information Services
1997	MAACO AUTO PAINTING & BODYWORKS	NYNEX
1994	MAACO AUTO PAINTING & BODYWORKS	Cole Information Services
1992	MAACO AUTO PAINTING & BODYWORKS	NYNEX Informantion Resource Co.
1985	AAMCO AUTOMATIC TRANSMISSIONS	NYNEX Information Resources Company
1980	AAMCO AUTOMATIC TRANSMISSIONS	New York Telephone
	SCHEIA EARL AUTO PAINT SHOPS BX	New York Telephone
1970	Earl Scheib Auto Paint Shops	New York Telephone
	Scheib Earl Auto Paint Shops	New York Telephone
1960	BILL S TYDOL SVCE STA	New York Telephone
	Bills Tydol Svce Sta	New York Telephone Company
1949	Bills Tydol Svce Sta	New York Telephone Company
1945	Bills Tydol Svce Sta	New York Telephone
1940	Lamberts Svce Sta	New York Telephone
1934	FULTON SMELTING & REFINING WORKS INC ADOLPH KELLER PRES-TREAS EUG ARON V-PR	R. L. Polk & Co.
	KELLER ADOLPH PRES-TREAS FULTON SMELTING & REFINING WORKS INC	R. L. Polk & Co.
1928	KELLER A RUBBERS METALS	New York Telephone

4th Avenue

284 4th Avenue

Year	Uses	Source
2005	4 Avenue Burner & Heating Supl	Hill-Donnelly Corporation
1997	SEEHUSEN Richard	NYNEX

FINDINGS

Year	Uses	Source
1992	4 AVENUE BURNER & HEATING SUPPLIES INC	NYNEX Informantion Resource Co.
	SEEHAUSEN RICHARD	NYNEX Informantion Resource Co.
1985	4 AVENUE BURNER & HEATING SUPPLIES INC	NYNEX Information Resources Company
1976	UNION BURNER SUPLS	New York Telephone
1973	Union Burner Supls	New York Telephone
1970	Square Fuel Corp	New York Telephone
	Union Burner Supls	New York Telephone
1965	Square Fuel Corp	New York Telephone
	Union Burner Supls	New York Telephone
1960	BURMAR CHEMCL CORP	New York Telephone
	BURTON MARINE CORP	New York Telephone
	BURMAR CHEMCL CORP	New York Telephone Company
	BURTON MARINE CORP	New York Telephone Company
1949	Cody Mfg Co	New York Telephone Company

290 4th Avenue

Year	Uses	Source
2005	Great Bear Auto Ctr	Hill-Donnelly Corporation
1997	Great Bear Auto Center	NYNEX
1992	GREAT BEAR AUTO CENTER	NYNEX Informantion Resource Co.
1985	GREAT BEAR	NYNEX Information Resources Company
	TIRE WORLD DISCOUNT CENTER	NYNEX Information Resources Company
1976	GREAT BEAR AUTO CENTERS	New York Telephone
1973	A & S Auto Supply Co	New York Telephone
	Gowanus Auto Glass	New York Telephone
1970	Chaley Nat Doors Inc	New York Telephone
1965	Sabre Parts Distribtrs Inc	New York Telephone
1960	UNION AUTOMTV PARTS INC	New York Telephone
	UNION AUTOMTV PARTS INC	New York Telephone Company
1949	Automotive Maintenance Co	New York Telephone Company
1945	Automotive Maintenance Co	New York Telephone
1928	MATCOVICH PHILIP IRON WKS	New York Telephone

FINDINGS

Denton Place

21 Denton Place

Year	*Uses*	*Source*

27 Denton Place

Year	*Uses*	*Source*

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

1 HUBARD St

247 1 HUBARD St

Year	Uses	Source
1965	Alborano J R	New York Telephone

1 KNAP St

225 1 KNAP St

Year	Uses	Source
1965	Robbins Monroe	New York Telephone

1 KNAPP

225 1 KNAPP

Year	Uses	Source
1997	RESNICK Richard	NYNEX

1 KNAPP St

225 1 KNAPP St

Year	Uses	Source
1965	Berelson Irving A	New York Telephone

1 KNGS st

225 1 KNGS st

Year	Uses	Source
1970	Lichtenstein Fannie Mrs	New York Telephone

1ST FL

233 1ST FL

Year	Uses	Source
1934	GLOBE CRAYON CO	R. L. Polk & Co.

FINDINGS

253 1ST FL

Year	Uses	Source
1934	LOGAN GEAR CO HARRY C FRANK MGR	R. L. Polk & Co.
	BAIER MARY E DRSMKR	R. L. Polk & Co.
	HALFAST RUBBER CO THE HARRY C FRANK NY REP MFRS RUBBER GDS	R. L. Polk & Co.

257 1ST FL

Year	Uses	Source
1934	FELZMANN BERTHA R	R. L. Polk & Co.
	FELZMANN IRWIN PLATEMN R	R. L. Polk & Co.
	FELZMANN WM R MACH H	R. L. Polk & Co.
	FELZMANN WM R JR CLK R	R. L. Polk & Co.

1ST LA LINDN HOUSES

238 1ST LA LINDN HOUSES

Year	Uses	Source
1949	Simmons Scymour	New York Telephone Company

1ST PL

224 1ST PL

Year	Uses	Source
1970	Lubrano Louis	New York Telephone

1ST ST

222 1ST ST

Year	Uses	Source
2009	CONSOLIDATED EDISN C NY INC	Cole Information Services

226 1ST ST

Year	Uses	Source
2017	SUMET I	Cole Information Services

240 1ST ST

Year	Uses	Source
2014	ERICA EGIZI	Cole Information Services

FINDINGS

251 1ST ST

Year	Uses	Source
2014	ALEKSEY BELZER	Cole Information Services

255 1ST ST

Year	Uses	Source
2017	JENNIFER HIGGINS	Cole Information Services
2014	ANDREW FISHER	Cole Information Services
	JENNIFER HIGGINS	Cole Information Services
2004	EDSON USA INC	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
2000	EDSON USA INC	Cole Information Services
1999	EDSON USA INCORPORATED	Cole Information Services
1997	EDSON USA INC	NYNEX
1994	EDSON CONSTR CORP	Cole Information Services
1992	EDSON CONSTR CORP	NYNEX Informantion Resource Co.
1985	EDSON CONSTR CORP	NYNEX Information Resources Company

1ST St W

255 1ST St W

Year	Uses	Source
1965	Petrizzo Dante A Jr	New York Telephone

4TH AV MANH

300 4TH AV MANH

Year	Uses	Source
1940	Therm O Ray Corp The lab	New York Telephone

4TH AV MHN REFRIGERATORS

265 4TH AV MHN REFRIGERATORS

Year	Uses	Source
1934	COLE REX INC MAN OFFICE	R. L. Polk & Co.

FINDINGS

4TH AV PATERSON NJ st

265 4TH AV PATERSON NJ st

Year	Uses	Source
1973	Wynmor Fabrics Inc	New York Telephone
1970	Wynmor Fabrics Inc	New York Telephone

4TH AV R

282 4TH AV R

Year	Uses	Source
1940	Bookstaver Peyser	New York Telephone

4TH AV R St

306 4TH AV R St

Year	Uses	Source
1965	Shanahan Ronald	New York Telephone

4TH AV V st

300 4TH AV V st

Year	Uses	Source
1973	Dickman Isaac	New York Telephone

4TH AV V St

300 4TH AV V St

Year	Uses	Source
1965	Udoff Louis	New York Telephone

302 4TH AV V St

Year	Uses	Source
1965	Silverstein H	New York Telephone

FINDINGS

4TH AVE

265 4TH AVE

Year	Uses	Source
2017	TENNESSEE GRIMES	Cole Information Services
	DAVID HOOD	Cole Information Services
	VICTOR MALDONADO	Cole Information Services
	MICHAEL CREE	Cole Information Services
	NADIA SOLOMON	Cole Information Services
	EMILIA BARBELLA	Cole Information Services
2014	VICTOR MALDONADO	Cole Information Services
	MICHAEL CREE	Cole Information Services
	THOMAS RIZZO	Cole Information Services
	JEREMY MACK	Cole Information Services
	JORDAN WOTKOWSKI	Cole Information Services
	NADIA SOLOMON	Cole Information Services
	STEVEN NICHOLS	Cole Information Services
2009	EMILIA BARBELLA	Cole Information Services
	VICTOR MALDONADO	Cole Information Services
	ELIZABETH CAMIN	Cole Information Services
	VERONICA NEILAN	Cole Information Services
	SETH WALTER	Cole Information Services
	LAURA WOODYARD	Cole Information Services
	STEVEN NICHOLS	Cole Information Services
	JEREMY MACK	Cole Information Services
2005	h Barbella Emilia	Hill-Donnelly Corporation
	h Maldonado Victor	Hill-Donnelly Corporation
	h Nichols Steve A	Hill-Donnelly Corporation
	h Walter Seth	Hill-Donnelly Corporation
	Woodyard Laura	Hill-Donnelly Corporation
2004	SETH WALTER	Cole Information Services
	YUKI UCHIDA	Cole Information Services
	ERIN WILDER	Cole Information Services
	EMILIA BARBELLA	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	LAURA WOODYARD	Cole Information Services
	STEVEN NICHOLS	Cole Information Services
	I RAIZO	Cole Information Services
	VICTOR MALDONADO	Cole Information Services
	THOMAS RIZZO	Cole Information Services
	HISAE KATO	Cole Information Services
1997	ADAMS Lula C	NYNEX
	BARBELLA Emilia	NYNEX
	LEWIS I C	NYNEX
	MALDONADO Victor	NYNEX
	NICHOLS Steve	NYNEX
	REED D	NYNEX
	SOMNA C	NYNEX
	VANIBLE John	NYNEX
1994	BARBELLA, EMILIA	Cole Information Services
	MALDONADO, VICTOR	Cole Information Services
	SOMNA, C	Cole Information Services
	REED, D	Cole Information Services
	VANIBLE, JOHN	Cole Information Services
	RICHARDSON, F	Cole Information Services
	NICHOLS, STEVE	Cole Information Services
	ADAMS, LULA C	Cole Information Services
	LEWIS, I C	Cole Information Services
1992	BARBELLA EMILIA	NYNEX Informantion Resource Co.
	MALDONADO A	NYNEX Informantion Resource Co.
	MALDONADO VICTOR	NYNEX Informantion Resource Co.
	NICHOLS STEVE	NYNEX Informantion Resource Co.
	REED D	NYNEX Informantion Resource Co.
	RICHARDSON F	NYNEX Informantion Resource Co.
	SOMNA C	NYNEX Informantion Resource Co.
	TORRES GLADYS	NYNEX Informantion Resource Co.
1985	BARBELLA EMILLA	NYNEX Information Resources Company

FINDINGS

Year	Uses	Source
1985	LIMA MANUEL	NYNEX Information Resources Company
	MALDONADO VICTOR	NYNEX Information Resources Company
	NICHOLS STEVE	NYNEX Information Resources Company
	SOMNA C	NYNEX Information Resources Company
1980	PERZ & SON	New York Telephone
1976	BARBELLA S	New York Telephone
	CHALEY NAT DOORS INC	New York Telephone
	FORTUNATO PETER	New York Telephone
	MALDONADO VICTOR	New York Telephone
	PARZ & SON	New York Telephone
1973	Calcagno John	New York Telephone
	Calvaruso G	New York Telephone
	CHALEY NAT DOORS INC	New York Telephone
	Dias Domingos	New York Telephone
	Fioravantes Gerry	New York Telephone
	Maldonado Victor	New York Telephone
	Nichols Steve	New York Telephone
	Polyhroinis Fredk	New York Telephone
1970	Angelo A	New York Telephone
	Angelo Vin Cent	New York Telephone
	Calcagno John	New York Telephone
	Dias Domingos	New York Telephone
	Maldonado Victor	New York Telephone
	Nichols Steve	New York Telephone
	Pallante Concetta	New York Telephone
	Polyhronis Fredk	New York Telephone
	Rio Angela	New York Telephone
1965	Angelo Vincent	New York Telephone
	Angiolettl Lilly	New York Telephone
	Calcagno John	New York Telephone
	Crociante Carmela	New York Telephone
	Dias Domingos	New York Telephone

FINDINGS

Year	Uses	Source
1965	Fortunato Dominick	New York Telephone
	Liebros Candy Co	New York Telephone
	Manganaro Jos	New York Telephone
	Nichols Steve	New York Telephone
	Polyhronis Fredk	New York Telephone
	Rio Sebastian	New York Telephone
	Trombetta Theresa	New York Telephone
1960	ANASTASIA ANTHONY	New York Telephone
	BARBA J	New York Telephone
	CALCAGNO JOHN	New York Telephone
	COOPER MARTIN	New York Telephone
	DIAS DOMINGOS	New York Telephone
	FORTUNATO DOMINICK	New York Telephone
	HANKIN JACEB	New York Telephone
	LIEBROS CANDY CO	New York Telephone
	MANGANARO JOS	New York Telephone
	NICHOLS STEVE	New York Telephone
	RANDO SALVATORE	New York Telephone
	RIO SEBASTIAN	New York Telephone
	TROMBETTA THERESA	New York Telephone
	Anastasia Anthony	New York Telephone Company
	Barba J	New York Telephone Company
	Calcagno John	New York Telephone Company
	Cooper Martin	New York Telephone Company
	Dias Domingos	New York Telephone Company
	Fortunato Dominick	New York Telephone Company
	Hankin Jaceb	New York Telephone Company
	Liebros Candy Co	New York Telephone Company
	Manganaro Jos	New York Telephone Company
	Nichols Steve	New York Telephone Company
	Rando Salvatore	New York Telephone Company
	Rio Sebastian	New York Telephone Company

FINDINGS

Year	Uses	Source
1960	Trombetta Theresa	New York Telephone Company
1949	Anastasia Anthony	New York Telephone Company
	Barba John F	New York Telephone Company
	Cooper Martin	New York Telephone Company
	Fortunato Dominick	New York Telephone Company
	Hankin Elias	New York Telephone Company
	Liebros Candy Co	New York Telephone Company
	Lipari Frank	New York Telephone Company
	Nichols Steve	New York Telephone Company
	Reo Sebastian	New York Telephone Company
	Somma Jos J	New York Telephone Company
1940	Cardello Edith	New York Telephone
1934	ANZALONE MARIE PROP H	R. L. Polk & Co.
	DEMIRILAN HARRY CLNG AND PRESS	R. L. Polk & Co.
	FERNENO J R PHYS H DO	R. L. Polk & Co.
	FIRNENO BARBARA R	R. L. Polk & Co.
	FIRNENO FRANK H	R. L. Polk & Co.
	FIRNENO JACON R PHYS H DO	R. L. Polk & Co.
	FIRNENO JENNIE H	R. L. Polk & Co.
	FIRNENO JOHN R	R. L. Polk & Co.
	SICA JOHN ELECTN H	R. L. Polk & Co.
1928	ARCULEO A WSTS & DRSSES	New York Telephone
	CASINE RUDOLPH R	New York Telephone
	FIRNENO JACOB M R	New York Telephone
	FIRNENO JENNIE MRS R	New York Telephone
	FIRNENO JUBN R	New York Telephone
	PETER ELIZ LNCH	New York Telephone
	SERPE M BARBA R	New York Telephone

267 4TH AVE

Year	Uses	Source
2014	LEE WANG	Cole Information Services
2009	LEE WANG	Cole Information Services

FINDINGS

Year	Uses	Source
2005	No Current Listing	Hill-Donnelly Corporation
2004	LEE WANG	Cole Information Services
1997	Spama	NYNEX
1994	SPAMA	Cole Information Services
1992	SPAMA	NYNEX Informantion Resource Co.
1985	SPAMA	NYNEX Information Resources Company
1934	NICHOLS STEPH RESTR	R. L. Polk & Co.

269 4TH AVE

Year	Uses	Source
1973	Saladinos Auto Body	New York Telephone
1965	Fumara Jos	New York Telephone
	Ram Charger Svce	New York Telephone
1940	Emil Auto Repes	New York Telephone
	Bottigliere Emil auto reprs	New York Telephone
1934	EVANS G H PRES E L ELECTRIC WELDING REPAIR CO INC	R. L. Polk & Co.
	TROY ANTHONY SOFT DRINKS	R. L. Polk & Co.

271 4TH AVE

Year	Uses	Source
2009	ALBA AUTO REPAIRS INC	Cole Information Services
2005	Alba Auto Repairs i	Hill-Donnelly Corporation
2004	ALBA AUTO REPAIRS INC	Cole Information Services
	SHELLEYRINE JACKSON	Cole Information Services
1999	ALBA AUTO REPAIRS INCORPORATED	Cole Information Services
1997	Alba Auto Repairs Inc	NYNEX
1994	ALBA AUTO REPAIRS INC	Cole Information Services
1992	ALBA AUTO REPRS	NYNEX Informantion Resource Co.
1985	ALBA AUTO REPR	NYNEX Information Resources Company
1976	ALBA AUTO REPR	New York Telephone
1973	Joes Body & Fender Wks	New York Telephone
1970	Joes Body & Fender Wks	New York Telephone
1965	Joes Body & Fender Wks	New York Telephone

FINDINGS

Year	Uses	Source
1960	Nassau Welding Co	New York Telephone Company
	NASSAU WELDING CO	New York Telephone
1949	Nassau Welding Co	New York Telephone Company
1945	Nassau Welding Co	New York Telephone
1940	Nassau Welding Co	New York Telephone
1934	SICA VINCENT MEATS	R. L. Polk & Co.
	NASSAU WELDING CO	R. L. Polk & Co.

273 4TH AVE

Year	Uses	Source
1965	Sams Live Poultry Mkt	New York Telephone
1960	Sams Live Poultry Mkt	New York Telephone Company
	SAM S LIVE-POULTRY MKT	New York Telephone
1949	Sams Live Poultry Mkt	New York Telephone Company
1945	Fourth Av Live Pltry Corp	New York Telephone
1940	Rainish W pltry	New York Telephone
	Fourth Av Live Pltry Mkt Inc	New York Telephone
1934	FOURTH AVENUE POULTRY MARKET RETAIL POULTRY	R. L. Polk & Co.
1928	FOURTH AV POULTRY MKT	New York Telephone
	RAINISH WM POULTRY	New York Telephone

275 4TH AVE

Year	Uses	Source
2014	MCDONALDS	Cole Information Services
2009	MCDONALDS	Cole Information Services
1999	MCDONALD JCDT CORPORATION	Cole Information Services
1997	Mcdonald JCDT Corp	NYNEX
1992	SAFELITE AUTO GLASS	NYNEX Informantion Resource Co.
1985	NORTHWEST SVCE STA INC	NYNEX Information Resources Company
	REGOUR SVCE STA	NYNEX Information Resources Company
1976	DIANA FUEL CORP	New York Telephone
1973	Bunker Hill Svce Center	New York Telephone
1970	Mobil Oil Corp	New York Telephone

FINDINGS

Year	Uses	Source
1965	New Eagle Gas Sta	New York Telephone
1960	EAGLE GAS STA	New York Telephone
	Eagle Gas Sta	New York Telephone Company
1949	Sams Fourth Av Sta Inc Svce sta	New York Telephone Company
1945	Mandel Fuel Inc	New York Telephone
	Fourth Av Svce Sta	New York Telephone
1940	Mandel Fuel Inc	New York Telephone
	Fourth Av Svce Sta	New York Telephone
1934	MCCLURD FREDK BLDR CONTR H	R. L. Polk & Co.
	HOMESTEAD SERVICE STATION INC MAX FROMOWITZ BR MGR	R. L. Polk & Co.
1928	DE VITO PETER GARAGE	New York Telephone

279 4TH AVE

Year	Uses	Source
1928	ASTORIA-STAR WELDING CO	New York Telephone

281 4TH AVE

Year	Uses	Source
1985	D S REPR SHOP	NYNEX Information Resources Company
1928	FREITAG & ERTHAL AUTO REPRS	New York Telephone

282 4TH AVE

Year	Uses	Source
2009	ISA WHOLESALE CORP	Cole Information Services
2005	Isa Wholesale Corp	Hill-Donnelly Corporation
1940	Automotive Mntnce Co	New York Telephone
1934	GARMS HERMAN MECH H	R. L. Polk & Co.
	KANTOR GERTRUDE MRS STATIONER H DO	R. L. Polk & Co.
	RUSTICO JOS GARAGE	R. L. Polk & Co.
1928	PRIVATE AUTO RENTING CO	New York Telephone

283 4TH AVE

Year	Uses	Source
2014	ZD H TRADING INCORPORATED	Cole Information Services

FINDINGS

Year	Uses	Source
2009	PROJEKT	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
1976	CROWN PAPR BOX CO	New York Telephone
	ANDY L & L PAPR BOX CO INC	New York Telephone
1973	Andy L & L Papr Box Coinc	New York Telephone
1970	Andy L & L Papr Box Co Inc	New York Telephone
	Crown Papr Box Co	New York Telephone

286 4TH AVE

Year	Uses	Source
1934	PETTITO JAS FCTYWKR R	R. L. Polk & Co.

288 4TH AVE

Year	Uses	Source
2014	ANNA MELENDEZ	Cole Information Services

289 4TH AVE

Year	Uses	Source
1960	MARQUETTE LEAGUE	New York Telephone
1934	WALSH FRANK RETAIL MEATS	R. L. Polk & Co.

291 4TH AVE

Year	Uses	Source
1934	DEMIC ANNA SEC-TREAS THOS DEMIE CORP	R. L. Polk & Co.

292 4TH AVE

Year	Uses	Source
1965	Freds Svce Sta	New York Telephone

293 4TH AVE

Year	Uses	Source
2009	OGA LENSKAYA	Cole Information Services
2004	OGA LENSKAYA	Cole Information Services

FINDINGS

294 4TH AVE

Year	Uses	Source
1934	FULTON METAL CO	R. L. Polk & Co.

300 4TH AVE

Year	Uses	Source
2004	HUI HUANG	Cole Information Services
1985	DANCER BEN J	NYNEX Information Resources Company
1965	Ed & Joes Svce Sta	New York Telephone
1960	SONNY S SVCE STA	New York Telephone
	Sonnys Svce Sta	New York Telephone Company
1949	Pauls Shell Service Station	New York Telephone Company
1945	Bills Shell Svce Sta	New York Telephone
1940	Jays Shell Svce Sta	New York Telephone
1934	CURTIS BEAU CLK R	R. L. Polk & Co.
	CASEY CHAS H	R. L. Polk & Co.
1928	WELDED TANK & CONSTN CO INC	New York Telephone

302 4TH AVE

Year	Uses	Source
2004	ARON KUPERMAN	Cole Information Services
1992	MIASTOWSKI FELIX	NYNEX Informantion Resource Co.
1985	LOMBARDO ROSARIO	NYNEX Information Resources Company
1976	SINOWITZ SOL	New York Telephone

304 4TH AVE

Year	Uses	Source
2004	JOSE SANABRIA	Cole Information Services
1992	BRODY GLORIA	NYNEX Informantion Resource Co.

310 4TH AVE

Year	Uses	Source
1928	JOSE R	New York Telephone

FINDINGS

312 4TH AVE

Year	*Uses*	*Source*
2004	DHARMU NATH	Cole Information Services

4TH AVE W

302 4TH AVE W

Year	*Uses*	*Source*
1973	Sillman I	New York Telephone
1965	Welsh Joe	New York Telephone
1960	MILLER ROBT A	New York Telephone
	Miller Robt A	New York Telephone Company

DENTON AVENUE SOUTH HYD PIKE NW

69 DENTON AVENUE SOUTH HYD PIKE NW

Year	*Uses*	*Source*
1976	CONSERVATIVE GAS	New York Telephone

DENTON PL

69 DENTON PL

Year	*Uses*	*Source*
1997	National Propane New Hyde Park	NYNEX
	National Propane New Hyde Park	NYNEX

S DENTON AVENUE NEW HYDE PARK

69 S DENTON AVENUE NEW HYDE PARK

Year	*Uses*	*Source*
1997	National Propane	NYNEX

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
222 1ST ST	2017, 2014, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
224 1ST PL	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
225 1 KNAP St	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
225 1 KNAPP	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
225 1 KNAPP St	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
225 1 KNGS st	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
226 1ST ST	2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
233 1ST FL	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
238 1ST LA LINDN HOUSES	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
240 1ST ST	2017, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
247 1 HUBARD St	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
251 1ST ST	2017, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
253 1ST FL	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
255 1ST ST	2017, 2014, 2009, 2005, 2004, 1999, 1994, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
255 1ST ST	2009, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
255 1ST St W	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
257 1ST FL	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
265 4TH AV MHN REFRIGERATORS	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
265 4TH AV PATERSON NJ st	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
265 4TH AVE	2017, 2014, 2009, 2004, 2000, 1999, 1994, 1945

FINDINGS

Address Researched	Address Not Identified in Research Source
265 4TH AVE	2005, 2000, 1999, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
267 4TH AVE	2017, 2005, 2000, 1999, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
267 4TH AVE	2017, 2014, 2009, 2004, 2000, 1999, 1994, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
269 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1970, 1960, 1949, 1945, 1928
271 4TH AVE	2017, 2014, 2009, 2004, 2000, 1999, 1994, 1980, 1928
271 4TH AVE	2017, 2014, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
273 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970
275 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1994, 1980
275 4TH AVE	2017, 2005, 2004, 2000, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
279 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
281 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
282 4TH AV R	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
282 4TH AVE	2017, 2014, 2009, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945
282 4TH AVE	2017, 2014, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
283 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1965, 1960, 1949, 1945, 1940, 1934, 1928
283 4TH AVE	2017, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
286 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
288 4TH AVE	2017, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
289 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
291 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
292 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
293 4TH AVE	2017, 2014, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
294 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
300 4TH AV MANH	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
300 4TH AV V St	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
300 4TH AV V st	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
300 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1980, 1976, 1973, 1970
300 4TH AVE	2017, 2014, 2009, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
302 4TH AV V St	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
302 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
302 4TH AVE	2017, 2014, 2009, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
302 4TH AVE W	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1970, 1949, 1945, 1940, 1934, 1928
304 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
304 4TH AVE	2017, 2014, 2009, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
306 4TH AV R St	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
310 4TH AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
312 4TH AVE	2017, 2014, 2009, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
69 DENTON AVENUE SOUTH HYD PIKE NW	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
69 DENTON PL	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
69 S DENTON AVENUE NEW HYDE PARK	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
296 4th Avenue	2000

APPENDIX D
Regulatory Records Documentation

296 4th Avenue
296 4th Avenue
Brooklyn, NY 11215

Inquiry Number: 07124126.2r
September 20, 2022

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1449
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2022 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

296 4TH AVENUE
BROOKLYN, NY 11215

COORDINATES

Latitude (North):	40.6755770 - 40ˆ 40' 32.07''
Longitude (West):	73.9850410 - 73ˆ 59' 6.14''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	585779.8
UTM Y (Meters):	4503028.0
Elevation:	23 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019
West Map:	14317809 JERSEY CITY, NJ
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150729, 20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	MAACO AUTO PAINTING	296 4TH AVE.	US AIRS, FINDS, ECHO		TP
A2	JEN JAY TRANSMISSION	296 4TH AVE	EDR Hist Auto		TP
A3	MAACO AUTO PAINTING	296 4TH AVE & 1ST ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST		TP
Reg	GOWANUS CANAL	BUTLER ST (BETWEEN B	NPL, SEMS, US ENG CONTROLS, US INST CONTROLS, ROD	Same	1037, 0.196, WSW
A4	CON EDISON	292 4TH AV	NY MANIFEST	Higher	1 ft.
A5	CON EDISON	292 4TH AV	NY MANIFEST	Higher	1 ft.
A6	MC DONALD'S	245 1ST STREET	NY Spills	Lower	40, 0.008, WNW
A7	STREET	1ST STREET/4TH AVE	NY Spills	Higher	60, 0.011, SSE
A8	3RD AVE YARD	1ST ST & 4TH AVE	NY Spills	Higher	93, 0.018, SSE
A9	MTA NYCT - 4TH AVE G	276 4TH AVE	RCRA-SQG	Higher	99, 0.019, ENE
B10	4TH AVE/GARFIELD ST	4TH AVE/GARFIELD ST	NY Spills	Higher	105, 0.020, ENE
A11	272 4TH AVENUE	272 4TH AVENUE	NY BROWNFIELDS, NY Spills	Higher	122, 0.023, NE
A12	CONSTRUCTION SITE	267 FOURTH AVENUE IN	NY Spills	Higher	123, 0.023, East
A13	275 FOURTH AVENUE DE	275 4TH AVE	RCRA-LQG	Higher	138, 0.026, ESE
A14	NORTH PETROLEUM CORP	275 FOURTH AVE	NY UST, NY AST	Higher	138, 0.026, ESE
A15	275 4TH AVE INVESTOR	275 4TH AVE	NY MANIFEST	Higher	138, 0.026, ESE
A16	275 4TH AVENUE	275 4TH AVENUE	NY VCP	Higher	138, 0.026, ESE
A17	DIANA FUEL CORP	275 4TH AVE	EDR Hist Auto	Higher	138, 0.026, ESE
A18	275 4TH AVENUE INVES	275 4TH AVENUE	PA MANIFEST	Higher	138, 0.026, ESE
A19	LOT 1,TAXBLOCK 964	275 4 AVENUE	NY E DESIGNATION	Higher	138, 0.026, ESE
A20	269-271 4TH AVENUE	271 4TH AVENUE	NY VCP	Higher	139, 0.026, ESE
A21	LOT 6,TAXBLOCK 964	271 4 AVENUE	NY E DESIGNATION	Higher	139, 0.026, ESE
A22	FORMER GAS STATION	269-271 4TH AVE	NY Spills	Higher	139, 0.026, ESE
A23	LOT 7,TAXBLOCK 964	269 4 AVENUE	NY E DESIGNATION	Higher	139, 0.026, ESE
A24	YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A25	CONSOLIDATED EDISON	222 FIRST STREET	NY MANIFEST	Lower	142, 0.027, West
A26	CON EDISON	222 FIRST ST	NY MANIFEST	Lower	142, 0.027, West
A27	CON EDISON VEHICLE 6	222 1ST ST	NY Spills	Lower	142, 0.027, West
A28	THIRD AVE YARD - SER	222 1ST STREET	NY Spills	Lower	142, 0.027, West
A29	THIRD AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A30	CON EDISON	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A31	THIRD AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A32	SERVICE BOX 3RD AVE	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A33	CON EDISON - 3RD AVE	222 1ST ST	RCRA-LQG, NJ MANIFEST	Lower	142, 0.027, West
A34	CON ED 3RD AVE STATI	222 1ST ST	NY Spills	Lower	142, 0.027, West
A35	COOLANT RELEASE FROM	222 1 STREET (THIRD	NY Spills	Lower	142, 0.027, West
A36	CONSOLIDATED EDISON	222 1ST ST	NY MANIFEST	Lower	142, 0.027, West
A37	CON ED THIRD AVE YAR	222 FIRST ST	NY Spills	Lower	142, 0.027, West
A38	CON-ED THIRD AVE YAR	222 FIRST ST	NY Spills	Lower	142, 0.027, West

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A39	CONSOLIDATED EDISON	222 FIRST ST	NY MANIFEST	Lower	142, 0.027, West
A40	CON ED 3RD AV YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A41	CON ED 3RD AV GARAGE	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A42	CON ED FACILITY	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A43	OIL LEAK FROM VEHICL	222 FIRST ST AT 3 AV	NY Spills	Lower	142, 0.027, West
A44	CON EDISON 3RD AVE Y	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A45	CON ED STATION	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A46	3RD AVENUE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A47	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A48	3RD AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A49	CON EDISON - OTHER -	222 1 ST	RCRA-LQG	Lower	142, 0.027, West
A50	THIRD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A51	3 QT ANTI-FREEZE FRO	222 FIRST ST. CON ED	NY Spills	Lower	142, 0.027, West
A52	3RD AVE SERVICE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A53	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A54	CON EDISON	222 FIRST ST	NY MANIFEST	Lower	142, 0.027, West
A55	CON EDISON TM439	222 1ST ST	RCRA NonGen / NLR, NY MANIFEST	Lower	142, 0.027, West
A56	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A57	3RD AVE YARD CON ED	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A58	222 1ST STREET	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A59	CON ED	222 1 ST	NY MANIFEST	Lower	142, 0.027, West
A60	CON EDISON	222 1ST ST	NY MANIFEST	Lower	142, 0.027, West
A61	THIRD AVENUE YARD	222 1ST STREET	NY Spills	Lower	142, 0.027, West
A62	CON ED	222 FIRST ST	NY Spills	Lower	142, 0.027, West
A63	222 FIRST STREET	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A64	3RD AVE FLUSH TRUCK	222 FIRST STREET	NY SWF/LF	Lower	142, 0.027, West
A65	3RD AV YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A66	3 AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A67	LEAK FROM VEHICLE IN	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A68	CON EDISON GARAGE	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A69	VEHICLE 60722 LOST H	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A70	THIRD AVENUE YARD	222 FIRST STREET	NY BROWNFIELDS	Lower	142, 0.027, West
A71	THIRD AVENUE YARD	222 FIRST STREET	NY TANKS, NY Spills	Lower	142, 0.027, West
A72	CON ED WORK / 3RD AV	222 1ST ST	NY Spills	Lower	142, 0.027, West
A73	FLUSH PIT	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A74	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A75	CON EDISON	221 1ST	NY MANIFEST	Lower	143, 0.027, WNW
A76	CON EDISON	221 1ST ST	NY Spills, NY MANIFEST	Lower	143, 0.027, WNW
A77	CON EDISON	221 1ST	RCRA NonGen / NLR	Lower	143, 0.027, WNW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A78	CON EDISON	221 1ST ST	RCRA NonGen / NLR	Lower	143, 0.027, WNW
B79	CON EDISON MANHOLE:	540 CARROLL ST	RCRA NonGen / NLR	Higher	145, 0.027, NNE
B80	CON EDISON	540 CARROLL ST	NY MANIFEST	Higher	145, 0.027, NNE
A81	220 1ST STREET	220 1ST STREET	NY Spills	Lower	149, 0.028, West
B82	LOT 1,TAXBLOCK 961	261 4 AVENUE	NY E DESIGNATION	Higher	164, 0.031, East
A83	FIVE GALLONS OF OIL	222 1 STREET	NY Spills	Lower	164, 0.031, SW
A84	SIX GAL HYDRAULIC FL	222 FIRST STREET & 3	NY Spills	Lower	164, 0.031, SW
A85	VEHICLE 60677	THIRD AVE YARD	NY Spills	Lower	164, 0.031, SW
A86	222 1ST STREET	CON EDSION	NY Spills	Lower	164, 0.031, SW
A87	HYDRAULIC OIL	3 AVE YARD NEW CONST	NY Spills	Lower	164, 0.031, SW
B88	RIDGE AUTO TRANSMISS	270 4TH AVE	EDR Hist Auto	Higher	166, 0.031, NE
B89	AUTO BODY CONCEPTS D	270 4TH AVE	RCRA NonGen / NLR	Higher	166, 0.031, NE
B90	LOT 2,TAXBLOCK 961	259 4 AVENUE	NY E DESIGNATION	Higher	180, 0.034, ENE
C91	ROMAN CATHOLIC CHURC	522 CARROLL ST	NY UST	Higher	192, 0.036, NNE
B92	CON EDISON	9 GARFIELD ST	NY MANIFEST	Higher	194, 0.037, East
B93	CON EDISON SERVICE B	9 GARFIELD ST	RCRA NonGen / NLR, FINDS	Higher	194, 0.037, East
C94	PS 418 K SCHOOL	512 CARROLL ST	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Lower	199, 0.038, North
C95	P.S. 372 (OUR LADY O	512 CARROLL STREET	NY Spills, NY LEAD	Lower	199, 0.038, North
C96	P.S. 372 (OUR LADY O	512 CARROLL STREET	NY AST	Lower	199, 0.038, North
C97	P.S. 372 (OUR LADY O	512 CARROLL STREET	NY UST	Lower	199, 0.038, North
B98	CON EDISON	CARROLL ST & 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	205, 0.039, NE
B99	CON EDISON	255 4TH AVE	NJ MANIFEST	Higher	208, 0.039, ENE
B100	CON EDISON	255 4TH AVE	RCRA NonGen / NLR	Higher	208, 0.039, ENE
B101	CON ED	255 4TH AVE	NY MANIFEST	Higher	208, 0.039, ENE
B102	LOT 69,TAXBLOCK 961	13 GARFIELD PLACE	NY E DESIGNATION	Higher	211, 0.040, East
C103	CON EDISON	DENTON ST & CARROLL	RCRA NonGen / NLR, FINDS, ECHO	Higher	220, 0.042, NNE
C104	CON EDISON	DENTON ST & CARROLL	NY MANIFEST	Higher	220, 0.042, NNE
C105	CON EDISON	DENTON ST & CARROLL	NJ MANIFEST	Higher	220, 0.042, NNE
B106	CON EDISON SERVICE B	12 GARFIELD PL	RCRA NonGen / NLR	Higher	224, 0.042, ESE
B107	CON EDISON - SERVICE	255 1ST ST	NY MANIFEST	Higher	242, 0.046, ESE
B108	LOT 67,TAXBLOCK 961	15 GARFIELD PLACE	NY E DESIGNATION, NY MANIFEST	Higher	253, 0.048, East
B109	4TH AVE	CARROLL ST & 4TH AVE	NY Spills	Higher	266, 0.050, ENE
B110	LOT 7,TAXBLOCK 961	566 CARROLL STREET	NY E DESIGNATION	Higher	275, 0.052, East
B111	566 CARROLL STREET	566 CARROLL STREET	NY VCP	Higher	275, 0.052, East
B112	LOT 21,TAXBLOCK 352	CARROLL STREET	NY E DESIGNATION	Higher	278, 0.053, ENE
D113	LOT 1,TAXBLOCK 969	283 4 AVENUE	NY E DESIGNATION	Higher	284, 0.054, SSE
E114	3RD AVE YARD	3RD AVE YARD	NY Spills	Lower	287, 0.054, WSW
B115	LOT 1,TAXBLOCK 958	253 4 AVENUE	NY E DESIGNATION	Higher	298, 0.056, ENE
D116	CON EDISON SERVICE B	100 4TH ST & 2ND AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	299, 0.057, South

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C117	CON EDISON	511 CARROLL ST	NY MANIFEST	Lower	306, 0.058, North
C118	CON EDISON	511 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	306, 0.058, North
C119	CON EDISON	511 CARROLL ST	NJ MANIFEST	Lower	306, 0.058, North
B120	NYCDOT BRIDGE BIN 22	PRESIDENT ST BRG OVE	RCRA NonGen / NLR	Higher	312, 0.059, NE
B121	LOT 2,TAXBLOCK 958	249 4 AVENUE	NY E DESIGNATION	Higher	314, 0.059, ENE
F122	3RD AV YARD INFO STO	M 222 1ST ST	NY Spills	Lower	316, 0.060, WNW
F123	COMMERCIAL BUILDING	14 WHITWELL PLACE	NY Spills	Lower	322, 0.061, NNW
G124	CON EDISON	22 GARFIELD ST	NY MANIFEST	Higher	347, 0.066, ESE
G125	CON EDISON	22 GARFIELD ST	NJ MANIFEST	Higher	347, 0.066, ESE
G126	CON EDISON	22 GARFIELD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	347, 0.066, ESE
H127	LOT 4,TAXBLOCK 958	245 4 AVENUE	NY E DESIGNATION	Higher	349, 0.066, ENE
H128	L&B AUTO REPAIR CORP	245 4TH AVENUE	NY AST	Higher	349, 0.066, ENE
H129	241 - 245 4TH AVENUE	245 4TH AVENUE	NY VCP	Higher	349, 0.066, ENE
D130	CON EDISON CO. OF NY	3RD AVE (BET. 3RD &	NY SWF/LF	Higher	360, 0.068, South
D131	LOT 7504,TAXBLOCK 97	302 2 STREET	NY E DESIGNATION	Higher	380, 0.072, South
H132	243 DEVELOPMENT LLC	243-245 4TH AVE	NY MANIFEST	Higher	384, 0.073, ENE
H133	LOT 5,TAXBLOCK 958	243 4 AVENUE	NY E DESIGNATION	Higher	384, 0.073, ENE
H134	245 4TH AVENUE LLC	243-245 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	384, 0.073, ENE
H135	2 FAMILY HOUSE	557 CARROLL ST	NY AST	Higher	386, 0.073, ENE
I136	505 CARROLL ST.	505 CARROLL STREET	NY AST	Lower	389, 0.074, NNW
I137	PROCIDA REALTY	505 CARROLL STREET	NY Spills	Lower	389, 0.074, NNW
E138	THIRD AV YARD	222 FIRST STREET	NY Spills	Lower	402, 0.076, West
E139	FLUSHPIT 3RD AVE YAR	222 FIRST STREET	NY Spills	Lower	402, 0.076, West
F140	CON EDISON	319 3 AVE	NY MANIFEST	Lower	412, 0.078, WNW
H141	CON EDISON	237 4TH AVE	PA MANIFEST	Higher	413, 0.078, NE
H142	LOT 7,TAXBLOCK 958	586 PRESIDENT STREET	NY E DESIGNATION	Higher	433, 0.082, ENE
H143	CON EDISON	586 PRESIDENT ST	NY MANIFEST	Higher	433, 0.082, ENE
D144	LOT 7502,TAXBLOCK 97	306 2 STREET	NY E DESIGNATION	Higher	438, 0.083, South
G145	CON EDISON	584 CARROLL ST	NY MANIFEST	Higher	440, 0.083, East
G146	CON EDISON	584 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	440, 0.083, East
J147	315 4TH AVE	315 4TH AVENUE	NY Spills	Higher	445, 0.084, South
G148	CON EDISON	586 CARROL ST	NJ MANIFEST	Higher	459, 0.087, East
G149	CON EDISON	586 CARROL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	459, 0.087, East
G150	CON EDISON	586 CARROL ST	NY MANIFEST	Higher	459, 0.087, East
I151	540 PRESIDENT STREET	540 PRESIDENT STREET	NY LTANKS	Lower	462, 0.087, North
F152	222 1ST ST	3RD AVE YARD	NY Spills	Lower	475, 0.090, WNW
F153	THIRD AVENUE YARD	THIRD AVENUE & FIRST	NY Spills	Lower	475, 0.090, WNW
F154	3RD AVE YARD	3RD AVE YARD	NY Spills	Lower	475, 0.090, WNW
H155	VAULT# TM0253	PRESIDENT ST & 4TH A	NY Spills	Higher	490, 0.093, ENE

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G156	CON EDISON	590 CARROLL ST	NY MANIFEST	Higher	497, 0.094, East
G157	CON EDISON	590 CARROLL ST	NJ MANIFEST	Higher	497, 0.094, East
G158	CON EDISON	590 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	497, 0.094, East
F159	FEEDER LEAK	3RD AVE & 1ST STREET	NY Spills	Lower	501, 0.095, WNW
F160	3RD AVE SERVICE CENT	3RD AVE & 1ST ST	NY Spills	Lower	501, 0.095, WNW
F161	CONSOLIDATED EDISON	3RD AVE & 1ST STREET	NY MANIFEST	Lower	501, 0.095, WNW
F162	MANHOLE # 65435	3RD AVE/1ST STREET	NY Spills	Lower	502, 0.095, WNW
J163	LOT 73,TAXBLOCK 974	303 3 STREET	NY E DESIGNATION	Higher	521, 0.099, South
D164	CON EDISON - SERVICE	328 2ND ST	NY MANIFEST	Higher	537, 0.102, SSE
D165	CON EDISON - SERVICE	328 2ND ST	RCRA-LQG	Higher	537, 0.102, SSE
K166	CON EDISON	577 CARROLL ST	NY MANIFEST	Higher	548, 0.104, East
K167	CON EDISON	577 CARROLL ST	NJ MANIFEST	Higher	548, 0.104, East
K168	CON EDISON	577 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	548, 0.104, East
I169	L.L.L. AUTO REPAIR I	528 PRESIDENT STREET	NY AST	Lower	549, 0.104, NNW
F170	CON EDISON	318 3RD AVE FRONT OF	NY MANIFEST	Lower	550, 0.104, WNW
F171	FINEST AUTO & RECOVE	310 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	550, 0.104, NW
F172	CLARIN TRUCK LEASING	312 3RD AVE	NY UST	Lower	566, 0.107, WNW
L173	CON EDISON - SERVICE	302 3RD AVE	NY MANIFEST	Lower	570, 0.108, NW
L174	CON EDISON - SERVICE	302 3RD AVE	RCRA-LQG	Lower	570, 0.108, NW
J175	MANHOLE 5436	4TH AVE/3RD ST	NY Spills	Higher	570, 0.108, South
M176	ABF FREIGHTS	545 PRESIDENT ST	NY Spills	Lower	573, 0.109, North
N177	2ND & 3RD AVE	2ND & 3RD AVE	NY Spills	Lower	573, 0.109, West
N178	MAN HOLE 5354	3RD AND AVE AND 2ND	NY Spills	Lower	581, 0.110, West
O179	B M T STOP DRY CLEAN	230 4TH AVE STE B	EDR Hist Cleaner	Higher	587, 0.111, NE
J180	CON EDISON SERVICE B	260 3RD ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Higher	614, 0.116, South
P181	CONSTRUCTION SITE	340 4TH AVE	NY Spills	Higher	630, 0.119, SSW
P182	PARKSIDE SERVICE CEN	340 4TH AVE	NY Spills	Higher	630, 0.119, SSW
P183	PARKSIDE SERVICE CEN	340 4TH AVENUE	NY UST	Higher	630, 0.119, SSW
P184	PARKSIDE SERVICE STA	340 FOURTH AVE	EDR Hist Auto	Higher	630, 0.119, SSW
L185	CON EDISON	284 THIRD AVE	NY MANIFEST	Lower	641, 0.121, NNW
L186	CON EDISON	284 3RD AVE	NY MANIFEST	Lower	641, 0.121, NNW
O187	CON EDISON	226 4TH AVE	PA MANIFEST	Higher	645, 0.122, NE
M188	CON EDISON SERVICE B	604 UNION ST	RCRA NonGen / NLR, NY MANIFEST	Higher	667, 0.126, NNE
Q189	276 3RD AVENUE	276 THIRD AVENUE	NY AST	Lower	682, 0.129, NNW
L190	JO-LEE TRUCKING	463 CARROLL ST	RCRA NonGen / NLR	Lower	713, 0.135, NW
O191	NYCT - UNION STATION	UNION ST & 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	718, 0.136, NE
M192	KLOR-DE CLEANERS	263 3RD AVENUE	NY DRYCLEANERS	Lower	720, 0.136, North
O193	CON EDISON MANHOLE:	4TH & UNION AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	723, 0.137, NE
M194	CON EDISON SERVICE B	578 UNION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	724, 0.137, North

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
N195	CON EDISON VAULT SUB	213 3RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	731, 0.138, West
R196	CON EDISON	3RD ST & 3RD AVE	NJ MANIFEST	Lower	739, 0.140, WSW
R197	VERIZON LOG 31756 MA	3RD ST & 3RD AVE	RCRA NonGen / NLR	Lower	739, 0.140, WSW
R198	CON EDISON	3RD ST & 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	739, 0.140, WSW
R199	CON EDISON	3RD ST & 3RD AVE	NY MANIFEST	Lower	739, 0.140, WSW
R200	CONSOLIDATED EDISON	3 AVE & 3 STREET & 6	NY MANIFEST	Lower	741, 0.140, WSW
P201	PEP BOYS #0247	354 4TH AVENUE	NY AST	Higher	748, 0.142, SSW
P202	PEP BOYS #0247	354 4TH AVENUE	NY UST	Higher	748, 0.142, SSW
P203	PEP BOYS 247	354 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	748, 0.142, SSW
P204	PEP BOYS #0247	354 4TH AVE	NY CBS, NY Spills	Higher	748, 0.142, SSW
P205	PEP BOYS #0247	354 4TH AVE	NY AST	Higher	748, 0.142, SSW
L206	LINDA TOOL & DIE COR	459 CARROLL ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	752, 0.142, NW
S207	CON EDISON	251 3RD AVE	NY MANIFEST	Lower	794, 0.150, North
S208	CON EDISON EXCAVATIO	251 3RD AVE	RCRA NonGen / NLR	Lower	794, 0.150, North
T209	HOLYLAND AUTO REPAIR	637 UNION STREET	NY AST	Lower	795, 0.151, NNE
Q210	RIDGE COMPLETE AUTO	264 THIRD AVENUE	NY AST	Lower	798, 0.151, NNW
P211	MAACO AUTO PAINTING	358 FOURTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	807, 0.153, SSW
P212	CON EDISON - MANHOLE	358 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	807, 0.153, SSW
M213	CON ED	617 UNION ST & 3RD A	NY MANIFEST	Lower	833, 0.158, North
M214	CON EDISON - UNION S	617 UNION STREET	PA MANIFEST	Lower	833, 0.158, North
R215	CON EDISON SERVICE B	210 3RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	839, 0.159, WSW
U216	CON EDISON SERVICE B	85-87 1ST AVE & 5TH	RCRA NonGen / NLR, FINDS	Higher	847, 0.160, SE
V217	CON EDISON - TRANSFO	5TH AVE & GARFIELD P	NY MANIFEST	Higher	849, 0.161, ESE
O218	204 4TH AVE LLC - BC	204 4TH AVE	RCRA-LQG	Higher	850, 0.161, NNE
O219	SPEEDWAY # 7835	204-222 FOURTH AVENU	NY UST	Higher	850, 0.161, NNE
O220	HESS#32530	204-222 FOURTH AVE	RCRA-VSQG, US AIRS, FINDS, ECHO, NY MANIFEST	Higher	850, 0.161, NNE
O221	MERRITT GAS STATION	204-222 4TH AVENUE	NY LTANKS, NY Spills	Higher	850, 0.161, NNE
O222	204 4TH AVENUE	204 4TH AVENUE	NY BROWNFIELDS	Higher	850, 0.161, NNE
W223	CON EDISON	451 CARROLL ST FRONT	NY MANIFEST	Lower	853, 0.162, NW
W224	CON EDISON	451 CARROLL ST FRONT	RCRA NonGen / NLR	Lower	853, 0.162, NW
W225	CON EDISON	451 CARROLL ST FRONT	NJ MANIFEST	Lower	853, 0.162, NW
S226	CON EDISON	617 UNION ST & 3RD A	RCRA NonGen / NLR, FINDS, ECHO	Lower	872, 0.165, North
Q227	CON EDISON	501 PRESIDENT ST	NY MANIFEST	Lower	876, 0.166, NNW
Q228	CON EDISON	501 PRESIDENT ST	RCRA NonGen / NLR	Lower	876, 0.166, NNW
Q229	CON EDISON	501 PRESIDENT ST	NJ MANIFEST	Lower	876, 0.166, NNW
X230	4TH & SACKETT STREET	4TH & SACKETT STREET	NY LTANKS	Higher	880, 0.167, NE
S231	SJ FUEL CO. INC.	601 UNION STREET	NY TANKS	Lower	886, 0.168, North
S232	A 2 Z ENVIRONMENTAL	601 UNION ST	RCRA NonGen / NLR	Lower	886, 0.168, North
W233	CON EDISON	450 CARROL ST	NY MANIFEST	Lower	888, 0.168, NW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Y234	RALPH'S CLEANERS	230 5TH AVE	NY DRYCLEANERS	Higher	900, 0.170, East
Y235	RALPHS CLEANERS	230 FIFTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	900, 0.170, East
R236	216 3RD STREET	216 3RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	910, 0.172, West
W237	CON ED	443 CARROLL ST	NY MANIFEST	Lower	910, 0.172, NW
W238	CON EDISON	443 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	910, 0.172, NW
R239	190-220 THIRD STREET	214 3RD ST	NJ MANIFEST	Lower	916, 0.173, West
R240	190-220 THIRD STREET	214 3RD ST	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	916, 0.173, West
T241	CONSOLIDATED EDISON	V5491-633 SACKETT ST	NY MANIFEST	Higher	923, 0.175, NNE
U242	JORDAN MALACHIE CLEA	295 5TH AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	925, 0.175, SE
U243	MALACHI DRY CLNR	279 5TH AVENUE	NY DRYCLEANERS	Higher	932, 0.177, SE
U244	JET FRENCH CLEANERS	279 5TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	932, 0.177, SE
Z245	BRIDGE FORD	343 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	943, 0.179, SSW
Z246	343 4TH AVENUE	343 4TH AVENUE	NY UST	Higher	943, 0.179, SSW
R247	ALL BORO'S	200 3RD ST	NY LTANKS	Lower	950, 0.180, West
AA248	CON EDISON	354 3RD ST	NY MANIFEST	Higher	950, 0.180, SSE
AA249	CON EDISON	354 3RD ST	RCRA NonGen / NLR	Higher	950, 0.180, SSE
AA250	CON EDISON	354 3RD ST	NJ MANIFEST	Higher	950, 0.180, SSE
W251	CON EDISON - SERVICE	484 PRESIDENT ST	RCRA-LQG	Lower	959, 0.182, NW
W252	CON EDISON - SERVICE	484 PRESIDENT ST	NY MANIFEST	Lower	959, 0.182, NW
Z253	BROOKLYN IGNITION &	370 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	966, 0.183, SSW
AB254	CON EDISON	688 SACKET ST	NY MANIFEST	Higher	975, 0.185, NE
AB255	CON EDISON	688 SACKETT ST	NY MANIFEST	Higher	975, 0.185, NE
AB256	CON EDISON	688 SACKETT ST	NY MANIFEST	Higher	975, 0.185, NE
AC257	CON EDISON SERVICE B	198 3RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	976, 0.185, West
Z258	SUSAN MAINTENANCE CO	374 4TH AVENUE	NY UST	Higher	989, 0.187, SSW
Z259	SUSAN MAINTENANCE	374 4TH AVE	RCRA-SQG, FINDS, ECHO, NJ MANIFEST, NY MANIFEST	Higher	989, 0.187, SSW
Z260	374 4TH AVENUE	374 4TH AVENUE	NY VCP	Higher	989, 0.187, SSW
Z261	SUSAN MAINTENANCE CO	374 4TH AVENUE	NY AST	Higher	989, 0.187, SSW
U262	CON EDISON	318 1 ST	NY MANIFEST	Higher	1009, 0.191, SE
S263	MATTHEWS INTERNATION	585 UNION ST	RCRA NonGen / NLR	Lower	1016, 0.192, NNW
X264	SEMPLE RIEGER CO	635 SACKETT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1022, 0.194, NNE
U265	32 UNIT 4 STORY WALK	325 1ST STREET	NY AST	Higher	1025, 0.194, ESE
U266	CON EDISON	365 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1030, 0.195, SE
U267	CON EDISON	365 2ND ST	NJ MANIFEST	Higher	1030, 0.195, SE
U268	CON ED	365 2ND ST	NY MANIFEST	Higher	1030, 0.195, SE
V269	640 CARROLL LLC	640 CARROLL STREET	NY AST	Higher	1042, 0.197, ESE
Z270	CON EDISON SERVICE B	209 5TH ST OPPOSITE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1053, 0.199, SSW
T271	617 SACKETT STREET R	617 SACKETT STREET	NY UST	Lower	1057, 0.200, NNE
AD272	220 3RD STREET	220 3RD STREET	NY UST	Lower	1059, 0.201, WSW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AD273	PIPPIN ENTERPRISES L	220 3RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1059, 0.201, WSW
AE274	585 UNION STREET	577-599 UNION STREET	NY BROWNFIELDS	Lower	1074, 0.203, NNW
Y275	670 PRESIDENT ST HOU	670 PRESIDENT STREET	NY AST	Higher	1079, 0.204, East
AF276	CON EDISON - EXCAVAT	232 3RD AVE	RCRA-LQG	Lower	1082, 0.205, North
AF277	CON EDISON	232 3RD AVE	NY MANIFEST	Lower	1082, 0.205, North
AC278	CON EDISON	227 3RD ST	NY MANIFEST	Lower	1082, 0.205, West
U279	CON EDISON	335 1ST ST	NJ MANIFEST	Higher	1093, 0.207, ESE
U280	CON EDISON	335 1ST ST	NY MANIFEST	Higher	1093, 0.207, ESE
U281	CON EDISON	335 1ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1093, 0.207, ESE
AA282	BHW NV ASSOCIATES	321 FIFTH AVENUE	NY AST	Higher	1096, 0.208, SSE
AC283	CON EDISON MANHOLE:	190 3RD ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Lower	1097, 0.208, West
W284	CRUSADER CANDLE CO I	325 NEVINS ST	NJ MANIFEST	Lower	1098, 0.208, NW
W285	325 NEVINS STREET	325 NEVINS STREET	NY LTANKS	Lower	1098, 0.208, NW
W286	CRUSADER CANDLE CO I	325 NEVINS ST	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Lower	1098, 0.208, NW
AF287	CON EDISON	SACKETT ST & 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1104, 0.209, North
AF288	CON EDISON	SACKETT ST & 3RD AVE	NJ MANIFEST	Lower	1104, 0.209, North
AF289	NYCDEP	SACKETT ST & 3RD AVE	NY MANIFEST	Lower	1104, 0.209, North
AG290	473 PRESIDENT STREET	473 PRESIDENT STREET	NY BROWNFIELDS	Lower	1107, 0.210, NNW
AG291	473 PRESIDENT STREET	473 PRESIDENT STREET	NY LTANKS, NY BROWNFIELDS, NY MANIFEST	Lower	1107, 0.210, NNW
AG292	473 PRESIDENT STREET	473 PRESIDENT ST	RCRA-LQG	Lower	1107, 0.210, NNW
AF293	BELL ATLANTIC-NY	SACKETT & 3 AVE MANH	NY MANIFEST	Lower	1108, 0.210, North
AH294	CON ED	CARROLL ST & NEVINS	NY MANIFEST	Lower	1110, 0.210, NW
AH295	CON EDISON	CARROLL ST & NEVINS	NY MANIFEST	Lower	1110, 0.210, NW
AH296	CON EDISON - TRANSFO	CARROLL ST & NEVINS	NJ MANIFEST	Lower	1110, 0.210, NW
AH297	CON EDISON	CARROLL ST & NEVINS	RCRA NonGen / NLR, FINDS, ECHO	Lower	1110, 0.210, NW
AH298	CON EDISON - TRANSFO	CARROLL ST & NEVINS	RCRA-LQG	Lower	1110, 0.210, NW
AH299	CON EDISON	CARROLL ST AND NEVIN	NY MANIFEST	Lower	1110, 0.210, NW
AH300	CON EDISON	CARROLL ST & NEVINS	NJ MANIFEST	Lower	1110, 0.210, NW
AH301	CON EDISON	CARROLL ST & NEVINS	NY MANIFEST	Lower	1110, 0.210, NW
AE302	473 PRESIDENT LLC -	514 UNION ST	RCRA-LQG	Lower	1113, 0.211, NNW
AE303	514 UNION STREET	514 UNION STREET	NY BROWNFIELDS	Lower	1113, 0.211, NNW
Y304	CON EDISON SERVICE B	674 PRESIDENT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1121, 0.212, East
AI305	CON EDISON	386 2ND ST	NY MANIFEST	Higher	1122, 0.213, SE
AD306	PARK SLOPE U-HAUL RE	389 3RD AVENUE	NY AST	Lower	1129, 0.214, WSW
AC307	VERIZON NEW YORK INC	175 THIRD ST	NY MANIFEST, NY SPDES	Lower	1130, 0.214, West
AC308	VERIZON NEW YORK INC	175 THIRD STREET	NY AST	Lower	1130, 0.214, West
AC309	NEW YORK TELEPHONE C	175 THIRD ST	RCRA NonGen / NLR	Lower	1130, 0.214, West
AC310	VERIZON NEW YORK INC	175 THIRD STREET	NY UST	Lower	1130, 0.214, West
AC311	175-225 3RD STREET	175-225 3RD STREET	NY BROWNFIELDS	Lower	1130, 0.214, West

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC312	175 3RD STREET	175 3RD STREET	NY LTANKS, NY Spills	Lower	1130, 0.214, West
AJ313	CON EDISON	676 PRESIDENT ST	NY MANIFEST	Higher	1138, 0.216, East
AJ314	CON EDISON	676 PRESIDENT ST	NJ MANIFEST	Higher	1138, 0.216, East
AJ315	CON EDISON	676 PRESIDENT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1138, 0.216, East
AK316	P.S. # 51- 350 5TH A	P.S. #51 - 350 5TH A	NY LTANKS	Higher	1139, 0.216, South
AL317	CON EDISON SERVICE B	726 SACKETT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1144, 0.217, ENE
318	207 CORP	207 5TH AVENUE	NY AST	Higher	1146, 0.217, East
AG319	PRESIDENT STREET POR	469 PRESIDENT STREET	NY BROWNFIELDS	Lower	1153, 0.218, NNW
AJ320	CON EDISON	675 PRESIDENT ST	NY MANIFEST	Higher	1177, 0.223, East
AJ321	CON EDISON	675 PRESIDENT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1177, 0.223, East
AJ322	CON EDISON	675 PRESIDENT ST	NJ MANIFEST	Higher	1177, 0.223, East
AM323	A SHAMOSH	620-628 DEGRAW STREE	NY UST, NY AST	Higher	1178, 0.223, NNE
AH324	GOWANUS VILLAGE I, L	420 CARROLL STREET	NY BROWNFIELDS, NY Spills	Lower	1182, 0.224, NW
AC325	RED HOOK CRUSHERS; I	186 3RD STREET	NY SWF/LF	Lower	1184, 0.224, West
AN326	CON EDISON	664 DEGRAW ST	NJ MANIFEST	Higher	1195, 0.226, NE
AN327	CON EDISON	664 DEGRAW ST	RCRA NonGen / NLR	Higher	1195, 0.226, NE
AN328	CON EDISON	664 DEGRAW ST	NY MANIFEST	Higher	1195, 0.226, NE
AG329	VERIZON	318 NEVINS STREET	NY LTANKS, NY Spills	Lower	1199, 0.227, NW
AG330	VERIZON NEW YORK INC	318 NEVINS STREET	NY AST	Lower	1199, 0.227, NW
AG331	VERIZON NEW YORK INC	318 NEVINS STREET	NY UST	Lower	1199, 0.227, NW
AG332	NEW YORK TELEPHONE C	318 NEVINS ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	1199, 0.227, NW
AK333	NYC DEPT OF EDUCATIO	350 5TH AVE	RCRA-SQG, FINDS, ECHO	Higher	1200, 0.227, SSE
AK334	K051	350 5TH AVENUE	NY UST	Higher	1200, 0.227, SSE
AO335	CON EDISON	298 5TH ST	NY MANIFEST	Higher	1200, 0.227, South
AO336	CON EDISON SERVICE B	298 5TH ST	RCRA NonGen / NLR	Higher	1200, 0.227, South
Z337	CON ED - V 3685	522 W 44 ST	RCRA NonGen / NLR	Higher	1206, 0.228, SSW
AA338	CON EDISON SERVICE B	315 4TH ST S	RCRA NonGen / NLR, NY MANIFEST	Higher	1207, 0.229, SSE
AG339	318 NEVINS STREET	300-344 NEVINS STREE	NY BROWNFIELDS	Lower	1218, 0.231, NW
AP340	KAM SERVICE CENTER I	363 4TH AVE	NY LTANKS, NY Spills, RCRA NonGen / NLR, FINDS,...	Higher	1225, 0.232, SSW
AP341	BP SS # 13397	363 FOURTH AVENUE	NY UST	Higher	1225, 0.232, SSW
AI342	CON EDISON	391 2ND ST	NY MANIFEST	Higher	1256, 0.238, SE
AI343	CON EDISON	391 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1256, 0.238, SE
AI344	CON EDISON	391 2ND ST	NJ MANIFEST	Higher	1256, 0.238, SE
AE345	PARK SLOPE PAINT STR	553 UNION ST	RCRA-SQG, NY MANIFEST, NJ MANIFEST	Lower	1257, 0.238, NNW
AK346	CON EDISON	314 5TH ST	NY MANIFEST	Higher	1262, 0.239, South
AK347	CON EDISON - SERVICE	314 5 ST	RCRA-LQG	Higher	1262, 0.239, South
AP348	AMOCO SERVICE STATIO	375-381 4TH AVE & 6T	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1263, 0.239, SSW
AE349	563 SACKETT STREET	563 SACKETT STREET	NY BROWNFIELDS	Lower	1266, 0.240, North
AH350	CON EDISON	408 CARROL ST	NY MANIFEST	Lower	1275, 0.241, NW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AH351	CON EDISON - MANHOLE	408 CARROL ST	RCRA-LQG	Lower	1275, 0.241, NW
AL352	CON EDISON SERVICE B	195 5TH AVE FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1282, 0.243, ENE
AP353	U-HAUL CO OF METRO N	259 6TH STREET	NY UST	Higher	1284, 0.243, SSW
AP354	U-HAUL	259 6TH ST	NY LTANKS	Higher	1284, 0.243, SSW
AP355	U-HAUL CORP	259 6TH ST - PARK SL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1284, 0.243, SSW
AN356	RINALDI RECYCLING CO	182 4TH AVE.	NY SWF/LF	Higher	1285, 0.243, NNE
357	NYSDOT 3RD ST BRIDGE	3RD ST BRG OVER GOWA	RCRA NonGen / NLR	Lower	1287, 0.244, WNW
AO358	CON EDISON MANHOLE:	267 6TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1292, 0.245, SSW
AE359	A & A BRAKE CO INC	560 SACKETT STREET	NY AST	Lower	1295, 0.245, NNW
AE360	A & A BRAKE CO INC	560 SACKETT STREET	NY UST	Lower	1295, 0.245, NNW
361	SOUTH BROOKLYN REALT	301 NEVINS STREET	NY UST	Lower	1299, 0.246, NNW
362	MESSINA	392 3RD ST	NY AST	Higher	1305, 0.247, SSE
AM363	AJR (COMMERCIAL BLDG	599 DEGRAW ST	NY LTANKS	Lower	1313, 0.249, NNE
AQ364	553 SACKETT STREET	553 SACKETT STREET	NY VCP	Lower	1320, 0.250, North
AI365	401 3RD STREET	401 3RD STREET	NY LTANKS	Higher	1365, 0.259, SE
AP366	FERRANTINO & CO	278 6TH ST	NY LTANKS	Higher	1397, 0.265, SSW
367	RINALDI RECYCLING CO	326 DOUGLASS STREET	NY SWRCY	Higher	1441, 0.273, NNE
368	CARROLL ST. TRANSFER	400 CARROLL ST	NY SWF/LF	Lower	1460, 0.277, NW
AR369	GOWANUS VILLAGE I	153 2ND ST A/K/A 322	NY INST CONTROL	Lower	1465, 0.277, WNW
AS370	280 DOUGLAS ST/PENSK	280 DOUGLAS ST/PENSK	NY LTANKS	Lower	1514, 0.287, North
AS371	280 DOUGLAS ST	280 DOUGLAS STREET	NY LTANKS, NY Spills	Lower	1514, 0.287, North
372	19 BERKELEY PL	19 BERKELEY PL	NY LTANKS, NY Spills	Higher	1528, 0.289, ENE
AQ373	FULTON MUNICIPAL WOR	NEVINS, DEGRAW AND S	EDR MGP	Lower	1530, 0.290, NNW
AT374	163 6TH STREET LLC	163 6TH ST	NY SWRCY, NY MANIFEST, NY SPDES	Lower	1597, 0.302, WSW
AT375	US RECYCLING INC	141 6TH STREET	NY SWRCY, NY Spills	Lower	1602, 0.303, WSW
AR376	141 3RD STREET	141 3RD STREET	NY BROWNFIELDS	Lower	1611, 0.305, WNW
AU377	GOWANUS CANAL CONSER	2 SECOND AVE.	NY SWF/LF	Lower	1651, 0.313, West
AU378	BK6 SALT LOT COMMUNI	2 SECOND AVENUE	NY SWF/LF	Lower	1651, 0.313, West
379	SPILL NUMBER 0209206	11 LINCOLN PLACE	NY LTANKS	Higher	1661, 0.315, ENE
AV380	FULTON WORKS	DEGRAW STREET AND NE	NY VCP	Lower	1661, 0.315, NNW
AV381	FULTON WORKS	DEGRAW STREET AND NE	EDR MGP	Lower	1672, 0.317, North
382	D GAVER & SONS INC	267 DOUGLASS ST	NY LTANKS, NY UST	Lower	1692, 0.320, North
AW383	450 UNION STREET	450 UNION STREET	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1710, 0.324, NW
AX384	365 BOND STREET	365 BOND STREET	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1712, 0.324, WNW
AY385	335 BOND STREET	335 BOND STREET	NY BROWNFIELDS	Lower	1721, 0.326, NW
AW386	BAYSIDE FUEL OIL DEP	510 SACKETT ST.	NY MOSF UST	Lower	1738, 0.329, NNW
AW387	BAYSIDE FUEL OIL DEP	510 SACKETT ST	NY MOSF, NY Spills	Lower	1738, 0.329, NNW
AY388	DENTS OUT AUTO BODY	327 BOND ST	SEMS-ARCHIVE, RCRA NonGen / NLR	Lower	1743, 0.330, NW
389	THIRD STREET GOWANUS	125 3RD STREET	NY BROWNFIELDS	Lower	1769, 0.335, WNW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
390	225 6TH AVE.	225 6TH AVE	NY LTANKS	Higher	1777, 0.337, East
AT391	CONTAINER SERVICE CO	107 6TH STREET	NY SWF/LF, NY Spills, NY SPDES	Lower	1779, 0.337, WSW
AT392	106 6TH ST	106 6TH ST	NY LTANKS	Lower	1806, 0.342, WSW
AV393	CROSS BAY CONTRACTIN	242 NEVINS ST.	NY SWF/LF	Lower	1811, 0.343, NNW
AV394	ROYAL RECYCLING CORP	242 NEVINS STREET	NY SWF/LF	Lower	1811, 0.343, NNW
AV395	242 NEVINS STREET	242 NEVINS STREET	NY BROWNFIELDS, NY Spills	Lower	1811, 0.343, NNW
AX396	TOLL BROOKLYN, LP	64-98 1ST ST; 82-107	NY BROWNFIELDS	Lower	1820, 0.345, WNW
AZ397	OCEAN SUPPLY CO	437 3RD AVE	NY LTANKS	Lower	1828, 0.346, SW
AY398	388 CARROLL STREET A	388 CARROLL STREET A	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1828, 0.346, NW
BA399	BKLYN UNION GAS /CIT	6TH ST & 2ND AVE	SEMS-ARCHIVE	Lower	1835, 0.348, WSW
BA400	BUG, CITIZENS GATE S	6TH STREET AND 2ND A	NY HSWDS	Lower	1881, 0.356, WSW
AZ401	168 8TH STREET	168 8TH STREET	NY BROWNFIELDS	Lower	1921, 0.364, SW
402	126 4TH AVENUE - MIS	126 4TH AVENUE	NY LTANKS	Higher	1927, 0.365, NNE
403	236 8TH ST	236 8TH ST	NY LTANKS	Higher	1945, 0.368, SSW
404	INTERCONTINENTAL REC	??	NY SWF/LF	Lower	1957, 0.371, WSW
405	ECONOMY CLEANERS	123 5TH AVE	RCRA-VSQG, NY LTANKS, US AIRS, NY MANIFEST	Higher	1962, 0.372, ENE
BB406	233 NEVINS STREET PH	233 NEVINS STREET	NY VCP	Lower	1978, 0.375, North
407	SPILL NUMBER 9804333	705 CARROLL STREET	NY LTANKS, NY Spills	Higher	2004, 0.380, ESE
408	UNDERGROUND TANK	151-169 3RD AVE	NY LTANKS	Lower	2031, 0.385, NNE
BC409	PATTERSON CHEMICAL C	102 3RD ST	CORRACTS, RCRA NonGen / NLR, FINDS, ECHO	Lower	2079, 0.394, WNW
BD410	210 DOUGLASS STREET	210 DOUGLASS STREET	NY BROWNFIELDS	Lower	2105, 0.399, NNW
BC411	99 NORTH 4TH STREET	99 4TH STREET	NY VCP	Lower	2106, 0.399, WNW
BD412	FORMER O.Z. ELECTRIC	198 DOUGLASS STREET	NY SHWS, NY Spills	Lower	2136, 0.405, NNW
BB413	233 NEVINS STREET	236 BUTLER STREET	NY VCP	Lower	2143, 0.406, North
414	BALTIC RECYCLING COR	524-26 BALTIC STREET	NY SWF/LF	Lower	2144, 0.406, North
BB415	234 BUTLER STREET	234 BUTLER STREET	NY BROWNFIELDS	Lower	2152, 0.408, North
BE416	424 5TH AVENUE	424 5TH STREET	NY LTANKS	Higher	2163, 0.410, SSE
BD417	GOWANUS CANAL SITE	GOWANUS CANAL	NY SHWS	Lower	2202, 0.417, NNW
418	IESI (110 5TH ST.)(S	110 5TH STREET	NY SWF/LF, NY Spills	Lower	2216, 0.420, West
419	572 WARREN ST. HOUSE	572 WARREN ST	NY LTANKS, NY Spills	Higher	2234, 0.423, NNE
BE420	442 5TH ST	442 5TH ST	NY LTANKS	Higher	2300, 0.436, SSE
BF421	SPILL NUMBER 0212934	233 BUTLER ST	NY LTANKS	Lower	2308, 0.437, North
BG422	74-76 SOUTH SECOND S	74-76 SECOND STREET	NY VCP	Higher	2314, 0.438, WNW
423	124 LINCOLN PLACE	124 LINCOLN PLACE	NY LTANKS	Higher	2328, 0.441, East
BE424	APARTMENT BUILDING	446 5TH ST	NY LTANKS	Higher	2334, 0.442, SSE
425	US POST OFFICE	198 7TH AVENUE	NY LTANKS, NY Spills	Higher	2362, 0.447, SE
BH426	66 FOURTH STREET	66 4TH STREET	NY LTANKS, NY UST	Lower	2382, 0.451, West
427	STELLAR 341 LLC	341 10TH STREET	NY LTANKS, NY UST, NY AST	Higher	2403, 0.455, SSW
428	CVS PHARMACY #2498	341 9TH ST	SEMS-ARCHIVE, RCRA-VSQG	Higher	2407, 0.456, South

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BG429	DEL'S AUTO REPAIR	70 2ND ST/NEW UTRECH	NY LTANKS	Higher	2409, 0.456, WNW
430	GOWANUS HOUSING COMP	238 BOND ST	NY LTANKS	Lower	2419, 0.458, NNW
431	TTF	300 10TH ST	NY LTANKS	Higher	2435, 0.461, SSW
432	79-97 4TH AVENUE	85 4TH AVENUE	NY VCP	Higher	2467, 0.467, NNE
BH433	425 HOYT STREET	419-429 HOYT STREET	NY BROWNFIELDS	Lower	2484, 0.470, WNW
BF434	BASIN HAULAGE INC. I	462-470 BALTIC STREE	NY SWF/LF	Lower	2490, 0.472, North
435	125 THIRD AVENUE	125 3RD AVENUE	NY VCP	Higher	2520, 0.477, NNE
436	WYCKOFF GARDENS	185 NEVINS ST	NY LTANKS	Lower	2522, 0.478, North
437	SINSI RESIDENCE	112 ST MARKS PL	NY LTANKS	Higher	2532, 0.480, NE
438	498 3RD AVENUE	498 3RD AVENUE	NY LTANKS	Lower	2633, 0.499, SW
BI439	K - METROPOLITAN MGP	124-136 SECOND AVE	NY SHWS, NY BROWNFIELDS	Lower	2846, 0.539, WSW
BI440	BU-METROPOLITAN MGP	124-136 SECOND AVE	EDR MGP	Lower	2846, 0.539, WSW
441	FORMER CITIZEN GAS W	5TH STREET AND SMITH	EDR MGP	Lower	2972, 0.563, West
442	CARROLL GARDENS	CORNER OF 5TH STREET	NY DEL SHWS	Higher	3139, 0.595, WNW
443	USPS GOWANUS SITE. F	2ND AVENUE AND 12TH	EDR MGP	Lower	3369, 0.638, WSW
444	FORMER BARRETT MANUF	627 SMITH ST.	NY SHWS, NY BROWNFIELDS	Lower	4584, 0.868, WSW
BJ445	182 SIGOURNEY ST	182 SIGOURNEY ST	NY SHWS	Lower	4808, 0.911, WSW
BJ446	CHEMTURA 633 COURT S	633 COURT STREET	NY SHWS	Lower	4846, 0.918, WSW
BK447	643 COURT ST.	643 COURT ST.	NY SHWS	Lower	5020, 0.951, WSW
BK448	CHEM TURA	688-700 COURT ST	NY CBS UST, NY CBS, NY AST, NY DEL SHWS, RCRA...	Lower	5052, 0.957, WSW
449	SUNSET INDUSTRIAL PA	74 20TH ST	CORRACTS, RCRA-TSDF, RCRA-LQG, NY BROWNFIELDS,...	Lower	5149, 0.975, SW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
MAACO AUTO PAINTING 296 4TH AVE. BROOKLYN, NY 11215	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110001593339 FINDS Registry ID:: 110001593339 ECHO Registry ID: 110001593339	N/A
JEN JAY TRANSMISSION 296 4TH AVE BROOKLYN, NY 11215	EDR Hist Auto	N/A
MAACO AUTO PAINTING 296 4TH AVE & 1ST ST BROOKLYN, NY 11215	RCRA NonGen / NLR EPA ID:: NYD986925642 FINDS Registry ID:: 110008043900 ECHO Registry ID: 110008043900 NY MANIFEST EPA ID: NYD986925642	NYD986925642

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

EXECUTIVE SUMMARY

Federal institutional controls / engineering controls registries

LUCIS---------- Land Use Control Information System

Federal ERNS list

ERNS---------- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST---------- Underground Storage Tank Listing
NY CBS AST---------- Chemical Bulk Storage Database
NY MOSF AST---------- Major Oil Storage Facilities Database
INDIAN UST---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL---------- Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE---------- Registered Waste Tire Storage & Facility List
INDIAN ODI---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9---------- Torres Martinez Reservation Illegal Dump Site Locations
ODI---------- Open Dump Inventory
IHS OPEN DUMPS---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL---------- Delisted National Clandestine Laboratory Register
US CDL---------- National Clandestine Laboratory Register
NY PFAS---------- PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST---------- Historical Petroleum Bulk Storage Database

NY HIST AST - Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS - Spill Liens Information
LIENS 2 - CERCLA Lien Information

Records of Emergency Release Reports

HMIRS - Hazardous Materials Information Reporting System
NY Hist Spills - SPILLS Database
NY SPILLS 90 - SPILLS 90 data from FirstSearch
NY SPILLS 80 - SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS - Formerly Used Defense Sites
DOD - Department of Defense Sites
SCRD DRYCLEANERS - State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR - Financial Assurance Information
EPA WATCH LIST - EPA WATCH LIST
2020 COR ACTION - 2020 Corrective Action Program List
TSCA - Toxic Substances Control Act
TRIS - Toxic Chemical Release Inventory System
SSTS - Section 7 Tracking Systems
RMP - Risk Management Plans
RAATS - RCRA Administrative Action Tracking System
PADS - PCB Activity Database System
FTTS - FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS - Material Licensing Tracking System
COAL ASH DOE - Steam-Electric Plant Operation Data
COAL ASH EPA - Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER - PCB Transformer Registration Database
RADINFO - Radiation Information Database
HIST FTTS - FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS - Incident and Accident Data
CONSENT - Superfund (CERCLA) Consent Decrees
INDIAN RESERV - Indian Reservations
FUSRAP - Formerly Utilized Sites Remedial Action Program
UMTRA - Uranium Mill Tailings Sites
LEAD SMELTERS - Lead Smelter Sites
US MINES - Mines Master Index File
ABANDONED MINES - Abandoned Mines
DOCKET HWC - Hazardous Waste Compliance Docket Listing
UXO - Unexploded Ordnance Sites
FUELS PROGRAM - EPA Fuels Program Registered Listing
NY AIRS - Air Emissions Data
NY COAL ASH - Coal Ash Disposal Site Listing
NY Financial Assurance - Financial Assurance Information Listing
NY VAPOR REOPENED - Vapor Intrusion Legacy Site List
NY UIC - Underground Injection Control Wells
MINES MRDS - Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS - Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 07/26/2022 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL Cerclis ID:: 206222 EPA Id: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***15***

Lists of Federal sites subject to CERCLA removals and CERCLA orders

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 07/26/2022 has revealed that there is 1 SEMS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL Site ID: 0206222 EPA Id: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***15***

EXECUTIVE SUMMARY

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 07/26/2022 has revealed that there are 3 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #2498 Site ID: 0201536 EPA Id: NYD042777128	***341 9TH ST***	***S 1/4 - 1/2 (0.456 mi.)***	***428***	***1338***

Lower Elevation	Address	Direction / Distance	Map ID	Page
DENTS OUT AUTO BODY Site ID: 0203501 EPA Id: NYD986961167	***327 BOND ST***	***NW 1/4 - 1/2 (0.330 mi.)***	***AY388***	***1192***
BKLYN UNION GAS /CIT Site ID: 0201995 EPA Id: NYD980532212	6TH ST & 2ND AVE	WSW 1/4 - 1/2 (0.348 mi.)	BA399	1255

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 06/20/2022 has revealed that there are 2 CORRACTS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PATTERSON CHEMICAL C EPA ID:: NYD980592471	***102 3RD ST***	***WNW 1/4 - 1/2 (0.394 mi.)***	***BC409***	***1284***
SUNSET INDUSTRIAL PA EPA ID:: NYD091590471	***74 20TH ST***	***SW 1/2 - 1 (0.975 mi.)***	***449***	***1407***

EXECUTIVE SUMMARY

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 14 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
275 FOURTH AVENUE DE EPA ID:: NYD986914133	275 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A13	68
CON EDISON - SERVICE EPA ID:: NYP005093950	328 2ND ST	SSE 0 - 1/8 (0.102 mi.)	D165	372
204 4TH AVE LLC - BC EPA ID:: NYR000255687	204 4TH AVE	NNE 1/8 - 1/4 (0.161 mi.)	O218	514
CON EDISON - SERVICE EPA ID:: NYP004363230	314 5 ST	S 1/8 - 1/4 (0.239 mi.)	AK347	1014

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - 3RD AVE EPA ID:: NYD000706218	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A33***	***107***
CON EDISON - OTHER - EPA ID:: NYP004851131	222 1 ST	W 0 - 1/8 (0.027 mi.)	A49	168
PS 418 K SCHOOL EPA ID:: NYR000199968	***512 CARROLL ST***	***N 0 - 1/8 (0.038 mi.)***	***C94***	***247***
CON EDISON - SERVICE EPA ID:: NYP005136561	302 3RD AVE	NW 0 - 1/8 (0.108 mi.)	L174	393
CON EDISON - SERVICE EPA ID:: NYP005072996	484 PRESIDENT ST	NW 1/8 - 1/4 (0.182 mi.)	W251	672
CON EDISON - EXCAVAT EPA ID:: NYP005022769	232 3RD AVE	N 1/8 - 1/4 (0.205 mi.)	AF276	756
473 PRESIDENT STREET EPA ID:: NYR000232116	473 PRESIDENT ST	NNW 1/8 - 1/4 (0.210 mi.)	AG292	813
CON EDISON - TRANSFO EPA ID:: NYP004734786	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH298	825
473 PRESIDENT LLC - EPA ID:: NYR000253203	514 UNION ST	NNW 1/8 - 1/4 (0.211 mi.)	AE302	832
CON EDISON - MANHOLE EPA ID:: NYP004342978	408 CARROL ST	NW 1/8 - 1/4 (0.241 mi.)	AH351	1026

EXECUTIVE SUMMARY

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 5 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - 4TH AVE G EPA ID:: NYR000250654	276 4TH AVE	ENE 0 - 1/8 (0.019 mi.)	A9	51
SUSAN MAINTENANCE EPA ID:: NYR000076091	***374 4TH AVE***	***SSW 1/8 - 1/4 (0.187 mi.)***	***Z259***	***692***
NYC DEPT OF EDUCATIO EPA ID:: NYR000198952	***350 5TH AVE***	***SSE 1/8 - 1/4 (0.227 mi.)***	***AK333***	***922***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CRUSADER CANDLE CO I EPA ID:: NYD987005840	***325 NEVINS ST***	***NW 1/8 - 1/4 (0.208 mi.)***	***W286***	***791***
PARK SLOPE PAINT STR EPA ID:: NYR000170472	***553 UNION ST***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AE345***	***995***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 4 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HESS#32530 EPA ID:: NYD982185563	***204-222 FOURTH AVE***	***NNE 1/8 - 1/4 (0.161 mi.)***	***O220***	***545***
JORDAN MALACHIE CLEA EPA ID:: NYR000087486	***295 5TH AVE***	***SE 1/8 - 1/4 (0.175 mi.)***	***U242***	***647***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LINDA TOOL & DIE COR EPA ID:: NYD987025822	***459 CARROLL ST***	***NW 1/8 - 1/4 (0.142 mi.)***	***L206***	***483***
NEW YORK TELEPHONE C EPA ID:: NYD987028016	***318 NEVINS ST***	***NW 1/8 - 1/4 (0.227 mi.)***	***AG332***	***917***

Federal institutional controls / engineering controls registries

US ENG CONTROLS: A listing of sites with engineering controls in place.

A review of the US ENG CONTROLS list, as provided by EDR, and dated 05/16/2022 has revealed that there is 1 US ENG CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL EPA ID:: NYN000206222 EPA ID:: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***15***

US INST CONTROLS: A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

A review of the US INST CONTROLS list, as provided by EDR, and dated 05/16/2022 has revealed that there is 1 US INST CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL EPA ID:: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***15***

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 7 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER O.Z. ELECTRIC Site Code: 450318	***198 DOUGLASS STREET***	***NNW 1/4 - 1/2 (0.405 mi.)***	***BD412***	***1301***
GOWANUS CANAL SITE Site Code: 406956 Class Code: Significant threat to the public health or environment - action required.	GOWANUS CANAL	NNW 1/4 - 1/2 (0.417 mi.)	BD417	1310
K - METROPOLITAN MGP Site Code: 372656 Class Code: Significant threat to the public health or environment - action required.	***124-136 SECOND AVE***	***WSW 1/2 - 1 (0.539 mi.)***	***BI439***	***1365***
FORMER BARRETT MANUF Site Code: 466165	***627 SMITH ST.***	***WSW 1/2 - 1 (0.868 mi.)***	***444***	***1373***
182 SIGOURNEY ST Site Code: 499845	182 SIGOURNEY ST	WSW 1/2 - 1 (0.911 mi.)	BJ445	1378
CHEMTURA 633 COURT S	633 COURT STREET	WSW 1/2 - 1 (0.918 mi.)	BJ446	1380

Site Code: 443256
Class Code: Significant threat to the public health or environment - action required.

643 COURT ST. | 643 COURT ST. | WSW 1/2 - 1 (0.951 mi.) | BK447 | 1384
Site Code: 498440

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 06/29/2022 has revealed that there are 14 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON CO. OF NY	3RD AVE (BET. 3RD &	S 0 - 1/8 (0.068 mi.)	D130	314
RINALDI RECYCLING CO	182 4TH AVE.	NNE 1/8 - 1/4 (0.243 mi.)	AN356	1044

Lower Elevation	Address	Direction / Distance	Map ID	Page
3RD AVE FLUSH TRUCK	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A64	193
RED HOOK CRUSHERS; I	186 3RD STREET	W 1/8 - 1/4 (0.224 mi.)	AC325	894
CARROLL ST. TRANSFER	400 CARROLL ST	NW 1/4 - 1/2 (0.277 mi.)	368	1068
GOWANUS CANAL CONSER	2 SECOND AVE.	W 1/4 - 1/2 (0.313 mi.)	AU377	1112
BK6 SALT LOT COMMUNI	2 SECOND AVENUE	W 1/4 - 1/2 (0.313 mi.)	AU378	1112
CONTAINER SERVICE CO	***107 6TH STREET***	***WSW 1/4 - 1/2 (0.337 mi.)***	***AT391***	***1201***
CROSS BAY CONTRACTIN	242 NEVINS ST.	NNW 1/4 - 1/2 (0.343 mi.)	AV393	1212
ROYAL RECYCLING CORP	242 NEVINS STREET	NNW 1/4 - 1/2 (0.343 mi.)	AV394	1213
INTERCONTINENTAL REC	??	WSW 1/4 - 1/2 (0.371 mi.)	404	1272
BALTIC RECYCLING COR	524-26 BALTIC STREET	N 1/4 - 1/2 (0.406 mi.)	414	1306
IESI (110 5TH ST.)(S	***110 5TH STREET***	***W 1/4 - 1/2 (0.420 mi.)***	***418***	***1313***
BASIN HAULAGE INC. I	462-470 BALTIC STREE	N 1/4 - 1/2 (0.472 mi.)	BF434	1360

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 42 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERRITT GAS STATION	***204-222 4TH AVENUE***	***NNE 1/8 - 1/4 (0.161 mi.)***	***O221***	***552***
Spill Number/Closed Date: 9515732 / 1997-06-11				
Site ID: 204687				
Spill Date: 1996-03-07				
4TH & SACKETT STREET	4TH & SACKETT STREET	NE 1/8 - 1/4 (0.167 mi.)	X230	586
Spill Number/Closed Date: 9113310 / 1994-08-03				

Site ID: 221268 Spill Date: 1992-03-31				
P.S. # 51- 350 5TH A Spill Number/Closed Date: 9409320 / 1995-02-06 Site ID: 105617 Spill Date: 1994-10-12	P.S. #51 - 350 5TH A	S 1/8 - 1/4 (0.216 mi.)	AK316	867
KAM SERVICE CENTER I Spill Number/Closed Date: 8901904 / 2016-02-04 Site ID: 90896 Spill Date: 1989-05-24	***363 4TH AVE***	***SSW 1/8 - 1/4 (0.232 mi.)***	***AP340***	***940***
U-HAUL Spill Number/Closed Date: 9412186 / 2006-03-13 Site ID: 225909 Spill Date: 1994-12-12	259 6TH ST	SSW 1/8 - 1/4 (0.243 mi.)	AP354	1036
401 3RD STREET Spill Number/Closed Date: 9310090 / 1993-11-19 Site ID: 244717 Spill Date: 1993-11-11	401 3RD STREET	SE 1/4 - 1/2 (0.259 mi.)	AI365	1064
FERRANTINO & CO Spill Number/Closed Date: 9705330 / 2011-08-01 Site ID: 304152 Spill Date: 1997-08-01	278 6TH ST	SSW 1/4 - 1/2 (0.265 mi.)	AP366	1065
19 BERKELEY PL Spill Number/Closed Date: 0209599 / 2002-12-18 Site ID: 238174 Spill Date: 2002-12-18	***19 BERKELEY PL***	***ENE 1/4 - 1/2 (0.289 mi.)***	***372***	***1101***
SPILL NUMBER 0209206 Spill Number/Closed Date: 0209206 / 2004-04-16 Site ID: 156887 Spill Date: 2002-12-07	11 LINCOLN PLACE	ENE 1/4 - 1/2 (0.315 mi.)	379	1113
225 6TH AVE. Spill Number/Closed Date: 8705973 / 1992-11-19 Site ID: 163112 Spill Date: 1987-10-15	225 6TH AVE	E 1/4 - 1/2 (0.337 mi.)	390	1200
126 4TH AVENUE - MIS Spill Number/Closed Date: 9505523 / 2013-01-17 Site ID: 261276 Spill Date: 1995-08-03	126 4TH AVENUE	NNE 1/4 - 1/2 (0.365 mi.)	402	1264
236 8TH ST Spill Number/Closed Date: 9508664 / 1995-10-16 Site ID: 211107 Spill Date: 1995-10-15	236 8TH ST	SSW 1/4 - 1/2 (0.368 mi.)	403	1271
ECONOMY CLEANERS Spill Number/Closed Date: 0507654 / 2005-11-30 Site ID: 353099 Spill Date: 2005-09-26	***123 5TH AVE***	***ENE 1/4 - 1/2 (0.372 mi.)***	***405***	***1273***
SPILL NUMBER 9804333 Spill Number/Closed Date: 9311807 / 1994-01-05 Site ID: 213345 Spill Date: 1994-01-05	***705 CARROLL STREET***	***ESE 1/4 - 1/2 (0.380 mi.)***	***407***	***1279***
424 5TH AVENUE	424 5TH STREET	SSE 1/4 - 1/2 (0.410 mi.)	BE416	1309

Spill Number/Closed Date: 9412686 / 1994-12-21
Site ID: 306765
Spill Date: 1994-12-21

572 WARREN ST. HOUSE	***572 WARREN ST***	***NNE 1/4 - 1/2 (0.423 mi.)***	***419***	***1315***
Spill Number/Closed Date: 9105220 / 2005-03-08 Site ID: 115495 Spill Date: 1991-08-14				
442 5TH ST	442 5TH ST	SSE 1/4 - 1/2 (0.436 mi.)	BE420	1318
Spill Number/Closed Date: 9107178 / 1991-10-10 Site ID: 271727 Spill Date: 1991-10-03				
124 LINCOLN PLACE	124 LINCOLN PLACE	E 1/4 - 1/2 (0.441 mi.)	423	1320
Spill Number/Closed Date: 9502716 / 1995-06-02 Site ID: 145166 Spill Date: 1995-06-02				
APARTMENT BUILDING	446 5TH ST	SSE 1/4 - 1/2 (0.442 mi.)	BE424	1321
Spill Number/Closed Date: 0410001 / 2005-10-28 Site ID: 334901 Spill Date: 2004-12-03				
US POST OFFICE	***198 7TH AVENUE***	***SE 1/4 - 1/2 (0.447 mi.)***	***425***	***1323***
Spill Number/Closed Date: 9007536 / 2009-10-06 Site ID: 92521 Spill Date: 1990-10-10				
STELLAR 341 LLC	***341 10TH STREET***	***SSW 1/4 - 1/2 (0.455 mi.)***	***427***	***1332***
Spill Number/Closed Date: 0413183 / 2005-11-09 Site ID: 339044 Spill Date: 2004-04-09				
DEL'S AUTO REPAIR	70 2ND ST/NEW UTRECH	WNW 1/4 - 1/2 (0.456 mi.)	BG429	1352
Spill Number/Closed Date: 9713407 / 2003-03-03 Site ID: 319396 Spill Date: 1998-03-03				
TTF	300 10TH ST	SSW 1/4 - 1/2 (0.461 mi.)	431	1356
Spill Number/Closed Date: 1406432 / 2014-11-13 Site ID: 499901 Spill Date: 2014-09-16				
SINSI RESIDENCE	112 ST MARKS PL	NE 1/4 - 1/2 (0.480 mi.)	437	1362
Spill Number/Closed Date: 9600499 / 1996-04-11 Site ID: 208826 Spill Date: 1996-04-10				

Lower Elevation	Address	Direction / Distance	Map ID	Page
540 PRESIDENT STREET	540 PRESIDENT STREET	N 0 - 1/8 (0.087 mi.)	I151	353
Spill Number/Closed Date: 9211878 / 1993-01-18 Site ID: 262667 Spill Date: 1993-01-18				
ALL BORO'S	200 3RD ST	W 1/8 - 1/4 (0.180 mi.)	R247	666
Spill Number/Closed Date: 9702117 / 1999-08-22 Site ID: 253671 Spill Date: 1997-05-19				
325 NEVINS STREET	325 NEVINS STREET	NW 1/8 - 1/4 (0.208 mi.)	W285	789

Spill Number/Closed Date: 9501568 / 1995-05-08
Spill Number/Closed Date: 9508359 / 1995-10-09
Site ID: 266812
Site ID: 266813
Spill Date: 1995-05-08
Spill Date: 1995-10-09

473 PRESIDENT STREET ***473 PRESIDENT STREET*** ***NNW 1/8 - 1/4 (0.210 mi.)*** ***AG291*** ***808***
Spill Number/Closed Date: 9412605 / Not Reported
Site ID: 323409
Spill Date: 1994-12-20

175 3RD STREET ***175 3RD STREET*** ***W 1/8 - 1/4 (0.214 mi.)*** ***AC312*** ***859***
Spill Number/Closed Date: 9208180 / 1992-10-15
Site ID: 103805
Spill Date: 1992-10-14

VERIZON ***318 NEVINS STREET*** ***NW 1/8 - 1/4 (0.227 mi.)*** ***AG329*** ***901***
Spill Number/Closed Date: 0306012 / 2003-10-02
Site ID: 164586
Spill Date: 2003-09-06

AJR (COMMERCIAL BLDG 599 DEGRAW ST NNE 1/8 - 1/4 (0.249 mi.) AM363 1062
Spill Number/Closed Date: 0500453 / 2005-04-28
Site ID: 343388
Spill Date: 2005-04-11

280 DOUGLAS ST/PENSK 280 DOUGLAS ST/PENSK N 1/4 - 1/2 (0.287 mi.) AS370 1095
Spill Number/Closed Date: 9112095 / 1992-03-03
Site ID: 280189
Spill Date: 1992-02-25

280 DOUGLAS ST ***280 DOUGLAS STREET*** ***N 1/4 - 1/2 (0.287 mi.)*** ***AS371*** ***1097***
Spill Number/Closed Date: 9410669 / 1995-03-10
Site ID: 160988
Spill Date: 1994-11-10

D GAVER & SONS INC ***267 DOUGLASS ST*** ***N 1/4 - 1/2 (0.320 mi.)*** ***382*** ***1116***
Spill Number/Closed Date: 8800904 / 1992-10-02
Site ID: 104086
Spill Date: 1988-04-28

106 6TH ST 106 6TH ST WSW 1/4 - 1/2 (0.342 mi.) AT392 1211
Spill Number/Closed Date: 9502574 / 1995-05-31
Site ID: 153670
Spill Date: 1995-05-31

OCEAN SUPPLY CO 437 3RD AVE SW 1/4 - 1/2 (0.346 mi.) AZ397 1221
Spill Number/Closed Date: 9905579 / 1999-09-22
Site ID: 306200
Spill Date: 1999-08-06

UNDERGROUND TANK 151-169 3RD AVE NNE 1/4 - 1/2 (0.385 mi.) 408 1281
Spill Number/Closed Date: 1402248 / 2014-07-09
Spill Number/Closed Date: 0902974 / 2009-08-18
Site ID: 495561
Site ID: 415051
Spill Date: 2014-06-02
Spill Date: 2009-06-12

SPILL NUMBER 0212934 233 BUTLER ST N 1/4 - 1/2 (0.437 mi.) BF421 1319
Spill Number/Closed Date: 0212934 / 2003-09-03

Site ID: 180335
Spill Date: 2003-03-31

66 FOURTH STREET	***66 4TH STREET***	***W 1/4 - 1/2 (0.451 mi.)***	***BH426***	***1327***
Spill Number/Closed Date: 0106619 / 2003-11-17 Site ID: 228322 Spill Date: 2001-09-25				
GOWANUS HOUSING COMP	238 BOND ST	NNW 1/4 - 1/2 (0.458 mi.)	430	1353
Spill Number/Closed Date: 0201330 / 2005-12-23 Spill Number/Closed Date: 0201191 / 2008-09-23 Site ID: 197021 Site ID: 224675 Spill Date: 2002-05-06 Spill Date: 2002-05-01				
WYCKOFF GARDENS	185 NEVINS ST	N 1/4 - 1/2 (0.478 mi.)	436	1361
Spill Number/Closed Date: 9811464 / 1999-05-14 Site ID: 237645 Spill Date: 1998-12-11				
498 3RD AVENUE	498 3RD AVENUE	SW 1/4 - 1/2 (0.499 mi.)	438	1363
Spill Number/Closed Date: 8809911 / 2021-08-31 Site ID: 66897 Spill Date: 1989-03-14				

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 19 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NORTH PETROLEUM CORP	***275 FOURTH AVE***	***ESE 0 - 1/8 (0.026 mi.)***	***A14***	***73***
Database: UST, Date of Government Version: 06/21/2022				
ROMAN CATHOLIC CHURC	522 CARROLL ST	NNE 0 - 1/8 (0.036 mi.)	C91	241
Database: UST, Date of Government Version: 06/21/2022				
PARKSIDE SERVICE CEN	340 4TH AVENUE	SSW 0 - 1/8 (0.119 mi.)	P183	414
Database: UST, Date of Government Version: 06/21/2022				
PEP BOYS #0247	354 4TH AVENUE	SSW 1/8 - 1/4 (0.142 mi.)	P202	468
Database: UST, Date of Government Version: 06/21/2022				
SPEEDWAY # 7835	204-222 FOURTH AVENU	NNE 1/8 - 1/4 (0.161 mi.)	O219	516
Database: UST, Date of Government Version: 06/21/2022				
343 4TH AVENUE	343 4TH AVENUE	SSW 1/8 - 1/4 (0.179 mi.)	Z246	660
Database: UST, Date of Government Version: 06/21/2022				
SUSAN MAINTENANCE CO	374 4TH AVENUE	SSW 1/8 - 1/4 (0.187 mi.)	Z258	690
Database: UST, Date of Government Version: 06/21/2022				
A SHAMOSH	***620-628 DEGRAW STREE***	***NNE 1/8 - 1/4 (0.223 mi.)***	***AM323***	***884***
Database: UST, Date of Government Version: 06/21/2022				
K051	350 5TH AVENUE	SSE 1/8 - 1/4 (0.227 mi.)	AK334	925
Database: UST, Date of Government Version: 06/21/2022				

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BP SS # 13397 Database: UST, Date of Government Version: 06/21/2022	363 FOURTH AVENUE	SSW 1/8 - 1/4 (0.232 mi.)	AP341	977
U-HAUL CO OF METRO N Database: UST, Date of Government Version: 06/21/2022	259 6TH STREET	SSW 1/8 - 1/4 (0.243 mi.)	AP353	1033

Lower Elevation	Address	Direction / Distance	Map ID	Page
P.S. 372 (OUR LADY O Database: UST, Date of Government Version: 06/21/2022	512 CARROLL STREET	N 0 - 1/8 (0.038 mi.)	C97	261
CLARIN TRUCK LEASING Database: UST, Date of Government Version: 06/21/2022	312 3RD AVE	WNW 0 - 1/8 (0.107 mi.)	F172	388
617 SACKETT STREET R Database: UST, Date of Government Version: 06/21/2022	617 SACKETT STREET	NNE 1/8 - 1/4 (0.200 mi.)	T271	742
220 3RD STREET Database: UST, Date of Government Version: 06/21/2022	220 3RD STREET	WSW 1/8 - 1/4 (0.201 mi.)	AD272	744
VERIZON NEW YORK INC Database: UST, Date of Government Version: 06/21/2022	175 THIRD STREET	W 1/8 - 1/4 (0.214 mi.)	AC310	852
VERIZON NEW YORK INC Database: UST, Date of Government Version: 06/21/2022	318 NEVINS STREET	NW 1/8 - 1/4 (0.227 mi.)	AG331	915
A & A BRAKE CO INC Database: UST, Date of Government Version: 06/21/2022	560 SACKETT STREET	NNW 1/8 - 1/4 (0.245 mi.)	AE360	1054
SOUTH BROOKLYN REALT Database: UST, Date of Government Version: 06/21/2022	301 NEVINS STREET	NNW 1/8 - 1/4 (0.246 mi.)	361	1056

NY MOSF UST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY MOSF UST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP	510 SACKETT ST.	NNW 1/4 - 1/2 (0.329 mi.)	AW386	1184

NY MOSF: These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

A review of the NY MOSF list, as provided by EDR, and dated 06/21/2022 has revealed that there is 1 NY MOSF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP Tank Status: Unregulated/Closed Facility Id: 2-1220	***510 SACKETT ST***	***NNW 1/4 - 1/2 (0.329 mi.)***	***AW387***	***1186***

EXECUTIVE SUMMARY

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 06/21/2022 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PEP BOYS #0247	***354 4TH AVE***	***SSW 1/8 - 1/4 (0.142 mi.)***	***P204***	***481***
Facility Status: Unregulated/Closed CBS Number: 2-000417				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 23 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NORTH PETROLEUM CORP	***275 FOURTH AVE***	***ESE 0 - 1/8 (0.026 mi.)***	***A14***	***73***
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-241849				
L&B AUTO REPAIR CORP	245 4TH AVENUE	ENE 0 - 1/8 (0.066 mi.)	H128	312
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-606714				
2 FAMILY HOUSE	557 CARROLL ST	ENE 0 - 1/8 (0.073 mi.)	H135	321
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-201928				
PEP BOYS #0247	354 4TH AVENUE	SSW 1/8 - 1/4 (0.142 mi.)	P201	466
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-032301				
PEP BOYS #0247	354 4TH AVE	SSW 1/8 - 1/4 (0.142 mi.)	P205	482
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-000417				
SUSAN MAINTENANCE CO	374 4TH AVENUE	SSW 1/8 - 1/4 (0.187 mi.)	Z261	714
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-611328				
32 UNIT 4 STORY WALK	325 1ST STREET	ESE 1/8 - 1/4 (0.194 mi.)	U265	728
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-252794				
640 CARROLL LLC	640 CARROLL STREET	ESE 1/8 - 1/4 (0.197 mi.)	V269	736
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-608751				
670 PRESIDENT ST HOU	670 PRESIDENT STREET	E 1/8 - 1/4 (0.204 mi.)	Y275	754
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-254460				
BHW NV ASSOCIATES	321 FIFTH AVENUE	SSE 1/8 - 1/4 (0.208 mi.)	AA282	767
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-291412				
207 CORP	207 5TH AVENUE	E 1/8 - 1/4 (0.217 mi.)	318	872
Database: AST, Date of Government Version: 06/21/2022				

Facility Id: 2-257176

A SHAMOSH	***620-628 DEGRAW STREE***	***NNE 1/8 - 1/4 (0.223 mi.)***	***AM323***	***884***
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-611758				
MESSINA	392 3RD ST	SSE 1/8 - 1/4 (0.247 mi.)	362	1060
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-272094				

Lower Elevation	Address	Direction / Distance	Map ID	Page
P.S. 372 (OUR LADY O	512 CARROLL STREET	N 0 - 1/8 (0.038 mi.)	C96	259
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-267562				
505 CARROLL ST.	505 CARROLL STREET	NNW 0 - 1/8 (0.074 mi.)	I136	324
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-602516				
L.L.L. AUTO REPAIR I	528 PRESIDENT STREET	NNW 0 - 1/8 (0.104 mi.)	I169	380
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-610816				
276 3RD AVENUE	276 THIRD AVENUE	NNW 1/8 - 1/4 (0.129 mi.)	Q189	435
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-608461				
HOLYLAND AUTO REPAIR	637 UNION STREET	NNE 1/8 - 1/4 (0.151 mi.)	T209	491
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-605796				
RIDGE COMPLETE AUTO	264 THIRD AVENUE	NNW 1/8 - 1/4 (0.151 mi.)	Q210	493
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-611243				
PARK SLOPE U-HAUL RE	389 3RD AVENUE	WSW 1/8 - 1/4 (0.214 mi.)	AD306	844
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-612146				
VERIZON NEW YORK INC	175 THIRD STREET	W 1/8 - 1/4 (0.214 mi.)	AC308	847
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-344133				
VERIZON NEW YORK INC	318 NEVINS STREET	NW 1/8 - 1/4 (0.227 mi.)	AG330	915
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-344265				
A & A BRAKE CO INC	560 SACKETT STREET	NNW 1/8 - 1/4 (0.245 mi.)	AE359	1051
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-604492				

NY TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the NY TANKS list, as provided by EDR, has revealed that there are 2 NY TANKS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
THIRD AVENUE YARD	***222 FIRST STREET***	***W 0 - 1/8 (0.027 mi.)***	***A71***	***205***
Database: TANKS, Date of Government Version: 06/21/2022				

Facility Id: 2-452726
Site Status: Active

SJ FUEL CO. INC. 601 UNION STREET N 1/8 - 1/4 (0.168 mi.) S231 587
Database: TANKS, Date of Government Version: 06/21/2022
Facility Id: 2-601627
Site Status: Active

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 4 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
190-220 THIRD STREET Site Code: 333299	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***607***
450 UNION STREET Site Code: 507633	***450 UNION STREET***	***NW 1/4 - 1/2 (0.324 mi.)***	***AW383***	***1120***
365 BOND STREET Site Code: 478842	***365 BOND STREET***	***WNW 1/4 - 1/2 (0.324 mi.)***	***AX384***	***1146***
388 CARROLL STREET A Site Code: 478612	***388 CARROLL STREET A***	***NW 1/4 - 1/2 (0.346 mi.)***	***AY398***	***1223***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 05/09/2022 has revealed that there are 5 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
190-220 THIRD STREET Site Code: 333299	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***607***
GOWANUS VILLAGE I Site Code: 332623	153 2ND ST A/K/A 322	WNW 1/4 - 1/2 (0.277 mi.)	AR369	1069
450 UNION STREET Site Code: 507633	***450 UNION STREET***	***NW 1/4 - 1/2 (0.324 mi.)***	***AW383***	***1120***
365 BOND STREET Site Code: 478842	***365 BOND STREET***	***WNW 1/4 - 1/2 (0.324 mi.)***	***AX384***	***1146***
388 CARROLL STREET A Site Code: 478612	***388 CARROLL STREET A***	***NW 1/4 - 1/2 (0.346 mi.)***	***AY398***	***1223***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 13 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
275 4TH AVENUE Database: VCP NYC, Date of Government Version: 06/06/2022	275 4TH AVENUE	ESE 0 - 1/8 (0.026 mi.)	A16	87
269-271 4TH AVENUE Database: VCP NYC, Date of Government Version: 06/06/2022	271 4TH AVENUE	ESE 0 - 1/8 (0.026 mi.)	A20	90
566 CARROLL STREET Database: VCP NYC, Date of Government Version: 06/06/2022	566 CARROLL STREET	E 0 - 1/8 (0.052 mi.)	B111	282
241 - 245 4TH AVENUE Database: VCP NYC, Date of Government Version: 06/06/2022	245 4TH AVENUE	ENE 0 - 1/8 (0.066 mi.)	H129	314
374 4TH AVENUE Database: VCP NYC, Date of Government Version: 06/06/2022	374 4TH AVENUE	SSW 1/8 - 1/4 (0.187 mi.)	Z260	714
74-76 SOUTH SECOND S Database: VCP NYC, Date of Government Version: 06/06/2022	74-76 SECOND STREET	WNW 1/4 - 1/2 (0.438 mi.)	BG422	1320
79-97 4TH AVENUE Database: VCP NYC, Date of Government Version: 06/06/2022	85 4TH AVENUE	NNE 1/4 - 1/2 (0.467 mi.)	432	1358
125 THIRD AVENUE Database: VCP NYC, Date of Government Version: 06/06/2022	125 3RD AVENUE	NNE 1/4 - 1/2 (0.477 mi.)	435	1360

Lower Elevation	Address	Direction / Distance	Map ID	Page
553 SACKETT STREET Database: VCP NYC, Date of Government Version: 06/06/2022	553 SACKETT STREET	N 1/8 - 1/4 (0.250 mi.)	AQ364	1064
FULTON WORKS Database: VCP, Date of Government Version: 05/09/2022 Site Code: 57151	DEGRAW STREET AND NE	NNW 1/4 - 1/2 (0.315 mi.)	AV380	1114
233 NEVINS STREET PH Database: VCP NYC, Date of Government Version: 06/06/2022	233 NEVINS STREET	N 1/4 - 1/2 (0.375 mi.)	BB406	1279
99 NORTH 4TH STREET Database: VCP NYC, Date of Government Version: 06/06/2022	99 4TH STREET	WNW 1/4 - 1/2 (0.399 mi.)	BC411	1301
233 NEVINS STREET Database: VCP NYC, Date of Government Version: 06/06/2022	236 BUTLER STREET	N 1/4 - 1/2 (0.406 mi.)	BB413	1305

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 25 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
272 4TH AVENUE Site Code: 590723	***272 4TH AVENUE***	***NE 0 - 1/8 (0.023 mi.)***	***A11***	***63***
204 4TH AVENUE Site Code: 587854	204 4TH AVENUE	NNE 1/8 - 1/4 (0.161 mi.)	O222	571

Lower Elevation	Address	Direction / Distance	Map ID	Page
THIRD AVENUE YARD Site Code: 533255	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A70	202
190-220 THIRD STREET Site Code: 333299	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***607***
585 UNION STREET Site Code: 619763	577-599 UNION STREET	NNW 1/8 - 1/4 (0.203 mi.)	AE274	752
473 PRESIDENT STREET Site Code: 507634	473 PRESIDENT STREET	NNW 1/8 - 1/4 (0.210 mi.)	AG290	803
473 PRESIDENT STREET Site Code: 568180	***473 PRESIDENT STREET***	***NNW 1/8 - 1/4 (0.210 mi.)***	***AG291***	***808***
514 UNION STREET Site Code: 615885	514 UNION STREET	NNW 1/8 - 1/4 (0.211 mi.)	AE303	836
175-225 3RD STREET Site Code: 504582	175-225 3RD STREET	W 1/8 - 1/4 (0.214 mi.)	AC311	854
PRESIDENT STREET POR Site Code: 602138	469 PRESIDENT STREET	NNW 1/8 - 1/4 (0.218 mi.)	AG319	875
GOWANUS VILLAGE I, L Site Code: 356610	***420 CARROLL STREET***	***NW 1/8 - 1/4 (0.224 mi.)***	***AH324***	***892***
318 NEVINS STREET Site Code: 630084	300-344 NEVINS STREE	NW 1/8 - 1/4 (0.231 mi.)	AG339	938
563 SACKETT STREET Site Code: 507650	563 SACKETT STREET	N 1/8 - 1/4 (0.240 mi.)	AE349	1022
141 3RD STREET Site Code: 624862	141 3RD STREET	WNW 1/4 - 1/2 (0.305 mi.)	AR376	1109
450 UNION STREET Site Code: 507633	***450 UNION STREET***	***NW 1/4 - 1/2 (0.324 mi.)***	***AW383***	***1120***
365 BOND STREET Site Code: 478842	***365 BOND STREET***	***WNW 1/4 - 1/2 (0.324 mi.)***	***AX384***	***1146***
335 BOND STREET Site Code: 507653	335 BOND STREET	NW 1/4 - 1/2 (0.326 mi.)	AY385	1181
THIRD STREET GOWANUS Site Code: 628534	125 3RD STREET	WNW 1/4 - 1/2 (0.335 mi.)	389	1197
242 NEVINS STREET Site Code: 568573	***242 NEVINS STREET***	***NNW 1/4 - 1/2 (0.343 mi.)***	***AV395***	***1213***
TOLL BROOKLYN, LP Site Code: 348572	64-98 1ST ST; 82-107	WNW 1/4 - 1/2 (0.345 mi.)	AX396	1219
388 CARROLL STREET A Site Code: 478612	***388 CARROLL STREET A***	***NW 1/4 - 1/2 (0.346 mi.)***	***AY398***	***1223***
168 8TH STREET	168 8TH STREET	SW 1/4 - 1/2 (0.364 mi.)	AZ401	1258

Site Code: 568008 Site Code: 563661				
210 DOUGLASS STREET Site Code: 615221	210 DOUGLASS STREET	NNW 1/4 - 1/2 (0.399 mi.)	BD410	1296
234 BUTLER STREET Site Code: 550328	234 BUTLER STREET	N 1/4 - 1/2 (0.408 mi.)	BB415	1306
425 HOYT STREET Site Code: 507652	419-429 HOYT STREET	WNW 1/4 - 1/2 (0.470 mi.)	BH433	1358

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

Registered Recycling Facility List from the Department of Environmental Conservation.

A review of the NY SWRCY list, as provided by EDR, and dated 06/29/2022 has revealed that there are 3 NY SWRCY sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RINALDI RECYCLING CO	326 DOUGLASS STREET	NNE 1/4 - 1/2 (0.273 mi.)	367	1067

Lower Elevation	Address	Direction / Distance	Map ID	Page
163 6TH STREET LLC	***163 6TH ST***	***WSW 1/4 - 1/2 (0.302 mi.)***	***AT374***	***1103***
US RECYCLING INC	***141 6TH STREET***	***WSW 1/4 - 1/2 (0.303 mi.)***	***AT375***	***1107***

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the NY DEL SHWS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 2 NY DEL SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CARROLL GARDENS Site Code Id: 224012	CORNER OF 5TH STREET	WNW 1/2 - 1 (0.595 mi.)	442	1370

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHEM TURA	***688-700 COURT ST***	***WSW 1/2 - 1 (0.957 mi.)***	***BK448***	***1386***

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/09/2022 has revealed that there are 75 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STREET Spill Number/Closed Date: 0404988 / 2004-08-06 Site ID: 276456 Spill Date: 2004-08-06	1ST STREET/4TH AVE	SSE 0 - 1/8 (0.011 mi.)	A7	49
3RD AVE YARD Spill Number/Closed Date: 0002643 / 2001-09-25 Site ID: 155576 Spill Date: 2000-06-02	1ST ST & 4TH AVE	SSE 0 - 1/8 (0.018 mi.)	A8	50
4TH AVE/GARFIELD ST Spill Number/Closed Date: 8404005 / 2020-04-29 Site ID: 192509 Spill Date: 1984-12-17	4TH AVE/GARFIELD ST	ENE 0 - 1/8 (0.020 mi.)	B10	54
272 4TH AVENUE Spill Number/Closed Date: 2005727 / Not Reported Site ID: 611527 Spill Date: 2020-09-23	***272 4TH AVENUE***	***NE 0 - 1/8 (0.023 mi.)***	***A11***	***63***
CONSTRUCTION SITE Spill Number/Closed Date: 0912838 / 2010-03-11 Site ID: 425747 Spill Date: 2010-03-10	267 FOURTH AVENUE IN	E 0 - 1/8 (0.023 mi.)	A12	67
FORMER GAS STATION Spill Number/Closed Date: 0501021 / 2006-02-20 Site ID: 344148 Spill Date: 2005-04-25	269-271 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A22	91
4TH AVE Spill Number/Closed Date: 0004550 / 2001-10-19 Site ID: 287775 Spill Date: 2000-07-15	CARROLL ST & 4TH AVE	ENE 0 - 1/8 (0.050 mi.)	B109	281
315 4TH AVE Spill Number/Closed Date: 9814678 / 1999-03-26 Site ID: 186475 Spill Date: 1999-03-09	315 4TH AVENUE	S 0 - 1/8 (0.084 mi.)	J147	346
VAULT# TM0253 Spill Number/Closed Date: 0400989 / 2004-07-20 Site ID: 317096 Spill Date: 2004-04-28	PRESIDENT ST & 4TH A	ENE 0 - 1/8 (0.093 mi.)	H155	358
MANHOLE 5436 Spill Number/Closed Date: 0412308 / 2005-02-18 Site ID: 337753 Spill Date: 2005-02-17	4TH AVE/3RD ST	S 0 - 1/8 (0.108 mi.)	J175	396
CONSTRUCTION SITE	340 4TH AVE	SSW 0 - 1/8 (0.119 mi.)	P181	404

Spill Number/Closed Date: 1302908 / 2013-06-17
Site ID: 483360
Spill Date: 2013-06-17

PARKSIDE SERVICE CEN — 340 4TH AVE — SSW 0 - 1/8 (0.119 mi.) — P182 — 406
Spill Number/Closed Date: 0704349 / 2014-03-28
Spill Number/Closed Date: 8911553 / 1990-03-08
Spill Number/Closed Date: 0801262 / 2008-05-01
Site ID: 384480
Site ID: 244057
Site ID: 397156
Spill Date: 2007-07-18
Spill Date: 1990-03-07
Spill Date: 2008-05-01

Lower Elevation	Address	Direction / Distance	Map ID	Page
MC DONALD'S Spill Number/Closed Date: 0551768 / 2013-10-07 Site ID: 361253 Spill Date: 2006-02-01	245 1ST STREET	WNW 0 - 1/8 (0.008 mi.)	A6	43
YARD Spill Number/Closed Date: 1105298 / 2011-10-28 Site ID: 452947 Spill Date: 2011-07-21	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A24	94
CON EDISON VEHICLE 6 Spill Number/Closed Date: 1110967 / 2012-01-17 Site ID: 458834 Spill Date: 2011-12-09	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A27	98
THIRD AVE YARD - SER Spill Number/Closed Date: 9808009 / 2017-06-08 Site ID: 299103 Spill Date: 1998-09-30	222 1ST STREET	W 0 - 1/8 (0.027 mi.)	A28	99
THIRD AVE YARD Spill Number/Closed Date: 0110159 / 2003-05-01 Site ID: 263575 Spill Date: 2002-01-22	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A29	103
CON EDISON Spill Number/Closed Date: 9510404 / 1995-11-20 Site ID: 299101 Spill Date: 1995-11-16	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A30	104
THIRD AVE YARD Spill Number/Closed Date: 0408750 / 2005-01-06 Site ID: 333489 Spill Date: 2004-11-08	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A31	105
SERVICE BOX 3RD AVE Spill Number/Closed Date: 9907981 / 2002-01-30 Site ID: 299104 Spill Date: 1999-09-30	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A32	106
CON ED 3RD AVE STATI Spill Number/Closed Date: 1601300 / 2017-03-28 Site ID: 526616 Spill Date: 2016-05-09	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A34	140
COOLANT RELEASE FROM	222 1 STREET (THIRD	W 0 - 1/8 (0.027 mi.)	A35	141

Spill Number/Closed Date: 0700220 / 2007-05-23
Site ID: 379559
Spill Date: 2007-04-07

CON ED THIRD AVE YAR — 222 FIRST ST — W 0 - 1/8 (0.027 mi.) — A37 — 143
Spill Number/Closed Date: 1105608 / 2011-10-04
Spill Number/Closed Date: 2104705 / 2021-10-04
Site ID: 453268
Site ID: 623525
Spill Date: 2011-08-17
Spill Date: 2021-08-18

CON-ED THIRD AVE YAR — 222 FIRST ST — W 0 - 1/8 (0.027 mi.) — A38 — 145
Spill Number/Closed Date: 1110305 / 2012-01-17
Site ID: 458118
Spill Date: 2011-11-18

CON ED 3RD AV YARD — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A40 — 147
Spill Number/Closed Date: 9913132 / 2000-02-18
Site ID: 263145
Spill Date: 2000-02-18

CON ED 3RD AV GARAGE — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A41 — 148
Spill Number/Closed Date: 9607770 / 1998-05-27
Site ID: 276610
Spill Date: 1996-09-20

CON ED FACILITY — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A42 — 149
Spill Number/Closed Date: 9811783 / 2003-02-14
Site ID: 263579
Spill Date: 1998-12-18

OIL LEAK FROM VEHICL — 222 FIRST ST AT 3 AV — W 0 - 1/8 (0.027 mi.) — A43 — 150
Spill Number/Closed Date: 0508341 / 2005-11-25
Site ID: 353906
Spill Date: 2005-10-12

CON EDISON 3RD AVE Y — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A44 — 151
Spill Number/Closed Date: 9703946 / 2003-02-28
Site ID: 299102
Spill Date: 1997-07-01

CON ED STATION — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A45 — 152
Spill Number/Closed Date: 1205717 / 2013-03-08
Site ID: 468682
Spill Date: 2012-09-08

3RD AVENUE YARD — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A46 — 153
Spill Number/Closed Date: 9714230 / 1998-05-13
Site ID: 263578
Spill Date: 1998-03-24

3RD AVE YARD — 222 1ST ST — W 0 - 1/8 (0.027 mi.) — A47 — 155
Spill Number/Closed Date: 0813445 / 2009-06-03
Site ID: 411134
Spill Date: 2009-03-13

3RD AVE YARD — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A48 — 156
Spill Number/Closed Date: 0300475 / 2003-04-15
Spill Number/Closed Date: 0410262 / 2005-04-22
Spill Number/Closed Date: 1000131 / 2010-04-27
Spill Number/Closed Date: 1000132 / 2010-04-22

Spill Number/Closed Date: 0910207 / 2010-02-16
**Additional key fields are available in the Map Findings section*
Site ID: 299100
Site ID: 335210
Site ID: 427053
Site ID: 427054
Site ID: 422955
**Additional key fields are available in the Map Findings section*
Spill Date: 2003-04-14
Spill Date: 2004-12-15
Spill Date: 2010-04-04
Spill Date: 2009-12-15
Spill Date: 2000-02-14
**Additional key fields are available in the Map Findings section*

THIRD AVE YARD	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A50	170
Spill Number/Closed Date: 1114458 / 2012-05-10 Site ID: 462517 Spill Date: 2012-03-29				
3 QT ANTI-FREEZE FRO	222 FIRST ST. CON ED	W 0 - 1/8 (0.027 mi.)	A51	171
Spill Number/Closed Date: 0711576 / 2008-05-12 Site ID: 393082 Spill Date: 2008-02-02				
3RD AVE SERVICE YARD	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A52	172
Spill Number/Closed Date: 9801450 / 2002-10-30 Site ID: 263140 Spill Date: 1998-05-03				
3RD AVE YARD	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A53	174
Spill Number/Closed Date: 0807096 / 2008-11-17 Site ID: 404414 Spill Date: 2008-09-24				
3RD AVE YARD	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A56	179
Spill Number/Closed Date: 1008213 / 2017-06-08 Site ID: 441688 Spill Date: 2010-11-05				
3RD AVE YARD CON ED	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A57	184
Spill Number/Closed Date: 9801934 / 1998-06-12 Site ID: 263141 Spill Date: 1998-05-14				
222 1ST STREET	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A58	185
Spill Number/Closed Date: 9415797 / 1998-02-13 Site ID: 201957 Spill Date: 1995-03-06				
THIRD AVENUE YARD	222 1ST STREET	W 0 - 1/8 (0.027 mi.)	A61	190
Spill Number/Closed Date: 1000930 / 2010-05-21 Site ID: 433623 Spill Date: 2010-04-23				
CON ED	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A62	191
Spill Number/Closed Date: 1104942 / 2011-09-07 Site ID: 452560 Spill Date: 2011-07-31				
222 FIRST STREET	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A63	192

Spill Number/Closed Date: 9706833 / 1997-09-10
Site ID: 263577
Spill Date: 1997-09-08

3RD AV YARD — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A65 — 194
Spill Number/Closed Date: 0007860 / 2001-12-14
Spill Number/Closed Date: 9614742 / 1997-03-25
Spill Number/Closed Date: 9603338 / 1996-08-22
Site ID: 263128
Site ID: 263136
Site ID: 276609
Spill Date: 2000-10-04
Spill Date: 1997-03-21
Spill Date: 1996-06-10

3 AVE YARD — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A66 — 197
Spill Number/Closed Date: 0513083 / 2006-04-21
Site ID: 359500
Spill Date: 2006-02-13

LEAK FROM VEHICLE IN — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A67 — 199
Spill Number/Closed Date: 0514637 / 2006-06-14
Site ID: 361408
Spill Date: 2006-03-22

CON EDISON GARAGE — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A68 — 200
Spill Number/Closed Date: 0602266 / 2006-10-05
Site ID: 364698
Spill Date: 2006-05-31

VEHICLE 60722 LOST H — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A69 — 201
Spill Number/Closed Date: 0514814 / 2008-01-10
Site ID: 361624
Spill Date: 2006-03-27

THIRD AVENUE YARD — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A71 — 205
Spill Number/Closed Date: 0203307 / 2017-06-08
Site ID: 263576
Spill Date: 2002-06-27

CON ED WORK / 3RD AV — 222 1ST ST — W 0 - 1/8 (0.027 mi.) — A72 — 211
Spill Number/Closed Date: 1301088 / 2013-07-10
Site ID: 481453
Spill Date: 2013-05-02

FLUSH PIT — 222 FIRST STREET — W 0 - 1/8 (0.027 mi.) — A73 — 212
Spill Number/Closed Date: 9807969 / 2002-12-30
Site ID: 276613
Spill Date: 1998-09-27

3RD AVE YARD — 222 1ST ST — W 0 - 1/8 (0.027 mi.) — A74 — 213
Spill Number/Closed Date: 1012255 / 2011-03-22
Site ID: 446173
Spill Date: 2011-03-10

CON EDISON — 221 1ST ST — WNW 0 - 1/8 (0.027 mi.) — A76 — 216
Spill Number/Closed Date: 9911979 / 2000-02-23
Site ID: 177460
Spill Date: 2000-01-17

220 1ST STREET — 220 1ST STREET — W 0 - 1/8 (0.028 mi.) — A81 — 228
Spill Number/Closed Date: 9207274 / 2008-09-19

Site ID: 153446 Spill Date: 1992-09-15				
FIVE GALLONS OF OIL Spill Number/Closed Date: 0604245 / 2017-06-08 Spill Number/Closed Date: 0512763 / 2006-04-12 Site ID: 367178 Site ID: 359135 Spill Date: 2006-06-28 Spill Date: 2006-02-03	222 1 STREET	SW 0 - 1/8 (0.031 mi.)	A83	229
SIX GAL HYDRAULIC FL Spill Number/Closed Date: 0705772 / 2007-11-08 Site ID: 386143 Spill Date: 2007-08-20	222 FIRST STREET & 3	SW 0 - 1/8 (0.031 mi.)	A84	232
VEHICLE 60677 Spill Number/Closed Date: 0512797 / 2006-04-12 Site ID: 359174 Spill Date: 2006-02-04	THIRD AVE YARD	SW 0 - 1/8 (0.031 mi.)	A85	233
222 1ST STREET Spill Number/Closed Date: 9501055 / 2004-07-16 Site ID: 201439 Spill Date: 1995-04-25	CON EDSION	SW 0 - 1/8 (0.031 mi.)	A86	234
HYDRAULIC OIL Spill Number/Closed Date: 0505767 / 2005-08-11 Site ID: 350857 Spill Date: 2005-08-10	3 AVE YARD NEW CONST	SW 0 - 1/8 (0.031 mi.)	A87	235
P.S. 372 (OUR LADY O Spill Number/Closed Date: 0402598 / 2021-10-20 Site ID: 288471 Spill Date: 2004-06-09	***512 CARROLL STREET***	***N 0 - 1/8 (0.038 mi.)***	***C95***	***252***
3RD AVE YARD Spill Number/Closed Date: 9702955 / 2003-02-28 Spill Number/Closed Date: 1003520 / 2010-10-18 Spill Number/Closed Date: 9514611 / 2003-01-31 Site ID: 281782 Site ID: 436752 Site ID: 281779 Spill Date: 1997-06-09 Spill Date: 2010-06-29 Spill Date: 1996-02-15	3RD AVE YARD	WSW 0 - 1/8 (0.054 mi.)	E114	284
3RD AV YARD INFO STO Spill Number/Closed Date: 0105268 / 2001-08-15 Site ID: 243216 Spill Date: 2001-08-15	M 222 1ST ST	WNW 0 - 1/8 (0.060 mi.)	F122	301
COMMERCIAL BUILDING Spill Number/Closed Date: 0606675 / 2009-03-17 Site ID: 370045 Spill Date: 2006-09-11	14 WHITWELL PLACE	NNW 0 - 1/8 (0.061 mi.)	F123	302
PROCIDA REALTY Spill Number/Closed Date: 0602894 / 2008-10-20 Site ID: 365475 Spill Date: 2006-06-15	505 CARROLL STREET	NNW 0 - 1/8 (0.074 mi.)	I137	326
THIRD AV YARD	222 FIRST STREET	W 0 - 1/8 (0.076 mi.)	E138	333

Spill Number/Closed Date: 0001798 / 2000-06-20
Site ID: 276606
Spill Date: 2000-05-11

FLUSHPIT 3RD AVE YAR	222 FIRST STREET	W 0 - 1/8 (0.076 mi.)	E139	335
Spill Number/Closed Date: 0009168 / 2000-11-14 Site ID: 263574 Spill Date: 2000-11-08				
222 1ST ST	3RD AVE YARD	WNW 0 - 1/8 (0.090 mi.)	F152	354
Spill Number/Closed Date: 9803310 / 1998-08-06 Site ID: 281783 Spill Date: 1998-06-12				
THIRD AVENUE YARD	THIRD AVENUE & FIRST	WNW 0 - 1/8 (0.090 mi.)	F153	355
Spill Number/Closed Date: 9605550 / 1998-05-04 Site ID: 73086 Spill Date: 1996-07-30				
3RD AVE YARD	3RD AVE YARD	WNW 0 - 1/8 (0.090 mi.)	F154	356
Spill Number/Closed Date: 9514614 / 2003-02-24 Spill Number/Closed Date: 9702275 / 2003-02-25 Site ID: 281780 Site ID: 281781 Spill Date: 1996-02-15 Spill Date: 1997-05-20				
FEEDER LEAK	3RD AVE & 1ST STREET	WNW 0 - 1/8 (0.095 mi.)	F159	366
Spill Number/Closed Date: 1809345 / 2019-06-21 Site ID: 580185 Spill Date: 2018-12-05				
3RD AVE SERVICE CENT	3RD AVE & 1ST ST	WNW 0 - 1/8 (0.095 mi.)	F160	367
Spill Number/Closed Date: 9608437 / 2004-09-02 Site ID: 203791 Spill Date: 1996-10-07				
MANHOLE # 65435	3RD AVE/1ST STREET	WNW 0 - 1/8 (0.095 mi.)	F162	369
Spill Number/Closed Date: 0502530 / 2005-08-17 Site ID: 346909 Spill Date: 2005-06-02				
ABF FREIGHTS	545 PRESIDENT ST	N 0 - 1/8 (0.109 mi.)	M176	397
Spill Number/Closed Date: 2006668 / 2020-10-22 Site ID: 612520 Spill Date: 2020-10-22				
2ND & 3RD AVE	2ND & 3RD AVE	W 0 - 1/8 (0.109 mi.)	N177	398
Spill Number/Closed Date: 9914001 / 2003-08-08 Site ID: 126958 Spill Date: 2000-03-11				
MAN HOLE 5354	3RD AND AVE AND 2ND	W 0 - 1/8 (0.110 mi.)	N178	399
Spill Number/Closed Date: 1006176 / 2010-09-24 Site ID: 439522 Spill Date: 2010-09-04				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/20/2022 has revealed that there are 73 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID:: NYP004571485	540 CARROLL ST	NNE 0 - 1/8 (0.027 mi.)	B79	224
AUTO BODY CONCEPTS D EPA ID:: NYR000060392	270 4TH AVE	NE 0 - 1/8 (0.031 mi.)	B89	237
CON EDISON SERVICE B EPA ID:: NYP004572756	***9 GARFIELD ST***	***E 0 - 1/8 (0.037 mi.)***	***B93***	***245***
CON EDISON EPA ID:: NYP004757563	***CARROLL ST & 4TH AVE***	***NE 0 - 1/8 (0.039 mi.)***	***B98***	***264***
CON EDISON EPA ID:: NYP004879932	255 4TH AVE	ENE 0 - 1/8 (0.039 mi.)	B100	267
CON EDISON EPA ID:: NYP004757555	***DENTON ST & CARROLL***	***NNE 0 - 1/8 (0.042 mi.)***	***C103***	***272***
CON EDISON SERVICE B EPA ID:: NYP005172960	12 GARFIELD PL	ESE 0 - 1/8 (0.042 mi.)	B106	277
CON EDISON SERVICE B EPA ID:: NYP004425880	***100 4TH ST & 2ND AVE***	***S 0 - 1/8 (0.057 mi.)***	***D116***	***288***
NYCDOT BRIDGE BIN 22 EPA ID:: NY0000375220	PRESIDENT ST BRG OVE	NE 0 - 1/8 (0.059 mi.)	B120	297
CON EDISON EPA ID:: NYP004738910	***22 GARFIELD ST***	***ESE 0 - 1/8 (0.066 mi.)***	***G126***	***309***
245 4TH AVENUE LLC EPA ID:: NYR000229906	***243-245 4TH AVE***	***ENE 0 - 1/8 (0.073 mi.)***	***H134***	***318***
CON EDISON EPA ID:: NYP004744215	***584 CARROLL ST***	***E 0 - 1/8 (0.083 mi.)***	***G146***	***343***
CON EDISON EPA ID:: NYP004743068	***586 CARROL ST***	***E 0 - 1/8 (0.087 mi.)***	***G149***	***349***
CON EDISON EPA ID:: NYP004744306	***590 CARROLL ST***	***E 0 - 1/8 (0.094 mi.)***	***G158***	***362***
CON EDISON EPA ID:: NYP004735734	***577 CARROLL ST***	***E 0 - 1/8 (0.104 mi.)***	***K168***	***377***
CON EDISON SERVICE B EPA ID:: NYP004429650	***260 3RD ST FRONT OF***	***S 0 - 1/8 (0.116 mi.)***	***J180***	***401***
CON EDISON SERVICE B EPA ID:: NYP004349064	***604 UNION ST***	***NNE 1/8 - 1/4 (0.126 mi.)***	***M188***	***431***
NYCT - UNION STATION EPA ID:: NYR000107938	***UNION ST & 4TH AVE***	***NE 1/8 - 1/4 (0.136 mi.)***	***O191***	***440***
CON EDISON MANHOLE:	***4TH & UNION AVE***	***NE 1/8 - 1/4 (0.137 mi.)***	***O193***	***445***

EPA ID:: NYP004318366				
PEP BOYS 247	***354 4TH AVE***	***SSW 1/8 - 1/4 (0.142 mi.)***	***P203***	***476***
EPA ID:: NYR000071936				
MAACO AUTO PAINTING	***358 FOURTH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P211***	***496***
EPA ID:: NYD981488232				
CON EDISON - MANHOLE	***358 4TH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P212***	***500***
EPA ID:: NYP004130670				
CON EDISON SERVICE B	***85-87 1ST AVE & 5TH***	***SE 1/8 - 1/4 (0.160 mi.)***	***U216***	***510***
EPA ID:: NYP004485942				
RALPHS CLEANERS	***230 FIFTH AVE***	***E 1/8 - 1/4 (0.170 mi.)***	***Y235***	***592***
EPA ID:: NYD986951069				
JET FRENCH CLEANERS	***279 5TH AVE***	***SE 1/8 - 1/4 (0.177 mi.)***	***U244***	***652***
EPA ID:: NYR000016402				
BRIDGE FORD	***343 4TH AVE***	***SSW 1/8 - 1/4 (0.179 mi.)***	***Z245***	***656***
EPA ID:: NYD982280091				
CON EDISON	354 3RD ST	SSE 1/8 - 1/4 (0.180 mi.)	AA249	668
EPA ID:: NYP004783759				
BROOKLYN IGNITION &	***370 4TH AVE***	***SSW 1/8 - 1/4 (0.183 mi.)***	***Z253***	***675***
EPA ID:: NY0000228106				
SEMPLE RIEGER CO	***635 SACKETT ST***	***NNE 1/8 - 1/4 (0.194 mi.)***	***X264***	***723***
EPA ID:: NYD986891885				
CON EDISON	***365 2ND ST***	***SE 1/8 - 1/4 (0.195 mi.)***	***U266***	***730***
EPA ID:: NYP004825176				
CON EDISON SERVICE B	***209 5TH ST OPPOSITE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***Z270***	***738***
EPA ID:: NYP004307930				
CON EDISON	***335 1ST ST***	***ESE 1/8 - 1/4 (0.207 mi.)***	***U281***	***765***
EPA ID:: NYP004731998				
CON EDISON SERVICE B	***674 PRESIDENT ST***	***E 1/8 - 1/4 (0.212 mi.)***	***Y304***	***838***
EPA ID:: NYP004330726				
CON EDISON	***676 PRESIDENT ST***	***E 1/8 - 1/4 (0.216 mi.)***	***AJ315***	***864***
EPA ID:: NYP004738498				
CON EDISON SERVICE B	***726 SACKETT ST***	***ENE 1/8 - 1/4 (0.217 mi.)***	***AL317***	***868***
EPA ID:: NYP004349585				
CON EDISON	***675 PRESIDENT ST***	***E 1/8 - 1/4 (0.223 mi.)***	***AJ321***	***881***
EPA ID:: NYP004738811				
CON EDISON	664 DEGRAW ST	NE 1/8 - 1/4 (0.226 mi.)	AN327	896
EPA ID:: NYP004781910				
CON EDISON SERVICE B	298 5TH ST	S 1/8 - 1/4 (0.227 mi.)	AO336	929
EPA ID:: NYP004570321				
CON ED - V 3685	522 W 44 ST	SSW 1/8 - 1/4 (0.228 mi.)	Z337	931
EPA ID:: NYP000928358				
CON EDISON SERVICE B	***315 4TH ST S***	***SSE 1/8 - 1/4 (0.229 mi.)***	***AA338***	***934***
EPA ID:: NYP004337168				
KAM SERVICE CENTER I	***363 4TH AVE***	***SSW 1/8 - 1/4 (0.232 mi.)***	***AP340***	***940***
EPA ID:: NYD986988004				
CON EDISON	***391 2ND ST***	***SE 1/8 - 1/4 (0.238 mi.)***	***AI343***	***991***

EPA ID:: NYP004760401				
AMOCO SERVICE STATIO EPA ID:: NYD986933109	***375-381 4TH AVE & 6T***	***SSW 1/8 - 1/4 (0.239 mi.)***	***AP348***	***1017***
CON EDISON SERVICE B EPA ID:: NYP004326278	***195 5TH AVE FRONT OF***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AL352***	***1029***
U-HAUL CORP EPA ID:: NY0000970509	***259 6TH ST - PARK SL***	***SSW 1/8 - 1/4 (0.243 mi.)***	***AP355***	***1039***
CON EDISON MANHOLE: EPA ID:: NYP004322004	***267 6TH ST***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AO358***	***1048***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON TM439 EPA ID:: NYP004036729	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A55***	***176***
CON EDISON EPA ID:: NYP004772869	221 1ST	WNW 0 - 1/8 (0.027 mi.)	A77	219
CON EDISON EPA ID:: NYP004837696	221 1ST ST	WNW 0 - 1/8 (0.027 mi.)	A78	221
CON EDISON EPA ID:: NYP004757548	***511 CARROLL ST***	***N 0 - 1/8 (0.058 mi.)***	***C118***	***293***
FINEST AUTO & RECOVE EPA ID:: NYR000090431	***310 3RD AVE***	***NW 0 - 1/8 (0.104 mi.)***	***F171***	***383***
JO-LEE TRUCKING EPA ID:: NYR000131938	463 CARROLL ST	NW 1/8 - 1/4 (0.135 mi.)	L190	437
CON EDISON SERVICE B EPA ID:: NYP004376315	***578 UNION ST***	***N 1/8 - 1/4 (0.137 mi.)***	***M194***	***449***
CON EDISON VAULT SUB EPA ID:: NYP004476214	***213 3RD ST***	***W 1/8 - 1/4 (0.138 mi.)***	***N195***	***453***
VERIZON LOG 31756 MA EPA ID:: NYP000962894	3RD ST & 3RD AVE	WSW 1/8 - 1/4 (0.140 mi.)	R197	458
CON EDISON EPA ID:: NYP004743779	***3RD ST & 3RD AVE***	***WSW 1/8 - 1/4 (0.140 mi.)***	***R198***	***460***
CON EDISON EXCAVATIO EPA ID:: NYP004551230	251 3RD AVE	N 1/8 - 1/4 (0.150 mi.)	S208	489
CON EDISON SERVICE B EPA ID:: NYP004479192	***210 3RD ST***	***WSW 1/8 - 1/4 (0.159 mi.)***	***R215***	***507***
CON EDISON EPA ID:: NYP004818912	451 CARROLL ST FRONT	NW 1/8 - 1/4 (0.162 mi.)	W224	575
CON EDISON EPA ID:: NYP004836340	***617 UNION ST & 3RD A***	***N 1/8 - 1/4 (0.165 mi.)***	***S226***	***578***
CON EDISON EPA ID:: NYP004795480	501 PRESIDENT ST	NNW 1/8 - 1/4 (0.166 mi.)	Q228	582
A 2 Z ENVIRONMENTAL EPA ID:: NYR000187302	601 UNION ST	N 1/8 - 1/4 (0.168 mi.)	S232	587
216 3RD STREET EPA ID:: NYD001869049	***216 3RD ST***	***W 1/8 - 1/4 (0.172 mi.)***	***R236***	***596***
CON EDISON	***443 CARROLL ST***	***NW 1/8 - 1/4 (0.172 mi.)***	***W238***	***602***

EPA ID:: NYP004827267				
190-220 THIRD STREET EPA ID:: NYR000197178	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***607***
CON EDISON SERVICE B EPA ID:: NYP004479184	***198 3RD ST***	***W 1/8 - 1/4 (0.185 mi.)***	***AC257***	***686***
MATTHEWS INTERNATION EPA ID:: NYN008027997	585 UNION ST	NNW 1/8 - 1/4 (0.192 mi.)	S263	720
PIPPIN ENTERPRISES L EPA ID:: NYD987023181	***220 3RD ST***	***WSW 1/8 - 1/4 (0.201 mi.)***	***AD273***	***748***
CON EDISON MANHOLE: EPA ID:: NYP004479242	***190 3RD ST FRONT OF***	***W 1/8 - 1/4 (0.208 mi.)***	***AC283***	***769***
CON EDISON EPA ID:: NYP004841512	***SACKETT ST & 3RD AVE***	***N 1/8 - 1/4 (0.209 mi.)***	***AF287***	***799***
CON EDISON EPA ID:: NYP004822777	***CARROLL ST & NEVINS***	***NW 1/8 - 1/4 (0.210 mi.)***	***AH297***	***822***
NEW YORK TELEPHONE C EPA ID:: NYD987028008	175 THIRD ST	W 1/8 - 1/4 (0.214 mi.)	AC309	848
NYSDOT 3RD ST BRIDGE EPA ID:: NYD986975316	3RD ST BRG OVER GOWA	WNW 1/8 - 1/4 (0.244 mi.)	357	1044

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 07/26/2022 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL EPA ID:: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***15***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 08/30/2022 has revealed that there are 3 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RALPH'S CLEANERS Facility Id: 2-6103-00246	230 5TH AVE	E 1/8 - 1/4 (0.170 mi.)	Y234	591
MALACHI DRY CLNR Facility Id: 2-6103-00538	279 5TH AVENUE	SE 1/8 - 1/4 (0.177 mi.)	U243	651

Lower Elevation	Address	Direction / Distance	Map ID	Page
KLOR-DE CLEANERS Facility Id: 2-6103-00151	263 3RD AVENUE	N 1/8 - 1/4 (0.136 mi.)	M192	445

EXECUTIVE SUMMARY

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 03/22/2022 has revealed that there are 18 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 964	275 4 AVENUE	ESE 0 - 1/8 (0.026 mi.)	A19	90
LOT 6,TAXBLOCK 964	271 4 AVENUE	ESE 0 - 1/8 (0.026 mi.)	A21	91
LOT 7,TAXBLOCK 964	269 4 AVENUE	ESE 0 - 1/8 (0.026 mi.)	A23	93
LOT 1,TAXBLOCK 961	261 4 AVENUE	E 0 - 1/8 (0.031 mi.)	B82	229
LOT 2,TAXBLOCK 961	259 4 AVENUE	ENE 0 - 1/8 (0.034 mi.)	B90	241
LOT 69,TAXBLOCK 961	13 GARFIELD PLACE	E 0 - 1/8 (0.040 mi.)	B102	271
LOT 67,TAXBLOCK 961	***15 GARFIELD PLACE***	***E 0 - 1/8 (0.048 mi.)***	***B108***	***280***
LOT 7,TAXBLOCK 961	566 CARROLL STREET	E 0 - 1/8 (0.052 mi.)	B110	282
LOT 21,TAXBLOCK 352	CARROLL STREET	ENE 0 - 1/8 (0.053 mi.)	B112	283
LOT 1,TAXBLOCK 969	283 4 AVENUE	SSE 0 - 1/8 (0.054 mi.)	D113	283
LOT 1,TAXBLOCK 958	253 4 AVENUE	ENE 0 - 1/8 (0.056 mi.)	B115	287
LOT 2,TAXBLOCK 958	249 4 AVENUE	ENE 0 - 1/8 (0.059 mi.)	B121	300
LOT 4,TAXBLOCK 958	245 4 AVENUE	ENE 0 - 1/8 (0.066 mi.)	H127	311
LOT 7504,TAXBLOCK 97	302 2 STREET	S 0 - 1/8 (0.072 mi.)	D131	315
LOT 5,TAXBLOCK 958	243 4 AVENUE	ENE 0 - 1/8 (0.073 mi.)	H133	317
LOT 7,TAXBLOCK 958	586 PRESIDENT STREET	ENE 0 - 1/8 (0.082 mi.)	H142	339
LOT 7502,TAXBLOCK 97	306 2 STREET	S 0 - 1/8 (0.083 mi.)	D144	341
LOT 73,TAXBLOCK 974	303 3 STREET	S 0 - 1/8 (0.099 mi.)	J163	371

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUG, CITIZENS GATE S	6TH STREET AND 2ND A	WSW 1/4 - 1/2 (0.356 mi.)	BA400	1257

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 106 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004655908	292 4TH AV	0 - 1/8 (0.000 mi.)	A4	40
CON EDISON EPA ID: NYP004615274	292 4TH AV	0 - 1/8 (0.000 mi.)	A5	42
275 4TH AVE INVESTOR	275 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A15	85

EPA ID: NYD986914133				
CON EDISON EPA ID: NYP004571485	540 CARROLL ST	NNE 0 - 1/8 (0.027 mi.)	B80	226
CON EDISON EPA ID: NYP004572756	9 GARFIELD ST	E 0 - 1/8 (0.037 mi.)	B92	243
CON ED EPA ID: NYP004879932	255 4TH AVE	ENE 0 - 1/8 (0.039 mi.)	B101	271
CON EDISON EPA ID: NYP004757555	DENTON ST & CARROLL	NNE 0 - 1/8 (0.042 mi.)	C104	274
CON EDISON - SERVICE EPA ID: NYP004977890	255 1ST ST	ESE 0 - 1/8 (0.046 mi.)	B107	279
LOT 67,TAXBLOCK 961 EPA ID: NYP004980361	***15 GARFIELD PLACE***	***E 0 - 1/8 (0.048 mi.)***	***B108***	***280***
CON EDISON SERVICE B EPA ID: NYP004425880	***100 4TH ST & 2ND AVE***	***S 0 - 1/8 (0.057 mi.)***	***D116***	***288***
CON EDISON EPA ID: NYP004738910	22 GARFIELD ST	ESE 0 - 1/8 (0.066 mi.)	G124	306
243 DEVELOPMENT LLC EPA ID: NYR000229906	243-245 4TH AVE	ENE 0 - 1/8 (0.073 mi.)	H132	316
CON EDISON EPA ID: NYP004691457	586 PRESIDENT ST	ENE 0 - 1/8 (0.082 mi.)	H143	339
CON EDISON EPA ID: NYP004744215	584 CARROLL ST	E 0 - 1/8 (0.083 mi.)	G145	341
CON EDISON EPA ID: NYP004743068	586 CARROL ST	E 0 - 1/8 (0.087 mi.)	G150	351
CON EDISON EPA ID: NYP004744306	590 CARROLL ST	E 0 - 1/8 (0.094 mi.)	G156	359
CON EDISON - SERVICE EPA ID: NYP005093950	328 2ND ST	SSE 0 - 1/8 (0.102 mi.)	D164	371
CON EDISON EPA ID: NYP004735734	577 CARROLL ST	E 0 - 1/8 (0.104 mi.)	K166	375
CON EDISON SERVICE B EPA ID: NYP004429650	***260 3RD ST FRONT OF***	***S 0 - 1/8 (0.116 mi.)***	***J180***	***401***
CON EDISON SERVICE B EPA ID: NYP004349064	***604 UNION ST***	***NNE 1/8 - 1/4 (0.126 mi.)***	***M188***	***431***
NYCT - UNION STATION EPA ID: NYR000107938	***UNION ST & 4TH AVE***	***NE 1/8 - 1/4 (0.136 mi.)***	***O191***	***440***
CON EDISON MANHOLE: EPA ID: NYP004318366	***4TH & UNION AVE***	***NE 1/8 - 1/4 (0.137 mi.)***	***O193***	***445***
PEP BOYS 247 EPA ID: NYR000071936	***354 4TH AVE***	***SSW 1/8 - 1/4 (0.142 mi.)***	***P203***	***476***
MAACO AUTO PAINTING EPA ID: NYD981488232	***358 FOURTH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P211***	***496***
CON EDISON - MANHOLE EPA ID: NYP004130670	***358 4TH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P212***	***500***
CON EDISON - TRANSFO	5TH AVE & GARFIELD P	ESE 1/8 - 1/4 (0.161 mi.)	V217	513

EPA ID: NYP004964548				
HESS#32530	***204-222 FOURTH AVE***	***NNE 1/8 - 1/4 (0.161 mi.)***	***O220***	***545***
EPA ID: NYD982185563				
RALPHS CLEANERS	***230 FIFTH AVE***	***E 1/8 - 1/4 (0.170 mi.)***	***Y235***	***592***
EPA ID: NYD986951069				
CONSOLIDATED EDISON	V5491-633 SACKETT ST	NNE 1/8 - 1/4 (0.175 mi.)	T241	646
EPA ID: NYP004047791				
JORDAN MALACHIE CLEA	***295 5TH AVE***	***SE 1/8 - 1/4 (0.175 mi.)***	***U242***	***647***
EPA ID: NYR000087486				
JET FRENCH CLEANERS	***279 5TH AVE***	***SE 1/8 - 1/4 (0.177 mi.)***	***U244***	***652***
EPA ID: NYR000016402				
CON EDISON	354 3RD ST	SSE 1/8 - 1/4 (0.180 mi.)	AA248	667
EPA ID: NYP004783759				
BROOKLYN IGNITION &	***370 4TH AVE***	***SSW 1/8 - 1/4 (0.183 mi.)***	***Z253***	***675***
EPA ID: NY0000228106				
CON EDISON	688 SACKET ST	NE 1/8 - 1/4 (0.185 mi.)	AB254	680
EPA ID: NYP004704458				
CON EDISON	688 SACKETT ST	NE 1/8 - 1/4 (0.185 mi.)	AB255	682
EPA ID: NYP004707279				
EPA ID: NYP004632907				
CON EDISON	688 SACKETT ST	NE 1/8 - 1/4 (0.185 mi.)	AB256	685
EPA ID: NYP004669222				
SUSAN MAINTENANCE	***374 4TH AVE***	***SSW 1/8 - 1/4 (0.187 mi.)***	***Z259***	***692***
EPA ID: NYR000076091				
CON EDISON	318 1 ST	SE 1/8 - 1/4 (0.191 mi.)	U262	718
EPA ID: NYP004592192				
SEMPLE RIEGER CO	***635 SACKETT ST***	***NNE 1/8 - 1/4 (0.194 mi.)***	***X264***	***723***
EPA ID: NYD986891885				
CON ED	365 2ND ST	SE 1/8 - 1/4 (0.195 mi.)	U268	734
EPA ID: NYP004825176				
CON EDISON SERVICE B	***209 5TH ST OPPOSITE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***Z270***	***738***
EPA ID: NYP004307930				
CON EDISON	335 1ST ST	ESE 1/8 - 1/4 (0.207 mi.)	U280	763
EPA ID: NYP004731998				
CON EDISON SERVICE B	***674 PRESIDENT ST***	***E 1/8 - 1/4 (0.212 mi.)***	***Y304***	***838***
EPA ID: NYP004330726				
CON EDISON	386 2ND ST	SE 1/8 - 1/4 (0.213 mi.)	AI305	842
EPA ID: NYP004592226				
CON EDISON	676 PRESIDENT ST	E 1/8 - 1/4 (0.216 mi.)	AJ313	862
EPA ID: NYP004738498				
CON EDISON SERVICE B	***726 SACKETT ST***	***ENE 1/8 - 1/4 (0.217 mi.)***	***AL317***	***868***
EPA ID: NYP004349585				
CON EDISON	675 PRESIDENT ST	E 1/8 - 1/4 (0.223 mi.)	AJ320	879
EPA ID: NYP004738811				
CON EDISON	664 DEGRAW ST	NE 1/8 - 1/4 (0.226 mi.)	AN328	898
EPA ID: NYP004856769				
EPA ID: NYP004781910				
CON EDISON	298 5TH ST	S 1/8 - 1/4 (0.227 mi.)	AO335	927

EPA ID: NYP004570321				
CON EDISON SERVICE B EPA ID: NYP004337168	***315 4TH ST S***	***SSE 1/8 - 1/4 (0.229 mi.)***	***AA338***	***934***
CON EDISON EPA ID: NYP004760401	391 2ND ST	SE 1/8 - 1/4 (0.238 mi.)	AI342	990
CON EDISON EPA ID: NYP004363230	314 5TH ST	S 1/8 - 1/4 (0.239 mi.)	AK346	1013
AMOCO SERVICE STATIO EPA ID: NYD986933109	***375-381 4TH AVE & 6T***	***SSW 1/8 - 1/4 (0.239 mi.)***	***AP348***	***1017***
CON EDISON SERVICE B EPA ID: NYP004326278	***195 5TH AVE FRONT OF***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AL352***	***1029***
U-HAUL CORP EPA ID: NY0000970509	***259 6TH ST - PARK SL***	***SSW 1/8 - 1/4 (0.243 mi.)***	***AP355***	***1039***
CON EDISON MANHOLE: EPA ID: NYP004322004	***267 6TH ST***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AO358***	***1048***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYD000706218	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A25	95
CON EDISON EPA ID: NYP004704946	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A26	96
CONSOLIDATED EDISON EPA ID: NYP000920355	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A36	142
CONSOLIDATED EDISON EPA ID: NYP000706218	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A39	146
CON EDISON EPA ID: NYP004703534	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A54	175
CON EDISON TM439 EPA ID: NYP004036729	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A55***	***176***
CON ED EPA ID: NYP004851131	222 1 ST	W 0 - 1/8 (0.027 mi.)	A59	187
CON EDISON EPA ID: NYP004704771	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A60	188
CON EDISON EPA ID: NYP004772869	221 1ST	WNW 0 - 1/8 (0.027 mi.)	A75	215
CON EDISON EPA ID: NYP004837696	***221 1ST ST***	***WNW 0 - 1/8 (0.027 mi.)***	***A76***	***216***
PS 418 K SCHOOL EPA ID: NYR000199968	***512 CARROLL ST***	***N 0 - 1/8 (0.038 mi.)***	***C94***	***247***
CON EDISON EPA ID: NYP004757548	511 CARROLL ST	N 0 - 1/8 (0.058 mi.)	C117	292
CON EDISON EPA ID: NYP004706313	319 3 AVE	WNW 0 - 1/8 (0.078 mi.)	F140	337
CONSOLIDATED EDISON EPA ID: NYP004155701	3RD AVE & 1ST STREET	WNW 0 - 1/8 (0.095 mi.)	F161	368
CON EDISON	318 3RD AVE FRONT OF	WNW 0 - 1/8 (0.104 mi.)	F170	382

EPA ID: NYP004325122				
CON EDISON - SERVICE EPA ID: NYP005136561	302 3RD AVE	NW 0 - 1/8 (0.108 mi.)	L173	393
CON EDISON EPA ID: NYP004974760	284 THIRD AVE	NNW 0 - 1/8 (0.121 mi.)	L185	427
CON EDISON EPA ID: NYP004959132	284 3RD AVE	NNW 0 - 1/8 (0.121 mi.)	L186	429
CON EDISON SERVICE B EPA ID: NYP004376315	***578 UNION ST***	***N 1/8 - 1/4 (0.137 mi.)***	***M194***	***449***
CON EDISON VAULT SUB EPA ID: NYP004476214	***213 3RD ST***	***W 1/8 - 1/4 (0.138 mi.)***	***N195***	***453***
CON EDISON EPA ID: NYP004743779	3RD ST & 3RD AVE	WSW 1/8 - 1/4 (0.140 mi.)	R199	463
CONSOLIDATED EDISON EPA ID: NYP004154290	3 AVE & 3 STREET & 6	WSW 1/8 - 1/4 (0.140 mi.)	R200	464
LINDA TOOL & DIE COR EPA ID: NYD987025822	***459 CARROLL ST***	***NW 1/8 - 1/4 (0.142 mi.)***	***L206***	***483***
CON EDISON EPA ID: NYP004551230	251 3RD AVE	N 1/8 - 1/4 (0.150 mi.)	S207	487
CON ED EPA ID: NYP004836340	617 UNION ST & 3RD A	N 1/8 - 1/4 (0.158 mi.)	M213	505
CON EDISON SERVICE B EPA ID: NYP004479192	***210 3RD ST***	***WSW 1/8 - 1/4 (0.159 mi.)***	***R215***	***507***
CON EDISON EPA ID: NYP004818912	451 CARROLL ST FRONT	NW 1/8 - 1/4 (0.162 mi.)	W223	573
CON EDISON EPA ID: NYP004795480	501 PRESIDENT ST	NNW 1/8 - 1/4 (0.166 mi.)	Q227	581
CON EDISON EPA ID: NYP004696415	450 CARROL ST	NW 1/8 - 1/4 (0.168 mi.)	W233	590
216 3RD STREET EPA ID: NYD001869049	***216 3RD ST***	***W 1/8 - 1/4 (0.172 mi.)***	***R236***	***596***
CON ED EPA ID: NYP004827627	443 CARROLL ST	NW 1/8 - 1/4 (0.172 mi.)	W237	600
190-220 THIRD STREET EPA ID: NYR000197178	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***607***
CON EDISON - SERVICE EPA ID: NYP005072996	484 PRESIDENT ST	NW 1/8 - 1/4 (0.182 mi.)	W252	674
CON EDISON SERVICE B EPA ID: NYP004479184	***198 3RD ST***	***W 1/8 - 1/4 (0.185 mi.)***	***AC257***	***686***
PIPPIN ENTERPRISES L EPA ID: NYD987023181	***220 3RD ST***	***WSW 1/8 - 1/4 (0.201 mi.)***	***AD273***	***748***
CON EDISON EPA ID: NYP005022769	232 3RD AVE	N 1/8 - 1/4 (0.205 mi.)	AF277	759
CON EDISON EPA ID: NYP004597928	227 3RD ST	W 1/8 - 1/4 (0.205 mi.)	AC278	760
CON EDISON MANHOLE:	***190 3RD ST FRONT OF***	***W 1/8 - 1/4 (0.208 mi.)***	***AC283***	***769***

EPA ID: NYP004479242				
CRUSADER CANDLE CO I EPA ID: NYD987005840	***325 NEVINS ST***	***NW 1/8 - 1/4 (0.208 mi.)***	***W286***	***791***
NYCDEP EPA ID: NYP010001790	SACKETT ST & 3RD AVE	N 1/8 - 1/4 (0.209 mi.)	AF289	803
473 PRESIDENT STREET EPA ID: NYR000232116	***473 PRESIDENT STREET***	***NNW 1/8 - 1/4 (0.210 mi.)***	***AG291***	***808***
BELL ATLANTIC-NY EPA ID: NYP000940593	SACKETT & 3 AVE MANH	N 1/8 - 1/4 (0.210 mi.)	AF293	817
CON ED EPA ID: NYP004822777	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH294	818
CON EDISON EPA ID: NYP004734786	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH295	820
CON EDISON EPA ID: NYP004698718	CARROLL ST AND NEVIN	NW 1/8 - 1/4 (0.210 mi.)	AH299	828
CON EDISON EPA ID: NYP004698700	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH301	831
VERIZON NEW YORK INC EPA ID: NYD987028008	***175 THIRD ST***	***W 1/8 - 1/4 (0.214 mi.)***	***AC307***	***846***
NEW YORK TELEPHONE C EPA ID: NYD987028016	***318 NEVINS ST***	***NW 1/8 - 1/4 (0.227 mi.)***	***AG332***	***917***
PARK SLOPE PAINT STR EPA ID: NYR000170472	***553 UNION ST***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AE345***	***995***
CON EDISON EPA ID: NYP004342978	408 CARROL ST	NW 1/8 - 1/4 (0.241 mi.)	AH350	1024

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 25 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004879932	255 4TH AVE	ENE 0 - 1/8 (0.039 mi.)	B99	266
CON EDISON EPA Id: NYP004757555	DENTON ST & CARROLL	NNE 0 - 1/8 (0.042 mi.)	C105	276
CON EDISON EPA Id: NYP004738910	22 GARFIELD ST	ESE 0 - 1/8 (0.066 mi.)	G125	308
CON EDISON EPA Id: NYP004743068	586 CARROL ST	E 0 - 1/8 (0.087 mi.)	G148	347
CON EDISON EPA Id: NYP004744306	590 CARROLL ST	E 0 - 1/8 (0.094 mi.)	G157	361
CON EDISON EPA Id: NYP004735734	577 CARROLL ST	E 0 - 1/8 (0.104 mi.)	K167	376
CON EDISON EPA Id: NYP004783759	354 3RD ST	SSE 1/8 - 1/4 (0.180 mi.)	AA250	671
SUSAN MAINTENANCE	***374 4TH AVE***	***SSW 1/8 - 1/4 (0.187 mi.)***	***Z259***	***692***

EPA Id: NYR000076091				
CON EDISON EPA Id: NYP004825176	365 2ND ST	SE 1/8 - 1/4 (0.195 mi.)	U267	733
CON EDISON EPA Id: NYP004731998	335 1ST ST	ESE 1/8 - 1/4 (0.207 mi.)	U279	762
CON EDISON EPA Id: NYP004738498	676 PRESIDENT ST	E 1/8 - 1/4 (0.216 mi.)	AJ314	863
CON EDISON EPA Id: NYP004738811	675 PRESIDENT ST	E 1/8 - 1/4 (0.223 mi.)	AJ322	883
CON EDISON EPA Id: NYP004781910	664 DEGRAW ST	NE 1/8 - 1/4 (0.226 mi.)	AN326	895
CON EDISON EPA Id: NYP004760401	391 2ND ST	SE 1/8 - 1/4 (0.238 mi.)	AI344	994

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - 3RD AVE EPA Id: NYD000706218	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A33***	***107***
CON EDISON EPA Id: NYP004757548	511 CARROLL ST	N 0 - 1/8 (0.058 mi.)	C119	296
CON EDISON EPA Id: NYP004743779	3RD ST & 3RD AVE	WSW 1/8 - 1/4 (0.140 mi.)	R196	457
CON EDISON EPA Id: NYP004818912	451 CARROLL ST FRONT	NW 1/8 - 1/4 (0.162 mi.)	W225	577
CON EDISON EPA Id: NYP004795480	501 PRESIDENT ST	NNW 1/8 - 1/4 (0.166 mi.)	Q229	584
190-220 THIRD STREET EPA Id: NYR000197178	214 3RD ST	W 1/8 - 1/4 (0.173 mi.)	R239	604
CRUSADER CANDLE CO I EPA Id: NYD987005840	325 NEVINS ST	NW 1/8 - 1/4 (0.208 mi.)	W284	773
CON EDISON EPA Id: NYP004841512	SACKETT ST & 3RD AVE	N 1/8 - 1/4 (0.209 mi.)	AF288	802
CON EDISON - TRANSFO EPA Id: NYP004734786	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH296	821
CON EDISON EPA Id: NYP004822777	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH300	830
PARK SLOPE PAINT STR EPA Id: NYR000170472	***553 UNION ST***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AE345***	***995***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 4 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
275 4TH AVENUE INVES Generator EPA Id: NYD986914133	275 4TH AVENUE	ESE 0 - 1/8 (0.026 mi.)	A18	87
CON EDISON	237 4TH AVE	NE 0 - 1/8 (0.078 mi.)	H141	338

Generator EPA Id: NYP005107804				
CON EDISON Generator EPA Id: NYP005107812	226 4TH AVE	NE 0 - 1/8 (0.122 mi.)	O187	430

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - UNION S Generator EPA Id: NYP004836340	617 UNION STREET	N 1/8 - 1/4 (0.158 mi.)	M214	506

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 5 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FULTON MUNICIPAL WOR	NEVINS, DEGRAW AND S	NNW 1/4 - 1/2 (0.290 mi.)	AQ373	1103
FULTON WORKS	DEGRAW STREET AND NE	N 1/4 - 1/2 (0.317 mi.)	AV381	1116
BU-METROPOLITAN MGP	124-136 SECOND AVE	WSW 1/2 - 1 (0.539 mi.)	BI440	1370
FORMER CITIZEN GAS W	5TH STREET AND SMITH	W 1/2 - 1 (0.563 mi.)	441	1370
USPS GOWANUS SITE. F	2ND AVENUE AND 12TH	WSW 1/2 - 1 (0.638 mi.)	443	1372

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DIANA FUEL CORP	275 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A17	87
RIDGE AUTO TRANSMISS	270 4TH AVE	NE 0 - 1/8 (0.031 mi.)	B88	236
PARKSIDE SERVICE STA	340 FOURTH AVE	SSW 0 - 1/8 (0.119 mi.)	P184	427

EXECUTIVE SUMMARY

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
B M T STOP DRY CLEAN	230 4TH AVE STE B	NE 0 - 1/8 (0.111 mi.)	O179	400

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 12 records.

Site Name	Database(s)
BROOKLYN MILITARY OCEAN TERMINAL	NY SHWS
DAVIDSON PIPE SUPPLY COMPANY	NY SHWS
HAMILTON AVENUE PIERS/19TH & 18TH	NY SHWS
CARROL GARDEN	SEMS-ARCHIVE
CONEY ISLAND, STILLWELL AND NEPTUN	NY SWF/LF
PAERDEGAT BASIN NORTH	NY SWF/LF
BASEMENT	NY LTANKS
25 ST & 4TH AVENUE	NY Spills
USPS GOWANUS SITE, FORMER MGP METR	NY VCP
455 SMITH STREET (VICHAR, INC.)	NY VCP
FULTON MUNICIPAL WORKS	NY VCP
DANGMAN PARK	NY VCP

OVERVIEW MAP - 07124126.2R



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	296 4th Avenue	CLIENT:	Haley & Aldrich, Inc.
ADDRESS:	296 4th Avenue Brooklyn NY 11215	CONTACT:	Sarah Commisso
		INQUIRY #:	07124126.2r
LAT/LONG:	40.675577 / 73.985041	DATE:	September 20, 2022 5:23 pm

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 07124126.2R



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 296 4th Avenue ADDRESS: 296 4th Avenue Brooklyn NY 11215 LAT/LONG: 40.675577 / 73.985041	CLIENT: Haley & Aldrich, Inc. CONTACT: Sarah Commisso INQUIRY #: 07124126.2r DATE: September 20, 2022 5:24 pm

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	1	0	0	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	1	0	NR	NR	1
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	3	NR	NR	3
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	1	1	NR	2
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		6	8	NR	NR	NR	14
RCRA-SQG	0.250		1	4	NR	NR	NR	5
RCRA-VSQG	0.250		0	4	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	1	0	NR	NR	1
US INST CONTROLS	0.500		0	1	0	NR	NR	1
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	0	2	5	NR	7
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		2	2	10	NR	NR	14
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		1	11	30	NR	NR	42
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		5	14	NR	NR	NR	19
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	1	NR	NR	1
NY MOSF	0.500		0	0	1	NR	NR	1
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		6	17	NR	NR	NR	23
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		1	1	NR	NR	NR	2
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	1	3	NR	NR	4
NY INST CONTROL	0.500		0	1	4	NR	NR	5
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		4	2	7	NR	NR	13
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		2	11	12	NR	NR	25
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	3	NR	NR	3
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	2	NR	2
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		75	NR	NR	NR	NR	75
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	21	52	NR	NR	NR	74
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	1	0	0	NR	1
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	1	NR	NR	NR	NR	NR	1
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	2	NR	NR	NR	NR	NR	2
DOCKET HWC	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UXO	1.000		0	0	0	0	NR	0
ECHO	TP	2	NR	NR	NR	NR	NR	2
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	3	NR	NR	NR	3
NY E DESIGNATION	0.125		18	NR	NR	NR	NR	18
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	1	NR	NR	1
NY MANIFEST	0.250	1	37	69	NR	NR	NR	107
NJ MANIFEST	0.250		8	17	NR	NR	NR	25
PA MANIFEST	0.250		3	1	NR	NR	NR	4
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	2	3	NR	5
EDR Hist Auto	0.125	1	3	NR	NR	NR	NR	4
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		8	194	224	80	11	0	517

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

MAACO AUTO PAINTING -296 4TH AVE
296 4TH AVE.
BROOKLYN, NY 11215

US AIRS **1006042115**
FINDS **N/A**
ECHO

Site 1 of 83 in cluster A

Actual:
23 ft.

US AIRS MINOR:

Envid:	1006042115
Region Code:	02
Programmatic ID:	AIR NY0000002610300124
Facility Registry ID:	110001593339
D and B Number:	Not reported
Primary SIC Code:	7532
NAICS Code:	811121
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610300124
Facility Registry ID:	110001593339
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1998-10-30 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610300124
Facility Registry ID:	110001593339
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2007-05-29 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:
Registry ID: 110001593339

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major

MAACO AUTO PAINTING -296 4TH AVE (Continued) **1006042115**

redesign to support facility operating permits required under Title V of the Clean Air Act.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1006042115
Registry ID:	110001593339
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001593339
Name:	MAACO AUTO PAINTING -296 4TH AVE
Address:	296 4TH AVE.
City,State,Zip:	BROOKLYN, NY 11215

A2 **JEN JAY TRANSMISSION INC** **EDR Hist Auto** **1022021870**
Target Property **296 4TH AVE** **N/A**
BROOKLYN, NY 11215

Site 2 of 83 in cluster A

Actual: 23 ft.

EDR Hist Auto

Year:	Name:	Type:
1979	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1980	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1982	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1983	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1985	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1986	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1987	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1988	JEN JAY TRANSMISSION INC	Automotive Repair Shops, NEC
1989	JEN JAY TRANSMISSION INC	Automotive Transmission Repair Shops
1990	JEN JAY TRANSMISSION INC	Automotive Transmission Repair Shops
1991	JEN JAY TRANSMISSION INC	Automotive Transmission Repair Shops
1992	JEN JAY TRANSMISSION INC	Automotive Transmission Repair Shops
1993	JEN JAY TRANSMISSION INC	Automotive Transmission Repair Shops
2002	AFFORTABLE AUTO COLLISION	General Automotive Repair Shops
2003	AFFORTABLE AUTO COLLISION	General Automotive Repair Shops
2004	AFFORTABLE AUTO COLLISION	General Automotive Repair Shops
2005	AFFORTABLE AUTO COLLISION	General Automotive Repair Shops

---

A3 **MAACO AUTO PAINTING & BODYWORKS INC** **RCRA NonGen / NLR** **1000457406**
Target Property **296 4TH AVE & 1ST ST** **FINDS** **NYD986925642**
BROOKLYN, NY 11215 **ECHO**
NY MANIFEST

Site 3 of 83 in cluster A

Actual: 23 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	MAACO AUTO PAINTING & BODYWORKS INC
Handler Address:	296 4TH AVE & 1ST ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYD986925642

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000457406**

Contact Name:		Not reported
Contact Address:		4TH AVE & 1ST ST
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4TH AVE & 1ST ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	VINCENT NICASTRO	
Owner Type:		Private
Operator Name:	VINCENT NICASTRO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000457406**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: VINCENT NICASTRO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000457406**

Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: VINCENT NICASTRO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: VINCENT NICASTRO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000457406**

Receive Date: 20070101
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901004
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000457406**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19980920
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110008043900

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000457406
Registry ID:	110008043900
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008043900
Name:	MAACO AUTO PAINTING & BODYWORKS INC
Address:	296 4TH AVE & 1ST ST
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	MAACO AUTO PAINTING & BODYWORKS INC
Address:	296 4TH AVE & 1ST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYD986925642

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000457406**

Facility Status:	Not reported
Location Address 1:	296 4TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986925642
Mailing Name:	MAACO AUTO PAINTING & BODYWORKS INC
Mailing Contact:	VINCENT NICASTRO
Mailing Address 1:	296 4TH AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188525505

NPL **GOWANUS CANAL** **NPL** **1010782149**
Region **BUTLER ST (BETWEEN BOND ST AND NEVINS ST** **SEMS** **NYN000206222**
WSW **BROOKLYN, NY 11231** **US ENG CONTROLS**
1/8-1/4 **US INST CONTROLS**
1037 ft. **ROD**
PRP
ICIS
FINDS
ECHO

NPL:

EPA Region:	2
EPA ID:	NYN000206222
Site ID:	206222
Name:	GOWANUS CANAL
Address:	BUTLER ST (BETWEEN BOND ST AND NEVINS ST
City,State,Zip:	BROOKLYN, NY 11231
Federal:	N
Final Date:	2010-03-04 00:00:00
Latitude:	40.681639
Longitude:	-73.987333
Site Score:	50
NAI:	Not reported
Native American Entity:	Not reported

SEMS:

Site ID:	0206222
EPA ID:	NYN000206222
Name:	GOWANUS CANAL
Address:	BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11231
Cong District:	07

GOWANUS CANAL (Continued) **1010782149**

FIPS Code: 36047
Latitude: +40.681639
Longitude: -73.987333
FF: N
NPL: Currently on the Final NPL
Non NPL Status: Not reported

SEMS Detail:

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 2013-09-30 05:00:00
Finish Date: Not reported
Qual: E
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2008-01-10 05:00:00
Finish Date: 2008-01-10 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 00
Action Code: NF
Action Name: NPL FINL
SEQ: 1
Start Date: 2010-03-04 05:00:00
Finish Date: 2010-03-04 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F

GOWANUS CANAL (Continued) **1010782149**

FF:	N
OU:	00
Action Code:	NP
Action Name:	PROPOSED
SEQ:	1
Start Date:	2009-04-09 04:00:00
Finish Date:	2009-04-09 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	00
Action Code:	HR
Action Name:	HAZRANK
SEQ:	1
Start Date:	2009-04-09 04:00:00
Finish Date:	2009-04-09 04:00:00
Qual:	O
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	RO
Action Name:	ROD
SEQ:	1
Start Date:	2013-09-27 05:00:00
Finish Date:	2013-09-27 05:00:00
Qual:	R
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	2009-07-21 05:00:00
Finish Date:	2013-09-27 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206222

GOWANUS CANAL (Continued) **1010782149**

EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 00
Action Code: TG
Action Name: TA GRANT
SEQ: 1
Start Date: 2012-09-14 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 00
Action Code: CR
Action Name: CI
SEQ: 1
Start Date: 2012-05-11 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: TS
Action Name: TRTSTUDY
SEQ: 1
Start Date: 2014-09-30 05:00:00
Finish Date: 2015-06-10 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: NA
Action Name: PRP RI
SEQ: 1
Start Date: 2010-04-29 04:00:00
Finish Date: 2010-08-06 05:00:00
Qual: Not reported
Current Action Lead: EPA Ovrsght

GOWANUS CANAL (Continued) **1010782149**

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: NA
Action Name: PRP RI
SEQ: 2
Start Date: 2010-04-29 04:00:00
Finish Date: 2010-08-06 05:00:00
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: NA
Action Name: PRP RI
SEQ: 3
Start Date: 2010-04-29 04:00:00
Finish Date: 2010-08-06 05:00:00
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: NA
Action Name: PRP RI
SEQ: 4
Start Date: 2010-04-29 04:00:00
Finish Date: 2010-11-23 05:00:00
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 1
Start Date: 2013-09-26 05:00:00
Finish Date: 2015-03-16 04:00:00

GOWANUS CANAL (Continued) **1010782149**

Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	3
Start Date:	2014-08-07 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	2
Start Date:	2014-06-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BE
Action Name:	PRP RD
SEQ:	1
Start Date:	2014-04-21 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	00
Action Code:	EE
Action Name:	EE/CA

GOWANUS CANAL (Continued) **1010782149**

SEQ: 1
Start Date: 2016-04-14 05:00:00
Finish Date: 2016-06-09 04:00:00
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 5
Start Date: 2017-11-17 05:00:00
Finish Date: 2018-08-14 05:00:00
Qual: S
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 8
Start Date: 2017-06-26 04:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 6
Start Date: 2017-03-27 05:00:00
Finish Date: 2019-08-14 05:00:00
Qual: S
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N

GOWANUS CANAL (Continued) **1010782149**

OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	7
Start Date:	2017-05-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	9
Start Date:	2018-05-24 04:00:00
Finish Date:	2021-09-23 05:00:00
Qual:	S
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	11
Start Date:	2015-07-09 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	10
Start Date:	2018-09-27 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206222
EPA ID:	NYN000206222

GOWANUS CANAL (Continued) **1010782149**

Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	12
Start Date:	2019-04-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	13
Start Date:	2019-08-23 05:00:00
Finish Date:	2020-09-14 05:00:00
Qual:	S
Current Action Lead:	EPA Ovrsght

Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BF
Action Name:	PRP RA
SEQ:	2
Start Date:	2020-07-21 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	02
Site ID:	0206222
EPA ID:	NYN000206222
Site Name:	GOWANUS CANAL
NPL:	F
FF:	N
OU:	01
Action Code:	BB
Action Name:	PRP RV
SEQ:	16
Start Date:	2020-04-09 05:00:00
Finish Date:	2021-09-23 05:00:00
Qual:	S
Current Action Lead:	EPA Ovrsght

GOWANUS CANAL (Continued) **1010782149**

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 14
Start Date: 2020-02-12 06:00:00
Finish Date: 2021-09-23 05:00:00
Qual: S
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 15
Start Date: 2020-02-21 06:00:00
Finish Date: 2021-09-23 05:00:00
Qual: S
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 17
Start Date: 2020-07-24 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 21
Start Date: 2021-05-17 05:00:00
Finish Date: Not reported

GOWANUS CANAL (Continued) **1010782149**

Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206222
EPA ID: NYN000206222
Site Name: GOWANUS CANAL
NPL: F
FF: N
OU: 01
Action Code: BB
Action Name: PRP RV
SEQ: 22
Start Date: 2021-07-01 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Ovrsght

SIte:
Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11231
Event Code: Not reported
Action Taken Date: 09/27/2013
EPA ID: NYN000206222
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Contaminated Media: Free-phase NAPL
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2013
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +40.681639
Longitude: -73.987333

Media:
EPA ID: NYN000206222
Contaminated Media: Free-phase NAPL
Action ID: 1
Operable Unit: 01
Action Name: Record of Decision
Action Taken Date: 09/27/2013
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2013
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +40.681639

GOWANUS CANAL (Continued) **1010782149**

Longitude:	-73.987333
EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333
EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333
EPA ID:	NYN000206222
Contaminated Media:	Free-phase NAPL
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333
EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01

GOWANUS CANAL (Continued) **1010782149**

Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Free-phase NAPL
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported

GOWANUS CANAL (Continued) **1010782149**

Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Free-phase NAPL
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

GOWANUS CANAL (Continued) **1010782149**

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Free-phase NAPL
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013

GOWANUS CANAL (Continued) **1010782149**

Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Free-phase NAPL
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.681639
Longitude:	-73.987333

EPA ID:	NYN000206222
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/27/2013
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2013

GOWANUS CANAL (Continued) **1010782149**

NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +40.681639
Longitude: -73.987333

US INST CONTROLS:
Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11231
EPA ID: NYN000206222
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Actual Date: 09/27/2013
Contaminated Media: Free-phase NAPL
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2013
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +40.681639
Longitude: -73.987333

Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11231
EPA ID: NYN000206222
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Actual Date: 09/27/2013
Contaminated Media: Sediment
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2013
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +40.681639
Longitude: -73.987333

ROD:
Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
City,State,Zip: BROOKLYN, NY 11231
EPA ID: NYN000206222
RG: 2
Site ID: 206222

GOWANUS CANAL (Continued) **1010782149**

Action: GOVT Decision Document (ROD)
Operable Unit Number: CANAL SEDIMENTS
SEQ ID: 1
Action Completion: 2013-09-27 00:00:00
NPL Status: Final
Non NPL Status: Not reported

PRP:
PRP Name:
155 THIRD STREET, LLC
163 6TH STREET LLC
300 HUNTINGTON STREET LLC
3911 LEMMON AVENUE ASSOCIATES
420 CARROLL LLC
450 UNION LLC
539 SMITH STREET REALTY CORP
AMERADA HESS CORP.
AMERADA HESS CORP.
AMERADA HESS CORP.
BAYSIDE FUEL OIL DEPOT CORPORATION
BAYSIDE FUEL OIL DEPOT CORPORATION
BAYSIDE FUEL OIL DEPOT CORPORATION
BEAZER EAST INC
BEAZER EAST INC
BEAZER EAST INC
BEAZER EAST INC
BENSON METAL CORP
BRINK'S INC
BRINK'S INC

Click this hyperlink while viewing on your computer to access
65 additional PRP: record(s) in the EDR Site Report.

ICIS:
Enforcement Action ID: 02-2016-2003
FRS ID: 110033604197
Action Name: City of New York
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 106
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698
Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2015-2012
FRS ID: 110033604197
Action Name: Bayside Fuel Oil Corp. et al.
Facility Name: GOWANUS CANAL

GOWANUS CANAL (Continued) **1010782149**

Facility Address:	BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type:	CERCLA 106 AO For Resp Action/Imm Haz
Facility County:	KINGS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	106
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.676033
Longitude in Decimal Degrees:	-73.99698
Permit Type Desc:	Not reported
Program System Acronym:	2200000435
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-2015-2008
FRS ID:	110033604197
Action Name:	Patterson Fuel Oil Co., Inc. (SB)
Facility Name:	GOWANUS CANAL
Facility Address:	BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type:	CERCLA 122h Agrmt For Cost Recovery
Facility County:	KINGS
Program System Acronym:	CERCLIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	122H
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.67893
Longitude in Decimal Degrees:	-73.99422
Permit Type Desc:	Not reported
Program System Acronym:	NYN000206222
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-2014-2019
FRS ID:	110033604197
Action Name:	City of New York
Facility Name:	GOWANUS CANAL
Facility Address:	BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type:	CERCLA 106 AO For Resp Action/Imm Haz
Facility County:	KINGS
Program System Acronym:	CERCLIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	106
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.67893
Longitude in Decimal Degrees:	-73.99422
Permit Type Desc:	Not reported
Program System Acronym:	NYN000206222
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	02-2014-2008

GOWANUS CANAL (Continued) **1010782149**

FRS ID: 110033604197
Action Name: LSG 365 Bond Street, LLC
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type: Prospective Purchaser Agreement
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: PPA
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698
Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2014-2004
FRS ID: 110033604197
Action Name: LSG 363 Bond Street, LLC
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type: Prospective Purchaser Agreement
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: PPA
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698
Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2014-2001
FRS ID: 110033604197
Action Name: Beam, Inc. et al.
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 106
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698
Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported

GOWANUS CANAL (Continued) **1010782149**

Tribal Land Code: Not reported

Enforcement Action ID: 02-2013-2023
FRS ID: 110033604197
Action Name: Benson Metal Corp. et al.
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: KINGS
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 106
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67893
Longitude in Decimal Degrees: -73.99422
Permit Type Desc: Not reported
Program System Acronym: NYN000206222
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2010-2022
FRS ID: 110033604197
Action Name: Joyce A. Kjellgren
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 104E5A AO For Access And/Or Info
Facility County: KINGS
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 104E5A
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67893
Longitude in Decimal Degrees: -73.99422
Permit Type Desc: Not reported
Program System Acronym: NYN000206222
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2010-2022
FRS ID: 110033604197
Action Name: Joyce A. Kjellgren
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 104E5A AO For Access And/Or Info
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 104E5A
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698

GOWANUS CANAL (Continued) **1010782149**

Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2010-2011
FRS ID: 110033604197
Action Name: City of New York
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 122A/104A Agrmt For RI/FS
Facility County: KINGS
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 122/104
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67893
Longitude in Decimal Degrees: -73.99422
Permit Type Desc: Not reported
Program System Acronym: NYN000206222
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2010-2011
FRS ID: 110033604197
Action Name: City of New York
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 122A/104A Agrmt For RI/FS
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 122/104
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698
Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2010-2009
FRS ID: 110033604197
Action Name: Brooklyn Union Gas Co. d/b/a National Grid NY
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 122A/104A Agrmt For RI/FS
Facility County: KINGS
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 122/104
Facility SIC Code: Not reported

GOWANUS CANAL (Continued) **1010782149**

Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67893
Longitude in Decimal Degrees: -73.99422
Permit Type Desc: Not reported
Program System Acronym: NYN000206222
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2010-2009
FRS ID: 110033604197
Action Name: Brooklyn Union Gas Co. d/b/a National Grid NY
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231
Enforcement Action Type: CERCLA 122A/104A Agrmt For RI/FS
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 122/104
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.676033
Longitude in Decimal Degrees: -73.99698
Permit Type Desc: Not reported
Program System Acronym: 2200000435
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2009-0017
FRS ID: 110033604197
Action Name: Chemtura Corporation (NC)
Facility Name: GOWANUS CANAL
Facility Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231
Enforcement Action Type: Bankruptcy
Facility County: KINGS
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Judicial
EA Type Code: BNK
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67893
Longitude in Decimal Degrees: -73.99422
Permit Type Desc: Not reported
Program System Acronym: NYN000206222
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL

GOWANUS CANAL (Continued) **1010782149**

Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST

GOWANUS CANAL (Continued) **1010782149**

Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
Tribal Indicator: N

GOWANUS CANAL (Continued) **1010782149**

Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

FINDS:
Registry ID: 110033604197

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
SUPERFUND NPL
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1010782149
Registry ID: 110033604197
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110033604197
Name: GOWANUS CANAL
Address: BUTLER ST (BETWEEN BOND ST AND NEVINS ST
City,State,Zip: BROOKLYN, NY 11231

A4 **CON EDISON** **NY MANIFEST** **S117318093**
292 4TH AV **N/A**
< 1/8 **BROOKLYN, NY 11215**
1 ft.

Site 4 of 83 in cluster A

Relative: Higher
Actual: 24 ft.

NY MANIFEST:
Name: CON EDISON
Address: 292 4TH AV
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004655908
Facility Status: Not reported
Location Address 1: 292 4TH AV
Code: BP
Location Address 2: SB45404
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

CON EDISON (Continued) **S117318093**

NY MANIFEST:

EPAID:	NYP004655908
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/12/2014
Trans1 Recv Date:	09/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004655908
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617216GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117318093**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A5 **CON EDISON** **NY MANIFEST** **S117314471**
292 4TH AV **N/A**
< 1/8 **BROOKLYN, NY 11201**
1 ft.

Site 5 of 83 in cluster A

Relative: **Higher**
Actual: **24 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	292 4TH AV
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004615274
Facility Status:	Not reported
Location Address 1:	292 4TH AV
Code:	BP
Location Address 2:	SB4504
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004615274
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/01/2014
Trans1 Recv Date:	08/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004615274
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117314471**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013254945JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A6 **MC DONALD'S** **NY Spills** **S107658364**
WNW **245 1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.008 mi.
40 ft. **Site 6 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual:
20 ft.

Name:	MC DONALD'S
Address:	245 1ST STREET
City,State,Zip:	BROOKLYN, NY 11215
Spill Number/Closed Date:	0551768 / 2013-10-07
Facility ID:	0551768
Facility Type:	ER
DER Facility ID:	311447
Site ID:	361253
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-02-01
Investigator:	ADZHITOM
Referred To:	NFA
Reported to Dept:	2006-02-01
CID:	Not reported

MC DONALD'S (Continued) **S107658364**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2013-10-29
Spiller Name:	Not reported
Spiller Company:	DAVID OIL CORP
Spiller Address:	3333 NEW HYDE PARK ROAD SUITE 201
Spiller Company:	001
Contact Name:	DAVID OIL CORPORATION
DEC Memo:	"3/20/2006 An investigation was performed at adjacent property 269-271 4th Avenue Brooklyn by Hydro Tech Environmental (spill# 0501021). Marvin Kramer & Associates sumbitted a report on February 1, 2006, which stated that the property 269-271 4th Avenue was investigated by Hydro Tech Env and it is located downgradient from a possible source. The report also stated that the property adjacent to the investigated property on the north is presently occupied by Mc Donald and was formerly a gas station. After a consultation with Koon Tang (DEC) spill #05517680 was opened and Spill#0501021 was closed. AZ 3/22/2006 A contaminated soil letter was sent by certified mail to David Oil Corporation 3333 New Hyde Park Road, NY, 11042 AZ 3/28/2006 Contacted Kevin Kleaka (Impact Environmental 631-269-8800). The owner received DEC letter and will hire Impact Environmental to perform the investigation. The owner's phone number is 516-365-8700. (Henry Albert - President). I requested a submittal of site investigation plan and site background information. They will submit a plan by Apil 7, 2006. AZ 4/18/2006 Reviewed and discussed with Kevin Kleaka submitted Investigation Plan. Twelve 550 gal gasoline tanks, one 550 gal fuel oil and one 550 waste oil tanks were historically operated at the site (275 Fourth Avenue-281 Fourth Avenue)since 1967. Former gasoline tanks were probably located in the southwest corner at the intersection of 1st Street and 4th Avenue. Tanks were removed in September 1990. I made several changes to the Work Plan: at least 2 diameter wells should be installed, if no samples with PID readings are encountered, a sample at water-soil interface should be taken, plume should be fully delineated, test borings should be advanced at the former pump islands, 5 wells should be installed. The plan with these corrections was approved. AZ 6/12/2006 Contacted Kevin Kleaka. They will conduct the field work next week. The client worked out access agreement with Mc Donald's. The work will be done during the middle of the night. AZ 10/24/2006 I contacted Kevin Kleaka (Impact Environmental @631-269-8800). They sent the report to DEC last night. GW contamination was found. AZ 11/14/2006 Report dated October 24, 2006, was submitted to DEC. The report found dissolved gw contamination up to 5,624 ppb. The plume is not fully delineated. The analytical results for VOC concentrations should be expressed in total VOCs. Impact Environmental did not establish groundwater flow direction, although based on the presented data, gw flow direction appears to be to the north-east. Location of the former tanks were not shown on the plan. Groundwater contour map was not included in the report. I left a message for Kevin Kleaka (Impact Environmental

MC DONALD'S (Continued) **S107658364**

@631-269-8800). AZ 11/15/2006 I contacted Kevin Kleaka (Impact Environmental @631-269-8800). We discussed the site. Impact Environmental will install an additional well in the vicinity of MW-3 on 1st Street sidewalk (southern side of the street) depending on the utilities. Suggested ORC seems to be a reasonable remedy for the existing contamination. Remedial Action will be submitted to DEC. AZ 2/26/2007 Reviewed Corrective Action Plan submitted by Impact Environmental on December 26, 2006. Dissolved VOC were found in groundwater. MW-3 had 5,677 ppb of total VOC.Impact Environmental suggested implementing ORC injection. DEC concurred. A letter with the plan approval was sent to Impact Environmental. AZ 7/17/2007 Contacted Kevin Kleaka (Impact Environmental @631-269-8800). They started the injections on July 5, 2007. Due to the Mc Donald's complains they had to change their work hours. They will finish injection on July 30th. They will submit the report by the end of August. AZ 2/25/2008 Called Mr. Wenqinq Fang (Impact Environmental @631-269-8800) and discussed the site. MW-2 contained approximately 415 ppb of total VOCs (October 2007). ORC injection was performed in July 2007 - one round. I requested that Impact Environmental submit to DEC the following: Total calculated VOCs and SVOCs concentrations, individual contaminant concentrations should be compared to NYS DEC Guidance Values, a plume map should be submitted (block diagrams with total VOC/SVOC concentrations), gw flow direction should be shown on the plan and recommendations for the site should provided. An amendment to the report dated October 29, 2007, should be submitted to DEC by mid March. They will send us an electronic copy of the report. AZ 3/3/2008 I contacted the owner Henry Alpert. His mailing address is: David Oil Corp. 333 New Hyde Park Rd. New Hyde Park, NY 11042 Suite# 201. I reiterated DEC's requests. They will submit the modified report by the end of the week. AZ 6-2-2008 Reviewed quarterly monitoring report dated March 11, 2008 by Impact Environmental. Samples obtained from MW-1, 2,3 and MW-5 detected concentrations of gasoline related compounds above NYSDEC ambient water quality standards. A decline in contaminant concentrations after ORC injection was observed. Groundwater monitoring will be continued. I left a message for Kevin Kleaka @631-269-8800 and requested an electronic copy of the report. AZ 9-4-2008 Reviewed quarterly monitoring report (first quarter of 2008) dated May 6, 2008, by Impact Environmental. In July 2007 ORC was injected through 11 injection points. 510 LBS of ORC mixed to a 70% slurry was injected at the site. Upon completion of ORC injection groundwater monitoring is performed. Groundwater samples acquired from MW-1, MW-2, MW-3 and MW-5 showed elevated concentrations of gasoline related VOCs (up to 378 ppb of total VOCs). Monitoring data showed a decline in contaminant concentrations, indicating that ORC has enhanced biodegradation. Impact Environmental will continue groundwater monitoring. AZ 11-04-2008 Reviewed and discussed with Kevin Kleaka(Impact Environmental) Quarterly Monitoring Report for the 2nd Quarter 2008 and ORC Injection Proposals dated September 4, 2008. Injection plan did not propose injection points near MW-1 and MW-2, the most contaminated wells (529 and 630 ppb of total VOC). I asked for injection plan modification. I also requested that downgradient wells be installed north of MW-1 and MW-2, utilities and structures allowing. AZ 11-10-2008 Called Wenqinq Fang (Impact Environmental tel. #631-269-8800) and conveyed my comments regarding the site. He stated that there is a building (auto repair shop) situated north of the former gas station which prevents installation

MC DONALD'S (Continued) **S107658364**

of the downgradient wells. I requested submittal of a sketch made to scale which would show locations of the surrounding structures and the sidewalk. An explanation why the downgradient wells could not be installed should be submitted to DEC. AZ 12-04-2008 An email was sent to W. Feng (Imact Environmental): I have reviewed and discussed with you and Kevin Kleaka Quarterly Monitoring Report for the 2nd Quarter 2008 and ORC Injection Proposals dated September 4, 2008, for the above site. Submitted Injection Plan did not propose injection points near MW-1 and MW-2, the most contaminated wells (529 ppb and 630 ppb of total VOC concentrations). The Department requests injection plan modification. Downgradient wells should be installed north of MW-1 and MW-2, utilities and structures allowing. Also, a site sketch to scale showing locations of the surrounding structures and the sidewalk should be submitted to DEC. AZ 3-29-2009 Additional Remediation WP was received on 3-10-2009. The site was formerly utilized as a gas station. In July 2007 application of ORC was conducted on the site as part of the bio-remediation strategy. By June 2008, according to the consultant, significant reduction in contaminants' levels has been observed. Despite the performed remedial actions, some dissolved VOC contamination remains at the site. Additonal ORC injections via 13 injection points were proposed. According to the consultant, gw flow direction is towards north. The adjacent downgradient property has a building that occupied the entire property, and so does the property next to it. The nearest possible location for a downgradient well would be on the sidewalk of Carrol St., which 100 ft. away from the site. According to the consultant, given the low concentration of the contaminants, downgradient well 100 ft away might not be useful. AZ 4-1-2009 An e-mail was sent to Impact Env./V. Brevdo: I have received and reviewed Additional Remediation Work Plan dated 3-10-2009. The above site was formerly utilized as a gas station. In July 2007 application of ORC was conducted on the site as part of the bio-remediation strategy. Despite the performed remedial actions, some dissolved VOC contamination remains at the site. Additional ORC injections via 13 injection points are proposed. The Additional Remediation Work Plan is approved. Total VOC concentrations should be calculated and presented in tables and shown on the Geochemical Results plate. If the contamination persists, downgradient monitoring wells should be installed on the sidewalk of Carroll Street. AZ' 3-25-2010 Reviewed Quarterly Monitoring Report (1st Quarter 2010) for this site. Impact Env. states that in 2 rounds of ORC about 900 lbs of ORC has been injected at this site. Impact states that more than 90% of the groundwater contamination has been remediated by enhanced bio degradation. However, residual groundwater contamination is present at the site (up to about 300 ppb of total VOC). MW-1 exhibited 97.1 ppb of benzine on 2/24/2010. I contacted Wenqinq Fang of Impact and requested historical information on VOC contamination (total VOC concentrations) correlated with ORC injection dates. Also, information regarding soil contamination will be submitted to DEC. AZ 4-15-10 Received tank closure report and Total VOCs table and e-doc'ed. An e-mail was sent to Wenqinq Fang: I received the attached files. Thanks. But you were supposed to send also soil plume information: tables with total VOCs and SVOCs and a plume map. This info has not been included. I checked the numbers. Individual contaminant concentrations in gw are relatively high so it's premature to work on the Exposure Assessment for the spill closure. AZ 6-24-2010 Reviewed Quarterly Monitoring Report (2nd Quarter 2010)

MC DONALD'S (Continued) **S107658364**

for this site by Impact Env. I contacted Wenqinq Fang of Impact and requested that a plume map be submitted to DEC with total VOC concentrations for each well sampled. Also, report was wrongly dated. Analysis of the last monitoring and sampling round should be done. The date of the sampling should be indicated. The moniroing report should be resubmitted with the changes. Also, information regarding soil contamination will be submitted to DEC. AZ 6-3-2010 Received modified 2nd Quarter Report from Wenqinq Fang (e-file). AZ 8-19-2010 Contacted Wenqing Fang. They requested reduction of frequency of sampling to semi-annual and remove MW-4 and MW-6. Total VOCs concentrations increased in four wells. Therefore, quarterly sampling be continued. MW-4 and MW-6 are upgradient wells with no detections since October 2007 and could be removed from the monitoring schedule. AZ 8-19-2010 An e-mail was sent to Wenqing Fang/V.Brevdo: I have reviewed revised monitoring report for the above site. You requested reduction of sampling frequency to semi-annual from quarterly. This request is denied due to increase in VOCs concentrations. Wells MW-4 and MW-6 could be removed from the monitoring schedule since no detections were recorded since October 2007. AZ 10-28-2010 Received and reviewed 3rd Quarter monitoring report. Total VOC concentrations in MW--528 ppb, MW-2 726 ppb. No further ORC injections are planned. AZ 3-31-2011 An e-mail was sent to Wenqing Fang and V. Brevdo: Dear Wenqinq, I have reviewed a quarterly sampling report for the above site submitted on March 24, 2011. Total VOCs ranged from 115 ppb to 340 ppb. The concentrations decreased in all wells except MW-3, where total VOC concentrations increased. Impact Environmental recommended reduction in monitoring schedule from quarterly to semi-annual. This recommendation is approved. Monitoring and sampling should be performed semi-annually (twice a year). AZ 11-29-2011 Reviewed Quarterly Monitoring Report and Exposure Assessment for this site. The VOCs numbers dropped in the last monitoring event 9/24/2011. However, there are exceedances of the groundwater standards. The last monitoring event results are generally significantly lower than in the previous monitoring rounds. I contacted Wenqing Fang and asked to have two more rounds of sampling. Also, I sent an email to Wenqing asking to submit e-copies of the above documents. 12-5-2011 Impact emailed me e-copies which were uploaded. AZ 9-5-2012 I reviewed Revised Exposure Assessment report dated May 31, 2012. I contacted Kevin Kleaka of Impact Environmental and discussed the site with him. The submitted report did not contain a CD with the PDF file. The latest monitoring data from 4/6/12 was no reflected in the groundwater plume map, however, this monitoring event was tabulated in table 2. The data in the tables does not corresspond with the data in the figures. Not all existing monitoring wells were sampled (MW-4 and MW-6 were not sampled). MW-1 contains 140 ppb of benzene. There is a hot spot at the location of monitoring well MW-1 and soil boring SP-1. Boring SP-1 exhibited a total VOC in soil of 46,371 ppb. Kevin Kleaka will review technical details of the report and will get back to me. He will send a CD with the PDF copy of report. AZ 9-14-2012 E-copy of exposure assessment was downloaded into e-docs. AZ 12-20-2012 Contacted Michael Bluight (Impact Env. Project Manager)631-269-8800 Ext.118. I updated Michael on the state of the spill. He will review the reports and will get back to me. AZ 4-1-2013 Discussed the site with Michael Bluight. Two downgradient wells at the edge of of the plume (MW-1 and MW-2) showed exceedances of gw standards. This exceedance might be indicative of a downgradient plume migration. Michael Bluight will submit details of

MC DONALD'S (Continued) **S107658364**

the tank excavation and soil investigation to DEC. Boring SP-1 exhibited total VOC in soil of 46371 ppb. AZ 4-17-2013 Received a revised semi-annual QMR report from Impact. Discussed the site with V. Brevdo and Michael Bluight. According to Tyree tank closure report (1990). About 14 tanks were excavated. The samples taken from the bottom excavation revealed total BTEX concentrations of 238,858 ppb and 131,718 ppb respectively. Total TPH concentrations were 1,1545 ppm and 68 ppm. AZ 10-7-2013 Received a semi-annual monitoring report from Impact Environmental. The report was dated August 14, 2013 and received on September 17, 2013. According to the report a soil probe was advanced and no exceedances of the standards were observed. The following e-mail was sent to Kevin Kleaka: Dear Kevin, I have reviewed a Request for Spill Closure dated August 14, 2013, and received on September 17, 2013. This spill is associated with a former gasoline filling and automobile service station. Fourteen Underground Storage Tanks (USTs) were removed in 1990 and eight USTs were removed in 1994. Approximately 218 tons of contaminated soil was removed. The results of the performed investigation indicated the presence of volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in subsurface soil and groundwater above the applicable guidance criteria. In 2007 and 2009 Oxygen Releasing Compound (ORC) application was conducted on the site to enhance bio-remediation. In June 2013, Impact Environmental performed a Supplemental Subsurface Investigation at the site. The investigation consisted of advancement of a soil probe SP-1 and collecting groundwater samples. The laboratory analysis of the soil sample did not detect any VOCs above the standards. Analysis of the groundwater samples detected VOC concentrations slightly above the standards. Based on the above information, Impact Environmental requested that spill#0551768 be closed. Based on the documentation provided to date, the New York State Department of Environmental Conservation (the Department) has closed the spill case number 0551768. All wells associated with this project should be closed according to the Department's Groundwater Monitoring Well Decommissioning Procedures. All wells should gaged for the presence of free product before closure. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts must be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely, Alexander Zhitomirsky "

Remarks: ""

A7 **STREET** **NY Spills** **S106698101**
SSE **1ST STREET/4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.011 mi.
60 ft. **Site 7 of 83 in cluster A**

Relative: **Higher**

Actual: **25 ft.**

SPILLS:

Name:	STREET
Address:	1ST STREET/4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0404988 / 2004-08-06
Facility ID:	0404988
Facility Type:	ER
DER Facility ID:	224759
Site ID:	276456
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-08-06
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2004-08-06
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-06
Spill Record Last Update:	2004-08-06
Spiller Name:	ERT DESK
Spiller Company:	CONED VEHICLE #23257
Spiller Address:	1ST STREET /4TH AVE
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL COMP VEHICLE 23257 WAS INVOLVED IN A ACCIDENT WHILE WATING FOR A TRAFFIC LIGHT WITH ANOTHER CAR. 1-1/2 GALLONS BETWEEN THE TWO VEHICLES LEAKED ANTI FREEZE IN STREET. CLEANUP WAS COMPLETED 100% AT 08:55HRS BY MR. G. KERN OF ENV OPS USING OIL ABSORBANTS."
Remarks:	"CLEAN UP IS COMPLETE AT 8:55AM: CON ED # 154744: "

All Materials:

Site ID:	276456
Operable Unit ID:	888375
Operable Unit:	01
Material ID:	488957
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A8 **3RD AVE YARD** **NY Spills** **S104653291**
SSE **1ST ST & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.018 mi.
93 ft. **Site 8 of 83 in cluster A**

Relative: **Higher**

Actual: **25 ft.**

SPILLS:

Name:	3RD AVE YARD
Address:	1ST ST & 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0002643 / 2001-09-25
Facility ID:	0002643
Facility Type:	ER
DER Facility ID:	131774
Site ID:	155576
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-06-02
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-06-02
CID:	490
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-02
Spill Record Last Update:	2001-10-11
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	JIMMIE FOX
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 6/2/00 Transformer removed from vault was sitting in a containment pan and leaked 4oz cable oil from cable ends. 4oz went into containment pan. There is 40gal of rain water in pan also. Will put tarp over transformer and pan to protect from any other rain water. 6/5/00 Oil sample for this incident was lost. Took new sample and returned 422ppm PCB. Drained 3-55gal drums of water and oil from transformer pan. Put contaminated pump in barrel #4 for future use. Re-tarp transformer and pan. 6/6/00 Pan double washed with bio-gen 760 and oil absorb. Waste placed into barrels and disposed by Stores as 422ppm waste."
Remarks:	"transformer that was removed from a vault and placed on a containment pad started to leak - has not been cleaned up as of yet"

All Materials:

Site ID:	155576
Operable Unit ID:	824566
Operable Unit:	01
Material ID:	551001
Material Code:	0020B

3RD AVE YARD (Continued) **S104653291**

Material Name:	cable oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A9 **MTA NYCT - 4TH AVE GARFIELD PL** **RCRA-SQG** **1026834088**
ENE **276 4TH AVE** **NYR000250654**
< 1/8 **BROOKLYN, NY 11215**
0.019 mi.
99 ft. **Site 9 of 83 in cluster A**

Relative: RCRA-SQG:
Higher

Actual: Date Form Received by Agency:		20210823
25 ft. Handler Name:	MTA NYCT - 4TH AVE GARFIELD PL	
Handler Address:		276 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000250654
Contact Name:		ISABEL POTTER
Contact Address:		BROADWAY 27TH FL
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-5777
Contact Fax:		Not reported
Contact Email:		ISABEL.POTTER@NYCT.COM
Contact Title:		SYSTEM SAFETY SPECIALIST
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BROADWAY 27TH FL
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	MTA NYCT	
Owner Type:		State
Operator Name:	MTA NYCT	
Operator Type:		State
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

MTA NYCT - 4TH AVE GARFIELD PL (Continued) **1026834088**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210823
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19200101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FL

MTA NYCT - 4TH AVE GARFIELD PL (Continued) **1026834088**

Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: ENVIRONMENTALPROTECTIONNYCT@NYCT.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA - NEW YORK CITY TRANSIT
Legal Status: State
Date Became Current: 19200101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: ENVIRONMENTALPROTECTIONNYCT@NYCT.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA NYCT
Legal Status: State
Date Became Current: 19200101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: ENVIRONMENTALPROTECTIONNYCT@NYCT.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA - NEW YORK CITY TRANSIT
Legal Status: State
Date Became Current: 19200101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: ENVIRONMENTALPROTECTIONNYCT@NYCT.COM

Historic Generators:
Receive Date: 20210608
Handler Name: MTA - NEW YORK CITY TRANSIT 4TH AVE GARFIELD PL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210823

MTA NYCT - 4TH AVE GARFIELD PL (Continued) **1026834088**

Handler Name: MTA NYCT - 4TH AVE GARFIELD PL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B10 **4TH AVE/GARFIELD ST** **NY Spills** **S103483429**
ENE **4TH AVE/GARFIELD ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.020 mi.
105 ft. **Site 1 of 24 in cluster B**

Relative: Higher
Actual: 26 ft.

SPILLS:
Name: 4TH AVE/GARFIELD ST
Address: 4TH AVE/GARFIELD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8404005 / 2020-04-29
Facility ID: 8404005
Facility Type: ER
DER Facility ID: 160506
Site ID: 192509
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1984-12-17
Investigator: VXBREVDO
Referred To: Not reported
Reported to Dept: 1995-05-04
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

4TH AVE/GARFIELD ST (Continued) **S103483429**

Date Entered In Computer:	Not reported
Spill Record Last Update:	2020-04-29
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL APPENDIX B SITE NO. 57. 08-08-06: See also 9203835. MCT 12/6/12 - Site Investigation Work Plan prepared by Langan Engineering & Environmental Services dated January 2010 discusses eight spills as part of the Appendix B site 57. The spills were all along 4th Avenue in Brooklyn, from roughly Pacific Street south to 6th Street. The spills all involve releases from feeders that run along top of the subway that runs along 4th Avenue. Two of the eight spills have open spill numbers, 8303206 and 8404005. Spill 9203835, which had affected the Pacific Street subway station, was administratively closed and referred to these two open spills. A letter with comments on the SIWP was sent on November 14th. (JOC) 6/27/14 - Letter dated June 4, 2014 from Langan for Con Edison in response to SIWP comment letter. Most of the responses were acceptable. A few points need some additional clarification. For this spill, the available information does not specifically identify the feeders involved in the release, and Langan responded that there were other feeders at the location, but said the feeders running along 4th Avenue were presumed to be the source. Letter was sent 6/24 in which clarification on that point was requested. Also requested inclusion of additional language to arrange with the Department for selection of final investigation locations based on utility markouts, for prompt notification to the Department when a field modification is needed and for evaluation of migration along utilities; requested clarification on what was included as requirement to not work inside tolerance zone for subsurface utilities; requested clarification on sample analysis; and requested clarification on who would make the determination in the field for conforming to the expected MTA/NYCT permit stipulations for working over/near the subway structure. (JOC) 8/5/14 - met with Con Edison PM 8/4 - expect to have subway information from MTA and response to comments this quarter. (JOC) 2/25/16 - responses to comments were received March 2015 along with revised SIWP; Con Edison project manager is now Mariela Gonzalez; sent response letter today to Ms. Gonzalez with comments on the responses/SIWP from Langan. (JOC) 10/26/2016 - V. Brevdo Due to Project Manager Joe O'Connell's promotion to the DMM, and per discussions between Chiefs of Spill Prevention and Response and Remediation Section B, this spill case is re-assigned to Remediation Section B. VB 06/27/2017 - V. Brevdo Con Edison Appendix B Sites Spill Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8303206, 8404005, 9203835) On June 23, 2017, Con Edison submitted for the Department s review and concurrence/approval the Con Edison s response letter to Department s February 25, 2016 comments regarding the Site Investigation Work Plan (SIWP) for Site 57 dated March 2015, as amended by a March 23, 2015 letter. The Department s February 25, 2016 comments on the SIWP were pertinent to spills historical records, locations and sources of the releases, determination of the boundaries of investigation around release locations and contaminant migration pathways, identification of dielectric fluid containing equipment, diameter of feeder lines and associated pressure pipes, locations of the proposed

4TH AVE/GARFIELD ST (Continued) **S103483429**

investigations/boring locations in relation to the NYCT subway stations (Union and Bergen Streets, Brooklyn), soil sampling intervals, rationale for installation of permanent or temporary monitoring wells, scope of chemical analysis for collected samples, and MTA s concurrence with the final sampling locations around the subway stations. The Department completed review of the Con Edison s June 23, 2017 response letter containing responses to the Department s 14 comments. The Department determined that all Con Edison s responses are acceptable, however, 5 responses suggest further revisions to the SIWP. The Department communicated with Con Edison on June 27, 2017 advising that their responses to Department s February 25, 2016 comments on SIWP are acceptable and requested submission of either the revised SIWP or a separate amendment to the SIWP containing suggested revisions. VB 08/14/2017 - V. Brevdo On August 14, 2017, Con Edison informed the Department that they intend to resubmit the revised Site Investigation Work Plan shortly. VB 08/17/2017 - V. Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8303206 & 8404005) On June 23, 2017, Con Edison submitted for the Department s review and concurrence/approval the Con Edison s response letter to Department s February 25, 2016 comments regarding the Site Investigation Work Plan (SIWP) for Site 57 dated March 2015, as amended by a March 23, 2015 letter. The Department s February 25, 2016 comments on the SIWP were pertinent to spills historical records, locations and sources of the releases, determination of the boundaries of investigation around release locations and contaminant migration pathways, identification of dielectric fluid containing equipment, diameter of feeder lines and associated pressure pipes, locations of the proposed investigations/boring locations in relation to the NYCT subway stations (Union and Bergen Streets, Brooklyn), soil sampling intervals, rationale for installation of permanent or temporary monitoring wells, scope of chemical analysis for collected samples, and MTA s concurrence with the final sampling locations around the subway stations. The Department completed review of the Con Edison s June 23, 2017 response letter containing responses to the Department s 14 comments. The Department determined that all Con Edison s responses were acceptable, however, 5 responses suggested further revisions to the SIWP. The Department communicated with Con Edison on June 27, 2017 advising that their responses to Department s February 25, 2016 comments on SIWP were acceptable and requested submission of either the revised SIWP or a separate amendment to the SIWP containing suggested revisions. Con Edison informed the Department on June 27, 2017 that they would revise SIWP and submit revised document to the Department for review and approval. On August 11, 2017, Con Edison submitted to the Department for review and approval the Final SIWP, dated August 2017, transmittal letter dated August 11, 2017. The scope of investigation activities specified in the Final SIWP include the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluids impact areas; The installation of up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, scaled site maps,

4TH AVE/GARFIELD ST (Continued) **S103483429**

tabulated analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The complete Field Sampling Plan (FSP), Quality Assurance Project Plan (QAPP), and Health and Safety Plan (HASP) are provided in Appendices B, C, and D, of the Final SIWP, respectively. Based on Project Schedule, the Site Investigation Report (SIR) will be submitted to the Department within 13 months following Department s approval of the Final SIWP. The Department completed review of the document and approved Final SIWP on August 17, 2017. VB 10/03/2018 - V. Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8303206 & 8404005) Spill Site No. 57 consists of eight separate releases that occurred on 4th Avenue between 6th Street and Pacific Street, Brooklyn. On August 11, 2017, Con Edison submitted to the Department for review and approval the Final SIWP, dated August 2017, transmittal letter dated August 11, 2017. The scope of investigation activities specified in the Final SIWP include the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluid impact areas; The installation of up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, scaled site maps, tabulated analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The complete Field Sampling Plan (FSP), Quality Assurance Project Plan (QAPP), and Health and Safety Plan (HASP) are provided in Appendices B, C, and D, of the Final SIWP, respectively. The Department completed review of the document and approved Final SIWP on August 17, 2017. On October 3, 2018, Con Edison informed the Department that based on the physical features of the subway tunnel along 4th Avenue at Site 57, Con Edison needs to modify the proposed scope of work for the upcoming investigation. The August 2017 Final Site Investigation Work Plan for the Site proposed the use of a drill rig to extend borings to the water table at 28 of the proposed locations if they were determined to lie outside the footprint of the subway tunnel. Based on Con Edison s review of the NYCTA subway tunnel drawings, the subway tunnel and ancillary structures lie beneath the entire width of the roadway, prohibiting the use of a drill rig for the site investigation. Con Edison has submitted a package to NYCTA requesting approval to perform all 56 of the proposed boring locations using hand auguring to depths of 6 and 7 feet below grade. Since the feeders being investigated for this Site are situated approximately 3 feet bgs, the proposed borings will extend several feet below the depth of the lines, while remaining at least two feet above the roof of the subway tunnel. The subway tunnel roof generally lies between 8 and 12 feet below road surface at the investigation locations. Con Edison are currently awaiting NYCTA approval to proceed with the field investigation, and are tentatively planning to start the work in late November/early December 2018. Once

4TH AVE/GARFIELD ST (Continued) **S103483429**

Con Edison receive a response from NYCTA, they will provide the Department with a firm start date of site investigation. The Department advised Con Edison on October 3, 2018, that given the scope/nature of the proposed investigation and physical settings of the site and the subway tunnel, the Department concurs with the use of hand auguring to depths of 6 and 7 feet below grade in lieu of the drilling rig. The Department s concurrence is contingent on the NYCTA s approval to perform aforementioned borings. VB 3/4/2019 - V. Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8303206 & 8404005) Spill Site No. 57 consists of eight separate releases that occurred on 4th Avenue between 6th Street and Pacific Street, Brooklyn. On August 11, 2017, Con Edison submitted to the Department for review and approval the Final SIWP, dated August 2017, transmittal letter dated August 11, 2017. The scope of investigation activities specified in the Final SIWP include the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluid impact areas; The installation of up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, scaled site maps, tabulated analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The complete Field Sampling Plan (FSP), Quality Assurance Project Plan (QAPP), and Health and Safety Plan (HASP) are provided in Appendices B, C, and D, of the Final SIWP, respectively. The Department completed review of the document and approved Final SIWP on August 17, 2017. Con Edison submitted the permit application package to the NYCTA on September 19, 2018 requesting approval to install the proposed borings at the locations identified in the Work Plan. Following this submission, MTA notified Con Edison that there were additional subway detailed drawings that needed to be obtained for the length of the subway route along which the borings will be excavated. As per Department s October 3, 2018 approval, the investigation will be performed using hand auguring in lieu of drilling at the site due to shallow depth (approximately 10 feet) of the subway tunnel and associated MTA subsurface structures at the site. Delays occurred over the next few months as MTA was attempting to locate the necessary drawings. The MTA eventually informed Con Edison that the particular drawings were not in their archives. Con Edison made subsequent submittals to MTA on December 11 and December 28, 2018 and January 17, 2019. Following the December 2018 and January 2019 submittals by Con Edison, MTA provided necessary drawings to Con Edison which enabled Con Edison to finalize and submit the application package to MTA. Con Edison s consultant, CDM Smith was notified on January 23, 2019 that NYCTA had approved the Con Edison s application package. On February 4, 2019, Con Edison sent the final signed/sealed 27 sheet application package to MTA as a follow-up. Con Edison informed the Department that no additional approval from MTA is warranted on February 4, 2019 follow-up package and MTA s January 23, 2019 application package approval remains

4TH AVE/GARFIELD ST (Continued) **S103483429**

valid. The approved package includes all 56 proposed boring locations. Due to the relatively shallow depths of the subway sub?structures, the maximum depths of the borings will be 7 feet bgs. Following receipt of the final February 4, 2019 application package, NYCTA notified Con Edison that MTA will provide the final authorization for the field work when a New Service Agreement insurance package is submitted by Con Edison and approved by the MTA. Con Edison is currently in the process of getting the insurance package prepared for submittal to NYCTA. Con Edison anticipates that a final approval for the field work will be received from NYCTA in early?mid April 2019. Con Edison currently anticipates start date for fieldwork on this project in early-mid May 2019. VB June 3, 2019 - Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8303206 & 8404005) Spill Site No. 57 consists of eight separate releases that occurred on 4th Avenue between 6th Street and Pacific Street, Brooklyn. On August 11, 2017, Con Edison submitted the Final SIWP. The scope of investigation activities specified in the Final SIWP included the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples, and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluid impact areas; The installation of up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, site maps, analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The Department completed review of the document and approved Final SIWP on August 17, 2017. Con Edison submitted the permit application package to the NYCTA on September 19, 2018 requesting approval to install the proposed borings at the locations identified in the Work Plan. As per Department s October 3, 2018 approval, the investigation will be performed using hand auguring in lieu of drilling at the site due to shallow depth (approximately 10 feet) of the subway tunnel and associated MTA subsurface structures at the site. Con Edison s consultant, CDM Smith was notified on January 23, 2019 that NYCTA had approved the Con Edison s application package. Due to the relatively shallow depths of the subway sub?structures, the maximum depths of the borings will be 7 feet bgs. On June 3, 2019, Con Edison notified the Department that the field work associated with the implementation of an approved Site Investigation Work Plan is scheduled to commence on June 6, 2019. The duration of the investigation is estimated to be about 8 weeks. VB July 17, 2019 - V. Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8303206 & 8404005) Spill Site No. 57 consists of eight separate releases that occurred on 4th Avenue between 6th Street and Pacific Street, Brooklyn. On August 11, 2017, Con Edison submitted the Final SIWP. The scope of investigation activities specified in the Final SIWP included the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples, and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluid impact areas; The installation of

4TH AVE/GARFIELD ST (Continued) **S103483429**

up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, site maps, analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The Department completed review of the document and approved Final SIWP on August 17, 2017. Con Edison submitted the permit application package to the NYCTA on September 19, 2018 requesting approval to install the proposed borings at the locations identified in the Work Plan. As per Department s October 3, 2018 approval, the investigation will be performed using hand auguring in lieu of drilling at the site due to shallow depth (approximately 10 feet) of the subway tunnel and associated MTA subsurface structures at the site. Con Edison s consultant, CDM Smith was notified on January 23, 2019 that NYCTA had approved the Con Edison s application package. Due to the relatively shallow depths of the subway sub?structures, the maximum depths of the borings will be 7 feet bgs. On June 3, 2019, Con Edison notified the Department that the field work associated with the implementation of an approved Site Investigation Work Plan is scheduled to commence on June 6, 2019. The duration of the investigation is estimated to be about 8 weeks. On July 16, 2019, Con Edison submitted a written request to amend the scope of investigative work which was defined in approved August 2017 work plan, and revised work plan approved on October 3, 2018. Con Edison s July 16, 2019 request to amend the scope of investigative work is based on the MTA Stop Work Order issued due to the subway tunnel roof breach experienced on June 12, 2019 between Pacific Street and Dean Street along 4th Avenue. During investigative field activities on June 12, 2019, Con Edison and MTA discovered that the subway tunnel is shallow through the central portion of the block between Pacific and Dean Streets. This was discovered when Con Edison attempted to install boring 57-3/5-3 and breached the roof of the tunnel at 18 inches below ground surface. Based on MTA drawings, Con Edison expected the roof of the tunnel to lie at least seven (7) feet bgs at this boring location. MTA Subway R Line service was halted on the NW bound line for one hour in the afternoon of June 12, 2019 while repair crew performed patch and repairs to the subway tunnel roof. A further geophysical survey of the area was able to identify the extent of the shallow tunnel. Con Edison feeders (which lie approximately 3 feet bgs) are immediately west of this shallow portion of the tunnel, within the south-bound lanes. As such, any fluid released from the feeder lines would not have been able to migrate east of the leak location due to the presence of the tunnel. Based on this information, Con Edison requested elimination of the borings located on the east side of the median (north bound lanes), including: 57-3/5-1; 57-3/5-3 (attempted/breached the tunnel); and 57-3/5-13. Based on the MTA drawings and the geophysical survey, the borings to the west and south of the median along 4th Avenue, between Pacific and Dean Streets, are expected to be completed (57-3/5-2, -4, -5, -11, and -14). Con Edison will progress with the investigative activities from north to south along 4th Avenue. At each block, a new geophysical survey will be performed. Based on the finding for each section, it may be necessary to eliminate additional locations as the

4TH AVE/GARFIELD ST (Continued) **S103483429**

investigation progresses. Con Edison will confer with MTA and NYSDEC as necessary after each block is surveyed should there be a need to eliminate borings based on the physical features present. In addition, since the accuracy of the MTA drawings is in question, as a precaution to avoid breaching the tunnel, should concrete be identified below the road surface that is similar to what was observed at the location of the breach, Con Edison will not excavate more than 6 inches into this material. If such situation is encountered, Con Edison will notify MTA and NYSDEC and the boring will not be completed at that location. In addition, for the duration of the field activities, a representative from MTA will be onsite to confirm that Con Edison has measured each location per the approved MTA plans and completed the geophysical survey prior to performing intrusive work over the tunnel. NYSDEC has reviewed Con Edison s July 16, 2019 letter request to amend the scope of investigative work and approved amendment on July 17, 2019. Con Edison is scheduled to re-mobilize on July 22, 2019 to continue site investigation field activities. VB September 17, 2019 - V. Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8404005 & 8303206) Spill Site No. 57 consists of eight separate releases that occurred on 4th Avenue between 6th Street and Pacific Street, Brooklyn. On August 11, 2017, Con Edison submitted the Final SIWP. The scope of investigation activities specified in the Final SIWP included the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples, and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluid impact areas; The installation of up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, site maps, analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The Department completed review of the document and approved Final SIWP on August 17, 2017. Con Edison submitted the permit application package to the NYCTA on September 19, 2018 requesting approval to install the proposed borings at the locations identified in the Work Plan. As per Department s October 3, 2018 approval, the investigation will be performed using hand auguring in lieu of drilling at the site due to shallow depth (approximately 10 feet) of the subway tunnel and associated MTA subsurface structures at the site. Con Edison s consultant, CDM Smith was notified on January 23, 2019 that NYCTA had approved the Con Edison s application package. Due to the relatively shallow depths of the subway substructures, the maximum depths of the borings will be 7 feet bgs. Site Investigation field work commenced on June 6, 2019. As of September 16, 2019, field implementation of the remedial investigation at the site is approximately 60% complete based on Con Edison s estimate. Based on the revised drilling approach to abandon drilling locations that are observed to show the presence of a continuous 6-inch concrete layer and completing boring locations only after MTA s concurrence has been secured, 34 out of 56 boring/sampling locations have been evaluated to date. Out of 34 boring locations evaluated, 5 locations were eliminated with the MTA

4TH AVE/GARFIELD ST (Continued) **S103483429**

s and NYSDEC s concurrence due to various risks to subway system, 18 locations have been completed to shallower then design depth but ultimately abandoned due to the presence of a continuous monolithic concrete layer more than 6 inches deep, and 11 locations were successfully completed to target depth with soil samples collected for laboratory analyses. Con Edison scheduled completion of the field work by October 31, 2019, and submission of the Investigation Reports for two (2) spill cases associated with project on December 3 and December 16, 2019, respectively. VB October 22, 2019 - V. Brevdo Con Edison Appendix B Site No. 57, 4th Ave/ Garfield Pl./ 6th Street, Brooklyn (Spill Nos. 8404005 & 8303206) Spill Site No. 57 consists of eight separate releases that occurred on 4th Avenue between 6th Street and Pacific Street, Brooklyn. On August 11, 2017, Con Edison submitted the Final SIWP. The scope of investigation activities specified in the Final SIWP included the following tasks: Completion of approximately 56 primary borings and collection of 112 soil samples, and completion of contingent borings and soil sampling, as necessary, to delineate the horizontal and vertical extent of dielectric fluid impact areas; The installation of up to 8 monitoring wells, after assessing MTA underground structures and field confirmation of utilities, to assess potential impacts to ground water and potential migration pathways to surface water receptors; and, Preparation of a Site Investigation Report, that will include a site history summary, description of site conditions and the site investigation activities, site maps, analytical data, soil boring and well construction logs, laboratory analytical reports, and discussions of the findings. Groundwater data including monitoring well locations, ground water flow maps, and ground water analytical data will also be included. The Department completed review of the document and approved Final SIWP on August 17, 2017. Con Edison submitted the permit application package to the NYCTA on September 19, 2018 requesting approval to install the proposed borings at the locations identified in the Work Plan. As per Department s October 3, 2018 approval, the investigation will be performed using hand auguring in lieu of drilling at the site due to shallow depth (approximately 10 feet) of the subway tunnel and associated MTA subsurface structures at the site. Con Edison s consultant, CDM Smith was notified on January 23, 2019 that NYCTA had approved the Con Edison s application package. Due to the relatively shallow depths of the subway sub?structures, the maximum depths of the borings will be 7 feet bgs. Site Investigation field work commenced on June 6, 2019. On October 22, 2019, Con Edison informed the Department that the field work associated with implementation of the remedial investigation at Site 57 was completed on October 18, 2019. Con Edison scheduled submission of the Investigation Reports for two (2) spill cases associated with the project on December 3 and December 16, 2019, respectively. VB April 30, 2020 Con Edison Appendix B Site No. 57-2, 4th Ave. between Carroll & Garfield Streets Brooklyn (Spill No. 8303206) Spill was reported on December 12, 1984 and consisted of a discharge of approximately 1,000 gallons of dielectric fluid from Feeder 31231 on 4th Avenue between Carroll and Garfield Streets. The depth of feeder is approximately 1.0 foot below ground surface in this area. According to the spill records, there was no indication of product identified at the leak location. An investigation was performed in October of 2019 and included the attempted excavation of four soil borings. No samples were collected to prevent damage to MTA infrastructure, due to the presence of greater than six inches of

4TH AVE/GARFIELD ST (Continued) **S103483429**

concrete at all boring locations. The presence of concrete at a consistent shallow depth at the four attempted boring locations confirms the presence of shallow MTA structures (i.e., the tunnel and/or pipe galleries) in the investigation area. Con Edison submitted Site Investigation Report, including spill closure request, on April 15, 2020. Based on the shallow depth of the subway tunnel and associated infrastructure at this spill location and the absence of any physical evidence of residual dielectric fluid at the time of the release, Con Edison recommended the closure of Spill No. 8404005. Based on review of the April 15, 2020 Site Investigation Report, information in the DEC project document repository, and continued use of the site as roadway, DEC concluded that the closure of spill case is appropriate and closed spill on April 30, 2020. VB "

Remarks: "Reported by Con Ed as required under Consent Order."

All Materials:

Site ID:	192509
Operable Unit ID:	894835
Operable Unit:	01
Material ID:	482459
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A11 **272 4TH AVENUE** **NY BROWNFIELDS S125465242**
NE **272 4TH AVENUE** **NY Spills N/A**
< 1/8 **BROOKLYN, NY 11215**
0.023 mi.
122 ft. **Site 10 of 83 in cluster A**

Relative: Higher
Actual: 25 ft.

BROWNFIELDS:

Name:	272 4TH AVENUE
Address:	272 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	590723
Acres:	0.200
HW Code:	C224298
SWIS:	2401
Town:	New York City
Record Added Date:	06/18/2019
Record Updated Date:	08/15/2019
Update By:	LSZINOMA
Site Description:	"Location The site is located at 272 4th Avenue, and includes the addresses 264 4th Avenue through 270 4th Avenue, and 544 through 554 Carroll Street. The Site is located in the Gowanus section of Brooklyn, New York. The site was abutted to the northeast by Carroll Street, followed by a cafe; to the northwest by an auto repair shop, followed by a community garden; to the southeast by 4th Avenue, followed by apartment buildings and a furniture store; and to the southwest by a bar/cafe, followed by a New York City Transit (NYCT) system substation. Site Features The site consists of one tax lot on

272 4TH AVENUE (Continued) **S125465242**

an approximately 8,900-square foot parcel. The site contains an approximately 17,800-gross-sf, two-story commercial building with a partial cellar, constructed around 1931. The building is operated as an automobile collision repair facility, which occupies both the first and second stories of the building. Current Zoning and Land Use The current zoning designation of the site is M1-2 (manufacturing district). The surrounding area is predominately mixed-use residential and commercial, with some industrial uses; however, an area-wide rezoning is currently underway. Past Use of the Site The April 2019 Phase I ESA indicated that site had numerous historical automotive uses, with some commercial and residential uses. The site was mostly vacant with a single dwelling and a stable with attached sheds in 1888. An apparent marshland was depicted, which appeared to be filled in on subsequent maps. The Property was developed into part of a bottle facility, with the stable remaining in 1906. In 1926, the Property was developed into a two-story garage with two gasoline tanks. In 1951, the first floor of the Property building converted into an auto repair shop with a filling station and gasoline tanks, while the second floor remained a garage. In 1965, the filling station and associated gasoline tanks were no longer depicted, and the Property became an auto sales and service shop with a garage. In 1982, the Property remained an auto service shop, but was no longer shown as an auto sales shop. Site Geology and Hydrology Based on the U.S. Geological Survey Brooklyn, New York 2013 Quadrangle map, the site is approximately 25 feet above mean sea level. Groundwater was encountered at the site between approximately 11 and 16 feet below the building slab, an estimated 12.5 feet below sidewalk grade along Fourth Avenue. Groundwater is expected to flow west-southwest across the site towards the Gowanus Canal, which is approximately 0.25 miles west of the site. Eight Soil borings, which were advanced to 20 feet below sidewalk grade across the site, encountered historic fill material underlain by native brown silt."

Env Problem:

"Based on the investigations conducted to date, the primary contaminants of concern for the Site are petroleum-related Volatile Organic Compounds (VOCs), chlorinated VOCs, Polycyclic Aromatic Hydrocarbons (PAHs), and metals. Soil Soil sample analytical results obtained during the Phase II investigation were compared to NYSDEC Part 375 Restricted Residential Soil Cleanup objectives (RRSCOs). Twenty-seven VOCs were detected in the soil samples with total concentrations ranging from 0.0003 to 26.8 mg/kg. No VOCs were detected above the RRSCOs in the soil samples. The VOCs 1,2,4-trimethylbenzene, chlorobenzene, and total xylenes were detected at concentrations above their respective Unrestricted Use Soil Cleanup Objectives (UUSCOs) in one or more of the soil samples. Chlorobenzene was detected at 1.9 mg/kg, above the Protection of Groundwater standard. A total of nine PAHs were detected above the UUSCOs and/or RRSCOs in one or more of seven of the soil samples collected. The PAHs benzo(a)anthracene [maximum (max.) 9.6 mg/kg] compared to RRSCO of 1 mg/kg. Benzo(a)pyrene (max. 7.5 mg/kg)compared to RRSCO 1mg/kg. Benzo(b)fluoranthene (max. 10 mg/kg)compared to RRSCO of 1 mg/kg. Chrysene (max. 9.3mg/kg) compared to RRSCO of 3.9 mg/kg. Dibenzo(a,h)anthracene (max. 1.2 mg/kg) compared to RRSCO of 0.33 mg/kg. Indeno(1,2,3-cd)pyrene (max. 5.2 mg/kg) compared to RRSCO of 0.5 mg/kg. A total of six metals were detected above the UUSCOs and/or RRSCOs in one of more of 10 of the soil samples collected. Arsenic (max. 29 mg/kg)compared to RRSCO of 16 mg/kg, lead (max. 1,800 mg/kg) RRSCO of 400 mg/kg and mercury (max. 24.1 mg/kg) RRSCO

272 4TH AVENUE (Continued) **S125465242**

	of 0.81 mg/kg were detected above their respective RRSCOs in one or more of the soil samples. No PCBs were detected in the three soil samples submitted for laboratory analyses. Groundwater Groundwater samples collected during previous investigations were compared to the NYSDEC Ambient Water Quality Standards (AWQS). Petroleum-related VOCs were detected at concentrations above the AWQS in two of the groundwater samples, including: 1,2-dichlorobenzene [3.4 micrograms per liter (?g/L)] AWQS of 3 ug/L, p- & m xylenes (6.6 ?g/L) AWQS of 5 ug/L, and o- xylenes (5.2 ?g/L) AWQS of 5 ug/L, 1,2,4,5-trimethylbenzene (9 ?g/L) AWQS of 5 ug/L, chlorobenzene (7.1 ?g/L) AWQS of 5 ug/L, and methylene chloride (14 ?g/L) AWQS of 5 ug/L. Seven PAHs were detected at concentrations that exceeded the AWQS in one or more of the groundwater samples analyzed, including: benzo(a)anthracene (max. 2.6 ?g/L) AWQS of 0.002 ug/L, benzo(a)pyrene (max. 2.2 ?g/L) AWQS of non detect (ND), benzo(b)fluoranthene (max. 3.0 ?g/L) AWQS of 0.002 ug/L, benzo(k)fluoranthene (max. 1.1 ?g/L) AWQS of 0.002 ug/L, chrysene (max. 2.3 ?g/L) AWQS of 0.002 ug/L, indeno(1,2,3-cd)pyrene (max. 1.1 ?g/L) AWQS of 0.002 ug/L, and phenol (max. 3.8 ?g/L) AWQS of 1 ug/L. The highest concentrations were detected in groundwater in the southern portion of the Site. Soil Vapor - Soil vapor samples collected were compared to New York State Department of Health Guidance for Evaluating Soil Vapor Intrusion in the State of New York. Tetrachloroethene (PCE) and Trichloroethene (TCE) at the northwest corner of the site were detected at values which required mitigation, 7120 ug/m3 and 372 ug/m3 respectively. PCE was also detected inside the office building on the east side of the site at 1890 ug/m3 which is also above the mitigation threshold."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	P03
Owner Name:	Jesse Wark
Owner Company:	272 4th Avenue LLC
Owner Address:	51 East 12th Street, 7th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library: Park Slope Branch
Owner Address:	431 6th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215

272 4TH AVENUE (Continued) **S125465242**

Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mr. Jesse Wark
Owner Company:	272 4th Avenue LLC
Owner Address:	51 East 12th Street, 7th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board District 6
Owner Address:	250 Baltic Street, Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mr. Jesse Wark
Owner Company:	274 4th and 538 Carroll LLC
Owner Address:	51 East 12th Street, 7th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	COMMERCIAL/ INDUSTRIAL
Address:	272 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2005727 / Not Reported
Facility ID:	2005727
Facility Type:	ER
DER Facility ID:	559685
Site ID:	611527
DEC Region:	2
Spill Cause:	Other
Spill Class:	D4
SWIS:	2401
Spill Date:	2020-09-23
Investigator:	SXWU
Referred To:	Not reported
Reported to Dept:	2020-09-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other

272 4TH AVENUE (Continued) **S125465242**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2020-09-23
Spill Record Last Update:	2020-09-29
Spiller Name:	PATRICK DIGGINS
Spiller Company:	UNK
Spiller Address:	272 FOREST AVENUE
Spiller Company:	999
Contact Name:	PATRICK DIGGINS
DEC Memo:	"hx spill- petroleum to soil per lab results. brownfeild clean up info c224298 PM Stephen Woo"
Remarks:	"hx spill- petroleum to soil per lab results. brownfeild clean up info c224298 PM Stephen Woo"

All Materials:

Site ID:	611527
Operable Unit ID:	1358672
Operable Unit:	01
Material ID:	2370101
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A12 **CONSTRUCTION SITE** **NY Spills** **S110242972**
East **267 FOURTH AVENUE IN BROOKLYN** **N/A**
< 1/8 **BROOKLYN, NY**
0.023 mi.
123 ft. **Site 11 of 83 in cluster A**

Relative:
Higher

Actual:
27 ft.

SPILLS:

Name:	CONSTRUCTION SITE
Address:	267 FOURTH AVENUE IN BROOKLYN
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0912838 / 2010-03-11
Facility ID:	0912838
Facility Type:	ER
DER Facility ID:	374636
Site ID:	425747
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-03-10
Investigator:	rjfeng
Referred To:	Not reported
Reported to Dept:	2010-03-10
CID:	Not reported
Water Affected:	Not reported

CONSTRUCTION SITE (Continued) **S110242972**

Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-10
Spill Record Last Update:	2010-03-11
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	267 FOURTH AVENUE IN BROOKLYN
Spiller Company:	999
Contact Name:	CYNTHIA SIMONOFF
DEC Memo:	"refer to the old spill at the same location, 89-01904"
Remarks:	"We received the following email complaint(I will have her contact her building code enforcement officer for the foundation issues): Hello, There is an open construction site at 267 Fourth Avenue in Brooklyn, NY. The site is full of water and now has begun to stink with an oil and gasoline smell. My apartment is next door to the site and I believe this is a real health concern as well as a water issue for the foundation of my building. Could you please check this problem out and contact the owner to clean it up. Thank you. Cynthia Simonoff 270 Fifth Street Brooklyn, NY 11215 718-369-2102"

All Materials:

Site ID:	425747
Operable Unit ID:	1181459
Operable Unit:	01
Material ID:	2175552
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A13 **275 FOURTH AVENUE DEV** **RCRA-LQG** **1000446339**
ESE **275 4TH AVE** **NYD986914133**
< 1/8 **BROOKLYN, NY 11215**
0.026 mi.
138 ft. **Site 12 of 83 in cluster A**

Relative: **Higher**

Actual: **27 ft.**

RCRA-LQG:

Date Form Received by Agency:		20160524
Handler Name:	275 FOURTH AVENUE DEV	
Handler Address:		275 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYD986914133
Contact Name:		JOSH ZUCKER
Contact Address:		3RD AVE
Contact City,State,Zip:		NEW YORK, NY 10022
Contact Telephone:		917-753-4330
Contact Fax:		Not reported

275 FOURTH AVENUE DEV (Continued) **1000446339**

Contact Email:	JOSH@ADAMAMERICARE.COM
Contact Title:	PROJECT MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	3RD AVE
Mailing City,State,Zip:	NEW YORK, NY 10022
Owner Name:	275 4TH AVENUE INVESTORS LLC
Owner Type:	Private
Operator Name:	275 4TH AVENUE INVESTORS LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

275 FOURTH AVENUE DEV (Continued) **1000446339**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D008
Waste Description: LEAD

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SPARTAN PETROLEUM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: 275 4TH AVENUE INVESTORS LLC	
Legal Status:	Private
Date Became Current:	20130712
Date Ended Current:	Not reported
Owner/Operator Address:	850 3RD AVE
Owner/Operator City,State,Zip:	NEW YORK, NY 10022
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

275 FOURTH AVENUE DEV (Continued) **1000446339**

Owner/Operator Indicator: Owner
Owner/Operator Name: SPARTAN PETROLEUM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 275 4TH AVENUE INVESTORS LLC
Legal Status: Private
Date Became Current: 20130712
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SPARTAN PETROLEUM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 275 4TH AVENUE INVESTORS LLC
Legal Status: Private
Date Became Current: 20130712
Date Ended Current: Not reported
Owner/Operator Address: 850 THIRD AVE SUITE 13D
Owner/Operator City,State,Zip: NEW YORK, NY 10022
Owner/Operator Telephone: 646-422-7224
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 275 4TH AVENUE INVESTORS LLC
Legal Status: Private
Date Became Current: 20130712
Date Ended Current: Not reported
Owner/Operator Address: 850 3RD AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10022
Owner/Operator Telephone: 646-422-7224
Owner/Operator Telephone Ext: Not reported

275 FOURTH AVENUE DEV (Continued) **1000446339**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160524
Handler Name: 275 FOURTH AVENUE DEV
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950419
Handler Name: SPARTAN PETROLEUM
Federal Waste Generator Description: Not reported
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SPARTAN PETROLEUM
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SPARTAN PETROLEUM
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900927

275 FOURTH AVENUE DEV (Continued) **1000446339**

Handler Name: SPARTAN PETROLEUM
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150108
Handler Name: 275 FOURTH AVENUE DEVELOPMENT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53111
NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

NAICS Code: 531110
NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A14 **NORTH PETROLEUM CORP** **NY UST U003074454**
ESE **275 FOURTH AVE** **NY AST N/A**
< 1/8 **BROOKLYN, NY 11215**
0.026 mi.
138 ft. **Site 13 of 83 in cluster A**

Relative:
Higher

Actual:
27 ft.

UST:
Name: NORTH PETROLEUM CORP
Address: 275 FOURTH AVE
City,State,Zip: BROOKLYN, NY 11215
Id/Status: 2-241849 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585857.91453
UTM Y: 4503195.07611

NORTH PETROLEUM CORP (Continued) **U003074454**

Site Type: Unknown

Affiliation Records:

Site Id: 9234
Affiliation Type: Mail Contact
Company Name: ODESSA OIL CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 1158 BROADWAY
Address2: Not reported
City: HEWLETET
State: NY
Zip Code: 11557
Country Code: 001
Phone: (516) 295-3400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9234
Affiliation Type: Facility Owner
Company Name: ODESSA OIL CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 1158 BROADWAY
Address2: Not reported
City: HEWLETET
State: NY
Zip Code: 11557
Country Code: 001
Phone: (516) 295-3400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9234
Affiliation Type: Facility Operator
Company Name: NORTH PETROLEUM CORP
Contact Type: Not reported
Contact Name: NORTH PETROLEUM CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 788-0274
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9234
Affiliation Type: Emergency Contact
Company Name: ODESSA OIL CORP
Contact Type: Not reported

NORTH PETROLEUM CORP (Continued) **U003074454**

Contact Name:	MR LOUIS RENZO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 788-0274
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	40445
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	40446
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

NORTH PETROLEUM CORP (Continued) **U003074454**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 40447
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 11/01/1967
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 40448
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91

NORTH PETROLEUM CORP (Continued) **U003074454**

Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	005
Tank ID:	40449
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

NORTH PETROLEUM CORP (Continued) **U003074454**

Tank Number:	006
Tank ID:	40450
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	007
Tank ID:	40451
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

NORTH PETROLEUM CORP (Continued) **U003074454**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 40452
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 11/01/1967
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 009
Tank ID: 40453
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 11/01/1967
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

NORTH PETROLEUM CORP (Continued) **U003074454**

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	010
Tank ID:	40454
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	011
Tank ID:	40455
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1967
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

NORTH PETROLEUM CORP (Continued) **U003074454**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 40456
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 11/01/1967
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 40457
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 01/01/1968
Date Tank Closed: Not reported

NORTH PETROLEUM CORP (Continued) **U003074454**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Number: 014
Tank ID: 40458
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 11/01/1967
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

AST:
Name: NORTH PETROLEUM CORP
Address: 275 FOURTH AVE
City,State,Zip: BROOKLYN, NY 11215

NORTH PETROLEUM CORP (Continued) **U003074454**

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-241849
Program Type:	PBS
UTM X:	585857.91453
UTM Y:	4503195.07611
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	9234
Affiliation Type:	Mail Contact
Company Name:	ODESSA OIL CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1158 BROADWAY
Address2:	Not reported
City:	HEWLETET
State:	NY
Zip Code:	11557
Country Code:	001
Phone:	(516) 295-3400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9234
Affiliation Type:	Facility Owner
Company Name:	ODESSA OIL CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1158 BROADWAY
Address2:	Not reported
City:	HEWLETET
State:	NY
Zip Code:	11557
Country Code:	001
Phone:	(516) 295-3400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9234
Affiliation Type:	Facility Operator
Company Name:	NORTH PETROLEUM CORP
Contact Type:	Not reported
Contact Name:	NORTH PETROLEUM CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 788-0274
EMail:	Not reported

NORTH PETROLEUM CORP (Continued) **U003074454**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	9234
Affiliation Type:	Emergency Contact
Company Name:	ODESSA OIL CORP
Contact Type:	Not reported
Contact Name:	MR LOUIS RENZO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 788-0274
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	015
Tank Id:	48045
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

	I00 - Overfill - None
	H00 - Tank Leak Detection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	G00 - Tank Secondary Containment - None
	J00 - Dispenser - None
	D00 - Pipe Type - No Piping
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	gasoline
Tank Number:	016

NORTH PETROLEUM CORP (Continued) **U003074454**

Tank Id: 48046
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/01/1994
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: gasoline

A15 **275 4TH AVE INVESTORS LLC** **NY MANIFEST** **S119071837**
ESE **275 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.026 mi.
138 ft. **Site 14 of 83 in cluster A**

Relative:
Higher

Actual:
27 ft.

NY MANIFEST:
Name: 275 4TH AVE INVESTORS LLC
Address: 275 4TH AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYD986914133
Facility Status: Not reported
Location Address 1: 275 4TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986914133
Mailing Name: 275 4TH AVE INVESTORS LLC
Mailing Contact: 275 4TH AVE INVESTORS LLC/SPARTAN PETROLEUM
Mailing Address 1: 850 3RD AVE STE 130
Mailing Address 2: Not reported

275 4TH AVE INVESTORS LLC (Continued) **S119071837**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10022
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5162953400

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000029957
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/2015
Trans1 Recv Date:	04/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986914133
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	013799063JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	45700
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D006
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A16 **275 4TH AVENUE** **NY VCP** **S118943374**
ESE **275 4TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.026 mi.
138 ft. **Site 15 of 83 in cluster A**

Relative: VCP NYC:
Higher

Project ID:	14TMP0054K,14EHAZ054K,14CVCP240K
Name:	275 4TH AVENUE
Address:	275 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0096400013009599E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.6754
Longitude:	-73.984502
Postcode:	6
Community Board:	39
Council District:	133
Census Tract:	3424427
BIN:	3009647505
NTA:	Park Slope-Gowanus

Actual:
27 ft.

A17 **DIANA FUEL CORP** **EDR Hist Auto** **1021708330**
ESE **275 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.026 mi.
138 ft. **Site 16 of 83 in cluster A**

Relative: EDR Hist Auto
Higher

Actual:
27 ft.

Year:	Name:	Type:
1974	DIANA FUEL CORP	Gasoline Service Stations
1975	DIANA FUEL CORP	Gasoline Service Stations
1976	DIANA FUEL CORP	Gasoline Service Stations
1977	DIANA FUEL CORP	Gasoline Service Stations
1977	M & P SERVICE STATION	Gasoline Service Stations
1978	DIANA FUEL CORP	Gasoline Service Stations
1978	M & P SERVICE STATION	Gasoline Service Stations
1979	M & P SERVICE STATION	Gasoline Service Stations
1979	DIANA FUEL CORP	Gasoline Service Stations
1982	ZOYA DIAGNOSTIC INC	Gasoline Service Stations
1983	ZOYA DIAGNOSTIC INC	Gasoline Service Stations
1985	ZOYA DIAGNOSTIC INC	Gasoline Service Stations
1986	ZOYA DIAGNOSTIC INC	Gasoline Service Stations
1987	ZOYA DIAGNOSTIC INC	Gasoline Service Stations

A18 **275 4TH AVENUE INVESTORS LLC** **PA MANIFEST** **S118888463**
ESE **275 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.026 mi.
138 ft. **Site 17 of 83 in cluster A**

Relative: Manifest Details:
Higher

Year:	2015
Manifest Number:	013799061JJK
Manifest Type:	TSD Copy

Actual:
27 ft.

275 4TH AVENUE INVESTORS LLC (Continued) **S118888463**

Generator EPA Id:	NYD986914133
Generator Date:	04/15/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	48200
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013799064JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986914133
Generator Date:	04/16/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	48040
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013799058JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986914133
Generator Date:	04/14/2015
Mailing Address:	Not reported

275 4TH AVENUE INVESTORS LLC (Continued) **S118888463**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	49280
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013799062JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986914133
Generator Date:	04/15/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	53260
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013799063JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986914133
Generator Date:	04/16/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

275 4TH AVENUE INVESTORS LLC (Continued) **S118888463**

TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	45700
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

A19 **LOT 1,TAXBLOCK 964** **NY E DESIGNATION** **S109318007**
ESE **275 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.026 mi.
138 ft. **Site 18 of 83 in cluster A**

Relative: **Higher**
Actual: **27 ft.**

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 964
Address:	275 4 AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	964
Borough Code:	Not reported
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

A20 **269-271 4TH AVENUE** **NY VCP** **S125316959**
ESE **271 4TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.026 mi.
139 ft. **Site 19 of 83 in cluster A**

Relative: **Higher**
Actual: **27 ft.**

VCP NYC:

Project ID:	14TMP0455K,14EHAZ455K,14CVCP250K
Name:	269-271 4TH AVENUE
Address:	271 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.00964000630096E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Closure

269-271 4TH AVENUE (Continued) **S125316959**

Latitude:	40.67549
Longitude:	-73.984422
Postcode:	6
Community Board:	39
Council District:	133
Census Tract:	3426694
BIN:	3009640007
NTA:	Park Slope-Gowanus

A21 **LOT 6,TAXBLOCK 964** **NY E DESIGNATION** **S108075323**
ESE **271 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.026 mi.
139 ft. **Site 20 of 83 in cluster A**

Relative: **Higher**
Actual: **27 ft.**

E DESIGNATION:

Name:	LOT 6,TAXBLOCK 964
Address:	271 4 AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	6
Tax Block:	964
Borough Code:	Not reported
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

A22 **FORMER GAS STATION** **NY Spills** **S106868437**
ESE **269-271 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.026 mi.
139 ft. **Site 21 of 83 in cluster A**

Relative: **Higher**
Actual: **27 ft.**

SPILLS:

Name:	FORMER GAS STATION
Address:	269-271 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0501021 / 2006-02-20
Facility ID:	0501021
Facility Type:	ER
DER Facility ID:	290783
Site ID:	344148
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-04-25
Investigator:	ADZHITOM
Referred To:	INVESTIGATION IS PENDING
Reported to Dept:	2005-04-25
CID:	444

FORMER GAS STATION (Continued) **S106868437**

Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-25
Spill Record Last Update:	2006-03-20
Spiller Name:	MR. MORRIS PRATT
Spiller Company:	COMMERCIAL PROP-ERTY
Spiller Address:	269-271 4TH AVE
Spiller Company:	001
Contact Name:	MR. MORRIS PRATT
DEC Memo:	"HydroTech did the investigation for a potential purchaser, Mr Pratt According to Property Shark Records, Owner of both lots #269 and #271 4th Ave is: Dimitrios Batistatos, 1137 63rd St, Brooklyn 11219 - Contaminated Soil Letter sent to him.- SS 5/10/05 - Mr. John Spenako called. He represent the owner who claims that the contamination is coming from the next door neighbor at 275 4th Ave., a former gas station, PBS #2-241849, and is now a McDonald. I asked Mr. Spenako to send in the site investogation report by HydroTech. The Site assessment was done as a due diligent for a pending property sale. - KST 5/12/05 - Received a letter from Mr. John Mike Spanakos who is representing the property owner. Case assigned to ALex Zhitomirsky. - KST 6/1/05 Spoke with John Spanakos and requested to send to the Department a legible copy of Hydro Tech report. A copy in the file is not legible. AZ 6/23/2005 Department received a copy of Hydro Tech Report regarding subsurface investigation at 269-271 4 Ave Brooklyn. I contacted John Spanacos (Spanacos and Spanacos 718-833-6900) and informed him that thE submitted copy is not fully legible. Also, the report does not contain a site plan where borings, wells and direction of gw flow are shown. They should resubmit this report in legible form and include all missing info. AZ 7/12/2005 Reviewed the Subsurface Investigation dated March 18, 2005, and submitted by Hydro Tech Environmental, Inc. on July 5, 2005. A letter was issued to the owner (Mr.Batistatos). The letter required the following: 1. Delineation of soil and groundwater contamination - a subsurface investigation to adequately characterize site hydrogeology and to better delineate the full extent of petroleum contamination to soil and groundwater both on-site and off-site must be performed. The investigation at a minimum must include installation of four wells including wells near SP-2 and SP-3. In addition, one well should be installed on the 4th Avenue sidewalk at the south end of the property and one well should be installed north of SP-5 at the northern edge of the property. Wells should be installed, at these locations, as permitted by subsurface utilities and surrounding structures. Groundwater flow direction should be determined to help establish the source of contamination. The soil should be screened continuously with a PID. The deepest dry soil sample and the sample with the highest PID reading in each boring/well should be sent for EPA Method 8021/8270 analyses and the results should be sent to the Department. A water sample should be obtained at each well location and submitted for EPA Method 8021/8270 analyses. MTBE must be included on all soil and groundwater analyses. A report summarizing the findings of the

FORMER GAS STATION (Continued) **S106868437**

subsurface investigation, including boring logs, well installation logs, sample analyticals, site plan, conclusions and recommendations, must be submitted to the Department. Upon completion of the investigation, the owner/consultant should evaluate the data to determine the source of contamination. 2. Site History including: previous site usage; current and historical petroleum storage including tank removals and abandonments; sizes of tanks removed/abandoned and types of product stored; number of tanks; spill numbers; Petroleum Bulk Storage (PBS) Registration including PBS Number(s).AZ 7-25-2005 Telephone conversation with Ted Yen (Don Carlo Env. Services 718-857-3100). Mr.Yen called to clarify DEC request. He will be collecting all necessary information and prepare a report for the site owner Mr. Batistatos. AZ 1/17/2006 Left a message for Ted Yen (Don Carlo Env.). Investigation is pending. AZ 1/19/2006 I contacted John Spanacos (attorney for the client). He stated that the consultants were paid 1/2 half and supposed to start investigation. He will follow up with the inquiry. AZ 3/20/2006 A report was submitted by Marvin Kramer & Associates (516-742-2800) and issued by Hydro Tech Environmental (718-636-0800). The report stated that the inestigated property is located downgradient from the property adjacent to it on the north and presently occupied by MC Donalds's which was formerly a gas station. A major clean up work was performed at Mc Donald's property according to Marvin Kramer. The report documented that 269-271 4th Avenue is located downgradient from the possible source of contamination. This spill report was closed and a new spill report #0551768 was opened as per Koon Tang (NYSDEC) instructions. AZ "

Remarks: "FOUND CONTAMINATED SOIL IN GROUNDWATER: MR. PRATT IS PROSPECTIVE BUYER OF PROPERTY:"

All Materials:

Site ID:	344148
Operable Unit ID:	1102802
Operable Unit:	01
Material ID:	583021
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A23 **LOT 7,TAXBLOCK 964** **NY E DESIGNATION** **S108075331**
ESE **269 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.026 mi.
139 ft. **Site 22 of 83 in cluster A**

Relative: **Higher**
Actual: **27 ft.**

E DESIGNATION:

Name:	LOT 7,TAXBLOCK 964
Address:	269 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	7
Tax Block:	964
Borough Code:	BK

LOT 7,TAXBLOCK 964 (Continued) **S108075331**

E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

A24 **YARD** **NY Spills** **S111159555**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 23 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:

Name:	YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1105298 / 2011-10-28
Facility ID:	1105298
Facility Type:	ER
DER Facility ID:	407587
Site ID:	452947
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-07-21
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-08-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-08-09
Spill Record Last Update:	2011-10-28
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 FIRST STREET
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"10/28/11 - Austin - 1 pint of gasoline found in UST fillport sec. containment sump (discovered 7/21/11, last delivery was on 7/15/11) - Con Ed contained and cleaned up spill - See eDocs for additional info. in documents submitted - Spill closed - end"
Remarks:	"1 pint of gas."

All Materials:

Site ID:	452947

YARD (Continued) **S111159555**

Operable Unit ID:	1203109
Operable Unit:	01
Material ID:	2199723
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A25 **CONSOLIDATED EDISON** **NY MANIFEST** **S120957304**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 24 of 83 in cluster A**

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY 11215-0000
Country:	USA
EPA ID:	NYD000706218
Facility Status:	Not reported
Location Address 1:	222 1ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	1892

NY MANIFEST:

EPAID:	NYD000706218
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	RM 828
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	12/31/2009
Trans1 Recv Date:	12/31/2009
Trans2 Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S120957304**

TSD Site Recv Date:	01/04/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000706218
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	002490145FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	124
Units:	P - Pounds
Number of Containers:	78
Container Type:	CY - Cylinders
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A26 **CON EDISON** **NY MANIFEST** **S117058154**
West **222 FIRST ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 25 of 83 in cluster A**

Relative: NY MANIFEST:
Lower

Actual: Name:	CON EDISON
19 ft. Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004704946
Facility Status:	Not reported
Location Address 1:	222 FIRST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN

CON EDISON (Continued) **S117058154**

Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004704946
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/10/2014
Trans1 Recv Date:	12/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004704946
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001084459GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117058154**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A27 **CON EDISON VEHICLE 6077 HYDRAULIC SPILL** **NY Spills** **S121982275**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 26 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON EDISON VEHICLE 6077 HYDRAULIC SPILL
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1110967 / 2012-01-17
Facility ID:	1110967
Facility Type:	ER
DER Facility ID:	353674
Site ID:	458834
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-12-09
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-12-09
Spill Record Last Update:	2012-01-17
Spiller Name:	ERT
Spiller Company:	CON EDISON
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"12/9/11-Vought-Duty desk officer. Spill assigned to DEC Feroze as part of routine Con Edison minor spill portfolio review and possible closure. Initial EMIS #228242 deleted from proxy and added to E-docs and also added to Cross Reference Field. As per EMIS, OIL LEAKED FROM VEHICLE ONTO GARAGE FLOOR, THE CONCRETE PIT, AND THE STEPS INTO THE CONCRETE PIT.....CLEANUP TO BEGIN..... 1/17/12 - Austin - 1 pint (quart?) hydraulic fluid spill from Con Ed truck in their maintenance garage - Con Ed contained and cleaned up the spill - See documents in

CON EDISON VEHICLE 6077 HYDRAULIC SPILL (Continued) **S121982275**

eDocs files for further info - Spill closed - end"
Remarks: "1 pint to concrete, c/u pending"

All Materials:
Site ID: 458834
Operable Unit ID: 1208945
Operable Unit: 01
Material ID: 2206301
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .25
Units: G
Recovered: Not reported
Oxygenate: Not reported

A28 **THIRD AVE YARD - SERVICE CENTER** **NY Spills** **S121987815**
West **222 1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 27 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:
Name: THIRD AVE YARD - SERVICE CENTER
Address: 222 1ST STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9808009 / 2017-06-08
Facility ID: 9808009
Facility Type: ER
DER Facility ID: 347552
Site ID: 299103
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B2
SWIS: 2401
Spill Date: 1998-09-30
Investigator: MJHAGGER
Referred To: Not reported
Reported to Dept: 1998-09-30
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-09-30
Spill Record Last Update: 2017-06-08
Spiller Name: CALLER
Spiller Company: 3RD AVE YARD
Spiller Address: 222 1ST STREET
Spiller Company: 001
Contact Name: CALLER

THIRD AVE YARD - SERVICE CENTER (Continued) **S121987815**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL From DEC # 9608854 file: 11/21/96: KATZ SPOKE WITH CHERYL PAYNE, CON ED - FREE PRODUCT FOUND IN WELL. TIGHTNESS TEST DONE ON TANK & PIPING AND FOUND TO BE TIGHT. UNKNOWN SOURCE OF PRODUCT - POSSIBLY OVERFILLS. 2000 GALLON GASOLINE & 2000 GALLON DIESEL UNDER CONCRETE MAT. NOT AWARE OF ANY PROBLEMS WITH DISPENSERS. (GHK) 2/10/97: Con Ed submits pre-closure assessment for north and south tank areas (north UST area contains 1 x 2,500 gallon gasoline and 1 x 2,500 gallon diesel tank; south UST area contains 1 x 4,000 gallon gasoline and 1 x 4,000 gallon diesel tank). Results of soil and groundwater sampling indicate both areas have been impacted by releases from the tanks and/or piping. Con Ed proposes to conduct site investigation. (GHK) 9/30/98, 12:31 PM: Voice message from Ann Ip (Con Ed Remediation) - digging around 2,500 gal diesel UST (north UST area) - found contaminated soil. Estimated 15 cu yds soil. (CAE) 10/8/98: Spoke with Tom Lasker (Con Ed Const Mgmt) - 2500 gal tanks are not out yet. He doesn't anticipate that excavation will be ready for inspection til next Tuesday. Jim Seisfeld is handling the project for Ann Ip while she is away. (CAE) 10/21/98: Excavation for removal of 2500 gallon tanks (north area) - excavation about 15 feet deep, 20' x 30'. No apparent visible contamination. No odor. Will do 5 composites (5:1) on side walls, 5 grabs. (CAE) 11/2/98: Tank pulls - Con Ed Construction Mgmt. has excavated as deep as they need to go to put in new tanks. Inspected soil from bottom of excavation - strong petroleum odor. Jar test - sheen on water. Dug down with bucket into bottom of excavation - groundwater about 1.5 to 2 feet below bottom. Told Con Ed to excavate to that depth on entire excavation. Will tanke 4 grab, 4 composite samples for VOCs, SVOCs - 3 walls and bottom. Already did some sampling when tank was originally pulled (5 grab, 5 composite) but present excavation extends beyond original so have to do more samples. (CAE) 11/12/03: e-mail from Ray Fitzpatrick (Con Ed Remediation) indicating that 2 x 4000 gallon tanks (south UST area) are to be removed on Nov. 19 (tentative schedule). 6/20/00: Meeting w/ Angel Chang (Con Ed Remediation) - Con Ed was told of possible off-site contamination at Mendon Truck Leasing site (located south of Third Ave Yard). Ground water analytical data provided by Mark Tibbe (DEC project manager) indicates contamination in two of their upgradient wells - gw contour map shows Con Ed's south UST area is immediately upgradient (across the street) from these wells. Con Ed is to submit draft work plan for additional investigation around both north and south UST areas. (JHO) 7/24/00: Con Ed submits Tank Closure Report documenting results of post-excavation soil samples, and a Site Investigation Work Plan (SIWP). Proposal includes 6 soil borings/4 monitoring wells for the north UST area, and 10 soil borings/7 monitoring wells for the south UST area. 9/11/00: Comment letter to Con Ed on SIWP - requests addition of one well upgradient of the north UST area; clarifies soil sampling protocol; clarifies lab analytical methods. (KMF) 11/22/00: response form Con Ed satisfactorily responds to comments. 11/27/00: SIWP approved. (KMF) 12/13/00: Field work commences. 1/18/01: Free product found in well MW-4N in north UST area. This is the well immediately north (upgradient) of the tanks. Approximately 1 inch of product was noted. Absorbent sock installed to recover product. (KMF) 6/1/01: Site Characterization Report submitted. Results indicate elevated concentrations of BTEX and MTBE in soils and groundwater for both tank areas, and intermittent free product in north UST area (well MW-4N). 2/13/03: comment letter to Con Ed - recommends monthly

THIRD AVE YARD - SERVICE CENTER (Continued) **S121987815**

gauging to continue, and include VEFR event; requests installation of 2 add'l borings/wells northeast and west of north UST area (work plan required); requests submittal of historic groundwater analytical data. (KMF) 3/6/03: VEFR event postponed - waste characterization results for groundwater has benzene concentration of 3.7 ppm (cannot be accepted at Astoria waste treatment facility - must arrange for subcontractor. (KMF) 3/7/03: Clarified with M. Gonzalez that quarterly sampling to be conducted on all wells. Also, monthly monitoring on all wells. (KMF) 3/17/03: Response letter from Con Ed addresses comments in 2/13/03 letter. 4/21/03: Work Plan for installation of 3 additional wells at the north UST area. Plan prepared by First Environment. 6/25/03: comment letter to Con Ed - clarifies sampling and analytical protocols; and requests revisions to QAPP. (KMF) 10/9/03: Response letter from Con Ed satisfactorily addresses comments in 6/25/03 comment letter. (JHO) 10/14/03: Work plan approved. (JHO) 12/16/03: Meeting with M. Gonzalez - VEFR requested by K. Foley in March 2003 was done. Con Ed only implemented quarterly sampling at this location in 2003 - three quarters done so far (4Q this week). Dissolved-phase contamination found in both north and south tank areas. Free product only noted in one well (MW-4N, north tanks). Three new wells are to be installed by First Environment in January. Following meeting, e-mail sent to M. Conzalez requesting lead be added to list of analytes for future quarterly sampling events. (JHO) 11/05/09: Mulitple documents had been received over interim period including RAWP, GW monitoring reports and subsequent IRM WP. RAWP was not implemented. Free product identified in one well in south UST area in September 2009. RP's consultant proposed additional delineation investigation of south UST area with VEFR and IRM for injection of ORC to address GW comtamination remaining in north UST area. Discussed project with RP's consultant and a revised IRM WP will be submitted. (JOC) 5/23/12: Draft remedial selection/remedial action work plan submitted 2/28/12. Document reviewed and letter with comments sent 3/19/12. Letter response and revised work plan received on 5/4/12. (JOC) 6/8/12: Reviewed 5/4/12 response from Con Edison and AECOM and sent comments via email 5/25/12; met today with Con Edison and AECOM to discuss those comments. As agreed today, Con Edison will put together a letter which documents the changes; based on some anticipated logistical issues at the facility, the pre-design work will be separated out with the objective of getting it completed within the next 3 weeks, so the focus of the letter should be to document changes to the pre-design work; the revisions to the RAWP can come later based on the pre-design work. Overall we had reached agreement on all the issues. (JOC) 9/6/12 - received email 9/4/12 from AECOM for Con Edison which was text as received at 6/8/12 meeting; attached to email was revised pre-design investigation summary, revised sample table, revised figure. Under review. (JOC) 9/28/12 - sent letter conditionally approving pre-design investigation as a separate effort from the remedial action 9/14; per discussion with Con Edison 9/24, their consultant is waiting for purchase order finalization through from Con Edison before they will start the work; Con Edison is working on getting the changes into their new PO system and will advise of updated schedule when available (JOC) 10/23/12 - received email from Con Edison: greater than greater than greater than Gonzalez, Mariela 10/23/2012 9:29 AM greater than greater than greater than Joe, preparation field activities for the drilling work are in progress. AECOM and GEOD mobilized on October 17 to start with

THIRD AVE YARD - SERVICE CENTER (Continued) **S121987815**

a geophysical survey and then to commence with utility clearance which will continue thru the end of this week. (1)Aztec, a subcontractor for AECOM, is pre-clearing the soil boring locations using a Safex unit and hand tools dig; and (2) day lightening (by test pits) of marked out utilities with GEOD surveying location and depths. Below a brief chronology of activities completed thru October 22nd. Wednesday October 17, 2012: Geod was on site to perform GPR of the excavation. A sketch was created for field use. A map will be completed in a couple weeks. Thursday October, 18, 2012: Geod was on site to continue with the topographical survey. Allstate a subcontractor of Geod cleared 3 locations of asphalt. Friday October 19, 2012: Geod and AECOM were on site. Allstate was scheduled to be on site at 730 with a vac truck but failed to show up. It was raining and there was a good deal of traffic. At 11AM Allstate was still en route and the day was called. Allstate will not be allowed on site to complete the work. Monday October 22, 2012: Aztech Pre cleared down to 5 feet D1 and D6. 3 locations were started for day lighting, to uncover gas lines and electrical lines. Geod pinpointed the depth of the gas lines. Con Ed electrical Operations crew on site to assist determining which lines are active or dead. Called Con Edison PM to discuss/confirm. Pre-clearing should be finished this week; drilling should start next week. They will keep me posted on the schedule if any changes. (JOC) 11/09/12 - PDI activities were completed on October 26th. No impledіments were identified to implementing the investigation as approved. Field progress updates in edocs. (JOC) 5/3/13 - Investigation continued to attempt to delineate the soil contamination around the south UST area, but is not completed. Notably one area (to the northwest of the UST area) had contamination with a different profile than observed in the UST area and may not be related to UST operations. Reviewed the report and sent comments/items for discussion to Con Edison via email 4/10/13; meeting was scheduled for 4/24 but was cancelled by Con Edison. (JOC) 7/14/16 - Con Edison proceeded with additional investigation at the 3rd Avenue Yard on their own, primarily related to the findings initially reported as spill 1008213, without Department input and provided a report on those efforts in January 2016. Department staff met with Con Edison on May 10, 2016 and July 8, 2016 to discuss Con Edison’s 3rd Avenue Yard overall and how to move forward with a comprehensive approach. Anticipate feedback from Con Edison shortly. (JOC) 11/18/2016 Austin This spill report is being transferred from Joe O Connell to Jennifer Kann - end. 06/05/17: J.Kann - as per Jeff spill reassigned to Kumar. 6/8/17 - Haggerty: Closed/consolidated under Site C224245. Further investigation and remediation will be conducted under the BCP."

Remarks: "CONTRACTORS REMOVING GAS TANK AND DISCOVERED APPROX 15 SQ YARDS OF STAINED SOIL THAT SMELLS LIKE GASOLINE. CROSS REF TO 96-05014 "

All Materials:

Site ID:	299103
Operable Unit ID:	1065568
Operable Unit:	01
Material ID:	315546
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

THIRD AVE YARD - SERVICE CENTER (Continued) **S121987815**

Recovered: .00
Oxygenate: Not reported

A29
West
< 1/8
0.027 mi.
142 ft.

THIRD AVE YARD
222 FIRST STREET
BROOKLYN, NY

Site 28 of 83 in cluster A

NY Spills **S121979436**
N/A

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	THIRD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0110159 / 2003-05-01
Facility ID:	0110159
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263575
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-01-22
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2002-01-22
CID:	216
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-22
Spill Record Last Update:	2003-05-01
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	CHARLIE MCCARTHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ E2MIS notes: 1/22/2002 22:20 hours: While making repairs to vehicle at 22:00 hrs. approximately 10 gallons hydraulic fluid spilled from a broken hydraulic hose onto concrete floor in shop at 3rd avenue yard. spill is contained. cleanup in progress at this time. 22:45 hours: cleanup complete. UDATE 10/02/02 A CHECK WITH TRANSPORTATION SHOWS HOSE WAS REPAIRED ON 1/23/02"
Remarks:	"spill from a bucket truck all of the product recovered con edison ref #141011 "

All Materials:

Site ID:	263575
Operable Unit ID:	848638
Operable Unit:	01

THIRD AVE YARD (Continued) **S121979436**

Material ID:	527790
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

A30 **CON EDISON** **NY Spills** **S102238222**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 29 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:

Name:	CON EDISON
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9510404 / 1995-11-20
Facility ID:	9510404
Facility Type:	ER
DER Facility ID:	167996
Site ID:	299101
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1995-11-16
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1995-11-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-18
Spill Record Last Update:	1996-01-24
Spiller Name:	MR PANICOGENE
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	MR PANICOGENE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Cleaned up by spiller"
Remarks:	"ANTIFREEZE LEAKED OUT OF VEHICLE IN GARAGE"

All Materials:

Site ID:	299101
Operable Unit ID:	1024882

CON EDISON (Continued) **S102238222**

Operable Unit:	01
Material ID:	553742
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

A31 **THIRD AVE YARD** **NY Spills** **S121980136**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 30 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual:
19 ft.

Name:	THIRD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0408750 / 2005-01-06
Facility ID:	0408750
Facility Type:	ER
DER Facility ID:	167996
Site ID:	333489
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-11-08
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2004-11-08
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-08
Spill Record Last Update:	2005-01-06
Spiller Name:	ERT DESK
Spiller Company:	CABLE COMPOUND
Spiller Address:	222 1ST ST
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis no. 156164: 11/8/04 - 1040 G. PANICO - SUPERVISOR - STORES, REPORTS A LEAK OF APPROX 10 GALS OF HYDRAULIC FLUID FROM VEH # 50588 ONTO ASPHALT IN THE 3RD AVE YD CABLE COMPOUND. SPILL IS CONTAINED WITH BALONEY'S, SPEEDY DRY & DIAPERS. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES. NO PRIVATE PROPERTY AFFECTED. CLEANUP IS IN PROGRESS. 11/8/04 1200HRS G. PANICO REPORTS

THIRD AVE YARD (Continued) **S121980136**

Remarks: CLEANUP COMPLETED USED DIAPERS SPEEDY DRY AND SLICKS. " "con ed vehicle number 50588"

All Materials:

Site ID:	333489
Operable Unit ID:	1095643
Operable Unit:	01
Material ID:	575766
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A32 **SERVICE BOX 3RD AVE YARD** **NY Spills** **S104195828**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 31 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	SERVICE BOX 3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9907981 / 2002-01-30
Facility ID:	9907981
Facility Type:	ER
DER Facility ID:	167996
Site ID:	299104
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-09-30
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-09-30
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-09-30
Spill Record Last Update:	2004-11-08
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	CALLER

SERVICE BOX 3RD AVE YARD (Continued) **S104195828**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis no. 128151: 9/30/99--1645HRS N.MCONNELLY #9 REPORTS WHILE CHECKING SBX IN 3RD AVE YARD ,HE FOUND APPROX 1-GALLON OF UNKNOWN OIL ON 8 GALLONS OF WATER IN SBX,IT APPEARS TO BE CONTAINED AT THIS TIME ,NO SEWERS OR WATERWAYS AFFECTED ,1-SAMPLE TAKEN TAG#12370 PLACED ==========G DONATONE========== 9/30/99 22:05 HRS -- LAB SEQ #99-10293, <1.0 PPM PCB ========== update********** 17:00HRS MR. BANKHEAD REPORTS, CLEANUP COMPLETED USING SLIX AND TAG# 12370 REMOVED. ========== update 10/08/99 ---- flash point results received --- lab seq#99-10294 -- flash point= >210 deg.f"

Remarks: "SAMPLE TAKEN-CLEANUP PENDING RESULTS. CON ED #128151"

All Materials:

Site ID:	299104
Operable Unit ID:	1086645
Operable Unit:	01
Material ID:	553083
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A33 **CON EDISON - 3RD AVE** **RCRA-LQG** **1000111635**
West **222 1ST ST** **NJ MANIFEST** **NYD000706218**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 32 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

RCRA-LQG:

Date Form Received by Agency:		20220222
Handler Name:	CON EDISON - 3RD AVE	
Handler Address:		222 1ST ST
Handler City,State,Zip:		BROOKLYN, NY 11215-1892
EPA ID:		NYD000706218
Contact Name:		ALEXANDER PIZZANO
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-4005
Contact Fax:		315-454-4467
Contact Email:		PIZZANOA@CONED.COM
Contact Title:		SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2021
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY

CON EDISON - 3RD AVE (Continued) **1000111635**

State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220405
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON - 3RD AVE (Continued) **1000111635**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:
Year: 2011

Click Here for Biennial Reporting System Data:
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM

CON EDISON - 3RD AVE (Continued) **1000111635**

Waste Code: D011
Waste Description: SILVER

Waste Code: D018
Waste Description: BENZENE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: U151
Waste Description: MERCURY

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE, 15TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE, 15TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19450731
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19450731
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19450731
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE

CON EDISON - 3RD AVE (Continued) **1000111635**

Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private

CON EDISON - 3RD AVE (Continued) **1000111635**

Date Became Current: 19450731
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19450731
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Historic Generators:

Receive Date:	20100323
Handler Name: CON EDISON - 3RD AVE	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120306
Handler Name: CON EDISON - 3RD AVE	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140327
Handler Name: CON EDISON - 3RD AVE	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160205
Handler Name: CON EDISON - 3RD AVE	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180410
Handler Name: CON EDISON - 3RD AVE	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY

CON EDISON - 3RD AVE (Continued) **1000111635**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220222
Handler Name:	CON EDISON - 3RD AVE
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20060220
Handler Name:	CON EDISON - 3RD AVE
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	CON EDISON - 3RD AVE
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19800818
Handler Name:	CON EDISON - THIRD AVENUE SERVICE YARD
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON - 3RD AVE (Continued) **1000111635**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920228
Handler Name: CON ED - 3RD AVENUE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940331
Handler Name: CON EDISON-THIRD AVENUE SERVICE CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960329
Handler Name: CON EDISON -
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - THIRD AVENUE SERVICE CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101

CON EDISON - 3RD AVE (Continued) **1000111635**

Handler Name: 3RD AVE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020531
Handler Name: CON EDISION - 3RD AVE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040225
Handler Name: CON EDISON - 3RD AVE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - 3RD AVE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080221
Handler Name: CON EDISON - 3RD AVE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CON EDISON - 3RD AVE (Continued) **1000111635**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20170615
Actual Return to Compliance Date: 20170807
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170711
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20090223
Actual Return to Compliance Date:	20090430
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090311
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20090430
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)

CON EDISON - 3RD AVE (Continued) **1000111635**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSAN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20031024
Actual Return to Compliance Date: 20031204
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20031120
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSAN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Contingency Plan and Emergency Procedures
Date Violation was Determined:	20170615
Actual Return to Compliance Date:	20170807
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20170711
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYSC
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20170615
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSC
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20170807
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20110401
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2STP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20090223
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090430
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Former Citation:	Not reported
Evaluation Date:	20031024
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSAN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20031204
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20170615
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20170807
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20121114
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE ASSISTANCE VISIT
Evaluation Responsible Person Identifier:	R2JDW
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NJ MANIFEST:

EPA Id:	NYD000706218
Mail Address:	222 FIRST ST
Mail City/State/Zip:	BROOKLYN 11215
Facility Phone:	7188025672
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5316846
EPA ID:	NYD000706218
Date Shipped:	06/07/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/07/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/07/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08020621
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	000182029GBF
EPA ID:	NYD000706218
Date Shipped:	06/11/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/11/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/11/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	42120 P

Manifest Number:	NJA5121770
EPA ID:	NYD000706218
Date Shipped:	01/07/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/07/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03160425
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5205855
EPA ID:	NYD000706218
Date Shipped:	12/02/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/02/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/02/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01040521
Was Load Rejected:	BROOKLYN 11215

CON EDISON - 3RD AVE (Continued) **1000111635**

Reason Load Was Rejected:	Not reported
Manifest Number:	000266847GBF
EPA ID:	NYD000706218
Date Shipped:	10/04/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/04/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/04/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported
Manifest Number:	000411117GBF
EPA ID:	NYD000706218
Date Shipped:	04/16/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Date Trans1 Transported Waste:	04/16/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/16/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	38820 P

Manifest Number:	000416551GBF
EPA ID:	NYD000706218
Date Shipped:	07/23/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/23/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Date TSDF Received Waste:	07/23/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	45240 P

Manifest Number:	000411120GBF
EPA ID:	NYD000706218
Date Shipped:	04/28/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/28/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/20/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	36700 P

Manifest Number:	000180268GBF
EPA ID:	NYD000706218
Date Shipped:	02/07/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/07/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/07/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008

CON EDISON - 3RD AVE (Continued) **1000111635**

Hand Code:	H14
Quantity:	49200 P
Manifest Number:	000180269GBF
EPA ID:	NYD000706218
Date Shipped:	02/07/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/07/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/07/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H14
Quantity:	30480 P
Manifest Number:	NJA5316946
EPA ID:	NYD000706218
Date Shipped:	07/10/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/10/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/10/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08220625
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	000416914GBF
EPA ID:	NYD000706218
Date Shipped:	8/29/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5239134
EPA ID:	NYD000706218
Date Shipped:	07/06/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/06/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/06/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08030521

CON EDISON - 3RD AVE (Continued) **1000111635**

Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5271973
EPA ID:	NYD000706218
Date Shipped:	10/21/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/21/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/21/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01100621
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported
Manifest Number:	002661259GBF
EPA ID:	NYD000706218
Date Shipped:	5/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	000182036GBF
EPA ID:	NYD000706218
Date Shipped:	07/12/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/12/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/12/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	51240 P

Manifest Number:	000262944GBF
EPA ID:	NYD000706218
Date Shipped:	08/02/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/02/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/02/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11215

CON EDISON - 3RD AVE (Continued) **1000111635**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H14
Quantity: 54140 P

Manifest Number: NJA5206110
EPA ID: NYD000706218
Date Shipped: 02/16/2005
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 02/16/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 02/16/2005
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 04180521
Was Load Rejected: BROOKLYN 11215
Reason Load Was Rejected: Not reported

Manifest Number: NJA5239002
EPA ID: NYD000706218
Date Shipped: 05/23/2005
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/23/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/23/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06270521
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5239141
EPA ID:	NYD000706218
Date Shipped:	07/27/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/27/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON - 3RD AVE (Continued) **1000111635**

Date TSDF Received Waste:	07/27/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08300522
Was Load Rejected:	BROOKLYN 11215
Reason Load Was Rejected:	Not reported

A34 **CON ED 3RD AVE STATION** **NY Spills** **S118638446**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 33 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:

Name:	CON ED 3RD AVE STATION
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1601300 / 2017-03-28
Facility ID:	1601300
Facility Type:	ER
DER Facility ID:	353674
Site ID:	526616
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2016-05-09
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2016-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-05-09
Spill Record Last Update:	2017-03-28
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT

CON ED 3RD AVE STATION (Continued) **S118638446**

DEC Memo: "5/9/16: Mahat EMIS : 245161 [crossed referenced] EMIS Remark: Adrian F Davis (06217) reported that as he delivered a 55 gallon drum to the parking area in the 3rd Ave Yard he discovered approximately 1 qt of hydraulic fluid had spilled on the asphalt and some had entered to storm drain. cleanup is in progress. Based on the EMIS report, the spill case is assigned to Con Ed Unassigned. 3/28/17 TJD File review. Final EMIS #245161/2 submitted in support of closure request, as per report: Location: 3rd Ave Stores 222 FIRST STREET Initial Observation: Adrian F Davis (06217) reported that as he delivered a 55 gallon drum to the parking area in the 3rd Ave Yard he discovered approximately 1 qt of hydraulic fluid had spilled on the asphalt and some had entered to storm drain. Cleanup is in progress. Cause: Equipment Malfunction - Aged equipment Resolution: 2/7/2017 1:48 PM Operating Supervisor K. Smith 04409 reported spill was cleaned within two hours on 5/9/2016. Site was inspected at the time and no material made it to any storm drains. Site was cleaned using speedi dry and absorbent material which was placed in a non haz 55 gallon drum of oily debris at the 3rd Avenue Yard. Based upon the documentation provided, the reported environmental condition has been appropriately remediated in accordance with applicable regulations. No further action is required. Spill closed."

Remarks: "lost to storm drain and asphalt; c/u in progress"

All Materials:

Site ID:	526616
Operable Unit ID:	1275538
Operable Unit:	01
Material ID:	2280279
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.25
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A35 **COOLANT RELEASE FROM VEH 41130** **NY Spills** **S108635888**
West **222 1 STREET (THIRD AVE YARD)** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 34 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual: Name:	COOLANT RELEASE FROM VEH 41130
19 ft. Address:	222 1 STREET (THIRD AVE YARD)
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0700220 / 2007-05-23
Facility ID:	0700220
Facility Type:	ER
DER Facility ID:	329039
Site ID:	379559
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-04-07

COOLANT RELEASE FROM VEH 41130 (Continued) **S108635888**

Investigator:	gdbreen
Referred To:	Not reported
Reported to Dept:	2007-04-07
CID:	78
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-04-10
Spill Record Last Update:	2007-05-23
Spiller Name:	Not reported
Spiller Company:	CON EDISON VEH#41130
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERTS
DEC Memo:	"05/23/07 - See e-docs for Con Ed report detailing cleanup and closure. 205265. see eDocs"
Remarks:	"leak from radiator 205265 spill contained"

All Materials:

Site ID:	379559
Operable Unit ID:	1137038
Operable Unit:	01
Material ID:	2126979
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

A36
West
< 1/8
0.027 mi.
142 ft.

CONSOLIDATED EDISON **NY MANIFEST** **S105058470**
222 1ST ST **N/A**
BROOKLYN, NY 11215

Site 35 of 83 in cluster A

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP000920355
Facility Status:	Not reported
Location Address 1:	222 1ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY

CONSOLIDATED EDISON (Continued) **S105058470**

Location Zip: 11215
Location Zip 4: 1892

NY MANIFEST:
EPAID: NYP000920355
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: 1892
Mailing Country: USA
Mailing Phone: 2124602808

A37 **CON ED THIRD AVE YARD** **NY Spills** **S111159788**
West **222 FIRST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 36 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:
Name: CON ED YARD
Address: 222 FIRST ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1105608 / 2011-10-04
Facility ID: 1105608
Facility Type: ER
DER Facility ID: 361857
Site ID: 453268
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2011-08-17
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2011-08-17
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-08-17
Spill Record Last Update: 2011-10-04
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT
DEC Memo: "10/4/11 - Austin - A broken piston on a Con Ed vehicle spilled 10

CON ED THIRD AVE YARD (Continued) **S111159788**

gals. hydraulic oil onto pavement - Con Ed contained and cleaned up the spill - See eDocs for further information - Spill closed - end"
Remarks: "on asphalt - cleanup in progress"

All Materials:
Site ID: 453268
Operable Unit ID: 1203426
Operable Unit: 01
Material ID: 2200075
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Site ID: 453268
Operable Unit ID: 1203426
Operable Unit: 01
Material ID: 2200074
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: CON ED THIRD AVE YARD
Address: 222 FIRST ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 2104705 / 2021-10-04
Facility ID: 2104705
Facility Type: ER
DER Facility ID: 361857
Site ID: 623525
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2021-08-18
Investigator: EJKIM
Referred To: Not reported
Reported to Dept: 2021-08-18
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

CON ED THIRD AVE YARD (Continued) **S111159788**

Date Entered In Computer:	2021-08-18
Spill Record Last Update:	2021-10-04
Spiller Name:	Not reported
Spiller Company:	CON ED VEHICLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"EMIS 281193 8/18/2021 - Feng - Desk Duty in office. Received EMIS report. Backhoe 9229 had a hydraulic leak of 1 liter to bluestone in the yard. Transportation will assist the vehicle repair. Cleanup in progress. Assigned spill to Con Ed Unassigned. 10/4/21 - Kim - On 8/18/21 Con Ed removed the impacted bluestone and cleaned up the spilled hydraulic oil using Simple Green. Waste was disposed of as non-hazardous oily debris. Con Ed took the vehicle to Con Ed Transportation for repairs. See document files for further information Spill closed end"
Remarks:	"blue stone, c/u pending"

All Materials:

Site ID:	623525
Operable Unit ID:	1370676
Operable Unit:	01
Material ID:	2383753
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.25
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A38
West
< 1/8
0.027 mi.
142 ft.

CON-ED THIRD AVE YARD **NY Spills** **S111319109**
222 FIRST ST **N/A**
BROOKLYN, NY

Site 37 of 83 in cluster A

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	CON-ED THIRD AVE YARD
Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1110305 / 2012-01-17
Facility ID:	1110305
Facility Type:	ER
DER Facility ID:	361857
Site ID:	458118
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-11-18
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-11-18
CID:	Not reported
Water Affected:	Not reported

CON-ED THIRD AVE YARD (Continued) **S111319109**

Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-11-18
Spill Record Last Update:	2012-01-17
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 FIRST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"1/17/12 - Austin - 4 gals. of hydraulic oil leaked from a drum onto pavement - Con Ed contained and cleaned up the spill - See documents in eDocs files for further info - Spill closed - end"
Remarks:	"4 gallons of unknown oil leaking from a 55 gallon drum."

All Materials:

Site ID:	458118
Operable Unit ID:	1208227
Operable Unit:	01
Material ID:	2205560
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A39 **CONSOLIDATED EDISON** **NY MANIFEST** **S120957666**
West **222 FIRST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 38 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP000706218
Facility Status:	Not reported
Location Address 1:	222 FIRST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000706218

CONSOLIDATED EDISON (Continued) **S120957666**

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

A40 **CON ED 3RD AV YARD** **NY Spills** **S104510043**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 39 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON ED 3RD AV YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9913132 / 2000-02-18
Facility ID:	9913132
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263145
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-02-18
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-02-18
CID:	323
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-18
Spill Record Last Update:	2000-05-22
Spiller Name:	Not reported
Spiller Company:	PRIVATE CONTRACTOR
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RICHARD ROACH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2 MIS REPORT 2/18/00 Island Transportation, private contractor was making delivery of gasoline to our pumps at 3rd Ave. yard 222 1st Street, there was a spill of approx. 5 gallons of residual gasoline that was in hose onto concrete. Spill is contained- no sewers or waterways affected, no outside impact , cleanup is in

CON ED 3RD AV YARD (Continued) **S104510043**

progress with balonies -diapers- and speedy dry. Cleanup will be completed within 2hrs. 2/18/00 10:28hrs. Cleanup is completed at this time with speedy-dry, diapers and balonies. DEC INSPECTOR NOTES ERT Bill Wallace - While ITC corp was making delivery 5 gals. from hose (residual in hose after disconnect) spilled to concrete. Contained within balonies , cleared with dpeedy-dry and absorbant pads. No impact to soil, wayerways or sewere."

Remarks: "SPILLED ON CON ED PROPERTY. BEING CLEANED UP. CON ED #130039"

All Materials:

Site ID:	263145
Operable Unit ID:	1091849
Operable Unit:	01
Material ID:	294990
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A41 **CON ED 3RD AV GARAGE** **NY Spills** **S121987241**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 40 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON ED 3RD AV GARAGE
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9607770 / 1998-05-27
Facility ID:	9607770
Facility Type:	ER
DER Facility ID:	167996
Site ID:	276610
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-09-20
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-09-20
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-09-20

CON ED 3RD AV GARAGE (Continued) **S121987241**

Spill Record Last Update:	1998-05-27
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	128 WEST END AVENUE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"unknown cause out of con ed veh"

All Materials:

Site ID:	276610
Operable Unit ID:	1038926
Operable Unit:	01
Material ID:	347027
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

A42 **CON ED FACILITY** **NY Spills** **S103575627**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 41 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON ED FACILITY
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9811783 / 2003-02-14
Facility ID:	9811783
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263579
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-12-18
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1998-12-18
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

CON ED FACILITY (Continued) **S103575627**

Date Entered In Computer:	1998-12-18
Spill Record Last Update:	2003-02-19
Spiller Name:	RICHARD ROACH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	RICHARD ROACH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks:	"CAN FELL FROM TRUCK"

All Materials:

Site ID:	263579
Operable Unit ID:	1069048
Operable Unit:	01
Material ID:	312067
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

A43
West
< 1/8
0.027 mi.
142 ft.

OIL LEAK FROM VEHICLE 23089 **NY Spills** **S107415965**
222 FIRST ST AT 3 AVE **N/A**
BROOKLYN, NY

Site 42 of 83 in cluster A

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	OIL LEAK FROM VEHICLE 23089
Address:	222 FIRST ST AT 3 AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0508341 / 2005-11-25
Facility ID:	0508341
Facility Type:	ER
DER Facility ID:	301245
Site ID:	353906
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-10-12
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-10-12
CID:	407
Water Affected:	RELEASE TO SEWER
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

OIL LEAK FROM VEHICLE 23089 (Continued) **S107415965**

Remediation Phase:	0
Date Entered In Computer:	2005-10-12
Spill Record Last Update:	2005-11-25
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	222 FIRST ST/3RD AVE
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"161485. 12-OCT-2005 16:29 HRS. TRANSPORTATION DEPT.O.S. C.WISHER EMP# 43664 REPORTS: TRANSPORTATION MECH-A V.CARDONE EMP# 84810 WHILE VEHICLE # 23089 WAS IN FOR MAINTENANCE WORK FOUND IT HAD LEAKED FROM A HOLE IN THE OIL PAN 3QTS OF MOTOR OIL ON TO 200 GALS OF WATER DIRECTLY OVER A STORM DRAIN. THERE IS NO FIRE INVOLVEMENT .NO SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. NO PRIVATE PROPERTY AFFECTED. OWNER OF SUBSTANCES IS CONED. ABSORBENT PADS & PIGS WERE PLACED ON SPILL AREA IN AN ATTEMPT TO CONTROL & CONTAIN THE SPILL. THE VEHICLE WAS TURNED IN TO TRANSPORTATION. THE SPILL WILL HAVE TO BE MONITORED FOR MIGRATION TO OTHER WATERWAYS. C.HOGAN 07511 UPDATE 12-OCT-2005 17:23 HRS. TRANSPORTATION DEPT.O.S. C.WISHER EMP# 43664 REPORTS: THE WATER HAS RECEDED AND THE STORM DRAIN HAS BEEN IMPACTED AT THIS TIME. C.HOGAN 07511. Closed. 11-25-05. see eDocs. GB "
Remarks:	"amount 3 quarts on 200 gallons of water, punctured oil pan. 161485"

All Materials:

Site ID:	353906
Operable Unit ID:	1111352
Operable Unit:	01
Material ID:	2101391
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A44 **CON EDISON 3RD AVE YARD** **NY Spills** **S121987460**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 43 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON EDISON 3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9703946 / 2003-02-28
Facility ID:	9703946
Facility Type:	ER
DER Facility ID:	167996
Site ID:	299102
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401

CON EDISON 3RD AVE YARD (Continued) **S121987460**

Spill Date:	1997-07-01
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1997-07-01
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-01
Spill Record Last Update:	2003-02-28
Spiller Name:	CALLER
Spiller Company:	CON EDISON 3RD AVE YARD
Spiller Address:	222 1ST STREET
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis 108851 01 JUL 1997 1212HRS MR DITRENTO #52669 REPORTS AT 3 RD AVE YARD NORTH GARAGE VEHICLE C60305 OIL LINE RUPTURED SPILLING 20 GALLONS OIL ON TRUCK AND CONCRETE FLOOR . AREA HAD BEEN PROTECTED BY BALONEYS AND IS CONTAINED. LAST UNIT RECYCLED 10 PPM. CLEAN UP IN PROGRESS. 01-JUL-1997 1435HRS DITRENTO REPORTS CLEANUP COMPLETE WITH FLUSH TRUCK, SLIX, DIAPERS AND ABSORBANT."
Remarks:	"ruptured hose on a recycling truck. clean up started."

All Materials:

Site ID:	299102
Operable Unit ID:	1046881
Operable Unit:	01
Material ID:	569514
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A45 **CON ED STATION** **NY Spills** **S112226482**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 44 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual: Name:	CON ED STATION
19 ft. Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1205717 / 2013-03-08
Facility ID:	1205717
Facility Type:	ER

CON ED STATION (Continued) **S112226482**

DER Facility ID:	407587
Site ID:	468682
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2012-09-08
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2012-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-09-08
Spill Record Last Update:	2013-03-08
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 FIRST STREET
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"3/8/13 - Austin - Report of oil escaping from a transformer that was located at Con Ed's Stores facility turned out to be water only, no oil spill - See documents in eDocs file for further details - Spill closed - end"
Remarks:	"transformer overflowed from the rain went into catch basin"

All Materials:

Site ID:	468682
Operable Unit ID:	1218599
Operable Unit:	01
Material ID:	2217002
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A46 **3RD AVENUE YARD** **NY Spills** **S103036950**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 45 of 83 in cluster A**

Relative: SPILLS:
Lower

Name:	3RD AVENUE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY

Actual:
19 ft.

3RD AVENUE YARD (Continued) **S103036950**

Spill Number/Closed Date:	9714230 / 1998-05-13
Facility ID:	9714230
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263578
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-03-24
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-03-24
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-24
Spill Record Last Update:	2003-03-06
Spiller Name:	CALLER
Spiller Company:	CON EDISON
Spiller Address:	128 WEST END AVENUE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 4/28/98 e-mail from Con Ed ERT Carbone: Spill was to asphalt. Absorbent was used andcleanup completed on 3/24. E2MIS 115509 C.AVELLA#51939 OF THIRD AVE STORES REPORTS TRUCK#H62064 LEAKING MOTOR OIL OUTSIDE STORES BUILDING#1. TRUCK LEAKED APPROXIMATELY 1-QUART OF MOTOR OIL ON ASPHALT. SPILL CONTAINED -- NO SEWERS OR WATERWAYS AFFECTED. SPILL CLEANED AT 0215 HRS.WITH OIL ABSORB. D.HERBST 27461. AT 0700 J.FERRAIUOLO#44744 O.S.STORES REPORTS ABOVE CLEANUP NOT COMPLETED.OIL SOAKED OIL ABSORB STILL UNDER TRAILER. CANNOT COMPLETE CLEANUP UNTIL TRAILER IS MOVED.WAITING TRANSPORTATION. D.HERBST 27461. CIG CESARE NITIFIED AT 0700HRS. D.HERBST THIS INCIDENT UPDATED 6/9/98 MR DONOVANI RECEIVED A CALL FROM ISIAK HAWKINS STATING THIS CLEANUP WAS ORIGINALLY CALLED IN COMPLETED 3/24/98 AT"
Remarks:	"VEHICLE HAD LEAK AT OIL PAN. VEHICLE TOWED TO BE FIXED. SITE CLEANED."

All Materials:

Site ID:	263578
Operable Unit ID:	1057090
Operable Unit:	01
Material ID:	325202
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G

3RD AVENUE YARD (Continued) **S103036950**

Recovered: .00
Oxygenate: Not reported

A47 **3RD AVE YARD** **NY Spills** **S121981441**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 46 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:

Name:	3RD AVE YARD
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0813445 / 2009-06-03
Facility ID:	0813445
Facility Type:	ER
DER Facility ID:	353674
Site ID:	411134
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-03-13
Investigator:	asnagi
Referred To:	Not reported
Reported to Dept:	2009-03-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-03-13
Spill Record Last Update:	2009-06-03
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"06/03/09 - See eDocs for Con Ed report detailing cleanup and closure. "
Remarks:	"Caller states an unknown foam is coming out of an oil - water seperator onto the side of the building and sidewalk. Cleasnup is in progress."

All Materials:

Site ID:	411134
Operable Unit ID:	1167601
Operable Unit:	01
Material ID:	2159180
Material Code:	9999
Material Name:	other - Foam
Case No.:	Not reported

3RD AVE YARD (Continued) **S121981441**

Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A48
West
< 1/8
0.027 mi.
142 ft.

3RD AVE YARD **NY Spills** **S102239537**
222 FIRST STREET **N/A**
BROOKLYN, NY

Site 47 of 83 in cluster A

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0300475 / 2003-04-15
Facility ID:	0300475
Facility Type:	ER
DER Facility ID:	167996
Site ID:	299100
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2003-04-14
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2003-04-14
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-14
Spill Record Last Update:	2003-04-15
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	KEVIN MCCARDLE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ e2mis 147881 4-14-03 09:30 HRS E. WILLIAMS # 56346 OS FLUSH DEPT REPORTS WHILE MAKING INSPECTION IN 222 FIRST STREET YARD HE FOUND IN 3 AVE CABLE YARD 1 OZ OF DI ELECTRIC (OIL) FLUID ON 1 GALLON WATER THAT HAD LEAKED (OVERFLOWED) FROM A HOLDING TUB THAT A TRANSF WAS SITTING IN . THIS TUB OVERFLOW FROM THE RAIN OVER THE WEEKEND ONTO ASPHALT RDWY. THE SPILL WAS CONTAINED TO A 5' X 5' AREA NO SEWERS OR WATERWAYS AFFECTED. THE TRANSF WAS REMOVED FROM VS6084 AND WAS ON E2MIS INCIDENT 146366 (DATE OF INCIDENT 12-13-02) AND CHEM LAB # 02-11648-001 < 1 PPM. THERE WAS NO FIRE OR SMOKE AT THIS LOCATION . NO PRIVATE PROPERTY AFFECTED. NO INJURIES. NO SEWERS OR

3RD AVE YARD (Continued) **S102239537**

WATERWAYS AFFECTED. THEY STARTED CLEANUP. NO SAMPLE TAKEN AND NO E.S.TAG PLACED. THIS IS NOT A DEMINIMIS SPILL WILL NOT COMPLETE CLEANUP IN LESS THEN 2 HRS. UPDATE 4-14-03 1030 HRS S . GIOIA MECH A FLUSH DEPT REPORTS CLEANUP IS COMPLETED. HE DOUBLE WASH AREA AND REMOVED ALL CLEANUP MATERIAL IN A UNDER 50 DRUM. CLEANUP IS COMPLETED."

Remarks: "Discarded transformer was sitting in a tub at above location. It rained over the weekend and tub filled with water allowing material to overflow out of tub. Cleanup is in progress at the time of the call. Con Ed #147881."

All Materials:

Site ID:	299100
Operable Unit ID:	868770
Operable Unit:	01
Material ID:	508552
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0410262 / 2005-04-22
Facility ID:	0410262
Facility Type:	ER
DER Facility ID:	167996
Site ID:	335210
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-12-15
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-12-15
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-15
Spill Record Last Update:	2005-04-22
Spiller Name:	ERT DESK
Spiller Company:	Con Ed
Spiller Address:	Not reported
Spiller Company:	001

3RD AVE YARD (Continued) **S102239537**

Contact Name: ERT DESK
DEC Memo: "156594 12/15/04 1430HRS MICHELINO #60380 REPORTS VEHICLE #60380 LEAKED APPROX 50 GALLONS OF HYDRAULIC FLUID ONTO ASPHALT AT CABLE COMPOND AT 3RD AVE YD. AREA IS CORDONED OFF. IT IS CONTAINED NO SEWERS OR WATERWAYS AFFECTED NO FIRE OR SMOKE. CONES, DIAPERS, OIL ABSORBING PADS ARE PLACED IN AREA. TRANSPORTATION ON LOCATION TO MAKE REPAIRS TO VEHICLE THAT IS STILL LEAKING FROM DEFECTIVE HYDRALUIC PUMP ON VEHICLE. CLEANUP IN PROGRESS MORE INFORMATION TO FOLLOW. 12/15/04 1535HRS G.ARGYROPOULOS O.S CABLE REPORTS CLEANUP WAS COMPLETED ALL MATL PLACED IN 2-DRUMS MARKED AS NON-HAZARDOUS MATL. TRANSPORTATION IN PROGRESS MAKING REPAIRS TO VEHICLE. 12/15/04 1550HRS G.ARGYROPOULOS O.S CABLE REPORTS AMOUNT OF HYDRAULIC FLUID SPILL IS DOWN- GRADED TO APPROX 25 GALLONS. 12/15/04 1610 HRS WALKER #70226 O.S. TRANSPORTATION REPORTS VEHICLE LEAK HAS BEEN REPAIRED.NO LONGER LEAKING"
Remarks: "no to the 5 ?'s, clean up in progress. con ed #156594"

All Materials:
Site ID: 335210
Operable Unit ID: 1097291
Operable Unit: 01
Material ID: 577281
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: CON EDISON 3RD AVE YARD
Address: 222 FIRST ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1000131 / 2010-04-27
Facility ID: 1000131
Facility Type: ER
DER Facility ID: 361857
Site ID: 427053
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2010-04-04
Investigator: Con Ed Unassigned
Referred To: Not reported
Reported to Dept: 2010-04-04
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

3RD AVE YARD (Continued) **S102239537**

Date Entered In Computer:	2010-04-04
Spill Record Last Update:	2010-04-27
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 FIRST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"04/27/10 - See eDocs for Con Ed report detailing cleanup and closure. 4/5/10-Vought-Primary off-hours responder. Spill assigned to DEC Feroze as part of routine Con Ed portfolio review and possible closure. Initial EMIS Report (#220906) deleted from Proxy and filed into E-docs."
Remarks:	"Caller reporting 1 quart of diesel fuel to concrete. Clean up pending."

All Materials:

Site ID:	427053
Operable Unit ID:	1182735
Operable Unit:	01
Material ID:	2176917
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	CON EDISON 3RD AVE YARD (SPILL #2)
Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1000132 / 2010-04-22
Facility ID:	1000132
Facility Type:	ER
DER Facility ID:	361857
Site ID:	427054
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C5
SWIS:	2401
Spill Date:	2010-04-04
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2010-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-04
Spill Record Last Update:	2010-04-22

3RD AVE YARD (Continued) **S102239537**

Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 FIRST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"4/5/10-Vought-Primary off-hours responder. Spill assigned to DEC Feroze as part of routine Con Ed portfolio review and possible closure. Initial EMIS Report (#220907) deleted from Proxy and filed into E-docs. 4/22/10 - Austin - vehicle motor fuel tank leak - spill contained and cleaned up by Con Ed - see eDocs for more details - Spill closed - end"
Remarks:	"Caller reporting a spill of 1 quart to concrete. Clean up pending."

All Materials:

Site ID:	427054
Operable Unit ID:	1182736
Operable Unit:	01
Material ID:	2176919
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0910207 / 2010-02-16
Facility ID:	0910207
Facility Type:	ER
DER Facility ID:	361857
Site ID:	422955
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-12-15
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2009-12-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-15
Spill Record Last Update:	2010-02-16
Spiller Name:	ERT
Spiller Company:	CON ED

3RD AVE YARD (Continued) **S102239537**

Spiller Address:	222 FIRST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"12/15/09- Zhune spoke to Parick Hanluy from ERT. He said maintenance workers were working in multiple refrigeration units in one location. They noticed freon was release. A total of 57.9 L was realsed from 24 pieces of equipment. Austin - 2/16/10 - No furhter action needed - see eDocs for more info - spill closed - end."
Remarks:	"r22 release - 57.9 all freon #1 r5 release - 3.5 all freon #2 404a release - 4.0 all freon #3 cleanup in yard when airborne release"

All Materials:

Site ID:	422955
Operable Unit ID:	1178773
Operable Unit:	01
Material ID:	2172278
Material Code:	0050A
Material Name:	freon
Case No.:	Not reported
Material FA:	Other
Quantity:	57.90
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Site ID:	422955
Operable Unit ID:	1178773
Operable Unit:	01
Material ID:	2172280
Material Code:	0050A
Material Name:	freon
Case No.:	Not reported
Material FA:	Other
Quantity:	4.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Site ID:	422955
Operable Unit ID:	1178773
Operable Unit:	01
Material ID:	2172279
Material Code:	0050A
Material Name:	freon
Case No.:	Not reported
Material FA:	Other
Quantity:	3.50
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9912931 / 2002-02-27
Facility ID:	9912931
Facility Type:	ER

3RD AVE YARD (Continued) **S102239537**

DER Facility ID:	167996
Site ID:	263144
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-02-14
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-02-14
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-14
Spill Record Last Update:	2002-02-28
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	STEVE ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks:	"rain did cause some to go into sewer - truck #60399 cleanup in progress ref #129968"

All Materials:

Site ID:	263144
Operable Unit ID:	1091652
Operable Unit:	01
Material ID:	294791
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0002672 / 2001-09-25
Facility ID:	0002672
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263127
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4

3RD AVE YARD (Continued) **S102239537**

SWIS:	2401
Spill Date:	2000-06-02
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-06-02
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-02
Spill Record Last Update:	2001-10-11
Spiller Name:	CALLER
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 6/2/00 Transformer that was removed from a vault leaked 1gal oil on roadway (blacktop). Leak occurred when valve came off while moving transformer. Historical 3ppm PCB from 3/1/97. 6/5/00 On 6/2/00 sample returned 6ppm PCB. Drained transformer in Third Ave Yard. Removed 4 barrels of oil and 1 barrel of solid waste. Placed transformer in holding area for removal. Double washed blacktop area and placed tarp over it until result came back."
Remarks:	"WHILE TRANSPORTING TRANSFORMER IN YARD ABOVE MATERIAL WAS SPILLED. MATERIAL TO BE CLEANED UP AS 50/499 PCB. CON ED # 131682. PCB DONE 3/1/97 INDICATED 3PPM PCB'S.NO CALL BACK"

All Materials:

Site ID:	263127
Operable Unit ID:	824196
Operable Unit:	01
Material ID:	563335
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012324 / 2001-02-16
Facility ID:	0012324
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263129

3RD AVE YARD (Continued) **S102239537**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-02-16
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2001-02-16
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-16
Spill Record Last Update:	2001-05-22
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY E2MIS NOTES: 2 oz. dielectirc fluid leaked from recycling truck onto cement ground in 3rd Ave Yard. No sewers or waterways were affected and was cleaned by 0900hrs by Mr. Campanile as 50-499ppm. All diapers and PPE were discarded as 50-499ppm. This truck is used for draining and recycling. This leak came from a loose cap on hose."
Remarks:	"lose cap on a hose - 2 oz's was spilled and cleaned up ref #135557"

All Materials:

Site ID:	263129
Operable Unit ID:	834215
Operable Unit:	01
Material ID:	542597
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0202384 / 2002-08-21
Facility ID:	0202384
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263130
DEC Region:	2
Spill Cause:	Equipment Failure

3RD AVE YARD (Continued) **S102239537**

Spill Class:	C4
SWIS:	2401
Spill Date:	2002-06-05
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2002-06-05
CID:	198
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-05
Spill Record Last Update:	2002-08-21
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	CHARLIE MCCARTHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ E2MIS NOTES 143174 6/5/02 - 1100 D. SEGARRA - 15181 - TRANSP, REPORTS A SPILL OF APPROX 10 GALS OF HYDRAULIC FLUID FROM VEH # 60380 ONTO THE CONCRETE FLOOR OF THE SOUTH GARAGE IN 3RD AVE YD. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO SPILL. NO PRIVATE PROPERTY AFFECTED. CLEANUP COMPLETED AT 1115 HRS USING SPEEDY DRY & DIAPERS. CIG MCCARTHY NOTIFIED AT 1138 HRS. UPDATE BROKEN HOSE WAS REPAIRED. 13: 20 HRS "
Remarks:	"LEAK FROM A CON ED TRUCK #60380. MATERIAL CLEANED UP. CON ED # 143174."

All Materials:

Site ID:	263130
Operable Unit ID:	853225
Operable Unit:	01
Material ID:	520243
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9812500 / 2002-10-17
Facility ID:	9812500
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263142

3RD AVE YARD (Continued) **S102239537**

DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1999-01-09
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-01-09
CID:	246
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-09
Spill Record Last Update:	2003-12-09
Spiller Name:	STEVE ROMERO
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	STEVE ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis no. 122-350: P.CONTI #13108 OS TRANSPORTATION REPORTS THAT CONTRACTOR DIGGING TRENCH FOR INSTALATION OF NEW GAS PUMP LINES LEFT A SHEEN OF DIESEL FUEL [15FTX500FT] FROM HIS BACKHOE & BOBCAT. CONTAINED TO TRENCH NO SEWERS OR WATERWAYS AFFECTED. CLEANUP IN PROGRESS AT THIS TIME. UPDATE: A.HOWELL FLUSH OS REPORTS SHEEN IS A REIDUE FROM FRESH ASPALT THAT HAD JUST BEEN LAID BY CONTRACTOR CREWS ON LOCATION DIAPERING UP ALL THAT CAN BE DIAPERED."
Remarks:	"diesel fuel sheen 15 by 500 in trench where contractors were installing gas fuel line. Cleanup is in progress #122350"

All Materials:

Site ID:	263142
Operable Unit ID:	1073057
Operable Unit:	01
Material ID:	312783
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9900006 / 1999-04-02
Facility ID:	9900006
Facility Type:	ER
DER Facility ID:	167996

3RD AVE YARD (Continued) **S102239537**

Site ID:	263143
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-04-01
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-04-01
CID:	270
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-01
Spill Record Last Update:	2002-06-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Con Ed e2mis #123985: 4/1/99--0700hrs-g.anderson u/g mgr.reports a none employee jumped fence southernly entrance of north garage ,at 3rd ave yard and knocked over a barrel of oil spilling 5 gallons on concrete surface .on purpose, n.p.d. notified,cleanup in progress, contained no sewers or waterways effected ,-will call back within 2-hours when cleanup is completed. UPDATE: 4/1/99 - 0840 C. FERNANDEZ - O.S. - ENV. OPS., REPORTS CORRECTION TO ABOVE: NON-EMPLOYEE WALKED IN THROUGH 1ST STREET GATE AND RAN THROUGH NORTH GARAGE. AFTER KNOCKING OVER NUMEROUS LADDERS, HE KNOCKED OVER A 55 GALLON DRUM OF MOTOR OIL SPILLING APPROXIMATELY 10 GALLONS. CREWS IN GARAGE CONTAINED AND CLEANED SPILL. WITH ABSORBANT, AND DIAPERS NO SEWERS OR, WATERWAYS AFFECTED. INCIDENT IS CLOSED."
Remarks:	"unknown subj jumped a fence and spilled oil 123985 clean up in progeree"

All Materials:

Site ID:	263143
Operable Unit ID:	1078787
Operable Unit:	01
Material ID:	307150
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

3RD AVE YARD (Continued) **S102239537**

Click this hyperlink while viewing on your computer to access
14 additional NY SPILL: record(s) in the EDR Site Report.

A49 **CON EDISON - OTHER - SPECIFY 0000** **RCRA-LQG** **1019325713**
West **222 1 ST** **NYP004851131**
< 1/8 **BROOKLYN, NY 11217**
0.027 mi.
142 ft. **Site 48 of 83 in cluster A**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20160205
Actual: Handler Name:	CON EDISON - OTHER - SPECIFY 0000
19 ft. Handler Address:	222 1 ST
Handler City,State,Zip:	BROOKLYN, NY 11217
EPA ID:	NYP004851131
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	Not reported
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No

CON EDISON - OTHER - SPECIFY 0000 (Continued) **1019325713**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151010
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

CON EDISON - OTHER - SPECIFY 0000 (Continued) **1019325713**

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151010
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - OTHER - SPECIFY 0000
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A50 **THIRD AVE YARD** **NY Spills** **S121982344**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 49 of 83 in cluster A**

Relative: SPILLS:
Lower
Name: THIRD AVE YARD
Actual: Address: 222 1ST ST
19 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1114458 / 2012-05-10
Facility ID: 1114458
Facility Type: ER
DER Facility ID: 353674
Site ID: 462517
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: C4
SWIS: 2401

THIRD AVE YARD (Continued) **S121982344**

Spill Date:	2012-03-29
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2012-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-03-29
Spill Record Last Update:	2012-05-10
Spiller Name:	ERT
Spiller Company:	UNK SPILLER/ 3RD PARTY SPILL
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"5/10/12 - Austin - @ gal. anti-freeze spil to pavement/sewer near Con Ed facility, involving two non-Con Ed vehicles - FDNY put down Dryz-sorb, Con Ed removed the material - See eDocs files for further information - Spill closed - end"
Remarks:	"2 gallons lost to sewer from a mva , con ed is not the spiller. nrc 1007179"

All Materials:

Site ID:	462517
Operable Unit ID:	1212600
Operable Unit:	01
Material ID:	2210471
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A51
West
< 1/8
0.027 mi.
142 ft.

3 QT ANTI-FREEZE FROM COMPRESSOR **NY Spills** **S108982705**
222 FIRST ST. CON ED'S THIRD AVE YARD **N/A**
BROOKLYN, NY

Site 50 of 83 in cluster A

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	3 QT ANTI-FREEZE FROM COMPRESSOR
Address:	222 FIRST ST. CON ED'S THIRD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0711576 / 2008-05-12
Facility ID:	0711576
Facility Type:	ER
DER Facility ID:	342701
Site ID:	393082

3 QT ANTI-FREEZE FROM COMPRESSOR (Continued) **S108982705**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-02-02
Investigator:	gdbreen
Referred To:	Not reported
Reported to Dept:	2008-02-02
CID:	78
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-02
Spill Record Last Update:	2008-05-12
Spiller Name:	ETA
Spiller Company:	CON EDISON
Spiller Address:	THIRD AVENUE YARD
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"05/12/08 - See eDocs for Con Ed report detailing cleanup and closure. 209771. see eDocs"
Remarks:	"3 quarts spilled from a contractos air compressor onto asphalt. Clean up has been comp. No to five questions. 209771"

All Materials:

Site ID:	393082
Operable Unit ID:	1150056
Operable Unit:	01
Material ID:	2140619
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A52 **3RD AVE SERVICE YARD** **NY Spills** **S103274076**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 51 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual: Name:	3RD AVE SERVICE YARD
19 ft. Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9801450 / 2002-10-30
Facility ID:	9801450
Facility Type:	ER

3RD AVE SERVICE YARD (Continued) **S103274076**

DER Facility ID:	167996
Site ID:	263140
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-05-03
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-05-03
CID:	323
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-03
Spill Record Last Update:	2002-10-30
Spiller Name:	MIKE CEASAR
Spiller Company:	CON EDISON
Spiller Address:	1 IRVING PLACE
Spiller Company:	001
Contact Name:	MIKE CEASAR
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 5/22/98 e-mail from Con Ed ERT Lukshides: Spill cleaned by 2140 on 3 May 98 by double washing. e2mis no. 116-579: WHITNEY #37781 SPLICER REPORTS IN AVE YARD WHILE HE WAS PUTTING OIL FROM RESERVOIR INTO DRUMS HE SPILLED GAL OF OIL ON FLOOR HE CLEANUP SPILL (TREATED IT AS 50-499 PPM) AND DOUBLE WASH IT WITH SLIX. NO SEWER OR WATERWAYS AFFECTED. CLEANUP COMPLETED 2140 HRS"
Remarks:	"TREATED AT 50/500 ppm. WAS CLEANED UP."

All Materials:

Site ID:	263140
Operable Unit ID:	1059087
Operable Unit:	01
Material ID:	323388
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

A53 **3RD AVE YARD** **NY Spills** **S121981322**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 52 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	3RD AVE YARD
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0807096 / 2008-11-17
Facility ID:	0807096
Facility Type:	ER
DER Facility ID:	353674
Site ID:	404414
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-09-24
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2008-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-24
Spill Record Last Update:	2008-11-17
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"11/17/08 - Austin - minor spill on pavement - cleaned and closed - end"
Remarks:	"8 ounces of gas spilled from a trash can onto the blacktop."

All Materials:

Site ID:	404414
Operable Unit ID:	1161074
Operable Unit:	01
Material ID:	2152263
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A54 **CON EDISON** **NY MANIFEST** **S121967251**
West **222 FIRST ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 53 of 83 in cluster A**

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004703534
Facility Status:	Not reported
Location Address 1:	222 FIRST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004703534
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2014
Trans1 Recv Date:	12/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004703534
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773834JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S121967251**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A55 **CON EDISON TM439** **RCRA NonGen / NLR** **1007207059**
West **222 1ST ST** **NY MANIFEST** **NYP004036729**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 54 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20010103
Handler Name:	CON EDISON TM439	
Handler Address:		222 1ST ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004036729
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		IRVING PLACE RM300
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE RM300
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported

CON EDISON TM439 (Continued) **1007207059**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220509
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON TM439 (Continued) **1007207059**

Historic Generators:

Receive Date:		20010102
Handler Name:	TM439	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20010103
Handler Name:	CON EDISON TM439	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		Not reported
Recognized Trader Exporter:		Not reported
Spent Lead Acid Battery Importer:		Not reported
Spent Lead Acid Battery Exporter:		Not reported
Current Record:		Yes
Non Storage Recycler Activity:		No
Electronic Manifest Broker:		No

Receive Date:		20010101
Handler Name:	TM439	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON TM439 (Continued) **1007207059**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	222 1ST STREET
City,State,Zip:	NEW YORK CITY, NY 11215
Country:	USA
EPA ID:	NYP004036729
Facility Status:	Not reported
Location Address 1:	TM439-ST MACKS & FLATBUSH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004036729
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

A56 **3RD AVE YARD** **NY Spills** **S121981973**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 55 of 83 in cluster A**

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	3RD AVE YARD
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1008213 / 2017-06-08
Facility ID:	1008213
Facility Type:	ER
DER Facility ID:	353674
Site ID:	441688
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-11-05
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	2010-11-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

3RD AVE YARD (Continued) **S121981973**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-05
Spill Record Last Update:	2017-06-08
Spiller Name:	ERT
Spiller Company:	3RD AVE YARD
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"11/17/11 - changed Lead DEC from Feroze to O'Connell per discussion between Hussein and Austin. (JOC) 4/18/12 - telecon with Con Edison (Gonzalez) and First Environment (Farrell); discussed investigation work in process, proposed additional sampling points and DEC's prior comments on them. Geophysical is planned for Weds 4/25/12 on the southeast side of the fence (SE of MW-4) so the delineation may continue in that direction. No laboratory results back yet. Will be proceeding with points S-9 and S-11 via sonic drill rig. MW-3 was not installed yet; will decide on its location based on field results from boring S-21. Will move S-24 to other side of fence, add addtional points. Will add additional point between S-7 and S-24 on NW of fence. FE will provide updated drawings to show proposed locations as discussed. (JOC) 4/26/12 - updated drawing with proposed locations received 4/20/12; sent comments on 4/20: I looked at the figure you provided. I just noticed that the DW labeled borings are mostly not shown, and most of them showed little impact. Based on the figures from FE's Nov. 2011 report, it looks like DW-2 is about where proposed S-25 is. Please check this; if it is right there, S-25 should not be needed. One other item to check; the location shown for TW-1 in the figures in the Nov. 2011 report is much further up into the corner of structure labeled shed . Please confirm that the location shown for TW-1 on these recent figures is accurate. I attached the figure you sent me, and I added a bubble around the area that seems to have generally shown impacts to this point. I changed the file name to try to avoid confusion. I drew the bubble extending to the other side of the fence from MW-4 based on its relatively high field indicators of contamination. Note that the locations of S-24 and S-26 would not zero it out even if they show no impacts. It might be best to wait for Naeva to do their work next week, see if they find anything worth looking at, and if there's nothing of interest to have a point more on an extension of that line of SB-1 to MW-4. If you are working on an assumption that there is some area of impact there on the other side of the fence from MW-4 please advise, and we can work with that assumption. Has the plan for S-9 changed since TP-8 went to the extent that it did? Also, as we discussed on Wednesday I understood S-11 was going to be moved to the location of TP-4. Please confirm. I have no comments on the locations for S-21, S-22, S-23, S-28. I appreciate your adding S-27, but please advise on the location of TW-1 as above. If TW-1 was further up in the corner as shown in earlier figures, I might rather have S-27 where TW-1 is shown here. Can FE provide a little more info characterizing the impacts noted in TP-8, and summaries for the surrounding points (S-10, TP-6, S-16) to make sure we're all comfortable on the delineation on that side? I'm concerned over the described vertical extent of impacts there (7 to 12') which is larger than noted in most

3RD AVE YARD (Continued) **S121981973**

other locations. - responses from FE and Con Ed on 4/23/12: they advised that TW-1 is where shown on recent drawings; DW-2 was closer to location of proposed s-28; they will install S-9 next to TP-8; - held telecon among Con Ed and FE on 4/23/12 to discuss the comments/responses; included that locations east of the fence (SE of MW-4 should be decided after geophys completed); revised figure sent by FE based on telecon received 4/23/12; approved on 4/24/12. Geophys and pre-clearing completed on 4/25/12. Went to site on 4/26: from field observations S-27 was clean, rest on east side showed impact, locations SE of fence (s-24 and S-26 showed impact (S26 showed relatively more than S24, but both were less than MW-4); S-9 showed impact similar to TP-8; S-25 showed impact. Driller de-mobilized. Agreed that at this point it would be best to get the lab data together, get the boring logs completed, and then get together to discuss what additional delination is needed. (JOC) 5/21/12 - met at site with Con Edison (Mariela Gonzalez and Nick Borgia) and First Environment (Meghan Farrell); Con Edison presented data summary tables for VOCs and SVOCs in soil samples and a figure showing the totals; based on this data, additional delineation needed on north and northeast of area of concern; paced off MW-3 as 6 feet from the building and S-27 as 7 feet from the building, so there is not much open space left to work with; there is ample space on the east side and on the other side of the fence which separates this area from the parking lot (this area had already been assessed by Naeva via geophysics and found nothing inside the storm line running along the end of the last row of parking spaces against the fence; they are still waiting on the chromatogram from TestAmerica, and the results of Meta's forensic fingerprint work; the surveyor was onsite today but could not conduct the well elevation surveying due to the weather (thunder/lightning in area) but expects it should be done by the end of the week. Among the items requested from Con Edison were to pull together information on the storm systems within the yard; to go through the data to see what sampling points might be able to be parsed out as exceedances due to fill rather than from the product/plume identified; to overlay the Sanborn maps over the site figure with the data points; to try to get more info from Con Edison CM regarding the depths of the foundations across the site from the former buildings (some had basements); to put together cross sections which show the borings/data. When all of the above is pulled together, we will reconvene to determine what additional delineation is needed. While at the site, we walked around the demo/dry well area; it had been very heavily raining earlier in the morning. Even though the area is covered with blue stone, there are areas of standing water. There are at least five storm drains in the area which are connected together and were taking on from from the surface; this system also takes storm water from the roof of the building labeled on site drawings as shed . These all seem to discharge to dry wells that had been installed in an area just at the south end of the area of concern (basically, within the area of the earlier sampling points DW-1, DW-5 and DW-8. We discussed how this large inflow of storm water to the subsurface will have an effect on the groundwater flow. I paced off MW-7 being ~20 feet south(measured along a line parallel to 3rd Avenue) of the north roof line of the building across 3rd Avenue, and the southwestern-most dry well being ~42 feet north of MW-7 along a line parallel to 3rd Avenue(it is east of MW-7 as well as north). (JOC) 9/28/12 received 9/21 email from Con Edison's consultant: greater than greater than greater than Daniel D.

3RD AVE YARD (Continued) **S121981973**

Lattanzi 9/21/2012 4:00 PM greater than greater than greater than Joe, I hope all is well. Con Edison and First Environment are prepared to continue the remedial investigation (RI) activities at the above referenced site. As such, First Environment is proposing to submit a letter report to the NYSDEC. This letter report will summarize the RI activities completed to date at the Site, and provide a scope-of-work to delineate the extent of contamination in soil and groundwater. Since First Environment is only proposing additional soil borings and monitoring wells, these tasks remain consistent with the previously approved November 2011 Remedial Investigation Work Plan. Once the remedial investigation is complete (i.e., extent of contamination is identified), First Environment will submit a complete Remedial Investigation Report/Remedial Action Work Plan to the NYSDEC. The report will summarize all remedial investigation activities conducted at the Site, and will provide a site-specific remedial strategy to address residual soil and groundwater contamination. In order to effectively proceed, please confirm that this approach is acceptable --------- responded as below: greater than greater than greater than Joseph O'Connell 9/24/2012 8:27 AM greater than greater than greater than Hi Dan and Mariela, I looked back through my files/notes on this. I think what I was expecting at this point based on the last meeting among Mariela, Meghan and myself was cross-sections, a revised plan-view figure and an attempt to differentiate fill-derived SVOCs. I don't think I need a report other than what you feel you might need to explain any figures or SVOCs. If you think you have some other/new information to discuss that's fine too, but I don't think there's a need to put together a summary type report at this point. I think we can continue as we had been, and propose new delineation borings/wells on a figure, and we'll discuss/agree on it before implementation. ---------- received response same day that they will proceed as requested (JOC) 11/13/12 - received email response from First Environment with figures and tables, and proposed additional investigation locations - under review (JOC) 12/7/12 - Revised figures sent from First Environment on 11/28 responding to my email of 11/14 responding to the above; telecon with them and Con Edison on 11/29; additional soil borings added as discussed, understood that specific locations may be slightly modified based on clearing and investigation findings; discussed that gw flow direction as shown was inconsistent with what had been the case in the past, requested additional rounds of elevation monitoring, to be observant of rainfall at site to see effects on gw flow direction from dry wells; work may proceed as shown, may be asking for additional gw monitoring downgradient of well MW-3 based on established flow direction (JOC) 12/14/12 - received updated proposed site boring location figure on 12/11 based on geophysical work; some proposed locations were moved further north and east than they had been due to subsurface utilities; I requested that the utilities identified by the geophysical work be added to the drawing; received revised updated figure 12/13 with the utilities shown and additional revision to some of the boring/well locations. OK to proceed. Clearing activities ongoing. Planned schedule is to start boring work week of 12/17. (JOC) 1/30/13 - received updated summary information about the last round of step out borings; in short, the area of contamination has not yet been completely delineated. Agreed with Con Edison PM that before considering what additional investigation might be appropriate, Con Edison will have their consultant do some additional

3RD AVE YARD (Continued) **S121981973**

groundwater elevation monitoring to better understand flow direction and will put together a summary report for the investigation conducted to date for the entire area. (JOC) 2/15/13 - received email from FE; wanted to confirm that report can come by email. I called him (D. Lattanzi, FE); agreed he will try to send the summary report via email, if it is too large and does not go through, he will send an CD that night, which should be by 2/19. I added that I might ask for figures in print if I find them too detailed/complicated to review in pdf format. (JOC) 5/3/13 - reviewed the summary report and sent comments/items for discussion to Con Edison via email 4/10/13; meeting was scheduled for 4/24 but was cancelled by Con Edison. (JOC) 7/8/13 - had received confirmation from Con Edison that they would be proceeding with expanding the investigation scope to a larger area; received notice from member of the public about 55 gallon drums at the 3rd Avenue Yard facility, which upon discussion were described as being stored within the fenced area on the property near the corner of 3rd Avenue and 3rd Street. Spoke with Con Edison PM; the drums from pre-/clearing and/or investigation activities around the perimiter are being brought into the yard for storage in that area of the yard. (JOC) 2/27/14 - discussed with Con Edison PM Gonzalez 2/26. Consultant was sampling additional groundwater wells around sidewalk, that report with all the information was then going to be prepared for all the investigation completed. (JOC) 3/30/16 - received report on investigation completed by Con Edison in January 2016; report describes site history which shows all of the site was marshland associated with the historic Gowanus Creek and the majority of the site was the location of a former mill pond; it is believed that the property was filled at some point in the late 1800s to approximately its current grade; large area of this fill material is contaminated with what was identified through laboratory analysis (Meta Environmental) that the PAH distributions in most of the samples were similar to each other and to tar reference samples in META s archive from the carbureted water gas process , while the NAPL sample from well MW-4 contained a tar-like material similar to that found in the soil samples and also contained a substantial petroleum-derived component that appeared to be weathered gasoline or a similar material; one sample (MW-C10D 33-35'bg) contained a pyrogenic PAH pattern more similar to combustion-derived sources and coal carbonization source; PAH impacted soils were encountered between 7.5 and 17 ft bgs in the Demo Area with the greatest total PAH concentration of 18,358 mg/Kg detected in S-38 from 10- to 10.5 ft bgs in the central/western portion of the site; Subsurface soil PAH impacts in the area west of the southern end of the Operations and Transportation Building were encountered between 9 and 29 ft bgs with the greatest total PAH concentration of 14,590 mg/Kg detected in D12 from 12 to 13 ft bgs. PAH impacted soil was encountered between 16 and 20 ft bgs in the South UST Area with the greatest total PAH concentration of 2,500 mg/Kg detected in SB D1 at 16 ft bgs. In addition, separate work as part of parking area re-paving identified PCBs in shallow soils (see spill 1502673) up to 431 mg/kg in one sample and 10 mg/l TCLP lead in one composite sample. The site conditions are being discussed internally within DEC to determine a course of action. (JOC) 7/14/16 - Department staff met with Con Edison on May 10, 2016 and July 8, 2016 to discuss Con Edison's 3rd Avenue Yard overall and how to move forward with a comprehensive approach. Anticipate feedback from Con Edison shortly. (JOC) 11/18/2016 Austin This spill report is being transferred from Joe O

3RD AVE YARD (Continued) **S121981973**

Connell to Jennifer Kann - end. 06/05/17: J.Kann - as per Jeff spill reassigned to Kumar. 6/8/17 - Haggerty: Closed/consolidated under Site C224245. Further investigation and remediation will be conducted under the BCP."

Remarks: "Test pit shows 1 part per million PCB in soil. Clean up pending"

All Materials:

Site ID:	441688
Operable Unit ID:	1192235
Operable Unit:	01
Material ID:	2187471
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A57 **3RD AVE YARD CON ED** **NY Spills** **S103274365**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 56 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	3RD AVE YARD CON ED
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9801934 / 1998-06-12
Facility ID:	9801934
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263141
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1998-05-14
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-05-14
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-14
Spill Record Last Update:	2002-10-30
Spiller Name:	RICHARD ROACH
Spiller Company:	3RD AVE YARD CON ED

3RD AVE YARD CON ED (Continued) **S103274365**

Spiller Address:	222 1ST ST
Spiller Company:	001
Contact Name:	RICHARD ROACH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 6/11/98 e-mail from Con Ed ERT Dan Shah: product similar to dielectric fluid (< 1ppm PCB); vendor's dumpster overflowed the liquid; clean-up completed (5/14/98 2100); double washed asphalt and catch basin. e2mis no. 116-832: 5-14-98 10:30HRS E.EBERT REPORTS, FOUND 4 GAL OF UNKNOWN OIL ON PAVEMENT. AREA IS NOT CONTAINED, & SEWERS ARE AFFECTED. SAMPLE WAS TAKEN ON A 4-HR PRIORITY. ENV. STOP TAG # 1615 WAS PLACED. 5-14-98 11:30HRS E. EBERT REPORTS, PRIVATE VENDOR WHO PICKED UP 5 YD PAPER DUMSTER, WITNESS MS. ANNE MARIE OF PROPERTY PROTECTION CLAIMS SHE SAW VENDORS TRUCK OVERFLOW WITH PRODUCT WHEN DUMPSTER PICKED UP. 5/14/98 14:00HRS R. JAMES REPORTS, CHECKED ADJACENT DRAINS AND THERE IS NO EVIDENCE OF OIL IN DRAINS. AT THIS TIME CLEANING WILL BEGIN ON ASPHALT AROUND BASIN ONCE PCB RESULTS COME BACK. 5-14-98 20:15HRS FERNANDEZ REPORTS, DOUBLED WASHED- BLOCKED OFF & DOUBLED WASHED CATCH BASIN. CLEANED BOTTOM OF DUMPSTER REMOVED TAG#16115."
Remarks:	"unknown were it came from or what product is cleanup is taking place now"

All Materials:

Site ID:	263141
Operable Unit ID:	1062470
Operable Unit:	01
Material ID:	323842
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A58 **222 1ST STREET** **NY Spills** **S121986827**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 57 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:

Name:	222 1ST STREET
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9415797 / 1998-02-13
Facility ID:	9415797
Facility Type:	ER
DER Facility ID:	167996
Site ID:	201957
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-03-06
Investigator:	SIGONA

222 1ST STREET (Continued) **S121986827**

Referred To:	Not reported
Reported to Dept:	1995-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-04-12
Spill Record Last Update:	1998-02-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"3 QTS. LEAKED OUT OF A CABLE"

All Materials:

Site ID:	201957
Operable Unit ID:	1009235
Operable Unit:	01
Material ID:	370974
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Site ID:	201957
Operable Unit ID:	1009235
Operable Unit:	01
Material ID:	370975
Material Code:	0020B
Material Name:	cable oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

A59 **CON ED** **NY MANIFEST** **S120957800**
West **222 1 ST** **N/A**
< 1/8 **BROOKLYN, NY 11217**
0.027 mi.
142 ft. **Site 58 of 83 in cluster A**

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CON ED
Address:	222 1 ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004851131
Facility Status:	Not reported
Location Address 1:	222 1 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004851131
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2015
Trans1 Recv Date:	10/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004851131
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245469JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S120957800**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5127
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A60 **CON EDISON** **NY MANIFEST** **S117537870**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 59 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004704771
Facility Status:	Not reported
Location Address 1:	222 1ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004704771
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117537870**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/10/2014
Trans1 Recv Date:	12/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004704771
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773783JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A61 **THIRD AVENUE YARD** **NY Spills** **S121981812**
West **222 1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 60 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	THIRD AVENUE YARD
Address:	222 1ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1000930 / 2010-05-21
Facility ID:	1000930
Facility Type:	ER
DER Facility ID:	388530
Site ID:	433623
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C5
SWIS:	2401
Spill Date:	2010-04-23
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2010-04-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-23
Spill Record Last Update:	2010-05-21
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	222 1ST STREET
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"04/23/10- Zhune spoke to Dennis from ERT 212-580-8383. He said the hydraulic liquid hose broke from a Con-ED vehicle spilled 6 gallons of liquid onto the asphalt. Spill is being cleanedup. No drain, no soil impacted. 5/21/10 - Austin -Contained and cleaned up by Con Edison - see eDocs for further info - spill closed - end"
Remarks:	"1640 THE CALLER ADVISED DISPATCH THE SPILL IS CONTAINED AND IN THR PROCESS OF CLEAN UP. NO WATER WAYS AFFECTED."

All Materials:

Site ID:	433623
Operable Unit ID:	1184498
Operable Unit:	01
Material ID:	2178766
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	Not reported

THIRD AVENUE YARD (Continued) **S121981812**

Oxygenate: Not reported

A62 **CON ED** **NY Spills** **S111159307**
West **222 FIRST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 61 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON ED
Address:	222 FIRST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1104942 / 2011-09-07
Facility ID:	1104942
Facility Type:	ER
DER Facility ID:	361857
Site ID:	452560
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-07-31
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-07-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-31
Spill Record Last Update:	2011-09-07
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"9/7/11 - Austin - 8 oz - 1/2 gal. leak from Con Ed bucket truck hydraulic hose - Con Ed contained and cleaned up the spill - See eDocs for further details in the EMIS report - Spill closed - end"
Remarks:	"vehicle number 50823 - cleanup pending"

All Materials:

Site ID:	452560
Operable Unit ID:	1202742
Operable Unit:	01
Material ID:	2199346
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50

CON ED (Continued) **S111159307**

Units: G
Recovered: Not reported
Oxygenate: Not reported

A63 **222 FIRST STREET** **NY Spills** **S121987519**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 62 of 83 in cluster A**

Relative: SPILLS:
Lower
Name: 222 FIRST STREET
Actual: Address: 222 FIRST STREET
19 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9706833 / 1997-09-10
Facility ID: 9706833
Facility Type: ER
DER Facility ID: 167996
Site ID: 263577
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1997-09-08
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1997-09-08
CID: 207
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-09-08
Spill Record Last Update: 2003-02-24
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: JOHN DEVOTI
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 9/9/97, 1643 hrs. called EH&S, spoke with Paul Carbone. According to notes taken by Glenn Newell, approximately 2 gallons got into an on-site catch basin. DEP (Anthony Henry) resp[onded to the site. Con Ed vac'ed out the catch basin and a service box, but no oil got to the sewer. The remaining 98 gallons spilled on the parking area and was vac'ed up by Con Ed. E2MIS 111222 8/9/97-2010HRS--D.WALKER #70226 OS TRANSPORTATION REPORTS THAT APROX 100 GALLONS OIL AND WATER FROM VEH.60505 LEAKED ONTO THE ROADWAY IN THE 3RD AVE YARD . IT IS BELIEVED THAT APROX 2 GALLONS OF LIQUID ENTERED TWO CATCH BASINS IN THE THIRD AVE. YARD. THE CLEANUP IS ON GOING AND NO SOLID DEBRIS ENTERED THE CATCH BASIN. MR WALKER HAS DETERMINED THAT NO LIQUID ENTERED THE SEWER PIPES IN EITHER CATCH

222 FIRST STREET (Continued) **S121987519**

BASIN. ----------G DONATONE---- UPDATE 21:40HRS 9/8/97 DEP A.HENRY IS ON LOCATION & ERT NEWELL IS ON LOCATION.....AT 23:20HRS 9/8/97 SUPERVISIOR WALKER REPORTS THAT THE CLEAN UP IS COMPLETE USING A FLUSH TRUCK, DIAPERS AND ABSORBANT BOTH CATCH BASINS WERE CLEANED UPDATE.- 9-SEPT-1997, 10:00 AM, MANAGER M.RODRIGUEZ MEET ERT GLENN NEWELL AND DEP REPR. A. HENRY AT 2140. ALL THREE CATCH BASINS STARTING AT 3RD STREET WERE OPENED AND CLEANED BY FLUSH AT THE REQUEST OF DEP AND ERT. 23:20HRS CLEANUP COMMPLETED. CORRECTION: THE LIQUID THAT LEAKED FROM VEHICLE 60505 (VACTOR) WAS FROM INSIDE THE DEBRIS TANK OF THE VEHICLE. THE CONTENTS OF THIS TANK IS THE DEBRIS WE PICK UP FROM UNDERGROUND ELECTRICAL STRUCTURES. THESE VEHICLES DO NOT AT ANY TIME PICK UP OIL. THE INCIDENT SHOULD NOT SAY OIL AND WATER, BUT DIRTY WATER AND LEAD DEBRIS. MJR - 77809 THIS INCIDENT IS CLOSED."

Remarks: "FLUSH TRUCK FOR SEWERS WHILE IN OPERATION ACCIDENTLY SPILLED PRODUCT - ALL CONTAINED - POSS SEWER CONTAINATION - NOT VERIFIED"

All Materials:

Site ID:	263577
Operable Unit ID:	1053056
Operable Unit:	01
Material ID:	332420
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	100.00
Oxygenate:	Not reported

A64 **3RD AVE FLUSH TRUCK** **NY SWF/LF** **S117269722**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 63 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SWF/LF:

Name:	3RD AVE FLUSH TRUCK
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY 11215
Flag:	INACTIVE
Region Code:	2
Phone Number:	7186664678
Owner Name:	Consolidated Edison Co of NY Inc
Owner Type:	Private
Owner Address:	4 Irving Place; Rm 15 NE
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Email:	Not reported
Owner Phone:	2124602278
Contact Name:	Bailey Tyler
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	TylerB@coned.com
Contact Phone:	2122034942

3RD AVE FLUSH TRUCK (Continued) **S117269722**

Activity Desc:	Transfer station - permit
Activity Number:	[24T]
Active:	No
East Coordinate:	585750
North Coordinate:	4503197
Accuracy Code:	Not reported
Regulatory Status:	None
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Bailey Tyler
Operator Type:	Private
Laste Date:	Not reported

A65 **3RD AV YARD** **NY Spills** **S103272845**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 64 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	3RD AV YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0007860 / 2001-12-14
Facility ID:	0007860
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263128
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-10-04
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-10-04
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-04
Spill Record Last Update:	2001-12-14
Spiller Name:	CALLER
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #133777 Notes: 10-4-00 1/2 pint dielectric fluid on 20gal water in a pan containing a transformer in the cable

3RD AV YARD (Continued) **S103272845**

compound of Third Ave. Yard. Fluid came from a cut feeder cable on the transformer and was immediately sealed with shrink caps. Sample returned <1ppm PCBs. 10-6-00 Cleanup completed by double washing with slix. "

Remarks: "1/2 PINT ON 20GAL OF WATER IN CATCH PAN FOR RETIRED TRANSFORMER - TRANSFORMER #1216206 - SAMPLE TAKEN - CASE #133777"

All Materials:

Site ID:	263128
Operable Unit ID:	828519
Operable Unit:	01
Material ID:	545385
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AV YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9614742 / 1997-03-25
Facility ID:	9614742
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263136
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-03-21
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1997-03-21
CID:	323
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-21
Spill Record Last Update:	2003-04-01
Spiller Name:	PAT MCHUGH
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	PAT MCHUGH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Maria Rodriguez - manager of Third Ave. Yard (718) 802-5629 3/25/97, 1224 hrs: spoke with Rodrigues - spill was cleaned,

3RD AV YARD (Continued) **S103272845**

treated as 50-400 ppm PCBc. Referred me to Bob Weiner's group (Environmental Affairs). E2MIS 105506 R.TESTA #60943 A.MECH TRANSPORTATION REPORTS IN 3 AVE YARD SOUTH GARAGE WALL OF MECH SHOP A UNKNOWN SUBSTANCE LEACHING THRU FLOOR OPP FLUSH TRUCK PITS. LIQUID AFFECTING A 12' BY 4' AREA OF CEMENT. NO SEWERS OR WATERWAYS AFFECTED. SAMPLE TAKEN FOR PH & ID. AREA IS ROPED OFF AND OIL ABSORENT PLACED AROUND AFFECTED AREA. INCIDENT TURN INTO P.CRESAI , J.SABO , S, ZALLOUGHI , B.WEINER. K.BAROUCH LOCATED IN TIRE CAGE SEEPING WATER CONTAINED BY BALONIES A SMALL STREAM , FLUSH CREW TO SUIT UP AND CLEAN AND PROTECT AREA FOR WEEKEND. CIVIL ENGNEERING WILL BE CONTACTED ON MONDAY IF NECESSARY TO ASSESS. WALL. TEST FOR CONTENT WILL BE TAKEN ON MONDAY AND A DYE TEST WILL BE DONE TO LOCATE LEAK THRU WALL FLUSH CREW TO CLEAN UP AREA. CIG MCHUGH NOTIFIED 1750 HRS UDATE / CORRECTION; THE CLEANUP WAS ACCOMPLISHED BY DOUBLE WASHING THE AFFECTED AREA OF THEN UNKNOWN LIQUID SUBSTANCE. THERE WAS NEVER A DETECTION OF ANY PETROLEUM BASED PRODUCTS IN THE AREA OF THE THEN UNKNOWN SPILL. THE DOUBLE WASH AND PROTECTIVE GEAR WAS A POSSIBLE HAZARD PRECAUTION ACTION. CHEM LAB SUPERVISOR, W.MURPHY ON 3-24-97, ADVISED BROOKLYN ENVIRONMENTAL THAT THE SAMPLE PRVIDED TO CHEM LAB WAS, IN FACT, WATER BASED AND NO OIL ID WAS POSSIBLE AS THERE WAS NO DETECTABLE OIL PRESENT. CHEM LAB SUPERVISOR THEN SUBMITTED THE SAMPLE TO THEIR SPECIAL ANALYSIS GROUP FOR PH AND WHATEVER OTHER ANALYSIS THEY COULD PERFORM. ON 3-25-97 CHEM LAB REPORTED ON THE SPECIAL TESTING RESULTS. THE ANA LYSIS INDICATES THIS WAS A NON HAZARDOUS LIQUID. FURTHER, AFTER CONSULTING WITH SEVERAL ENVIRONMENTAL AND HEALTH AND SAFETY PERSONNEL, THE CONSENUS IS THAT THIS LIQUID IS CONSISTENT WITH RUSTY WATER AND THE TRACE AMOUNTS OF MINERALS / ELEMENTS FOUND ARE CONSISTENT WITH WHAT WOULD BE EXPECTED TO BE FOUND IN THIS WORK ENVIRONMENT. THE REFERENCE LAB SEQUENCE REPORT NUMBER IS 97-03430-001. THE FOUNDATION WALL THAT ALLOWED THE WATER TO ENTER TO THE GARAGE HAS BEEN EXPOSED AND FACILITIES MANAGEMENT IS IN PROGRESS OF FIXING THE CRACKS IN THE WALL TO ENSURE THAT THE WATER DOSEN'T ENTER THE TRANSPORTATION AREA. LAZ #04425...UPDATE 4/2/97 FACILITIES MGT. REPORTS THAT THE WALL HAS BEEN PROPERLY SEALED. THIS WILL PREVENT ANY LIQUIDS FROM PASSING THROUGH."

Remarks: "THERE IS AN UNKNOWN FLUID LEACHING UP FROM THE CEMENT FLOOR, INVESTIGATING AT THIS TIME."

All Materials:

Site ID:	263136
Operable Unit ID:	1042420
Operable Unit:	01
Material ID:	339846
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AV YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9603338 / 1996-08-22
Facility ID:	9603338

3RD AV YARD (Continued) **S103272845**

Facility Type:	ER
DER Facility ID:	167996
Site ID:	276609
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-06-10
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-06-10
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-10
Spill Record Last Update:	1998-04-24
Spiller Name:	LISA PRIMEGGIA
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"veh leaked 1 quart of antifreeze onto asphault"

All Materials:

Site ID:	276609
Operable Unit ID:	1030884
Operable Unit:	01
Material ID:	349593
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

A66 **3 AVE YARD** **NY Spills** **S107522901**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 65 of 83 in cluster A**

Relative: SPILLS:
Lower

Name:	3 AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0513083 / 2006-04-21

Actual:
19 ft.

3 AVE YARD (Continued) **S107522901**

Facility ID:	0513083
Facility Type:	ER
DER Facility ID:	309673
Site ID:	359500
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-02-13
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-02-13
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-13
Spill Record Last Update:	2006-04-21
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON 3RD AVE YARD
Spiller Address:	222 FIRST STREET
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"162957. 2/13/06 0955HRS. L. CLARK #05374 MC&S REPORTED A LEAK OF APPROX. 1 GAL. DIESEL FUEL FROM A PORTABLE SPACE HEATER ONTO SNOW AND SOIL. NO SMOKE, FIRE OR INJURIES INVOLVED. NO SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. SPILL WAS CONTAINED AND PADS WERE PUT DOWN. THE TEMPORARY HEATER WAS IN A PLASTIC LINED CONTAINMENT BUILT ON TOP SOIL AND THE SPILL OCCURED WHILE RE-FILLING THE HEATER. MOST OF THE FUEL FELL ONTO SNOW WHICH IS BEING SHOVELLED AND PLACED INTO A DRUM. A SMALL, UNDETERMINED AMOUNT WAS LEAKED UNTO THE SOIL BEYOND THE PLASTIC AND THAT IS BEING SHOVELLED AND PLACED INTO A DRUM. CLEAN UP IS IN PROGRESS. J. MASON Update 4/21/06 Spill closed based on report in eDocs. (SKA)"
Remarks:	"clean up in progress, coned #162957"

All Materials:

Site ID:	359500
Operable Unit ID:	1116708
Operable Unit:	01
Material ID:	2107156
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A67 **LEAK FROM VEHICLE IN CON ED 3 AVE YARD** **NY Spills** **S107657920**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 66 of 83 in cluster A**

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	LEAK FROM VEHICLE IN CON ED 3 AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514637 / 2006-06-14
Facility ID:	0514637
Facility Type:	ER
DER Facility ID:	167996
Site ID:	361408
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-22
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-03-22
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-22
Spill Record Last Update:	2006-07-17
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON 3RD AVE YARD
Spiller Address:	222 FIRST STREET
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"06/14/06 - See e-docs for Con Ed report detailing cleanup and closure. 163461. 3-22-06 10:31HRS L. CLARK (MAINT SER) 05374 REPORTS, NOTICED A 25' TRAIL OF UNKNOWN OIL ON SOIL IN CONSTRUCTION SITE OF 3RD AVE YARD AND A 20' LEADING INTO PAVEMENT IN STREET LEFT BY UNKNOWN VEHICLE AND STOPS. AT THIS TIME AREA IN STREET IS CONTAINED AND OIL IN DIRT WILL BE HANDLED IN PROPER MANNER. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED AND NO INJURIES WERE RELATED TO SPILL WITH NO WEATHER CONDITIONS CONTRIBUTING TO THE HAZARD OF THE SPILL. CLEANUP EXPECTED TO BE CLEANED UP SHORTLY. S. PACE 49874."
Remarks:	"no to 5 questions: 4 ounces spilled: could be from a contractor: coned # 163461"

All Materials:

Site ID:	361408
Operable Unit ID:	1119559
Operable Unit:	01
Material ID:	2108993
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported

LEAK FROM VEHICLE IN CON ED 3 AVE YARD (Continued) **S107657920**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A68
West
< 1/8
0.027 mi.
142 ft.

CON EDISON GARAGE **NY Spills** **S107788598**
222 FIRST STREET **N/A**
BROOKLYN, NY

Site 67 of 83 in cluster A

Relative:
Lower

Actual:
19 ft.

SPILLS:

Name:	CON EDISON GARAGE
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0602266 / 2006-10-05
Facility ID:	0602266
Facility Type:	ER
DER Facility ID:	314924
Site ID:	364698
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-05-31
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-05-31
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-31
Spill Record Last Update:	2006-10-05
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON GARAGE
Spiller Address:	222 1ST STREET
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"10/05/06 - See e-docs for Con Ed report detailing cleanup and closure. 200315. see eDocs."
Remarks:	"1 QUART ON 60 GALLONS OF WATER CLEAN UP PENDING LAB RESULTS: NO TO 5 QUESTIONS: CONED # 200315"

All Materials:

Site ID:	364698
Operable Unit ID:	1122719
Operable Unit:	01
Material ID:	2112197
Material Code:	0066A

CON EDISON GARAGE (Continued) **S107788598**

Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A69 **VEHICLE 60722 LOST HYDRAULIC FLUID** **NY Spills** **S107658059**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 68 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	VEHICLE 60722 LOST HYDRAULIC FLUID
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514814 / 2008-01-10
Facility ID:	0514814
Facility Type:	ER
DER Facility ID:	167996
Site ID:	361624
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-27
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-03-27
CID:	75
Water Affected:	N/A
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-27
Spill Record Last Update:	2008-01-10
Spiller Name:	ERT DESK
Spiller Company:	CON ED YARD
Spiller Address:	222 1ST STREET
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"01/10/08 - See eDocs for Con Ed report detailing cleanup and closure. 163530. 3/27/06 0615 HRS. E. WILLIAMS #56346 FLUSH OPS SUPV REPORTS FINDING APPROX 1 GAL OF HYDRAULIC FLUID LEAKED ON TO ASPHALT FROM VEHICLE #60722. ABSORBENT WAS IMMEDIATELY PLACED ON THE SPILL AND THE TRUCK WAS NOT OPERATING AT THE TIME OF THE SPILL. NO FIRE, SMOKE,OR INJURIES INVOLVED & NO SEWERS, WATERWAYS OR PRIVATE PROPERTY WAS AFFECTED. TRANSPORTATION DEPT HAS BEEN NOTIFIED FOR REPAIRS BUT IT IS NOT KNOWN WHEN A TOW WILL BE AVAILABLE. CLEAN UP CANNOT BE COMPLETED UNTIL THE TRUCK IS MOVED. J. MASON "

VEHICLE 60722 LOST HYDRAULIC FLUID (Continued) **S107658059**

Remarks: "1 gal hyd oil from a truck onto asphalt-cleanup pending but contained n-wayer affetcted Con ED # 163530"

All Materials:

Site ID:	361624
Operable Unit ID:	1119754
Operable Unit:	01
Material ID:	2109197
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

A70 **THIRD AVENUE YARD** **NY BROWNFIELDS** **S120706183**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
142 ft. **Site 69 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

BROWNFIELDS:

Name:	THIRD AVENUE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	533255
Acres:	6.770
HW Code:	C224245
SWIS:	2401
Town:	New York City
Record Added Date:	10/05/2016
Record Updated Date:	03/21/2022
Update By:	HMDUDEK
Site Description:	"Location: The BCP site is the Con Edison Third Avenue Yard Service Center located in an urban area in Brooklyn, NY. The Property occupies a city block (approximately 6.77 acres) and is bounded to the north by 1st Street, to the south by 3rd Street, to the west by 3rd Avenue, and to the east by 4th Avenue. Current Site Features: The Property is entirely covered by contiguous impervious surfaces consisting of buildings, asphalt pavement and concrete. The property is fenced in with secure access points located on 3rd and 1st Streets. Seven functional areas are present at the Property: Stores Building; Operations and Transportation Buildings; Pole/Cable Reel Storage Area; Flush Truck Facility (used to receive and treat flush truck wastes); South Undergound Storage Tanks (UST) Area (contains two 2,500 gallon USTs containing gasoline and diesel fuel); Former North UST Area (previously contained gasoline and diesel USTs) and paved parking lots. Current Zoning and Land Use: The Property is zoned M1 2 (commercial/industrial). Con Edison currently uses the Property as a utility service center. Operations include indoor storage, pole/cable reel storage, operation of fleet fuel dispensing, auto repair garage, parking of fleet and staff vehicles, administrative offices, and flush truck area. The surrounding area is mostly commercial/light industrial. Past Use of the Site: The

THIRD AVENUE YARD (Continued) **S120706183**

property consisted of a tidal wetland until 1860 when the property was backfilled. A baseball stadium was present until approximately 1918, when it was converted into warehouse space. Between 1918 and the time the Property was acquired by Brooklyn Edison Company, Inc. (predecessor to the current owner) in 1925 the property was used mainly for warehouse and trucking operations. After being acquired by Brooklyn Edison, the Property has been used as an electric utility work out location. From at least 1933 to 1964, a portion of the Property fronting Fourth Avenue also housed gasoline service stations leased to third party operators. In 1947, a concrete pit was constructed on the southern corner of the property for dewatering sludge recovered from Con Edison electric manholes/vaults. This pit was connected to the municipal sewer and was utilized until 1974 when it was decommissioned and the current Flush Truck facility was constructed in the same location. Site Geology and Hydrogeology: The subsurface soil includes three primary lithologies that include urban fill, the naturally occurring marsh deposits and underlying sands and silt. The urban fill is continuous across the Property, extends from ground surface to 20 to 25 feet below ground surface (ft bgs) and consists of sand and silt, gravel, cobbles, concrete, brick, slag, cinders, coal fragments, glass, wood, shells, and metal. Beneath the fill and on top of the silt clay layer are discrete lenses of more coarse grained sand and gravel. Underlying fill at the Property is naturally occurring deposits, which consist primarily of silt, clay and peat. The presence of shell and plant fragments suggests that these are tidal marsh deposits. The shallow water table occurs in the fill layer beneath the Property at depths ranging from 7 12 ft bgs. Generally, groundwater flow at the property is to the west. "

Env Problem: "The majority of the contamination encountered during previous investigations at the site consist of petroleum-related compounds however polychlorinated biphenyls (PCBs) were detected in shallow soil. Subsurface Soil: Several semi-volatile organic compounds (SVOCs) were detected above industrial soil cleanup objectives (SCOs). For example, naphthalene was detected at 6,500 ppm compared to an commercial SCO of 500 ppm Surface Soil: PCBs was detected up to 430 ppm compared to an commercial SCO of 1 ppm. Groundwater: Petroleum dissolved-phase contamination was detected above Ambient Water Quality Standards and Guidance Values. For example, naphthalene was detected at 20,000 parts per billion (ppb) compared to a guidance value of 10 ppb. Free-phase oil or light non-aqueous phase liquid (LNAPL) was encountered floating of the water table in the northeastern corner of the site where gasoline and diesel underground storage tanks were previously located. "

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2016-11-21 10:03:00
Record Upd: 2016-11-21 10:03:00

THIRD AVENUE YARD (Continued) **S120706183**

Updated By:	RJCOZZY
Own Op:	6
Sub Type:	P02
Owner Name:	Andrea Schmitz
Owner Company:	Consolidated Edison Company of New York, Inc.
Owner Address:	4 Irving Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	Andrea Schmitz
Owner Company:	Consolidated Edison Company of New York, Inc.
Owner Address:	4 Irving Place
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library Pacific Branch
Owner Address:	25 4th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Mary Ellen Conlin, Director - Remediation
Owner Company:	Con Edison
Owner Address:	Con Edison
Owner Addr2:	31-01 20th Avenue
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

A71
West
< 1/8
0.027 mi.
142 ft.

THIRD AVENUE YARD
222 FIRST STREET
BROOKLYN, NY 11215

Site 70 of 83 in cluster A

NY TANKS **U001832241**
NY Spills **N/A**

Relative:
Lower

Actual:
19 ft.

TANKS:

Name:	THIRD AVENUE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY 11215
Facility Id:	2-452726
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	08/23/2023
UTM X:	585744.08429
UTM Y:	4503185.87893

SPILLS:

Name:	THIRD AVENUE YARD - EMPLOYEE LOT
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0203307 / 2017-06-08
Facility ID:	0203307
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263576
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	2002-06-27
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	2002-06-27
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2002-06-27
Spill Record Last Update:	2017-06-08
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY / ARAKHAN 7/25/02 Met with M. Sicherman and Sam Arakhan to discuss the high PCB readings in the employee parking lot. She explained that this spill was called in and was thought to be gasoline. We discussed combining the UST and PCB investigations. (KMF) 9/5/02 Phonecall from Maureen Sicherman. So far, they cannot

THIRD AVENUE YARD (Continued) **U001832241**

locate 14 tanks. Suggested Con Ed submit proposal to do a site investigation. (KMF) 9/16/02 Phone converstaion with M. Sicherman. Submitting letter on how they're going to locate tanks. Not going to try GPR because they've tried this in the area before and were unsuccessful. Going to dig 5'deep trenches and test pits based on information from property records and Sanborne maps. These records indicate tanks were removed in 1964 (they disappear from map to map). QAPP/Workplan being rewritten. (KMF) 9/25/02 Received UST Investigation proposal from M. Gonzalez. (KMF) 10/9/02 Phone conversation with M. Sicherman. Include diesel as contaminant and PCBs. Use Fuel oil contaminated soil TAGM 4046. Will send letter confirming conversation. (KMF) 10/9/02 Relayed Sam Arakhan's comments to M. Sicherman. Requested site map and MW-2 location. (KMF) 10/10/02 Spoke with M. Sicherman. Will address comments when she receives a letter. (KMF) 10/10/02 Sent out letter in response to scope of work. (KMF) 11/4/02 Received QAPP for the Groundwater Investigation and Remedial Action Plan for PCBs and unknown USTs in the employee parking lot dated May 28, 2002 (revised November 1, 2002). 11/21/02 Yesterday afternoon found wall of tank while trenching. Appear to be heating oil tanks (maybe 250gal). Clean Harbors uncovered another tank while looking for port to first tank. Excavation is 40'X20'. Asked about 30day requirement to notify DEC to close the tanks. Replied that this did not apply in this case. Also directed her to arrange to register the tanks. (KMF) 11/21/02 Update: Removed 3 drums of oily sludge from tanks. Will fully characterize and analyze for PCBs. Regular turnaround for rolloff waste characterization of soils and sludge. Appendix B Category B deliverables will cause them to store rolloff for about a month. 11/25/02 Construction management was proceeding this morning and saw two tanks ad adjacent two tanks. Four tanks altogether. Appear to be 550gal. Will sample liquid and determine flash point and product. (KMF) 11/25/02 Update: UST-II area (where they had shifted the soil within the excavation) was expanded another 5' north and uncovered top of tanks. Found mostly water inside. Took samples and saw some sludge at bottom. 12/11/02 Update: PCB confirmatory sampling results are not yet available. All potentially impacted soil from around lube tanks had been excavated and samples collected from soil. Also reported as hazardous for lead. Will be disposed of as such. At the south area, gas tanks liquids were treated as hazardous for benzene. (KMF) 12/17/02 Mariela Gonzalez informed me that an additional 6 tanks were located and were full of water. Will sample for oil ID, PCBs and RCRA. Soil is stained under the other 4 tanks. Concrete anchoring slab was broken out (approx 4 thick) and contamination was found. Waiting to see if water in excavation percolates. Will inspect graves tomorrow afternoon if possible. (KMF) 12/19/02 Met with M. Gonzalez and Chad of Jacques Whitford. Met to discuss results of preliminary samples. She will send a summary of results with an updated map of tank areas. Mariela is concerned about levels of metals and requested that DEC negotiate cleanup levels and amounts of soil to be removed. Sidewalk on east side of UST-II area mat be undermined. One high PCB hit (26ppm) on south side of PCB-II area. Mariela is concerned about how much soil will need to be removed from this area. Will research test pit data and determine extent of contamination in this area if possible. UST-I area - no tanks were found initially. Found two lube oil tanks when trench was extended. Additionally 6 tanks located north of UST-I area. Samples have been taken from the tanks. (KMF) 1/05/04 Arakhan PCB cleanup and removal of old USTs have been completed. ConEd (Maria

THIRD AVENUE YARD (Continued) **U001832241**

Gonzalez) will submit report shortly. Subsequent to completion of PCB remediation, elevated concentrations of BTEX/gasoline detected in monitoring wells. Additional investigation and remediation efforts conducted. (JHO) 4/22/04: Con Edison submits UST Closure Summary Report for 14 tanks uncovered during excavation and removal of PCB contamianted soil associated with the employee parking lot. The report documents post-excavation soil sampling resultsfor PCBs, VOCs and SVOCs. 5/27/04: E-mail from Con Ed (M. Gonzalez) transmitting results of May 2004 groundwater sampling event. To summarize, there are low to moderate conentrations of BTEX compounds in groundwater which exceed standards. For example, benzene = 22 ppb max, toluene = 15 ppb max, ethylbenzene = 140 ppb max, xylene = 170 ppb max. See eDocs for results. (JHO) 6/7/04: revised groundwater contour map submitted by Con ed. See eDocs. (JHO) 6/8/04: e-mail to Con Ed Mariela Gonzalez: This is the third different groundwater contour/flow direction that I have seen for this site. I guess the addition of the wells around the north UST area helped get a better handle on it. I reviewed the groundwater analytical data for both the employee parking lot and the Service Center tanks [NOTE - see spill no. 9808009 for Service Center spill - JHO]. I think we are dealing with two distinct plumes, based on the following observations: 1. I don't see any MTBE associated with the employee parking lot plume. If this was, in fact, the leading edge of the plume from the Service Center, I would expect to see MTBE in addition to the BTEX. 2. The presence of lead in the employee parking lot soils also leads me to believe this is a plume of older gasoline (leaded gas, no MTBE). How long before the new building is to be constructed on the employee parking lot? My suggestion would be to use ORC on this plume (hopefully we can do this now before construction begins) and install two wells each in the sidewalk adjacent to MW-1 and MW-3. (JHO) 6/10/04: E-mail update from M. Gonzalez: I'm glad you had the chance to catch up with this site. It is my understanding that construction activities at this site may begin in early August or September. [NOTE: Con Ed is planning on constructing a new office building on the former employee parking lot area.- JHO] Regarding ORC application at this site, I believe that because of the aggressive remediation at this site (more than 9,000 tons of soil removed and all 14 USTs removed) and the current levels of VOCs in GW -range between 11 ppb (Benzene) to 160 ppb (Xylenes), it wouldn't be necessary. It seems like the plume is stable and mainly around the MW1. I know that we have a short window of opportunity to do it and with the ORC treatment being able to get a faster remediation conditions to achieve a NFA, rather than waiting and monitoring GW for much longer time. So, I'm open to discuss. Perhaps, we could perform one ORC application but limited to the North Area (around MW1), since the middle and south areas (where MW2 and MW3) are clean. The approximate cost of ORC application for the north area is $30-40 K. Regarding installation of additional MWs, we need to further evaluate the number and the location required because heavy presence of all kind of underground utilities between the property and the Fourth Ave. Within the property say, by the north-east corner (about 60-65 feet north of MW1) is a possibility. MW1 and MW 3 will be preserved. I'll be calling you to discuss. (JHO) 6/25/04: e-mail from M. Gonzalez proposing ORC injection for wells at parking lot, as follows: Jane, here attached the GW flow contour for the 3rd Ave Yard (combining the MWs at the Service Center and the parking Lot). Also, FE [First Environment]used Regenesis calculation web tool to determine the

THIRD AVENUE YARD (Continued) **U001832241**

optimal grid size and ORC material required for a limited ORC injection to address VOCs exceedances in the MW#1. I provided FE the end-point soil results for the North excavation area. John plotted the soil VOC results in the proposed ORC injection site Plan. (Note: I took a second look to those end-point soil VOCs concentration, and they are below the TAGM Recommended Cleanup objective to protect GW, Also to note that excavation at the north area went down to 10-11 feet, in contrast to the south or TP15 area which were excavated as deep as 14 feet.) I would like to schedule the ORC application at the Parking Lot ASAP. See eDocs for e-mail and attachments. (JHO) 7/9/04: E-mail to Con Ed Gonzalez approving ORC proposal: I reviewed the info you e-mailed me on June 25 and agree with the ORC proposal with one change: I'd like FE to install one new monitoring well in the sidewalk downgradient of the ORC injection area. I know you told me that well MW-1 will be spared from the construction activities, but I'd still like to have a monitoring point that is outside of the immediate injection zone. (JHO) 7/23/04: e-mail from Con Ed Gonzalez: This note to update you with our plans regarding the ORC project at the 3rd Ave yard Parking Lot. * Monday, July 26: A field walk among Remediation, CM, the consultant and subcontractor is scheduled at 9 AM. We will be reviewing the scope of work and selecting the injection points. Also we will be reviewing utility drawings and the code 753 markups so that we can select a location for the requested sentinel MW. *The ORC implementation will commence on July 30th. *Pending on MW location, if for example is to be done outside the site property (on the sidewalk), a street permit will have be secured, at this time we don't know, or at which sidewalk the MW will be installed, therefore, upon Monday field walk, I'll update you regarding proposed schedule to install this MW. (JHO) 7/26/04: site visit with Con ed (Mariela Gonzalez, Vinny Desiderio and Ulrick Samuel) and First Environment (John Engdahl). 2 additional wells will be installed to the northeast and southeast of existing well MW-1 in the former parking lot area. Both proposed wells are within property/fence line.(JHO) 7/26/07: e-mail from Con Ed Gonzalez: As we discussed, I'm attaching GW data from the original three MWs installed at the parking Lot. These wells were destroyed during soil excavation. Also attached is GW data (three rounds of data) for the existing MW#3 (at the south area). I only summarized VOCs since SVOC are either ND or below GW standards. And to document, below I typed some of the clarifications regarding the scope of work: - Two MWs (could be 2 diameter) to be installed at about 5' south and north of the ORC injection borders. The wells to be located the closest possible toward the property fence at 4th Ave, but inside the parking lot property. - At these two MW locations, soil sampling is not anticipated since wells are being drilled on clean sand from 0 to 10'. If soil below 10' shows any evidence of contamination (odor, color or high PID readings) then a soil sample above the GW elevation should be collected. - The MW #1 and #2 will be extended out [NOTE: converted to stick up wells - JHO] so that the MWs are not covered during paving/site surface restoration activities. E-mailed response to Gonzalez: The concentrations in groundwater from the one round of sampling of the original wells in the south tank area indicates no detectable VOCs. These wells were closer to the tanks (the ostensible source of the contamination). The concentrations in new MW-3 seem to be fairly consistent, and are low. You can stick to the original plan - i.e., ORC for the north tank area. The south area will be capped with the new building, preventing any further rainwater infiltration.

THIRD AVENUE YARD (Continued) **U001832241**

I would recommend that well MW-3 be sampled on the same frequency as the north area wells in order to track any remaining contaminant concerns. NOTE ADDED 9/11/07 BY JHO - there were 14 x 550-gallon gasoline USTs located in the northern area, which is the source of the contamination. (JHO) 7/28/04: NFA letter for PCBs in soil issued to Con Edison. (SKA) 9/24/04: E-mail from M. Gonzalez transmitting lab results for soil and groundwater collected during installation of additional monitoring wells. High concentrations of gasoline constituents were noted in soil along fence line, where no soil was previously excavated. The original excavation for the PCB contamianted soil encountered a number of 550-gallon gasoline USTs, which were excavated and removed. However, in an effort to prevent the fence along the site perimeter from collapsing, excavation was halted before reaching clean end-points. The two new wells (MW-4 and MW-5) were installed in the native material. Concentrations in soil in the native material range from ND for benzene to 1416 ppm for xylenes. Groundwater collected from wells MW-1, MW-3, MW-4 and MW-5 show moderate to high conentrations of dissolved BTEX (highest benzene = 1730 ppb, toluene = 7070 ppb, ethylbenzene = 3170 ppb, xylene = 16,600 ppb). These are the concentrations following ORC injection, which was completed on July 31, 2004. 10/5/04: Con Ed submits report on September 2004 monitoring well installation and groundwater sampling event. 8/6/07: e-mail from John Engdahl (First Environment) transmitting conceptual proposal for surfactant injection to enhance product recovery efforts: Attached please find our memo summarizing the recent investigation activities and the proposed investigation (soil gas) and remediation (VEFR w/ surfactant injection) for the 3rd Avenue Employee Parking Lot. Your expedited review of the document would be greatly appreciated, particularly the soil gas sampling portion. We followed the NYS DOH guidance document, however the guidance document does not specifically address our situation (i.e., near slab samples for VI assessment purposes, unconfined surface cover, etc.). We developed our scope based on our experience and knowledge from other sites and other guidance documents, including the NJDEP, EPA, ITRC, and API. We have schedule the GeoProbe for this Thursday, August 9, 2007. See eDocs for memo. (JHO) 8/9/07: e-mail response to First Environment (Engdahl): As we discussed on the phone this morning, NYSDOH has reviewed the soil vapor sampling plan and finds it acceptable. You will not need to run the SIM method, since the TO-15 detection limits should be sufficient. Please make sure to tell the lab what contaminants you are specifically interested in (i.e., BTEX). As for the proposal for surfactant flushing, please send a hard copy of the memo with the revised figure to: Jim Harrington NYSDEC - Bureau of Technical Support 625 Broadway Albany, NY 12233-7020 Please send me a hard copy of the revised figure, and e-mail me a PDF version as well. NOTE: memo saved in eDocs contains both original and revised site plan. (JHO) 8/22/07: Spoke with Jim Harrington, DER Technical Support - he has assigned this to Kevin Carpenter, who will review the proposal and provide comments. (JHO) 1/31/14 - Remedial action work plan recieved from consultant recommended surfactant injection to address LNAPL which has been recurring in site wells. Sent comments/questions reply via email. (JOC) 2/27/14 - discussed with Con Edison PM Gonzalez 2/26. She would be check with consultant for response to my questions/comments. (JOC) 6/2/15 - received email from consultant 5/22/15 that they conducted a round of groundwater sampling in March 2015 and based on their findings they would like to discuss modifying

THIRD AVENUE YARD (Continued) **U001832241**

their prior proposal, which had been for surfactant injection. Latest round did not see LNAPL in any wells, while dissolved VOC contaminants remain: in 8 wells sampled, 2 had low VOC concentrations, 2 had concentrations about 1 ppm (0.7 and 1.1) and 4 had concentrations in excess of 5 ppm (6.4, 7, 20 and 26 ppm) for CP-51 VOC list contaminants. The 5/22 email includes that an in-situ bio-augmentation program will most likely be the preferred approach, but that updated conditions and other site specifics must be first evaluated, and included that they would like to discuss the matter. Responded by email on 5/22 that I would be available to discuss it and provided some dates to do so. Awaiting response from consultant/Con Edison. (JOC) 7/14/16 had conference call 6/15/15 with Con Ed (Gonzalez), First Environment (Lattanzi) went through that the prior excavation work stayed within the property line and with the continued elevated dissolved concentrations that there remained a need for further work under the sidewalk, bringing up again that the old property drawing shows the old fill lines for the former gasoline station on the sidewalk along the curb; Mr. Lattanzi talked about the difficulty of work with the utilities under the sidewalk (e.g., sewer and subway ductwork) and the adjacent subway under 4th Avenue; the conversation ended with Ms. Gonzalez advising that FE s contract was ending very shortly, that Con Ed would be working on transitioning the project over to their other consultant AECOM. Department staff met with Con Edison on May 10, 2016 and July 8, 2016 to discuss Con Edison’s 3rd Avenue Yard overall and how to move forward with a comprehensive approach. Anticipate feedback from Con Edison shortly.(JOC) 11/18/2016 Austin This spill report is being transferred from Joe O Connell to Jennifer Kann - end. 06/05/17: J.Kann - as per Jeff spill reassigned to Kumar. 6/8/17 - Haggerty: Closed/consolidated under Site C224245. Further investigation and remediation will be conducted under the BCP."

Remarks: "HISTORICAL SPILL FOUND DURING SOME TEST BORINGS. NO SEWERS OR WATERWAYS. NO SMOKE OR FIRE. NO PRIVATE PROPERTY AFFECTED. CON EDISON REFERENCE NUMBER NOT AVAILABLE AT THIS TIME."

All Materials:

Site ID:	263576
Operable Unit ID:	854139
Operable Unit:	01
Material ID:	521137
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A72 **CON ED WORK / 3RD AVE YARD** **NY Spills** **S113493631**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 71 of 83 in cluster A**

Relative: **Lower**

Actual: **19 ft.**

SPILLS:

Name:	CON ED WORK / 3RD AVE YARD
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1301088 / 2013-07-10
Facility ID:	1301088
Facility Type:	ER
DER Facility ID:	353674
Site ID:	481453
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2013-05-02
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2013-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-02
Spill Record Last Update:	2013-07-10
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	222 1ST ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"7/10/13 - Austin - 5 gals unk. oil and 20 gals of water seeped from a 30 yd. dumpster onto ground and sewer - Con Ed contained and cleaned up the spill as a 50-499 PCB waste spill - See eDocs files for further information - Spill closed - end"
Remarks:	"lost from dumpster, some into catch basin, NRC generated, c/u pending"

All Materials:

Site ID:	481453
Operable Unit ID:	1231225
Operable Unit:	01
Material ID:	2229944
Material Code:	0020B
Material Name:	cable oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A73 **FLUSH PIT** **NY Spills** **S103484823**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 72 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual:
19 ft.

Name:	FLUSH PIT
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9807969 / 2002-12-30
Facility ID:	9807969
Facility Type:	ER
DER Facility ID:	167996
Site ID:	276613
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1998-09-27
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1998-09-29
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-29
Spill Record Last Update:	2002-12-30
Spiller Name:	JOE DEVOTI
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	JOE DEVOTI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #120147: 2030 Hrs 9/29/98 A vactor truck (#60404) picked up 5 gallons of Non-PCB oil (2 PPM), on 9/27/98 at 0340 Hrs from M-2244 s/s Monroe St. 430' E/O Patchem Ave. After completing other work during the day, the truck was brought back to the 3rd Ave Yard Waste Treatment Facility and dumped on 9/27/98 at 1600 Hrs. Contents of the truck were dumped and processed through the waste treatment facility which contains an oil skimmer. DEP notified and it was agreed that the effluent would be sampled. Results will be provided to the DEP. Reported by Mimnagh #75055, Section manager Environmental Operations. 9/29/98 2135 ERT Rep. Perez notified by Mimnagh. 29-SEP-1998 21:34 C.I.G DEVOTI NOTIFIED BY R.DONNELLY LOGGED BY 9/30/98 - Update - Status was changed from possibe waterway to contained. It is believed that the waste treatment facility sufficiently extracts oil from the water stream prior to discharge to the sanitary sewer system. Updated by Tom Mimnagh # 75055. - Envir Ops. In an attempt to update status on event involved material history from ppw possible waterway to contained received an error message that prevented us from performing the update. We will update

FLUSH PIT (Continued) **S103484823**

e2mis when we receive further information as to how to save the status. 12:15 9/30/98 T.MIMNAGH CALLED TO REPORT THAT AS OF 11:45 THE 3RD AVE YARD FLUSH PIT IS CLOSED, BY ORDER OF THE DEP (MANJIT SINGH) It must remain closed until they authorize/ have results from grab samples. Anita Wicklund CC Shift Manager. 09/30/98 17:50 PER STEVE ZALLOUGHI. DERECK HUGHES OF THE LAW DEPT. FORMALLY INFORMED STEVE ZALLOUGHI ACTING SECTION MANAGER OF B/Q E.H.&S. THAT WE HAVE AN ORDER FROM THE DEP THAT WE ARE PROHIBITED FROM PROCESSING WASTE WATER FROM THE SOLID WASTE TRANSFER FACILITY AT 3RD AVE YARD. THIS SUBJECT ORDER # 11910 WAS RECEIVED AT 17:35 OM 9/30/98. UPDATE: 10/1/98 - 0830 UPON DEP REQUEST, ENV. OPS. WILL BE TAKING SAMPLES FROM THE OUTLET SIDE OF THE WASTE TREATMENT SYSTEM. WE HAVE BEEN REQUESTED TO TAKE 4 SETS OF SAMPLES PER DAY. 9/29/98: ROBERT HUTCHINSON TOOK ONE QUART JAR SAMPLE AT APPROXIMATELY 1930 HRS. 9/30/98 - 0900: PAUL KISSEL TOOK ONE QUART JAR SAMPLE FROM BARREL THAT COLLECTS OIL SKIMMED FROM THE MAINTANK. MR. KISSEL ALSO TOOK TWO SETS OF SAMPLES (1ST SET AT1300 AND 2ND SET AT 1600) AFTER CYCLING THE SYSTEM WITH THE OUTLET TO THE SEWER PLUGGED. EACH SAMPLE INCLUDED TWO QUART JARS FOR PPT PCB, AND ONE QUART JAR FOR TOTAL PETROLEUM HYDROCARBONS (TPH). UPDATE: 10/1/98 P. KISSEL - PLANNER - ENV. OPS., REPORTS TAKING 4 SETS OF SAMPLES FOR PPT PCB AND TPH. SAMPLES DELIVERED TO CHEM LAB AT 1700. 10/2/98 T. MIMNAGH - MANAGER - ENV. OPS., REPORTS SAMPLES FROM 9/30/98 CAME BACK LESS THAN 65 PPT PCB, AND TPH VALUES OF 1.05 AND .803 PPM. HARD COPIES OF RESULTS GIVEN TO DEP CHIEF PATEL. 10/3/98 T. MIMNAGH - MANAGER - ENV. OPS., REPORTS SAMPLES FROM 10/1/98 CAME BACK WITH NO REPORTABLE CONCENTRATIONS ABOVE DETECTABLE LIMITS FOR PPT PCB AND TPH. HARD COPIES FAXED TO DEP CHIEF PATEL. 10/3/98 T. MIMNAGH - MANAGER - ENV. OPS., REPORTS AT 1400 HRS BROOKLYN WTF RE-OPENED AS PER AGREEMENT WITH ED RADTKE (MANHATTAN EH&S) AND DEP CHIEF PATEL. ORDER RECINDED BY DEP. "

Remarks: "caller states that truck inadverntly poss sucked out water from flush pit"

All Materials:

Site ID:	276613
Operable Unit ID:	1069160
Operable Unit:	01
Material ID:	315508
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A74 **3RD AVE YARD** **NY Spills** **S121982062**
West **222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
142 ft. **Site 73 of 83 in cluster A**

Relative: SPILLS:
Lower

Name:	3RD AVE YARD
Address:	222 1ST ST
City,State,Zip:	BROOKLYN, NY

Actual:
19 ft.

3RD AVE YARD (Continued) **S121982062**

Spill Number/Closed Date:	1012255 / 2011-03-22
Facility ID:	1012255
Facility Type:	ER
DER Facility ID:	353674
Site ID:	446173
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-03-10
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-03-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-10
Spill Record Last Update:	2011-03-22
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"3/22/11 - Austin - Con Ed vehicle leaked 2 gals. hydraulic fluid onto pavement - Con Ed contained and cleaned up the spill - See eDocs for further info - Spill closed - end"
Remarks:	"on ashphalt - no resources - cleanup pending"

All Materials:

Site ID:	446173
Operable Unit ID:	1196533
Operable Unit:	01
Material ID:	2192848
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A75 **CON EDISON** **NY MANIFEST** **S119074730**
WNW **221 1ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
143 ft. **Site 74 of 83 in cluster A**

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	221 1ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004772869
Facility Status:	Not reported
Location Address 1:	222 FIRST ST B/T 3RD & 4TH AVE
Code:	BP
Location Address 2:	CUSTOMER BOX 1584
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772869
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/27/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772869
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	007748418FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119074730**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B002
Waste Code 1_2:	Not reported
Waste Code 1_3:	D009
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A76 **CON EDISON** **NY Spills** **S104509159**
WNW **221 1ST ST** **NY MANIFEST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
143 ft. **Site 75 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

SPILLS:

Name:	3RD AVE YARD
Address:	221 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9911979 / 2000-02-23
Facility ID:	9911979
Facility Type:	ER
DER Facility ID:	149120
Site ID:	177460
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-01-17
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-01-17
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

CON EDISON (Continued) **S104509159**

Remediation Phase:	0
Date Entered In Computer:	2000-01-17
Spill Record Last Update:	2000-05-22
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	FRANK MASSERA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2 MIS REPORT After starting truck 22395 - found that a hose broke spilling approx. 2qts Antifreeze onto asphalt, contained, no sewers or waterways affected. No outside impact, began cleanup right away with diapers and absorbants. Transportation to be notified and will prevent any further spill by wrappin ghose. "
Remarks:	"hose broke on con ed vehicle and spilled 2 qts of material onto concrete. clean up in progress. con ed 129-630"

All Materials:

Site ID:	177460
Operable Unit ID:	1086510
Operable Unit:	01
Material ID:	293869
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON
Address:	221 1ST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004837696
Facility Status:	Not reported
Location Address 1:	3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004837696
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S104509159**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD000002713
Trans2 State ID:	Not reported
Generator Ship Date:	09/12/2015
Trans1 Recv Date:	09/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837696
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014086273JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A77
WNW
< 1/8
0.027 mi.
143 ft.

CON EDISON
221 1ST
BROOKLYN, NY 11215

Site 76 of 83 in cluster A

RCRA NonGen / NLR **1019902363**
NYP004772869

Relative:
Lower

Actual:
19 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20150422
Handler Name:	CON EDISON	
Handler Address:		221 1ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004772869
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019902363**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150422
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019902363**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A78 **CON EDISON** **RCRA NonGen / NLR** **1019325559**
WNW **221 1ST ST** **NYP004837696**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
143 ft. **Site 77 of 83 in cluster A**

Relative: **Lower**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150912
Handler Name:	CON EDISON	
Handler Address:		221 1ST ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004837696
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

CON EDISON (Continued) **1019325559**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20150912

CON EDISON (Continued) **1019325559**

Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: 20150912
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - OTHER - SPECIFY PIT SAND FI
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150912
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150912
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

CON EDISON (Continued) **1019325559**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B79 **CON EDISON MANHOLE: 22624** **RCRA NonGen / NLR** **1017779168**
NNE **540 CARROLL ST** **NYP004571485**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
145 ft. **Site 2 of 24 in cluster B**

Relative: **Higher**
Actual: **24 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140720
Handler Name:	CON EDISON MANHOLE: 22624	
Handler Address:		540 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004571485
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

CON EDISON MANHOLE: 22624 (Continued) **1017779168**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140620
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON MANHOLE: 22624 (Continued) **1017779168**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140620
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140720
Handler Name: CON EDISON MANHOLE: 22624
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B80 **CON EDISON** **NY MANIFEST** **S117064648**
NNE **540 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.027 mi.
145 ft. **Site 3 of 24 in cluster B**

Relative: **Higher**
Actual: **24 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 540 CARROLL ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004571485
Facility Status: Not reported
Location Address 1: 540 CARROLL ST

CON EDISON (Continued) **S117064648**

Code:	BP
Location Address 2:	MH 2226
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004571485
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/2014
Trans1 Recv Date:	06/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004571485
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013254899JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117064648**

Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A81 **220 1ST STREET** **NY Spills** **S103560397**
West **220 1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.028 mi.
149 ft. **Site 78 of 83 in cluster A**

Relative: SPILLS:
Lower

Actual:
19 ft.

Name:	220 1ST STREET
Address:	220 1ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9207274 / 2008-09-19
Facility ID:	9207274
Facility Type:	ER
DER Facility ID:	130183
Site ID:	153446
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	1992-09-15
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1992-09-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-29
Spill Record Last Update:	2008-09-19
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 11/23/94: REASSIGNED FROM SIGONA TO ENGELHARDT ON 11/23/94. 09/19/08. J.Krimgold reviewed info presented by Con Ed. There are no historic data regarding this spill event. NFA "

220 1ST STREET (Continued) **S103560397**

Remarks: ""

All Materials:
Site ID: 153446
Operable Unit ID: 974239
Operable Unit: 01
Material ID: 407921
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

B82 **LOT 1,TAXBLOCK 961** **NY E DESIGNATION** **S108469613**
East **261 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.031 mi.
164 ft. **Site 4 of 24 in cluster B**

Relative: **Higher**
Actual: **27 ft.**

E DESIGNATION:
Name: LOT 1,TAXBLOCK 961
Address: 261 4 AVENUE
City,State,Zip: BROOKLYN, NY 11215
Tax Lot(s): 1
Tax Block: 961
Borough Code: BK
E-No: E-113
Effective Date: 4/30/2003
Satisfaction Date: Not reported
Ceqr Number: 03DCP030K
Ulurp Number: 030194(A)ZMK030194(A)ZMK
Zoning Map No: 16b, 16c

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

A83 **FIVE GALLONS OF OIL IN SOIL** **NY Spills** **S108058550**
SW **222 1 STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
164 ft. **Site 79 of 83 in cluster A**

Relative: **Lower**
Actual: **22 ft.**

SPILLS:
Name: FIVE GALLONS OF OIL IN SOIL
Address: 222 1 STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0604245 / 2017-06-08
Facility ID: 0604245
Facility Type: ER
DER Facility ID: 317243
Site ID: 367178
DEC Region: 2
Spill Cause: Unknown

FIVE GALLONS OF OIL IN SOIL (Continued) **S108058550**

Spill Class:	C4
SWIS:	2401
Spill Date:	2006-06-28
Investigator:	MJHAGGER
Referred To:	ERT
Reported to Dept:	2006-07-17
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-17
Spill Record Last Update:	2017-06-08
Spiller Name:	ERT DESK MIKE DAUGHTERY
Spiller Company:	CON EDISON
Spiller Address:	222 1ST STREET
Spiller Company:	999
Contact Name:	ERT DESK MIKE DAUGHTERY
DEC Memo:	"201193. see eDocs 5/21/12 - requested Con Edison's PM for other open spills at 3rd Avenue Yard to track down information on this spill to determine where exactly it was and whether it affected any of the other areas being investigated via email 3/5/12. Con Ed PM tracked down some information, and we met at the location of Bay #1, inside the Stores Bldg during field work activities for Spill 1008213 on 4/3/12. Con Ed personnel at the location had no specific information about the spill, but described that there is a large pit in the floor in the bay. It was covered by steel plates which were tach welded together. These personnel described that the pit was rather deep. At the time of the inspection, the Bay was being used for storage, which they described was the case for a long time. They suspected that in the past there may have been vehicle repairs made in the bay. The bay has two large overhead garage doors. The bay is at the north end of the Stores bldg, so it is distant from any of the other areas of concern ongoing at the 3rd Avenue Yard. Figure added to edocs showing the location. Con Ed has been unable to track down any further information about the incident or any resolution. Con Edison will need to investigate. (JOC) 11/18/2016 Austin This spill report is being transferred from Joe O Connell to Jennifer Kann - end. 06/05/17: J.Kann - as per Jeff spill reassigned to Kumar. 6/8/17 - Haggerty: Closed/consolidated under Site C224245. Further investigation and remediation will be conducted under the BCP."
Remarks:	"MIXED WITH SOIL AND IS IN REMIDIATION. CON ED 201193"

All Materials:

Site ID:	367178
Operable Unit ID:	1125101
Operable Unit:	01
Material ID:	2114621
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00

FIVE GALLONS OF OIL IN SOIL (Continued) **S108058550**

Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	3 AVE YARD
Address:	222 NORTH 1 STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0512763 / 2006-04-12
Facility ID:	0512763
Facility Type:	ER
DER Facility ID:	309135
Site ID:	359135
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-02-03
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-02-03
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-03
Spill Record Last Update:	2006-04-12
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	222 NORTH 1ST
Spiller Company:	999
Contact Name:	ERT DESK’
DEC Memo:	"162827. 2-3-06 11:15HRS L. CLARK M&CS 05374 REPORTS, TWO PINTS OF DIESEL FUEL LEAKED FROM A HEATER ON DIRT ON CONSTRUCTION SITE AT 3RD AVE YARD. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED. NO SEWERS OR WATERWAYS WERE AFFECTED AND CLEANUP WILL COMMENCE AND WILL BE UPDATED ON NEXT UPDATE. S. PACE 49874. UPDATE 2-3-06 13:10HRS MR. CLARK REPORTS, DUG DOWN 2’ DEEP TO DRY DIRT DIAPERED UP AND BARRELLED IT. JOB 100% COMPLETED. S. PACE 49874. Update 4/12/06 Spill closed based on report in eDocs. (SKA) "
Remarks:	"LEAKED FROM A JEATER ON TO DIRT, 2 OUNCES AND IN PROCESS OF CLEANING UP, CONED # 162827; NO TO 5 QUESTIONS"

All Materials:

Site ID:	359135
Operable Unit ID:	1116359
Operable Unit:	01
Material ID:	2106506
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum

FIVE GALLONS OF OIL IN SOIL (Continued) **S108058550**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

A84 **SIX GAL HYDRAULIC FLUID FROM VEH** **NY Spills** **S108763880**
SW **222 FIRST STREET & 3 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
164 ft. **Site 80 of 83 in cluster A**

Relative: **Lower**
Actual: **22 ft.**

SPILLS:
Name: SIX GAL HYDRAULIC FLUID FROM VEH
Address: 222 FIRST STREET & 3 AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0705772 / 2007-11-08
Facility ID: 0705772
Facility Type: ER
DER Facility ID: 335533
Site ID: 386143
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2007-08-20
Investigator: gdbreen
Referred To: Not reported
Reported to Dept: 2007-08-20
CID: 410
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-08-20
Spill Record Last Update: 2007-11-08
Spiller Name: ERTSDESK
Spiller Company: CON EDISON
Spiller Address: 222 FIRST ST & 3RD ST
Spiller Company: 999
Contact Name: ERTSDESK
DEC Memo: "11/08/07 - See eDocs for Con Ed report detailing cleanup and closure. 207654. see eDocs"
Remarks: "MATERIAL SPILLED TO CONCRETE CONTAINMENT PIT, ALL CONTAINED: CONED # 207654"

All Materials:
Site ID: 386143
Operable Unit ID: 1143392
Operable Unit: 01
Material ID: 2133669
Material Code: 0010
Material Name: hydraulic oil

SIX GAL HYDRAULIC FLUID FROM VEH (Continued) **S108763880**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A85 **VEHICLE 60677** **NY Spills** **S107522699**
SW **THIRD AVE YARD** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
164 ft. **Site 81 of 83 in cluster A**

Relative: **Lower**
Actual: **22 ft.**

SPILLS:

Name:	VEHICLE 60677
Address:	THIRD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0512797 / 2006-04-12
Facility ID:	0512797
Facility Type:	ER
DER Facility ID:	309312
Site ID:	359174
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-02-04
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-02-04
CID:	75
Water Affected:	N/A
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-04
Spill Record Last Update:	2006-04-12
Spiller Name:	WAINRIGHT
Spiller Company:	CON EDISON YARD
Spiller Address:	222 1ST STREET
Spiller Company:	001
Contact Name:	WAINRIGHT
DEC Memo:	"162841. 2/04/2006 06:28 HRS. BROOKLYN ENV OPS SUPERVISOR C. FERNANDEZ # 56150 REPORTS AT 06:05 HRS. FOUND VACTOR # 60677 HAD LEAKED APPROX. 1 GAL HYDRAULIC FLUID ONTO CONCRETE IN GARAGE AT 3RD AVE YARD. SOURCE IS A BROKEN HYDRAULIC HOSE. THIS IS AN ACTIVE LEAK AND HE ESTIMATES RATE AS APPROX. 1 GAL PER HOUR. SPILL CONTAINED WITH OIL ABSORBANT. NO SEWERS OR WATERWAYS AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE/SMOKE INVOLVED. HE WILL NOTIFY TRANSPORTATION TO MAKE REPAIRS TO STOP THE LEAK. ENTERED AS 2-HOUR DEMINIMIS AS PER C. FERNANDEZ -- HE WILL NOTIFY ME IF REPAIRS AND CLEANUP CANNOT BE DONE WITHIN TWO HOURS OF TIME FOUND. ** NOTE: A PRIOR HYDRAULIC SPILL FROM

VEHICLE 60677 (Continued) **S107522699**

SAME VEHICLE WAS FOUND AT 04:00 HRS AND THAT CLEANUP WAS COMPLETED AT 04:45 HRS. (SEE E2MIS REPORT # 162840). W. WAINWRIGHT #17344 2/4/06 07:56 HRS. -- BROOKLYN ENV OPS O/S D. LICHTENSTEIN REPORTS TRANSPORTATION HAS NOT YET ARRIVED (COMING FROM QUEENS) AND INCIDENT WILL NOT BE COMPLETE BEFORE 08:05 HRS. INCIDENT REMOVED FROM 2-HOUR DEMIMINIS. W.W. #17344 4/12/06 Spill closed based on report in eDocs. (SKA)"

Remarks: "1 gal hyd oil from a truck #60677 onto the floor inside garage on floor concrete-all cleaned up and contained 162841 con ed #"

All Materials:

Site ID:	359174
Operable Unit ID:	1116399
Operable Unit:	01
Material ID:	2106778
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A86 **222 1ST STREET** **NY Spills** **S102150009**
SW **CON EDSION** **N/A**
< 1/8 **KINGS (County), NY**
0.031 mi.
164 ft. **Site 82 of 83 in cluster A**

Relative: **Lower**

Actual: **22 ft.**

SPILLS:

Name:	222 1ST STREET
Address:	CON EDSION
City,State,Zip:	NY
Spill Number/Closed Date:	9501055 / 2004-07-16
Facility ID:	9501055
Facility Type:	ER
DER Facility ID:	167594
Site ID:	201439
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-04-25
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1995-04-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

222 1ST STREET (Continued) **S102150009**

Date Entered In Computer:	1995-05-16
Spill Record Last Update:	2004-07-16
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 7/16/04: Cpm Ed submitted copy of NYCDEP notification letter: Con Ed crew cleaned up the spill with pads and noncombustible absorbent material. Close out. (JHO)"
Remarks:	"BLOW OFF VALVE ON VEHICLE FAILED WHILE BEING FILLED - SPILL IS CONTAINED IN PROCESS PF BEING CLEANED."

All Materials:

Site ID:	201439
Operable Unit ID:	1015172
Operable Unit:	01
Material ID:	369669
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A87 **HYDRAULIC OIL** **NY Spills** **S106970838**
SW **3 AVE YARD NEW CONST SITE** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
164 ft. **Site 83 of 83 in cluster A**

Relative: **Lower**

Actual: **22 ft.**

SPILLS:

Name:	HYDRAULIC OIL
Address:	3 AVE YARD NEW CONST SITE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0505767 / 2005-08-11
Facility ID:	0505767
Facility Type:	ER
DER Facility ID:	297758
Site ID:	350857
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-08-10
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-08-10
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

HYDRAULIC OIL (Continued) **S106970838**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-10
Spill Record Last Update:	2005-10-18
Spiller Name:	Not reported
Spiller Company:	IMPERIAL PAINTING CONTRAC
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERT DESK'
DEC Memo:	"160402. 8/10/2005 14:15 HRS J. EUBANK #05653 EHS REP REPORTS THAT APPROX 1 PT OF HYDRAULIC OIL LEAKED FROM A GENIE-LIFT BEING USED BY IMPERIAL PAINTING CONTRACTORS (3RD PARTY) WHILE THEY WERE DOING WORK ON THE NEW BUILDING UNDER CONSTRUCTION AT 3RD AVE. THERE WAS NO SMOKE, FIRE, OR INJURIES RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THIS SPILLED ON BLUESTONE AND IS IN THE PROCESS OF BEING CLEANED UP. MR. EUBANK WAS ON LOCATION AS PART OF A ROUTINE INSPECTION. J ANDERSON UPDATE 8/10/05 15:07 HRS J. EUBANK REPORTS THE AFFECTED BLUESTONE AND DIRT HAS BEEN PICKED UP AND DISPOSED, CLEANUP COMPLETE. J ANDERSON. Closed. 8-11-05. George Breen see eDocs. "
Remarks:	"DUE TO A LIFT ON A TRUCK.. PRODUCT WAS ONE PINT AND HAS BEEN CLEANED UP. CON ED #160402"

All Materials:

Site ID:	350857
Operable Unit ID:	1108399
Operable Unit:	01
Material ID:	2098335
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

B88 **RIDGE AUTO TRANSMISSION** **EDR Hist Auto** **1020259439**
NE **270 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.031 mi.
166 ft. **Site 5 of 24 in cluster B**

Relative: EDR Hist Auto
Higher

Actual: **26 ft.**

Year:	Name:	Type:
1972	RIDGE AUTMTC TRANSMISSION CTR	General Automotive Repair Shops
1973	RIDGE AUTMTC TRANSMISSION CTR	General Automotive Repair Shops
1974	RIDGE AUTMTC TRANSMISSION CTR	General Automotive Repair Shops
1975	RIDGE AUTO COLLISION INC	Automotive Repair Shops, NEC
1975	RIDGE AUTMTC TRANSMISSION CTR	General Automotive Repair Shops
1976	RIDGE AUTO COLLISION INC	Automotive Repair Shops, NEC
1976	RIDGE AUTMTC TRANSMISSION CTR	General Automotive Repair Shops
1977	RIDGE AUTO COLLISION INC	Automotive Repair Shops, NEC
1978	RIDGE AUTO COLLISION INC	Automotive Repair Shops, NEC

RIDGE AUTO TRANSMISSION (Continued) **1020259439**

1979	RIDGE AUTO COLLISION INC	Automotive Repair Shops, NEC
1980	DELK TRANSMISSION INC	General Automotive Repair Shops
1982	DELK TRANSMISSION INC	General Automotive Repair Shops
1983	DELK TRANSMISSION INC	General Automotive Repair Shops
1985	RIDGE AUTO TRANSMISSION	Automotive Repair Shops, NEC
1985	DELK TRANSMISSION INC	General Automotive Repair Shops
1986	DELK TRANSMISSION INC	General Automotive Repair Shops
1986	RIDGE AUTO TRANSMISSION	Automotive Repair Shops, NEC
1987	RIDGE AUTO TRANSMISSION	Automotive Repair Shops, NEC
1987	DELK TRANSMISSION INC	General Automotive Repair Shops
1988	RIDGE AUTO TRANSMISSION	Automotive Repair Shops, NEC
1989	RIDGE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1990	RIDGE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1991	RIDGE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1992	DELK TRANSMISSION INC	General Automotive Repair Shops
1992	RIDGE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1993	RIDGE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1993	DELK TRANSMISSION INC	General Automotive Repair Shops
1994	RIDGE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1995	RIDGE TRANSMISSIONS AND MOTORS	Automotive Transmission Repair Shops
1996	RIDGE TRANSMISSIONS AND MOTORS	Automotive Transmission Repair Shops
1997	RIDGE DELK TRANSMISSIONS ENGS	Automotive Transmission Repair Shops
1998	RIDGE DELK TRANSMISSIONS ENGS	Automotive Transmission Repair Shops
1999	AUTO BODY CONCEPTS INC	General Automotive Repair Shops
1999	RIDGE DELK TRANSMISSIONS ENGS	Automotive Transmission Repair Shops
2000	AUTO BODY CONCEPTS INC	General Automotive Repair Shops
2000	RIDGE DELK TRANSMISSIONS ENGS	Automotive Transmission Repair Shops
2001	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2001	RIDGE DELK TRANSMISSIONS ENGS	Automotive Transmission Repair Shops
2002	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2003	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2004	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2005	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2006	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2007	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2008	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2009	AUTOMOTIVE EXPRESS	General Automotive Repair Shops
2010	AUTOMOTIVE EXPRESS INC	General Automotive Repair Shops
2011	AUTOMOTIVE EXPRESS INC	General Automotive Repair Shops
2012	AUTOMOTIVE EXPRESS INC	General Automotive Repair Shops
2013	AUTOMOTIVE EXPRESS INC	General Automotive Repair Shops
2014	AUTOMOTIVE EXPRESS INC	General Automotive Repair Shops

B89 **AUTO BODY CONCEPTS DBA ABC** **RCRA NonGen / NLR** **1001229433**
NE **270 4TH AVE** **NYR000060392**
< 1/8 **BROOKLYN, NY 11215**
0.031 mi.
166 ft. **Site 6 of 24 in cluster B**

Relative:
Higher

Actual:
26 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	AUTO BODY CONCEPTS DBA ABC
Handler Address:	270 4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11215-1819
EPA ID:	NYR000060392
Contact Name:	ANTHONY DIMONDA
Contact Address:	4TH AVE
Contact City,State,Zip:	BROOKLYN, NY 11215

AUTO BODY CONCEPTS DBA ABC (Continued) **1001229433**

Contact Telephone:		718-522-3111
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	ANTHONY DIMONDA	
Owner Type:		Private
Operator Name:	ANTHONY DIMONDA	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

AUTO BODY CONCEPTS DBA ABC (Continued) **1001229433**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ANTHONY DIMONDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	100 POILLON AVE
Owner/Operator City,State,Zip:	STATEN ISLAND, NY 10312
Owner/Operator Telephone:	718-966-4135
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: ANTHONY DIMONDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	100 POILLON AVE
Owner/Operator City,State,Zip:	STATEN ISLAND, NY 10312
Owner/Operator Telephone:	718-966-4135
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: ANTHONY DIMONDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

AUTO BODY CONCEPTS DBA ABC (Continued) **1001229433**

Owner/Operator Address: 100 POILLON AVE
Owner/Operator City,State,Zip: STATEN ISLAND, NY 10312
Owner/Operator Telephone: 718-966-4135
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: AUTO BODY CONCEPTS DBA ABC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: AUTO BODY CONCEPTS DBA ABC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980916
Handler Name: AUTO BODY CONCEPTS DBA ABC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B90
ENE
< 1/8
0.034 mi.
180 ft.

LOT 2,TAXBLOCK 961
259 4 AVENUE
BROOKLYN, NY 11215

Site 7 of 24 in cluster B

NY E DESIGNATION **S108075299**
N/A

Relative:
Higher

Actual:
27 ft.

E DESIGNATION:

Name:	LOT 2,TAXBLOCK 961
Address:	259 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	2
Tax Block:	961
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

C91
NNE
< 1/8
0.036 mi.
192 ft.

ROMAN CATHOLIC CHURCH OF OUR L
522 CARROLL ST
BROOKLYN, NY 11215

Site 1 of 11 in cluster C

NY UST **U001839551**
N/A

Relative:
Higher

Actual:
23 ft.

UST:

Name:	ROMAN CATHOLIC CHURCH OF OUR L
Address:	522 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-346667 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585813.08518
UTM Y:	4503329.14780
Site Type:	School

Affiliation Records:

Site Id:	16960
Affiliation Type:	Facility Owner
Company Name:	ROMAN CATHOLIC CHURCH OF OUR LADY OF PEACE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	522 CARROLL ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 624-5122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

ROMAN CATHOLIC CHURCH OF OUR L (Continued) **U001839551**

Site Id:	16960
Affiliation Type:	Mail Contact
Company Name:	ROMAN CATHOLIC CHURCH OF OUR LADY OF PEACE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	522 CARROLL ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 624-5122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16960
Affiliation Type:	Facility Operator
Company Name:	ROMAN CATHOLIC CHURCH OF OUR L
Contact Type:	Not reported
Contact Name:	FR LOUIS DETOMMASO, O.F.M.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 624-5122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16960
Affiliation Type:	Emergency Contact
Company Name:	ROMAN CATHOLIC CHURCH OF OUR LADY OF PEACE
Contact Type:	Not reported
Contact Name:	FR LOUIS DETOMMASO, O.F.M.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 624-5122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	32929
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use

ROMAN CATHOLIC CHURCH OF OUR L (Continued) **U001839551**

Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	05/12/2017
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

B92 **CON EDISON** **NY MANIFEST** **S117064771**
East **9 GARFIELD ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.037 mi.
194 ft. **Site 8 of 24 in cluster B**

Relative:
Higher

Actual:
27 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	9 GARFIELD ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004572756
Facility Status:	Not reported
Location Address 1:	FO 9 GARFIELD PL
Code:	BP
Location Address 2:	SB 17869
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004572756
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON (Continued) **S117064771**

Mailing Phone: Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/2014
Trans1 Recv Date:	06/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004572756
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502781GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B93 **CON EDISON SERVICE BOX: 17869** **RCRA NonGen / NLR** **1017779286**
East **9 GARFIELD ST** **FINDS** **NYP004572756**
< 1/8 **BROOKLYN, NY 11215**
0.037 mi.
194 ft. **Site 9 of 24 in cluster B**

Relative: **Higher**
Actual: **27 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140723
Handler Name:	CON EDISON SERVICE BOX:	17869
Handler Address:		9 GARFIELD ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004572756
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 17869 (Continued) **1017779286**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140623
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140623
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 17869 (Continued) **1017779286**

Electronic Manifest Broker: Not reported

Receive Date: 20140723
Handler Name: CON EDISON SERVICE BOX: 17869
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063836014

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

C94 **PS 418 K SCHOOL** **RCRA-LQG** **1016144416**
North **512 CARROLL ST** **FINDS** **NYR000199968**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.038 mi. **NY MANIFEST**
199 ft. **Site 2 of 11 in cluster C**

Relative: **Lower**
Actual: **21 ft.**

RCRA-LQG:
Date Form Received by Agency: 20140220
Handler Name: PS 418 K SCHOOL
Handler Address: 512 CARROLL ST
Handler City,State,Zip: BROOKLYN, NY 11215
EPA ID: NYR000199968
Contact Name: ALEXANDER LEMPERT
Contact Address: THOMSON AVE
Contact City,State,Zip: LONG ISLAND CITY, NY 11101
Contact Telephone: 718-472-8501

PS 418 K SCHOOL (Continued) **1016144416**

Contact Fax:	Not reported
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	SCAIEH DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	NYC DEPARTMENT OF EDUCATION
Owner Type:	Municipal
Operator Name:	NYC DEPARTMENT OF EDUCATION
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

PS 418 K SCHOOL (Continued) **1016144416**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	19000101
Date Ended Current:	Not reported
Owner/Operator Address:	44-36 VERNON BLVD
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	19730517
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES	
Legal Status:	Municipal
Date Became Current:	19730517
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

PS 418 K SCHOOL (Continued) **1016144416**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140220
Handler Name: PS 418 K SCHOOL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130423
Handler Name: NYC DEPT OF EDUCATION - PS 834K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055471760

PS 418 K SCHOOL (Continued) **1016144416**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016144416
Registry ID:	110055471760
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055471760
Name:	PS 418 K SCHOOL
Address:	512 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	NYC DEPT OF EDUCATION - PS 418K
Address:	512 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000199968
Facility Status:	Not reported
Location Address 1:	512 CARROLL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000199968
Mailing Name:	NYC DEPT OF EDUCATION - PS 418K
Mailing Contact:	NYC DEPT OF SCHOOL CONTRUCTION AUTHORITY - PS 834
Mailing Address 1:	30-30 THOMSON AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184728000

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD986938645

PS 418 K SCHOOL (Continued) **1016144416**

Trans2 State ID:	PAD146714878
Generator Ship Date:	08/30/2013
Trans1 Recv Date:	08/30/2013
Trans2 Recv Date:	09/04/2013
TSD Site Recv Date:	09/05/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000199968
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD000622464
TSDF ID 2:	Not reported
Manifest Tracking Number:	006378703JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	254
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C95 **P.S. 372 (OUR LADY OF PEACE)-K** **NY Spills S106469867**
North **512 CARROLL STREET** **NY LEAD N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
199 ft. **Site 3 of 11 in cluster C**

Relative: **Lower**
Actual: **21 ft.**

SPILLS:

Name:	PUBLIC SCHOOL
Address:	512 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0402598 / 2021-10-20
Facility ID:	0402598
Facility Type:	ER
DER Facility ID:	233652

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

Site ID:	288471
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-06-09
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2004-06-09
CID:	444
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-09
Spill Record Last Update:	2021-10-20
Spiller Name:	BRAD MULLNER
Spiller Company:	PS 372 SCHOOL
Spiller Address:	512 CARROLL ST.
Spiller Company:	001
Contact Name:	BRAD MULLNER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 11/15/2005: Lead transferred to Joe White as part of the Spill Initiative Project. 12/08/2005: Joe White spoke sith James Merlo, the NYC Schools spill coordinator, who will be sending the closeoout report for this spill. 1/9/2006: Mr Merlo indicated that this property is not managed by the NYC Division of School Facilities but is privately owned. 1/23/2006: Joe White sent a letter to school superintendent requesting additional information. A copy of this letter is on eDocs files system for our records. 1/27/2006: Joe White received a call from the school maintennce, Vinnie Peters (718-923-1650) who indicated that they had no records for the spill and the contact number for the Berger firm that did the work did not work. However, Vinnie indicated that there is no obvious problem currently at the site and no work is ongoing at present to address any problem and they are not aware of any problem. This spill was addressed in the past and work concluded. Joe White will follow up to see if we can get something from the Berger firm to document closure. 11/16/06 - Austin - Reassigned to Rahman for followup/review - end 11/19/09 Letter was sent to(asking pertinent documents) P.S. 372, The Children s School 512 Carroll Street Brooklyn, NY 11215 Attn: Lorraine Boyhan(sr) 12/14/09 Rec'd letter requesting extension of report submittal.Letter is from Wingate,Kearney & Cullen,LLP.(sr) 04/5/10 Rec'd email from Katie Coon.She is with Wingate,Kearney & Cullen.She has requested the copy of the Phase II report to the tenant.Once she receives the report, she will forward it to DEC.(sr) 5/30/14 - Austin - Spill transferred from Rahman to Mahat for followup - end 11/5/14: Mahat e/c : An email was sent out to Mr. Munendra Sharma inquiring recent data/report on the spill case. 10/6/2016: Rashad Spill will be reassigned to DEC Omar from DEC Mahat. 11/2/2016: Rashad 512 Carroll Street has alternate addresses of 512-522 Carroll Street and 2-34 Denton Place. No additional spills

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

found, PBS#2-346667 found for site there is a 5000 gallon #2fuel oil UST converted to non regulated use. Various letters found in D2. 11/8/2016: Rashad Sent email to Ms. Guterman: I was previously reassigned a spill from 512 Carroll Street in Brooklyn for P.S 372. I have found a Phase 1 for this site prepared by Louis Berger and I am looking for the Phase 2 report, as well as any documentation stating if further work was completed. Any additional information on this site would be much appreciated so that I may close out this older spill. Thank you. Review of paper documents yielded Phase 1 and Phase 2 reports, they have been uploaded to D2. Brief Review of Phase 1 is as follows: The complex will be comprised of three buildings, the church, the school building, and the recreational center. The site consists of a two story brick building with a basement and has been used for educational and recreational purposes since being built in the 1920s. To the east of the site is a car wash and auto repair facility. Also a Con Ed facility is located adjacent to the south of the site. The mail school and church use a 5000 gallon #2fuel oil UST. One 10,000 gallon AST is located in the main building. Review of Phase 2 is as follows: The investigation consists of three temporary well points, three soils borings along the perimeter, and 2 borings in the basement. Groundwater was encountered in soil borings from 14-18ftbg. SB-04 (3-4ft): No VOCs or SVOCs were detected in soil sample. SB-05 (0-3ft): No VOCs were detected, SVOCs were detected slightly above standards in soil. SB-01 Water Sample: Benzene-229ppb, toluene-1570ppb, ethylbenzene-853ppb, xylene-1020ppb, 1,2,4 trimethylbenzene-337ppb, naphthalene-3930ppb. SB-02 Water Sample: Benzene-8.65ppb, Naphthalene-393ppb. SB-03 Water Sample: Benzene-21.9ppb, toluene-61.3ppb, Ethylbenzene-67.7ppb, Naphthalene-921ppb Sheen and odor were observed in all three groundwater wells. The report concludes that there is petroleum contamination in soil and groundwater, however the source could not be determined. They recommend construct a vapor barrier to prevent migration of VOCs from soil gas into basement . 11/18/2016: Rashad Received email from Lee Guterman yesterday: In response to your request, we have pulled the attached information from our project files. These documents include a Phase II Environmental Site Investigation report for the site, an IAQ Report, and a letter regarding suitability for occupancy of the building basement. Our records indicate that this information was shared with the property owner back in 2004. We would recommend that you reach out directly to the landlord if you have any further questions, since he would be better positioned to address any work that may have been done after our involvement. Three files were attached to email. Files need to be reviewed. 11/17/17 - Obligado - spill transferred to Obligado from Omar as per Austin 1/17/2017 Austin This spill report is being transferred from Rashad Omar to Andre Obligado end. 12/19/2017 - Austin - Project transferred from Andre Obligado to Rick Lin - end 10/20/17-Lin-No elevated soil contamination was found in the soil samples and sheen was found in the monitoring wells. Based on database search, found a spill site across the street at 505 carrol st, Brooklyn (spill# 0602894). The spill at 505 carroll was reported in 2006. They found soil and groundwater contamination at the site from phase I and II and found the leak to be from an UST at the site. The UST has since been removed. Soil injection was performed to treatment the contamination. The spill was closed in 2008 based on soil and groundwater results. Since the source of the contamination was removed, any residue contamination at 512 carol is expected to

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

attenuate naturally. Case closed."

Remarks: "LAB RESULTS BACK , 5 BORINGS, OBTAINED ELEVATED READINGS TYPE OF CHEMICALS FOUND IN SOIL, SEMIVOLATILES; IN GROUND WATER HAD VOC'S MAINLY DEALING WITH BTECHS ALSO SOME SEMIVOLATILES IN GROUNDWATER"

All Materials:

Site ID:	288471
Operable Unit ID:	884268
Operable Unit:	01
Material ID:	490215
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LEAD 2:

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	102
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	103
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	104
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

Geographical District:	15
Building Code:	K834
Room:	301
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	2nd floor BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B05A BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B08
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B08A BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

Room:	B09
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B09A BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B10
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B10A BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B12
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B12A BR
Deteriorated Paint:	NO

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B14
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	B14A BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	CAF BOYS BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	CAF GIRLS BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	GYM BATHROOM BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA

P.S. 372 (OUR LADY OF PEACE)-K (Continued) **S106469867**

Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	GYM BOYS BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	GYM GIRLS BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 372 (OUR LADY OF PEACE)-K
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K834
Room:	MEZZ BOYS BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

C96 **P.S. 372 (OUR LADY OF PEACE) K 834** **NY AST** **A100295716**
North **512 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.038 mi.
199 ft. **Site 4 of 11 in cluster C**

Relative:
Lower

Actual:
21 ft.

AST:

Name:	P.S. 372 (OUR LADY OF PEACE) K 834
Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-267562
Program Type:	PBS
UTM X:	585745.85360
UTM Y:	4503353.38680
Expiration Date:	12/14/2022
Site Type:	School

Affiliation Records:

Site Id:	11110
Affiliation Type:	Mail Contact

P.S. 372 (OUR LADY OF PEACE) K 834 (Continued) **A100295716**

Company Name:	RC CHURCH OF OUR LADY OF PEACE
Contact Type:	Not reported
Contact Name:	REV. ORLANDO RUIZ, OFM
Address1:	522 CARROLL STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 624-5122
EMail:	OLP1899@AOL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	11110
Affiliation Type:	Emergency Contact
Company Name:	R C CHURCH OF OUR LADY OF PEACE
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 344-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Site Id:	11110
Affiliation Type:	Facility Operator
Company Name:	P.S. 372 (OUR LADY OF PEACE) K 834
Contact Type:	Not reported
Contact Name:	MICHAEL LANZI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 624-5271
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-02-16

Site Id:	11110
Affiliation Type:	Facility Owner
Company Name:	R C CHURCH OF OUR LADY OF PEACE
Contact Type:	PASTOR
Contact Name:	REV. ORLANDO RUIZ, OFM
Address1:	522 CARROLL ST
Address2:	Not reported
City:	BROOKLYN

P.S. 372 (OUR LADY OF PEACE) K 834 (Continued) **A100295716**

State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 624-5122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Tank Info:

Tank Number:	001
Tank Id:	18293
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1974
Capacity Gallons:	10000
Tightness Test Method:	03
Date Test:	05/01/1998
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

C97 **P.S. 372 (OUR LADY OF PEACE) K 834** **NY UST** **U004272241**
North **512 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.038 mi.
199 ft. **Site 5 of 11 in cluster C**

Relative: UST:
Lower

Actual: Name:	P.S. 372 (OUR LADY OF PEACE) K 834
21 ft. Address:	512 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-267562 / Active
Program Type:	PBS

P.S. 372 (OUR LADY OF PEACE) K 834 (Continued) **U004272241**

Region: STATE
DEC Region: 2
Expiration Date: 12/14/2022
UTM X: 585745.85360
UTM Y: 4503353.38680
Site Type: School

Affiliation Records:

Site Id: 11110
Affiliation Type: Mail Contact
Company Name: RC CHURCH OF OUR LADY OF PEACE
Contact Type: Not reported
Contact Name: REV. ORLANDO RUIZ, OFM
Address1: 522 CARROLL STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (718) 624-5122
EMail: OLP1899@AOL.COM
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-07

Site Id: 11110
Affiliation Type: Emergency Contact
Company Name: R C CHURCH OF OUR LADY OF PEACE
Contact Type: Not reported
Contact Name: MUNENDRA SHARMA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 344-5752
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-07

Site Id: 11110
Affiliation Type: Facility Operator
Company Name: P.S. 372 (OUR LADY OF PEACE) K 834
Contact Type: Not reported
Contact Name: MICHAEL LANZI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 624-5271
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-02-16

P.S. 372 (OUR LADY OF PEACE) K 834 (Continued) **U004272241**

Site Id:	11110
Affiliation Type:	Facility Owner
Company Name:	R C CHURCH OF OUR LADY OF PEACE
Contact Type:	PASTOR
Contact Name:	REV. ORLANDO RUIZ, OFM
Address1:	522 CARROLL ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 624-5122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-07

Tank Info:

Tank Number:	002
Tank ID:	63954
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	08/01/1974
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	51
Date Test:	06/08/2021
Next Test Date:	06/08/2022
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

B98 **CON EDISON** **RCRA NonGen / NLR** **1018280848**
NE **CARROLL ST & 4TH AVE** **FINDS** **NYP004757563**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.039 mi.
205 ft. **Site 10 of 24 in cluster B**

Relative: **Higher**
Actual: **26 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150325
Handler Name:	CON EDISON	
Handler Address:		CARROLL ST & 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004757563
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018280848**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150325
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150325
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018280848**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067682564

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280848
Registry ID:	110067682564
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067682564
Name:	CON EDISON
Address:	CARROLL ST & 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215

B99 **CON EDISON** **NJ MANIFEST** **S120678185**
ENE **255 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.039 mi.
208 ft. **Site 11 of 24 in cluster B**

Relative: Higher
Actual: 27 ft.

NJ MANIFEST:

EPA Id:	NYP004879932
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported

CON EDISON (Continued) **S120678185**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015320441JJK
EPA ID:	NYP004879932
Date Shipped:	12/16/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B100 **CON EDISON** **RCRA NonGen / NLR** **1019326040**
ENE **255 4TH AVE** **NYP004879932**
< 1/8 **BROOKLYN, NY 11215**
0.039 mi.
208 ft. **Site 12 of 24 in cluster B**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20151216
Handler Name:	CON EDISON	
Handler Address:		255 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215

Actual:
27 ft.

CON EDISON (Continued) **1019326040**

EPA ID:		NYP004879932
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No

CON EDISON (Continued) **1019326040**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151216
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151216
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CON EDISON (Continued) **1019326040**

Historic Generators:
Receive Date: 20160226
Handler Name: CON EDISON - MANHOLE 22633
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151216
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151216
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B101 **CON ED** **NY MANIFEST** **S118563785**
ENE **255 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.039 mi.
208 ft. **Site 13 of 24 in cluster B**

Relative:
Higher

Actual:
27 ft.

NY MANIFEST:

Name:	CON ED
Address:	255 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004879932
Facility Status:	Not reported
Location Address 1:	255 4TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004879932
Mailing Name:	CON ED
Mailing Contact:	CON ED
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

B102 **LOT 69,TAXBLOCK 961** **NY E DESIGNATION** **S117676530**
East **13 GARFIELD PLACE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.040 mi.
211 ft. **Site 14 of 24 in cluster B**

Relative:
Higher

Actual:
27 ft.

E DESIGNATION:

Name:	LOT 69,TAXBLOCK 961
Address:	13 GARFIELD PLACE
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	69
Tax Block:	961
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

C103 **CON EDISON** **RCRA NonGen / NLR** **1018280847**
NNE **DENTON ST & CARROLL ST** **FINDS** **NYP004757555**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.042 mi.
220 ft. **Site 6 of 11 in cluster C**

Relative: **Higher**
Actual: **23 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150325
Handler Name:	CON EDISON	
Handler Address:		DENTON ST & CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004757555
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018280847**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150325
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150325
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018280847**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067682555

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280847
Registry ID:	110067682555
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067682555
Name:	CON EDISON
Address:	DENTON ST & CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215

C104 **CON EDISON** **NY MANIFEST** **S118088208**
NNE **DENTON ST & CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.042 mi.
220 ft. **Site 7 of 11 in cluster C**

Relative: Higher
Actual: 23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	DENTON ST & CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004757555
Facility Status:	Not reported
Location Address 1:	DENTON PL. & CARROLL ST
Code:	BP
Location Address 2:	MH # 22621
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

CON EDISON (Continued) **S118088208**

NY MANIFEST:

EPAID:	NYP004757555
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/25/2015
Trans1 Recv Date:	03/25/2015
Trans2 Recv Date:	03/26/2015
TSD Site Recv Date:	03/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004757555
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619004GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S118088208**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C105 **CON EDISON** **NJ MANIFEST** **S120669566**
NNE **DENTON ST & CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.042 mi.
220 ft. **Site 8 of 11 in cluster C**

Relative:
Higher

Actual:
23 ft.

NJ MANIFEST:

EPA Id:	NYP004757555
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619004GBF
EPA ID:	NYP004757555
Date Shipped:	3/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120669566**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B106 **CON EDISON SERVICE BOX: 17869** **RCRA NonGen / NLR** **1025504515**
ESE **12 GARFIELD PL** **NYP005172960**
< 1/8 **BROOKLYN, NY 11215**
0.042 mi.
224 ft. **Site 15 of 24 in cluster B**

Relative: **Higher**
Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20200413
Handler Name:	CON EDISON SERVICE BOX:	17869
Handler Address:		12 GARFIELD PL
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP005172960
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No

CON EDISON SERVICE BOX: 17869 (Continued) **1025504515**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20180106
Handler Name: CON EDISON SERVICE BOX:	17869
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 17869 (Continued) **1025504515**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20200413
Handler Name: CON EDISON SERVICE BOX:	17869
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B107 **CON EDISON - SERVICE BOX 38701** **NY MANIFEST** **S120958944**
ESE **255 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.046 mi.
242 ft. **Site 16 of 24 in cluster B**

Relative:
Higher

Actual:
28 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 38701
Address:	255 1ST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004977890
Facility Status:	Not reported
Location Address 1:	255 1ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004977890
Mailing Name:	CON EDISON - SERVICE BOX 38701
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE

CON EDISON - SERVICE BOX 38701 (Continued) **S120958944**

Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

B108 **LOT 67,TAXBLOCK 961** **NY E DESIGNATION S108075326**
East **15 GARFIELD PLACE** **NY MANIFEST N/A**
< 1/8 **BROOKLYN, NY 11215**
0.048 mi.
253 ft. **Site 17 of 24 in cluster B**

Relative:
Higher

Actual:
28 ft.

E DESIGNATION:
Name: LOT 67,TAXBLOCK 961
Address: 15 GARFIELD PLACE
City,State,Zip: BROOKLYN, NY 11215
Tax Lot(s): 67
Tax Block: 961
Borough Code: BK
E-No: E-113
Effective Date: 4/30/2003
Satisfaction Date: Not reported
Ceqr Number: 03DCP030K
Ulurp Number: 030194(A)ZMK030194(A)ZMK
Zoning Map No: 16b, 16c

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

NY MANIFEST:
Name: CON EDISON - SERVICE BOX 17865
Address: 15 GARFIELD PLACE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004980361
Facility Status: Not reported
Location Address 1: 15 GARFIELD PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004980361
Mailing Name: CON EDISON - SERVICE BOX 17865
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

LOT 67,TAXBLOCK 961 (Continued) **S108075326**

Mailing Country: USA
Mailing Phone: Not reported

B109 **4TH AVE** **NY Spills** **S104787288**
ENE **CARROLL ST & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
266 ft. **Site 18 of 24 in cluster B**

Relative:
Higher

Actual:
27 ft.

SPILLS:

Name:	4TH AVE
Address:	CARROLL ST & 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0004550 / 2001-10-19
Facility ID:	0004550
Facility Type:	ER
DER Facility ID:	233095
Site ID:	287775
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-07-15
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-07-15
CID:	233
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-15
Spill Record Last Update:	2004-09-29
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 7/15/00 1qt unknown oil on 1000gal water in manhole. Liquid sample returned 19ppm PCB. Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump"
Remarks:	"con ed # 132402 no seweres or water ways sample taken clean up pending lab results no on all questions "

All Materials:

Site ID:	287775
Operable Unit ID:	825728
Operable Unit:	01
Material ID:	549288
Material Code:	0066A

4TH AVE (Continued) **S104787288**

Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B110 **LOT 7,TAXBLOCK 961** **NY E DESIGNATION** **S122872802**
East **566 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.052 mi.
275 ft. **Site 19 of 24 in cluster B**

Relative:
Higher

Actual:
28 ft.

E DESIGNATION:

Name:	LOT 7,TAXBLOCK 961
Address:	566 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	7
Tax Block:	961
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

B111 **566 CARROLL STREET** **NY VCP** **S118943359**
East **566 CARROLL STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.052 mi.
275 ft. **Site 20 of 24 in cluster B**

Relative:
Higher

Actual:
28 ft.

VCP NYC:

Project ID:	13TMP0454K,13EHAZ454K,14CVCP224K
Name:	566 CARROLL STREET
Address:	566 CARROLL STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3009610007
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.675872
Longitude:	-73.983211
Postcode:	6
Community Board:	39
Council District:	133
Census Tract:	3426950
BIN:	3009610007
NTA:	Park Slope-Gowanus

B112 **LOT 21,TAXBLOCK 352** **NY E DESIGNATION** **S108075330**
ENE **CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.053 mi.
278 ft. **Site 21 of 24 in cluster B**

Relative: E DESIGNATION:
Higher

Actual: Name: LOT 21,TAXBLOCK 352
28 ft. Address: CARROLL STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 21
Tax Block: 352
Borough Code: Not reported
E-No: E-202
Effective Date: 10/29/2007
Satisfaction Date: Not reported
Ceqr Number: 06DCP095K
Ulurp Number: 060477ZMK
Zoning Map No: 16a

Description: Air Quality - #2 Fuel Oil or #4 Fuel Oil or Natural Gas for HVAC systems
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

D113 **LOT 1,TAXBLOCK 969** **NY E DESIGNATION** **S108469614**
SSE **283 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.054 mi.
284 ft. **Site 1 of 7 in cluster D**

Relative: E DESIGNATION:
Higher

Actual: Name: LOT 1,TAXBLOCK 969
27 ft. Address: 283 4 AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 1
Tax Block: 969
Borough Code: Not reported
E-No: E-113
Effective Date: 4/30/2003

LOT 1,TAXBLOCK 969 (Continued) **S108469614**

Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

E114 **3RD AVE YARD** **NY Spills** **S102239110**
WSW **3RD AVE YARD** **N/A**
< 1/8 **BROOKLYN, NY**
0.054 mi.
287 ft. **Site 1 of 3 in cluster E**

Relative: **Lower**
Actual: **20 ft.**

SPILLS:

Name:	CON ED SITE
Address:	3RD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702955 / 2003-02-28
Facility ID:	9702955
Facility Type:	ER
DER Facility ID:	228767
Site ID:	281782
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-06-09
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1997-06-09
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-09
Spill Record Last Update:	2003-02-28
Spiller Name:	UNK
Spiller Company:	VENDORS TRUCK
Spiller Address:	UNK
Spiller Company:	001
Contact Name:	MIKE CESARE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT E2MIS 108095 09-JUN-1997 14:00:00 NO ECS BOB ECKSTEIN PROPERTY PROTECTION REPORTS THAT APPR 3 GALS OF OIL WAS SPILLED ONTO APSHALT INSIDE THE 3RD AVE GATE ON THE 1ST AVE SIDE. OIL WAS SEEN SPILLING FROM A VENDOR TRUCK THAT LEFT THE YARD. NO SEWERS AFFECTED . THE GATE IS NOW CLOSED TO RESTRICT TRAFFIC AND FACILITIES IS PUTTING DOWN OIL ABSORB TO CONTAIN SPILL. HE WILL ARRANGE CLEANUP AND CALL BACK WITH WHO IS TAKING OVER JOB. AT 1420 HRS IT WAS DETERMINED OIL WAS SPILLED FROM ONE END OF THE YARD TO THE 1ST AVE SIDE BY THE VENDOR. R WEINER WAS NOTIFIED BY THE YARD MASTER. SPILL IS BEING

3RD AVE YARD (Continued) **S102239110**

CONTAINED AND CLEANUP TO BEGIN SHORTLY. UPDATE IT HAS BEEN DETERMINED THE SPILL IS GREATER THAN 5 GALS AND THAT THE OIL IS GEAR OIL WHICH IS NONE PCB. J. FERRAUILLO IS DIRECTING CLEANUP AT THIS TIME. 1500 HRS UPDATE CONSTRUCTION MANNY SANCHEZ TO TAKE OVER CLEANUP AND TRUCK THAT SPILLED OIL IS STILL IN YARD AND IS CLEANING UP TRUCK. LIMITI 74410.....UPDATE 6/9/97 17:25HRS CLEAN UP COMPLETE 17:20HRS 6/9/97."

Remarks: "VENDOR TRUCK WAS LEAKING GEAR OIL AS IT DROVE THRU CON ED SITE CON ED ON SCENE CLEANING UP SPILL FROM PAVEMENT"

All Materials:

Site ID:	281782
Operable Unit ID:	1048818
Operable Unit:	01
Material ID:	335870
Material Code:	1045
Material Name:	gear/spindle oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	3RD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1003520 / 2010-10-18
Facility ID:	1003520
Facility Type:	ER
DER Facility ID:	228767
Site ID:	436752
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-06-29
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2010-06-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-06-29
Spill Record Last Update:	2010-10-18
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	ERT
DEC Memo:	"6/29/10-HRAHMED-Minor ConEd spill. Assigned to Feroze Mohammad.

3RD AVE YARD (Continued) **S102239110**

10/18/10 - Austin - Con Ed contained and cleaned up the release - see eDocs documents for more information - closed - end "
Remarks: "Pallet fell over and lost product onto concrete. Clean up pending."

All Materials:
Site ID: 436752
Operable Unit ID: 1187442
Operable Unit: 01
Material ID: 2182321
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Site ID: 436752
Operable Unit ID: 1187442
Operable Unit: 01
Material ID: 2182319
Material Code: 0013
Material Name: lube oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Site ID: 436752
Operable Unit ID: 1187442
Operable Unit: 01
Material ID: 2182320
Material Code: 0043A
Material Name: antifreeze
Case No.: Not reported
Material FA: Other
Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: CON ED
Address: 3RD AVE YARD
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9514611 / 2003-01-31
Facility ID: 9514611
Facility Type: ER
DER Facility ID: 228767
Site ID: 281779
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1996-02-15

3RD AVE YARD (Continued) **S102239110**

Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	257
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	2003-01-31
Spiller Name:	Not reported
Spiller Company:	NADE COMPANY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MR ROMANELLI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"vehicle leaking in con ed lot ny reg # b203zh"

All Materials:

Site ID:	281779
Operable Unit ID:	1025715
Operable Unit:	01
Material ID:	354740
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

B115 **LOT 1,TAXBLOCK 958** **NY E DESIGNATION** **S108469612**
ENE **253 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.056 mi.
298 ft. **Site 22 of 24 in cluster B**

Relative:
Higher

Actual:
27 ft.

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 958
Address:	253 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	1
Tax Block:	958
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c

LOT 1,TAXBLOCK 958 (Continued) **S108469612**

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

D116 **CON EDISON SERVICE BOX: 868** **RCRA NonGen / NLR** **1016968949**
South **100 4TH ST & 2ND AVE** **FINDS** **NYP004425880**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.057 mi. **NY MANIFEST**
299 ft. **Site 2 of 7 in cluster D**

Relative: **Higher**
Actual: **26 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140226
Handler Name:	CON EDISON SERVICE BOX:	868
Handler Address:		100 4TH ST & 2ND AVE
Handler City,State,Zip:		NEW YORK, NY 10003
EPA ID:		NYP004425880
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

CON EDISON SERVICE BOX: 868 (Continued) **1016968949**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140126
Handler Name: CON EDISON SERVICE BOX:	868
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140226
Handler Name: CON EDISON SERVICE BOX:	868
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 868 (Continued) **1016968949**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110064110260

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016968949
Registry ID: 110064110260
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110064110260
Name: CON EDISON SERVICE BOX: 868
Address: 100 4TH ST & 2ND AVE
City,State,Zip: NEW YORK, NY 10003

NY MANIFEST:
Name: CON EDISON
Address: 100 4TH ST & 2ND AVE
City,State,Zip: NEW YORK, NY 10003
Country: USA
EPA ID: NYP004425880
Facility Status: Not reported
Location Address 1: 100 E 4TH ST & 2ND AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

CON EDISON SERVICE BOX: 868 (Continued) **1016968949**

NY MANIFEST:

EPAID:	NYP004425880
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/26/2014
Trans1 Recv Date:	01/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004425880
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329120GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	Y
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	NJD991291105
Alt Facility Sign Date:	02/04/2014
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON SERVICE BOX: 868 (Continued) **1016968949**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

C117 **CON EDISON** **NY MANIFEST** **S118088207**
North **511 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.058 mi.
306 ft. **Site 9 of 11 in cluster C**

Relative:
Lower

Actual:
22 ft.

NY MANIFEST:
Name: CON EDISON
Address: 511 CARROLL ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004757548
Facility Status: Not reported
Location Address 1: 511 CARROLL ST.
Code: BP
Location Address 2: MH # 22620
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004757548
Mailing Name: CON EDISON
Mailing Contact: TOM TELLING
Mailing Address 1: 4 IRVING PLACE-15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 03/25/2015
Trans1 Recv Date: 03/25/2015
Trans2 Recv Date: 03/26/2015
TSD Site Recv Date: 03/26/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004757548
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON (Continued) **S118088207**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660491GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C118 **CON EDISON** **RCRA NonGen / NLR** **1018280846**
North **511 CARROLL ST** **FINDS** **NYP004757548**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.058 mi.
306 ft. **Site 10 of 11 in cluster C**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20150325
22 ft. Handler Name:	CON EDISON	
Handler Address:		511 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004757548
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

CON EDISON (Continued) **1018280846**

Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported

CON EDISON (Continued) **1018280846**

Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150325
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150325
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067682546

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON (Continued) **1018280846**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280846
Registry ID:	110067682546
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067682546
Name:	CON EDISON
Address:	511 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215

C119 **CON EDISON** **NJ MANIFEST** **S120669565**
North **511 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.058 mi.
306 ft. **Site 11 of 11 in cluster C**

Relative: **Lower**
Actual: **22 ft.**

NJ MANIFEST:

EPA Id:	NYP004757548
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660491GBF
EPA ID:	NYP004757548
Date Shipped:	3/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON (Continued) **S120669565**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B120 **NYCDOT BRIDGE BIN 2243210** **RCRA NonGen / NLR** **1000911985**
NE **PRESIDENT ST BRG OVER FRANKLIN** **NY0000375220**
< 1/8 **BROOKLYN, NY 11225**
0.059 mi.
312 ft. **Site 23 of 24 in cluster B**

Relative: **Higher**

Actual: **26 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NYCDOT BRIDGE BIN 2243210	
Handler Address:		PRESIDENT ST BRG OVER FRANKLIN
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NY0000375220
Contact Name:		ALEX BEZCHASTNOV
Contact Address:		RECTOR ST - 8TH FLOOR
Contact City,State,Zip:		NEW YORK, NY 10006
Contact Telephone:		212-788-2091
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Municipal
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		RECTOR ST - 8TH FLOOR
Mailing City,State,Zip:		NEW YORK, NY 10006
Owner Name:	NYCDOT	
Owner Type:		Municipal
Operator Name:	NYCDOT	

NYCDOT BRIDGE BIN 2243210 (Continued) **1000911985**

Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

NYCDOT BRIDGE BIN 2243210 (Continued) **1000911985**

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYCDOT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 RECTOR ST
Owner/Operator City,State,Zip: NEW YORK, NY 10006
Owner/Operator Telephone: 212-788-2091
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCDOT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 RECTOR ST
Owner/Operator City,State,Zip: NEW YORK, NY 10006
Owner/Operator Telephone: 212-788-2091
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYCDOT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 RECTOR ST
Owner/Operator City,State,Zip: NEW YORK, NY 10006
Owner/Operator Telephone: 212-788-2091
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYCDOT BRIDGE BIN 2243210
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

NYCDOT BRIDGE BIN 2243210 (Continued) **1000911985**

Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCDOT BRIDGE BIN 2243210
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990216
Handler Name: NYCDOT BRIDGE BIN 2243210
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B121 **LOT 2,TAXBLOCK 958** **NY E DESIGNATION** **S108469616**
ENE **249 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.059 mi.
314 ft. **Site 24 of 24 in cluster B**

Relative:
Higher

Actual:
27 ft.

E DESIGNATION:
Name: LOT 2,TAXBLOCK 958
Address: 249 4 AVENUE
City,State,Zip: BROOKLYN, NY 11215
Tax Lot(s): 2
Tax Block: 958
Borough Code: BK
E-No: E-113
Effective Date: 4/30/2003
Satisfaction Date: Not reported
Ceqr Number: 03DCP030K
Ulurp Number: 030194(A)ZMK030194(A)ZMK

LOT 2,TAXBLOCK 958 (Continued) **S108469616**

Zoning Map No: 16b, 16c

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

F122 **3RD AV YARD INFO STOREROO** **NY Spills** **S105141525**
WNW **M 222 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.060 mi.
316 ft. **Site 1 of 13 in cluster F**

Relative: SPILLS:
Lower
Actual:
17 ft.

Name:	3RD AV YARD INFO STOREROO
Address:	M 222 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0105268 / 2001-08-15
Facility ID:	0105268
Facility Type:	ER
DER Facility ID:	199793
Site ID:	243216
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2001-08-15
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2001-08-15
CID:	270
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-15
Spill Record Last Update:	2001-08-27
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY CON ED E2MIS REPORT 8-15-01 0600 Approx. 1gal. of unknown green substance mixed with approx. 2gals. of water leaking from a dumpster in front of stores. Mr. Graham has placed bolognas around the spill tocontain it. It has entered a drain. Unknown at this time as to whether it connects with the NYC sewer system. Cleanup is in progress. The substance did in infact enter the NYC sewer system. 0725hrs. Source of substance was found by facilities, Substance is a green dye used to trace water leaks. 0755hrs. While cleaning out vehicle last night, he dumped and almost empty container of water leak tracing dye into the dumpster. After rainfall, dye leaked out from dumpster. Facilities to do cleanup."
Remarks:	"unk green material discovered leaking from dumpster clean up in

3RD AV YARD INFO STOREROO (Continued) **S105141525**

progress material is a green dye used to locate water leaks "

All Materials:

Site ID:	243216
Operable Unit ID:	843634
Operable Unit:	01
Material ID:	533745
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F123 **COMMERCIAL BUILDING** **NY Spills** **S108130792**
NNW **14 WHITWELL PLACE** **N/A**
< 1/8 **BROOKLYN, NY**
0.061 mi.
322 ft. **Site 2 of 13 in cluster F**

Relative: **Lower**

Actual: **20 ft.**

SPILLS:

Name:	COMMERCIAL BUILDING
Address:	14 WHITWELL PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0606675 / 2009-03-17
Facility ID:	0606675
Facility Type:	ER
DER Facility ID:	319903
Site ID:	370045
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-09-11
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2006-09-11
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-11
Spill Record Last Update:	2009-04-20
Spiller Name:	CHARLIE DEVITO
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	14 WHITWELL PLACE
Spiller Company:	999
Contact Name:	CHARLIE DEVITO
DEC Memo:	"Need to send CSL to Property Owner: Charlie Devito Brooklyn Real

COMMERCIAL BUILDING (Continued) **S108130792**

Estate Mgt Corp. 88 Ninth Street Brooklyn, NY 11215
10/04/06-Vought-Daytime runner. Vought sent soil contamination letter with one month due date to above address. Vought called Boeckel for more information and left message to return call prior to sending letter. 8/3/07 - Austin - Transferred from Vought to Ketani for further review and action - end 9/25/07 - Raphael Ketani. I found 2 unsigned copies of an October 2, 2006 CSL letter in the record. There is also an October 26, 2006 Phase II Subsurface Investigation Report from Associated Environmental Services, Ltd. (631) 234-4280. There is no PBS record. I reviewed the Phase II Report. Borings B-1 and B-2 were tanken on either side of a suspected UST at 20-20A Whitewell Place. Boring B-3 was taken on the east (street) side of a suspected UST at 14 Whitewell Place. Only groundwater samples were collected. These were from B-2 and B-3. Groundwater sample B-2 was completely non-dectect. Groundwater sample B-3 had 2 hits that were 3 times the TAGM limit, several hits that were just above the TAGM limit and the rest non-detect. 9/26/07 - Raphael Ketani. I spoke to Matt Boeckel of Associated Environmental. He said that after the project was done, Mr. Devito didn't pursue any further activities. I asked Mr. Boeckel why only groundwater samples were taken. He said that Mr. Devito didn't want to spend any more money investigating the site. I looked up the owners of the property using Property Shark and ACRIS. I found several addresses for the owners of 20 Whitwell Place (block and lot 00454/0025). The owner is Whitwell Place Realty Corp. at either 20 Whitwell Place, Brooklyn or 335 Chelsea Road, Staten Island. There was another Brooklyn address at 88 9th Street, Brooklyn, 11215. The 9th Street address is the latest one. I looked up the owners of the property at 14 Whitwell Place (block and lot 00454/0022). ACRIS listed Frozen Music Incorp., 10 Whitwell Pl., Brklyn., and Property Shark listed C.W. Grinnell, 325 E. 41 Street, Ste 501, NY, 10017. As the 14 Whitwell Place site had the indications of contamination, I will pursue the remediation of this location only. I sent a CSL to both addresses for the owners. 10/2/07 - I received a call today from Daniel Wax regarding the CSL. He said that DEC had the wrong property and that no borings were done on his site. He said that Frozen Music Incorporated and Ms. Grinnell owned 10 Whitwell Place, but this is not where the boring occurred. He said that the NYC Property database and ACRIS listed Ms. Grinnell and his company as the owner of 14 Whitwell, but this has been a mistake that he has not been able to correct. He asked what he should do. I asked him who owned 14 Whitwell. He said he didn't know. I told him that I will look into the matter. I tried to contact Mathew Boeckel of Associated Environmental, but could only leave a message. 10/3/07 - Raphael Ketani. I made an unannounced site visit. The site is a red painted 3 story building. It contains offices for a book company, a lobster company, and some other business on the ground floor. I met Roger Coy, a tenant who rents an office on an upper floor of the building. He called up the owner of the property, Charlie Devito (914) 482-5520 (Ninth Street Storage). I spoke to Mr. Devito and explained that Associated Environmental Services had done a boring on the property which had discovered contaminated soil next to an anomaly that was never defined. He said that he was aware of the investigation. He said that he thought the anomaly was a tank that had never been removed. I told him that a larger investigation was necessary to delineate the contamination and that the tank has to be either closed in place or removed. I told him he had to hire an environmental company and start the work. He said he will do this and he will

COMMERCIAL BUILDING (Continued) **S108130792**

contact me later in the week. Mr. Devito's company is Ninth Street Self Storage, 88 9th Street, Brooklyn, 11231, (718) 788-0880. A CSL was sent out today to Mr. Devito. 12/3/07 - Raphael Ketani. I tried to contact Mr. Devito, but could only leave a message with his secretary. 12/12/07 - Raphael Ketani. I tried to contact Mr. Devito, but could only leave a message with the secretary. I told her that if DEC doesn't hear from him towards the end of regular business hours, then we will send a warning letter. Mr. Devito called me back. He said that he had lost the letter and that is why nothing has taken place to date. I FAXed him (718) 788-3233 the 10/3/07 letter. He said that he will give it to Associated Environmental. 12/27/07 - Raphael Ketani. Bill Locke of Trade Winds Environmental (631) 289-5500 called. He said he was putting together a proposal for Mr. Devito. He said there is an inactive 550 tank buried behind a brick wall under the back half of the property. Then there are two active 275 gal. tanks in the half basement in the front part of the property. He said that he will abandon or pull all three tanks. He said he will do at least 6 soil borings to investigate the fill port, fill line and tanks. 1/3/08 - Raphael Ketani. I tried to reach Mr. Locke, but could only leave a message. 1/7/08 - Raphael Ketani. Mr. Locke called back. He said that he plans to start the investigation at the site today. 1/10/08 - Raphael Ketani. I spoke to Doug Schrimpf (cell (516) 779-7822) of Trade Winds. He is the project manager and contact. His crew removed 2 ASTs in the basement. The tanks were in good condition and not leaking. The old fuel line to the old UST was rotten and leaking and 2 drums of contaminated soil were removed. More soil will be removed. They will expose the line in its entirety to see if it leaked in other locations. Borings will be done through the bottom of the old UST after it is cleaned out. I will meet Mr. Schrimpf tomorrow at the site. 1/11/08 - Raphael Ketani. I made the site visit at about 12:30PM. I met Carol, the head of the work crew. I took 3 pictures. He showed me the 1,000 gal. tank that had been cut open. It looked very clean inside and was odor free. He showed me the fuel pipes that his crew was following and trying to expose. He said he wasn't sure where they will lead him, but he was hoping that, somewhere, they will contact to the 1,000 gal. tank which wasn't completely exposed yet. After my overview of the situation, I left the site. Later, I spoke to Mr. Schrimpf. I told him that it looked like his crew was doing a good job. I also told him that since there was a 1000 gal. tank and two 275 gallon tanks, this puts the site over the 1100 gal. ceiling for total capacity. I told him that all 3 tanks need to be registered. He said he will do this and he will keep me informed of the progress. 1/15/08 - Raphael Ketani. I spoke to Mr. Schrimpf today. He said that his crew exposed the rest of the fuel and return line, but found no contamination. So they filled the 1000 gallon tank with sand and abandoned it in place. They also filled the old fill port in the basement with cement. He said he that three soil samples were taken below the bottom of the tank and he will attempt a boring in the sidewalk to see whether there is any contamination. 4/2/08 - Raphael Ketani. I spoke to Mr. Schrimpf (cell (516) 779-7822). He said Mr. Locke is the one I should be speaking to regarding the report. He said he will talk to Mr. Locke and get everything out to me. 8/18/08 - Raphael Ketani. I spoke to Mr. Locke. He said that Mr. Devito, the owner, owes him thousands of dollars. So he can't release the report. He said Mr. Devito is paying him in drips and drabs. The case is being prepared for transfer due to a case realignment within the unit. The case manager needs to send Mr.

COMMERCIAL BUILDING (Continued) **S108130792**

Devito a warning letter stating that he is in violation of the NAV Law and the regulations because DEC has no documentation that the spill is cleaned up. 9/19/08 - Raphael Ketani. Mr. Schrimpf called me. He asked whether I had ever received the remediation report. I told him no. He asked why. I told him that from the case notes describing my conversations with Mr. Locke, the report wasn't going to be released until Mr. Devito payed Trade Winds in full for the work. He said he will put the report together, but he will let Mr. Devito know that it wont be sent until payment is received. 2/27/09 - Raphael Ketani. Mark Pasco of Analytical Testing Labs (a consulting firm) (908) 241-5040 called to find out the status of the site. He represented a bank involved with a potential purchaser. I told him that I was no longer the case manager and to talk to Veronica Zhune. However, I also told him that Trade Winds is out of business and that DEC never received the investigation-remediation report. He said that he will talk to Ms. Zhune. 2/27/09- Melissa DiBella 718-482-4984 from whitwell Place Realty Corp. faxed the report. The report included: 1. A cover letter to the report. 2. Afidavit 3. Two manifest for waste disposal and oil disposal 4. Chain of custody Endpoint soil Samples Results 5.Site Map. The letter states: Trade-Winds Environmental Restoration Inc. was contracted by property owner to remove (2)275 gallon AST containing fuel oil and abandon or remove(1) 550 gallon UST containing fuel oil. Subsurface sampling was conducting by property owners previuos Environmental Contractor and a NYSDEC Spill number 0606675 was assigned to property. On January 7th, 2008 Trade-Winds Environmental removed, cut and cleaned (2)275 gallon AST that contained fuel oil and disposed of them at a permitted disposal facility. In addition Trade-Winds project team excavated and exposed (1)550 gallon UST that contained fuel oil. During the process of exposing (1) 550 gallon tank Trade-Wind encountered fuel oil contaminated soil around tank. All oil impacted soils were excavated and placed in 55 gallon drums and the total of 7 drums were generated. Trade-winds project team then cut an opening into tank and entered tank and decontaminated tank interior. Tank excavation and decontaminated tank was left open for NYSDEC inspection. Based on inspection NYSDEC case manager required to collect samples from beneath tank and samples from tank excavation. Three holes were cut in bottom of tank (East, Middle, West) and soil samples were collect at each location. In addition 3 samples were taken from tank excavation for a total of 6 samples. Soil samples were analyzed for methods 8260 and 8270 and forwarded to NYSDE case manger for review. On January 15th ,2008 completed the abandoment of the 550 gallon fuel oil tank was filled to 100% capacity with masonry sand and excavation and new concrete slab were completed. The analytical results identified VOC's and SVOC's below the minimun detection limit for samples #2(Tank Middel and #3(Tank west). Sample #1 Tank East results identified VOC's below the minimun detection limit but some SVOC's (Benzo-b-fluoroanthene, Benzo-k-fluoroanthene, Benzo-1-pyrene, Indeno (1.2.3,-c,d)Pyrene and Dibenzo-a,h anthracene) were exceding the NYCSDEC Recomended Soil Cleanup Objectives (RSCOs). The analytical results identified VOC's and VOC's below the minimun detection limit for samples #4(Excavation middle), #5(East Excavation). Sample #6(Tank top)results showed VOC's below the minimun detection. Some SVOC's (Phenanthrene, Anthracene, Fluoranthene, Benzo-a-anthracene, Chrysene, Pyrene, Benzo-b-fluoroanthene, Benzo-k-fluoroanthene, Benzo-a-pyreneIndeno (1.2.3,-c,d)Pyrene, Dibenzo-a,h anthracene and benzo-g,hy,i perylene) were exceding the NYCDEC Recomended Soil

COMMERCIAL BUILDING (Continued) **S108130792**

Cleanup Objectives (RSCOs). 03/16/09-Zhune called Doug Schrimf from trade-winds to find out about SOV's contamination in sample #6. As per Doug all oil impacted soil were excavated and removed. Spill Closed. "

Remarks: "voc's above standards:"

All Materials:

Site ID:	370045
Operable Unit ID:	1127866
Operable Unit:	01
Material ID:	2117472
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G124 **CON EDISON** **NY MANIFEST** **S117740711**
ESE **22 GARFIELD ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.066 mi.
347 ft. **Site 1 of 11 in cluster G**

Relative:
Higher

Actual:
30 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	22 GARFIELD ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004738910
Facility Status:	Not reported
Location Address 1:	22 GARFIELD PL
Code:	BP
Location Address 2:	SB 17870
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738910
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported

CON EDISON (Continued) **S117740711**

Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2015
Trans1 Recv Date:	02/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610324GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G125
ESE
< 1/8
0.066 mi.
347 ft.

CON EDISON
22 GARFIELD ST
BROOKLYN, NY 11215

Site 2 of 11 in cluster G

NJ MANIFEST **S120667931**
N/A

Relative:
Higher

Actual:
30 ft.

NJ MANIFEST:

EPA Id:	NYP004738910
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610324GBF
EPA ID:	NYP004738910
Date Shipped:	2/26/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667931**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

G126 **CON EDISON** **RCRA NonGen / NLR** **1018279093**
ESE **22 GARFIELD ST** **FINDS** **NYP004738910**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.066 mi.
347 ft. **Site 3 of 11 in cluster G**

Relative: **Higher**
Actual: **30 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150226
Handler Name:	CON EDISON	
Handler Address:		22 GARFIELD ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004738910
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1018279093**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150226
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150226
Handler Name: CON EDISON	

CON EDISON (Continued) **1018279093**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067685865

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279093
Registry ID:	110067685865
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067685865
Name:	CON EDISON
Address:	22 GARFIELD ST
City,State,Zip:	BROOKLYN, NY 11215

H127 **LOT 4,TAXBLOCK 958** **NY E DESIGNATION** **S108469617**
ENE **245 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.066 mi.
349 ft. **Site 1 of 11 in cluster H**

Relative: **Higher**
Actual: **27 ft.**

E DESIGNATION:

Name:	LOT 4,TAXBLOCK 958
Address:	245 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	4
Tax Block:	958

LOT 4,TAXBLOCK 958 (Continued) **S108469617**

Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

H128 **L&B AUTO REPAIR CORP. II** **NY AST** **A100183296**
ENE **245 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.066 mi.
349 ft. **Site 2 of 11 in cluster H**

Relative:
Higher

Actual:
27 ft.

AST:

Name:	L&B AUTO REPAIR CORP. II
Address:	245 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-606714
Program Type:	PBS
UTM X:	585896.87257
UTM Y:	4503322.95309
Expiration Date:	08/20/2016
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	28571
Affiliation Type:	Facility Owner
Company Name:	L&B AUTO REPAIR CORP. II
Contact Type:	PRES
Contact Name:	WATFA EID
Address1:	245 4TH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 398-6228
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-05-18

Site Id:	28571
Affiliation Type:	Mail Contact
Company Name:	L&B AUTO REPAIR CORP. II
Contact Type:	PRES
Contact Name:	WATFA EID
Address1:	245 4TH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY

L&B AUTO REPAIR CORP. II (Continued) **A100183296**

Zip Code:	11215
Country Code:	001
Phone:	(718) 398-6228
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-05-18

Site Id:	28571
Affiliation Type:	Facility Operator
Company Name:	L&B AUTO REPAIR CORP. II
Contact Type:	Not reported
Contact Name:	WATFA EID
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 398-6228
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Site Id:	28571
Affiliation Type:	Emergency Contact
Company Name:	L&B AUTO REPAIR CORP. II
Contact Type:	Not reported
Contact Name:	WATFA EID
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 398-6228
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Tank Info:

Tank Number:	001
Tank Id:	61804
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None

L&B AUTO REPAIR CORP. II (Continued) **A100183296**

I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1995
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

H129 **241 - 245 4TH AVENUE** **NY VCP** **S125316943**
ENE **245 4TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.066 mi.
349 ft. **Site 3 of 11 in cluster H**

Relative: **Higher**
Actual: **27 ft.**

VCP NYC:

Project ID:	16TMP0220K,16EHAZ204K,17CVCP027K
Name:	241 - 245 4TH AVENUE
Address:	245 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0095800043009499E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.676388
Longitude:	-73.983726
Postcode:	6
Community Board:	39
Council District:	133
Census Tract:	3000000
BIN:	3009580004
NTA:	Park Slope-Gowanus

D130 **CON EDISON CO. OF NY INC. @ F/T FACILITY** **NY SWF/LF** **S105841902**
South **3RD AVE (BET. 3RD & 4TH)** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.068 mi.
360 ft. **Site 3 of 7 in cluster D**

Relative: **Higher**
Actual: **27 ft.**

SWF/LF:

Name:	CON EDISON CO. OF NY INC. @ F/T FACILITY
Address:	3RD AVE (BET. 3RD & 4TH)
City,State,Zip:	BROOKLYN, NY 11215

CON EDISON CO. OF NY INC. @ F/T FACILITY (Continued) **S105841902**

Flag:	INACTIVE
Region Code:	2
Phone Number:	2124604833
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	HARRY A. COATES
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W18]
Active:	No
East Coordinate:	585800
North Coordinate:	4503100
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6103-00073
Authorization Date:	1/24/1991
Expiration Date:	1/24/1996
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

D131 **LOT 7504,TAXBLOCK 974** **NY E DESIGNATION** **S113453326**
South **302 2 STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.072 mi.
380 ft. **Site 4 of 7 in cluster D**

Relative:
Higher

Actual:
27 ft.

E DESIGNATION:

Name:	LOT 7504,TAXBLOCK 974
Address:	302 2 STREET
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	7504
Tax Block:	974
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

H132 **243 DEVELOPMENT LLC** **NY MANIFEST** **S120959647**
ENE **243-245 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.073 mi.
384 ft. **Site 4 of 11 in cluster H**

Relative:
Higher

Actual:
28 ft.

NY MANIFEST:

Name:	243 DEVELOPMENT LLC
Address:	243-245 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000229906
Facility Status:	Not reported
Location Address 1:	243-245 4TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000229906
Mailing Name:	243 DEVELOPMENT LLC
Mailing Contact:	243 DEVELOPMENT LLC
Mailing Address 1:	478 ALBANY AVE #88
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11203
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2122084614

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR986649705
Trans2 State ID:	Not reported
Generator Ship Date:	06/30/2017
Trans1 Recv Date:	06/30/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/30/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000229906
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	017128989JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N

243 DEVELOPMENT LLC (Continued) **S120959647**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50760
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H133 **LOT 5,TAXBLOCK 958** **NY E DESIGNATION** **S108469618**
ENE **243 4 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.073 mi.
384 ft. **Site 5 of 11 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

E DESIGNATION:

Name:	LOT 5,TAXBLOCK 958
Address:	243 4 AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	5
Tax Block:	958
Borough Code:	Not reported
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

H134 **245 4TH AVENUE LLC** **RCRA NonGen / NLR** **1019909619**
ENE **243-245 4TH AVE** **FINDS** **NYR000229906**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.073 mi.
384 ft. **Site 6 of 11 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20170418
Handler Name:	245 4TH AVENUE LLC	
Handler Address:		243-245 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000229906
Contact Name:		JAMES MUELLER
Contact Address:		BROADWAY SUITE 203
Contact City,State,Zip:		BROOKLYN, NY 11211
Contact Telephone:		718-388-8686
Contact Fax:		631-234-4297
Contact Email:		JOHNS@ASSOCENVSVCS.COM
Contact Title:		SITE DEVELOPER ZEPHYR CONSTRUCTION MGMT LLC
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		PROSPECT PARK WEST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	243 DEVELOPMENT LLC	
Owner Type:		Private
Operator Name:	HAYSHA DEITSCH	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

245 4TH AVENUE LLC (Continued) **1019909619**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170530
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: 243 DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20151214
Date Ended Current:	Not reported
Owner/Operator Address:	1 PROSPECT PARK WEST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-388-8686
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

245 4TH AVENUE LLC (Continued) **1019909619**

Owner/Operator Indicator:	Operator
Owner/Operator Name: HAYSHA DEITSCH	
Legal Status:	Private
Date Became Current:	20151214
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HAYSHA DEITSCH	
Legal Status:	Private
Date Became Current:	20151214
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: 243 DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20151214
Date Ended Current:	Not reported
Owner/Operator Address:	1 PROSPECT PARK WEST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-388-8686
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20170418
Handler Name: 245 4TH AVENUE LLC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20161103
Handler Name: 245 4TH AVENUE LLC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

245 4TH AVENUE LLC (Continued) **1019909619**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

NAICS Code: 811191
NAICS Description: AUTOMOTIVE OIL CHANGE AND LUBRICATION SHOPS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070122146

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909619
Registry ID: 110070122146
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110070122146
Name: 245 4TH AVENUE LLC
Address: 243-245 4TH AVE
City,State,Zip: BROOKLYN, NY 11215

H135 **2 FAMILY HOUSE** **NY AST** **U003128902**
ENE **557 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.073 mi.
386 ft. **Site 7 of 11 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

AST:
Name: 2 FAMILY HOUSE
Address: 557 CARROLL ST
City,State,Zip: BROOKLYN, NY 11215
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed

2 FAMILY HOUSE (Continued) **U003128902**

Facility Id: 2-201928
Program Type: PBS
UTM X: 585935.10324
UTM Y: 4503285.77438
Expiration Date: N/A
Site Type: Private Residence

Affiliation Records:

Site Id: 6886
Affiliation Type: Facility Owner
Company Name: LOISE CORSOVER & JOHN P ALESSI
Contact Type: Not reported
Contact Name: Not reported
Address1: 557 CARROLL ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (718) 857-3655
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 6886
Affiliation Type: Mail Contact
Company Name: LOISE CORSOVER & JOHN P ALESSI
Contact Type: Not reported
Contact Name: Not reported
Address1: 557 CARROLL ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (718) 857-3655
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 6886
Affiliation Type: Facility Operator
Company Name: 2 FAMILY HOUSE
Contact Type: Not reported
Contact Name: LOISE CORSOVER & JOHN P ALESSI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 857-3655
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

2 FAMILY HOUSE (Continued) **U003128902**

Site Id:	6886
Affiliation Type:	Emergency Contact
Company Name:	LOISE CORSOVER & JOHN P ALESSI
Contact Type:	Not reported
Contact Name:	LOISE CORSOVER & JOHN P ALESSI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 857-3655
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	11503
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1955
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

I136 **505 CARROLL ST.** **NY AST** **A100173503**
NNW **505 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.074 mi.
389 ft. **Site 1 of 4 in cluster I**

Relative:
Lower

Actual:
20 ft.

AST:

Name:	505 CARROLL ST.
Address:	505 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602516
Program Type:	PBS
UTM X:	585746.33907
UTM Y:	4503379.52312
Expiration Date:	N/A
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	24473
Affiliation Type:	Emergency Contact
Company Name:	505 CARROLL ST. DEVELOPMENT GROUP LLC
Contact Type:	Not reported
Contact Name:	JUSTA VIAFARA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 875-7257
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-03

Site Id:	24473
Affiliation Type:	Facility Operator
Company Name:	505 CARROLL ST.
Contact Type:	Not reported
Contact Name:	JUSTA VIAFARA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 875-7257
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-03

Site Id:	24473
Affiliation Type:	Facility Owner
Company Name:	505 CARROLL ST. DEVELOPMENT GROUP LLC
Contact Type:	MEMBER
Contact Name:	MARIO PROCIDA

505 CARROLL ST. (Continued) **A100173503**

Address1:	456 E. 173RD ST.
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10457
Country Code:	001
Phone:	(718) 299-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-03

Site Id:	24473
Affiliation Type:	Mail Contact
Company Name:	PROCIDA REALTY & CONSTRUCTION
Contact Type:	Not reported
Contact Name:	SARAH WILLIAMS
Address1:	456 EAST 173RD ST.
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10457
Country Code:	001
Phone:	(718) 299-7000 234
EMail:	SWILLIAMS@SDSPROCIDA.COM
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-03

Tank Info:

Tank Number:	1
Tank Id:	50341
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G01 - Tank Secondary Containment - Diking (Aboveground)
	I05 - Overfill - Vent Whistle
	J01 - Dispenser - Pressurized Dispenser
	H00 - Tank Leak Detection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

505 CARROLL ST. (Continued) **A100173503**

Date Tank Closed:	10/11/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

I137 **PROCIDA REALTY** **NY Spills** **S107782960**
NNW **505 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.074 mi.
389 ft. **Site 2 of 4 in cluster I**

Relative: **Lower**

Actual: **20 ft.**

SPILLS:

Name:	PROCIDA REALTY
Address:	505 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0602894 / 2008-10-20
Facility ID:	0602894
Facility Type:	ER
DER Facility ID:	315605
Site ID:	365475
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-06-15
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2006-06-15
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-06-15
Spill Record Last Update:	2008-10-20
Spiller Name:	MARIO PROCIDA
Spiller Company:	PROCIDA REALTY
Spiller Address:	505 CARROLL STREET
Spiller Company:	001
Contact Name:	MARIO PROCIDA
DEC Memo:	"Sangesland spoke to Marc Califano at Galli Engineering. The building was just purchased and the new owner wanted some work done in the basement. Soil borings were taken through the basement floor and groundwater was found with a sheen on it. They believe there is a 500 gal UST under the floor. This will be investigated in the next couple of days. CSL was sent out to Mr. Mario Procida (owner) 7/14/06 - Raphael Ketani. I tried calling Mr. Procida (718) 299-7000 and Marc Califano of Galli Engineering (631) 271-9292, but could only leave messages. There is a PBS case #2-602516 showing an active 3000 gal. tank with #2 oil. Mr. Califano called me back. He said that the GPR anomalie turned out to be a very old brick and mortar cesspool with feces and oil on the water, not a tank. He took a sample and sent it

PROCIDA REALTY (Continued) **S107782960**

off to a lab for analysis. Once he gets the results back, he will know what to do with the water and oil. He said there is an AST and they will pressure test it. Presently, there are 6 boilers in this commercial building. Some work and some don't. Mr. Califano will send me a RAP. 7/17/06 - Raphael Ketani. I returned Mr. Procida's call (646) 201-0489, but could only leave a voice mail message describing what Mr. Califano and I talked about last friday, 7/14. 7/31/06 - Raphael Ketani. I received a call from Nick Pressly of Pressly & Associates, Inc. (607) 264-9521. He said that he is the environmental consultant for Mr. Procida. He said that Galli Engineering was working for Mr. Greco, the partner, but Mr. Procida is taking the lead. The company address is: 721 County Highway 54, Cherry Valley, NY, 13320. He mentioned that the building is slated for demolition and the soil is scheduled to be removed in 3 years. He asked whether DEC can wait 3 years for cleanup of the site in order to coordinate the 2 projects. I told him that the Spills Unit can't wait so long and that DEC wants a quick cleanup of the site. He mentioned that there is a 550 gal. UST that is filled with sand at the site, aside from the AST. I told him that soil borings will have to be done around the UST and analytical results sent to the DEC. He said he already had the results and will send them to me. I told him that the AST has to be tested, and if it passes, then I will just need the passing tank test report. If it fails, I told him, then I will need soil sampling around this tank, too. I told him that the water in the cesspool will need to be tested and that all of the information should be in an RAP. Mr. Pressly told me that he will put together an RAP and send it to me. 8/8/06 - Raphael Ketani. I tried calling Mr. Pressly, but could only leave a voice mail. 8/10/06 - Raphael Ketani. Mr. Pressly called me and said that he will send me the documents I need tomorrow. He said the RAP will follow next week. 8/16/06 - Raphael Ketani. I received the Phase I and Phase II Environmental Site Assessment reports yesterday. They were produced by Galli Engineering and were dated 1/5/06 and 4/18/06, respectively. The Phase II report indicates that there are no VOC exceedences for the 6 soil samples, but each soil sample has 7 SVOC exceedences, on average, of TAGM RSCOs. The SVOC exceedences are high for SB-5 and very high for SB-6, but the reason for this is not apparent from the soil descriptions in the report, nor from the soil core pictures. The groundwater results for BW-1 had 4 VOC exceedences and 3 SVOC exceedences, but they were not much above TAGM. 8/17/06 - Raphael Ketani. Mr. Pressly called to find out what DEC wanted in an RAP. I told him that I didn't see the need for soil digging based on the VOC and SVOC results alone. I told him that though the SVOCs were high to very high from SB-5 and SB-6, these were combustion products. Also, I told him that the groundwater contamination was not high enough to justify pumping it. Mr. Pressly added that there are a lot of old pipes in the boiler room which no one knows what they lead to or whether there is any free product in them. Additionally, he said that his contractor has already found oil in a pit he dug. I told Mr. Pressly that for these reasons there should be further investigation. He agreed and said that these items will be in the RAP. 8/28/06 - Raphael Ketani. I reviewed the 8/17/06 RAP from Pressly and Associates, Inc. I found it to be satisfactory. However, there was no mention of sampling the liquid in the cesspool. I will send a response letter requesting that sampling be done. 9/29/06 - Raphael Ketani. Mr. Pressly tried to call me. I returned his call (607) 264-9521, but could only leave a voice mail. Mr. Pressly called me

PROCIDA REALTY (Continued) **S107782960**

back and filled me in on what has been taking place. The progress was: removed 4 layers of laid brick soaked with oil in the center of the area where they're working cesspool was 7' deep, pumped it out and cut and sealed a pipe that was feeding storm water found water 2' below floor tank test was done - vent pipe failed, will repair and retest - if fails, will do boring water and oil keep seeping in - already removed 18 drums full tested 2'X2' test pits around center area - no oil was a sheen on water in test pits - pumped center area and they dried up no idea where oil from - adjacent property? or when bricks laid? if tank found tight after repair, will dig 3 more feet down in center, total of 8 feet, and put in 6 well hit old bricks wall and found everything all black - old coal chute? water could be coming through a path via bricks or structures - don't know will put boring next to tank even if found tight center hole stayed dry for several days, then seeping started with oil and water building uses only gas I suggested to Mr. Pressly to sample oil and water separately and send off to lab for fingerprinting to determine whether water is from water main (high chlorides) and whether oil is #6 from adjacent building using #6. He agreed to do this. I also told him that the solution may be to periodically pump out the water collecting in the well (8' deep pit) until is just water. He said he will think about this as $60,000 has already been spent on the project. 10/25/06 - Raphael Ketani. Mr. Pressly called with an update: boiler room was remediated - filled 20 drums with an oil/water mix dug 7 test pits in the floor under floor was 7 layers of brick enlarged central hole in room to 20 feet to collect more oil dug down 4 feet below water table to facilitate collecting more oil tested the 2400 gal. tank with #2 fuel oil in the next room - pipes from tank to boiler failed badly - couldn't hold any pressure did boring next to tank - had 16 of oil in hole will pump out tank, remove tank and excavate soil as much as possible will submit proposal to Procida for tank emptying, removal, soil excavation and further remediation contractor has to leave to start another job on Rikers Island - I told Mr. Pressly that would be alright as long as things keep moving. He said he will send me an interim report for the work that has already been done. Mr. Pressly said that work will resume in January. 3/9/07 - Raphael Ketani. I tried calling Mr. Pressly (607) 264-9521, but could only leave a voice message. 3/12/07 - Raphael Ketani. Mr. Pressly returned my phone call today. He said that the tank had been cleaned out and will be removed soon. He said that all of the oil contaminated soil and material will be removed. His company was finally paid for all of the work and so the interim report will be sent soon. 4/10/07 - Raphael Ketani. I received the Interim Remediation Report dated 4/4/07 and received by DEC on 4/6/07. The report contained a log for the days that work was done, hand drawn plans for the boiler room at several different stages of boiler and equipment removal and site investigation, color pictures of what was found, analytical results, and a bill from Environmental Closures for all of the debris that was removed. The soil analytical results were for TH-1 to TH-3, and TH-8. TH-2 was completely non-detect, and TH-3 and TH-8 had several hits each, but these were well below the RSCO limits. TH-1 had 6 VOC hits and 2 SVOC hits, but they were all below the RSCOs. 7/25/07 - Raphael Ketani. I tried to call Mr. Pressly (607) 264-9521, but could only leave a message. From my 10/25/06 notes, it was stated by Mr. Pressly that the work will resume in January. 9/28/07 - Raphael Ketani. The tank that was removed is still listed as in service. I received a call from

PROCIDA REALTY (Continued) **S107782960**

Cristine Beaver of Dvirka & Bardilucci Consulting Engineers (516) 364-9890, ext 3056. She said her company is the consulting company for the NYC School Construction Authority and the SCA is thinking of buying the building. She wanted to know the status of the site. She said that she had some records and reports at her office, but it was very confusing. I explained to her what was going on. She said the oil tank has been cleaned out, but it is still there. I called up Mr. Pressly and he said that nothing has happened because he hasn't been involved in the project for a while. I asked him about the cesspool. He said that it wasn't a cesspool, but merely a depression. I asked him about the oil in the holes. He said that it has been removed. He added that only the oil below the leaking tank wasn't removed. He suggested that the owners were looking for a remediation contractor and that I call Ryan Tunstall (718) 299-7000, ext 216 directly. I tried to reach Mr. Tunstall, but could only leave a message. 10/17/07 - Raphael Ketani. I tried to reach Mr. Tunstall, but could only leave a message. I gave him one week to return my call, or else DEC will start to initiate some type of action. I checked the PBS registration. The 3,000 gal. tank is still listed as in service. The following items need to take place: 1) PBS revision to show the tank as removed 2) removal of oil below the former tank location with end point samples 3) removal of oil and contaminated soil and debris that may be remaining at site 10/22/07 - Raphael Ketani. I spoke with Mr. Procida and Sarah Williams (project manager for the development of the site). Mr. Procida asked that DEC hold off 1 year before requiring the removal of the contaminated soil that was below the tank. He said this was because there may be extensive contamination and it would be easier to get it when the building is down (he wants to convert the property to apartment housing). I told him that DEC wont wait so long for the property to be remediated. I told him that the tank has to be registered as removed, the contaminated soil has to be removed and end-points taken. He said that he will get Mr. Pressly to come back and do soil sampling where the tank used to be. If the contamination is not extensive and deep, then he will have it removed very soon. He asked that I give him some time to have the sampling done, the analytical results returned and a determination made as to what will happen. I told him that will be alright. I also told him that any open wells should be checked for more returning oil. He said this will be done. Mr. Pressly (607)264-9521 called me back. He said that Mr. Procida contacted him to do the work of investigating the soil that was under the tank. He said he will put together the proposal to Mr. Procida and that, hopefully, he will be able to start soon. 11/6/07 - Raphael Ketani. I tried to contact Mr. Pressly, but could only leave a message. The tank is still listed as in service. Mr. Pressly called me back. He said that Sarah Williams, the company's attorney, called him and asked for his work proposal. He said that he will correct the PBS and submit his proposal by sometime next week. 11/7/07 - Raphael Ketani. Mr. Pressly (607) 264-9521 called to say that geoprobing will begin at the site on 11/16/07. I received a letter from Sarah Williams, Esq., of 505 Carroll Street Development Group, LLC. Attached to the letter was a copy of tank removal/abandonment affidavit from A.L. Eastmond. 11/15/07 - Raphael Ketani. Mr. Pressly called to say that he filled out the PBS form and was sending it in with a check. 11/20/07 - Raphael Ketani. Mr. Pressly called with an update. He said he put in a boring near the door to the boiler room. He did borings south of the first one and found oil at two locations in the soil at 33' and

PROCIDA REALTY (Continued) **S107782960**

63' away, but not further from the first boring at 114' away. Then he did boring PB-5 and found oil. There was oil at 30' from PB-5, but not at 130' away. The water table is at 3' to 5' below the basement floor. Mr. Pressly said that it's a big, old oil spill - a huge spill - and that the best way to clean it up would be to dig it up after the building is torn down. He said he thought that because of the high water table, the foundation was constraining the oil contamination. I asked him how long will it be before the building is demolished. He said 12 to 18 months. I told him Spills can't wait that long. He said he will talk to the owners of the site and see what their plans are. 12/3/07 - Raphael Ketani. I checked the PBS registration. It still shows the tank as active. 12/14/07 - Raphael Ketani. Today I received a letter report dated 12/11/07 from Pressly & Associates regarding a soil investigation of the site. I reviewed the report. The soil analyticals were below TAGM, with the exception of total xylenes for SB-1. SB-2 was a composite sample. SB-3 was never tested for. SB-4 was broken in transport. 12/17/07 - Raphael Ketani. I tried to contact Mr. Pressly about the report, but could only leave a message. 12/18/07 - Raphael Ketani. I spoke to Mr. Pressly and asked him about the sampling that was performed. He said that SB-3 looked a lot like PB-2 in the soil cores. So he didn't send off a sample for SB-3. I asked him why he did a composite of SB-2 and SB-5. He said that both soil cores looked equally contaminated. I told Mr. Pressly that, in the future, a sample should be sent off from each boring that is done whether or not they look the same during a visual inspection. I told him this is how DEC wants the sampling done. He said he will do this in the future. I told Mr. Pressly that DEC wants the oil to be remediated now, not in 2009. I told him his company can either arrange to have it dug out or do soil treatment. He said that soil treatment would be the preferred method as there are rows of shelves with large heavy fabric rolls in the building. The site is an active fabric warehouse and the rolls can't be moved anywhere. I told him this is fine and to send a remediation plan for DEC approval. He said he will. I sent a letter to Sarah Williams, Esq. explaining that soil remediation has to take place now, not in 2009, and that the tank has to be listed as closed and removed. 12/24/07 - Raphael Ketani. I received a copy of the PBS registration form for the 3000 gal. tank. In an attached letter to me, Ms. Williams stated that the signed form went to Albany PBS. 1/2/08 - Raphael Ketani. I received a FAXed copy of a letter Ms. Williams had sent to Albany DER for registering the tank as removed, along with a change in ownership for the site. This is a response letter to DER returning the PBS application as incomplete. Her original PBS application was returned as it was missing ownership information, the federal tax I.D., the date of tank removal and documentation. 1/8/08 - Raphael Ketani. Mr. Pressly (607) 264-9521 called regarding how many soil samples to take after the soil treatment solution has been injected. He said that he is using RegenOx. The company supplying the chemical told him it takes only 3 weeks to break down the oil. I told him that the longer the chemical is allowed to react, the lower the contamination concentrations will be. He said he will do 6 treatment confirmation borings. I told him that sounded fine. 1/11/08 - Raphael Ketani. Today I received a short cover letter with a copy of the corrected PBS registration attached showing that the 3000 gal. tank is listed as closed and removed. 1/15/08 - Raphael Ketani. I spoke to Mr. Pressly today. He told me that the owner gave the go-ahead to do the RegenOx injecting. The

PROCIDA REALTY (Continued) **S107782960**

owner wants to move things along quickly. So it will happen very soon. He intends to do 1 round of groundwater sampling shortly after the RegenOx is injected. Mr. Pressly also sent me the RAP for the RegenOx injections. The only comment I had was that he should test the soil samples via methods 8260 and 8270, not STARS. 1/24/08 - Raphael Ketani. Mr. Pressly e-mailed me today that soil excavation will start the week of 2/4 (weather contingent). RegenOx will be added to the excavated soil at this time. On 2/28, drilling will begin and so will RegenOx injections. 2/4/08 - Raphael Ketani. I received an e-mail from Mr. Pressly stating that the excavation of the contaminated soil will take place through to the end of the week. Also, he stated that drilling and injection of the solution will take place from 2/25 to 3/7/08. 2/29/08 - Raphael Ketani. Mr. Pressly called to state that solution injection has been taking place all this week and will continue into next week. 3/27/08 - Raphael Ketani. Nick Canonico of NOVA Consulting (718) 343-4440 called to inquire about the site. He said that he was hired by a potential buyer and that he is trying to find out as much as he can about it. I let him know a few of the details regarding the contaminated soil and groundwater. 3/28/08 - Raphael Ketani. Mr. Pressly (607) 264-9521 called me. He said that they will take 6 soil samples during the first week of April to see how well the oil was broken down. He mentioned that they did the first injections at the perimeter of the oil pool in the subsurface and then worked inwards. The injection holes were 10 feet apart. Fifteen thousand gallons of solution were used. When they got to the location of the source, the oil started coming out of the drill holes. However, he said it was not enough to collect. He will start the 6 borings on April 1, 2008. I told him I will be there to see the work at 10AM on April 1. 4/1/08 - Raphael Ketani. I made the scheduled site visit and met Nick Pressly of Pressly & Associates, Inc., and Nick Canonico of NOVA Consulting (cell (516) 244-4069). Mr. Pressly showed me a map he had drawn showing about 80 solution injection points and some refusal points. He showed me around the two level wharehouse that stores rolls of fabric. I could see the white caps of the injection wells. He showed me the area where the tank used to be. There was crystallized RegenOx at this site. He showed me where the soil had been excavated in the boiler room. The work was taking place on the lower level. Mr. Pressly explained that the geoprobe company was coming to do confirmatory soil borings to see how well the RegenOx dissolved the oil. The drilling company arrived and did one boring for Mr. Pressly and I. There were broken up pieces of the concrete floor and about 6 inches of sandy, gravelly soil. The soil was wet and oil stained. The oil odors were strong. Mr. Pressly stated that he will have the crew do about a dozen or so confirmatory borings. I asked him why he was doing the borings after about 4 weeks from the date of injection. He said that RegenOx recommended sampling after 3 or 4 weeks. They told him that the solution looses effectiveness after that time. He said he planned on another round of treatment if the rest of the confirmatory samples looked as bad as this first one. We planned out a few more confirmatory boring locations and after that I left. Mr. Pressly sent me an e-mail later in the day. He stated that the boring he did just outside the lower level garage door entrance was free of product. 4/28/08 - Raphael Ketani. Mr. Pressly called to say that the second round of treatment solution injections took place last friday, 4/25/08. He said that he double dosed the worst areas - next to the tank pit and next to the elevators. The injection process was

PROCIDA REALTY (Continued) **S107782960**

successful. 5/21/08 - Raphael Ketani. Mr. Pressly sent me an e-mail that the confirmatory soil sampling round for the second round of treatment solution injections will start on 5/27/08. He also asked for an approval letter for the 1/14/08 RAP that DEC said was approved via an e-mail. I sent the approval letter today. 5/27/08 - Raphael Ketani. Mr. Canonico called to ask what would close the spill case for DEC. I told him that the soil end point results and the groundwater results would have to be about at the TAGM limits or below. He said that Mr. Pressly is taking the end point samples today. 5/30/08 - Raphael Ketani. Mr. Pressly sent an e-mail today requesting confirmation that DEC wanted groundwater samples to be taken. I responded back that we did want new groundwater samples taken in the worst areas as the last set of groundwater data is from 2006. I told him that data is old and we need to see what the present levels of contamination are in order to have a basis that there is no threat from the groundwater. I also checked the PBS registration (#2-602516). It shows the tank as closed and removed. 6/25/08 - Raphael Ketani. I received an e-mail from Mr. Pressly regarding remediation progress at the site. The e-mail stated that on 5/27/08, two soil samples from the eastern side of the plume exceeded TAGM limits. They vacuumed out free product from the eastern wells that are in the vicinity of the former tank location and did a third round of RegenOx injections. The free product didn't return during the week. Mr. Pressly recommended doing another round of confirmatory soil borings within the eastern plume and groundwater sampling. I concurred in my response e-mail that DEC approves the additional sampling. I spoke to Mr. Pressly (607) 264-9521. He said that they will go back on 7/17/08 to collect new soil samples and groundwater samples. 7/14/08 - Raphael Ketani. Mr. Pressly called today. He said that it's been a month since the third round of treatment solution injections took place. So they will do confirmatory soil sampling in the former tank on friday. He said that they had injected 5000 gal. of solution and they believe the contamination is below TAGM now. 7/23/08 - Raphael Ketani. Yesterday Mr. Pressly sent me the analytical results for the third treatment round confirmatory soil samples and one groundwater sample. I reviewed the results. The groundwater sample from Well #64 had hits in the hundreds of ppb for 8 VOCs and 1500 ppb of 2-methylnaphthalene, with 2 other SVOCs in the hundreds of ppb. Samples T-1 and T-2 had results that were below TAGM. Sample T-3 had 4 VOC hits up to 30,000 ppb, and a 2-methylnaphthalene hit of 115,000 ppb. I sent Mr. Pressly a letter stating that more water should be removed from well #64 and that another treatment is necessary for the soil at T-3. 8/1/08 - Raphael Ketani. David Sweeney of PDS Carroll Street, LLC called me up (718) 768-6726. He said that his company just bought the property. He said that they buy commercial/industrial properties and preserve the structures without developing them. He said that his company is in contact with Mr. Pressley and they are pursuing the cleanup of the site, as per DEC's instructions. 8/27/08 - Raphael Ketani. Today I received the 8/25/08 Remedial Action Plan which was produced by Pressly & Associates and submitted by Sarah Williams, counsel for Procida Realty. The plan gave a history of the installation of the solution injections wells and the levels of soil contamination that were found after each round of treatment. The report concluded by stating that a fourth round of soil treatment will be conducted within the former tank area, and that confirmation soil and water samples will be taken after the fourth round. Also, the other

PROCIDA REALTY (Continued) **S107782960**

injection wells that were installed outside the tank area will be abandoned. The report contained manifests for soil that was removed and soil and groundwater analytical results reports for the tank grave sampling, sampling after each treatment round, and a sample of the groundwater. 10/20/08 - Raphael Ketani. I received the analytical report for the groundwater at well #64 and the soil at T-3 (now called S-1). The groundwater had 4 VOC hits in the double digits (up to 97 ppb) and 4 SVOC hits up to 440 ppb of phenanthrene. The only SVOC of significance was naphthalene at 200 ppb. Sample S-1 had 11 combined hits of VOCs and SVOCs. The only exceedences were total xylenes at 1680 ppb. 2-methylnaphthalene was at 11000 ppb, but the RSCO limit is 36,400 ppb. I spoke to Mr. Pressly (607) 264-9521 about the results. I told him that the DEC didn't see the need to do additional work at the site based upon the latest soil and groundwater analyticals. I told him that DEC is closing the spill case. He said that he will send a closer report. I told him that DEC will review it when it is received and E-doc it, but that we are not holding up the closing of the spill case as we feel there is enough information to do a closure right now. He said that he will send the report soon. Based upon all of the sets of analytical results submitted by Pressly & Associates, and the closed PBS case, I am closing the spill case."

Remarks: "FOUND FLOATING PRODUCT IN A 55O GALLON UST TANK:"

All Materials:

Site ID:	365475
Operable Unit ID:	1123492
Operable Unit:	01
Material ID:	2112951
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E138 **THIRD AV YARD** **NY Spills** **S104652697**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.076 mi.
402 ft. **Site 2 of 3 in cluster E**

Relative: **Lower**

Actual: **16 ft.**

SPILLS:

Name:	THIRD AV YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001798 / 2000-06-20
Facility ID:	0001798
Facility Type:	ER
DER Facility ID:	167996
Site ID:	276606
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401

THIRD AV YARD (Continued) **S104652697**

Spill Date:	2000-05-11
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-05-11
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-11
Spill Record Last Update:	2000-06-20
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed E2MIS notes: Clean Ventures was dumping in Brooklyn Flush Facility and had dumped 10 gallons #6 fuel oil. Immediately shut down facility. There was no discharge to city sewer. Mobilizing personnel to do clean up. Currently, investigation underway as to where the oil came from. The structures cleaned were TMs or vaults - non-hazardous waste. 3 samples taken PCB, oil ID and flashpoint. 1 sample rear of truck. 1 solid sample from pits from solid debris area. Found sewer discharge area clean. No contaminated product has entered the treatment plant. Update 5/11/00, 2230 hrs - Clean Ventures has arrived on location. Clean up crew on wasy. Update 5/11/00, 2255 hrs - Clean Ventures driver indicated that he started off the day with a clean vehicle and as per his non-haz paperwork he cleaned the following 4 structures in Yonkers before dumping at 3rd Avenue Yard: 1 - tm5509 - Sawmill River Rd. n/o Delaware Ave. 2 - vs282 - Nepperhaw Ave. 3 - tm4085 - 937 Sawmill River Rd n/o Odell Ave. 4 - v4607 - Nepperhaw Ave. s/o Tompkins Ave. Update 5/12/00, 0335 hrs - Clean Ventures removed 12 of water and any visible signs of oily debris and cleaned side walls of all settling pits. They are now in the process of setting up to remove solid debris from dumping pit. 2 of the 5 samples being analyzed at Chem Lab for oil ID have been identified as a light fuel oil such as home heating oil. Update 5/12/00, 0730 hrs - Clean up completed by vendor (Clean Ventures). Solid debris will be disposed as hazardous for lead and asbestos. Update 5/12/00 - PCB results all <1 ppm Flashpoint all >140 deg F"
Remarks:	"contractor(clean ventures) working for con ed & dumped 10 gal of #6 fuel oil into the flush pit from one of their trucks - clean up pending clean up crew - no ref # yet "

All Materials:

Site ID:	276606
Operable Unit ID:	823309
Operable Unit:	01
Material ID:	552964
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported

THIRD AV YARD (Continued) **S104652697**

Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E139 **FLUSHPIT 3RD AVE YARD** **NY Spills** **S104880303**
West **222 FIRST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.076 mi.
402 ft. **Site 3 of 3 in cluster E**

Relative: SPILLS:
Lower

Actual:
16 ft.

Name:	FLUSHPIT 3RD AVE YARD
Address:	222 FIRST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0009168 / 2000-11-14
Facility ID:	0009168
Facility Type:	ER
DER Facility ID:	167996
Site ID:	263574
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-11-08
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-11-08
CID:	282
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-08
Spill Record Last Update:	2001-01-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN FOR NOW
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	STEVEN ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL DEC Investigator Notes: Sam Arakhan spoke to Ed Radtke at 4:15pm. Second sample was collected and sent to CHem Lab for re-analysis. Results expected tonight. Original sample was a composite taken from drying bin prior to disposal. This load has been segregated on-site awaiting confirmatory samples. Referred to DSHM-Sam Arakhan for follow-up 11/9/00. e2MIS Notes: Routine soil sample taken on 11/7/00 from drying bin at 3rd Ave Flush Pit came back as 18,000ppm PCB. At this time source unknown and amount unknown. Contained to drying bin. R. Saladino notified the following: Bill Wallace(ERT), M. Saladino (EH&S), Ed Radtke(EH&S), G.

FLUSHPIT 3RD AVE YARD (Continued) **S104880303**

Pennecke(EH&S) and E. Dessen(Law Dept.). E2MIS report turned in by R. Saladino at request of Bill Wallace. Flush pit has been closed. Due to high PCB count, Chem Lab will resample solids and retest. Update 1440: B. Cohen of EH&S requested that Chem Lab take 20 grab samples of soil in drying bin. Update 11/8/00 1900hrs: Chem Lab took 20 samples from drying bin. Drying bin area was isolated where suspected high PCB's are. Advised EPA and DEC of situation and plans. E. Radtke advised us to wait for all results prior to disposal and cleanup. Update 11/9/00 1615hrs: LSN 00-10624-Results 8048ppm (the reported PCB result is the average of four sample analysis). Cleanup to be performed as >500ppm PCB. Steve Ferrone secured TSDF and rolloffs for waste. Grid maps were made of contaminated areas. Chem lab technician took 25 pre-wipe samples of dumping pad. Dumping pad area and backhoe were covered with tarpaulin. DEC Sam Arakhan inspected site and reviewed our action plan. Sam would like to be present when we drum the first four feet of debris which is suspect for the high PCB concentration. Present were the following:Ed Radtke, G. Pennecke, R. James, R. Saladino, C. Fernandez, V. Devillez. Cleanup will commence tomorrow pending weather conditions. Barry Cohen provided a sampling/disposal plan. This plan was faxed to Sam Arakhan. Update 11/10/00 1930hrs: Drummed first four feet of debris pile. This was a total of 16 drums. All drums were individually tested. Drums were labeled and marked pending analysis. DEC Sam Arakhan visited site during drumming operation. Sam instructed us that the drums could remain on-site at Flush Facility pending results for proper disposal. Four 20 yard lined dumpsters were loaded with the balance of debris from the drying bin area. 3 of the dumpsters were placed adjacent to the north garage. 1 was placed inside the north garage. All dumpsters were properly labeled and caution tape was placed around the area. Chem Lab took all required samples from each dumpster. Results have been received for the wipes which were taken of the dumping pad. All 25 wipes passed. Update 11/11/00: Chem Lab results have been posted for solid debris from dumpster #20015, LSN 00-10792, all six samples are non-hazardous for PCBs. Update 11/11/00: 2 additional dumpsters were loaded with solids from the west dumping pad. The dumpsters were labeled and placed inside the north garage. Teh drying bin area was double washed with detergent and rinsed, using a pressure washer and Bio Gen cleaner. Twenty-one post-wipe samples of the drying bin area were taken by chem lab. Dumping pads and facility backhoe(91202) were double washed and rinsed. All liquids were removed as hazardous for PCBs by tanker from Clean Harbors, manifest NYG1703439. The liquids were being shipped to Spring Grove Resource Recovery, Cincinnati, OH 45232. Nine post-wipe samples were taken of backhoe. All work areas have been covered with plastic or tarpaulins pending the wipe results. The facility remains closed pending results and direction from EH&S."

Remarks: "they took soil samples and came back with readings of 18,000ppm pcb.cleanup pending test results and flush pit is closed. 134301 con ed"

All Materials:

Site ID:	263574
Operable Unit ID:	831477
Operable Unit:	01
Material ID:	543127
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported

FLUSHPIT 3RD AVE YARD (Continued) **S104880303**

Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F140 **CON EDISON** **NY MANIFEST** **S117738130**
WNW **319 3 AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.078 mi.
412 ft. **Site 3 of 13 in cluster F**

Relative: **Lower**

Actual: **16 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	319 3 AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004706313
Facility Status:	Not reported
Location Address 1:	319 3 AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004706313
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/12/2014
Trans1 Recv Date:	12/12/2014
Trans2 Recv Date:	12/16/2014
TSD Site Recv Date:	12/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004706313
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117738130**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618657GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H141 **CON EDISON** **PA MANIFEST** **S123093387**
NE **237 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.078 mi.
413 ft. **Site 8 of 11 in cluster H**

Relative: **Higher**

Actual: **27 ft.**

Manifest Details:

Year:	2017
Manifest Number:	010427665FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP005107804
Generator Date:	07/07/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1

CON EDISON (Continued) **S123093387**

Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

H142 **LOT 7,TAXBLOCK 958** **NY E DESIGNATION** **S108469620**
ENE **586 PRESIDENT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.082 mi.
433 ft. **Site 9 of 11 in cluster H**

Relative:
Higher

Actual:
28 ft.

E DESIGNATION:

Name:	LOT 7,TAXBLOCK 958
Address:	586 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	7
Tax Block:	958
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

H143 **CON EDISON** **NY MANIFEST** **S117536659**
ENE **586 PRESIDENT ST** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.082 mi.
433 ft. **Site 10 of 11 in cluster H**

Relative:
Higher

Actual:
28 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	586 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004691457
Facility Status:	Not reported
Location Address 1:	586 PRESIDENT ST
Code:	BP
Location Address 2:	SB31665
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004691457

CON EDISON (Continued) **S117536659**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/06/2014
Trans1 Recv Date:	11/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004691457
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416874GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117536659**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

D144 **LOT 7502,TAXBLOCK 974** **NY E DESIGNATION** **S111073086**
South **306 2 STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.083 mi.
438 ft. **Site 5 of 7 in cluster D**

Relative:
Higher

Actual:
28 ft.

E DESIGNATION:
Name: LOT 7502,TAXBLOCK 974
Address: 306 2 STREET
City,State,Zip: BROOKLYN, NY 11215
Tax Lot(s): 7502
Tax Block: 974
Borough Code: BK
E-No: E-113
Effective Date: 4/30/2003
Satisfaction Date: Not reported
Ceqr Number: 03DCP030K
Ulurp Number: 030194(A)ZMK030194(A)ZMK
Zoning Map No: 16b, 16c

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

G145 **CON EDISON** **NY MANIFEST** **S117741205**
East **584 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.083 mi.
440 ft. **Site 4 of 11 in cluster G**

Relative:
Higher

Actual:
33 ft.

NY MANIFEST:
Name: CON EDISON
Address: 584 CARROLL ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004744215
Facility Status: Not reported
Location Address 1: 584 CARROLL ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004744215
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

CON EDISON (Continued) **S117741205**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2015
Trans1 Recv Date:	03/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744215
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091024JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G146 **CON EDISON** **RCRA NonGen / NLR** **1018279590**
East **584 CARROLL ST** **FINDS** **NYP004744215**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.083 mi.
440 ft. **Site 5 of 11 in cluster G**

Relative: **Higher**
Actual: **33 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150305
Handler Name:	CON EDISON	
Handler Address:		584 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004744215
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018279590**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150305
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private

CON EDISON (Continued) **1018279590**

Date Became Current: 20150305
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 22637
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150305
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150305
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON (Continued) **1018279590**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067693151

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279590
Registry ID:	110067693151
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067693151
Name:	CON EDISON
Address:	584 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215

J147 **315 4TH AVE** **NY Spills** **S104648674**
South **315 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.084 mi.
445 ft. **Site 1 of 4 in cluster J**

Relative:
Higher

Actual:
27 ft.

SPILLS:

Name:	315 4TH AVE
Address:	315 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9814678 / 1999-03-26
Facility ID:	9814678
Facility Type:	ER
DER Facility ID:	155856
Site ID:	186475
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-03-09
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-03-09
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

315 4TH AVE (Continued) **S104648674**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-09
Spill Record Last Update:	2006-02-15
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Con ed e2mis notes: J.LIPORI #11179 OF ENVIRONMENTAL OPERATIONSREPORTS FOUND APPROXIMATELY 1- QUART OF UNKNOWN OIL ON 10 GALLONS OF WATER IN SB45405 F/O 315 4 AVE. NO SEWERS OR WATERWAYS AFFECTED.SPILL CONTAINED TO SERVICE BOX. SAMPLE TAKEN & E.S.TAG#22015 PLACED.-- MARKED SAMPLE FOR A 4-6 HOUR TURNAROUND. REPORTED TO CIG M.CESARE AT 2123HRS. 3/10/99 02:35 HRS - LAB SEQ #99-02512, <1.0 PPM PCB UPDATE 3-12-1999 0130 HRS LIPORI FLUSH REPORTS CLEANUP IS COMPLETED USING SLIX AND E.S.TAG # 22015 WAS REMOVED < 1PPM. "
Remarks:	"SERVICE BOX #SB45405. ONE PINT UNKNOWN OIL ON TEN GALLONS OF WATER. CONTAINED WITHIN SERVICE BOX. SAMPLES TAKEN. CLEAN UP PENDING TEST RESULTS."

All Materials:

Site ID:	186475
Operable Unit ID:	1075704
Operable Unit:	01
Material ID:	311357
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

G148 **CON EDISON** **NJ MANIFEST** **S120668296**
East **586 CARROL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.087 mi.
459 ft. **Site 6 of 11 in cluster G**

Relative: **Higher**
Actual: **34 ft.**

NJ MANIFEST:

EPA Id:	NYP004743068
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported

CON EDISON (Continued) **S120668296**

Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002563838GBF
EPA ID:	NYP004743068
Date Shipped:	3/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

G149 **CON EDISON** **RCRA NonGen / NLR** **1018279483**
East **586 CARROL ST** **FINDS** **NYP004743068**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.087 mi.
459 ft. **Site 7 of 11 in cluster G**

Relative: **Higher**
Actual: **34 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150304
Handler Name:	CON EDISON	
Handler Address:		586 CARROL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004743068
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018279483**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150304
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150304
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018279483**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067691297

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279483
Registry ID:	110067691297
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067691297
Name:	CON EDISON
Address:	586 CARROL ST
City,State,Zip:	BROOKLYN, NY 11215

G150 **CON EDISON** **NY MANIFEST** **S117741098**
East **586 CARROL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.087 mi.
459 ft. **Site 8 of 11 in cluster G**

Relative:
Higher

Actual:
34 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	586 CARROL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004743068
Facility Status:	Not reported
Location Address 1:	589 CARROLL ST
Code:	BP
Location Address 2:	MH22637
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

CON EDISON (Continued) **S117741098**

NY MANIFEST:

EPAID:	NYP004743068
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/04/2015
Trans1 Recv Date:	03/04/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004743068
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002563838GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117741098**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

I151 **540 PRESIDENT STREET** **NY LTANKS** **S102672075**
North **540 PRESIDENT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.087 mi.
462 ft. **Site 3 of 4 in cluster I**

Relative: LTANKS:
Lower
Name: 540 PRESIDENT STREET
Actual: Address: 540 PRESIDENT STREET
22 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9211878 / 1993-01-18
Facility ID: 9211878
Site ID: 262667
Spill Date: 1993-01-18
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: 1993-01-18
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1993-01-18
CID: Not reported
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-01-28
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: HOLMES FUEL CO.
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 214455
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: "HOLMES OVERFILLED TANK NYC DOS ON SCENE NOTIFIED CON ED SAND PLACE IN SPILL HOLMES TO COME AND PICK UP CALLED FD HAZ MAT FIREMAN HANK REPORTED THAT SPILLED FROM VENT PIPE CONTAINED ON SIDEWALK CLEANUP"

All Materials:
Site ID: 262667
Operable Unit ID: 976318
Operable Unit: 01

540 PRESIDENT STREET (Continued) **S102672075**

Material ID:	405261
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F152 **222 1ST ST** **NY Spills** **S103275170**
WNW **3RD AVE YARD** **N/A**
< 1/8 **BROOKLYN, NY**
0.090 mi.
475 ft. **Site 4 of 13 in cluster F**

Relative: **Lower**
Actual: **15 ft.**

SPILLS:

Name:	222 1ST ST
Address:	3RD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9803310 / 1998-08-06
Facility ID:	9803310
Facility Type:	ER
DER Facility ID:	228767
Site ID:	281783
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-06-12
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-06-15
CID:	196
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-15
Spill Record Last Update:	2000-06-26
Spiller Name:	BILL MURPHY
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"OIL SHEEN UNDER CON ED VEHICLE, SPILL CLEANED UP. VEHICLE 50351."

All Materials:

Site ID:	281783
Operable Unit ID:	1061242

222 1ST ST (Continued) **S103275170**

Operable Unit:	01
Material ID:	563682
Material Code:	9999
Material Name:	other -
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F153 **THIRD AVENUE YARD** **NY Spills** **S102401870**
WNW **THIRD AVENUE & FIRST STRE** **N/A**
< 1/8 **BROOKLYN, NY**
0.090 mi.
475 ft. **Site 5 of 13 in cluster F**

Relative: **Lower**

Actual: **15 ft.**

SPILLS:

Name:	THIRD AVENUE YARD
Address:	THIRD AVENUE & FIRST STRE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9605550 / 1998-05-04
Facility ID:	9605550
Facility Type:	ER
DER Facility ID:	68857
Site ID:	73086
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-07-30
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1996-07-30
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-30
Spill Record Last Update:	1998-05-04
Spiller Name:	RICHARD ROACH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	MR ROSARIO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL OVERHEATED FORKLIFT SPILLED ON THE BLUE STONE - ALL CLEANED UP"
Remarks:	"OVERHEATED FORKLIFT. ONTO BLACKTOP. CLEANED UP."

All Materials:

THIRD AVENUE YARD (Continued) **S102401870**

Site ID:	73086
Operable Unit ID:	1033076
Operable Unit:	01
Material ID:	348291
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

F154 **3RD AVE YARD** **NY Spills** **S102239113**
WNW **3RD AVE YARD** **N/A**
< 1/8 **BROOKLYN, NY**
0.090 mi.
475 ft. **Site 6 of 13 in cluster F**

Relative: SPILLS:
Lower

Actual:
15 ft.

Name:	3RD AVE YARD
Address:	3RD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9514614 / 2003-02-24
Facility ID:	9514614
Facility Type:	ER
DER Facility ID:	228767
Site ID:	281780
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-02-15
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	270
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	2003-02-24
Spiller Name:	LISA PRIMEGGIA
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 02/24/2003 Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"leak from veh"

3RD AVE YARD (Continued) **S102239113**

All Materials:

Site ID:	281780
Operable Unit ID:	1029161
Operable Unit:	01
Material ID:	354742
Material Code:	0028A
Material Name:	ethylene glycol
Case No.:	00107211
Material FA:	Hazardous Material
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	3RD AVE YARD
Address:	3RD AVE YARD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702275 / 2003-02-25
Facility ID:	9702275
Facility Type:	ER
DER Facility ID:	228767
Site ID:	281781
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-05-20
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1997-05-22
CID:	369
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-22
Spill Record Last Update:	2003-02-25
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	MIKE CESARE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis 107625 JOE SZABO #17921 FACILITIES REPORTS THERE IS OIL MIXED WITH SLUDGE IN CATCH BASIN AT 3 RD AVE YARD - #6 CATCH BASIN BY TOOL ROOM BY 3 RD AVE & 3RD ST SIDE. CATCH BASIN IS 18 X18 X43' DEEP. NO SEWERS OR WATER WAYS INVOLVED. THE SEWER PIPE -DISCHARGE IS ABOVE OIL LEVEL. SAMPLES WERE TAKEN LAST WEEK & RESULTS CAME BACK 1 SAMPLE OVER 50 PPM. UNKNOWN SOURCE. OPAK NOTIFIED & COSENTINO NOTIFIED, OIL FOUND 5/20/97 2305 HRS WAS NEVER TURNED INTO CONTROL CENTER. #12255 VDC.---UPDATE 5/23 OPAK REPORTS CLEAN HARBORS

3RD AVE YARD (Continued) **S102239113**

COMPLETED CLEAN UP OF CATCH BASIN #6 3 LIQUID BARRELS FROM CATCH BASIN #6 WERE LEFT IN STORES @ 3 RD AVE YARD. CLEAN HARBORS STARTED CLEAN UP IN CATCH BASIN #1. CLEAN HARBORS CREW CANNOT COMPLETE THE OTHER 5 UNDER 50 PPM CLEANUPS. THEY [CLEAN HARBORS] WILL RETURN IN AM TO COMPLETE. E.VESCE ENVIROMENTAL AFFAIRS INSTRUCTED FLUSH DEPT TO COVER CATCH BASINS THAT WERE NOT CLEANED. 1155HRS FERNANDEZ REPORTS BALONEYS & TARPS PLACED OVER CATCH BASINS. UPDATE 5-23-97 1510 HRS A.HOWELL OS FLUSH DEPT REPORTS ALL CATCH BASONS IN 3 AVE YARD ARE CLEANED COMPLETE. JOB IS COMPLETED. LAZ #04425"

Remarks: "CONTAINED TO LAND-CLEANUP IN PROGRESS-HOLDING TANK FILLED UP BUT DID NOT OVERFILL"

All Materials:

Site ID:	281781
Operable Unit ID:	1045012
Operable Unit:	01
Material ID:	335215
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

H155 **VAULT# TM0253** **NY Spills** **S106468549**
ENE **PRESIDENT ST & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.093 mi.
490 ft. **Site 11 of 11 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

SPILLS:

Name:	VAULT# TM0253
Address:	PRESIDENT ST & 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0400989 / 2004-07-20
Facility ID:	0400989
Facility Type:	ER
DER Facility ID:	255616
Site ID:	317096
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-04-28
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2004-04-28
CID:	407
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

VAULT# TM0253 (Continued) **S106468549**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-04-28
Spill Record Last Update:	2004-07-20
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 153110: FOUND APPROX 2-GALLONS OF UNKNOWN OIL ON APPROX 400 GALLONS WATER IT APPEARS TO BE CONTAINED. UNIT PRESSURE TESTED AND HELD. RECORDS SHOW 32 PPM DATED 9/12/89. 1-SAMPLE TAKEN. Lab Sequence Number: 04-03210-001 PCB <1 ppm. TRANSFORMER TO BE REPLACED ON 4/29/04 AND STRUCTURE WILL NEED TO BE CLEANED AFTER REMOVAL OF OLD UNIT. 29-APR-2004 12:35 HRS. TRANS REMOVED STRUCTURE DBL. WASHED WITH BIO-GEN 760. NO SUMP FOUND IN STRUCTURES. TAG #16551 REMOVED. CLEANUP COMPLETE 100%."
Remarks:	"2 gallons of oil spilled into containment which is filled with 400 gallons of water. This is origionaly on a 24 hour program, was taken off at 4/28/04 18:55 because they are going to replace the transformer in the vault."

All Materials:

Site ID:	317096
Operable Unit ID:	885166
Operable Unit:	01
Material ID:	492219
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G156 **CON EDISON** **NY MANIFEST** **S117741213**
East **590 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.094 mi.
497 ft. **Site 9 of 11 in cluster G**

Relative:
Higher

Actual:
36 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	590 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004744306
Facility Status:	Not reported
Location Address 1:	590 CARROLL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215

CON EDISON (Continued) **S117741213**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004744306
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/05/2015
Trans1 Recv Date: 03/05/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/06/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744306
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014091025JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 4000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117741213**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G157 **CON EDISON** **NJ MANIFEST** **S120668406**
East **590 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.094 mi.
497 ft. **Site 10 of 11 in cluster G**

Relative:
Higher

Actual:
36 ft.

NJ MANIFEST:

EPA Id:	NYP004744306
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091025JJK
EPA ID:	NYP004744306
Date Shipped:	3/5/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON (Continued) **S120668406**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

G158 **CON EDISON** **RCRA NonGen / NLR** **1018279598**
East **590 CARROLL ST** **FINDS** **NYP004744306**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.094 mi.
497 ft. **Site 11 of 11 in cluster G**

Relative: **Higher**
Actual: **36 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150305
Handler Name:	CON EDISON	
Handler Address:		590 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004744306
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

CON EDISON (Continued) **1018279598**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

CON EDISON (Continued) **1018279598**

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150305
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150305
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 22638
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150305
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150305

CON EDISON (Continued) **1018279598**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067693213

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279598
Registry ID: 110067693213
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067693213
Name: CON EDISON
Address: 590 CARROLL ST
City,State,Zip: BROOKLYN, NY 11215

F159 **FEEDER LEAK** **NY Spills** **S123659108**
WNW **3RD AVE & 1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
501 ft. **Site 7 of 13 in cluster F**

Relative: **Lower**

Actual: **14 ft.**

SPILLS:

Name:	FEEDER LEAK
Address:	3RD AVE & 1ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1809345 / 2019-06-21
Facility ID:	1809345
Facility Type:	ER
DER Facility ID:	532869
Site ID:	580185
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2018-12-05
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2018-12-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-12-05
Spill Record Last Update:	2019-06-21
Spiller Name:	ERT
Spiller Company:	CONED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CON EDISON
DEC Memo:	"12/06/18 - Lakhani The Leak Committee Declared a Leak on 345kV Feeder #41 that runs between the Farragut SS and Gowanus SS due to frequent pump starts and tank level discrepancies. The leak rate is currently estimated at 6.5 gallons per hour with an estimated loss of 530 gallons of dielectric fluid. Trans Ops crews will inspect manholes and a ConEd PFT Van will run the 21,480 foot feeder route. Dielectric Fluid Leak Committee Conference Call, December 6, 2018 @ 07:00 " The Leak Committee declared a leak Terminated on 345kV transmission feeder 41 at 05:04 on 12/6/18 when a clamp was installed stopping the leak. " The estimated loss is 530 gallons of dielectric fluid with an estimated leak rate of 6.5 gallons per hour. " Transmission Operations found the leak located on the feeder pipe behind the reducer in MH 65435 located at 3rd Ave & 1st street, Brooklyn. " Transmission Operations will continue checking manholes. " PFT van has patrolled the entire feeder outside of the substations. Leak was found and contained in a concrete manhole. 06/21/19-Hiralkumar Patel. received final emis report from ConEd. a clamp and barrel have been installed on the feeder line. no further leak noted. case closed. "

FEEDER LEAK (Continued) **S123659108**

Remarks: "Feeder line leak between Farragut SubStation & Gowanus SubStation @ 27th St & 3rd Ave in Brooklyn. Investigating and will report further when it is known."

All Materials:

Site ID:	580185
Operable Unit ID:	1327900
Operable Unit:	01
Material ID:	2336845
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

F160 **3RD AVE SERVICE CENTER** **NY Spills** **S103569896**
WNW **3RD AVE & 1ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
501 ft. **Site 8 of 13 in cluster F**

Relative: **Lower**
Actual: **14 ft.**

SPILLS:

Name:	3RD AVE SERVICE CENTER
Address:	3RD AVE & 1ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9608437 / 2004-09-02
Facility ID:	9608437
Facility Type:	ER
DER Facility ID:	169458
Site ID:	203791
DEC Region:	2
Spill Cause:	Other
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-10-07
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1996-10-07
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-07
Spill Record Last Update:	2004-09-02
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	128 WEST END AVENUE
Spiller Company:	001

3RD AVE SERVICE CENTER (Continued) **S103569896**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Track under spill number 9808009. Close out. (JHO)"
Remarks: "poss leak from a ust - sheen on water in monitoring well"

All Materials:
Site ID: 203791
Operable Unit ID: 1039473
Operable Unit: 01
Material ID: 344176
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

F161 **CONSOLIDATED EDISON** **NY MANIFEST** **S119073028**
WNW **3RD AVE & 1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.095 mi.
501 ft. **Site 9 of 13 in cluster F**

Relative:
Lower

Actual:
14 ft.

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 3RD AVE & 1ST STREET
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004155701
Facility Status: Not reported
Location Address 1: 3rd AVE & 1st STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004155701
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CONSOLIDATED EDISON (Continued) **S119073028**

seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/2008
Trans1 Recv Date:	01/10/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/11/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004155701
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001437071FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	D006
Waste Code 1_3:	D007
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F162 **MANHOLE # 65435** **NY Spills** **S106968362**
WNW **3RD AVE/1ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
502 ft. **Site 10 of 13 in cluster F**

Relative: SPILLS:
Lower

Name:	MANHOLE # 65435
Address:	3RD AVE/1ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0502530 / 2005-08-17

Actual:
14 ft.

MANHOLE # 65435 (Continued) **S106968362**

Facility ID:	0502530
Facility Type:	ER
DER Facility ID:	293173
Site ID:	346909
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-06-02
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-06-02
CID:	444
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-02
Spill Record Last Update:	2005-08-17
Spiller Name:	Not reported
Spiller Company:	UKNOWN AT THIS TIME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT DESK MIKE DAUGHTERY
DEC Memo:	"158912. UPDATE 02-JUN-5. TRANSMISSIONS OPERATIONS B MECHANIC JOHN LOBIANCO, EMPLOYEE NO 00642, WHILE ON LOCATION TO INSPECT MH65435 LOCATED ON THE E/S OF THIRD AVE 100' N/O THE N/E/C OF 1ST STREET, REPORTS FINDING APPX 3 GALS OF UNK OIL ON APPX 300 GALS OF WATER IN THE STRUCTURE. NO FIRE OR SMOKE INVOLVED, NO INJURIES RELATED TO THE SPILL, NO SEWERS, WATERWAYS OR PRIVATE PROPERTY AFFECTED. SPILL APPEARS TO BE CONTAINED TO THE STRUCTURE. HE IS UNABLE TO VERIFY THE SOURCE OF THE SPILL OR THE PRESENCE OF ANY SEWER CONNECTIONS, SUMPS OR SUBSTANTIAL CRACKS IN THE STRUCTURE AT THIS TIME. WATER IS STANDING STILL, THERE IS NO VISUAL WATER MOVEMENT. ENVIRONMENTAL TAG NO 37292 WAS PLACED IN THE STRUCTURE, SAMPLE TAKEN FOR PCB'S, MARKED PRIORITY E WHICH WILL BE TAKEN TO ASTORIA LAB FOR ANALYSIS ON CC. NO. EE03491. BORCHERDING C UPDATE 02-JUN-2005 0945 CIG SHIKAREDES NOTIFIED. TOA NOTED @ 0949 HRS. BORCHERDING C OIL SPILL CLEANUP CHECKLIST. SPILL INFORMATION. Amount: -500 GAL. PCB sample LSN number -05-05232-001. PCB Concentration (PPM) -11 PPM Was a oil ID/fingerprint taken -YES Oil ID sample LSN number -05-05231-001. oil ID -CABLE OIL Was the spill contained to the Manhole-YES Were sewers or waterways affected-NO Oil removed/recovered -YES/6-21-05 Sludge removed-500 GAL Surfaces power washed-POWER WASHED BY ALLSTATE Person Directing the cleanup-SAM WALKER 06/21/05-ALLSTATE -APV 22340 -NON HAZ -500 -GAL Is cleanup acceptable-YES Employee verifying cleanup-BONCARAGLIO,A FORM COMPLETED BY: Name & employee #: -SAM WALKER 11210 Responsible Department:-MAINTENANCE AND CONSTRUCTION SERVICES Closed. 8-17-05. George Breen "
Remarks:	"ON 300 GALLONS OF WATER: NO TO THE 5 QUESTIONS: CONED # 158912"

All Materials:

Site ID:	346909

MANHOLE # 65435 (Continued) **S106968362**

Operable Unit ID:	1104664
Operable Unit:	01
Material ID:	814220
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J163 **LOT 73,TAXBLOCK 974** **NY E DESIGNATION** **S108075334**
South **303 3 STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.099 mi.
521 ft. **Site 2 of 4 in cluster J**

Relative: **Higher**
Actual: **28 ft.**

E DESIGNATION:

Name:	LOT 73,TAXBLOCK 974
Address:	303 3 STREET
City,State,Zip:	BROOKLYN, NY 11215
Tax Lot(s):	73
Tax Block:	974
Borough Code:	BK
E-No:	E-113
Effective Date:	4/30/2003
Satisfaction Date:	Not reported
Ceqr Number:	03DCP030K
Ulurp Number:	030194(A)ZMK030194(A)ZMK
Zoning Map No:	16b, 16c
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

D164 **CON EDISON - SERVICE BOX 38850** **NY MANIFEST** **S121968216**
SSE **328 2ND ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.102 mi.
537 ft. **Site 6 of 7 in cluster D**

Relative: **Higher**
Actual: **31 ft.**

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 38850
Address:	328 2ND ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP005093950
Facility Status:	Not reported
Location Address 1:	328 2ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215

CON EDISON - SERVICE BOX 38850 (Continued) **S121968216**

Location Zip 4: Not reported

NY MANIFEST:

EPAID:	NYP005093950
Mailing Name:	CON EDISON - SERVICE BOX 38850
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

D165 **CON EDISON - SERVICE BOX 38850** **RCRA-LQG** **1024891294**
SSE **328 2ND ST** **NYP005093950**
< 1/8 **BROOKLYN, NY 11215**
0.102 mi.
537 ft. **Site 7 of 7 in cluster D**

Relative: **Higher**

Actual: **31 ft.**

RCRA-LQG:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - SERVICE BOX 38850
Handler Address:	328 2ND ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP005093950
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON - SERVICE BOX 38850 (Continued) **1024891294**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

CON EDISON - SERVICE BOX 38850 (Continued) **1024891294**

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170608
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170608
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX 38850
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K166 **CON EDISON** **NY MANIFEST** **S117740407**
East **577 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.104 mi.
548 ft. **Site 1 of 3 in cluster K**

Relative:
Higher

Actual:
35 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	577 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004735734
Facility Status:	Not reported
Location Address 1:	577 CARROLL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004735734
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/23/2015
Trans1 Recv Date:	02/23/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	02/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004735734
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610824GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117740407**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K167 **CON EDISON** **NJ MANIFEST** **S120667643**
East **577 CARROLL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.104 mi.
548 ft. **Site 2 of 3 in cluster K**

Relative: **Higher**
Actual: **35 ft.**

NJ MANIFEST:

EPA Id:	NYP004735734
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610824GBF
EPA ID:	NYP004735734
Date Shipped:	2/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120667643**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K168 **CON EDISON** **RCRA NonGen / NLR** **1018278791**
East **577 CARROLL ST** **FINDS** **NYP004735734**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.104 mi.
548 ft. **Site 3 of 3 in cluster K**

Relative: **Higher**
Actual: **35 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150223
Handler Name:	CON EDISON	
Handler Address:		577 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004735734
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON (Continued) **1018278791**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

CON EDISON (Continued) **1018278791**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150223
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150223
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067681155

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

CON EDISON (Continued) **1018278791**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278791
Registry ID:	110067681155
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067681155
Name:	CON EDISON
Address:	577 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215

I169 **L.L.L. AUTO REPAIR INC.** **NY AST** **A100320260**
NNW **528 PRESIDENT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.104 mi.
549 ft. **Site 4 of 4 in cluster I**

Relative:
Lower

Actual:
20 ft.

AST:

Name:	L.L.L. AUTO REPAIR INC.
Address:	528 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610816
Program Type:	PBS
UTM X:	585732.00309
UTM Y:	4503454.02078
Expiration Date:	04/16/2013
Site Type:	Other

Affiliation Records:

Site Id:	396425
Affiliation Type:	Facility Owner
Company Name:	L.L.L. AUTO REPAIR INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	528 PRESIDENT ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 488-9244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-04-16

Site Id:	396425
Affiliation Type:	Mail Contact
Company Name:	L.L.L. AUTO REPAIR INC.

L.L.L. AUTO REPAIR INC. (Continued) **A100320260**

Contact Type:	Not reported
Contact Name:	CHI LUEN LEE
Address1:	528 PRESIDENT STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 488-9244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-04-16

Site Id:	396425
Affiliation Type:	Facility Operator
Company Name:	L.L.L. AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	CHI LUEN LEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 488-9244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-04-16

Site Id:	396425
Affiliation Type:	Emergency Contact
Company Name:	L.L.L. AUTO REPAIR INC
Contact Type:	Not reported
Contact Name:	CHI LUEN LEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 488-9244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-04-16

Tank Info:

Tank Number:	001
Tank Id:	222454
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

L.L.L. AUTO REPAIR INC. (Continued) **A100320260**

	G10 - Tank Secondary Containment - Impervious Underlayment
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/2008
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

F170 **CON EDISON** **NY MANIFEST** **1016960520**
WNW **318 3RD AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11217**
0.104 mi.
550 ft. **Site 11 of 13 in cluster F**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	318 3RD AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004325122
Facility Status:	Not reported
Location Address 1:	N/E/C 3 AVE & 2 STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004325122
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **1016960520**

Trans2 State ID:	Not reported
Generator Ship Date:	07/06/2013
Trans1 Recv Date:	07/06/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004325122
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084590GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F171 **FINEST AUTO & RECOVERY** **RCRA NonGen / NLR** **1004761790**
NW **310 3RD AVE** **FINDS** **NYR000090431**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.104 mi.
550 ft. **Site 12 of 13 in cluster F**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20070101
Actual: Handler Name:	FINEST AUTO & RECOVERY	
14 ft. Handler Address:		310 3RD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000090431
Contact Name:		JAMES LEWIS
Contact Address:		3RD AVE

FINEST AUTO & RECOVERY (Continued) **1004761790**

Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-488-7100
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		3RD AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	JAMES LEWIS	
Owner Type:		Private
Operator Name:	JAMES LEWIS	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No

FINEST AUTO & RECOVERY (Continued) **1004761790**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS

FINEST AUTO & RECOVERY (Continued) **1004761790**

LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JAMES LEWIS	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	310 3RD AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-488-7100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JAMES LEWIS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	310 3RD AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-488-7100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JAMES LEWIS	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	310 3RD AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-488-7100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: FINEST AUTO & RECOVERY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: FINEST AUTO & RECOVERY	

FINEST AUTO & RECOVERY (Continued) **1004761790**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20000922
Handler Name:	FINEST AUTO & RECOVERY
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004564953

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004761790
Registry ID:	110004564953
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004564953
Name:	FINEST AUTO & RECOVERY
Address:	310 3RD AVE

FINEST AUTO & RECOVERY (Continued) **1004761790**

City,State,Zip: BROOKLYN, NY 11215

F172 **CLARIN TRUCK LEASING CORP** **NY UST** **U001839158**
WNW **312 3RD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.107 mi.
566 ft. **Site 13 of 13 in cluster F**

Relative: **Lower**

Actual: **13 ft.**

UST:

Name:	CLARIN TRUCK LEASING CORP
Address:	312 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-007552 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585611.59271
UTM Y:	4503346.15069
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	61
Affiliation Type:	Facility Owner
Company Name:	CLARIN TRUCK LEASING CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	312 3RD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 855-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	61
Affiliation Type:	Mail Contact
Company Name:	CLARIN TRUCK LEASING CORP
Contact Type:	Not reported
Contact Name:	GEORGE M. CAMBIES
Address1:	312 3RD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 855-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	61
Affiliation Type:	Facility Operator

CLARIN TRUCK LEASING CORP (Continued) **U001839158**

Company Name:	CLARIN TRUCK LEASING CORP
Contact Type:	Not reported
Contact Name:	CLARIN TRUCK LEASING CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 855-4800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	61
Affiliation Type:	Emergency Contact
Company Name:	CLARIN TRUCK LEASING CORP
Contact Type:	Not reported
Contact Name:	GEORGE CAMBEIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 855-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	30356
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1963
Date Tank Closed:	03/09/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination

CLARIN TRUCK LEASING CORP (Continued) **U001839158**

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 30357
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1963
Date Tank Closed: 03/09/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 30358
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1963
Date Tank Closed: 03/09/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

CLARIN TRUCK LEASING CORP (Continued) **U001839158**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Number: 004
Tank ID: 30359
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1963
Date Tank Closed: 03/09/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 30360
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1963
Date Tank Closed: 03/01/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001

CLARIN TRUCK LEASING CORP (Continued) **U001839158**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 006
Tank ID: 30361
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 09/01/1963
Date Tank Closed: 03/09/2001
Registered: True
Tank Location: Underground
Tank Type: Z
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

L173 **CON EDISON - SERVICE BOX 38958** **NY MANIFEST** **S121968633**
NW **302 3RD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.108 mi.
570 ft. **Site 1 of 6 in cluster L**

Relative: **Lower**

Actual: **15 ft.**

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 38958
Address:	302 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP005136561
Facility Status:	Not reported
Location Address 1:	302 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005136561
Mailing Name:	CON EDISON - SERVICE BOX 38958
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

L174 **CON EDISON - SERVICE BOX 38958** **RCRA-LQG** **1024891701**
NW **302 3RD AVE** **NYP005136561**
< 1/8 **BROOKLYN, NY 11215**
0.108 mi.
570 ft. **Site 2 of 6 in cluster L**

Relative: **Lower**

Actual: **15 ft.**

RCRA-LQG:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - SERVICE BOX 38958
Handler Address:	302 3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP005136561
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017

CON EDISON - SERVICE BOX 38958 (Continued) **1024891701**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON - SERVICE BOX 38958 (Continued) **1024891701**

Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170907
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170907
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - SERVICE BOX 38958
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON - SERVICE BOX 38958 (Continued) **1024891701**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J175 **MANHOLE 5436** **NY Spills** **S106866703**
South **4TH AVE/3RD ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.108 mi.
570 ft. **Site 3 of 4 in cluster J**

Relative: **Higher**
Actual: **29 ft.**

SPILLS:
Name: MANHOLE 5436
Address: 4TH AVE/3RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0412308 / 2005-02-18
Facility ID: 0412308
Facility Type: ER
DER Facility ID: 273084
Site ID: 337753
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2005-02-17
Investigator: SKARAKHA
Referred To: Not reported
Reported to Dept: 2005-02-18
CID: 74
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-02-18
Spill Record Last Update: 2005-02-18
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT DESK
DEC Memo: "e2mis no 157277 2-17-05 11:20HRS K. NIXON 29766 (U.G) REPORTS, FOUND ONE GALLON OF UNKNOWN OIL ON 100 GALLONS OF WATER IN MH5436. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE

MANHOLE 5436 (Continued) **S106866703**

AFFECTED. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED. NO INJURIES WERE RELATED TO SPILL WITH NO WEATHER CONDITIONS CONTRIBUTING TO THE HAZARD OF THE SPILL. OIL WAS DISCOVERED WHILE INSPECTING SPARE DUCTS FOR SECONDARY. CAN NOT VERIFY IF THERE IS ANY OTHER OIL FILLED EQUIPMENT IN HOLE. ENV STOP TAG# 11976 WAS PLACED. ALSO CAN NOT VERIFY IF THERE IS ANY SEWER CONNECTIONS OR SUMPS. ONE LIQUID SAMPLE WAS TAKEN ON A E PRIORTY AND CLEANUP PENDING LAB SAMPLE. LAB RESULT RECEIVED 2/17/05 - 2010. 05-01385. <1.0 PPM. TJ - 50495 UPDATE:
2/18/05 - 0200 K. HUFFORD - ENV. OPS., REPORTS AN EARTHEN SUMP IN THE STRUCTURE. THIS INCIDENT IS NOW OFF THE 24 HR CLOCK. CLEANUP CONTINUES. UPDATE: 2/18/05 - 0350 K. HUFFORD - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. SUMP CEMENTED. TAG # 11976 REMOVED."

Remarks: "1 gallon of unknown oil on 100 gallons of water. Cleanup is in progress - they found an earthen sump. Ref. 157277 "

All Materials:

Site ID:	337753
Operable Unit ID:	1099770
Operable Unit:	01
Material ID:	580015
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M176 **ABF FREIGHTS** **NY Spills** **S126998057**
North **545 PRESIDENT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.109 mi.
573 ft. **Site 1 of 6 in cluster M**

Relative: **Lower**
Actual: **21 ft.**

SPILLS:

Name:	ABF FREIGHTS
Address:	545 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2006668 / 2020-10-22
Facility ID:	2006668
Facility Type:	ER
DER Facility ID:	560595
Site ID:	612520
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2020-10-22
Investigator:	AAOBLIGA
Referred To:	Not reported
Reported to Dept:	2020-10-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other

ABF FREIGHTS (Continued) **S126998057**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-10-22
Spill Record Last Update:	2020-10-22
Spiller Name:	MATTHEW ANDRLE
Spiller Company:	ABF FREIGHTS
Spiller Address:	545 PRESIDENT ST
Spiller Company:	999
Contact Name:	MATTHEW ANDRLE
DEC Memo:	"10/22/2020 - Clean harbors is en route. It was a 270 gallon tote of ethal alcohol. Spilled to the road. Upside down leaking from the top. Clean Harbors contact person - Martin Howard. 631 260 8608. When Clean Harbors arrived only a small puddle of alcohol was remaining on the sidewalk. They soaked it up. Clean up is complete. Spill closed."
Remarks:	"tote fell from lift gate, no sewers. c/u pending"

All Materials:

Site ID:	612520
Operable Unit ID:	1359653
Operable Unit:	01
Material ID:	2371250
Material Code:	0303B
Material Name:	ethyl alcohol
Case No.:	00064175
Material FA:	Other
Quantity:	3.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

N177 **2ND & 3RD AVE** **NY Spills** **S104510741**
West **2ND & 3RD AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.109 mi.
573 ft. **Site 1 of 3 in cluster N**

Relative: **Lower**

Actual: **14 ft.**

SPILLS:

Name:	2ND & 3RD AVE
Address:	2ND & 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9914001 / 2003-08-08
Facility ID:	9914001
Facility Type:	ER
DER Facility ID:	109674
Site ID:	126958
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-03-11
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-03-11

2ND & 3RD AVE (Continued) **S104510741**

CID:	282
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-03-11
Spill Record Last Update:	2004-06-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MR KESSEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"THEY HAD A WASTE OIL SPILL ON THE STREET AT THE ABOVE LOCATION THE NYC DEPT WAS ON THE SCENE ALSO.SPILL WAS CLEANED UP. "

All Materials:

Site ID:	126958
Operable Unit ID:	1092302
Operable Unit:	01
Material ID:	292295
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N178 **MAN HOLE 5354** **NY Spills** **S110540059**
West **3RD AND AVE AND 2ND STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.110 mi.
581 ft. **Site 2 of 3 in cluster N**

Relative: **Lower**
Actual: **14 ft.**

SPILLS:

Name:	MAN HOLE 5354
Address:	3RD AND AVE AND 2ND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1006176 / 2010-09-24
Facility ID:	1006176
Facility Type:	ER
DER Facility ID:	394522
Site ID:	439522
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-09-04
Investigator:	RWAUSTIN

MAN HOLE 5354 (Continued) **S110540059**

Referred To:	Not reported
Reported to Dept:	2010-09-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-04
Spill Record Last Update:	2010-09-24
Spiller Name:	ERT
Spiller Company:	CONEDISON
Spiller Address:	3RD AND AVE AND 2ND STREET
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"9/24/10 - Austin - Unk. oil found on water in vault - hole in concrete floor was patched after cleanup - Con Ed contained and removed spill - see documents in eDocs for further information - spill closed - end"
Remarks:	"1 gallon of oil on 50 gallons of water."

All Materials:

Site ID:	439522
Operable Unit ID:	1190160
Operable Unit:	01
Material ID:	2185130
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

O179 **B M T STOP DRY CLEANERS INC** **EDR Hist Cleaner** **1019933779**
NE **230 4TH AVE STE B** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.111 mi.
587 ft. **Site 1 of 9 in cluster O**

Relative: EDR Hist Cleaner
Higher

Actual: **25 ft.**

Year:	Name:	Type:
1997	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
1998	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
1999	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2000	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2001	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2002	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2003	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2004	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2005	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs

B M T STOP DRY CLEANERS INC (Continued) **1019933779**

2006	BMT STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2007	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2008	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2009	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2010	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2011	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2012	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2013	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs
2014	B M T STOP DRY CLEANERS INC	Drycleaning Plants, Except Rugs

---

J180 **CON EDISON SERVICE BOX: 75190** **RCRA NonGen / NLR** **1016969308**
South **260 3RD ST FRONT OF** **NY MANIFEST** **NYP004429650**
< 1/8 **BROOKLYN, NY 11215**
0.116 mi.
614 ft. **Site 4 of 4 in cluster J**

Relative: **Higher**

Actual: **29 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140228
Handler Name:	CON EDISON SERVICE BOX:	75190
Handler Address:		260 3RD ST FRONT OF
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004429650
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 75190 (Continued) **1016969308**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140130
Handler Name: CON EDISON SERVICE BOX:	75190
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 75190 (Continued) **1016969308**

Receive Date:	20140228
Handler Name: CON EDISON SERVICE BOX:	75190
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	260 3RD ST FRONT OF
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004429650
Facility Status:	Not reported
Location Address 1:	260 3RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004429650
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 75190 (Continued) **1016969308**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/30/2014
Trans1 Recv Date:	01/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004429650
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697541JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P181 **CONSTRUCTION SITE** **NY Spills** **S113818062**
SSW **340 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.119 mi.
630 ft. **Site 1 of 11 in cluster P**

Relative: SPILLS:
Higher

Name:	CONSTRUCTION SITE
Address:	340 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1302908 / 2013-06-17

Actual:
25 ft.

CONSTRUCTION SITE (Continued) **S113818062**

Facility ID:	1302908
Facility Type:	ER
DER Facility ID:	333884
Site ID:	483360
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	2401
Spill Date:	2013-06-17
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2013-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-06-17
Spill Record Last Update:	2013-06-19
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	UNKNOWN
DEC Memo:	"could not decipher address from report. Contacted hotline and that is what was taken. No other info avail as caller was anonymous. spill closed due to lack of info. Caller followed up and gave correct address. Open spill 0704349 exists. This spill remains closed as it is a duplicate. See 0704349 for more info."
Remarks:	"caller reports stong gas smell and dark soil being excavated"

All Materials:

Site ID:	483360
Operable Unit ID:	1233077
Operable Unit:	01
Material ID:	2231940
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

P182 **PARKSIDE SERVICE CENTER** **NY Spills** **S108762756**
SSW **340 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.119 mi.
630 ft. **Site 2 of 11 in cluster P**

Relative: **Higher**

Actual: **25 ft.**

SPILLS:

Name:	PARKSIDE SERVICE CENTER
Address:	340 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0704349 / 2014-03-28
Facility ID:	0704349
Facility Type:	ER
DER Facility ID:	333884
Site ID:	384480
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-07-18
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2007-07-18
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-07-18
Spill Record Last Update:	2021-03-02
Spiller Name:	FRANCIS ONAGA
Spiller Company:	PARKSIDE SERVICE CENTER
Spiller Address:	340 4TH AVENUE
Spiller Company:	999
Contact Name:	FRANCIS ONAGA
DEC Memo:	"Sangesland called Francis Onaga and left a voice message asking for the name/address/contact info for the property owner of 240 Flood Ave, Brooklyn. A CSL letter needs to be sent. 7/19/07 - Raphael Ketani. The contact person is Francis Onaga of CES Environmental at (732) 257-9955. I tried to call her, but could only leave a message. I tried to find the address 240 Flood Avenue in Brooklyn through Property Shark, the NYC Property Database and other resources, but Flood Avenue didn't come up anywhere. I will wait for Ms. Onaga to call back. 7/23/07 - Raphael Ketani. I tried to reach Ms. Onaga, but could only leave a message. I did an Internet Search for CES Environmental and found several companies that have CES in their name. I sent e-mails to each of them. However, some didn't respond and the ones that did said they didn't have anyone by the name of Francis Onaga. 7/26/07 - Raphael Ketani. Ms. Onaga didn't call back. I left another message. 8/13/07 - Raphael Ketani. Susan Sarch, Esq., (914) 682-7800, ext 30, of Zarin & Steinmetz called and left a message on 8/10/07 regarding the Parkside Service Center. I tried to return her call, but could only leave a message. Ms. Sarch returned my call. She said that she represented a potential buyer and that she

PARKSIDE SERVICE CENTER (Continued) **S108762756**

had the permission of the owner to do the investigation. She asked for a meeting, but I told her to first send a site investigation plan. She said she thought there was an old investigation report for the site. I told her to send DEC a copy. In the meantime, I said, have the consultants put together a plan. She said she will have them do it. I asked her what the correct address of the site was. She said it is 340 4th Avenue, Brooklyn. 10/2/07 - Raphael Ketani. I tried to contact Ms. Sarch, but could only leave a message. There is no PBS registration for the site. The owner is Parkside Service Center, Inc., 340 4th Avenue, Brklyn., NY, 11215. I sent a CSL. 10/23/07 - Raphael Ketani. Ms. Sarch tried to call me earlier today. I tried to return her phone call, but could only leave a message. Ms. Sarch called me back. She said that the present owner of the site and her client, the prospective buyer, are negotiating the contract for the sale of the property and the contract for the environmental consultant who will be hired to do the investigation. I reminded Ms. Sarch that the tanks that had existed on site, and any that are found to still be present on site, must be registered with the DEC. She said she was writing this down as part of a laundry list of things that need to be done. She said that the environmental investigation will tentatively take place in November. 11/28/07 - Raphael Ketani. I contacted Ms. Sarch (914) 682-7800, ext 30. She said that the prospective buyer is close to hiring an environmental company to do the investigation. She said that as soon as she knows who it is, then DEC will be notified. 12/6/07 - Raphael Ketani. Dawn Vought of C.A. Rich Consultants (516) 576-8844 called. She said she represented a potential buyer and wanted to know what needed to be done at the site to bring it into environmental compliance. She said the tanks will all be removed and soil borings and groundwater wells will be installed. I told her the tanks needed to be cleaned out and abandonded properly and registered with DEC, soil samples and groundwater samples needed to be submitted to a laboratory, and DEC needed to get all of the analytical data. She said she understood and will relay this information to her client. 1/9/07 - Raphael Ketani. I tried to contact Ms. Sarch, but could only leave a voice mail. 1/10/07 - Raphael Ketani. Ms. Sarch returned my call and left a message. She stated that C.A. Rich Consultants will do the remediation. Right now, they are in the process of doing the testing (boring and sampling). Asbestos abatement is taking place and demolition. 4/8/08 - Raphael Ketani. I contacted Ms. Vought. She said that Con Ed has been slow regarding issuing permits and disconnecting utilities. However, her demolition contractor expects to have the necessary permits within a week in order to start the work. She said that all of the contractors are lined up. The PBS registration is being worked on and she has been in contact with Nick Lombardo of Region 2 PBS. 4/22/08 - Raphael Ketani. Ms. Vought sent me an e-mail stating that the tank pull will be on 4/30/08. The process will take place for a week. 4/30/08 - Raphael Ketani. Ms. Vought told me that the tank pulling started today. After the tanks are pulled, field screening with a PID meter will take place and point samples will be taken. I checked the PBS database. The site has a registration. It is #2-347353. There are 12 tanks closed in place. All had gasoline. One was 4,000 gals. and the rest were 550 gals. 5/1/08 - Raphael Ketani. Ms. Vought pulled the tanks and found oil in the tank grave. She called in a new spill. It was assigned number 0801262. I am closing the later spill case and combining it with this older one. 5/2/08 - Raphael Ketani. I spoke to Ms. Vought regarding the site

PARKSIDE SERVICE CENTER (Continued) **S108762756**

investigation. She said that they discovered that the tanks were not abandoned properly. Only the fill ports were filled with cement. However, the tanks had a little liquid inside and free product. She added that they are working in a different area of the site and they have discovered 4 more tanks that no one knew about, aside from the 14 that were known to be in one area. I told her the associated PBS case lists only 12 tanks. She said that there should have been 2 more on the list - a 550 gal. waste oil tank and a #2 fuel oil 550 gal. tank. I told her these tanks are not in the database and will have to be added. She said that once all the tanks are discovered, then a revised PBS form will be submitted. Ms. Vought mentioned that when they removed the #2 fuel oil tank, they found floating product and they vacuumed it up. Then more product and liquid entered the tank grave and they vacuumed this up, too. She said that they are watching the hole for more liquid. I told her that it sounds like there is extensive groundwater contamination. She agree and said that a full investigation will take place. I told her that the groundwater contamination and flow will have to be determined on and off site. She said that they will do this. I asked her to keep DEC informed as to what is taking place. She said she will. 8/18/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The case manager needs to make followup calls to check on the progress of the investigation and remediation. The DEC needs to receive the investigation/remediation report and the revised PBS registration. 05/209/09- Zhune spoke to Ms. Vought. She said a year ago they got a work stopped from MTA becouse a subway extention is closed by where they were doing excavation. Since this time no work was done at this site. She also said the owner is running on some financial issues. 10/06/09- Zhune spoke to Ms. Vought. She said the owner put us a hold since June /08 She gave me the following information; Office 31 West 3th st. Suite 506 New york, NY 10001 Owner: Joseph Zafarani 212- 221-5331 Fax # 212-221-5345 Tried to contact Mr. Zafarani. Office said he will be back next week any day after 3:00pm. 08/31/10-Zhune. John Bogdenki 293- 630-1406 called. He said owner requested to do a soil and grondwater investigation of the site. 02/2/12-Zhune called Ms Vought. Estela from C.A Rich Consultants said that Ms. Vought is no longer with Rich Consultant. She is going to find out who is managing this case and she will call back with the information. Mr. Charles Rich from Rcich Consultant called back and let me know that they stopped work at this site becouse they did not get paid. They did not complete the remediation. They removed all the tanks and probably half of the soil contaminated and no groundwater innvestigation. 02/2/12- Zhune called the owner Mr. Joseph Zafarani. Mr. Zafarani said that he hired BL company to do the remediation. The contact person is John Bogdanski(203-630-1406 Ext. 4256. Tried to contact John. I left a message. 02/27/12- John Bogdanski called to say that they are going to send the RAP in two weeks. 01/02/2011- BL Company sent the RemediaL Investigation Work Plan dated 01/05/2011. 01/2012- BLCompany sent the RemediaL Investigation Report dated 01/2012. 1.- 10 soil borings were installed across the project site and 24 soil samples were collected from the soil borings' 2.- Four Monitoring wells were installed to establish groundwater flow direction and groundwater samples were collected from the wells. 3.- Nine soil vapor were installed throughout the site and nine soil vapors were collected -Soil. ----- The soil analytical results indicated no VOCS and inorganic compounds detected at concentrations that exceed the limit. SVOCs were detected

PARKSIDE SERVICE CENTER (Continued) **S108762756**

at concentrations that exceeded the limit in sample B-3(18'-19')(Benzo (a) anthracene 1.05mg/kg), sample B-5(5.5'-6.5')(Benzo (a) anthracene 28.4 mg/kg, benzo (a) pyrene 62.8 mg/kg, benzo (b) fluoranthene 39.3 mg/kg, Indeno (1,2,3-cd pyrene), sample B-6(9'-10')(Acenaphthene 970 mg/kg, Anthracene 539 mg/kg, fluoranthene 589 mg/kg, Fluorene 463 mg/kg, naphthslene 4880 mg/kg, Phenanthrene 1470 mg/kg, pyrene 935 mg/kg. Sample B-6)9'-10')contained evidence of non-aquous phase liquid (NAPL). --Groundwater. ---------- The groundwater analytical results indicated VOCs and SVOCs exceeded the limit in sample MW-1(1,2,4 trimethylbenzene 420 ug/l,Ethylbenzene 580 ug/l, p&m-xylenes 1500 ug/l, Acenaphthene 51.2 ug/lt, Sample MW-2 (1,2,4 trimethylbenzene 530 ug/l, Ethylbenzene 470 ug/l, o-xylene 720 ug/l, p-&m xylenes 1800 mg/lt, toluene 1100 ug/l, Xylenes total 2600 mg/l), sample MW-3 (1,2,4 trimethylbenzene 9.5 ug/lt), sample MW-4(1,2,4 trimethylbenzene 46 ug/lt, 1,3,5 trimethylbenzene 34 ug/lt, benzene 150 ug lt, Ethylbenzene 57 ug/lt, Isopropylbenzene 13 ug/lt, N-propylbenzene 9.1 ug lt, p-&m xylenes 48 ug/lt, Isopropyltoluene 11 ug/lt, toluene 14 ug/lt, Xylenes total 55 ug/lt). -SOIL VAPOR. ---------- Nine VOCS were detected in soil vapor samples at concentrations above the limit including 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, 2-butanone, acetone, benzzene, methylene chloride, n-hexane,toluene and trichloroethylene(TCE). 4/10/12-Sent a review letter with following requirements: 1.-Delineation of Soil and Groundwater Contamination, installation of three downgradient wells along south side of 3rd Street. 2.- Installation of soil boring at all remote fill port. 3.-Submission of development plan for the site 4.- Submission of vapor and Moisture Mitigation techniques to be used in the site development. 04/03/12- Mr. Zafarani called, He want to have a meeting to disscuss the DEC-letter sent to him on 4/10/12. 04/05/12-Zhune called Mr. Zafarani could not speak to him, left a message with his secretary that the Department have no problem to meet him but first he has to send the Remedial Action Plan. 04/07/12-Zhune called MR. Zafarani. Her secretary said that she spoke to him in reference to the Remedial Action Plan. She said Mr Bodanski from BL company is in the process to send the RAP. 4/10/12- In response to RIR 01/05/2011. DEC-Requiremnts on letter dated March 02, 2011 1. Delineation of soil and GW incluiding installation of three downgradient wells along south side of 3rd street. 2.Installation of soil borings at all remote fill port 3.Subnmission of development plan for the site 4.Submission of vapor and moisture mitigation techniques to be used in the site development. 07/10/12- Hydro Tech Environmental sent the subsurface investigsation report dated 07/19/12 Three soil probes and three monitoring wells were installed. Soil probes SP-1 and SP-2 were installed along the sidewalk between the property and 3rd street. oil probes SP-3 was installed along the sidewalk between the property and 4th avenue. Probes SP-1, SP-2 and Sp-3 were converted to monitorind wells Mw-5,MW-6 andMW-7 respectively. The soil analytical results identified (6) VOCs (1,2,4 trimethylbenzene, 1,3,5 trimethylbenzene 100mg/kg, ethylbenzene, n-propylbenzene 19 mg/kg, naphthalene 35 mg/kg, xylene total 33 mg/kg) at concentrations exceeding the limits in SP-3. The groundwater analitycal results indicates VOCs (1,2,4 trimethylbenzene 6.7 ug/l, benzene 6.6 ug/l)exceedimg the limits in MW-6, and VOCs (1,2,4 trimethylbenzene 1000 ug/l, 1,3,5 trimethylbenzene 540ug/l, ethylbenzene 770 ug/l, n-propylbenzene 200 ug/l, n-butylbenzene 82 ug/l, naphthalene 490 ug/l, p&m xylenes 740 ug/l, Xylene total 740

PARKSIDE SERVICE CENTER (Continued) **S108762756**

ug/l and p-isopropyltoluene 60ug/l at concntration exceedimg the limits in MW-7. 07/18/12-In response to the Subsurfaace Investigation Report. DEC-requirements on letter dated 07/19/12 1.Submission of Remedial Action Plan to remediate contamination at SP-3 /MW-7 2.Subnmission of development plan for the site 3.Submission of vapor and moisture mitigation techniques to be usedinthe ite development 08/20/12- Hydro Tech Environmental sent the Remedial Action Plan dated 07/19/12 The RAP proposed: 1. Analysis of groundwater samples for common aquifer parameters in order to establish a brechmark of aquifer characteristics and to evaluate the success of the remedial program. 2. Groundwater contamination will be treated via bioremedial solutions. 3. Implementation of a groundwater-monitoring program. 4. Installation of a vapor barrier and active depressurization system beneath the foundation of new development. 08/21/12- DEC reviewed the RAP and sent a letter dated August 27,2012 with the following requirements: 1. Plans for SSDS to be reviewed by the NYCDOH. 2. Injections upgradient of source areas. 3. Delineation of soil and groundwater contamination via installation of two down-gradient monitoring wells from MW-7 4. Sensitive receptor/ surrounding area Hyfro Tech Environmental sent a Remedial Action Plan dated August 23/12. 12/6/12-Zhune reviewed site status due to recent extreme workload on other spill sites associated with Hurricane Sandy. 3/18/13- Paul sent the following email to Micheal Hughed from NYSDOH. Michael Please use the web link below to upload the remedial investigations and remedial action work plan including a vapor barrier and SSDS design specifications prepared for the above referenced spill site. We appreciate if you can provide your approval of the proposed vapor barrier and SSDS design and specs. I appreciate your expedited response on this matter as construction at this site is scheduled very soon and was delayed after we were informed that we need NYSDOH approval of the SSDS system. 3/18/13-Michael Hughes from NYSDOH sent the following email. The workplan looks fine. DOH has no comments. 06/19/13- Paul Matli from Hydroteck called to notify concern about strong odor from excavation. At 2:oo pm jeff Vought, Veronica Zhune and Paul Matli had a conference call. Jeff required to Paul to subbmit the following: 1. Comunity Air Monitroing Plan Camp. 2. Star air monitoring tomorow 6/20/13 in the morning. 06/19/13- Zhune visited the site met Paul and the contractor. Michael explained that as the excavation was getting close to the area where the tanks were located the gasline odors were really strong. He also said that the soil removed for placement of concrete footing and grade beams will be used to level the excavation. 06/20/13-Paul emailed the following: documents: -Community Air Monitoring Plan (CAMP) -Plan of past trenching exercise to characterize the soil. -Waste characterization data for a 6-grab composite sample collected from six grids across the site to 4 feet in anticipation of mixed missing from excavating and moving of soil for footing foundations to 4 feet. 01/28/14- Endpoint samples not collected. however no longer required as per Vought due to known soil conamination previuosly documented, instalation of SSDS, and relatively clean downgradient groundwater. 3/5/14-Paul sent the revised Vapor Barrier and Active SSD System Design Plan dated 3/5/14. 3/11/14-Paul sent the following email to Michael Hughes from NYSDOH. Michael attached please find a revised vapor barrier and active sub-slab depressurization system prepared for above spill site. You have reviewed and approved this plan before and the recent version includes a section for operation and maintenance 3/19/14-Michael Hughes from NYSDOH sent the following

PARKSIDE SERVICE CENTER (Continued) **S108762756**

email. I have no comments on the workplan. The O&M appears consistent with the approach outlined in our guidance. Spill Closed with active SSDS. 2/20/20- Zhune-Paul Matli from Hydroteck emailed the Documentation of Installation, Startup and Monitoring of Engineering Controls dated December 16, 2019. The report stated that SSDS starup was performed on December 9, 2019. The SSDS vacuum readings observed at the Dwyer Magnehelic gauges ranged between -2.3 inches H2O and -3.4 inches H2O. Organic vapors were measured at the four SSDS effluents utilizing a Photoionization detector. No organic vapors (,0.1 parts per million (PPM) were detected at SSDS-1 and SSD-2. Organic vapors in SSDS-3 were identified at 5.2 ppm and in SSDS-4 at 10.5 ppm. The vacuum was measured at the four sub-slab vacuum monitoring points with an Extech HD755 Differential Pressure manometer. Differential pressure readings obtained at the four vacuum monitoring points indicated a minimum vacuum 0f -0.03 inches H2O beneath the building slab. this level of negative pressure is evidence of a satisfactory sub-slab vacuum communication. Attachment C provides the SSDS monitoring log. 2/20/20-Zhune emailed the report to Nathan Walsh from NYSDOH. Nathan sent the following email: I reviewed the SSDS commissioning report for the above referenced spill. It appears that the SSDS is operating effectively, I have no comments to offer at this time. 3/2/21- Zhune-Paul Matli emailed the annual SSDS Inspection system dated January 27, 2021. Based upon the site inspection, the SSD system appears to be operating as designed to render the site protective of human health and the environment. No evidence of current of former deficiencies undermining the operation or function of the SSD system were identified during the site inspection. The active SSD system monitoring will continue to be monitored on an annual basis as per the NYSDEC -approved O&N plan. The next annual SSD system monitoring event is acgeduled for December 2021."

Remarks: "FOUND CONTAMINATED SOIL DURING BORINGS"

All Materials:

Site ID:	384480
Operable Unit ID:	1141783
Operable Unit:	01
Material ID:	2131994
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	340 4TH AVE - BKLN
Address:	340 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8911553 / 1990-03-08
Facility ID:	8911553
Facility Type:	ER
DER Facility ID:	333884
Site ID:	244057
DEC Region:	2
Spill Cause:	Human Error

PARKSIDE SERVICE CENTER (Continued) **S108762756**

Spill Class:	Not reported
SWIS:	2401
Spill Date:	1990-03-07
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1990-03-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	1990-03-08
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-08
Spill Record Last Update:	2006-03-17
Spiller Name:	Not reported
Spiller Company:	I P T TRUCKING, INC
Spiller Address:	1 SHERIDAN BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SPILL DUE TO UNAUTHORIZED DELIVERY. NYFD RESPONDS & SAYS PROBLEM IS ALLEVIATED."

All Materials:

Site ID:	244057
Operable Unit ID:	938436
Operable Unit:	01
Material ID:	441066
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	PARKSIDE SERVICE CENTER
Address:	340 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0801262 / 2008-05-01
Facility ID:	0801262
Facility Type:	ER
DER Facility ID:	333884
Site ID:	397156
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	2008-05-01
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2008-05-01

PARKSIDE SERVICE CENTER (Continued) **S108762756**

CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-01
Spill Record Last Update:	2008-05-01
Spiller Name:	DAWN VOUGHT
Spiller Company:	FORMER GAS
Spiller Address:	340 4TH AVE
Spiller Company:	001
Contact Name:	DAWN VOUGHT
DEC Memo:	"5/1/08 - Raphael Ketani. Site is the location of a tank pull today. The PBS case is #2-347353. There were 12 tanks. All of them had gas. One was 4000 gal. and the others were 550 gals. each. The tanks were closed in place. Once the tanks were pulled, oil was discovered in the tank graves. Hence, this spill was called in. The older associated spill case is #0704349. I am closing this newer spill case and combining it with the older one."
Remarks:	"from underground storage tank: doing tank removal today and some product in bottom of tank hole: FAFAEL KETANI FROM REGION 2 IS HANDLING A GAS SPILL AT ABOVE"

All TTF:

Facility ID:	0801262
Spill Number:	0801262
Spill Tank Test:	2453629
Site ID:	397156
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	397156
Operable Unit ID:	1154112
Operable Unit:	01
Material ID:	2144909
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

PARKSIDE SERVICE CENTER (Continued) **S108762756**

Units: G
Recovered: .00
Oxygenate: Not reported

P183 **PARKSIDE SERVICE CENTER** **NY UST** **U001839590**
SSW **340 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.119 mi.
630 ft. **Site 3 of 11 in cluster P**

Relative:
Higher

Actual:
25 ft.

UST:
Name: PARKSIDE SERVICE CENTER
Address: 340 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11215
Id/Status: 2-347353 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585671.26380
UTM Y: 4503054.66825
Site Type: Other

Affiliation Records:
Site Id: 17019
Affiliation Type: Facility Owner
Company Name: 340 4TH AVENUE, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 31 WEST 34TH STREET, SUITE 506
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 221-5331
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-07-31

Site Id: 17019
Affiliation Type: Mail Contact
Company Name: 340 4TH AVENUE, LLC
Contact Type: Not reported
Contact Name: JOE ZARARANI
Address1: 31 WEST 34TH STREET
Address2: SUITE 506
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 221-5331
EMail: ZAFARANI@AOL.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-07-31

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Site Id:	17019
Affiliation Type:	Facility Operator
Company Name:	PARKSIDE SERVICE CENTER
Contact Type:	Not reported
Contact Name:	NONE - VACANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	NONE
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-31

Site Id:	17019
Affiliation Type:	Emergency Contact
Company Name:	340 4TH AVENUE, LLC
Contact Type:	Not reported
Contact Name:	JOE ZAFARANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 221-5331
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-31

Tank Info:

Tank Number:	001
Tank ID:	33113
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	05/06/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

PARKSIDE SERVICE CENTER (Continued) **U001839590**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	33114
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/06/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number:	003
Tank ID:	33115
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/06/2008
Registered:	True
Tank Location:	Underground

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 33116
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

PARKSIDE SERVICE CENTER (Continued) **U001839590**

G00 - Tank Secondary Containment - None

Tank Number:	005
Tank ID:	33117
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/06/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	006
Tank ID:	33118
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/06/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	007
Tank ID:	33119
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/06/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	008
Tank ID:	33120
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/06/2008

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 009
Tank ID: 33121
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

PARKSIDE SERVICE CENTER (Continued) **U001839590**

L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 010
Tank ID: 33122
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 011
Tank ID: 33123
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 012
Tank ID: 33124
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 013
Tank ID: 224363
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 014
Tank ID: 224364
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

PARKSIDE SERVICE CENTER (Continued) **U001839590**

C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 015
Tank ID: 224365
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 016
Tank ID: 224366
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number: 017
Tank ID: 224367
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 018
Tank ID: 224368
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 750

PARKSIDE SERVICE CENTER (Continued) **U001839590**

Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 019
Tank ID: 224369
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 750
Install Date: Not reported
Date Tank Closed: 05/06/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

PARKSIDE SERVICE CENTER (Continued) **U001839590**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

P184 **PARKSIDE SERVICE STATION** **EDR Hist Auto** **1020972743**
SSW **340 FOURTH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.119 mi.
630 ft. **Site 4 of 11 in cluster P**

Relative: EDR Hist Auto
Higher

Actual:
25 ft.

Year:	Name:	Type:
1969	PARKSIDE SERVICE STATION	Gasoline Service Stations
1970	PARKSIDE SERVICE STATION	Gasoline Service Stations
1971	PARKSIDE SERVICE STATION	Gasoline Service Stations
1972	PARKSIDE SERVICE STATION	Gasoline Service Stations
1973	PARKSIDE SERVICE STATION	Gasoline Service Stations
1974	PARKSIDE SERVICE STATION	Gasoline Service Stations
1975	PARKSIDE SERVICE STATION	Gasoline Service Stations
1976	PARKSIDE SERVICE STATION	Gasoline Service Stations
1977	PARKSIDE SERVICE STATION	Gasoline Service Stations
1978	PARKSIDE SERVICE STATION	Gasoline Service Stations
1979	PARKSIDE SERVICE STATION	Gasoline Service Stations
1980	PARKSIDE SERVICE CENTER INC	Gasoline Service Stations
1982	PARKSIDE SERVICE CENTER INC	Gasoline Service Stations
1983	PARKSIDE SERVICE CENTER INC	Gasoline Service Stations
1985	PARKSIDE SERVICE CENTER INC	Gasoline Service Stations
1987	PARKSIDE SERVICE CENTER INC	Truck Rental And Leasing, Without Drivers
1991	PARKSIDE SERVICE CTR BROOKLYN	General Automotive Repair Shops
1992	PARKSIDE SERVICE CTR BROOKLYN	General Automotive Repair Shops
1996	MAGLIOCCO VICTOR	Automotive Repair Shops, NEC
1997	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
1998	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
1999	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2000	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2001	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2002	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2003	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2004	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2005	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2006	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops
2007	PARKSIDE SERVICE CENTER INC	General Automotive Repair Shops

---

L185 **CON EDISON** **NY MANIFEST** **S119078278**
NNW **284 THIRD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.121 mi.
641 ft. **Site 3 of 6 in cluster L**

Relative: NY MANIFEST:
Lower

Actual:
18 ft.

Name:	CON EDISON
Address:	284 THIRD AVE
City,State,Zip:	BROOKLYN, NY 11215

CON EDISON (Continued) **S119078278**

Country: USA
EPA ID: NYP004974760
Facility Status: Not reported
Location Address 1: 284 THIRD AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004974760
Mailing Name: CON EDISON
Mailing Contact: THERESA BURKARD
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/07/2016
Trans1 Recv Date: 09/07/2016
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/08/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004974760
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: 008166434FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S119078278**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L186 **CON EDISON** **NY MANIFEST** **S118954154**
NNW **284 3RD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.121 mi.
641 ft. **Site 4 of 6 in cluster L**

Relative:
Lower

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	284 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004959132
Facility Status:	Not reported
Location Address 1:	284 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004959132
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON (Continued) **S118954154**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/2016
Trans1 Recv Date:	08/26/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004959132
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	008166531FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O187 **CON EDISON** **PA MANIFEST** **S123093388**
NE **226 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.122 mi.
645 ft. **Site 2 of 9 in cluster O**

Relative: **Higher**

Actual: **25 ft.**

Manifest Details:

Year:	2017
Manifest Number:	010427666FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP005107812
Generator Date:	07/07/2017
Mailing Address:	Not reported

CON EDISON (Continued) **S123093388**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

M188 **CON EDISON SERVICE BOX: 43332** **RCRA NonGen / NLR** **1016961963**
NNE **604 UNION ST** **NY MANIFEST** **NYP004349064**
1/8-1/4 **BROOKLYN, NY 11231**
0.126 mi.
667 ft. **Site 2 of 6 in cluster M**

Relative: **Higher**

Actual: **23 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130921
Handler Name:	CON EDISON SERVICE BOX:	43332
Handler Address:		604 UNION ST
Handler City,State,Zip:		BROOKLYN, NY 11231
EPA ID:		NYP004349064
Contact Name:		ROSA PERALTA
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4586
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		ADMINISTRATIVE CLERK L1-2
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

CON EDISON SERVICE BOX: 43332 (Continued) **1016961963**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130821
Handler Name:	CON EDISON SERVICE BOX: 43332

CON EDISON SERVICE BOX: 43332 (Continued) **1016961963**

Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130921
Handler Name: CON EDISON SERVICE BOX: 43332
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 604 UNION ST
City,State,Zip: BROOKLYN, NY 11231
Country: USA
EPA ID: NYP004349064
Facility Status: Not reported
Location Address 1: 604 UNION ST
Code: BP
Location Address 2: SB 43332
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004349064
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported

CON EDISON SERVICE BOX: 43332 (Continued) **1016961963**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/21/2013
Trans1 Recv Date:	08/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004349064
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084362GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q189 **276 3RD AVENUE** **NY AST** **A100353041**
NNW **276 THIRD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.129 mi.
682 ft. **Site 1 of 5 in cluster Q**

Relative: **Lower**

Actual: **19 ft.**

AST:

Name:	276 3RD AVENUE
Address:	276 THIRD AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608461
Program Type:	PBS
UTM X:	585692.00583
UTM Y:	4503465.97706
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30313
Affiliation Type:	Facility Operator
Company Name:	276 3RD AVENUE
Contact Type:	Not reported
Contact Name:	276 REALTY ENTERPRISE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 290-1404
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-05-10

Site Id:	30313
Affiliation Type:	Emergency Contact
Company Name:	276 REALTY ENTERPRISE CORP
Contact Type:	Not reported
Contact Name:	MARK ROSE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 781-9483
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-05-10

Site Id:	30313
Affiliation Type:	Facility Owner
Company Name:	276 REALTY ENTERPRISE CORP
Contact Type:	MANAGER
Contact Name:	MARK ROSE

276 3RD AVENUE (Continued) **A100353041**

Address1:	1274 49TH STREET, SUITE 211
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 781-9483
EMail:	MNCO3@MSN.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-05-10

Site Id:	30313
Affiliation Type:	Mail Contact
Company Name:	276 REALTY ENTERPRISE CORP
Contact Type:	Not reported
Contact Name:	MARK ROSE
Address1:	1274 49TH STREET
Address2:	SUITE 211
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 781-9483
EMail:	MNCO3@MSN.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-09-22

Tank Info:

Tank Number:	001
Tank Id:	65196
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN

276 3RD AVENUE (Continued) **A100353041**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2009
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

L190 **JO-LEE TRUCKING** **RCRA NonGen / NLR** **1008374454**
NW **463 CARROLL ST** **NYR000131938**
1/8-1/4 **BROOKLYN, NY 11215**
0.135 mi.
713 ft. **Site 5 of 6 in cluster L**

Relative: **Lower**
Actual: **15 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	JO-LEE TRUCKING	
Handler Address:		463 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000131938
Contact Name:		ELEANOR RUSSO
Contact Address:		CARROLL ST
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-625-1598
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CARROLL ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	NO NAME FOUND	
Owner Type:		Private
Operator Name:	NO NAME FOUND	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

JO-LEE TRUCKING (Continued) **1008374454**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JO-LEE TRUCKING	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private

JO-LEE TRUCKING (Continued) **1008374454**

Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: ELEANOR RUSSO	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: JO-LEE TRUCKING	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: JO-LEE TRUCKING	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

JO-LEE TRUCKING (Continued) **1008374454**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050425
Handler Name: JO-LEE TRUCKING
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48849
NAICS Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

O191 **NYCT - UNION STATION R LINE** **RCRA NonGen / NLR** **1005905708**
NE **UNION ST & 4TH AVE** **NY MANIFEST** **NYR000107938**
1/8-1/4 **BROOKLYN, NY 11215**
0.136 mi.
718 ft. **Site 3 of 9 in cluster O**

Relative: **Higher**
Actual: **26 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: NYCT - UNION STATION R LINE
Handler Address: UNION ST & 4TH AVE
Handler City,State,Zip: BROOKLYN, NY 11215
EPA ID: NYR000107938
Contact Name: JAMES CRANDALL
Contact Address: JAY ST ROOM 819
Contact City,State,Zip: BROOKLYN, NY 11201
Contact Telephone: 718-243-4581
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Other
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: JAY ST ROOM 819

NYCT - UNION STATION R LINE (Continued) **1005905708**

Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:	NEW YORK CITY TRANSIT	
Owner Type:		Other
Operator Name:	NEW YORK CITY TRANSIT	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No

NYCT - UNION STATION R LINE (Continued) **1005905708**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 819
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-243-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 819
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-243-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 819
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-243-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYCT - UNION STATION R LINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

NYCT - UNION STATION R LINE (Continued) **1005905708**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCT - UNION STATION R LINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020717
Handler Name: NYCT - UNION STATION R LINE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: NYCTA UNION STREET STATION RR LINE
Address: UNION ST & 4TH AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYR000107938
Facility Status: Not reported
Location Address 1: UNION AND 4TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN

NYCT - UNION STATION R LINE (Continued) **1005905708**

Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000107938
Mailing Name: NYCTA UNION STREET STATION RR LINE
Mailing Contact: PETER
Mailing Address 1: 370 JAY STREET RM 819
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7182434227

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJR986628162
Trans2 State ID: Not reported
Generator Ship Date: 08/05/2015
Trans1 Recv Date: 08/05/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/05/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000107938
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 008274845FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: DM - Metal drums, barrels

NYCT - UNION STATION R LINE (Continued) **1005905708**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M192 **KLOR-DE CLEANERS** **NY DRYCLEANERS** **S110247069**
North **263 3RD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.136 mi.
720 ft. **Site 3 of 6 in cluster M**

Relative: **Lower**
Actual: **19 ft.**

DRYCLEANERS:

Name:	KLOR-DE CLEANERS
Address:	263 3RD AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Facility ID:	2-6103-00151
Phone Number:	718-875-4448
Region:	Not reported
Registration Effective Date:	2-Nov-19
Inspection Date:	2013-09-06 00:00:00
Install Date:	94/06
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

O193 **CON EDISON MANHOLE: 2618** **RCRA NonGen / NLR** **1016454185**
NE **4TH & UNION AVE** **FINDS** **NYP004318366**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.137 mi. **NY MANIFEST**
723 ft. **Site 4 of 9 in cluster O**

Relative: **Higher**
Actual: **27 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130704
Handler Name:	CON EDISON MANHOLE: 2618
Handler Address:	4TH & UNION AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004318366
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON MANHOLE: 2618 (Continued) **1016454185**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No

CON EDISON MANHOLE: 2618 (Continued) **1016454185**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20131227
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130604
Handler Name:	CON EDISON MANHOLE: 2618
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130704
Handler Name:	CON EDISON MANHOLE: 2618
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056509773

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

CON EDISON MANHOLE: 2618 (Continued) **1016454185**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016454185
Registry ID:	110056509773
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056509773
Name:	CON EDISON MANHOLE: 2618
Address:	4TH & UNION AVE
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	CON EDISON
Address:	4TH & UNION AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004318366
Facility Status:	Not reported
Location Address 1:	4TH AVE & UNION ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004318366
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/04/2013
Trans1 Recv Date:	06/04/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/06/2013

CON EDISON MANHOLE: 2618 (Continued) **1016454185**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004318366
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002018160GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M194 **CON EDISON SERVICE BOX: 43335** **RCRA NonGen / NLR** **1016964719**
North **578 UNION ST** **NY MANIFEST** **NYP004376315**
1/8-1/4 **BROOKLYN, NY 11231**
0.137 mi.
724 ft. **Site 4 of 6 in cluster M**

Relative: **Lower**

Actual: **20 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20131118
Handler Name:	CON EDISON SERVICE BOX:	43335
Handler Address:		578 UNION ST
Handler City,State,Zip:		BROOKLYN, NY 11231
EPA ID:		NYP004376315
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST

CON EDISON SERVICE BOX: 43335 (Continued) **1016964719**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported

CON EDISON SERVICE BOX: 43335 (Continued) **1016964719**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131018
Handler Name: CON EDISON SERVICE BOX:	43335
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131118
Handler Name: CON EDISON SERVICE BOX:	43335
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	578 UNION ST

CON EDISON SERVICE BOX: 43335 (Continued) **1016964719**

City,State,Zip:	BROOKLYN, NY 11231
Country:	USA
EPA ID:	NYP004376315
Facility Status:	Not reported
Location Address 1:	578 UNION ST
Code:	BP
Location Address 2:	SB 43335
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004376315
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	10/18/2013
Trans1 Recv Date:	10/18/2013
Trans2 Recv Date:	10/18/2013
TSD Site Recv Date:	10/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004376315
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002236802GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON SERVICE BOX: 43335 (Continued) **1016964719**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N195 **CON EDISON VAULT SUBMERSIBLE: 5837** **RCRA NonGen / NLR** **1016973813**
West **213 3RD ST** **NY MANIFEST** **NYP004476214**
1/8-1/4 **BROOKLYN, NY 11215**
0.138 mi.
731 ft. **Site 3 of 3 in cluster N**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140423
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 5837
Handler Address:	213 3RD ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004476214
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

CON EDISON VAULT SUBMERSIBLE: 5837 (Continued) **1016973813**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140323
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 5837
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY

CON EDISON VAULT SUBMERSIBLE: 5837 (Continued) **1016973813**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140423
Handler Name: CON EDISON VAULT SUBMERSIBLE: 5837
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 213 3RD ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004476214
Facility Status: Not reported
Location Address 1: 3RD AVE & 3RD STREET
Code: BP
Location Address 2: VAULT # 5837
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11210
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004476214
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

CON EDISON VAULT SUBMERSIBLE: 5837 (Continued) **1016973813**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/23/2014
Trans1 Recv Date:	03/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004476214
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002359353GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R196
WSW
1/8-1/4
0.140 mi.
739 ft.

CON EDISON
3RD ST & 3RD AVE
BROOKLYN, NY 11215

Site 1 of 10 in cluster R

NJ MANIFEST **S120668359**
N/A

Relative:
Lower

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004743779
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002621343GBF
EPA ID:	NYP004743779
Date Shipped:	3/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120668359**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R197 **VERIZON LOG 31756 MANHOLE 325** **RCRA NonGen / NLR** **1014917856**
WSW **3RD ST & 3RD AVE** **NYP000962894**
1/8-1/4 **BROOKLYN, NY 11215**
0.140 mi.
739 ft. **Site 2 of 10 in cluster R**

Relative: **Lower**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20080307
Handler Name:	VERIZON LOG 31756 MANHOLE 325	
Handler Address:		3RD ST & 3RD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP000962894
Contact Name:		JOHN QUATRALE
Contact Address:		HANSE AVE
Contact City,State,Zip:		FREEPORT, NY 11520
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		MGR
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		HANSE AVE
Mailing City,State,Zip:		FREEPORT, NY 11520
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

VERIZON LOG 31756 MANHOLE 325 (Continued) **1014917856**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211103
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20080307
Handler Name:	VERIZON LOG 31756 MANHOLE 325
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

VERIZON LOG 31756 MANHOLE 325 (Continued) **1014917856**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R198 **CON EDISON** **RCRA NonGen / NLR** **1018279550**
WSW **3RD ST & 3RD AVE** **FINDS** **NYP004743779**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.140 mi.
739 ft. **Site 3 of 10 in cluster R**

Relative: **Lower**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150305
Handler Name:	CON EDISON	
Handler Address:		3RD ST & 3RD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004743779
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1018279550**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150305
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1018279550**

Receive Date:	20150305
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067692777

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279550
Registry ID:	110067692777
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067692777
Name:	CON EDISON
Address:	3RD ST & 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215

R199 **CON EDISON** **NY MANIFEST** **S117741161**
WSW **3RD ST & 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.140 mi.
739 ft. **Site 4 of 10 in cluster R**

Relative:
Lower

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	3RD ST & 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004743779
Facility Status:	Not reported
Location Address 1:	250 3 ST
Code:	BP
Location Address 2:	SB45292
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004743779
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/05/2015
Trans1 Recv Date:	03/05/2015
Trans2 Recv Date:	03/10/2015
TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004743779
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002621343GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117741161**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R200 **CONSOLIDATED EDISON** **NY MANIFEST** **S108933201**
WSW **3 AVE & 3 STREET & 6 STREET** **N/A**
1/8-1/4 **NEW YORKBROOKLYN, NY 11201**
0.140 mi.
741 ft. **Site 5 of 10 in cluster R**

Relative: **Lower**
Actual: **14 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	3 AVE & 3 STREET & 6 STREET
City,State,Zip:	NEW YORKBROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004154290
Facility Status:	Not reported
Location Address 1:	3 AVE & 3 STREET & 6 STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORKBROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004154290
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CONSOLIDATED EDISON (Continued) **S108933201**

Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/2007
Trans1 Recv Date:	10/12/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004154290
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001451489FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D006
Waste Code 1_2:	D007
Waste Code 1_3:	D008
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P201 **PEP BOYS #0247** **NY AST** **A100520470**
SSW **354 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.142 mi.
748 ft. **Site 5 of 11 in cluster P**

Relative:
Higher

Actual:
26 ft.

AST:

Name:	PEP BOYS #0247
Address:	354 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-032301
Program Type:	PBS
UTM X:	585623.63993
UTM Y:	4503036.46767
Expiration Date:	07/26/2024
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	204
Affiliation Type:	Mail Contact
Company Name:	PEP BOYS - MANNY, MOE & JACK
Contact Type:	Not reported
Contact Name:	ANGELA BANKS
Address1:	3111 W. ALLEGHENY AVENUE
Address2:	ENVIRONMENTAL DEPARTMENT
City:	PHILADELPHIA
State:	PA
Zip Code:	19132
Country Code:	001
Phone:	(215) 430-9645
EMail:	ANGELA_BANKS@PEPBOYS.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-09-23

Site Id:	204
Affiliation Type:	Facility Operator
Company Name:	PEP BOYS #0247
Contact Type:	Not reported
Contact Name:	PEP BOYS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 596-2833
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-05

Site Id:	204
Affiliation Type:	Emergency Contact
Company Name:	RELACO HOLDING CO., LLC
Contact Type:	Not reported
Contact Name:	ANGELA BANKS

PEP BOYS #0247 (Continued) **A100520470**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(267) 994-0038
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-05

Site Id:	204
Affiliation Type:	Facility Owner
Company Name:	RELACO HOLDING CO., LLC
Contact Type:	ENVIRONMENTAL COORDINATOR
Contact Name:	ALANA PERSAD
Address1:	362 KINGSLAND AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 391-5300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-08-15

Tank Info:

Tank Number:	1
Tank Id:	252678

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/26/1999
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

PEP BOYS #0247 (Continued) **A100520470**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

P202 **PEP BOYS #0247** **NY UST** **U001831292**
SSW **354 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.142 mi.
748 ft. **Site 6 of 11 in cluster P**

Relative:
Higher

Actual:
26 ft.

UST:

Name:	PEP BOYS #0247
Address:	354 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-032301 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/26/2024
UTM X:	585623.63993
UTM Y:	4503036.46767
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	204
Affiliation Type:	Mail Contact
Company Name:	PEP BOYS - MANNY, MOE & JACK
Contact Type:	Not reported
Contact Name:	ANGELA BANKS
Address1:	3111 W. ALLEGHENY AVENUE
Address2:	ENVIRONMENTAL DEPARTMENT
City:	PHILADELPHIA
State:	PA
Zip Code:	19132
Country Code:	001
Phone:	(215) 430-9645
EMail:	ANGELA_BANKS@PEPBOYS.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-09-23

Site Id:	204
Affiliation Type:	Facility Operator
Company Name:	PEP BOYS #0247
Contact Type:	Not reported
Contact Name:	PEP BOYS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 596-2833
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM

PEP BOYS #0247 (Continued) **U001831292**

Date Last Modified: 2014-08-05

Site Id: 204
Affiliation Type: Emergency Contact
Company Name: RELACO HOLDING CO., LLC
Contact Type: Not reported
Contact Name: ANGELA BANKS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (267) 994-0038
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-08-05

Site Id: 204
Affiliation Type: Facility Owner
Company Name: RELACO HOLDING CO., LLC
Contact Type: ENVIRONMENTAL COORDINATOR
Contact Name: ALANA PERSAD
Address1: 362 KINGSLAND AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 391-5300
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-08-15

Tank Info:

Tank Number: 001A
Tank ID: 51747
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 12/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

PEP BOYS #0247 (Continued) **U001831292**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B99 - Tank External Protection - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	001B
Tank ID:	51748
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	12/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
B99 - Tank External Protection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	001C
Tank ID:	51749
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008

PEP BOYS #0247 (Continued) **U001831292**

Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 12/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B99 - Tank External Protection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 001D
Tank ID: 51750
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 12/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B99 - Tank External Protection - Other
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 001E
Tank ID: 51752
Tank Status: Closed - Removed

PEP BOYS #0247 (Continued) **U001831292**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	12/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B99 - Tank External Protection - Other

Tank Number:	001F
Tank ID:	51751
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	12/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B99 - Tank External Protection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel

PEP BOYS #0247 (Continued) **U001831292**

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002A
Tank ID:	51754
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	12/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B99 - Tank External Protection - Other

Tank Number:	002B
Tank ID:	51755
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	12/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

PEP BOYS #0247 (Continued) **U001831292**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
B99 - Tank External Protection - Other

Tank Number:	002C
Tank ID:	51756
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	12/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B99 - Tank External Protection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002D
Tank ID:	51758
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008

PEP BOYS #0247 (Continued) **U001831292**

Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 12/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B99 - Tank External Protection - Other
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 003A
Tank ID: 54676
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B99 - Tank External Protection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 003B
Tank ID: 54677
Tank Status: Closed - Removed
Material Name: Closed - Removed

PEP BOYS #0247 (Continued) **U001831292**

Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B99 - Tank External Protection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

P203 **PEP BOYS 247** **RCRA NonGen / NLR** **1004761053**
SSW **354 4TH AVE** **FINDS** **NYR000071936**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.142 mi. **NY MANIFEST**
748 ft. **Site 7 of 11 in cluster P**

Relative: **Higher**
Actual: **26 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	PEP BOYS 247
Handler Address:	354 4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYR000071936
Contact Name:	JOHN KERELO
Contact Address:	W ALLEGHENY AVE
Contact City,State,Zip:	PHILADELPHIA, NY 19132
Contact Telephone:	215-430-9277
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W ALLEGHENY AVE
Mailing City,State,Zip:	PHILADELPHIA, NY 19132
Owner Name:	THE PEP BOYS - MANNY MOE & JACK

PEP BOYS 247 (Continued) **1004761053**

Owner Type:	Private
Operator Name:	THE PEP BOYS - MANNY MOE & JACK
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

PEP BOYS 247 (Continued) **1004761053**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: THE PEP BOYS - MANNY MOE & JACK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3111 W ALLEGHENY AVE
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19132
Owner/Operator Telephone: 215-430-9277
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE PEP BOYS - MANNY MOE & JACK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3111 W ALLEGHENY AVE
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19132
Owner/Operator Telephone: 215-430-9277
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE PEP BOYS - MANNY MOE & JACK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3111 W ALLEGHENY AVE
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19132
Owner/Operator Telephone: 215-430-9277
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: PEP BOYS 247
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

PEP BOYS 247 (Continued) **1004761053**

Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PEP BOYS 247
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990528
Handler Name: PEP BOYS 247
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004553395

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004761053

PEP BOYS 247 (Continued) **1004761053**

Registry ID:	110004553395
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004553395
Name:	PEP BOYS 247
Address:	354 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	PEP BOYS 247
Address:	354 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000071936
Facility Status:	Not reported
Location Address 1:	354 4TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000071936
Mailing Name:	PEP BOYS 247
Mailing Contact:	PEP BOYS 247
Mailing Address 1:	354 4TH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJD054126164
Generator Ship Date:	11/28/2012
Trans1 Recv Date:	11/28/2012
Trans2 Recv Date:	11/29/2012
TSD Site Recv Date:	12/11/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000071936
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	005429122FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

PEP BOYS 247 (Continued) **1004761053**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	21
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P204 **PEP BOYS #0247** **NY CBS S108410815**
SSW **354 4TH AVE** **NY Spills N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.142 mi.
748 ft. **Site 8 of 11 in cluster P**

Relative:
Higher

Actual:
26 ft.

CBS:

Name:	PEP BOYS #0247
Address:	354 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
CBS Number:	2-000417
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	585623.63993
UTMY:	4503036.46767

SPILLS:

Name:	MENDON LEASING
Address:	354 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9800967 / 2002-03-19
Facility ID:	9800967
Facility Type:	ER
DER Facility ID:	68111
Site ID:	72114
DEC Region:	2
Spill Cause:	Unknown

PEP BOYS #0247 (Continued) **S108410815**

Spill Class:	B4
SWIS:	2401
Spill Date:	1998-04-22
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1998-04-22
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-22
Spill Record Last Update:	2002-03-19
Spiller Name:	ABOVE CALLER
Spiller Company:	MENDON LEASING
Spiller Address:	354 4TH AVE
Spiller Company:	001
Contact Name:	ABOVE CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE see file."
Remarks:	"tank removal found contaminated soil - spill contained - unk further about cleanup"

P205 **PEP BOYS #0247** **NY AST** **A100520437**
SSW **354 4TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.142 mi.
748 ft. **Site 9 of 11 in cluster P**

Relative:
Higher

Actual:
26 ft.

AST:

Name:	PEP BOYS #0247
Address:	354 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000417
Program Type:	CBS
UTM X:	585623.63993
UTM Y:	4503036.46767
Expiration Date:	N/A
Site Type:	Other Wholesale/Retail Sales

Tank Info:

Tank Number:	2
Tank Id:	207205
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/26/1999

PEP BOYS #0247 (Continued) **A100520437**

Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/17/2005
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

L206 **LINDA TOOL & DIE CORP** **RCRA-VSQG 1000791081**
NW **459 CARROLL ST** **FINDS NYD987025822**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.142 mi. **NY MANIFEST**
752 ft. **Site 6 of 6 in cluster L**

Relative: **Lower**
Actual: **15 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	LINDA TOOL & DIE CORP	
Handler Address:		459 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYD987025822
Contact Name:		MIKE DIMARINO
Contact Address:		CARROLL ST
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-522-2066
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CARROLL ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	MIKE DIMARINO	
Owner Type:		Private
Operator Name:	MIKE DIMARINO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

LINDA TOOL & DIE CORP (Continued) **1000791081**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

LINDA TOOL & DIE CORP (Continued) **1000791081**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MIKE DIMARINO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	459 CARROLL ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-522-2066
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MIKE DIMARINO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	459 CARROLL ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-522-2066
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MIKE DIMARINO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	459 CARROLL ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-522-2066
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: LINDA TOOL & DIE CORP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: LINDA TOOL & DIE CORP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

LINDA TOOL & DIE CORP (Continued) **1000791081**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19930114
Handler Name:	LINDA TOOL & DIE CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004499766

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000791081
Registry ID:	110004499766
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004499766
Name:	LINDA TOOL & DIE CORP
Address:	459 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215

LINDA TOOL & DIE CORP (Continued) **1000791081**

NY MANIFEST:

Name:	LINDA TOOL & DIE
Address:	459 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYD987025822
Facility Status:	Not reported
Location Address 1:	459 CARROLL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	1010

NY MANIFEST:

EPAID:	NYD987025822
Mailing Name:	LINDA TOOL & DIE
Mailing Contact:	MICHAEL MARINO
Mailing Address 1:	459 CARROLL ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	1010
Mailing Country:	USA
Mailing Phone:	7185222066

S207 **CON EDISON** **NY MANIFEST** **S117062742**
North **251 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.150 mi.
794 ft. **Site 1 of 6 in cluster S**

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	251 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004551230
Facility Status:	Not reported
Location Address 1:	UNION & 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004551230
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported

CON EDISON (Continued) **S117062742**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/04/2014
Trans1 Recv Date:	06/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004551230
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	004808656FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	45
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S208 **CON EDISON EXCAVATION: TRENCH** **RCRA NonGen / NLR** **1017777232**
North **251 3RD AVE** **NYP004551230**
1/8-1/4 **BROOKLYN, NY 11215**
0.150 mi.
794 ft. **Site 2 of 6 in cluster S**

Relative: **Lower**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140703
Handler Name:	CON EDISON EXCAVATION:	TRENCH
Handler Address:		251 3RD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004551230
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON EXCAVATION: TRENCH (Continued) **1017777232**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140603
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140603
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON EXCAVATION: TRENCH (Continued) **1017777232**

Electronic Manifest Broker: Not reported

Receive Date: 20140703
Handler Name: CON EDISON EXCAVATION: TRENCH
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T209 **HOLYLAND AUTO REPAIR INC.** **NY AST** **A100178067**
NNE **637 UNION STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.151 mi.
795 ft. **Site 1 of 3 in cluster T**

Relative: **Lower**
Actual: **22 ft.**

AST:
Name: HOLYLAND AUTO REPAIR INC.
Address: 637 UNION STREET
City,State,Zip: BROOKLYN, NY 11217
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605796
Program Type: PBS
UTM X: 585857.74766
UTM Y: 4503504.81433
Expiration Date: 04/27/2026
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 27663
Affiliation Type: Facility Owner
Company Name: HOLYLAND AUTO REPAIR INC.
Contact Type: PRESIDENT
Contact Name: YOUSEF DARI
Address1: 637 UNION ST.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001

HOLYLAND AUTO REPAIR INC. (Continued) **A100178067**

Phone:	(718) 246-9695
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-03-18

Site Id:	27663
Affiliation Type:	Mail Contact
Company Name:	HOLYLAND AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	YOUSEF DARI
Address1:	637 UNION STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 246-9695
EMail:	HOLYLAND637@AOL.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-03-31

Site Id:	27663
Affiliation Type:	Facility Operator
Company Name:	HOLYLAND AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	YOUSEF DARI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 246-9695
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-06-19

Site Id:	27663
Affiliation Type:	Emergency Contact
Company Name:	HOLYLAND AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	YOUSEF DARI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 923-5205
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2021-05-11

HOLYLAND AUTO REPAIR INC. (Continued) **A100178067**

Tank Info:

Tank Number:	001
Tank Id:	60481
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2003
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Q210 **RIDGE COMPLETE AUTO** **NY AST** **A100348969**
NNW **264 THIRD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.151 mi.
798 ft. **Site 2 of 5 in cluster Q**

Relative: AST:
Lower

Actual:
19 ft.

Name:	RIDGE COMPLETE AUTO
Address:	264 THIRD AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611243
Program Type:	PBS
UTM X:	585712.79814
UTM Y:	4503506.45739
Expiration Date:	02/04/2015
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

RIDGE COMPLETE AUTO (Continued) **A100348969**

Site Id:	424625
Affiliation Type:	Facility Owner
Company Name:	RIDGE COMPLETE AUTO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	264 THIRD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 832-1413
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-02-04

Site Id:	424625
Affiliation Type:	Facility Operator
Company Name:	RIDGE COMPLETE AUTO
Contact Type:	Not reported
Contact Name:	MARC MANNINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 832-1413
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-02-04

Site Id:	424625
Affiliation Type:	Emergency Contact
Company Name:	RIDGE COMPLETE AUTO
Contact Type:	Not reported
Contact Name:	MARC MANNINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 723-3563
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-02-04

Site Id:	424625
Affiliation Type:	Mail Contact
Company Name:	RIDGE COMPLETE AUTO INC.
Contact Type:	Not reported
Contact Name:	MARC MANNINO
Address1:	264 THIRD AVENUE

RIDGE COMPLETE AUTO (Continued) **A100348969**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 832-1413
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-02-05

Tank Info:

Tank Number:	001
Tank Id:	232808
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	E00 - Piping Secondary Containment - None
	G11 - Tank Secondary Containment - Double-bottom (Aboveground)
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	K01 - Spill Prevention - Catch Basin
	J00 - Dispenser - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	G10 - Tank Secondary Containment - Impervious Underlayment
	D00 - Pipe Type - No Piping
	L00 - Piping Leak Detection - None
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/02/1999
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

P211 **MAACO AUTO PAINTING & BODYWORKS INC** **RCRA NonGen / NLR** **1000174861**
SSW **358 FOURTH AVE** **NY MANIFEST** **NYD981488232**
1/8-1/4 **BROOKLYN, NY 11215**
0.153 mi.
807 ft. **Site 10 of 11 in cluster P**

Relative: **Higher**
Actual: **25 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	MAACO AUTO PAINTING & BODYWORKS INC
Handler Address:	358 FOURTH AVE
Handler City,State,Zip:	BROOKLYN, NY 11215-2718
EPA ID:	NYD981488232
Contact Name:	Not reported
Contact Address:	FOURTH AVE
Contact City,State,Zip:	BROOKLYN, NY 11215
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	FOURTH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11215
Owner Name:	NICASTRO VINCENT
Owner Type:	Private
Operator Name:	NICASTRO VINCENT
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000174861**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NICASTRO VINCENT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NICASTRO VINCENT	
Legal Status:	Private
Date Became Current:	Not reported

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000174861**

Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NICASTRO VINCENT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000174861**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860609
Handler Name: MAACO AUTO PAINTING & BODYWORKS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported

MAACO AUTO PAINTING & BODYWORKS INC (Continued) **1000174861**

Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19980920
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MD
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

NY MANIFEST:
Name: MAACO AUTO PAINTING
Address: 358 FOURTH AVE
City,State,Zip: BROOKLYN, NY 11215-2718
Country: USA
EPA ID: NYD981488232
Facility Status: Not reported
Location Address 1: 358 4TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD981488232
Mailing Name: MAACO AUTO PAINTING
Mailing Contact: MAACO AUTO PAINTING
Mailing Address 1: 358 FOURTH AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11215
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7188525505

P212 **CON EDISON - MANHOLE 5437** **RCRA NonGen / NLR** **1010325649**
SSW **358 4TH AVE** **NY MANIFEST** **NYP004130670**
1/8-1/4 **BROOKLYN, NY 11215**
0.153 mi.
807 ft. **Site 11 of 11 in cluster P**

Relative: **Higher**
Actual: **25 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20060223
Handler Name: CON EDISON - MANHOLE 5437
Handler Address: 358 4TH AVE

CON EDISON - MANHOLE 5437 (Continued) **1010325649**

Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004130670
Contact Name:	FRANKLIN MURRAY
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

CON EDISON - MANHOLE 5437 (Continued) **1010325649**

TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20041104
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20041104
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

CON EDISON - MANHOLE 5437 (Continued) **1010325649**

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20041104
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20041104
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060222
Handler Name: CON EDISON - MANHOLE 5437
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060223
Handler Name: CON EDISON - MANHOLE 5437
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - MANHOLE 5437
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CON EDISON - MANHOLE 5437 (Continued) **1010325649**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	358 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004130670
Facility Status:	Not reported
Location Address 1:	358 4TH AVE MH5437
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004130670
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

M213 **CON ED** **NY MANIFEST** **S118259711**
North **617 UNION ST & 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.158 mi.
833 ft. **Site 5 of 6 in cluster M**

Relative:
Lower

Actual:
19 ft.

NY MANIFEST:

Name:	CON ED
Address:	617 UNION ST & 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004836340
Facility Status:	Not reported
Location Address 1:	617 UNION STREET
Code:	BP
Location Address 2:	SB 43331
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004836340
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2015
Trans1 Recv Date:	09/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004836340
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002625171GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118259711**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M214 **CON EDISON - UNION STREET** **PA MANIFEST** **S123092918**
North **617 UNION STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.158 mi.
833 ft. **Site 6 of 6 in cluster M**

Relative: **Lower**

Actual: **19 ft.**

Manifest Details:

Year:	2017
Manifest Number:	009796742FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP004836340
Generator Date:	01/24/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	100
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592

CON EDISON - UNION STREET (Continued) **S123092918**

Date TSP Sig: Not reported

R215 **CON EDISON SERVICE BOX: 45290** **RCRA NonGen / NLR** **1016974108**
WSW **210 3RD ST** **NY MANIFEST** **NYP004479192**
1/8-1/4 **BROOKLYN, NY 11215**
0.159 mi.
839 ft. **Site 6 of 10 in cluster R**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140426
Handler Name:	CON EDISON SERVICE BOX:	45290
Handler Address:		210 3RD ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004479192
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported

CON EDISON SERVICE BOX: 45290 (Continued) **1016974108**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140326
Handler Name: CON EDISON SERVICE BOX:	45290
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140426
Handler Name: CON EDISON SERVICE BOX:	45290
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 45290 (Continued) **1016974108**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 210 3RD ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004479192
Facility Status: Not reported
Location Address 1: 210 3 ST
Code: BP
Location Address 2: SB45290
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004479192
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2014
Trans1 Recv Date: 03/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014

CON EDISON SERVICE BOX: 45290 (Continued) **1016974108**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004479192
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012354428JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U216 **CON EDISON SERVICE BOX: 34336** **RCRA NonGen / NLR** **1017771653**
SE **85-87 1ST AVE & 5TH ST N OF** **FINDS** **NYP004485942**
1/8-1/4 **NEW YORK, NY 10003**
0.160 mi.
847 ft. **Site 1 of 12 in cluster U**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20140501
Handler Name:	CON EDISON SERVICE BOX:	34336
Handler Address:		85-87 1ST AVE & 5TH ST N OF
Handler City,State,Zip:		NEW YORK, NY 10003
EPA ID:		NYP004485942
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST

Actual:
49 ft.

CON EDISON SERVICE BOX: 34336 (Continued) **1017771653**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported

CON EDISON SERVICE BOX: 34336 (Continued) **1017771653**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140401
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140401
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140501
Handler Name: CON EDISON SERVICE BOX: 34336	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

CON EDISON SERVICE BOX: 34336 (Continued) **1017771653**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063790045

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

V217 **CON EDISON - TRANSFORMER MANHOLE 320** **NY MANIFEST** **S120958786**
ESE **5TH AVE & GARFIELD PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.161 mi.
849 ft. **Site 1 of 2 in cluster V**

Relative: **Higher**
Actual: **52 ft.**

NY MANIFEST:

Name:	CON EDISON - TRANSFORMER MANHOLE 320
Address:	5TH AVE & GARFIELD PL
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004964548
Facility Status:	Not reported
Location Address 1:	5TH AVE & GARFIELD PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004964548
Mailing Name:	CON EDISON - TRANSFORMER MANHOLE 320
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON - TRANSFORMER MANHOLE 320 (Continued) **S120958786**

Mailing Phone: Not reported

O218 **204 4TH AVE LLC - BCP REDEVELOPMENT PROJECT** **RCRA-LQG** **1027222223**
NNE **204 4TH AVE** **NYR000255687**
1/8-1/4 **BROOKLYN, NY 11217**
0.161 mi.
850 ft. **Site 5 of 9 in cluster O**

Relative: **Higher**

Actual: **26 ft.**

RCRA-LQG:

Date Form Received by Agency:		20220531
Handler Name:	204 4TH AVE LLC - BCP REDEVELOPMENT PROJECT	
Handler Address:		204 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11217
EPA ID:		NYR000255687
Contact Name:		ALEXANDER CUTRONA
Contact Address:		E 12TH ST 7TH FL
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		215-435-9310
Contact Fax:		Not reported
Contact Email:		ALEXANDER@AVERYHALLINVESTMENTS.COM
Contact Title:		SENIOR DEVELOPMENT MANAGER
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		DENTON PL
Mailing City,State,Zip:		BROOKLYN, NY 11217
Owner Name:	204 4TH AVE LLC	
Owner Type:		Private
Operator Name:	204 4TH AVE LLC	
Operator Type:		Private
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

204 4TH AVE LLC - BCP REDEVELOPMENT PROJECT (Continued) **1027222223**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220601
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Yes
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: 204 4TH AVE LLC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	51 E 12TH ST 7TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: 204 4TH AVE LLC	
Legal Status:	Private

204 4TH AVE LLC - BCP REDEVELOPMENT PROJECT (Continued) **1027222223**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	51 E 12TH ST 7TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20220531
Handler Name:	204 4TH AVE LLC - BCP REDEVELOPMENT PROJECT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Yes
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	53111
NAICS Description:	LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

O219 **SPEEDWAY # 7835** **NY UST** **U001835738**
NNE **204-222 FOURTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.161 mi.
850 ft. **Site 6 of 9 in cluster O**

Relative: Higher

Actual: 26 ft.

UST:

Name:	SPEEDWAY # 7835
Address:	204-222 FOURTH AVENUE
City,State,Zip:	BROOKLYN, NY 11217
Id/Status:	2-297666 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585963.62972
UTM Y:	4503521.59070
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	13756
Affiliation Type:	Facility Owner

SPEEDWAY # 7835 (Continued) **U001835738**

Company Name:	SPEEDWAY LLC
Contact Type:	REGIONAL GASOLINE ENVIRONMENTAL COMPLIANCE MANAGER
Contact Name:	BRANDIE LEHMAN
Address1:	500 SPEEDWAY DR
Address2:	Not reported
City:	ENON
State:	OH
Zip Code:	45323
Country Code:	999
Phone:	(937) 863-7071
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MJRICE
Date Last Modified:	2022-04-20

Site Id:	13756
Affiliation Type:	Emergency Contact
Company Name:	SPEEDWAY LLC
Contact Type:	Not reported
Contact Name:	BRANDIE LEHMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(937) 863-7071
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MASTREIC
Date Last Modified:	2021-01-05

Site Id:	13756
Affiliation Type:	Mail Contact
Company Name:	SPEEDWAY LLC
Contact Type:	REGIONAL GASOLINE ENV COMPLIANCE MGR
Contact Name:	BRANDIE LEHMAN
Address1:	500 SPEEDWAY DRIVE
Address2:	Not reported
City:	ENON
State:	OH
Zip Code:	45323
Country Code:	001
Phone:	(937) 863-7071
EMail:	BRANDIE.LEHMAN@7-11.COM
Fax Number:	Not reported
Modified By:	MJGRIFFI
Date Last Modified:	2022-05-05

Site Id:	13756
Affiliation Type:	Facility Operator
Company Name:	SPEEDWAY # 7835
Contact Type:	Not reported
Contact Name:	BRANDIE LEHMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

SPEEDWAY # 7835 (Continued) **U001835738**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (585) 349-3056
EMail: Not reported
Fax Number: Not reported
Modified By: MASTREIC
Date Last Modified: 2021-01-05

Tank Info:

Tank Number: 046
Tank ID: 51360
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 08/01/1996
Date Tank Closed: 10/04/2019
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 09
Date Test: 12/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 047
Tank ID: 51361
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 08/01/1996
Date Tank Closed: 10/04/2019
Registered: True
Tank Location: Underground

SPEEDWAY # 7835 (Continued) **U001835738**

Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 09
Date Test: 12/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 048
Tank ID: 51362
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 08/01/1996
Date Tank Closed: 10/04/2019
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 09
Date Test: 12/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass

SPEEDWAY # 7835 (Continued) **U001835738**

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	049
Tank ID:	51363
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1996
Date Tank Closed:	10/04/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	09
Date Test:	12/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number:	050
Tank ID:	51364
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1996
Date Tank Closed:	10/04/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	09

SPEEDWAY # 7835 (Continued) **U001835738**

Date Test: 12/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 0A9
Tank ID: 15907
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 0W7
Tank ID: 15905
Tank Status: Closed - Removed

SPEEDWAY # 7835 (Continued) **U001835738**

Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 11/01/1988
Date Tank Closed: 10/04/2019
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D10 - Pipe Type - Copper
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 0W8
Tank ID: 15906
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 06/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: ZZ
Date Test: 03/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None

SPEEDWAY # 7835 (Continued) **U001835738**

Tank Number:	37
Tank ID:	15899
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	07/01/1979
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	03/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve

Tank Number:	38
Tank ID:	15900
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	07/01/1979
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	03/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

SPEEDWAY # 7835 (Continued) **U001835738**

I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 39
Tank ID: 15901
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 07/01/1979
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 03/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve

Tank Number: 40
Tank ID: 15902
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 07/01/1979
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 03/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

SPEEDWAY # 7835 (Continued) **U001835738**

Equipment Records:

H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve

Tank Number:	41
Tank ID:	15903
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	07/01/1979
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	03/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	42
Tank ID:	15904
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	07/01/1979
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

SPEEDWAY # 7835 (Continued) **U001835738**

Tightness Test Method: 20
Date Test: 03/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve

Tank Number: 6
Tank ID: 15908
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/01/1992
Date Tank Closed: 10/04/2019
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 34
Date Test: 03/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: A11
Tank ID: 15909
Tank Status: Closed - In Place

SPEEDWAY # 7835 (Continued) **U001835738**

Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None

Tank Number:	A12
Tank ID:	15910
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None

SPEEDWAY # 7835 (Continued) **U001835738**

I00 - Overfill - None

Tank Number: A13
Tank ID: 15911
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: A14
Tank ID: 15912
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

SPEEDWAY # 7835 (Continued) **U001835738**

C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number:	A15
Tank ID:	15913
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	A16
Tank ID:	15914
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

SPEEDWAY # 7835 (Continued) **U001835738**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: A17
Tank ID: 15915
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

Tank Number: A18
Tank ID: 15916
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

SPEEDWAY # 7835 (Continued) **U001835738**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: A19
Tank ID: 15917
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: A20
Tank ID: 15918
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550

SPEEDWAY # 7835 (Continued) **U001835738**

Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	A21
Tank ID:	15919
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

SPEEDWAY # 7835 (Continued) **U001835738**

Tank Number:	A22
Tank ID:	15920
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	A23
Tank ID:	15921
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

SPEEDWAY # 7835 (Continued) **U001835738**

A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	A24
Tank ID:	15922
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number:	A25
Tank ID:	15923
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

SPEEDWAY # 7835 (Continued) **U001835738**

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	A26
Tank ID:	15924
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	A27
Tank ID:	15925
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

SPEEDWAY # 7835 (Continued) **U001835738**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: A28
Tank ID: 15926
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: A29
Tank ID: 15927
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979

SPEEDWAY # 7835 (Continued) **U001835738**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: A30
Tank ID: 15928
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: A31

SPEEDWAY # 7835 (Continued) **U001835738**

Tank ID: 15929
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: A32
Tank ID: 15930
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

SPEEDWAY # 7835 (Continued) **U001835738**

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	A33
Tank ID:	15931
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	A34
Tank ID:	15932
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

SPEEDWAY # 7835 (Continued) **U001835738**

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: A35
Tank ID: 15933
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: A36
Tank ID: 15934
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

SPEEDWAY # 7835 (Continued) **U001835738**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: A37
Tank ID: 15935
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: A38
Tank ID: 15936
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground

SPEEDWAY # 7835 (Continued) **U001835738**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: A39
Tank ID: 15937
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: A40
Tank ID: 15938
Tank Status: Closed - In Place

SPEEDWAY # 7835 (Continued) **U001835738**

Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number:	A41
Tank ID:	15939
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

SPEEDWAY # 7835 (Continued) **U001835738**

J02 - Dispenser - Suction Dispenser

Tank Number: A42
Tank ID: 15940
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: A43
Tank ID: 15941
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1965
Date Tank Closed: 12/01/1979
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

SPEEDWAY # 7835 (Continued) **U001835738**

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	A44
Tank ID:	15942
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1965
Date Tank Closed:	12/01/1979
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

O220 **HESS#32530** **RCRA-VSQG** **1000263763**
NNE **204-222 FOURTH AVE** **US AIRS** **NYD982185563**
1/8-1/4 **BROOKLYN, NY 11217** **FINDS**
0.161 mi. **ECHO**
850 ft. **Site 7 of 9 in cluster O** **NY MANIFEST**

Relative: **Higher**
Actual: **26 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20160921
Handler Name:	SPEEDWAY 7835	
Handler Address:		204 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11217-3121
EPA ID:		NYD982185563
Contact Name:		CHARLES A BESSE
Contact Address:		PO BOX 1500
Contact City,State,Zip:		SPRINGFIELD, OH 45501-1500
Contact Telephone:		937-863-6272
Contact Fax:		937-863-6078
Contact Email:		CABESSE@SPEEDWAY.COM

HESS#32530 (Continued) **1000263763**

Contact Title:		ENVIRONMENTAL COMPLIANCE ADMIN
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		PO BOX 1500
Mailing City,State,Zip:		SPRINGFIELD, OH 45501-1500
Owner Name:	MERIT OIL CORP	
Owner Type:		Private
Operator Name:	MERIT OIL CORP	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported

HESS#32530 (Continued) **1000263763**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161012
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

HESS#32530 (Continued) **1000263763**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MERIT OIL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SPEEDWAY LLC
Legal Status: Private
Date Became Current: 20141001
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MERIT OIL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SPEEDWAY LLC
Legal Status: Private
Date Became Current: 20141001
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1500
Owner/Operator City,State,Zip: SPRINGFIELD, OH 45501-1500
Owner/Operator Telephone: 937-864-3000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY

HESS#32530 (Continued) **1000263763**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: MERIT OIL CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: MERIT OIL CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19870511
Handler Name: MERIT OIL CORP	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160921
Handler Name: SPEEDWAY 7835	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

HESS#32530 (Continued) **1000263763**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980223
Handler Name: MERIT OIL OF NEW YORK, INC.,
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 4471
NAICS Description: GASOLINE STATIONS

NAICS Code: 44711
NAICS Description: GASOLINE STATIONS WITH CONVENIENCE STORES

NAICS Code: 447110
NAICS Description: GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000263763
Region Code: 02
Programmatic ID: AIR NY0000002610300089
Facility Registry ID: 110001572628
D and B Number: Not reported
Primary SIC Code: 5541
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610300089
Facility Registry ID: 110001572628
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-03 00:00:00
Activity Status Date: Not reported

HESS#32530 (Continued) **1000263763**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001572628

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000263763
Registry ID: 110001572628
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110001572628
Name: HESS#32530
Address: 204-222 FOURTH AVE
City,State,Zip: BROOKLYN, NY 11217

NY MANIFEST:
Name: MERIT OIL CORP - SACKETT
Address: 204-222 4TH AVE
City,State,Zip: BROOKLYN, NY 11217-3121
Country: USA
EPA ID: NYD982185563
Facility Status: Not reported
Location Address 1: 204-222 FOURTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY

HESS#32530 (Continued) **1000263763**

Location Zip: 11217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD982185563
Mailing Name: MERIT OIL CORP - SACKETT
Mailing Contact: DOM DEBENEDICTI
Mailing Address 1: 551 W LANCASTER AVE
Mailing Address 2: Not reported
Mailing City: HAVERFORD
Mailing State: PA
Mailing Zip: 19041
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5167310036

O221 **MERRITT GAS STATION** **NY LTANKS S104276740**
NNE **204-222 4TH AVENUE** **NY Spills N/A**
1/8-1/4 **BROOKLYN, NY**
0.161 mi.
850 ft. **Site 8 of 9 in cluster O**

Relative: **Higher**

Actual: **26 ft.**

LTANKS:
Name: MERRITT GAS STATION
Address: 204-222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9515732 / 1997-06-11
Facility ID: 9515732
Site ID: 204687
Spill Date: 1996-03-07
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 1996-03-07
CID: 349
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1996-03-07
Spill Record Last Update: 1997-06-11
Spiller Name: Not reported
Spiller Company: MERRITT GAS STATION
Spiller Address: 204-222 4TH AV
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 310148

MERRITT GAS STATION (Continued) **S104276740**

DEC Memo: ""
Remarks: "line failed during testing - failure .12 gallons per hour"

All Materials:
Site ID: 204687
Operable Unit ID: 1026774
Operable Unit: 01
Material ID: 355851
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: HESS STATION 32530
Address: 204-222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0210654 / 2003-11-03
Facility ID: 0210654
Facility Type: ER
DER Facility ID: 310148
Site ID: 74469
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2003-01-23
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2003-01-23
CID: 199
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-01-23
Spill Record Last Update: 2003-11-03
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: TOM VITARELLI
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND REF TO SPILL # 9605719"
Remarks: "it appears a customer may have overfilled tank causing spill no product got into sewers - clean up in progress -- second contractor is in route to assist"

MERRITT GAS STATION (Continued) **S104276740**

All Materials:

Site ID:	74469
Operable Unit ID:	863994
Operable Unit:	01
Material ID:	555410
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	FORMER HESS STATION 32530
Address:	204-222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9605719 / Not Reported
Facility ID:	9605719
Facility Type:	ER
DER Facility ID:	479891
Site ID:	74470
DEC Region:	2
Spill Cause:	Other
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-08-02
Investigator:	SXWU
Referred To:	REPORT (11/05/2021) REVIEWED
Reported to Dept:	1996-08-02
CID:	252
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	1996-08-02
Spill Record Last Update:	2021-12-08
Spiller Name:	RON BAMER
Spiller Company:	FORMER HESS STATION
Spiller Address:	204-222 4TH AVE
Spiller Company:	999
Contact Name:	RON BAMER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 01/23/2004-Sun-File Review by Sun: Site Status Update Report, Aprip 2003 through August 2003, by Geological Services Corp (GSC), dated 10/16/2003: Six (6) monitorin wells were gauged and sampled on July 17, 2003. A soil vaplr extraction well (SVE-1) was installed on July 30, 2003 and pilot test on SVE-1 was conducted on August 8, 2003. No LPH was detected. The groundwater depth ranged from 11.74 feet to 15.68 feet, and groundwater flow was in northwest direction. MW-2 has the maximum BTEX concentration of 11,400 ug/l and maimum

MERRITT GAS STATION (Continued) **S104276740**

MTBE concentration of 1,800 ug/l. Work performed during this period included repair and patch leak from wall in oil closet located in the subway, installation of three additional wells. A remedial action plan will be submitted by GSC based on the results of the pilot test. Per Hess' letter to DEC dated 10/28/2003, Hess is working with the New York City Transit Authority (NYCTA) to address an apparent hydrocarbon sheen in conjunction with groundwater seepage within a subsurface subway station utility closet. (Sun) 01/22/2004- Site visit by Joe Sun and Mark Tibbe on 1/22/2004. Inspection with Mike Matri of Hess and William Schaefer of GSC showed that some slight infiltration of groundwater continues where the urethane grout waterproofing did not adhere to the concrete. GSC has recommended a second waterproofing event utilizing a hydraulic concrete product. The product is now waiting for NYCTA's approval. (Sun) SEE Also Spill Nos. 0104798/0201876. 05/05/04-File Update by Sun: On 05/05/04 Sun sent a letter to Hess requiring complete delineation of soil and groundwater contamination, submittal of an Investigation Summary report followed by a Remedial Action Plan. The Department set a deadline of May 28, 2004 for signing the Stipulation Agreement. (Sun) 06/06/05 File Update by Sun: On 06/06/05, Sun sent a letter to Hess' Project Manager, Mike Matri, informing him that the Department approves Hess proposed plan to take the opportunity of station renovation commencing in June, 2005 to install below ground environmental remediation infrastructure for future remediation of petroleum impacted soil and groundwater. Specifically, the Department approves the following planned installations at the station: 1.Installation of three additional SVE wells (PMW-8 through PMW-10). 2.Modification of existing 2-inch well FW-7 to include a 1-inch injection line which will be piped to the proposed remediation system location, The piping will potentially be used in the future for injection purposes (e.g., Biosolve, chemical oxidation and/or bioremediation). 3.Monitoring wells SVE-1, MW-2, and the three proposed SVE wells (PMW-8 through PMW-10) will have environmental piping installed from the wells to the proposed system location area. The Department requires a formal Remedial Action Plan (RAP) in conjunction with the station redevelopment activities be submitted by Hess during the third quarter of 2005. (Sun) 10/19/2005: Project reassigned from Sun to Andersen 10/19/2005: Reviewed hydrogeologic groundwater report dated 8/29/2005. Report indicated liquid phase hydrocarbons and BTEX concentrations of up to 19,520 ppb. Report indicated that informal proposed remedial action plan discussed in abovementioned 6/6/05 entry is delayed and possibly canceled. The report states Amerada Hess Corporation will either request an extension to submit the currently proposed Remedial Action Plan or to submit a revised Remedial Action Plan . The next triannual sampling event is scheduled for November 2005. Additionally, a Stip was sent out on 5/5/04, which was never signed due to Hess waiting for a Consent Order. 10/25/05: Mailed a failure to sign Stip letter. Stip signature due on 11/15/2005. 1/26/06: 1/25/06 meeting between Quantum, NYSDEC, and GSC/Kleinfelder. The site in under redevelopment. An RAP will be prepared. Delineation will be investigated on the other side of 4th avenue. 3/1/06: Signed stipulation agreement, effective date 2/23/06. Investigation plan due 4/24/06. 4/24/06: Reviewed the site status update report/investigation plan dated 4/21/06. Report indicates that additional delineation on the east side of 4th avenue is not feasible due to utilites. Max BTEX 28,587 ppb (SVE1) and max MTBE 1,710 ppb

MERRITT GAS STATION (Continued) **S104276740**

(MW2). Depth to water 10-15 ft. RAP due 6/22/06. 5/25/06: Pilot testing on 5/25/06 6/29/2006: Meeting with Hess, NYSDEC, Quantum, EnviroTrac and GSC on 6/28/2006. RAP in progress. Endpoint sampling will be submitted for spill bucket replacement excavation. 7/28/06: RAP submission deadline extended to 9/21/06. 8/9/06: Conference call with Hess, Quantum, and GSC/Kleinfelder. The ROI during SVE pilot testing was only 10 ft. A Hivac pilot test will be performed on 8/10/06 to try to increase the ROI. If it fails an extension will be required to perform additional testing prior to RAP submittal. 8/11/06: Received phone call from Gail Helfrick. A HVAC test was performed which did not result in a significant increase in the RIO. An RAP will be submitted on 9/21/06 as planned, but will require additional sampling to improve the ROI. 8/15/06: See spill 06-02980. The RAP should include remediation for the soil contamination from spill 06-02980. 9/12/06: Received RAP. SVE proposed. Pilot testing was conducted on May 25, 2006 and August 10, 2006. Two existing wells (MW-3 and SVE-1), and six proposed wells (SVE-2 - SVE-7) wil be used as extraction points to be connected to a SVE remediation system. The ROI varies from 10 to 50 feet throughout the site. Soil samples will be collected during installation of the new SVE wells, as well as from a soil boring proposed adjacent to MW-6. During system startup operation and maintenance visits will be conducted daily for three days, followed by weekly for the first monthy, followed by monthly. Based on start-up testing, a determination will be made as to whether emission treatment is necessary. Contamination from spill 06-02980 addressed, spill 06-02980 closed and consolidated with 9605719. Numerous sensitive receptors: subway, utilities, basements, schools, Gowanus Canal. AS not proposed due to the proximity of the subway, which runs parrallel and adjacent to the site. RAP conditionally approved, with additional groundwater treatment required. 9/21/06: Received phone call from Gail Helfrick (Quantum) and Al Tonn (GSC-K) requesting that the RAP be approved without additional gw treatment. Confirmed that additional gw treatment is required for MW-2, SVE-1, and FW-8. 10/3/06: Received email from gail helfrick: This email is to confirm our conversation on Tuesday, September 26, 2006 regarding the Remedial Action Plan (RAP) for Hess Station # 32530 in Brooklyn, New York. In the RAP, Hess proposed the installation and operation of a Soil Vapor Extraction system at the site. The NYSDEC approved the proposal for SVE, and also requested groundwater remediation. Based on our conversations, it was agreed that Hess would install underground piping for groundwater treatment during the installation of the SVE system. It was further agreed that Hess would operate the SVE system for 1 full year, and during that year, Hess would 1) evaluate the performance of the SVE system on a monthly basis, 2) continue to monitor roundwater quality (March, July and November), and 3) submit progress reports to the NYSDEC (May, September and January). If after that 1 year period, the data demonstrates that groundwater remediation is necessary, alternative remedial technologies will evaluated and discussed with the NYSDEC. 10/4/06: Received update report dated 9/27/06. Groundwater samples collected on 7/27/06. BTEX 38,200 ppb (SVE1), mtbe 208 ppb (SVE1). SVE implementation required. 12/11/06: Sent email to Hess to followup on implementation schedule. 12/18/06: Received email from Hess: We still hope to be able to obtain the MTA permits needed to complete the subsurface intrusive work by January 10, 2007. Once these permits are obtained, we will provide the NYSDEC a schedule for system installation. 1/17/07: Meeting on 1/16/07 with Hess, Delta, NYSDEC.

MERRITT GAS STATION (Continued) **S104276740**

SVE implementation in progress. 3/26/07: Reviewed update report. Wells sampled on 12/26/06. Max BTEX 30,720 ppb (SVE1). Max MTBE 1,000 ppb (MW2). SVE implementation in progress. 5/31/07: Reviewed site status report. Wells sampled on 3/16/07. Max BTEX 25,280 ppb (SVE1). Max MTBE 410 ppb (MW2). SVE installation in progress. 9/20/07: Reviewed site status report. Wells sampled in July 2007. LNAPL in MW 2 (0.03 ft).Max BTEX 30,370 ppb (SVE1). SVE startup planned for November 2007. Sent letter requiring RAP addendum for groundwater treatment (pipes for water removal are planned on being installed as a back-up plan). And increased sampling frequency to quarterly sampling. 5/14/08 - Carlson: Meeting on May 7th 2008 - Hess/Envirotrac will submit a RAP addendum. Reviewed First Quarterly 2008 Update Report. Wells sampled on 2/5/08. Max BTEX concentration 24,220 ppb (SVE1), max MTBE concentration 71 ppb (SVE1). MW-2 was dry. 8/7/08 - Carlson: Reviewed July 2008 Update Report. Wells sampled on 5/22/08. Maximum BTEX concentration 43,693 ppb (SVE1). Maximum MTBE concentration 554 ppb (MW2). RAP Addendum will be submitted under a separate cover. Emailed Hess/Envirotrac requiring submission of RAP Addendum by 9/8/08. Received email from Ed Russo stating that 9/8/08 deadline can probably be met. 9/8/08 - Carlson: The Department approved an extension until 10/1/08 to submit an RAP Addendum. 10/22/08 - Carlson: Meeting with Hess/Envirotrac. RAP Addendum will be submitted by 12/15/08. 11/20/08 - Carlson: Reviewed October 2008 Update Report. Wells sampled on 8/14/08. Maximum BTEX concentration 41,837 ppb (SVE1). RAP Addendum not received. Sent failure to comply letter. Start legal proceedings if RAP Addendum not submitted by 12/5/08. 12/23/08 - Carlson: Received Remedial Action Plan Addendum. Two SVE system, two wells strippers, and monthly dual phase extraction events proposed. Revised RAP Addendum required with following modifications: 1) removal of two wells from SVE system, 2) relocation of two of the proposed monitoring wells, 3) startup report must be submitted, 4) inclusion of more detailed information about the well strippers. 2/19/09 - Carlson: Received email from Ed Russo in response to 12/23/08 letter. Monthly O&M visits requiring monthly WS water effluent testing, monthly SVE air discharge testing by PID, and quarterly SVE air discharge testing by laboratory. Revised letter addendum required. 3/11/09 - Carlson: Reviewed update report dated January 2009. Wells gauged and sampled on 11/5/08. LNAPL at depth of 0.02 ft in MW2. Maximum BTEX concentration 12,672 ppb (SVE1). 3/18/09 - Carlson: Meeting with Hess/Envirotrac. Revised addendum due in April 2009. 5/7/09 - Carlson: Reviewed April 2009 Update Report. Revised addendum letter overdue. Emailed John Schenkewitz about overdue letter/report. 5/11/09 - Carlson: Received revised RAP Addendum letter. Issued approval letter. 5/28/09 - Carlson: Well installation scheduled for 6/22/09. 8/7/09 - Carlson: Reviewed update report. Monthly EFR IRM ongoing. What is status of RAP implementation? 8/19/09 - Carlson: Meeting with Hess. RAP addendum will be submitted to include air sparge on the eastern portion on the site. 10/21/09 - Carlson: Reviewed RAP addendum. Issued approval letter. SVE/AS will be installed, except in sidewalk (because of subway). SVE in sidewalk with HVAC events to treat impacted groundwater. 11/17/09 - Carlson: Reviewed update report. Monthly HVAC events from sidewalk wells ongoing. SVE/AS system installation in progress. 1/27/2010 - Carlson: Meeting with Hess. 2/5/2010 - Carlson: Reviewed update report. EFR conducted in September and October. SVE/AS installation not begun yet. 5/20/2010 - Carlson: Meeting with Hess. They are working with MTA because the property is adjacent to

MERRITT GAS STATION (Continued) **S104276740**

the subway. 5/27/2010 - Carlson: Reviewed April 2010 Update Report. Six AS wells and one MW installed. HVAC was not conducted this quarter. 7/22/2010 - Carlson: Reviewed wastewater UST closure report. Tank abandoned in place with concrete slurry. Endpoint samples collected from the east wall (clean) and north wall (trace VOCs/sVOCs detected). West wall/south wall were not accessible for sample collection. 8/13/2010 - Carlson: Reviewed July 2010 Update Report. EFR events ongoing. System construction pending NYCTA permits. 5/9/11 - Obligado - This spill transferred to Obligado as per Brevdo. I reviewed the 4Q10 update report. Free product (0.03 ft) was found in MW2. MAx BTEX 17674 ug/L in SVE1. They are still waiting for MTA permits. 8/30/11 - Obligado - I reviewed the 2Q11 update report. They are still waiting on NYCTA permits. Max BTEX is 9800 ug/L. No product detected this quarter. 11/14/11 - Carlson: Reviewed October 2011 update report. System construction pending NYCTA permits. Monthly EFR ongoing. 3/13/2012 - The site has SVE/AS system operation pending on the NYCTA's permission. Spoke to the consultant who works for the property owner next door in the Union Street. Groundwater contamination was identified during their Phase 2 investigation. Advised to call in for a spill number and prove to DEC it is from Hess site as they believe. 8/23/2012 - 1Q2012, 4/30/2012, by EnviroTrac. The groundwater was sampled on 2/13/2012. DTW 9.98 to 15.70 feet. Flows to north. No LNAPL. The remediation system construction is pending permit approval by NYCTA. CW-9, 560.1 BTEX, 182 MTBE. MW-7, 7.52J BTEX, 22.8 MTBE. MW-2, 5,529 BTEX, 162 MTBE. FW-7, 24.5 BTEX, MTBE ND. SVE-1, 6,369 BTEX, 6.7J MTBE. FW-8, 270.2 BTEX, 1.3J MTBE. FW-9, 570.6 BTEX, 2.5 MTBE. 10/12/2012 - 2Q2012, 7/31/2012, by EnviroTrac. The groundwater was sampled on May 14, 2012. DTW 10.87 to 16.05. Flows to north. CW-9, 43 BTEX, 106 MTBE. MW-7, 0.44J BTEX, 19.7 MTBE. MW-2, 1,626.9 BTEX, 100 MTBE. FW-7, 67.4 BTEX, 0.24J MTBE. FW-9, 961.6 BTEX, 1.6J MTBE. FW-8, 224.9 BTEX, 1.8 MTBE. SVE-1, 3,746.3 BTEX, 8.0J MTBE. EFR on on MW-2 and SVE-1 on 3/14, 4/9, and 5/2/2012. 1/24/2013 - 3Q2012, 11/5/2012, by EnviroTrac. The groundwater was sampled on 8/31/2012. DTW 10.49 to 14.72 feet. Flows to north. NO LNAPL. CW-8, 26J BTEX, 0.77J MTBE. CW-9, 297.9 BTEX, 73 MTBE. MW-7, 95.3 BTEX, 4.4 MTBE. MW-2, 8,656 BTEX, 101 MTBE. FW-7, 291.2 BTEX, 0.25J MTBE. SVE-1, 6,205 BTEX, 2.7J MTBE. FW-9, 1,894.3 BTEX, 1.1J MTBE. FW-8, 587.6 BTEX, 1.4 MTBE. EFR on MW-2 and SVE-1 on 6/7, 7/16, and 8/22/2012. The next sampling will be in 11/2012. 9/24/2013 - 4Q2012, 1/31/2013, by EnviroTrac. The groundwater was sampled on 11/16/2012. On 9/24 and 11/13/2012, conducted EFR on MW-2 and SVE-1. DTW 7.80 to 15.49 feet. Flows to north. CW-9, 223.4 BTEX, 94.1 MTBE. MW-7, 38.04J BTEX, 18 MTBE. MW-2, 6,630.7 BTEX, 136 MTBE. FW-7, 179.7 BTEX, MTBE ND. SVE-1, 1,933 BTEX, 2.7 MTBE. FW-8, 779.9 BTEX, MTBE ND. 1Q2013, 4/30/2013, by EnviroTrac. The groundwater was sampled on 2/26/2013. On 12/3/2012, 1/17/2013 and 2/20/2013, EFR on MW-2 and SVE-1. DTW 10.41 to 15.88 feet. Flows to north. NO LNAPL. CW-9, 77.6 BTEX, 116 MTBE. MW-7, 1.43J BTEX, 22.1 MTBE. MW-2, 2,610.4 BTEX, 94.8 MTBE. FW-7, 33.6 BTEX, MTBE ND. SVE-1, 638 BTEX, MTBE ND. FW-8, 570.4 BTEX, 1.0 MTBE. FW-9, 347.3 BTEX, 0.30J MTBE. 11/14/2014 - 2Q2014, 7/31/2014. 3/24, 4/15, 5/14/2014, EFR on MW-2 and SVE-1. 5/20/2014, sampled groundwater. DTW 9.39 to 15.43 feet. Flows to north. MW-7, 71.6 BTEX. MW-2, 10,042 BTEX, 76.2 MTBE. FW-7, 230.9 BTEX. SVE-1, 984 BTEX. FW-8, 257.9 BTEX. FW-9, 356 BTEX. 11/17/2014 - 3Q2014, 11/7/2014. 6/12, 7/10 and 8/5/2014, EFR on MW-2 and SVE-1. 8/25/2014, sampled groundwater. DTW 10.52 to 15.81 feet. Flows to north. CW-9, 144.4

MERRITT GAS STATION (Continued) **S104276740**

BTEX, 91.1 MTBE. MW-2, 6,517 BTEX, 83.5 MTBE. FW-7, 329.9 BTEX. SVE-1, 2,527 BTEX. FW-9, 856 BTEX. 4/9/2015 - 4Q2014, 1/26/2015. 9/15, 10/15 and 11/10/2014, EFR on MW-2 and SVE-1. 11/15/2014, gauged 15 monitoring wells and sampled 14 monitoring wells. DTW 11.54 to 15.81 feet. Flows to north. MW-2, 5,112.3 BTEX, 68.1 MTBE. FW-7, 332.1 BTEX. SVE-1, 500.9 BTEX. FW-9, 612.9 BTEX. 1Q2015, 4/9/2015. 12/8/2014, 1/9/2015 and 2/6/2015, EFR on MW-2 and SVE-1, STREs on MW-2/AS-2 and SVE-6/AS-1. 2/12/2015, gauged and sampled 11 monitoring wells. DTW 6.47 to 15.45 feet. Flows to north. CW-9, 121.1 BTEX, 82.9 MTBE. MW-2, 4,347 BTEX, 63.5 MTBE. FW-7, 54.8 BTEX. 10/29/2015 - 2Q2015, 7/15/2015. 3/9, 4/6, 5/6/2015, EFR on SVE-1 and STREs on SVE-6/AS-1. 5/12/2015, gauged and sampled 15 monitoring wells. DTW 6.15 to 15.69 feet. Flows to north. MW-2, 3,017.4 BTEX. FW-7, 504.8 BTEX. SVE-1, 768.6 BTEX. FW-9, 74.6 BTEX. 3Q2015, 10/19/2015. 6/11/2015 EFR on MW-2 and SVE-1. 7/14 and 8/7/2015, EFR on SVE-1 and STREs on SVE-6/AS-1. 8/27/2015, gauged 15 monitoring wells and sampled 14 monitoring wells. DTW 10.25 to 15.46 feet. Flows to north. MW-2, 9,914 BTEX, 78.3 MTBE. MW-7, 47.7 BTEX, 12.1 MTBE. FW-7, 596.1 BTEX. SVE-1, 4,550 BTEX. FW-8, 339.7 BTEX. FW-9, 691.9 BTEX. 1/28/2016 - 4Q2015, 1/28/2016. 9/16, 10/9, 11/4/2015, EFR on SVE-1 and STREs on SVE-6/AS-1. 11/10/2015, gauged 13 and sampled 12 monitoring wells. NO LNAPL. DTW 9.51 to 15.94 feet. Flows to north. CW-9, 53.9 BTEX, 55.7 MTBE. MW-2, 2,189.5 BTEX, 34.6 MTBE. FW-9, 426.1 BTEX. SVE-1, 1,161.4 BTEX. 3/30/2016 Feng This spill is transferred from J. Feng to V. Brevdo as per J. Vought. 3/30/16 - Raphael Ketani. This spill case has been assigned to me effective today. According to ACRIS, the block and lot are 434 and 35. The latest deed is dated 4/24/14. The property owner is HESS Retail Stores, LLC, 1 HESS Plaza, Woodbridge, NJ, 07095. The PBS record is #2-297666. The owner is Speedway #7835. Seven USTs were closed and removed from 6/1/92 to 8/1/96. Thirty seven USTs (mostly gasoline 550 gallon tanks) were closed in place on 12/1/79. There are 5 active 4000 gallon USTs - 4 gasoline and 1 diesel. These tanks were installed on 8/1/96. The contacts are as follows: Speedway/Hess contact: Matthew Butler, (732) 738-2924, MButler1@Speedway.com Consultants: Edward Russo (EnviroTrac), (631) 924-3001, EDR@EnviroTrac.com Joseph Rennie (EnviroTrac), (631) 924-3001, JoeR@EnviroTrac.com 4/26/16 - Raphael Ketani. Today I received the EnviroTrac 4/25/16 Quarterly Update Report. On 12/9/15, 1/28/16 and on 2/1/16 VEFRing was conducted at SVE-1 and short term remediation events were conducted at SVE-6/AS-1. On 2/11/16 MW-2 to 6, 8, FW-7 to 9, CW-8, CW-9 and SVE-1 were gauged. MW-2 to 6, 8, FW-7 to 9, CW-8, CW-9 and SVE-1 were sampled on 2/11/16. Product was not measured in any of the wells. Groundwater was measured at 6.79' and 15.66' below grade and was determined to be flowing northerly. Total BTEX was 2968.1 ppb (856 ppb) at MW-2, non-detect at MW-3 to MW-6 and MW-8 and FW-7, 138.7 ppb (15 ppb benzene) at FW-8, 201.7 ppb (8 ppb benzene) at FW-9, 3.6 ppb at CW-8, 22.1 ppb (13.2 ppb benzene) at CW-9 and 450.3 ppb (12 ppb benzene) at SVE-1. 7/26/16 - Raphael Ketani. Today I received the EnviroTrac July 2016 Quarterly Update Report dated 7/26/16 for the period March to May 2016. On 3/1/16, 4/20/16 and on 5/6/16 VEFRing was conducted at SVE-1 and short term remediation events were conducted at SVE-6/AS-1. On 5/13/16 MW-1 to 8, FW-7, CW-8, CW-9, SVE-1 and SVE-7 were gauged. MW-1 to 8, FW-7, CW-8, CW-9, SVE-1 and SVE-7 were sampled on 5/13/16. Product was not measured in any of the wells. Groundwater was measured at 8.76' and 16.03' below grade and was determined to be flowing northerly. Total BTEX was

MERRITT GAS STATION (Continued) **S104276740**

non-detect at MW-1, 929.9 ppb (254 ppb) at MW-2, non-detect at MW-3 to MW-8, 143.8 ppb (non-detect benzene) at FW-7, non-detect at CW-8 and at CW-9, 427 ppb (62.9 ppb benzene) at SVE-1 and non-detect at SVE-7. 10/24/16 - Raphael Ketani. I reviewed the EnviroTrac August 2016 Quarterly Update Report dated 10/24/16 for the period June to August 2016. On 6/8/16, 7/13/16 and on 8/9/16 VEFRing was conducted at SVE-1 and short term remediation events were conducted at SVE-6/AS-1. On 8/10/16 MW-1 to 8, FW-7 to 9, CW-8, CW-9, SVE-1 and SVE-7 were gauged. MW-1 to 8, FW-7 to FW-9, CW-8, CW-9, SVE-1 and SVE-7 were sampled on 8/10/16. Product was not measured in any of the wells. Groundwater was measured at 9.09' and 15.67' below grade and was determined to be flowing northerly. Total BTEX was non-detect at MW-1 and MW-4 to MW-8. MW-2 was 568.5 ppb (247 ppb benzene). FW-7 had 469.5 ppb (20.2 ppb benzene). FW-8 had 180.8 ppb (19.9 ppb benzene). FW-9 had 231.2 ppb (23 ppb benzene). CW-8 had 4.4 ppb. CW-9 had 2.3 ppb. SVE-1 had 373.8 ppb (15.9 ppb benzene). SVE-7 had 4.2 ppb BTEX. 12/19/16 - Raphael Ketani. Today I received an email as a c-c from Ryan Piper, Engineering Geologist I at DEC Region 2, concerning a new spill (#1608842)at the site. The spill concerned oil contaminated surface water flowing off of the site and onto the street in front due to a clogged drain at the northern end of the property. There was an odor complaint as a result. I sent an email to Mr. Fleming, the representative of Speedway, stating that they faced possible fines and legal action for violating the SPDES regulation, 6 NYCRR Part 750.1.3. I also stated that the subject northern drain must be cleaned out immediately and that Speedway must check the drains at its other stations and make sure they can receive precipitation. Mr. Ryan's original email to Mr. Fleming is as below: A neighbor complained about a diesel spill/ condition at the station that is affecting the surrounding neighborhood. I performed a site visit on Sunday Dec 18th in which I observed the condition. Apparently, there are a number of storm drains on the premises, particularly the drain on the north side of the property, that are clogged with sediment causing large puddles to run off into and down the street to a NYCDEP storm drain. Combined with poor housekeeping and minor spilling at the Diesel pump island on the North side of the property, this is causing a nuisance odor and adverse condition down the road. Therefore I am directing you to take the appropriate action to address this issue as follows. Control of Storm Water Emanating from 204-222 4th Ave, Brooklyn, NY: As per 6 NYCRR Part 750.1.3, The following discharges into the waters of the State are hereby prohibited, and no SPDES or other permit shall be issued authorizing any such discharge: (d) any discharge from a point source, which is in conflict with a plan or amendment thereto approved pursuant to section 208(b) of the Act and 40 CFR part 35 (see section 750-1.24 of this Part), or any other discharge not permitted by this Part, ECL Article 17, other rules and regulations adopted or applicable pursuant thereto or to the Act, or the provisions of an SPDES permit. During the site visit referenced above, evidence was observed of storm water flowing from 204-222 4th Ave, Brooklyn, NY to the street. As such the Department requires that the storm water from 204-222 4th Ave be directed to onsite drainage systems. Documentation of catch basin cleaning must be submitted to the Department no more than 1 month from the date of this email. Mr. Fleming responded back quickly by email stating that the problem will be immediately corrected. 1/19/17 - Raphael Ketani. Today I received an email from Mr. Russo [(631) 924-3001, EDR@EnviroTrac.com] regarding the plugged drains at

MERRITT GAS STATION (Continued) **S104276740**

the site (spill #1608842). The email had attachments consisting of a site plan showing the 6 catch basin locations, photos of the basins taken on 12/20/16 and photos of the basins taken on 1/17/17. Mr. Russo explained in his email that 3 of the catch basins were noted as not draining during EnviroTrac's 12/20/16 inspection. All of the catch basins were cleaned of debris and jetted for 70 feet by a Speedway contractor on 12/31/16. On 1/17/17, the site was inspected again. This time only CB-3 was not draining properly. Mr. Russo stated that this drain will be addressed again by Speedway's contractor. He stated that he will send the DEC an update regarding the re-establishment of drainage at CB-3. 2/2/17 - Raphael Ketani. I reviewed the EnviroTrac January 2017 Quarterly Update Report dated 1/31/17 for the period September to November 2016. On 9/2/16, 10/17/16 and on 11/8/16 VEFRing was conducted at SVE-1 and short term remediation events were conducted at SVE-6/AS-1. On 11/23/16 MW-1 to 6, MW-8, FW-7 to 9, CW-8, CW-9, SVE-1 and SVE-7 were gauged. MW-1 to 6, MW-8, FW-7, FW-9, CW-8, CW-9, SVE-1 and SVE-7 were sampled on 11/23/16. Product was not measured in any of the wells. Groundwater was measured at 7.55' and 15.55' below grade and was determined to be flowing northerly. Total BTEX was non-detect at MW-1, 3 to 6, 8 and SVE-7. The samples for FW-9, CW-8, CW-9 and SVE-1 had 1 to 3 low hits. MW-2 was 1091.1 ppb (487 ppb benzene). FW-7 had 899.6 ppb (45.6 ppb benzene). 4/28/17 - Raphael Ketani. Today I received an email from Mr. Butler that he is leaving Speedway. He stated that John Engdahl [jjengdahl@speedway.com (732) 738-2923] will take over his duties. 5/2/17 - Raphael Ketani. I reviewed the EnviroTrac April 2017 Quarterly Update Report dated 4/28/17 for the period December to February 2017. On 12/7/16, 1/11/17 and on 2/2/17 VEFRing was conducted at SVE-1 and short term remediation events (STREs) were conducted at SVE-6/AS-1. On 2/7/17, MW-1 to 6, MW-8, FW-7 to 9, CW-8, CW-9, SVE-1 and SVE-7 were gauged and sampled. Product was not measured in any of the wells. Groundwater was measured at 7.57' and 15.48' below grade and was determined to be flowing northerly. BTEX was non-detect at MW-3 to 6, 8 and CW-9. The samples for MW-1, FW-7 to FW-9, CW-8 and SVE-7 had 1 to 4 low hits. MW-2 was 3876.1 ppb (991 ppb benzene). SVE-1 was 1329.4 ppb (38.3 ppb benzene). The PID effluent concentration a SVE-6/AS-1 was 665.3 ppm, 405.6 ppm and 290.8 ppm on 12/7/16, 1/11/17 and 2/2/17, respectively. I approved the report with a comment to Mr. Rennie asking him to explain the extremely high benzene concentration in the groundwater at MW-2. 8/1/17 - Raphael Ketani. I reviewed the EnviroTrac July 2017 Quarterly Update Report dated 7/28/17 for the period March to May 2017. On 3/7/17, 4/7/17 and on 5/3/17 VEFRing was conducted at SVE-1 and short term remediation events (STREs) were conducted at SVE-6/AS-1. On 5/30/17, MW-1 to 8, FW-7 to 9, CW-8, CW-9, SVE-1 and SVE-7 were gauged and sampled. Product was not detected in any of the wells. Groundwater was measured at 8.00' to 18.42' below grade and was determined to be flowing northerly. BTEX was non-detect or low at MW-1, 3 to 6, 8, FW-8, CW-8, CW-9 and SVE-7. MW-2 was 2699.1 ppb (563 ppb benzene). MW-7 was 110.6 ppb (90 ppb benzene). FW-7 was 252.5 ppb (non-detect for benzene). FW-9 was 81.1 ppb (30.8 ppb benzene). SVE-1 was 5475.7 ppb (48.7 ppb benzene). The PID effluent concentration at SVE-6/AS-1 was 324.1 ppm and 175.5 ppm on 3/7/17 and 4/7/17, respectively. 10/31/17 - Raphael Ketani. I reviewed the EnviroTrac October 2017 Quarterly Update Report dated 10/30/17 for the period June to August 2017. On 6/14/17, 7/12/17 and on 8/15/17 VEFRing was conducted at SVE-1 and short term remediation events (STREs) were

MERRITT GAS STATION (Continued) **S104276740**

conducted at SVE-6/AS-1. On 8/23/17, MW-1 to 3, 5 to 8, FW-7 to 9, CW-8, CW-9, SVE-1 and SVE-7 were gauged and sampled. Product was not detected in any of the wells. Groundwater was measured at 8.44' to 15.08' below grade and was determined to be flowing northerly. BTEX was non-detect or low at MW-1, 3 to 6, 8, FW-8, CW-8, CW-9 and SVE-7. MW-2 was 2269.9 ppb (481 ppb benzene). MW-7 was 129.5 ppb (115 ppb benzene). FW-7 was 122 ppb (non-detect for benzene). FW-9 was 126.3 ppb (48 ppb benzene). SVE-1 was 1558.1 ppb (83.1 ppb benzene). The PID effluent concentration at SVE-6/AS-1 was 95.3 ppm, 165.4 ppm and 131.2 ppm on 6/14/17, 7/12/17 and 8/15/17, respectively. EnviroTrac requested permission to abandon upgradient and side-gradient wells MW-1, 4, 5, 6, and SVE-7 based upon historical and current analytical data results. I reviewed the data for these wells and determined that their abandonment would not impact the monitoring of the site. 1/31/18 - Raphael Ketani. I reviewed the EnviroTrac January 2018 Quarterly Update Report dated 1/31/18 for the period September to November 2017. On 9/14/17, 10/30/17 and on 11/6/17 VEFRing was conducted at SVE-1 and short term remediation events (STREs) were conducted at SVE-6/AS-1. On 11/21/17, MW-2, 3, 8, FW-7 to 9, CW-8, CW-9 and SVE-1 were gauged and sampled. Product was not detected in any of the wells. Groundwater was measured at 8.25' to 15.64' below grade and was determined to be flowing northerly. Wells MW-1, 4 to 6 and SVE-7 were abandoned on 11/6/17. BTEX was non-detect or low at MW-3, 8, FW-7 to 9, CW-8 and CW-9. MW-2 was 3550.6 ppb (791 ppb benzene). MW-7 was not sampled. SVE-1 was 1126.5 ppb (69.5 ppb benzene). The PID effluent concentration at SVE-6/AS-1 was 408.1 ppm, 77.7 ppm and 360.9 ppm on 9/14/17, 10/30/17 and 11/6/17, respectively. 05/01/2018: This spill case was transferred to A. Doronova - AD. AD Received the following e-mail from Mr. Rennie: Dear Ms. Doronova, Please find attached the most recent Update Report for the above referenced location. Sincerely, Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com DL the report to DDocs. Will review. AD 05/29/2018: Reviewed the report. It states that the spill case was reported when petroleum-impacted soil were encountered during underground storage tank (UST) upgrade activities in August 1996. This report covers monitoring period from December 2017 to February 2018. On December 11, 2017, January 16, and February 1, 2018 - EnviroTrac conducted enhanced fluid recovery (EFR) events on monitoring well SVE-1 and short term remediation events (STREs) on SVE-6/AS-1. On February 6, 2018 - the consultant gauged ten (10) and sampled eight (8) monitoring wells. On April 12, 2018 EnviroTrac sampled three (3) monitoring wells. Wells Gauged: MW-2, 3, 7, 8; FW-7, 8, 9; CW-8, 9, and SVE-1 Wells Containing LPH (feet): None Groundwater Depth: 7.68 feet- 18.58 feet Groundwater Flow: Northerly Wells Sampled: MW-2, 3, 8; FW-7, 9; CW-8, 9, and SVE-1 Maximum Benzene Concentration: 355 micrograms per liter (ug/L) (MW-2) Maximum MTBE Concentration: 30.6 ug/L (MW-2) BTEX: highest concentrations are in well MW-2 (900ppb) EnviroTrac will continue quarterly groundwater sampling, with the next sampling event scheduled for May 2018. An Update Report summarizing these activities will be submitted to NYSDEC in July 2018. Monthly EFR and STRE events to continue. AD 07/18/2018: Received the following e-mail from Mr. Rennie: Dear Ms. Doronova, Please find attached the most recent Update Report for the above referenced location. Sincerely, Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) -

MERRITT GAS STATION (Continued) **S104276740**

joer@envirotrac.com Will review. AD 07/26/2018: Reviewed the report. This report covers monitoring period from March 2018 May 2018. On March 5, April 11, and May 3, 2018 - the consultant conducted enhanced fluid recovery (EFR) events on monitoring well SVE-1 and short term remediation events (STREs) on SVE-6/AS-1. - April 12, 2018 four (4) wells were gauged and three (3) monitoring wells were sampled. - May 8, 2018 nine (9) wells were gauged and eight (8) monitoring wells were sampled. Wells Gauged: MW-2, 3, 8; FW-7, 8, 9; CW-8, 9, and SVE-1. Wells Containing LPH (feet): None Groundwater Depth: 8.32 feet - 15.32 feet Groundwater Flow: Northerly Wells Sampled: MW-2, 3, 8; FW-7, 9; CW-8, 9, and SVE-1 Maximum Benzene Concentration: 620 micrograms per liter (ug/L) (MW-2) Maximum MTBE Concentration: 56.7 ug/L (MW-2) BTEX concentrations ranged in the site wells from ND in MW-3, MW-8, CW-9 to 2,600ppb in the most contaminated site well MW-2. Current Plans/Proposals: Continue quarterly groundwater sampling, with the next sampling event scheduled for August 2018. An Update Report summarizing these activities will be submitted to NYSDEC in October 2018. Continue monthly EFR and STRE events. AD 10/29/2018: Received the following e-mail from Mr. Rennie: Dear Ms. Doronova, Please find attached the most recent Update Report for the above referenced location. Sincerely, Joe Rennie Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com Will review. AD 11/23/2018: Reviewed the report for the monitoring period: June 2018 August 2018. Work Performed: - June 13, July 24, & August 7, 2018 - Conducted enhanced fluid recovery (EFR) events on monitoring well SVE-1 and short term remediation events (STREs) on SVE-6/AS-1. - August 30, 2018 Gauged and sampled ten (10) monitoring wells. Groundwater Monitoring: Wells Gauged: MW-2, 3, 7, 8, FW-7, 8, 9, CW-8, 9, and SVE-1. Wells Containing LPH (feet): None. Groundwater Depth: 8.19 feet - 15.02 feet. Groundwater Flow: Northerly Wells Sampled: MW-2, 3, 7, 8; FW-7, 9; CW-8, 9, and SVE-1. Maximum Benzene Concentration: 802 micrograms per liter (ug/L) (MW-2) Maximum MTBE Concentration: 44.1 ug/L (MW-2) Total VOCs Range: Non-detect (ND) 4,440.2 ug/L Recommendations: Continue quarterly groundwater sampling, with the next sampling event scheduled for November 2018. An Update Report summarizing these activities will be submitted to NYSDEC in January 2019. Continue monthly EFR and STRE events. AD 01/29/2019: Received the following e-mail from Ed Russo: Ainura attached is the most recent update report for your review/files. Let us know if you have any questions or comments. Thanks. Edward Russo - Senior Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - 516.523.6714 (Cell) - edr@envirotrac.com Will review. AD 02/15/2019: Reviewed the report. It states that for the monitoring period: September 2018 November 2018, the following work was performed at the site: - September 4 & November 6, 2018 - Conducted enhanced fluid recovery (EFR) events on monitoring well SVE-1 and short term remediation events (STREs) on SVE-6/AS-1. - October 11, 2018 Conducted EFR on monitoring well SVE-1. - November 12, 2018 Gauged and sampled ten (10) monitoring wells. Groundwater Monitoring: Wells Gauged: MW-2, 3, 7, 8, FW-7, 8, 9, CW-8, 9, and SVE-1 Wells Containing LPH (feet): None Groundwater Depth: 7.11 feet - 15.23 feet. Groundwater Flow: Northerly. Wells Sampled: MW-2, 3, 7, 8; FW-7, 9; CW-8, 9, and SVE-1. Maximum Benzene Concentration: 640 micrograms per liter (ug/L) (MW-2) Maximum MTBE Concentration: 33.8 ug/L (MW-2) Total VOCs Range: Non-detect (ND)

MERRITT GAS STATION (Continued) **S104276740**

2,656.8 ug/L Recommendations: the consultant will continue quarterly groundwater sampling, with the next sampling event scheduled for February 2019. An Update Report summarizing these activities will be submitted to NYSDEC in April 2019. EnviroTrac will continue monthly EFR and STRE events. AD 04/18/2019: Received the following e-mail from Mr. Rennie: Please find attached the most recent Update Report for the above referenced location. Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com Will review. AD 05/01/2019: Reviewed the report. It states that for the monitoring period: December 2018 February 2019 the following work was performed at the site: - December 4, 2018 and January 16 & February 7, 2019 - Conducted enhanced fluid recovery (EFR) events on monitoring well SVE-1 and short-term remediation events (STREs) on SVE-6/AS-1. - February 26, 2019 Gauged and sampled ten (10) monitoring wells. Groundwater Monitoring: Wells Gauged: MW-2, 3, 7, 8, FW-7, 8, 9, CW-8, 9, and SVE-1. Wells Containing LPH (feet): None Groundwater Depth: 6.71 feet 15.62 feet. Groundwater Flow: Northerly Wells Sampled: MW-2, 3, 7, 8; FW-7, 9; CW-8, 9, and SVE-1 Maximum Benzene Concentration: 694 micrograms per liter (ug/L) (MW-2) Maximum MTBE Concentration: 37.6 ug/L (MW-2) Total VOCs Range: Non-detect (ND) 4,116.0 ug/L Recommendations: Continue quarterly groundwater sampling, with the next sampling event scheduled for May 2019. An Update Report summarizing these activities will be submitted to NYSDEC in July 2019. Continue monthly EFR and STRE events. AD 05/07/2019: I had an internal meeting with DEC BCP regarding this site, and was informed that they received an application for this spill case to enter into BCP. If their application will be approved, this spill case will be transferred to BCP section. AD 07/31/2019: Received the following e-mail from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager phone: 631.924.3001 - email: joer@envirotrac.com EnviroTrac Ltd., 5 Old Dock Road Yaphank, NY 11980 Will review, AD 08/02/2019: Reviewed the report. It states that for the monitoring period: March May 2019, the following work was performed: at the site: - March 29, April 5, & May 2, 2019 - Conducted EFR events on monitoring well SVE-1 and STREs on SVE-6/AS-1. - May 15, 2019 Gauged and sampled ten (10) monitoring wells. GW monitoring: Wells Gauged: MW-2, 3, 7, 8, FW-7, 8, 9, CW-8, 9, and SVE-1 Wells Containing LPH (feet): None Groundwater Depth: 7.67 feet 15.24 feet Groundwater Flow: Northerly Wells Sampled: MW-2, 3, 7, 8; FW-7, 9; CW-8, 9, and SVE-1 Maximum Benzene Concentration: 719 micrograms per liter (ug/L) (MW-2) Maximum MTBE Concentration: 37.4 ug/L (MW-2) Total VOCs Range: Non-detect (ND) 3,439.5 ug/L Recommendations: This site will potentially be approved into the New York State Brownfields Program. Until the site is approved into this program, Speedway will continue quarterly groundwater sampling, with the next sampling event scheduled for August 2019. An Update Report summarizing these activities will be submitted to NYSDEC in October 2019. Continue monthly EFR and STRE events. AD 08/23/2019: Received the following e-mail from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD 09/19/2019: Reviewed the report. It states that the site is now active gas station. The spill was reported when petroleum-impacted soils were encountered during

MERRITT GAS STATION (Continued) **S104276740**

UST upgrade activities in August 1996. Site Remediation Activities: - June and September 2004 BioSolve injection events were completed in select on-site wells. - October 2008 Monthly Enhanced Fluid Recovery (EFR) events commenced on select wells. - December 2014 Monthly Soil Vapor Extraction (SVE)/Air Sparge (AS) Short-Term Remediation Events (STREs) events commenced on select wells. For the reported monitoring Ppriod: June - August 2019, the following work was performed at the site: - June 6, July 10, & August 1, 2019 - Conducted EFR events on monitoring well SVE-1 and STREs on SVE-6/AS-1. - August 12, 2019 Gauged ten (10) and sampled nine (9) monitoring wells. Groundwater Monitoring: Wells Gauged: MW-2, 3, 7, 8, FW-7, 8, 9, CW-8, 9, and SVE-1 Wells Containing LPH (feet): None Groundwater Depth: 7.48 feet 15.33 feet Groundwater Flow: Northerly Wells Sampled: MW-2, 3, 7, 8; FW-7, 9; CW-8, 9, and SVE-1 Maximum Benzene Concentration: 489 ug/L (MW-2) Maximum MTBE Concentration: 28.8 ug/L (MW-2) Total VOCs Range: Non-detect (ND) 3,901.3 ug/L (MW-2) GW data: Well 08/2018 08/2019 (TVOCs in ppb) MW-2 4440 3900 MW-3 26 ND MW-7 37 19 MW-8 ND ND FW-7 468 52 FW-8 75 NS FW-9 139 1020 CW-8 69 148 CW-9 116 ND SVE-1 4035 863 Recommendations: This site will potentially be approved into the New York State Brownfields Program for a redevelopment project. Speedway is scheduled to complete divestment/UST system removal activities in September 2019. UST system closure reporting and future monitoring/reporting related to this site, if needed, will be conducted by the new property owner (assuming the site is approved into the Brownfields Program). AD 04/21/2020: Received the following email from Mr. Morley of PWG: ATTENTION: This email came from an external source. Do not open attachments or click on links from unknown senders or unexpected emails. Ainura, Please find attached the 1st Quarter 2020 spill monitoring report for 204 4th Ave in Brooklyn for your review. Please let me know if you have any questions or concerns. -Ryan -- Ryan Morley, PG - Project Manager 630 Johnson Ave, Suite 7 Bohemia, NY 11716 w. 631.589.6353 f. 631.589.8705 Will review. AD 05/12/2020: Reviewed the report. It states that The property ownership changed in November 2019 and PWGC was retained to continue groundwater monitoring at the site. A Supplemental Remedial Investigation (SRI) was performed as part of the sites enrolment into the New York State Department of Environmental Conservation s (NYSDEC s) Brownfield Cleanup Program (BCP) which included groundwater sampling. The groundwater sampling performed during the SRI substituted for the fourth quarter 2019 monitoring event. The subject property is a former retail gasoline fueling station, fueling operations ceased in October 2019. The lot measures approximately 19,000 square-feet and is bounded by Sackett Street to the north, commercial properties to the west, 4th avenue to the east, and Union Street to the south. The property is improved with a 360-square foot at-grade storage building, and a cashier s kiosk. In October 2019, four (4) 4,000-gallon gasoline USTs, one (1) 4,000-gallon diesel UST, and one (1) 550-gallon wastewater UST were closed and removed from the property. An abandoned 2,000-gallon fuel oil UST near the storage building at the northwest corner of the Site was partially exposed, however the UST was not removed due to nearby utilities and potential for undermining the sidewalk and onsite storage building. Upon completing UST removal, associated product and vent lines were exposed and removed. During the October 2019 UST removal activities, monitoring well MW-3, which was located near the storage building, was destroyed. During the November 2019 SRI, GW018 was installed on the northwest corner of the site. Based on

MERRITT GAS STATION (Continued) **S104276740**

information documented in previous monitoring events, regional groundwater flow is towards the north. GW sampling: PWGC mobilized to the site on Monday, March 9, 2020 to perform quarterly groundwater monitoring activities. Groundwater analytical results were compared to the NYSDEC Ambient Groundwater Quality Standards (AWQS). Samples were collected from 7 wells: CW-8, MW-8, GW018, FW-7, MW-2, MW-7, and CW-9. Monitoring wells FW-8 and FW-9 were dry and were not sampled. Analytical results for samples collected at CW-8, MW-8, GW018, FW-7, MW-2, MW-7 and CW-9 were compared to AWQS. MBTE was detected in MW-2, GW018, FW-7, MW-7, and CW-9 and BTEX was detected in MW-2, CW-8, FW-7, and MW-7. The highest concentration of MBTE was detected in CW-9 (11.0 ug/L). The lowest detectable concentration of MBTE was in GW018 (1.9 ug/L). The highest concentration of BTEX was detected in MW-2 (117.47 ug/L). The lowest detectable concentration of BTEX was in MW-7 (0.16 ug/L). Additionally, the highest concentrations of isopropylbenzene were detected at MW-2, FW-7, and CW-8. Based on these results, the highest degree of impact appears to be located adjacent to the former UST locations located in the central and western portions of the property. Generally, these concentrations were similar to previous sampling events. GW data: Well 08/2018 08/2019 03/2020 (TVOCs in ppb) MW-2 4440 3900 248 MW-3 26 ND destr MW-7 37 19 ND MW-8 ND ND ND FW-7 468 52 49.5 FW-8 75 NS NS dry FW-9 139 1020 NS dry CW-8 69 148 67 CW-9 116 ND 11 SVE-1 4035 863 NS GW018 ND Removal of the sourse of contamination significantly decreased TVOCs in the most contaminated site well MW-2 from 3900 ppb in August 2019 to 248 ppb in march of 2020. The consultanr states that based on analytical data, it appears that the highest levels of residual impact are located adjacent to the former UST areas located in the central and western portions of the site. Analytical results were generally consistent with previous monitoring events performed by Envirotrac. At this time, PWGC offers the following recommendations for the site: - Continue quarterly groundwater sampling at CW-8, MW-8, GW018, FW-7, MW-2, MW-7, and CW-9. The next sampling event is scheduled for May 2020. AD 08/21/2020: Received the following email from Mr. Morley: Ainura, Please find attached the 2nd Quarter 2020 spill monitoring report for 204 4th Ave in Brooklyn for your review. Please let me know if you have any questions or concerns. -Ryan Ryan Morley, PG - Project Manager 630 Johnson Ave, Suite 7 Bohemia, NY 11716 w. 631.589.6353 f. 631.589.8705 Will review. AD 09/23/2020: Reviewed the 2nd quarter 2020 report. It states that PWGC mobilized to the site on Thursday, June 18, 2020 to perform quarterly groundwater monitoring activities. Groundwater monitoring consisted of measuring depth to water and total well depth measurements for the nine monitoring wells at the site. Groundwater analytical results were compared to the NYSDEC Ambient Groundwater Quality Standards (AWQS). Samples were collected from CW-8, MW-8, GW018, MW-2, MW-7, and CW-9. Monitoring wells FW-7, FW-8 and FW-9 were observed to be dry at the time of field activities and could not be sampled. The samples were analyzed for the presence of: " Volatile Organic Compounds (VOCs) by USEPA method 8260 NYSDEC CP-51 List. Monitoring Well Sampling Results: Analytical results for samples collected at CW-8, MW-8, GW018, MW-2, MW-7, and CW-9 were compared to AWQS. Samples collected from MW-8, GW018, MW07, and CW-9 yielded concentrations of VOCs less than AWQS. MBTE was detected in CW-8, GW018, MW-2 and MW-7, with the concentrations of each under the AWQS of 10 ug/L. The highest concentration of MBTE was detected in MW-7 (9.6 ug/L). The lowest detectable concentration of MBTE was in CW-8

MERRITT GAS STATION (Continued) **S104276740**

(0.75 ug/L). Detectable concentrations of MBTE were less than AWQS at each sampling location. Benzene was detected at concentrations greater than AWQS at monitoring wells MW-2 and CW-8 with the highest concentration, 35 ug/L, detected at MW-2. Ethylbenzene was detected at a concentration grater than AWQS at MW-2 with a concentration of 11 ug/L. The highest BTEX (benzene, toluene, ethylbenzene, and xylene) was detected in MW-2 (46 ug/L). Additionally, isopropylbenzene and n-propylbenzene was detected above AWQS in samples from MW-2 and CW-8 (11 ug/L and 13 ug/L : 20 ug/L and 15 ug/L, respectively). 1,2,4-trimethylbenzene was detected at a concentration of 77 ug/l at MW-2. 1,2,4-trimethylbenzene, isopropylbenzene, and n-propylbenzene are common compounds associated with petroleum impact. Based on these results, the highest degree of impact appears to be located adjacent to the former UST locations located in the central and western portions of the property. Generally, these concentrations were similar to previous sampling events. At this time, PWGC offers the following recommendations for the site: " Continue quarterly groundwater sampling at CW-8, MW-8, GW018, FW-7, MW-2, MW-7, and CW-9. The next sampling event is scheduled for September 2020. AD 11/10/2020: Received the following email from Mr. Morley: Ainura, Please find attached the 3rd Quarter 2020 spill monitoring report for 204 4th Ave in Brooklyn for your review. Please let me know if you have any questions or concerns. -Ryan Ryan Morley, PG - Project Manager 630 Johnson Ave, Suite 7 Bohemia, NY 11716 w. 631.589.6353 f. 631.589.8705 Will review. AD 12/11/2020: Reviewed the report. It states that The property ownership changed in November 2019 and PWGC was retained to continue groundwater monitoring at the site. The subject property is a former retail gasoline fueling station, fueling operations ceased in October 2019. The lot measures approximately 19,000 square-feet and is bounded by Sackett Street to the north, commercial properties to the west, 4th avenue to the east, and Union Street to the south. The property is improved with a 360-square foot at-grade storage building, and a cashier s kiosk. PWGC mobilized to the site on Wednesday, September 23, 2020 to perform quarterly groundwater monitoring activities. Samples were collected from CW-8, MW-8, GW018, MW-2, MW-7, and CW-9. Monitoring wells FW-7, FW-8 and FW-9 were observed to be dry at the time of field activities and could not be sampled. Total BTEX was detected in MW-2 at a concentration of 1,015 ug/L. Minimal concentrations or non-detectable concentrations of total were observed in the remaining monitoring wells. Based on these results, remaining petroleum impact in groundwater above AWQS appears to be located adjacent to the former UST locations located in the central and western portions of the property. At this time, PWGC offers the following recommendations for the site: - Continue quarterly groundwater sampling at CW-8, MW-8, GW018, FW-7, MW-2, MW-7, and CW-9. The next sampling event is scheduled for December 2020. 04/22/2021: Received the following email from Mr. Morley: Ainura, Please find attached the first quarter 2021 spill monitoring report for 204 4th Ave in Brooklyn for your review. Please let me know if you have any questions or concerns. -Ryan Ryan Morley, PG - Project Manager 630 Johnson Ave, Suite 7 Bohemia, NY 11716 w. 631.589.6353 f. 631.589.8705 Will review. AD 05/26/2021: Reviewed the report. It states that PWGC mobilized to the site on Wednesday, March 17, 2021 to perform quarterly groundwater monitoring activities. Samples were collected from CW-8, MW-8, GW018, MW-2, MW-7, and CW-9. Monitoring well FW-7 was observed to be dry at the time of field

MERRITT GAS STATION (Continued) **S104276740**

activities and could not be sampled. The samples were analyzed for the presence of: " Volatile Organic Compounds (VOCs) by USEPA method 8260 NYSDEC CP-51 List Monitoring Well Sampling Results: Analytical results for samples collected at CW-8, MW-8, GW018, MW-2, MW-7, and CW-9 were compared to AWQS. Samples collected from wells MW-8, GW018, and CW-9 indicated VOCs less than AWQS. MBTE was detected in MW-2 at 11 ug/L, which is slightly more than the AWQS of 10 ug/L. Sample results from the five other wells yielded concentrations of MBTE that were below AWQS or below the laboratory detection limit. Benzene was detected in the sample collected from MW-7 at 6.9 ug/L. Sample results from the five other wells for benzene were below AWQS or below the laboratory detection limit. Concentrations of total BTEX comprised of solely the detections of Benzene, as the other three compounds were not detected at any of the six monitoring wells. Additionally, isopropylbenzene was detected at a concentration greater than AWQS in the sample collected from CW-8 with a result of 5.3 ug/L. Based on these results, remaining petroleum impact in groundwater above AWQS appears to be located adjacent to the former UST locations located in the central and western portions of the property. Based on these results, remaining petroleum impact in groundwater above AWQS appears to be located adjacent to the former UST locations located in the central and western portions of the property. Analytical results were generally consistent with previous monitoring events in terms of which locations exhibited the highest degree of impact, however the concentrations of VOCs were significantly lower than concentrations reported during previous sampling events. Recommendations: At this time, PWGC offers the following recommendations for the site: - Continue quarterly groundwater sampling at CW-8, MW-8, GW018, FW-7, MW-2, MW-7, and CW-9. The next sampling event is scheduled for June 2021. AD 11/05/2021: Received the following email from Mr. Morley: Ainura, Please find attached the third quarter 2021 spill monitoring report for 204 4th Ave in Brooklyn for your review. Please let me know if you have any questions or concerns. -Ryan Ryan Morley, PG - Project Manager 630 Johnson Ave, Suite 7 Bohemia, NY 11716 w. 631.589.6353 f. 631.589.8705 Will review. AD 12/02/2021: Reviewed the 3rd quarter 2021 report. It states that PWGC mobilized to the site on Monday September 13, 2021 to perform quarterly groundwater monitoring activities. Groundwater monitoring consisted of measuring depth to water and total well depth measurements for the nine monitoring wells at the site. Water levels were collected using a Solinst Oil / Water Interface Probe. Groundwater analytical results were compared to the NYSDEC Ambient Groundwater Quality Standards (AWQS). Samples were collected from CW-8, MW-8, GW018, MW-2, MW-7, and CW-9. Monitoring well FW-7 was observed to be dry at the time of field activities and could not be sampled. The samples were analyzed for the presence of: " Volatile Organic Compounds (VOCs) by USEPA method 8260 NYSDEC CP-51 List Monitoring Well Sampling Results: Analytical results for samples collected at CW-8, MW-8, GW018, MW-2, MW-7, and CW-9 were compared to NYSDEC s AWQS. Samples collected from wells MW-2, MW-8, and GW018 indicated VOCs less than AWQS. MBTE was detected below the AWQS of 10 ug/L in all six samples. Benzene was detected in the samples collected from MW-7, CW-8, and CW-9 at concentrations of 22 ug/L, 12 ug/L, and 5.7 ug/L, respectively, which are greater than the AWQS of 1 ug/L. Sample results from the three other wells yielded concentrations of benzene below the laboratory detection limit. Concentrations of BTEX comprised of solely the detections of Benzene,

MERRITT GAS STATION (Continued) **S104276740**

as the other three compounds were not detected at any of the six wells. Isopropylbenzene was detected in the samples collected from MW-7, CW-8, and CW-9 at of 95 ug/L, 110 ug/L and 6.2/L, respectively, which are greater than the AWQS of 5 ug/L. N-proplybenzene was detected in MW-7 and CW-8 at 150 ug/L and 140 ug/L, respectively, which are greater than the AWQS of 10 ug/L. Sec-butylbenzene was detected in MW-7 and CW-8 at 23 ug/L and 9.5 ug/L, respectively, which are greater than the AWQS of 5 ug/L. Napthalene was detected in the sample collected from CW-8 at a concentration of 12 ug/L which is greater than the AWQS of 5 ug/L. N-butylbenzene was detected in the sample collected from CW-8 at 6.2 ug/L which is greater than the AWQS of 5 ug/L. VOs levels have increased when compared to last quarter s sampling event but overall show decreasing concentrations when compared to previous sampling events. Hydrographs have been developed for each of the seven monitoring wells illustrating the trends in BTEX and MBTE concentrations over time compared to groundwater elevations dating back to May 2016. Based on these results, remaining petroleum impact in groundwater above AWQS appears to be located adjacent to the former UST locations located in the central and western portions of the property. Analytical results were generally consistent with previous monitoring events in terms of which locations exhibited the highest degree of impact, however the concentrations of VOCs were generally lower than concentrations reported during previous sampling events. At this time, PWGC offers the following recommendations for the site: " Continue quarterly groundwater sampling at CW-8, MW-8, GW018, FW-7, MW-2, MW-7, and CW-9. The next sampling event is scheduled for December 2021. Given that BTEX ranges in the site well s from ND to 27 ppb in well MW-7, his site is a good candidate for a case closure in the future. AD 12/8/21 - Spill transferred to Steven Wu for tracking under BCP site no. C224295. JHO"

Remarks: "removal of under ground tanks-poss soil contamination"

All Materials:

Site ID:	74470
Operable Unit ID:	1036525
Operable Unit:	01
Material ID:	348465
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	74470
Operable Unit ID:	1036525
Operable Unit:	01
Material ID:	348466
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

MERRITT GAS STATION (Continued) **S104276740**

Oxygenate: Not reported

Name: HESS STATION #32530
Address: 204-222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0602980 / 2006-09-12
Facility ID: 0602980
Facility Type: ER
DER Facility ID: 310148
Site ID: 365575
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2006-06-17
Investigator: SKCARLSO
Referred To: CONSOLIDATED WITH 96-05719
Reported to Dept: 2006-06-17
CID: 71
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-06-17
Spill Record Last Update: 2006-09-12
Spiller Name: MICHAEL MATRI
Spiller Company: HESS STATION #32530
Spiller Address: 204-222 4TH AVE
Spiller Company: 001
Contact Name: MICHAEL MATRI
DEC Memo: "6/19/06: Left Mike Matri a voice message requesting a report with endpoint sampling. Received voice message from Mike Matri, post-excavation sampling results will be submitted. 8/7/06: Sent followup email for endpoint sampling results to Dawn Coughlin of Hess. 8/15/06: Received the results of endpoint sampling conducted during spill bucket replacement. Contaminants exceeding TAGM standards were found in both samples. A monitoring well is required adjacent to endpoint sampling locations. If possible, the RAP due for Spill 96-05719 should include remediation of spill 06-02980. 9/12/06: Consolidated with spill 96-05719. A RAP for installation of a SVE system was approved which will remediate spills 96-05719 and 06-02980."
Remarks: "SPILL BUCKET LEAKING. IMPACT TO SOIL. SOIL EXCAVATED. HESS WAS UPGRADING SPILL BUCKET. IDENTIFIED CONTAMINATED SOIL. STATION HAS EXISTING DEC SPILL . CASE MGR IS SARAH ANDERSON - REGION 2"

All Materials:
Site ID: 365575
Operable Unit ID: 1123589
Operable Unit: 01
Material ID: 2113056
Material Code: 0009

MERRITT GAS STATION (Continued) **S104276740**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O222 **204 4TH AVENUE** **NY BROWNFIELDS** **S125298840**
NNE **204 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.161 mi.
850 ft. **Site 9 of 9 in cluster O**

Relative:
Higher

Actual:
26 ft.

BROWNFIELDS:

Name:	204 4TH AVENUE
Address:	204 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11217
Program:	BCP
Site Code:	587854
Acres:	0.440
HW Code:	C224295
SWIS:	2401
Town:	New York City
Record Added Date:	04/29/2019
Record Updated Date:	06/07/2021
Update By:	JHOCONNE
Site Description:	"Location The site is located in an urban area in the Gowanus neighborhood of Brooklyn. The Site is bounded by Sackett Street to the north, Union Street to the south, 4th Avenue to the east, and commercial properties to the west. Site Features The site was a gasoline filling station and was improved with a 360 square foot at grade storage building, a cashier s kiosk, and a canopy covering the pump islands. The site is no longer being used as a filling station and the kiosk has been removed. Current Zoning and Land Use The site is zoned M1-2 for light manufacturing and is surrounded by similarly zoned properties and residential zoned properties to the east. Past Use of the Site Based on information gathered as part of the February 2019 Phase I ESA, the site was first developed in approximately 1906 and used for residential/commercial purposes from approximately 1906 to 1961. In the early 1960s, the residential/commercial buildings were demolished, and a gasoline station was constructed in 1965. The site has been used as a gasoline station since then. Site Geology and Hydrogeology The stratigraphy of the site, from the surface down, consists of primarily historic urban fill, characterized by loosely compacted fine to coarse sand with fragments of brick and concrete, to depths ranging from 12 to 21 feet below grade across the site. Historic urban fill material is underlain by silty light brown sand, underlain by a layer of grey sandy clay material with organic matter (wood, roots) present in the matrix. Groundwater at the site is approximately 14 feet below grade and generally flows towards the north/northwest. "
Env Problem:	"Nature and extent of contamination Based upon investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Soil - VOCs including 1,2,4-Trimethylbenzene was found in soil at concentrations of 2,100

204 4TH AVENUE (Continued) **S125298840**

	parts per million (ppm) compared to restricted residential soil cleanup objective (RRSCO) of 52 ppm and the protection of groundwater SCO (PGSCO) of 3.9 ppm. Xylenes was found at concentrations of 3,600 ppm (RRSCO is 100 ppm, PGSCO is 1.6 ppm). SVOCs including benzo(a)anthracene was found at concentrations of 120 ppm (RRSCO is 1 ppm). Benzo(b)fluoranthene was found at concentrations of 110 ppm (RRSCO is 1 ppm). Metals including lead was found at concentrations of 3,170 ppm (RRSCO is 400 ppm), arsenic was found at 542 ppm (RRSCO is 16 ppm). Groundwater - VOCs including benzene was found in groundwater at concentrations of 9.6 parts per billion (ppb) compared to Ambient Water Quality Standards (AWQS) of 1 ppb. 1,2,4,5-Tetramethylbenzene was found at concentrations of 61 ppb (AWQS is 5 ppb). SVOCs including acenaphthene was found at concentrations of 64 ppb (AWQS is 20 ppb). Metals including arsenic was found at concentrations of 33.61 ppb (AWQS is 25 ppb). Soil Vapor - VOCs including 2,2,4-Trimethylpentane was found throughout the site but at highest concentration at the north-east portion of the site at concentrations of 509,000 micrograms per cubic meter (ug/m3). "
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-07-10 12:10:00
Record Upd:	2019-07-10 12:11:00
Updated By:	GWBURKE
Own Op:	6
Sub Type:	P02
Owner Name:	John M. Helms
Owner Company:	Speedway LLC
Owner Address:	500 Speedway Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Enon, OH 45323
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	Not reported
Owner Company:	204 4th Avenue LLC
Owner Address:	51 East 12th Street, 7th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Pacific Branch
Owner Address:	25 4th Avenue at Pacific Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America

204 4TH AVENUE (Continued) **S125298840**

Own Op:	6
Sub Type:	P02
Owner Name:	Avi Fisher
Owner Company:	204 4th Avenue LLC
Owner Address:	51 East 12th Street, 7th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	2-297666
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2020-02-11 13:06:00
Record Updated:	2020-02-11 13:06:00
Updated By:	LXZIELIN

W223 **CON EDISON** **NY MANIFEST** **S119077023**
NW **451 CARROLL ST FRONT OF** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.162 mi.
853 ft. **Site 1 of 11 in cluster W**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	451 CARROLL ST FRONT OF
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004818912
Facility Status:	Not reported
Location Address 1:	451 CARROLL
Code:	BP
Location Address 2:	SB 22610
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004818912
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S119077023**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2015
Trans1 Recv Date:	08/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004818912
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469366JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W224
NW
1/8-1/4
0.162 mi.
853 ft.

CON EDISON
451 CARROLL ST FRONT OF
BROOKLYN, NY 11225

Site 2 of 11 in cluster W

RCRA NonGen / NLR

1019906244
NYP004818912

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20150805
Handler Name:	CON EDISON	
Handler Address:		451 CARROLL ST FRONT OF
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004818912
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019906244**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019906244**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

W225 **CON EDISON** **NJ MANIFEST** **S120675005**
NW **451 CARROLL ST FRONT OF** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.162 mi.
853 ft. **Site 3 of 11 in cluster W**

Relative:
Lower

Actual:
12 ft.

NJ MANIFEST:

EPA Id:	NYP004818912
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469366JJK
EPA ID:	NYP004818912
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120675005**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

S226 **CON EDISON** **RCRA NonGen / NLR** **1019907638**
North **617 UNION ST & 3RD AVE** **FINDS** **NYP004836340**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.165 mi.
872 ft. **Site 3 of 6 in cluster S**

Relative: **Lower**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150909
Handler Name:	CON EDISON	
Handler Address:		617 UNION ST & 3RD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004836340
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No

CON EDISON (Continued) **1019907638**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1019907638**

Historic Generators:

Receive Date:	20150909
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150909
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069704519

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019907638
Registry ID: 110069704519

CON EDISON (Continued) **1019907638**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069704519
Name: CON EDISON
Address: 617 UNION ST & 3RD AVE
City,State,Zip: BROOKLYN, NY 11215

Q227 **CON EDISON** **NY MANIFEST** **S118256981**
NNW **501 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.166 mi.
876 ft. **Site 3 of 5 in cluster Q**

Relative: **Lower**
Actual: **16 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 501 PRESIDENT ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004795480
Facility Status: Not reported
Location Address 1: 501 PRESIDENT ST
Code: BP
Location Address 2: SB 31651
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004795480
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 06/17/2015
Trans1 Recv Date: 06/17/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/19/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004795480
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported

CON EDISON (Continued) **S118256981**

Manifest Tracking Number:	002614311GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q228 **CON EDISON** **RCRA NonGen / NLR** **1019904241**
NNW **501 PRESIDENT ST** **NYP004795480**
1/8-1/4 **BROOKLYN, NY 11215**
0.166 mi.
876 ft. **Site 4 of 5 in cluster Q**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20150617
Actual: Handler Name:	CON EDISON	
16 ft. Handler Address:		501 PRESIDENT ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004795480
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported

CON EDISON (Continued) **1019904241**

State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909
Recognized Trader-Importer:		No

CON EDISON (Continued) **1019904241**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150617
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150617
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

Q229 **CON EDISON** **NJ MANIFEST** **S120672898**
NNW **501 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.166 mi.
876 ft. **Site 5 of 5 in cluster Q**

Relative: NJ MANIFEST:
Lower

Actual: EPA Id:	NYP004795480
16 ft. Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

CON EDISON (Continued) **S120672898**

Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614311GBF
EPA ID:	NYP004795480
Date Shipped:	6/17/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

X230 **4TH & SACKETT STREET** **NY LTANKS** **S105053980**
NE **4TH & SACKETT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.167 mi.
880 ft. **Site 1 of 2 in cluster X**

Relative:
Higher

Actual:
26 ft.

LTANKS:

Name:	4TH & SACKETT STREET
Address:	4TH & SACKETT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9113310 / 1994-08-03
Facility ID:	9113310
Site ID:	221268
Spill Date:	1992-03-31
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	1994-08-03
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1992-03-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-07
Spill Record Last Update:	1994-08-03
Spiller Name:	Not reported
Spiller Company:	MERIT GAS STA.
Spiller Address:	4TH & SACKETT ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	182999
DEC Memo:	""
Remarks:	"WILL E.I.R., ALSO REG. UNLEADED PRODUCT LINE FAILED AT SAME LOCATION, LEAK RATE = .112 GPH."

All TTF:

Facility ID:	9113310
Spill Number:	9113310
Spill Tank Test:	1539808
Site ID:	221268
Tank Number:	Not reported
Tank Size:	0
Material:	0022
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

4TH & SACKETT STREET (Continued) **S105053980**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 221268
Operable Unit ID: 964072
Operable Unit: 01
Material ID: 414820
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

S231 **SJ FUEL CO. INC.** **NY TANKS** **U003396247**
North **601 UNION STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.168 mi.
886 ft. **Site 4 of 6 in cluster S**

Relative: TANKS:
Lower
Name: SJ FUEL CO. INC.
Actual: Address: 601 UNION STREET
17 ft. City,State,Zip: BROOKLYN, NY 11215
Facility Id: 2-601627
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 11/02/2013
UTM X: 585771.97343
UTM Y: 4503547.22018

S232 **A 2 Z ENVIRONMENTAL LLC** **RCRA NonGen / NLR** **1014926942**
North **601 UNION ST** **NYR000187302**
1/8-1/4 **BROOKLYN, NY 11215**
0.168 mi.
886 ft. **Site 5 of 6 in cluster S**

Relative: RCRA NonGen / NLR:
Lower
Date Form Received by Agency: 20111129
Actual: Handler Name: A 2 Z ENVIRONMENTAL LLC
17 ft. Handler Address: 601 UNION ST
Handler City,State,Zip: BROOKLYN, NY 11215
EPA ID: NYR000187302
Contact Name: KEVIN M BARTLEY
Contact Address: BARTLEY RD
Contact City,State,Zip: JACKSON, NJ 08527
Contact Telephone: 877-388-8265
Contact Fax: 732-364-6515
Contact Email: MRKBARTLEY@HOTMAIL.COM

A 2 Z ENVIRONMENTAL LLC (Continued) **1014926942**

Contact Title:		PRESIDENT
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BARTLEY RD
Mailing City,State,Zip:		JACKSON, NJ 08527
Owner Name:	601 UNION STREET REALTY	CORP
Owner Type:		Private
Operator Name:	KEVIN M BARTLEY	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported

A 2 Z ENVIRONMENTAL LLC (Continued) **1014926942**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: 601 UNION STREET REALTY	CORP
Legal Status:	Private
Date Became Current:	19890830
Date Ended Current:	Not reported
Owner/Operator Address:	601 UNION ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	877-388-8265
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: KEVIN M BARTLEY	
Legal Status:	Private
Date Became Current:	20110701
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20111129
Handler Name: A 2 Z ENVIRONMENTAL LLC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

A 2 Z ENVIRONMENTAL LLC (Continued) **1014926942**

List of NAICS Codes and Descriptions:
NAICS Code: 54162
NAICS Description: ENVIRONMENTAL CONSULTING SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

W233 **CON EDISON** **NY MANIFEST** **S117537111**
NW **450 CARROL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.168 mi.
888 ft. **Site 4 of 11 in cluster W**

Relative: **Lower**
Actual: **11 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 450 CARROL ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004696415
Facility Status: Not reported
Location Address 1: 450 CARROL ST
Code: BP
Location Address 2: MH 2544
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004696415
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 11/17/2014
Trans1 Recv Date: 11/17/2014
Trans2 Recv Date: 11/21/2014

CON EDISON (Continued) **S117537111**

TSD Site Recv Date:	11/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004696415
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416820GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y234 **RALPH'S CLEANERS** **NY DRYCLEANERS** **S128781715**
East **230 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.170 mi.
900 ft. **Site 1 of 4 in cluster Y**

Relative:
Higher

Actual:
50 ft.

DRYCLEANERS:

Name:	RALPH'S CLEANERS
Address:	230 5TH AVE
City,State,Zip:	BROOKLYN, NY 11215 1201
Facility ID:	2-6103-00246
Phone Number:	7187892326
Region:	Not reported
Registration Effective Date:	2000-07-26 12:54:50
Inspection Date:	2001-05-01 11:00:00
Install Date:	Not reported
Expiration Date:	03/31/2003
Removal Date:	Not reported

RALPH'S CLEANERS (Continued) **S128781715**

Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported
Name:	RALPH'S CLEANERS
Address:	230 5TH AVE
City,State,Zip:	BROOKLYN, NY 11215 1201
Facility ID:	2-6103-00246
Phone Number:	7187892326
Region:	Not reported
Registration Effective Date:	2000-07-26 12:54:50
Inspection Date:	2000-05-01 13:00:00
Install Date:	Not reported
Expiration Date:	03/31/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Y235 **RALPHS CLEANERS** **RCRA NonGen / NLR** **1000552701**
East **230 FIFTH AVE** **NY MANIFEST** **NYD986951069**
1/8-1/4 **BROOKLYN, NY 11215**
0.170 mi.
900 ft. **Site 2 of 4 in cluster Y**

Relative: **Higher**
Actual: **50 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	RALPHS CLEANERS	
Handler Address:		230 FIFTH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYD986951069
Contact Name:		RALPH MONTERO
Contact Address:		FIFTH AVE
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-789-2326
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		FIFTH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	RALPH MONTERO	
Owner Type:		Private
Operator Name:	RALPH MONTERO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

RALPHS CLEANERS (Continued) **1000552701**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

RALPHS CLEANERS (Continued) **1000552701**

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RALPH MONTERO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: RALPH MONTERO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: RALPH MONTERO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: RALPHS CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

RALPHS CLEANERS (Continued) **1000552701**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: RALPHS CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19910503
Handler Name: RALPHS CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	RALPHS CLNRS
Address:	230 FIFTH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYD986951069
Facility Status:	Not reported
Location Address 1:	230 FIFTH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

RALPHS CLEANERS (Continued) **1000552701**

NY MANIFEST:

EPAID:	NYD986951069
Mailing Name:	RALPHS CLNRS
Mailing Contact:	RALPHS CLNRS
Mailing Address 1:	230 FIFTH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187892326

R236 **216 3RD STREET** **RCRA NonGen / NLR** **1000195630**
West **216 3RD ST** **FINDS** **NYD001869049**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.172 mi. **NY MANIFEST**
910 ft. **Site 7 of 10 in cluster R**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	216 3RD STREET	
Handler Address:		216 3RD ST
Handler City,State,Zip:		BROOKLYN, NY 11211
EPA ID:		NYD001869049
Contact Name:		SARAH ATTIAS
Contact Address:		3RD ST
Contact City,State,Zip:		BROOKLYN, NY 11211
Contact Telephone:		718-522-5656
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		3RD ST
Mailing City,State,Zip:		BROOKLYN, NY 11211
Owner Name:	JOSEPH DUNN	
Owner Type:		Private
Operator Name:	JOSEPH DUNN	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

216 3RD STREET (Continued) **1000195630**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOSEPH DUNN	
Legal Status:	Private

216 3RD STREET (Continued) **1000195630**

Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9265 SHORE RD
Owner/Operator City,State,Zip: BROOKLYN, NY 99999
Owner/Operator Telephone: 718-522-5656
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOSEPH DUNN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9265 SHORE RD
Owner/Operator City,State,Zip: BROOKLYN, NY 99999
Owner/Operator Telephone: 718-522-5656
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOSEPH DUNN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9265 SHORE RD
Owner/Operator City,State,Zip: BROOKLYN, NY 99999
Owner/Operator Telephone: 718-522-5656
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: 216 3RD STREET
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: 216 3RD STREET
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

216 3RD STREET (Continued) **1000195630**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19911023
Handler Name: 216 3RD STREET
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004336193

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000195630
Registry ID: 110004336193
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004336193
Name: 216 3RD STREET
Address: 216 3RD ST
City,State,Zip: BROOKLYN, NY 11211

NY MANIFEST:
Name: LINEAR ABATEMENT
Address: 216 3RD ST
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYD001869049

216 3RD STREET (Continued) **1000195630**

Facility Status: Not reported
Location Address 1: 216 3RD ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001869049
Mailing Name: LINEAR ABATEMENT
Mailing Contact: KERRY MCNAMARA
Mailing Address 1: 216 3RD STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11215
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185225656

W237 **CON ED** **NY MANIFEST** **S118259177**
NW **443 CARROLL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.172 mi.
910 ft. **Site 5 of 11 in cluster W**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:
Name: CON ED
Address: 443 CARROLL ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004827627
Facility Status: Not reported
Location Address 1: 443 CARROLL ST
Code: BP
Location Address 2: SB 82030
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004827627
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON ED (Continued) **S118259177**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/20/2015
Trans1 Recv Date:	08/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004827627
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624799GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W238 **CON EDISON** **RCRA NonGen / NLR** **1019906853**
NW **443 CARROLL ST** **FINDS** **NYP004827267**
1/8-1/4 **BROOKLYN, NY 11209** **ECHO**
0.172 mi.
910 ft. **Site 6 of 11 in cluster W**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150820
Handler Name:	CON EDISON	
Handler Address:		443 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11209
EPA ID:		NYP004827267
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019906853**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150820
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150820
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019906853**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069675435

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906853
Registry ID:	110069675435
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069675435
Name:	CON EDISON
Address:	443 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11209

R239 **190-220 THIRD STREET STORE LLC** **NJ MANIFEST** **S117987466**
West **214 3RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.173 mi.
916 ft. **Site 8 of 10 in cluster R**

Relative: **Lower**

Actual: **11 ft.**

NJ MANIFEST:

EPA Id:	NYR000197178
Mail Address:	3RD ST
Mail City/State/Zip:	BROOKLYN, NY 11215
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOHN K BOGDANSKI
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported

190-220 THIRD STREET STORE LLC (Continued) **S117987466**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010556089JJK
EPA ID:	NYR000197178
Date Shipped:	10/26/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	40,520.00 Pounds

Manifest Number:	010556087JJK
EPA ID:	NYR000197178
Date Shipped:	10/26/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported

190-220 THIRD STREET STORE LLC (Continued) **S117987466**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	38,000.00 Pounds

Manifest Number:	010556088JJK
EPA ID:	NYR000197178
Date Shipped:	10/26/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

190-220 THIRD STREET STORE LLC (Continued) **S117987466**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	38,000.00 Pounds

R240
West
1/8-1/4
0.173 mi.
916 ft.

190-220 THIRD STREET STORE LLC
214 3RD ST
BROOKLYN, NY 11215

Site 9 of 10 in cluster R

NY ENG CONTROLS **1015747246**
NY INST CONTROL **NYR000197178**
NY BROWNFIELDS
RCRA NonGen / NLR
NY MANIFEST

Relative:
Lower

Actual:
11 ft.

ENG CONTROLS:

Name:	WHOLE FOODS SITE
Address:	214 3RD ST.
City,State,Zip:	BROOKLYN, NY 11215
Site Code:	333299
HW Code:	C224100
Control Code:	15
Control Type:	ENG
Date Record Added:	07/11/2011
Date Rec Updated:	09/07/2021
Updated By:	JXPEREZM
Site Description:	"Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Lat/Long:	40:40'29 / 73:59'21
Dell:	False
Record Add:	2004-11-03 11:28:00
Record Upd:	2011-12-02 10:09:00
Updated By:	JAQUINN
Own Op:	6
Sub Type:	P03
Owner Name:	Mark Mobley
Owner Company:	190-220 Third Street Store Brooklyn NY, LLC
Owner Address:	930 Sylvan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Englewood Cliffs, NJ 07632
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Ms. Cheryl Powell
Owner Company:	New York City Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Mark Mobley
Owner Company:	190-220 Third Street Store Brooklyn NY, LLC
Owner Address:	930 Sylvan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Englewood Cliffs, NJ 07632
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Christina Minardi
Owner Company:	Whole Foods Market Group, Inc.
Owner Address:	930 Sylvan Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Englewood Cliffs, NJ 07632
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224100
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

INST CONTROL:
Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: Site Management Plan
HW Code: C224100
Control Code: 32
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: Monitoring Plan
HW Code: C224100
Control Code: 31
Control Type: INST

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "
Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Site Code: 333299
Control Name: Building Use Restriction
HW Code: C224100
Control Code: 26
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "
Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40’29 / 73:59’21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: Ground Water Use Restriction
HW Code: C224100
Control Code: 08
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "
Health Problem: "Since some contaminated soils remain at the site below clean

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40’29 / 73:59’21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: O&M Plan
HW Code: C224100
Control Code: 33
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: IC/EC Plan
HW Code: C224100
Control Code: 34
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: Landuse Restriction
HW Code: C224100
Control Code: 25
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings.

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: Environmental Easement
HW Code: C224100
Control Code: J
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

Name: WHOLE FOODS SITE
Address: 214 3RD ST.
City,State,Zip: BROOKLYN, NY 11215
Site Code: 333299
Control Name: Soil Management Plan
HW Code: C224100
Control Code: 14
Control Type: INST
Dt record added: 07/11/2011
Dt rec updated: 09/07/2021
Updated By: JXPEREZM
Site Code: 333299
Site Description: "Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'29 / 73:59'21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN
Own Op: 6
Sub Type: P03
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Ms. Cheryl Powell
Owner Company: New York City Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Mark Mobley
Owner Company: 190-220 Third Street Store Brooklyn NY, LLC
Owner Address: 930 Sylvan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Christina Minardi
Owner Company: Whole Foods Market Group, Inc.
Owner Address: 930 Sylvan Ave.
Owner Addr2: Not reported
Owner City,St,Zip: Englewood Cliffs, NJ 07632
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board #6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224100
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Waste Code: Not reported
HW Code: C224100
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2011000389393
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-11-22 14:05:00
Record Updated: 2011-11-22 14:05:00
Updated By: JXPEREZM
Crossref ID: w2-1052-05-02
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2009-04-16 14:48:00
Record Updated: 2009-04-16 14:48:00
Updated By: THKNIZEK
Crossref ID: 0501334
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-03-16 10:17:00
Record Updated: 2010-03-16 10:17:00
Updated By: jxperezm

BROWNFIELDS:

Name:	WHOLE FOODS SITE
Address:	214 3RD ST.
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	333299
Acres:	2.101
HW Code:	C224100
SWIS:	2401
Town:	New York City
Record Added Date:	11/03/2004
Record Updated Date:	06/15/2021
Update By:	GWBURKE
Site Description:	"Location: The Whole Foods site is located in the vicinity of the intersection of 3rd Street and 3rd Avenue in Kings County, NY. Site Features: The site consists of approximately 2.101-acres with a building operating as a food store and parking. The site is fenced and is bordered on the south by 4th Street Basin (Gowanus Canal), on the north by 3rd Street, on the west by privately owned real property, and on the east by 3rd Avenue. Current Zoning/Uses: The property is zoned as medium manufacturing in a commercial area. The site is currently owned by 190-220 Third Street Store, LLC and has a building operating as a food store. The surrounding parcels are currently used for a combination of mixed light industrial, commercial and residential. The closest residential area is believed

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

to be on 4th Avenue. Historical Uses: The subject site formerly consisted of several interconnected buildings and an open rear area that bordered the Gowanus Canal. The buildings prior uses that appear to have led to possible contamination include a coal yard, oil company, and junkyard and auto repair business. All buildings have been demolished. Site Geology and Hydrogeology: The Site is underlain by urban fill that varies in thickness from approximately 5 feet to 25 feet. The urban fill is underlain by an organic layer composed of varying proportions of silt and clay that varied in thickness from approximately 10 feet to 25 feet. The top of the organic layer likely represents the original surface of the Site, prior to filling in the late 1800s. The organic layer is underlain by a mixture of fine to coarse sands with increasing percentages of gravel and coarser sands with depth (coarsening downward sequence). Exploration borings were advanced to a total depth of approximately 77 feet below grade. The bedrock surface was not encountered in any of the test borings. Shallow groundwater is present in the overburden fill material beneath the Site. Groundwater is tidally influenced, but generally flows toward the 4th Street Basin in both high and low tide conditions. The groundwater level within the overburden aquifer ranges from an elevation of approximately 3 feet at the northwest boundary of the site to an elevation of approximately 8 feet in the southeast boundary of the site. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were associated with historic fill material, including semi-volatile organic compounds (specifically PAHs) and metals. Residual contamination at site will be managed in accordance with the Site Management Plan to ensure compliance with all the institutional/engineer controls required by the environmental easement. "

Health Problem: "Since some contaminated soils remain at the site below clean backfill, people will not come in contact with contaminated soils unless they dig below the surface. People are not expected to come into direct contact with contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants of concern due to vapor intrusion does not represent a current concern. Furthermore, environmental sampling indicates soil vapor intrusion is not a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40’29 / 73:59’21
Dell: False
Record Add: 2004-11-03 11:28:00
Record Upd: 2011-12-02 10:09:00
Updated By: JAQUINN

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Own Op:	6
Sub Type:	P03
Owner Name:	Mark Mobley
Owner Company:	190-220 Third Street Store Brooklyn NY, LLC
Owner Address:	930 Sylvan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Englewood Cliffs, NJ 07632
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Ms. Cheryl Powell
Owner Company:	New York City Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Mark Mobley
Owner Company:	190-220 Third Street Store Brooklyn NY, LLC
Owner Address:	930 Sylvan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Englewood Cliffs, NJ 07632
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Christina Minardi
Owner Company:	Whole Foods Market Group, Inc.
Owner Address:	930 Sylvan Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Englewood Cliffs, NJ 07632
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224100
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224100
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2011000389393
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-11-22 14:05:00
Record Updated:	2011-11-22 14:05:00
Updated By:	JXPEREZM
Crossref ID:	w2-1052-05-02
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2009-04-16 14:48:00
Record Updated:	2009-04-16 14:48:00
Updated By:	THKNIZEK
Crossref ID:	0501334
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2010-03-16 10:17:00
Record Updated:	2010-03-16 10:17:00
Updated By:	jxperezm

RCRA NonGen / NLR:

Date Form Received by Agency:	20160617
Handler Name:	190-220 THIRD STREET STORE LLC
Handler Address:	214 3RD ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYR000197178
Contact Name:	JOHN K BOGDANSKI
Contact Address:	RESEARCH PKWY
Contact City,State,Zip:	MERIDEN, CT 06450
Contact Telephone:	203-630-1406 2436
Contact Fax:	203-630-2615
Contact Email:	JBOGDANSKI@BLCOMPANIES.COM
Contact Title:	SENIOR ENVIRONMENTAL SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		3RD ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	190-22 THIRD STREET STORE LLC	
Owner Type:		Private
Operator Name:	190-22 THIRD STREET STORE LLC	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160617

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 190-22 THIRD STREET STORE LLC
Legal Status: Private
Date Became Current: 20060612
Date Ended Current: Not reported
Owner/Operator Address: 930 SYLVAN AVE
Owner/Operator City,State,Zip: ENGLEWOOD CLIFFS, NJ 07632
Owner/Operator Telephone: 201-567-2090
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 190-22 THIRD STREET STORE LLC
Legal Status: Private
Date Became Current: 20060612
Date Ended Current: Not reported
Owner/Operator Address: 930 SYLVAN AVE
Owner/Operator City,State,Zip: ENGLEWOOD CLIFFS, NJ 07632
Owner/Operator Telephone: 201-567-2090
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 190-22 THIRD STREET STORE LLC
Legal Status: Private
Date Became Current: 20060612
Date Ended Current: Not reported
Owner/Operator Address: 930 SYLVAN AVE
Owner/Operator City,State,Zip: ENGLEWOOD CLIFFS, NJ 07632
Owner/Operator Telephone: 201-567-2090
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 190-22 THIRD STREET STORE LLC
Legal Status: Private
Date Became Current: 20060612
Date Ended Current: Not reported
Owner/Operator Address: 930 SYLVAN AVE

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Owner/Operator City,State,Zip: ENGLEWOOD CLIFFS, NJ 07632
Owner/Operator Telephone: 201-567-2090
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160617
Handler Name: 190-220 THIRD STREET STORE LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120926
Handler Name: 190-220 THIRD STREET STORE LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23622
NAICS Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: 190-220 THIRD STREET STORE LLC
Address: 214 3RD ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYR000197178
Facility Status: Not reported
Location Address 1: 214 3RD STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000197178
Mailing Name: 190-220 THIRD STREET STORE LLC
Mailing Contact: 190-220 THIRD STREET STORE LLC
Mailing Address 1: 930 SYLVAN AVE
Mailing Address 2: Not reported
Mailing City: ENGLEWOOD CLIFFS
Mailing State: NJ
Mailing Zip: 07632
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2036082436

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 10/26/2012
Trans1 Recv Date: 10/26/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/26/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000197178
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 010556087JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 38000
Units: P - Pounds
Number of Containers: 1

190-220 THIRD STREET STORE LLC (Continued) **1015747246**

Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T241 **CONSOLIDATED EDISON** **NY MANIFEST** **1009238380**
NNE **V5491-633 SACKETT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.175 mi.
923 ft. **Site 2 of 3 in cluster T**

Relative:
Higher

Actual:
24 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	V5491-633 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004047791
Facility Status:	Not reported
Location Address 1:	V5491-633 SACKETT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004047791
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

U242 **JORDAN MALACHIE CLEANERS** **RCRA-VSQG** **1004761499**
SE **295 5TH AVE** **FINDS** **NYR000087486**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.175 mi. **NY MANIFEST**
925 ft. **Site 2 of 12 in cluster U**

Relative: **Higher**
Actual: **47 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	JORDAN MALACHIE CLEANERS	
Handler Address:		295 5TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000087486
Contact Name:		OSCAR HIDALGO
Contact Address:		5TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-230-3461
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		5TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	OSCAR HIDALGO	
Owner Type:		Private
Operator Name:	OSCAR HIDALGO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

JORDAN MALACHIE CLEANERS (Continued) **1004761499**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

JORDAN MALACHIE CLEANERS (Continued) **1004761499**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OSCAR HIDALGO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	295 5TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-230-3461
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: OSCAR HIDALGO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	295 5TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-230-3461
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: OSCAR HIDALGO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	295 5TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-230-3461
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: JORDAN MALACHIE CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: JORDAN MALACHIE CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

JORDAN MALACHIE CLEANERS (Continued) **1004761499**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000627
Handler Name: JORDAN MALACHIE CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004563071

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004761499
Registry ID: 110004563071
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004563071
Name: JORDAN MALACHIE CLEANERS
Address: 295 5TH AVE
City,State,Zip: BROOKLYN, NY 11215

JORDAN MALACHIE CLEANERS (Continued) **1004761499**

NY MANIFEST:

Name:	JORDAN MALACHIE CLNRS
Address:	295 5TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000087486
Facility Status:	Not reported
Location Address 1:	279 5TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000087486
Mailing Name:	JORDAN MALACHIE CLNRS
Mailing Contact:	OSCAR HIDALGO
Mailing Address 1:	279 5TH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182303461

U243 **MALACHI DRY CLNR** **NY DRYCLEANERS** **S110247207**
SE **279 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.177 mi.
932 ft. **Site 3 of 12 in cluster U**

Relative:
Higher

Actual:
50 ft.

DRYCLEANERS:

Name:	MALACHI DRY CLNR
Address:	279 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Facility ID:	2-6103-00538
Phone Number:	718-499-8420
Region:	Not reported
Registration Effective Date:	5-Jul-11
Inspection Date:	2017-06-09 00:00:00
Install Date:	99/09
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

U244 **JET FRENCH CLEANERS** **RCRA NonGen / NLR** **1004759636**
SE **279 5TH AVE** **NY MANIFEST** **NYR000016402**
1/8-1/4 **BROOKLYN, NY 11215**
0.177 mi.
932 ft. **Site 4 of 12 in cluster U**

Relative: **Higher**
Actual: **50 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	JET FRENCH CLEANERS	
Handler Address:		279 5TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000016402
Contact Name:		SAMET-AHARY ABDULKADER EL
Contact Address:		5TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-499-4353
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		5TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	JET FRENCH CLEANERS	
Owner Type:		Private
Operator Name:	JET FRENCH CLEANERS	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

JET FRENCH CLEANERS (Continued) **1004759636**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JET FRENCH CLEANERS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	279 5TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-499-4353
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JET FRENCH CLEANERS (Continued) **1004759636**

Owner/Operator Indicator: Operator
Owner/Operator Name: JET FRENCH CLEANERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 279 5TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-499-4353
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JET FRENCH CLEANERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 279 5TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-499-4353
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: JET FRENCH CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: JET FRENCH CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19951120
Handler Name: JET FRENCH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

JET FRENCH CLEANERS (Continued) **1004759636**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	JET FRENCH CLNRS
Address:	279 5TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000016402
Facility Status:	Not reported
Location Address 1:	279 5TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000016402
Mailing Name:	JET FRENCH CLNRS
Mailing Contact:	A ELSAMET
Mailing Address 1:	279 5TH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184994353

Z245 **BRIDGE FORD** **RCRA NonGen / NLR** **1000106506**
SSW **343 4TH AVE** **FINDS** **NYD982280091**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.179 mi.
943 ft. **Site 1 of 9 in cluster Z**

Relative: **Higher**

Actual: **26 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	BRIDGE FORD	
Handler Address:		343 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215-2717
EPA ID:		NYD982280091
Contact Name:		Not reported
Contact Address:		4TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	BRIDGE FORD INC	
Owner Type:		Private
Operator Name:	BRIDGE FORD INC	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

BRIDGE FORD (Continued) **1000106506**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: BRIDGE FORD INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	343 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-369-0788
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: BRIDGE FORD INC	
Legal Status:	Private
Date Became Current:	Not reported

BRIDGE FORD (Continued) **1000106506**

Date Ended Current:	Not reported
Owner/Operator Address:	343 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-369-0788
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: BRIDGE FORD INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	343 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-369-0788
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: BRIDGE FORD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: BRIDGE FORD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: BRIDGE FORD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

BRIDGE FORD (Continued) **1000106506**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940217
Handler Name: BRIDGE FORD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported

BRIDGE FORD (Continued) **1000106506**

Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19980920
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MD
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004419745

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000106506
Registry ID: 110004419745
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004419745
Name: BRIDGE FORD
Address: 343 4TH AVE
City,State,Zip: BROOKLYN, NY 11215

Z246 **343 4TH AVENUE** **NY UST** **U004045443**
SSW **343 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.179 mi.
943 ft. **Site 2 of 9 in cluster Z**

Relative:
Higher

Actual:
26 ft.

UST:
Name: 343 4TH AVENUE
Address: 343 4TH AVENUE
City,State,Zip: BROOKLYN, NY 11215
Id/Status: 2-608144 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585678.46372
UTM Y: 4502949.62354

343 4TH AVENUE (Continued) **U004045443**

Site Type: Other

Affiliation Records:

Site Id: 29996
Affiliation Type: Facility Operator
Company Name: 343 4TH AVENUE
Contact Type: Not reported
Contact Name: BRANDON WEESHLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 230-2600
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-09-15

Site Id: 29996
Affiliation Type: Emergency Contact
Company Name: NOVO CONDOMINIUM
Contact Type: Not reported
Contact Name: BRANDON WEESHLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 230-2600
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-09-15

Site Id: 29996
Affiliation Type: Facility Owner
Company Name: NOVO CONDOMINIUM
Contact Type: OFFICE MGR
Contact Name: JESSE WILCOX
Address1: C.O. GOLDIN MGMT 25 8TH AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (718) 230-2600
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-09-15

Site Id: 29996
Affiliation Type: Mail Contact
Company Name: NOVO CONDOMINIUM
Contact Type: OFFICE MGR

343 4TH AVENUE (Continued) **U004045443**

Contact Name:	JESSE WILCOX
Address1:	C.O. GOLDIN MGMT 25 8TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 230-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-09-15

Tank Info:

Tank Number:	001
Tank ID:	64663
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	64664
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

343 4TH AVENUE (Continued) **U004045443**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 003
Tank ID: 64665
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 12/01/2002
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 004
Tank ID: 64666
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use

343 4TH AVENUE (Continued) **U004045443**

Capacity Gallons:	275
Install Date:	12/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	005
Tank ID:	64667
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	275
Install Date:	12/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

343 4TH AVENUE (Continued) **U004045443**

Tank Number:	006
Tank ID:	64668
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	275
Install Date:	12/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	007
Tank ID:	64669
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	275
Install Date:	12/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

343 4TH AVENUE (Continued) **U004045443**

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

R247 **ALL BORO'S** **NY LTANKS** **S102618894**
West **200 3RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.180 mi.
950 ft. **Site 10 of 10 in cluster R**

Relative: LTANKS:
Lower

Actual:
10 ft.

Name:	ALL BORO'S
Address:	200 3RD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702117 / 1999-08-22
Facility ID:	9702117
Site ID:	253671
Spill Date:	1997-05-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-05-19
CID:	312
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-19
Spill Record Last Update:	2002-02-13
Spiller Name:	MIKE DENICOLA
Spiller Company:	ALL BORO'S
Spiller Address:	200 3RD ST
Spiller County:	001
Spiller Contact:	MIKE DENICOLA
Spiller Phone:	(718) 858-7600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	207790
DEC Memo:	""
Remarks:	"AIR PRESSURE TEST TO 10 LBS - TANK FAILED - NO LEAK"

All TTF:

Facility ID:	9702117
Spill Number:	9702117
Spill Tank Test:	1545120
Site ID:	253671
Tank Number:	001
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

ALL BORO'S (Continued) **S102618894**

Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

AA248 **CON EDISON** **NY MANIFEST** **S119075356**
SSE **354 3RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.180 mi.
950 ft. **Site 1 of 5 in cluster AA**

Relative:
Higher

Actual:
41 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	354 3RD ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004783759
Facility Status:	Not reported
Location Address 1:	FO 345 3RD ST
Code:	BP
Location Address 2:	SB 45297
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004783759
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/18/2015
Trans1 Recv Date:	05/18/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004783759

CON EDISON (Continued) **S119075356**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014467684JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA249 **CON EDISON** **RCRA NonGen / NLR** **1019903291**
SSE **354 3RD ST** **NYP004783759**
1/8-1/4 **BROOKLYN, NY 11215**
0.180 mi.
950 ft. **Site 2 of 5 in cluster AA**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:		20150518
Handler Name:	CON EDISON	
Handler Address:		354 3RD ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004783759
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

Actual:
41 ft.

CON EDISON (Continued) **1019903291**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

CON EDISON (Continued) **1019903291**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150518
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150518
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AA250 **CON EDISON** **NJ MANIFEST** **S120671879**
SSE **354 3RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.180 mi.
950 ft. **Site 3 of 5 in cluster AA**

Relative:
Higher

Actual:
41 ft.

NJ MANIFEST:

EPA Id:	NYP004783759
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014467684JJK
EPA ID:	NYP004783759
Date Shipped:	5/18/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120671879**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

W251 **CON EDISON - SERVICE BOX 31652** **RCRA-LQG** **1024891092**
NW **484 PRESIDENT ST** **NYP005072996**
1/8-1/4 **BROOKLYN, NY 11215**
0.182 mi.
959 ft. **Site 7 of 11 in cluster W**

Relative: RCRA-LQG:
Lower

Actual: Date Form Received by Agency:		20180410
12 ft. Handler Name:	CON EDISON - SERVICE BOX 31652	
Handler Address:		484 PRESIDENT ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP005072996
Contact Name:		ALYSSA SOTTO
Contact Address:		IRVING PLACE, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-2757
Contact Fax:		Not reported
Contact Email:		SOTTOA@CONED.COM
Contact Title:		ASSOCIATE SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2017
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	
Owner Type:		Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON - SERVICE BOX 31652 (Continued) **1024891092**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170428
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE

CON EDISON - SERVICE BOX 31652 (Continued) **1024891092**

Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170428
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX 31652
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

W252 **CON EDISON - SERVICE BOX 31652** **NY MANIFEST** **S121968007**
NW **484 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.182 mi.
959 ft. **Site 8 of 11 in cluster W**

Relative: NY MANIFEST:
Lower
Name: CON EDISON - SERVICE BOX 31652
Actual: Address: 484 PRESIDENT ST
12 ft. City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP005072996
Facility Status: Not reported

CON EDISON - SERVICE BOX 31652 (Continued) **S121968007**

Location Address 1: 484 PRESIDENT ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005072996
Mailing Name: CON EDISON - SERVICE BOX 31652
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Z253 **BROOKLYN IGNITION & SUPPLY** **RCRA NonGen / NLR** **1000890011**
SSW **370 4TH AVE** **FINDS** **NY0000228106**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.183 mi. **NY MANIFEST**
966 ft. **Site 3 of 9 in cluster Z**

Relative: **Higher**

Actual: **23 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: BROOKLYN IGNITION & SUPPLY
Handler Address: 370 4TH AVE
Handler City,State,Zip: BROOKLYN, NY 11215-2718
EPA ID: NY0000228106
Contact Name: Not reported
Contact Address: 4TH AVE
Contact City,State,Zip: BROOKLYN, NY 11215
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: 4TH AVE
Mailing City,State,Zip: BROOKLYN, NY 11215
Owner Name: 370 4TH AVE CORP
Owner Type: Private
Operator Name: 370 4TH AVE CORP
Operator Type: Private
Short-Term Generator Activity: No

BROOKLYN IGNITION & SUPPLY (Continued) **1000890011**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

BROOKLYN IGNITION & SUPPLY (Continued) **1000890011**

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D018
Waste Description: BENZENE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 370 4TH AVE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 4TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-834-5300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 370 4TH AVE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 4TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-834-5300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 370 4TH AVE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 4TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-834-5300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: BROOKLYN IGNITION & SUPPLY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

BROOKLYN IGNITION & SUPPLY (Continued) **1000890011**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: BROOKLYN IGNITION & SUPPLY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BROOKLYN IGNITION & SUPPLY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940418
Handler Name: BROOKLYN IGNITION & SUPPLY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported

BROOKLYN IGNITION & SUPPLY (Continued) **1000890011**

Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19980920
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004314037

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

BROOKLYN IGNITION & SUPPLY (Continued) **1000890011**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000890011
Registry ID:	110004314037
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004314037
Name:	BROOKLYN IGNITION & SUPPLY
Address:	370 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	BROOKLYN IGNITION & SUPPLY
Address:	370 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215-2718
Country:	USA
EPA ID:	NY0000228106
Facility Status:	Not reported
Location Address 1:	370 4TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000228106
Mailing Name:	BROOKLYN IGNITION & SUPPLY
Mailing Contact:	BROOKLYN IGNITION & SUPPLY
Mailing Address 1:	370 4TH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188345300

AB254 **CON EDISON** **NY MANIFEST** **S117537840**
NE **688 SACKET ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.185 mi.
975 ft. **Site 1 of 3 in cluster AB**

Relative:
Higher

Actual:
31 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	688 SACKET ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004704458
Facility Status:	Not reported
Location Address 1:	688 SACKET ST
Code:	BP
Location Address 2:	SB44230

CON EDISON (Continued) **S117537840**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004704458
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/09/2014
Trans1 Recv Date:	12/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004704458
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417059GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON (Continued) **S117537840**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB255 **CON EDISON** **NY MANIFEST** **S117316060**
NE **688 SACKETT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.185 mi.
975 ft. **Site 2 of 3 in cluster AB**

Relative:
Higher

Actual:
31 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	688 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004707279
Facility Status:	Not reported
Location Address 1:	688 SACKETT ST
Code:	BP
Location Address 2:	SB44230
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004707279
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/16/2014
Trans1 Recv Date:	12/16/2014
Trans2 Recv Date:	12/28/2014
TSD Site Recv Date:	12/29/2014

CON EDISON (Continued) **S117316060**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004707279
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002424338GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	688 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004632907
Facility Status:	Not reported
Location Address 1:	688 SACKETT ST
Code:	BP
Location Address 2:	SB 44230
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004632907
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **S117316060**

Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/2014
Trans1 Recv Date:	08/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004632907
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013254177JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117316060**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AB256 **CON EDISON** **NY MANIFEST** **S117319232**
NE **688 SACKETT ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.185 mi.
975 ft. **Site 3 of 3 in cluster AB**

Relative: **Higher**

Actual: **31 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	688 SACKETT ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004669222
Facility Status:	Not reported
Location Address 1:	688 SACKETT ST
Code:	BP
Location Address 2:	STRUCTURE # 44230
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004669222
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/2014
Trans1 Recv Date:	09/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004669222
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617302GBF
Import Indicator:	N

CON EDISON (Continued) **S117319232**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC257 **CON EDISON SERVICE BOX: 45289** **RCRA NonGen / NLR** **1016974107**
West **198 3RD ST** **NY MANIFEST** **NYP004479184**
1/8-1/4 **BROOKLYN, NY 11215**
0.185 mi.
976 ft. **Site 1 of 10 in cluster AC**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20140426
Handler Name:	CON EDISON SERVICE BOX:	45289
Handler Address:		198 3RD ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004479184
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2

CON EDISON SERVICE BOX: 45289 (Continued) **1016974107**

Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20141014
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No

CON EDISON SERVICE BOX: 45289 (Continued) **1016974107**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20140326
Handler Name: CON EDISON SERVICE BOX: 45289
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140426
Handler Name: CON EDISON SERVICE BOX: 45289
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 198 3RD ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004479184
Facility Status: Not reported
Location Address 1: 187 3 ST
Code: BP
Location Address 2: SB45289
Total Tanks: Not reported
Location City: BROOKLYN

CON EDISON SERVICE BOX: 45289 (Continued) **1016974107**

Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004479184
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/26/2014
Trans1 Recv Date: 03/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004479184
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012354426JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON SERVICE BOX: 45289 (Continued) **1016974107**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z258 **SUSAN MAINTENANCE CORP.** **NY UST** **U004277379**
SSW **374 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.187 mi.
989 ft. **Site 4 of 9 in cluster Z**

Relative:
Higher

Actual:
25 ft.

UST:

Name:	SUSAN MAINTENANCE CORP.
Address:	374 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-611328 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/03/2022
UTM X:	585619.74749
UTM Y:	4502931.85654
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	434059
Affiliation Type:	Facility Operator
Company Name:	SUSAN MAINTENANCE CORP
Contact Type:	Not reported
Contact Name:	D J SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 222-4040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-04-27

Site Id:	434059
Affiliation Type:	Emergency Contact
Company Name:	SUSAN F. LAMMEY
Contact Type:	Not reported
Contact Name:	D J SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

SUSAN MAINTENANCE CORP. (Continued) **U004277379**

Phone:	(718) 222-4040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-04-27

Site Id:	434059
Affiliation Type:	Mail Contact
Company Name:	SUSAN MAINT. CORP.
Contact Type:	Not reported
Contact Name:	D SINGH
Address1:	374 4TH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(212) 860-3110
EMail:	D.JTAXI1@AOL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-23

Site Id:	434059
Affiliation Type:	Facility Owner
Company Name:	374 4TH AVE. LLC CORP.
Contact Type:	MANAGER
Contact Name:	D J SINGH
Address1:	374 4TH AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 222-4040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-23

Tank Info:

Tank Number:	005
Tank ID:	234102
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	11/01/1998
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Stainless steel alloy
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported

SUSAN MAINTENANCE CORP. (Continued) **U004277379**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J02 - Dispenser - Suction Dispenser
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I01 - Overfill - Float Vent Valve
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
B99 - Tank External Protection - Other

Z259 **SUSAN MAINTENANCE** **RCRA-SQG** **1001493708**
SSW **374 4TH AVE** **FINDS** **NYR000076091**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.187 mi. **NJ MANIFEST**
989 ft. **Site 5 of 9 in cluster Z** **NY MANIFEST**

Relative:
Higher

Actual:
25 ft.

RCRA-SQG:

Date Form Received by Agency:		20070101
Handler Name:	SUSAN MAINTENANCE	
Handler Address:		374 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000076091
Contact Name:		DONNA FURNISH
Contact Address:		4TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-222-4040
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	370 4TH AVENUE CORP	
Owner Type:		Private
Operator Name:	370 4TH AVENUE CORP	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

SUSAN MAINTENANCE (Continued) **1001493708**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

SUSAN MAINTENANCE (Continued) **1001493708**

Waste Code: D018
Waste Description: BENZENE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 370 4TH AVENUE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 286 SPRING ST SUITE 303
Owner/Operator City,State,Zip: NEW YORK, NY 10013
Owner/Operator Telephone: 212-645-6145
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 370 4TH AVENUE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 286 SPRING ST SUITE 303
Owner/Operator City,State,Zip: NEW YORK, NY 10013
Owner/Operator Telephone: 212-645-6145
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 370 4TH AVENUE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 286 SPRING ST SUITE 303
Owner/Operator City,State,Zip: NEW YORK, NY 10013
Owner/Operator Telephone: 212-645-6145
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SUSAN MAINTENANCE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

SUSAN MAINTENANCE (Continued) **1001493708**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SUSAN MAINTENANCE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990902
Handler Name: SUSAN MAINTENANCE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004556016

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

SUSAN MAINTENANCE (Continued) **1001493708**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001493708
Registry ID:	110004556016
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004556016
Name:	SUSAN MAINTENANCE
Address:	374 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215

NJ MANIFEST:

EPA Id:	NYR000076091
Mail Address:	4TH AVE
Mail City/State/Zip:	BROOKLYN, NY 11215
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONNA FURNISH
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001154278SKS
EPA ID:	NYR000076091
Date Shipped:	06/04/2008
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/04/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/09/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	24 G

Manifest Number:	000814881SKS
EPA ID:	NYR000076091
Date Shipped:	08/06/2007
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/06/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/13/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H14
Quantity: 12 G

Manifest Number: 001190789SKS
EPA ID: NYR000076091
Date Shipped: 04/24/2008
TSDF EPA ID: NJD982270506
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 04/24/2008
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 04/27/2008
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 27 G

SUSAN MAINTENANCE (Continued) **1001493708**

Manifest Number:	000266235CEX
EPA ID:	NYR000076091
Date Shipped:	10/19/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/19/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/22/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	26 G

Manifest Number:	002231617SKS
EPA ID:	NYR000076091
Date Shipped:	02/25/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/25/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/01/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H020
Quantity:	26 G

Manifest Number:	000450811SKS
EPA ID:	NYR000076091
Date Shipped:	06/27/2007
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/27/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/03/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H14
Quantity:	25 G

Manifest Number:	001119894SKS
EPA ID:	NYR000076091
Date Shipped:	07/14/2008
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/14/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/16/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	15 G

Manifest Number:	002076267SKS
EPA ID:	NYR000076091
Date Shipped:	07/28/2009
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 27 G

Manifest Number: 000394830SKS
EPA ID: NYR000076091
Date Shipped: 02/20/2007
TSDF EPA ID: NJD982270506
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 02/20/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 02/25/2007
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H14
Quantity: 25 G

Manifest Number: 002442521SKS
EPA ID: NYR000076091

SUSAN MAINTENANCE (Continued) **1001493708**

Date Shipped:	07/12/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/12/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H020
Quantity:	30 G

Manifest Number:	000945623SKS
EPA ID:	NYR000076091
Date Shipped:	12/11/2007
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/11/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/18/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	003638414FLE
EPA ID:	NYR000076091
Date Shipped:	1/4/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H020
Quantity:	30.00 gallons

Manifest Number:	002426698SKS
EPA ID:	NYR000076091
Date Shipped:	04/13/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/13/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H020
Quantity: 25 G

Manifest Number: 000923570SKS
EPA ID: NYR000076091
Date Shipped: 03/12/2008
TSDF EPA ID: NJD982270506
Transporter EPA ID: TXR000050930
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 03/12/2008
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 03/17/2008
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 28 G

SUSAN MAINTENANCE (Continued) **1001493708**

Manifest Number:	002593643SKS
EPA ID:	NYR000076091
Date Shipped:	3/30/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H020
Quantity:	30.00 gallons

Manifest Number:	001149409SKS
EPA ID:	NYR000076091
Date Shipped:	08/26/2008
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/26/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/28/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	26 G

Manifest Number:	001447672SKS
EPA ID:	NYR000076091
Date Shipped:	10/08/2008
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/08/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/13/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	27 G

Manifest Number:	004273568FLE
EPA ID:	NYR000076091
Date Shipped:	10/07/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/07/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/11/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H020
Quantity:	30 G

Manifest Number:	000789734SKS
EPA ID:	NYR000076091
Date Shipped:	09/17/2007
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/17/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/24/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Manifest Number:	001444746SKS
EPA ID:	NYR000076091
Date Shipped:	11/20/2008
TSDF EPA ID:	NJD982270506
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/20/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/25/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	26 G

NY MANIFEST:

Name:	SUSAN MAINTENANCE
Address:	374 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000076091
Facility Status:	Not reported
Location Address 1:	374 4TH AVE

SUSAN MAINTENANCE (Continued) **1001493708**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000076091
Mailing Name:	SUSAN MAINTENANCE
Mailing Contact:	RAFAEL MOREL
Mailing Address 1:	374 4TH AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182224040

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2007
Trans1 Recv Date:	12/11/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/18/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000076091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD982270506
TSDF ID 2:	Not reported
Manifest Tracking Number:	000945623SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

SUSAN MAINTENANCE (Continued) **1001493708**

Quantity:	22
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D018
Waste Code 1_3:	D039
Waste Code 1_4:	D040
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z260 **374 4TH AVENUE** **NY VCP** **S128587696**
SSW **374 4TH AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.187 mi.
989 ft. **Site 6 of 9 in cluster Z**

Relative: VCP NYC:
Higher

Project ID:	22TMP0010K,22CVCP031K,22EHAN150K
Name:	374 4TH AVENUE
Address:	374 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3009800077
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.672941
Longitude:	-73.986579
Postcode:	6
Community Board:	39
Council District:	119
Census Tract:	3021051
BIN:	3009800077
NTA:	Park Slope-Gowanus

Actual:
25 ft.

Z261 **SUSAN MAINTENANCE CORP.** **NY AST** **A100350449**
SSW **374 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.187 mi.
989 ft. **Site 7 of 9 in cluster Z**

Relative: AST:
Higher

Name:	SUSAN MAINTENANCE CORP.
Address:	374 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611328
Program Type:	PBS
UTM X:	585619.74749
UTM Y:	4502931.85654
Expiration Date:	01/03/2022

Actual:
25 ft.

SUSAN MAINTENANCE CORP. (Continued) **A100350449**

Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 434059
Affiliation Type: Facility Operator
Company Name: SUSAN MAINTENANCE CORP
Contact Type: Not reported
Contact Name: D J SINGH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 222-4040
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2010-04-27

Site Id: 434059
Affiliation Type: Emergency Contact
Company Name: SUSAN F. LAMMEY
Contact Type: Not reported
Contact Name: D J SINGH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 222-4040
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2010-04-27

Site Id: 434059
Affiliation Type: Mail Contact
Company Name: SUSAN MAINT. CORP.
Contact Type: Not reported
Contact Name: D SINGH
Address1: 374 4TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (212) 860-3110
EMail: D.JTAXI1@AOL.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-02-23

Site Id: 434059
Affiliation Type: Facility Owner
Company Name: 374 4TH AVE. LLC CORP.
Contact Type: MANAGER

SUSAN MAINTENANCE CORP. (Continued) **A100350449**

Contact Name:	D J SINGH
Address1:	374 4TH AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 222-4040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-23

Tank Info:

Tank Number:	001
Tank Id:	234098
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

	J02 - Dispenser - Suction Dispenser F00 - Pipe External Protection - None G01 - Tank Secondary Containment - Diking (Aboveground) H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G) L00 - Piping Leak Detection - None A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating K00 - Spill Prevention - None E00 - Piping Secondary Containment - None C01 - Pipe Location - Aboveground I04 - Overfill - Product Level Gauge (A/G) D03 - Pipe Type - Stainless Steel Alloy
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1998
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil

Tank Number:	002
Tank Id:	234099
Material Code:	0015
Common Name of Substance:	Motor Oil

SUSAN MAINTENANCE CORP. (Continued) **A100350449**

Equipment Records:
D03 - Pipe Type - Stainless Steel Alloy
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1998
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil
Tank Number:	003
Tank Id:	234100
Material Code:	0021
Common Name of Substance:	Transmission Fluid

Equipment Records:
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D03 - Pipe Type - Stainless Steel Alloy
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1998
Capacity Gallons:	275
Tightness Test Method:	-

SUSAN MAINTENANCE CORP. (Continued) **A100350449**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	transmission fluid
Tank Number:	004
Tank Id:	234101
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

D03 - Pipe Type - Stainless Steel Alloy
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1998
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

U262 **CON EDISON** **NY MANIFEST** **S117066554**
SE **318 1 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.191 mi.
1009 ft. **Site 5 of 12 in cluster U**

Relative: **Higher**
Actual: **53 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	318 1 ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004592192
Facility Status:	Not reported
Location Address 1:	318 1 ST

CON EDISON (Continued) **S117066554**

Code:	BP
Location Address 2:	STRUCTURE 38707
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004592192
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004592192
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503777GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117066554**

Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S263 **MATTHEWS INTERNATIONAL CASKET DIV** **RCRA NonGen / NLR** **1018158807**
NNW **585 UNION ST** **NYN008027997**
1/8-1/4 **BROOKLYN, NY 11215**
0.192 mi.
1016 ft. **Site 6 of 6 in cluster S**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		20150811
15 ft. Handler Name:	MATTHEWS INTERNATIONAL CASKET DIV	
Handler Address:		585 UNION ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYN008027997
Contact Name:		CHRISTOPHER ZANETAKOS
Contact Address:		UNION ST
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-852-6606
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		MGR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		UNION ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

MATTHEWS INTERNATIONAL CASKET DIV (Continued) **1018158807**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150811
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150811
Handler Name:	MATTHEWS INTERNATIONAL CASKET DIV
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

MATTHEWS INTERNATIONAL CASKET DIV (Continued) **1018158807**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20150806
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2STP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported

MATTHEWS INTERNATIONAL CASKET DIV (Continued) **1018158807**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

X264 **SEMPLE RIEGER CO** **RCRA NonGen / NLR** **1000347934**
NNE **635 SACKETT ST** **FINDS** **NYD986891885**
1/8-1/4 **BROOKLYN, NY 11217** **ECHO**
0.194 mi. **NY MANIFEST**
1022 ft. **Site 2 of 2 in cluster X**

Relative: **Higher**
Actual: **24 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	SEMPLE RIEGER CO	
Handler Address:		635 SACKETT ST
Handler City,State,Zip:		BROOKLYN, NY 11217-3196
EPA ID:		NYD986891885
Contact Name:		Not reported
Contact Address:		SACKETT ST
Contact City,State,Zip:		BROOKLYN, NY 11217
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		SACKETT ST
Mailing City,State,Zip:		BROOKLYN, NY 11217
Owner Name:	SEMPLE RIEGER CO	
Owner Type:		Private
Operator Name:	SEMPLE RIEGER CO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N

SEMPLE RIEGER CO (Continued) **1000347934**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: SEMPLE RIEGER CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

SEMPLE RIEGER CO (Continued) **1000347934**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SEMPLE RIEGER CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SEMPLE RIEGER CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: SEMPLE RIEGER CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SEMPLE RIEGER CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SEMPLE RIEGER CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY

SEMPLE RIEGER CO (Continued) **1000347934**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900216
Handler Name: SEMPLE RIEGER CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

SEMPLE RIEGER CO (Continued) **1000347934**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19980920
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004443273

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000347934
Registry ID:	110004443273
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004443273
Name:	SEMPLE RIEGER CO
Address:	635 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11217

NY MANIFEST:

Name:	SEMPLE RIEGER CO
Address:	635 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11217-3196
Country:	USA
EPA ID:	NYD986891885
Facility Status:	Not reported

SEMPLE RIEGER CO (Continued) **1000347934**

Location Address 1: 635 SACKETT ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986891885
Mailing Name: SEMPLE RIEGER CO
Mailing Contact: SEMPLE RIEGER CO
Mailing Address 1: 635 SACKETT STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11217
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7188553161

U265 **32 UNIT 4 STORY WALK UP** **NY AST** **U003388517**
ESE **325 1ST STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.194 mi.
1025 ft. **Site 6 of 12 in cluster U**

Relative:
Higher

Actual:
56 ft.

AST:
Name: 32 UNIT 4 STORY WALK UP
Address: 325 1ST STREET
City,State,Zip: BROOKLYN, NY 11215
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-252794
Program Type: PBS
UTM X: 586065.03594
UTM Y: 4503049.19770
Expiration Date: 05/02/2023
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 10203
Affiliation Type: Mail Contact
Company Name: GNM MANAGEMENT LLC
Contact Type: Not reported
Contact Name: GEORGE N. MALAFIS
Address1: 148 22ND STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 788-4907
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR

32 UNIT 4 STORY WALK UP (Continued) **U003388517**

Date Last Modified: 2018-02-27

Site Id: 10203
Affiliation Type: Facility Operator
Company Name: 32 UNIT 4 STORY WALK UP
Contact Type: Not reported
Contact Name: GEORGE N. MALAFIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 788-4907
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10203
Affiliation Type: Emergency Contact
Company Name: 325 1ST STREET APTS LLC
Contact Type: Not reported
Contact Name: GEORGE N. MALAFIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 748-5308
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-02-27

Site Id: 10203
Affiliation Type: Facility Owner
Company Name: 325 1ST STREET APTS LLC
Contact Type: MEMBER
Contact Name: GEORGE N. MALAFIS
Address1: P.O. BOX 150610
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215-0610
Country Code: 001
Phone: (718) 788-4907
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-02-27

Tank Info:

Tank Number: 001
Tank Id: 14170

32 UNIT 4 STORY WALK UP (Continued) **U003388517**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B99 - Tank External Protection - Other
I05 - Overfill - Vent Whistle

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/26/1983
Capacity Gallons: 4000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

U266 **CON EDISON** **RCRA NonGen / NLR** **1019906687**
SE **365 2ND ST** **FINDS** **NYP004825176**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.195 mi.
1030 ft. **Site 7 of 12 in cluster U**

Relative: **Higher**
Actual: **51 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150817
Handler Name:	CON EDISON	
Handler Address:		365 2ND ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004825176
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported

CON EDISON (Continued) **1019906687**

Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909

CON EDISON (Continued) **1019906687**

Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150817
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150817
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069668443

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CON EDISON (Continued) **1019906687**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906687
Registry ID:	110069668443
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069668443
Name:	CON EDISON
Address:	365 2ND ST
City,State,Zip:	BROOKLYN, NY 11215

U267 **CON EDISON** **NJ MANIFEST** **S120675483**
SE **365 2ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.195 mi.
1030 ft. **Site 8 of 12 in cluster U**

Relative:
Higher

Actual:
51 ft.

NJ MANIFEST:

EPA Id:	NYP004825176
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612908GBF
EPA ID:	NYP004825176
Date Shipped:	8/17/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

CON EDISON (Continued) **S120675483**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

U268 **CON ED** **NY MANIFEST** **S118259038**
SE **365 2ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.195 mi.
1030 ft. **Site 9 of 12 in cluster U**

Relative: **Higher**

Actual: **51 ft.**

NY MANIFEST:

Name:	CON ED
Address:	365 2ND ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004825176
Facility Status:	Not reported
Location Address 1:	365 2ND ST
Code:	BP
Location Address 2:	SB 38854
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004825176
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON ED (Continued) **S118259038**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2015
Trans1 Recv Date:	08/17/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004825176
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612908GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V269 **640 CARROLL LLC** **NY AST** **A100292625**
ESE **640 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.197 mi.
1042 ft. **Site 2 of 2 in cluster V**

Relative:
Higher

Actual:
58 ft.

AST:

Name:	640 CARROLL LLC
Address:	640 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608751
Program Type:	PBS
UTM X:	586132.04731
UTM Y:	4503164.03777
Expiration Date:	04/02/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30602
Affiliation Type:	Facility Operator
Company Name:	640 CARROLL LLC
Contact Type:	Not reported
Contact Name:	JOSE PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 857-1260
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-28

Site Id:	30602
Affiliation Type:	Emergency Contact
Company Name:	640 CARROLL LLC
Contact Type:	Not reported
Contact Name:	JOSE PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 857-1260
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-28

Site Id:	30602
Affiliation Type:	Facility Owner
Company Name:	640 CARROLL LLC
Contact Type:	MANAGER
Contact Name:	CESAR HIDALGO

640 CARROLL LLC (Continued) **A100292625**

Address1:	57 FIFTH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 857-1260
EMail:	CDALGO@AOL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-28

Site Id:	30602
Affiliation Type:	Mail Contact
Company Name:	640 CARROLL LLC
Contact Type:	MANAGER
Contact Name:	CESAR HIDALGO
Address1:	57 FIFTH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 857-1260
EMail:	CDALGO@AOL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-28

Tank Info:

Tank Number:	001
Tank Id:	65599
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/10/2002
Capacity Gallons:	4000

640 CARROLL LLC (Continued) **A100292625**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Z270 **CON EDISON SERVICE BOX: 16194** **RCRA NonGen / NLR** **1016677230**
SSW **209 5TH ST OPPOSITE N** **FINDS** **NYP004307930**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.199 mi. **NY MANIFEST**
1053 ft. **Site 8 of 9 in cluster Z**

Relative: **Higher**

Actual: **26 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130607
Handler Name:	CON EDISON SERVICE BOX:	16194
Handler Address:		209 5TH ST OPPOSITE N
Handler City,State,Zip:		BROOKLYN, NY 11211
EPA ID:		NYP004307930
Contact Name:		ANTHONY SIGNORE
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4714
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		GENERAL UTILITY WORKER L1-2
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 16194 (Continued) **1016677230**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130507
Handler Name: CON EDISON SERVICE BOX:	16194
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130607

CON EDISON SERVICE BOX: 16194 (Continued) **1016677230**

Handler Name: CON EDISON SERVICE BOX: 16194
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058878763

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677230
Registry ID: 110058878763
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058878763
Name: CON EDISON SERVICE BOX: 16194
Address: 209 5TH ST OPPOSITE N
City,State,Zip: BROOKLYN, NY 11211

NY MANIFEST:
Name: CON EDISON
Address: 209 5TH ST OPPOSITE N
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYP004307930
Facility Status: Not reported
Location Address 1: OPP 209 N 5TH ST
Code: BP
Location Address 2: SERV BOX 16194

CON EDISON SERVICE BOX: 16194 (Continued) **1016677230**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004307930
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/2013
Trans1 Recv Date:	05/07/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307930
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017580GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON SERVICE BOX: 16194 (Continued) **1016677230**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T271 **617 SACKETT STREET REALTY CORP.** **NY UST** **U000394275**
NNE **617 SACKETT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.200 mi.
1057 ft. **Site 3 of 3 in cluster T**

Relative:
Lower

Actual:
22 ft.

UST:

Name:	617 SACKETT STREET REALTY CORP.
Address:	617 SACKETT STREET
City,State,Zip:	BROOKLYN, NY 11217
Id/Status:	2-069299 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/10/1997
UTM X:	585880.04087
UTM Y:	4503578.49138
Site Type:	Other

Affiliation Records:

Site Id:	1465
Affiliation Type:	Facility Owner
Company Name:	617 SACKETT STREET REALTY CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	617 SACKETT STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 797-3434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1465
Affiliation Type:	Mail Contact
Company Name:	617 SACKETT STREET REALTY CORP.
Contact Type:	Not reported
Contact Name:	LOUIS TURCO
Address1:	617 SACKETT STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY

617 SACKETT STREET REALTY CORP. (Continued) **U000394275**

Zip Code:	11217
Country Code:	001
Phone:	(718) 797-3434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1465
Affiliation Type:	Facility Operator
Company Name:	617 SACKETT STREET REALTY CORP.
Contact Type:	Not reported
Contact Name:	LOUIS TURCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 797-3434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1465
Affiliation Type:	Emergency Contact
Company Name:	617 SACKETT STREET REALTY CORP.
Contact Type:	Not reported
Contact Name:	LOUIS TURCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 797-3434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	2532
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

617 SACKETT STREET REALTY CORP. (Continued) **U000394275**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

AD272 **220 3RD STREET** **NY UST** **U004067675**
WSW **220 3RD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.201 mi.
1059 ft. **Site 1 of 3 in cluster AD**

Relative:
Lower

Actual:
3 ft.

UST:
Name: 220 3RD STREET
Address: 220 3RD STREET
City,State,Zip: BROOKLYN, NY 11215
Id/Status: 2-610369 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585492.57160
UTM Y: 4503187.56633
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 371805
Affiliation Type: Facility Owner
Company Name: 190-220 THIRD STREET STORE BROOKLYN NY, LLC
Contact Type: SENIOR PROJECT MANAGER
Contact Name: JOHN BOGDANSKI
Address1: 550 BOWIE STREET
Address2: Not reported
City: AUSTIN
State: TX
Zip Code: 78703
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2006-10-12

Site Id: 371805
Affiliation Type: Mail Contact

220 3RD STREET (Continued) **U004067675**

Company Name:	HYDRO TECH ENVIRONMENTAL CORP
Contact Type:	Not reported
Contact Name:	MUKTA PATIL
Address1:	15 OCEAN AVE, 2ND FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 636-0800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-07-20

Site Id:	371805
Affiliation Type:	Facility Operator
Company Name:	220 3RD STREET
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2006-10-12

Site Id:	371805
Affiliation Type:	Emergency Contact
Company Name:	190-220 THIRD STREET STORE BROOKLYN NY, LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2006-10-12

Tank Info:

Tank Number:	1
Tank ID:	213988
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported

220 3RD STREET (Continued) **U004067675**

Date Tank Closed:	09/08/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	2
Tank ID:	213989
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/08/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	3
Tank ID:	213990
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/08/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

220 3RD STREET (Continued) **U004067675**

Tank Number:	4
Tank ID:	213991
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1969
Date Tank Closed:	03/16/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Z
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	4A
Tank ID:	213992
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	150
Install Date:	01/01/1969
Date Tank Closed:	04/21/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Z
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	5
Tank ID:	213993
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1969
Date Tank Closed:	03/16/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Z
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported

220 3RD STREET (Continued) **U004067675**

Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

AD273 **PIPPIN ENTERPRISES LTD** **RCRA NonGen / NLR** **1000790830**
WSW **220 3RD ST** **FINDS** **NYD987023181**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.201 mi. **NY MANIFEST**
1059 ft. **Site 2 of 3 in cluster AD**

Relative: **Lower**
Actual: **3 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	PIPPIN ENTERPRISES LTD	
Handler Address:		220 3RD ST
Handler City,State,Zip:		BROOKLYN, NY 11215-2702
EPA ID:		NYD987023181
Contact Name:		Not reported
Contact Address:		3RD ST
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		3RD ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	RICH KOWALSKI	
Owner Type:		Private
Operator Name:	RICH KOWALSKI	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N

PIPPIN ENTERPRISES LTD (Continued) **1000790830**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RICH KOWALSKI	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	220 3RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-858-2020
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

PIPPIN ENTERPRISES LTD (Continued) **1000790830**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RICH KOWALSKI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 220 3RD ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-858-2020
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: RICH KOWALSKI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 220 3RD ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-858-2020
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: PIPPIN ENTERPRISES LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: PIPPIN ENTERPRISES LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PIPPIN ENTERPRISES LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY

PIPPIN ENTERPRISES LTD (Continued) **1000790830**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19921204
Handler Name: PIPPIN ENTERPRISES LTD	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004498552

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000790830
Registry ID:	110004498552
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004498552
Name:	PIPPIN ENTERPRISES LTD
Address:	220 3RD ST
City,State,Zip:	BROOKLYN, NY 11215

PIPPIN ENTERPRISES LTD (Continued) **1000790830**

NY MANIFEST:

Name:	PIPPIN AUTO RADIATOR
Address:	220 3RD ST
City,State,Zip:	BROOKLYN, NY 11215-2702
Country:	USA
EPA ID:	NYD987023181
Facility Status:	Not reported
Location Address 1:	220 3D AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987023181
Mailing Name:	PIPPIN AUTO RADIATOR
Mailing Contact:	RICHARD KOWALSKI
Mailing Address 1:	220 THIRD AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188588300

AE274 **585 UNION STREET** **NY BROWNFIELDS** **S127750710**
NNW **577-599 UNION STREET (AKA 586 SACKETT STREET)** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.203 mi.
1074 ft. **Site 1 of 7 in cluster AE**

Relative:
Lower

Actual:
15 ft.

BROWNFIELDS:

Name:	585 UNION STREET
Address:	577-599 UNION STREET (AKA 586 SACKETT STREET)
City,State,Zip:	BROOKLYN, NY 11217
Program:	BCP
Site Code:	619763
Acres:	0.770
HW Code:	C224329
SWIS:	2401
Town:	New York City
Record Added Date:	06/03/2021
Record Updated Date:	08/10/2021
Update By:	HMDUDEK
Site Description:	"Location: The site is situated in an urban area surrounded by commercial and residential properties. The site was initially comprised of two (2) parcels (Block 433 and Lots 28 and 46), however, it should be noted that Lot 28 and Lot 46 have been merged as of March 29, 2021 and the site is now identified only as Lot 28. The subject property has a total footprint of approximately 33,550 square feet (SF). Site Features: The main site features are two (2) single-story warehouse buildings. Current Zoning and Land Use: The site is currently zoned for manufacturing (M1-2) and is located

585 UNION STREET (Continued) **S127750710**

within the Gowanus Canal Corridor as well as the Red Hook-Gowanus Brownfield Opportunity Areas. The surrounding parcels are used for a combination of residential, commercial and light industrial/manufacturing purposes. Past Use of the Site: Historic Sanborn Fire Insurance maps indicate that as early as 1889, lot 28 was used as a timber yard and lot 46 contained a single building used as a paint shop. The 1938 map depicts water distilling on lot 46, and lot 28 was improved with the current warehouse structure which was utilized by the NY Fire Department as an automobile repair garage and by the Telegraph Department for storage. By 1950, lot 28 was used by the NY Fire Department Telegraph Bureau, and by 1982, the South Brooklyn Casket Company occupied the entire site. Site Geology and Hydrogeology: The ground surface within the site is generally flat and the elevation of the property is approximately +15 (NAVD-88) feet. During previous investigation activities, groundwater was encountered at depths ranging from 11 to 15 feet below ground surface (bgs). Based on United States Geological Survey (USGS) mapping, groundwater is inferred to flow to the west toward the Gowanus Canal, which is located approximately 800 feet west of the Site. The site is not located in the 100-year or 500-year flood zone, however, Federal Emergency Management Agency (FEMA) flood maps show that the site is located adjacent to the 500-year flood zone associated with the Gowanus Canal to the west. Based on observations made during soil boring activities, subsurface soil at the site consisted of urban fill, which was primarily comprised of slag, brick, and gravel in a brown medium-grained sand matrix. Urban fill was encountered at a depth interval from grade to 15 feet bgs throughout the majority of the site. Neither native material, nor bedrock was encountered during this investigation."

Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library-Pacific Branch
Owner Address:	25 Fourth Avenue at Pacific Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03

585 UNION STREET (Continued) **S127750710**

Owner Name:	Philip Caporaso
Owner Company:	Gowanus Union Street LLC
Owner Address:	19 West 24th Street, 12th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Philip Caporaso
Owner Company:	Gowanus Union Street LLC
Owner Address:	19 West 24th Street, 12th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Harry Potone
Owner Company:	Milso Industries Corporation
Owner Address:	534 Union Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Y275 **670 PRESIDENT ST HOUSING CORP** **NY AST** **U004077233**
East **670 PRESIDENT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.204 mi.
1079 ft. **Site 3 of 4 in cluster Y**

Relative:
Higher

Actual:
56 ft.

AST:

Name:	670 PRESIDENT ST HOUSING CORP
Address:	670 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-254460
Program Type:	PBS
UTM X:	586159.75546
UTM Y:	4503238.69415
Expiration Date:	07/10/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10351
Affiliation Type:	Facility Owner
Company Name:	670 PRESIDENT ST HOUSING CORP
Contact Type:	ADMNISTRATOR

670 PRESIDENT ST HOUSING CORP (Continued) **U004077233**

Contact Name:	ELIZABETH PETERS
Address1:	670 PRESIDENT ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(917) 830-3549
EMail:	ELIZNYC@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-15

Site Id:	10351
Affiliation Type:	Mail Contact
Company Name:	670 PRESIDENT ST HOUSING CORP
Contact Type:	ADMNISTRATOR
Contact Name:	ELIZABETH PETERS
Address1:	670 PRESIDENT ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(917) 830-3549
EMail:	ELIZNYC@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-15

Site Id:	10351
Affiliation Type:	Emergency Contact
Company Name:	670 PRESIDENT ST HOUSING CORP
Contact Type:	Not reported
Contact Name:	ELIZABETH PETERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 398-1002
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2008-04-22

Site Id:	10351
Affiliation Type:	Facility Operator
Company Name:	670 PRESIDENT ST HOUSING CORP
Contact Type:	Not reported
Contact Name:	ELIZABETH PETERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

670 PRESIDENT ST HOUSING CORP (Continued) **U004077233**

Country Code:	001
Phone:	(917) 830-3549
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-10-22

Tank Info:

Tank Number:	001
Tank Id:	13008
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/11/1937
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AF276 **CON EDISON - EXCAVATION OIL-O-STATIC** **RCRA-LQG** **1024890651**
North **232 3RD AVE** **NYP005022769**
1/8-1/4 **BROOKLYN, NY 11215**
0.205 mi.
1082 ft. **Site 1 of 6 in cluster AF**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - EXCAVATION OIL-O-STATIC
Handler Address:	232 3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP005022769
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE

Actual:
17 ft.

CON EDISON - EXCAVATION OIL-O-STATIC (Continued) **1024890651**

Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

CON EDISON - EXCAVATION OIL-O-STATIC (Continued) **1024890651**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170120
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170120
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - EXCAVATION OIL-O-STATIC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON - EXCAVATION OIL-O-STATIC (Continued) **1024890651**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AF277 **CON EDISON** **NY MANIFEST** **S120959323**
North **232 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.205 mi.
1082 ft. **Site 2 of 6 in cluster AF**

Relative:
Lower

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	232 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP005022769
Facility Status:	Not reported
Location Address 1:	232 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005022769
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	3RD AVE B/W SACKET STREET & DEGRAW STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11105
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **S120959323**

seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/10/2017
Trans1 Recv Date:	03/10/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/13/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP005022769
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	008171116FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC278 **CON EDISON** **NY MANIFEST** **S117067066**
West **227 3RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.205 mi.
1082 ft. **Site 2 of 10 in cluster AC**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	227 3RD ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA

Actual:
5 ft.

CON EDISON (Continued) **S117067066**

EPA ID:	NYP004597928
Facility Status:	Not reported
Location Address 1:	227 3RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004597928
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004597928
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013246154JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117067066**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U279 **CON EDISON** **NJ MANIFEST** **S120667299**
ESE **335 1ST ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.207 mi.
1093 ft. **Site 10 of 12 in cluster U**

Relative:
Higher

Actual:
59 ft.

NJ MANIFEST:

EPA Id:	NYP004731998
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002621056GBF
EPA ID:	NYP004731998
Date Shipped:	2/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CON EDISON (Continued) **S120667299**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

U280 **CON EDISON** **NY MANIFEST** **S117740048**
ESE **335 1ST ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.207 mi.
1093 ft. **Site 11 of 12 in cluster U**

Relative:
Higher

Actual:
59 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	335 1ST ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004731998
Facility Status:	Not reported
Location Address 1:	335 1ST ST
Code:	BP
Location Address 2:	SB 38709
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004731998
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117740048**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/13/2015
Trans1 Recv Date:	02/13/2015
Trans2 Recv Date:	02/24/2015
TSD Site Recv Date:	02/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004731998
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002621056GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U281 **CON EDISON** **RCRA NonGen / NLR** **1018278429**
ESE **335 1ST ST** **FINDS** **NYP004731998**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.207 mi.
1093 ft. **Site 12 of 12 in cluster U**

Relative: **Higher**
Actual: **59 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150213
Handler Name:	CON EDISON	
Handler Address:		335 1ST ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004731998
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018278429**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150213
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150213
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018278429**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067705601

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278429
Registry ID:	110067705601
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067705601
Name:	CON EDISON
Address:	335 1ST ST
City,State,Zip:	BROOKLYN, NY 11215

AA282 **BHW NV ASSOCIATES** **NY AST** **U004046147**
SSE **321 FIFTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 11215**
0.208 mi.
1096 ft. **Site 4 of 5 in cluster AA**

Relative:
Higher

Actual:
45 ft.

AST:

Name:	BHW NV ASSOCIATES
Address:	321 FIFTH AVENUE
City,State,Zip:	NEW YORK, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-291412
Program Type:	PBS
UTM X:	585930.01750
UTM Y:	4502909.38175
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

BHW NV ASSOCIATES (Continued) **U004046147**

Site Id:	13213
Affiliation Type:	Facility Owner
Company Name:	BHW NV ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	321 5TH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 686-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	13213
Affiliation Type:	Mail Contact
Company Name:	BHW NV ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	321 FIFTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 686-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	13213
Affiliation Type:	Facility Operator
Company Name:	BHW NV ASSOCIATES
Contact Type:	Not reported
Contact Name:	CECIL BLADES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 889-9270
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	13213
Affiliation Type:	Emergency Contact
Company Name:	BHW NV ASSOCIATES
Contact Type:	Not reported
Contact Name:	MS. WEINBERG
Address1:	Not reported

BHW NV ASSOCIATES (Continued) **U004046147**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 686-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	11881
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H99 - Tank Leak Detection - Other
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	D02 - Pipe Type - Galvanized Steel
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	G10 - Tank Secondary Containment - Impervious Underlayment
	G99 - Tank Secondary Containment - Other
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AC283 **CON EDISON MANHOLE: 45289** **RCRA NonGen / NLR** **1016974113**
West **190 3RD ST FRONT OF** **NY MANIFEST** **NYP004479242**
1/8-1/4 **BROOKLYN, NY 11215**
0.208 mi.
1097 ft. **Site 3 of 10 in cluster AC**

Relative: **Lower**
Actual: **6 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20140426
Handler Name:	CON EDISON MANHOLE: 45289
Handler Address:	190 3RD ST FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004479242

CON EDISON MANHOLE: 45289 (Continued) **1016974113**

Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVG PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No

CON EDISON MANHOLE: 45289 (Continued) **1016974113**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140326
Handler Name: CON EDISON MANHOLE: 45289	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140426
Handler Name: CON EDISON MANHOLE: 45289	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON MANHOLE: 45289 (Continued) **1016974113**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	190 3RD ST FRONT OF
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004479242
Facility Status:	Not reported
Location Address 1:	190 3 ST
Code:	BP
Location Address 2:	SB45289
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004479242
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004479242
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012354427JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON MANHOLE: 45289 (Continued) **1016974113**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W284 **CRUSADER CANDLE CO INC** **NJ MANIFEST** **S117984914**
NW **325 NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.208 mi.
1098 ft. **Site 9 of 11 in cluster W**

Relative:
Lower

Actual:
10 ft.

NJ MANIFEST:

EPA Id:	NYD987005840
Mail Address:	NEVINS ST
Mail City/State/Zip:	BROOKLYN, NY 11215
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003733085SKS
EPA ID:	NYD987005840
Date Shipped:	8/23/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004932074SKS
EPA ID:	NYD987005840
Date Shipped:	6/8/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	003099382SKS
EPA ID:	NYD987005840
Date Shipped:	5/30/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	18.00 gallons

Manifest Number:	003310296SKS
EPA ID:	NYD987005840
Date Shipped:	12/17/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

CRUSADER CANDLE CO INC (Continued) **S117984914**

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	003101442SKS
EPA ID:	NYD987005840
Date Shipped:	11/4/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004065131SKS
EPA ID:	NYD987005840
Date Shipped:	12/30/2013
TSDF EPA ID:	NJD002182897

CRUSADER CANDLE CO INC (Continued) **S117984914**

Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004920070SKS
EPA ID:	NYD987005840
Date Shipped:	5/18/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	003461873SKS
EPA ID:	NYD987005840
Date Shipped:	1/30/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004984568SKS
EPA ID:	NYD987005840
Date Shipped:	9/30/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Manifest Number:	003086332SKS
EPA ID:	NYD987005840
Date Shipped:	1/17/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004060437SKS
EPA ID:	NYD987005840
Date Shipped:	12/5/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004025015SKS
EPA ID:	NYD987005840
Date Shipped:	11/22/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	004643106SKS
EPA ID:	NYD987005840
Date Shipped:	3/9/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	003100680SKS
EPA ID:	NYD987005840
Date Shipped:	6/10/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

CRUSADER CANDLE CO INC (Continued) **S117984914**

Manifest Number:	004911076SKS
EPA ID:	NYD987005840
Date Shipped:	5/1/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Manifest Number:	003400129SKS
EPA ID:	NYD987005840
Date Shipped:	4/24/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	14.00 gallons

Manifest Number:	003090194SKS
EPA ID:	NYD987005840
Date Shipped:	5/6/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	Not reported
Quantity:	16.00 gallons

Manifest Number:	003469459SKS
EPA ID:	NYD987005840
Date Shipped:	2/14/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

CRUSADER CANDLE CO INC (Continued) **S117984914**

Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D039
Hand Code: Not reported
Quantity: 14.00 gallons

Manifest Number: 004605674SKS
EPA ID: NYD987005840
Date Shipped: 1/29/2015
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000081205
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Manifest Number: 004964056SKS
EPA ID: NYD987005840
Date Shipped: 8/17/2015
TSDF EPA ID: NJD002182897
Transporter EPA ID: TXR000081205

CRUSADER CANDLE CO INC (Continued) **S117984914**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

W285 **325 NEVINS STREET** **NY LTANKS** **S102672916**
NW **325 NEVINS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.208 mi.
1098 ft. **Site 10 of 11 in cluster W**

Relative: LTANKS:
Lower

Name:	325 NEVINS STREET
Address:	325 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9501568 / 1995-05-08
Facility ID:	9501568
Site ID:	266812
Spill Date:	1995-05-08
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1995-05-08
SWIS:	2401
Investigator:	SMMARTIN
Referred To:	Not reported

Actual:
10 ft.

325 NEVINS STREET (Continued) **S102672916**

Reported to Dept:	1995-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-19
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO - DRIVER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	217327
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	""

All Materials:

Site ID:	266812
Operable Unit ID:	1015969
Operable Unit:	01
Material ID:	370173
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

Name:	325 NEVINS STREET
Address:	325 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9508359 / 1995-10-09
Facility ID:	9508359
Site ID:	266813
Spill Date:	1995-10-09
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C6
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1995-10-09
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported

325 NEVINS STREET (Continued) **S102672916**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-10-09
Spill Record Last Update:	1995-10-30
Spiller Name:	Not reported
Spiller Company:	WHALCO FUEL OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	CRUSADER CANDLE CO
Spiller Phone:	(718) 625-0005
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	217327
DEC Memo:	""
Remarks:	"TANK OVERFILL"

All Materials:

Site ID:	266813
Operable Unit ID:	1019061
Operable Unit:	01
Material ID:	362868
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

W286 **CRUSADER CANDLE CO INC** **RCRA-SQG** **1000694280**
NW **325 NEVINS ST** **FINDS** **NYD987005840**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.208 mi. **NY MANIFEST**
1098 ft. **Site 11 of 11 in cluster W**

Relative: **Lower**
Actual: **10 ft.**

RCRA-SQG:

Date Form Received by Agency:	20150806
Handler Name:	CRUSADER CANDLE CO INC
Handler Address:	325 NEVINS ST
Handler City,State,Zip:	BROOKLYN, NY 11215-1015
EPA ID:	NYD987005840
Contact Name:	Not reported
Contact Address:	NEVINS ST
Contact City,State,Zip:	BROOKLYN, NY 11215
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CRUSADER CANDLE CO INC (Continued) **1000694280**

Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		NEVINS ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	PAUL J MORRA	
Owner Type:		Private
Operator Name:	PAUL J MORRA	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150810

CRUSADER CANDLE CO INC (Continued) **1000694280**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAUL J MORRA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	145 KILBURN RD
Owner/Operator City,State,Zip:	GARDEN CITY, NY 11530
Owner/Operator Telephone:	718-625-0005
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAUL J MORRA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	145 KILBURN RD
Owner/Operator City,State,Zip:	GARDEN CITY, NY 11530
Owner/Operator Telephone:	718-625-0005
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAUL J MORRA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	145 KILBURN RD
Owner/Operator City,State,Zip:	GARDEN CITY, NY 11530
Owner/Operator Telephone:	718-625-0005
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CRUSADER CANDLE CO INC (Continued) **1000694280**

Owner/Operator Indicator: Operator
Owner/Operator Name: PAUL J MORRA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 145 KILBURN RD
Owner/Operator City,State,Zip: GARDEN CITY, NY 11530
Owner/Operator Telephone: 718-625-0005
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PAUL J MORRA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 145 KILBURN RD
Owner/Operator City,State,Zip: GARDEN CITY, NY 11530
Owner/Operator Telephone: 718-625-0005
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: CRUSADER CANDLE CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: CRUSADER CANDLE CO INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CRUSADER CANDLE CO INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CRUSADER CANDLE CO INC (Continued) **1000694280**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150806
Handler Name: CRUSADER CANDLE CO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920612
Handler Name: CRUSADER CANDLE CO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported

CRUSADER CANDLE CO INC (Continued) **1000694280**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

CRUSADER CANDLE CO INC (Continued) **1000694280**

Evaluation Action Summary:

Evaluation Date:	20090813
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RAM
Evaluation Responsible Sub-Organization:	DESA
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20150806
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004491283

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000694280
Registry ID:	110004491283
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004491283
Name:	CRUSADER CANDLE CO INC
Address:	325 NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	CRUSADER CANDLE CO INC
Address:	325 NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215-1015
Country:	USA

CRUSADER CANDLE CO INC (Continued) **1000694280**

EPA ID:	NYD987005840
Facility Status:	Not reported
Location Address 1:	325 NEVINS ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987005840
Mailing Name:	CRUSADER CANDLE CO INC
Mailing Contact:	CRUSADER CANDLE CO INC
Mailing Address 1:	325 NEVINS ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7186250005

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2013
Trans1 Recv Date:	12/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/02/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987005840
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	004065131SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CRUSADER CANDLE CO INC (Continued) **1000694280**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	16
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF287 **CON EDISON** **RCRA NonGen / NLR** **1019908059**
North **SACKETT ST & 3RD AVE** **FINDS** **NYP004841512**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.209 mi.
1104 ft. **Site 3 of 6 in cluster AF**

Relative: **Lower**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150921
Handler Name:	CON EDISON	
Handler Address:		SACKETT ST & 3RD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004841512
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No

CON EDISON (Continued) **1019908059**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150921
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1019908059**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150921
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069654350

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908059
Registry ID:	110069654350
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069654350
Name:	CON EDISON
Address:	SACKETT ST & 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215

AF288 **CON EDISON** **NJ MANIFEST** **S120676968**
North **SACKETT ST & 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.209 mi.
1104 ft. **Site 4 of 6 in cluster AF**

Relative:
Lower

Actual:
17 ft.

NJ MANIFEST:

EPA Id:	NYP004841512
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014470906JJK
EPA ID:	NYP004841512
Date Shipped:	9/21/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120676968**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AF289 **NYCDEP** **NY MANIFEST** **1009244330**
North **SACKETT ST & 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.209 mi.
1104 ft. **Site 5 of 6 in cluster AF**

Relative: **Lower**
Actual: **17 ft.**

NY MANIFEST:

Name:	NYCDEP
Address:	SACKETT ST & 3RD AVE
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP010001790
Facility Status:	Not reported
Location Address 1:	SACKETT ST & 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP010001790
Mailing Name:	NYCDEP
Mailing Contact:	WAI MAN WONG
Mailing Address 1:	59-17 JUNCTION BOULEVARD
Mailing Address 2:	Not reported
Mailing City:	ELMHURST
Mailing State:	NY
Mailing Zip:	11373
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185954656

AG290 **473 PRESIDENT STREET** **NY BROWNFIELDS** **S121933761**
NNW **473 PRESIDENT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.210 mi.
1107 ft. **Site 1 of 9 in cluster AG**

Relative: **Lower**
Actual: **10 ft.**

BROWNFIELDS:

Name:	473 PRESIDENT STREET
Address:	473 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	507634
Acres:	0.460

473 PRESIDENT STREET (Continued) **S121933761**

HW Code:	C224220
SWIS:	2401
Town:	New York City
Record Added Date:	05/08/2015
Record Updated Date:	11/22/2021
Update By:	GWBURKE
Site Description:	"Location: The 473 President Street site is located in an urban area in Brooklyn, NY. It is located in the southern portion of Block 440, Lot 12. The Gowanus Canal is approximately 350 ft to the west of the site. The site is bounded by a shuffleboard club to the north, a former electronics-waste recycler to the west, President Street to the south, and a former casket company to the east. Site Features: The site is comprised of a 1 story warehouse that is fully utilized. Current Zoning and Land Use: The site is vacant and was a former bicycle retailer, a furniture maker, and a showroom for a light designer. It is currently zoned M1-2 (commercial and light industrial uses). The proposed development project calls for demolition of the existing structures and the construction of a mixed-use residential and commercial building, in accordance with zoning laws for that area, with ground floor retail and parking. The development will coincide with the development activities at the neighboring site, President St. Portfolio, BCP Site No. C224309. The nearest residential area is across President Street, but the proposed redevelopment will be largely residential. Past Use of the Site: The site has an industrial history dating to the 1880s. From 1886 to 1928, the site was a sash and door factory, and later a mill with a machine shop and boilers. In 1938 the Coca-Cola Bottling Co. operated two gasoline underground storage tanks (USTs) as part of their site activities. From 1969 to the 1990s, the site was occupied by Dolin Metal Manufacturing Co. From 1993 to 2007, the building was occupied by manufacturing and storage. There is an open spill from a failed tank test which resulted in petroleum-contaminated soils on-site. The spill number is 9412605. Site Geology and Hydrogeology: The soils of the area consist of urban fill in the upper 10 feet. The fill consists of brown, medium to fine sand with varying amounts of gravel, brick, concrete, asphalt, coal fragments, coal ash, slag, and wood. Hardened coal tar was observed within the fill layer in a boring located in the southeastern portion of the site. The fill layer was underlain mainly by brown fine sand with varying amounts of silt and clay. Groundwater is approximately 10 foot below ground surface. The regional groundwater table is relatively flat with a slight gradient to the west towards the Gowanus Canal. "
Env Problem:	"Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, emerging contaminants, and metals. Groundwater was analyzed for VOCs, SVOCs, pesticides, emerging contaminants, and metals. Based upon investigations conducted to date, the primary contaminants of concern for the site include petroleum-related and chlorinated VOCs, SVOCs consisting primarily of Polycyclic Aromatic Hydrocarbons (PAHs), lead, mercury, and arsenic. Soil: Benzene was found in soil at a maximum concentration of 2.1 parts per million (ppm), exceeding the protection of groundwater soil cleanup objective (SCO) of 0.06 ppm. Ethyl benzene was found in soil at a maximum concentration 32 ppm, exceeding the protection of groundwater standard of 1 ppm. Toluene was found in soil at a maximum concentration of 5.5 ppm, exceeding the protection of groundwater standard of 0.7 ppm. Xylenes (total) were found in soil at a maximum

473 PRESIDENT STREET (Continued) **S121933761**

concentration of 250 ppm, exceeding the protection of groundwater standard of 0.26 ppm. Trichloroethene (TCE) was found in soil at a maximum concentration of 5.1 ppm, exceeding the protection of groundwater standard of 0.47 ppm. Cis-1,2-Dichloroethylene was found in soil at a maximum concentration of 3.7 ppm, exceeding the protection of groundwater standard of 0.25 ppm. 1,2,4-Trimethylbenzene was found in soil at a maximum concentration of 100 ppm, exceeding the protection of groundwater standard of 3.4 ppm. 1,3,5-Trimethylbenzene was found in soil at a maximum concentration of 29 ppm, exceeding the protection of groundwater standard of 8.4 ppm. Arsenic was found in soil at a maximum concentration of 203 ppm, exceeding the restricted residential standard of 16 ppm. Lead was found in soil at a maximum concentration of 1080 ppm, exceeding its restricted residential standard of 400 ppm. Mercury was found in soil at a maximum concentration of 18 ppm, exceeding its restricted residential standard of 0.73 ppm. Benzo(a)anthracene was found at a maximum concentration of 34 ppm, exceeding its restricted residential standard of 1 ppm. Benzo(a)pyrene was found at a maximum concentration of 29 ppm, exceeding its restricted residential standard of 1 ppm. Benzo(b)fluoranthene was found at a maximum concentration of 35 ppm, exceeding its restricted residential standard of 1 ppm. Diben(a,h)anthracene was found at a maximum concentration of 2.6 ppm, exceeding its restricted residential standard of 0.33 ppm. Indeno(1,2,3-cd)pyrene was found at a maximum concentration of 17 ppm, exceeding its restricted residential standard of 0.5 ppm. Data does not indicate any off-site impacts in soil related to this site. Groundwater: TCE and its associated degradation products are found in groundwater on the northern half of the site at levels exceeding groundwater standards (5 parts per billion - ppb) with a maximum concentration of 1,300 ppb. Benzene was found exceeding its groundwater standard (1 ppb) at a maximum concentration of 3,500 ppb. Ethylbenzene was found exceeding its groundwater standard (5 ug/L) at a maximum concentration of 2,000 ppb. Toluene was found exceeding its groundwater standard (5 ppb) at a maximum concentration of 740 ppb. Xylene (total) was found exceeding its groundwater standard (5 ppb) at a maximum concentration of 6,900 ppb. Cis-1,2-Dichloroethylene was found exceeding its groundwater standard (5 ppb) at a maximum concentration of 4,900 ppb. 1,2,4-Trimethylbenzene was found exceeding its groundwater standard (5 ppb) at a maximum concentration of 1,600 ppb. 1,3,5-Trimethylbenzene was found exceeding its groundwater standard (5 ppb) at a maximum concentration of 470 ppb. Arsenic was found exceeding its groundwater standard (25 ppb) at a maximum concentration of 38.2 ppb. Naphthalene was found exceeding its groundwater standard (10 ppb) at a maximum concentration of 427 ppb. Data does not indicate any off-site impacts in groundwater related to this site. Sub-Slab Soil Vapor and Indoor Air: Trichloroethene (TCE) was detected at a maximum concentration of 39,000 micrograms per cubic meter (ug/m3) in the soil vapor, and 23.9 ug/m3 in indoor air. Tetrachloroethene (PCE) was detected at a maximum concentration of 440 ug/m3 in the soil vapor, and 2.81 ug/m3 in indoor air. Cis-1,2-dichloroethene (DCE) was detected at a maximum concentration of 95 ug/m3 in the soil vapor, and 0.218 ug/m3 in indoor air. Data indicates there is the potential for off-site impacts in soil vapor related to this site. "

Health Problem: "People will not come into contact with contaminated soil or groundwater since the site is covered with a building and concrete

473 PRESIDENT STREET (Continued) **S121933761**

unless they dig below the ground surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site related contaminants due to soil vapor intrusion does not represent a current concern. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for future onsite development. Environmental sampling indicates that soil vapor intrusion is a concern for offsite buildings."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-13 10:57:00
Record Upd:	2020-09-28 14:23:00
Updated By:	RPMUSTIC
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	EcoRise Development
Owner Address:	473 President Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Jesse Wark
Owner Company:	473 President LLC
Owner Address:	51 East 12th Street
Owner Addr2:	7th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America

473 PRESIDENT STREET (Continued) **S121933761**

Own Op:	1
Sub Type:	06
Owner Name:	Jesse Wark
Owner Company:	473 President LLC
Owner Address:	51 East 12th Street, 7th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
HW Code:	C224220
Waste Type:	dichloroethene (1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220
Waste Type:	1,2,4-TMB
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224220

473 PRESIDENT STREET (Continued) **S121933761**

Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224220-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2019-06-20 09:10:00
Record Updated:	2019-06-20 09:10:00
Updated By:	MLSWEET
Crossref ID:	9412605
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-13 11:07:00
Record Updated:	2015-05-13 11:07:00
Updated By:	SRHEIGEL

AG291 **473 PRESIDENT STREET - OFF-SITE** **NY LTANKS** **S101508966**
NNW **473 PRESIDENT STREET** **NY BROWNFIELDS** **N/A**
1/8-1/4 **BROOKLYN, NY 11215** **NY MANIFEST**
0.210 mi.
1107 ft. **Site 2 of 9 in cluster AG**

Relative: **Lower**
Actual: **10 ft.**

LTANKS:

Name:	BRUCE RIBELNON OMNI MALL
Address:	473 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9412605 / Not Reported
Facility ID:	9412605
Site ID:	323409
Spill Date:	1994-12-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RPMUSTIC
Referred To:	Not reported
Reported to Dept:	1994-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	1995-03-01
Spill Record Last Update:	2021-05-12
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BRUCE RIBELNON
Spiller Phone:	(718) 522-3000
Spiller Extention:	265
DEC Region:	2
DER Facility ID:	260527
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M

473 PRESIDENT STREET - OFF-SITE (Continued) **S101508966**

TIBBE 3500 gallon tank unregistered. Property contact is Steve Zakheim at 718-629-3333. Zakheim stated that this area was addressed and will send in documentation. Other tank and subsurface work has been conducted under different #s at this site in past. Check other files to determine if this area has been addressed. 05/22/09-Zhune called Mr. Zakheim. Could not get him. Left message. 04/03/13- Zhune spoke to Stella. She said Mr. Steve Zakhein is going to be absent for long time call Joseph at 718-629-1000 Ext. 383. 10/4/13- Zhune called Joseph. he indicated he is no longer managing the building. Bruce Ribelnon 4 wheeler Drive Huntintong Station NY 11746 631-673-9884 Second address: 514 Union Street 4/30/15-Albert Tashji from Langan Engineerring (212-479-5508) called to say that they are in the process to fill an aplication for BCP at this site. He needs to know is the site has a Consent Order. He also said the site is currently a warehouse and is going to be develop. 8/26/19 - Spill reassigned to Kim as per Obligado. 8/27/19 - Kim - Spill reassigned to Melissa Sweet Project Manager for C224220. 5/12/21 - Melissa - Spill reassigned to Richard Mustico Project Manager for C224220"

Remarks: "ABOANDONED LINE FAILED TEST - NO SPILL OF PRODUCT - TANK TESTER HAD NO TANK NUMBER"

All TTF:

Facility ID:	9412605
Spill Number:	9412605
Spill Tank Test:	1543466
Site ID:	323409
Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	323409
Operable Unit ID:	1010209
Operable Unit:	01
Material ID:	374899
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BROWNFIELDS:

Name: 473 PRESIDENT STREET - OFF-SITE

473 PRESIDENT STREET - OFF-SITE (Continued) **S101508966**

Address:	473 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	568180
Acres:	Not reported
HW Code:	C224220A
SWIS:	2401
Town:	New York City
Record Added Date:	03/22/2018
Record Updated Date:	01/25/2021
Update By:	JCGRATHW
Site Description:	"Location: The on-site 473 President Street site is located in an urban area in Brooklyn, Kings County. It is located in the southern portion of Block 440 Lot 12. The Gowanus Canal is approximately 350 ft to the west of the site. Site is bounded by a shuffleboard club to the north, an e-waste recycler to the west, President Street to the south, and a casket company to the east. Fulton Works MGP site is 1 block to the north. Site Features: The on-site is comprised of a 1 story warehouse that is fully utilized. Current Zoning and Land Use: The site is an active warehouse for a bicycle company, a furniture maker, and a showroom for a light designer. It is currently zoned for M1-2, commerical to light industrial. The nearest residential area is across President Street. Past Use of the Site: The on-site has an industrial history back to the 1880s. In 1886 to 1928, the site was a sash and door factory and later a trim and planing mill with machine shop and boilers. In 1938 the Coca-Cola Bottling Co was the operator with two gasoline USTs. In 1969 to the 1990s, the site was occupied by Dolin Metal Manufacturing Co. From 1993 to 2007, the building was occupied by manufacturing and storage. Currently the site is occupied by a furniture maker, a lighting designer, and a bicycle retailer. There is an open spill from a failed tank test which may have resulted in BTEX-contaminated soils on-site. The spill number is 9412605. Site Geology and Hydrogeology: The soils of the area consist of urban fill for the top 10 feet. The groundwater is approximately 10 foot below ground surface at the site. Based on the topography of the land, the local groundwater flows in a westerly direction, towards the Gowanus Canal. "
Env Problem:	"The on-site investigation yielded the following results: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs)(only during the pre-application investigation), pesticides, and metals. Groundwater was analyzed for VOCs, SVOCs, pesticides, and metals. Based upon investigations conducted to date, the primary contaminants of concern for the site include TCE, BTEX (Benzene, Toluene, Ethylbenzene, Xylene), naphthalene, Polycyclic Aromatic Hydrocarbons (PAHs - a class of SVOCs), Lead, Mercury, and Arsenic. Soil Soil borings were installed and samples collected as part of the remedial investigation. Concentrations exceeding the Commercial SCOs were found for PAHs, arsenic, lead, and mercury. Primarily the top 10 foot of material, known as historic fill, exceeds the SCOs for PAHs, lead, mercury, and arsenic. Spatially, the native materials were most contaminated in the northern corner near a suspected gasoline tank with trichloroethene (TCE) and BTEX. Groundwater TCE and its associated degradation products are found in groundwater on the northern half of the site moderately exceeding groundwater standards (5 ug/L) with a maximum concentration of 1300 ug/L. Fuel breakdown products (i.e. BTEX and naphthalene) were found in groundwater on the

473 PRESIDENT STREET - OFF-SITE (Continued) **S101508966**

	northern portion of the site at concentrations exceeding the standard near the suspected gasoline tank. Soil Vapor TCE, tetrachloroethene (PCE), and cis-1,2-dichloroethene (DCE), were detected in sub-slab soil vapor at significantly elevated concentrations. "
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY MANIFEST:

Name:	MCP PRESIDENT STREET LLC
Address:	473 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYR000232116
Facility Status:	Not reported
Location Address 1:	473 PRESIDENT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000232116
Mailing Name:	MCP PRESIDENT STREET LLC

473 PRESIDENT STREET - OFF-SITE (Continued) **S101508966**

Mailing Contact:	MCP PRESIDENT STREET LLC
Mailing Address 1:	473 PRESIDENT ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	06/22/2017
Trans1 Recv Date:	06/22/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000232116
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ARD069748192
TSDF ID 2:	Not reported
Manifest Tracking Number:	010326498FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	5
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D040
Waste Code 1_2:	F002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

473 PRESIDENT STREET - OFF-SITE (Continued) **S101508966**

Waste Code 1_6: Not reported

AG292 **473 PRESIDENT STREET LLC - BCP SITE #C224220** **RCRA-LQG** **1023679233**
NNW **473 PRESIDENT ST** **NYR000232116**
1/8-1/4 **BROOKLYN, NY 11215**
0.210 mi.
1107 ft. **Site 3 of 9 in cluster AG**

Relative: **Lower**

Actual: **10 ft.**

RCRA-LQG:

Date Form Received by Agency:	20220308
Handler Name:	473 PRESIDENT STREET LLC - BCP SITE #C224220
Handler Address:	473 PRESIDENT ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYR000232116
Contact Name:	COLIN MCLEAN
Contact Address:	E 12TH ST 7TH FL
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	646-828-3588
Contact Fax:	718-599-1997
Contact Email:	COLIN@AVERYHALLINVESTMENTS.COM
Contact Title:	AUTHORIZED SIGNATORY
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2021
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	E 12TH ST 7TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	473 PRESIDENT STREET LLC
Owner Type:	Private
Operator Name:	473 PRESIDENT STREET LLC
Operator Type:	Private
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No

473 PRESIDENT STREET LLC - BCP SITE #C224220 (Continued) **1023679233**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220308
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	473 PRESIDENT STREET LLC
Legal Status:	Private
Date Became Current:	20190905

473 PRESIDENT STREET LLC - BCP SITE #C224220 (Continued) **1023679233**

Date Ended Current: Not reported
Owner/Operator Address: 51 E 12TH ST 7TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-982-9467
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 473 PRESIDENT STREET LLC
Legal Status: Private
Date Became Current: 20190905
Date Ended Current: Not reported
Owner/Operator Address: 51 E 12TH ST 7TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-982-9467
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 473 PRESIDENT STREET LLC
Legal Status: Private
Date Became Current: 20190905
Date Ended Current: Not reported
Owner/Operator Address: 51 E 12TH ST 7TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-982-9467
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ECORISE DEVELOPMENT
Legal Status: Private
Date Became Current: 20141009
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ECORISE DEVELOPMENT
Legal Status: Private
Date Became Current: 20141009
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner

473 PRESIDENT STREET LLC - BCP SITE #C224220 (Continued) **1023679233**

Owner/Operator Name: MCP PRESIDENT STREET LLC
Legal Status: Private
Date Became Current: 20141009
Date Ended Current: Not reported
Owner/Operator Address: 550 GRAND ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 212-982-9467
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 473 PRESIDENT STREET LLC
Legal Status: Private
Date Became Current: 20190905
Date Ended Current: Not reported
Owner/Operator Address: 51 E 12TH ST 7TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-982-9467
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MCP PRESIDENT STREET LLC
Legal Status: Private
Date Became Current: 20141009
Date Ended Current: Not reported
Owner/Operator Address: 550 GRAND ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 212-982-9467
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20220308
Handler Name: 473 PRESIDENT STREET LLC - BCP SITE #C224220
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20170616
Handler Name: MCP PRESIDENT STREET LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

473 PRESIDENT STREET LLC - BCP SITE #C224220 (Continued) **1023679233**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20211101
Handler Name: 473 PRESIDENT STREET LLC - BCP SITE #C224220
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20170613
Handler Name: MCP PRESIDENT STREET LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 562910
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AF293 **BELL ATLANTIC-NY** **NY MANIFEST** **S109064589**
North **SACKETT & 3 AVE MANHOLE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.210 mi.
1108 ft. **Site 6 of 6 in cluster AF**

Relative: NY MANIFEST:
Lower
Actual: Name: BELL ATLANTIC-NY
17 ft. Address: SACKETT & 3 AVE MANHOLE
City,State,Zip: BROOKLYN, NY
Country: USA
EPA ID: NYP000940593
Facility Status: Not reported
Location Address 1: SACKETT & 3 AVE MANHOLE

BELL ATLANTIC-NY (Continued) **S109064589**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000940593
Mailing Name:	BELL ATLANTIC-NY
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

AH294 **CON ED** **NY MANIFEST** **S119077205**
NW **CARROLL ST & NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.210 mi.
1110 ft. **Site 1 of 11 in cluster AH**

Relative:
Lower

Actual:
10 ft.

NY MANIFEST:

Name:	CON ED
Address:	CARROLL ST & NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004822777
Facility Status:	Not reported
Location Address 1:	NEVINS ST AND CARROLL ST
Code:	BP
Location Address 2:	SB 22609
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004822777
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

CON ED (Continued) **S119077205**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/12/2015
Trans1 Recv Date:	08/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004822777
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469085JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH295 **CON EDISON** **NY MANIFEST** **S117740314**
NW **CARROLL ST & NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.210 mi.
1110 ft. **Site 2 of 11 in cluster AH**

Relative: **Lower**

Actual: **10 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	CARROLL ST & NEVINS ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004734786
Facility Status:	Not reported
Location Address 1:	CARROLL ST & NEVINS ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004734786
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2015
Trans1 Recv Date:	02/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004734786
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014161573JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117740314**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH296 **CON EDISON - TRANSFORMER MANHOLE 0105** **NJ MANIFEST** **S120667553**
NW **CARROLL ST & NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.210 mi.
1110 ft. **Site 3 of 11 in cluster AH**

Relative: **Lower**
Actual: **10 ft.**

NJ MANIFEST:

EPA Id:	NYP004734786
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014161573JJK
EPA ID:	NYP004734786
Date Shipped:	2/20/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON - TRANSFORMER MANHOLE 0105 (Continued) **S120667553**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AH297 **CON EDISON** **RCRA NonGen / NLR** **1019906589**
NW **CARROLL ST & NEVINS ST** **FINDS** **NYP004822777**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.210 mi.
1110 ft. **Site 4 of 11 in cluster AH**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150812
Handler Name:	CON EDISON	
Handler Address:		CARROLL ST & NEVINS ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004822777
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON (Continued) **1019906589**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

CON EDISON (Continued) **1019906589**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150812
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150812
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069664161

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

CON EDISON (Continued) **1019906589**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906589
Registry ID:	110069664161
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069664161
Name:	CON EDISON
Address:	CARROLL ST & NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215

AH298 **CON EDISON - TRANSFORMER MANHOLE 0105** **RCRA-LQG** **1018278697**
NW **CARROLL ST & NEVINS ST** **NYP004734786**
1/8-1/4 **BROOKLYN, NY 11217**
0.210 mi.
1110 ft. **Site 5 of 11 in cluster AH**

Relative: **Lower**
Actual: **10 ft.**

RCRA-LQG:

Date Form Received by Agency:	20160205
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 0105
Handler Address:	CARROLL ST & NEVINS ST
Handler City,State,Zip:	BROOKLYN, NY 11217
EPA ID:	NYP004734786
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	646-582-2258
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

CON EDISON - TRANSFORMER MANHOLE 0105 (Continued) **1018278697**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

CON EDISON - TRANSFORMER MANHOLE 0105 (Continued) **1018278697**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150221
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150221
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - TRANSFORMER MANHOLE 0105
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150221
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON - TRANSFORMER MANHOLE 0105 (Continued) **1018278697**

Receive Date:	20150221
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AH299 **CON EDISON** **NY MANIFEST** **S117738027**
NW **CARROLL ST AND NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11231**
0.210 mi.
1110 ft. **Site 6 of 11 in cluster AH**

Relative: **Lower**

Actual: **10 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	CARROLL ST AND NEVINS ST
City,State,Zip:	BROOKLYN, NY 11231
Country:	USA
EPA ID:	NYP004698718
Facility Status:	Not reported
Location Address 1:	CARROLL ST AND NEVINS ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11231
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004698718
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON (Continued) **S117738027**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/21/2014
Trans1 Recv Date:	11/21/2014
Trans2 Recv Date:	11/26/2014
TSD Site Recv Date:	12/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004698718
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417046GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH300 **CON EDISON** **NJ MANIFEST** **S120675367**
NW **CARROLL ST & NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.210 mi.
1110 ft. **Site 7 of 11 in cluster AH**

Relative:
Lower

Actual:
10 ft.

NJ MANIFEST:

EPA Id:	NYP004822777
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469085JJK
EPA ID:	NYP004822777
Date Shipped:	8/12/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675367**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AH301 **CON EDISON** **NY MANIFEST** **S117537323**
NW **CARROLL ST & NEVINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.210 mi.
1110 ft. **Site 8 of 11 in cluster AH**

Relative:
Lower

Actual:
10 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	CARROLL ST & NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004698700
Facility Status:	Not reported
Location Address 1:	CARROLL ST & NEVINS ST
Code:	BP
Location Address 2:	MH 2542
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004698700
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/21/2014
Trans1 Recv Date:	11/21/2014
Trans2 Recv Date:	11/26/2014
TSD Site Recv Date:	12/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004698700
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117537323**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417045GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE302 **473 PRESIDENT LLC - BCP SITE #C224318** **RCRA-LQG** **1027099640**
NNW **514 UNION ST** **NYR000253203**
1/8-1/4 **BROOKLYN, NY 11215**
0.211 mi.
1113 ft. **Site 2 of 7 in cluster AE**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20220308
Handler Name:	473 PRESIDENT LLC - BCP SITE #C224318
Handler Address:	514 UNION ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYR000253203
Contact Name:	COLIN MCLEAN
Contact Address:	UNION ST
Contact City,State,Zip:	BROOKLYN, NY 11215
Contact Telephone:	646-828-3588
Contact Fax:	Not reported
Contact Email:	COLIN@AVERYHALLINVESTMENTS.COM
Contact Title:	AUTHORIZED SIGNATORY
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported

Actual:
12 ft.

473 PRESIDENT LLC - BCP SITE #C224318 (Continued) **1027099640**

Biennial Report Cycle:		2021
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		E 12TH ST 7TH FLR
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	473 PRESIDENT LLC	
Owner Type:		Private
Operator Name:	473 PRESIDENT LLC	
Operator Type:		Private
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No

473 PRESIDENT LLC - BCP SITE #C224318 (Continued) **1027099640**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220308
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D040
Waste Description:	TRICHLORETHYLENE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: 473 PRESIDENT LLC	
Legal Status:	Private
Date Became Current:	20190905
Date Ended Current:	Not reported
Owner/Operator Address:	51 E 12TH ST 7TH FLR
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	646-828-3588
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JESSE@AVERYHALLINVESTMENTS.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: 473 PRESIDENT LLC	
Legal Status:	Private
Date Became Current:	20190905
Date Ended Current:	Not reported
Owner/Operator Address:	51 E 12TH ST 7TH FLR
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	646-828-3588
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JESSE@AVERYHALLINVESTMENTS.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: 473 PRESIDENT LLC	
Legal Status:	Private
Date Became Current:	20190905
Date Ended Current:	Not reported

473 PRESIDENT LLC - BCP SITE #C224318 (Continued) **1027099640**

Owner/Operator Address: 51 E 12TH ST 7TH FLR
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 646-828-3588
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JESSE@AVERYHALLINVESTMENTS.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: 473 PRESIDENT LLC
Legal Status: Private
Date Became Current: 20190905
Date Ended Current: Not reported
Owner/Operator Address: 51 E 12TH ST 7TH FLR
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 646-828-3588
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JESSE@AVERYHALLINVESTMENTS.COM

Historic Generators:
Receive Date: 20220308
Handler Name: 473 PRESIDENT LLC - BCP SITE #C224318
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20211101
Handler Name: 473 PRESIDENT LLC - BCP SITE #C224318
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 562910
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AE303 **514 UNION STREET** **NY BROWNFIELDS** **S127750694**
NNW **514 UNION STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.211 mi.
1113 ft. **Site 3 of 7 in cluster AE**

Relative: **Lower**
Actual: **12 ft.**

BROWNFIELDS:

Name:	514 UNION STREET
Address:	514 UNION STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	615885
Acres:	0.390
HW Code:	C224318
SWIS:	2401
Town:	New York City
Record Added Date:	01/21/2021
Record Updated Date:	06/07/2021
Update By:	AMSERVIS
Site Description:	"Location: The approximately 0.39-acre site is located in an urban area in the Gowanus neighborhood of Brooklyn, New York, and consists of a one-story brick building occupied by the Royal Palms Shuffleboard Club. The site is located at 514 Union Street and is located at the northern portion of Brooklyn Borough Tax Block 440, Lot 12. The south-adjoining property (p/o Lot 1; formerly the southern portion of Lot 12) is in the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP) (BCP Site No. C224220). The east- and west-adjoining parcels are also in the NYSDEC BCP (BCP Site No. C224309). A lot merger application (RP-602 included) was approved by the New York City (NYC) Department of Finance (DOF) on 5 February 2020 to merge former Lots 1, 21, 23 to 26, 47, 48, and the portion of former Lot 12 that comprises BCP Site No. C224220 into new Lot 1. The property at 514 Union Street remained Lot 12. The site is located on the block bound by Union Street to the north, 3rd Street to the east, President Street to the south, and Nevins Street to the west. Surrounding properties include single- and multi-story buildings occupied by industrial, commercial and residential occupants. The Gowanus Canal (a National Priorities List [NPL] site) is located about 375 feet west of the site. Site Features: The site is improved with a one-story brick building occupied by The Royal Palms Shuffleboard Club. Current Zoning and Land Use: The site is located in an M1-2 manufacturing zoning district. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale and storage facilities. Offices, hotels and most retail uses are also permitted in M1 districts. The 30 January 2019 draft Gowanus zoning proposal by the NYC Department of City Planning (DCP), if approved, would rezone the site to a mixed-use district that permits residential uses (M1(3)/R7A). Past and Current Use of the Site: The site has been occupied by commercial and industrial facilities since as early as 1886. The site is currently occupied by The Royal Palms Shuffleboard Club. The historical and current site uses include: The Royal Palms Shuffleboard Club (2014 present); Manufacturing and Storage (1993 2007); Dolin Metal Manufacturing Co. (1969 1992); Coca-Cola Bottling Co. of NY (1938 1950); Albro J. Newton Co. Trim and Planning Mill (1904 1915); Kenyon and Newton Sash and Door Factory (1886). Site Geology and Hydrogeology: Soil and bedrock stratigraphy throughout Brooklyn typically consists of a layer of historic fill material that overlies glacial till, decomposed unconsolidated bedrock, and

514 UNION STREET (Continued) **S127750694**

bedrock. The United State Geological Survey (USGS) Bedrock and Engineering Geologic Maps of New York County and Parts of Kings and Queens Counties, New York, and Parts of Bergen and Hudson Counties, New Jersey indicate the bedrock underlying the site is part of the Hartland Formation. The Hartland Formation is comprised of mica schist and quartz-feldspar granulite, with localized intrusions of granite and pegmatite. Based on a previous Langan geotechnical study, bedrock was encountered at about 200 feet below grade surface (bgs) at property located 250 feet northwest of the site. A subsurface investigation has not been conducted at the site, however, subsurface investigations have been conducted at adjoining sites, which now comprise Lot 1. The stratigraphy of the surrounding sites consists of historic fill material underlain by native soil generally characterized as fine- to medium-grained sand with varying amounts of silt, clay, and gravel. Historic fill material, characterized as unconsolidated, fine- to medium-grained sand with varying amounts of gravel, brick, coal, concrete, asphalt, coal ash, wood, glass, slag, organics, tar-like material, white ashy material, and silt, was encountered beneath the surface cover to depths ranging from about 6 to 14 feet bgs. Bedrock was not encountered. "

Env Problem: "Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: Jesse Wark
Owner Company: 473 President LLC
Owner Address: c/o Avery Hall Investments
Owner Addr2: 51 East 12th Street, 7th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Jesse Wark
Owner Company: 473 President LLC
Owner Address: c/o Avery Hall Investments
Owner Addr2: 51 East 12th Street, 7th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mike Racioppo

514 UNION STREET (Continued) **S127750694**

Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	John Leighton
Owner Company:	Brooklyn Public Library - Carroll Gardens Branch
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 12231
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Y304 **CON EDISON SERVICE BOX: 31672** **RCRA NonGen / NLR** **1016454644**
East **674 PRESIDENT ST** **FINDS** **NYP004330726**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.212 mi. **NY MANIFEST**
1121 ft. **Site 4 of 4 in cluster Y**

Relative: **Higher**
Actual: **58 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130817
Handler Name:	CON EDISON SERVICE BOX:	31672
Handler Address:		674 PRESIDENT ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004330726
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported

CON EDISON SERVICE BOX: 31672 (Continued) **1016454644**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20131227
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 31672 (Continued) **1016454644**

Historic Generators:

Receive Date:		20130717
Handler Name:	CON EDISON SERVICE BOX:	31672
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130817
Handler Name:	CON EDISON SERVICE BOX:	31672
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056499016

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016454644
Registry ID: 110056499016

CON EDISON SERVICE BOX: 31672 (Continued) **1016454644**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056499016
Name: CON EDISON SERVICE BOX: 31672
Address: 674 PRESIDENT ST
City,State,Zip: BROOKLYN, NY 11215

NY MANIFEST:
Name: CON EDISON
Address: 674 PRESIDENT ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004330726
Facility Status: Not reported
Location Address 1: 674 PRESIDENT ST
Code: BP
Location Address 2: MH #31677
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004330726
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/17/2013
Trans1 Recv Date: 07/17/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004330726
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002086380GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 31672 (Continued) **1016454644**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI305 **CON EDISON** **NY MANIFEST** **S117066557**
SE **386 2ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.213 mi.
1122 ft. **Site 1 of 5 in cluster AI**

Relative:
Higher

Actual:
52 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	386 2ND ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004592226
Facility Status:	Not reported
Location Address 1:	386 2ND ST
Code:	BP
Location Address 2:	STRUCTURE 38853
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004592226
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117066557**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004592226
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504221GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD306 **PARK SLOPE U-HAUL RERS** **NY AST** **A100384621**
WSW **389 3RD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.214 mi.
1129 ft. **Site 3 of 3 in cluster AD**

Relative:
Lower

Actual:
13 ft.

AST:

Name:	PARK SLOPE U-HAUL RERS
Address:	389 3RD AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612146
Program Type:	PBS
UTM X:	585454.34118
UTM Y:	4503051.43512
Expiration Date:	11/22/2018
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	489301
Affiliation Type:	Facility Owner
Company Name:	AREC 6, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2727 N CENTRAL AVE
Address2:	Not reported
City:	PHOENIX
State:	AZ
Zip Code:	85004
Country Code:	001
Phone:	(602) 261-6555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-11-22

Site Id:	489301
Affiliation Type:	Mail Contact
Company Name:	U-HAUL CO. BROOKLYN QUEENS STATEN ISLAND
Contact Type:	Not reported
Contact Name:	WILLIAM WOLFF III
Address1:	213 6TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 522-4859
EMail:	802_EA@UHAUL.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-11-22

Site Id:	489301
Affiliation Type:	Facility Operator
Company Name:	PARK SLOPE U-HAUL RERS
Contact Type:	Not reported
Contact Name:	MOHANLALL BUDHRAM

PARK SLOPE U-HAUL RERS (Continued) **A100384621**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 875-2682
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-11-22

Site Id:	489301
Affiliation Type:	Emergency Contact
Company Name:	AREC 6, LLC
Contact Type:	Not reported
Contact Name:	MOHANLALL BUDRAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 865-3061
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-11-22

Tank Info:

Tank Number:	1
Tank Id:	250348

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
G12 - Tank Secondary Containment - Double-Walled (AG only)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/2011
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

PARK SLOPE U-HAUL RERS (Continued) **A100384621**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

AC307 **VERIZON NEW YORK INC NY35549** **NY MANIFEST** **U003074727**
West **175 THIRD ST** **NY SPDES** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.214 mi.
1130 ft. **Site 4 of 10 in cluster AC**

Relative:
Lower

Actual:
4 ft.

NY MANIFEST:

Name:	BELL ATLANTIC
Address:	175 THIRD ST
City,State,Zip:	BROOKLYN, NY 11215-2701
Country:	USA
EPA ID:	NYD987028008
Facility Status:	Not reported
Location Address 1:	175 3RD ST -BLDG 35549
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987028008
Mailing Name:	BELL ATLANTIC
Mailing Contact:	BELL ATLANTIC
Mailing Address 1:	175 3RD ST -BLDG 35549
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182849984

SPDES:

Name:	VERIZON NEW YORK INC NY35549
Address:	175 THIRD ST
City,State,Zip:	BROOKLYN, NY 11215
Permit Number:	NYR00F468
State-Region:	2
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	Not reported

VERIZON NEW YORK INC NY35549 (Continued) **U003074727**

DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AC308 **VERIZON NEW YORK INC-NY-35549** **NY AST** **S116349274**
West **175 THIRD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.214 mi.
1130 ft. **Site 5 of 10 in cluster AC**

Relative: **Lower**

Actual: **4 ft.**

AST:

Name:	VERIZON NEW YORK INC-NY-35549
Address:	175 THIRD STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-344133
Program Type:	PBS
UTM X:	585428.67093
UTM Y:	4503277.45526
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	005
Tank Id:	46185
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1994

VERIZON NEW YORK INC-NY-35549 (Continued) **S116349274**

Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/11/2020
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

AC309 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000791294**
West **175 THIRD ST** **NYD987028008**
1/8-1/4 **BROOKLYN, NY 11215**
0.214 mi.
1130 ft. **Site 6 of 10 in cluster AC**

Relative: **Lower**

Actual: **4 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	NEW YORK TELEPHONE CO	
Handler Address:		175 THIRD ST
Handler City,State,Zip:		BROOKLYN, NY 11215-2701
EPA ID:		NYD987028008
Contact Name:		Not reported
Contact Address:		31ST AVE
Contact City,State,Zip:		WOODSIDE, NY 11377
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		31ST AVE
Mailing City,State,Zip:		WOODSIDE, NY 11377
Owner Name:	175 3RD ST ASSOC C-O H CHAVES	
Owner Type:		Private
Operator Name:	175 3RD ST ASSOC C-O H CHAVES	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

NEW YORK TELEPHONE CO (Continued) **1000791294**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

NEW YORK TELEPHONE CO (Continued) **1000791294**

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 175 3RD ST ASSOC C-O H CHAVES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 116 JOHN ST ROOM 312
Owner/Operator City,State,Zip: NEW YORK, NY 10032
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: 175 3RD ST ASSOC C-O H CHAVES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 116 JOHN ST ROOM 312
Owner/Operator City,State,Zip: NEW YORK, NY 10032
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 175 3RD ST ASSOC C-O H CHAVES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 116 JOHN ST ROOM 312
Owner/Operator City,State,Zip: NEW YORK, NY 10032
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No

NEW YORK TELEPHONE CO (Continued) **1000791294**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930325
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: BELL ATLANTIC- NY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 5133
NAICS Description: TELECOMMUNICATIONS

NAICS Code: 51331
NAICS Description: WIRED TELECOMMUNICATIONS CARRIERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

NEW YORK TELEPHONE CO (Continued) **1000791294**

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC310 **VERIZON NEW YORK INC-NY-35549** **NY UST** **U004330243**
West **175 THIRD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.214 mi.
1130 ft. **Site 7 of 10 in cluster AC**

Relative:
Lower

Actual:
4 ft.

UST:

Name:	VERIZON NEW YORK INC-NY-35549
Address:	175 THIRD STREET
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-344133 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585428.67093
UTM Y:	4503277.45526
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	001
Tank ID:	32497
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	ZZ
Date Test:	10/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	002
Tank ID:	32498
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	ZZ
Date Test:	10/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

VERIZON NEW YORK INC-NY-35549 (Continued) **U004330243**

Last Modified:	05/09/2022

Tank Number:	003
Tank ID:	45605
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	280
Install Date:	Not reported
Date Tank Closed:	05/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	004
Tank ID:	87347
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	05/01/1994
Date Tank Closed:	07/03/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	004-A
Tank ID:	87348
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	05/01/1994
Date Tank Closed:	05/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

AC311 **175-225 3RD STREET** **NY BROWNFIELDS** **S117535357**
West **175-225 3RD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.214 mi.
1130 ft. **Site 8 of 10 in cluster AC**

Relative: **Lower**
Actual: **4 ft.**

BROWNFIELDS:

Name:	175-225 3RD STREET
Address:	175-225 3RD STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	504582
Acres:	3.200
HW Code:	C224209
SWIS:	2401
Town:	New York City
Record Added Date:	02/12/2015
Record Updated Date:	11/02/2021
Update By:	JHOCONNE
Site Description:	"Location: The about 140,000-square-foot (3.2 acres) site is located at 175-225 3rd Street in the Gowanus neighborhood of Brooklyn, New York (Block 972, Lots 1, 43, and 58). Site Features: The rectangular-shaped site is occupied by a Verizon service center. Lot 1 is adjacent to the Gowanus Canal and is generally covered by vegetation and trees and does not contain structures or foundations. Lot 1 is fenced off at its three landward boundaries and is not accessible to pedestrians or vehicles. Lot 43 is the easternmost lot and contains asphalt-paved parking areas and an about 7,100-square-foot, single-story, pre-fabricated building with sheet metal walls. Verizon currently uses the building for offices and storage. Lot 58 contains an approximately 8,300-square-foot single-story brick building, an open-ended steel storage shed, and asphalt paved parking areas. The building is used as a work operations center and service garage. The site is bound to the north by a closed section of 2nd Street, to the east by 3rd Avenue, to the south by 3rd Street, and to the west by the Gowanus Canal. Current Zoning: The site is located in an M2-1 manufacturing district which allows for office spaces. Historic Use: Historical use of the site includes a coal and stone yard with wagon painting (1886 to 1904), blacksmith (1904), a transit facility with iron coal conveyor transecting the site from east to west (1915 to 1938), an automobile wrecking facility (1934 to 1950), a filling station with gasoline tanks (1950 to 1977), and automobile repair facilities with hydraulic lifts, drums, and waste oil storage (1950 to present). Site Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level with site grade ranging from about elevation (el) 17 in the southeast to el 9.4 in the southwest. The topography of the site is generally level, and the surrounding area slopes gently toward the southwest. The subsurface consists of historic urban fill characterized by brown silty sand with gravel, concrete, wood, brick, stone and debris extending to varying depths of 8 to 14.5 feet below grade. The Fill material is underlain by either an organic layer consisting of soft silt and clay or by a fine- to coarse-grained sand layer with varying amounts of silt and gravel. Groundwater is present beneath the site at 2.5 to 9.3 feet below surface grade or elevation 1.83 at low tide to elevation 8.54 (NAVD88)at high tide. "
Env Problem:	"Nature and Extent of Contamination: The site is contaminated with volatile organic compounds (VOCs), semi-volatile organic compounds

175-225 3RD STREET (Continued) **S117535357**

(SVOCs) and metals from a history of light industrial activity including use of petroleum and hazardous materials, the presence of historic fill, and potential impacts from off-site sources. Petroleum-related impacts appear to be limited to the western portion of the site, near releases from historic underground storage tanks (USTs). Soil The primary contaminants of concern in soil are SVOCs and metals, which exceed the soil cleanup objectives (SCOs) for commercial use. SVOCs are present primarily on the western portion of the site from depths of 2 to 10 feet below surface grade. Petroleum impacts were also observed in this area and depth range. SVOCs that exceed the SCOs for commercial use include: acenaphthene as high as 1,530 parts per million (ppm) compared to the SCO of 500 ppm; acenaphthylene as high as 1,490 ppm compared to the SCO of 500 ppm; anthracene as high as 842 ppm compared to the SCO of 500 ppm; benzo(a)anthracene as high as 274 ppm compared to the SCO of 5.6 ppm; benzo(a)pyrene as high as 153 ppm compared to the SCO of 1 ppm; benzo(k)fluoranthene as high as 99.7 ppm compared to the SCO of 56 ppm; chrysene as high as 352 ppm compared to the SCO of 56 ppm; diben(a,h)anthracene as high as 1.79 ppm compared to the SCO of 0.56 ppm; fluoranthene as high as 1,370 ppm compared to the SCO of 500 ppm; fluorene as high as 1,480 ppm compared to the SCO of 500 ppm; naphthalene as high as 14,700 ppm compared to the SCO of 500 ppm; phenanthrene as high as 3,720 ppm compared to the SCO of 500 ppm; and pyrene as high as 2,050 ppm compared to the SCO of 500 ppm. VOCs detected in the soil exceed the unrestricted use SCOs but are below the SCOs for commercial use, and include: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, n-propylbenzene, toluene, and xylenes. Metals detected in soil at concentrations that exceed the commercial use SCOs include: arsenic as high as 81.7 ppm compared to the SCO of 16 ppm; barium as high as 9,100 ppm compared to the SCO of 400 ppm; cadmium as high as 885 ppm compared to the SCO of 9.3 ppm; copper as high as 3,210 ppm compared to the SCO of 270 ppm; lead as high as 7,190 ppm compared to the SCO of 1,000 ppm; mercury as high as 26.4 ppm compared to the SCO of 2.8 ppm; and zinc as high as 18,400 ppm compared to the SCO of 10,000 ppm. Two samples of lead exceeded the RCRA hazardous waste regulatory limit, as determined by Toxic Characteristic Leachate Procedure (TCLP) analysis. Two TCLP samples had concentrations of 7.57 ppm and 25.7 ppm compared to the RCRA standard of 5 ppm. Groundwater The primary contaminants of concern in groundwater are VOCs and SVOCs. VOCs in groundwater that exceed the Ambient Water Quality Standards (AWQS) include: 1,2,4-trimethylbenzene as high as 71 parts per billion (ppb); 1,3,5-trimethylbenzene as high as 140 ppb; ethylbenzene as high as 770 ppb; n-propylbenzene as high as 26 ppb; toluene as high as 190 ppb; and total xylenes as high as 630 ppb, all of which have a AWQS of 5 ppb. Benzene was detected at 24 ppb compared to the AWQS of 1 ppb. SVOCs in groundwater that exceed the AWQS of 0.002 ppb include: benzo(a)anthracene as high as 0.49 ppb; benzo(a)pyrene as high as 1.03 ppb; benzo(b)fluoranthene as high as 0.26 ppb; benzo(k)fluoranthene as high as 0.32 ppb; and chrysene as high as 0.38 ppb. Naphthalene was detected as high as 7,070 ppb compared to the AWQS of 10 ppb. Bis(2-ethylhexyl)phthalate was also detected in groundwater at a concentration of 159 ppb compared to the AWQS of 5 ppb. Soil vapor One sub-slab soil vapor sample was collected from beneath the slab of the auto repair garage and identified tetrachloroethylene (PCE) at 510 micrograms per cubic meter (g/m3) and trichloroethylene (TCE) at 33 g/m3. TCE was also detected in two

175-225 3RD STREET (Continued) **S117535357**

	other soil vapor samples (not sub-slab) at a maximum of 300 g/m3. Other petroleum-related VOCs were also detected in soil vapor samples at elevated concentrations. "
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-02-12 10:09:00
Record Upd:	2015-02-24 11:30:00
Updated By:	DPMECOMB
Own Op:	4
Sub Type:	NNN
Owner Name:	Patricia Otterstedt
Owner Company:	Global Corporate Service Verizon Account
Owner Address:	201 Centennial Avenue
Owner Addr2:	Room 1S-182
Owner City,St,Zip:	Piscataway, NJ 08854
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Laurent Morali
Owner Company:	175-225 Third Owner LLC
Owner Address:	c/o Kushner Companies
Owner Addr2:	666 Fifth Avenue - 15th Floor
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Park Slope Library
Owner Address:	431 6th Avenue at 9th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11213
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	charles rosemarino
Owner Company:	Gowanus Owner LLC
Owner Address:	c/o RFR Holding LLC
Owner Addr2:	390 Park Ave.
Owner City,St,Zip:	New York, NY
Owner Country:	United States of America
HW Code:	C224209
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	ZINC
Waste Quantity:	UNKNOWN

175-225 3RD STREET (Continued) **S117535357**

Waste Code:	Not reported
HW Code:	C224209
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	1,3,5-Trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	ACENAPTHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	FLUORENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	N-PROPYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

175-225 3RD STREET (Continued) **S117535357**

HW Code:	C224209
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	BIS(2-ETHYLHEXYL)PHTHALATE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	1,2,4-TRICHLOROBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	PHENANTHRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224209
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1405008
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-03-30 12:38:00
Record Updated:	2021-03-30 12:38:00
Updated By:	JHOCONNE

AC312 **175 3RD STREET** **NY LTANKS** **S104073401**
West **175 3RD STREET** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.214 mi.
1130 ft. **Site 9 of 10 in cluster AC**

Relative: **Lower**

Actual: **4 ft.**

LTANKS:

Name:	175 3RD STREET
Address:	175 3RD STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9208180 / 1992-10-15
Facility ID:	9208180
Site ID:	103805
Spill Date:	1992-10-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-15
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1992-10-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-10-15
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	91764
DEC Memo:	""
Remarks:	"INITIAL INVESTIGATION SEEMS TO SHOW SURFACE TYPE SPILLAGE-SAMPLES IS BEING TESTED."

All Materials:

Site ID:	103805
Operable Unit ID:	975104
Operable Unit:	01
Material ID:	408780
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

175 3RD STREET (Continued) **S104073401**

SPILLS:

Name:	NYNEX
Address:	175 3RD STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9402981 / 2000-12-04
Facility ID:	9402981
Facility Type:	ER
DER Facility ID:	91764
Site ID:	315352
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1994-05-31
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1994-05-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-06-29
Spill Record Last Update:	2003-11-05
Spiller Name:	Not reported
Spiller Company:	PETER INGRASSIA
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE TRANSFERED FROM SIGONA TO TIBBE ON 12/4/00. SEE FILE."
Remarks:	"CONDUCTING A TANK REMOVAL AND FOUND SOIL CONTAMINATION . NOTIFIED DEP"

All Materials:

Site ID:	315352
Operable Unit ID:	996778
Operable Unit:	01
Material ID:	383153
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	BELL ATLANTIC
Address:	175 3RD STREET
City,State,Zip:	BROOKLYN, NY

175 3RD STREET (Continued) **S104073401**

Spill Number/Closed Date:	9706734 / 1997-09-05
Facility ID:	9706734
Facility Type:	ER
DER Facility ID:	91764
Site ID:	315353
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-09-05
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1997-09-05
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-05
Spill Record Last Update:	1997-09-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	IKE DEJESUS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG REFERRED DEP. HAZMAT & SANITATION. 212 219-8090"
Remarks:	"SPILL IFO THE MAIN DRIVEWAY - REQ A CALLBACK"

All Materials:

Site ID:	315353
Operable Unit ID:	1050097
Operable Unit:	01
Material ID:	332318
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ313 **CON EDISON** **NY MANIFEST** **S117740672**
East **676 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.216 mi.
1138 ft. **Site 1 of 6 in cluster AJ**

Relative:
Higher

Actual:
58 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	676 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004738498
Facility Status:	Not reported
Location Address 1:	676 PRESIDENT ST
Code:	BP
Location Address 2:	SB31672
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738498
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738498
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087297JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117740672**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ314 **CON EDISON** **NJ MANIFEST** **S120667898**
East **676 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.216 mi.
1138 ft. **Site 2 of 6 in cluster AJ**

Relative: **Higher**
Actual: **58 ft.**

NJ MANIFEST:

EPA Id:	NYP004738498
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014087297JJK
EPA ID:	NYP004738498
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120667898**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AJ315 **CON EDISON** **RCRA NonGen / NLR** **1018279055**
East **676 PRESIDENT ST** **FINDS** **NYP004738498**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.216 mi.
1138 ft. **Site 3 of 6 in cluster AJ**

Relative: **Higher**
Actual: **58 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150225
Handler Name:	CON EDISON	
Handler Address:		676 PRESIDENT ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004738498
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON (Continued) **1018279055**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

CON EDISON (Continued) **1018279055**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067685543

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

CON EDISON (Continued) **1018279055**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279055
Registry ID:	110067685543
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067685543
Name:	CON EDISON
Address:	676 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11215

AK316 **P.S. # 51- 350 5TH AVE** **NY LTANKS** **S105053994**
South **P.S. #51 - 350 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.216 mi.
1139 ft. **Site 1 of 5 in cluster AK**

Relative: **Higher**

Actual: **34 ft.**

LTANKS:

Name:	P.S. # 51- 350 5TH AVE
Address:	P.S. #51 - 350 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9409320 / 1995-02-06
Facility ID:	9409320
Site ID:	105617
Spill Date:	1994-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	1995-02-06
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1994-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-11-07
Spill Record Last Update:	1999-11-16
Spiller Name:	Not reported
Spiller Company:	NYC BOARD OF EDUCATION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

P.S. # 51- 350 5TH AVE (Continued) **S105053994**

DER Facility ID: 93158
DEC Memo: ""
Remarks: "PUMPING TANK OUT - EXCAVATED TO TOP OF TANK, REPLACED FILL LINE NO SOIL CONT. RETESTED AND PASSED 12/8/95"

All TTF:
Facility ID: 9409320
Spill Number: 9409320
Spill Tank Test: 1543242
Site ID: 105617
Tank Number: Not reported
Tank Size: 0
Material: 0003
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 105617
Operable Unit ID: 1003278
Operable Unit: 01
Material ID: 378742
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

AL317 **CON EDISON SERVICE BOX: 44232** **RCRA NonGen / NLR** **1016455304**
ENE **726 SACKETT ST** **FINDS** **NYP004349585**
1/8-1/4 **BROOKLYN, NY 11217** **ECHO**
0.217 mi. **NY MANIFEST**
1144 ft. **Site 1 of 2 in cluster AL**

Relative: Higher
Actual: 41 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20130922
Handler Name: CON EDISON SERVICE BOX: 44232
Handler Address: 726 SACKETT ST
Handler City,State,Zip: BROOKLYN, NY 11217
EPA ID: NYP004349585
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST

CON EDISON SERVICE BOX: 44232 (Continued) **1016455304**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported

CON EDISON SERVICE BOX: 44232 (Continued) **1016455304**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20131227
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130822
Handler Name: CON EDISON SERVICE BOX:	44232
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130922
Handler Name: CON EDISON SERVICE BOX:	44232
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056500914

CON EDISON SERVICE BOX: 44232 (Continued) **1016455304**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016455304
Registry ID:	110056500914
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056500914
Name:	CON EDISON SERVICE BOX: 44232
Address:	726 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11217

NY MANIFEST:

Name:	CON EDISON
Address:	726 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004349585
Facility Status:	Not reported
Location Address 1:	726 SACKER ST
Code:	BP
Location Address 2:	SB 44232
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004349585
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047

CON EDISON SERVICE BOX: 44232 (Continued) **1016455304**

Generator Ship Date:	08/22/2013
Trans1 Recv Date:	08/22/2013
Trans2 Recv Date:	08/24/2013
TSD Site Recv Date:	08/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004349585
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002220121GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

---

318 **207 CORP** **NY AST** **A100301175**
East **207 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.217 mi.
1146 ft.

Relative: **Higher**

Actual: **53 ft.**

AST:

Name:	207 CORP
Address:	207 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-257176
Program Type:	PBS

207 CORP (Continued) **A100301175**

UTM X: 586167.15354
UTM Y: 4503316.99465
Expiration Date: N/A
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 10592
Affiliation Type: Facility Owner
Company Name: SAL MAMMANA
Contact Type: Not reported
Contact Name: Not reported
Address1: 207 5TH AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (718) 647-1220
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10592
Affiliation Type: Mail Contact
Company Name: 207 CORP.
Contact Type: Not reported
Contact Name: VITO MAMMANA
Address1: 876 JAMAICA AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11208
Country Code: 001
Phone: (718) 647-1220
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10592
Affiliation Type: Facility Operator
Company Name: 207 CORP
Contact Type: Not reported
Contact Name: VITO MAMMANA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 647-1220
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10592

207 CORP (Continued) **A100301175**

Affiliation Type:	Emergency Contact
Company Name:	SAL MAMMANA
Contact Type:	Not reported
Contact Name:	VITO MAMMANA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 647-1220
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	15051
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	D00 - Pipe Type - No Piping
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1080
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/22/1997
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AG319 **PRESIDENT STREET PORTFOLIO** **NY BROWNFIELDS** **S126218335**
NNW **469 PRESIDENT STREET AND 532 UNION STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.218 mi.
1153 ft. **Site 4 of 9 in cluster AG**

Relative: **Lower**

Actual: **9 ft.**

BROWNFIELDS:

Name:	PRESIDENT STREET PORTFOLIO
Address:	469 PRESIDENT STREET AND 532 UNION STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	602138
Acres:	0.730
HW Code:	C224309
SWIS:	2401
Town:	New York City
Record Added Date:	03/13/2020
Record Updated Date:	11/15/2021
Update By:	GWBURKE
Site Description:	"Location: The 0.73-acre site is located in an urban area in the Gowanus neighborhood of Brooklyn and consists of two non-contiguous parcels on Brooklyn Borough Tax Block 440: the E Waste Parcel and the Pontone Parcel. The two parcels are separated by BCP site No. C224220, 473 President Street. The two primary addresses associated with the site are 469 President Street and 532-542 Union Street. The site is located on the block bounded by Union Street to the north, 3rd Street to the east, President Street to the south, and Nevins Street to the west. The Gowanus Canal, a National Priorities List (NPL) site, is located about 275 feet west of the E Waste Parcel. Site Features: The E-Waste Parcel is a one-story brick and concrete building which had been occupied by an electronics recycling facility. The ground floor of the E-Waste Parcel was used as a warehouse and an office, and a partial second floor level was used for office space. The Pontone Parcel consists of an interconnected one- to three-story brick building which had been occupied by a casket manufacturer and had offices on the second and third floors. Current Zoning and Land Use: According to the New York City (NYC) Planning Commission Zoning Map 16c, the site is located in an M1-2 manufacturing zoning district. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale and storage facilities. Offices, hotels and most retail uses are also permitted in M1 districts. The 30 January 2019 draft Gowanus zoning proposal by the NYC Department of City Planning (DCP), if approved, would rezone the site to a mixed-use district that permits residential uses (M1(3)/R6A and M1(3)/R7A). Surrounding properties include single and multi-story buildings occupied by industrial, commercial and residential tenants. Past and Current Use of the Site: The site has been occupied by commercial and industrial facilities since as early as 1886. The E-Waste Parcel was used as a blacksmithery, rag storage facility, dental manufacturing facility, parking area, warehouse, and electronics recycling facility. The E-Waste Parcel is currently unoccupied. The Pontone Parcel was used as a factory, woodworking and engraving facility, auto repair shop, painting place, and casket manufacturing facility. The Pontone Parcel is currently unoccupied. Proposed development calls for demolition of existing structures and construction of a mixed-use residential and commercial building with ground floor. Site Geology and Hydrogeology: Soil and bedrock stratigraphy throughout Brooklyn typically consists of a layer of historic fill material that overlies glacial till,

PRESIDENT STREET PORTFOLIO (Continued) **S126218335**

decomposed unconsolidated bedrock, and bedrock. Based on a previous study at a neighboring property, bedrock is present at about 200 feet below grade surface (bgs). Site stratigraphy consists of historic fill material underlain by native soil generally characterized as fine- to medium-grained sand with varying amounts of silt, clay, and gravel. Historic fill material, characterized as unconsolidated, fine-grained sand with varying amounts of gravel, brick, coal, concrete, glass, slag, organics, tar-like material, white ashy material, and silt, was encountered beneath the site to depths ranging from about 6 to 14 feet bgs. Groundwater at the site was encountered at elevations ranging from about 9 to 13 feet bgs. The inferred groundwater flow direction is generally to the west-northwest toward the Gowanus Canal and former Mill Pond. Groundwater flow is restricted by predominantly fine-grained deposits (silt) to the west of the Pontone Parcel. These fines create a localized rise in groundwater elevation that drops as grain size coarsens towards the E-Waste Parcel, continuing towards the Gowanus Canal."

Env Problem: "Nature and Extent of Contamination: Soil was analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, emerging contaminants, and metals. Groundwater was analyzed for VOCs, SVOCs, pesticides, emerging contaminants, and metals. Based upon investigations conducted to date, the primary contaminants of concern for the site include VOCs, polycyclic aromatic hydrocarbons (PAHs - a class of SVOCs), lead, mercury, copper, and arsenic. Soil: Several SVOCs (specifically, polycyclic aromatic hydrocarbons, or PAHs) were detected including benzo(a)anthracene at a maximum concentration of 120 parts per million, or ppm, exceeding its restricted residential soil cleanup objective (RRSCO) of 1 ppm, benzo(a)pyrene at a maximum concentration of 90 ppm (RRSCO is 1 ppm), benzo(b)fluoranthene at a maximum concentration of 130 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene at a maximum concentration of 38 ppm (RRSCO is 3.9 ppm, chrysene at a maximum concentration of 100 ppm (RRSCO is 3.9 ppm), dibenz(a,h)anthracene at a maximum concentration of 16 ppm (RRSCO is 0.33 ppm), indeno(1,2,3-cd)pyrene at a maximum concentration of 63 ppm (RRSCO is 0.5 ppm), fluoranthene at a maximum concentration of 260 ppm (RRSCO is 100 ppm), and pyrene at a maximum concentration of 200 ppm (RRSCO is 100 ppm). Metals found include arsenic at a maximum concentration of 126 ppm (RRSCO is 16 ppm), barium at a maximum concentration of 497 ppm (RRSCO is 400 ppm), lead at a maximum concentration of 8,220 ppm (RRSCO is 400 ppm), mercury at a maximum concentration of 6.58 ppm (RRSCO is 0.81 ppm), copper at a maximum concentration of 41,900 ppm (RRSCO is 270 ppm), cadmium at a maximum concentration of 13.9 ppm (RRSCO is 4.3 ppm), and zinc at a maximum concentration of 25,400 ppm (RRSCO is 10,000 ppm). Tar-like material was encountered in the soil at depths ranging from 7 to 10 feet bgs. This material encompasses an area of about 400 square feet and is located in the northeast portion of the Pontone Parcel. No VOCs, PCBs or pesticides were detected at concentrations exceeding their respective RRSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater: Several VOCs were detected in groundwater. Trichloroethene (TCE) and its associated degradation products were found in groundwater on the western half of the site at levels exceeding the Ambient Water Quality Standard (AWQS) for TCE of 5 parts per billion, or ppb with a maximum concentration of 2,400 ppb. Benzene was found at a maximum concentration of 1.3 ppb (AWQS is

PRESIDENT STREET PORTFOLIO (Continued) **S126218335**

	1 ppb). Cis-1,2-dichloroethene (Cis-1,2-DCE) was found at a maximum concentration of 2,500 ppb (AWQS is 5 ppb). 1,1-Dichloroethene (1,1-DCE) was found at a maximum concentration of 29 ppb (AWQS is 5 ppb). The following SVOCs were found at concentrations exceeding their respective standards: benzo(a)anthracene at a maximum concentration of 0.96 ppb (AWQS is 0.002 ppb); benzo(a)Pyrene at a maximum concentration of 0.87 ppb; benzo(b)fluoranthene at a maximum concentration of 1.1 ppb (AWQS is 0.002 ppb); benzo(k)fluoranthene at a maximum concentration of 0.45 ppb (AWQS is 0.002 ppb); chrysene at a maximum concentration of 0.84 ppb (AWQS is 0.002 ppb); and indeno(1,2,3-c,d)pyrene at a maximum concentration of 0.58 ppb (AWQS is 0.002 ppb). Perfluorooctanoic Acid (PFOA) was found exceeding its maximum contaminant level (MCL) of 10 ppt at a maximum concentration of 119 ppt. Perfluorooctanesulfonic Acid (PFOS) was found exceeding its MCL of 10 ppt at a maximum concentration of 27.3 ppt. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor and Indoor Air: TCE was detected at a maximum concentration of 1,730 micrograms per cubic meter (ug/m3) in the soil vapor, and 31.3 ug/m3 in indoor air, above the TCE Air Guideline Value of 2 ug/m3. Concentrations of TCE in the soil vapor and concurrent indoor air are above the threshold for mitigation of vapor intrusion. DCE was detected at a maximum concentration of 139 ug/m3 in the soil vapor and was not detected in indoor air. 1,1-DCE was detected at a maximum concentration of 8.05 ug/m3 in the soil vapor and was not detected in indoor air. Data does not indicate that there is the potential for off-site impacts in soil vapor related to this site."
Health Problem:	"Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. People will not come into contact with contaminated soil or groundwater since the site is covered with buildings and concrete unless they dig below the ground surface. Volatile organic compounds in the soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates that the potential exists for the inhalation of site contaminants due to soil vapor intrusion for the existing buildings onsite as well as any future on-site development. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-06-23 14:39:00
Record Upd:	2020-12-17 11:36:00
Updated By:	RPMUSTIC
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street

PRESIDENT STREET PORTFOLIO (Continued) **S126218335**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Jesse Wark
Owner Company:	473 President LLC
Owner Address:	c/o Avery Hall Investments
Owner Addr2:	51 East 12th Street, 7th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Carroll Gardens Branch
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
HW Code:	C224309
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	cadmium

PRESIDENT STREET PORTFOLIO (Continued) **S126218335**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224309
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AJ320 **CON EDISON** **NY MANIFEST** **S117740701**
East **675 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.223 mi.
1177 ft. **Site 4 of 6 in cluster AJ**

Relative:
Higher

Actual:
57 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	675 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004738811
Facility Status:	Not reported
Location Address 1:	F.O 675 PRESIDEN ST
Code:	BP
Location Address 2:	SB31669
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738811
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK

CON EDISON (Continued) **S117740701**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738811
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091580JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ321 **CON EDISON** **RCRA NonGen / NLR** **1018279083**
East **675 PRESIDENT ST** **FINDS** **NYP004738811**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.223 mi.
1177 ft. **Site 5 of 6 in cluster AJ**

Relative: **Higher**
Actual: **57 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150225
Handler Name:	CON EDISON	
Handler Address:		675 PRESIDENT ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004738811
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018279083**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018279083**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067685785

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279083
Registry ID:	110067685785
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067685785
Name:	CON EDISON
Address:	675 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11215

AJ322 **CON EDISON** **NJ MANIFEST** **S120667922**
East **675 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.223 mi.
1177 ft. **Site 6 of 6 in cluster AJ**

Relative:
Higher

Actual:
57 ft.

NJ MANIFEST:

EPA Id:	NYP004738811
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported

CON EDISON (Continued) **S120667922**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091580JJK
EPA ID:	NYP004738811
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AM323 **A SHAMOSH** **NY UST U004189562**
NNE **620-628 DEGRAW STREET** **NY AST N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.223 mi.
1178 ft. **Site 1 of 2 in cluster AM**

Relative:
Higher

Actual:
23 ft.

UST:

Name:	A SHAMOSH
Address:	620-628 DEGRAW STREET
City,State,Zip:	BROOKLYN, NY 11217
Id/Status:	2-611758 / Unregulated/Closed

A SHAMOSH (Continued) **U004189562**

Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	586044.12028
UTM Y:	4503565.49449
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	461170
Affiliation Type:	Facility Owner
Company Name:	A. SHAMOSH REALTY LLC
Contact Type:	GENERAL MGR
Contact Name:	JACK IMIR
Address1:	620-628 DEGRAW STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(212) 532-5005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2012-03-09

Site Id:	461170
Affiliation Type:	Mail Contact
Company Name:	A. SHAMOSH REALTY LLC
Contact Type:	Not reported
Contact Name:	JACK IMIR
Address1:	1527 OCEAN PARKWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(212) 532-5005
EMail:	JACKIMIR@YAHOO.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2012-03-09

Site Id:	461170
Affiliation Type:	Facility Operator
Company Name:	A SHAMOSH
Contact Type:	Not reported
Contact Name:	JACK IMIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 240-2622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE

A SHAMOSH (Continued) **U004189562**

Date Last Modified: 2012-03-09

Site Id: 461170
Affiliation Type: Emergency Contact
Company Name: A, SHAMOSH REALTY LLC
Contact Type: Not reported
Contact Name: JACK IMIR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 240-2622
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2012-03-09

Tank Info:

Tank Number: 003
Tank ID: 242888
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/05/2012
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 004

A SHAMOSH (Continued) **U004189562**

Tank ID: 242889
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/05/2012
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 005
Tank ID: 242890
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/05/2012
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

A SHAMOSH (Continued) **U004189562**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	006
Tank ID:	242891
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/05/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	007
Tank ID:	242892
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	01/05/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

A SHAMOSH (Continued) **U004189562**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

AST:

Name: A SHAMOSH
Address: 620-628 DEGRAW STREET
City,State,Zip: BROOKLYN, NY 11217
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-611758
Program Type: PBS
UTM X: 586044.12028
UTM Y: 4503565.49449
Expiration Date: N/A
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 461170
Affiliation Type: Facility Owner
Company Name: A. SHAMOSH REALTY LLC
Contact Type: GENERAL MGR
Contact Name: JACK IMIR
Address1: 620-628 DEGRAW STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (212) 532-5005
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2012-03-09

Site Id: 461170
Affiliation Type: Mail Contact
Company Name: A. SHAMOSH REALTY LLC
Contact Type: Not reported
Contact Name: JACK IMIR

A SHAMOSH (Continued) **U004189562**

Address1:	1527 OCEAN PARKWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(212) 532-5005
EMail:	JACKIMIR@YAHOO.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2012-03-09

Site Id:	461170
Affiliation Type:	Facility Operator
Company Name:	A SHAMOSH
Contact Type:	Not reported
Contact Name:	JACK IMIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 240-2622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-03-09

Site Id:	461170
Affiliation Type:	Emergency Contact
Company Name:	A, SHAMOSH REALTY LLC
Contact Type:	Not reported
Contact Name:	JACK IMIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 240-2622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-03-09

Tank Info:

Tank Number:	001
Tank Id:	242886
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None

A SHAMOSH (Continued) **U004189562**

E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
J03 - Dispenser - Gravity
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/05/2012
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	242887
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/05/2012
Register:	True

A SHAMOSH (Continued) **U004189562**

Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

AH324 **GOWANUS VILLAGE I, LLC - 420 CARROLL STREET** **NY BROWNFIELDS** **S102145301**
NW **420 CARROLL STREET** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.224 mi.
1182 ft. **Site 9 of 11 in cluster AH**

Relative: **Lower**
Actual: **9 ft.**

BROWNFIELDS:

Name:	GOWANUS VILLAGE I, LLC - 420 CARROLL STREET
Address:	420 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11217
Program:	BCP
Site Code:	356610
Acres:	0.920
HW Code:	C224118
SWIS:	2401
Town:	New York City
Record Added Date:	12/09/2005
Record Updated Date:	02/15/2007
Update By:	brwolose
Site Description:	"This is a new BCP application and pertains to the Gowanus Village I, LLC-420 Carroll Street located at 420 Carroll Street, Brooklyn, Kings County. This site is approximately .92 acres in size. Current use of this site is commercial and future use of this site will be residential. Suspected contaminants at this site are chlorinated solvents, pesticides, SVOCs and PCBs. These contaminants are impacting the soil and groundwater. This BCP application is currently under review and the Department of Environmental Conservation will determine the application's approval and eligibility in conjunction with the Department of Health. 8/30/06: the BCP Application was denied."
Env Problem:	"Information submitted with the BCP application and additional information submitted regarding the environmental conditions at the site were reviewed. It was determined that due to lack of known contamination and the unlikely potential for contamination would not complicate the redevelopment of the site, the application was denied."
	Not reported
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	NNN
Owner Name:	SARA MIRSKI-GOWANUS VILLAGE I, LLC
Owner Company:	BOYMELGREEN DEVELOPERS
Owner Address:	752 PACIFIC STREET

GOWANUS VILLAGE I, LLC - 420 CARROLL STREET (Continued) **S102145301**

Owner Addr2:	6TH FLOOR
Owner City,St,Zip:	BROOKLYN, NY 11238
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	SARA MIRSKI - GOWANUS VILLAGE I, LLC
Owner Company:	BOYMELGREEN DEVELOPERS
Owner Address:	752 PACIFIC STREET
Owner Addr2:	6TH FLOOR
Owner City,St,Zip:	BROOKLYN, NY 11238
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	420 CARROLL STREET/BKLYN
Address:	420 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8810095 / 1989-03-30
Facility ID:	8810095
Facility Type:	ER
DER Facility ID:	82019
Site ID:	90905
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	2401
Spill Date:	1989-03-30
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1989-03-30
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	1989-03-30
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-04-04
Spill Record Last Update:	2005-09-21
Spiller Name:	Not reported
Spiller Company:	BELCHER OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

GOWANUS VILLAGE I, LLC - 420 CARROLL STREET (Continued) **S102145301**

AUSTIN 9/21/05 - Austin - Recently found sampling data submitted by NYCDEP, dated 4/18/86. Samples were taken from tank trailers on the site. Document wil be scanned into eDocs database.- end"

Remarks: "MR. BERNSTEIN AT 420 CARROL ST SAYS THAT OIL IS COMING FROM BELCHER OIL'S PROPERTY, CROSSING BERSTEIN'S PROPERTY & GOING INTO GOWANUS CANAL, REFERRED TO ECO'S FOR INVESTIGATION."

All Materials:

Site ID:	90905
Operable Unit ID:	926123
Operable Unit:	01
Material ID:	451273
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AC325 **RED HOOK CRUSHERS; INC.** **NY SWF/LF** **S105841237**
West **186 3RD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11210**
0.224 mi.
1184 ft. **Site 10 of 10 in cluster AC**

Relative: **Lower**
Actual: **4 ft.**

SWF/LF:

Name:	RED HOOK CRUSHERS; INC.
Address:	186 3RD STREET
City,State,Zip:	BROOKLYN, NY 11210
Flag:	INACTIVE
Region Code:	2
Phone Number:	7188559442
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Thomas Saccomanno
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W90]
Active:	No
East Coordinate:	585398
North Coordinate:	4503244
Accuracy Code:	4.3 - Utilization of Digital Orthophoto Quads
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported

RED HOOK CRUSHERS; INC. (Continued) **S105841237**

Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

AN326 **CON EDISON** **NJ MANIFEST** **S120671714**
NE **664 DEGRAW ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.226 mi.
1195 ft. **Site 1 of 4 in cluster AN**

Relative:
Higher

Actual:
29 ft.

NJ MANIFEST:

EPA Id:	NYP004781910
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624178GBF
EPA ID:	NYP004781910
Date Shipped:	5/12/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON (Continued) **S120671714**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AN327 **CON EDISON** **RCRA NonGen / NLR** **1019903138**
NE **664 DEGRAW ST** **NYP004781910**
1/8-1/4 **BROOKLYN, NY 11217**
0.226 mi.
1195 ft. **Site 2 of 4 in cluster AN**

Relative: **Higher**
Actual: **29 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150512
Handler Name:	CON EDISON	
Handler Address:		664 DEGRAW ST
Handler City,State,Zip:		BROOKLYN, NY 11217
EPA ID:		NYP004781910
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISON (Continued) **1019903138**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150512
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON (Continued) **1019903138**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150512
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AN328 **CON EDISON** **NY MANIFEST** **S118090559**
NE **664 DEGRAW ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.226 mi.
1195 ft. **Site 3 of 4 in cluster AN**

Relative: Higher
Actual: 29 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	664 DEGRAW ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004856769
Facility Status:	Not reported
Location Address 1:	664 DEGRAW ST
Code:	BP
Location Address 2:	SB 13570
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856769
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **S118090559**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856769
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002622121GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON

CON EDISON (Continued) **S118090559**

Address:	664 DEGRAW ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004781910
Facility Status:	Not reported
Location Address 1:	664 DEGRAW ST
Code:	BP
Location Address 2:	SB 13570
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004781910
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	05/12/2015
Trans1 Recv Date:	05/12/2015
Trans2 Recv Date:	05/15/2015
TSD Site Recv Date:	05/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004781910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624178GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110

CON EDISON (Continued) **S118090559**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG329 **VERIZON** **NY LTANKS** **S103274088**
NW **318 NEVINS STREET** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.227 mi.
1199 ft. **Site 5 of 9 in cluster AG**

Relative: **Lower**
Actual: **7 ft.**

LTANKS:

Name:	VERIZON
Address:	318 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0306012 / 2003-10-02
Facility ID:	0306012
Site ID:	164586
Spill Date:	2003-09-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	WXSUN
Referred To:	9207367
Reported to Dept:	2003-09-06
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-09-06
Spill Record Last Update:	2009-05-21
Spiller Name:	ENVIROTRAC
Spiller Company:	VERIZON
Spiller Address:	318 NEVINS ST

VERIZON (Continued) **S103274088**

Spiller County:	001
Spiller Contact:	ENVIROTRAC
Spiller Phone:	(631) 471-1500
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	257452
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 9/29/03 1119 Hrs DDO Sawyer tracked down address and sent tank test failure letter to John Quatrale at Verizon. 9/29/03 Reassinged from DeMeo to Sun. 10/02/03 This spill is being remediated under Spill # 9207367. closed. "
Remarks:	"tank failed test - no product spillage"

All TTF:

Facility ID:	0306012
Spill Number:	0306012
Spill Tank Test:	1528647
Site ID:	164586
Tank Number:	Not reported
Tank Size:	4000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	164586
Operable Unit ID:	874585
Operable Unit:	01
Material ID:	503248
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	NEVIN ST GARAGE
Address:	318 NEVINS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9801467 / 1998-05-05
Facility ID:	9801467
Facility Type:	ER
DER Facility ID:	64089
Site ID:	67006
DEC Region:	2

VERIZON (Continued) **S103274088**

Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-05-04
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1998-05-04
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-04
Spill Record Last Update:	2010-05-25
Spiller Name:	Not reported
Spiller Company:	BELL ATLANTIC
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ABOVE NOTIFIER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY RP. "
Remarks:	"spill to pavement - spill contained - cleanup crew enroute - unk cause from a veh"

All Materials:

Site ID:	67006
Operable Unit ID:	1059104
Operable Unit:	01
Material ID:	558084
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	VERIZON
Address:	318 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9314103 / 2003-04-14
Facility ID:	9314103
Facility Type:	ER
DER Facility ID:	257452
Site ID:	296335
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1994-03-02
Investigator:	MCTIBBE

VERIZON (Continued) **S103274088**

Referred To:	9207367
Reported to Dept:	1994-03-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-03
Spill Record Last Update:	2009-05-21
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE refer to 9207367. "
Remarks:	"LOOKS TO BE PROBLEM WITH FILL BOX SPILL ON GRAVED AT FILL AREA - TO VAC UP & DO FOLLOW UP CLEAN UP."

All Materials:

Site ID:	296335
Operable Unit ID:	996062
Operable Unit:	01
Material ID:	558809
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	318 NEVINS STREET
Address:	318 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9208840 / 1992-10-30
Facility ID:	9208840
Facility Type:	ER
DER Facility ID:	257452
Site ID:	319547
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	1992-10-30
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1992-10-30
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Commercial/Industrial

VERIZON (Continued) **S103274088**

Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-10-30
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-11-04
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"OCURRED WHILE TESTING OIL WATER SEPERATION DRAIN SYSTEM OIL WENT TO BOOM DELAYED SINCE YESTERDAY,MECHANICAL PROBLEM HAS FIXED PROBLEM NO MORE LEAK ONLY 2 GALS"

All Materials:

Site ID:	319547
Operable Unit ID:	972381
Operable Unit:	01
Material ID:	405919
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	VERIZON
Address:	318 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9207367 / 2015-06-04
Facility ID:	9207367
Facility Type:	ER
DER Facility ID:	257452
Site ID:	319546
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1992-09-24
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1992-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

VERIZON (Continued) **S103274088**

Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-28
Spill Record Last Update:	2015-06-04
Spiller Name:	Not reported
Spiller Company:	VERIZON
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN transfered from tang/sullivan to tibbe. see also 9314103 and 0306012 at the same location. 09/23/03 Transferred from Tibbe to Sun 10/01/03 Joe Sun of NYSDEC spoke to Jeff Bohlen of Envirotrac (Consultant to Verizon) regarding the removal of two (2)x4000 gallon FRP USTs, which are scheduled to be removed today, 10/01/03. J.Bohlen stated that they will take the end samples next Tuesday or Wednesday . He will call again to confirm the time and date for DEC people to be at the site to witness the soil sampling. 10/02/03- Sun- Faxed letter to John Quatrale of Verizon and Jeff Bohlen of EnviroTrac requesting the area to be excavated in conjunction with the tank removal activities currently progressing on site. Soil excavation will remove the source of the groundwater contamination, and accelerate the remediation of the spill site. Since source material exists under the sidewalk, an attached letter can be used to expedite the DOT permit acquisition. 10/03/2003-Sun-Spoke with John Quatrale of Verizon about excavation of contaminated soils at 318 Nevins Street. He stated that he agrees with DEC's recommendation to excavate the area on south side of Union Stret. Per DEC's request, Verizon will proceed to expedite the DOT permit acquisition immediately. We will meet next week at the site to further survey the facility when Envirotrac starts to take end samples. 10/7/2003-Sun & Vought visited the Verizon's site and met John Quatrale of Verizon and Jeff Bohlen of Envirotrac. At the time of our visit, one 4000 gallon gasoline FRP UST was already removed. Based on our discussion, Verizon will take one end sample for every twenty five (25) feet on each side wall and one ground water sample on the bottom of the tank. The extent of excavation will be based on the PID readings. The analysis of volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) will be performed using EPA Methods 8260 & 8270, respectively. Verizon will excavate another 4000 gallon fiberglass coated steel UST (diesel tank) on 10/9/2003. 1/5/06: Case reassigned to Andersen. Reviewed the quarterly report for April - June 2005. There is a strong decrease in contaminants by natural attentuation. Max BTEX 2,855 (MW8) and max MTBE 110 (MW 8 and 9). 1/12/06: Reviewed quarterly third 2005 quarterly report. Increase in contaminant concentration in the hotspot (MW-8 and MW12). Wait one more quarter and send and RAP required letter. Max BTEX 6,791 ppb (MW8) and max MTBE 145 ppb (MW8). 2/9/06: Reviewed fourth quarterly 2005 report. Fluctuating concentrations in MW-8. Max BTEX 3991 ppb and max MTBE 137 ppb. Sent RAP required letter. 4/6/06: RAP approved. Two closed-in-place 2,000 gallon tanks will be removed and soil excavated. 4/27/06: Meeting with Verizon, NYSDEC, and EnviroTrac. Two closed in place tanks will be removed. There is old fill material and concrete remnants of old buildings in the ground. This site is adjacent to the Gowanus Canal. 5/4/06: Access letter sent to envirotrac for MTA permit. 5/11/06: Received first quarterly 2006

VERIZON (Continued) **S103274088**

report. Excavation and tank removal planned for 5/15/06. Max BTEX 4,348ppb (MW8), max MTBE 61 ppb. 8/25/06: One 2,000 gallon diesel and one 2,000 gallon gasoline previously abandoned USTs were removed in May 2006. Impacted soil was removed to limits of excavation (tieback wall of gowanus canal and retaining wall). A petroleum sheen was seen in water in excavation and 838 gallons of was were removed with a vacuum truck. Two endpoint samples collected, no VOC exceedances, some sVOC exceedances. Two monitoring wells were installed in the excavation (MW16 and MW17). Groundwater sampled on 6/15/06. Max BTEX 3,806 ppb in MW8, max MTBE 27ppb in MW17. Third quarter 2006 gw sampling scheduled for September. 11/27/06: Received July - September 2006 update report. Wells sampled on 9/11/06. Max BTEX 5,164 ppb in MW8. Fluctuating gw concentrations. This is the second sampling event since source removal. An RAP may be required after next sampling event. 2/22/07: Reviewed update report. Wells sampled on 12/15/06. Max BTEX 1,648 ppb (MW8), max MTBE 46 ppb (MW17). Local treatment of MW8 may be required if it does not naturally attenuate. 5/24/07: RAP required for groundwater treatment of MW8. Due 7/5/07. 7/6/07: Received RAP for MNA until the end of 2007. At that time, if the level of contamination warrants remedial action, the feasibility of chemical oxidation in the area of mw8 will be evaluated . 8/30/07: Reviewed update report. Wells sampled on 6/8/07. Max BTEX 833 ppb (MW8), max MTBE 120 ppb (MW17). MNA until fourth quarter 2007. 7/2/08 - Carlson: Reviewed January - March 2008 update report. Wells sampled on 3/26/08. Max BTEX 1,848 ppb (MW8). Report states a workplan will be submitted under a separate cover. Emailed Tom Bosshard - what is the expected workplan submittal date. 7/3/08 - Carlson: Received email from Tom Bosshard. RAP will be submitted by July 31, 2008. 8/6/08 - Carlson: Approved Remedial Work Plan for the use of Regenox. Regenox will be injected into four new injection wells in the sidewalk adjacent to wells MW8 and MW12. 8/7/08 - Carlson: Received email from John Quatrale: Labor negotiations are ongoing and the union is working without a contract since August 3, this may drag on for some time. That said, I am still trying to get the work done before the end of the month and will advise as to the actual scheduled date. 8/25/08 - Carlson: Received OMMP report dated 8/25/08. Injection well installation scheduled for 9/9/08. Received email from Tom Bosshard : Please note that baseline monitoring for parameters outlined in the OMMP will be conducted during the third quarter ground-water sampling event, which will be conducted during the week of September 8th. We expect to conduct the RegenOx injection in late September or October, prior to the fourth quarter ground-water sampling event scheduled for December. Reviewed April through June 2008 Update Report. Wells sampled on June 20, 2008. Depth to water 4 - 9 ft. Maximum BTEX concentration 12,370 ppb (MW8). 10/17/08 - Carlson: Reviewed July 2008 - September 2008 Update Report. Wells sampled on 9/7/08. Maximum BTEX concentration 720 ppb in MW12. Six injection wells installed and Regenox injected in September 2008. Monitoring wells MW8 and MW12 will be sampled in October 2008 to evaluate Regenox effectiveness. 3/5/09 - Carlson: Reviewed October - December 2008 Quarterly Report. Regenox injected in November. Spike in MW8 may be from dissolution resulting from Regenox. Regenox injection planned again in May 2009. 5/4/09 - Carlson: Reviewed update report. General decrease in contaminant concentrations. Another regenox injection planned in may 2009. 8/20/09 - Carlson: Reviewed April 2009 through June 2009 Update Report. A third injection event was performed in May 2009. BTEX,TVOCs

VERIZON (Continued) **S103274088**

are still high in MW8. 12/18/09 - Carlson: Reviewed update report. EFR planned on December 10 to recover contaminants desorbed by Regenox. 2/19/2010 - Carlson: Reviewed update report. EFR conducted in December 2009 prior to December sampling event. Impacted groundwater remains in MW8. Another EFR planned prior to March sampling event. 5/13/2010 - Carlson: Reviewed update report. EFR on 3/3/2010. Wells sampled on 3/30/2010. Low dissolved concentrations. Another EFR event planned prior to June sampling event. 8/27/2010 - Carlson: Reviewed April 2010 through June 2010 Update Report. EFR conducted from MW8. Spike in concentration in MW8. Quarterly EFR and groundwater sampling to continue. 11/9/2010 - Breen. July through September Update report received from Environtrac. EFR extraction at MW-8 on 9-7-10. Next event scheduled for December. 2/17/2011 - Breen. Paper copy of October-December 2010 Update rpt received from Environtrac. 08/08/11: This spill case transferred from G. Breen to J. Kolleeny. Reviewed Update Rpt for Jan. thru March 2011 by EnviroTrac, submitted on 5/9/11 (in eDocs). Rpt gives results of 3/29/11 GW sampling event. High levels of contam continue to persist in MW-8, which had 7,410 ug/L total VOCs (down from 13,031 ug/L in Dec. 2010). Off-site up-gradient well MW-11 had 343 ug/L tVOCs (up a little from 322 ug/L in Dec. 2010), and up-gradient on-site well MW-12 had 401 ug/L tVOCs, up from 320 ug/L in Dec. 2010; contam in both MW-11 and MW-12 is primarily benzene (320 ug/L benzene in MW-11; 400 ug/L in MW-12). Rpt states that EFR events will continue at MW-8 on regular basis, with next EFR event scheduled for June 2011, and GW sampling to be conducted 2 or 3 weeks after that. Spoke with Tom Bosshard of EnviroTrac, who mentioned they found an unknown monitoring well across Union St. from MW-8, and wondered if I knew who installed it and if it would be OK for them to sample it for addt'l up-gradient GW data. I could not find a nearby open spill case, but told Tom I see no reason not to sample well. I suggested that they should measure depth to bottom of well and determine screened interval to make sure well will provide reliable data. He said they would. Changed site priority ranking to P2, because site is in post-injection monitoring phase. - J. Kolleeny 03/16/12: On 3/13/12, got phone message from Gavin Zollo of EnviroTrac asking that I review proposal in Sept. - Dec. 2011 Update Rpt to remove a number of monitoring wells from quarterly sampling program. I reviewed EnviroTrac's Update Rpts for April-June 2011, July-Sept. 2011, and Oct.-Dec. 2011, submitted 8/9/11, 11/18/11, and 3/13/11, resp. (all in eDocs). Rpts show no impacts in wells proposed for removal from quarterly GW mon. program, but increasing total VOCs in well MW-8 and to lesser extent in off-site wells MW-11 and MW-18 (across Union St. from MW-8). For June 2011 sampling event, MW-8 had 11,381 ug/L total VOCs, MW-11 had 439 ug/L tVOCs (MW-18, referred to in rpt as unknown well, was not sampled, but rpt states that well will be inspected during Sept. 2011 event and if in satisfactory condition, will be sampled). In Sept. 2011, MW-8 had 12,671 ug/L tVOCs, MW-11 had 331 ug/L tVOCs, and MW-18 had 36 ug/L tVOCs. (Rpt notes that DEC conducted a spill search of area which did not reveal any open or closed spills that might explain presence of well MW-18; also says EnviroTrac requests that DEC conduct addt'l review of properties up-gradient of site to northeast of Verizon site to try to find reason this well was installed, and states that it appears that an off-site source is impacting Verizon's up-gradient monitoring well network.) For Dec. 2011 sampling event, MW-8 had 16,454 ug/L tVOCs, MW-11 had 423 ug/L tVOCs, and MW-18 had 343 ug/L tVOCs. Rpt

VERIZON (Continued) **S103274088**

recommends removing wells MW-3, MW-4, MW-6, MW-7, MW-10, MW-13, MW-15, MW-16 & MW-17 from quarterly GW sampling schedule; these wells would continue to be gauged for depth to water and presence of product on quarterly basis and would be sampled annually during September GW monitoring event. On 3/16/12, I sent email to Gavin Zollo of EnviroTrac: Gavin, I've looked over EnviroTrac's Update Rpt for Sept. thru Dec. 2011 for this spill site, dated 3/13/12, and want to send out email approving recommendations to eliminate most on-site wells from quarterly sampling program but to continue to gauge them quarterly and sample them annually. Can you please provide contact info for your client, including name, position, address and email address? Also, looking back over last three quarterly status rpts, I notice that total VOC concentrations in problematic well MW-8 have steadily increased, from about 11,000 ug/L to over 16,000 ug/L! This is in spite of EnviroTrac performing quarterly EFR events on well and recently adding air sparging at several nearby wells that were installed for chem ox injections. Do you have any thoughts as to what might be going on at well MW-8? If you're going to suggest an up-gradient off-site source, I'm sorry but I don't buy it. First, even tho EnviroTrac's rpts refer to MW-8 as an off-site well, I don't consider it to be off site, just because it's in sidewalk. It's in immediate vicinity of Verizon's USTs that are known to have leaked. Second, concentrations in wells across street, MW-18 and MW-11, are much lower, which argues against an off-site plume reaching MW-8 from an up-gradient source. Third, as concentrations in MW-8 have increased, moderate VOC levels in wells across street have also increased, suggesting to me that they are responding to whatever is going on at MW-8; possibly there is some tidal effect from nearby Gowanus Canal smearing contamination in MW-8 over toward MW-18 and MW-11. Anyway, please let me know your thoughts on this, and please provide contact info for someone at Verizon. Gavin wrote back: Jon, Please send all correspondence for any Region 2 Verizon facilities, including 318 Nevins Street, to Tom Bosshard. After a recent rearrangement of their envt'l group he is current Envt'l Manager for Verizon in NY area. His info is below: Thomas H. Bosshard, CPG Environmental Manager, Verizon Global EH&S Compliance 501 North Ocean Avenue, Patchogue, New York 11772 O: 631-654-7920, F: 631-475-2217, C: 631-901-8272 thomas.bosshard@verizon.com Jeff Bohlen, who is out in field today, and myself will review other points mentioned in your email and get back with you next week. Thank you for expediting your review of current rpt prior to our next sampling event. We appreciate your efforts. - J. Kolleeny 03/19/12: I sent email to Tom Bosshard of Verizon, cc to Gavin Zollo of EnviroTrac: Dear Mr. Bosshard: I have reviewed Update Rpt for Sept. thru Dec. 2011 pertaining to this spill site, prepared by EnviroTrac Envt'l Svcs and submitted on 3/13/12. Rpt presents results of GW sampling performed at site in Dec. 2011, as well as historical GW sampling data. Based on data, EnviroTrac recommends removing monitoring wells MW-3, MW-4, MW-6, MW-7, MW-10, MW-13, MW-15, MW-16 & MW-17 from quarterly GW sampling schedule; these wells would continue to be gauged for depth to water and presence of free product on quarterly basis and would be sampled annually during September GW monitoring event. This recommendation is approved. However, DEC notes that contaminant levels in well MW-8, located in sidewalk along Union Street and in vicinity of removed gasoline & diesel USTs, have steadily increased over last three sampling events, from ~11,000 ug/L total VOCs in June 2011 to over 16,000 ug/L total VOCs in Dec. 2011. This increase has occurred in

VERIZON (Continued) **S103274088**

spite of quarterly enhanced fluid recovery events being performed on this well, plus recent addition of air sparging using several nearby injection wells installed for application of chemical oxidant. DEC requests that EnviroTrac review available historical soil data from UST removal and from install'n of monitoring and injection wells to evaluate possibility that residual soil contamination in this area may be acting as an ongoing source of GW contamination. If contaminant levels in MW-8 continue to remain elevated, addt'l remedial actions may be required to address contamination. Please feel free to contact me if you have any questions. - J. Kolleeny 03/20/12: Received email response from Gavin Zollo of EnviroTrac, with cc's to Jeff Bohlen of EnviroTrac and Tom Bosshard of Verison Envt'l: John, Per your request, attached is hydrograph of MW-8 with notes of significant events. As you can see, water table elevation has increased over last few years by approx 2-3 ft. A rise in water table appears to correlate with higher BTEX concentrations and following injection of RegenOx, BTEX apparently desorbed from soil resulting in higher BTEX concentrations as compared to previous levels (this is common with RegenOx and tapers off with time). I suggest we continue with EFR/Air Sparging schedule and evaluate BTEX levels after 6 months (following 3rd quarter sampling in September). If you have any questions, please contact me. I wrote back, with same cc's: Gavin, Thanks for your comments and for hydrograph of well MW-8. It is very possible that rise in water table elevation and effects of RegenOx injections may explain increase in VOC concentrations in well MW-8. I agree with your suggestion that EnviroTrac continue with EFR/air sparging program and re-evaluate GW conditions after 3rd quarter 2012 sampling event. Email exchange is in eDocs, with hydrograph attached as last page. - J. Kolleeny 07/05/12: Reviewed Update Rpt - Jan. thru March 2012 by EnviroTrac, submitted with transmittal sheet dated 4/13/12 and received 4/16/12 (in eDocs). Rpt states that enhanced fluid recovery was performed on worst well, MW-8, on 3/16/12, recovering 1,536 gals of GW, and portable air sparge system was also used to enhance recovery of residual soil vapors in vicinity of MW-8 by injecting air into surrounding injection wells IW-1 thru IW-3; effluent air had PID readings up to 31 ppm. GW samples were collected on 3/30/12 from wells MW-8, MW-9, MW-11, MW-12 and MW-18. Well MW-8 had 11,344 ug/L total BTEX (down from 12,018 ug/L in December 2011) and 17,528 ug/L total VOCs (up from 16,454 ug/L in December 2011); MW-11 had 344.5 ug/L tVOCs (down from 423.2 ug/L in Dec. 2011), MW-12 had 200 ug/L tVOCs (down from 261.1 ug/L in Dec. 2011), and MW-18 (which rpt refers to as up-gradient) had 272.5 ug/L tVOCs (down from 343.4 ug/L in Dec. 2011). Well MW-18 seems to be cross-gradient to me, and contam there is likely due to tidal smearing from nearby Gowanus Canal. Rpt states that EFR events in conjunction with air sparging events will continue at MW-8 on quarterly basis, with next event scheduled for June 2012, followed by GW sampling 2-3 weeks later. - J. Kolleeny 09/14/12: Reviewed Update Rpt April-June 2012 by EnviroTrac, submitted with transmittal sheet dated 8/20/12 (in eDocs). GW sampling on 6/28/12 showed worst well, MW-8, had 10,487 ug/L total VOCs (down from 17,528 ug/L in March 2012); well MW-11 had 501 ug/L tVOCs (up from 345 ug/L in March 2012) and well MW-18 had 341 ug/L tVOCs (up from 273 ug/L in March 2012). Rpt states that quarterly EFR events will continue to be performed on MW-8 in conjunction with AS events at surrounding injection wells, with next event scheduled for Sept. 2012; 3rd quarter 2012 GW sampling event

VERIZON (Continued) **S103274088**

will be conducted 2 or 3 weeks after EFR/AS event. Also, received phone call from Mark Godick of AKRF (914-922-2356), consultant to property owner (Verizon is tenant), who is trying to get NYC to rezone property. They plan to develop property with a bldg in a year or so; bldg will likely cover former UST area (but not sidewalk where MW-8 is located), and they will likely be excavating soil, perhaps dewatering, and installing vapor barrier beneath bldg (GW too shallow for SSDS). They will be doing a RAP for NYCOER related to this. We discussed remedial options for Verizon and whether re-development could interfere with spill cleanup, and agreed that this is unlikely since main residual impacts appear to be in sidewalk along Union St., not in former UST area. Mark will be in touch in future. - JK
10/25/12: Met with Tom Bosshard of Verizon and Jeff Bohlen of EnviroTrac; Vadim Brevdo and Paul John of DEC also attended (sign-in sheet in eDocs). Verizon's lease expires at end of 2013, and they plan to close bldg by mid-December 2012. To expedite spill closure, they propose to excavate soil in sidewalk area around problem well MW-8 down to GW. I suggested they also apply oxidizing chemicals to GW in excavation; they agreed. They will prepare and submit work plan for excavation, separate from 3rd quarter monitoring rpt. - J. Kolleeny 12/04/12: Reviewed Update Rpt July 2012 through Sept. 2012 by EnviroTrac, submitted under transmittal letter dated 11/28/12 (in eDocs). Rpt summarizes performance of EFR on well MW-8, and presents results of Sept. 2012 GW sampling event. EFR was done on Sept. 8, 2012, recovering total of ~1,135 gals of GW. Results of GW sampling on Sept. 25, 2012 show MW-8 had 7,147 ug/L total VOCs, down from 10,487 ug/L in June 2012; MW-11 had 381 ug/L tVOCs, down from 501 ug/L in June 2012; MW-12 had 330 ug/L tVOCs, up from 230 ug/L in June 2012; MW-18 had 92 ug/L tVOCs, down from 341 ug/L in June 2012. Rpt states that remedial alternatives for area of MW-8 are currently being evaluated; in meantime, quarterly GW monitoring and EFR events will continue, with next round scheduled for December 2012. - J. Kolleeny 01/30/13: Reviewed Update Rpt Oct. thru Dec. 2012 by EnviroTrac, dated 1/23/13 (in eDocs). EFR was conducted on MW-8 on 12/11/12, with air sparging at nearby injection wells; during EFR with sparging, PID monitoring of effluent air stream at MW-8 gave readings up to 101 ppm. Vacuum measurements taken at nearby wells show no measurable vacuum influence; however, water levels in nearby wells decreased slightly, indicating creation of capture zone around MW-8. Total of 600 gals of water were recovered during 8-hr event. GW sampling on 12/28/12 showed significant decrease in VOCs in worst well MW-8, which had 2,690 ug/L total VOCs, down from 7,147 ug/L in Sept. 2012, and was 3rd consecutive quarterly decrease. Well MW-11 had 206 ug/L tVOCs (down from 381 ug/L in Sept. 2012) and well MW-12 had 331 ug/L tVOCs (~same as 330 ug/L in Sept. 2012). Rpt states that quarterly GW monitoring will continue, and that remedial plan to address area of MW-8 will be submitted under separate cover. - J. Kolleeny 02/01/13: Reviewed Addt'l Remedial Work Plan by EnviroTrac, dated 1/31/13 (in eDocs). Work Plan proposes excavation of soil from vicinity of persistently most-contaminated well MW-8, in sidewalk along Union St adjacent to site, and application of RegenOx"! and ORC Advanced to excavation. Existing on-site monitoring wells will be abandoned, and any wells destroyed during excavation will be replaced for post-excavation GW monitoring, which will be performed and reported on quarterly basis. Work plan includes a Community Air Monitoring Plan (after request by DEC). I sent letter (in eDocs) to Tom Bosshard of Verizon, cc to Jeff Bohlen of EnviroTrac, approving

VERIZON (Continued) **S103274088**

plan but asking that end-pt soil samples be collected from excavation sidewalls if feasible, to document soil conditions at excavation limits. - J. Kolleeny 08/07/13: Reviewed 4/29/13 Update Rpt Jan. thru March 2013 by EnviroTrac (in eDocs as Post-Excavation Status Rpt). Summarizes excavation of contam soil in sidewalk area along Union St. during Feb. 2013. Excavation done in two parts; from first area, two sidewall and one bottom end-pt soil samples were collected, results showed no significant residual impacts. In 2nd area, one bottome end-pt sample was collected (due to sheeting, no sidewalls could be collected); results again showed no significant residual impacts. Prior to backfilling, RegenOx and ORC Advanced were applied to both excavation areas. Well MW-8 (historically worst well) was destroyed during excavation but was reinstalled during backfilling. Total of 82.64 tons of soil were removed. After excavation, all on-site monitoring wells were properly abandoned (as previously approved by DEC). On March 29, 2013, off-site (i.e., sidewalk) wells MW-8, MW-9, MW-11, MW-12 and MW-18 were gauged and sampled. No free product detected. Results show MW-8 had 8,644 ug/L total VOCs, up from 2,690 ug/L in Dec. 2012; well MW-11 had 214.5 ug/L tVOCs, up from 206 ug/L in Dec. 2012. EnviroTrac states that increases are likely due to disturbance of subsurface by excavation and application of chem ox. Quarterly GW monitoring will continue, with next event to be in June 2013. - J. Kolleeny 12/04/13: Reviewed 8/27/13 Update Rpt April-June 2013 by EnviroTrac (in eDocs). Results of June 2013 GW sampling event show well MW-8 had 4,052 ug/L total VOCs (down from 8,644 ug/L in March 2013), well MW-12 had 220 ug/L tVOCs (same as in March 2013), well MW-18 had 81 ug/L tVOCs (up from 37 ug/L in March 2013). EnviroTrac attributes tVOCs decrease in MW-8 to excavation of contam soil source material and subsequent chem ox application, states that well network will continue to be sampled on quarterly basis, in Sept. and Dec. 2013. - JK 01/27/14: Reviewed 10/29/13 Update Rpt June-Sept. 2013 by EnviroTrac (in eDocs). Results of Sept. 2013 GW sampling event show well MW-8 had 4,378 ug/L total VOCs (up from 4,052 ug/L in June 2013), well MW-12 had 391 ug/L tVOCs (up from 220 ug/L in June 2013), well MW-18 had 9 ug/L tVOCs (down from 81 ug/L in June 2013). EnviroTrac notes that total BTEX in well MW-8 decreased from 1,983 ug/L in June 2013 to 1,814 ug/L in Sept. 2013, and attributes this to excavation of contaminated source material and subsequent chem ox/ORC application. Rpt states that well network will continued to be sampled quarterly, with Dec. 2013 event. - J. Kolleeny 02/18/14: Reviewed 1/15/14 Update Rpt Sept.-Dec. 2013 by EnviroTrac (in eDocs). Results of 12/24/13 GW sampling show well MW-8 had 11,332 ug/L total VOCs (up from 4,378 ug/L in Sept. 2013), well MW-11 had 155 ug/L tVOCs (up from 72 ug/L in Sept. 2013), well MW-12 had 280 ug/L tVOCs (down from 391 ug/L in Sept. 2013). Rpt states that rebounding of VOC concentrations in GW is common after chem ox / ORC applications and is likely cause of increase in VOCs in well MW-8. This seems somewhat dubious, as RegenOx & ORC Advanced were applied to open excavation (i.e., not injected) in Feb. 2013, and this was 4th GW sampling event since then. On 1/15/14, Gavin Zollo of EnviroTrac sent email noting that 4th Quarter 2013 rpt being sent summarizes 4th quarterly event since remedial actions, and requesting meeting to discuss future options. On 2/12/14, I did prelim review of rpt and emailed Gavin with suggested meeting date of 3/5/14; on 2/14/14, Gavin confirmed date was good for meeting. - J. Kolleeny 03/07/14: On 3/5/14, met with Tom Bosshard of Verizon and Jeff Bohlen of EnviroTrac to discuss site status and future course of action. DEC stated that spill cannot

VERIZON (Continued) **S103274088**

be closed yet in light of increased VOC concentrations in well MW-8; Verizon & EnviroTrac agreed, but noted that many remedial actions have been performed at site, including two UST removals with soil excavation, chem ox injections, vacuum-enhanced fluid recovery plus air sparging, and most-recent soil excavation in sidewalk area of MW-8 (well was replaced) plus application of chem ox to open excavation. I suggested further quarterly monitoring of well MW-8 only, with annual sampling of other wells; however, if results for MW-8 show decreasing trend before year is over, other wells should be sampled in support of spill closure. Verizon/EnviroTrac agreed with this suggestion. After meeting, on 3/6/14, Tom Bosshard sent email to document these discussions: Jon, Thank you to Vadim and yourself for your time in meeting with Jeff and myself yesterday to discuss spill case. As you know, Verizon NY has expended a great deal of effort in remediating this spill site, and is appreciative of DEC s continued guidance as we continue on path to spill closure. Most recently, remedial efforts included soil excavation and chemical oxidation application in area of off-site monitoring well MW-8 in Feb. 2013, followed by four quarters of GW monitoring and sampling through Dec. 2013 utilizing five off-site monitoring wells. As discussed and mutually agreed during yesterday s meeting, Verizon NY proposes to continue quarterly monitoring and sampling at monitoring well MW-8 in 2014 during months of March, June, September and December, and conducting annual monitoring and sampling at monitoring wells MW-9, 11, 12 and 18 during month of December 2014, at which time request for spill closure will again be considered. Results of quarterly monitoring and sampling at MW-8 will also be continually evaluated, and MW-9, 11, 12 and 18 may be monitored and sampled prior to December 2014 if a trend in quarterly dissolved concentrations at MW-8 supports a spill closure request. I sent email reply: Tom, Thanks for your email documenting our discussions from Wednesday's meeting and agreed-upon future course of action for this spill site. - J. Kolleeny 05/28/14: Reviewed Update Rpt January thru March 2014 by EnviroTrac, dated 4/25/14 (in DecDocs). Rpt presents results of GW sampling of well MW-8 on 3/20/14, showing well had 2,725 ug/L total VOCs, down from 11,332 ug/L in Dec. 2013. Rpt states that monitoring of MW-8 will continue, with next sampling event scheduled for June 2014. - J. Kolleeny 10/15/14: Reviewed Update Rpt April-June 2014 by EnviroTrac, dated 7/1/14 (in DecDocs). Rpt presents result of June 20, 2014 sampling of well MW-8, showing well had 3,248 ug/L total VOCs (up from 2,725 ug/L in March 2014). Rpt states that GW monitoring will continue, with next sampling event for MW-8 in Sept. 2014, and with annual sampling of all remaining wells (MW-8, MW-9, MW-11, MW-12 & MW-18) in Dec. 2014, at which time results will be re-evaluated for petitioning for spill closure. - J. Kolleeny 12/15/14: Reviewed Update Rpt July-Sept 2014 by EnviroTrac, dated 11/7/14 (in DecDocs). Sampling of well MW-8 in Sept 2014 showed 2,658 ug/L total VOCs (down from 3,248 ug/L in June 2014). Rpt states that wells MW-8, MW-9, MW-11 and MW-18 will be sampled in Dec. 2014 for annual GW sampling event. Rpt also states that well MW-12 (in Union St sidewalk to SE of MW-8) was found to have been destroyed, and that Verizon does not intend to replace well. Rpt states that results of post-remediation quarterly GW monitoring will continue to be summarized in quarterly reports and continually evaluated for request of spill closure. - JK 02/23/15: Reviewed Update Rpt Oct.-Dec. 2014 by EnviroTrac, dated 1/12/15 (in DecDocs). GW sampling on 12/19/14 showed well MW-8 had 7,260 ug/L total VOCs (up from 2,658 ug/L in

VERIZON (Continued) **S103274088**

Sept. 2014), well MW-9 had 4.3 ug/L tVOCs (had 4.8 ug/L tVOCs when last sampled in Dec. 2013), well MW-11 had 158.6 ug/L tVOCs (had 155.1 ug/L tVOCs when last sampled in Dec. 2013), well MW-12 had 282.4 ug/L tVOCs (had 280 ug/L when last sampled in Dec. 2013), well MW-18 had 7.9 ug/L tVOCs (had 3.2 ug/L tVOCs when last sampled in Dec. 2013). Rpt notes that construction activities in sidewalk along Union St. were noted during Sept. 2014 GW sampling event, and EnviroTrac speculates that such ground disturbance activities may have caused increase in VOCs in MW-8 this quarter, which was a departure from previous 3 quarters. EnviroTrac recommends another GW sampling event in March 2015 to evaluate request for spill closure. - JK 06/04/15: Reviewed Update Rpt & Request for Spill Closure, Jan. through March 2015 by EnviroTrac, dated 4/3/15 (in DecDocs). On 3/16/15, a GW sample was collected only from problem well MW-8, as I agreed to in discussions with EnviroTrac. Sample result showed well MW-8 had 1,158 ug/L total VOCs (down from 7,260 ug/L in Dec. 2014, an upward fluctuation or spike which EnviroTrac stated was likely attributable to construction activities in Union Street sidewalk near MW-8 in Fall 2014, possibly related to subsurface utilities). Well MW-8 had only 12 ug/L of benzene (down from 72 ug/L in Dec. 2014). Based on overall decreasing trend in VOC levels in MW-8, absence of significant impacts in other site-related wells, and substantial remedial efforts undertaken at site (including UST removals, soil excavations, application of oxygen-releasing material and chemical oxidant (to open excavations and via injections), performance of vac truck extraction events, EnviroTrac requests spill closure. I agree spill closure is appropriate based on remedial actions performed, relatively low residual contaminant levels, and decreasing trend in contaminant levels, which is likely to continue by natural attenuation processes. I closed spill case, sent spill closure letter (in DecDocs) to Thomas Bosshard of Verison, cc to Jeff Bohlen of EnviroTrac. - J. Kolleeny"

Remarks: "GASOLINE DISCOVERED IN WELL NEAR TANK 2K GASOLINE WILL TEST NEXT WEEK4K GASOLINE DOUBLE WALL,FIBERGLASS WILL CHECK LEAK DET- SYSTEM AND SPACE 2K DEISEL WILL TEST NEXT WEEK."

All Materials:

Site ID:	319546
Operable Unit ID:	974312
Operable Unit:	01
Material ID:	408007
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AG330 **VERIZON NEW YORK INC. (NY35570)** **NY AST** **A100382320**
NW **318 NEVINS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.227 mi.
1199 ft. **Site 6 of 9 in cluster AG**

Relative:
Lower

Actual:
7 ft.

AST:

Name:	VERIZON NEW YORK INC. (NY35570)
Address:	318 NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-344265
Program Type:	PBS
UTM X:	585562.31327
UTM Y:	4503535.51578
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	007
Tank Id:	46195
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1993
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/11/2012
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

AG331 **VERIZON NEW YORK INC. (NY35570)** **NY UST** **U004198767**
NW **318 NEVINS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.227 mi.
1199 ft. **Site 7 of 9 in cluster AG**

Relative:
Lower

Actual:
7 ft.

UST:

Name:	VERIZON NEW YORK INC. (NY35570)
Address:	318 NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-344265 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585562.31327
UTM Y:	4503535.51578
Site Type:	Utility (Other than Municipal)

Tank Info:

VERIZON NEW YORK INC. (NY35570) (Continued) **U004198767**

Tank Number:	001
Tank ID:	32534
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/16/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	01
Date Test:	05/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	003
Tank ID:	32535
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/16/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	01
Date Test:	06/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	004
Tank ID:	45622
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1988
Date Tank Closed:	10/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Tightness Test Method:	01
Date Test:	09/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	005
Tank ID:	45623
Tank Status:	Closed - In Place

VERIZON NEW YORK INC. (NY35570) (Continued) **U004198767**

Material Name:	Closed - In Place
Capacity Gallons:	280
Install Date:	Not reported
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	006
Tank ID:	46194
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1993
Date Tank Closed:	10/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

AG332 **NEW YORK TELEPHONE CO** **RCRA-VSQG** **1000791295**
NW **318 NEVINS ST** **FINDS** **NYD987028016**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.227 mi. **NY MANIFEST**
1199 ft. **Site 8 of 9 in cluster AG**

Relative: **Lower**
Actual: **7 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	NEW YORK TELEPHONE CO
Handler Address:	318 NEVINS ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYD987028016
Contact Name:	FRED SMITH
Contact Address:	31ST AVE
Contact City,State,Zip:	WOODSIDE, NY 11377
Contact Telephone:	718-726-9909
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities

NEW YORK TELEPHONE CO (Continued) **1000791295**

State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		31ST AVE
Mailing City,State,Zip:		WOODSIDE, NY 11377
Owner Name:	BANKERS LIFE CO	
Owner Type:		Private
Operator Name:	BANKERS LIFE CO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No

NEW YORK TELEPHONE CO (Continued) **1000791295**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: BANKERS LIFE CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 10387
Owner/Operator City,State,Zip:	DES MOINES, IA 50306
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: BANKERS LIFE CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 10387
Owner/Operator City,State,Zip:	DES MOINES, IA 50306
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: BANKERS LIFE CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 10387
Owner/Operator City,State,Zip:	DES MOINES, IA 50306
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

NEW YORK TELEPHONE CO (Continued) **1000791295**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930325
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004500825

NEW YORK TELEPHONE CO (Continued) **1000791295**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000791295
Registry ID:	110004500825
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004500825
Name:	NY TELEPHONE-318 NEVINS ST
Address:	318 NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	NYNEX
Address:	318 NEVINS ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYD987028016
Facility Status:	Not reported
Location Address 1:	318 NEVINS ST -BLDG 35570
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987028016
Mailing Name:	NYNEX
Mailing Contact:	NICK CADAVILLO
Mailing Address 1:	318 NEVINS ST -BLDG 35570
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182849984

AK333 **NYC DEPT OF EDUCATION - I S 51K** **RCRA-SQG** **1016144316**
SSE **350 5TH AVE** **FINDS** **NYR000198952**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.227 mi.
1200 ft. **Site 2 of 5 in cluster AK**

Relative: **Higher**
Actual: **37 ft.**

RCRA-SQG:

Date Form Received by Agency:		20130219
Handler Name:	NYC DEPT OF EDUCATION - I S 51K	
Handler Address:		350 5TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000198952
Contact Name:		ALEXANDER LEMPERT
Contact Address:		THOMSON AVE
Contact City,State,Zip:		LONG ISLAND CITY, NY 11101
Contact Telephone:		718-472-8501
Contact Fax:		718-472-8500
Contact Email:		ALEMPERT@NYCSCA.ORG
Contact Title:		DIRECTOR
EPA Region:		02
Land Type:		Municipal
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		THOMSON AVE
Mailing City,State,Zip:		LONG ISLAND CITY, NY 11101
Owner Name:	NYC DEPT OF EDUCATION	
Owner Type:		Municipal
Operator Name:	NYC DEPT OF SCHOOL FACILITIES	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

NYC DEPT OF EDUCATION - I S 51K (Continued) **1016144316**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	19510601
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES	
Legal Status:	Municipal
Date Became Current:	19510601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

NYC DEPT OF EDUCATION - I S 51K (Continued) **1016144316**

Historic Generators:
- Receive Date: 20130219
- Handler Name: NYC DEPT OF EDUCATION - I S 51K
- Federal Waste Generator Description: Small Quantity Generator
- State District Owner: NY
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 61111
- NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

FINDS:
- Registry ID: 110063898956

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1016144316
- Registry ID: 110063898956
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110063898956
- Name: NYC DEPT OF EDUCATION - I S 51K
- Address: 350 5TH AVE
- City,State,Zip: BROOKLYN, NY 11215

AK334 **K051** **NY UST** **U000418095**
SSE **350 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.227 mi.
1200 ft. **Site 3 of 5 in cluster AK**

Relative:
Higher

Actual:
37 ft.

UST:

Name:	K051
Address:	350 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-356247 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/28/2023
UTM X:	585850.81856
UTM Y:	4502842.01673
Site Type:	School

Affiliation Records:

Site Id:	17787
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2022-03-28

Site Id:	17787
Affiliation Type:	Facility Operator
Company Name:	JUNIOR HIGH SCHOOL 51 - BROOKLYN
Contact Type:	Not reported
Contact Name:	CARMINE SOMMA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 369-7603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-03-16

Site Id:	17787
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported

K051 (Continued) **U000418095**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2022-06-16

Site Id:	17787
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Tank Info:

Tank Number:	001
Tank ID:	34808
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	01/01/1950
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Tightness Test Method:	34
Date Test:	06/10/2021
Next Test Date:	06/10/2022
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

K051 (Continued) **U000418095**

D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	34809
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	01/01/1950
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	06/10/2021
Next Test Date:	06/10/2022
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AO335 **CON EDISON** **NY MANIFEST** **S117064538**
South **298 5TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.227 mi.
1200 ft. **Site 1 of 3 in cluster AO**

Relative:
Higher

Actual:
28 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	298 5TH ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004570321
Facility Status:	Not reported
Location Address 1:	298 5 ST
Code:	BP
Location Address 2:	STRUCTURE 45986

CON EDISON (Continued) **S117064538**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004570321
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/2014
Trans1 Recv Date:	06/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004570321
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502744GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON (Continued) **S117064538**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO336 **CON EDISON SERVICE BOX: 45986** **RCRA NonGen / NLR** **1017779065**
South **298 5TH ST** **NYP004570321**
1/8-1/4 **BROOKLYN, NY 11215**
0.227 mi.
1200 ft. **Site 2 of 3 in cluster AO**

Relative:
Higher

Actual:
28 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20140719
Handler Name:	CON EDISON SERVICE BOX:	45986
Handler Address:		298 5TH ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004570321
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No

CON EDISON SERVICE BOX: 45986 (Continued) **1017779065**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 45986 (Continued) **1017779065**

Electronic Manifest Broker: Not reported

Receive Date: 20140619
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140719
Handler Name: CON EDISON SERVICE BOX: 45986
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Z337 **CON ED - V 3685** **RCRA NonGen / NLR** **1007205266**
SSW **522 W 44 ST** **NYP000928358**
1/8-1/4 **NEW YORK, NY 10036**
0.228 mi.
1206 ft. **Site 9 of 9 in cluster Z**

Relative: **Higher**
Actual: **27 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 19980228
Handler Name: CON ED - V 3685
Handler Address: 522 W 44 ST
Handler City,State,Zip: NEW YORK, NY 10036-0000
EPA ID: NYP000928358
Contact Name: ANTHONY DRUMMINGS
Contact Address: CONSOLIDATED EDISON INC
Contact City,State,Zip: NEW YORK, NY 10003-0000
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported

CON ED - V 3685 (Continued) **1007205266**

Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported

CON ED - V 3685 (Continued) **1007205266**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - V 3685	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - V 3685	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - V 3685	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON ED - V 3685 (Continued) **1007205266**

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AA338 **CON EDISON SERVICE BOX: 37885** **RCRA NonGen / NLR** **1016961208**
SSE **315 4TH ST S** **NY MANIFEST** **NYP004337168**
1/8-1/4 **BROOKLYN, NY 11232**
0.229 mi.
1207 ft. **Site 5 of 5 in cluster AA**

Relative: **Higher**
Actual: **43 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130829
Handler Name:	CON EDISON SERVICE BOX:	37885
Handler Address:		315 4TH ST S
Handler City,State,Zip:		BROOKLYN, NY 11232
EPA ID:		NYP004337168
Contact Name:		ROBERTA BELL
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4590
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OFFICE ASSISTANT L1-2
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

CON EDISON SERVICE BOX: 37885 (Continued) **1016961208**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130729
Handler Name:	CON EDISON SERVICE BOX: 37885
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 37885 (Continued) **1016961208**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130829
Handler Name: CON EDISON SERVICE BOX: 37885
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON ED
Address: 315 4TH ST S
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004337168
Facility Status: Not reported
Location Address 1: 315 SO 4TH ST
Code: BP
Location Address 2: SERV BOX 37855
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11211
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004337168
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON SERVICE BOX: 37885 (Continued) **1016961208**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	07/29/2013
Trans1 Recv Date:	07/29/2013
Trans2 Recv Date:	07/29/2013
TSD Site Recv Date:	08/01/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004337168
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084712GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG339 **318 NEVINS STREET** **NY BROWNFIELDS** **S128529087**
NW **300-344 NEVINS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.231 mi.
1218 ft. **Site 9 of 9 in cluster AG**

Relative:
Lower

Actual:
7 ft.

BROWNFIELDS:

Name:	318 NEVINS STREET
Address:	300-344 NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	630084
Acres:	2.340
HW Code:	C224350
SWIS:	2401
Town:	New York City
Record Added Date:	12/08/2021
Record Updated Date:	02/01/2022
Update By:	HMDUDEK
Site Description:	"Location: The site is situation in an urban areas surrounded historically by mainly industrial properties. The Gowanus Canal, a USEPA National Priorities List (NPL) site, is located directly adjacent to the site and was once a vital cargo transportation hub prior to the mid-20th century. The subject property has a total footprint of approximately 102, 070 square feet (SF). Site Features: the main site feature are one (1) single-story commercial building and a bulkhead along Gowanus Canal frontage. Current Zoning and Land Use: The site is currently zoned with the M1-4/R7-2 designation, which is representative of residential zoning. The site, prior to a zoning change that went into effect in November 2021 by the NYCDCP, was previously located within a M2-1 designation. The M2-1 designation is a district characterized by a middle g60round between light and heavy industrial areas. The surrounding parcels have also been re-zoned and presently are within the M1-4/R7-2 designation as well. Past Use of the Site: Historic Sanborn Fire Insurance maps indicate that the site was used as a lumber yard as early as 1886 through the 1910s. Kopper s Seaboard Coke Co. is depicted as the occupant of the site from circa 1922 until the 1950s, during this time the site was used as a yard designed to receive coke for barges, screen and deliver to trucks for distribution to consumers. The current on-site structure was reportedly constructed in 1958 and was occupied by a motor freight stations through the 1960s through the late 1970s. Subsequently, the building was utilized by NY Telephone Co., Bell Atlantic and Verizon. Site Geology and Hydrogeology: The ground surface within the site is generally flat and the elevation of the property is approximately +10 (NAVD-88) feet. During previous investigation activities, groundwater was encountered at depths ranging from 5 to 7.5 feet below ground surface (bgs). Based on United States Geological Survey (USGS) mapping, groundwater is inferred to flow to the west-northwest toward the Gowanus Canal, which is located directly adjacent to the site. According to the Federal Emergency Management Agency (FEMA), the site is located within a Special Flood Hazard Area (SFHA), Zone AE, characterized by having a 1 percent annual chance of flooding. Historic investigation reports prepared for the site characterized subsurface soil as historic fill material consisting of fine-grained sand with varying amounts of gravel, brick and concrete. The fill material was encountered at grade to depths of 6 to 9 feet bgs throughout the majority of the site. The fill material was reportedly underlain by

318 NEVINS STREET (Continued) **S128529087**

	sand and clay. In addition, a clay layer was observed at approximately 10 feet bgs throughout the site. Bedrock was not encountered during historic investigations. "
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	P03
Owner Name:	Philip Caporaso
Owner Company:	Gowanus 300 Nevins Street LLC
Owner Address:	19 West 24th Street, 12th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	n/a
Owner Company:	Brooklyn Public Library Carroll Gardens Branch
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Philip Caporaso
Owner Company:	Gowanus 300 Nevins Street LLC
Owner Address:	19 West 24th Street, 12th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	n/a
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported

318 NEVINS STREET (Continued) **S128529087**

Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AP340 **KAM SERVICE CENTER INC** **NY LTANKS** **1000556241**
SSW **363 4TH AVE** **NY Spills** **NYD986988004**
1/8-1/4 **BROOKLYN, NY 11234** **RCRA NonGen / NLR**
0.232 mi. **FINDS**
1225 ft. **Site 1 of 7 in cluster AP** **ECHO**

Relative: **Higher**
Actual: **26 ft.**

LTANKS:

Name:	BP AMOCO STATION #13397
Address:	363 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8901904 / 2016-02-04
Facility ID:	8901904
Site ID:	90896
Spill Date:	1989-05-24
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	2005-04-28
SWIS:	2401
Investigator:	RJFENG
Referred To:	080613 CASE TRANSFERRED TO SPILLS UNIT
Reported to Dept:	1989-05-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2008-02-28
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-25
Spill Record Last Update:	2016-03-29
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	82010
DEC Memo:	"3/14/03 REASSIGNED FROM SULLIVAN TO VOUGHT. 10/27/03 Also see spill # 0307900. 11/25/03 Reassigned from Vought to Foley. 11/25/03 Received Delta Dispenser Upgrade Report dated 11/10/03 on 11/17/03. Lab analysis of post-ex soil samples collected from beneath four dispensers identified VOC concentrations in excess of TAGM 4046 soil cleanup objectives in three dispenser locations (D-1, D-2, D-3). Delta will delineate the soil impacts beneath the product dispensers. 4/19/04 Received SHAR. On 3/17/04, four borings were advanced by Geoprobe in the vicinity of the dispensers. DTW 13-20'bgs. Nine soil samples were collected at the depth interval exhibiting the highest

KAM SERVICE CENTER INC (Continued) **1000556241**

PID reading or immediately above the water table. SB-1 (3.5-4.5'), SB-1 (17-18'), SB-2(19-20'), SB-3(2.5-3.5'), SB-3 (12-13'), SB-4(2.5-3.5'), SB-4(7-8'), SB-4(12-13'). Analysis by 8260 showed hits for VOCs above cleanup levels in five of nine soil samples in all four borings. Total BTEX conc ranged from ND (SB-1, 3.5-4.5' and SB-2, 3.5-4.5') to 1,076,900ppb in SB-4(12-13'). The four borings were converted to 1 temporary wells. Four groundwater samples were collected and analyzed for VOCs. DTW 18-24'bgs. MWs were advanced to 23-26'bgs. Temporary wells were removed. No LNAPL was detected. Total BTEX ranged from 3,732ppb (MW-1) to 45,380ppb(MW-4). Total VOC range from 17,061ppb(MW-2) to 69,062ppb(MW-1). MTBE ranged from 9,050ppb(MW-4) to 64,600ppb(MW-1). 12/21/04 4Q04 report received(samples collected 11/23/04). BTEX ranged from 38ppb(MW-5) to 38810ppb(MW-4). MTBE ranged from 33ppb(MW-5) to 174000ppb(MW-1). DTW approx 12-15'bgs. 6/28/04 Investigation report received. On 4/23/04, one 1 well(MW-3) was installed through existing soil boring SB-3 and one 2 well(MW-4) was installed through previously advanced soil boring SB-4. Wells were advanced to 25.5 and 26.5' respectively. GW was encountered at 17.15'bgs in MW-3 and 17'bgs in MW-4. No soil samples collected due to previous investigation. On 5/24/04, three 2 wells (MW-1, MW-2, MW-5) were installed to 24', 20', and 20' respectively. GW encountered at 11.7' and 16.8'bgs. Four soil samples were collected. Hits for VOCs in SB-5/MW-2(10-11'), SB-5/MW-2(12-13'). On 5/28/04, five GW samples were collected. GW was identified at 11'-14.5'bgs. Flow was interpreted as NW. BTEX ranged from 74ppb(MW-5) to 45550ppb(MW-4). MTBE from 19ppb(MW-5) to 192000ppb(MW-1). 9/30/04 3Q04 monitoring report received. BTEX from 57ppb(MW-5) to 39150ppb(MW-4). MTBE from 17ppb(MW-5) to 164000ppb(MW-1). DTW 11-14'bgs. Need to delineate downgradient and sidegradient. 3/10/05 Received 1Q05 monitoring report. BTEX ranged from 65ppb(MW-5) to 38730ppb(MW-4). MTBE from 12ppb(MW-5) to 204000ppb(MW-1). 3/15/05 Issued sidewalk permit letter to install three MWs along the west sidewalk of 4th Ave. 3/15/05 Stip issued. Due 4/29/05. 4/21/05 Received stip signed by C. Wein on 4/19/05. 4/27/05 Portfolio meeting- Vadose and saturated soil impacts at northern border and SW portion of property. PS #51 300' NW. Impacts across street(total BTEX 100ppb). Service station and taxi stand on Sanborns for property across street. 4/28/05 Stip executed by T. Kunkel. An Investigation Summary report is due 6/27/05. RAP due 8/26/05. 6/13/05 Received subsurface hydrocarbon assessment report dated 6/7/05. MW-6,7,8 installed off-site. Soil results show impacts at MW-7(11-12'bgs & 15-16'bgs). Adjacent to U-Haul and Taxi Stand with garage. Total BTEX in GW was 1ppb(MW-6), 272ppb(MW-7) and ND(MW-8). MTBE concentrations were 2ppb(MW-6), 3ppb(MW-7) and 13ppb(MW-8). 6/24/05 Received Investigation summary report dated 6/22/05. On-site vadose zone soil impacts in and around dispensers are from historical release. Elevated MTBE concentrations in MW-1 and MW-2 may be related to more recent release. This is also supported by analysis of BTEX ratios. Off-site soil and GW impacts were detected across 4th Ave at MW-7 and MW-8, which appear to be from U-Haul or taxi stand(impacts as shallow as 11'bgs). 9/6/05 Received well installation report documenting installation of EW-1, MW-9 and MW-10. MPE pilot conducted 8/16/05. Pilot test feasibility report to be submitted. 12/30/05 Received 3Q05 monitoring report. DTW 11.37-14.90'bgs. BTEX ranged from ND(MW-8) to 50320ppb(MW-4). MTBE ranged from 5.1ppb(MW-6) to 170000ppb(MW-1). 2/23/06 Received letter from Delta requesting extension to stip and summarizing MPE pilot

KAM SERVICE CENTER INC (Continued) **1000556241**

test results which was conducted in 8/05. Since 8/05, Delta has tried to identify an appropriate remedial alternative to address site impacts within the vadose, smear and saturated zones on-site. On 11/4/05, Delta sampled on and off-site wells for geochemical parameters and stable carbon isotope ratio analysis. Delta is currently reviewing the results as they relate to the potential use of aerobic stimulation(sparging). Request extension to submit RAP by 5/14/06. 3/9/06 4Q05- DTW 11.96-14.63'bgs. BTEX ranged from ND(MW-8) to 44200ppb(MW-4). MTBE ranged from 1ppb(MW-8) to 81900ppb(MW-10). 3/16/06 Met with BP and Delta. MW-6,7,8 installed in 4/05. Pilot for MPE completed in 8/05 which determined it is not an option. Geochemical sampling completed 10/05 which showed no degradation. DTW 11.5-14.5'bgs. Very high MTBE concentrations. Sensitive receptors include utility vaults along 4th Ave. Delta was planning to submit biosparge proposal. Vic Kremesec, BP, requested Delta look into something more agressive. 5/9/06 Received feasibility pilot testing and analysis report for Multi-Phase Extraction and a Remedial Action Plan. 6/8/2006 - Feng - project reassigned to RJFeng. (RJF) 7/28/2006 - Feng - Quarterly Monitoring Report, 1Q2006, 6/6/2006, submitted by Delta. As of sampling on 3/6/2006, groundwater flows to northwest at the depth of 10.89' to 15.17' bg. 11 monitoring wells. W-1, 9,350 ppb BTEX (3,410 ppb B, 1,050 ppb T, 1,480 ppb E, 3,410 ppb X), 21,100 ppb MTBE. W-2, 2,840 ppb BTEX (1,170 ppb B, 163 ppb T, 811 ppb E, 696 ppb X), 3,330 ppb MTBE. W-3, 20,990 ppb BTEX (3,070 ppb B, 6,800 ppb T, 2,120 ppb E, 9,000 ppb X), 10,400 ppb MTBE. W-4, 38,920 ppb BTEX (4,400 ppb B, 17,300 ppb T, 3,220 ppb E, 14,000 ppb X), 33,500 ppb MTBE. W-5, 35.4 ppb BTEX, 4.6 ppb MTBE. W-6, 1.42 ppb BTEX, 4.6 ppb MTBE. W-7, 677 ppb BTEX (22.8 ppb B, 8.9 ppb T, 304 ppb E, 341 ppb X), 8.1 ppb MTBE. W-8, ND. W-9, 16,780 ppb BTEX (2,180 ppb B, 1,890 ppb T, 2,210 ppb E, 10,500 ppb X), 14,200 ppb MTBE. W-10, 17,760 ppb BTEX (3,810 ppb B, 3,180 ppb T, 2,890 ppb E, 7,880 ppb X), 44,900 ppb MTBE. EW-1, 12,180 ppb BTEX (2,110 ppb B, 1,780 ppb T, 1,940 ppb E, 6,350 ppb X), 8,260 ppb MTBE. (RJF) 8/1/2006 - Feng - Remedial Action Plan, 5/8/2006, submitted by Delta Environmental. Delta proposed MultiPhase Extraction System to be installed to address FP, soil vapor and gw contamination. Delta conducted pilot test twice. The 1st time it was concluded that The results of this MPE pilot event conflicted with the expected response from the site's lithology . During the 2nd pilot test, 5 air samples collected at specific intervals to quantify specific vapor VOC concentration being removed. The recovery rates are 0.19 lb/hr BTEX, 0.091 lbs/hr MTBE, 4.89 lbs/hr TPH. For the groundwater drawdown reading, W-9 at 0.28' which located 5 feet away from EW-1. Delta explained that The limited groundwater drawdown ROI from extraction well EW-1 is likely due to the more transmissive subsurface soils which allow more significant groundwater recharge into the cone of depression generated by MPE operation at the extraction well EW-1 . The system components included 4 extraction wells, phase separator, liquid ring pump, system control panel, for vapor and liquid treatment are being designed. System flow chart is provided. By running the MPE, there is better hydraulic control and source removal. RAP is approved conditionally: 1) add the air exhaust in the system flow chart. 2) reinstall the MW-1, MW-3 and MW-4 due to their screen interval starts at the water table or below the water table. 3) Investigate the impact to the subway tunnel right next to the station (N, R and F trains run along 4th Ave). (RJF) 8/2/2006 - Feng - Approval of MPE letter sent to BP and cc to Delta. (RJF) 9/26/2006 - Feng - Quarterly

KAM SERVICE CENTER INC (Continued) **1000556241**

Monitoring Report, 2Q2006, 9/7/2006, by Delta. Sampled and monitored on 6/19/2006. DTW 10.60' to 14.42' bg, flows to northwest. 10 of 11 monitoring wells were sampled. MW-2 was not accessible. MW-1, 8,012 ppb BTEX, 28,200 ppb MTBE. MW-3, 16,430 ppb BTEX, 8,540 ppb MTBE. MW-4, 37,250 ppb BTEX, 32,400 ppb MTBE. MW-5, 59.1 ppb BTEX, 5.4 ppb MTBE. MW-6, 0.25 ppb BTEX, 2.8 ppb MTBE. MW-7, 569 ppb BTEX, 6.1 ppb MTBE. MW-8, BTEX ND, 0.71 ppb MTBE. MW-9, 10,688 ppb BTEX, 4,620 ppb MTBE. MW-10, 21,300 ppb BTEX, 63,500 ppb MTBE. EW-1, 8,055 ppb BTEX, 5,250 ppb MTBE. (RJF) 9/28/2006 - Feng - Portfolio meeting with BP and Delta. Plan changed for this site. On 8/2006, Delta had the plan in place for redevelopment and construction of high rise building. There will be multi-story basement, USTs will be pulled and additional soil will be removed. Construction schedule will be confirmed and remedial plan will start from the groundwater quality after tanks removal. (RJF) 3/6/3007 - Feng - 3Q2006, 12/21/2006. Groundwater sampled and gauged 9/13/2006. 11 monitoring wells were sampled. DTW 10.68' to 14.36' bg. Flows northwest. LNAPL in MW-9 (0.12'). MW-1, 9,350 ppb BTEX, 21,100 ppb MTBE. MW-2, 2,840 ppb BTEX, 3,330 ppb MTBE. MW-3, 20,990 ppb BTEX, 10,400 ppb MTBE. MW-4, 38,920 ppb BTEX, 33,500 ppb MTBE. MW-5, 35.4 ppb BTEX, 4.6 ppb MTBE. MW-6, 1.42 ppb BTEX, 4.6 ppb MTBE. MW-7, 677 ppb BTEX, 8.1 ppb MTBE. MW-8, ND. MW-9, 16,780 ppb BTEX, 14,200 ppb MTBE. MW-10, 17,760 ppb BTEX, 44,900 ppb MTBE. EW-1, 12,180 ppb BTEX, 8,260 ppb MTBE. Email Delta for status on tank pull, site development and RAP. (RJF) 3/6/3007 - Feng - Updates from D. Greffenius (Delta), the USTs, piping, and dispenser removals will begin on Monday, March 12, 2007. Alvin Petroleum is the contractor. 3/6/2007 - Feng - email from D. Taylor (Delta), USTs will be removed and endpoint samples will be taken and Closure report will be submitted. Delta are currently in touch with the site owner who hasn t yet provided the development schedule. (RJF) 7/24/2007 - Feng - 4Q2006, 4/30/2007. Groundwater sampled 12/7/2006. All 11 monitoring wells were sampled. DTW 10.42' to 14.17' bg. Flows to northwest. No LNAPL. MW-1, 7,750 ppb BTEX, 9,800 ppb MTBE. MW-2, 2,754 ppb BTEX, 1,340 ppb MTBE. MW-3, 10,370 ppb BTEX, 5,350 ppb MTBE. MW-4, 31,030 ppb BTEX, 14,300 ppb MTBE. MW-5, 47.7 ppb BTEX, 4.4 ppb MTBE. MW-6, 1.94 ppb BTEX, 4 ppb MTBE. MW-7, 650 ppb BTEX, 4.7 ppb MTBE. MW-8, BTEX ND, less than 1 ppb MTBE. MW-9, 9,510 ppb BTEX, 3,630 ppb MTBE. MW-10, 17,180 ppb BTEX, 15,900 ppb MTBE. EW-1, 9,850 ppb BTEX, 3,640 ppb MTBE. (RJF) 7/27/2007 - Feng - 1Q2007, 5/7/2007. Groundwater sampled 3/7/2007. 9/11 monitoring wells were sampled. DTW 11.51' to 14.6' bg. Flows to north-northwest. No LNAPL. MW-1, 6,936 ppb BTEX, 4,930 ppb MTBE. MW-2, 2,820 ppb BTEX, 632 ppb MTBE. MW-3, not accessible. MW-4, 40,800 ppb BTEX, 34,800 ppb MTBE. MW-5, well not located. MW-6, ND. MW-7, 468 ppb BTEX, 3.1 ppb MTBE. MW-8, ND. MW-9, 9,160 ppb BTEX, 2,230 ppb MTBE. MW-10, 24,490 ppb BTEX, 7,960 ppb MTBE. EW-1, 10,430 ppb BTEX, 2,460 ppb MTBE. (RJF) 7/31/2007 - Feng - Underground Storage Tank Excavation Assessment Report, 4/26/2007, by Delta. Between 3/12/2007 and 3/15/2007, 4 (4,000-gallon) double-walled steel gasoline USTs and 1 (4,000-gallon) double walled steel abandoned UST from a single tank cavity on the central portion of the site were excavated. The abandoned UST was filled with concrete slurry. Upon excavation, the tanks were observed to be in good condition with no visible holes or areas of pitting. Between 3/16/2007 to 3/20/2007, 4 pump island dispensers and the associated product piping were excavated and removed. On 3/12/2007, 1 hydraulic lift was removed. 25 over-excavation soil samples were collected. High contamination

KAM SERVICE CENTER INC (Continued) **1000556241**

detected in soil samples. For USTs excavation, the total BTEX range from ND (SW-17) to 1,796,700 ug/kg in SW-5 (9'), the total VOCs ranged from 205 ug/kg in SW-14 (9') to 2,828,170 ug/kg in SW-5 (9'). For the pump islands and piping excavation, total BTEX concentration ranged from ND in B-13 (12-12.5') to 327,700 ug/kg in B-2 (12-12.5'), the total VOCs concentration ranged from ND in B-3 to 659,890 ug/kg in B2 (12-12.5'). For the hydraulic lift excavation, no SVOCs exceedance. Groundwater encountered at a depth of 13' bg. 1 groundwater sample was taken from MW-4, 40,800 ppb ug/L BTEX, 34,800 ug/L MTBE. On 3/28-29/2007, 795.24 tons of soil was generated during the over excavation activities. The soil was transported an disposed at the Clean Earth of Philadelphia (CEP). The excavations were backfilled with the Certified Clean Fill. 8/1/2007 - Feng - Letter to Kevin Endriss (BP) requiring RAP and the construction details. Due 10/1/2007. (RJF) 10/10/2007 - Feng - Portfolio meeting with BP and Delta. Potentially developing the site. Tanks closure done and soil over-excavated. Drill at the side near the subway to inspect for impact on the subway tunnel. The new development may need to excavate down to 30 feet bg. Development schedule is unknown at this point. Delta will submit a work plan for proposing MPE events on 2 wells for short term remediation. (RJF) 12/10/2007 - Feng - Call from potential buyer and inquired about the site status. DEC stated the requirement of gw and soil remediation, plus the soil vapor mitigation. Buying is in process. (RJF) 1/11/2008 - Feng - Reviewed various documents submitted by HydroTech. 1) Phase I Environmental Site Assessment Report, dated 10/12/2007. Some Recognized Environmental Concerns were identified: the E Designation listing of the site for HAZMAT; historical utilization of the site as an auto repair facility and a gasoline station; presence of an open NYSDEC spill at the site; presence of elevated levels of VOCs in the soil and groundwater at the site at concentrations exceeding regulatory standards; inconsistent PBS information. 2) Investigation Work Plan, dated 11/27/2007. Investigation were proposed to be conducted in addressing the E Designation. HydroTech proposed GPR Survey to scan for any subsurface anomalies such as unknown tanks; to install 12 soil borings and 2 soil samples will be taken from each soil boring; and 3 groundwater probes will be installed for groundwater sampling. Site plan with proposed soil boring location is provided. 3) Site Investigation Report, dated 12/20/2007. The GPR Survey did not identify any significant anomalies. Gasoline contaminated soil is present in the shallow soil in the northern and northwestern portions of the site. The gasoline contamination extends vertically to the deeper depths of the soil and horizontally to the northwestern boundary and western portion of the site. Soil samples collected from HTE-SP-2, 662,600 ppb VOCs at 2'-4', 934,900 ppb VOCs at 10'-12'. Groundwater was encountered at 12 feet bg and flows to northwest. The compounds detected in the groundwater plume are mainly gasoline compounds, range ND to 79,300 ug/L. 4) Remedial Action Plan, 12/14/2007. HydroTech proposed to have 1) soil excavation, down to 12'; 2) installation vapor barrier and sub-slab venting system; 3) RAP for groundwater will be submitted to NYSDEC. 5) Floor Plans for the new building. The new building will be occupied the whole site. Called Yash Saha (HydroTech). The excavation will cover the whole site and down to 12'-14', no dewatering is planned. DEC required the vapor barrier and sub-slab venting system design, groundwater remediation. HydorTech will submit a RAP including the soil excavation, groundwater remediation, and soil vapor mitigation

KAM SERVICE CENTER INC (Continued) **1000556241**

shortly. (RJF) 2/7/2008 - Feng - Reviewed the Revised RAP, 1/31/2008, by HydroTech. HydroTech proposed: 1) soil excavation; 2) installation of vapor barrier and sub-slab venting system; 3) RegenOx and ORC injections for groundwater remediation. Reveiwed also the 3Q2007 quarterly report. During the tank excavation activities in 3/2007, monitoring wells MW-1, MW-5, MW-9 and EW-1 were destroyed. 7/11 wells were sampled. BTEX range 73 ppb (MW-6) to 15,260 ppb (MW-4). MTBE range 18 ppb (MW-6) to 47,200 ppb (MW-4). Emailed HydroTech the comments and questions. (RJF) 2/15/2008 - Feng - Stipulation Agreement to Katan Group. Due back 3/7/2008. (RJF) 2/27/2008 - Feng - Received signed Stipulation Agreement. Sent for RD's signature. (RJF) 3/3/2008 - Feng - Reviewed the Revised RAP, 2/13/2008, by HydroTech. Addressed the comments provided on 2/7/2008. Approval letter to Katan Group and cc to HydroTech. DEC require the vapor barrier to be extended vertically to the surface grade through the foundation walls and more RegenOx injection points to be installed. Revised the vapor barrier design and the injection diagram will be submitted within 10 days. (RJF) 3/7/2008 - Feng - Spoke to D. Greffenius (Delta). BP will also oversee the remediation progress occuring onsite. An addendum letter/plan will be submitted for post-excavation sampling, dewatering plan in case dewatering is needed, and monitoring plan after the construction. BP will still continue to comply with the Stipulation between BP and DEC. (RJF) 3/13/2008 - Feng - Stipulation Agreement executed 2/28/2008. (RJF) 4/17/2008 - Feng - Email to HydroTech regarding the notification of chemox injection to EPA UIC program. HydroTech contacted EPA and it may take 30 days to have EPA review the details of the injections. Letter for offsite soil vapor point to HydroTech. 4/18/2008 - Feng - Call from HydroTech (Yash). HydroTech will inject the ORC while installing the soil vapor points. ORC will be injected at the sidewalk across the 4th Ave and some onsite injection points. (RJF) 4/24/2008 - Feng - email from Yash Saha (HydroTech). HydroTech has finished the onsite ORC injection and the soil gas implants offsite. (RJF) 5/1/2008 - Feng - Site visit. Met with Carlos Quinonez from HydroTech. The tech team was late. The work will be rescheduled. 5/2/2008 - Feng - Site visit and met with Yash Saha. Started RegenOx injection using GeoProbe. The intended injection points were marked. It will be drilled down to 25 feet and the RegenOx will be injected into the 25 feet to 16 feet. Planned to finish 10 point today. Offsite soil vapor sampling also ongoing. According to Yash, there will be some dewatering activities along with the development. Dewatering water will need to be treated. Met with D. Greffenius (Delta) in DEC office. Received the IRAP. (RJF) 5/9/2008 - Feng - cc-d the EPA Underground Injection Control section's letter to Katan group for authorization to inject RegenOx and ORC. (RJF) 6/12/2008 - Feng - Called from Yash (HydroTech). All the RegenOx injections are completed at this time. They started the site excavation on 6/4/2008, so far at 8 feet bg, and had some foundation pillars installed. The elevator shaft part has not worked on yet. At this time, no work on site, but may excavate deeper later on. DEC still requires groundwater samples to confirm the effectiveness of the RegenOx, taken gw samples from the previous baseline sampling points. 6/16/2008 - Feng - 4Q2008, 3/18/2008, by Delta. The monitoring well network was gauged and sampled on 1/17/2008. 7 wells. DTW 11.01' to 14.88' bg. Flows to northwest. BTEX range ND to 18,500 ppb (MW-10). MTBE range ND to 21,000 ppb (MW-4). 6/18/2008 - Feng - Portfolio meeting with BP and Delta. In 6/2008, soil removal is about 4,600 tons. Delta is submitting the final

KAM SERVICE CENTER INC (Continued) **1000556241**

version of IRAP. The exhaust blowers planned for building's lower parking levels will control vapors. No sub slab venting system might be installed since the basement is so close to water table. Conference call with BP/Delta, Katan/HydroTech will be scheduled. (RJF) 7/28/2008 - Conference call with Delta (D. Greffenius and G. Hinshalwood) and HydroTech (Rachel). Delta and HydroTech will be sending the brief summary of the site status. (RJF) 9/17/2008 - Vapor complaint from the resident across the street. DEC has contacted and required the developer (Perry Soskin from Katan Group) and the RP (BP) to immediately mitigate the vapor by today. Mr. Soskin from Katan Group and David Greffenius from Delta called back. Delta and EnviroTrac will be onsite and lay the plastic sheeting on the area today. They will there around 4:30pm. Tomorrow they will cover with a few loads of fills and more plastic sheeting on top of the fills if necessary. Called the resident David Simonoff and informed him that the responsible party will be onsite start taking of the odor today and DEC will continue to monitor the situation. (RJF) 9/17/2008 - Site visit and met with Delta and EnviroTrac. The north portion of property near the 5th Street is filled with water, half foot to one foot deep. Delta and EnviroTrac lay the plastic sheeting on the waterly area with some product, next to 4th Ave and east portion. A vac truck will be mobilized tomorrow morning and remove the water before the backfills. (RJF) 10/16/2008 - Letter to Katan Group and BP requiring the developer/RP to submit a Revised RAP which include monitoring wells installation around the property to access the current and during construction groundwater condition, dewatering plan, post construction remediation plan if necessary, and post construction groundwater monitoring plan. Revised RAP due 11/17/2008. The Department notifies the city agencies, DOB, DEP, and DOH on the site status and its intended development. (RJF) 10/29/2008 - 1Q2008, 7/25/2008, by Delta. Vacant. The monitoring well network was gauged and sampled on 3/6/2008. During tank excavation activities in 3/2007, MW-1, MW-5, MW-9, and EW-1 were destroyed. Due to construction onsite during first quarter 2008, all onsite wells are covered with soil and gravel and are suspected to be destroyed. 3 were were gauged (offsite wells). No LNAPL. DTW 14.04' to 14.78' bg. Flows to northwest. 3 were sampled. BTEX range ND to 407 ug/L (MW-7). MTBE range ND to 2.8 ug/L (MW-6). 2Q2008, 9/29/2008, by Delta. Vacant. The monitoring wells were gauged and sampled 6/30/2008. 3 offsite wells were gauged. No LNApL. DTW 13.48' to 14.12' bg. flows to northwest. 3 wells were sampled. BTEX range ND to 486 ug/L (MW-7). MTBE range ND to 1.9 ug/L (MW-6). (RJF) 11/10/2008 - Vapor complaint received from resident adjacent to the site. Visited the site, no access because the site was locked. Walked around the site and did not observe odor. No PID reading. Water retained in the open excavation again. (RJF) 11/10/2008 - Email to Bill Bogdon approving the 60 days extension for RAP. (RJF) 11/12/2008 - Delta and EnviroTrac were onsite to mitigate the vapor. A vac truck was mobilized and vac out the product in the property line area and water. Delta and EnviroTrac will then cover the area with product and rest of the water. They will come back tomorrow to see if water level rise again. Soil backfill may be done if necessary. (RJF) 12/10/2008 - Email from David Greffenius (Delta) Please note that Delta and EnviroTrac, on behalf of Atlantic Richfield, will be transporting additional backfill to the 363 4th Avenue, Brooklyn site this Friday, December 12, 2008, in order to fill-in the remaining standing (ground) water at this site for the purpose of preventing another vapor complaint by the residents in

KAM SERVICE CENTER INC (Continued) **1000556241**

this neighborhood. Our plan will be identical to our last effort: we will cover the standing water with plastic (where it is safe to do so), and then cover the plastic/water with between 4 and 6 loads of recycled concrete aggregate (RCA) backfill. 12/17/2008 - Spoke with David Greffenius (Delta). The excavation where been with water is backfilled. The product seems coming back again. Might need to investigate the adjacent parking lot. (RJF) 12/18/2008 - Visited the site and met with David Greffenius. The site is backfilled in most of the area with water. Some water is still retained near the back apartment building. No product was seen this time. David will stop by regularly to check if there is any recharge of the product. SanBorn maps may be reviewed for the parking lot next door. (RJF) 1/20/2009 - Met with Domenick Tonacchia (Tona Development), Bill Bogdon (Tona Development), Kevin Kleaka (Impact Environmental), and phone conference with David Greffenius (Delta). There will no dewatering. The building will be covered the entire site with cellar, no subcellar. There will be changes for the new building since they are trying to avoid dewatering process. DEC required an investigation work plan for both onsite and offsite by 2/2009. (RJF) 3/20/2009 - Reviewed Investigation Work Plan, dated 3/3/2009, by Delta. Delta proposes to install 7 monitoring wells at the sidewalks around the perimeter of the site. Work to be scheduled and RI report to be due within 90 days, 6/19/2009. Work Plan is approved. Letter to BP and cc to Delta. (RJF) 3/23/2009 - Reviewed the Investigation Work Plan, dated 2/2009, by Leggette, Brashears & Graham, Inc (LBG). LBG proposes to install 4 monitoring wells onsite within the perimeter. Comments to LBG and Tona Development via email. see comments in eDoc. (RJF) 3/24/2009 - Reviewed LBG's responses to the comments on the IWP, uploaded in eDocs. Additional comments on the responses were sent to LBG and Tona Development, in eDocs. (RJF) 4/3/2009 - Reviewed the Updated IWP, via email on 3/25/2009, by LBG. Previous comments are addressed. Work plan to be approved. Letter to Tona Development and LBG. 4/3/2009 - Conference call with BP, Delta, Tona Development and LBG. The offsite wells installation will be started within 2 weeks. The onstie will be within 1 week. Tona Development will advance some test pits to verify the real water table and will notify BP 2 days in advace so BP could send a field technician to the site. Changes to the development plan will be made, the basement slab will be above water table. DEC require the RAP should include the vapor barrier and SSDS. Stipulation agreement will be sent to Tona Development. (RJF) 4/6/2009 - Stipulation Agreement to 267 Sixth Street, LLC. eDocs. (RJF) 4/28/2009 - Conference call with Tona Development and Delta. The onsite wells are installed and the report will be sent to DEC and Delta. Sewer line is identified beneath the sidewalk. A Con Ed oil line is also identified between the sidewalk and the site and might be extented into the site. Hand clearance will be made during the installation of the offsite wells. The test pits were advanced down to 9-10 feet below current grade, and found groundwater at 5 feet in one of them. Construction excavation will be above/at water table. Tona will be moving the soil around this week to make the ramp for the machines entrance. A plan to suppress the possible odor shall be in place before the excavation. And soil shall be tested for disposal and this enable the soil to be disposed immediated when being generated. Delta will review the Tona's recent investigation report to come up the IRAP, remedy to be proposed depend on the current site condition, soil and groundwater residual. Next updates call will be held upon the submission of IRAP. (RJF)

KAM SERVICE CENTER INC (Continued) **1000556241**

7/7/2009 - Reviewed Subsurface Investigation Report, dated 5/13/2009, by Leggette, Brashears & Graham, Inc. On April 9, 2009, the groundwater monitoring wells were installed onsite. Soil samples were collected continuously through the boring from the excavation grade to approximately 15 feet below the excavation grade. The final boring depth is approximately 20 feet below the historical grade of the site. The wells were surveyed. DTW 4.54' to 10.55'. no product was encountered, but film was observed. Soil samples run for VOCs and SVOCs. VOCs and SVOCs exceedances were detected, unit in ug/kg. MW-21, 10-15 feet, 920 benzene, 770 toluene, 30,000 ethylbenzene, 22,700 xylenes. MW-22, 5-10 feet, 6,200 benzene, 100,000 toluene,, 120,000 ethylbenzene, 400,000 xylene, 1,100 MTBE. MW-25, 10-15 feet, 1,500 benzene, 11,000 toluene, 43,000 ethylbenzene, 183,000 xylene. Groundwater samples were run for VOCs and SVOCs. Exceedances were detected, unit in ug/L. MW-21, 360 benzene, 300 toluene, 1,300 ethylbenzene, 1,480 xylene, 610 MTBE. MW-22, 230 benzene, 3,700 toluene, 2,300 ethylbenzene, 7,900 xylene, 28 MTBE. MW-25, 1,200 benzene, 620 toluene, 3,500 ethylbenzene, 6,200 xylene, 1,100 MTBE. And SVOCs were also detected in these wells. Compared to the historical soil and groundwater concentration levels, data show down trend for most of the wells. The data gained from this investigation will be used in preparing of the IRAP. Email BP and Delta for the status of the IRAP. (RJF) 7/14/2009 - Conference call with Tona Development, BP and Delta. Delta is putting together the LBG's report data and the new building plan, the IRAP will be submitted next week. Delta is also going through the MTA permitting process to have the wells installed at the sidewalk along 4th Ave. There are probably 3-4 feet of soil to be removed, no dewatering. Film = sheet in LBG's report. DEC required there are shall be wells being able to monitor the effectiveness of Delta's proposed remedy. BP will gauge and sample the onsite wells after the perimeter wells are in. (RJF) 1/4/2010 - Reviewed Work Plan for Offsite Monitoring Wells Abandonment, dated October 12, 2009, by Delta. Delta will abandon the three monitoring wells across 4th Ave, MW-6, MW-7 and MW-8. (RJF) 1/12/2010 - Reviewed Subsurface Hydrocarbon Assessment Report Addendum, dated October 29, 2009, by Delta. On June 19, 2009, EnviroTrac, on behalf of Atlantic Richfield and under the direction of Delta, installed one permanent two-inch monitoring well (MW-13) at the northeast sidewalk of 6th Street using Geoprobe 6610 hollow-stem auger drill rig with direct push, macro-core sampling capability. MW-13 was drilled to 18 feet and groundwater was encountered at 12 feet. 2 soil samples were collected. MW-13 (11.5-12'), VOCs ND. MW-13 (19.5-20'), VOCs ND. On September 21, 2009, MW-13 as well as the monitoring wells onsite MW-20, MW-21, MW-22, MW-23, MW-24 and MW-15 were gauged and sampled. DTW 6.31' to 12.63' bg. NO LNAPL. unit in ug/L. MW-13, ND. MW-20, 7.6 benzene, 26 MTBE, 6 isopropylbenzene, 9.4 n-propylbenzene, 61 total VOCs. MW-21, 350 benzene, 290 toluene, 1,250 ethylbenzene, 860 xylene, 2,750 BTEX, 430 MTBE, 34 n-butylbenzene, 18 sec-butylbenzene, 87 isopropylbenzene, 10 p-isopropylbenzene, 520 naphthalene, 240 n-propylbenzene, 590 1,2,4-trimethylbenzene, 140 1,3,5-trimethylbenzene, 4,819 total VOCs. MW-22, 140 benzene, 810 toluene, 1,450 ethylbenzene, 420 xylene, 2,820 BTEX, 76 MTBE, 11 n-butylbenzene, 32 isopropylbenzene, 7.1 p-isopropylbenzene, 260 naphthalene, 60 n-propylbenzene, 250 1,2,4-trimethylbenzene, 100 1,3,5-trimethylbenzene, 3,621 total VOCs. MW-23, ND. MW-24, 21 MTBE, 27 total VOCs. MW-25, 1,100 benzene, 440 toluene, 2,790 ethylbenzene, 2,600 xylene, 6,930 BTEX, 390 MTBE, 25

KAM SERVICE CENTER INC (Continued) **1000556241**

n-butylbenzene, 15J sec-butylbenzene, 170 isopropylbenzene, 14J p-isopropylbenzene, 280 naphthalene, 300 n-propylbenzene, 830 1,2,4-trimethylbenzene, 400 1,3,5-trimethylbenzene, 9,354 total VOCs. Off-site Monitoring Well Abandonment Report, dated December 30, 2009, by Delta. On October 21, 2009, EnviroTrac, on behalf of Atlantic Richfield, abandoned offsite wells MW-6, MW-7 and MW-8 by 1) removing the bolt-down cover and riser cap from each well; 2) tremmie-filling each well screen and riser pipe with Portland cement/bentonite slurry from the bottom of the well to 5 feet bg using a grout pump; and 3) filling the top 5 feet of riser pipe and the flush-mount cover of the each well with Portland cement to the groundwater surface. (RJF) 3/10/2010 - Neil Steven (646-542-4312) from Law Enforcement Region 2 called. Odor complaint from the residents. He went to the site yesterday, there was strong odor and dark product. Email to Nick Onufrak (BP), Bill Bogdon (Tona Development) and David Greffenius (Delta). Bill and Nick, DEC received a odor complaint from the nearby residents for this site. Our ECO went to the site yesterday and he said there was strong odor and dark product was witnessed. You MUST send someone out there TODAY, to take pictures, sample the product, remove the product and mitigate the odor. If nobody is there today, we will send contractor out tomorrow and bill everybody. Called and spoke with Nick Onufrak. He will call EnviroTrac and see what they can do, and give us an update by the end of today. Call Domenick (Tona Construction), he will send out someone to check out. Forwarded him the email since Bill is no longer with Tona. (RJF) 3/10/2010 - email from Gordon Hinshalwood (Delta). We investigated SS 13397 today in response to your email below. Some soil staining was identified in the rear area of the site, but free-phase NAPL was not identified on the standing water in the excavation, nor were hydrocarbon odors identified. We plan on delivering a frac tank to the property tomorrow afternoon and pumping the standing water out of the excavation (the volume of water is reportedly too large for a vac truck to handle). We will store the water in the tank on-site until we can arrange for it's proper disposal. We also intend to backfill the excavation to prevent further water accumulation on-site, which will likely happen on Friday, or early on next week. 3/11/2010 - closed the spill 09-12838 opened for receiving the odor complain from Cynthia Simonoff and refer to spill 89-01904. Called Ms. Simonoff and told her that BP will be there this afternoon to vac the water out and will do some backfill by Friday. (RJF) 3/11/2010 - NYCDEP called and claimed there was odor and product onsite. DEC Tibbe visited the site and met Dave Greffenius (Delta) and EnviroTrac. There was a petroleum odor but it was not significant. There was some floating product and sheen on the water in the excavation, and there was stained soil most of the way around the excavation, at water level. Delta was directed to sample the oil and excavate the stained soil. DEC also required addressing any floating product, if there is any, during the monthly gauging event. DEC emailed to Delta and required the submital of RAP to address the soil and groundwater, regardless of the potential development, because the schedule is unknown. Draft prposal or a review of alternatives by 3/2010. (RJF) 3/17/2010 - email from Nick Onufrak (BP). They will be onsite to pump out more water and backfill some of the excavation Wednesday and Thursday. Domenick (Tona Development) is aware of the work. DEC responded to the Yvonne Schmitz's inquiry. (RJF) 4/7/2010 - received complaint and spill 1000269 was opened. DEC Spill staff visited the site. The responder did not detect any petroleum odors and from his vantage

KAM SERVICE CENTER INC (Continued) **1000556241**

point outside the fence, could not see floating product, but he did see standing water in the excavation. DEC email to BP and Tona Development requiring that the issue of standing water in the excavation must be rectified in order to prevent future impacts to the area residents as well as reduce and/or eliminate future complaints. The only way could be pumping out the water and completely fill the excavation to grade. DEC requires arrangements to complete this task immediately. Email from David Greffenius and attached with LNAPL Forensic Analysis Letter Report. Based on the fingerprinting forensic analysis of the sample collected from the top of the standing water, the floating oil was determined to be a relatively fresh diesel/fuel oil product probably released within the last two years. Based on BP's underground storage tank (UST) registration records, no diesel or fuel oil USTs were registered at the subject site from 1990 forward. 4/8/2010 - email from David Greffenius. EnviroTrac will begin water pumping opeartion tomorrow and site backfilling is scheduled for next week. 4/9/2010 - Letter from BP committing to address the odor complaint issue in a timely fashion and the spill remediation. 4/12/2010 - letter to NYC DOB, DOH, DEP notifying the open excavation issue at the site. 4/13/2010 - email from David Greffenius. Additional water pumping and removal, and site backfilling activities are scheduled to begin on Thursday, April 15. They are planning to bring in 1,000-1,500 yards of additional backfill material to the site (1,500-2,500 tons) over a 2-3 days period. checked spill 97-05330 at 278 6th Street. No investigation has been done at this site. PBS record 2-603857 at 383-393 4th Ave 278 6th Street show one 550-gallon kerosene (#1 fuel oil), one 275-gallon #2 fuel oil, one 4,000-gallon diesel, and one 4,000-gallon gasoline were removed in 3/2008. But no tanks closure report in file. 4/14/2010 - DEC Zhune called the owner of 278 6th Street. The property is sold already and he will call the consultant who did the closure to send the report in. 6/8/2010 - DEC responds to the Dailey News inquiry. Documentation of the backfill of the excavation including 3 photos taken after the backfill on 4/19/2010 were received from Delta. As seen from the photos, the backfill is up to the street level, and the monitoring wells are still in place. 6/9/2010 - DEC inspected the site around 9am and took some photos. No petroleum odors noticed. NO sign of contaminated soil was found. 4Q2009, 3/2/2010, by EnviroTrac. Currently a vacant lot. The monitoring well network was gauged and sampled on 12/28/2009. Due to site flooding several wells were inaccessible during the 12/2009 event (MW-21, MW-22, MW-23, MW-24 were under water) and were subsequently gauged and sampled on 1/22/2010. 6 wells were gauged. No LNAPL. DTW 3.76 - 12.82 (below existing grade?). Flows to northwest. historic flows to south. 6 wells were sampled. MW-24 was under water, not sampled. Max benzene 490 ug/L (MW-25). Max BTEX 2,820 ug/L (MW-25). Max MTBE 120 ug/L (MW-25). 1Q2010, 5/17/2010, by EnviroTrac. The monitoring well newtork was gauged and monitored on 3/25/2010. 7 wells were gauged. NO LNAPL. DTW 2.19 - 10.23' (below existing grade?). Flows to northwest. 7 wells were sampled. Max benzene 9.1 ug/L (MW-22). Max BTEX 248.6 ug/L (MW-21). Max MTBE 10 ug/L (MW-24). 7/20/2010 - Reviewed Remediation Work Plan for Chemical Oxidation Solution Pilot Application, dated July 12, 2010, by Delta. During the week of June 21, 2010, Delta installed 6 soil borings in the portion near the 4th Ave. SB-8 (12-13'), 1,302,600 ug/kg total VOCs. SB-8 (20-21'), 12,568 total VOCs. SB-9 (8-10'), 1,884 total VOCs. SB-9 (19-20'), 525 VOCs. SB-10 (7.5-10'), 828,240 VOCs. SB-10 (15-16'),

KAM SERVICE CENTER INC (Continued) **1000556241**

217 total VOCs. MW-14 (11-12'), 167,549 total VOCs. MW-14 (17-18'), 15,788 total VOCs. MW-15 (7.5-10'), 318,470 total VOCs. MW-15 (14-15'), 15,908 total VOCs. 3 soil borings turned into MW-14, MW-15 and MW-16. soil sample was not recovered and therefore no sample was collected for MW-16. Delta proposes to inject iron activated sodium persulfate and a pilot will be conducted first. 2 application wells AW-1 and AW-2 will be installed in the northwest portion of the site. The application wells will be installed to 15 feet bg with 10 feet 4-inch diameter screen. 500 gallon of sodium persulfate/EDTA-chelated Fe(II) solution (0.50 kg/gal/0.01 kg/gal EDTA-Fe(II) as Fe) will be added into the two application wells. Surrounding wells MW-15, MW-16 and MW-22 will be monitored. Pre-application sampling will be included BTEX/MTBE, sulfate, DO, pH, ORP, and alkalinity. Sampling will be also conducted the day of the application, following day, and weekly for 2 weeks. Anticipated the pilot to be conducted the final week of 7/2010. ChemOx pilot work plan is approved. Report due 8/2010. 10/26/10 The site is temporarily reassigned to Alex Zhitomirsky as per V. Brevdo and M. Tibbe. I went to the site today. There is some standing water and some residential garbage at the site. I could not smell any odor. An e-mail with my findings was sent to V. Brevdo and M. Tibbe. AZ 4/11/2011 - Spill transferred back to JFeng. 6/24/2011 - On June 24, 2011, DEC reviewed the work plan proposing full scale ChemOx injection. Then DEC was also notified by the developer that they have financing coming into place and plan again to develop the site. A conference call was held on June 28th with BP, its consultant, and the property developer. The developer is planning to construct a building with a full basement that will cover the entire footprint of the property; with the basement only to a depth at which dewatering will not be needed. As such, BP will need to change plans the developer agreed to provide us with their construction drawings, and BP agreed to provide a work plan for a focused investigation to determine whether they could over-excavate to remove remaining impacts; we also spoke about the need for continued gw monitoring which would likely need to include wells in the basement. 8/1/2011 - Reviewed Soil Investigation Work Plan, dated 7/14/2011, by Antea Group. 8 soil borings were proposed in order to identify remaining soil contamination. Comments: the drilling should be beyond the historical contamination depth until hitting clean soil; sewer information in the sidewalk of 4th Ave; the 1997 misfiled oil burner replacement Block 987 Lot 11, but address 363 4th Ave; and if this site is a e-designated site under NYC DEP. 8/9/2011 - meeting with BP and Antea Group. Discussed the submitted IWP. DEC required the drilling down to the clean depth in order to vertically profile of the soil and identify remaining soil contamination. Revised IWP will be submitted. 9/9/2011 - reviewed additional revision of the IWP submitted via email by Antea Group on 9/5/2011. reduced PID reading is defined as immeasurable reading. So soil samples from the water table interface, highest PID reading, reduced PID reading, and 3 feet below reduced PID reading will be taken. 9/9/2011 - approved IWP for installing 8 soil borings to assess the current soil condition. Report due 12/2011. 10/27/2011 - 2Q2011, 9/7/2011, by Antea Group. The groundwater samples were collected on June 6, 2011. 10 wells were sampled. NO LNAPL. BTEX concentration increased from the last quarterly sampling results. MW-14, 36,320 ug/L BTEX, less than 25 ug/L MTBE. MW-15, 8,230 ug/L BTEX, less than 5.0 ug/L MTBE. MW-21, 1,060 ug/L BTEX, 97 ug/L MTBE. MW-25, 195 ug/L BTEX, 21 ug/L MTBE. 11/22/11 - Raphael Ketani. Arnie Fleming of Fleming-Lee-Shue (212)

KAM SERVICE CENTER INC (Continued) **1000556241**

675-3225 called me today about the case. He said that FLS is the consultant for the new developer. The site has an E designation. He said that BP is moving slowly on remediating the site. However, the site was excavated and oil flowed out from the east wall. Mr. Fleming stated that there is a yard area that belongs to the condominium building next door and that this would be a good place to do the investigation. However, the condominium has not been cooperative about letting BP's crew on the neighboring property. I told Mr. Fleming to send DEC the contact information for the condominium and we will pursue aquiring access for an investigation on their property. He said that he will. 11/22/2011 - As per Ketani, spill 11-10410 was generated for the offsite issue. 11/23/2011 - sent via email to Naftali Group LLC the stipulation agreement along with corrective action plan. As per DEC Ketani, sent letter notifying petroleum contamination at 270 Fifth Street and required investigation. Response is required within 15 days in receipt of the letter. Letter was sent to: 270 Fifth Street Corp. 270 Fifth Street Brooklyn, NY 11215 BPC Management 84 Livingston Street Brooklyn, NY 11201 11/29/2011 - Reviewed Investigation Summary Report, dated October 28, 2011, by Antea Group. 6 soil borings were installed in the central portion and western portion along 4th Ave of the site. The borings were advanced to 20 to 30 feet bgs where a peat layer was encountered. Very high total VOCs and SVOCs were detected in various location. For total VOCs in soil samples ug/kg, SB-26 (7.5-9) 54,300, (15-16) dark NAPL stain 17,801, (20-21), 30.2. SB-29 (10-11) 155,380, (13.75-14.25) odd staining 236,111, (27-28) 26.19. SB-30 (7.25-8.25) staining 251,429, (22.33-22.66) stain with product 18,287, (25-26.33) 23,781. SB-31 (3.5-4) 108,609, (9-10) odor sheen on acetate 1,017,620, (29-30) 8,217. SB-32 (3.5-4) 2,990, (10-15)17,024, (20-22) 334.7. For SVOCs, SB-26 (15-16) 1,907,400. SB-30 (22.33-22.66) 1,653,800. Antea concluded that soil contamination were identifed in the central area of the site and along western border by 4th Ave. Varied depth 3.5 to greater than 20' and soil staining showed visible evidence of a heavier than gasoline grade of hydrocarbon in some location. Excavation alone may not be possible to remediate. Will propose vapor barrier and SSDS and development of a post construction remediation strategy to address the impacts. 11/30/2011 - letter to BP and requiring a RAWP to be submitted by 1/2012. DEC require the contaminated soil to be excavated, install hydraulic barrier to prevent site recontamination by the seeping oil, and vapor barrier + SSDS for the future building. The letter which was sent to the apartment building was attached as per DEC Paul John's request. 12/9/11 - Raphael Ketani. Today there was a conference call with Arnie Fleming of Fleming Lee Shue, Hassan Hussein, head of the Hazardous Materials Unit, June Feng, project manager, and myself. Mr. Fleming commented about the oil seep that was coming in from the east side of the property. I told him that the DEC wanted BP to excavate down about 16 feet at each location that showed excessive contamination (above CP-51 standards). Mr. Fleming said that BP had made a determination that these locations were too deep to excavate. Wells would be put in the sidewalk. Mr. Fleming also stated that he had bad experiences with installing wells through a vapor barrier. Once you open the wells to sample them, then the vapors come out and the VOCs are suddenly high in the building. He added that his client, the latest developer, was willing to install a 150 foot long curtain to prevent the oil from seeping onto the property. They would excavate to 10 feet below grade, the foundation level, and drive

KAM SERVICE CENTER INC (Continued) **1000556241**

sheeting along the east border. He suggested ordering a STIP for his client to hold him as responsible for installing the 150 foot long curtain wall. He said that he believed that chemical oxidation can work. The soil is sandy. He can use pressure pulse technology to treat the contamination. Mr. Fleming went on to describe how this technology works and the benefits. After this, the conference ended. 12/15/11 - Raphael Ketani. Today I received a response letter from Mr. Onufrak of Atlantic Richfield Company (ARCO). In the letter, Mr. Onufrak states that he is responding to DEC's 11/30/11 letter requesting a RAWP describing the excavation of the contaminated soil and the construction of a barrier in order to prevent the oil from the neighboring condo building from migrating onto the subject former BP property. Mr. Onufrak writes that ARCO disagrees with taking any responsibility for any off site oil that is migrating onto the property. However, he also wrote that the site owner, 267 Sixth Street LLC, is willing to pay for the barrier. ARCO will submit a RAWP for only excavating the contaminated soil at the site. 12/16/11 - Raphael Ketani. I sent a response letter stating that ARCO should submit a RAWP just for the excavation. However, I added that the containment and cleanup of the off site oil should be worked out between 267 Sixth Street LLC, 267 Development LLC and the owners of the neighboring condo building (270 5th Street). responsible party: ARCO (BP #13397) owner of site: 267 Sixth Street LLC developer: 267 Development LLC neighbor: 270 5th Street (condo) 12/27/11 - Raphael Ketani. Kevin McGuinness (developer's consultant) (212) 675-3225 called. He said that the developer and BP have reached an agreement regarding the retaining wall for holding back the oil on the east side of the property. BP will submit a work plan for only the west side excavation and the developer will submit a work plan for only the retaining wall construction. This was being done because the developer is under a short time constraint whereby he has to start work by a certain date. I told Mr. McGuinness that the submission of two work plans was fine. Mr. McGuiness responded that the DEC should receive the wall work plan by January 9, 2012. I asked him who was the owner of the site. He said that it was still BP. 1/5/12 - Raphael Ketani. I received the 1/4/12 Hydraulic Barrier RAP from Flemng Lee Shue for preventing the seepage of oil onto the site from the property to the east. I found the RAP to be acceptable for installing the steel sheet piling wall. I sent a letter to Mr. McGuinness stating this and an e-mail. I also had received the 1/3/12 Remedial Action Plan - Chemical Oxidation from the Antea Group. The basis of the plan was to use chemical oxidation and soil vapor intrusion to remove the contamination from the soil and the groundwater. Within the plan, there were diagrams showing the installation of piping for accessing the wells remotely after the site is developed and a building is constructed. The idea was that remediation would continue after site development. This I did not believe was a good plan. The reason being that if the treatment methods didn't perform as expected, then there would be no other options for the remediation, except natural attenuation. From the 9/28/-29/11 sample data in the work plan, the locations of concern for the soil contamination were SB-26 and SB-29 to SB-32. SB-26 = 7.5'-9' 54,300 ppb total VOCs; 15'-16' 17,801 ppb total VOCs and 1,907,400 ppb total SVOCs SB-29 = 10'-11' 155,380 ppb total VOCs; 13.75'-14.25' 236,111 ppb total VOCs SB-30 = 7.25'-8.25' 251,429 ppb total VOCs; 22.33'-22.56' 18,287 ppb total VOCs and 1,653,800 ppb total SVOCs; 25'-26.33' 23,781 ppb total VOCs SB-31 = 1.5'-4' 108,609 ppb total VOCs; 9'-10' 1,017,620 ppb

KAM SERVICE CENTER INC (Continued) **1000556241**

total VOCs; 29.65'-30' 8,217 ppb total VOCs SB-32 = 10'15' 17,024 ppb total VOCs The locations of concern for the groundwater contamination were MW-14 (3/10/11 NAPL; 9/6/11 34,880 ppb total VOCs) and MW-15 (9/6/11 3,022 ppb total VOCs). I sent a letter approving the 1/3/12 RAP - Chemical Oxidation for conducting the work before the property construction. I disapproved the installation of the remote conduit piping before the building construction. In the letter, I also let the Antea Group know that they have to come up with an alternative method of remediation in the event that the treatment methods fail to achieve a level of remediation that is at or below the standards. 1/10/12 - Raphael Ketani. I sent an addendum letter to my 1/9/12 letter regarding the Chemical Oxidation RAP. In this letter, I stated that Atlantic Richfield has to delineate the off site groundwater contamination, as depicted in the last diagram in the 1/3/12 Chemical Oxidation RAP. The diagram shows a hot spot of 16,385 ppb of total BTEX that abuts the fencing on the northwest side (4th Avenue). In the letter, I added that if the chemical treatments don't reduce the soil and groundwater contamination to or below the CP-51 standards, then they should consider excavation. Mr. Fleming (212) 675-3225 called in the morning. He tried to convince me to let the building be constructed first and have the piping for the solution treatment wells installed at the same time before the remediation takes place. I told him that my experience has shown me that this method doesn't usually work. I added that if the treatment solutions don't work, then everyone is stuck with high contamination below the new building. Mr. Fleming said that the developer is under a deadline to start the construction or else he will loose the money. I told Mr. Fleming that the idea of treating the soil and groundwater after the construction was unacceptable. Later in the morning Mr. Fleming called again. He said that the sheet piles could be made to go down more than 10 feet. He also stated that they could excavate the site generally down to 14 feet with no problems, excavate some small hot spots to 16 feet, and, if necessary, then drive the piling deeper and excavate further down. I told him this sounded alright. Mr. Fleming closed the conversation by stating that he will have a conference call with his client and Atlantic Richfield in a few minutes to discuss the plan. 1/19/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called today. We had a 30 minute phone conversation regarding the site. He argued for having DEC give a verbal approval to allow the construction company to put in piles and excavate generally to 10 feet down. He said that, at that point, they would dig out the contaminated soil in places down to 13 feet (this was 3 feet shallower than he had told me before). Then BP would inject lots of treatment solution into the soil in order to break down the contamination. After this, access piping would be installed for possible future injections and groundwater monitoring. Then the building would be built. I told Mr. Fleming that with the building constructed, you can't take confirmatory soil samples in order to see whether the treatment solutions did the job of reducing the contamination. Mr. Fleming stated that we would know whether the contamination has been sufficiently reduced by monitoring the groundwater. If the groundwater concentrations are low, then the treatments are being successful. He added that more treatments would be able to take place if needed. I told Mr. Fleming that all of the hot spots should be dug out. That's the best way to deal with this. Mr. Fleming said that the edge of the property is right up against an 8 foot NYC sewer main and this main is between the site and the

KAM SERVICE CENTER INC (Continued) **1000556241**

subway. I told Mr. Fleming that he had never stated this before. He said that he found this out yesterday when the owner sent him the building drawings. I asked him how deep this sewer was. He said that being 8 feet, it's one of Brooklyn's main sewers. So it must be at least 15 below grade. Mr. Fleming added that he had spoken to the NYC OER and had asked them what would satisfy their requirements for remediation of the site. He said that they told him Whatever DEC wants. I told Mr. Fleming that this was not an answer and that we always want the contamination cleaned up first. Mr. Fleming said that his client was willing to wait several months for the injected solutions to do their work and then build. However, if this is going to drag on for a year or two, then his client will just walk away from the project. I told Mr. Fleming to send the DEC a letter describing what he is proposing with lots of pictures, diagrams and drawings showing the sewer and I will take a look at his proposal. However, I stated, I will not promise him anything over the phone. He said that this didn't sound good, but he will send me the plan. 1/20/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called me today. He said that he had spoken to his client and had worked out a plan whereby treatment solution injection and confirmatory soil sampling would be possible even with the foundation in place. I asked him how he would accomplish this. He said that 12 inch access ports would be built into the foundation so that drilling can take place in order to inject treatment solutions and take confirmatory samples. Then I asked him how additional treatment solution injections would take place. Mr. Fleming stated that special wells would be installed into the sidewalk that would have very long risers which would curve under the foundation and go into the water table. I told him to send me plans showing the access ports, the 8 foot sewer and the groundwater sampling wells. Mr. Fleming said that he will. Later in the day, Mr. Fleming sent me the plans (4/2/09 foundation plan and 1/29/12 groundwater well sampling plan). 1/23/12 - Raphael Ketani. I reviewed the plans and my notes from my conversations with Mr. Fleming on 1/19/12 and 1/20/12 and before. I sent Mr. Onufrak of ARCO, Mr. Hinshalwood of Antea and Mr. McGuinness of Fleming Lee Shue a letter approving the plan to construct the 12 inch diameter access ports and the groundwater monitoring wells with the very long risers. I stated in the letter that they should try to dig out as much of the contamination as is possible before embarking on the foundation construction. I included copies of the boring and well locations for every boring and well that had elevated VOCs and SVOCs since the project had begun. I also included copies of the DEC 1/9/12 letter warning of possible damage to the subway tunnel walls if the they use sodium persulfate, and that they should include a work schedule for each step of the access port and well construction, and foundation construction. 1/30/12 - Raphael Ketani. Dan Cole of the NYC Office of Environmental Remediation (212) 341-0964 called regarding the site. He said that he wanted to have the owner install a much thicker vapor barrier that would be impervious to product, also. I asked him how thick a barrier. He said 20 MILS. I told him to send a letter to the owners with a c-c to me (after the owners agree to this) stating that the barrier will be 20 MILS. Mr. Cole said that he will. I received an e-mail from Mr. Cole as a c-c. The e-mail was sent to Toni Finger of Kramer Levin (presumeably the developer's lawyer). It stated that the OER needed several things in order to close out its review for the site: notarized affidavit from the buyer stating that the previously issued DOB job number will be used for development of the

KAM SERVICE CENTER INC (Continued) **1000556241**

project; information about how the 20 MIL vapor barrier will be installed; a signed and stamped letter from Karl Fischer summarizing the full project description. Upon receipt of the above information, the OER will issue a Notice of No Objection. 2/1/12 - Raphael Ketani. On 1/31/12 and 2/1/12, the Naftali 1/31/12 OER Notice to Proceed, the Witek 1/30/12 Affidavit, the KFA Architects 1/30/12 Affidavit and the 1/1/12 Grace Letter were sent to Mr. Cole. On 1/31/12, Mr. Cole sent a Notice of No Objection to Mr. Finger for DOB Job No. NB-310071294. 2/21/12 - Raphael Ketani. Peter Helseth of Fleming-Lee Shue sent an e-mail containing a document describing the use of steel sheet piling in combination with a sealant. This barrier system would be used to prevent oil from seeping onto the site. I responded back by stating that it was the responsibility of the consultant and the developer to make sure that the barrier is appropriate and efficaceous. 2/24/12 - Raphael Ketani. Today, I received a letter from Gordon Hinshalwood, PhD. of Antea Group. In the letter Dr. Hinshalwood stated that the 1/3/12 Remedial Action Plan - Chemical Oxidation was being implemented. Excavation will take place generally to 13 feet below grade, and deeper where it is feasible to remove more contaminated soil. The additional soil impacts and the historical groundwater impacts were expected to be addressed by the actions described in the Remedial Action Plan. In addition, redevelopment is scheduled for 2/20/12. Once the basement level excavation is complete, then the ISCO application wells, associated piping and monitoring wells will be installed within 30 days. Also, during this time, the SSDS, vapor barrier and soil sampling access ports will be installed. Redevelopment will be completed in 12 to 24 months. After this time, the soil sampling ports will be sealed and the ability to evaluate the treatments will be very limited. The remedial activities schedule was included in the letter. The first round of solution applications will take place within 14 days of installing the wells. Three additional rounds of solution application are indicated (if this many will be necessary to treat the contamination). Post application soil and groundwater sampling will take place one month after each application. So Dr. Hinshalwood expects the entire remediation process to take no more than 12 months following the initial phase of construction. 2/27/12 - Raphael Ketani. I sent an e-mail to Dr. Hinshalwood again warning him about the use of sodium persulfate near a subway structure and to contact the NYCT about its use at the site. I also again asked for the soil descriptions and calculations that were used to determine how much treatment solution would be necessary to remediate the contamination. I contacted the NYCT about the intended use of sodium persulfate by Antea Group, but I could only leave a message. Later, Dr. Hinshalwood called me in response to my e-mail. He said that Antea had contacted the NYCT regarding the proposed treatment solution injections and they are in the process for getting a permit to do the injections. Also, we discussed what type of information the DEC wanted in order to understand whether the solution injections will proceed as planned. Dr. Hinshalwood will send an addendum letter with the information. 3/1/12 - Raphael Ketani. Peter Helseth, P.E. of Fleming-Lee Shue sent me an e-mail with an attachment showing an alternative product for use as a hydraulic barrier. 3/2/12 - Raphael Ketani. Dr. Hinshalwood sent me an e-mail today. He stated that Clean Earth of Carteret, NJ will be the destination for the contaminated soil that will be excavated. No soil will leave the site until he has an acceptance letter from Clean Earth. 3/12/12 - Raphael Ketani. Dr. Hinshalwood sent me the Addendum

KAM SERVICE CENTER INC (Continued) **1000556241**

to Proposed Schedule for Implementation of Remedial Action Plan dated 3/12/12 and produced by Antea Group. In the RAP, Dr. Hinshalwood explained that a a permit application to use sodium persulfate was submitted to the NYCT on 2/22/12. Boring logs and Rockware software were used to create cross sections of the site. The soils are predominantly sand and silty sand with peat in the central portion of the site. Soil porosity varies from 25% to 30%. Permeability is from 10-2 to 10-4 darcys, but is highly variable. Cross sectional diagrams were provided which depicted the lateral distribution of the sand, silty sand and peat in the subsurface. He also explained that a pilot test was conducted in the northwest corner of the property in the vicinity of MW-15 and MW-16. The treatment solution was injected into the 4' to 14' interval. It was found that AW-2 would only accept 150 gals. of solution over the course of a day. While AW-1 would accpet up to 280 gals. of solution per day. Dr. Hinshalwood stated that, given the limited reagent volume to be used, it will not affect the subway. The volumes to be used per injection well will likely be 150 to 300 gals. per day. The solution density will be no more than 0.5 kg/gal. The total mass to be injected will be 2500 gals. for this round. This means that each injection well will receive about 75 gals. I responded back to Dr. Hinshalwood by e-mail that the DEC had accepted the RAP without comment, but that no work should proceed until the NYCT sends the permit for using the solution. Also, I stated in the e-mail that the DEC should receive a copy of this permit. 3/23/12 - Raphael Ketani. I called up Mr. Fleming (212) 675-3225 today. He said that the removal of the fill material will start April 1. The contaminated fill has been delineated. It will be disposed of. Test piles have been done for the foundation. The foundation plan calls for 14 or 16 soil sampling ports in the foundation floor. The barrier sheeting has been ordered. Fleming-Lee Shue will have someone on site everyday for air monitoring and construction - it is an OER requirement. 4/10/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called today. He said that they had wanted to drive the steel sheet piling between the neighboring condo building and the site. However, they found out that the building had already been damaged from vibrations caused by the previous demolition and excavation work to remove the old gas station. The condo building was built in 1911 and can't take any vibrations. The NYC Dept of Buildings has required that seismometers be placed next to the building in order to measure the vibrations. If there are significant vibrations, then all work will have to stop. Mr. Fleming said that this would make it impossible to install the steel sheeting as originally planned. However, he had an alternative method in mind. As the water table is about 20 feet down, he told me that after they have removed the cover soil down to 10 feet below grade, the construction company can dig a trench that extends 10 feet deeper along the property boundary with the condo property. Once this trench is constructed they will hand install, not drive, steel sheeting such that they will have a wall that is 20 feet high. The base of the steel wall will be below the water table and will be keyed into the future building foundation. The wall will be deep enough to stop the migration of the oil from the condo property which is appearing at 10 to 13 feet below grade. I told Mr. Fleming that this would be fine and to send me a new work plan. Mr. Fleming said that they are anxious to start the work and the DEC will receive the plan very soon. 4/25/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called to say that a UST was discovered below the neighboring condo property

KAM SERVICE CENTER INC (Continued) **1000556241**

(spill #1110410 and #1200737). The contractors for Mr. Fleming were installing the required sheeting when they found free product running into the site from the neighbor's soil. They also saw that the neighbor's parking lot was sinking a couple of inches. They looked at the parking lot east of the building and found an old fill pipe. They stuck a rebar down the pipe and came up with 2 feet of oil. The condo was contacted and they hired YU Associates to do a GPR survey. One 550 gal. tank was found. The tank was emptied and cleaned out and the oil stopped seeping onto the site. The tank will be removed. Mr. Fleming asked whether DEC would allow 267 Sixth Street LLC (alternate address for 363 4th Avenue) to not put in the steel sheeting - as it was intended to prevent oil from seeping onto the site. I told him that since the oil is not moving onto the site, there is no need for the sheeting and it can be left out of the development of the site. I asked Mr. Fleming whether the condo was going to dig out the contamination. Mr. Fleming said that they were talking about it, but they weren't moving. I told Mr. Fleming to suggest to Mr. Naftali that he let his contractor do the excavation and back bill the condo. Mr. Fleming said that this was presently being discussed as he already has his equipment and trucks on site. After this, the conversation ended. 5/2/12 - Raphael Ketani. Arnie Fleming of Fleming Lee Shue called. He is the consultant for the developer of the neighboring site to the west (363 4th Avenue; #8901904). He said that he was at the co-op site yesterday and the contractors had emptied and cleaned out the tank. Because of this, the oil seepage onto 363 4th Avenue had stopped. The tank on the co-op property was a 1,000 gals. and was 2 feet away from the border between the two properties. No piping was found associated with the tank. Mr. Fleming said that he was dewatering his client's property and no oil was flowing in. However, he told Mr. Yu of Yu & Associates that he should start digging out the contaminated soil around the tank as he will stop dewatering and then Yu & Associates will have do their own dewatering in order to remove the contaminated soil. Mr. Yu said that he was waiting for the co-op board to meet in order to give him a decision regarding whether he can proceed with the remediation work. Mr. Yu also state that an oil sample was sent off for fingerprinting. So everyone is waiting for the results. Mr. Fleming said that he emphasized to Mr. Yu that he should take advantage of the present dewatering because it will save him some money. Also, I sent an e-mail to Mr. Fleming stating that the steel sheeting didn't need to be installed as no oil was seeping onto the property and because the only purpose for installing the sheeting was to prevent the seepage. Later today, Rodney Rivera from the Regional Direction office of Region 2 came to the DER floor. He said that there had been a dust and petroleum odor complaint by someone from the co-op next door to Channel 11 News. Mr. Rivera was trying to find out what was happening at the site. I spoke to him and told him that this was the first time that I had been told there were dust and odor problems at the site. I also explained that excavation work was supposed to take place as part of the remediation of the site. However, I also told Mr. Rivera that the UST under the co-op property had just been cleaned out and had leaked oil into the ground. So this may also be a source of odors. Next, I spoke to one of the supervisors in the Spills Unit and he ordered a person in his unit to go and investigate the complaint. Next, I contacted Mr. Fleming (212) 675-3225. He said that he is aware that there are odors, but there isn't a significant problem with the dust. However, they are usually mild. However, there are

KAM SERVICE CENTER INC (Continued) **1000556241**

instances of strong odors when they dig in the site to put the pile caps for the foundation. These odors usually affect a resident in the first floor of the co-op as his apartment is right next to the digging. Mr. Fleming also stated that this person's apartment is 5 feet from the newly discovered UST which was just cleaned out. So there will be odors when the soil is dug out in this location. A consultant from PAL Environmental is walking around the site with a PID meter and checking the odor levels. The first floor apartment was investigated for odors, but they are mild. I told Mr. Fleming that he will have to come up with a solution to the odor problem in order to alleviate the issue for this resident. Mr. Fleming said that he will send the DEC a plan in writing, but they will first try sealing the person's windows with plastic and caulk so that there are no air leaks. Maybe this will solve the problem. I asked Mr. Fleming what he and his crew are doing about the odors. Mr. Fleming said that the odors only happen with the initial dig into a location and then they quickly dissipate. However, he is using biosolve (a masking agent). Also, Fleming Lee Shue is now starting to dig out the hot spots. I asked Mr. Fleming to keep me informed. He said that he will. The Spill investigator contacted DER from the site and reported back that presently there were no odors. 5/7/12 - Raphael Ketani. Vanessa Meer of Yu & Associates (201) 791-0075, 116 called today and left a message. I tried to return her call, but could only leave a responding message. 5/8/12 - Raphael Ketani. I spoke to Mr. Fleming (212) 675-3225 today. I told him that there had been another odor complaint and the EPA was now involved. He said that the neighbor who had been complaining was moved into a hotel across the street from his apartment building. I told him that was fine and I asked who had arranged this. He said that it was the contractor. I asked Mr. Fleming to find out the name of the person who was affected by the odors. Mr. Fleming said that he will. Mr. Fleming added that the odors are of gasoline, not fuel oil. So everytime they dig, some odors appear. He said that he has a guy walking around the site with a PID meter and checking that there are no exceedences of the 10 ppm standard. However, if there are, then the work stops to let the odors disipate. An odor suppressing material was put down, but it's not very effective. Mr. Fleming added that the NYC DOB came by and stopped the work. There's a stop work order. He doesn't know why this happened, but they usually don't get involved in odor complaints. On another note, Mr. Fleming said that they are presently dewatering the site and the water table has been depressed 3 feet. So, if the contractors from Yu & Associates want to, now is the time to dig out the soil contamination. I told Mr. Fleming that the co-op may not be ready to remediate the spill. 5/9/12 - Raphael Ketani. I spoke to Ryan Piper, EG I of the Region Spills Unit, about the latest odor incident. He said that the odor incident was called into the Spills Hotline by the NYC DEP. The incident was assigned spill number 1200916. Mr. Piper told me that he went to the site, but didn't find any odors. I told him that the citizen who had been complaining about odors in his apartment had been moved to a hotel. I asked him whether he knew the name of the citizen. Mr. Piper said that he didn't. However, he said that the spill case had been closed and referred back to this one. Tona Construction and Management, 615 Baltic Street, Brooklyn, 11217 is the construction company. The contact is Michael Izzo, General Superintendent, at (718) 399-3800/cell (718) 825-9309. 5/11/12 - Raphael Ketani. Steve Sangesland, Duty Desk Officer for the Region 2 Spills Unit, gave me a note that Matt Law

KAM SERVICE CENTER INC (Continued) **1000556241**

(718) 593-9028 had tried to contact someone at the DEC regarding odors from the former BP station. I spoke to Mr. Law at length about the site, about the nature of the contamination (that is was just gasoline) and about the procedures for monitoring and managing the vapors and odors. He said that he was concerned that something else had contaminated the site, other than gasoline. I asked him whether he was the resident who had been moved to the hotel. Mr. Law said that he was not and that he lives on the other side of the building from the site. He stated that he was glad that the DEC was aware of the situation and that the contractors were managing the odors. I explained that they are working to get rid of the contamination as fast as possible in order to alleviate the odors and that the building that will be built will have a vapor barrier and a passive vapor venting system. So this building will be safe to live in. With that, Mr. Law thanked me for all of the information and the conversation ended. 5/18/12 - Raphael Ketani. I received a copy of a letter today by e-mail from Antea Group. The letter was dated 5/16/12 and was sent by Antea Group in response to comments by the NYCT regarding the use of sodium persulfate to treat the contamination and the extent of the contamination. I reviewed the letter. From its contents, I determined that Antea Group had adequately responded to the NYCT's comments and concerns. 5/30/12 - Raphael Ketani. I received an e-mail today from Peter Helseth of Fleming Lee Shue. He stated that most of the foundation elements have been constructed on the site and the area for the foundation walls has been capped with clean stone. There is no more exposed soil, nor excavating taking place. So air monitoring has been stopped. 6/7/12 - Raphael Ketani. I received a call from Jay Solomon (212) 661-9400, the attorney for the Shepherd family that had been moved out of apartment 1G at 270 5th Street. He said that when the foundation was laid at the construction site next door, lots of oil vapors entered the apartment and the parents and two kids had to be moved into a hotel temporarily. However, he added that the foundation work has been finished. I told Mr. Solomon to contact the company responsible for the air monitoring and have them do a followup indoor air inspection just to be sure everything is alright. He said that the vapors had come from the construction site. I told him that the vapors would more likely come from the 1,080 gal. UST site because there is lots of contaminated soil there and this location is much closer to apartment 1G. Mr. Solomon didn't comment on this. I added that once the tank is removed, the contamination in the soil is exposed and the oil will vaporize. In any event, I said, it would be good to have a followup indoor air survey done of the apartment. I told him that Fleming Lee Shue was the consultant in charge of setting up the air monitoring and he should contact them. With that, the conversation ended. I tried to contact Mr. Fleming (212) 675-3225 regarding the attorney's request for another indoor air inspection, but I could only leave a message. Mr. Helseth from Fleming Lee Shue called in response to my message. He said that Mr. Fleming was out today, but he will take care of anything that's an issue. I explained that Mr. Solomon had called and wanted a vapor survey performed in his client's apartment. Mr. Helseth said that this will be done. I added that a vapor survey should also be done in the hallway outside the apartment, outside the building itself and next to the excavation area for the 1,080 UST. Mr. Helseth said that this will be done. Later, Mr. Fleming called. We discussed the issue of doing a PID survey in the Shepherd's apartment. I told him that the DEC also wanted a survey inside the

KAM SERVICE CENTER INC (Continued) **1000556241**

building's hallway, just outside the apartment, just outside the apartment in order to get the ambient air concentrations, then next to the UST removal site and finally next to the border of the two concerned properties (condo and excavation site). Mr. Fleming said that he will talk to his client about this. Some time later, Mr. Fleming left a phone message that all parties had agreed to do the vapor surveying. The co-op board was being contacted and it was hoped that the surveying will take place tomorrow, 6/8/12. Mr. Fleming stated that he will keep me posted. 6/8/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called me regarding doing the vapor testing inside apartment 1G at the co-op and outside at the UST excavation location. Mr. Fleming told me that the lawyer told him not to enter the property and that Yu & Associates will do the work. I told Mr. Fleming that it didn't matter who was going to do the testing, just that the DEC gets the data. Later, I contacted Mr. Leung (201) 791-0075/cell (201) 310-2501 and explained that I wanted Yu & Associates to do the vapor survey. Mr. Leung said that more than one resident had been complaining about vapors from the BP site a while ago. I asked him whether they still were complaining. He said No. Mr. Leung added that nothing is happening right now as he was told the DEC wanted to take a look at the soil delineation results first before more excavating takes place. I told him that was not true. I told him that the DEC wants Yu & Associates to move as quickly as possible to excavate the contaminated soil, then submit the end point results once all of the soil is removed, and then go forward with installing groundwater wells. Mr. Leung said that he thought this was what the DEC wanted. So he will mobilize his crew. 6/14/12 - Raphael Ketani. Mr. Fleming left me a message today. He said that one of his workers did a PID survey of the neighborhood. The only vapor detections were about 8 ppm just across the property fence with 270 5th Street. The detections were at the location of the open tank grave. Mr. Fleming added that the tank is sitting on the ground and hasn't been removed and the tank grave is uncovered. His worker was not able to do a PID survey of the Shepherd's apartment as he was not allowed access. 6/18/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called me regarding doing the neighborhood vapor survey. He said that the only detections were at the location of the tank removal next door. However, there is another construction site to the south across the street and they are doing dewatering. There is a 20,000 gal. Baker Tank for storing the recovered water on site before disposal. Mr. Fleming didn't know what the site used to be. He did state that the groundwater level always was a little lower than expected on the southern side of the site. Now he understands why. Lastly, he said that the developer is going to pour the concrete floor very soon. However, BP and Antea Group have not done the first round of treatment solution injections. By way of the timing for letting the treatment solutions do their work, they will miss the opportunity to do a second round of treatment (if necessary) if BP and Antea don't move quickly. Mr. Fleming said that he will keep me informed. I tried to conact Mr. Onufrak (410) 825-8213 regarding having the first round of treatment injections performed. However, I could only leave a message. Next, I contacted Dr. Hinshalwood at Antea (914) 495-9950. I told him that the developer was going to install the floor for the new building very soon and that BP and Antea should do the solution injections very soon. Otherwise, they may not have the opportunity to do them. Dr. Hinshalwood said that Antea has been in touch with the developer on a daily basis in order to know when there is a pause in

KAM SERVICE CENTER INC (Continued) **1000556241**

the construction and they can do the injections. He said that the injections will take place in wells that will be installed at two depths throughout the site - as had been agreed upon. I told Dr. Hinshalwood that was correct, but Mr. Fleming had lead me to believe that doing the injections wood not be possible as the floor would be completed. Dr. Hinshalwood said that they would bore through the floor to install the needed wells. He added that he was not the project manager anymore. He said that the new project manager is Tim Fisher (914) 495-9935. He said that he will have Mr. Fisher call me regarding the project and the solution injecting. I told him that would be fine. As an alternate, Dr. Hinshalwood said, I could also talk to Chris Meyer (914) 495-9937, the portfolio manager, about the project. With this, the conversation ended. 6/19/12 - Raphael Ketani. Chris Meyer of Antea Group sent me the following e-mail: As a follow-up to the conversation you had yesterday with Gordon Hinshalwood, I thought this update was appropriate. I realize it s been a little while since we discussed this project. In accordance with the RAP that was approved by the NYSDEC on March 15th, last Friday (June 15), we completed the installation of the ISCO application wells and ground water monitoring wells along the western property boundary. Installation of the sub slab depressurization piping and soil vapor barrier was also completed last Friday by the developer. Per the email approval you provided to the developer on May 2, the steel sheeting was not installed by the developer. Yesterday (June 18), the developer poured the concrete slab for the building. Today, we are collecting baseline readings from the newly installed monitoring wells present along the western property boundary, as requested by the Transit Authority (TA). At this time we are in the process of coordinating the first ISCO application. We do not have a definitive schedule of when the first application will occur, but we expect it will be in July. 6/25/12 - Raphael Ketani. Mr. Meyer sent me an e-mail stating that the first ISCO is scheduled for thursday, 6/28/12. 7/9/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called to say that the first injections took place about a week ago. 8/16/12 - Raphael Ketani. Mr. Fleming sent me an e-mail stating that BP installed the groundwater treatment injection pipes and performed the first injection about two weeks ago. However, they were not keeping him in the loop. The building is progressing and is well above grade. 8/22/12 - Raphael Ketani. I responded to Mr. Fleming's last e-mail and stated that there was a meeting with staff from BP yesterday. They had indicated that the building construction is moving forward and that 3 rounds of injections had already taken place. They were concerned that groundwater injection and confirmatory soil sampling access could be lost as the construction was moving so quickly that the access portals will be closed soon. I added that the groundwater samples to be taken after the treatment injections must be at or close to GA standards. If they are not, then more treatment will have to take place. If the foundation portals are closed up before the groundwater is sufficiently remediated, then the DEC will contact the NYC DOB and the NYC OER and tell them to hold off on issuing the Certificate of Occupancy. Mr. Fleming called me. He said that the soil confirmation access ports will remain open until next summer. The holes will be closed only just before the owner goes for his Certificate of Occupancy. 10/15/12 - Raphael Ketani. I tried to contact Tim Fisher (914) 495-9935 and Chris Meyer (914) 495-9937 of Antea Group, and Nick Onufrak (410) 825-8213 of BP regarding progress at the site and whether confirmatory soil borings

KAM SERVICE CENTER INC (Continued) **1000556241**

had been taken and whether groundwater samples had been taken. However, I could only leave voice messages. Mr. Meyer called me back. The last injection was completed. All 8 applications have been completed. The sodium persulfate solutions and EDTA chelated iron are in the ground. On October 22, Antea is going out to do groundwater and soil confirmatory sampling. 10/18/12 - Raphael Ketani. Mr. Meyer called. He said that due to the crane still being in place for constructing the building, the sampling date has been pushed back to October 24. 10/22/12 - Raphael Ketani. Mr. Meyer (914) 495-9937 called. He said that the soil and groundwater confirmatory sampling has been pushed back to November 5, 2012. The sampling will take 5 to 6 days. 11/12/12 - Raphael Ketani. Mr. Fisher left me the following e-mail message today: Today we are beginning the process of collecting confirmation soil and grab ground water samples from below the building slab at former BP station 13397 to determine if impacts remain following the completion of ISCO applications. We expect site activities to last through this Thursday. 1/9/2013 - Raphael Ketani. A conference call took place today between Nick Onufrak of BP-ARCO(410) 825-8213, Chris Meyer (914) 495-9937 and Gordon Hinshalwood (914) 495-9950 of Antea Group and myself. The subjects of the call were the groundwater and soil sample results and the Certificate of Occupancy for the building. Mr. Onufrak stated that they had received the soil and groundwater results after 8 rounds of solution injections had taken place. The results were not good. There wasn't much improvement. They wanted to know whether this would affect the ability of the building's owner to get the Certificate of Occupancy. I told him that the poor results will. I added that you can't have a building sitting over a pool of oil. The vapors will travel up the footings and into the concrete walls of the basement - bypassing the vapor barrier - and then into the building. Mr. Meyer stated that the building will have a vapor barrier and a passive venting system. I told everyone that another way to reduce the contamination has to be found. I added that I had another case with the same problem and they can't get a permanent C of O as they have oil seeping under the property. Their contamination was known, but the owner built his building anyway. I also said that the DEC would have to contact the NYC OER and they would let the NYC DOB know that someone has built on top of contamination that still exists. I asked whether the groundwater could be extracted. Mr. Meyer said that the wells can't pass a pump down the pipe. I asked whether just pushing a hose down each well would suffice. Mr. Onufrak and Mr. Meyer said that they will have to consider what can be done. They will send the DEC the report with the analytical results. Later, I talked to Dan Cole of the NYC OER and passed the above case notes to him via e-mail. He responded back by e-mail. 1/10/13 - Raphael Ketani. I responded to Mr. Cole's 1/9/13 e-mail (see the e-docs). I stated in the e-mail that a meeting needed to be held with all parties in order to make everyone aware of the continuing existence of the oil and contamination below the site. We would also have to discuss what can be done to resolve this problem. 1/24/13 - Raphael Ketani. The meeting took place as planned. In attendance were representatives from the owner's consulting company, the lawyer for the owner, BP, BP's consultants, BP's lawyer, Dan Cole from the NYC OER and myself. I brought up the issue that despite the numerous rounds of solution injections, the Department was informed that the contamination was still about as concentrated as before. I stated that an alternative means of remediation needed to be found and employed. Mr. Hinshalwood

KAM SERVICE CENTER INC (Continued) **1000556241**

stated that only a 5% solution was used for the rounds of injections. As the site is next to the subway tunnel, this was the strength limit of the solution that the MTA would approve. I told Mr. Hinshalwood that this explained why the contamination hadn't been broken down. I again insisted that a remediation method be found to reduce or remove the soil contamination. I also stated that there was product on the water table. Mr. Onufrak and Mr. Meyer stated that they will start using a vacuum truck to collect the product from one well where they have seen free oil. I told them to submit a work plan and I gave them 30 days from today to do so. Mr. Onufrak said that this was enough time. Mr. Onufrak stated that two wells were destroyed during the building construction. I told him that the re-installation of the wells must be part of the work plan. I asked them when I will receive the soil confirmatory sampling data report. Mr. Meyer said that it was still going through internal review, but the DEC should receive it soon. The meeting ended with an agreement to present an alternative means of remediation. 2/1/13 - Raphael Ketani. Mr. Meyer (914) 495-9937 sent me an e-mail stating that a site visit was made on January 30 to see whether it was possible to position a vacuum truck near some of the wells in order to collect the groundwater. A location was found where the vacuum truck could park. So the first vacuum event will take place the week of February 11. Stingers will be used to collect groundwater from the observation wells. 2/7/13 - Raphael Ketani. Mr. Meyer sent me the following e-mail: The first VEFR event is scheduled to take place on Wednesday, February 13th. Six consecutive weekly VEFR events are planned. 2/15/13 - Raphael Ketani. I received the following e-mail from Mr. Meyer: The first VEFR event took place this past Wednesday, February 13th. The next VEFR event is scheduled for Wednesday, February 20th to gain additional information. We will also be submitting a VEFR work plan to you next week. I ve also attached the report we ve prepared to summarize a number of activities that were implemented as proposed in the Remedial Action Plan Chemical Oxidation, dated January 3, 2012, the Proposed Schedule for Implementation of Remedial Action Plan addendum, dated February 22, 2012, and the Addendum to Proposed Schedule for Implementation of Remedial Action Plan, dated March 12, 2012. As such, the post-application sampling results we discussed during our meeting in January, are also presented. 2/19/13 - Raphael Ketani. I finished my review of the Antea Group 2/13/13 Remedial Action Summary Report. From 4/11/12 to 5/25/12, 7386 tons of contaminated soil were excavated and taken to Clean Earth of Carteret, NJ. Between 4/26/12 and 6/19/12, 75,297 gals. of groundwater accumulated on site and this was taken to Lorco Petroleum Services in Elizabeth, NJ as non-hazardous waste. The SSDS system was installed prior to construction of the foundation. It consisted of 4 inch schedule 40 PVC piping with 0.020 slots benaeath the concrete basement slab. The piping was laid down in a layer of 3/4 inch crushed stone that is 4 feet thick with 3 risers extending through the slab, which will be extended to the roof. A Grace Preprufe 300R and 160R/Bithuthene 4000 vapor barrier was installed. Eight (8) soil borings were performed from 5/24/12 to 6/12/12. These borings were turned into wells OW-1A to OW-4A and OW-1B to OW-4B. The borings were started at the excavation floor, which was 10 feet bgs. OW-1A to OW-4A were drilled to 30 feet bgs. OW-1B to OW-4B were drilled to 20 feet bgs. The wells were installed along the western boundary of the property which is along 4th Avenue in order to monitor the sodium persulfate concentrations and the groundwater. During the same time

KAM SERVICE CENTER INC (Continued) **1000556241**

interval, 16 soil borings were performed and were turned into wells for the purpose of injecting the treatment solutions. These wells were AW-1A to AW-8A and AW-1B to AW-8B. The borings started at the excavation floor. AW-1A were finished at 16 to 19 feet bgs and AW-1B to AW-8B were finished at 24 to 28 feet bgs. Each well was connected with a 2 inch diameter PVC hose. AW-1 (A,B) to AW-4 (A,B) and AW-7(A,B) were used to treat the soil and the groundwater under the western portion of the site. AW-3 (A,B), AW-6 (A,B) and AW-8 (A,B) were installed to treat the soil and groundwater under the central portion of the site. AW-5 (A,B) were installed in order to treat the soil and groundwater under the southwestern portion of the site. Soil samples were only taken from the deep B series of borings due to the proximity to the shallow A series of borings. No soil samples were taken from AW-1B or AW-7B. The analytical results showed exceedences at AW-2B to AW-4B, AW-6B, AW-8B, OW-1B to OW-4B. On 2/21/12 (dated as 2/21/13 in the report), groundwater samples were collected from MW-13, MW-15, MW-16, MW-20, MW-22 and MW-24. The VOC results for MW-13 were all non-detect. Those for MW-15 were extremely high. MW-16 had VOC results from just a little above the TOGS standards to below the standards. The results for MW-20 were all a little above the standards. MW-22 had 2 high VOC hits with the rest being low to moderate hits. MW-24 had hits from below to 3 a little above the standards. Pre-injection groundwater samples were taken on 6/19/12 from OW-1A to OW-4A and OW-1B to OW-4B. Each of the samples had exceedences for almost all of the TOGS 1.1.1 standards. All of the samples, except for OW-4B, had very high exceedences for total xylenes and ethylbenzene. OW-1A, OW-2A, OW-1B and OW-2B had very high exceedences for 1,2,4-trimethylbenzene. OW-2A, OW-2B, OW-3A and OW-3B had very high benzene exceedences. OW-1A, OW-2A, OW-2B, OW-3A and OW-3B had very high toluene exceedences. OW-1A, OW-1B, OW-2A and OW-2B had very high naphthalene and 1,3,5-trimethylbenzene exceedences. OW-1A, OW-1B and OW-2A had very high n-propylbenzene exceedences. Eight applications were performed from 6/28/12 to 9/20/12. The sodium persulfate solutions were applied over several rounds at a concentration of 50,000 mg/l for each individual injection. This concentration was required by the NYCT as they were concerned that stronger concentrations would affect the subway tunnel bordering the property under 4th Avenue. About 12,800 gals. of 50,000 mg/l solution was injected with ferrous iron as an activation chemical. Staff at Antea Group calculated that an injected concentration of 130,000 mg/l would degrade to 5,000 mg/l at the property boundary, which would further degrade to 15 mg/l at the tunnel. Post injection, 6 borings were performed from 11/12/12 to 11/14/12 to 26.5 to 38.5 feet bgs. These were SB-33 to SB-38. A seventh boring, SB-39, hit refusal at 17 feet bgs and SB-40 hit a void below ground and could not be completed. The analytical results for the soil samples from the 6 borings all had exceedences. SB-33 had extremely high VOC exceedences and many SVOC exceedences. SB-34 was tested only for VOCs and had high hits. The SB-35 results were a little above standards to non-detect. SB-36 had low to high VOCs and SVOCs exceedences. SB-37 had low VOC hits, but extremely high SVOC exceedences. SB-38 had extremely high VOC hits and low to moderate SVOC exceedences. The median soil contamination total concentrations increased after the injections from 12,330 ppb total VOCs to 22,869 ppb. The mean total soil SVOC concentrations decreased from 14,691 ppb to 3914 ppb. Groundwater samples were taken from 11/12/12 to 11/14/12. SB-33 had many very high VOCs, and SVOC exceedences. SB-34

KAM SERVICE CENTER INC (Continued) **1000556241**

and SB-35 had high to very high VOCs. The water sample from SB-36 had 5 high VOCs and many high SVOC hits. SB-37 had high to very high VOC hits and low to high SVOC hits. SB-38 had many very high VOCs and also SVOC exceedences. Later, groundwater was sampled on 1/8/13 from OW-1A, OW-1B to OW-4A, OW-4B. The groundwater samples from OW-1B, OW-2A, OW-2B and OW-3B had many very high VOC hits and SVOCs which were mostly non-detect to low hits below TOGS with a few low exceedences. The sample from OW-4A had VOC hits from below the standards to 4 very high exceedences. OW-4B had VOC hits from below the standards to several moderate exceedences. I approved the data in the report as it gave a reasonable picture of the degree of soil and groundwater contamination below the site. However, it will remain to be seen how effective the VEFR events are in reducing the groundwater contamination. 2/21/13 - Raphael Ketani. I sent Mr. Hinshalwood (914) 495-9950, Mr. Meyer (914) 495-9937 and Mr. Onufrak (410) 825-8213 an e-mail stating that the DEC wanted groundwater to be sampled from the MW, AW and OW series of wells. Mr. Hinshalwood (914) 495-9950 responded back by e-mail stating that the MW series of wells were destroyed by the foundation construction, except for MW-13 which will be used to monitor the groundwater when the construction ends. Also, he stated that the AW series of wells were not accessible and wells OW-1A and OW-1B had been destroyed, but will be reinstalled. So only 9 wells will be available for monitoring. The OW series are all along 4th Avenue. MW-13 is along 6th Street along the southern border of the property. 2/25/13 - Raphael Ketani. I received the 2/22/13 Antea Group Vacuum Enhanced Fluid Recovery Work Plan. The purpose of the plan is to extract NAPL and contaminated groundwater. VEFR events will take place weekly. Wells OW-1A to OW-3A will be used for VEFRing. Stinger devices will be used in the wells to collect the total liquids. Vacuuming using a vacuum truck will be undertaken for a single well. During the vacuuming event, the radius of influence (ROI) will be determined. Vacuuming will be conducted for 2 hours at each observation well. At the end of each VEFR event, product and groundwater levels will be gauged. The volume of NAPL and groundwater collected will be measured and recorded. The vacuum will be measured every 30 minutes. Vapor concentrations will be measured every 15 minutes using a PID meter. Before any future solution injection applications are performed, it will be determined whether the ROI extends under the western border of the property. Data from the ROI and the VEFR events will be used to determine whether more extraction wells are needed. 2/26/13 - Raphael Ketani. I found the Vacuum Enhanced Fluid Recovery Work Plan to be acceptable with the comment that the product and groundwater gauging must take place before the VEFR or vacuum events take place. I added that monthly progress update reports must be submitted to the DEC by the third week of the month following the VEFR and vacuum events and gauging. The progress reports must include the NAPL and groundwater elevations, the amount of product recovered and the groundwater flow map. I also added that quarterly groundwater analytical reports must be submitted no later than 30 days following the date of sample collection. The sampling must be for the expanded lists of VOCs and SVOCs. I drafted a letter for the review of Mr. Hussein with the above approval and requirements. Mr. Hussein approved the letter and it was sent out. 3/1/13 - Raphael Ketani. Mr. Meyer (914) 495-9937 sent me the below e-mail today: Three vacuum enhanced fluid recovery events were conducted at former service station 13397 on February 13th, February 20th, and February 27th, 2013. The objective of these events was to

KAM SERVICE CENTER INC (Continued) **1000556241**

recover any NAPL that may have been present (as was evident from a sampling event in one of the observation wells along Fourth Avenue in January), and to explore the potential for ground water recovery using this technology on the existing wells (OW-1 through 3), which are located under the newly-constructed building with remote access ports for sampling located in the sidewalk as proposed in the approved Vacuum Enhanced Fluid Recovery Work Plan dated February 22, 2013. Ground water samples were collected from Observation Wells OW-1A, OW-1B, OW-2B and OW-3B on February 27th and will be compared to the baseline ground water samples collected from the observation wells in January 2013 (before the VEFR events) to see if there is any significant change in VOC concentrations. Monitoring well MW-13 is located beneath some temporary infrastructure that is being used as part of the building construction. As such, it could not be sampled. To date, minimal water (115 gallons) and no measurable NAPL was recovered during the three extraction events, indicating that the practical application of this technology for hydraulic control is limited. Additionally, no significant vacuum influence was observed in surrounding wells during any of the extraction events, and vapor recovery was minimal as well, indicating that insufficient air flow was induced to mobilize significant vapor mass. Given these results, it is unlikely that this remedial approach will recover significant contaminant mass from the subsurface. At this point, no additional extraction events are planned, pending a review of the results of the ground water samples that were collected. Per your approval letter, we will be providing a more formal summary of these results in the third week of March. As I mentioned in my email on 2/21/13, efforts are also underway for Naftali to replace the two sidewalk wells that were destroyed during their construction activities (OW-1 and OW-3A).

---------- I responded by e-mail stating that the Atlantic Richfield Company and Antea Group had to find a way of recovering the contaminated groundwater, even if this meant installing larger diameter wells or more wells. 3/6/13 - Raphael Ketani. Mr. Meyer sent me the contact information for the person at the MTA who approved the sodium persulfate treatment plan. This person is Rajen Udeshi (646) 252-3673. 3/7/13 - Raphael Ketani. I spoke Mr. Udeshi. He said that he didn't do the analysis to determine that a 5% solution was required. He added that he is a Principal Engineer and a structural engineer. However, he is only involved in coordinating the treatment solution application process. Mr. Udeshi told me that Emil Dul (dool), Principal Engineer, MTA Environmental Group, at (646) 252-2405 is the person who calculated what the treatment solution concentration should be. I spoke to Mr. Dul. Mr. Dul said that whenever a treatment project is proposed within 200 feet of an MTA tunnel or such, then the Six Agency rule comes into play. He said that the six agencies include the Fire Department, the NYC DOB and a few others. The rule is administered by the NYC DOB. The engineer or architectural drawings need the approval of the six agencies. He said that some time ago, a meeting took place between the consultants from Antea Group and staff from the MTA to discuss the proposed sodium persulfate treatment plan. Mr. Dul added that the MTA was concerned that the treatment solution not leave the site - in other words, be completely used up - so that the subway tunnel would not be affected. Mr. Dul said that once they had all of the information, then they considered the treatment plan, which included drawings showing the locations of the injections points. Staff from

KAM SERVICE CENTER INC (Continued) **1000556241**

the MTA went over the calculations for obtaining the solution mixture that Antea Group wanted to use and what the expected concentration would be at the property boundary. However, Mr. Dul said, he was not sure of all of the details regarding what had transpired. So he wanted to call me back with the rest of his staff to discuss the matter. I told him that would be fine, but that I still wanted to know who in MTA had decided that a 5% solution was the correct concentration. Mr. Dul responded that Antea Group had proposed this in order to make sure the solution would be used up and to prevent its escape from the site. With that, the conversation ended. Later, Mr. Dul called me back and started a conference call with Derrick Braithwaite and Mary Kong, engineers from the MTA. Mr. Dul lead the conversation. He said that the MTA met with Antea Group on 3/27/12. They discussed the proposed treatment plan. On 5/16/12, the MTA sent Antea Group a letter with many questions regarding the injection plan. Antea Group later responded back. Mr. Dul was emphatic that the MTA never asked Antea Group why they were going to use a 5% solution. He added that they never challenged what Antea Group was proposing. The MTA's only concern was that the treatment solutions not contact the subway tunnel. Ms. Kong stated that they wanted sentinel wells installed (which Antea Group did). Antea Group told them that they modeled the injections and had confidence in the model. Mr. Braithwaite said that he went to the site twice to witness the injections. Mr. Dul stated that the MTA simply doesn't want anything getting near the concrete. As long as the groundwater is non-detect for persulfate, then they are happy. He added that the MTA doesn't approve the outside consultant's plans. They only accept them. With that, the conversation ended. 3/12/13 - Raphael Ketani. Mr. Meyer (consultant to BP) sent me an e-mail stating that wells OW-4A and OW-4B will be replaced today. 3/29/13 - Raphael Ketani. Mr. Meyer sent me the 3/22/13 Antea Group Progress Update Report. VEFR events took place on 2/13, 2/20 and 2/27. The wells used were OW-1A, OW-2A and OW-3A. OW-4A was not used as it had been destroyed. No NAPL was recovered during any of the events. Vapor concentrations in the wells were typically less than 100 ppm during each of the VEFR events. Groundwater was sampled on 2/27 and 3/7 from OW-1A, OW-1B, OW-2B and OW-3B. BTEX was very high in all of the samples and was up to 9840 ppb. Total VOCs ranged up to 11,321 ppb. The SVOCs were only slightly elevated. On 3/12/13, OW-4A-R and OW-4B-R were installed. 5/9/13 - Raphael Ketani. I spoke to Mr. Meyer (914) 495-9937 today regarding progress at the site. He said that Mr. Naftali, the owner, had replaced two wells that his construction crew had damaged. Presently, Antea is working on a work plan to install 6 new wells for groundwater monitoring and product/groundwater recovery. He said that these new wells will be straight instead of curved and so they will be able to do VEFRing. All of the wells will be installed along 4th Avenue. From the excavation along the sidewalk which took place in the past, Antea now knows where the utilities are. So they will be able to hand clear past the utilities and install the wells. Mr. Meyer said that he had the draft work plan on his desk. The final plan will be sent to the DEC soon. 6/24/13 - Raphael Ketani. I reviewed the 6/20/13 Well Installation Work Plan Notification. Antea Group plans to install up to 11 wells. Five of the wells will be installed in the existing 12 inch diameter sampling ports in the basement, SB-33 to SB-37. Three additional dual nested well clusters are also proposed along 4th Avenue. Each cluster will have a shallow screen from 5 to 20 bgs and a deep screen from 20 to 30 feet bgs. The

KAM SERVICE CENTER INC (Continued) **1000556241**

wells will be 4 inches in diameter. The work is scheduled to start in late July. I approved the work plan with one comment. This regarded the nested pairs of wells that will be installed along 4th Avenue. The figure enclosed in this document shows that the wells in each pair will be closely spaced laterally. The Department is concerned that this arrangement will allow for groundwater cross communication between each well. The construction must be modified in order to prevent this from happening. 8/6/13 - Raphael Ketani. As per the order of Paul John, Environmental Engineer IV/Regional Re/mediation Engineer, this BP spill case is being transferred to Jeff Vought in Region 2 Spills. Mr. Vought will be the new case manager effective today. 1/11/16-Vought-Spill being managed by DEC Feng for approximately past three years. Vought as her supervisor sent email to Chris Meyer that Chris, I hope your holidays were good. As you know we had discussed having a teleconference with DEC Central Office Bureau of Technical Services (BTS) to discuss the possible closure of the two above referenced BP sites. As noted in the email chain below to Arcadis, we are waiting for additional data on their site which will take about two weeks and this data is crucial in the closure discussion of their Site with Central Office. I would respectfully request that we hold on the scheduling the 363 4th Avenue site discussion with BTS until we receive the data on 1303 Webster so that we may discuss both sites at once. This would not only be easier from a scheduling perspective, but also in that it would enable both Arcadis and Antea to learn from each other s sites in the possible closure of their own respective portfolios while ensuring consistency across all BP sites. Let us know your thoughts. 1/29/16-Vought-After further consideration, spill at 1303 Webster closed as product no longer present and plume is contained. Vought called and spoke with DEC Central Office BTS Kevin Hale and discussed this site. Vought noted that the site was characterized by: product that appeared occasionally in one monitoring well; dissolved groundwater concentrations up to 25,00ppb that were contained to one well; presence of a NYCT subway tunnel immediately adjacent to the dissolved contamination resulting in plume containment due to constant dewatering associated with the tunnel; no reports in past 15-20 years of impacts to the tunnel from the spill, development of former BP gas station with a building that encompasses entire site; installation of a SSDS and vapor barrier in new development preventing any possible impact to building occupants; repeated performance of sulfate injections and VEFR by BP and demonstration of infeasibility as per CP-51 to further reduce groundwater concentrations; and inability to further remediate possible source soils under development due to inability to penetrate vapor barrier as part of occupant protection. Feng to close spill as per Vought and Hale with standard soil contamination clause in spill closure letter approved by RSE. 2/4/2016 - As per J. Vought K. Hale on 1/29/2016, the spill is closed based on J. Vought’s notes on 1/29/2016 in DEC Remark. Spill is closed. Spill closure letter to BP/Antea. "

Remarks: "TWO 4K TANKS FAILED PETRO. (1) LR = -0.448 GPH, (2) LR = GROSS."

All TTF:

Facility ID: 8901904
Spill Number: 8901904
Spill Tank Test: 1535513
Site ID: 90896
Tank Number: Not reported
Tank Size: 0

KAM SERVICE CENTER INC (Continued) **1000556241**

Material: 1213A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 90896
Operable Unit ID: 929176
Operable Unit: 01
Material ID: 449628
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: True

Site ID: 90896
Operable Unit ID: 929176
Operable Unit: 01
Material ID: 2106611
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

SPILLS:
Name: BP SERVICE STATION 13397
Address: 363 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0307900 / 2003-10-27
Facility ID: 0307900
Facility Type: ER
DER Facility ID: 82010
Site ID: 90895
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 2003-10-27
Investigator: JBVOUGHT
Referred To: Not reported

KAM SERVICE CENTER INC (Continued) **1000556241**

Reported to Dept:	2003-10-27
CID:	204
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-27
Spill Record Last Update:	2004-07-26
Spiller Name:	BRAD FISHER
Spiller Company:	BP SERVICE STATION 13397
Spiller Address:	363 4TH AVENUE
Spiller Company:	001
Contact Name:	BRAD FISHER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 10/27/03. Ref. to spill # 8901904. YK."
Remarks:	"STILL UNDER INVESTIGATION"

All Materials:

Site ID:	90895
Operable Unit ID:	874291
Operable Unit:	01
Material ID:	501426
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	KAM SERVICE CENTER INC	
Handler Address:		363 4TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11234
EPA ID:		NYD986988004
Contact Name:		ALI A CEYLAN
Contact Address:		4TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11234
Contact Telephone:		718-499-0191
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported

KAM SERVICE CENTER INC (Continued) **1000556241**

State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11234
Owner Name:	AMOCO OIL CO	
Owner Type:		Private
Operator Name:	NO NAME FOUND	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No

KAM SERVICE CENTER INC (Continued) **1000556241**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AMOCO OIL CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	555 WHARF DR
Owner/Operator City,State,Zip:	NEW HAVEN, CT 06511
Owner/Operator Telephone:	203-865-1910
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: KAM SERVICE CENTER INC	
Legal Status:	Private
Date Became Current:	20020301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MUSTAFA CETIN	
Legal Status:	Private
Date Became Current:	20020301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

KAM SERVICE CENTER INC (Continued) **1000556241**

Owner/Operator Name: AMOCO OIL CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 555 WHARF DR
Owner/Operator City,State,Zip: NEW HAVEN, CT 06511
Owner/Operator Telephone: 203-865-1910
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND
Legal Status: Private
Date Became Current: 20020301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NORTH PETROLEUM INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061022
Handler Name: KAM SERVICE CENTER INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: KAM SERVICE CENTER INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

KAM SERVICE CENTER INC (Continued) **1000556241**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19911213
Handler Name: NORTH PETROLEUM INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061023
Handler Name: KAM SERVICE CENTER INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44711
NAICS Description: GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported

KAM SERVICE CENTER INC (Continued) **1000556241**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19980920
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MD
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004483675

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000556241
Registry ID: 110004483675
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004483675
Name: KAM SERVICE CENTER INC
Address: 363 4TH AVE
City,State,Zip: BROOKLYN, NY 11234

AP341 **BP SS # 13397** **NY UST** **U001837489**
SSW **363 FOURTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.232 mi.
1225 ft. **Site 2 of 7 in cluster AP**

Relative:
Higher

Actual:
26 ft.

UST:

Name:	BP SS # 13397
Address:	363 FOURTH AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-401455 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585641.08609
UTM Y:	4502890.49594
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	19193
Affiliation Type:	Facility Operator
Company Name:	BP SS # 13397
Contact Type:	Not reported
Contact Name:	BP PRODUCTS NORTH AMERICA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 499-0191
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-04-10

Site Id:	19193
Affiliation Type:	Emergency Contact
Company Name:	BP PRODUCTS NORTH AMERICA
Contact Type:	Not reported
Contact Name:	MARK OKAMOTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(800) 272-4357
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-11-25

Site Id:	19193
Affiliation Type:	Facility Owner
Company Name:	BP PRODUCTS NORTH AMERICA
Contact Type:	ENVIRONMENT COMPIANCE SPECIALIST
Contact Name:	MARK OKAMOTO
Address1:	P.O. BOX 6038

BP SS # 13397 (Continued) **U001837489**

Address2:	Not reported
City:	ARTESIA
State:	CA
Zip Code:	90702
Country Code:	001
Phone:	(732) 743-0901
EMail:	MARK.OKAMOTO@BP.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-06-04

Site Id:	19193
Affiliation Type:	Mail Contact
Company Name:	BP PRODUCTS NORTH AMERICA
Contact Type:	ENVIRONMENT COMPIANCE SPECIALIST
Contact Name:	MARK OKAMOTO
Address1:	P.O. BOX 6038
Address2:	Not reported
City:	ARTESIA
State:	CA
Zip Code:	90702
Country Code:	001
Phone:	(732) 743-0901
EMail:	MARK.OKAMOTO@BP.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-06-04

Tank Info:

Tank Number:	001
Tank ID:	170329
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1990
Date Tank Closed:	03/13/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

Tightness Test Method:	21
Date Test:	03/14/2006
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
F02 - Pipe External Protection - Original Sacrificial Anode
B02 - Tank External Protection - Original Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

BP SS # 13397 (Continued) **U001837489**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	001-A
Tank ID:	170330
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	11/01/1970
Date Tank Closed:	11/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	04/01/1990
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	170344
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1990
Date Tank Closed:	03/13/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	03/14/2006
Next Test Date:	Not reported
Pipe Model:	Not reported

BP SS # 13397 (Continued) **U001837489**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
F02 - Pipe External Protection - Original Sacrificial Anode
B02 - Tank External Protection - Original Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 002-A
Tank ID: 170345
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 4000
Install Date: 06/01/1971
Date Tank Closed: 11/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 04/01/1990
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Tank Number: 003
Tank ID: 170346
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 10/01/1990
Date Tank Closed: 03/13/2007

BP SS # 13397 (Continued) **U001837489**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 19
Date Test: 11/07/2000
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003-A
Tank ID: 170348
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 4000
Install Date: 06/01/1971
Date Tank Closed: 11/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 04/01/1990
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

BP SS # 13397 (Continued) **U001837489**

I00 - Overfill - None

Tank Number: 004
Tank ID: 170350
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 10/01/1990
Date Tank Closed: 03/13/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 03/14/2006
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
F02 - Pipe External Protection - Original Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 004-A
Tank ID: 170351
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 04/01/1959
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

BP SS # 13397 (Continued) **U001837489**

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	005
Tank ID:	170352
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1990
Date Tank Closed:	03/13/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	03/14/2006
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	005-A
Tank ID:	170353
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	04/01/1959
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

BP SS # 13397 (Continued) **U001837489**

Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 21816
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 04/01/1959
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 007
Tank ID: 21817
Tank Status: Closed Prior to Micro Conversion, 03/91

BP SS # 13397 (Continued) **U001837489**

Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	04/01/1959
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	ZZZZ
Common Name of Substance:	Invalid Material - Please Fix
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	008
Tank ID:	21818
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	ZZZZ
Common Name of Substance:	Invalid Material - Please Fix
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
I00 - Overfill - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

BP SS # 13397 (Continued) **U001837489**

F00 - Pipe External Protection - None

Tank Number: 009
Tank ID: 21819
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 010
Tank ID: 21820
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity

BP SS # 13397 (Continued) **U001837489**

C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	011
Tank ID:	21821
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	ZZZZ
Common Name of Substance:	Invalid Material - Please Fix
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
I00 - Overfill - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	012
Tank ID:	21822
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	ZZZZ
Common Name of Substance:	Invalid Material - Please Fix
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

BP SS # 13397 (Continued) **U001837489**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 013
Tank ID: 21823
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 014
Tank ID: 21824
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ

BP SS # 13397 (Continued) **U001837489**

Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 015
Tank ID: 21825
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

AI342 **CON EDISON** **NY MANIFEST** **S118088476**
SE **391 2ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.238 mi.
1256 ft. **Site 2 of 5 in cluster AI**

Relative:
Higher

Actual:
59 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	391 2ND ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004760401
Facility Status:	Not reported
Location Address 1:	391 2ND ST
Code:	BP
Location Address 2:	SB 38855
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760401
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/2015
Trans1 Recv Date:	03/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760401
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618906GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118088476**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI343 **CON EDISON** **RCRA NonGen / NLR** **1018281108**
SE **391 2ND ST** **FINDS** **NYP004760401**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.238 mi.
1256 ft. **Site 3 of 5 in cluster AI**

Relative: **Higher**
Actual: **59 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150330
Handler Name:	CON EDISON	
Handler Address:		391 2ND ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004760401
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported

CON EDISON (Continued) **1018281108**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1018281108**

Historic Generators:
Receive Date: 20150330
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150330
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067687211

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018281108
Registry ID: 110067687211

CON EDISON (Continued) **1018281108**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067687211
Name: CON EDISON
Address: 391 2ND ST
City,State,Zip: BROOKLYN, NY 11215

AI344 **CON EDISON** **NJ MANIFEST** **S120669812**
SE **391 2ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.238 mi.
1256 ft. **Site 4 of 5 in cluster AI**

Relative: **Higher**
Actual: **59 ft.**

NJ MANIFEST:

EPA Id:	NYP004760401
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002618906GBF
EPA ID:	NYP004760401
Date Shipped:	3/30/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON (Continued) **S120669812**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AE345 **PARK SLOPE PAINT STRIPPERS INC** **RCRA-SQG** **1012187182**
NNW **553 UNION ST** **NY MANIFEST** **NYR000170472**
1/8-1/4 **BROOKLYN, NY 11215** **NJ MANIFEST**
0.238 mi.
1257 ft. **Site 4 of 7 in cluster AE**

Relative: **Lower**

Actual: **11 ft.**

RCRA-SQG:

Date Form Received by Agency:		20091112
Handler Name:	PARK SLOPE PAINT STRIPPERS INC	
Handler Address:		553 UNION ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYR000170472
Contact Name:		DEAN CAMENARES
Contact Address:		UNION ST
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		718-783-4112
Contact Fax:		Not reported
Contact Email:		DEAN@WESTRIPWOOD.COM
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		UNION ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	MICHAEL MARCHITELLO	
Owner Type:		Private
Operator Name:	DEAN CAMENARES	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: DEAN CAMENARES	
Legal Status:	Private
Date Became Current:	20090901
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MICHAEL MARCHITELLO	
Legal Status:	Private
Date Became Current:	19971001
Date Ended Current:	Not reported
Owner/Operator Address:	8512 14TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11228
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20091112
Handler Name:	PARK SLOPE PAINT STRIPPERS INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	23832
NAICS Description:	PAINTING AND WALL COVERING CONTRACTORS

NAICS Code:	81142
NAICS Description:	REUPHOLSTERY AND FURNITURE REPAIR

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20150806
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	PARK SLOPE PAINT STRIPPERS INC
Address:	553 UNION ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

EPA ID:	NYR000170472
Facility Status:	Not reported
Location Address 1:	553 UNION ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000170472
Mailing Name:	PARK SLOPE PAINT STRIPPERS INC
Mailing Contact:	PARK SLOPE PAINT STRIPPERS INC
Mailing Address 1:	553 UNION ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11215
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	12/14/2009
Trans1 Recv Date:	12/14/2009
Trans2 Recv Date:	12/18/2009
TSD Site Recv Date:	12/24/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000170472
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004718183JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1350
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	Not reported
Waste Code 1_3:	D008
Waste Code 1_4:	D001
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYR000170472
Mail Address:	UNION ST
Mail City/State/Zip:	BROOKLYN, NY 11215
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DEAN CAMENARES
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006651124JJK
EPA ID:	NYR000170472
Date Shipped:	5/10/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1,200.00 Pounds

Manifest Number:	008758697JJK
EPA ID:	NYR000170472
Date Shipped:	3/7/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002 D008 D001
Hand Code:	Not reported
Quantity:	2,000.00 Pounds

Manifest Number:	004718397JJK
EPA ID:	NYR000170472
Date Shipped:	03/30/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/30/2010
Date Trans2 Transported Waste:	04/02/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/08/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 200 P

Manifest Year: Not reported
Waste Code: F002
Hand Code: H141
Quantity: 1500 P

Manifest Number: 006657876JJK
EPA ID: NYR000170472
Date Shipped: 11/03/2010
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/03/2010
Date Trans2 Transported Waste: 11/05/2010
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 11/10/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F003
Hand Code: H141

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Quantity: 900 P

Manifest Number: 008757720JJK
EPA ID: NYR000170472
Date Shipped: 6/4/2012
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11215
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F002 D008 F003 D001 D010
Hand Code: Not reported
Quantity: 1,350.00 Pounds

Manifest Number: 006651336JJK
EPA ID: NYR000170472
Date Shipped: 9/1/2011
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1,350.00 Pounds

Manifest Number:	008757563JJK
EPA ID:	NYR000170472
Date Shipped:	2/29/2012
TSDF EPA ID:	NJD080631369
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002 D008
Hand Code:	Not reported
Quantity:	1,350.00 Pounds

Manifest Number:	006651422JJK
EPA ID:	NYR000170472
Date Shipped:	11/11/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1,350.00 Pounds

Manifest Number:	004718306JJK
EPA ID:	NYR000170472
Date Shipped:	06/14/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/14/2010
Date Trans2 Transported Waste:	06/14/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/16/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1450 P

Manifest Number:	008757997JJK
EPA ID:	NYR000170472
Date Shipped:	10/25/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002 D008
Hand Code:	Not reported
Quantity:	800.00 Pounds

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Manifest Number:	008757891JJK
EPA ID:	NYR000170472
Date Shipped:	8/14/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002 D008 D001
Hand Code:	Not reported
Quantity:	1,350.00 Pounds

Manifest Number:	006657718JJK
EPA ID:	NYR000170472
Date Shipped:	08/17/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/17/2010
Date Trans2 Transported Waste:	08/20/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/24/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1350 P

Manifest Number:	006657957JJK
EPA ID:	NYR000170472
Date Shipped:	1/10/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1,350.00 Pounds

Manifest Number:	004718471JJK
EPA ID:	NYR000170472
Date Shipped:	05/03/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/03/2010
Date Trans2 Transported Waste:	05/03/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/11/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1350 P

Manifest Number:	008758673JJK
EPA ID:	NYR000170472
Date Shipped:	2/13/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11215
Reason Load Was Rejected:	Not reported

PARK SLOPE PAINT STRIPPERS INC (Continued) **1012187182**

Waste:
Manifest Year: Not reported
Waste Code: F002 D001 D008
Hand Code: Not reported
Quantity: 1,600.00 Pounds

AK346 **CON EDISON** **NY MANIFEST** **S119073767**
South **314 5TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11205**
0.239 mi.
1262 ft. **Site 4 of 5 in cluster AK**

Relative:
Higher

Actual:
32 ft.

NY MANIFEST:
Name: CON EDISON
Address: 314 5TH ST
City,State,Zip: BROOKLYN, NY 11205
Country: USA
EPA ID: NYP004363230
Facility Status: Not reported
Location Address 1: 314 5 ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11205
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004363230
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/19/2013
Trans1 Recv Date: 09/19/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/24/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CON EDISON (Continued) **S119073767**

Generator EPA ID:	NYP004363230
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002220646GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK347 **CON EDISON - SERVICE BOX 45987** **RCRA-LQG** **1016963307**
South **314 5 ST** **NYP004363230**
1/8-1/4 **BROOKLYN, NY 11205**
0.239 mi.
1262 ft. **Site 5 of 5 in cluster AK**

Relative: **Higher**

Actual: **32 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - SERVICE BOX 45987
Handler Address:	314 5 ST
Handler City,State,Zip:	BROOKLYN, NY 11205
EPA ID:	NYP004363230
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private

CON EDISON - SERVICE BOX 45987 (Continued) **1016963307**

Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

CON EDISON - SERVICE BOX 45987 (Continued) **1016963307**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130919
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130919
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - SERVICE BOX 45987
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON - SERVICE BOX 45987 (Continued) **1016963307**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130919
Handler Name: CON EDISON SERVICE BOX: 45987
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131019
Handler Name: CON EDISON SERVICE BOX: 45987
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AP348 **AMOCO SERVICE STATION** **RCRA NonGen / NLR** **1004757402**
SSW **375-381 4TH AVE & 6TH ST** **FINDS** **NYD986933109**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.239 mi. **NY MANIFEST**
1263 ft. **Site 3 of 7 in cluster AP**

Relative: **Higher**
Actual: **26 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: AMOCO SERVICE STATION
Handler Address: 375-381 4TH AVE & 6TH ST
Handler City,State,Zip: BROOKLYN, NY 11215
EPA ID: NYD986933109
Contact Name: ADEL HREITZ
Contact Address: ANITA DR

AMOCO SERVICE STATION (Continued) **1004757402**

Contact City,State,Zip:		JACKSON, NY 08527
Contact Telephone:		201-928-5315
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		ANITA DR
Mailing City,State,Zip:		JACKSON, NY 08527
Owner Name:	AMOCO OIL CO	
Owner Type:		Private
Operator Name:	AMOCO OIL CO	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No

AMOCO SERVICE STATION (Continued) **1004757402**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AMOCO OIL CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: AMOCO OIL CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AMOCO OIL CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

AMOCO SERVICE STATION (Continued) **1004757402**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: AMOCO SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: AMOCO SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901214
Handler Name: AMOCO SERVICE STATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AMOCO SERVICE STATION (Continued) **1004757402**

FINDS:
Registry ID: 110008045613

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004757402
Registry ID:	110008045613
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008045613
Name:	AMOCO SERVICE STATION
Address:	375-381 4TH AVE & 6TH ST
City,State,Zip:	BROOKLYN, NY 11215

NY MANIFEST:

Name:	AMOCO OIL COMPANY
Address:	375-381 4TH AVE & 6TH ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYD986933109
Facility Status:	Not reported
Location Address 1:	375-381 4TH AVE & 6TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986933109
Mailing Name:	AMOCO OIL COMPANY
Mailing Contact:	AMOCO OIL COMPANY
Mailing Address 1:	52 ANITA DRIVE
Mailing Address 2:	Not reported
Mailing City:	JACKSON
Mailing State:	NJ
Mailing Zip:	08527
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

AE349 **563 SACKETT STREET** **NY BROWNFIELDS** **S118141136**
North **563 SACKETT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.240 mi.
1266 ft. **Site 5 of 7 in cluster AE**

Relative: **Lower**
Actual: **15 ft.**

BROWNFIELDS:

Name:	563 SACKETT STREET
Address:	563 SACKETT STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	507650
Acres:	0.229
HW Code:	C224222
SWIS:	2401
Town:	New York City
Record Added Date:	05/08/2015
Record Updated Date:	06/08/2021
Update By:	DJEATON
Site Description:	"Location: The site is located at 563 Sackett Street in the Gowanus neighborhood of Brooklyn, Kings County, and is identified as Block 426 lot 44. The site is approximately 0.229 acres in size. Site Features: The site is developed with a large open shed, which is divided into two portions. A two-story structure consisting of stacked metal shipping containers is present at the northeast side of the site and is used for storage and office space by the site occupants. The remainder of the site consists of an unpaved yard that is used for general storage by the occupants. The majority of the eastern portion of the yard is covered with metal plates and the remainder of the yard consists primarily of exposed soil and gravel cover. Current Zoning and Land Use: The current zoning of the property is for commercial use. The eastern portion of the shed is occupied by Partner For You, a general commercial products (e.g., plastic bottles and aluminum cans) recycling facility, and the western portion of the shed is occupied by Brooklyn Truck & Equipment Repair, a vehicle and equipment repair operation. Historical Use: The site and surrounding area have been developed for residential, commercial and industrial uses since at least 1886. Historical site uses included Nolan Bro s Contractors (1904), a wagon builder (1915), a bottle storage facility (1938-1950), parking (1969 to 2007). Geology and Hydrogeology: The site lies at an average elevation of about 15 feet. The site is generally covered with paved roads, walkways and buildings. The built environment is generally underlain by fill material used for construction and development since the 1800's. The subsurface strata at the site consists of historic fill material characterized by loose silty sand with varying amounts of brick and concrete fragments, rubber, metal wire and coal fragments extending to depths ranging from about 10 to 20 feet below grade surface. The historic fill material was underlain by alluvial deposits consisting of poorly sorted sands with gravel and marsh deposits, referred to as meadow mat, which consists of interbedded sands, clays and silts. Depth of groundwater was measured at 13.84 feet below grade surface in a monitoring well located in the center of 560 DeGraw Street and at 6.85 feet below grade surface in the southwestern corner of 560 DeGraw Street. The depth to groundwater was measured at 9 feet bgs within the former gasholder footprint. Groundwater elevation measurements recorded from monitoring wells across the former MGP site indicate that the shallow groundwater, on the east side of the Canal, generally flows westward toward the

563 SACKETT STREET (Continued) **S118141136**

	Gowanus Canal at high and low tide levels. "
Env Problem:	"Nature and Extent of Contamination: The primary contaminants of concern at the site are Semi-Volatile Organic Compounds (SVOCs) and Metals. SVOCs include Benzo(a)pyrene, Benzo(b)fluoranthene, Benzo(k)fluoranthene and Chrysene. Metals include Arsenic, Barium, Cadmium, Copper, Lead and Mercury. The Volatile Organic Compound (VOC) Benzene was detected in one groundwater well. Soil: Contamination including SVOC and Metals were observed throughout the historic fill layer that exists at the site. The fill layer is generally present from grade to depths of approximately twenty feet below grade. The SVOCs Benzo(a)pyrene, Benzo(b)fluoranthene, Benzo(k)fluoranthene and Chrysene were detected at maximum concentrations of 22.7; 14.7; 16.1 and 14.5 parts per million (ppm), respectively. Their respective unrestricted use soil cleanup objectives are 1, 1, 0.8 and 1 ppm. The Metals Arsenic, Barium, Cadmium, Copper, Lead and Mercury were detected at maximum concentrations of 36.4; 679; 34.3; 1,240; 1,840; and 1.57 ppm respectively. Their respective unrestricted use soil cleanup objectives are 13; 350; 2.5; 50; 63 and 0.18 ppm. Groundwater: Limited groundwater contamination was observed. Benzene was detected in one on-site well at a concentration of 2.6 parts per billion (ppb). The ambient groundwater standard for Benzene is 1 ppb. The SVOC benzo(b)fluoranthene was detected in one well at 0.6 ppb, exceeding its ambient groundwater standard of 0.002 ppb. In addition, the Metals Manganese and Selenium were detected in groundwater at maximum concentrations of 1,000 and 13 ppb respectively. Their respective groundwater quality standards are 300 and 10 ppb. Soil and Sub-Slab Soil Vapor: Various petroleum related VOCs were detected in the soil vapor samples collected at the site. Tetrachloroethene was detected in a soil vapor sample at a concentration of 240 micrograms per cubic meter (ug/m^3). There is no standard for soil vapor concentrations. Special Resources Impacted or Threatened: None"
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-14 08:50:00
Record Upd:	2015-05-14 08:50:00
Updated By:	SRHEIGEL
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Candace Vasquez
Owner Company:	Brooklyn Public Library - Pacific Branch
Owner Address:	25 4th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	1
Sub Type:	06

563 SACKETT STREET (Continued) **S118141136**

Owner Name:	Not reported
Owner Company:	242 Nevins, Inc.
Owner Address:	444 Third Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Marino Mazzei
Owner Company:	Bella Venezia, LLC
Owner Address:	242 Nevins Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AH350 **CON EDISON** **NY MANIFEST** **1016961536**
NW **408 CARROL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.241 mi.
1275 ft. **Site 10 of 11 in cluster AH**

Relative: **Lower**

Actual: **4 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	408 CARROL ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004342978
Facility Status:	Not reported
Location Address 1:	408 CARROL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004342978
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON (Continued) **1016961536**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/07/2013
Trans1 Recv Date:	08/07/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004342978
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002219243GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH351 **CON EDISON - MANHOLE 4** **RCRA-LQG** **1016961535**
NW **408 CARROL ST** **NYP004342978**
1/8-1/4 **BROOKLYN, NY 11201**
0.241 mi.
1275 ft. **Site 11 of 11 in cluster AH**

Relative: **Lower**
Actual: **4 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 4
Handler Address:	408 CARROL ST
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004342978
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 4 (Continued) **1016961535**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130807
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private

CON EDISON - MANHOLE 4 (Continued) **1016961535**

Date Became Current:	20130807
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name: CON EDISON - MANHOLE 4	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130807
Handler Name: CON EDISON MANHOLE: 4	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130907
Handler Name: CON EDISON MANHOLE: 4	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON - MANHOLE 4 (Continued) **1016961535**

Evaluation Action Summary:
Evaluations: No Evaluations Found

AL352 **CON EDISON SERVICE BOX: 45175** **RCRA NonGen / NLR** **1016454433**
ENE **195 5TH AVE FRONT OF** **FINDS** **NYP004326278**
1/8-1/4 **BROOKLYN, NY 11217** **ECHO**
0.243 mi. **NY MANIFEST**
1282 ft. **Site 2 of 2 in cluster AL**

Relative: **Higher**
Actual: **49 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130809
Handler Name:	CON EDISON SERVICE BOX:	45175
Handler Address:		195 5TH AVE FRONT OF
Handler City,State,Zip:		BROOKLYN, NY 11217
EPA ID:		NYP004326278
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN

CON EDISON SERVICE BOX: 45175 (Continued) **1016454433**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20131227
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130709
Handler Name: CON EDISON SERVICE BOX:	45175
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130809
Handler Name: CON EDISON SERVICE BOX:	45175
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 45175 (Continued) **1016454433**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056507506

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016454433
Registry ID:	110056507506
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056507506
Name:	CON EDISON SERVICE BOX: 45175
Address:	195 5TH AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11217

NY MANIFEST:

Name:	CON EDISON
Address:	195 5TH AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004326278
Facility Status:	Not reported
Location Address 1:	195 5TH AVE
Code:	BP
Location Address 2:	SB #45175
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217

CON EDISON SERVICE BOX: 45175 (Continued) **1016454433**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004326278
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/09/2013
Trans1 Recv Date: 07/09/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/10/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004326278
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002084404GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 45175 (Continued) **1016454433**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AP353 **U-HAUL CO OF METRO NY** **NY UST** **U000394587**
SSW **259 6TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.243 mi.
1284 ft. **Site 4 of 7 in cluster AP**

Relative:
Higher

Actual:
27 ft.

UST:

Name:	U-HAUL CO OF METRO NY
Address:	259 6TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Id/Status:	2-083976 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585479.15778
UTM Y:	4502946.99870
Site Type:	Other

Affiliation Records:

Site Id:	1917
Affiliation Type:	Facility Owner
Company Name:	U-HAUL CO OF METRO NY.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	230 WEST 230TH STREET
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10463
Country Code:	001
Phone:	(212) 562-8700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1917
Affiliation Type:	Mail Contact
Company Name:	U-HAUL CO OF METRONY
Contact Type:	Not reported
Contact Name:	BILL NEWTON
Address1:	230 WEST 230TH STREET
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10463
Country Code:	001
Phone:	(212) 562-8700
EMail:	Not reported

U-HAUL CO OF METRO NY (Continued) **U000394587**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1917
Affiliation Type:	Facility Operator
Company Name:	U-HAUL CO OF METRO NY
Contact Type:	Not reported
Contact Name:	KAREN MARKS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 237-2894
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1917
Affiliation Type:	Emergency Contact
Company Name:	U-HAUL CO OF METRO NY.
Contact Type:	Not reported
Contact Name:	WILLIAM NEWTON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 562-8700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	3161
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	06/01/1983
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	03
Date Test:	01/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported

U-HAUL CO OF METRO NY (Continued) **U000394587**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 002
Tank ID: 3162
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1983
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 03
Date Test: 01/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 3163
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1983
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

U-HAUL CO OF METRO NY (Continued) **U000394587**

Tightness Test Method: 03
Date Test: 01/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

AP354 **U-HAUL** **NY LTANKS** **S102672726**
SSW **259 6TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.243 mi.
1284 ft. **Site 5 of 7 in cluster AP**

Relative: **Higher**

Actual: **27 ft.**

LTANKS:

Name: U-HAUL
Address: 259 6TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9412186 / 2006-03-13
Facility ID: 9412186
Site ID: 225909
Spill Date: 1994-12-12
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: aaobliga
Referred To: Not reported
Reported to Dept: 1994-12-12
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-01-27
Spill Record Last Update: 2006-03-13
Spiller Name: Not reported
Spiller Company: U-HAUL CORP
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 186468

U-HAUL (Continued) **S102672726**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT VOLATILE ORGANIC COMPOUNDS DETECTED IN SOIL BORINGS AT PROPERTY. REMEDIATION WAS RECOMMENDED TO AMERICAN HI-TECH/ALLAN MILLER. 12/2/2003 Transferred from Sangesland to Rommel 5/25/05-Vought-Received from Michael Morris (ATC 212-353-8280x345) regarding status of report review. Vought returned call and requested another copy of report be sent. New groundwater data will be collected and sent. 6/7/05-Vought-File review by Vought: Letter from American Hi-Tech (Trish Merwin)-12/15/94. American Hi-Tech has attmepted to remove two 4000 gallon and one 4000 diesel underground storage tanks from the above referenced facility. However, these tanks are encased in three feet of concrete and removal is not possible . AHT would like to abandon these tanks. Revised and Final Site Assessment Work Plan (Dames & Moore)-7/8/94. Three (4000-gallon) USTs onsite. ...the tank incoluated with the tracer gas detected in the soil gas was filled with water and not petroleum product at the time of testing. On this basis, it appears that one of the USTs may have failed the recent integrity testing . if a tank test failure is confirmed then a site assessment as desribed below will be conducted . Site assessment will include soil borings at former tankfield and at pump island. Focused Subsurface Site Investigation (ATC Associates)-2/20/01. Three 4000-gallon gasoline/diesel USTs were abandoned at the Site in 1996. Two 550-gallon gasoline USTs were removed from the Site in 1996; and three 5000-gallon fuel oil USTs were abandoned in 1998. Fifteen soil borings were performed at the site. ...ATC concludes that the former presence of gasoline and/or diesel USTs has adversely affected the subsurface soil and groundwater quality at the site and that further investigation is recommended . ATC recommends that additional soil borings and groundwater monitoring wells be installed tat the Site to further delineate soil and groundwater conditions . In 1995 approximately 49.25 tons of impacted soil was removed from the Site. Sixteen soil samples and six groundwater samples were collected. Soil analyticals show 20200ppb 1,2,4-trimethylbenzene(B1 11.5-12.5'bg), 3950ppb xylene(B2 12-13'bg), 908ppb benzene(B7 6-7'bg), 15800ppb ethylbenzene(B7 6-7'bg), 141000ppb 1,2,4-trimethylbenzene(B7 6-7'bg), 305ppb benzene(B8 11.5-12.5'bg), 78.4ppb benzene(B9 11-12'bg), 177ppb MTBE(B9 11-12'bg), 135ppb benzene(B10 10-11'bg), 75ppb benzene(B12 6.5-7.5'bg), 64ppb benzene(B13 12.5-13.5'bg). Analyticals also show high SVOCs at B6 19-20'bg such as 126000ppb flouranthene, 156000ppb phenanthrene, 38400ppb benzo(b)fluoranthene. Boring logs for B6 show coal fragments, cinders and ash in layers . Groundwater analyticals show 193ppb MTBE(UHP 1W), 38ppb MTBE(UHP 8W). Groundwater Investigation (ATC Associates)-6/3/02. Installation of six monitoring wells. The lack of contamination in the upgradient sample from MW4 along with the calculated groundwater flow direction indicated that the former gas station locations both onsite and offsite at the intersection of Fourth Avenue and Sixth Street have not contributed to the groundwater contamination at this Site . No active USTs onsite. Therefore steady state equilibrium has been reached between the contamination present in the soil and groundwater resulting in attenuation of the contamination by the mechanism of sorption, degradation and dilution . ATC request No Further Action. Groundwater at depth of 15-17' below grade and flow to the north. Groundwater analyticals show 7.4ppb 1,2,4-trimethylbenzene(MW1), 109ppb MTBE(MW1), 10ppb MTBE(MW2), 5ppb ethylbenzene(MW5), 15ppb xylene(MW5), 30ppb MTBE(MW5), 19ppb MTBE(MW6). Limited Groundwater

U-HAUL (Continued) **S102672726**

Investigation(ATC Associates)-6/2/05. ...ATC personnel attempted to collect groundwater samples from six onsite groundwater monitoring wells; however, ATC could only locate five of the wells . Groundwater at depth of 15 feet below grade and flow to the north. Report recommends No Further Action. Groundwater analyticals show 140ppb benzene(MW3), 12ppb ethylbenzene(MW3) and 12ppb MTBE(MW4). 6/7/05-Vought-Called Michael Morris and required that 1)he provided suspected source of groundwater contamination in MW3 2)continue quarterly monitoring of groundwater 3)submit surrounding area site plan. Vought sent letter stating same. 9/26/05- Obligado - FILE TRANFERRED FROM VOUGHT TO OBLIGADO 10/20/05 - Obligado - Received phone call from Michael Morris. Requesting status of closure report review. Told him had not been reviewed yet but would look at it in near future. 10/28/05 - Obligado - Review Limited Remedial Investigation Report. Gasoline service station 363 4th avenue east of site across 4th Ave with open spill number 9606963. further, although sensitive receptors, including the Gowanas Canal, residential development, schools, et.c, were observed in the area, none of these receptors are suspected to be impacted as a results of the limited impacted groundwater at the Site. Ground water analyticals from 5 wells: 118 ppb benzene (mw3), 7.58 ppb ethylbenzene (mw3), 10.5 ppb MTBE (MW5). NFA rejected. Require 1) continued quarterly groundwater monitoring, and include MW6 in monitoring network. 2) Include Gowanus Canal on Surrounding Area Site plan. Call Michael Moore, inform him of above requirements. 3/13/06 - Obligado - Review report from ATC, dated January 23, 2006. Subway line approximately 30 to 40 ft bgs and upgradient, ATC doesn't suspect any impact to subway line. Ground water sampled on 11/18/05 and 1/4/06. On 11/18/05, the only BTEX compound is xylene at 5.98 ppb in MW2 and MTBE is 27.7 ppb at MW3. MW-6 not sampled. On 1/4/06, no BTEX compounds were detected in anywells, MTBE was detected at MW3, MW4, MW5, and MW6, with max at MW6 of 353 ppb. Conclusions: - No odor, sheen, or floating product was observed, and no sensitive receptors appear to be impacted by the groundwater beneath the site. BTEX concentrations have decreased to non-detect. Request no further action. Discussed site with J.Sun on 3/10/06. Agree to grant no further action. "

Remarks: "SOIL DISOCVERED IN TANK PULLS -TANKS ARE VAULTED IN CONCRETE. JACOB KRIMGOLD WAS AT SITE ."

All Materials:

Site ID:	225909
Operable Unit ID:	1009931
Operable Unit:	01
Material ID:	374516
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AP355 **U-HAUL CORP** **RCRA NonGen / NLR** **1000981347**
SSW **259 6TH ST - PARK SLOPE** **FINDS** **NY0000970509**
1/8-1/4 **BROOKLYN, NY 11210** **ECHO**
0.243 mi. **NY MANIFEST**
1284 ft. **Site 6 of 7 in cluster AP**

Relative: **Higher**
Actual: **27 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	U-HAUL CORP	
Handler Address:		259 6TH ST - PARK SLOPE
Handler City,State,Zip:		BROOKLYN, NY 11210
EPA ID:		NY0000970509
Contact Name:		RONALD MARKEY
Contact Address:		6TH ST - PARK SLOPE
Contact City,State,Zip:		BROOKLYN, NY 11210
Contact Telephone:		908-389-8181
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		6TH ST - PARK SLOPE
Mailing City,State,Zip:		BROOKLYN, NY 11210
Owner Name:	U-HAUL CORP - AMERCO REAL ESTATE	
Owner Type:		Private
Operator Name:	U-HAUL CORP - AMERCO REAL ESTATE	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

U-HAUL CORP (Continued) **1000981347**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	U-HAUL CORP - AMERCO REAL ESTATE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2727 N CENTRAL AVE
Owner/Operator City,State,Zip:	PHOENIX, AZ 85004
Owner/Operator Telephone:	602-263-6555
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	U-HAUL CORP - AMERCO REAL ESTATE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2727 N CENTRAL AVE
Owner/Operator City,State,Zip:	PHOENIX, AZ 85004

U-HAUL CORP (Continued) **1000981347**

Owner/Operator Telephone: 602-263-6555
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: U-HAUL CORP - AMERCO REAL ESTATE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2727 N CENTRAL AVE
Owner/Operator City,State,Zip: PHOENIX, AZ 85004
Owner/Operator Telephone: 602-263-6555
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: U-HAUL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: U-HAUL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941209
Handler Name: U-HAUL CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

U-HAUL CORP (Continued) **1000981347**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19981202
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MD
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

U-HAUL CORP (Continued) **1000981347**

FINDS:
Registry ID: 110008108216

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000981347
Registry ID:	110008108216
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008108216
Name:	U-HAUL CORP
Address:	259 6TH ST - PARK SLOPE
City,State,Zip:	BROOKLYN, NY 11210

NY MANIFEST:

Name:	UHAUL CORP CT PARKSLOPE
Address:	259 6TH ST - PARK SLOPE
City,State,Zip:	BROOKLYN, NY 11210
Country:	USA
EPA ID:	NY0000970509
Facility Status:	Not reported
Location Address 1:	259 6TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11210
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000970509
Mailing Name:	UHAUL CORP CT PARKSLOPE
Mailing Contact:	RONALD MARKEY
Mailing Address 1:	259 6TH STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11210
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9083898181

AN356
NNE
1/8-1/4
0.243 mi.
1285 ft.

RINALDI RECYCLING CO. INC.
182 4TH AVE.
BROOKLYN, NY 11217

Site 4 of 4 in cluster AN

NY SWF/LF **S105842419**
N/A

Relative:
Higher

Actual:
26 ft.

SWF/LF:

Name:	RINALDI RECYCLING CO. INC.
Address:	182 4TH AVE.
City,State,Zip:	BROOKLYN, NY 11217
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185226648
Owner Name:	Frank Rinaldi
Owner Type:	Not reported
Owner Address:	182 4th Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Email:	Not reported
Owner Phone:	7185226648
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Regulated medical waste - radiopharmacy
Activity Number:	[24MA9]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

357
WNW
1/8-1/4
0.244 mi.
1287 ft.

NYSDOT 3RD ST BRIDGE & GOWANUS CANAL
3RD ST BRG OVER GOWANUS CANAL
BROOKLYN, NY 11201

RCRA NonGen / NLR **1000555036**
NYD986975316

Relative:
Lower

Actual:
0 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	NYSDOT 3RD ST BRIDGE & GOWANUS CANAL
Handler Address:	3RD ST BRG OVER GOWANUS CANAL
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYD986975316
Contact Name:	MUHAMMAD AFZAL
Contact Address:	RECTOR ST
Contact City,State,Zip:	NEW YORK, NY 10006
Contact Telephone:	212-414-7172
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

NYSDOT 3RD ST BRIDGE & GOWANUS CANAL (Continued) **1000555036**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		RECTOR ST
Mailing City,State,Zip:		NEW YORK, NY 10006
Owner Name:	NYSDOT	
Owner Type:		Private
Operator Name:	NYSDOT	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported

NYSDOT 3RD ST BRIDGE & GOWANUS CANAL (Continued) **1000555036**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYSDOT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 RECTOR ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10008
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NYSDOT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 RECTOR ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10008
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NYSDOT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 RECTOR ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10008
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported

NYSDOT 3RD ST BRIDGE & GOWANUS CANAL (Continued) **1000555036**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYSDOT 3RD ST BRIDGE & GOWANUS CANAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYSDOT 3RD ST BRIDGE & GOWANUS CANAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19911101
Handler Name: NYSDOT 3RD ST BRIDGE & GOWANUS CANAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AO358 **CON EDISON MANHOLE: 5416** **RCRA NonGen / NLR** **1016960296**
SSW **267 6TH ST** **NY MANIFEST** **NYP004322004**
1/8-1/4 **BROOKLYN, NY 11215**
0.245 mi.
1292 ft. **Site 3 of 3 in cluster AO**

Relative: **Higher**

Actual: **27 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20130720
Handler Name:	CON EDISON MANHOLE: 5416	
Handler Address:		267 6TH ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004322004
Contact Name:		KHARY BERRY
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4574
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		ADMINISTRATIVE ASSISTANT L1-2
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON MANHOLE: 5416 (Continued) **1016960296**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130620
Handler Name:	CON EDISON MANHOLE: 5416
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130720
Handler Name:	CON EDISON MANHOLE: 5416
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 5416 (Continued) **1016960296**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	267 6TH ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004322004
Facility Status:	Not reported
Location Address 1:	OPP 267 6TH ST
Code:	BP
Location Address 2:	MH 5416
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004322004
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/2013
Trans1 Recv Date:	06/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004322004

CON EDISON MANHOLE: 5416 (Continued) **1016960296**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084565GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE359 **A & A BRAKE CO INC** **NY AST** **A100349510**
NNW **560 SACKETT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.245 mi.
1295 ft. **Site 6 of 7 in cluster AE**

Relative: **Lower**

Actual: **12 ft.**

AST:

Name:	A & A BRAKE CO INC
Address:	560 SACKETT STREET
City,State,Zip:	BROOKLYN, NY 11217
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604492
Program Type:	PBS
UTM X:	585655.75898
UTM Y:	4503665.63198
Expiration Date:	05/04/2015
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	26364

A & A BRAKE CO INC (Continued) **A100349510**

Affiliation Type:	Facility Owner
Company Name:	GERALD P. ABATEMARCO
Contact Type:	PRESIDENT
Contact Name:	GERALD P. ABATEMARCO
Address1:	560 SACKETT ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Site Id:	26364
Affiliation Type:	Mail Contact
Company Name:	A&A BRAKE SERVICE
Contact Type:	Not reported
Contact Name:	GERALD P. ABATEMARCO
Address1:	224 THIRD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-05-20

Site Id:	26364
Affiliation Type:	Facility Operator
Company Name:	A & A BRAKE CO INC
Contact Type:	Not reported
Contact Name:	GERALD P. ABATEMARCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Site Id:	26364
Affiliation Type:	Emergency Contact
Company Name:	GERALD P. ABATEMARCO
Contact Type:	Not reported
Contact Name:	GERALD P. ABATEMARCO
Address1:	Not reported
Address2:	Not reported

A & A BRAKE CO INC (Continued) **A100349510**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Tank Info:

Tank Number:	002
Tank Id:	233064
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	C01 - Pipe Location - Aboveground I04 - Overfill - Product Level Gauge (A/G) G11 - Tank Secondary Containment - Double-bottom (Aboveground) E02 - Piping Secondary Containment - Vault (with Access) F00 - Pipe External Protection - None H02 - Tank Leak Detection - Interstitial - Manual Monitoring A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground) J02 - Dispenser - Suction Dispenser D00 - Pipe Type - No Piping L02 - Piping Leak Detection - Interstitial - Manual Monitoring
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/17/2009
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

AE360 **A & A BRAKE CO INC** **NY UST** **U003740198**
NNW **560 SACKETT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.245 mi.
1295 ft. **Site 7 of 7 in cluster AE**

Relative:
Lower

Actual:
12 ft.

UST:

Name:	A & A BRAKE CO INC
Address:	560 SACKETT STREET
City,State,Zip:	BROOKLYN, NY 11217
Id/Status:	2-604492 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	05/04/2015
UTM X:	585655.75898
UTM Y:	4503665.63198
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	26364
Affiliation Type:	Facility Owner
Company Name:	GERALD P. ABATEMARCO
Contact Type:	PRESIDENT
Contact Name:	GERALD P. ABATEMARCO
Address1:	560 SACKETT ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Site Id:	26364
Affiliation Type:	Mail Contact
Company Name:	A&A BRAKE SERVICE
Contact Type:	Not reported
Contact Name:	GERALD P. ABATEMARCO
Address1:	224 THIRD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-05-20

Site Id:	26364
Affiliation Type:	Facility Operator
Company Name:	A & A BRAKE CO INC
Contact Type:	Not reported
Contact Name:	GERALD P. ABATEMARCO
Address1:	Not reported

A & A BRAKE CO INC (Continued) **U003740198**

Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Site Id:	26364
Affiliation Type:	Emergency Contact
Company Name:	GERALD P. ABATEMARCO
Contact Type:	Not reported
Contact Name:	GERALD P. ABATEMARCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 624-4488
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-31

Tank Info:

Tank Number:	001
Tank ID:	57989
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	275
Install Date:	01/01/1988
Date Tank Closed:	04/15/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	C
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C01 - Pipe Location - Aboveground
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin

A & A BRAKE CO INC (Continued) **U003740198**

L09 - Piping Leak Detection - Exempt Suction Piping
B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser

---

361 **SOUTH BROOKLYN REALTY LLC** **NY UST** **U003128182**
NNW **301 NEVINS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.246 mi.
1299 ft.

Relative:
Lower

Actual:
11 ft.

UST:

Name:	SOUTH BROOKLYN REALTY LLC
Address:	301 NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11217
Id/Status:	2-452483 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585595.33969
UTM Y:	4503649.92015
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	19772
Affiliation Type:	Facility Owner
Company Name:	SOUTH BROOKLYN REALTY LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	410 4TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 797-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19772
Affiliation Type:	Mail Contact
Company Name:	SOUTH BROOKLYN REALTY LLC
Contact Type:	Not reported
Contact Name:	KEN SILBER
Address1:	410 4TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 797-9000
EMail:	Not reported

SOUTH BROOKLYN REALTY LLC (Continued) **U003128182**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19772
Affiliation Type:	Facility Operator
Company Name:	SOUTH BROOKLYN REALTY LLC
Contact Type:	Not reported
Contact Name:	KEN SILBER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 625-8667
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19772
Affiliation Type:	Emergency Contact
Company Name:	SOUTH BROOKLYN REALTY LLC
Contact Type:	Not reported
Contact Name:	NICK IANNETTI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 797-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	35475
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	06/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

SOUTH BROOKLYN REALTY LLC (Continued) **U003128182**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 002
Tank ID: 35476
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 003
Tank ID: 35477
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

SOUTH BROOKLYN REALTY LLC (Continued) **U003128182**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 004
Tank ID: 35478
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F00 - Pipe External Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 005
Tank ID: 63808
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550

SOUTH BROOKLYN REALTY LLC (Continued) **U003128182**

Install Date:	Not reported
Date Tank Closed:	06/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None

362
SSE
1/8-1/4
0.247 mi.
1305 ft.

MESSINA **NY AST** **U003386108**
392 3RD ST **N/A**
BROOKLYN, NY 11215

Relative:
Higher

Actual:
52 ft.

AST:

Name:	MESSINA
Address:	392 3RD ST
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-272094
Program Type:	PBS
UTM X:	585999.65429
UTM Y:	4502867.96198
Expiration Date:	N/A
Site Type:	Private Residence

Affiliation Records:

Site Id:	11512
Affiliation Type:	Facility Owner
Company Name:	MESSINA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	392 3RD ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 965-2561

MESSINA (Continued) **U003386108**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2004-12-15

Site Id:	11512
Affiliation Type:	Mail Contact
Company Name:	MESSINA
Contact Type:	Not reported
Contact Name:	SUPER FACILITY MANAGER
Address1:	392 3RD ST
Address2:	APT. #1
City:	BROOKLYN
State:	NY
Zip Code:	11215
Country Code:	001
Phone:	(718) 965-2561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2004-12-15

Site Id:	11512
Affiliation Type:	Facility Operator
Company Name:	MESSINA
Contact Type:	Not reported
Contact Name:	MESSINA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-2561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11512
Affiliation Type:	Emergency Contact
Company Name:	MESSINA
Contact Type:	Not reported
Contact Name:	MESSINA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-2561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

MESSINA (Continued) **U003386108**

Tank Info:

Tank Number:	001
Tank Id:	9187
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/30/2004
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AM363 **AJR (COMMERCIAL BLDG.)** **NY LTANKS** **S106869125**
NNE **599 DEGRAW ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.249 mi.
1313 ft. **Site 2 of 2 in cluster AM**

Relative: LTANKS:
Lower

Actual: Name:	AJR (COMMERCIAL BLDG.)
22 ft. Address:	599 DEGRAW ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0500453 / 2005-04-28
Facility ID:	0500453
Site ID:	343388
Spill Date:	2005-04-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2005-04-11
CID:	406
Water Affected:	Not reported
Spill Notifier:	Other

AJR (COMMERCIAL BLDG.) (Continued) **S106869125**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-11
Spill Record Last Update:	2005-04-28
Spiller Name:	JAMES FLEMING
Spiller Company:	AJR WOODWORKING
Spiller Address:	599 DEGRAW ST
Spiller County:	001
Spiller Contact:	RICHIE
Spiller Phone:	(718) 624-2929
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	289859
DEC Memo:	"need to send TTF letter no PBS for this address. 4/28/05. J.Krimgold reviewed a letter report submitted by Mercury Tank & Pump dated April 25, 2005. According to the report a 550 gal #2 oil tank failed the test due to disconnected pipe fittings on the top of the tank. The tank was empty at the time of test. Tank top was excavated,tank was cleaned up and filled with concrete slurry. Before this a hole was drilled through the bottom of the tank to obtain a soil sample. All analytes were found below TAGMs objectives. NFA letter. "
Remarks:	"Doing a tank test on an old heating tank that no one knew was there. No contamination found or evidence of a leak. Ullage failure... unsure of any removal of tank."

All TTF:

Facility ID:	0500453
Spill Number:	0500453
Spill Tank Test:	1548775
Site ID:	343388
Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	343388
Operable Unit ID:	1102073
Operable Unit:	01
Material ID:	582304
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported

AJR (COMMERCIAL BLDG.) (Continued) **S106869125**

Units: G
Recovered: .00
Oxygenate: Not reported

AQ364 **553 SACKETT STREET** **NY VCP** **S128723346**
North **553 SACKETT STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.250 mi.
1320 ft. **Site 1 of 2 in cluster AQ**

Relative: **Lower**
Actual: **14 ft.**

VCP NYC:
Project ID: 21TMP1642K,22EHAN154K,22CVCP044K
Name: 553 SACKETT STREET
Address: 553 SACKETT STREET
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 3.0042600493004202E+29
OER Program: VCP (Enrolled), E/RD (Review), State BCP
Phase: Approved Remedial Plan
Latitude: 40.679451
Longitude: -73.986184
Postcode: 6
Community Board: 33
Council District: 119
Census Tract: 3000000
BIN: 3004260049
NTA: Park Slope-Gowanus

AI365 **401 3RD STREET** **NY LTANKS** **S102672277**
SE **401 3RD STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.259 mi.
1365 ft. **Site 5 of 5 in cluster AI**

Relative: **Higher**
Actual: **57 ft.**

LTANKS:
Name: 401 3RD STREET
Address: 401 3RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9310090 / 1993-11-19
Facility ID: 9310090
Site ID: 244717
Spill Date: 1993-11-11
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: C3
Cleanup Ceased: 1993-11-19
SWIS: 2401
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 1993-11-19
CID: Not reported
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False

401 3RD STREET (Continued) **S102672277**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-22
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	GUIDE BROS. OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	201015
DEC Memo:	""
Remarks:	"SPILL IN CELLAR IN DIRT FLOOR - SPILLER APPLIED -"

All Materials:

Site ID:	244717
Operable Unit ID:	989051
Operable Unit:	01
Material ID:	392722
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP366 **FERRANTINO & CO** **NY LTANKS** **S102659626**
SSW **278 6TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.265 mi.
1397 ft. **Site 7 of 7 in cluster AP**

Relative:
Higher

Actual:
29 ft.

LTANKS:

Name:	FERRANTINO & CO
Address:	278 6TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9705330 / 2011-08-01
Facility ID:	9705330
Site ID:	304152
Spill Date:	1997-08-01
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	1997-08-01
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

FERRANTINO & CO (Continued) **S102659626**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-08-01
Spill Record Last Update:	2011-08-02
Spiller Name:	VINCENT SAVINO
Spiller Company:	FERRANTINO & CO
Spiller Address:	278 6TH ST
Spiller County:	001
Spiller Contact:	VINCENT SAVINO
Spiller Phone:	(718) 499-6000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	245736
DEC Memo:	"4/10/06, Dyber: Received signed STIP. 3/30/06, Dyber: Sent STIP to Ken Mikkelson. 3/22/06, Dyber: Left message for Ken Mikkelson of Rosma Development. I said that I want to send him a STIP agreement. 02/21/06. J.Krimgold received a call from Billy Maysonet (Brothers Environmental) stating the his co. is a consultant for a current property owner. The owner is planing to redevelop the site and is willing to take steps necessary to close the spill case. However, they would like a letter or a phone call for directions. The owner's info: Attn. Mark Yonger M&N Development Corp. 65 Taaffe Place Brooklyn, NY 11205 (718)403-0900 The consultant info: Attn. Billy Maysonet Brothers Environmental 610 Underhill Avenue Bronx, NY 10473 877-839-6009 End JK. 8/18/05, Dyber: Ferrantino has not called back. Refer back to region. 8/02/05, Dyber: No call back from Ferrantino - left another message. 7/26/05, Dyber: Left message for Mark Ferrantino. 7/21/05, Dyber: Called Ferrantino Fuel Corp, 180 9th st, Brooklyn 11215-3111, 718-832-6700. Secretary told me to speak to Mark Ferrantino and call back next Tuesday. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill was reassigned from DEC Sigona to Rommel on January 7, 2004. 02/21/06. J.Krimgold received a call from Billy Maysonet (Brothers Environmental) stating the his co. is a consultant for a current property owner. The owner is planing to redevelop the site and is willing to take steps necessary to close the spill case. However, they would like a letter or a phone call for directions. The owner's info: Attn. Mark Yonger M&N Development Corp. 65 Taaffe Place Brooklyn, NY 11205 (718)403-0900 The consultant info: Attn. Billy Maysonet Brothers Environmental 610 Underhill Avenue Bronx, NY 10473 877-839-6009 End JK. 09/26/06 this case was transfer from Albany to Region 2. 10/2/06-Zhune called Rosma develpoment spoke to Joe Weiss. He told me that ken Mikkelson is no longer working for this company. He asked me to sent the stipulation letter copy to: Rosma Devepolment 199 Lee Ave Apt # 287 Brooklyn, NY 11211 Att: Joe Weiss 10/2/06-Zhune called Dyber. He doesn't have estipulation letter in his recods. 10/2/06. A copy of Stipulation letter signed was sent to Joe Weiss above address. 08/22/09- Zhune spoke to Dennis Goldstein from Ferrantino & Co. He need ccpies of stipulation and spill report. I said I will fax them. 04/14/10- Zhune spoke to Mike Taylor (Service Manager) from Ferrantino & CO 718-832-6700. He said Ferrantino sold the propety in 2005. The tanks were closed and soil invetigation was performed. The new owner knocked down the biulding. He plan to do something else. Mike will contact the company that closure the tanks and he will call back. 05/28/10-Zhune called Mike Taylor for three

FERRANTINO & CO (Continued) **S102659626**

weeks in a road. Everytime that I spoke to him he said I will call you back with name of company and he never called back. 05/28/10-The Petroleum Bulk Storage facility report show four tanks closed in 2008. 001 550 gal. Kerosene 002 275 #2 heating oil 003 4000 Diesel 004 4000 Gasoline 08/01/2011- Fenley & Nicol Environmental sent the subsurface investigation report, dated June 10,2011. The result of GPR survey did not revealed anomalies consistent with the presence of UST sytem. Apparently the UST system and pump island have been removed in August 2007 during demolition of structure On March 21 to 28, 2011 F&N installed thirteen(13) soil probes, three temporary wells and three monitoring wells. The analitycal soil results indicates one VOCs (1,2,4 Trimethylbenzene 6000 ug/kg in sample Sp-10(10-15') detected above the NYSDEC Soil Cleanup Guidance values and some SVOCS detected below the NYSDEC Soil Cleanup Guidance value. The groundwater results indicates that TW-2 had Isopropyltoluene and sec-Buthylbenzene exceedence of 10 ug/lt and 74 ug/lt respectively. TW-3 had secbulthylbenzene exceedence of 32 ug/lt. MW-2 had no exceedence and no VOCs were detected in monitoring wells MW-1 and MW-3. Groundwater flow direction was found to be southwesterly direction. Spill Closed. . "

Remarks: "IN PROCESS OF SEPARATING PIPING FROM TANKS AND ISOLATING IN ORDER TO CONTINUE INVESTIGATION"

All Materials:

Site ID:	304152
Operable Unit ID:	1048582
Operable Unit:	01
Material ID:	334552
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

367 **RINALDI RECYCLING CO.** **NY SWRCY** **S105842286**
NNE **326 DOUGLASS STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.273 mi.
1441 ft.

Relative:
Higher

Actual:
25 ft.

SWRCY:

Name:	RINALDI RECYCLING CO.
Address:	326 DOUGLASS STREET
City,State,Zip:	BROOKLYN, NY 11217
Region:	2
Facility Address 2:	Not reported
Phone Number:	7185226648
Owner Type:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported

RINALDI RECYCLING CO. (Continued) **S105842286**

Contact Name: DOMINICK RINALDI
Contact Address: Not reported
Contact Address 2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: RHRF - registration
Activity Number: [24MA9]
Active: No
East Coordinate: 585977
North Coordinate: 4503566
Accuracy Code: Not reported
Regulatory Status: Not reported
Permit #: Not reported
Auth. Date: Not reported
Expiration Date: Not reported
Waste Types: Not reported
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

368
NW
1/4-1/2
0.277 mi.
1460 ft.

CARROLL ST. TRANSFER STATION **NY SWF/LF** **S105841710**
400 CARROLL ST **N/A**
BROOKYN, NY 11215

Relative:
Lower

Actual:
4 ft.

SWF/LF:
Name: CARROLL ST. TRANSFER STATION
Address: 400 CARROLL ST
City,State,Zip: BROOKYN, NY 11215
Flag: INACTIVE
Region Code: 2
Phone Number: 7186436551
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: JOE COSTELLO; OWNER
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Transfer station - permit
Activity Number: [24T53]
Active: No
East Coordinate: 585300
North Coordinate: 4503500
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: 2-6103-00062
Authorization Date: Not reported
Expiration Date: Not reported

CARROLL ST. TRANSFER STATION (Continued) **S105841710**

Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

AR369 **GOWANUS VILLAGE I** **NY INST CONTROL** **S121933912**
WNW **153 2ND ST A/K/A 322 3RD AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.277 mi.
1465 ft. **Site 1 of 2 in cluster AR**

Relative:
Lower

Actual:
6 ft.

INST CONTROL:
Name: GOWANUS VILLAGE I
Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: Monitoring Plan
HW Code: C224099
Control Code: 31
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623
Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater movement generally to the northwest toward the Gowanus Canal. "
Env Problem: "Prior to Remediation: The primary contaminant of concern is

GOWANUS VILLAGE I (Continued) **S121933912**

polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The groundwater extraction well system will prevent LNAPL migration. Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America

GOWANUS VILLAGE I (Continued) **S121933912**

Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099

GOWANUS VILLAGE I (Continued) **S121933912**

Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

Name: GOWANUS VILLAGE I

GOWANUS VILLAGE I (Continued) **S121933912**

Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: Site Management Plan
HW Code: C224099
Control Code: 32
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623
Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater movement generally to the northwest toward the Gowanus Canal. "
Env Problem: "Prior to Remediation: The primary contaminant of concern is polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The groundwater extraction well system will prevent LNAPL migration.

GOWANUS VILLAGE I (Continued) **S121933912**

Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon

GOWANUS VILLAGE I (Continued) **S121933912**

Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported

GOWANUS VILLAGE I (Continued) **S121933912**

HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

Name: GOWANUS VILLAGE I
Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: Environmental Easement
HW Code: C224099
Control Code: J
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623

GOWANUS VILLAGE I (Continued) **S121933912**

Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater movement generally to the northwest toward the Gowanus Canal. "

Env Problem: "Prior to Remediation: The primary contaminant of concern is polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The groundwater extraction well system will prevent LNAPL migration. Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth

GOWANUS VILLAGE I (Continued) **S121933912**

containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported

GOWANUS VILLAGE I (Continued) **S121933912**

Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN

GOWANUS VILLAGE I (Continued) **S121933912**

Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

Name: GOWANUS VILLAGE I
Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: IC/EC Plan
HW Code: C224099
Control Code: 34
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623
Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential

GOWANUS VILLAGE I (Continued) **S121933912**

use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater movement generally to the northwest toward the Gowanus Canal. "

Env Problem: "Prior to Remediation: The primary contaminant of concern is polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The groundwater extraction well system will prevent LNAPL migration. Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False

GOWANUS VILLAGE I (Continued) **S121933912**

Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository

GOWANUS VILLAGE I (Continued) **S121933912**

Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26

GOWANUS VILLAGE I (Continued) **S121933912**

Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

Name: GOWANUS VILLAGE I
Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: O&M Plan
HW Code: C224099
Control Code: 33
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623
Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit

GOWANUS VILLAGE I (Continued) **S121933912**

R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater movement generally to the northwest toward the Gowanus Canal. "

Env Problem: "Prior to Remediation: The primary contaminant of concern is polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The groundwater extraction well system will prevent LNAPL migration. Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon

GOWANUS VILLAGE I (Continued) **S121933912**

Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported

GOWANUS VILLAGE I (Continued) **S121933912**

HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 28
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964

GOWANUS VILLAGE I (Continued) **S121933912**

Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

Name: GOWANUS VILLAGE I
Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: Soil Management Plan
HW Code: C224099
Control Code: 14
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623
Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater

GOWANUS VILLAGE I (Continued) **S121933912**

movement generally to the northwest toward the Gowanus Canal. "

Env Problem: "Prior to Remediation: The primary contaminant of concern is polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The groundwater extraction well system will prevent LNAPL migration. Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported

GOWANUS VILLAGE I (Continued) **S121933912**

Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN

GOWANUS VILLAGE I (Continued) **S121933912**

Waste Code: Not reported
HW Code: C224099
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

GOWANUS VILLAGE I (Continued) **S121933912**

Name: GOWANUS VILLAGE I
Address: 153 2ND ST A/K/A 322 3RD AVENUE
City,State,Zip: BROOKLYN, NY 11217
Site Code: 332623
Control Name: Ground Water Use Restriction
HW Code: C224099
Control Code: 08
Control Type: INST
Dt record added: 12/20/2017
Dt rec updated: 09/21/2020
Updated By: RPMUSTIC
Site Code: 332623
Site Description: "Location: The property is an approximately 2.5 acre site located in a commercial/industrial area of Brooklyn at 153 2nd Street a/k/a 322 3rd Avenue. The Gowanus Canal is located adjacent to the site to the northwest. Site Features: A 24,200 square foot, three story vacant structure occupies the eastern portion of the site. The building has a basement floor that is a 13 foot thick concrete slab that extends below the water table. The remainder of the site is covered by the final site cover system. Current Zoning and Land Use: The site is currently inactive and is zoned as a manufacturing district (M2-1) by the City of New York. The property uses surrounding the site are primarily light industrial, with a small concentration of residential use. The closest residential properties are located approximately 300 feet to the northeast of the site near the intersection of 3rd Avenue and Carroll Street. The site is bordered to the north by a 60 foot wide filled-in canal (former 1st Street Basin), which is to be restored as part of the Gowanus Canal NPL site remedy. To the east is a storage facility, a Verizon truck depot is located south of the site, and the Gowanus Canal, which is approximately 100 feet wide, lies directly west of the site. Past Use of the Site: Sanborn maps dating back to 1886 indicate that the site was occupied by Nassau Sulfur Works and Smith and Shaw Mattress Materials and Paper Stock. In 1904, the property was transferred to the Brooklyn Rapid Transit R.R. Power Plant. Under their ownership, it appears that coal was delivered by water and transported beneath the site via coal tunnel. In 1938, the property was turned over to the Williamsburg Power Plant Corporation and used as a central power station. The property was transferred to the New York City Transit System in 1950, where it was used as an electrical sub-station and switching yard until 1996. Site Geology and Hydrogeology: The site is underlain by urban fill, generally to a depth of about 8 feet, but reportedly ranging to depths up to 24 feet in some areas. Below the fill is a layer of organic silt indicative of a historic wetland. The depth to groundwater ranges from about 7 feet to 20 feet with groundwater movement generally to the northwest toward the Gowanus Canal. "
Env Problem: "Prior to Remediation: The primary contaminant of concern is polychlorinated biphenyls (PCBs). The PCBs do not appear to be contributing to off site environmental impacts that require additional investigation or remedial action. The contaminants found in each media sampled (soil, groundwater and soil vapor) are summarized below: Soil: Only one post excavation sample (44 ppm PCBs) exceeded the 10 ppm remedial cleanup objective specified in the Decision Document. The levels of PCB contamination are high under the existing on site building, but the groundwater remedy (LNAPL collection system) will prevent its migration. Groundwater: PCB contaminated LNAPL exists under the existing on site building. The

GOWANUS VILLAGE I (Continued) **S121933912**

groundwater extraction well system will prevent LNAPL migration. Monitoring the groundwater monitoring well network will illustrate the remedy is protective of public health and the environment. Soil Vapor: The most significant detection was for tetrachloroethene (perchloroethene or PCE) detected at concentrations up to 1,260 ug/m3 along 2nd Street. Soil Vapor Intrusion evaluations is to be performed for on-site buildings before occupancy is permitted. Post Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCB compounds in soil, and PCB-containing oil atop the groundwater table. Remedial action resulted in attainment of the site specific cleanup objectives throughout the parcel, with all soil below two feet in depth containing less than 10 ppm PCB. The site is now covered with a cover system allowing for restricted residential use. Remaining contamination in soil, groundwater, and soil vapor, if any, is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 40:40'39 /
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: Gemini Arts Initiative, Inc.
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03

GOWANUS VILLAGE I (Continued) **S121933912**

Owner Name: Katie Dixon
Owner Company: Gemini Arts Subsidiary LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Park Slope Library
Owner Address: 431 6th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11215
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Katie Dixon
Owner Company: BRT Powerhouse LLC
Owner Address: 98 4th Street
Owner Addr2: Suite 406
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Brian Davidson
Owner Company: NYSDEC
Owner Address: 625 Broadway - 12th Fl.
Owner Addr2: Not reported
Owner City,St,Zip: Albany, NY 12233-7016
Owner Country: United States of America
HW Code: C224099
Waste Type: 1,4-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: chlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: mercury
Waste Quantity: UNKNOWN

GOWANUS VILLAGE I (Continued) **S121933912**

Waste Code: Not reported
HW Code: C224099
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224099
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 08/21/2012
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-06-22 08:50:00
Record Updated: 2016-06-22 08:50:00
Updated By: JCGRATHW
Crossref ID: C224099-08-12
Cross Ref Type Code: 28
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-05-24 09:26:00
Record Updated: 2013-05-24 09:26:00
Updated By: BRWOLOSE
Crossref ID: 1609964
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2017-03-30 07:42:00
Record Updated: 2017-03-30 07:42:00
Updated By: JCGRATHW
Crossref ID: 2017000371814
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-17 09:44:00
Record Updated: 2017-11-17 09:44:00
Updated By: JCGRATHW

AS370 **280 DOUGLAS ST/PENSKE** **NY LTANKS** **S102671834**
North **280 DOUGLAS ST/PENSKE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.287 mi.
1514 ft. **Site 1 of 2 in cluster AS**

Relative: LTANKS:
Lower
Name: 280 DOUGLAS ST/PENSKE
Actual: Address: 280 DOUGLAS ST/PENSKE
21 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9112095 / 1992-03-03
Facility ID: 9112095

280 DOUGLAS ST/PENSKE (Continued) **S102671834**

Site ID:	280189
Spill Date:	1992-02-25
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1992-03-03
SWIS:	2401
Investigator:	SJMILLER
Referred To:	Not reported
Reported to Dept:	1992-02-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-03-02
Spill Record Last Update:	1992-03-04
Spiller Name:	Not reported
Spiller Company:	OIL INDUSTRIAL LTD CO
Spiller Address:	336 9TH ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	227495
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER "
Remarks:	"CONTAINED ON PAVEMENT. 1 GALLON TO STORM DRAIN, POSSIBLY. NYCFD ON SITE, NYCDEP NOTIFIED."

All Materials:

Site ID:	280189
Operable Unit ID:	965689
Operable Unit:	01
Material ID:	417082
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AS371 **280 DOUGLAS ST** **NY LTANKS** **S101341149**
North **280 DOUGLAS STREET** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.287 mi.
1514 ft. **Site 2 of 2 in cluster AS**

Relative:
Lower

Actual:
21 ft.

LTANKS:

Name:	280 DOUGLAS ST
Address:	280 DOUGLAS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9410669 / 1995-03-10
Facility ID:	9410669
Site ID:	160988
Spill Date:	1994-11-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-03-10
SWIS:	2401
Investigator:	SJMILLER
Referred To:	Not reported
Reported to Dept:	1994-11-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-12-08
Spill Record Last Update:	1995-04-17
Spiller Name:	Not reported
Spiller Company:	PENSKE TRUCK
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	105739
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER "
Remarks:	"TO EX-TANK AFTER PUMPING OUT"

All TTF:

Facility ID:	9410669
Spill Number:	9410669
Spill Tank Test:	1543335
Site ID:	160988
Tank Number:	Not reported
Tank Size:	0
Material:	0022
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

280 DOUGLAS ST (Continued) **S101341149**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 160988
Operable Unit ID: 1008534
Operable Unit: 01
Material ID: 376536
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: 280 DOUGLAS STREET
Address: 280 DOUGLAS STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9415539 / 1995-02-28
Facility ID: 9415539
Facility Type: ER
DER Facility ID: 105739
Site ID: 121831
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1995-02-28
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1995-02-28
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: 1995-02-28
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-04-20
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: WHALECO
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks: "VENT LINE OVERFILLED DUE TO BAD GAUGE"

280 DOUGLAS ST (Continued) **S101341149**

All Materials:

Site ID:	121831
Operable Unit ID:	1008983
Operable Unit:	01
Material ID:	370722
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	280 DOUGLAS STREET
Address:	280 DOUGLAS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9310083 / 1993-11-18
Facility ID:	9310083
Facility Type:	ER
DER Facility ID:	105739
Site ID:	121830
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1993-11-18
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1993-11-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-11-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-19
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO OIL CO.
Spiller Address:	1 COFFEY ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"DRIVER HOOKED UP TO THE WRONG TANK. WHALECO USED SPEEDY DRY AND SORBENTS TO CLEAN IT UP. NO CALL BACK."

All Materials:

Site ID:	121830
Operable Unit ID:	991794
Operable Unit:	01
Material ID:	392716

280 DOUGLAS ST (Continued) **S101341149**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	280 DOUGLAS ST
Address:	280 DOUGLAS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9415530 / 1995-03-01
Facility ID:	9415530
Facility Type:	ER
DER Facility ID:	105739
Site ID:	160989
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-02-28
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-02-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-03-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-04-20
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO FUEL
Spiller Address:	1 COFFEY ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"BAD GAUGE WHEN FILLING - PRODUCT VENTED ONTO THE ROOF OF THE BUILDING. 7-10 PEOPLE FROM WHALECO FUEL THERE NOW TO CLEAN UP. PETROLEEUM TANK CLEANERS WAS UP ON ROOF."

All Materials:

Site ID:	160989
Operable Unit ID:	1008973
Operable Unit:	01
Material ID:	370713
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum

280 DOUGLAS ST (Continued) **S101341149**

Quantity: 40.00
Units: G
Recovered: 40.00
Oxygenate: Not reported

372
ENE
1/4-1/2
0.289 mi.
1528 ft.

19 BERKELEY PL
19 BERKELEY PL
BROOKLYN, NY

NY LTANKS **S105997672**
NY Spills **N/A**

Relative:
Higher

Actual:
52 ft.

LTANKS:

Name:	AYALA RESIDENCE
Address:	19 BERKELEY PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0209599 / 2002-12-18
Facility ID:	0209599
Site ID:	238174
Spill Date:	2002-12-18
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	DO
Referred To:	Not reported
Reported to Dept:	2002-12-18
CID:	390
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-18
Spill Record Last Update:	2010-08-26
Spiller Name:	Not reported
Spiller Company:	CONSOLIDATED OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	JOHN
Spiller Phone:	(718) 230-9123
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	196170
DEC Memo:	"Austin - closed -see #0209601 - end"
Remarks:	"caller reporting oil company filled tank - and it spilled oil onto the floor - unk how much spilled caller states that there is approx 1 inch of material on the floor - would like dec to respond and check the air quality"

All Materials:

Site ID:	238174
Operable Unit ID:	860852
Operable Unit:	01
Material ID:	513019

19 BERKELEY PL (Continued) **S105997672**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	19 BERKELEY PL
Address:	19 BERKELEY PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0209601 / 2010-10-26
Facility ID:	0209601
Facility Type:	ER
DER Facility ID:	196170
Site ID:	238175
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-12-18
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2002-12-18
CID:	396
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-18
Spill Record Last Update:	2010-10-26
Spiller Name:	Not reported
Spiller Company:	CONSOLATED OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RAY LARA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/18/02 arakhan 3:50PM PTC CLEANUP CREW ON WAY TO SPILL LOCATION. WILL CALL BACK WITH UPDATE. SAME AS SPILL #0209599. 4:02 PM PET TANK CLEANERS NOT DOING CLEANUP; TRI-STATE CALLED BY OIL CO'S INSURANCE COMPANY. 10/26/10 - Austin - Nothing in spill description or uantity indicates that this was anything other than a small surface spill - spill closed - end"
Remarks:	"clean up inprogress."

All Materials:

Site ID:	238175
Operable Unit ID:	860854
Operable Unit:	01

19 BERKELEY PL (Continued) **S105997672**

Material ID:	513021
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AQ373 **FULTON MUNICIPAL WORKS** **EDR MGP** **1008407890**
NNW **NEVINS, DEGRAW AND SACKETT STS.** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.290 mi.
1530 ft. **Site 2 of 2 in cluster AQ**

Relative: Manufactured Gas Plants:
Lower No additional information available

Actual:
10 ft.

AT374 **163 6TH STREET LLC** **NY SWRCY** **S117392702**
WSW **163 6TH ST** **NY MANIFEST** **N/A**
1/4-1/2 **BROOKLYN, NY 11215** **NY SPDES**
0.302 mi.
1597 ft. **Site 1 of 4 in cluster AT**

Relative: SWRCY:
Lower

Actual:
11 ft.

Name:	SIXTH STREET IRON AND METAL
Address:	163 6TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	2
Facility Address 2:	Not reported
Phone Number:	7182223133
Owner Type:	Not reported
Owner Name:	Sixth Street Iron and Metal
Owner Address:	163 6th Street
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Anthony DeConcillis
Contact Address:	same
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	anthony@dorannresources.com
Contact Phone:	7182223133
Activity Desc:	RHRF - exempt (non-VDF)
Activity Number:	[24M00]
Active:	No
East Coordinate:	585300
North Coordinate:	4503057
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Permit #:	Not reported

163 6TH STREET LLC (Continued) **S117392702**

Auth. Date: Not reported
Expiration Date: Not reported
Waste Types: Not reported
Operator Name: Not reported
Operator Type: Not reported
Last Date: Not reported

NY MANIFEST:
Name: 163 6TH STREET LLC
Address: 163 6TH ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYR000232280
Facility Status: Not reported
Location Address 1: 163 6TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11215
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000232280
Mailing Name: 163 6TH STREET LLC
Mailing Contact: 163 6TH STREET LLC
Mailing Address 1: 163 6TH ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11215
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJR986653780
Trans2 State ID: Not reported
Generator Ship Date: 10/04/2017
Trans1 Recv Date: 10/04/2017
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/04/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000232280
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: PAD085690592
TSDF ID 2: Not reported
Manifest Tracking Number: 010962571FLE
Import Indicator: N
Export Indicator: N

163 6TH STREET LLC (Continued) **S117392702**

Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	51540
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

SPDES:

Name:	SIXTH STREET IRON AND METAL
Address:	163 6TH ST
City,State,Zip:	BROOKLYN, NY 11215
Permit Number:	NYR00F428
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5093
State Water Body Name:	GOWANUS CANAL
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	SC
Lat/Long:	+40.674 / -73.990
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	SIXTH STREET IRON AND METAL
Non-Gov Permit Street Address:	SIXTH STREET IRON AND METAL
Non-Gov Permit Supplemental Location:	163 6TH ST
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11215

163 6TH STREET LLC (Continued) **S117392702**

Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	SIXTH STREET IRON AND METAL
Non-Gov Facility Street Address:	SIXTH STREET IRON AND METAL
Non-Gov Facility Supplemental Location:	163 6TH ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11215
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	SIXTH STREET IRON AND METAL
Address:	163 6TH ST
City,State,Zip:	BROOKLYN, NY 11215
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	SIXTH STREET IRON AND METAL
Non-Gov Permit Street Address:	163 6TH ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11215
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	SIXTH STREET IRON AND METAL
Non-Gov Facility Street Address:	SIXTH STREET IRON AND METAL
Non-Gov Facility Supplemental Location:	163 6TH ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11215
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	SIXTH STREET IRON AND METAL
Address:	163 6TH ST
City,State,Zip:	BROOKLYN, NY 11215
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported

163 6TH STREET LLC (Continued) **S117392702**

Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	SIXTH STREET IRON AND METAL
Non-Gov Facility Street Address:	SIXTH STREET IRON AND METAL
Non-Gov Facility Supplemental Location:	163 6TH ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11215
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AT375 **US RECYCLING INC** **NY SWRCY** **S103560390**
WSW **141 6TH STREET** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.303 mi.
1602 ft. **Site 2 of 4 in cluster AT**

Relative: **Lower**
Actual: **8 ft.**

SWRCY:

Name:	US RECYCLING INC
Address:	141 6TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	2
Facility Address 2:	Not reported
Phone Number:	7184887576
Owner Type:	Private
Owner Name:	U.S. Recycling; Inc.
Owner Address:	141 6th Street
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Email:	Not reported
Owner Phone:	7184887576
Contact Name:	Not reported
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - greater than 5 tpd - registration
Activity Number:	[24R20088]
Active:	Yes
East Coordinate:	585234
North Coordinate:	4503097
Accuracy Code:	4.3 - Utilization of Digital Orthophoto Quads
Regulatory Status:	Registration
Permit #:	24R20088
Auth. Date:	3/16/2018
Expiration Date:	3/15/2023
Waste Types:	Commingled Paper;Commingled Containers

US RECYCLING INC (Continued) **S103560390**

Operator Name: Anthony P. Sindone
Operator Type: Private
Last Date: 1/20/2017

SPILLS:

Name:	141 6TH ST BET 1 & 2 AVES
Address:	141 6TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9204442 / 1992-07-31
Facility ID:	9204442
Facility Type:	ER
DER Facility ID:	168471
Site ID:	202525
DEC Region:	2
Spill Cause:	Other
Spill Class:	C2
SWIS:	2401
Spill Date:	1992-07-15
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1992-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	1992-07-31
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-22
Spill Record Last Update:	1993-04-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"NYCDEP SAMPLED. SANITATION POLICE INVESTIGATING."

All Materials:

Site ID:	202525
Operable Unit ID:	968172
Operable Unit:	01
Material ID:	412167
Material Code:	0945A
Material Name:	fabric shards
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Site ID:	202525
Operable Unit ID:	968172

US RECYCLING INC (Continued) **S103560390**

Operable Unit:	01
Material ID:	412166
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR376 **141 3RD STREET** **NY BROWNFIELDS** **S127990284**
WNW **141 3RD STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.305 mi.
1611 ft. **Site 2 of 2 in cluster AR**

Relative: **Lower**

Actual: **6 ft.**

BROWNFIELDS:

Name:	141 3RD STREET
Address:	141 3RD STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	624862
Acres:	1.030
HW Code:	C224336
SWIS:	2401
Town:	New York City
Record Added Date:	09/23/2021
Record Updated Date:	02/01/2022
Update By:	HMDUDEK
Site Description:	"Location: The about 45,500-square-foot (about 1.03 acre) site is located in the Gowanus neighborhood of Brooklyn, New York and is identified as Block 462, Lot 14 on the Brooklyn Borough Tax Map. The site is bound by 2nd Street to the north; the Gowanus Canal to the east; 3rd Street to the south; and parking facilities and commercial and residential buildings followed by Bond Street to the west. Site Features: The site is currently used as an office space, parking lot and construction materials storage for Monadnock Construction. A June 28, 2021 boundary & topographic survey, prepared by Control Point Associates Inc., indicates that the site ground surface slopes down from west (elevation [el]1 9.5) to east (el 5.5), toward the Gowanus Canal. A new steel sheet pile bulkhead was installed along the eastern boundary of the site and completed in August 2017. As part of the construction, dead man piles were installed about 50 feet inland of the canal, connected to the bulkhead with double channel wales. Sheet piles were installed to approximately el -34. Current Zoning and Land Use: The site is zoned for industrial/manufacturing use. The entire site is located in the M2-1 manufacturing district. The surrounding area includes commercial, industrial, residential, and transportation/utility buildings, as well as vacant lots, construction sites, and open space. Past Use of the Site: The site historically operated as a grain and feed mill and woodworking facility from as early as 1886 until at least 1928, a coal company from as early as 1928 until at least 1950, and an automobile salvage yard from as early as 1977 until at least 1986. During the 2011 Site Characterization performed by the ELM Group, droplets of light non-aqueous phase liquids (LNAPL) were observed in one soil boring at

141 3RD STREET (Continued) **S127990284**

the soil/water table interface. Based upon the findings, the New York State Department of Environmental Conservation (NYSDEC) was notified and Spill No. 11-11444 was assigned to the site. A remedial investigation (RI) was performed in March 2012 to further investigate and delineate the extents of the spill impacts. The RI included the installation of delineation borings from the boring location where LNAPL was previously identified, installation of a groundwater monitoring well, and the collection of a groundwater sample. Soil and groundwater analytical results identified that the LNAPL appeared to be bound in the soil and was not impacting the groundwater at the site. LNAPL impacts were limited to an about 20-foot-long, 10-foot-wide, and 6-foot-deep area, which was excavated and removed from site between March and June 2012. A review of groundwater analytical results from samples collected from the remedial excavation indicated target compound list (TCL) volatile organic compounds (VOCs) and semivolatile organic compounds (SVOCs) were not detected, indicating successful LNAPL removal. The excavated area was backfilled and capped to match surrounding grade. The NYSDEC closed the spill on 6 August 2012. A new bulkhead along the eastern boundary of the site was constructed and completed in August 2017. Site Geology and Hydrogeology: Langan s June 2021 limited subsurface investigation at the site identified an about 4-inch-thick asphalt cover in the parking lot area, and an about 7-inch-thick concrete cover near the existing office building. The cover was underlain by contaminated fill predominantly consisting of fine- to medium-grained sand with varying amounts of silt, gravel, concrete, brick, wood, glass, organics and shell fragments. The contaminated fill was observed from surface grade to about 11.5 to 16 feet below grade surface (bgs). Fine-grained silty sand with varying amounts of clay, shells fragments, organics, and gravel was observed below the fill. An approximately 3-foot layer of dark grey silt was observed from approximately 27 to 30 feet bgs. Beneath the silt layer, the soil consisted of reddish brown to brown, fine- to medium-grained sands with varying amounts of silt, fine gravel and clay. Bedrock was not encountered during the June 2021 limited subsurface investigation; however, based on Langan s experience in the surrounding area, bedrock is expected at approximately 150 feet bgs. A 2011 investigation performed by The ELM Group identified a layer of fine- to coarse-grained sands containing varying amounts of silt and gravel from immediately below the asphalt/concrete pavement to an approximate depth of about 6 feet bgs across the site was identified. Isolated lenses of contaminated fill containing varying amounts of brick, wood, concrete and glass were observed from immediately below the asphalt/concrete pavement to approximately 2 to 4 feet bgs across the site. The groundwater flow direction for the area surrounding the site is tidally influenced. Shallow, intermediate, and deep groundwater flow east towards Gowanus Canal. Groundwater underlying the site was observed at about 6 to 9 feet bgs. "

Env Problem: "Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported

141 3RD STREET (Continued) **S127990284**

Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	NNN
Owner Name:	monadnock Development, LLC
Owner Company:	monadnock Development, LLC
Owner Address:	155 3rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Matthew Albert
Owner Company:	155 Third St., LLC
Owner Address:	155 3rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Matthew Albert
Owner Company:	155 Third St., LLC
Owner Address:	155 3rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michael Racioppo
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported

141 3RD STREET (Continued) **S127990284**

Record Updated: Not reported
Updated By: Not reported

AU377 **GOWANUS CANAL CONSERVANCY; INC.** **NY SWF/LF** **S128178173**
West **2 SECOND AVE.** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.313 mi.
1651 ft. **Site 1 of 2 in cluster AU**

Relative: SWF/LF:
Lower

Actual:
2 ft.

Name:	GOWANUS CANAL CONSERVANCY; INC.
Address:	2 SECOND AVE.
City,State,Zip:	BROOKLYN, NY 11215
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185414378
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Composting - source separated organic waste - registration
Activity Number:	[24CG3]
Active:	No
East Coordinate:	585201
North Coordinate:	4503235
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Yard Waste
Authorization #:	24CG3
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Andrew Simons
Operator Type:	Private
Laste Date:	Not reported

AU378 **BK6 SALT LOT COMMUNITY COMPOST SITE** **NY SWF/LF** **S128177808**
West **2 SECOND AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.313 mi.
1651 ft. **Site 2 of 2 in cluster AU**

Relative: SWF/LF:
Lower

Actual:
2 ft.

Name:	BK6 SALT LOT COMMUNITY COMPOST SITE
Address:	2 SECOND AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Flag:	ACTIVE
Region Code:	2

BK6 SALT LOT COMMUNITY COMPOST SITE (Continued) **S128177808**

Phone Number:	Not reported
Owner Name:	NYC Compost Project Hosted by Big Reuse
Owner Type:	Not reported
Owner Address:	1 12th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Email:	justin@bigreuse.org
Owner Phone:	7185353365
Contact Name:	Devin Reitsma
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	devin@bigreuse.org
Contact Phone:	9738685647
Activity Desc:	Composting - SSO - registration
Activity Number:	[24P20012]
Active:	Yes
East Coordinate:	585186
North Coordinate:	4503231
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	Registration
Waste Type:	Source Separated Organic Waste (SSOW);Leaves;Wood/Brush;Yard Waste
Authorization #:	24P20012
Authorization Date:	4/22/2021
Expiration Date:	4/21/2026
Operator Name:	Big Initiatives Incorporated
Operator Type:	Not reported
Laste Date:	Not reported

---

379 **SPILL NUMBER 0209206** **NY LTANKS** **S105997531**
ENE **11 LINCOLN PLACE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.315 mi.
1661 ft.

Relative: **Higher**

Actual: **48 ft.**

LTANKS:

Name:	SPILL NUMBER 0209206
Address:	11 LINCOLN PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0209206 / 2004-04-16
Facility ID:	0209206
Site ID:	156887
Spill Date:	2002-12-07
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2002-12-07
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

SPILL NUMBER 0209206 (Continued) **S105997531**

Remediation Phase:	0
Date Entered In Computer:	2002-12-07
Spill Record Last Update:	2004-04-16
Spiller Name:	MATTHEW FACIANO
Spiller Company:	MORANIA OIL CO
Spiller Address:	2125 MILL AVE
Spiller County:	001
Spiller Contact:	MATTHEW FACIANO
Spiller Phone:	(718) 444-4800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	132734
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 12/9/2002-Vought-Spoke to William Falkenmeyer (Morania) who stated that amount spilled was 1/4 cup.Spoke with Doris Lopsely (Co-op treasurer) who will investigate basement and residence and call back to confirm cleanup within one hour. 12/9/02-Vought-Left Doris message to call back NYSDEC 1/7/04-Vought-Spill transferred from Vought to Austin. 1/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 3/30/04 - Sawyer - Called Doris Lopsey and there was no answer. Left message to call back. 4/16/04 - Sawyer - Talked to Doris Lopsey and she said her Oil Company cleaned up this minor spill long ago."
Remarks:	"CALLER STATES UNK AMT WAS SPILLED IN THE BASEMENT DUE TO TANK OVERFILL. CLEANUP CREW ENROUTE TO RESIDENCE FOR CLEANUP."

All Materials:

Site ID:	156887
Operable Unit ID:	862375
Operable Unit:	01
Material ID:	516185
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV380 **FULTON WORKS** **NY VCP** **S113922087**
NNW **DEGRAW STREET AND NEVINS STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.315 mi.
1661 ft. **Site 1 of 5 in cluster AV**

Relative:
Lower

Actual:
8 ft.

VCP:

Name:	FULTON WORKS
Address:	DEGRAW STREET AND NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11215-
Program Type:	VCP
Site Code:	57151
HW Code:	V00633
Site Class:	N
SWIS:	2401
Region:	2
Town:	New York City

FULTON WORKS (Continued) **S113922087**

Acres:	Not reported
Date Record Added:	01/16/2003
Date Record Updated:	12/07/2009
Updated By:	MOBARRIE
Site Description:	"See Site 224051 "
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	KEYSPAN CORPORATION
Owner Address:	ONE METROTECH CENTER
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	NYC PARKS DEPARTMENT
Owner Address:	ARSENAL WEST - 16 W 61ST STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10023
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	NYC INDUSTRIAL DEVELOPMENT
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	270 NEVINS ST. PROPERTIES
Owner Address:	(NEVINS CANAL CORP.) 116 JOHN STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10038
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	ATS REALTY
Owner Address:	537 SACKETT STREET
Owner Addr2:	Not reported

FULTON WORKS (Continued) **S113922087**

Owner City,St,Zip:	BROOKLYN, NY 11217
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AV381
North
1/4-1/2
0.317 mi.
1672 ft.

FULTON WORKS
DEGRAW STREET AND NEVINS STREET
BROOKLYN, NY 11217

Site 2 of 5 in cluster AV

EDR MGP **1008407891**
N/A

Relative:
Lower

Actual:
8 ft.

Manufactured Gas Plants:
No additional information available

382
North
1/4-1/2
0.320 mi.
1692 ft.

D GAVER & SONS INC
267 DOUGLASS ST
BROOKLYN, NY 11217

NY LTANKS **U001831861**
NY UST **N/A**

Relative:
Lower

Actual:
17 ft.

LTANKS:

Name:	267 DOUGLASS STREET
Address:	267 DOUGLASS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8800904 / 1992-10-02
Facility ID:	8800904
Site ID:	104086
Spill Date:	1988-04-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-02
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-04-29
Spill Record Last Update:	2002-02-15

D GAVER & SONS INC (Continued) **U001831861**

Spiller Name:	Not reported
Spiller Company:	D. GARBER & SONS.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	92017
DEC Memo:	""
Remarks:	"CAPACITY IS A 7,000 GALLON TANK WITH A LEAK RATE OF +2.248 G.P.H. THE TANK IS LOCATED UNDER CEMENT SO NAT RECOMMENDS TO UNCOVER AND RE-TEST FOR POSSIBLE AIR POCKETS."

All TTF:

Facility ID:	8800904
Spill Number:	8800904
Spill Tank Test:	1533785
Site ID:	104086
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	104086
Operable Unit ID:	916385
Operable Unit:	01
Material ID:	460068
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	D GAVER & SONS INC
Address:	267 DOUGLASS ST
City,State,Zip:	BROOKLYN, NY 11217
Id/Status:	2-070114 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

D GAVER & SONS INC (Continued) **U001831861**

UTM X: 585822.91213
UTM Y: 4503761.31858
Site Type: Other

Affiliation Records:

Site Id: 1532
Affiliation Type: Facility Owner
Company Name: D GAVER & SONS
Contact Type: Not reported
Contact Name: Not reported
Address1: 267 DOUGLASS ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (718) 858-2143
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 1532
Affiliation Type: Mail Contact
Company Name: D GAVER & SONS
Contact Type: Not reported
Contact Name: ROBERT GAVER
Address1: 267 DOUGLASS ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (718) 858-2143
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 1532
Affiliation Type: Facility Operator
Company Name: D GAVER & SONS INC
Contact Type: Not reported
Contact Name: ROBERT GAVER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 858-2143
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 1532
Affiliation Type: Emergency Contact

D GAVER & SONS INC (Continued) **U001831861**

Company Name:	D GAVER & SONS
Contact Type:	Not reported
Contact Name:	ROBERT WALKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 852-0392
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	2762
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7000
Install Date:	Not reported
Date Tank Closed:	04/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

AW383 **450 UNION STREET** **NY ENG CONTROLS** **S117936660**
NW **450 UNION STREET** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11231** **NY BROWNFIELDS**
0.324 mi.
1710 ft. **Site 1 of 3 in cluster AW**

Relative: **Lower**
Actual: **10 ft.**

ENG CONTROLS:

Name:	450 UNION STREET
Address:	450 UNION STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	507633
HW Code:	C224219
Control Code:	18
Control Type:	ENG
Date Record Added:	09/10/2020
Date Rec Updated:	05/04/2021
Updated By:	JHOCONNE
Site Description:	"Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported

450 UNION STREET (Continued) **S117936660**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-08 14:42:00
Record Upd:	2020-10-07 17:11:00
Updated By:	JHOCONNE
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Robert Rieger
Owner Company:	450 Union LLC
Owner Address:	10 GLENVILLE STREET, SUITE 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Rieger
Owner Company:	450 Union LLC
Owner Address:	c/o Pilot Real Estate Group LLC
Owner Addr2:	10 Glenville Street, Suite 1
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Robert Reiger
Owner Company:	450 Union Developer LLC
Owner Address:	10 Glenville Street
Owner Addr2:	Suite 1
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224219
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

450 UNION STREET (Continued) **S117936660**

HW Code:	C224219
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	coal tar
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-611519
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2020-07-31 07:57:00
Record Updated:	2020-07-31 07:57:00
Updated By:	LXZIELIN
Crossref ID:	C224219-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-09-10 17:15:00
Record Updated:	2020-09-10 17:15:00
Updated By:	NNCRAWFO
Crossref ID:	2020000271467
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-10-06 18:03:00
Record Updated:	2020-10-06 18:03:00
Updated By:	NNCRAWFO
Name:	450 UNION STREET
Address:	450 UNION STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	507633
HW Code:	C224219
Control Code:	15
Control Type:	ENG
Date Record Added:	09/10/2020
Date Rec Updated:	05/04/2021
Updated By:	JHOCONNE
Site Description:	"Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and

450 UNION STREET (Continued) **S117936660**

driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "

Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-08 14:42:00
Record Upd:	2020-10-07 17:11:00
Updated By:	JHOCONNE
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Robert Rieger
Owner Company:	450 Union LLC
Owner Address:	10 GLENVILLE STREET, SUITE 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03

450 UNION STREET (Continued) **S117936660**

Owner Name:	Robert Rieger
Owner Company:	450 Union LLC
Owner Address:	c/o Pilot Real Estate Group LLC
Owner Addr2:	10 Glenville Street, Suite 1
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Robert Reiger
Owner Company:	450 Union Developer LLC
Owner Address:	10 Glenville Street
Owner Addr2:	Suite 1
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224219
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	coal tar
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-611519
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.

450 UNION STREET (Continued) **S117936660**

Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

INST CONTROL:
Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633
Control Name: Environmental Easement
HW Code: C224219
Control Code: J
Control Type: INST
Dt record added: 09/10/2020
Dt rec updated: 05/04/2021
Updated By: JHOCONNE
Site Code: 507633
Site Description: "Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is

450 UNION STREET (Continued) **S117936660**

complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-05-08 14:42:00
Record Upd: 2020-10-07 17:11:00
Updated By: JHOCONNE
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Carroll Gardens Branch Library
Owner Address: 396 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street
Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported

450 UNION STREET (Continued) **S117936660**

Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633

450 UNION STREET (Continued) **S117936660**

Control Name:	Landuse Restriction
HW Code:	C224219
Control Code:	25
Control Type:	INST
Dt record added:	09/10/2020
Dt rec updated:	05/04/2021
Updated By:	JHOCONNE
Site Code:	507633
Site Description:	"Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-08 14:42:00
Record Upd:	2020-10-07 17:11:00
Updated By:	JHOCONNE
Own Op:	Document Repository
Sub Type:	NNN

450 UNION STREET (Continued) **S117936660**

Owner Name: Not reported
Owner Company: Carroll Gardens Branch Library
Owner Address: 396 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street
Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN

450 UNION STREET (Continued) **S117936660**

Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633
Control Name: IC/EC Plan
HW Code: C224219
Control Code: 34
Control Type: INST
Dt record added: 09/10/2020
Dt rec updated: 05/04/2021
Updated By: JHOCONNE
Site Code: 507633
Site Description: "Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the

450 UNION STREET (Continued) **S117936660**

Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-05-08 14:42:00
Record Upd: 2020-10-07 17:11:00
Updated By: JHOCONNE
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Carroll Gardens Branch Library
Owner Address: 396 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831

450 UNION STREET (Continued) **S117936660**

Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street
Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23

450 UNION STREET (Continued) **S117936660**

Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633
Control Name: O&M Plan
HW Code: C224219
Control Code: 33
Control Type: INST
Dt record added: 09/10/2020
Dt rec updated: 05/04/2021
Updated By: JHOCONNE
Site Code: 507633
Site Description: "Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to prevent

450 UNION STREET (Continued) **S117936660**

potential exposure to remaining contamination on the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-05-08 14:42:00
Record Upd: 2020-10-07 17:11:00
Updated By: JHOCONNE
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Carroll Gardens Branch Library
Owner Address: 396 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street
Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported

450 UNION STREET (Continued) **S117936660**

HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633
Control Name: Site Management Plan
HW Code: C224219
Control Code: 32
Control Type: INST
Dt record added: 09/10/2020
Dt rec updated: 05/04/2021

450 UNION STREET (Continued) **S117936660**

Updated By:	JHOCONNE
Site Code:	507633
Site Description:	"Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-08 14:42:00
Record Upd:	2020-10-07 17:11:00
Updated By:	JHOCONNE
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America

450 UNION STREET (Continued) **S117936660**

Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street
Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219

450 UNION STREET (Continued) **S117936660**

Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633
Control Name: Monitoring Plan
HW Code: C224219
Control Code: 31
Control Type: INST
Dt record added: 09/10/2020
Dt rec updated: 05/04/2021
Updated By: JHOCONNE
Site Code: 507633
Site Description: "Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The

450 UNION STREET (Continued) **S117936660**

subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-05-08 14:42:00
Record Upd: 2020-10-07 17:11:00
Updated By: JHOCONNE
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Carroll Gardens Branch Library
Owner Address: 396 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street

450 UNION STREET (Continued) **S117936660**

Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25

450 UNION STREET (Continued) **S117936660**

Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

Name: 450 UNION STREET
Address: 450 UNION STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 507633
Control Name: Ground Water Use Restriction
HW Code: C224219
Control Code: 08
Control Type: INST
Dt record added: 09/10/2020
Dt rec updated: 05/04/2021
Updated By: JHOCONNE
Site Code: 507633
Site Description: "Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False

450 UNION STREET (Continued) **S117936660**

Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-05-08 14:42:00
Record Upd: 2020-10-07 17:11:00
Updated By: JHOCONNE
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Carroll Gardens Branch Library
Owner Address: 396 Clinton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 1
Sub Type: 06
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: 10 GLENVILLE STREET, SUITE 1
Owner Addr2: Not reported
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Rieger
Owner Company: 450 Union LLC
Owner Address: c/o Pilot Real Estate Group LLC
Owner Addr2: 10 Glenville Street, Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: c/o Robert Reiger
Owner Company: 450 Union Developer LLC
Owner Address: 10 Glenville Street
Owner Addr2: Suite 1
Owner City,St,Zip: Greenwich, CT 06831
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201
Owner Country: United States of America
HW Code: C224219
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: fluoranthene

450 UNION STREET (Continued) **S117936660**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: coal tar
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224219
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-611519
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2020-07-31 07:57:00
Record Updated: 2020-07-31 07:57:00
Updated By: LXZIELIN
Crossref ID: C224219-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-10 17:15:00
Record Updated: 2020-09-10 17:15:00
Updated By: NNCRAWFO
Crossref ID: 2020000271467
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-10-06 18:03:00
Record Updated: 2020-10-06 18:03:00
Updated By: NNCRAWFO

BROWNFIELDS:

Name:	450 UNION STREET
Address:	450 UNION STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	507633
Acres:	0.654
HW Code:	C224219
SWIS:	2401
Town:	New York City
Record Added Date:	05/08/2015
Record Updated Date:	12/30/2020
Update By:	AMSERVIS
Site Description:	"Location: The site is approximately 0.65 acres in size and is located in an urban area at 450 Union Street in the Gowanus neighborhood of Brooklyn, New York. The site is bounded by Union

450 UNION STREET (Continued) **S117936660**

Street to the north, the Gowanus Canal to the east, a parking lot followed by President Street to the south, and Bond Street to the west. Site Features: The site is currently improved with a one-story building and two storage sheds. The exterior portion of the property contains an enclosed area for social events, a parking lot and driveway, and storage areas. A bulkhead which will separate the property from the Gowanus Canal was recently constructed. Current Zoning and Land Use: The site is zoned M2-1 (manufacturing/industrial) and is currently used as a private event space, an art gallery, and an outdoor restaurant. Past Use of the Site: The site was historically occupied by a coal and wood yard (1886-1928); a granite works (1915); a die casting/electroplating facility (1922); a garage (1918-1930); a fuel company, garage and office (1931); and a foundry (1930-2007). Geology and Hydrogeology: The site sits at an elevation of approximately 10 feet above mean sea level and slopes down to the east towards the Gowanus Canal. The subsurface strata at the site is comprised of historic urban fill consisting of sand with varying amounts of gravel, silt, brick, coal, wood and concrete fragments. The historic fill layer extends to a depth of about 15 feet below grade surface and is underlain by clay and silt. The groundwater interface is at depths between 7 and 11 feet below grade surface. Groundwater beneath the site flows southeast toward the Gowanus Canal, which adjoins the site to the east. "

Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were SVOCs and metals in soil, and coal tar in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to prevent potential exposure to remaining contamination on the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-05-08 14:42:00
Record Upd:	2020-10-07 17:11:00
Updated By:	JHOCONNE
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	06
Owner Name:	Robert Rieger
Owner Company:	450 Union LLC
Owner Address:	10 GLENVILLE STREET, SUITE 1

450 UNION STREET (Continued) **S117936660**

Owner Addr2:	Not reported
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Rieger
Owner Company:	450 Union LLC
Owner Address:	c/o Pilot Real Estate Group LLC
Owner Addr2:	10 Glenville Street, Suite 1
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Robert Reiger
Owner Company:	450 Union Developer LLC
Owner Address:	10 Glenville Street
Owner Addr2:	Suite 1
Owner City,St,Zip:	Greenwich, CT 06831
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224219
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	coal tar
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224219
Waste Type:	indeno(1,2,3-CD)pyrene

450 UNION STREET (Continued) **S117936660**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-611519
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2020-07-31 07:57:00
Record Updated:	2020-07-31 07:57:00
Updated By:	LXZIELIN
Crossref ID:	C224219-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-09-10 17:15:00
Record Updated:	2020-09-10 17:15:00
Updated By:	NNCRAWFO
Crossref ID:	2020000271467
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-10-06 18:03:00
Record Updated:	2020-10-06 18:03:00
Updated By:	NNCRAWFO

AX384 **365 BOND STREET** **NY ENG CONTROLS** **S106720972**
WNW **365 BOND STREET** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11231** **NY BROWNFIELDS**
0.324 mi. **NY Spills**
1712 ft. **Site 1 of 2 in cluster AX** **NY E DESIGNATION**
NY COOLING TOWERS

Relative:
Lower

Actual:
16 ft.

ENG CONTROLS:

Name:	365 BOND STREET
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478842
HW Code:	C224174
Control Code:	15
Control Type:	ENG
Date Record Added:	10/21/2015
Date Rec Updated:	08/03/2020
Updated By:	SXAHMED
Site Description:	"Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse

365 BOND STREET (Continued) **S106720972**

(1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-13 09:37:00
Record Upd:	2017-09-29 14:13:00
Updated By:	JCGRATHW
Own Op:	1
Sub Type:	NNN
Owner Name:	Mark Green c/o The Lightstone Group
Owner Company:	LSG 365 Bond Street LLC
Owner Address:	1985 Cedar Bridge Avenue, Suite 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Lakewood, NJ 08701
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mark Green c/o The Lightstone Group
Owner Company:	LSG 365 Bond Street LLC

365 BOND STREET (Continued) **S106720972**

Owner Address:	1985 Cedar Bridge Avenue, Suite 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Lakewood, NJ 08701
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
HW Code:	C224174
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	N-PROPYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174

365 BOND STREET (Continued) **S106720972**

Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	Isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224174-05-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:17:00
Record Updated:	2015-10-02 11:17:00
Updated By:	JCGRATHW
Crossref ID:	2015000236154
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-30 10:44:00
Record Updated:	2015-07-30 10:44:00
Updated By:	JCGRATHW
Crossref ID:	06/05/13
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2015-10-02 11:18:00
Record Updated:	2015-10-02 11:18:00
Updated By:	JCGRATHW

Name:	365 BOND STREET
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478842
HW Code:	C224174
Control Code:	13
Control Type:	ENG
Date Record Added:	10/21/2015
Date Rec Updated:	08/03/2020
Updated By:	SXAHMED
Site Description:	"Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story

365 BOND STREET (Continued) **S106720972**

commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-13 09:37:00
Record Upd:	2017-09-29 14:13:00
Updated By:	JCGRATHW
Own Op:	1
Sub Type:	NNN
Owner Name:	Mark Green c/o The Lightstone Group
Owner Company:	LSG 365 Bond Street LLC
Owner Address:	1985 Cedar Bridge Avenue, Suite 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Lakewood, NJ 08701
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street

365 BOND STREET (Continued) **S106720972**

Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mark Green c/o The Lightstone Group
Owner Company:	LSG 365 Bond Street LLC
Owner Address:	1985 Cedar Bridge Avenue, Suite 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Lakewood, NJ 08701
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
HW Code:	C224174
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	N-PROPYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN

365 BOND STREET (Continued) **S106720972**

Waste Code:	Not reported
HW Code:	C224174
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	Isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224174-05-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:17:00
Record Updated:	2015-10-02 11:17:00
Updated By:	JCGRATHW
Crossref ID:	2015000236154
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-30 10:44:00
Record Updated:	2015-07-30 10:44:00
Updated By:	JCGRATHW
Crossref ID:	06/05/13
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2015-10-02 11:18:00
Record Updated:	2015-10-02 11:18:00
Updated By:	JCGRATHW

INST CONTROL:

Name:	365 BOND STREET
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478842
Control Name:	Soil Management Plan
HW Code:	C224174
Control Code:	14
Control Type:	INST
Dt record added:	10/21/2015
Dt rec updated:	08/03/2020
Updated By:	SXAHMED
Site Code:	478842
Site Description:	"Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and

365 BOND STREET (Continued) **S106720972**

to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1

365 BOND STREET (Continued) **S106720972**

Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE

365 BOND STREET (Continued) **S106720972**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00
Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

Name: 365 BOND STREET
Address: 365 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478842
Control Name: Landuse Restriction
HW Code: C224174
Control Code: 25
Control Type: INST

365 BOND STREET (Continued) **S106720972**

Dt record added: 10/21/2015
Dt rec updated: 08/03/2020
Updated By: SXAHMED
Site Code: 478842
Site Description: "Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

365 BOND STREET (Continued) **S106720972**

Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)

365 BOND STREET (Continued) **S106720972**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00
Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

365 BOND STREET (Continued) **S106720972**

Name:	365 BOND STREET
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478842
Control Name:	Ground Water Use Restriction
HW Code:	C224174
Control Code:	08
Control Type:	INST
Dt record added:	10/21/2015
Dt rec updated:	08/03/2020
Updated By:	SXAHMED
Site Code:	478842
Site Description:	"Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False

365 BOND STREET (Continued) **S106720972**

Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC

365 BOND STREET (Continued) **S106720972**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00

365 BOND STREET (Continued) **S106720972**

Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

Name: 365 BOND STREET
Address: 365 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478842
Control Name: Environmental Easement
HW Code: C224174
Control Code: J
Control Type: INST
Dt record added: 10/21/2015
Dt rec updated: 08/03/2020
Updated By: SXAHMED
Site Code: 478842
Site Description: "Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully

365 BOND STREET (Continued) **S106720972**

achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE

365 BOND STREET (Continued) **S106720972**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number

365 BOND STREET (Continued) **S106720972**

Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00
Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

Name: 365 BOND STREET
Address: 365 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478842
Control Name: IC/EC Plan
HW Code: C224174
Control Code: 34
Control Type: INST
Dt record added: 10/21/2015
Dt rec updated: 08/03/2020
Updated By: SXAHMED
Site Code: 478842
Site Description: "Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining

365 BOND STREET (Continued) **S106720972**

unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported

365 BOND STREET (Continued) **S106720972**

Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN

365 BOND STREET (Continued) **S106720972**

Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00
Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

Name: 365 BOND STREET
Address: 365 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478842
Control Name: O&M Plan
HW Code: C224174
Control Code: 33
Control Type: INST
Dt record added: 10/21/2015
Dt rec updated: 08/03/2020
Updated By: SXAHMED
Site Code: 478842
Site Description: "Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility.

365 BOND STREET (Continued) **S106720972**

The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported

365 BOND STREET (Continued) **S106720972**

Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN

365 BOND STREET (Continued) **S106720972**

Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00
Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

Name: 365 BOND STREET
Address: 365 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478842
Control Name: Site Management Plan
HW Code: C224174
Control Code: 32
Control Type: INST
Dt record added: 10/21/2015
Dt rec updated: 08/03/2020
Updated By: SXAHMED
Site Code: 478842
Site Description: "Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story

365 BOND STREET (Continued) **S106720972**

commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-13 09:37:00
Record Upd: 2017-09-29 14:13:00
Updated By: JCGRATHW
Own Op: 1
Sub Type: NNN
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street

365 BOND STREET (Continued) **S106720972**

Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Mark Green c/o The Lightstone Group
Owner Company: LSG 365 Bond Street LLC
Owner Address: 1985 Cedar Bridge Avenue, Suite 1
Owner Addr2: Not reported
Owner City,St,Zip: Lakewood, NJ 08701
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
HW Code: C224174
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: N-PROPYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN

365 BOND STREET (Continued) **S106720972**

Waste Code: Not reported
HW Code: C224174
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: Isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: PHENOL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224174
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224174-05-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:17:00
Record Updated: 2015-10-02 11:17:00
Updated By: JCGRATHW
Crossref ID: 2015000236154
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-30 10:44:00
Record Updated: 2015-07-30 10:44:00
Updated By: JCGRATHW
Crossref ID: 06/05/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 11:18:00
Record Updated: 2015-10-02 11:18:00
Updated By: JCGRATHW

BROWNFIELDS:

Name:	365 BOND STREET
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	478842
Acres:	2.066
HW Code:	C224174
SWIS:	2401
Town:	New York City
Record Added Date:	02/13/2013
Record Updated Date:	02/09/2022
Update By:	WBBENNET
Site Description:	"Location: The site is located at 365 Bond Street, Brooklyn, Kings County. The site is south of the intersection of Bond Street and First Street. It is bounded to the northeast by First Street, to the southeast by the Gowanus Canal, to the southwest by Second Street and

365 BOND STREET (Continued) **S106720972**

to the northwest by Bond Street. Site Features: The site is 2.066 acres in area. The former vacant lot is has been re-developed into a 12-story mixed use commercial and residential building. Current Zoning and Land Use(s): The site is zoned as M1-4/R7-2, a Special Mixed Use District comprised of light industrial, commercial and community facility (residential) uses. The site is bounded to the north by 1st Street across which is located a BCP site, to the east by the Gowanus Canal, to the south by 2nd Street across which are located three-story residential buildings and one- and two-story commercial facilities, and to the west by Bond Street across which are located three-story mixed-use commercial and residential buildings. Past Use of the Site: Past uses of the site include oil terminal (1886 through 1939); a building materials warehouse (1886 through 1915); a lumber company (1939); a paper products warehouse (1950); an electric wire and cable company (1969); and a warehouse (1977 through 1986). Other recorded uses of the site include an automobile storage and repair facility, and a dry cleaning facility. The previous owner performed the Phase I and the Phase II Environmental Site Assessments in 2004. Site Geology and Hydrogeology: The site is underlain by an approximately 5.5- to 13-foot thick layer of miscellaneous fill material that is underlain by a 5- to 8-foot thick continuous clay confining layer. Groundwater is approximately 2.5 to 10 feet below ground surface (bgs). Due to the site's proximity to the Canal, groundwater flow is tidally influenced but generally flows to east/northeast. The clay confining unit is located approximately 9 feet to 10 feet bgs and separates the shallow aquifer from the lower groundwater unit. "

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluoranthene, arsenic, lead, barium, mercury, xylene, trichloroethene (TCE), propylbenzene, tetrachloroethylene (PCE), benzene, phenol, n-propylbenzene, isopropyl benzene in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil is being managed under a Site Management Plan. Groundwater contamination is nominal and will improve since the removal of contaminated soil is completed. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-13 09:37:00
Record Upd:	2017-09-29 14:13:00
Updated By:	JCGRATHW
Own Op:	1
Sub Type:	NNN
Owner Name:	Mark Green c/o The Lightstone Group
Owner Company:	LSG 365 Bond Street LLC
Owner Address:	1985 Cedar Bridge Avenue, Suite 1

365 BOND STREET (Continued) **S106720972**

Owner Addr2:	Not reported
Owner City,St,Zip:	Lakewood, NJ 08701
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mark Green c/o The Lightstone Group
Owner Company:	LSG 365 Bond Street LLC
Owner Address:	1985 Cedar Bridge Avenue, Suite 1
Owner Addr2:	Not reported
Owner City,St,Zip:	Lakewood, NJ 08701
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
HW Code:	C224174
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	N-PROPYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZENE

365 BOND STREET (Continued) **S106720972**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	Isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224174
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224174-05-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:17:00
Record Updated:	2015-10-02 11:17:00
Updated By:	JCGRATHW
Crossref ID:	2015000236154
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-30 10:44:00
Record Updated:	2015-07-30 10:44:00
Updated By:	JCGRATHW
Crossref ID:	06/05/13
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2015-10-02 11:18:00
Record Updated:	2015-10-02 11:18:00
Updated By:	JCGRATHW

SPILLS:

Name:	365 BOND STREET
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0407393 / 2015-11-06
Facility ID:	0407393
Facility Type:	ER
DER Facility ID:	266802

365 BOND STREET (Continued) **S106720972**

Site ID:	331823
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2004-10-04
Investigator:	JCGRATHW
Referred To:	BCP SITE - JOHN GRATHWOL IS PM
Reported to Dept:	2004-10-04
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-04
Spill Record Last Update:	2015-12-18
Spiller Name:	MIMI SOTIRIIOU
Spiller Company:	Not reported
Spiller Address:	365 BOND STREET
Spiller Company:	001
Contact Name:	MIMI SOTIRIIOU
DEC Memo:	"CSL has been sent to: Joseph Fillips P.O.Box 451 New York, NY 10028-0018 YK. 10/18/04. Paul Casowitz (212-421-2150)an attorney for Mr. J. Fillips called and informed that he is a contact person for this case. And a formal letter in response to our CSL will be sent soon. Y.K. 08/30/05: I attempted to return Paul Casowitz's phone call. His message stated that his client would be filing a brownfields application to handle all the environmental concerns. I will check on this. Steve Scharf Pcasowitz@sprlaw.com Paul Casowitz Sive Paget & Riesel, P.C. 460 Park Avenue New York, NY 10022 AKRF Inc. (Ally, King, Rosen and Fleming) will be consultant submitting application. Toll Brothers Inc., is buying the property. description: Phillips Bros is a trust, the purchase money is going mostly into escrow until the environmetnal issues are resolved. site is on the erie basin of the Gowonus canal. There was some free product identivied in the due diligance environmental sampling. Sampling was done by Petroleum Tank cleaners (718)624-4842. S. Scharf 09/07/05 Sent the following e-mail to Paul Casowitz 2/28/06- I am following up on 365 Bond Street. You were going to get back to me with regard to the open spill, spill No. 0407393, on the property and whether your client was going to file a Brownfields application. thanks Steven M. Scharf, P.E. Reply: Steven, My client is the owner--Toll Bros is the contract vendee, they may have closed on title, I am not sure. Toll Brothers filed the BCP application for the site. I am away on vacation from 3/1-8--let me know if you have an application from Toll Bros. Of course in real estate, one never knows the name---special purpose entities being the rule. The BCP group should be able to advise you by the site location.- Paul Casowitz-Sive Paget & Riesel, P.C., 460 Park Avenue New York, NY 10022 03/02/06: Copy of E-mail to Paul Casowitz: Paul, What I'm being told is that, under the NYS Navigation Law (Article 12), the owner at the time (your client) of the reported spill is responsible for remediation of the discharge.

365 BOND STREET (Continued) **S106720972**

thanks, Steven M. Scharf, P.E. greater than greater than greater than Paul Casowitz 3/2/2006 9:44:11 AM greater than greater than greater than Steve, Good---I assume any issues re the spill will be addressed to the applicant. Paul: pcasowitz@sprlaw.com From: Steven Scharf [mailto:sxscharf@gw.dec.state.ny.us] Sent: Thu 3/2/2006 9:33 AM To: Paul Casowitz Subject: RE: 365 Bond Street, Brooklyn, Spill no 0407393 Paul, FYI, A BCP application, App. No. C224116, was processed on 6/7/05. Thanks: Steven Scharf, P.E. NYSDEC refer to John Grathwol. Working on brownfield. S. scharf Previously assigned to S. Scharf and J. Grathwol in Albany office. 10/11/06 - Austin - Reassigned from Central Office staff to Piper, for follow up and closure - end Due to rezoning issues. the applicant withdrew the BCP application in December 2006. 12/08/2008: This spill case was transferred to A. Doronova. AD From now on the progress on this case should be tracked under spill case No.0400876. Toll Brothers is potential buyer who will redevelop the site. AD 04/2010: This site was listed as a part of Gowanus Cannal to EPA's Superfund Program. AD 04/29/2010: Received an e-mail from Mr. Yudelson (attorney for Toll Brothers) saying: Ainura This email is to confirm that I have met with EPA and EPA indicated they will not be in a position to determine what, if any, remedial activities they will require at the Bond Street properties regarding the Superfund Site until the fall. I expect to meet with them again and will inform you if anything changes. Dave (917)295-6449 06/2010: Called and spoke with Mr. Yudelson. He told me that Toll Brothers is no longer interested in buying the site, after it was listed as a Superfund site. Mr. Yudelson gave me a contact info in EPA: Mr. Brian Carr, phone: (212)637-3170. AD 07/26/2010: Called and left a message to D. Yudelson. AD 07/28/2010: Called and left a message to Mr. P. Casowitz - attorney for Mr. Joseph Phillips. Later received a call from D. Yudelson. He told me that the site is owned by Mr. Phillips and Citibank. The site is currently for sale, and Mr. Yudelson is representing a potential buyer. He is going to meet with Mr. Phillips regarding the site cleanup and will contact us later with the results. AD 08/04/2010: Called and spoke with Mr. Yudelson. He gave me a contact info of Mr. Niel Dorman (212)753-7500 - attorney for Mr. Phillips. Will call him. AD 12/2/11 - Austin - Received call from Craig (917-952-8216), an independent consultatnt, who wished to know who the DEC project manager was for this spill report. I provided him DEC Doronova's name and phone #. He indicated that he was working with Dave Yudelson on this site, onbehalf of a new buyer (who, according to Craig, was a different buyer than was prevously involved with Mr. Yudelson). - end 12/02/2011: Received a messade from Craig Puerta, phone: 917-952-8216. Called and spoke with him regarding site remediation. Mr. Puerta said that they plan to do remedial excavation instead of soil stabilization as per old approved work plan. Requested him to submit revised work plan for review. AD 01/06/2012: Called and spoke with Mr. Puerta. He told me that his company did not signed the contract yet with the potential buyer, so they are waiting for buyer's decision. Called and spoke with D. Yudelson. He informed me that he is working for the potential buyer, who wants to buy all three properties, previously known as Tall Brooklyn Project and included three spill sites: # 0407393, # 0501697 and # 0400876. Mr. Yudelson said that the contract will be probably singed within next weeks. Mr. Graig Puerta is working with Mr. Yudelson and will be performing environmnetal services to the buyer. Mr. Yudelson will contact me, when contract will be finalazied. AD 08/22/2012: Received the following e-mail from D. Yudelson: Ainura -

365 BOND STREET (Continued) **S106720972**

This project is under consideration and I represent the prospective purchaser, Lightstone Group. The attached is proposed additional delineation sampling with an objective of amending the RAP s for excavation like at 400 Carroll. I believe if this is a go work will start this winter. We are coordinating with EPA and NYC as well. I will keep you posted on the progress and let me know if you have questions. Dave From: David Yudelson Sent: Monday, July 23, 2012 10:19 AM To: Cole, Daniel (DanielCo@dep.nyc.gov) Cc: Steve Ciambruschini (sciambruschini@Langan.com); Christopher McMahon (cmcmahon@Langan.com) Subject: Need to schedule a meeting asap Dan Attached are compilations of all existing data and proposed sampling locations. Soil gas has been added on each site and additional delineation is proposed. There is also an approved DEC work plan for 400 which provides for excavation. I need to know if the additional sampling is adequate as we are doing it asap during due diligence. Dave DL documents into eDocs. AD 10/22/2012: Called and spoke with D. Yudelson. He said that they planning to start additional investigation soon, and that a work plan for such investigation will be submitted in one week. AD This site entered into BCP agreement and is managed by Albany. Site's PM is John Grathwol. 12/5/13: Under BCP site code C224174, IRM Work Plan is approved to be release for public comment. Citizen Participation Plan is under Department review. A public availability session will be held during the public comment period. It is anticipated that the spill contamination will be removed during this IRM. The 2014 Decision Document will address the remaining, if any, contamination. (Grathwol) 11/6/15: Department approved Final Engineering Report and executed the Certificate of Completion for the site owner. Spill closed."

Remarks: "WHILE DOING SOIL BORINGS, FOUND CONTAMNATED SOIL:"

All Materials:

Site ID:	331823
Operable Unit ID:	1094113
Operable Unit:	01
Material ID:	574232
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 458
Address:	365 BOND STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	458
Borough Code:	Not reported
E-No:	E-221
Effective Date:	3/11/2009
Satisfaction Date:	Not reported
Ceqr Number:	08DCP033K
Ulurp Number:	090047ZMK090047ZMK

365 BOND STREET (Continued) **S106720972**

Zoning Map No: 16c

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

COOLING TOWERS:

Name:	Not reported
Address:	365 BOND ST
City,State,Zip:	BROOKLYN, NY 11231
Equipment Unique ID:	13196
Equipment Borough:	Manhattan
Intended Use:	Air Conditioning
Manufacturer:	B.A.C
Model:	53E-1020-070-3
Cooling Capacity:	1500
Cooling Capacity Unit:	Tonnage
Commissioned Date:	07/01/2016
Inspection Date:	10/31/2018
Date of Bacteriological Collection:	10/26/2018
Date of Legionella Collection:	11/06/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	40.677832
Longitude:	-73.991126

AY385 **335 BOND STREET** **NY BROWNFIELDS** **S117936667**
NW **335 BOND STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.326 mi.
1721 ft. **Site 1 of 3 in cluster AY**

Relative: **Lower**
Actual: **14 ft.**

BROWNFIELDS:

Name:	335 BOND STREET
Address:	335 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	507653
Acres:	0.360
HW Code:	C224225
SWIS:	2401
Town:	New York City
Record Added Date:	05/08/2015
Record Updated Date:	05/04/2022
Update By:	JBSWARTO
Site Description:	"Location: The site is located in an urban area, in the Gowanus neighborhood of Brooklyn. The site is bound by a two-story residential building and an industrial lot to the north; a two-story industrial and commercial building to the east; Carroll Street to the south; and Bond Street to the west. Site Features: The approximately

335 BOND STREET (Continued) **S117936667**

0.36 acre site consists of a one-story building that includes a partial cellar, which houses an abandoned above ground storage tank (AST) in a concrete vault. Current Zoning/Use: The subject property is located in an M2-1 manufacturing district and is currently occupied by an office building and garage operated by a private car and limousine service. The zoning was recently changed to M1-4/R7-2. The M1-4 allows light manufacturing, commercial and community facilities. The R7-2 allows medium density residential. Historic Use: Past uses include a masonry materials, lath and lumber yard (1886 to 1922), a garage with possible auto servicing and gasoline storage (1925 to 1938), commercial delivery service (1969 to 1980), manufacturing (1981 to 1996), and a commercial car/livery service (appoximately 2002 to present). Site Geology and Hydrogeology: Subsurface strata at the site consists of fill material characterized by loose, brown, fine to coarse sand with some brick and concrete fragments, and trace coal ash. The fill layer extends to depths ranging from approximately 4 feet below ground surface (bgs) to 8.5 feet bgs and is intersected by layers of degraded concrete and brick at varying depths. The fill layer is underlain by native soil characterized by sands and silty sands. Bedrock is part of the Hartland Formation. Groundwater occurs at depths ranging from approximately 6 to 8.5 feet bgs."

Env Problem:	"Soil, groundwater, and soil vapor has been impacted by chlorinated solvents, especially in the garage area. There is also the potential for impact to soil, groundwater, and soil vapor from an abandoned 1000 gallon above ground storage tank located in a vault in the basement and from gasoline storage tanks which were formerly located on the property. "
Health Problem:	"Direct contact with contaminants in soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion at the current on-site building. The potential exists for indoor air quality impacts offsite."
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2022-01-18 10:35:00
Record Upd:	2022-01-20 11:27:00
Updated By:	SXSCHARF
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library

335 BOND STREET (Continued) **S117936667**

Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Eduard Slinin
Owner Company:	E & M Realty Corp.
Owner Address:	335 Bond Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Eduard Slinin
Owner Company:	E & M Realty Corp.
Owner Address:	335 Bond Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224225
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224225
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224225
Waste Type:	1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224225
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224225
Waste Type:	chlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224225
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported

335 BOND STREET (Continued) **S117936667**

Updated By: Not reported

AW386 **BAYSIDE FUEL OIL DEPOT CORP.** **NY MOSF UST** **S103275956**
NNW **510 SACKETT ST.** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.329 mi.
1738 ft. **Site 2 of 3 in cluster AW**

Relative: **Lower**
Actual: **10 ft.**

MOSF UST:

Id/Status:	2-1220 / ACTIVE FACILITY
SWIS Code:	61
Facility Town:	NEW YORK CITY
Contact Phone:	(718) 625-5932
Emergency Contact:	VINCENT ALLEGRETTI
Emergency Telephone:	(718) 625-5932
CBS Number:	Not reported
SPDES Num:	Not reported
Total Tanks:	2
Total Capacity:	1501000
Avg Throughput:	60000
License Stat:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options:	AC
Expiration Date:	03/31/2005
Applic Rcvd:	01/31/2000
Operator:	VINCENT ALLEGRETTI
Owner Name:	ALFRED ALLEGRETTI BAYSIDE FUEL OIL DEPOT CORP.
Owner Address:	1776 SHORE PARKWAY
Owner City,St,Zip:	BROOKLYN, NY 11214-
Owner Telephone:	(718) 372-9800
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner
Mail To Name:	BAYSIDE FUEL OIL DEPOT CORP.
Mail To Address:	1776 SHORE PARKWAY
Mail To Address 2:	P.O. BOX 140128
Mail City,St,Zip:	BROOKLYN, NY 11214-0002
Mail To Contact:	ALFRED ALLEGRETTI
Mail To Telephone:	(718) 372-9800
Legal Agent Name:	ALFRED ALLEGRETTI
Legal Agent Address:	1776 SHORE PARKWAY
Legal Agent City,St,Zip:	BROOKLYN, NY 11214-
Date Filed:	03/65
Latitude:	40|40|50
Longitude:	73|59|20

Tank ID:	A-B-C
Tank Location:	UNDERGROUND
Install Date:	12/47
Capacity (Gal):	1500000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	13
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S103275956**

Pipe External:	13
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	20
Dispenser:	Submersible
Test Date:	12/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	12/03/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2000
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/16/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	BOILER TANK
Tank Location:	UNDERGROUND
Install Date:	12/47
Capacity (Gal):	1000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	13
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	13
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	24
Dispenser:	Suction
Test Date:	08/79
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	12/03/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2000
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/16/1999
Federal Id No:	Not reported
COI Date:	/ /

AW387 **BAYSIDE FUEL OIL DEPOT CORP.** **NY MOSF** **S109826460**
NNW **510 SACKETT ST** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.329 mi.
1738 ft. **Site 3 of 3 in cluster AW**

Relative:
Lower

Actual:
10 ft.

MOSF:

Name:	BAYSIDE FUEL OIL DEPOT CORP.
Address:	510 SACKETT ST
City,State,Zip:	BROOKLYN, NY 11231
Facility ID:	2-1220
Program Type:	MOSF
Tank Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	585482.68052
UTMY:	4503750.50730

SPILLS:

Name:	510 SACKETT ST
Address:	510 SACKETT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0902825 / 2012-02-06
Facility ID:	0902825
Facility Type:	ER
DER Facility ID:	364035
Site ID:	414889
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-06-09
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2009-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-09
Spill Record Last Update:	2012-02-06
Spiller Name:	KATE BRUNNER
Spiller Company:	UNKNOWN
Spiller Address:	510 SACKETT ST
Spiller Company:	999
Contact Name:	KATE BRUNNER
DEC Memo:	"02-06-12 - LZ The 01-25-12 semi-annual well gauging report (eDocs) and the 02-02-12 request for spill closure (eDocs) show that during two-year gauging of the five monitoring wells at the site no free product was detected except the March 2011 event (less than 0.01 foot in MW-4). Soil contamination was evaluated in the February 2010 revised Site Assessment Report and Remedial Action Plan. The spill case has been closed, and a spill closure letter sent to the facility

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S109826460**

owner. 04-28-11 - LZ The Annual Well Gauging Summary Report, dated March 18, 2011, prepared by AKRF, Inc. (eDocs) provides results of four quarterly rounds of well inspections. Five site monitoring wells were gauged for LNAPL; no LNAPL was observed in any of the wells in April, July, or October 2010. During both March gauging events, an immeasurable skim layer (less than 0.01 foot) of LNAPL was noted in MW-4. An oil-absorbent sock was placed across the water table in MW-4. AKRF will continue quarterly gauging in accordance with the Revised RAP. The next report to DEC will follow the March 2012 gauging. 09/29/10 - LZ The AKRF, Inc., report (eDocs), dated July 28. 2010, provides data from April and July gauging of monitoring wells. No free product was detected in any wells. Next report is due January 2011. 03/24/10 - LZ Reviewed the February 2010 revised Site Assessment Report (SAR) and Remedial Action Plan (RAP)(eDocs), prepared by AKRF, Inc. Approved the revised submittals and required that the gauging be performed for two years, and reports reflecting the results of it twice a year. NYSDEC may require that the site achieve more stringent SCOs than for industrial use if the site zoning is to be changed or development of the site is inevitable. 12/22/09 - LZ The November 5th revised RAP (eDocs) includes advancing of two additional borings and installation of two monitoring wells. Soil from these borings would be analyzed for the presence of VOCs ans SVOCs. On December 22th, AKRF performed two borings as provided in the revised RAP. A report summarizing December activities and soil analytical results will be submitted by January 31st. 10/23/09 - LZ I has reviewed the October 14, 2009, Remedial Action Plan (RAP), prepared by AKRF, Inc. The RAP proposes installation of a monitoring well in the area where significant contamination was discovered to monitor and remove encountered free-phase product. I disapproved the proposed RAP since it does not address adequately the visual and olfactory contamination detected in borings B-10, B-13, and B-14. A revised RAP should be submitted by November 27, 2009. 08/17/09 - LZ In her letter (eDocs) of June 15, 2009, Kathleen Brunner of AKRF asserts that a investigation report will be submitted by July 17, 2009. 08-11-9 - LZ DEC approved the site assessment report and in its August 11th letter (eDocs)required a remediation action plan be prepared and submitted by October 14, 2009. "

Remarks: "Field tests revealed soil contamination at the above sight. MOSF 2-1220 Case Manager name: Leszek Zielinski Stipulation agreement that is in place: R2-20081209-603"

All Materials:

Site ID:	414889
Operable Unit ID:	1171261
Operable Unit:	01
Material ID:	2163053
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	510 SACKETT ST
Address:	510 SACKETT STREET

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S109826460**

City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9604267 / 1996-06-28
Facility ID:	9604267
Facility Type:	ER
DER Facility ID:	207605
Site ID:	66574
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-06-28
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1996-06-28
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-28
Spill Record Last Update:	1996-07-02
Spiller Name:	Not reported
Spiller Company:	BAYSIDE OIL CO
Spiller Address:	510 SACKETT ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"REPORTING PERSON WORKS FOR BAYSIDE OIL HE WAS ASK TO CLEAN UP MATERAL WHICH IS IN DRUMS AT LOCATION - DRUMS APPEARENTLY ARE LEAKING AND HE WOULD NOT CLEAN UP THE MATERAL DUE TO THE HAZARD HE CALLED DEPT OF ENVIRO. PROTECTION WHO INTERN CALLED US- ALONG WITH ABOVE MATERAL THERE IS ALSO LOOSE ASBESTOS ON SITE"

All Materials:

Site ID:	66574
Operable Unit ID:	1031916
Operable Unit:	01
Material ID:	350556
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	66574
Operable Unit ID:	1031916
Operable Unit:	01
Material ID:	350555
Material Code:	0009

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S109826460**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	510 SACKET ST/BKLYN
Address:	510 SACKETT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9011319 / 1991-01-25
Facility ID:	9011319
Facility Type:	ER
DER Facility ID:	207605
Site ID:	253424
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	1991-01-25
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1991-01-25
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Vessel
Spill Notifier:	Other
Cleanup Ceased:	1991-01-25
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-02-08
Spill Record Last Update:	2003-07-29
Spiller Name:	Not reported
Spiller Company:	ECKLOFF MARINE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"BARGE-GOWANUS TRADER LEAKING,NYCFD,USCG & DEC ON SITE,SPILL BOOMED OFF& SORBENTS BEING USED,PUMPING OUT COMPARTMENT OF BARGE,ECKLOFF'S SPILL CREW CLEANED UP SPILL & OFFLOADED BARGE."

All Materials:

Site ID:	253424
Operable Unit ID:	951416
Operable Unit:	01
Material ID:	427869
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S109826460**

Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MANHOLE 56074
Address:	510 SACKETT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514992 / 2006-04-17
Facility ID:	0514992
Facility Type:	ER
DER Facility ID:	207605
Site ID:	361851
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-28
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-03-30
CID:	41
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-30
Spill Record Last Update:	2006-06-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	ERT DESK’
DEC Memo:	"04/17/06 - See e-docs for Con Ed report detailing cleanup and closure. 04/17/06 - See e-docs for Con Ed report detailing cleanup and closure. 163561. see eDocs."
Remarks:	"two quarts on 500 gallons water - ref 163561 - coming off 72 hour clock"

All Materials:

Site ID:	361851
Operable Unit ID:	1119964
Operable Unit:	01
Material ID:	2109432
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S109826460**

Name:	BAYSIDE OIL TERMINAL
Address:	510 SACKETT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9011318 / 1991-01-26
Facility ID:	9011318
Facility Type:	ER
DER Facility ID:	207605
Site ID:	124793
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1991-01-25
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1991-01-25
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Vessel
Spill Notifier:	Federal Government
Cleanup Ceased:	1991-01-26
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-02-08
Spill Record Last Update:	2004-04-06
Spiller Name:	Not reported
Spiller Company:	TANK BARGE-GOWANUS TRADER
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"HOLE IN ONE OF THE COMPARTMENTS OF THE BARGE,HOLE BELOW WATERLINE, PRODUCT RELEASED IS APPROX 25GAL,BOOMS & SORBENT PADS ARE IN PLACE, LEAK STOPPED BY PUMPING OUT THE LEAKING COMPARTMENT."

All Materials:

Site ID:	124793
Operable Unit ID:	951415
Operable Unit:	01
Material ID:	427868
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY388 **DENTS OUT AUTO BODY LTD** **SEMS-ARCHIVE** **1003864459**
NW **327 BOND ST** **RCRA NonGen / NLR** **NYD986961167**
1/4-1/2 **BROOKLYN, NY 11215**
0.330 mi.
1743 ft. **Site 2 of 3 in cluster AY**

Relative:
Lower

Actual:
13 ft.

SEMS Archive:

Site ID:	0203501
EPA ID:	NYD986961167
Name:	VIDAN AUTO SALVAGE
Address:	327-321 BOND STREET
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11231
Cong District:	13
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0203501
EPA ID:	NYD986961167
Site Name:	VIDAN AUTO SALVAGE
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1999-09-30 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0203501
EPA ID:	NYD986961167
Site Name:	VIDAN AUTO SALVAGE
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1998-05-27 04:00:00
Finish Date:	1998-12-29 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0203501
EPA ID:	NYD986961167
Site Name:	VIDAN AUTO SALVAGE
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1

DENTS OUT AUTO BODY LTD (Continued) **1003864459**

Start Date: 1991-07-01 04:00:00
Finish Date: 1991-09-25 04:00:00
Qual: H
Current Action Lead: EPA Perf

Region: 02
Site ID: 0203501
EPA ID: NYD986961167
Site Name: VIDAN AUTO SALVAGE
NPL: N
FF: N
OU: 00
Action Code: RS
Action Name: RV ASSESS
SEQ: 1
Start Date: 1991-06-25 04:00:00
Finish Date: 1991-09-26 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0203501
EPA ID: NYD986961167
Site Name: VIDAN AUTO SALVAGE
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1991-06-25 04:00:00
Finish Date: 1991-06-25 04:00:00
Qual: Not reported
Current Action Lead: St Perf

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: DENTS OUT AUTO BODY LTD
Handler Address: 327 BOND ST
Handler City,State,Zip: BROOKLYN, NY 11215
EPA ID: NYD986961167
Contact Name: MICHAEL PLANTZ
Contact Address: BOND ST
Contact City,State,Zip: BROOKLYN, NY 11215
Contact Telephone: 718-488-5936
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY

DENTS OUT AUTO BODY LTD (Continued) **1003864459**

State District:		NYSDEC R2
Mailing Address:		BOND ST
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	MICHAEL PLANTZ	
Owner Type:		Private
Operator Name:	MICHAEL PLANTZ	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

DENTS OUT AUTO BODY LTD (Continued) **1003864459**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MICHAEL PLANTZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	327 BOND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-488-5936
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MICHAEL PLANTZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	327 BOND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215
Owner/Operator Telephone:	718-488-5936

DENTS OUT AUTO BODY LTD (Continued) **1003864459**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MICHAEL PLANTZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 327 BOND ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-488-5936
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: DENTS OUT AUTO BODY LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DENTS OUT AUTO BODY LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930510
Handler Name: DENTS OUT AUTO BODY LTD
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

DENTS OUT AUTO BODY LTD (Continued) **1003864459**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

389 WNW 1/4-1/2 0.335 mi. 1769 ft. **THIRD STREET GOWANUS** **NY BROWNFIELDS** **S128529086**
125 3RD STREET **N/A**
BROOKLYN, NY 11231

Relative: Lower
Actual: 10 ft.

BROWNFIELDS:

Name:	THIRD STREET GOWANUS
Address:	125 3RD STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	628534
Acres:	0.470
HW Code:	C224346
SWIS:	2401
Town:	New York City
Record Added Date:	11/17/2021
Record Updated Date:	02/02/2022
Update By:	HMDUDEK
Site Description:	"Location: The site is located at 125 3rd Street (latitude 40 40 37.5 , longitude -73 59 28.6) in the Gowanus neighborhood of Brooklyn, New York. The site encompasses the following tax lot: Block 462, Lot 6 and occupies a total area of about 20,300 square feet (0.47 acres). The site is bound to the north by 2nd Street: to the northeast by a 2-story industrial building (140 2nd Street/Lot 9); to the east by an open-air asphalt parking lot (155 3rd Street/Lot 14); to the south by 3rd Street; and to the west by a vacant lot (123 3rd Street/Lot 50) and a 3-story residential building (128 2nd Street/Lot 5). According to the United States Geology Survey (USGS) 7.5-Minute Quadrangle Map, the site elevation is about 10 feet above mean sea level (msl). Site Features/Current Zoning and Land Use: The current uses of each former tax lot on the site are as follows: (Former Lot 6) one-story warehouse occupied by a freight trucking company with open air parking to the north and south; (Former Lot 8) Vacant warehouse; (Former Lot 44) Warehouse occupied by a moving company; (Former Lot 42 and p/o Lot 9) Warehouse occupied by a van rental company According to the New York City Department of City Planning (NYCDCP) Zoning Map 16c, dated May 27, 2021, the site is currently located in a M2-1 manufacturing district and is proposed to be rezoned to a mixed M1(3)/R7-2 manufacturing and residential district, pursuant to a Uniform Land Use Review Procedure (ULURP) and the ongoing Gowanus Neighborhood Rezoning City Environmental Quality Review (CEQR) No. 19DCP157K. The adjoining parcels are used for residential, commercial, and industrial purposes, with the surrounding area generally consisting of residential, commercial, and light industrial use. Past Uses of the Site: According to historical

THIRD STREET GOWANUS (Continued) **S128529086**

records, the site was occupied by commercial and industrial facilities since the late 1800s. The historical uses are listed below: Painting company (1886), Stone cutting facility and carpenter (1886), Mattress and quilt manufacturing facility (1904), Brewing and bottling company (1915 to 1938), Garage (1938 to 1950, 1977 to 2007), Waste paper and rag bailing company (1950), Freight depot (1969 to 2007), Unknown manufacturing (1977 to 2007). The site is currently improved with a one-story warehouse with open air parking to the north and south occupied by a freight depo (former Lot 6), a vacant one-story warehouse (former Lot 8), a one-story warehouse occupied by a moving company (former Lot 44), and a one-story warehouse occupied by a van rental company (former Lot 42 and p/o Lot 9). Site Geology and Hydrogeology: Historic fill was encountered from surface grade to depths ranging from about 3 to 12 feet below grade surface (bgs). Fill material consisting of various amounts of sand, silt, gravel, coal, coal ash, slag, and wood. A layer of brown/grey medium to fine grained sand with varying amounts of silt and gravel was encountered below the fill layer. A layer of dark grey organic clay with varying amounts of organics was encountered below the upper sand layer. The top of the organic clay layer was found between about 10.5 and 20 feet bgs and was about 7 to 18.5 feet thick. A layer of sand with varying amounts of silt and gravel was encountered below the clay layer. Bedrock was not encountered. Groundwater was encountered at about 2.5 to 7 feet bgs and presumably flows east towards the Gowanus Canal. "

Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	n/a
Owner Company:	Third Street Holdings, LLC
Owner Address:	137 Third Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	n/a
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported

THIRD STREET GOWANUS (Continued) **S128529086**

Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	n/a
Owner Company:	Kirus Reliable Inc.
Owner Address:	135 3rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Andrew Bradfield
Owner Company:	Third Street Gowanus Owner LLC
Owner Address:	c/o Orange Management Inc.
Owner Addr2:	22 Carroll Street, Ground Floor
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michael Racioppo
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	n/a
Owner Company:	VTI Van Rental
Owner Address:	137 3rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	n/a
Owner Company:	Movers, Not Shakers!
Owner Address:	131 3rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

390
East
1/4-1/2
0.337 mi.
1777 ft.

225 6TH AVE.
225 6TH AVE
BROOKLYN, NY

NY LTANKS **S106703145**
N/A

Relative:
Higher

Actual:
78 ft.

LTANKS:

Name:	225 6TH AVE.
Address:	225 6TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8705973 / 1992-11-19
Facility ID:	8705973
Site ID:	163112
Spill Date:	1987-10-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1992-11-19
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1987-10-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-16
Spill Record Last Update:	2004-04-20
Spiller Name:	Not reported
Spiller Company:	ST. FRANCIS XAVIER
Spiller Address:	225 6TH AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	137569
DEC Memo:	""
Remarks:	"2K TANK FAILED, WILL REPAIR AND RETEST."

All TTF:

Facility ID:	8705973
Spill Number:	8705973
Spill Tank Test:	1531932
Site ID:	163112
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

225 6TH AVE. (Continued) **S106703145**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 163112
Operable Unit ID: 912012
Operable Unit: 01
Material ID: 565234
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

AT391 **CONTAINER SERVICE CORP.** **NY SWF/LF** **S104789732**
WSW **107 6TH STREET** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11231** **NY SPDES**
0.337 mi.
1779 ft. **Site 3 of 4 in cluster AT**

Relative:
Lower

Actual:
8 ft.

SWF/LF:
Name: CONTAINER SERVICE CORP.
Address: 107 6TH STREET
City,State,Zip: BROOKLYN, NY 11231
Flag: INACTIVE
Region Code: 2
Phone Number: Not reported
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: UNKNOWN
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Transfer station - permit
Activity Number: [24T39]
Active: No
East Coordinate: 585400
North Coordinate: 4503100
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: 2.610300203e+014
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported

CONTAINER SERVICE CORP. (Continued) **S104789732**

Laste Date: Not reported

SPILLS:

Name:	GOWANAS 6TH ST BASIN
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0007253 / 2003-02-13
Facility ID:	0007253
Facility Type:	ER
DER Facility ID:	151336
Site ID:	298822
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-09-20
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-09-20
CID:	208
Water Affected:	GAWANAS 6TH ST BASIN
Spill Source:	Unknown
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-09-20
Spill Record Last Update:	2004-02-23
Spiller Name:	Not reported
Spiller Company:	BERNIE BODERICK
Spiller Address:	71 HAUSMAN ST
Spiller Company:	001
Contact Name:	HOWARD ORAMA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 2/13/2003 - Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"two concrete slabs were dumped into the above location - subj issued appearance tickets for same by nyc sanitation pd "

All Materials:

Site ID:	298822
Operable Unit ID:	828119
Operable Unit:	01
Material ID:	548349
Material Code:	0507A
Material Name:	concrete products
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CONTAINER SERVICE CORP. (Continued) **S104789732**

Name:	S & S WATER COMPANY
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0030011 / 2003-09-08
Facility ID:	0030011
Facility Type:	ER
DER Facility ID:	151336
Site ID:	180433
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	B1
SWIS:	2401
Spill Date:	2000-07-05
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-07-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-05
Spill Record Last Update:	2003-09-08
Spiller Name:	Not reported
Spiller Company:	DAVID STEIER
Spiller Address:	94 HAUSMAN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"Removing tanks and dumping soil into Canal."

All Materials:

Site ID:	180433
Operable Unit ID:	836580
Operable Unit:	01
Material ID:	540901
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0030027
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0030027 / 2003-10-31
Facility ID:	0030027
Facility Type:	ER
DER Facility ID:	151336

CONTAINER SERVICE CORP. (Continued) **S104789732**

Site ID:	180434
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2000-11-13
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-11-13
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-13
Spill Record Last Update:	2003-10-31
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	107 6TH STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO CROSS STREETS: FIFTH STREET AND SECOND AVE. 10/31/03 TJD Old surface water spill. No further action possible. Spill closed."
Remarks:	"ECO SMITH NOTICED SHEEN ON GOWANUS CANAL POSSIBLY COMING FROM SPILL LOCATION. WALL COLLAPSE INTO GOWANUS CANAL. POSSIBLE FORMER PBS FACILITY. DEC TO NOTIFY USCG. T "

All Materials:

Site ID:	180434
Operable Unit ID:	835561
Operable Unit:	01
Material ID:	540920
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	107 6TH STREET
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8700241 / 1987-04-09
Facility ID:	8700241
Facility Type:	ER
DER Facility ID:	151336
Site ID:	180435
DEC Region:	2
Spill Cause:	Deliberate

CONTAINER SERVICE CORP. (Continued) **S104789732**

Spill Class:	A1
SWIS:	2401
Spill Date:	1987-04-08
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1987-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	1987-04-09
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-04-14
Spill Record Last Update:	2003-09-08
Spiller Name:	Not reported
Spiller Company:	OLYMPIC ENVIR. SERVICES
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TANK TRUCK SPILL. DEC WAS CALLED IN FOR TESTING. DEC, DEP, AND COAST GUARD. DEP DID SAMPLING."

All Materials:

Site ID:	180435
Operable Unit ID:	904825
Operable Unit:	01
Material ID:	470249
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	180435
Operable Unit ID:	904825
Operable Unit:	01
Material ID:	470248
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	S & S WASTE WATER
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY

CONTAINER SERVICE CORP. (Continued) **S104789732**

Spill Number/Closed Date:	9405982 / 2003-10-21
Facility ID:	9405982
Facility Type:	ER
DER Facility ID:	151336
Site ID:	180436
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1994-08-02
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1994-08-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-19
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	S & S WASTE WATER
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TRANSFERRING OIL FROM TANK TO TRAILER-TRAILER LEAKING OIL. NO ACTION TAKEN-DEC TRYING TO GET IN TOUCH WITH RESPONSIBLE PARTY. SPILL CLEANED UP BY S & S WASTE WATER CO. DAVID STEIER FACILITY REP."

All Materials:

Site ID:	180436
Operable Unit ID:	1000241
Operable Unit:	01
Material ID:	382549
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	S & S WATER COMPANY
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9406805 / 2003-09-08
Facility ID:	9406805
Facility Type:	ER
DER Facility ID:	151336
Site ID:	180437

CONTAINER SERVICE CORP. (Continued) **S104789732**

DEC Region:	2
Spill Cause:	Vandalism
Spill Class:	B1
SWIS:	2401
Spill Date:	1994-08-19
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1994-08-19
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-20
Spill Record Last Update:	2003-09-08
Spiller Name:	Not reported
Spiller Company:	DAVID STEIER
Spiller Address:	94 HAUSMAN STREET
Spiller Company:	001
Contact Name:	DAVID STEIER
DEC Memo:	""
Remarks:	"BECI Conducting Investigation found abandoned Oil Terminal."

All Materials:

Site ID:	180437
Operable Unit ID:	1001171
Operable Unit:	01
Material ID:	379836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	180437
Operable Unit ID:	1001171
Operable Unit:	01
Material ID:	379835
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	S & S WATER COMPANY
Address:	107 6TH STREET

CONTAINER SERVICE CORP. (Continued) **S104789732**

City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9407020 / 2003-09-08
Facility ID:	9407020
Facility Type:	ER
DER Facility ID:	151336
Site ID:	180438
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B1
SWIS:	2401
Spill Date:	1994-08-24
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1994-08-24
CID:	Not reported
Water Affected:	GOWANUS CANAL
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-21
Spill Record Last Update:	2003-09-08
Spiller Name:	Not reported
Spiller Company:	DAVID STEIER
Spiller Address:	94 HAUSMAN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"CREW PUMPING OIL OUT OF TANK FOR POSSIBLE REPAIR-GOING INTO BASIN-NYC DEP WAS NOTIFIED-U.S.C.G. TO SEND BOAT IF POSSIBLE."

All Materials:

Site ID:	180438
Operable Unit ID:	1004442
Operable Unit:	01
Material ID:	380042
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	S & S WATER COMPANY
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY 11222
Permit Number:	NY0201065
State-Region:	02

CONTAINER SERVICE CORP. (Continued) **S104789732**

Expiration Date:	08/01/2000
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5093
State Water Body Name:	GOWANUS CANAL
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.675139 / -73.993667
DMR Cognizant Official:	DAVID STEIER
UDF2:	001701
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	S & S WATER COMPANY
Non-Gov Permit Street Address:	S & S WATER COMPANY
Non-Gov Permit Supplemental Location:	94 HAUSMAN STREET
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11222
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	S & S WATER COMPANY
Non-Gov Facility Street Address:	S & S WATER COMPANY
Non-Gov Facility Supplemental Location:	107 6TH STREET
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11222
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	S & S WATER COMPANY
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY 11222
UDF2:	001701
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	S & S WATER COMPANY
Non-Gov Permit Street Address:	S & S WATER COMPANY
Non-Gov Permit Supplemental Location:	94 HAUSMAN STREET
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11222
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	S & S WATER COMPANY
Non-Gov Facility Street Address:	S & S WATER COMPANY
Non-Gov Facility Supplemental Location:	94 HAUSMAN STREET
Non-Gov Facility City:	BROOKLYN

CONTAINER SERVICE CORP. (Continued) **S104789732**

Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11222
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	S & S WATER COMPANY
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY 11222
UDF2:	001701
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	S S WATER COMPANY
Non-Gov Permit Street Address:	94 HAUSMAN ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11222
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	S & S WATER COMPANY
Non-Gov Facility Street Address:	S & S WATER COMPANY
Non-Gov Facility Supplemental Location:	107 6TH STREET
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11222
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	S & S WATER COMPANY
Address:	107 6TH STREET
City,State,Zip:	BROOKLYN, NY 11222
UDF2:	001701
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	S S WATER COMPANY
Non-Gov Permit Street Address:	94 HAUSMAN ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11222

CONTAINER SERVICE CORP. (Continued) **S104789732**

Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	S & S WATER COMPANY
Non-Gov Facility Street Address:	S & S WATER COMPANY
Non-Gov Facility Supplemental Location:	94 HAUSMAN STREET
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11222
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AT392 **106 6TH ST** **NY LTANKS** **S102660664**
WSW **106 6TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.342 mi.
1806 ft. **Site 4 of 4 in cluster AT**

Relative: **Lower**
Actual: **9 ft.**

LTANKS:

Name:	106 6TH ST
Address:	106 6TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9502574 / 1995-05-31
Facility ID:	9502574
Site ID:	153670
Spill Date:	1995-05-31
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	C4
Cleanup Ceased:	1995-05-31
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1995-05-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-06-07
Spill Record Last Update:	2003-01-23
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	130358
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

106 6TH ST (Continued) **S102660664**

	TANG "
Remarks:	"4 BARRELS ABANDONED - POSS. CONTAINING HAZARDOUS MATERIAL - NOT LEAKING - REFER TO NYCDEP HAZMAT"

All Materials:

Site ID:	153670
Operable Unit ID:	1016982
Operable Unit:	01
Material ID:	367631
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV393 **CROSS BAY CONTRACTING** **NY SWF/LF** **S128177977**
NNW **242 NEVINS ST.** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.343 mi.
1811 ft. **Site 3 of 5 in cluster AV**

Relative: **Lower**
Actual: **8 ft.**

SWF/LF:

Name:	CROSS BAY CONTRACTING
Address:	242 NEVINS ST.
City,State,Zip:	BROOKLYN, NY 11217
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	PETER MIGLIORINI; SUPERVISOR
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T87]
Active:	No
East Coordinate:	585800
North Coordinate:	4503800
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6103-00004
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CROSS BAY CONTRACTING (Continued) **S128177977**

Laste Date: Not reported

AV394 **ROYAL RECYCLING CORP.** **NY SWF/LF** **S128178753**
NNW **242 NEVINS STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.343 mi.
1811 ft. **Site 4 of 5 in cluster AV**

Relative: **Lower**
Actual: **8 ft.**

SWF/LF:

Name:	ROYAL RECYCLING CORP.
Address:	242 NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11217
Flag:	INACTIVE
Region Code:	2
Phone Number:	7187884731
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	M. GERARDO MAZZEI
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24WE4]
Active:	No
East Coordinate:	585665
North Coordinate:	4503843
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Concrete;Soil (Clean);Wood (Clean)
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AV395 **242 NEVINS STREET** **NY BROWNFIELDS** **S105841715**
NNW **242 NEVINS STREET** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.343 mi.
1811 ft. **Site 5 of 5 in cluster AV**

Relative: **Lower**
Actual: **8 ft.**

BROWNFIELDS:

Name:	242 NEVINS STREET
Address:	242 NEVINS STREET
City,State,Zip:	BROOKLYN, NY 11217
Program:	BCP
Site Code:	568573
Acres:	1.190

242 NEVINS STREET (Continued) **S105841715**

HW Code:	C224273
SWIS:	2401
Town:	New York City
Record Added Date:	04/04/2018
Record Updated Date:	03/06/2020
Update By:	DJEATON
Site Description:	"Location: The site is located in an urban area along the Gowanus Canal, within the Borough of Brooklyn, on the northwest corner of Nevins Street and Degraw Street. Site Features: The site is currently improved with a two-story building, which occupies approximately 2,000 square feet of the parcel (242 Nevins Street) and a one-story building, which occupies approximately 16,000 square feet of the parcel (254 Nevins Street). The remainder of the parcel consists of parking, storage, and outdoor work areas associated with the buildings operations, to include vehicle and equipment storage and repair. Current Zoning and Land Use: The site is currently zoned for industrial and manufacturing use (M2-1 district). The buildings are occupied by an automobile repair facility, commercial hauler, automobile upholsterer, production studio, plumbing contractor and general contractors whose operations include vehicle and equipment repair. Adjoining parcels are used for industrial, parking, and open space/recreational purposes, with the surrounding area generally consisting of industrial/commercial uses. Past Uses of the Site: Past use of the site includes a coal company (approximately 1886 to 1950), automobile/vehicle repair (approximately 1938 to 1950, and 2013 to present), an unpermitted solid waste management facility (prior to 1994), a Resource Conservation and Recovery Act Large Quantity Generator (1988), and various trucking and contracting companies (approximately 1969 to present), including a petroleum transporter. Site Geology and Hydrogeology: The site is located in a developed area of Brooklyn, generally covered with paved roads, walkways and buildings. The subsurface strata at the site consists of historic fill material characterized by loose silty sand with varying amounts of silt, sand, gravel, ash, asphalt, brick, clinkers, cobblestone, concrete, glass fragments, metal, and wood extending to depths of as great as 15 feet below grade surface (bgs). The historic fill material is underlain by alluvial deposits consisting of poorly sorted sands with gravel and marsh deposits, referred to as meadow mat, which consists of interbedded sands, clays and silts. Bedrock (Fordham Gneiss) was encountered at a depth of about 159 feet bgs. Groundwater was encountered between 4.54 and 5.6 feet bgs and generally flows westward toward the Gowanus Canal."
Env Problem:	"US Environmental Protection Agency (EPA) has determined that the property is part of the Gowanus Canal Superfund Site that is listed on the National Priorities List. Additionally, under ECL 27-1405(2)(e), there is currently an EPA environmental enforcement action related to contamination at the property, therefore the site was denied entry to the NYS BCP."
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported

242 NEVINS STREET (Continued) **S105841715**

Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Pacific Branch
Owner Address:	25 Fourth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Marino Mazzei
Owner Company:	242 Nevins, Inc.
Owner Address:	444 Third Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Marino Mazzei
Owner Company:	New Venezia LLC
Owner Address:	440 Third Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	BROOKLYN TRUCK & EQUIPMENT
Address:	242 NEVINS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1103765 / 2011-08-05
Facility ID:	1103765
Facility Type:	ER
DER Facility ID:	405887
Site ID:	451337
DEC Region:	2

242 NEVINS STREET (Continued) **S105841715**

Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-07-06
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	2011-07-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-06
Spill Record Last Update:	2011-08-05
Spiller Name:	ECO JENNIFER OKONUK
Spiller Company:	BROOKLYN TRUCK AND EQUIPTMENT CORP
Spiller Address:	242 NEVINS STREET
Spiller Company:	999
Contact Name:	ECO JENNIFER OKONUK
DEC Memo:	"Ketani responded to the site. 7/6/11 - Raphael Ketani. I arrived at the site at about noon time. The site was a large yard with a gray building on the back left corner that fronts on Nevins Street. The address is 242 Nevins Street (near Degraw and Nevins), Brooklyn, 11217. Several companies had their signs on the corrugated fence. These companies were Brooklyn Truck & Equipment, Phoenix Services Corp. (718) 567-2023, and Cole Partners, Inc. (718) 875-8300. I entered the yard and saw a red painted trailer (posssibly with a cement pump) on the left that had been leaking hydraulic fluid. The floor of the front half of the yard appeared to be partially paved and partially laid with paving stones. There was a steel plate in one location with holes in it. Vehicles were parked on both sides of the front half of the yard, but I did not see any leaks. Next, I went to the back half of the yard. The ground appeared to be only dirt. There were vehicles and construction machines parked along the west side and north edges of the yard. The Gowanus Canal bordered the west side of the yard and the water level was nearly even with the yard (maybe 3 feet below ground level). Most of the trucks belonged to two different garbage carting companies, M&G Carting, 303 5th Avenue, NY, 10016, (212) 689-0332, and Flash Recycling, 132 Ludlow Street, NY, 10002, (212) 673-6194 (Prince Street Station, P.O. Box 515, NY, 10012). Some of the trucks had leaked either motor oil or hydraulic oil. There was oil on the ground near one of the Flash Recycling trucks. One of the M&G Carting trucks looked like it hadn't been operational for a long time. There was a rolling container near this truck with many plastic bottles that had contained motor oil. I didn't see any leaking from the container, but this was not a proper container for liquids of any kind. After my tour of the back half of the yard, I entered the gray building. In many places, there was oil on the floor. I saw a zipper drain that looked like it may contain sludge. I entered the office of Brooklyn Truck & Equipment and met ECO Jennifer Okonuk (718) 482-4885 and the owner of the business, Bob Hepplewhite (718) 237-7976. ECO Okonuk informed me that she had

242 NEVINS STREET (Continued) **S105841715**

called in the spill. She had been making inspections of garages when she came across Brooklyn Truck & Equipment. She said that she had issued two tickets to Mr. Hepplewhite, for noisome and unwholesome. Mr. Hepplewhite, ECO Okonuk and myself toured the garage. ECO Okonuk pointed out the area with oil saturated Speedi Dri next to a 275 gal. waste oil tank and a 275 gal. tank that Mr. Hepplewhite said contained fresh motor oil for the trucks. One of the workers at the garage dug through the Speedi Dri and showed us that there was a concrete floor below. I pointed out to Mr. Hepplewhite that there were containers of motor oil on racks in the back of the oil contaminated area. He said that these weren't his and that they were empty and had been there since before he had moved his business in. Mr. Hepplewhite added that the oil tank next to them also wasn't his and he knew nothing about it. Next, we went outside to the yard. I asked Mr. Hepplewhite about the trucks. He said that he makes extra money by leasing space for parking the trucks. I pointed out the spilled oil, the rolling container with oil bottles, and the derelict truck. I told him that he had to inform M&G Carting and Flash Recycling and get them to clean up the site and remove the oil bottles and the derelict leaking truck (ECO Okonuk claimed it was leaking). He said that he will do this. ECO Okonuk and I asked about the steel plate in the back half of the yard and the perforated steel plate in the front half of the yard, and whether he leased both halves. Mr. Hepplewhite said that he leased only the gray building and the back half of the yard. He added that the plates covered sewer tanks. He went on to say that when it rains, the entire yard floods 8 to 10 inches because the sewers back up under the street. Mr. Hepplewhite added that even the Gowanus Canal floods during the rain storms and spills into his yard. The yard and the vicinity is a low area. ECO Okonuk told me that she has seen this happen, too. He also stated that the building to the south can not be sold because there is oil underground from the coal gasification that took place many years ago. Mr. Hepplewhite commented that the EPA and the NYC DEP did borings throughout the yard and elsewhere because of the underground contamination. While we were in the yard, Andrew Kelly, enforcement officer - Emergency Response Engineer with the ER Unit (718) 595-4761 of the NYC DEP arrived. We went back inside the shop and I went over what needed to be done to clean up the site. These items were: 1) clean up the saturated Speedi Dri and make sure fresh absorbent is kept at this location for any future spills that take place 2) hire an environmental company to do soil borings in the saturated area, along the sides of the zipper drains and in the back half of the yard - if contamination is found, then it will have to be cleaned up 3) call M&G and Flash and have them clean up their spills 4) clean up the floor of the garage and have someone keep on top of the spills with absorbent and power washing (Mr. Hepplewhite stated that the garage is powerwashed once a month) 5) hire a company to clean out the zipper drains (Mr. Hepplewhite said that there is a plug at the end of the last zipper and that nothing can flow to the sewers) I told Mr. Hepplewhite that the DEC will be sending a contaminated soil letter to him and to the owners of the property with a C-c to ECO Okonuk. I added that we will want a clean up report after everything is done. Mr. Hepplewhite said that he understood. There was one other spill case for the site. It was #0510846. It involved a 200 gal. oil spill to the yard and the street and the sewer on 12/16/05. Bonafide Energy was the responsible party. A valve had broken. The site was cleaned up by 4/21/06 and the case was closed. 7/8/11 - Raphael

242 NEVINS STREET (Continued) **S105841715**

Ketani. I tried contacting M&G Carting (212) 689-0332 to let them know that they have to clean up the spilled oil around and under their trucks. However, I reached the answering machine of Frank Mormando. I left a message for him to contact me. I contacted Billy Huang, the owner of Flash Recycling (212) 673-6194. I told him that he had to clean up the spilled oil from under and around his trucks and the pool of stinking leachate. He said that he will get one of his crew to do this. I told him that the oil has to be put in an appropriate container for oil disposal and that the DEC will do an inspection next week to see whether he has complied with our request. I added that if the oil and leachate aren't cleaned up, then he could face fines and penalties. Mr. Huang said that the oil and leachate will be removed. I looked up the property ownership using ACRIS. The latest deed for block and lot 418 and 1 is held by 242 Nevins, Inc., 444 Third Avenue, Brklyn, 11215. The deed date is 7/27/05, it was prepared on 10/5/05, and filed on 1/12/06. The property manager is Marino Mazzei, Bonified Realty, 140 Portland Road, Highland, NJ, 07732, (718) 788-2222. I spoke to Mr. Mazzei and told him about the leaking red painted trailer, the leaking trucks and the spills at Brooklyn Truck & Equipment. I told him that Mr. Hepplewhite will take care of the spills in his garage and that the trucking companies have been notified about the spills from their trucks. Mr. Mazzei said that he will visit the site and see to it that everything is cleaned up. I sent a CSL to 242 Nevins, Inc. regarding the hydraulic fluid that is leaking from the red trailer and the leaking trucks. Another CSL went to Mr. Mazzei regarding the same issues. I also sent Mr. Hepplewhite (718) 237-7976 and Mr. Mazzei CSLs with the 5 items from above. Later, Mr. Mormando, the owner of M&G Carting (212) 689-0332, called me back. He said that he will clean up the spill under and around his trucks and he will have the rolling container emptied. 7/12/11 - Raphael Ketani. Mr. Mazzei cell (347) 231-6440 called. He said that everything that the DEC was concerned about in the garage and in the yard has been cleaned up. He invited me to check the place. I told him that I will this week. However, I added that Mr. Hepplewhite still has to hire an environmental company to do soil borings in the former oil saturated area and along the sides of the zipper drains. He said that he understood. 7/19/11 - Raphael Ketani. The CSL to 242 Nevins Inc. was returned in an unopened envelope as ATTEMPTED - NOT KNOWN. 8/5/11 - Raphael Ketani. I made an unannounced site visit. The oil spill under the red trailer had been cleaned up. The small oil spills next to and around the garbage trucks had also been cleaned up. The small rolling trash dumpsters (about 1.5 cu. yds. each) had been emptied. I met Mr. Hepplewhite. He showed me the area inside the garage that had been badly affected by spilled oil. He said that the oil was actually on sheets of plywood, not on the garage floor. This appeared to be true as most of this area of the garage floor was very clean as if there had never been oil tanks here. It was cleaner than it could have been if someone had power washed the floor. All of the tanks and buckets had been removed. However, I did see a darkened corner of this area next to the racks which used to hold containers of oil. I knelt down at this corner, but didn't sense any oil odors. I assumed the darkening to be the result of moisture as it had rained heavily earlier during the week and the corrugated walls were not sealed to the floor. There still were mud puddles in the backyard where the garbage trucks were. Next, he showed me the new location of the waste oil tank. It was now in a larger tank which served as secondary containment - should any of his

242 NEVINS STREET (Continued) **S105841715**

workers spill oil while transfering it to the tank. The tank was in between the two back garage doors. Mr. Hepplewhite showed me the zipper drains. They were now covered by steel plates which fit flush with the garage floor. The plates had holes so that wash water can enter the drains. He lifted up one plate and I could see the concrete bottom of the drain. There were no odors and the bottom of the drain looked to be in good condition without any cracks. Lastly, he showed me the drums of sediment that had been removed from the drains. The lids were securely attached to the drums and they looked to be ready for pickup. Mr. Hepplewhite said that the person who runs the waste oil pickup company will arrange for the drums to be picked up. I looked at the floor of the shop and it was very clean, except for a small puddle under one engine. This engine had just been drained. I pointed this out to Mr. Hepplewhite and he said that the spill will be cleaned up immediately. After this, I left. As the former waste oil tank area was very clean and as the zipper drains didn't smell as if they had oil and were in good condition, I decided that soil borings weren't necessary at the site. As the spills appeared to have been remediated, I have determined that there is no threat to the public or the environment. Therefore, I am closing the spill case. DLE had issued tickets. So their case will remain active. "

Remarks: "The whole ground of the garage is saturated. Been dumping there for 6 years. No clean up as of yet."

All Materials:

Site ID:	451337
Operable Unit ID:	1201535
Operable Unit:	01
Material ID:	2198065
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AX396 **TOLL BROOKLYN, LP** **NY BROWNFIELDS** **S113916457**
WNW **64-98 1ST ST; 82-107 1ST ST; 119-145 2ND ST;** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.345 mi.
1820 ft. **Site 2 of 2 in cluster AX**

Relative: **Lower**
Actual: **19 ft.**

BROWNFIELDS:

Name:	TOLL BROOKLYN, LP
Address:	64-98 1ST ST; 82-107 1ST ST; 119-145 2ND ST;
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	348572
Acres:	3.570
HW Code:	C224116
SWIS:	2401
Town:	New York City
Record Added Date:	06/30/2005
Record Updated Date:	09/04/2008
Update By:	DMMOLOUG

TOLL BROOKLYN, LP (Continued) **S113916457**

Site Description:	"Remediation of the site is proposed under the Brownfield Cleanup Program. The Toll Brooklyn, LP site is located in Kings County, NY and is comprised of three separate parcels, which were investigated separately between 1997 and 2005. The parcels include 363 Bond Street (Tax Block 452, Lot 1), 365 Bond Street (Tax Block 458, Lot 1) and 400 Carroll Street (Tax Block 452, Lot 15). The specific addresses listed in the BCP Application are: 64-98 1st Street; 82-107 1st Street; 119-145 2nd Street; 357-379 Bond Street; and 400-402 Carroll Street. Residential use is proposed for the Toll Brooklyn, LP site. Due to rezoning issues, the applicant withdrew their BCP application without prejudice in December 2006."
Env Problem:	"Despite the termination of this project, there is an ongoing spill investigation at this site. Spill #04-07393 was referred to the DEC Region 2 spills office in Long Island City, Queens County."
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	NNN
Owner Name:	DAVID VON SPRECKELSEN
Owner Company:	TOLL BROTHERS, INC.
Owner Address:	16 COURT STREET
Owner Addr2:	SUITE 1009
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	JOHN ROMEO
Owner Company:	FIBERWAVE TECHNOLOGIES
Owner Address:	125 2ND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	C/O HARTMAN & CRAVEN, LLP
Owner Company:	CITIBANK, NA AND JOSEPH PHILLIPS
Owner Address:	488 MADISON AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10022
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	FOR 363 BOND ST PROPERTY (TAX #452-1)
Owner Company:	363 BOND STREET CORPORATION
Owner Address:	363 BOND STREET
Owner Addr2:	Not reported

TOLL BROOKLYN, LP (Continued) **S113916457**

Owner City,St,Zip:	BROOKLYN, NY 11231
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	ANDREW MARTORELLI
Owner Company:	ALL-BRITE CLEANERS
Owner Address:	123 2ND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	DAVID LEFKOWITZ
Owner Company:	WOODEN BRIDGE, LLC
Owner Address:	136 HICKS STREET
Owner Addr2:	SUITE 1C
Owner City,St,Zip:	BROOKLYN, NY 1
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	FOR 363 BOND ST PROPERTY (TAX #452-1)
Owner Company:	FRIEDKNIT CREATIONS
Owner Address:	363 BOND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11231
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	DAVID LEFKOWITZ
Owner Company:	WOODEN BRIDGE, LLC
Owner Address:	136 HICKS STREET
Owner Addr2:	SUITE 1C
Owner City,St,Zip:	BROOKLYN, NY 1
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AZ397 **OCEAN SUPPLY CO** **NY LTANKS** **S104191667**
SW **437 3RD AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.346 mi.
1828 ft. **Site 1 of 2 in cluster AZ**

Relative: **Lower**
Actual: **18 ft.**

LTANKS:

Name:	OCEAN SUPPLY CO
Address:	437 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9905579 / 1999-09-22
Facility ID:	9905579
Site ID:	306200

OCEAN SUPPLY CO (Continued) **S104191667**

Spill Date:	1999-08-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1999-08-09
CID:	382
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-09
Spill Record Last Update:	2002-01-23
Spiller Name:	JIM
Spiller Company:	OCEAN SUPPLY CO
Spiller Address:	437 3RD AVE
Spiller County:	001
Spiller Contact:	JIM
Spiller Phone:	(718) 788-5691
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	247328
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 8/23/99 - Sangesland spoke with owner Miki . She said she is trying to sell the building and the tank failed. She is taking the tank out and switching to gas heat. She has hired D&D Plumbing & Heating (718-436-6698) to remove the tank and switch to gas. Sangesland told Miki to call the DEC 1 or 2 days before work will be done. DEC needs to see the hole after the tank is removed and before it is backfilled. 9/1/99 - Jim from State Environmental said he opened the tank and tested the tank and the lines seperate. He found the problem in the neck of the tank. There was a bad weld, but since it was on the top of the tank there was no leak of oil to the ground. He saw no evidence of soil contamination in the area that was dug away. Sangesland asked him to submit a statement saying 1) The tank past the soundness test, 2) The problem was a weld line in the neck of the tank, 3) no contamination was found. Sangesland gave permission to close out the tank in place. The building is being converted to natural gas heat. 9/22/99 State Environmental sent an afidavit saying no contamination was found and the site is clean. Closed"
Remarks:	"GROSS FAILURE. TANK WILL BE PUMPED OUT AND RETESTED."

All TTF:

Facility ID:	9905579
Spill Number:	9905579
Spill Tank Test:	1547469
Site ID:	306200
Tank Number:	Not reported
Tank Size:	1080
Material:	0001
EPA UST:	Not reported

OCEAN SUPPLY CO (Continued) **S104191667**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	306200
Operable Unit ID:	1080058
Operable Unit:	01
Material ID:	301868
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY398 **388 CARROLL STREET AND 363 BOND STREET** **NY ENG CONTROLS** **S116041498**
NW **388 CARROLL STREET AND 363 BOND STREET** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11231** **NY BROWNFIELDS**
0.346 mi.
1828 ft. **Site 3 of 3 in cluster AY**

Relative: **Lower**
Actual: **19 ft.**

ENG CONTROLS:

Name:	388 CARROLL STREET AND 363 BOND STREET
Address:	388 CARROLL STREET AND 363 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478612
HW Code:	C224173
Control Code:	15
Control Type:	ENG
Date Record Added:	10/23/2015
Date Rec Updated:	03/14/2021
Updated By:	SXAHMED
Site Description:	"Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

	residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-05 14:19:00
Record Upd:	2015-10-02 10:38:00
Updated By:	JCGRATHW
Own Op:	6
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
HW Code:	C224173
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	1,2,4-TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224173
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-10-02 10:39:00
Record Updated:	2015-10-02 10:39:00

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Updated By:	JCGRATHW
Crossref ID:	C224173-08-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-10-02 11:10:00
Updated By:	JCGRATHW
Crossref ID:	2015000236153
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-21 11:01:00
Record Updated:	2015-07-21 11:01:00
Updated By:	JCGRATHW
Crossref ID:	08/14/13
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2015-10-02 10:40:00
Record Updated:	2015-10-02 10:40:00
Updated By:	JCGRATHW
Crossref ID:	C224173-07-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-11-05 09:44:00
Updated By:	JAMORAS

Name:	388 CARROLL STREET AND 363 BOND STREET
Address:	388 CARROLL STREET AND 363 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478612
HW Code:	C224173
Control Code:	12
Control Type:	ENG
Date Record Added:	10/23/2015
Date Rec Updated:	03/14/2021
Updated By:	SXAHMED
Site Description:	"Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

	(1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-05 14:19:00
Record Upd:	2015-10-02 10:38:00
Updated By:	JCGRATHW
Own Op:	6
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
HW Code:	C224173
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	1,2,4-TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224173
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-10-02 10:39:00
Record Updated:	2015-10-02 10:39:00
Updated By:	JCGRATHW
Crossref ID:	C224173-08-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-10-02 11:10:00

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Updated By:	JCGRATHW
Crossref ID:	2015000236153
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-21 11:01:00
Record Updated:	2015-07-21 11:01:00
Updated By:	JCGRATHW
Crossref ID:	08/14/13
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2015-10-02 10:40:00
Record Updated:	2015-10-02 10:40:00
Updated By:	JCGRATHW
Crossref ID:	C224173-07-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-11-05 09:44:00
Updated By:	JAMORAS

Name:	388 CARROLL STREET AND 363 BOND STREET
Address:	388 CARROLL STREET AND 363 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478612
HW Code:	C224173
Control Code:	13
Control Type:	ENG
Date Record Added:	10/23/2015
Date Rec Updated:	03/14/2021
Updated By:	SXAHMED
Site Description:	"Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

	below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-05 14:19:00
Record Upd:	2015-10-02 10:38:00
Updated By:	JCGRATHW
Own Op:	6
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

HW Code:	C224173
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	1,2,4-TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224173
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-10-02 10:39:00
Record Updated:	2015-10-02 10:39:00
Updated By:	JCGRATHW
Crossref ID:	C224173-08-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-10-02 11:10:00
Updated By:	JCGRATHW
Crossref ID:	2015000236153
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-21 11:01:00
Record Updated:	2015-07-21 11:01:00

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

INST CONTROL:
Name: 388 CARROLL STREET AND 363 BOND STREET
Address: 388 CARROLL STREET AND 363 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478612
Control Name: Monitoring Plan
HW Code: C224173
Control Code: 31
Control Type: INST
Dt record added: 10/23/2015
Dt rec updated: 03/14/2021
Updated By: SXAHMED
Site Code: 478612
Site Description: "Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-05 14:19:00
Record Upd: 2015-10-02 10:38:00
Updated By: JCGRATHW
Own Op: 6
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
HW Code: C224173
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

Name: 388 CARROLL STREET AND 363 BOND STREET
Address: 388 CARROLL STREET AND 363 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478612
Control Name: O&M Plan
HW Code: C224173
Control Code: 33
Control Type: INST
Dt record added: 10/23/2015
Dt rec updated: 03/14/2021
Updated By: SXAHMED
Site Code: 478612
Site Description: "Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

	restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-05 14:19:00
Record Upd:	2015-10-02 10:38:00
Updated By:	JCGRATHW
Own Op:	6
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
HW Code:	C224173
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

Name: 388 CARROLL STREET AND 363 BOND STREET
Address: 388 CARROLL STREET AND 363 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478612
Control Name: Environmental Easement
HW Code: C224173
Control Code: J
Control Type: INST
Dt record added: 10/23/2015
Dt rec updated: 03/14/2021
Updated By: SXAHMED
Site Code: 478612
Site Description: "Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-05 14:19:00
Record Upd: 2015-10-02 10:38:00
Updated By: JCGRATHW
Own Op: 6
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
HW Code: C224173
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

Name: 388 CARROLL STREET AND 363 BOND STREET
Address: 388 CARROLL STREET AND 363 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478612
Control Name: IC/EC Plan
HW Code: C224173
Control Code: 34
Control Type: INST
Dt record added: 10/23/2015
Dt rec updated: 03/14/2021
Updated By: SXAHMED
Site Code: 478612
Site Description: "Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump: False
Structure: False

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-05 14:19:00
Record Upd: 2015-10-02 10:38:00
Updated By: JCGRATHW
Own Op: 6
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
HW Code: C224173
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

Name: 388 CARROLL STREET AND 363 BOND STREET

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Address:	388 CARROLL STREET AND 363 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Site Code:	478612
Control Name:	Site Management Plan
HW Code:	C224173
Control Code:	32
Control Type:	INST
Dt record added:	10/23/2015
Dt rec updated:	03/14/2021
Updated By:	SXAHMED
Site Code:	478612
Site Description:	"Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-05 14:19:00
Record Upd: 2015-10-02 10:38:00
Updated By: JCGRATHW
Own Op: 6
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
HW Code: C224173
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

Name: 388 CARROLL STREET AND 363 BOND STREET
Address: 388 CARROLL STREET AND 363 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478612
Control Name: Soil Management Plan

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

HW Code: C224173
Control Code: 14
Control Type: INST
Dt record added: 10/23/2015
Dt rec updated: 03/14/2021
Updated By: SXAHMED
Site Code: 478612
Site Description: "Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-02-05 14:19:00

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Record Upd: 2015-10-02 10:38:00
Updated By: JCGRATHW
Own Op: 6
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
HW Code: C224173
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

Name: 388 CARROLL STREET AND 363 BOND STREET
Address: 388 CARROLL STREET AND 363 BOND STREET
City,State,Zip: BROOKLYN, NY 11231
Site Code: 478612
Control Name: Ground Water Use Restriction
HW Code: C224173
Control Code: 08
Control Type: INST
Dt record added: 10/23/2015

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Dt rec updated:	03/14/2021
Updated By:	SXAHMED
Site Code:	478612
Site Description:	"Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-05 14:19:00
Record Upd:	2015-10-02 10:38:00
Updated By:	JCGRATHW
Own Op:	6
Sub Type:	P03

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. John Leighton
Owner Company: Brooklyn Public Library
Owner Address: Carroll Gardens Branch
Owner Addr2: 396 Clinton Street
Owner City,St,Zip: Brooklyn, NY 11231
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Mr. Craig Hammerman
Owner Company: Brooklyn Community Board 6
Owner Address: 250 Baltic Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11201-6401
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Benjamin Hoffer
Owner Company: 363 Gowanus Developers, LLC
Owner Address: 90 Woodbridge Center Drive, 6th Floor
Owner Addr2: Not reported
Owner City,St,Zip: Woodbridge, NJ 07095
Owner Country: United States of America
HW Code: C224173
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Code: Not reported
HW Code: C224173
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224173
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224173
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2015-10-02 10:39:00
Record Updated: 2015-10-02 10:39:00
Updated By: JCGRATHW
Crossref ID: C224173-08-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-10-02 11:10:00
Updated By: JCGRATHW
Crossref ID: 2015000236153
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-07-21 11:01:00
Record Updated: 2015-07-21 11:01:00
Updated By: JCGRATHW
Crossref ID: 08/14/13
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2015-10-02 10:40:00
Record Updated: 2015-10-02 10:40:00
Updated By: JCGRATHW
Crossref ID: C224173-07-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-10-02 11:10:00
Record Updated: 2015-11-05 09:44:00
Updated By: JAMORAS

BROWNFIELDS:

Name:	388 CARROLL STREET AND 363 BOND STREET
Address:	388 CARROLL STREET AND 363 BOND STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	478612
Acres:	1.293
HW Code:	C224173
SWIS:	2401
Town:	New York City
Record Added Date:	02/05/2013
Record Updated Date:	02/09/2022
Update By:	WBBENNET

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Site Description:	"Location: This site is made up of two adjacent parcels, one located at 388 Carroll Street and one located at 363 Bond Street in Brooklyn, NY. The eastern edge of the site borders the Gowanus Canal. Site Features: A portion of the site contained a one- and two-story light industrial building and another portion was improved with a two-story residential building. Four decommissioned above ground storage tanks (ranging from 5,000 to 10,000 gallon capacity) also existed on the property. All buildings and structures were demolished in 2014 to facilitate remediation of the site. The site is now redeveloped as a five to twelve-story mixed used commercial/residential building with a partial basement, a water from esplanade, a pedestrian walkway and northern portion of the new First Street roadway and sidewalk. The area of the two parcels that make up the site is approximately 1.293 acres. Current Zoning and Land Use: The site is currently vacant. The site is current zoned MX-11 which is a mixed use district that allows residential, commercial, and industrial uses. The site is bounded to the north by a City of New York EMS station, to the east by the Gowanus Canal, to the south an active redevelopment site, and to the west by a three-story mixed-use commercial and residential building and a six-story residential building. Past Use of the Site: Portions of this site have historically been used as paint manufacturer (1915), an oil terminal (1916 1950), and a warehouse (1950 1986). Other recorded uses of the site include an automobile storage and repair facility and a lumber company. Site Geology and Hydrogeology: The site is underlain by an approximately 6-to-17 foot thick layer of miscellaneous fill which is underlain by a clay layer. Groundwater was generally observed at depths ranging from five to eight feet below ground surface. Groundwater flow is generally to the east but is affected by the tidal influence from the Gowanus Canal. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were benzo(a)pyrene, benzo(a)anthracene, benzo(b)fluorathene in soil, and naphthalene, 1,2,4 trimethylbenzene, toluene, and xylene in groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Sampling indicates that the potential for soil vapor intrusion to occur needs to be evaluated off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-05 14:19:00
Record Upd:	2015-10-02 10:38:00
Updated By:	JCGRATHW
Own Op:	6
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. John Leighton
Owner Company:	Brooklyn Public Library
Owner Address:	Carroll Gardens Branch
Owner Addr2:	396 Clinton Street
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Mr. Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Benjamin Hoffer
Owner Company:	363 Gowanus Developers, LLC
Owner Address:	90 Woodbridge Center Drive, 6th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodbridge, NJ 07095
Owner Country:	United States of America
HW Code:	C224173
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	1,2,4-TRIMETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	TETRACHLOROETHYLENE (PCE)

388 CARROLL STREET AND 363 BOND STREET (Continued) **S116041498**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224173
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224173
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-10-02 10:39:00
Record Updated:	2015-10-02 10:39:00
Updated By:	JCGRATHW
Crossref ID:	C224173-08-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-10-02 11:10:00
Updated By:	JCGRATHW
Crossref ID:	2015000236153
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-07-21 11:01:00
Record Updated:	2015-07-21 11:01:00
Updated By:	JCGRATHW
Crossref ID:	08/14/13
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2015-10-02 10:40:00
Record Updated:	2015-10-02 10:40:00
Updated By:	JCGRATHW
Crossref ID:	C224173-07-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-10-02 11:10:00
Record Updated:	2015-11-05 09:44:00
Updated By:	JAMORAS

BA399 **BKLYN UNION GAS /CITIZENS GATE STA** **SEMS-ARCHIVE** **1003863865**
WSW **6TH ST & 2ND AVE** **NYD980532212**
1/4-1/2 **BROOKLYN, NY 11215**
0.348 mi.
1835 ft. **Site 1 of 2 in cluster BA**

Relative: SEMS Archive:
Lower

Site ID:	0201995
EPA ID:	NYD980532212
Name:	BKLYN UNION GAS /CITIZENS GATE STA
Address:	6TH ST & 2ND AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11215
Cong District:	14
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL

Actual:
8 ft.

BKLYN UNION GAS /CITIZENS GATE STA (Continued) **1003863865**

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201995
EPA ID:	NYD980532212
Site Name:	BKLYN UNION GAS /CITIZENS GATE STA
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-24 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0201995
EPA ID:	NYD980532212
Site Name:	BKLYN UNION GAS /CITIZENS GATE STA
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1981-06-01 04:00:00
Finish Date:	1981-06-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201995
EPA ID:	NYD980532212
Site Name:	BKLYN UNION GAS /CITIZENS GATE STA
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1986-09-05 04:00:00
Finish Date:	1986-09-24 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

BA400 **BUG, CITIZENS GATE STATION** **NY HSWDS** **S108147010**
WSW **6TH STREET AND 2ND AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.356 mi.
1881 ft. **Site 2 of 2 in cluster BA**

Relative:
Lower

Actual:
8 ft.

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	Unknown
Owner Type:	Publ Utily
Owner:	Brooklyn Union Gas Co.
Owner Address:	195 Montague Street
Owner Phone:	(718)403-3053
Operator Type:	Unknown
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD980532212
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	40 40 30 N
Longitude:	73 59 30 W
Acres:	0.00
Operator Date:	1981
Close Date:	Unknown
Completed:	PA
Active:	Unknown
PCB's Disposed:	Unknown
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown

BUG, CITIZENS GATE STATION (Continued) **S108147010**

Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AZ401 **168 8TH STREET** **NY BROWNFIELDS** **S121933776**
SW **168 8TH STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.364 mi.
1921 ft. **Site 2 of 2 in cluster AZ**

Relative: **Lower**
Actual: **20 ft.**

BROWNFIELDS:

Name:	168 8TH STREET - OFF-SITE
Address:	168 8TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	568008
Acres:	Not reported
HW Code:	C224266A
SWIS:	2401
Town:	New York City
Record Added Date:	03/16/2018
Record Updated Date:	06/07/2021
Update By:	JHOCONNE
Site Description:	"The area of concern subject to this work is considered off-site from BCP site No. C224266 168 8th Street and reflects the investigation and possible remediation of contamination that may have migrated from that site. This work is being carried out as provided for under the Environmental Conservation Law Section 27-1411.5. Please see C224266 for further information regarding the status of the site in the Brownfield Cleanup program. Location - The site includes properties around the BCP site (C224266) located at 168 8th Street. This site is

168 8TH STREET (Continued) **S121933776**

an off-site project associated with the on-site BCP project. Site Features - The site does not have definite boundaries since it is an off-site project associated with an on-site BCP project. Potentially impacted areas from the BCP site 168 8th Street include a two-story commercial building and three-story residential building to the north, three and four-story commercial buildings to the east, to the west a one-story institutional building (American Legion Hall), one story commercial building occupied by a parking garage (Enterprise Rent-A-Car), and a four-story residential building with commercial use on the first floor, and to the south by Top Notch Auto Repair and a three-story residential building. The off-site areas are not necessarily limited to these areas. Current Zoning and Land Use: The site is currently zoned R6A and R6B for residential. The potentially impacted areas from the 168 8th Street BCP site include residential and commercial buildings surrounding the property. Potential for further migration include downgradient impacts from the on-site BCP Site. Past Use of the Site - The site has not yet been identified for its past historic use. The property potentially impacting the Sste but not limited to, 168 8th Street BCP site was historically used for residential and manufacturing processes including an ink manufacturer, storage facility, gauge manufacturer, chemical laboratory, machine works, textile factory and a gasoline station with a garage that occupied the BCP site from 1888-1992. The site has been vacant since approximately 1992. Site Geology and Hydrology - Based on the information collected during the investigation of C224266, the soil beneath the site consists of brown sand, silt with fine gravel, coal, and brick fragments associated with historic fill approximately 10 feet below surface. Deeper native material consisting of sand, silt, and clay was encountered at 20 feet below grade. Crystalline bedrock is estimated to be 200 feet below surface. Based on topography in the area and review of the USGS Hydraulic Conditions Map for Long Island, NY, 2013 (USGS Groundwater Conditions on Long Island, New York in 2013), it is expected that the predominant direction of groundwater flow is northwesterly. The depth to groundwater ranges from approximately 13 to 19 feet below surface. "

Env Problem: "During the on-site Remedial Investigation for site C224266, soil and groundwater samples were collected and analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, PCBs, and pesticides. Soil vapor samples were analyzed for VOCs. Based upon the results of the RI, the primary contaminants of concern for on-site include cis-1,2-dichloroethene, trichloroethene (TCE) and tetrachloroethene (PCE). Contamination can likely be attributed to activities associated with the historic use of the site for manufacturing activities. Further investigation is needed to fully delineate the extent of off-site contamination. "

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

168 8TH STREET (Continued) **S121933776**

Dell:	Not reported
Record Add:	2018-03-19 09:34:00
Record Upd:	2018-03-19 09:34:00
Updated By:	WYZHENG
Own Op:	6
Sub Type:	NNN
Owner Name:	Alexander Fried
Owner Company:	Derby Textile Corp.
Owner Address:	41 Varick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Country:	United States of America
HW Code:	C224266A
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266A
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266A
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	R2-20190619-211
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2019-10-01 13:08:00
Record Updated:	2019-10-01 13:08:00
Updated By:	WYZHENG
Name:	168 8TH STREET
Address:	168 8TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	563661
Acres:	0.310
HW Code:	C224266
SWIS:	2401
Town:	New York City
Record Added Date:	10/30/2017
Record Updated Date:	06/07/2021
Update By:	JHOCONNE
Site Description:	"Location: The site is located in the Gowanus neighborhood, a mixed-use urban area of Brooklyn, NY, which includes residential, commercial, and manufacturing areas. The site is bordered to the north by 8th Street followed by a two-story commercial building and three-story residential buildings; to the east by three- and four-story residential buildings; to the west by a one-story institutional building (American Legion Hall) with a parking lot followed by a one-story commercial building with a parking lot (Enterprise Rent-A-Car) and four-story residential buildings with one first-floor commercial tenant; and, to the south by 9th Street followed by a one story commercial building (Top Notch Auto Repair) and three-story residential buildings. Site Features: The site consists of one tax lot (Block 1003, Lot 11) totaling approximately 13,500 square feet or 0.31 acre. The site is a vacant concrete- and

168 8TH STREET (Continued) **S121933776**

gravel-covered lot and is fenced. The site will be developed into a Pre-K school. The northern portion of the site is approximately one to two feet lower in elevation in comparison to the southern portion of the lot, and a concrete ramp located on the east-central portion of the lot connects these two areas for vehicle access. Current Zoning and Land Use: The site is zoned for residential use (R6A for the southern portion of the lot and R6B for the northern portion of the lot). Residential districts permit community facilities such as schools. The site has been vacant for approximately 25 years. Past Use of the Site: Historic records indicate that the site was first developed as farmland. A residential building, which was demolished in the late 1800s, was present on the southern portion of the site. From the late 1800s to the early 1900s, the site was occupied by an ink manufacturer (1888 to 1906), a storage facility (1906 to 1926) with a gauge manufacturer (circa 1917), a chemical laboratory (1926), and a machine works facility (1928 to 1934). In the mid- to late-1900s the site was occupied by a garage and a gasoline station (from approximately 1926 to at least 1951), a plumbing supply/metal products manufacturer (1945 to 1965), and a textile factory (1976 to 1992). A fire occurred on the site in the early 1990s and the lot has been vacant since approximately 1992. An IRM was completed by the Volunteer in October 2017, prior to entry into the BCP to remove a hot spot of chlorinated solvents to depths of 19 feet at the northern portion of the site. Site Geology and Hydrogeology: The geology of Kings County consists of unconsolidated glacial deposits overlying crystalline bedrock. Bedrock is estimated to be 200 feet below ground surface (bgs). Fill material consisting of brown sand, silts with fine gravel, coal, and brick fragments was encountered at the site to a maximum depth of approximately 10 feet bgs. Deeper, native material consisting of sand, silt and clay was encountered to 20 feet bgs. Based on information collected during the site investigations, the predominant direction of groundwater flow is northwesterly, and the depth to groundwater at the site ranges from approximately 13 to 19 feet bgs. "

Env Problem:

"Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), pesticides, polychlorinated biphenyls (PCBs), and metals. Soil vapor was analyzed for VOCs. Soil - No VOCs were detected at concentrations exceeding the applicable Restricted-Residential Use Soil Cleanup Objectives (RRSCO) or Protection of Groundwater Soil Cleanup Objectives (PGWSCOs) during the 2018 Remedial Investigation (RI). The PGWSCOs are applicable to those contaminants identified in groundwater. In previous investigations, trichloroethene (TCE) was detected in one shallow soil sample at 8.44 parts per million (ppm), which exceeds the PGWSCO of 0.47 ppm but is lower than the RRSCO value of 21 ppm. Several metals were found, including chromium at a maximum concentration of 1,710 ppm (RRSCO is 180 ppm) and copper at a maximum concentration of 344 ppm (RRSCO is 270 ppm). A remedial excavation was completed by the Volunteer in October 2017, prior to entry into the BCP, to remove a hot spot of chlorinated solvents to depths of 19 feet at the northern portion of the site. Data does not indicate any off-site impacts in soil related to this site. Groundwater - Chlorinated solvents were detected in several wells during the 2018 RI. Cis-1,2-dichloroethene (cis-1,2-DCE) was detected above the Ambient Water Quality Standard (AWQS) of 5 parts per billion (ppb) at a maximum concentration of 13 ppb. TCE was detected at a maximum concentration of 39 ppb, which exceeds the AWQS value of 5 ppb.

168 8TH STREET (Continued) **S121933776**

Naphthalene was detected at a maximum concentration of 26 ppb (AWQS is 10 ppb) in the proximity of the underground storage tank. Chromium was detected at a maximum concentration of 262 ppb (AWQS is 50 ppb) in filtered groundwater samples. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several chlorinated solvent VOCs were detected at elevated concentrations in soil vapor samples during the 2018 RI. Cis-1,2-DCE was detected at a maximum concentration of 350 micrograms per cubic meter (ug/m3) and TCE at a maximum concentration of 12,000 ug/m3. In previous investigations, tetrachloroethene (PCE) was detected at a maximum concentration of 940 ug/m3 and 1,1-dichloroethene (1,1-DCE) at a maximum concentration of 10 ug/m3 in the northern portion of the site. Data indicates additional actions are needed to further evaluate soil vapor intrusion off-site. "

Health Problem: "People who enter the site could contact contaminants in the soil by walking on the soil, digging or otherwise disturbing the soil. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the soil vapor may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. Additional investigation is needed to evaluate the potential for soil vapor intrusion off-site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2017-11-06 08:31:00
Record Upd: 2019-06-11 11:13:00
Updated By: SMQUANDT
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public library - pacific branch
Owner Address: 25 4th avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: deborah lee guterman
Owner Company: NYC School Construction Authority (NYCSCA)
Owner Address: 30-30 Thomson Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: P03

168 8TH STREET (Continued) **S121933776**

Owner Name:	Alexander Lempert
Owner Company:	New York City School Construction Authority
Owner Address:	30-30 Thomson Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library Central Library
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
HW Code:	C224266
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224266
Waste Type:	chromium
Waste Quantity:	UNKNOWN

168 8TH STREET (Continued) **S121933776**

Waste Code:	Not reported
HW Code:	C224266
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

402
NNE
1/4-1/2
0.365 mi.
1927 ft.

126 4TH AVENUE - MISC **NY LTANKS** **S118953804**
126 4TH AVENUE **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
29 ft.

LTANKS:

Name:	126 4TH AVENUE - MISC
Address:	126 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9505523 / 2013-01-17
Facility ID:	9505523
Site ID:	261276
Spill Date:	1995-08-03
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	2004-12-14
SWIS:	2401
Investigator:	VXBREVDO
Referred To:	DELINEATION WORK PLAN 3/16/2009
Reported to Dept:	1995-08-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1995-09-25
Spill Record Last Update:	2013-01-17
Spiller Name:	Not reported
Spiller Company:	CITGO STATION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	433269
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 01/07/04 ALso refer to Spill #04-07082 9/27/04-Reassinged from Rommel to sun. 9/28/04 File Update by Sun: On 9/29/04, Joe Sun conducted a site visit. Sun spoke to Mark Turoff of Environmental System Group (Tel: 917-750-1483) about the site investigation he has

126 4TH AVENUE - MISC (Continued) **S118953804**

recently performed. Per Turoff, his company had installed twelve soil temporary wells on 9/27/04 and had collected soil and groundwater samples from eleven wells except one which contained one foot of free phase product. He will send me the invstigation report after the laboratory report is complete. 10/7/04 Sun received an e-mail from Lauren Gallagher, Project Manager from NYCDEP on 10/7/04 for this Little E Restricted site. She will fax to me a copy of Phase II testing and accompanying HASP which they approved on 9/8/04. 04/08/05-File Update by Sun: The Stipulation Agreement was signed by the owner and executed by the Department on 12/15/04. -On April 6, 2005, DEC received an Investigation Summary Report from owner's consultant, Advanced Site Restoration, LLC. Joe Sun called the owner (Paul Rigas)on 04/08/05, informing him that the Department disapproved the report, since it does not delineate the off-site contamination. A meeting is scheduled for April 19, 2005 at the site between the DEC and the owner to discuss the location of off-site wells. -WJS 04/25/05-File Update by Sun: On 5/25/05, Sun sent a letter to the property owner (George Rigas), informing him that the Department has reviewed and approved the Investigation Summary Report with the incorporation of the following items: 1.Install two (2) two-inch (minimum) off-site monitoring wells in sidewalk east of Butler Street between 3rd Avenue and 4th Avenue in Brooklyn, New York. The monitoring wells should be selected at locations down-gradient of the existing monitoring wells TMW-16 and TMW-17. The new wells will provide the additional off-site delineation of dissolved groundwater contamination plumes. Pursuant to the Stipulation Agreement signed and dated effective December 15, 2004, the Department requires a Remedial Action Plan (RAP) be submitted by June 24, 2005. THe Department requires that the RAP shall detail the work proposed to remediate all contaminated media (groundwater and soil) and provide a detailed descriptions of a vapor mitigation efforts used in the construction of the residence including the installation of vapor barriers and sub-foundation venting systems. (WJS) 06/29/05 File Update by Sun: On 06/29/05, Sun sent a letter to the property owner (George Rigas), informing him that the Department has reviewed and approved the Remedial Action Plan, prepared by Advanced Cleanup Technologies, Inc., with the incorporation of the following items: 1. The OMMP shall describe and tabulate the operation, maintenance and monitoring schedule (frequency) for system equipment and their performance, influent and effluent water sample, system influent and effluent air emission, all monitoring wells and soil vapor monitoring points. EPA Method TO-14A, not TO-02 as stated in Reference 1, shall be used to sample and analyze air stream before and after carbon treatment. 2. Soil Vapor Extraction System (SVES) Data sheet and Air Stripper Data Sheet shall be completed and submitted to the Department by November 15, 2005 for review. The Blank SVES and Air Stripper Data sheets are attached here for your reference. 3.Measurements of groundwater levels in all area are to be conducted monthly for the first three months, and then quarterly. Collection and analysis of groundwater and soil vapor samples shall be conducted monthly for all monitoring wells and soil vapor monitoring points. (Sun) 12/09/05-Sun: Sun received an email from Paul Stewart of ACT, Inc., informing the Department on the current status of the projec: The owner modified development plans for the property to include a full basement with elevator room and underground parking rather than a partial basement with elevator room only. The NYCDEP required modifications to the work plan approved by

126 4TH AVENUE - MISC (Continued) **S118953804**

the NYSDEC to account for the full basement. The modified work plan was approved by the NYCDEP and includes a vapor barrier under the entire property and a more extensive subslab ventilation system. A supplemental soil and ground water investigation is currently being performed and should be completed by Friday. The existing cased wells were surveyed and a flow direction to the west was calculated. The results of the supplemental investigation will be used to size and locate the soil vapor extraction and ground water recovery systems. (Sun) 01/11/06-Sun: Sun sent a letter to the property owner, Paul Bregianos of Arc Electrical and Mechanical, approving the revised Remedial Action Plan prepared by Advanced Cleanup Technologies, Inc. dated 01/04/06, as noted below: Soil Vapor Extraction System (SVES) data sheet and Air Stripper Data Sheet shall be completed and submitted to the Department by March 31, 2006 for review, (2)The owner must notify the Department of site status change from Closed-In Place to Closed-Removed for seven (7) 550-gallon gasoline underground storage tanks (USTs) within 30 days prior to sustantially modifying a facility. (Sun) 03/27/06-Sun received an email from Paul Stewart of ATC on 03/06/06 informing DEC that they are planning to issue to DEC a formal report on the extent of free product and dissolved gasoline in ground water beneath the site. It will also contain a summary of underground storage tank closure activities as requested in DEC's correspondence to the property owner. We should have the report to DEC by the end of this week. (Sun) 03/27/06-Sun sent an email to Paul Stewart of ATC stating that DEC is still waiting to receive a report from ATC on the extent of free product and dissolved gasoline in ground water beneath the siteand a summary of underground storage tank closure activities as requested in DEC's correspondence to the property owner. (Sun) 06/16/06-Sun: Paul Stewart of ACT (Consultant for RP) informed the Department that installation of the recovery well, monitoring wells and vapor monitoring points is complete. The horizontal ventilation screens and piping associated with the vapor extraction wells is also complete. Tomorrow,we will be overseeing installation of the vapor extraction wells. We will also be connecting those wells to piping leading to the location of the treatment system. Next week we will be installing the remaining sections of the 20 mil HDPE liner. The concrete foundation floor will be poured soon after that. Once the first floor parking garage has been completed, we will perform a ground water pump test and a pilot soil vapor extraction test to size a treatment system. Installation of the treatment system will depend upon the construction schedule and access to the alleyway where it will be located. We expect that will take place this fall. (Sun) 09/06/06-Sun: Sun received an email dated 09/04/06 from Paul Stewart of ACT (Consultant for RP)as follows: All wells and subsurface piping have been installed. We are waiting for completion of the first floor so we can install a pilot system and perform a pilot SVE and ground water pump test. I expect that should take place in October . (Sun) 12/13/06-Sun: Sun received an email from Paul Stewart on 10/30/06, stating taht All of the wells and piping for a pump and treat system, vapor extraction system and subslab depssurization system have been installed. He is currently waiting for completion of the first floor of the building so he can install a pilot system and perform a pilot SVE and ground water pump test. He spoke with Paul Bregianos who said the first floor would be completed after the steel was installed which should be this winter. (Sun) 03/23/07-Sun: On 03/23/07 Sun received the following email from Paul Stewart: We completed piping the soil vapor extraction and

126 4TH AVENUE - MISC (Continued) **S118953804**

recovery well conduits to the western portion of the utility room and the concrete floor was installed. We are now awaiting installation of electric service to the utility room in order to perform a pilot SVE and pump test. I will notify you when the pilot tests are scheduled. (Sun) 10/19/07-Sun: On 10/18/07 Sun received the following email from Paul Stewart of ACT for the status of this projec We performed a pilot test of the soil vapor extraction system and a pump test on the recovery well last week and plan to have a pilot test report issued next week. The full scale remedial system should be installed before Thanksgiving . (Sun) 12/18/07-Sun: Sun received the following email from Paul Stewart of ACT, A pump test performed on the recovery well indicated that ground water could not be recovered at a flow rate that could contain the ground water plume. Therefore, we will rely upon two 15 Hp regenerative blowers to remediate soil and ground water in the 6 SVE wells installed beneath the site. A 5.5 Hp regenerative blower for a sub-slab depressurization system is also being installed as a precaution to protect building occupants. The remedial system is being delivered this week and will be installed and put into operation the first week of January, 2008. I will forward a startup report to you and the NYCDEP once the remedial system has been rendered operational. (Sun) 2/25/08-Sun: Sun received the following email from Paul Stewart of ACT, the consultant for the RP, The remedial system has been completely installed and is ready for full scale operation. We are waiting for the owner to provide us with an active telephone line to permit unattended operation. The telephone line should be installed within 10 days at which time the remedial system will be turned on. A Startup Report and an Operation, Maintenance and Monitoring Plan will be forwarded to your attention in approximately 2 weeks. A Closure Report will also be submitted to the NYCDEP with a copy to you. (Sun) 3/12/08-Sun: Sun visited the site to witness the start-up of the remedial system. (Sun) 4/2/08-Sun; Sun received the Remedial System Operation, Maintenance and Monitoring Plan (OMMP) from Paul Stewart of ACT, Inc. (Phone # 631-293-4992). (Sun) 4/11/08: Sun sent the following email to Paul Stewart: Hi, Paul, While I was reviewing the Remedial System OMMP, submitted by you, dated April 1, 2008 for the above referenced site, I found the following documents are missing in the OMMP report: 1. Figure 1: Remedial System Layout 2. Figure 2: Treatment Room Equipment Layout 3. Table 1: Troubleshooting Guidance Table I also noticed that P&ID was not included in the OMMP. The P&ID is a very important document which shows all the equipment, and instrumentation and control. Please revise your OMMP to include P&ID. I have reviewed SVES Data Sheet and found one error on Item #12 (Contaminant). Based on 33 ft of Stack Height and 250 CFM of Air Flow Rate, the Permissible Air Output Concentration for Benzene is 0.02206 LBS/HR, NOT 0.00494 LBS/HR as indicated in your SVES Data Sheet. (Please note that 0.00494 LBS/HR is based on 15 ft of Stack Height). Please address the above comments and resubmit. (Sun) 4/22/08-Sun: Sun reviwed the Remedial System Operation, Maintenance and Monitoring Plan (OMMP), dated 3/31/08, submitted by RP's consultant, Advanced Cleanup Technologies, Inc. (ACT). The Department also reviewed the supplemental documents submitted by ACT on April 16, 2008, including Figure 1 through 3 and Table 1 which were missing in Reference 1 and a revised SVES Data Sheet indicating the correct Permissible Air Output Concentration for Benzene as 0.002206 LBS/HR. The Department approved the OMMP with the condition that a third Pressure gauge & sampling port be installed on inter-connection between two Vapor

126 4TH AVENUE - MISC (Continued) **S118953804**

Carbon Filters. (Sun) 6/24/08-Sun: Sun received the following email from Paul Stewart of ACT, Operation, maintenance and monitoring of the remedial system is being performed on a monthly basis. A quarterly monitoring report will be prepared for submittal in August. (Sun) 8/1/2008 - Project reassigned to Feng. 1/21/2009 - Quarterly Monitoring Report, 4/2008 - 7/2008, 10/3/2008, by ACT. The site is occupied by a ten-story residential apartment building. A remdial program was started 3/12/2008 consisting of an active SVE and treatment system and an active sub-slab depressurization system and treatment system. There are 3 vacuum probes VP-1 to VP-3 for monitoring sub-slab vacuum monthly and Groundwater monitoring wells MW-01 and MW-03 for quarterly monitoring, are located in the cellar floor. Additional monitoring well RW-01 is located in the first floor treatment room. A circuit breaker malfunctioned on the B-200 SVE blower causing it to remain off since 5/30/2008. The two SVE manifolds were joined together. Increased pressure in the B-100 carbon units required the B-100 SVE blower to be shut down unitl the problem could be resolved. Average DTW 11.71 feet. 4 wells were sampled on 4/28/2008. BTEX range 600 ug/L in MW-01 to 9,842 ug/L in MW-02. MTBE range from 23.1 ug/L in MW-01 to 229 ug/L in MW-02. (RJF) 1/26/2009 - Letter to Paul Bregianos (Arc Electrical and Mechanical). DEC requires 1) explanation of the reason why groundwater treatment is missing, 2)surrounding map, 3) delineation work plan for offsite. Investigation work plan include addressing the above comments by 3/16/2009. (RJF) 10/1/2009 - Site Status Report for 2/2009 to 7/2009, dated 9/2/2009, by Advanced Cleanup Technology. On July 16, 2009, a low flow pump test was performed on RW-01. Groundwater recharge is relatively fast. On July 22, 2009, the configuration of the SSD and SVE piping was modified by connecting the casing to RW-01 and the influent piping from the SSD system to the influent piping for SVE Blower B-100. The modified configuration was operated for a few days when high room temp required shut down of the B-100 blower. The ball valves for the SSD piping were re-directed to the 5.5 Hp B-300 blower which was turned on. The B-100 blower was turned off until ambient temp decrease this fall. DTW 13.53' in MW-02 to 14.05' in MW-01. DTW in RW-01 was 22.84'. Groundwater was sampled on 7/22/2009. BTEX range 177 ug/L in MW-01 to 7,200 ug/L in MW-03. MTBE range 15 ug/L in MW-01 to 76 ug/L in MW-03. Will continue monthly system operation, maintenance and monitoring and quarterly groundwater sampling. (RJF) 5/19/2010 - received inquiry regarding the two monitoring wells in front of the 355 Butler Street. The two wells were installed back in 5/2005, sampled once during installation, but no included in the quarterlys. 6/1/2010 - email to Paul Steward (ACT) for information on these two wells, and required site plan with all the wells, their monitoring data and contour map in the next quarterly. 11/4/10. Site Status Report was due in early September 2010. Breen 11/20/10. Sent e-mail to Paul Steward asking for status reports subsequent to 9-2-09. 06/28/2012 - V. Brevdo - Discussed project with Paul Stuart of ATC Environmental via telephone(Phone # 631-293-4992). Sent the following e-mail to Mr. Stuart: June 28, 2012 Dear Mr. Stuart: Thank you for discussing status of the project with me earlier today. It is my understanding that the project has undergone investigation, remediation and is currently in operations, maintenance and monitoring stage with groundwater monitoring ongoing. I also appreciate your thoughts regarding further course of action for the project. It is my understanding that you will be preparing a Project Status Update report and you intend to submit status update report to

126 4TH AVENUE - MISC (Continued) **S118953804**

the Department for review within 30 days . You also agreed to e-mail me a synopsis /briefing describing main highlights of the project and its current status and accomplishments. We agreed that you and I will further evaluate whether current site conditions and remedial progress at this project may advance it into a spill closure status. In evaluation of spill closure potential I would like you to be cognizant of the main criteria which we, in the Division of Environmental Remediation, Region 2 office are looking at when making a spill closure decision. These spill closure criteria are as follows: free product must be removed, grossly contaminated soil with visible staining must be removed, source of contamination must be removed, concentrations of contaminants in soil and groundwater are either at the levels of cleanup guidance values or higher but within acceptable range to DEC, no migration of contaminant off site occurs, remaining contamination is contained, no threat of exposure to vapors from remaining contamination exists, and site poses no further threat to human health and environment. We also use engineering controls such as vapor barriers and SSDS system where necessary. Please note that it is DEC's strong preference that SSDS system remain in operation and be maintained and functioning as an engineering control after spill case is closed . The system must be monitored and maintained in accordance with the procedures set forth in the future Spill Closure Report (when DEC agrees that spill closure is appropriate), including all system equipment such as piping, fans, vacuum gauge and low vacuum visual alarm. Furthermore, the Department strongly recommends the performance of an annual inspection of the system and requires notification of significant operational and maintenance related issues. I look forward to receiving a project synopsis via e-mail as well as Project Status Update report. Please note that I need one hard copy and one electronic PDF copy on CD of all the submissions (except e-mails). Please contact me at 718-482-4928 or via e-mail if you have questions regarding this matter. Respectfully, Vadim Brevdo 01/11/2013 - V. Brevdo Left telephone voice mail to Paul Stuart, requested a return call to discuss project's status. Paul Stuart returned call and said will submit report within a week. V. Brevdo 01/17/2013 - V. Brevdo E-mail from consultant, submitted spill closure request report dated January 17, 2013 with the following e-mail: Vadim, Attached please find an electronic copy of our report for the above-referenced property entitled Request for Spill Closure. Please contact me if you would like a CD or hard copy of our report or if you require further information concerning remedial activities at the subject property. Thank you for your assistance and cooperation in this matter. Regards, Paul P. Stewart, President Advanced Cleanup Technologies, Inc. 960 South Broadway, Suite 100 Hicksville, New York 11801 Phone: (516) 933-0655 x 12 Cell: (516) 840-8197 Fax: (516) 933-0659 Email: pauls@actenvirons.com 01/18/2013 - V. Brevdo Reviewed January 17, 2013 Spill Closure Report and spill closure request. The site consists of a ten-story residential apartment building surrounded by commercial and residential properties. The site was utilized as a gasoline service station from 1963 to 2000 which resulted in impacted soil and ground water beneath the site. Remedial activities have taken place at the site from 2005 through the current date. Petroleum storage facilities and impacted soil were removed from the site during construction of the existing building and below grade parking garage. Residual soil and ground water contamination have been remediated through the installation and operation of a pump and treat

126 4TH AVENUE - MISC (Continued) **S118953804**

system, soil vapor extraction and sub-slab depressurization (SVE/SSD) system that has continually operated from March 2008 to date. Recent ground water quality data indicate that asymptotically low levels of petroleum constituents have been attained in ground water beneath the site. Advanced Cleanup Technologies, environmental engineering consultant for the responsible party, submitted January 17, 2013 remediation report and requested closure of spill case. SSD component of the remedial system will remain in operation as an engineering control to ensure that there is no threat of exposure to vapors from the remaining residual contamination. The Department reviewed remediation report, including analytical data for the site, and concluded that closure of the spill case is appropriate based on the following: 1) Free-phase product has not been identified at the site since underground storage tanks were removed and petroleum impacted soil was excavated during construction of the existing building. 2) All underground storage tanks and petroleum-impacted soil were removed and properly disposed of during site development as indicated in ACT s March 31, 2008 Closure Report. 3) A review of historical ground water quality data demonstrates an asymptotic improvement in water quality beneath the site. 4) Air beneath building remains under negative pressure due to the active SSD system and as a result no migration of vapors from remaining contaminants into the building will occur. 5) Tthe site poses no further threat to human health and the environment. Spill is closed effective January 18, 2013. Spill Closure Letter sent to Paul Stuart of ACT with the following e-mail: January 17, 2013 Dear Mr. Stuart: The Department reviewed Spill Closure Report and request for spill closure dated January 17, 2013. Based on the review of the report, investigative and remedial activities completed to date, analytical data presented in the report, and Conclusions/Recommendations section of the Report, the Department agree that the closure of this spill case is appropriate at this time. Therefore, spill case is closed effective January 17, 2013. Spill closure letter is attached for your file. It is my understanding that the SSD system will remain in operation at the site as an engineering control to prevent possibility of exposure to potential vapors from remaining residual contamination beneath the site. If you have questions regarding this matter, please contact me. Respectfully, Vadim Brevdo "

Remarks: "PRODUCT LINE TEST - REMOTE DISCHARGE LINES LEAK RATE - 3"

All TTF:

Facility ID:	9505523
Spill Number:	9505523
Spill Tank Test:	1544053
Site ID:	261276
Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

126 4TH AVENUE - MISC (Continued) **S118953804**

All Materials:

Site ID:	261276
Operable Unit ID:	1016424
Operable Unit:	01
Material ID:	363517
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

403 **236 8TH ST** **NY LTANKS** **S102233209**
SSW **236 8TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.368 mi.
1945 ft.

Relative: **Higher**

Actual: **41 ft.**

LTANKS:

Name:	236 8TH ST
Address:	236 8TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9508664 / 1995-10-16
Facility ID:	9508664
Site ID:	211107
Spill Date:	1995-10-15
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1995-10-15
CID:	349
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-10-15
Spill Record Last Update:	1995-11-08
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	174990
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

236 8TH ST (Continued) **S102233209**

ZHITOMIRSKY "
Remarks: "TANK LEAK INSIDE BUILDING - DEP OPN SCENE WILL BE CALLING CONTRACTOR FOR CLEAN UP - SPEEDY DRY USED "

All Materials:

Site ID:	211107
Operable Unit ID:	1023012
Operable Unit:	01
Material ID:	359629
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

404 **INTERCONTINENTAL RECY.** **NY SWF/LF** **S101649575**
WSW **??** **N/A**
1/4-1/2 **??, NY 0**
0.371 mi.
1957 ft.

Relative: **Lower**
Actual: **11 ft.**

SWF/LF:

Name:	INTERCONTINENTAL RECY.
Address:	??
City,State,Zip:	??, NY 0
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Intercontinental Recycling Co.
Owner Type:	Private
Owner Address:	141 6th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Email:	Not reported
Owner Phone:	7185964214
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T88]
Active:	No
East Coordinate:	585200
North Coordinate:	4503000
Accuracy Code:	Not reported
Regulatory Status:	None
Waste Type:	Not reported
Authorization #:	2610300075
Authorization Date:	Not reported
Expiration Date:	7/9/1996
Operator Name:	Michael Stramiello
Operator Type:	Not reported

INTERCONTINENTAL RECY. (Continued) **S101649575**

Laste Date: Not reported

405
ENE
1/4-1/2
0.372 mi.
1962 ft.

ECONOMY CLEANERS
123 5TH AVE
BROOKLYN, NY 11217

RCRA-VSQG **1000318363**
NY LTANKS **NYD981085053**
US AIRS
NY MANIFEST

Relative:
Higher

Actual:
44 ft.

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	ECONOMY CLEANERS	
Handler Address:		123 5TH AVE
Handler City,State,Zip:		BROOKLYN, NY 11217
EPA ID:		NYD981085053
Contact Name:		Not reported
Contact Address:		5TH AVE
Contact City,State,Zip:		BROOKLYN, NY 11217
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		5TH AVE
Mailing City,State,Zip:		BROOKLYN, NY 11217
Owner Name:	OWNERNAME	
Owner Type:		Private
Operator Name:	OWNERNAME	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported

ECONOMY CLEANERS (Continued) **1000318363**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported

ECONOMY CLEANERS (Continued) **1000318363**

Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: ECONOMY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ECONOMY CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ECONOMY CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

ECONOMY CLEANERS (Continued) **1000318363**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850715
Handler Name: ECONOMY CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LTANKS:
Name: ECONOMY CLEANERS
Address: 123 5TH AVE
City,State,Zip: BROOKLYN, NY 11217
Spill Number/Closed Date: 0507654 / 2005-11-30
Facility ID: 0507654
Site ID: 353099
Spill Date: 2005-09-26
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2005-09-26
CID: 444
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-09-26
Spill Record Last Update: 2005-11-30
Spiller Name: KYUNG KANG
Spiller Company: ECONOMY CLEANERS
Spiller Address: 123 5TH AVE

ECONOMY CLEANERS (Continued) **1000318363**

Spiller County:	001
Spiller Contact:	KYUNG KANG
Spiller Phone:	(718) 789-2163
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	300392
DEC Memo:	"Sangesland called and left a message with a woman (wife?) - language difficulty 10.13.05 SR// Sharif sent a ttf letter. 11/30/05 Sharif//Milro did the clean up. The concrete floor was not contaminated. They replaced the tank and installed a new one.Waste disposal manifest is included and photographs.NFA required."
Remarks:	"TANK HAS A HOLE IN IT : LEAKING IN BASEMENT; TANK IS ROTTED"

All Materials:

Site ID:	353099
Operable Unit ID:	1110569
Operable Unit:	01
Material ID:	2100603
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

US AIRS MINOR:

Envid:	1000318363
Region Code:	02
Programmatic ID:	AIR NY0000002610300220
Facility Registry ID:	110004397126
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610300220
Facility Registry ID:	110004397126
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2000-12-13 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610300220
Facility Registry ID:	110004397126
Air Operating Status Code:	OPR

ECONOMY CLEANERS (Continued) **1000318363**

Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-12-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610300220
Facility Registry ID: 110004397126
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610300220
Facility Registry ID: 110004397126
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-12-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NY MANIFEST:
Name: ECONOMY CLNRS
Address: 123 5TH AVE
City,State,Zip: BROOKLYN, NY 11217
Country: USA
EPA ID: NYD981085053
Facility Status: Not reported
Location Address 1: 123 FIFTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD981085053
Mailing Name: ECONOMY CLNRS
Mailing Contact: ECONOMY CLNRS
Mailing Address 1: 123 FIFTH AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY

ECONOMY CLEANERS (Continued) **1000318363**

Mailing Zip: 11217
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187835386

BB406 **233 NEVINS STREET PHASE II** **NY VCP** **S125316935**
North **233 NEVINS STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.375 mi.
1978 ft. **Site 1 of 3 in cluster BB**

Relative:
Lower

Actual:
12 ft.

VCP NYC:

Project ID:	19TMP1548K,19CVCP066K,22EH-N271K
Name:	233 NEVINS STREET PHASE II
Address:	233 NEVINS STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3004120006
OER Program:	VCP (Enrolled)
Phase:	Closure
Latitude:	40.681345
Longitude:	-73.985863
Postcode:	6
Community Board:	33
Council District:	127
Census Tract:	3006603
BIN:	3004120006
NTA:	DUMBO-Vinegar Hill-Downtown Brooklyn-Boerum Hill

---

407 **SPILL NUMBER 9804333** **NY LTANKS** **S100782331**
ESE **705 CARROLL STREET** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.380 mi.
2004 ft.

Relative:
Higher

Actual:
86 ft.

LTANKS:

Name:	705 CARROLL STREET
Address:	705 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9311807 / 1994-01-05
Facility ID:	9311807
Site ID:	213345
Spill Date:	1994-01-05
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	B3
Cleanup Ceased:	1994-01-05
SWIS:	2401
Investigator:	SJMILLER
Referred To:	Not reported
Reported to Dept:	1994-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

SPILL NUMBER 9804333 (Continued) **S100782331**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-07
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	MS. NELLIE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	176754
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 10/10/95: This is additional information about material spilled from the translation of the old spill file: 3'' OF OIL."
Remarks:	"FUEL CO. DELIVERED OIL - TANK RUPTURED - CAN'T REACH LANDLORD - WANTS CALL BACK ASAP - WENT TO SITE. NO PBLM, NO CONFIRMATION MEET W/ MRS DONELLE CONFIR, NO EVIDENCE OF SPILL FROM OUT SIDE BY FILLER V"

All Materials:

Site ID:	213345
Operable Unit ID:	993813
Operable Unit:	01
Material ID:	390822
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	400.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SPILL NUMBER 9804333
Address:	705 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9804333 / 1998-07-07
Facility ID:	9804333
Facility Type:	ER
DER Facility ID:	176754
Site ID:	213346
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-07-07
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1998-07-07
CID:	266
Water Affected:	Not reported
Spill Source:	Tank Truck

SPILL NUMBER 9804333 (Continued) **S100782331**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-07
Spill Record Last Update:	1998-07-08
Spiller Name:	PETE LEPORE
Spiller Company:	WHALECO
Spiller Address:	55-60 58TH STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"DRIVER PARKED TRUCK, ENGAGED PTO, AND FOUND NOZZLE OPEN WHEN HE WENT TO BACK OF TRUCK. MAY HAVE OPENED FROM VEHICLE VIBRATION. ONTO PAVEMENT. CLEANED UP."

All Materials:

Site ID:	213346
Operable Unit ID:	1065209
Operable Unit:	01
Material ID:	319055
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	8.00
Oxygenate:	Not reported

408
NNE
1/4-1/2
0.385 mi.
2031 ft.

UNDERGROUND TANK **NY LTANKS** **S109829733**
151-169 3RD AVE **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
21 ft.

LTANKS:

Name:	UNDERGROUND TANK
Address:	151-169 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1402248 / 2014-07-09
Facility ID:	1402248
Site ID:	495561
Spill Date:	2014-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2014-06-02
CID:	Not reported

UNDERGROUND TANK (Continued) **S109829733**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-06-02
Spill Record Last Update:	2014-07-09
Spiller Name:	JOE MACCHIA
Spiller Company:	ASTI HOLDING CORP
Spiller Address:	151-169 3RD AVE
Spiller County:	999
Spiller Contact:	SHAWN SCKEAN
Spiller Phone:	(610) 278-7203
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	364188
DEC Memo:	"6/2/14 TJD Teleconfence with tank owner (Mr. Joseph Macchia) - he states tank has failed tighness test which vent piping is suspected cause. Original failing tighness test report was requested, Mr. Macchia states test report is not yet available. Cromco is scheduled to return to site on 6/3/14 to perform a helium isolation test. TTF letter has been prepared and sent via US Mail to correspondence address listed on PBS Facility Information Report. In addition leter has been e-mailed to Mr. Macchia at jmacchiamdi@aol.com. TTF letter could not be uploaded to DECDOCS as the file is not currently available. PM (Piper) has been provided an electronic copy of corespondence and will upload to DECDOCS when file location becomes available. Helium pinpoint service performed on failed Regular unleaded tank system. Through this pinpointing, crew Identified the leak source to be on the vent line back at vent stack. Alvin Petroleum was on site and made immediate repairs followed up by testing by Crornpco. System passed testing. Spill closed. Results and repair documentation in dec docs."
Remarks:	"Reporting tank test failure."

All Materials:

Site ID:	495561
Operable Unit ID:	1245064
Operable Unit:	01
Material ID:	2245969
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	MAXIMUM DISTRIBUTORS- TTF
Address:	151-169 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0902974 / 2009-08-18
Facility ID:	0902974
Site ID:	415051

UNDERGROUND TANK (Continued) **S109829733**

Spill Date:	2009-06-12
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2009-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-12
Spill Record Last Update:	2009-08-18
Spiller Name:	Not reported
Spiller Company:	MAXIMUM DISTRIBUTORS
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DENNIS WOOD
Spiller Phone:	(615) 372-6010
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	364188
DEC Memo:	"Telephone request to Dennis Wood of Titan Management - Asking for status update. Man way gasket needs to be replaced - Has this work been done? Was there any contamination? 8/4/2009 e-mail from Amanda Sisel at Titan Management (615.372.6006 office) 1006 Flagpole Ct, Suite 104, Brentwood, TN 37027 I wanted to let you know that I am working on getting the information you requested for the failed tank test at 169 Third Ave. Joe Macchia is on vacation until tomorrow and I am hoping to get the information from him and get this resolved upon his return to the office. 8/5/2009 TTF sent to: Mr. Dennis Wood Titan Management 1006 Flagpole Ct, Suite 104 Brentwood, TN 37027 8/10/2009 e-mail from Amanda Sisel at Titan says: Manway gasket repaired - no contamination found - passed new tank test Copy of June 2009 passing tank test attached in eDocs"
Remarks:	"1525 The caller advised dispatch there is no clean up necessary. A man way gasket needs to be replaced."

All Materials:

Site ID:	415051
Operable Unit ID:	1171412
Operable Unit:	01
Material ID:	2163214
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BC409 **PATTERSON CHEMICAL CO INC** **CORRACTS** **1000403436**
WNW **102 3RD ST** **RCRA NonGen / NLR** **NYD980592471**
1/4-1/2 **BROOKLYN, NY 11231** **FINDS**
0.394 mi. **ECHO**
2079 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
17 ft.

CORRACTS:

Name:	PATTERSON CHEMICAL CO INC
Address:	102 3RD ST
Address 2:	Not reported
EPA ID:	NYD980592471
Area Name:	SITEWIDE
Corrective Action:	RFA INITIATION
Actual Date:	19931119
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

Name:	PATTERSON CHEMICAL CO INC
Address:	102 3RD ST
Address 2:	Not reported
EPA ID:	NYD980592471
Area Name:	SITEWIDE
Corrective Action:	RFA COMPLETED
Actual Date:	19940920
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

Name:	PATTERSON CHEMICAL CO INC
Address:	102 3RD ST
Address 2:	Not reported
EPA ID:	NYD980592471
Area Name:	SITEWIDE
Corrective Action:	CA PRIORITIZATION-LOW CA PRIORITY
Actual Date:	19940527
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	PATTERSON CHEMICAL CO INC
Handler Address:	102 3RD ST
Handler City,State,Zip:	BROOKLYN, NY 11231
EPA ID:	NYD980592471
Contact Name:	MOE STONE
Contact Address:	3RD ST
Contact City,State,Zip:	BROOKLYN, NY 11231
Contact Telephone:	718-855-7676
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		3RD ST
Mailing City,State,Zip:		BROOKLYN, NY 11231
Owner Name:	ACE TERMINALS	
Owner Type:		Private
Operator Name:	PATTERSON CHEMICAL CO INC	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Storage
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Storage
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		Yes
Corrective Action Priority Ranking:		Low
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste Code: F007
Waste Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Waste Code: F008
Waste Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F009
Waste Description: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F010
Waste Description: QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F012
Waste Description: QUENCHING WASTEWATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F017
Waste Description: Not Defined

Waste Code: F018
Waste Description: Not Defined

Waste Code: K086
Waste Description: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

Waste Code: P030
Waste Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste Code: U101
Waste Description: 2,4-DIMETHYLPHENOL (OR) PHENOL, 2,4-DIMETHYL-

Handler - Owner Operator:
Owner/Operator Indicator: Owner

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Owner/Operator Name: ACE TERMINALS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 102 3RD ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11231
Owner/Operator Telephone: 212-855-7676
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PATTERSON CHEMICAL CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 102 THIRD STREET
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 212-855-7676
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ACE TERMINALS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 102 3RD ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11231
Owner/Operator Telephone: 212-855-7676
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PATTERSON CHEMICAL CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 102 THIRD STREET
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 212-855-7676
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19801119
Handler Name: PATTERSON CHEMICAL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19791231
Handler Name: PATTERSON CHEMICAL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: PATTERSON CHEMICAL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PATTERSON CHEMICAL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800725
Handler Name: PATTERSON CHEMICAL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

List of NAICS Codes and Descriptions:
NAICS Code: 48411
NAICS Description: GENERAL FREIGHT TRUCKING, LOCAL

NAICS Code: 49311
NAICS Description: GENERAL WAREHOUSING AND STORAGE

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19860722
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19860610
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850513
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850322
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19840726
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19860326
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

PATTERSON CHEMICAL CO INC (Continued) **1000403436**

FINDS:
Registry ID: 110004387814

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000403436
Registry ID:	110004387814
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004387814
Name:	PATTERSON CHEMICAL CO INC
Address:	102 3RD ST
City,State,Zip:	BROOKLYN, NY 11231

BD410 **210 DOUGLASS STREET** **NY BROWNFIELDS** **S127478129**
NNW **210 DOUGLASS STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.399 mi.
2105 ft. **Site 1 of 3 in cluster BD**

Relative: **Lower**

Actual: **2 ft.**

BROWNFIELDS:

Name:	210 DOUGLASS STREET
Address:	210 DOUGLASS STREET
City,State,Zip:	BROOKLYN, NY 11217
Program:	BCP
Site Code:	615221
Acres:	0.570
HW Code:	C224316
SWIS:	2401
Town:	New York City
Record Added Date:	12/23/2020
Record Updated Date:	03/21/2022
Update By:	HMDUDEK
Site Description:	"Location The approximate 24,850-square-foot (0.57 acres) proposed brownfield site is located at 210 Douglass Street in the Gowanus neighborhood of Brooklyn, New York, and is identified as Block 417 and Lot 21on the New York City Tax Map. The site is bound to the north by one-story commercial building followed by a three-story residential building, and the New York City Department of Environmental Protection (NYCDEP) Gowanus Pumping Station and Flushing Tunnel facility, to the east by the Gowanus Canal, a USEPA Superfund Site, to the south by Degraw Street followed by an asphalt-paved parking lot and associated garage, and to the west by 2 one- to two-story commercial/industrial buildings followed by Bond Street and 2 two- to three-story residential buildings, a two-story mixed used residential and commercial building, and 2 two-story industrial and manufacturing buildings. The site is located in a Manufacturing District (M2-1) which allows for industrial businesses.

210 DOUGLASS STREET (Continued) **S127478129**

The Site is currently designated for factory/industrial use (F1) by the New York City Department of Finance. Site Features The site is located in an urban area that is generally covered with roads, walkways, an asphalt-paved parking lot, and a commercial building. The Gowanus Canal, a USEPA Superfund site, is located adjacent to the east of the subject property. The site is currently occupied by an approximate 17,850-square foot single story movie studio and associated asphalt paved parking operated by Eastern Effects, Inc., a movie production company. Current Zoning and Land Use The proposed brownfield site is located in a M2-1 manufacturing district which allows for industrial businesses. No environmental restrictions are currently associated with the property. The adjoining parcels and surrounding area are of mixed use including residential, commercial, industrial/manufacturing, and parking lots. On 30 January 2019, the Department of City Planning released the draft Gowanus zoning proposal for the greater Gowanus Canal neighborhood of Brooklyn. According to the information provided in this release, the site is located in an area that would receive a new zoning designation of M1(3) / R7-2 which is identified as being within the Canal Corridor Sub-District. This rezoning action would allow for the redevelopment of the site with a mixed-use commercial/residential building(s) within the framework of that designation. The Gowanus Canal, a USEPA Superfund site, is located adjacent to the east of the subject property. Historical Site Use Historical Sanborn Map Review: Sanborn Fire Insurance Maps provided by Environmental Data Resources, LLC (EDR) reveal that the subject property operated as a P.G. Hughes lime, brick, and lath yard as well as W.H. Murtha & Sons coal and wood yard with a coal pocket storage facility and an engine building located in the southeastern portion of the Site in 1886. The 1904 map shows coal pockets and coal sheds associated with the John H. O Rourke Coal Yard. By 1915, the John H. O Rourke Coal Yard was identified as the John E. Larney Coal Yard. Limited detail is provided between 1922 and 1928, although the Knickerbocker Ice Company is shown on the northeastern portion of the property. By 1938, coal silos were identified on the eastern portion of the subject property associated with coal yard operations and two large coal silos are shown on the northern portion of the subject property with a conveyor connected to the engine room. Site conditions appear generally the same between 1938 and 1950, except the coal yard is listed as non-operating. By 1969, the non-operating coal yard facility was replaced by a plastic product manufacturing facility. Site conditions and operations appear generally the same between 1969 and 2007, except by the year 1988, the plastic manufacturer is identified as an unspecified manufacturing facility. The review of Sanborn Maps revealed historic site operations of concern at adjacent properties to the north, south, and west, including a coal yard (1886), a paper box factory (1915), a machine shop (1950), and a metal manufacturer (1969 2007) to the north; a coal yard (1886- 1915, 1938), a fuel company (1928), a wooden box manufacturer (1950), an auto repair shop (1969), and a truck rental company (1979-2007) to the south; and a coal yard (1886), lather (1886), ice factory (1904-1950), unspecified manufacturing (1969-2007), and an electrical manufacturer (1938-2007) to the west. Records maintained online by the NYC Department of Buildings (NYCDOB) and USEPA, in addition to historical phone directories summarized in the City Directory Abstract and government databases summarized in a Radius Map Report provided by EDR, were also reviewed for the Site and are summarized

210 DOUGLASS STREET (Continued) **S127478129**

below. Additional Historical Resources: Records maintained online by the NYCDOB identify the subject property as approved to operate as a paper product manufacturer in 1970 and an electrical supply manufacturing facility from 1993 to 2009. According to the City Directory Abstract, a production studio operated on the subject property from 2002 to 2014. Magnifco Enterprise located at 210 Douglass Street was identified in the Radius Map Report within the RCRA Small Quantity Generator (SQG) database for forms received by the USEPA on 14 November 2013 classifying the site as a SQG for the generation of waste impacted by hazardous concentrations of benzene by Eastern Effects operations. The site was also identified in the USEPA ECHO and Facility Index System (FINDS) databases for being tracked through the RCRA program as FRS ID 110056380045 and RCRA Source ID NYR000205278. No violations were identified for this facility. Site operations by Eastern Effects between 2002 and the present were confirmed within the City Directory Abstract Report and based on site observations during the investigation. Additional listings maintained in the online NYSDEC Spills database identify the Site as Unknown Fuel Oil Depot at the address 210 Douglas Street under Spill No. 0401107 for a release of unknown petroleum to the Gowanus Canal on 1 May 2004. The spill was administratively closed on 3 May 2004 as it was determined that no spill occurred and no corrective action was required. Site Geology and Hydrogeology According to Langan s 2019 Phase II investigation performed on Lot 21 as well as the adjacent Lot 10, miscellaneous fill was encountered between 2- and 10-feet below grade at all boring locations, with the exception of a soil boring located at the southwestern portion of the subject property where a fill layer was not observed. Material beneath the fill layer generally consisted of sand, silt, and/or clay, with the exception of a soil boring along eastern portion of the subject property where only fill was observed. A confining layer of clay and/or peat was identified at all locations except a boring location along the eastern site boundary, due to shallow drilling refusal, and a boring located along the western boundary of Lot 21. Site conditions encountered in Langan s 2019 Phase II environmental investigation are generally consistent with the Langan s 2019 geotechnical investigation. According to the USGS Bedrock and Engineering Geologic Maps of New York County and Parts of Kings and Queens Counties, New York, and parts of Bergen and Hudson Counties, New Jersey, by Charles A. Baskerville dated 1994, the site is underlain by the Hartland Formation, consisting mainly of gray muscovite-biotite-quartz schist. Competent bedrock was not encountered in soil borings installed as part of the 2019 Phase II investigation. Based on the environmental investigation conducted by Langan, groundwater was encountered at depths ranging from about 4.69 to 6.21 feet below ground surface (bgs) in monitoring wells installed during Langan s 2019 environmental investigation on the subject property. Based on area topography, observed water level measurements, and the proximity of the Site to the Gowanus Canal, groundwater is inferred to flow to the east towards the Gowanus Canal. "

Env Problem: "Nature and Extent of Contamination: The site entered the BCP in the investigation phase. To date, the following nature and extent of contamination is known: Soil: In 2012 GEI Consultants Inc. installed a soil boring on-site as part of the Fulton Manufactured Gas Plant (MGP) Remedial Investigation. In 2019, Langan performed a Phase II Environmental Investigation on-site. Together a total of six (6) soil

210 DOUGLASS STREET (Continued) **S127478129**

borings were installed across the site. Volatile Organic Compounds (VOCs), Semi-Volatile Organic Compounds (SVOCs), Metals, PCBs, and Pesticides were analyzed from those samples and exceedances were found. Most notable exceedances included Coal Tar related SVOC compounds: Benzo(a)pyrene was detected at a maximum concentration of 470 ppm (CSCO: 1 ppm and PoGWSCO: 22 ppm). Benzo(b)fluoranthene was detected at a maximum concentration of 330 ppm (CSCO: 5.6 ppm and PoGWSCO: 1.7 ppm). Naphthalene was detected at a maximum concentration of 7,900 ppm (CSCO: 500ppm and PoGWSCO: 12 ppm). Metals were also found in exceedance. Most notably: Lead was detected at a maximum concentration of 1,000 ppm (CSCO: 1,000 ppm and PoGWSCO: 63 ppm). Mercury was detected at a maximum concentration of 4.65 ppm (CSCO: 2.8 ppm and PoGWSCO: 0.18 ppm). Groundwater: Three (3) groundwater sampling locations were sampled during the remedial investigation. Volatile Organic Compounds (VOCs), Semi-Volatile Organic Compounds (SVOCs), Metals, PCBs, and Pesticides were analyzed from those samples and exceedances were found. Coal Tar related SVOCs were detected in the groundwater in addition to high levels of Iron, Manganese and Lead were also detected in the groundwater on-site. Soil Vapor: The site currently maintains a movie studio with parking lot. In 2013, three sub-slab vapor samples were collected throughout the on-site building. Tetrachloroethene (PCE) was detected at a maximum concentration of 91.6 micrograms per cubic meter (ug/m3). Trichloroethene (TCE) was detected a maximum concentration of 9,136 ug/m3. "

Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-04-13 09:50:00
Record Upd:	2021-04-13 09:50:00
Updated By:	GWBURKE
Own Op:	6
Sub Type:	P02
Owner Name:	Lauren Sanders
Owner Company:	DoBoDe Holdings LLC
Owner Address:	430 Park Avenue, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Lauren Sanders
Owner Company:	Eastern Effects
Owner Address:	210 Douglass Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	Document Repository

210 DOUGLASS STREET (Continued) **S127478129**

Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Carroll Gardens Branch
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Lauren Sanders
Owner Company:	Eponymous Gowanus LLC
Owner Address:	430 Park Avenue, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Lauren Sanders
Owner Company:	3911 Lemmon Avenue Associates
Owner Address:	430 Park Avenue, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201-6401
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Lauren Sanders
Owner Company:	GowDev Holdings LLC
Owner Address:	430 Park Avenue, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Lauren Sanders
Owner Company:	Esbond Realty, LLC
Owner Address:	430 Park Avenue, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BC411 **99 NORTH 4TH STREET** **NY VCP** **S125317258**
WNW **99 4TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.399 mi.
2106 ft. **Site 2 of 2 in cluster BC**

Relative: **Lower**
Actual: **13 ft.**

VCP NYC:

Project ID:	17TMP0113K,17EHAZ084K,17CVCP050K
Name:	99 NORTH 4TH STREET
Address:	99 4TH STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3023420026
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.676608
Longitude:	-73.992891
Postcode:	6
Community Board:	39
Council District:	77
Census Tract:	3008008
BIN:	3004650047
NTA:	Carroll Gardens-Columbia Street-Red Hook

BD412 **FORMER O.Z. ELECTRICAL** **NY SHWS** **S108057803**
NNW **198 DOUGLASS STREET** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.405 mi.
2136 ft. **Site 2 of 3 in cluster BD**

Relative: **Lower**
Actual: **7 ft.**

SHWS:

Name:	FORMER O.Z. ELECTRICAL
Address:	198 DOUGLASS STREET
City,State,Zip:	BROOKLYN, NY 11217
Program:	HW
Site Code:	450318
Classification:	N
Region:	2
Acres:	0.170
HW Code:	224152
Record Add:	06/10/2011
Record Upd:	08/24/2012
Updated By:	DPKAPLAN

Site Description: "LOCATION: The Site is located at 198 Douglass Street in Brooklyn, between Bond Street and the Gowanus Canal. SITE FEATURES: The property is 0.18 acres and features a one-story warehouse building which is currently used for the storage of art and antique goods and furniture. CURRENT USE/ZONING: The property is currently used for the storage of antique goods. It is zoned for manufacturing use. HISTORICAL USES: The Site has historically been used for a variety of industrial purposes. Prior to its current use, the Site was owned and operated by Paramount Plumbing (approx. 1995 to 1998) and O.Z. Electrical Manufacturing Company Inc. (approx. 1960 to 1995). O.Z. also formerly owned and operated on the adjacent property (196 Douglass) as well as three buildings to the west, across Bond Street (262 Bond Street). Earlier owners/operators include P.H. Hughes Lime, Brick and Lath Yard (approx. 1887 to 1900); a gravel/crushed stone yard (approx. 1900 to 1930); and the Knickerbockers Ice Company, which included a machine shop (1930?s). SITE GEOLOGY AND HYDROGEOLOGY: Fill material consisting of sand, silt, gravel, and

FORMER O.Z. ELECTRICAL (Continued) **S108057803**

construction/demolition debris has been encountered to approximately 10 feet below ground surface (fbgs). Beneath the fill material (10 to 36 fbgs) is a sequence of inter-bedded silt, clay, sand, and peat layers atop fine to coarse-grained sand to a depth of approximately 48 fbgs. Groundwater has been encountered at depths ranging from 1.5 fbgs to 9 fbgs, during various investigations. USEPA Superfund investigations in the area of the Gowanus Canal have found that shallow groundwater flows toward the canal at both low and high tide. Intermediate groundwater generally flows upward toward the canal. Based on water chemistry measurements in surface water and groundwater (collected during Superfund investigations of the Gowanus Canal), it was concluded that infiltration from the canal controls water quality in shallow wells adjacent to the canal, with decreasing influence with distance from the canal. The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. "

Env Problem: "NATURE AND EXTENT OF CONTAMINATION: A Site Investigation performed in April/May 2012 confirmed that tetrachloroethene (PCE) previously detected in groundwater was limited and not indicative of a release of hazardous waste. GROUNDWATER: In 2006, PCE was detected in groundwater at a concentration of 1,600 parts per billion (ppb) and benzene at 14 ppb, from one grab groundwater sample collected from one boring. In the 2012 Site Investigation, groundwater was sampled from four groundwater monitoring wells. Groundwater samples were analyzed for volatile organic compounds (VOCs). Several VOCs were detected; however, the only contaminants detected at concentrations that exceed standards were isopropylbenzene (detected at 5.1 ppb compared to the standard of 5.0 ppb) and methyl tertiary butyl ether (MTBE) (detected at 10.7 ppb compared to the standard of 10 ppb). The standards cited for groundwater are the NYS Ambient Water Quality Standards and Guidance Values for Water Class GA from NYSDEC Technical & Operational Guidance Series (TOGS) 1.1.1. SOIL: The 2012 Site Investigation included soil sampling from 7 soil borings and analysis for VOCs. The only contaminant detected above standards was isopropylbenzene, detected at 3.91 parts per million (ppm) compared to the CP-51 Supplemental Soil Cleanup Objective for protection of groundwater of 2.3 ppm. A few VOCs were detected on site in the 2006 soil boring, but at very low concentrations. SOIL VAPOR: In soil vapor, trichloroethene (TCE) was detected in two samples at a maximum concentration of 200 micrograms per cubic meter (ug/m3); however TCE was not detected above reporting limits in concurrent indoor air samples. The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. "

Health Problem: ""
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 4
Sub Type: 03

FORMER O.Z. ELECTRICAL (Continued) **S108057803**

Owner Name:	Jean Lignel
Owner Company:	Not reported
Owner Address:	332 Bleecker St., Apt. 10
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014-2980
Owner Country:	United States of America
Own Op:	1
Sub Type:	05
Owner Name:	Stephen D. Kramer, Esq. c/o Phillips Nizer, LLP
Owner Company:	Matthews Investments Limited
Owner Address:	666 Fifth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10103-0084
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	FORMER O.Z. ELECTRIC & MANUFACTURING COMPANY
Address:	198 DOUGLASS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0603334 / 2021-03-30
Facility ID:	0603334
Facility Type:	ER
DER Facility ID:	316117
Site ID:	366030
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	2401
Spill Date:	2006-06-02
Investigator:	DPKAPLAN
Referred To:	Not reported
Reported to Dept:	2006-06-26
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-26
Spill Record Last Update:	2021-03-30
Spiller Name:	JEFFERY FLANNIGAN
Spiller Company:	Not reported
Spiller Address:	Not reported

FORMER O.Z. ELECTRICAL (Continued) **S108057803**

Spiller Company: 999
Contact Name: JEFFERY FLANNIGAN
DEC Memo: "DEC Piper contacted Caller Jeff Flannigan. He will copy report and analytical and send to DEC. 9/8/06- DEC Piper reviewed subsurface investigation report. AS per report, investigaestigation was due to the presence of petroleum vaprs inside work area. 1 boring was completed. Groundwater was encountrered at 9 feet bgs. A water sample was collected at 34 feet which contained elevated levels of benzene, PCE and a variety of SVOCs were above standards. A soil sample was collected at 36 feet bgs which indicated trace levels of clorinated solvents. Indoor air samples revesaled elevated levels of petroleum and clorinated solvents were detected above standards. Due to the soil and gw samples not being collected at the gw interface, the concentrations observed where collected, and indoor air quality, additional investigation is warranted. Case referred to remediation. 9/20/06- DEC Piper . Spill transpferred to remediation as per Austin on 9/8/06. 11/13/06 - reviewed site assessment report, found PERC in GW. Need to contact consultant to get more delineation of the GW contamination. - KST 4/11/08 - This spill has been transferred to D. Kaplan. Since previous reports were missing the representative of the site was contacted and the subsurface investigation report was obtained from the environmental consultant. 5/7/08 - Met the environmental consultant (Djamel Lekmine, AMEC), architect Jeff Flannigan who was acting as representative of the owner (was in charge of construction at the time the spill was reported), and attorney for the owner at the site. The entire lot is covered with a building with slab on grade finished floor. The building serves as a storage facility for fine art. It was explained that additional investigation was necessary. 5/19/08 - Environmental consultant sent a proposed work plan for additional investigation which was very incomplete (see edocs). 5/27/08 - A letter was sent to the environmental consultant describing additional requirements for a subsurface investigation. 8/26/08 - Attorney for the owner has been trying to work out a site access agreement with the owner of the adjacent property (196 Douglass St). Representative for the owner of 196 indicated that they are unwilling to grant site access. 9/26/08 - After negotiations with the owner of 196 Douglass for site access proved unsuccessful, DEC attorney (John Urda) sent a letter to the owner siting statutory authority for site access for investigation work. See edocs. 5/11/09- The work was performed February 10th and 11th. The report has not yet been received. 6/18/10-Vought-Received inquiry from DEC Austin as to whether Site should be transferred to Vought as P-Site . Vought discussed with DEC O'Connell and spill reassigned from Kaplan to Vought and entered into P-Site Tracking Spreadsheet. 2/8/11-Vought-Spill transferred from DEC Vought to DEC Kaplan for further action. 6/10/11 - Transferred to hazardous waste program as potential hazardous waste site (P site 224152) 3/30/21 - closed - cross-reference site no 224152. (JHO)"
Remarks: "THERE WAS SOIL SAMPLE TESTING AND GROUND WATER TESTING. THERE WAS DIFFENENT MATERIAL THAT WAS FOUND AT THE SITE. THERE ARE TRACES OF VOLITALE ORGANIC COMPOUND, TETRACHLOROETHENE,ETHYLBENZENE, XYLENE WAS FOUND IN SOIL SAMPLE. THE WATER SAMPLE HAD BENZINE, TETRACHLOROETHENE. THEY WERE DIGGING AT THIS SITE."

All Materials:
Site ID: 366030
Operable Unit ID: 1123996
Operable Unit: 01

FORMER O.Z. ELECTRICAL (Continued) **S108057803**

Material ID:	2113473
Material Code:	0854A
Material Name:	benzene
Case No.:	00071432
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	366030
Operable Unit ID:	1123996
Operable Unit:	01
Material ID:	2184492
Material Code:	0040B
Material Name:	PCE
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BB413 **233 NEVINS STREET** **NY VCP** **S125316936**
North **236 BUTLER STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.406 mi.
2143 ft. **Site 2 of 3 in cluster BB**

Relative: **Lower**
Actual: **9 ft.**

VCP NYC:

Project ID:	18TMP0853K,19CVCP007K,22EH-N270K
Name:	233 NEVINS STREET
Address:	236 BUTLER STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0041200063004099E+19
OER Program:	VCP (Enrolled)
Phase:	Closure
Latitude:	40.681521
Longitude:	-73.985383
Postcode:	6
Community Board:	33
Council District:	127
Census Tract:	3006603
BIN:	3004120006
NTA:	DUMBO-Vinegar Hill-Downtown Brooklyn-Boerum Hill

414
North
1/4-1/2
0.406 mi.
2144 ft.

BALTIC RECYCLING CORP.
524-26 BALTIC STREET
BROOKLYN, NY 11217

NY SWF/LF **S105841705**
N/A

Relative:
Lower

Actual:
17 ft.

SWF/LF:

Name:	BALTIC RECYCLING CORP.
Address:	524-26 BALTIC STREET
City,State,Zip:	BROOKLYN, NY 11217
Flag:	INACTIVE
Region Code:	2
Phone Number:	7186242459
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	PAUL RUTIGLIANO; PRESIDENT
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T97]
Active:	No
East Coordinate:	585825
North Coordinate:	4503935
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6103-00063
Authorization Date:	3/19/1997
Expiration Date:	3/19/2002
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

BB415
North
1/4-1/2
0.408 mi.
2152 ft.

234 BUTLER STREET
234 BUTLER STREET
BROOKLYN, NY 11217

Site 3 of 3 in cluster BB

NY BROWNFIELDS **S121102082**
N/A

Relative:
Lower

Actual:
9 ft.

BROWNFIELDS:

Name:	234 BUTLER STREET
Address:	234 BUTLER STREET
City,State,Zip:	BROOKLYN, NY 11217
Program:	BCP
Site Code:	550328
Acres:	1.190
HW Code:	C224261
SWIS:	2401
Town:	New York City
Record Added Date:	06/05/2017
Record Updated Date:	03/06/2020
Update By:	DJEATON

234 BUTLER STREET (Continued) **S121102082**

Site Description:

"BCP Denial letter sent on 9/19/17. Location The site is located at 234 Butler Street in the Gowanus neighborhood of Brooklyn, New York (Kings County) and is denoted on the New York City Tax Map as Block 411, Lot 24. Alternative addresses for the site include 226 Nevins Street and 228 240 Nevins Street. The site is located in an urban environment. Site Features The site occupies an area of about 52,000 square feet and consists of a two-story, brick and concrete masonry commercial building and adjoining one-story warehouse building along Butler Street, a brick and concrete masonry maintenance building containing eight contiguous vehicle garages along Nevins Street, and an exterior, concrete-paved parking and storage lot for sanitation trucks. According to a 1956 USGS Brooklyn N.Y Quadrangle 7.5-minute Series Topographic Map, the site sits at an elevation of about 12 feet above mean sea level (msl). The topography of the site is generally flat, and the surrounding area slopes to the west towards the Gowanus Canal, which adjoins the site to the southwest. The site is located on the northeastern portion of the city block bound by Butler Street to the north; Nevins Street to the east; Block 418, Lot 1, followed by DeGraw Street to the south; and Block 411, Lot 14 and the Gowanus Canal, followed by Bond Street to the west. Current Zoning and Land Use According to the New York City Planning Commission Zoning Map 16c, the site is located within a M2-1 manufacturing district. M2 districts occupy the middle ground between light and heavy industrial areas. The district has a maximum floor area ratio (FAR) of 2.0. The Department of City Planning is in the process of rezoning the Gowanus neighborhood to allow for more residential development; therefore, a mixed-use commercial and residential project is anticipated to be built at the site. The project will be consistent with the goals of the City Council as embodied in the NYC zoning districts. The New York City Department of Finance classifies the site buildings as G-1 garage/gas station . The site has been owned by 226 Nevins Street Corp. since 1978. Past Use of the Site The following historical site usage may have led to site contamination: ? -City pipe yard (1904); ? -NYC water supply, gas and electricity department repair companies (1945 to 1949); ? -McNally Trucking Corp. (1969); ? -Truck and automotive maintenance Inc. (1976); ? -Sanitation Repairs (1976 to the present); ? -Truck parking and motor freight station (1977 to 1988); ? -Diesel Corp. (1985 to 1992); and ? -Truck parking and sanitation truck repair (1991 to 2007) Site Geology and Hydrogeology The site is located in a developed area of Brooklyn, New York that is generally covered with paved roads, walkways and buildings. The built environment is generally underlain by fill material used for construction and development since the mid-1800 s. The following description of the proposed brownfield site geology and hydrogeology is derived from the environmental reports referenced in the Environmental Assessment section below. The area surrounding the Gowanus Canal, including the proposed brownfield site, was originally part of the former Gowanus Creek and associated wetlands. In 1848, the State of New York authorized construction of the Gowanus Canal as well as the draining and filling of the wetlands of South Brooklyn. By 1869, the Gowanus Canal was completed with the current street configuration surrounding the canal. According to soil descriptions provided in previous environmental investigations (discussed in Attachment C), the subsurface strata at the proposed brownfield site consists of historic fill material characterized by fine to coarse sand with varying amounts of cobbles, gravel, coal ash, brick, wood, clinkers,

234 BUTLER STREET (Continued) **S121102082**

glass and paper ranging from directly below the surface to depths of 8 to 20 feet. The fill layer is underlain by silt and sand with trace amounts of gravel. Weathered bedrock was encountered at about 151 feet below ground surface (bgs) and bedrock (Fordham Gneiss) was encountered at about 159 feet bgs. According to the Fulton Municipal Works Former Manufactured Gas Plant (MGP) remediation investigation, groundwater depths range from about 5.65 to 7.05 feet bgs. Groundwater elevation measurements recorded from monitoring wells in the area indicate that the shallow groundwater, on the east side of the Canal, generally flows westward toward the Gowanus Canal at high and low tide levels. Groundwater in this area of New York City is not used as a potable water source. Potable water is provided to the site by the City of New York and is derived from surface impoundments in the Croton, Catskill, and Delaware watersheds."

Env Problem: "US Environmental Protection Agency (EPA) has determined that the property is part of the Gowanus Canal Superfund Site that is listed on the National Priorities List. Additionally, under ECL 27-1405(2)(e), there is currently an EPA environmental enforcement action related to contamination at the property, therefore the site was denied entry to the NYS BCP."

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 6
Sub Type: P03
Owner Name: Salvatore Tagliavia
Owner Company: 226 Nevins Street Corp.
Owner Address: 234 Butler Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Salvatore Tagliavia
Owner Company: 226 Nevins Street Corp.
Owner Address: 234 Butler Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11217
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Pacific Branch
Owner Address: 25 4th Avenue
Owner Addr2: Not reported

234 BUTLER STREET (Continued) **S121102082**

Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Gary Reilly
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BE416 **424 5TH AVENUE** **NY LTANKS** **S102660655**
SSE **424 5TH STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.410 mi.
2163 ft. **Site 1 of 3 in cluster BE**

Relative:
Higher

Actual:
80 ft.

LTANKS:

Name:	424 5TH AVENUE
Address:	424 5TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9412686 / 1994-12-21
Facility ID:	9412686
Site ID:	306765
Spill Date:	1994-12-21
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1994-12-21
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1994-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-28
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	A.R. FUELS
Spiller Address:	2125 MILL AVENUE
Spiller County:	001
Spiller Contact:	Not reported

424 5TH AVENUE (Continued) **S102660655**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 247760
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: "CLEAN UP CREW ON SITE NOW. TWO LEGS BUCKLED ON TANK THEREBY PUNCTUIRNG THE TANK- DELIVERY TRUCK #91. CONFIRMED CLEAN UP WITH MS. BROWN. MS BROWN WAS SATISFIED WITH THE CLEAN UP."

All Materials:
Site ID: 306765
Operable Unit ID: 1010269
Operable Unit: 01
Material ID: 374980
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

BD417 **GOWANUS CANAL SITE** **NY SHWS** **S110487590**
NNW **GOWANUS CANAL** **N/A**
1/4-1/2 **BROOKLYN, NY, NY 11217**
0.417 mi.
2202 ft. **Site 3 of 3 in cluster BD**

Relative: **Lower**
Actual: **9 ft.**

SHWS:
Name: GOWANUS CANAL SITE
Address: GOWANUS CANAL
City,State,Zip: BROOKLYN, NY, NY 11217
Program: HW
Site Code: 406956
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 20.000
HW Code: 224133
Record Add: 11/21/2008
Record Upd: 08/24/2021
Updated By: HMDUDEK
Site Description: "Site Description The Gowanus Canal is a man-made navigational waterway in southeastern Brooklyn, Kings County NY. Nearly the entire canal is bounded by hard urban shorelines in the form of bulkheads, moorings, and retaining walls. The site definition includes only the canal and its attached barge slips, totaling slightly over 1.5 linear miles of waterway. Averaging 100 feet in width, the open water area defined as the site totals approximately 1,000,000 square feet or 29 acres. The canal also serves as a storm water drain for the surrounding area. Currently, approximately six square miles of highly urbanized land drains into the canal. Sanitary sewers no longer discharge directly; however, numerous combined sewer overflows (CSO) continue to discharge to the canal during storm events. Industrial discharges from a wide variety of industrial processes were also

GOWANUS CANAL SITE (Continued) **S110487590**

historically routed to the canal, via private discharge pipes or the municipal sewers. Stagnant water conditions have plagued the canal since its initial construction. To combat this, a flushing tunnel at the north end of the canal was constructed in 1911 to divert water from the Buttermilk Channel to maintain flow through the canal to Gowanus Bay. Operation of the flushing system has had numerous problems resulting in lengthy periods during which it was inoperable. Significant upgrades to this system are scheduled over the next few years to increase the volume of water flushing the canal. Currently the flushing tunnel has been de-activated to facillitate its upgrade and an qxygenation system has been installed at the upper end of the canal. Site History Prior to European settlement, this area formed a large tidal marsh, drained by Gowanus Creek and surrounded by higher ground to the west (present-day Carroll Gardens) and east (present-day Park Slope). In the mid 1800s, the Canal was constructed, more or less along the alignment of Gowanus Creek, by straightening and deepening the stream channel and dumping the excavated materials behind rows of timber piles along the shoreline. Combined with other urban filling activities in the surrounding area, the result was a large area of reclaimed land with a dendritic, dead-end canal providing barge access through the middle. The canal offered barge access far inland into Brooklyn, effectively increasing Brooklyn s available tidewater frontage for water-borne commerce. Development of the area was rapid, and by 1869, the layout of the canal and the local street network were essentially complete. Long term decline of the local manufacturing economy has led to a marked decrease in commercial use of the Canal, with only a handful of petroleum distributors and concrete batch plants as regular users. Roughly the northern half no longer hosts barge movements as a result of siltation due to the significant CSOs which discharge street waste and sewage solids. The canal has not been dredged in several decades, consequently, substantial amounts of sediment have been deposited in upstream areas, and water depths approach zero at low tide. The sediment consists largely of solids settled from stormwater and CSO discharges. Presumably, industrial discharges to the canal have diminished in line with the de-industrialization of the surrounding neighborhood, although this is difficult to verify directly due to a lack of historical records for comparison. "

Env Problem: "Water quality issues have plagued the Gowanus Canal almost since its construction. Tidal flushing is largely ineffective due to the length, narrowness, and circuitous layout of the canal channel. Operation of the flushing tunnel has improved the situation during the years when flushing was being conducted; however, the current tunnel requires significant upgrades and is likely to be off-line for a year or more as the upgrades are performed. The canal is currently classified by NYSDEC as Class SD water body, acknowledging that natural or man-made conditions limit attainment of higher standards. Even the SD standards are not currently met. Oily sheens are common on the water surface during low tides, dissolved oxygen levels are low and surface contamination has been identified. Sediment quality is also low. Ongoing CSO discharges have resulted in extensive deposits of settled solids, particularly in the more sheltered areas near the upper end. Some parts of the canal bottom are exposed at low tide. Another particularly important contributor to sediment quality problems is the presence of three former manufactured gas plant (MGP sites) along the length of the canal. Although all three MGPs have been closed for decades, coal tar-impacted sediments have been

GOWANUS CANAL SITE (Continued) **S110487590**

identified at numerous locations along the length of the canal. The three MGPs are all covered by cleanup agreements with NYSDEC, and are at various stages of investigation,remedy selection and implementation. The Fulton Works, immediately east of the canal at its northern extremity, is in the Remedial Investigation process. The Carroll Gardens site (also widely known as Public Place) is in the Brownfield Cleanup Program, and is slated for remediation and redevelopment as a mixed commercial/residential project. The former Metropolitan works, immediately south of the 9th Street bridge, was partially redeveloped under a Voluntary Cleanup Agreement in 2002-2003. However, more work remains to be done part of the MGP facility lies beneath an active retail building. A Remedial Investigation began in March 2010. Numerous oil storage and handling facilities, asphalt plants,manufacturing facilities and chemical, paint, fertilizer and plastic manufacturers have, or continue to, operate along the canal."

Health Problem: "People using the canal for recreational purposes such as swimming and boating may come into direct contact with chemical contaminants and harmful biological organisms. People should avoid any activity that would result in swallowing or accidentally ingesting Canal water. Additionally, people using the canal for any purposes should wash their hands or shower after contacting the water, especially before eating and at the end of the day. Those people who are considering eating fish and shellfish caught in the Canal should follow the NYSDOH consumption advisory for fish and shellfish taken from the Upper Bay of New York Harbor. This advisory specifically includes: The NYSDOH recommends that women of childbearing age and children under the age of 15 not eat any fish from the Canal. Other people should eat no gizzard shad, white perch and crab hepatopancreas and crab cooking liquid. Also, other people should eat no more than one meal per month of American eel, Atlantic needlefish, bluefish, rainbow smelt and striped bass. People should eat no more than one (1/2 pound) meal per week of all other fish species except blue crab meat (six crabs per week). "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: True
Disp Start: 1880
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-11-25 13:09:00
Record Upd: 2016-02-05 09:22:00
Updated By: KALEWAND
Own Op: 1
Sub Type: 01
Owner Name: Not reported
Owner Company: NYC Law Department
Owner Address: 100 Church Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10007
Owner Country: United States of America
HW Code: 224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN

GOWANUS CANAL SITE (Continued) **S110487590**

Waste Code:	Not reported
HW Code:	224133
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224133
Waste Type:	PCB-AROCLOR 1242
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224133
Waste Type:	COAL TAR PITCH VOLATILES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224133
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224133
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224133
Waste Type:	PCB aroclor 1242
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYN000206222
Cross Ref Type Code:	05
Cross Ref Type:	CERCLA EPA ID No.
Record Added Date:	2013-06-13 14:54:00
Record Updated:	2013-06-13 14:54:00
Updated By:	EGHAUSAM

418
West
1/4-1/2
0.420 mi.
2216 ft.

IESI (110 5TH ST.)(SPARTAN DISMANTLING INC)
110 5TH STREET
BROOKLYN, NY 11215

NY SWF/LF **S110540477**
NY Spills **N/A**

Relative:
Lower

Actual:
0 ft.

SWF/LF:

Name:	IESI (110 5TH ST.)(SPARTAN DISMANTLING INC)
Address:	110 5TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185222263
Owner Name:	IESI NY Corp
Owner Type:	Private
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Robert Mrose
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported

IESI (110 5TH ST.)(SPARTAN DISMANTLING INC) (Continued) **S110540477**

Activity Desc:	Transfer station - permit
Activity Number:	[24TA6]
Active:	No
East Coordinate:	585160
North Coordinate:	4503211
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Asbestos (Friable)
Authorization #:	2-6103-00091
Authorization Date:	6/8/1993
Expiration Date:	6/8/2003
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

SPILLS:

Name:	ROAD
Address:	110 5TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1006165 / 2010-09-07
Facility ID:	1006165
Facility Type:	ER
DER Facility ID:	394511
Site ID:	439511
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-09-04
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2010-09-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-04
Spill Record Last Update:	2010-09-07
Spiller Name:	Not reported
Spiller Company:	CNA PROPERTIES
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RICARD RIBELLINO
DEC Memo:	"09/07/10-Hiralkumar Patel. spoke with Richard (at 10:05 AM on 09/04/10). Richard mentioned that a broken machine was located in front of 22 2nd ave. this machine was leaking fluids. and then someone moved that machine to in front of 110 5th street and leaked fluid along the way. visited site this morning. met Richard. found an old excavator in front of 110 5th Street. found strech of oil stains on asphalt street from the intersection of 5th street and 2nd ave to the location of excavator in front of 110 5th street. found minor oil

IESI (110 5TH ST.)(SPARTAN DISMANTLING INC) (Continued) **S110540477**

spill around tracks of the excavator. spoke with Hasan, person working in the garage at the 110 5th street site. Hasan mentioned that when he left garage friday evening, nothing was there, but the excavator was in front of garage on saturday morning. as per Richard, Jack Marmursteio (718-875-8200) owns the exacavator. but Jack denied that and doesn't know who owns it. found information written on machine which includes 'Precinct 76' and 'Row Tow' with date 09/03/10. spoke with operator at precinct 76 (718-834-3211), who confirmed that they had received a complaint of an abandoned machine and they put tag for tow company to remove it. as per retire NYPD officer, generally sanitation department removes these kind of abandoned vechicles to junk yard. but looks like someone moved the machine before sanitation removes it. spoke with NYPD operator again and informed him about new location of machine. he confirmed that machine will be removed, but doesn't know when. after discussing with DEC Austin, case closed."

Remarks: "Caller advised that approximately 10 gallons of hydraulic oil and 10 gallons of diesel fuel spilled onto roadway spanning a 2 block area from 22 2nd ave to 110 5th st."

All Materials:

Site ID:	439511
Operable Unit ID:	1190149
Operable Unit:	01
Material ID:	2185117
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

419
NNE
1/4-1/2
0.423 mi.
2234 ft.

572 WARREN ST. HOUSES -NYCHA
572 WARREN ST
BROOKLYN, NY

NY LTANKS **S102233327**
NY Spills **N/A**

Relative:
Higher

Actual:
25 ft.

LTANKS:

Name:	WYCKOFF CONSOLIDATED -NYCHA
Address:	572 WARREN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9105220 / 2005-03-08
Facility ID:	9105220
Site ID:	115495
Spill Date:	1991-08-14
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1991-08-14
CID:	Not reported

572 WARREN ST. HOUSES -NYCHA (Continued) **S102233327**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-09
Spill Record Last Update:	2005-03-08
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	100643
DEC Memo:	"Closed to consolidate; refer to open spill number 9602519. - J. Kolleeny 3/8/05."
Remarks:	"GROSS LEAK"

All TTF:

Facility ID:	9105220
Spill Number:	9105220
Spill Tank Test:	1538899
Site ID:	115495
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	115495
Operable Unit ID:	959405
Operable Unit:	01
Material ID:	421029
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

572 WARREN ST. HOUSES -NYCHA (Continued) **S102233327**

SPILLS:

Name:	572 WARREN ST. HOUSES -NYCHA
Address:	572 WARREN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9602519 / 2015-06-03
Facility ID:	9602519
Facility Type:	ER
DER Facility ID:	100643
Site ID:	115496
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-05-22
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1996-05-22
CID:	365
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-22
Spill Record Last Update:	2015-06-03
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"12/14/05: This spill transferred from J.Kolleeny to S.Kraszewski. 03/14/06: This spill reassigned to K.Tang. - SK 12/3/07: J.Kann - spill reassigned to J.Kann. Investigative Work Plan submitted on 11/5/07. 5/25/12: J.kann - spill priority assigned as P0 as a part of monthly reporting. 7/22/14: J.Kann - reviewed work plan. 3 permanent wells should be installed. Comments sent to NYCHA in an email today. 12/30/14: J.Kann - part of multi site stip. SIR due 3/14/15 6/3/15: J.Kann - The SIR was submitted on 4/3/15. The SIR was reviewed. 6 borings were advanced and 12 soil samples collected. Minor exceedences of PAHs in 2 locations but attributable to historic fill. 3 groundwater wells were installed and water samples collected and analyzed. Groundwater concentrations were all below TOGS 1.1.1. Site visit made today. Wells were gauged. Water only in wells. Spill closed. NFA. "
Remarks:	"removing a 10,000 gallon heating oil tank. under the tank there was some trapped water that had a petroleum sheen on it. less than 10 gallons are visible."

All Materials:

Site ID:	115496
Operable Unit ID:	1033968
Operable Unit:	01
Material ID:	352337

572 WARREN ST. HOUSES -NYCHA (Continued) **S102233327**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE420 **442 5TH ST** **NY LTANKS** **S100177053**
SSE **442 5TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.436 mi.
2300 ft. **Site 2 of 3 in cluster BE**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Name:	442 5TH ST
Address:	442 5TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9107178 / 1991-10-10
Facility ID:	9107178
Site ID:	271727
Spill Date:	1991-10-03
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1991-10-10
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1991-10-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-18
Spill Record Last Update:	1991-11-13
Spiller Name:	Not reported
Spiller Company:	MADISON OIL CO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	221142
DEC Memo:	""
Remarks:	"NYFD NOTIFIED."

All Materials:

Site ID:	271727
Operable Unit ID:	957518
Operable Unit:	01

442 5TH ST (Continued) **S100177053**

Material ID:	419401
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	160.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF421 **SPILL NUMBER 0212934** **NY LTANKS** **S105998554**
North **233 BUTLER ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.437 mi.
2308 ft. **Site 1 of 2 in cluster BF**

Relative: LTANKS:
Lower

Actual:
11 ft.

Name:	SPILL NUMBER 0212934
Address:	233 BUTLER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0212934 / 2003-09-03
Facility ID:	0212934
Site ID:	180335
Spill Date:	2003-03-31
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2003-03-31
CID:	418
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-31
Spill Record Last Update:	2003-09-03
Spiller Name:	STEVE UHRIK
Spiller Company:	Not reported
Spiller Address:	233 BUTLER ST
Spiller County:	001
Spiller Contact:	STEVE UHRIK
Spiller Phone:	(718) 855-2850
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	151261
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 3/31/03 TIPPLE SPOKE WITH OWNER, REGISTRATION PENDING TEST RESULTS, MR.UHRIK HAS BEEN NEGOTIATING REGISTRATION DETAILS WITH LEGAL. LEAK REPORTED TO BE A DRY LEAK. 9/3/2003 Sangesland received a letter with lab data from Steve Uhrik of New York String Service (718-237-2532). Soil borings taken from around the abandoned tank

SPILL NUMBER 0212934 (Continued) **S105998554**

came back all clean nondetect . Spill Closed"
Remarks: "VIOLATION CODE D2-1557-01-03 "

All Materials:
Site ID: 180335
Operable Unit ID: 866401
Operable Unit: 01
Material ID: 512653
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BG422 **74-76 SOUTH SECOND STREET** **NY VCP** **S125317197**
WNW **74-76 SECOND STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.438 mi.
2314 ft. **Site 1 of 2 in cluster BG**

Relative: **Higher**
Actual: **32 ft.**

VCP NYC:
Project ID: 19TMP0264K,19EH-N099K,19CVCP072K
Name: 74-76 SOUTH SECOND STREET
Address: 74-76 SECOND STREET
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 3024160008
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Construction
Latitude: 40.678241
Longitude: -73.992818
Postcode: 6
Community Board: 39
Council District: 77
Census Tract: 3007873
BIN: 3004610012
NTA: Carroll Gardens-Columbia Street-Red Hook

---

423 **124 LINCOLN PLACE** **NY LTANKS** **S101658343**
East **124 LINCOLN PLACE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.441 mi.
2328 ft.

Relative: **Higher**
Actual: **78 ft.**

LTANKS:
Name: 124 LINCOLN PLACE
Address: 124 LINCOLN PLACE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9502716 / 1995-06-02
Facility ID: 9502716
Site ID: 145166
Spill Date: 1995-06-02
Spill Cause: Tank Failure

124 LINCOLN PLACE (Continued) **S101658343**

Spill Source:	Vessel
Spill Class:	C3
Cleanup Ceased:	1995-06-02
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1995-06-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-06-15
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	TNS TRUCKING CO, INC
Spiller Address:	53 2ND STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	123713
DEC Memo:	""
Remarks:	"WHILE MAKING A DELIVERY, FUEL CAME OUT OF VENT CAUSING SPILL OF 10 GALS OF #2 FUEL - ALL HAS BEEN CLEANED UP OFF CEMENT FLOOR"

All Materials:

Site ID:	145166
Operable Unit ID:	1013936
Operable Unit:	01
Material ID:	367773
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

BE424 **APARTMENT BUILDING** **NY LTANKS** **S106737517**
SSE **446 5TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.442 mi.
2334 ft. **Site 3 of 3 in cluster BE**

Relative:
Higher

Actual:
91 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	446 5TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0410001 / 2005-10-28
Facility ID:	0410001
Site ID:	334901

APARTMENT BUILDING (Continued) **S106737517**

Spill Date:	2004-12-03
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2004-12-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-09
Spill Record Last Update:	2005-10-28
Spiller Name:	Not reported
Spiller Company:	BORO FUEL
Spiller Address:	2 CHURCH AVE
Spiller County:	001
Spiller Contact:	JOESEPH BRILLER
Spiller Phone:	(212) 669-8270
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	270139
DEC Memo:	"4/04/05 - Sawyer - Visited the dwelling above and met Susan Burton (718)788-1312. Found contamination in basement and dirt floor. Boro fuel was contacted and the started cleanup and removed four drums of debris. Bill Crocker at Boro is waiting for the analysis and the he will forward documentation to the Department. 10.07.05 SR// Sharif rec'd a call from Jeffrey Cohn, Boro Fuel. He will send DEC the closure report for review of the department. 10.28.05 Sharif- I received and reviewed the closure documents. Soil analytical result shows voc/svoc's are within limit. Waste disposal manifest were included with the report. NFA required."
Remarks:	"Requesting DEC callback. FD was on scene."

All Materials:

Site ID:	334901
Operable Unit ID:	1097011
Operable Unit:	01
Material ID:	576896
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

425
SE
1/4-1/2
0.447 mi.
2362 ft.

US POST OFFICE
198 7TH AVENUE
BROOKLYN, NY

NY LTANKS **S105141437**
NY Spills **N/A**

Relative:
Higher

Actual:
86 ft.

LTANKS:

Name:	198 7TH AVE/BKLYN/U S P S
Address:	198 7TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9007536 / 2009-10-06
Facility ID:	9007536
Site ID:	92521
Spill Date:	1990-10-10
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	1990-10-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-10
Spill Record Last Update:	2009-10-06
Spiller Name:	Not reported
Spiller Company:	U S P S
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	83083
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 8/20/01 INVESTIGATOR CHANGED FROM BATTISTA TO T. DEMEO. 3/17/06 Possibly refer to spill number 0105125. E-mailed Spill engineer for that spill to discuss. 04/06/06 Closed spill. Referred to spill number 0105125 on this date based concurrence from current project manager, H. Bishop, and upon feedback from T. Demeo. File has copies of relevant and complete e-mail threads. See T.Demeo's response below. Kevin: I remember this location - an old improperly abandoned tank was buried under the basement floor of a post office. Based upon my memory of this site the tank was emptied (mostly water) and a couple borings were performed which did not reveal significant contamination. The vapor condition was abated and did not return - This site should be closed if all documentation was received. At a minimum I would recommend consolidating the two open spills on this site. If Tim DeMeo R1- Spills 631 444 0338 10/6/09 - Raphael Ketani. I spoke to Brian Falvey of the PBS Unit since this was originally his case. He said that he hasn't had any involvement with the site. I told him the 5 end point samples came up with almost no soil

US POST OFFICE (Continued) **S105141437**

contamination. He said that I can close the case. "
Remarks: "1K TANK FAILED VACUTEST WITH A GROSS LEAK, SUSPECT VENT LINE."

All TTF:
Facility ID: 9007536
Spill Number: 9007536
Spill Tank Test: 1537677
Site ID: 92521
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 92521
Operable Unit ID: 948191
Operable Unit: 01
Material ID: 431388
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: US POST OFFICE
Address: 198 7TH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0105125 / 2009-12-14
Facility ID: 0105125
Facility Type: ER
DER Facility ID: 83083
Site ID: 65316
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2001-08-11
Investigator: RVKETANI
Referred To: Not reported
Reported to Dept: 2001-08-11
CID: 396
Water Affected: Not reported
Spill Source: Commercial/Industrial

US POST OFFICE (Continued) **S105141437**

Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-11
Spill Record Last Update:	2009-12-14
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO CITIZEN COMPLAINT REGARDING FUEL VAPORS EMINATING FROM A POST OFFICE LOCATED ON 7TH AVE IN BROOKLYN. INVESTIGATION REVEALED THIS IS AN ONGOING PROBLEM WHICH IS WORSE AFTER A HEAVY RAIN. NYFD REPORTABLY RESPONDED TO ANOTHER COMPLAINT AT THIS LOCATION ON 8/10, THE POST OFFICE WAS SHUT DOWN FOR THE AFTERNOON TO VENTILATE SPACE. NYSDEC WAS NOT NOTIFIED OF PROBLEM UNTIL FOLLOWING DAY, NOTIFICATION CAME FROM IMPACTED CITIZEN. SPILL RESPONDER DEMEO RESPONDED TO SCENE AND INSPECTED BASEMENT. aN IMPRPERLY ABANDONED UST IS BURIED BELOW THE BASEMENT FLOOR. 10/2/09 - Austin - Spill transferred from Albany staff(HL Bishop) to Ketani, for further investigation - end 10/6/09 - Raphael Ketani. Presently, there are no E-docs. There is no PBS registration. The spill was called in on 8/11/2001 by a citizen from next door who complained about strong oil odors. The property address is 198 7th Avenue, Brklyn, 11215. According to pictures in Property Shark, the site site is a four story walkup tenement style apartment building with a post office on the ground (first) floor. The block and lot are 976 and 40. According to ACRIS, the property is owned by Shanghied Ketch Co., c/o John Bijur, 498 2nd Street, Brklyn, 11210. The property was bought on 12/6/83. A CSL dated 8/16/01 was sent to Isaac Erlich at Shandheid Ketch Co. at 150 7th Ave, Brklyn 11215. A vapor abatement system must be installed and a subsurface soil investigation conducted. There is a 5/22/02 FAX from Petroleum Tank Cleaners containing the soil analytical results for five (5) end point samples. The VOCs were entirely non-detect and the SVOCs showed hits primarily for the benzo series combustion analytes. Some of these benzo series analytes exceeded the TAGM standards. There were no naphthalene hits. The results show that there is no significant soil contamination. There is no information regarding the status of the UST, nor the installation of a vapor abatement system. So I contacted BEM Systems, Inc. (908) 598-2600. The previous case manager no longer worked for BEM. So I was connected with Bill Munsick's voice mail. I left a message regarding the status of any installed vapor abatement system and the status of the UST. Next, I tried to contact Robert Skrivanek, Environmental Coordinator for the Post Office at (718) 529-7220, but I had to send him an e-mail to rsknvan@email.usps.gov as his voice mail box was full. I tried to contact Jason Bijur at (718) 230-8634, but could only leave a message. This spill case is associated with an earlier spill case #9007536. This spill was a tank test failure for the 1,000 gal. UST. It was called in on 10/10/90 by Tanknology Inc. (609) 753-9111. It was a gross leak and the vent pipe was suspected as the source of the problem. Tim Demeo was the case manager at the time and left the

US POST OFFICE (Continued) **S105141437**

following notes:
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXX 04/06/06 Closed spill. Referred to spill number 0105125 on this date based concurrence from current project manager, H. Bishop, and upon feedback from T. Demeo. File has copies of relevant and complete e-mail threads. See T.Demeo's response below. Kevin: I remember this location - an old improperly abandoned tank was buried under the basement floor of a post office. Based upon my memory of this site the tank was emptied (mostly water) and a couple borings were performed which did not reveal significant contamination. The vapor condition was abated and did not return - This site should be closed if all documentation was received. At a minimum I would recommend consolidating the two open spills on this site. If Tim DeMeo R1- Spills
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXX 10/6/09 - Raphael Ketani. Today, I closed spill case #9007536. In the afternoon, Mr. Bijur called me back. He said that he was not the lawyer for the owners of the building, Shangheid-Ketch Co., but that he was trying to help Mr. Demeo resolve the case. He said that he has an interest in one of the condos. He said that the building consists of 6 condos and 1 commercial space on the ground floor. He added that he thought the tank was gone, and that the vapor issue was resolved. The building was converted to gas and had never used oil, as far as he could remember. Mr. Bijur will get back to me regarding access to the basement so that I can do a quick vapor survey with a PID meter. I contacted the law office of Allen, Morris, Troisi & Simon (212) 353-0040. I spoke to Michael Troisi (troy-see), the lawyer for Isaac Erlich, Shangheid-Ketch Co. Mr. Troisi stated that Shangheid-Ketch owns just the commercial space and the basement. He said that he will look into my request for information regarding the tank, the indoor air vapors, and my desire to do an air survey and see the basement. At 5:04PM, Mr. Troisi left me a message. He stated that the tank had been pulled and that if I need any documentation regarding the remediation, I should contact Mr. Bijur. 10/8/09 - Raphael Ketani. James Nichols of BEM called me back again. He said that he finished looking through his records and he found out that BEM was only involved in the vapor issues as industrial hygienists. He said the vapors were bad in the Post Office and people had to leave the facility. He said I should contact the property owner as the tank belonged to him. 12/9/09 - Raphael Ketani. I made an unannounced site visit today. I entered the post office, but didn't detect any odors. I met Bella Cavella in the post office. She told me that she is the Chief Clerk for the post office and that there isn't anyone higher up who works here. I asked her whether there have been any oil odors in the post office recently or in the recent past. She said that she will talk to her clerks and find out. I waited and she came back to talk to me. She said that her clerks have no complaints regarding any odors. I thanked her and left the post office. I saw two cement patches on the sidewalk next to the right side of the building. These looked like reasonable locations for the former fill box and the former vent pipe. Next, I tried to open the metal cellar doors. The doors were locked, but I could depress one with my weight and get the doors to separate a little. I stuck the nose of the PID meter in the gap. However, no vapors were detected. 12/14/09 - Raphael Ketani. I reviewed the 9/6/2001 soil analytical results report from South Mall Labs., which is attached to the 5/22/02 FAX from Petroleum Tank Cleaners. The results are either

US POST OFFICE (Continued) **S105141437**

non-detect, well below TAGM, or (for some benzo series SVOCs) just at TAGM limits. A 9/20/01 FAX from Arnold Schwartz of Administrative Services for the US Post Office contains a page which is an invoice from Key Environmental. The invoice lists charges for work performed and materials used for the cleanup of the spill. The invoice indicates that a spill was cleaned up, and the end point sample results indicate that any contamination that is left is at a very low level and is not a threat to human health or the environment. Mr. Troisi left a message on 10/6/09 that the tank had been pulled. Therefore, I am closing the spill case."

Remarks: "caller states that there is an oil tank leaking in the basement of the post office...he says that he lives in another building and says the the smell is really bad. he spoke to someone at the post office and the fd was there yesterday but the employee didnt know any info on clean up. req a call back."

All Materials:

Site ID:	65316
Operable Unit ID:	843562
Operable Unit:	01
Material ID:	533603
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH426 **66 FOURTH STREET** **NY LTANKS U003749712**
West **66 4TH STREET** **NY UST N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.451 mi.
2382 ft. **Site 1 of 2 in cluster BH**

Relative: **Lower**
Actual: **15 ft.**

LTANKS:

Name:	SPILL NUMBER 0106619
Address:	66 4TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0106619 / 2003-11-17
Facility ID:	0106619
Site ID:	228322
Spill Date:	2001-09-25
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-09-25
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

66 FOURTH STREET (Continued) **U003749712**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-25
Spill Record Last Update:	2003-11-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	NEW YORK PETROLIUM AND DR
Spiller Phone:	(516) 338-0626
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	79057
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 11/17/03 TJD Consolidating open spills on property. Spill closed and cross referenced to spill #0106920."
Remarks:	""

All TTF:

Facility ID:	0106619
Spill Number:	0106619
Spill Tank Test:	1526625
Site ID:	228322
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	228322
Operable Unit ID:	843675
Operable Unit:	01
Material ID:	531465
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	66 FOURTH STREET
Address:	66 4TH STREET
City,State,Zip:	BROOKLYN, NY 11215

66 FOURTH STREET (Continued) **U003749712**

Id/Status: 2-604660 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585057.06247
UTM Y: 4503373.22674
Site Type: Other

Affiliation Records:

Site Id: 26531
Affiliation Type: Facility Owner
Company Name: ALFONSO FIGLIOLIA
Contact Type: Not reported
Contact Name: Not reported
Address1: 50 21ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 26531
Affiliation Type: Mail Contact
Company Name: SUNSET INDUSTRIAL PARK ASSOC.
Contact Type: Not reported
Contact Name: ALFONSO FIGLIOLIA
Address1: 50 21ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11232
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 26531
Affiliation Type: Facility Operator
Company Name: 66 FOURTH STREET
Contact Type: Not reported
Contact Name: AL FIGLIOLIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-6000
EMail: Not reported
Fax Number: Not reported

66 FOURTH STREET (Continued) **U003749712**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	26531
Affiliation Type:	Emergency Contact
Company Name:	ALFONSO FIGLIOLIA
Contact Type:	Not reported
Contact Name:	AL FIGLIOLIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	0001
Tank ID:	58472
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	06/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	0002
Tank ID:	58473
Tank Status:	Closed - In Place

66 FOURTH STREET (Continued) **U003749712**

Material Name:	Closed - In Place
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	06/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	0003
Tank ID:	58474
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	06/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

66 FOURTH STREET (Continued) **U003749712**

D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	0004
Tank ID:	58475
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	06/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

---

427 SSW 1/4-1/2 0.455 mi. 2403 ft. **STELLAR 341 LLC**
341 10TH STREET
BROOKLYN, NY 11215

NY LTANKS **U003178461**
NY UST **N/A**
NY AST

Relative: Higher

Actual: 51 ft.

LTANKS:

Name:	APARTMENT
Address:	341 10TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0413183 / 2005-11-09
Facility ID:	0413183
Site ID:	339044
Spill Date:	2004-04-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported

STELLAR 341 LLC (Continued) **U003178461**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-11-09
Spiller Name:	STUART
Spiller Company:	APARTMENT
Spiller Address:	341 10TH STREET
Spiller County:	001
Spiller Contact:	STUART
Spiller Phone:	(631) 926-2196
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	285665
DEC Memo:	"Why was there almost a 1 year gap between failure date and report date? sent ttf ltr on 3/25/2005 6/9/05 - Austin - Transferred from Sawyer to Rahman for review of 6/9 submission from SNS Energy Distribution - end 10.20.05 Sharif- Reviewed the submission prepared by SNS Energy Corp.The report does n't show from exactly where the five samples were taken. For UST closure in place samples should be taken from side wall and centerline of the bottom of the tank and also along the buried oil line. UST was 20000 gal. tank. Left a messege for Stuart, 631-691-1700 to call back DEC to follow up about the tank closure. 11.09.05 Sharif- Rec'd site plan, soil borings log. Spill closed."
Remarks:	"PBS No: 2-115886 "

All TTF:

Facility ID:	0413183
Spill Number:	0413183
Spill Tank Test:	1548701
Site ID:	339044
Tank Number:	001
Tank Size:	20000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	339044
Operable Unit ID:	1100962
Operable Unit:	01
Material ID:	581112
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

STELLAR 341 LLC (Continued) **U003178461**

Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

UST:
Name: STELLAR 341 LLC
Address: 341 10TH STREET
City,State,Zip: BROOKLYN, NY 11215
Id/Status: 2-115886 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585581.14379
UTM Y: 4502514.34205
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 3865
Affiliation Type: Facility Operator
Company Name: STELLAR 341 LLC
Contact Type: Not reported
Contact Name: SALVADOR DELAROSA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (877) 246-3053
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 2008-03-19

Site Id: 3865
Affiliation Type: Emergency Contact
Company Name: STELLAR 341 LLC % STELLAR MANAGEMENT
Contact Type: Not reported
Contact Name: BESIM BESKOVIC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 208-8984
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 2008-03-19

Site Id: 3865
Affiliation Type: Facility Owner

STELLAR 341 LLC (Continued) **U003178461**

Company Name:	STELLAR 341 LLC % STELLAR MANAGEMENT
Contact Type:	PERMIT COORDINATOR
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAM STREET, 10TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 406-0030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-01-16

Site Id:	3865
Affiliation Type:	Mail Contact
Company Name:	STELLAR MANAGEMENT
Contact Type:	Not reported
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAM STREET
Address2:	TENTH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 843-3783
EMail:	KVAZQUEZ@STELLARMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2017-04-03

Tank Info:

Tank Number:	1
Tank ID:	5296
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	20000
Install Date:	03/01/1968
Date Tank Closed:	06/08/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

STELLAR 341 LLC (Continued) **U003178461**

K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AST:

Name:	STELLAR 341 LLC
Address:	341 10TH STREET
City,State,Zip:	BROOKLYN, NY 11215
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-115886
Program Type:	PBS
UTM X:	585581.14379
UTM Y:	4502514.34205
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3865
Affiliation Type:	Facility Operator
Company Name:	STELLAR 341 LLC
Contact Type:	Not reported
Contact Name:	SALVADOR DELAROSA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(877) 246-3053
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-03-19

Site Id:	3865
Affiliation Type:	Emergency Contact
Company Name:	STELLAR 341 LLC % STELLAR MANAGEMENT
Contact Type:	Not reported
Contact Name:	BESIM BESKOVIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 208-8984
EMail:	Not reported
Fax Number:	Not reported

STELLAR 341 LLC (Continued) **U003178461**

Modified By:	dxliving
Date Last Modified:	2008-03-19

Site Id:	3865
Affiliation Type:	Facility Owner
Company Name:	STELLAR 341 LLC % STELLAR MANAGEMENT
Contact Type:	PERMIT COORDINATOR
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAM STREET, 10TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 406-0030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-01-16

Site Id:	3865
Affiliation Type:	Mail Contact
Company Name:	STELLAR MANAGEMENT
Contact Type:	Not reported
Contact Name:	KATINA V. VAZQUEZ
Address1:	156 WILLIAM STREET
Address2:	TENTH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 843-3783
EMail:	KVAZQUEZ@STELLARMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2017-04-03

Tank Info:

Tank Number:	2
Tank Id:	222087
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

STELLAR 341 LLC (Continued) **U003178461**

	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/17/2008
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/09/2017
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

---

428 South 1/4-1/2 0.456 mi. 2407 ft.

CVS PHARMACY #2498
341 9TH ST
BROOKLYN, NY 11215

SEMS-ARCHIVE 1000121612
RCRA-VSQG NYD042777128

Relative: Higher

Actual: 75 ft.

SEMS Archive:

Site ID:	0201536
EPA ID:	NYD042777128
Name:	G & L EYES INC
Address:	341 - 39TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Cong District:	15
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201536
EPA ID:	NYD042777128
Site Name:	G & L EYES INC
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1987-09-02 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0201536
EPA ID:	NYD042777128
Site Name:	G & L EYES INC
NPL:	N
FF:	N

CVS PHARMACY #2498 (Continued) **1000121612**

OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1981-05-01 04:00:00
Finish Date: 1981-05-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0201536
EPA ID: NYD042777128
Site Name: G & L EYES INC
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1987-09-02 04:00:00
Qual: N
Current Action Lead: EPA Perf

RCRA-VSQG:

Date Form Received by Agency:		20210222
Handler Name:	CVS PHARMACY #2498	
Handler Address:		341 9TH ST
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYD042777128
Contact Name:		NICOLE WILKINSON
Contact Address:		CVS DR MC2340
Contact City,State,Zip:		WOONSOCKET, RI 02895
Contact Telephone:		401-770-7132
Contact Fax:		Not reported
Contact Email:		NICOLE.WILKINSON@CVSHEALTH.COM
Contact Title:		DIRECTOR, CORPORATE ENVIRONMENTAL
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2020
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CVS DR MC2340
Mailing City,State,Zip:		WOONSOCKET, RI 02895
Owner Name:	ROYAL FARMS INC	
Owner Type:		Private
Operator Name:	CVS ALBANY, LLC	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

CVS PHARMACY #2498 (Continued) **1000121612**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210304
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

CVS PHARMACY #2498 (Continued) **1000121612**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	D016
Waste Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D024
Waste Description:	M-CRESOL
Waste Code:	D027
Waste Description:	1,4-DICHLOROBENZENE
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	F017
Waste Description:	Not Defined
Waste Code:	P001
Waste Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS,

CVS PHARMACY #2498 (Continued) **1000121612**

WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U070
Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U072

CVS PHARMACY #2498 (Continued) **1000121612**

Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U279
Waste Description: U279

Waste Code: U411

CVS PHARMACY #2498 (Continued) **1000121612**

Waste Description: U411

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS ALBANY LLC	
Legal Status:	Private
Date Became Current:	19990621
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROYAL FARMS INC	
Legal Status:	Private
Date Became Current:	19981027
Date Ended Current:	Not reported
Owner/Operator Address:	420 MADISON AVE STE 301
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-752-6160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROYAL FARMS INC	
Legal Status:	Private
Date Became Current:	19981027
Date Ended Current:	Not reported
Owner/Operator Address:	420 MADISON AVE STE 301
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-752-6160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ANTHONY LIGUORI JANET LIGUORI	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ANTHONY LIGUORI JANET LIGUORI	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED

CVS PHARMACY #2498 (Continued) **1000121612**

Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROYAL FARMS INC
Legal Status: Private
Date Became Current: 19981027
Date Ended Current: Not reported
Owner/Operator Address: 420 MADISON AVE STE 301
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-752-6160
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROYAL FARMS INC
Legal Status: Private
Date Became Current: 19981027
Date Ended Current: Not reported
Owner/Operator Address: 420 MADISON AVE STE 301
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-752-6160
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS ALBANY, LLC
Legal Status: Private
Date Became Current: 19990621
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR MC2340
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS ALBANY LLC
Legal Status: Private
Date Became Current: 19990621
Date Ended Current: Not reported
Owner/Operator Address: 420 MADISON AVE STE 301
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROYAL FARMS INC
Legal Status: Private

CVS PHARMACY #2498 (Continued) **1000121612**

Date Became Current:	19981027
Date Ended Current:	Not reported
Owner/Operator Address:	420 MADISON AVE STE 301
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-752-6160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROYAL FARMS INC	
Legal Status:	Private
Date Became Current:	19981027
Date Ended Current:	Not reported
Owner/Operator Address:	420 MADISON AVE STE 301
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-752-6160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS ALBANY LLC	
Legal Status:	Private
Date Became Current:	19990621
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS ALBANY LLC	
Legal Status:	Private
Date Became Current:	19990621
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ANTHONY LIGUORI JANET LIGUORI	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CVS PHARMACY #2498 (Continued) **1000121612**

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS ALBANY LLC
Legal Status: Private
Date Became Current: 19990621
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROYAL FARMS INC
Legal Status: Private
Date Became Current: 19981027
Date Ended Current: Not reported
Owner/Operator Address: 420 MADISON AVE STE 301
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-752-6160
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS ALBANY LLC
Legal Status: Private
Date Became Current: 19990621
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140314
Handler Name: CVS PHARMACY #2498
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210222
Handler Name: CVS PHARMACY #2498
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CVS PHARMACY #2498 (Continued) **1000121612**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990708
Handler Name: G & L EYES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: G & L EYES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: G & L EYES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800721
Handler Name: G & L EYES INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CVS PHARMACY #2498 (Continued) **1000121612**

Receive Date:	20120305
Handler Name: CVS PHARMACY #2498	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120830
Handler Name: CVS PHARMACY #2498	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150213
Handler Name: CVS PHARMACY #2498	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150728
Handler Name: CVS PHARMACY #2498	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190408
Handler Name: CVS PHARMACY #2498	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CVS PHARMACY #2498 (Continued) **1000121612**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	33611
NAICS Description:	AUTOMOBILE AND LIGHT DUTY MOTOR VEHICLE MANUFACTURING
NAICS Code:	339931
NAICS Description:	DOLL AND STUFFED TOY MANUFACTURING
NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	812922
NAICS Description:	ONE-HOUR PHOTOFINISHING

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported

CVS PHARMACY #2498 (Continued) **1000121612**

SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19870313
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported

CVS PHARMACY #2498 (Continued) **1000121612**

Former Citation:	Not reported
Evaluation Date:	19831026
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

BG429 **DEL'S AUTO REPAIR** **NY LTANKS** **S103037408**
WNW **70 2ND ST/NEW UTRECHT AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.456 mi.
2409 ft. **Site 2 of 2 in cluster BG**

Relative: **Higher**
Actual: **33 ft.**

LTANKS:

Name:	DEL'S AUTO REPAIR
Address:	70 2ND ST/NEW UTRECHT AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9713407 / 2003-03-03
Facility ID:	9713407
Site ID:	319396
Spill Date:	1998-03-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1998-03-03
CID:	371
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-03-03
Spill Record Last Update:	2003-04-03
Spiller Name:	Not reported
Spiller Company:	DEL'S AUTO REPAIR
Spiller Address:	70 2ND ST/NEW UTRECHT AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	257321
DEC Memo:	""

DEL'S AUTO REPAIR (Continued) **S103037408**

Remarks: "called in by calco to test tank - failed. no obvious spillage."

All TTF:

Facility ID:	9713407
Spill Number:	9713407
Spill Tank Test:	1545649
Site ID:	319396
Tank Number:	Not reported
Tank Size:	550
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	319396
Operable Unit ID:	1059371
Operable Unit:	01
Material ID:	324425
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

430
NNW
1/4-1/2
0.458 mi.
2419 ft.

GOWANUS HOUSING COMPLEX-NYCHA **NY LTANKS** **S105995765**
238 BOND ST **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
11 ft.

LTANKS:

Name:	GOWANAS HOUSING -NYCHA
Address:	238 BOND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0201330 / 2005-12-23
Facility ID:	0201330
Site ID:	197021
Spill Date:	2002-05-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	0201191
Reported to Dept:	2002-05-06

GOWANUS HOUSING COMPLEX-NYCHA (Continued) **S105995765**

CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-06
Spill Record Last Update:	2009-05-21
Spiller Name:	JOSEPH CAMERON
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	23-02 49TH AVE
Spiller County:	001
Spiller Contact:	JOSEPH CAMERON
Spiller Phone:	(718) 707-5725
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	164000
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY 11/07/05: This spill transferred from J.Kolleeny to S.Kraszewski. 12/23/05: This spill closed to consolidate with open spill #0201191. - SK"
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. FURTHER INVESTIGATION AND TESTING TO BE DONE."

All TTF:

Facility ID:	0201330
Spill Number:	0201330
Spill Tank Test:	1527107
Site ID:	197021
Tank Number:	1
Tank Size:	25000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	197021
Operable Unit ID:	854610
Operable Unit:	01
Material ID:	565865
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

GOWANUS HOUSING COMPLEX-NYCHA (Continued) **S105995765**

Oxygenate:	Not reported
Name:	GOWANUS HOUSING COMPLEX-NYCHA
Address:	238 BOND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0201191 / 2008-09-23
Facility ID:	0201191
Site ID:	224675
Spill Date:	2002-05-01
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	2002-05-01
CID:	282
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-01
Spill Record Last Update:	2008-09-23
Spiller Name:	MR MANDALONE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	23-02 49TH AVE
Spiller County:	001
Spiller Contact:	MR MANDALONE
Spiller Phone:	(718) 707-7839
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	164000
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY 4/30/04 TJD As per direction of RSE, site transferred Demeo >>> Kolleeny as spill location is at NYCHA owned facility. 11/07/05: This spill transferred from J.Kolleeny to S.Kraszewski. 12/23/05: Only thing on file is spill report. - SK 07/07/06: NYCHA summary report states that two 25K USTs are currently in service. The man way gasket leaked, was repaired and retested. No recovery system or MWs on-site, soil/GW conditions are unknown and no site assessment available. NYCHA recommends closure. - SK 02/06/07 - J.Kann - site reassigned from S. Kraszewski to J.Kann. 09/23/08: Documents related to tank tightness testing submitted to the Department. Results indicate that manway gasket nuts and bolts were cause of testing failure, they were replaced and the tank passed testing. Spill closed based on this information. J.kann "
Remarks:	"TANK FAILED THE TEST. "

All TTF:

Facility ID:	0201191
Spill Number:	0201191
Spill Tank Test:	1527096
Site ID:	224675

GOWANUS HOUSING COMPLEX-NYCHA (Continued) **S105995765**

Tank Number:	2
Tank Size:	25000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	224675
Operable Unit ID:	852244
Operable Unit:	01
Material ID:	522610
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

431 **TTF** **NY LTANKS** **S117364491**
SSW **300 10TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.461 mi.
2435 ft.

Relative:
Higher

Actual:
41 ft.

LTANKS:

Name:	TTF
Address:	300 10TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1406432 / 2014-11-13
Facility ID:	1406432
Site ID:	499901
Spill Date:	2014-09-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2014-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

TTF (Continued) **S117364491**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-09-16
Spill Record Last Update:	2015-10-28
Spiller Name:	Not reported
Spiller Company:	ERIC S.
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ERIC S.
Spiller Phone:	908 392 0136
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	454927
DEC Memo:	"09/17/14-Hiralkumar Patel. alternate addresses: 453-459 4th Avenue, 292-304 10th Street no other spills found. PBS #: 2-404926. as per PBS record, the site has one 5,000 gal #2 oil AST in contact with soil. PBS registration expired on 10/15/2007. 9:56 AM:- spoke with Eric Sutphen at Approved Oil, who hired PTC to conduct system test. Eric mentioned that the oil tank was cleaned out last week as part of fuel grade conversion from #6 to #2 oil. after cleaning, they filled up the tank with #2 oil and then decided to conduct a tightness test. the tank system failed in dry portion and PTC believed a leak in vent pipe. PTC will do vent repair and retesting. asked Eric to provide propert owner's contact info. he will call back. Approved Oil Eric Sutphen Ph. (718) 238-1050 (O) (347) 909-0994 (C) Fax (718) 621-8107 email: erics@approvedoil.com as per NYC ACRIS record, the property was sold to Prime Properties of New York Inc. in April 2007. but as per discussion with person at real estate office (718-748-0870), whose number is listed as property owner in last NYC DOB permit in 2012, subject property was sold to new entity six months ago and they don't have contact information. 300-304 10th Street FT LLC. **property owner** c/o Silverstone Property Group **management company** 825 Third Avenue, 37th Floor New York, NY 10022 Attn.: Jason Nunez **property manager** PH. (646) 786-8000 Ext. 7819 email: service@silverstonepg.com 11:00 AM:- sent TTF letter, including PBS application, to Mr. Nunez. letter emailed to Mr. Nunez and Eric. case assigned to DEC Mahat (off-hour secondary). 11/12/14: Mahat t/c: DEC Mahat received a call from Isreal (Milleneum Tank) inquiring what needed to be address in closing report. A closure report will provided to the Department by EOB 11/14/14. 11/13/14: Mahat A spill closure letter is supplied to the Department. Based on the picture, TT result and repair : No further investifation is required as no resources were impacted. Hence, the spill case will be closed in the Database . "
Remarks:	"Tank test fail"

All Materials:

Site ID:	499901
Operable Unit ID:	1249307
Operable Unit:	01
Material ID:	2250876
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

TTF (Continued) **S117364491**

Oxygenate: Not reported

432
NNE
1/4-1/2
0.467 mi.
2467 ft.

79-97 4TH AVENUE
85 4TH AVENUE
NEW YORK CITY, NY

NY VCP **S125317226**
N/A

Relative:
Higher

Actual:
29 ft.

VCP NYC:

Project ID:	13TMP0188K,13EHAZ188K,13CVCP133K
Name:	79-97 4TH AVENUE
Address:	85 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0093400053009301E+89
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Approved Remedial Plan
Latitude:	40.681608
Longitude:	-73.980192
Postcode:	6
Community Board:	39
Council District:	12901
Census Tract:	3018646
BIN:	3009340007
NTA:	Park Slope-Gowanus

BH433
WNW
1/4-1/2
0.470 mi.
2484 ft.

425 HOYT STREET
419-429 HOYT STREET
BROOKLYN, NY 11231

Site 2 of 2 in cluster BH

NY BROWNFIELDS **S117936666**
N/A

Relative:
Lower

Actual:
19 ft.

BROWNFIELDS:

Name:	425 HOYT STREET
Address:	419-429 HOYT STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	507652
Acres:	0.199
HW Code:	C224224
SWIS:	2401
Town:	New York City
Record Added Date:	05/08/2015
Record Updated Date:	02/03/2021
Update By:	DJEATON
Site Description:	"Location: The site is located in an urban area, on the southeast corner of Hoyt Street and 4th Street in the Carroll Gardens neighborhood of Brooklyn. The site is bound by 4th Street to the north, Hoyt Street to the west, multi-story industrial buildings to the east and Ferrara Brothers Brooklyn Concrete Plant to the south. Site Features: The site is developed with a one-story garage/warehouse building and two two-story commercial warehouse buildings with a partial basement. Current Zoning/Use: The site is zoned M3-1 (Manufacturing) and is currently an unoccupied warehouse. Historic Use: Past uses include a marble company, a feather holding

425 HOYT STREET (Continued) **S117936666**

	and separating operation, manufacturing and storage of plumbing supplies, and automobile repair. Site Geology and Hydrogeology: Historic fill extends from below the surface cover to depths ranging from 11 to 15 feet below ground level, generally coinciding with the depth of the groundwater table. The fill is described as brown sand with wood and brick. A layer of native organic clay lies below the fill. Bedrock is of the Middle Ordovician to Lower Cambrian Hartland Formation, which consists of fine-grained quartz-feldspar granulite. "
	Not reported
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	P03
Owner Name:	Doug Bomar
Owner Company:	Hoyt Street Partners LLC
Owner Address:	68 Jay Street, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Branch Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Linda Figliolia
Owner Address:	7 Delwood Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Holmdel, NJ 07733
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BF434 **BASIN HAULAGE INC. I** **NY SWF/LF** **S105841893**
North **462-470 BALTIC STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11217**
0.472 mi.
2490 ft. **Site 2 of 2 in cluster BF**

Relative: **Lower**
Actual: **12 ft.**

SWF/LF:

Name:	BASIN HAULAGE INC. I
Address:	462-470 BALTIC STREET
City,State,Zip:	BROOKLYN, NY 11217
Flag:	INACTIVE
Region Code:	2
Phone Number:	7188210310
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	STEPHEN SPALLINO; PRESIDENT
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W22]
Active:	No
East Coordinate:	585620
North Coordinate:	4504031
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6103-00054
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

---

435 **125 THIRD AVENUE** **NY VCP** **S125316811**
NNE **125 3RD AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.477 mi.
2520 ft.

Relative: **Higher**
Actual: **24 ft.**

VCP NYC:

Project ID:	15TMP0349K,15EH-N349K,16CVCP006K
Name:	125 THIRD AVENUE
Address:	125 3RD AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3003950003
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.682338
Longitude:	-73.982712
Postcode:	2
Community Board:	33

125 THIRD AVENUE (Continued) **S125316811**

Council District: 127
Census Tract: 3336057
BIN: 3003950003
NTA: DUMBO-Vinegar Hill-Downtown Brooklyn-Boerum Hill

---

436 **WYCKOFF GARDENS** **NY LTANKS** **S104283696**
North **185 NEVINS ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.478 mi.
2522 ft.

Relative: **Lower**

Actual: **17 ft.**

LTANKS:

Name:	WYCKOFF GARDENS
Address:	185 NEVINS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9811464 / 1999-05-14
Facility ID:	9811464
Site ID:	237645
Spill Date:	1998-12-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1998-12-11
CID:	365
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-11
Spill Record Last Update:	1999-05-14
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195738
DEC Memo:	""
Remarks:	"FAILURE OF HORNER EZ 3 TANK TEST"

All TTF:

Facility ID:	9811464
Spill Number:	9811464
Spill Tank Test:	1546630
Site ID:	237645
Tank Number:	2
Tank Size:	25000
Material:	0001
EPA UST:	Not reported

WYCKOFF GARDENS (Continued) **S104283696**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	237645
Operable Unit ID:	1068845
Operable Unit:	01
Material ID:	311761
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

437
NE
1/4-1/2
0.480 mi.
2532 ft.

SINSI RESIDENCE
112 ST MARKS PL
BROOKLYN, NY

NY LTANKS **S102673358**
N/A

Relative:
Higher

Actual:
34 ft.

LTANKS:

Name:	SINSI RESIDENCE
Address:	112 ST MARKS PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9600499 / 1996-04-11
Facility ID:	9600499
Site ID:	208826
Spill Date:	1996-04-10
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1996-04-11
CID:	297
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-11
Spill Record Last Update:	2004-04-19

SINSI RESIDENCE (Continued) **S102673358**

Spiller Name:	PETER LEPORE
Spiller Company:	WHALECO FUEL
Spiller Address:	1 COFFEE ST
Spiller County:	001
Spiller Contact:	SINSI
Spiller Phone:	(718) 789-1728
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	173238
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"DRIVER OVERFILLED THE FUEL TANK AND IT SPILLED OUTSIDE ONTO THE SIDEWALK - SPILL CLEANED UP WITH ABSORBANTS"

All Materials:

Site ID:	208826
Operable Unit ID:	1028179
Operable Unit:	01
Material ID:	353894
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

438
SW
1/4-1/2
0.499 mi.
2633 ft.

498 3RD AVENUE **NY LTANKS** **S100167654**
498 3RD AVENUE **N/A**
BROOKLYN, NY 11215

Relative:
Lower

Actual:
22 ft.

LTANKS:

Name:	498 3RD AVENUE
Address:	498 3RD AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Spill Number/Closed Date:	8809911 / 2021-08-31
Facility ID:	8809911
Site ID:	66897
Spill Date:	1989-03-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	EJKIM
Referred To:	Not reported
Reported to Dept:	1989-03-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True

498 3RD AVENUE (Continued) **S100167654**

Remediation Phase:	0
Date Entered In Computer:	1989-03-29
Spill Record Last Update:	2021-09-28
Spiller Name:	Not reported
Spiller Company:	CARMELO AUTO REPAIR
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	20999
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 01/07/2004. DEC Sigona sent a letter to RP on Jan 23, 1990 with requirements for spill investigation. On May 16, 2002, DEC (Austin) was contacted by Mr. Englemenan (917)747-7702 representative for the owner. He requested to pave over the monitoring wells at the site. DEC (Sigona) called Mr. Engleman on 5/17/02 and left message on answering machine to submit recent groundwater testing results to determine if the spill case could be closed. 3/17/06 This site had documented impacts to groundwater. A complete investigation was needed in 1989. The file does not reflect completion of an investigation. Available data indicates that remediation would have been necessary. Need to establish the current status and determine if site should be in one of the remedial programs. 9/12/2006 This case was transferred from Albany to Region #2. Zhune spoke to Mr. Engleman. He said as soon as he find documentation he will send it. 07/12/12- Zhune spoke to Mr. Englemenann he asked for two days to find the report and send it. 03/14/12-Zhune spoke to Mr. Englemenan. he said he is going to send the closure tank report next week. Mr. Englemenan email- e1462@aol.com ********** 08/16/13-David Engleman sent the following email: I got your e-mail and I am working on it. I will e-mail you the information within a few days G-D willing. 8/30/13-David Engleman sent the following email: As per your request I am attaching a copy of the affidavit for the property 498 3rd Avenue/tanks purged and filled with concrete in 1990 8/26/19 - Spill reassigned to Kim as per Obligado. 1/14/20 - Kim - PBS 2-475866: multiple tanks with a total capacity of 4,950 gallons of fuel were closed. 3/14/89 FDNY tested 6 tanks that failed (1) 5,000 gallon tank and (5) 550 gallon tanks. 7/25/90 tanks were closed-in-place i.e. purged and filled with concrete. 8/31/21 - Kim - No other spill or remediation site at this address on 3rd Ave was found that was associated with this spill. No other spill or remediation site at this address on 3rd Ave, 10th St, 11th St, or 12th St was found that could be associated with this spill. Based on the amount of time passed since the spill was reported, and no currently reported impacts - spill case closed."
Remarks:	"(6) 550 GALLON TANKS WERE TESTED BY FIRE DEPT, TANKS ARE LEAKING, LEAK ORDER FOR INVESTIGATION ISSUED BY CITY."

All TTF:

Facility ID:	8809911
Spill Number:	8809911
Spill Tank Test:	1535283
Site ID:	66897
Tank Number:	Not reported
Tank Size:	0

498 3RD AVENUE (Continued) **S100167654**

Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	66897
Operable Unit ID:	926214
Operable Unit:	01
Material ID:	451084
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI439 **K - METROPOLITAN MGP** **NY SHWS** **S108667326**
WSW **124-136 SECOND AVE** **NY BROWNFIELDS** **N/A**
1/2-1 **BROOKLYN, NY 11215**
0.539 mi.
2846 ft. **Site 1 of 2 in cluster BI**

Relative:
Lower

Actual:
13 ft.

SHWS:

Name:	K - METROPOLITAN MGP
Address:	124-136 SECOND AVE
City,State,Zip:	BROOKLYN, NY 11215
Program:	HW
Site Code:	372656
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	11.000
HW Code:	224046
Record Add:	10/27/2006
Record Upd:	03/18/2021
Updated By:	DJEATON
Site Description:	"Location: The Metropolitan Gas Works site is located at the intersection of 12th Street and Second Avenue in South Brooklyn. It is bounded on the west by the Gowanus Canal, on the north by 10th St., on the east by 2nd Avenue and on the south by 13th St. Site Features: The site is approximately 11 acres and completely developed. The original plant footprint is occupied by a large home improvement center, a strip mall and parking lots that serve them. The surrounding neighborhood is primarily industrial and commercial, with some residential properties within a few blocks. Past use of the site: The site was occupied by a large manufactured gas plant (MGP)

K - METROPOLITAN MGP (Continued) **S108667326**

from the late 1800s to the late 1930s. The MGP converted coal and petroleum products to gas, which was used for heating, cooking, and lighting purposes in the surrounding areas. The process produced large amounts of coal tar wastes which have heavily contaminated the soils beneath the site. The southeastern portion of the plant was remediated in 2001 to 2003. The remediation consisted of the excavation of 3 gas holders and the installation of a Dense Non-Aqueous Phase Liquid (DNAPL) recovery system that is currently operating. The western third of the site (where the actual gas plant was located) is now occupied by a multi-story brick commercial building including a Pathmark grocery store. A Remedial Investigation was conducted in this area between 2009 and 2013. Site Geology and Hydrogeology: Soils on the site consist of fill that overlies a peat/silt/clay meadow mat marsh deposit that lies approximately 16 feet below ground surface (bgs). Beneath the meadow mat are sand and silt glacial outwash deposite. Bedrock is greater than 150 ft.bgs. Groundwater flow is southwest, toward the Gowanus Canal. "

Env Problem: "From 2001 through 2003, the eastern portion of the historic MGP and two adjacent parcels were investigated and portions remediated through excavation of the former oil tanks and Holders No. 1 through 3. In addition, approximately 45 recovery wells were installed along 12th Street and perpendicular to 12th, northeast of Hamilton Place, to allow recovery of non-aqueous phase liquid (NAPL). Coal tar recovery from productive wells has been conducted since installation. At present, three recovery wells continue to collect coal tar. These remedial actions resulted in the eastern portion of the former MGP site and the two adjacent parcels to be administratively closed. A remedial investigation (RI) was performed on other portions of the former MGP site between 2010 and 2012, and a supplemental RI was performed between 2017 and 2019 to investigate the remaining areas of the site previously not accessible. Throughout the course of site investigations, soil and groundwater have been analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), cyanide, metals, pesticides and herbicides. Soil vapor and indoor air have been analyzed for VOCs. A barrier wall is being designed to prevent migration of contamination into the Gowanus Canal and is anticipated to be completed in 2023. This project and timeline follow the EPA s plan and schedule for remediation of the Gowanus Canal. Monitoring/recovery wells will be installed behind the sealed bulkhead/barrier wall to capture and remove any collectable residual coal tar at depth. This recovery system along with the barrier wall will remove mobile coal tar from the site and prevent any off-site migration of residual coal tar. Nature and Extent of Contamination: The principal contaminant of concern at the site is MGP related coal tar and associated petroleum contamination. Coal tar contains various volatile organic compounds (VOCs), primarily benzene, toluene, ethylbenzenes, and xylenes (collectively known as BTEX). A family of compounds referred to as polycyclic aromatic hydrocarbons (PAHs) are also associated with MGP coal tar. Subsurface impacts were observed in the following general areas: the area of former oil and tar tanks, located in the western portion of the former Pathmark footprint; in the area of former gas Holder No. 4 located beneath the central portion of the former Pathmark building extending to the west; and, in the area of former gas Holder No. 5 and downgradient of former gas Holder No. 1 through 3, near the intersection of 12th Street and Hamilton Place. Soil: Coal tar impacts have been observed across the site at various depths

K - METROPOLITAN MGP (Continued) **S108667326**

ranging from approximately one to 75 feet below grade (ft bg). MGP-related impacts to site soils primarily consist of BTEX and PAH compounds. The impacted soils are observed to generally correspond with locations of former MGP structures. Both the maximum BTEX and PAH concentrations were identified in samples collected from the area of former Holder No. 5 in the interval at 35 to 40 ft bg. The maximum BTEX concentration was 1,639 mg/kg and the maximum PAH concentration was 14,106.2 mg/kg. Cyanide was detected at low, estimated concentrations, with a maximum detection of 0.24 mg/kg in the 35-40 ft bg interval. There were two detections of PCBs in soils across the site, the maximum detection was 0.081 mg/kg in the 46 to 47.5 ft bg interval. Several metals, including arsenic, barium, copper, lead and mercury, have been detected in soils exceeding the corresponding Soil Cleanup Objectives (SCOs). There have been no detections of pesticides or herbicides above site SCOs. Groundwater: Groundwater at the site has been impacted by MGP related contaminants of concern including coal tar in the form of non-aqueous phase liquid. Groundwater exceedances of standards and guidance values primarily included total BTEX, PAHs, and metals with limited occurrences of cyanide. No PCBs, pesticides or herbicides were detected in groundwater above respective standards. In general, the greatest impacts were detected in the intermediate groundwater zone, consistent with the highest impacted soil horizon. MGP-related impacts in the deep groundwater zone appear to be limited to the area of the former tar tanks. Total BTEX in groundwater ranged from non-detect (ND) to 15,100 parts per billion (ppb). Total PAHs in groundwater ranged from ND to 5,885 ppb. Numerous metals were detected above their corresponding standards, including arsenic, iron, lead, magnesium, manganese, and sodium, likely associated with regional conditions rather than historical site operations. Total cyanide concentrations in groundwater ranged from ND to 279 parts per million (ppm). Soil Vapor: Soil vapor and indoor air samples were collected at the site to assess vapor intrusion conditions. No potentially MGP-related constituents were detected in indoor air or sub-slab soil vapor above the typical background indoor air concentrations from public and commercial buildings. Non MGP-related constituents were either not detected in indoor air and sub-slab soil vapor or detected in concentrations that indicated an indoor source of VOCs was present. Paired indoor air and sub-slab soil vapor samples do not indicate a complete vapor intrusion pathway. Special Resources impacted: No special resources were identified. The adjacent portion of the Gowanus Canal is heavily contaminated from a variety of sources including other MGP sites nearby, but specific impacts to the canal from this particular MGP site have not been identified. Any off-site tar migration appears to be taking place at depths below the bottom of the canal. "

Health Problem: "Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates soil vapor intrusion is not a concern for onsite or offsite buildings."

K - METROPOLITAN MGP (Continued) **S108667326**

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2006-10-31 16:33:00
Record Upd:	2013-09-20 14:14:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 12201-6401
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Two Trees Management Co, LLC
Owner Address:	45 Main Street, 12th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	224046
Waste Type:	BENZENE
Waste Quantity:	26.00
Waste Code:	Not reported
HW Code:	224046
Waste Type:	BENZENE
Waste Quantity:	26.00
Waste Code:	Not reported
HW Code:	224046
Waste Type:	BENZENE
Waste Quantity:	26.00
Waste Code:	Not reported
HW Code:	224046
Waste Type:	TOLUENE
Waste Quantity:	3000.00
Waste Code:	Not reported
HW Code:	224046
Waste Type:	NAPHTHALENE
Waste Quantity:	810.00
Waste Code:	Not reported
HW Code:	224046
Waste Type:	NAPHTHALENE
Waste Quantity:	810.00
Waste Code:	Not reported
HW Code:	224046
Waste Type:	NAPHTHALENE
Waste Quantity:	810.00
Waste Code:	Not reported
HW Code:	224046

K - METROPOLITAN MGP (Continued) **S108667326**

Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224046
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	130.00
Waste Code:	Not reported
Crossref ID:	v00405
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2010-01-19 10:10:00
Record Updated:	2010-01-19 10:10:00
Updated By:	SMWITHER

BROWNFIELDS:

Name:	K - METROPOLITAN MGP
Address:	124-136 SECOND AVE
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	57384
Acres:	7.800
HW Code:	C224046
SWIS:	2401
Town:	New York City
Record Added Date:	04/30/2004
Record Updated Date:	12/01/2009
Update By:	MOBARRIE
Site Description:	"See Site 224046"
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported

K - METROPOLITAN MGP (Continued) **S108667326**

Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

BI440
WSW
1/2-1
0.539 mi.
2846 ft.

BU-METROPOLITAN MGP **EDR MGP** **1008407883**
124-136 SECOND AVE **N/A**
BROOKLYN, NY 11215

Site 2 of 2 in cluster BI

Relative:
Lower

Actual:
13 ft.

Manufactured Gas Plants:
No additional information available

441
West
1/2-1
0.563 mi.
2972 ft.

FORMER CITIZEN GAS WORKS MGP SITE (CAROL **EDR MGP** **1008407888**
5TH STREET AND SMITH STREET TO GOWANUS CANAL **N/A**
BROOKLYN, NY 11215

Relative:
Lower

Actual:
22 ft.

Manufactured Gas Plants:
No additional information available

442
WNW
1/2-1
0.595 mi.
3139 ft.

CARROLL GARDENS **NY DEL SHWS** **S105972444**
CORNER OF 5TH STREET & SMITH STREET **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
37 ft.

DEL SHWS:

Name:	CARROLL GARDENS
Address:	CORNER OF 5TH STREET & SMITH STREET
City,State,Zip:	BROOKLYN, NY
Year:	Not reported
Site Code Id:	224012
Site Classification:	D1
Region:	2
Epa Id Number:	Not reported
Site Type - Dump:	No
Site Type - Structure:	No
Site Type - Lagoon:	No
Site Type - Landfill:	No
Site Type - Treat Pond:	No
Site Size (Acres):	6 Acres
Site Size Comment:	Not reported
Period Assoc/HW Start:	Not reported
Period Assoc/HW End:	Not reported
Lat/Long:	40 40' 33 / 73 59' 46
Lat/Long Decimal:	0.00000 / 0.00000
Lat/Long (dms):	0 0 0 / 0 0 0
Hazardous Waste Code:	Not reported
Hazard Waste Disposed:	Not reported

CARROLL GARDENS (Continued) **S105972444**

Quantity:	Not reported
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	No
Soil Type:	Not reported
Sediment Data Available:	No
GW Std Contravention:	No
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	No
Federal Legal Action:	No
Enforce Status Code:	Not reported
Remedial Act Proposed:	No
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	Not reported
Depth To Groundwater:	Not reported
Owner Name:	NYC Department of Real Property
Owner Address:	2 Lafayette Street
Owner City,St,Zip:	New York, NY 10007
Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Dump
HW Disposal Period:	From: unknown To:
Analytical Data Available:	Groundwater, Surface Water, Soil
Applicable Std Exceeded:	Groundwater, Surface Water
Geotech Info:	Sand and till.
Depth To Groundwater:	Range: 10 to 20 feet.
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	This site was formerly owned by the Brooklyn Union Gas Company, which operated a coal gasification plant. It is believed that products from previous operations may have been disposed at this site. The site is currently vacant and located in a mixed industrial/residential area. Single family homes and a concrete product manufacturing plant are adjacent to the site. At one time, residential housing was proposed for construction at this location. The lot is littered with debris piles, cinder blocks, old lumber and at least fourteen 55-gallon drums embedded in concrete. The NYSDEC has received the final Phase II site investigation report, but is awaiting the analytical results of the sampling of the 55 gallon drums disposed on site. These drums were sampled separately in December 1990. Analytical data for the 3 drums sampled in 1990 revealed that the waste present in the drums originated from a petroleum hydrocarbon source and is not classified as hazardous waste.
Confirmed HW:	Methylene Chloride: unknown

CARROLL GARDENS (Continued) **S105972444**

Environment Assesment:	Environmental problems not established.
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	0
NYTM Y:	0
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Not reported
Description:	Not reported
Record Added Date:	Not reported
Record Updated Date:	Not reported
Env Assessment:	Not reported
HW Disposed/Quantity:	Not reported
Assess/Env Prog:	Not reported
Assess/Health Prob:	Not reported
Site Description:	Not reported

443
WSW
1/2-1
0.638 mi.
3369 ft.

USPS GOWANUS SITE. FORMER MGP METROPOLIT **EDR MGP** **1008407902**
2ND AVENUE AND 12TH STREET **N/A**
BROOKLYN, NY 11215

Relative:
Lower

Actual:
12 ft.

Manufactured Gas Plants:
No additional information available

444
WSW
1/2-1
0.868 mi.
4584 ft.

FORMER BARRETT MANUFACTURING CO.
627 SMITH ST.
BROOKLYN, NY 11231

NY SHWS **S112818546**
NY BROWNFIELDS **N/A**

Relative:
Lower

Actual:
1 ft.

SHWS:

Name:	FORMER BARRETT MANUFACTURING CO.
Address:	627 SMITH ST.
City,State,Zip:	BROOKLYN, NY 11231
Program:	HW
Site Code:	466165
Classification:	N
Region:	2
Acres:	1.040
HW Code:	224163
Record Add:	07/06/2012
Record Upd:	05/24/2013
Updated By:	BXANDERS

Site Description: "See site C224163 Location: The 45,400 square foot site is located at 627-641 Smith Street in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site currently consists of a vacant 1-story warehouse and an asphalt-paved parking lot. The site warehouse is connected to the warehouse on the lot to the south. Current Zoning/Use(s): The site is currently zoned as M3-1 (manufacturing). Historical Use(s): The Site was occupied by Barrett Manufacturing Company, Storage and Shipping in the early 1900s. Later, Colonial Sand and Stone Company occupied the site in the 1950s. Black Diamond Cargo Line and Pittston Stevedoring Storage occupied the Site from the early 1960?s to the 1990s. The original occupant, Barrett Manufacturing, utilized nine coal tar storage tanks and two gasoline underground storage tanks (USTs) as part of their production of coal tar and roofing material. Additionally, Barrett Manufacturing operations occupied the entire city block west of the site (Block 492). Block 492 currently consists of three Lots: Lot 1, Lot 15, Lot 20. Block 492, Lot 1 is a State Superfund Site: Chemtura 633 Court Street ID No. 224146. Site Geology and Hydrogeology: Soil borings conducted between 2005 and 2012 indicate there are alternating layers of sand and dense clay. Two to four separate aquifers are present at the site, separated by clay confining layers. Groundwater is present at a depth of 2 ? 4 feet below grade."

Env Problem: "See site C224163 Nature and Extent of Contamination: Soil ? Coal tar related VOCs and SVOCs are present above Unrestricted Use SCOs. These include naphthalene (7,700 mg/kg), benzo(a)anthracene (280 mg/kg), benzo(a)pyrene (250 mg/kg), and benzo(b)fluoranthene (190 mg/kg). Contaminated soil is present on-site in the vicinity of the former tar storage tanks, and extends to the eastern property boundary, which is bordered by the Gowanus Canal. Additionally, the area of contaminated soil extends off-site to the south, and upgradient to the west. High soil VOCs and SVOCs upgradient and adjacent to Block 492 indicate that Block 492 may be a source of coal tar related VOCs and SVOCs. Groundwater ? VOCs and SVOCs are present above Class GA Standard in twenty monitoring wells. The groundwater plume has not been delineated to the south or to the west.VOC and SVOC contamination extends to the eastern property boundary, which is bordered by the Gowanus Canal. Napthalene is present at a concentration of up to 17,000 ug/l. Benzene is present at a maximum concentration of 11,000 ug/l. Toluene is present at a concentration of up to 7,300 ug/l. Soil Vapor ? Soil vapor samples have not been

FORMER BARRETT MANUFACTURING CO. (Continued) **S112818546**

collected. Significant Threat: No evaluation has been made thus far to determine if the contaminants represent an environmental significant threat."

Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	c/o Crown Acquisitions, Inc.
Owner Company:	Red Hook Developers Holdings, LLC
Owner Address:	362 Fifth Avenue
Owner Addr2:	Suite 1201
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	CF Smith, LLC
Owner Address:	404 Fifth Avenue
Owner Addr2:	5th Floor
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BROWNFIELDS:

Name:	RED HOOK SMITH STREET
Address:	627 SMITH ST.
City,State,Zip:	BROOKLYN, NY 11231
Program:	BCP
Site Code:	476652
Acres:	1.960
HW Code:	C224163
SWIS:	2401
Town:	New York City
Record Added Date:	12/12/2012
Record Updated Date:	04/18/2022
Update By:	SMQUANDT
Site Description:	"Location: The 1.96-acre site is located in an urban area of

FORMER BARRETT MANUFACTURING CO. (Continued) **S112818546**

Brooklyn. The site is bounded by Smith Street to the west, the Gowanus Canal to the east and south, and an industrial property to the north. Site Features: Two tax parcels comprise the site: Block 493, Lot 1 and Block 495, Lot 1. The site includes approximately 750-linear feet of waterfront along the Gowanus Canal at the mouth of the Gowanus Bay. The site was formerly developed with a one-story warehouse that was demolished in 2018, leaving the site vacant with asphalt and concrete surfaces. Current Zoning and Land Use(s): The site is zoned M-3, heavy manufacturing which also allows certain retail and commercial uses. Past Use of the Site: Barrett Manufacturing occupied Block 493 (northern area of the site) circa 1900 to 1940 and utilized nine coal tar storage tanks as part of their production of coal tar and roofing material. The facility also extended to the west of the site (hydraulically up-gradient). After Barrett Manufacturing sold the property in the 1950s, two gasoline underground storage tanks (USTs) were installed on the property. Various manufacturing and storage companies occupied Block 495 (southern part of the site) including: an ice company in the early 1900s; a dock and seaboard storage company from approximately 1930 to 1950; and a cargo line and storage company from the late 1960s to the 1990s. Site Geology and Hydrogeology: Site topography is relatively flat, gently sloping downward to the east-southeast towards the Gowanus Canal. The site is underlain by historic urban fill that extends to approximately 12 feet below grade surface (bgs). The historic fill generally consisted of sand, silt, clay, gravel, cobbles, with wood and brick fragments, cinder, and ash. A native clay lens containing some organic material was identified at varying depths (12 to 14 feet bgs). Native fine sand and silt were identified beneath the clay to a depth of 50-feet bgs. Bedrock was not encountered during this investigation. The depth to groundwater is approximately five feet below the ground surface and flows to the east-southeast towards the Gowanus Canal."

Env Problem:

"Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for per- and polyfluoroalkyl substances (PFAS). Soil vapor was analyzed for VOCs. The primary contaminants of concern are coal tar in soil and floating on the groundwater, SVOCs (total) and naphthalene in soil and naphthalene in groundwater. Soil: The primary soil contamination concern is the presence of coal tar and tar-like material across the site and to a maximum depth of 48 feet below ground surface (bgs). Grossly-impacted soils were observed in a soil boring, in both historic fill from 10-12 feet bgs and native material from 30 to 48 feet bgs, as well as a monitoring well boring from 6 to 27 feet bgs. In addition to the coal tar, SVOCs were detected to a depth of 5 to 6 feet bgs at levels exceeding commercial use soil cleanup objectives (CSCOs) and/or protection of groundwater soil cleanup objectives (PGWSCOs), where applicable, including: total SVOCs up to 18,518 parts per million (ppm), naphthalene up to 7,500 ppm (CSCO 500 ppm and PGWSCO 12 ppm), benzo(a)anthracene up to 31 ppb (CSCO 5.6 ppm), benzo(a)pyrene up to 74 ppm (CSCO 1 ppm), benzo(b)fluoranthene up to 71 ppm (CSCO 5.6 ppm and PGWSCO 1.7 ppm), and indeno(1,2,3-cd)pyrene up to 32 ppm (CSCO 5.6 ppm and PGWSCO 8.2 ppm). One VOC, 1,2,4-trimethylbenzene, was detected in two locations at 210 ppm and 270 ppm, above its CSCO of 190 ppm. Metals were detected at levels exceeding CSCOs to a depth of 6 feet bgs as follows: lead up to

FORMER BARRETT MANUFACTURING CO. (Continued) **S112818546**

15,000 ppm (CSCO 1,000 ppm) and copper up to 2,600 ppm (CSCO 270 ppm). No PCBs or pesticides were detected in soil above CSCOs. Site-related soil impacts may be migrating off-site. Groundwater: Coal tar was encountered beginning near the ground surface and extending well into groundwater, located at approximately 5 feet bgs, to a maximum depth of 47 feet bgs. VOCs detected above Class GA Ambient Water Quality Standard (AWQS) include: benzene up to 550 parts per billion (ppb) (AWQS is 1 ppb), ethylbenzene up to 1,400 ppb (AWQS is 5 ppb), toluene up to 1,500 ppb (AWQS is 5 ppb), total xylene up to 3,200 ppb (AWQS is 5 ppb), and 1,2,4-trimentylbenzene up to 41 ppb (AWQS 5 ppb).. The following SVOCs were detected above AWQS: naphthalene up to 13,000 ppb (AWQS is 10 ppb), phenol up to 200 ppb (AWQS is 1 ppb), acenaphthene up to 500 ppb (AWQS is 20 ppb), 2,4-dimethylphenol up to 1,100 ppb (AWQS is 50 ppb), anthracene up to 82 ppb (AWQS is 50 ppb), benzo(b)fluoranthene up to 0.3 ppb (AWQS is 0.002 ppb), benzo(k)fluoranthene up to 0.17 ppb (AWQS is 0.002 ppb), bis(2-ethylhexyl)phthalate up to 7.2 ppb (AWQS is 5 ppb), chrysene up to 0.28 ppb (AWQS is 0.002 ppb), fluorene up to 260 ppb (AWQS is 50 ppb), indeno(1,2,3-cd) up to 0.17 ppb (AWQS is 0.002 ppb), and phenanthrene up to 190 ppb (AWQS is 50 ppb). For PFAS, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations up to 126 parts per trillion (ppt) and 41.4 ppt, respectively, exceeding the Maximum Contaminant Level (MCL) (drinking water standard) of 10 ppt each in groundwater. There are no public water supply wells within a half a mile and there is a municipal prohibition for use of groundwater at the site. PCBs, metals, and pesticides were not detected above AWQS in site groundwater. Site-related groundwater impacts may be migrating off-site. Soil Vapor: Fifteen soil vapor samples were collected from approximately two feet bgs and analyzed for VOCs. Results detected benzene, toluene, ethylbenzene and xylene (BTEX) a across the site up to 1,304 micrograms per cubic meter (g/m3). The chlorinated VOC tetrachloroethene (PCE) was also detected up to 59.2 g/m3 but is not thought to be site related since PCE was not detected above standards in soil or groundwater at the site. The data do not indicate any off-site impacts in soil vapor related to this site."

Health Problem: "Direct contact with contaminated soil is unlikely because the site is completely fenced, which restricts public access, and is covered by concrete. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil), may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern because there are no buildings on-site, however the potential for indoor air impacts via the soil vapor intrusion pathway exists for any future occupied buildings. Sampling indicates soil vapor intrusion is not a concern for off-site structures."

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown

FORMER BARRETT MANUFACTURING CO. (Continued) **S112818546**

Disp Term:	unknown
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-10-25 15:30:00
Record Upd:	2016-08-18 15:11:00
Updated By:	CHPOST
Own Op:	6
Sub Type:	P03
Owner Name:	Emzon Shung
Owner Company:	Red Hook Developers Holdings, LLC
Owner Address:	1400 Broadway, 15th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brookklyn, NY 11238
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Emzon Shung
Owner Company:	Red Hook Developers Holdings, LLC
Owner Address:	1400 Broadway
Owner Addr2:	15th Floor
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	CF Smith, LLC
Owner Address:	404 Fifth Avenue
Owner Addr2:	5th Floor
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
HW Code:	C224163
Waste Type:	coal tar
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	benzene
Waste Quantity:	UNKNOWN

FORMER BARRETT MANUFACTURING CO. (Continued) **S112818546**

Waste Code:	Not reported
HW Code:	C224163
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	creosote
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224163
Waste Type:	coal tar pitch volatiles
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224163-03-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:53:00
Record Updated:	2020-02-10 08:53:00
Updated By:	CHPOST
Crossref ID:	C224215
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-05-11 11:00:00
Record Updated:	2015-05-11 11:00:00
Updated By:	CHPOST
Crossref ID:	0500510
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2012-12-12 16:08:00
Record Updated:	2012-12-12 16:08:00
Updated By:	BXANDERS
Crossref ID:	224197
Cross Ref Type Code:	09
Cross Ref Type:	DEC Case No.
Record Added Date:	2015-04-17 11:52:00
Record Updated:	2015-04-17 11:52:00
Updated By:	CHPOST

BJ445 **182 SIGOURNEY ST** **NY SHWS** **S117667764**
WSW **182 SIGOURNEY ST** **N/A**
1/2-1 **BROOKLYN, NY 11231**
0.911 mi.
4808 ft. **Site 1 of 2 in cluster BJ**

Relative:
Lower

Actual:
8 ft.

SHWS:

Name:	182 SIGOURNEY ST
Address:	182 SIGOURNEY ST
City,State,Zip:	BROOKLYN, NY 11231
Program:	HW
Site Code:	499845

182 SIGOURNEY ST (Continued) **S117667764**

Classification: P
Region: 2
Acres: 0.290
HW Code: 224197
Record Add: 09/15/2014
Record Upd: 04/14/2022
Updated By: SMQUANDT
Site Description: "Location: The 182 Sigourney St. Site is a 0.87-acre site located in the Red Hook section of Brooklyn. The site consists of two parcels listed as Block 492, Lot 20 (628 Smith Street) and Block 492, Lot 15 (182 Sigourney Street) on NYC tax maps. The site is at the intersections of Halleck Street, Smith Street and Sigourney Streets. The site is approximately 200-300 feet west of the Gowanus Canal. Site Features: The site is current primarily covered with a multi-story brick building with courtyard parking accessible from Sigourney Street. Current Zoning and Land Use: The site is currently zoned and M-1 (industrial) and is actively used for commercial and industrial operations. Historical Use: The properties that make up this site were part of a large tar paper manufacturing facility. A 1904 Sanborn Insurance Map depicts coal tar products, asphalt tanks and various oil tanks (including a 14,000-gallon underground tank). The Sanborn Map indicates that this property was operated by Barrett Manufacturing Company. The facility extended from Court Street to the Gowanus Canal. Site Geology and Hydrogeology: Based on geological information at an adjacent site, the groundwater at this property is anticipated to be approximately 5 feet bgs. Groundwater flow is anticipated to flow toward the Gowanus Canal traveling east and/or southeast. Much of this area is reclaimed water front property with fill material anticipated to exist from 0 to 12 feet bgs. A gray colored, discontinuous clayey layer (former base of the Gowanus Canal) is also anticipated beneath the fill material with a thickness varying up to eight feet."
Env Problem: "Investigations at adjacent properties indicate tar-like source material, light non-aqueous phase liquid (LNAPL) and petroleum VOCs are present in the soil and at the soil/groundwater interface. Downgradient and to the east of this potential site is the Red Hook Smith Street Brownfield Cleanup Program (volunteer) site (C224163) where tar-like material, metals, VOCs and SVOCs were identified. West of this potential site is the 633 Court St. (Chemtura #224146) site and the Red Hook Smith Recreation Area; tar-like material has been identified in each of these locations. A portion of the Red Hook Smith Street BCP and the 633 Court Street (Chemtura) property were both previously part of the former Barrett Manufacturing property. To the south is a State Superfund P-site (224196) where tar boils have been identified on site, which was initially Mica Roofing Company. Investigation of this site is warranted."
Health Problem: "As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

182 SIGOURNEY ST (Continued) **S117667764**

Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Jerrold Lerner
Owner Company:	Magrill Bros, Inc.
Owner Address:	247 W. 16th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10011-6065
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	610 Smith St. Corp.
Owner Address:	111 John St. Rm 312
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10038-3135
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BJ446 **CHEMTURA 633 COURT STREET** **NY SHWS** **S113828311**
WSW **633 COURT STREET** **N/A**
1/2-1 **BROOKLYN, NY 11231**
0.918 mi.
4846 ft. **Site 2 of 2 in cluster BJ**

Relative:
Lower

Actual:
7 ft.

SHWS:

Name:	CHEMTURA 633 COURT STREET
Address:	633 COURT STREET
City,State,Zip:	BROOKLYN, NY 11231
Program:	HW
Site Code:	443256
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	0.503
HW Code:	224146
Record Add:	12/10/2010
Record Upd:	04/18/2022
Updated By:	SMQUANDT
Site Description:	"Location: The site is located at 633 Court Street, Kings County, Brooklyn, New York within the Red Hook Industrial area of Brooklyn. The Site is located northeast of the Court Street and Halleck Street intersection. The site is immediately bordered to the south by Halleck Street and a National Grid truck facility, to the north by a paper street (Sigourney Street) and a petroleum cartage and storage (trucking) company. To the east there is small vacant lot and a

CHEMTURA 633 COURT STREET (Continued) **S113828311**

warehouse. A recreational park (Red Hook Smith Recreational Park) is located directly across Court Street to the west of the site. Additionally, an oil terminal that is currently owned by Buckeye Partners, L.P. is located approximately one block to the south of the site. Site Features: The entire site is completely developed and covered with two connected adjoining buildings. The building's foundations are slab on grade concrete and there are no basements. These buildings were formerly used by Chemtura's predicesor companies for chemical manufacturing and chemical laboratory operations. Current Zoning and Land Use: The site is currently active, and is zoned M3-1 for industrial use, however this zoning designation allows for certain commercial uses. Several tenants occupy the site including a wholesale food and food product supply warehouse and offices. The M3-1 does not allow for residential use at this site. The surrounding parcels are currently used for a combination of commercial, light industrial and utility right-of-ways. The park located to the west is zoned residential and is used exclusively for recreational purposes. The nearest residential structure is approximately one-half miles to the north. Past Use of the Site: In 1904 the site was owned by Barrett Manufacturing and was used for the manufacturing of tar paper. Barrett Manufacturing Company is a predecessor company to Honeywell International, Inc. Tar tanks, storage tanks, stills, a pitch shed and an oil house were located on-site. In the 1940s Doran Manganese Bronze Company, Inc. Foundry & Machine Shop occupied the site. In the 1940s to 1950s, Argus Chemical Laboratory, a predecessor company to Chemtura, purchased and operated the site. Argus Chemical Laboratory was subsequently purchased by Witco (also a predecessor company to Chemtura) in the early 1960s. Under Argus and Witco ownership, the plant produced metallic-organic soaps and salts, barium stearates, phosphites and epoxy plasticizers. During the 1950s and 1960s, aluminum paste was produced in a process on the roof of one of the buildings. This production ceased in the late 1950s to early 1960s and all plant operations were relocated to a parcel of land located to the southwest of the 688 Site. The laboratory and offices remained at the 633 Site until approximately 1990 when these functions were relocated to 688 Court Street. Site Geology and Hydrogeology: The Site is improved with impervious surfaces (concrete foundation of an active commercial building) which precluded extensive subsurface investigations. However, it is known that the Site and the surrounding area is reclaimed water front from what is now known as the Gowanus Canal. This historic fill material was observed from 0 to 12 ft below the ground surface (bgs). The fill material consisted primarily of fine to coarse sand-sized particles with varying amounts of silt and miscellaneous debris (ash, slag, coal, wood, brick, concrete, etc.). Underlying the fill materials, a silt-clay layer was encountered. This layer has a relatively low permeability and is believed to continue laterally across the site. This layer is gray in color and is believed to be about eight-feet thick. The Site is located approximately 400 feet west of the Gowanus Canal and ground water elevations ranges from approximately 3.5 to 6 feet bgs. Kings County lies within the Long Island aquifer system and overlies a sole-source aquifer. "

Env Problem: "Nature and Extent of Contamination: Based on investigations conducted to date, the primary contaminants of concern at the site include toluene, ethylbenzene, xylene, semi-volatile organic compounds (SVOCs)/polycyclic aromatic hydrocarbons (PAHs), phenol,

CHEMTURA 633 COURT STREET (Continued) **S113828311**

and metals. Soil: The VOCs toluene, ethylbenzene and xylene are found in soil from the surface to the water table. Benzene is found at 13 parts per million (ppm) at the center of the site and at 15 ppm at southern boundary of the site. This contamination is above the groundwater protection soil cleanup objective (SCO) of 0.06 parts per million (ppm) for benzene. PAHs are found throughout site soil. Benzo(a)pyrene is found in concentrations up to 62 ppm which is above the protection of groundwater SCO of 22 ppm. Metals are found throughout site soil. Lead was as high as 618 ppm, barium was found up to 590 ppm, cadmium was found up to 340 ppm, arsenic was found as high as 14.6 ppm and mercury was found as high as 2.4 ppm. Groundwater: Toluene, ethylbenze, xylene, naphthalene and benzene are found in groundwater at concentrations up to 240, 300, 530, 3,000 and 48 parts per billion (ppb), respectively which are all above the groundwater standards of 5, 5, 5, 10 and 1 ppb, respectively. SVOCs pyrene and naphthalene are found in groundwater at concentrations up to 200 and 6,400 ppb, respectively, which are above the groundwater guidance values of 50 and 10 ppb, respectively. Soil Vapor: Two rounds of sub-slab soil vapor sampling were performed. Based on the results DOH indicated that no further sampling or mitigation would be required."

Health Problem:	"Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for existing on-site buildings. An evaluation of the potential for soil vapor intrusion is recommended for any future on-site buildings. Surrounding properties are in various cleanup programs and the potential for soil vapor intrusion at those sites will be evaluated separately."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-02-15 16:10:00
Record Upd:	2013-04-22 12:46:00
Updated By:	KPSARNOW
Own Op:	1
Sub Type:	NNN
Owner Name:	Alan Hertz
Owner Company:	Alan B. Hertz, P.C.
Owner Address:	934 East 19th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11230
Owner Country:	United States of America

CHEMTURA 633 COURT STREET (Continued) **S113828311**

HW Code:	224146
Waste Type:	PHENANTHRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146

CHEMTURA 633 COURT STREET (Continued) **S113828311**

Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224146
Waste Type:	PHENOL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	V00249
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2012-12-28 15:59:00
Record Updated:	2012-12-28 15:59:00
Updated By:	KPSARNOW
Crossref ID:	C224215
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2015-05-11 11:02:00
Record Updated:	2015-05-11 11:02:00
Updated By:	CHPOST

BK447 **643 COURT ST.** **NY SHWS** **S117269718**
WSW **643 COURT ST.** **N/A**
1/2-1 **BROOKLYN, NY 11231**
0.951 mi.
5020 ft. **Site 1 of 2 in cluster BK**

Relative:
Lower

Actual:
5 ft.

SHWS:

Name:	643 COURT ST.
Address:	643 COURT ST.
City,State,Zip:	BROOKLYN, NY 11231
Program:	HW
Site Code:	498440
Classification:	P
Region:	2

643 COURT ST. (Continued) **S117269718**

Acres: 1.377
HW Code: 224196
Record Add: 08/08/2014
Record Upd: 04/18/2022
Updated By: SMQUANDT
Site Description: "Location: The site is located in the Red Hook section of Brooklyn, in the City of New York. The site is listed as Block 494, Lot 1 and is located on the south east corner of Court St. and Halleck St. in close proximity to the Gowanus Canal. An off site area has been designated Operable Unit 2 (OU2). This area is the southeast portion of the Red Hook Park's Soccer Field 1. Site Features: The site is currently a parking lot with a small building near the middle of the site occupying approximately 1/8th of the property acreage. OU2 is an public park with walking paths and a soccer field with an artificial surface. Current Use: The site is currently leased from Red Hook Realty Co. by National Grid who is using the site as a parking lot for their service vehicles. OU2 is a park and is open to the public. Historical Use: The property was used for tar paper manufacturing as depicted in the 1886 Sanborn map which shows tar pitch storage areas on the corners of Smith St./Halleck St. and Court St./Halleck St. OU2 has been a public park since the 1940s. Site Geology and Hydrogeology: Based on geological information at an adjacent site, the groundwater at this property is anticipated to be less than 5 feet bgs. Groundwater flow is anticipated to flow radially from the Gowanus Canal traveling north, northwest, west, southwest, and south. To the south and west of the site, the coastline is lined with sheet piling and to the east of the site, where groundwater enters, the coastline is lined with rip rap. The groundwater is likely saline due to its proximity to the canal. Much of this area is reclaimed water front property with fill material anticipated to exist from 0 to 12 feet bgs. A gray colored, low permeability clayey layer (former base of the Gowanus Canal) is also anticipated to exist beneath the fill material with a thickness of approximately 8 feet. "
Env Problem: "This site has had several instances over the last decade of tar seeping out of the ground, getting cleaned up, and reappearing some time later. Further investigation is required to determine the nature and extent of tar beneath the surface. "
Health Problem: "As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 4
Sub Type: NNN
Owner Name: Richard Schmitz
Owner Company: National Grid
Owner Address: Not reported

643 COURT ST. (Continued) **S117269718**

Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	David Weinberger
Owner Company:	Red Hook Realty Co. (LLC)
Owner Address:	88 Mineola Ave.
Owner Addr2:	PO Box 1356
Owner City,St,Zip:	Roslyn Heights, NY 11577
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BK448 **CHEM TURA** **NY CBS UST** **1001485652**
WSW **688-700 COURT ST** **NY CBS** **NY0001411404**
1/2-1 **BROOKLYN, NY 11231** **NY AST**
0.957 mi. **NY DEL SHWS**
5052 ft. **Site 2 of 2 in cluster BK** **RCRA NonGen / NLR**

Relative:
Lower

Actual:
7 ft.

CBS UST:

Id/Status:	2-000096 / CLOSED IN PLACE
Facility Type:	D
Facility Tel:	(718) 858-8694
Total Tanks:	0
Region:	STATE
ICS No:	2-500035
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	WITCO CORPORATION (POLYMER ADD
Emergency Contact:	MARIE PITTIGNANO
Emergency Contact Phone:	(203) 552-2477
Certification Date:	05/12/1999
Expiration Date:	07/07/2001
Owner Name:	CK WITCO
Owner Address:	ONE AMERICAN WAY
Owner City,State,Zip:	BROOKLYN, NY 11231
Owner Phone:	(203) 552-2477
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	CK WITCO
Mailing Contact:	MARIE PITTIGNANO
Mailing Address:	ONE AMERICAN WAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11231
Mailing Telephone:	(203) 552-2477
Tank Number:	T5016
Date Entered:	07/07/1989

CHEM TURA (Continued) **1001485652**

Capacity:	4000
Chemical:	m-Xylene
Tank Closed:	Not reported
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Install Date:	08/70
CAS No:	108383
Substance:	Not reported
Tank Location:	5
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Leak Detection:	Not reported
Secondary Containmentt:	Vault
Overfill Protection:	Not reported
Haz Percent:	0
Pipe Containment:	Not reported
Pipe Type:	STEEL/IRON
Tank Error Status:	Minor Data Missing
Tank Secret:	F
Date Entered:	12:04:21
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	40|40|10
Longitude:	74|00|13
Renew Date:	04/01/93
Deliquent:	F
Total Capacity:	0
Date Expired:	07/07/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

Id/Status:	2-000096 / NO LONGER A MAJOR FACILITY
Facility Type:	D
Facility Tel:	(718) 858-8694
Total Tanks:	0
Region:	STATE
ICS No:	2-500035
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	WITCO CORPORATION (POLYMER ADD
Emergency Contact:	MARIE PITTIGNANO
Emergency Contact Phone:	(203) 552-2477
Certification Date:	05/12/1999
Expiration Date:	07/07/2001
Owner Name:	CK WITCO

CHEM TURA (Continued) **1001485652**

Owner Address:	ONE AMERICAN WAY
Owner City,State,Zip:	BROOKLYN, NY 11231
Owner Phone:	(203) 552-2477
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	CK WITCO
Mailing Contact:	MARIE PITTIGNANO
Mailing Address:	ONE AMERICAN WAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11231
Mailing Telephone:	(203) 552-2477
Tank Number:	F203
Date Entered:	04/26/1995
Capacity:	4000
Chemical:	Benzene,1-methylethyl-
Tank Closed:	12/99
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Install Date:	06/93
CAS No:	98828
Substance:	Single Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	Epoxy Liner
Tank External:	SACRIFICIAL ANODE
Pipe Location:	Aboveground/Underground Combination
Pipe Internal:	None
Pipe External:	None
Leak Detection:	Interstitial Monitoring
Secondary Containmentt:	Cut-off Walls
Overfill Protection:	High Level Alarm
Haz Percent:	100
Pipe Containment:	None
Pipe Type:	STEEL/IRON
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	14:34:01
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	40|40|10
Longitude:	74|00|13
Renew Date:	04/01/93
Deliquent:	F
Total Capacity:	0
Date Expired:	07/07/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

CBS:

Name:	WITCO CORPORATION (POLYMER ADDITIVES GROUP)
Address:	700 COURT STREET

CHEM TURA (Continued) **1001485652**

City,State,Zip: BROOKLYN, NY 11231
CBS Number: 2-000096
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 584334.54992
UTMY: 4502563.48112

AST:
Name: WITCO CORPORATION (POLYMER ADDITIVES GROUP)
Address: 700 COURT STREET
City,State,Zip: BROOKLYN, NY 11231
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-000096
Program Type: CBS
UTM X: 584334.54992
UTM Y: 4502563.48112
Expiration Date: N/A
Site Type: Manufacturing (Other than Chemical)/Processing

Tank Info:

Tank Number: T1019
Tank Id: 186224
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 04/01/1987
Capacity Gallons: 3300
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: T1022
Tank Id: 186222
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 04/01/1987
Capacity Gallons: 3300
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T1023
Tank Id:	186223
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/01/1987
Capacity Gallons:	3300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T1026
Tank Id:	186220
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/01/1987
Capacity Gallons:	3300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T1027
Tank Id:	186221
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/01/1987
Capacity Gallons:	3300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T206
Tank Id:	190582
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/1982
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1999
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T208
Tank Id:	186209
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	03/01/1982
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T213
Tank Id:	186217
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1982
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2000

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4006
Tank Id:	186215
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Other
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1959
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4019
Tank Id:	186218
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1989
Capacity Gallons:	12000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4022
Tank Id:	186212
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1968
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4023
Tank Id:	186211
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1968
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4034A
Tank Id:	186214
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Other
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	06/01/1986
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/1998
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4042
Tank Id:	186210
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1981
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/1998

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4043
Tank Id:	186207
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1987
Capacity Gallons:	12000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4044
Tank Id:	186208
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1987
Capacity Gallons:	12000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4049
Tank Id:	189457
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Other
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/1989
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2000

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4050
Tank Id:	189454
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1989
Capacity Gallons:	14000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4052
Tank Id:	189455
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/1989
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4053
Tank Id:	189456
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1990
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2000

CHEM TURA (Continued) **1001485652**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4056
Tank Id:	190583
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	07/01/1991
Capacity Gallons:	11700
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T4060
Tank Id:	193293
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/1997
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/1999
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	T5016
Tank Id:	186219
Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	08/01/1970
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

CHEM TURA (Continued) **1001485652**

Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: T6007
Tank Id: 186216
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Other
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1959
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: T6016
Tank Id: 186213
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/01/1979
Capacity Gallons: 14000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1999
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

DEL SHWS:
Name: CHEMTURA 688-700 COURT STREET
Address: 688-700 COURT STREET
City,State,Zip: BROOKLYN, NY 11231
Year: Not reported
Site Code Id: Not reported
Site Classification: Not reported
Region: 2
Epa Id Number: Not reported
Site Type - Dump: No
Site Type - Structure: No
Site Type - Lagoon: No
Site Type - Landfill: No
Site Type - Treat Pond: No

CHEM TURA (Continued) **1001485652**

Site Size (Acres):	Not reported
Site Size Comment:	Not reported
Period Assoc/HW Start:	Not reported
Period Assoc/HW End:	Not reported
Lat/Long:	Not reported
Lat/Long Decimal:	Not reported
Lat/Long (dms):	Not reported
Hazardous Waste Code:	224145
Hazard Waste Disposed:	Not reported
Quantity:	Not reported
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	No
Soil Type:	Not reported
Sediment Data Available:	No
GW Std Contravention:	No
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	No
Federal Legal Action:	No
Enforce Status Code:	Not reported
Remedial Act Proposed:	No
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	Not reported
Depth To Groundwater:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Not reported
HW Disposal Period:	Not reported
Analytical Data Available:	Not reported
Applicable Std Exceeded:	Not reported
Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported

CHEM TURA (Continued) **1001485652**

Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Access to the site is restricted. However, persons who enter the site could contact contaminants in the soil by walking on the site, digging or otherwise disturbing the soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sampling indicates soil vapor intrusion is not occurring on-site and is not a concern for off-site buildings.
Description:	Location:The site is located at 688-700 Court Street within the Red Hook Industrial area of Brooklyn. The site is located southwest of the Court Street and Halleck Street intersection.Site Features:The site is relatively flat and mostly covered with blacktop and concrete. A small area in the southeast corner has a soil cover. Several previously decommissioned site buildings were either removed or rehabilitated without the Department's approval. The site is occupied by several tenants including a garbage hauling company, a motor coach repair facility, an electronics distribution warehouse, a commercial laundry repair business, a stone cutting business and a sheet metal fabricator. The dual-phase extraction remedial system is not operational. The site is surrounded with a concrete wall of varying height.Current Zoning and Land Use:The site is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial, light industrial and recreational uses. The site is bordered immediately to the east by Court Street, National Grid and Spentonbush Red Star Companies, to the west by Clinton Street and American Import Export Trucking and to the south by Bryant Street and a Buckeye, LLC oil terminal. A recreational park (Red Hook Recreational) is located immediately to the north of the site. Past Use of the Site: Milliken Brothers Iron Works occupied the southwestern portion of the site in 1904. In 1939 John F. McKenna,

CHEM TURA (Continued) **1001485652**

Inc. Lumber Yard, Marine Canvas Supply Corporation and John Menton Boiler Maker occupied the site. The site remained a lumberyard and marine canvas supply business until approximately 1958, when manufacturing at the site began. Historic manufacturing processes at the site include production of metallic-organic soaps and salts, phosphates and epoxy plasticizers. A hot-oil system, that used PCB containing oil, was part of the manufacturing process. Contamination at the site appears related to several historic operations, including materials handling from the chemical manufacturing processes, as well as releases to the environment from the hot oil system. Site Geology and Hydrogeology:The site was formed by backfilling the marsh and waterfront areas of the Gowanus Canal in the late 1800s through the early 1900s. Fill material consisting of fine to coarse sand-sized particles with varying amounts of silt and miscellaneous debris (ash, slag, coal, wood, brick, concrete, etc.) was observed across the site from ground surface to a depth of 12 ft. A clay layer of unkown thickness or continuity was encountered beneath the fill material. This layer is presumed to be the former base of the Gowanus Canal. Th effectiveness of this layer as a low-permeability barrier between the overlying fill and the underlying water-bearing zone located within the glacial deposits beneath the site is unknown.Based on the manmade coastline (rip-rap, pile sheeting), well gauging data and the generalized hydrogeological cross-sections, a horizontal and somewhat radial (north, northwest, west, southwest, south) pathway for groundwater flow exists. Depth to water beneath the site has ranged from 2.0 ft to 9.0-ft bgs over the course of investigation. Groundwater beneath the site is minimally influenced by the tide. Groundwater flow is radial with a high point in the central part of the site.

Record Added Date:	12/03/2010
Record Updated Date:	01/05/2016
Env Assessment:	Not reported
HW Disposed/Quantity:	Not reported
Assess/Env Prog:	Not reported
Assess/Health Prob:	Not reported
Site Description:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:		20121015
Handler Name:	CHEM TURA	
Handler Address:		688-700 COURT ST
Handler City,State,Zip:		BROOKLYN, NY 11231
EPA ID:		NY0001411404
Contact Name:		PAUL MEYER
Contact Address:		BENSON RD
Contact City,State,Zip:		MIDDLEBURY, CT 06749
Contact Telephone:		203-573-3545
Contact Fax:		203-573-3362
Contact Email:		PAUL.MEYER@CHEMTURA.COM
Contact Title:		MANAGER ENVIRONMENTAL REMEDIATION
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported

CHEM TURA (Continued) **1001485652**

State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BENSON RD
Mailing City,State,Zip:		MIDDLEBURY, CT 06749
Owner Name:	VIP BUILDERS LLC	
Owner Type:		Private
Operator Name:	VIP BUILDERS LLC	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No

CHEM TURA (Continued) **1001485652**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D013
Waste Description:	LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)
Waste Code:	D031
Waste Description:	HEPTACHLOR (AND ITS EPOXIDE)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: VIP BUILDERS LLC	
Legal Status:	Private
Date Became Current:	20040323
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CHEM TURA (Continued) **1001485652**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: VIP BUILDERS LLC	
Legal Status:	Private
Date Became Current:	20040323
Date Ended Current:	Not reported
Owner/Operator Address:	C/O CORAL REALTY LLC
Owner/Operator City,State,Zip:	NEW YORK, NY 10013
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: VIP BUILDERS LLC	
Legal Status:	Private
Date Became Current:	20040323
Date Ended Current:	Not reported
Owner/Operator Address:	C/O CORAL REALTY LLC
Owner/Operator City,State,Zip:	NEW YORK, NY 10013
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: VIP BUILDERS LLC	
Legal Status:	Private
Date Became Current:	20040323
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: WITCO CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 AMERICAN LANE
Owner/Operator City,State,Zip:	GREENWICH, CT 06831-2559
Owner/Operator Telephone:	203-552-2000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: WITCO CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 AMERICAN LANE
Owner/Operator City,State,Zip:	GREENWICH, CT 06831-2559

CHEM TURA (Continued) **1001485652**

Owner/Operator Telephone:	203-552-2000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: WITCO CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 AMERICAN LANE
Owner/Operator City,State,Zip:	GREENWICH, CT 06831-2559
Owner/Operator Telephone:	203-552-2000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: WITCO CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: WITCO CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20121015
Handler Name: CHEM TURA	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CHEM TURA (Continued) **1001485652**

Receive Date: 19981127
Handler Name: WITCO CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: CK WITCO CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120718
Handler Name: CHEM TURA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32511
NAICS Description: PETROCHEMICAL MANUFACTURING

NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported

CHEM TURA (Continued) **1001485652**

Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

CHEM TURA (Continued) **1001485652**

SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19990412
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19990406
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2THP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

449
SW
1/2-1
0.975 mi.
5149 ft.

Relative:
Lower

Actual:
6 ft.

SUNSET INDUSTRIAL PARK
74 20TH ST
BROOKLYN, NY 11232

CORRACTS **1000224955**
RCRA-TSDF **NYD091590471**
RCRA-LQG
NY BROWNFIELDS
ICIS
FINDS
ECHO
NY MANIFEST

CORRACTS:

Name:	SUNSET INDUSTRIAL PARK
Address:	74 20TH ST
Address 2:	Not reported
EPA ID:	NYD091590471
Area Name:	SITEWIDE
Corrective Action:	RFA COMPLETED
Actual Date:	19930329
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

Name: SUNSET INDUSTRIAL PARK
Address: 74 20TH ST
Address 2: Not reported
EPA ID: NYD091590471
Area Name: SITEWIDE
Corrective Action: CA PRIORITIZATION-MEDIUM CA PRIORITY
Actual Date: 19940405
Air Release Indicator: Not reported
Groundwater Release Indicator: Not reported
Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

RCRA-LQG:
Date Form Received by Agency: 20211210
Handler Name: SUNSET INDUSTRIAL PARK
Handler Address: 74 20TH ST
Handler City,State,Zip: BROOKLYN, NY 11232-1101
EPA ID: NYD091590471
Contact Name: JOHN PROCEK
Contact Address: GATEHALL DR STE 201
Contact City,State,Zip: PARSIPPANY, NJ 07054
Contact Telephone: 973-998-9890
Contact Fax: Not reported
Contact Email: JPORCEK@BRIDGEDEV.COM
Contact Title: GENERATOR AUTHORIZED REPRESENTATIVE
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: NY
State District: NYSDEC R2
Mailing Address: GATEHALL DR STE 201
Mailing City,State,Zip: PARSIPPANY, NJ 07054
Owner Name: SIP HOLDINGS VENTURE LLC
Owner Type: Private
Operator Name: SIP HOLDINGS VENTURE LLC
Operator Type: Private
Short-Term Generator Activity: Yes
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No
Universal Waste Indicator: No
Universal Waste Destination Facility: No
Federal Universal Waste: No
Active Site Fed-Reg Treatment Storage and Disposal Facility: Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Storage
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Storage
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	Yes
Corrective Action Priority Ranking:	Medium
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211216
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D008

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Waste Description: LEAD

Waste Code: K078
Waste Description: Not Defined

Waste Code: K079
Waste Description: Not Defined

Waste Code: K081
Waste Description: Not Defined

Waste Code: K082
Waste Description: Not Defined

Waste Code: P092
Waste Description: MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U017
Waste Description: BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U069
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U161
Waste Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: SIP HOLDINGS VENTURE LLC
Legal Status: Private
Date Became Current: 20190110
Date Ended Current: Not reported
Owner/Operator Address: 1 GATEHALL DR STE 201
Owner/Operator City,State,Zip: PARSIPPANY, NJ 07054
Owner/Operator Telephone: 973-998-9890
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JPORCEK@BRIDGEDEV.COM

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Owner/Operator Indicator: Operator
Owner/Operator Name: THE DEBEVOISE CO DIV PLC INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 74-20TH ST
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 212-965-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE DEBEVOISE CO DIV PLC INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 74-20TH ST
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 212-965-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE DEBEVOISE CO DIV-PLC INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 74 20TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 212-965-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE DEBEVOISE CO DIV-PLC INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 74 20TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 212-965-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SIP HOLDINGS VENTURE LLC
Legal Status: Private
Date Became Current: 20190110
Date Ended Current: Not reported
Owner/Operator Address: 1 GATEHALL DR STE 201
Owner/Operator City,State,Zip: PARSIPPANY, NJ 07054
Owner/Operator Telephone: 973-998-9890
Owner/Operator Telephone Ext: Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Owner/Operator Fax: Not reported
Owner/Operator Email: JPORCEK@BRIDGEDEV.COM

Historic Generators:
Receive Date: 19801119
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990708
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800813

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20211210
Handler Name: SUNSET INDUSTRIAL PARK
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 236210
NAICS Description: INDUSTRIAL BUILDING CONSTRUCTION

NAICS Code: 32551
NAICS Description: PAINT AND COATING MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Formal Enforcement Agreement or Order
Date Violation was Determined:	19831110
Actual Return to Compliance Date:	19831210
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19831210
Enforcement Identifier:	000
Date of Enforcement Action:	19831110
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R2
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	11500
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	TSD - General
Date Violation was Determined:	19820615

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Actual Return to Compliance Date:	19821109
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	000
Date of Enforcement Action:	19820615
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R2
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	11500
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	TSD - General
Date Violation was Determined:	19820615
Actual Return to Compliance Date:	19821109
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19830521
Enforcement Identifier:	002
Date of Enforcement Action:	19830321
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	7500
Paid Amount:	7500
Final Count:	1
Final Amount:	7500

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19850103
Actual Return to Compliance Date:	19850321
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	19850221
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R2PI
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19831110
Actual Return to Compliance Date:	19841130
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	TSD - General
Date Violation was Determined:	19820615
Actual Return to Compliance Date:	19821109
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	000
Date of Enforcement Action:	19820615
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R2
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	11500
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Formal Enforcement Agreement or Order
Date Violation was Determined:	19831110

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Actual Return to Compliance Date:	19831210
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19831110
Actual Return to Compliance Date:	19841130
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19831210
Enforcement Identifier:	000
Date of Enforcement Action:	19831110
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R2
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	11500
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	TSD - General
Date Violation was Determined:	19820615

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Actual Return to Compliance Date:	19821109
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19830521
Enforcement Identifier:	002
Date of Enforcement Action:	19830321
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	7500
Paid Amount:	7500
Final Count:	1
Final Amount:	7500

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19870612
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19831110
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier: R2PI
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 19831210
Scheduled Compliance Date: 19831210
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19820615
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2PI
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19821109
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19820615
Evaluation Responsible Agency: EPA

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19821109
Scheduled Compliance Date:	19830521
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850103
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19850321
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850129
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19841130
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19820615
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19821109

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19831210
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19860123
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19841130
Scheduled Compliance Date:	19831210
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19820615
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19821109
Scheduled Compliance Date:	19830521
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Evaluation Date:	19841130
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

RCRA-LQG:

Date Form Received by Agency:		20211210
Handler Name:	SUNSET INDUSTRIAL PARK	
Handler Address:		74 20TH ST
Handler City,State,Zip:		BROOKLYN, NY 11232-1101
EPA ID:		NYD091590471
Contact Name:		JOHN PROCEK
Contact Address:		GATEHALL DR STE 201
Contact City,State,Zip:		PARSIPPANY, NJ 07054
Contact Telephone:		973-998-9890
Contact Fax:		Not reported
Contact Email:		JPORCEK@BRIDGEDEV.COM
Contact Title:		GENERATOR AUTHORIZED REPRESENTATIVE
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

State District:		NYSDEC R2
Mailing Address:		GATEHALL DR STE 201
Mailing City,State,Zip:		PARSIPPANY, NJ 07054
Owner Name:	SIP HOLDINGS VENTURE LLC	
Owner Type:		Private
Operator Name:	SIP HOLDINGS VENTURE LLC	
Operator Type:		Private
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Storage
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Storage
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		Yes
Corrective Action Priority Ranking:		Medium
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20211216
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	K078
Waste Description:	Not Defined
Waste Code:	K079
Waste Description:	Not Defined
Waste Code:	K081
Waste Description:	Not Defined
Waste Code:	K082
Waste Description:	Not Defined
Waste Code:	P092
Waste Description:	MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE
Waste Code:	U002
Waste Description:	2-PROPANONE (I) (OR) ACETONE (I)
Waste Code:	U017
Waste Description:	BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-
Waste Code:	U031
Waste Description:	1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
Waste Code:	U069
Waste Description:	1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE
Waste Code:	U154
Waste Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Waste Code:	U159
Waste Description:	2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)
Waste Code:	U161

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Waste Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SIP HOLDINGS VENTURE LLC
Legal Status:	Private
Date Became Current:	20190110
Date Ended Current:	Not reported
Owner/Operator Address:	1 GATEHALL DR STE 201
Owner/Operator City,State,Zip:	PARSIPPANY, NJ 07054
Owner/Operator Telephone:	973-998-9890
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JPORCEK@BRIDGEDEV.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE DEBEVOISE CO DIV PLC INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	74-20TH ST
Owner/Operator City,State,Zip:	OPERCITY, NY 99999
Owner/Operator Telephone:	212-965-2700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE DEBEVOISE CO DIV PLC INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	74-20TH ST
Owner/Operator City,State,Zip:	OPERCITY, NY 99999
Owner/Operator Telephone:	212-965-2700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE DEBEVOISE CO DIV-PLC INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	74 20TH ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	212-965-2700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Owner/Operator Indicator: Owner
Owner/Operator Name: THE DEBEVOISE CO DIV-PLC INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 74 20TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 212-965-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SIP HOLDINGS VENTURE LLC
Legal Status: Private
Date Became Current: 20190110
Date Ended Current: Not reported
Owner/Operator Address: 1 GATEHALL DR STE 201
Owner/Operator City,State,Zip: PARSIPPANY, NJ 07054
Owner/Operator Telephone: 973-998-9890
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JPORCEK@BRIDGEDEV.COM

Historic Generators:
Receive Date: 19801119
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990708
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800813
Handler Name: DEBEVOISE CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20211210
Handler Name: SUNSET INDUSTRIAL PARK
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 236210
NAICS Description: INDUSTRIAL BUILDING CONSTRUCTION

NAICS Code: 32551
NAICS Description: PAINT AND COATING MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Formal Enforcement Agreement or Order
Date Violation was Determined:	19831110
Actual Return to Compliance Date:	19831210
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19831210
Enforcement Identifier:	000
Date of Enforcement Action:	19831110
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R2
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 11500
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: TSD - General
Date Violation was Determined: 19820615
Actual Return to Compliance Date: 19821109
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19820615
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: R2
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R2
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 11500
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Violation Short Description:	TSD - General
Date Violation was Determined:	19820615
Actual Return to Compliance Date:	19821109
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19830521
Enforcement Identifier:	002
Date of Enforcement Action:	19830321
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	7500
Paid Amount:	7500
Final Count:	1
Final Amount:	7500

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19850103
Actual Return to Compliance Date:	19850321
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	19850221
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R2PI
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Violation Short Description:	Generators - General
Date Violation was Determined:	19831110
Actual Return to Compliance Date:	19841130
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	TSD - General
Date Violation was Determined:	19820615
Actual Return to Compliance Date:	19821109
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	000
Date of Enforcement Action:	19820615
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R2
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 11500
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Formal Enforcement Agreement or Order
Date Violation was Determined: 19831110
Actual Return to Compliance Date: 19831210
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19831110
Actual Return to Compliance Date:	19841130
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19831210
Enforcement Identifier:	000
Date of Enforcement Action:	19831110
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R2
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 11500
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: TSD - General
Date Violation was Determined: 19820615
Actual Return to Compliance Date: 19821109
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: 19830521
Enforcement Identifier: 002
Date of Enforcement Action: 19830321
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 7500
Paid Amount: 7500
Final Count: 1
Final Amount: 7500

Found Violation: No
Agency Which Determined Violation: Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19870612
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19831210

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Scheduled Compliance Date:	19831210
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19820615
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19821109
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19820615
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19821109
Scheduled Compliance Date:	19830521
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19850103
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19850321
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19850129
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19841130
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19820615
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19821109
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19831210
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19860123
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19831110
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R2PI

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19841130
Scheduled Compliance Date:	19831210
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19820615
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2PI
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19821109
Scheduled Compliance Date:	19830521
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19841130
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

BROWNFIELDS:

Name:	SUNSET INDUSTRIAL PARK
Address:	74 20TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Program:	BCP
Site Code:	611063
Acres:	0.940
HW Code:	C224148
SWIS:	2401
Town:	New York City
Record Added Date:	09/09/2020
Record Updated Date:	04/28/2022
Update By:	GWBURKE
Site Description:	"Location: The 0.94 acres site is located at 74 20th Street, Brooklyn, NY and is identified as Tax Block 638 and Lot 10 on the New York City Tax Map. The site is bounded by a lumber yard to the east; and industrial property to the west; 20th Street to the north; and 21st Street to the south. Further to the west is an area with numerous industrial, manufacturing, and commercial properties known as Sunset Industrial Park, before reaching the Gowanus Canal. Further east is Interstate 278 (the Brooklyn-Queens Expressway). Site Features: All buildings on site were recently demolished as an interim remedial measure (IRM). Currently, the site is a vacant lot. Current Zoning and Land Use: The current property zoning is M3-1 for Industrial and Manufacturing Use. M3 districts are designated for areas with heavy industries such as power plants, solid waste transfer facilities, recycling plants, and fuel supply depots. The area surrounding the site mainly consists of industrial and manufacturing buildings with a mix of commercial, vacant properties, and properties used for transportation/utilities. Interstate 278/BQE and the nearest residential and institutional uses (South Brooklyn Medical Associates) are approximately 500 feet west of the site. The Gowanus Canal is located approximately 400 feet to the southwest of the site. Past Use of the Site: Historic Sanborn fire insurance maps depicted development at the site as early as 1906 as a cedar mill/cigar box manufacturing facility containing a sawmill and an independent electric plant. By 1922, the facility appeared to be part of a printing ink manufacturing facility. During operation as a paint manufacturing facility, the site was reported to produce waste from the cleaning of paint mixing vats with xylene. The facility was assigned a United States Environmental Protection Agency (USEPA) Handler ID of NYD091590471. The Environmental Data Resources (EDR) database report contained information about the site s regulatory status including types of waste generated, which include unknown solvent mixtures, xylenes, benzenes, phthalates, phenyl mercury acetate, 2-propanone, 2-butanone, n-butyl alcohol, and various paint sludges and waste waters. A 1984 Consent Decree obtained from the USEPA Online Freedom of Information Law (FOIL) database indicated that the Debevoise Company, a former owner and operator of the site, had violated record keeping, waste storage, and closure requirements of RCRA. A RCRA Site Closure Plan for Debevoise Paint was prepared by Elson T. Killam Associates, Inc, dated 1985, with detailed procedures concerning the waste removal, cleanup, and decontamination activities required to decommission the facility, and included a soil sampling plan to satisfy the Consent Decree requirements. No additional information indicating that the closure plan had been or had not been completed was identified. Site Geology & Hydrogeology: The site

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

surface is relatively flat with a land surface elevation 5-10 feet above mean sea level. Based on the investigations completed on-site to date, the shallow deposits at the site are typical of urban fill material. The depth to the bottom of the urban fill layer extends to between two and ten ft bls across the Site. This urban fill material overlies deeper native deposits primarily consisting of sand and silt with some clay deposits encountered. Bedrock was not encountered during the remedial investigation. Groundwater was encountered at depths ranging from about 5.12 to 6.38 feet below ground surface (bgs) at the site and groundwater generally flows to the southwest towards the Gowanus Canal/Gowanus Bay. "

Env Problem:

"A site wide and off-site investigation were conducted to delineate contamination in soil, groundwater, and soil vapor. Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, the emerging contaminants per-and polyfluoroalkyl substances (PFAS) and 1,4 dioxane. Soil vapor was analyzed for VOCs and mercury vapor. Based on the results of the investigation, the primary contaminants of concern at the site are metals, petroleum related VOCs and SVOCs in soil, petroleum-related VOCs in groundwater, and petroleum related VOCs and chlorinated VOCs in soil vapor. Results are summarized below: Soil: Several petroleum related VOCs were detected at concentrations that exceed their applicable protection of groundwater soil cleanup objectives (PGSCOs) and/or industrial use soil cleanup objectives (IUSCOs) including: 1,2,4-trimethylbenzene up to 390 parts per million (ppm) (PGSCO is 3.6 ppm) and xylene up to 2,000 ppm (PGSCO is 1.6 ppm). Several SVOCs were detected at concentrations that exceed their respective PGSCOs and/or IUSCOs, including benzo(a)anthracene up to 38 ppm (PGSCO is 1 ppm), benzo(a)pyrene up to 38 ppm (IUSCO is 1.1 ppm), benzo(b)fluoranthene up to 47 ppm (IUSCO is 11 ppm), and indeno(1,2,3-c,d)pyrene up to 20 ppm (IUSCO is 11 ppm). Several metals were detected at concentrations that exceed their respective PGSCOs and/or IUSCOs, including arsenic up to 63 ppm (PGSCO is 16 ppm) and mercury up to 26.6. ppm (PGSCO is 0.73 ppm). Data does not indicate any off-site impacts in soil related to the site.
Groundwater: Several petroleum related VOCs were detected in on-site groundwater at levels exceeding their respective ambient water quality standards (AWQS), including: 1,2,4-trimethylbenzene up to 5.7 parts per billion (ppb) (AWQS is 5.1 ppb), ethylbenzene up to 110 ppb (AWQS is 5 ppb), isopropylbenzene up to 8.7 ppb (AWQS is 5 ppb), m, p-xylene up to 450 ppb (AWQS is 5 ppb), xylene (total) up to 140 ppb (AWQS is 5 ppb). SVOCs such as benzo(a)anthracene was detected in on-site groundwater at a maximum concentration of 0.63 (AWQS is 0.002 ppb). Perfluorooctanoic Acid (PFOA) was detected in groundwater samples at a maximum concentration of 198 parts per trillion, or ppt compared to the maximum contaminant level (MCL) (drinking water standard) of 10 ppt and perfluorooctanesulfonic acid (PFOS) was detected in groundwater samples at a maximum concentration of 15.7 ppt (MCL is 10 ppt). 1,4-dioxane was not detected in groundwater samples. Additionally, an off-site groundwater sample was collected from a downgradient monitoring well located on the southern side of the parking lot adjoining the site. PFOA was detected in off-site groundwater samples at a maximum concentration of 289 ppt (MCL is 10 ppt). PFOS was not detected in off-site groundwater samples. Based on the on-site and off-site groundwater sampling results, data does not indicate any off-site impacts in groundwater related to the site.

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

	Soil Vapor: PCE was detected in seven soil vapor samples at a maximum concentration of 4.3 micrograms per cubic meter (?g/m3) and trichloroethene (TCE) was detected in one soil vapor sample at a concentration of 0.73 ?g/m3. Petroleum-related VOCs such as benzene, toluene, ethylbenzene, and xylenes (BTEX) were detected in soil vapor ranging from 26.5 ?g/m3 to 1,299 ?g/m3. Based on the soil vapor sampling results, data does not indicate any off-site impacts in soil vapor related to the site. "
Health Problem:	"People will not come into contact with contaminated soil or groundwater unless they dig below the ground surface. People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air is not a current concern. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion in any future on-site development. Environmental sampling indicates soil vapor intrusion from site contamination is not a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-12-02 08:07:00
Record Upd:	2020-12-02 15:44:00
Updated By:	HMDUDEK
Own Op:	6
Sub Type:	P03
Owner Name:	John Porcek, P.E.
Owner Company:	SIP Holdings Venture, LLC
Owner Address:	One Gatehall Drive, Suite 201
Owner Addr2:	Not reported
Owner City,St,Zip:	Parsippany, NJ 07054
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Park Slope Branch
Owner Address:	431 6th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11215
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Jeremy Laufer
Owner Company:	Brooklyn Community Board District 7
Owner Address:	4201 4th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

Owner Country:	United States of America
HW Code:	C224148
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	m-xylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	o-xylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224148
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

HW Code:	C224148
Waste Type:	acetone
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

ICIS:

Enforcement Action ID:	02-1983-0015
FRS ID:	110004374114
Action Name:	PLC ENTERPRISES, INC.
Facility Name:	DEBEVOISE CO
Facility Address:	74 20TH ST BROOKLYN, NY 112321101
Enforcement Action Type:	Civil Judicial Action
Facility County:	KINGS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Judicial
EA Type Code:	CIV
Facility SIC Code:	2851
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.665093
Longitude in Decimal Degrees:	-73.997955
Permit Type Desc:	Not reported
Program System Acronym:	27418
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	DEBEVOISE CO
Address:	74 20TH ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	2851

Facility Name:	DEBEVOISE CO
Address:	74 20TH ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	2851

FINDS:

Registry ID: 110004374114

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000224955
Registry ID:	110004374114
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004374114
Name:	DEBEVOISE CO
Address:	74 20TH ST
City,State,Zip:	BROOKLYN, NY 11232

NY MANIFEST:

Name:	DEBEVOISE PAINT-PR-ALL PAINT PRODUCTS
Address:	74 20TH ST
City,State,Zip:	BROOKLYN, NY 11232-1101
Country:	USA
EPA ID:	NYD091590471
Facility Status:	Not reported
Location Address 1:	74 20 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11232
Location Zip 4:	1101

NY MANIFEST:

EPAID:	NYD091590471
Mailing Name:	DEBEVOISE PAINT-PR-ALL PAINT PRODUCTS
Mailing Contact:	JOAN MANGIARANO
Mailing Address 1:	700 GOTHAM PARKWAY
Mailing Address 2:	Not reported
Mailing City:	CARLSTADT
Mailing State:	NJ
Mailing Zip:	07072
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129652700

Count: 12 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S121986656	25 ST & 4TH AVENUE	25 ST & 4TH AVENUE		NY Spills
BROOKLYN	S105003695	USPS GOWANUS SITE, FORMER MGP METR	2ND AVENUE AND 12TH STREET	11215	NY VCP
BROOKLYN	S113917066	BROOKLYN MILITARY OCEAN TERMINAL	2ND AVE BTWN 57TH, 65TH STREET	11232	NY SHWS
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S113922111	455 SMITH STREET (VICHAR, INC.)	5TH STREET & SMITH STREET TO G	11231	NY VCP
BROOKLYN	S126022764	CONEY ISLAND, STILLWELL AND NEPTUN	BOUNDED BY STILLWELL AVE, NEPT		NY SWF/LF
BROOKLYN	S126023554	PAERDEGAT BASIN NORTH	BOUNDED PAERDEGAT BASIN, SEAVI		NY SWF/LF
BROOKLYN	1003864070	CARROL GARDEN	CORNER OF 5TH AND SMITH STREET	11231	SEMS-ARCHIVE
BROOKLYN	S113922123	FULTON MUNICIPAL WORKS	NEVINS, DEGRAW & SACKETT STS.	11201	NY VCP
BROOKLYN	S105972442	HAMILTON AVENUE PIERS/19TH & 18TH	REAR OF 566 HAMILTON AVENUE	11232	NY SHWS
BROOKLYN	S113922162	DANGMAN PARK	SHEEPSHEAD BAY ROAD & WEST 5TH	11215	NY VCP
BROOKLYN	S117535331	BASEMENT	925 UNION ST		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 09/06/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/19/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 71

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/14/2022
Date Data Arrived at EDR: 06/15/2022
Date Made Active in Reports: 06/21/2022
Number of Days to Update: 6

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/15/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/29/2022
Date Data Arrived at EDR: 06/30/2022
Date Made Active in Reports: 09/15/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/14/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 06/02/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 79

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/28/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/02/2022
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 06/02/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 79

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/28/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/07/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/14/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 03/22/2022
Date Data Arrived at EDR: 06/17/2022
Date Made Active in Reports: 09/02/2022
Number of Days to Update: 77

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 03/22/2022
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 09/02/2022
Number of Days to Update: 80

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/13/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 06/06/2022
Date Data Arrived at EDR: 06/07/2022
Date Made Active in Reports: 08/25/2022
Number of Days to Update: 79

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/06/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/09/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 09/06/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 06/29/2022
Date Data Arrived at EDR: 06/30/2022
Date Made Active in Reports: 09/15/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/21/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/12/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/21/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/30/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/18/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/30/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/18/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 08/04/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. The primary focus is inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants, including per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane.

Date of Government Version: 10/29/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 04/26/2022
Number of Days to Update: 158

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 08/01/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 05/03/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 07/26/2022
Number of Days to Update: 82

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 07/27/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/21/2022
Date Made Active in Reports: 06/14/2022
Number of Days to Update: 85

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/09/2022
Date Data Arrived at EDR: 05/11/2022
Date Made Active in Reports: 08/02/2022
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/11/2022
Date Data Arrived at EDR: 05/17/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 73

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/13/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/08/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/29/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/04/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 07/18/2022
Date Data Arrived at EDR: 07/18/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 11

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/18/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/14/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/08/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/10/2022
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 69

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/04/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/23/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/21/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2022
Date Data Arrived at EDR: 04/14/2022
Date Made Active in Reports: 07/12/2022
Number of Days to Update: 89

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/08/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/26/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/24/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 07/26/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 09/01/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/22/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 3

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Quarterly

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 14

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/14/2022
Date Data Arrived at EDR: 06/15/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 68

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/13/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/13/2022
Date Data Arrived at EDR: 05/18/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 13

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/22/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 01/11/2022
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 34

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/07/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 04/02/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 07/01/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/17/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 73

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 07/27/2022
Date Data Arrived at EDR: 07/27/2022
Date Made Active in Reports: 08/04/2022
Number of Days to Update: 8

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/14/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 06/23/2022
Date Data Arrived at EDR: 06/23/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 08/30/2022
Date Data Arrived at EDR: 08/31/2022
Date Made Active in Reports: 09/07/2022
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 08/30/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 03/22/2022
Date Data Arrived at EDR: 06/22/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 6

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 03/29/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 06/24/2022
Number of Days to Update: 85

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/07/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 08/30/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/29/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 03/25/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/18/2022
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/14/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 05/30/2022
Date Data Arrived at EDR: 05/31/2022
Date Made Active in Reports: 08/17/2022
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 04/05/2022
Date Data Arrived at EDR: 04/13/2022
Date Made Active in Reports: 07/08/2022
Number of Days to Update: 86

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/12/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 04/25/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 07/26/2022
Number of Days to Update: 83

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

NYC LEAD: Lead-based Paint Testing Results
The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 04/04/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 07/26/2022
Number of Days to Update: 83
Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 08/04/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120
Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Semi-Annually

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29
Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A
Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A
Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

NASSAU COUNTY:

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/24/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/24/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 04/12/2022
Date Data Arrived at EDR: 05/12/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 81

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 04/12/2022
Date Data Arrived at EDR: 05/12/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 81

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/08/2022
Date Data Arrived at EDR: 05/09/2022
Date Made Active in Reports: 07/28/2022
Number of Days to Update: 80

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/06/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/10/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/12/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/29/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

296 4TH AVENUE
296 4TH AVENUE
BROOKLYN, NY 11215

TARGET PROPERTY COORDINATES

Latitude (North):	40.675577 - 40ˆ 40’ 32.08’’
Longitude (West):	73.985041 - 73ˆ 59’ 6.15’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	585779.8
UTM Y (Meters):	4503028.0
Elevation:	23 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019
West Map:	14317809 JERSEY CITY, NJ
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 23 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970211F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970203F	FEMA FIRM Flood data
3604970192F	FEMA FIRM Flood data
3604970063B	FEMA Q3 Flood data
3604970073B	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/4 - 1/2 Mile NW
Site Name:	Vidan Auto Salvage
Site EPA ID Number:	NYD986961167
Groundwater Flow Direction:	SW TOWARD THE NARROWS.
Inferred Depth to Water:	approximately 38 feet.
Hydraulic Connection:	The surficial aquifer and underlying aquifer are hydraulically connected.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000828170	0 - 1/8 Mile SSE
B4	USGS40000828295	0 - 1/8 Mile NNE
B5	USGS40000828296	0 - 1/8 Mile NNE
B6	USGS40000828294	0 - 1/8 Mile NNE
7	USGS40000828120	1/8 - 1/4 Mile South
8	USGS40000828114	1/4 - 1/2 Mile SSW
C9	USGS40000828117	1/4 - 1/2 Mile SW
C10	USGS40000828115	1/4 - 1/2 Mile SW
13	USGS40000828297	1/4 - 1/2 Mile WNW
14	USGS40000828092	1/4 - 1/2 Mile SSW
E15	USGS40000828284	1/4 - 1/2 Mile ENE
E16	USGS40000828293	1/4 - 1/2 Mile ENE
17	USGS40000828070	1/4 - 1/2 Mile SSE
F18	USGS40000828124	1/4 - 1/2 Mile WSW
F19	USGS40000828125	1/4 - 1/2 Mile WSW
20	USGS40000828469	1/4 - 1/2 Mile NNE
21	USGS40000828165	1/2 - 1 Mile West
26	USGS40000828265	1/2 - 1 Mile West
H27	USGS40000828451	1/2 - 1 Mile NE
I28	USGS40000828018	1/2 - 1 Mile SW
H29	USGS40000828468	1/2 - 1 Mile NE
30	USGS40000828478	1/2 - 1 Mile NW
I31	USGS40000828019	1/2 - 1 Mile SW
J32	USGS40000828512	1/2 - 1 Mile NNW
J33	USGS40000828518	1/2 - 1 Mile NNW
K34	USGS40000828532	1/2 - 1 Mile North
35	USGS40000828501	1/2 - 1 Mile NNW
K36	USGS40000828544	1/2 - 1 Mile North
37	USGS40000827905	1/2 - 1 Mile SSW
38	USGS40000828444	1/2 - 1 Mile NW
39	USGS40000828549	1/2 - 1 Mile North
40	USGS40000828443	1/2 - 1 Mile NE
41	USGS40000828523	1/2 - 1 Mile NNE
L42	USGS40000828020	1/2 - 1 Mile WSW
L43	USGS40000828021	1/2 - 1 Mile WSW
44	USGS40000828558	1/2 - 1 Mile NNE
45	USGS40000828410	1/2 - 1 Mile WNW
M46	USGS40000828587	1/2 - 1 Mile NNE
N47	USGS40000828183	1/2 - 1 Mile West
N48	USGS40000828193	1/2 - 1 Mile West
M49	USGS40000828602	1/2 - 1 Mile North
M50	USGS40000828606	1/2 - 1 Mile NNE
51	USGS40000828601	1/2 - 1 Mile NNE
O52	USGS40000828620	1/2 - 1 Mile North
O53	USGS40000828619	1/2 - 1 Mile NNE
O54	USGS40000828627	1/2 - 1 Mile North
P56	USGS40000828254	1/2 - 1 Mile West
P57	USGS40000828200	1/2 - 1 Mile West
58	USGS40000828339	1/2 - 1 Mile West

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	NYREG1000000232	0 - 1/8 Mile SE
A3	NYREG1000000233	0 - 1/8 Mile SE
D11	NYREG1000000080	1/4 - 1/2 Mile West
D12	NYREG1000000081	1/4 - 1/2 Mile West
G22	NYREG1000000090	1/2 - 1 Mile ENE
G23	NYREG1000000089	1/2 - 1 Mile ENE
G24	NYREG1000000158	1/2 - 1 Mile East
G25	NYREG1000000159	1/2 - 1 Mile East
55	NYREG1000000125	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 07124126.2r



0 1/4 1/2 1 Miles

- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	296 4th Avenue	CLIENT:	Haley & Aldrich, Inc.
ADDRESS:	296 4th Avenue Brooklyn NY 11215	CONTACT:	Sarah Commisso
		INQUIRY #:	07124126.2r
LAT/LONG:	40.675577 / 73.985041	DATE:	September 20, 2022 5:24 pm

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
A1 **SSE** **0 - 1/8 Mile** **Higher**	**FED USGS**	**USGS40000828170**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 917. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	106	Well Hole Depth Units:	ft

	Database	EDR ID Number
A2 **SE** **0 - 1/8 Mile** **Higher**	**NY WELLS**	**NYREG1000000232**

Well Number:	K003580	Owner:	Hertz, Joseph
Well Depth:	100	Diameter:	4
Casing Length:	0	Screen Diameter:	4
Screen Length:	10		

	Database	EDR ID Number
A3 **SE** **0 - 1/8 Mile** **Higher**	**NY WELLS**	**NYREG1000000233**

Well Number:	K003581D	Owner:	Hertz, Joseph
Well Depth:	100	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	20		

	Database	EDR ID Number
B4 **NNE** **0 - 1/8 Mile** **Higher**	**FED USGS**	**USGS40000828295**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 956. 1	Type:	Well
Description:	0501	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	182	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B5
NNE
0 - 1/8 Mile
Higher

FED USGS **USGS40000828296**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1030. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	182	Well Hole Depth Units:	ft

B6
NNE
0 - 1/8 Mile
Higher

FED USGS **USGS40000828294**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 930. 1	Type:	Well
Description:	0401	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	180	Well Hole Depth Units:	ft

7
South
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000828120**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 646. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	194	Well Hole Depth Units:	ft

8
SSW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000828114**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 648. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	197	Well Hole Depth Units:	ft

C9
SW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000828117**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 920. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	164	Well Hole Depth Units:	ft

C10
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000828115**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 916. 1	Type:	Well
Description:	2101	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	162	Well Hole Depth Units:	ft

D11
West
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000080**

Well Number:	K003438	Owner:	Nyc Sanitation Dept.
Well Depth:	66	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

D12
West
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000081**

Well Number:	K003438	Owner:	Nyc Sanitation Dept.
Well Depth:	66	Diameter:	6
Casing Length:	0	Screen Diameter:	0

Screen Length: 0

13
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000828297**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 10. 1	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	75	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	268	Level reading date:	1943-02-27
Feet below surface:	Not Reported	Feet to sea level:	-15.45
Note:	Not Reported		

Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-16.47	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-17.14	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-16.81	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-17.58	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-17.11	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-17.86	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-17.51	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-17.74	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-18.28	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-17.56	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-17.95	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-18.01	Note:	Not Reported

Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-17.84	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-18.25	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-17.93	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-18.53	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-18.13	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-17.85	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-18.39	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-17.77	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-17.92	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-17.94	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-17.83	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-17.65	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-17.52	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-17.90	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-17.38	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-17.50	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-17.40	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-16.97	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-17.15	Note:	Not Reported

Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-16.95	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-17.27	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-16.65	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-16.46	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-16.58	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-15.97	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-16.55	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-15.93	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-16.51	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-16.42	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-16.78	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-16.11	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-16.90	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-15.95	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-16.19	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-16.19	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-16.13	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-16.49	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-16.25	Note:	Not Reported

Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-16.63	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-16.19	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-17.01	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-17.26	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-16.66	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-16.80	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-16.95	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-16.82	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-16.83	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-17.08	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-17.32	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-17.09	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-17.50	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-17.85	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-16.93	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-17.13	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-17.04	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-16.85	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-17.05	Note:	Not Reported

Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-17.17	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-16.93	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-16.35	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-16.70	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-16.35	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-16.71	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-16.42	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-15.69	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-16.38	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-15.86	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-15.45	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-15.46	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-15.00	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-15.41	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-15.63	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-14.35	Note:	Not Reported

Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-14.18	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-14.25	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-13.98	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-13.98	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-14.43	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-14.73	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-14.56	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-14.28	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-14.14	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-14.92	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-14.34	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-13.64	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-14.75	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-14.41	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-14.70	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-14.95	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-15.36	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-14.90	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-15.09	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-15.24	Note:	Not Reported

Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-15.31	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-16.60	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-15.69	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-15.94	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-15.55	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-16.14	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-15.50	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-15.43	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-15.47	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-15.44	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-14.86	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-15.18	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-14.88	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-14.50	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-14.66	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-15.15	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-14.43	Note:	Not Reported
Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-14.12	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-14.15	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-14.28	Note:	Not Reported

Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-13.94	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-13.96	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-13.94	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-13.65	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-13.76	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-13.12	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-12.59	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-13.59	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-13.35	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-14.07	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-13.82	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-14.22	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-13.58	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-13.57	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-13.32	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-13.46	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-14.34	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-14.20	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-13.60	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported

Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-13.59	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-13.93	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-13.30	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-13.73	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-13.96	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-14.48	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-14.32	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-15.32	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-15.59	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-15.72	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-15.47	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-16.89	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-16.26	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-16.16	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-16.41	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-16.45	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-16.02	Note:	Not Reported
Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-15.74	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-15.72	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-16.73	Note:	Not Reported

Level reading date:	1939-07-21	Feet below surface:	Not Reported
Feet to sea level:	-16.22	Note:	Not Reported
Level reading date:	1939-07-14	Feet below surface:	Not Reported
Feet to sea level:	-16.05	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-15.06	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-15.29	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-15.36	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-14.96	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-15.15	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-14.09	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-14.44	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-14.44	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-14.25	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-13.83	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-14.32	Note:	Not Reported
Level reading date:	1939-04-15	Feet below surface:	Not Reported
Feet to sea level:	-13.92	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-13.84	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-14.33	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-14.82	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-14.80	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-14.35	Note:	Not Reported

Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-14.30	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-14.45	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-14.98	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-14.68	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-15.15	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-14.77	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-14.49	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-14.30	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-14.79	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-13.50	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-14.81	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-14.84	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-15.06	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-14.95	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-14.28	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-14.04	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-13.85	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-13.74	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-13.73	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-13.63	Note:	Not Reported

Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-13.72	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-13.63	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-13.38	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-13.68	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-13.35	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-13.33	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-13.09	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-13.05	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-12.79	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-12.65	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-12.52	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-12.57	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-12.18	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-12.26	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-12.22	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-12.05	Note:	Not Reported
Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-12.20	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-12.24	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-12.29	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-12.15	Note:	Not Reported

Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-11.98	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-11.64	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-11.52	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-11.54	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-11.69	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-11.52	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-11.72	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-11.63	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-11.74	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-12.43	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-12.66	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-12.31	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-12.22	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-12.00	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-11.96	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-12.09	Note:	Not Reported
Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-12.12	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-12.11	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-12.05	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-12.45	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-12.09	Note:	Not Reported

Level reading date:	1937-11-13	Feet below surface:	Not Reported
Feet to sea level:	-12.02	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-12.50	Note:	Not Reported

14
SSW **FED USGS** **USGS40000828092**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 650. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	195	Well Hole Depth Units:	ft

E15
ENE **FED USGS** **USGS40000828284**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3261. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	45
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	172	Level reading date:	2002-01-28
Feet below surface:	Not Reported	Feet to sea level:	23.61
Note:	Not Reported		
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	24.06	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	24.59	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	25.01	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	25.44	Note:	Not Reported
Level reading date:	2001-08-30	Feet below surface:	Not Reported
Feet to sea level:	25.37	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	25.18	Note:	Not Reported

Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	25.19	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	24.70	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	23.92	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	23.35	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	23.31	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	23.54	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	23.81	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	23.96	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	24.12	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	24.22	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	23.99	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	23.81	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	23.28	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	23.03	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	22.82	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	22.79	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	22.83	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	23.24	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	23.33	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	23.59	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	23.82	Note:	Not Reported

Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	24.03	Note:	Not Reported
Level reading date:	1999-07-20	Feet below surface:	Not Reported
Feet to sea level:	24.13	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	24.17	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	24.18	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	24.22	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	24.37	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	24.62	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	25.10	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	26.29	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	26.78	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	27.33	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	27.73	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	27.89	Note:	Not Reported
Level reading date:	1998-06-10	Feet below surface:	Not Reported
Feet to sea level:	27.28	Note:	Not Reported
Level reading date:	1998-05-20	Feet below surface:	Not Reported
Feet to sea level:	26.72	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	26.16	Note:	Not Reported
Level reading date:	1998-03-25	Feet below surface:	Not Reported
Feet to sea level:	25.51	Note:	Not Reported
Level reading date:	1998-01-29	Feet below surface:	Not Reported
Feet to sea level:	25.48	Note:	Not Reported
Level reading date:	1997-12-17	Feet below surface:	Not Reported
Feet to sea level:	26.17	Note:	Not Reported
Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	26.39	Note:	Not Reported
Level reading date:	1997-11-05	Feet below surface:	Not Reported
Feet to sea level:	26.71	Note:	Not Reported

Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	27.18	Note:	Not Reported
Level reading date:	1997-07-23	Feet below surface:	Not Reported
Feet to sea level:	27.56	Note:	Not Reported
Level reading date:	1997-06-26	Feet below surface:	Not Reported
Feet to sea level:	27.61	Note:	Not Reported
Level reading date:	1997-05-29	Feet below surface:	Not Reported
Feet to sea level:	27.43	Note:	Not Reported
Level reading date:	1997-03-18	Feet below surface:	Not Reported
Feet to sea level:	26.89	Note:	Not Reported
Level reading date:	1997-02-28	Feet below surface:	Not Reported
Feet to sea level:	26.82	Note:	Not Reported
Level reading date:	1997-01-24	Feet below surface:	Not Reported
Feet to sea level:	26.81	Note:	Not Reported
Level reading date:	1997-01-07	Feet below surface:	Not Reported
Feet to sea level:	26.69	Note:	Not Reported
Level reading date:	1996-09-19	Feet below surface:	Not Reported
Feet to sea level:	27.36	Note:	Not Reported
Level reading date:	1996-07-02	Feet below surface:	Not Reported
Feet to sea level:	27.45	Note:	Not Reported
Level reading date:	1996-03-13	Feet below surface:	Not Reported
Feet to sea level:	25.62	Note:	Not Reported
Level reading date:	1995-11-28	Feet below surface:	Not Reported
Feet to sea level:	25.39	Note:	Not Reported
Level reading date:	1995-09-26	Feet below surface:	Not Reported
Feet to sea level:	25.82	Note:	Not Reported
Level reading date:	1995-07-19	Feet below surface:	Not Reported
Feet to sea level:	26.07	Note:	Not Reported
Level reading date:	1995-05-23	Feet below surface:	Not Reported
Feet to sea level:	25.88	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	25.11	Note:	Not Reported
Level reading date:	1995-01-25	Feet below surface:	Not Reported
Feet to sea level:	25.01	Note:	Not Reported
Level reading date:	1994-12-13	Feet below surface:	Not Reported
Feet to sea level:	25.36	Note:	Not Reported
Level reading date:	1994-10-18	Feet below surface:	Not Reported
Feet to sea level:	26.05	Note:	Not Reported
Level reading date:	1994-09-21	Feet below surface:	Not Reported
Feet to sea level:	26.44	Note:	Not Reported
Level reading date:	1994-08-24	Feet below surface:	Not Reported
Feet to sea level:	26.78	Note:	Not Reported

Level reading date:	1994-07-27	Feet below surface:	Not Reported
Feet to sea level:	26.83	Note:	Not Reported
Level reading date:	1994-06-20	Feet below surface:	Not Reported
Feet to sea level:	26.70	Note:	Not Reported
Level reading date:	1994-05-17	Feet below surface:	Not Reported
Feet to sea level:	26.23	Note:	Not Reported
Level reading date:	1994-04-26	Feet below surface:	Not Reported
Feet to sea level:	25.71	Note:	Not Reported
Level reading date:	1994-03-25	Feet below surface:	Not Reported
Feet to sea level:	25.46	Note:	Not Reported
Level reading date:	1994-02-22	Feet below surface:	Not Reported
Feet to sea level:	25.49	Note:	Not Reported
Level reading date:	1993-12-27	Feet below surface:	Not Reported
Feet to sea level:	24.83	Note:	Not Reported
Level reading date:	1993-11-18	Feet below surface:	Not Reported
Feet to sea level:	25.21	Note:	Not Reported
Level reading date:	1993-10-28	Feet below surface:	Not Reported
Feet to sea level:	25.49	Note:	Not Reported
Level reading date:	1993-09-15	Feet below surface:	Not Reported
Feet to sea level:	25.96	Note:	Not Reported
Level reading date:	1993-08-18	Feet below surface:	Not Reported
Feet to sea level:	26.27	Note:	Not Reported
Level reading date:	1993-07-15	Feet below surface:	Not Reported
Feet to sea level:	26.40	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	26.32	Note:	Not Reported
Level reading date:	1993-05-20	Feet below surface:	Not Reported
Feet to sea level:	25.95	Note:	Not Reported
Level reading date:	1993-04-29	Feet below surface:	Not Reported
Feet to sea level:	25.45	Note:	Not Reported
Level reading date:	1993-03-23	Feet below surface:	Not Reported
Feet to sea level:	24.84	Note:	Not Reported
Level reading date:	1993-02-24	Feet below surface:	Not Reported
Feet to sea level:	24.27	Note:	Not Reported
Level reading date:	1993-01-26	Feet below surface:	Not Reported
Feet to sea level:	24.11	Note:	Not Reported
Level reading date:	1992-12-29	Feet below surface:	Not Reported
Feet to sea level:	24.14	Note:	Not Reported
Level reading date:	1992-11-24	Feet below surface:	Not Reported
Feet to sea level:	24.04	Note:	Not Reported
Level reading date:	1992-10-28	Feet below surface:	Not Reported
Feet to sea level:	24.44	Note:	Not Reported

Level reading date:	1992-09-16	Feet below surface:	Not Reported
Feet to sea level:	24.47	Note:	Not Reported
Level reading date:	1992-08-25	Feet below surface:	Not Reported
Feet to sea level:	24.46	Note:	Not Reported
Level reading date:	1992-07-15	Feet below surface:	Not Reported
Feet to sea level:	24.45	Note:	Not Reported
Level reading date:	1992-06-23	Feet below surface:	Not Reported
Feet to sea level:	24.43	Note:	Not Reported
Level reading date:	1992-05-12	Feet below surface:	Not Reported
Feet to sea level:	24.56	Note:	Not Reported
Level reading date:	1992-04-14	Feet below surface:	Not Reported
Feet to sea level:	25.66	Note:	Not Reported
Level reading date:	1992-03-18	Feet below surface:	Not Reported
Feet to sea level:	25.91	Note:	Not Reported
Level reading date:	1992-02-19	Feet below surface:	Not Reported
Feet to sea level:	25.17	Note:	Not Reported
Level reading date:	1992-01-22	Feet below surface:	Not Reported
Feet to sea level:	26.45	Note:	Not Reported
Level reading date:	1991-12-18	Feet below surface:	Not Reported
Feet to sea level:	26.63	Note:	Not Reported
Level reading date:	1991-11-14	Feet below surface:	Not Reported
Feet to sea level:	25.85	Note:	Not Reported
Level reading date:	1991-10-16	Feet below surface:	Not Reported
Feet to sea level:	26.05	Note:	Not Reported
Level reading date:	1991-09-17	Feet below surface:	Not Reported
Feet to sea level:	26.22	Note:	Not Reported
Level reading date:	1991-08-15	Feet below surface:	Not Reported
Feet to sea level:	26.41	Note:	Not Reported
Level reading date:	1991-07-16	Feet below surface:	Not Reported
Feet to sea level:	26.63	Note:	Not Reported
Level reading date:	1991-06-12	Feet below surface:	Not Reported
Feet to sea level:	26.63	Note:	Not Reported
Level reading date:	1991-05-15	Feet below surface:	Not Reported
Feet to sea level:	26.51	Note:	Not Reported
Level reading date:	1991-04-15	Feet below surface:	Not Reported
Feet to sea level:	26.33	Note:	Not Reported
Level reading date:	1991-03-20	Feet below surface:	Not Reported
Feet to sea level:	26.31	Note:	Not Reported
Level reading date:	1991-02-21	Feet below surface:	Not Reported
Feet to sea level:	26.26	Note:	Not Reported
Level reading date:	1991-01-24	Feet below surface:	Not Reported
Feet to sea level:	26.30	Note:	Not Reported

Level reading date:	1990-12-10	Feet below surface:	Not Reported
Feet to sea level:	26.63	Note:	Not Reported
Level reading date:	1990-11-13	Feet below surface:	Not Reported
Feet to sea level:	26.66	Note:	Not Reported
Level reading date:	1990-10-10	Feet below surface:	Not Reported
Feet to sea level:	26.67	Note:	Not Reported
Level reading date:	1990-09-12	Feet below surface:	Not Reported
Feet to sea level:	26.52	Note:	Not Reported
Level reading date:	1990-08-14	Feet below surface:	Not Reported
Feet to sea level:	26.43	Note:	Not Reported
Level reading date:	1990-07-12	Feet below surface:	Not Reported
Feet to sea level:	26.41	Note:	Not Reported
Level reading date:	1990-06-20	Feet below surface:	Not Reported
Feet to sea level:	26.32	Note:	Not Reported
Level reading date:	1990-05-25	Feet below surface:	Not Reported
Feet to sea level:	26.20	Note:	Not Reported
Level reading date:	1990-04-24	Feet below surface:	Not Reported
Feet to sea level:	26.18	Note:	Not Reported
Level reading date:	1990-04-04	Feet below surface:	Not Reported
Feet to sea level:	26.26	Note:	Not Reported
Level reading date:	1990-03-27	Feet below surface:	Not Reported
Feet to sea level:	26.37	Note:	Not Reported
Level reading date:	1990-02-26	Feet below surface:	Not Reported
Feet to sea level:	26.45	Note:	Not Reported
Level reading date:	1990-01-24	Feet below surface:	Not Reported
Feet to sea level:	26.74	Note:	Not Reported
Level reading date:	1989-12-28	Feet below surface:	Not Reported
Feet to sea level:	26.91	Note:	Not Reported
Level reading date:	1989-11-21	Feet below surface:	Not Reported
Feet to sea level:	27.15	Note:	Not Reported
Level reading date:	1989-10-27	Feet below surface:	Not Reported
Feet to sea level:	26.86	Note:	Not Reported
Level reading date:	1989-09-29	Feet below surface:	Not Reported
Feet to sea level:	26.89	Note:	Not Reported
Level reading date:	1989-08-31	Feet below surface:	Not Reported
Feet to sea level:	26.60	Note:	Not Reported
Level reading date:	1989-07-25	Feet below surface:	Not Reported
Feet to sea level:	25.86	Note:	Not Reported
Level reading date:	1989-06-22	Feet below surface:	Not Reported
Feet to sea level:	25.06	Note:	Not Reported
Level reading date:	1989-05-22	Feet below surface:	Not Reported
Feet to sea level:	24.29	Note:	Not Reported

Level reading date:	1989-04-28	Feet below surface:	Not Reported
Feet to sea level:	24.10	Note:	Not Reported
Level reading date:	1989-04-11	Feet below surface:	Not Reported
Feet to sea level:	24.04	Note:	Not Reported
Level reading date:	1989-03-29	Feet below surface:	Not Reported
Feet to sea level:	24.03	Note:	Not Reported
Level reading date:	1989-02-28	Feet below surface:	Not Reported
Feet to sea level:	24.29	Note:	Not Reported
Level reading date:	1989-01-17	Feet below surface:	Not Reported
Feet to sea level:	24.42	Note:	Not Reported
Level reading date:	1988-12-09	Feet below surface:	Not Reported
Feet to sea level:	24.65	Note:	Not Reported
Level reading date:	1988-11-16	Feet below surface:	Not Reported
Feet to sea level:	24.83	Note:	Not Reported
Level reading date:	1988-10-19	Feet below surface:	Not Reported
Feet to sea level:	25.04	Note:	Not Reported
Level reading date:	1988-09-14	Feet below surface:	Not Reported
Feet to sea level:	25.20	Note:	Not Reported
Level reading date:	1988-08-31	Feet below surface:	Not Reported
Feet to sea level:	25.21	Note:	Not Reported
Level reading date:	1988-07-22	Feet below surface:	Not Reported
Feet to sea level:	25.33	Note:	Not Reported
Level reading date:	1988-06-17	Feet below surface:	Not Reported
Feet to sea level:	25.13	Note:	Not Reported
Level reading date:	1988-06-01	Feet below surface:	Not Reported
Feet to sea level:	25.26	Note:	Not Reported
Level reading date:	1985-10-01	Feet below surface:	Not Reported
Feet to sea level:	25.49	Note:	Not Reported
Level reading date:	1985-05-21	Feet below surface:	Not Reported
Feet to sea level:	26.01	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	30.30	Note:	Not Reported
Level reading date:	1984-10-04	Feet below surface:	Not Reported
Feet to sea level:	31.41	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	31.01	Note:	Not Reported
Level reading date:	1984-03-16	Feet below surface:	Not Reported
Feet to sea level:	31.86	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	28.48	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	28.26	Note:	Not Reported

Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	26.81	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	25.81	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	25.81	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	25.68	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	25.11	Note:	Not Reported
Level reading date:	1982-04-01	Feet below surface:	Not Reported
Feet to sea level:	25.30	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	25.47	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	25.76	Note:	Not Reported
Level reading date:	1981-06-25	Feet below surface:	Not Reported
Feet to sea level:	26.23	Note:	Not Reported
Level reading date:	1981-03-20	Feet below surface:	Not Reported
Feet to sea level:	26.36	Note:	Not Reported
Level reading date:	1981-02-25	Feet below surface:	Not Reported
Feet to sea level:	26.37	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	28.27	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	28.28	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	30.01	Note:	Not Reported
Level reading date:	1980-09-02	Feet below surface:	Not Reported
Feet to sea level:	29.84	Note:	Not Reported
Level reading date:	1980-06-24	Feet below surface:	Not Reported
Feet to sea level:	29.35	Note:	Not Reported
Level reading date:	1980-06-10	Feet below surface:	Not Reported
Feet to sea level:	28.81	Note:	Not Reported
Level reading date:	1980-04-09	Feet below surface:	Not Reported
Feet to sea level:	24.66	Note:	Not Reported

E16
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000828293**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3301. 1	Type:	Well

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	19840301	Well Depth:	70
Well Depth Units:	ft	Well Hole Depth:	70
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	136	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	17.93
Note:	Not Reported		

Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	18.11	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	17.65	Note:	Not Reported
Level reading date:	2004-11-30	Feet below surface:	Not Reported
Feet to sea level:	17.90	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	18.16	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	18.10	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	17.98	Note:	Not Reported
Level reading date:	2004-07-20	Feet below surface:	Not Reported
Feet to sea level:	18.07	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	18.05	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	18.32	Note:	Not Reported
Level reading date:	2004-04-30	Feet below surface:	Not Reported
Feet to sea level:	17.64	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	17.53	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	17.74	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	17.38	Note:	Not Reported
Level reading date:	2003-11-19	Feet below surface:	Not Reported
Feet to sea level:	17.73	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	18.06	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	17.98	Note:	Not Reported

Level reading date:	2003-08-26	Feet below surface:	Not Reported
Feet to sea level:	18.00	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	18.00	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	17.30	Note:	Not Reported
Level reading date:	2003-05-20	Feet below surface:	Not Reported
Feet to sea level:	16.46	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	16.50	Note:	Not Reported
Level reading date:	2003-03-17	Feet below surface:	Not Reported
Feet to sea level:	15.97	Note:	Not Reported
Level reading date:	2003-01-28	Feet below surface:	Not Reported
Feet to sea level:	14.80	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	14.27	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	13.89	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	13.65	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	13.35	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	12.96	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	13.27	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	13.18	Note:	Not Reported
Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	13.99	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	14.21	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	14.15	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	14.71	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	14.98	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	15.45	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	15.31	Note:	Not Reported

Level reading date:	2001-08-30	Feet below surface:	Not Reported
Feet to sea level:	15.27	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	15.40	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	15.22	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	15.06	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	14.40	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	13.62	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	13.71	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	14.04	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	14.47	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	14.57	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	14.50	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	14.53	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	14.68	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	14.32	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	14.20	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	14.08	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	13.67	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	13.63	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	13.91	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	14.14	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	14.03	Note:	Not Reported

Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	14.03	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	14.55	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	14.60	Note:	Not Reported
Level reading date:	1999-07-20	Feet below surface:	Not Reported
Feet to sea level:	14.81	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	14.97	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	14.95	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	14.73	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	14.93	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	15.53	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	15.64	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	16.67	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	17.12	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	17.31	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	17.65	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	17.91	Note:	Not Reported
Level reading date:	1998-06-10	Feet below surface:	Not Reported
Feet to sea level:	17.38	Note:	Not Reported
Level reading date:	1998-05-20	Feet below surface:	Not Reported
Feet to sea level:	17.34	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	16.42	Note:	Not Reported
Level reading date:	1998-03-25	Feet below surface:	Not Reported
Feet to sea level:	15.66	Note:	Not Reported
Level reading date:	1998-01-29	Feet below surface:	Not Reported
Feet to sea level:	16.33	Note:	Not Reported
Level reading date:	1997-12-17	Feet below surface:	Not Reported
Feet to sea level:	16.36	Note:	Not Reported

Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	16.74	Note:	Not Reported
Level reading date:	1997-11-05	Feet below surface:	Not Reported
Feet to sea level:	16.21	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	17.75	Note:	Not Reported
Level reading date:	1997-07-23	Feet below surface:	Not Reported
Feet to sea level:	17.19	Note:	Not Reported
Level reading date:	1997-06-26	Feet below surface:	Not Reported
Feet to sea level:	17.68	Note:	Not Reported
Level reading date:	1997-05-29	Feet below surface:	Not Reported
Feet to sea level:	17.13	Note:	Not Reported
Level reading date:	1997-03-18	Feet below surface:	Not Reported
Feet to sea level:	17.00	Note:	Not Reported
Level reading date:	1997-02-28	Feet below surface:	Not Reported
Feet to sea level:	16.98	Note:	Not Reported
Level reading date:	1997-01-24	Feet below surface:	Not Reported
Feet to sea level:	16.45	Note:	Not Reported
Level reading date:	1997-01-07	Feet below surface:	Not Reported
Feet to sea level:	16.99	Note:	Not Reported
Level reading date:	1996-09-19	Feet below surface:	Not Reported
Feet to sea level:	17.13	Note:	Not Reported
Level reading date:	1996-07-02	Feet below surface:	Not Reported
Feet to sea level:	17.51	Note:	Not Reported
Level reading date:	1996-03-13	Feet below surface:	Not Reported
Feet to sea level:	16.21	Note:	Not Reported
Level reading date:	1995-11-28	Feet below surface:	Not Reported
Feet to sea level:	16.10	Note:	Not Reported
Level reading date:	1995-09-26	Feet below surface:	Not Reported
Feet to sea level:	16.28	Note:	Not Reported
Level reading date:	1995-07-19	Feet below surface:	Not Reported
Feet to sea level:	16.44	Note:	Not Reported
Level reading date:	1995-05-23	Feet below surface:	Not Reported
Feet to sea level:	15.97	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	15.95	Note:	Not Reported
Level reading date:	1995-01-25	Feet below surface:	Not Reported
Feet to sea level:	15.56	Note:	Not Reported
Level reading date:	1994-12-13	Feet below surface:	Not Reported
Feet to sea level:	15.62	Note:	Not Reported
Level reading date:	1994-10-18	Feet below surface:	Not Reported
Feet to sea level:	16.51	Note:	Not Reported

Level reading date:	1994-09-21	Feet below surface:	Not Reported
Feet to sea level:	16.49	Note:	Not Reported
Level reading date:	1994-08-24	Feet below surface:	Not Reported
Feet to sea level:	16.44	Note:	Not Reported
Level reading date:	1994-07-27	Feet below surface:	Not Reported
Feet to sea level:	17.01	Note:	Not Reported
Level reading date:	1994-06-20	Feet below surface:	Not Reported
Feet to sea level:	16.79	Note:	Not Reported
Level reading date:	1994-05-17	Feet below surface:	Not Reported
Feet to sea level:	16.81	Note:	Not Reported
Level reading date:	1994-04-26	Feet below surface:	Not Reported
Feet to sea level:	16.30	Note:	Not Reported
Level reading date:	1994-03-25	Feet below surface:	Not Reported
Feet to sea level:	15.83	Note:	Not Reported
Level reading date:	1994-02-22	Feet below surface:	Not Reported
Feet to sea level:	15.29	Note:	Not Reported
Level reading date:	1993-12-27	Feet below surface:	Not Reported
Feet to sea level:	15.00	Note:	Not Reported
Level reading date:	1993-11-18	Feet below surface:	Not Reported
Feet to sea level:	15.68	Note:	Not Reported
Level reading date:	1993-10-28	Feet below surface:	Not Reported
Feet to sea level:	16.30	Note:	Not Reported
Level reading date:	1993-09-15	Feet below surface:	Not Reported
Feet to sea level:	16.23	Note:	Not Reported
Level reading date:	1993-08-18	Feet below surface:	Not Reported
Feet to sea level:	16.45	Note:	Not Reported
Level reading date:	1993-07-15	Feet below surface:	Not Reported
Feet to sea level:	16.55	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	16.77	Note:	Not Reported
Level reading date:	1993-05-20	Feet below surface:	Not Reported
Feet to sea level:	16.45	Note:	Not Reported
Level reading date:	1993-04-29	Feet below surface:	Not Reported
Feet to sea level:	15.66	Note:	Not Reported
Level reading date:	1993-03-26	Feet below surface:	Not Reported
Feet to sea level:	15.16	Note:	Not Reported
Level reading date:	1993-02-24	Feet below surface:	Not Reported
Feet to sea level:	14.86	Note:	Not Reported
Level reading date:	1993-01-26	Feet below surface:	Not Reported
Feet to sea level:	14.61	Note:	Not Reported
Level reading date:	1992-12-29	Feet below surface:	Not Reported
Feet to sea level:	14.67	Note:	Not Reported

Level reading date:	1992-11-24	Feet below surface:	Not Reported
Feet to sea level:	14.83	Note:	Not Reported
Level reading date:	1992-03-18	Feet below surface:	Not Reported
Feet to sea level:	15.50	Note:	Not Reported
Level reading date:	1991-03-20	Feet below surface:	Not Reported
Feet to sea level:	16.73	Note:	Not Reported
Level reading date:	1990-04-04	Feet below surface:	Not Reported
Feet to sea level:	17.50	Note:	Not Reported
Level reading date:	1990-03-27	Feet below surface:	Not Reported
Feet to sea level:	16.61	Note:	Not Reported
Level reading date:	1989-04-11	Feet below surface:	Not Reported
Feet to sea level:	14.51	Note:	Not Reported
Level reading date:	1988-06-01	Feet below surface:	Not Reported
Feet to sea level:	15.82	Note:	Not Reported
Level reading date:	1985-10-01	Feet below surface:	Not Reported
Feet to sea level:	16.10	Note:	Not Reported
Level reading date:	1985-05-21	Feet below surface:	Not Reported
Feet to sea level:	16.78	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	18.60	Note:	Not Reported
Level reading date:	1984-10-04	Feet below surface:	Not Reported
Feet to sea level:	20.10	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	20.16	Note:	Not Reported
Level reading date:	1984-03-16	Feet below surface:	Not Reported
Feet to sea level:	18.46	Note:	Not Reported
Level reading date:	1984-03-02	Feet below surface:	Not Reported
Feet to sea level:	18.37	Note:	Not Reported

17
SSE **FED USGS** **USGS40000828070**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 104. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	102	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	129	Level reading date:	1943-08-28
Feet below surface:	Not Reported	Feet to sea level:	-25.72
Note:	Not Reported		

Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-25.61	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-25.43	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-25.37	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-25.43	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-25.91	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-25.93	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-26.33	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-26.47	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-26.55	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-26.65	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-26.68	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-26.69	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-26.68	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-26.66	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported

Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-26.58	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-26.56	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-26.49	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-26.49	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-26.48	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-26.43	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-26.44	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-26.39	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-26.37	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-26.31	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-26.32	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported

Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-26.40	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-26.43	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-26.44	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-26.48	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-26.55	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-26.61	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-26.67	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-26.72	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-26.76	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-26.78	Note:	Not Reported

Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-26.80	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-26.81	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-26.84	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-26.87	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-26.87	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-26.87	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-26.84	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-26.80	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-26.74	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-26.68	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-26.40	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-26.30	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-26.22	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-26.16	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-26.13	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-26.10	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-26.05	Note:	Not Reported

Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-26.01	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-25.92	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-25.85	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-25.80	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-25.75	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-25.68	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-25.63	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-25.50	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-25.49	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported

Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-25.62	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-25.65	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-25.74	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-25.81	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-25.87	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-25.91	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-25.99	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-26.03	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-26.09	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-26.10	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-26.11	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-26.12	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-26.11	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-26.04	Note:	Not Reported

Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-26.04	Note:	Not Reported
Level reading date:	1940-08-27	Feet below surface:	Not Reported
Feet to sea level:	-25.89	Note:	Not Reported

F18
WSW **FED USGS** **USGS40000828124**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 638. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	175	Well Hole Depth Units:	ft

F19
WSW **FED USGS** **USGS40000828125**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1332. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	168	Well Hole Depth Units:	ft

20
NNE **FED USGS** **USGS40000828469**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3259. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	30
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	45	Level reading date:	1995-03-14
Feet below surface:	Not Reported	Feet to sea level:	13.98
Note:	Not Reported		

Level reading date:	1995-01-03	Feet below surface:	Not Reported
Feet to sea level:	13.34	Note:	Not Reported
Level reading date:	1994-06-28	Feet below surface:	Not Reported
Feet to sea level:	13.99	Note:	Not Reported
Level reading date:	1994-03-25	Feet below surface:	Not Reported
Feet to sea level:	14.42	Note:	Not Reported
Level reading date:	1993-11-22	Feet below surface:	Not Reported
Feet to sea level:	12.15	Note:	Not Reported
Level reading date:	1993-08-25	Feet below surface:	Not Reported
Feet to sea level:	12.04	Note:	Not Reported
Level reading date:	1993-07-22	Feet below surface:	Not Reported
Feet to sea level:	12.75	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	13.30	Note:	Not Reported
Level reading date:	1993-06-14	Feet below surface:	Not Reported
Feet to sea level:	13.47	Note:	Not Reported
Level reading date:	1993-03-23	Feet below surface:	Not Reported
Feet to sea level:	13.46	Note:	Not Reported
Level reading date:	1993-01-19	Feet below surface:	Not Reported
Feet to sea level:	13.09	Note:	Not Reported
Level reading date:	1992-12-28	Feet below surface:	Not Reported
Feet to sea level:	12.92	Note:	Not Reported
Level reading date:	1992-11-19	Feet below surface:	Not Reported
Feet to sea level:	12.13	Note:	Not Reported
Level reading date:	1992-10-27	Feet below surface:	Not Reported
Feet to sea level:	11.90	Note:	Not Reported
Level reading date:	1992-09-18	Feet below surface:	Not Reported
Feet to sea level:	12.32	Note:	Not Reported
Level reading date:	1992-07-14	Feet below surface:	Not Reported
Feet to sea level:	12.76	Note:	Not Reported
Level reading date:	1992-03-18	Feet below surface:	Not Reported
Feet to sea level:	11.35	Note:	Not Reported
Level reading date:	1991-03-20	Feet below surface:	Not Reported
Feet to sea level:	12.45	Note:	Not Reported
Level reading date:	1990-03-27	Feet below surface:	Not Reported
Feet to sea level:	12.47	Note:	Not Reported
Level reading date:	1989-04-11	Feet below surface:	Not Reported
Feet to sea level:	12.81	Note:	Not Reported
Level reading date:	1988-06-01	Feet below surface:	Not Reported
Feet to sea level:	13.38	Note:	Not Reported
Level reading date:	1985-10-01	Feet below surface:	Not Reported
Feet to sea level:	12.45	Note:	Not Reported

Level reading date:	1985-05-21	Feet below surface:	Not Reported
Feet to sea level:	12.53	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	12.91	Note:	Not Reported
Level reading date:	1984-10-05	Feet below surface:	Not Reported
Feet to sea level:	13.24	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	13.60	Note:	Not Reported
Level reading date:	1984-03-16	Feet below surface:	Not Reported
Feet to sea level:	13.38	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	5.13	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	5.98	Note:	Not Reported
Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	12.13	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	12.38	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	11.88	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	13.28	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	13.66	Note:	Not Reported
Level reading date:	1982-03-24	Feet below surface:	Not Reported
Feet to sea level:	13.42	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	13.90	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	14.24	Note:	Not Reported
Level reading date:	1981-06-25	Feet below surface:	Not Reported
Feet to sea level:	13.76	Note:	Not Reported
Level reading date:	1981-03-20	Feet below surface:	Not Reported
Feet to sea level:	13.94	Note:	Not Reported
Level reading date:	1981-02-10	Feet below surface:	Not Reported
Feet to sea level:	13.43	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	13.16	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	13.35	Note:	Not Reported
Level reading date:	1980-06-24	Feet below surface:	Not Reported
Feet to sea level:	13.06	Note:	Not Reported

Level reading date:	1980-06-10	Feet below surface:	Not Reported
Feet to sea level:	14.02	Note:	Not Reported
Level reading date:	1980-04-11	Feet below surface:	Not Reported
Feet to sea level:	12.13	Note:	Not Reported

21
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828165**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 9. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	159	Well Hole Depth Units:	ft

G22
ENE
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000090**

Well Number:	K003445	Owner:	Affordable Dwellings Units
Well Depth:	100	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

G23
ENE
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000089**

Well Number:	K003444D	Owner:	Affordable Dwellings Units
Well Depth:	100	Diameter:	8
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

G24
East
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000158**

Well Number:	K003512	Owner:	Fimar Construction
Well Depth:	120	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G25
East
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000159**

Well Number:	K003513D	Owner:	Fimar Construction
Well Depth:	120	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

26
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828265**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1536. 1	Type:	Well
Description:	5001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	156	Well Hole Depth Units:	ft

H27
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828451**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 657. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	227	Well Hole Depth Units:	ft

I28
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828018**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 639. 1	Type:	Well
Description:	4001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	176	Well Depth Units:	ft
Well Hole Depth:	190	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H29
NE
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000828468**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 19. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	186
Well Depth Units:	ft	Well Hole Depth:	186
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	276	Level reading date:	2003-03-17
Feet below surface:	Not Reported	Feet to sea level:	8.15
Note:	Not Reported		

Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	7.73	Note:	Not Reported
Level reading date:	2001-03-21	Feet below surface:	Not Reported
Feet to sea level:	8.15	Note:	Not Reported
Level reading date:	2000-03-22	Feet below surface:	Not Reported
Feet to sea level:	8.01	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	8.43	Note:	Not Reported
Level reading date:	1998-05-28	Feet below surface:	Not Reported
Feet to sea level:	8.88	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	8.67	Note:	Not Reported
Level reading date:	1998-03-25	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	1998-02-26	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	1998-01-26	Feet below surface:	Not Reported
Feet to sea level:	8.27	Note:	Not Reported
Level reading date:	1997-12-29	Feet below surface:	Not Reported
Feet to sea level:	8.33	Note:	Not Reported
Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	8.48	Note:	Not Reported
Level reading date:	1997-10-29	Feet below surface:	Not Reported
Feet to sea level:	8.39	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	8.56	Note:	Not Reported

Level reading date:	1997-03-18	Feet below surface:	Not Reported
Feet to sea level:	8.57	Note:	Not Reported
Level reading date:	1996-07-12	Feet below surface:	Not Reported
Feet to sea level:	8.31	Note:	Not Reported
Level reading date:	1995-09-29	Feet below surface:	Not Reported
Feet to sea level:	7.73	Note:	Not Reported
Level reading date:	1995-06-22	Feet below surface:	Not Reported
Feet to sea level:	7.87	Note:	Not Reported
Level reading date:	1995-03-15	Feet below surface:	Not Reported
Feet to sea level:	8.28	Note:	Not Reported
Level reading date:	1995-01-03	Feet below surface:	Not Reported
Feet to sea level:	8.59	Note:	Not Reported
Level reading date:	1994-06-28	Feet below surface:	Not Reported
Feet to sea level:	8.97	Note:	Not Reported
Level reading date:	1993-11-22	Feet below surface:	Not Reported
Feet to sea level:	8.35	Note:	Not Reported
Level reading date:	1993-08-25	Feet below surface:	Not Reported
Feet to sea level:	8.38	Note:	Not Reported
Level reading date:	1993-07-22	Feet below surface:	Not Reported
Feet to sea level:	8.51	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	8.66	Note:	Not Reported
Level reading date:	1993-05-24	Feet below surface:	Not Reported
Feet to sea level:	8.82	Note:	Not Reported
Level reading date:	1993-04-28	Feet below surface:	Not Reported
Feet to sea level:	8.91	Note:	Not Reported
Level reading date:	1993-03-23	Feet below surface:	Not Reported
Feet to sea level:	8.44	Note:	Not Reported
Level reading date:	1993-01-19	Feet below surface:	Not Reported
Feet to sea level:	8.41	Note:	Not Reported
Level reading date:	1992-12-28	Feet below surface:	Not Reported
Feet to sea level:	8.39	Note:	Not Reported
Level reading date:	1992-11-19	Feet below surface:	Not Reported
Feet to sea level:	8.25	Note:	Not Reported
Level reading date:	1992-10-27	Feet below surface:	Not Reported
Feet to sea level:	8.29	Note:	Not Reported
Level reading date:	1992-09-18	Feet below surface:	Not Reported
Feet to sea level:	8.37	Note:	Not Reported
Level reading date:	1992-08-24	Feet below surface:	Not Reported
Feet to sea level:	8.34	Note:	Not Reported
Level reading date:	1992-07-14	Feet below surface:	Not Reported
Feet to sea level:	8.31	Note:	Not Reported

Level reading date:	1989-03-08	Feet below surface:	Not Reported
Feet to sea level:	8.14	Note:	Not Reported
Level reading date:	1988-06-01	Feet below surface:	Not Reported
Feet to sea level:	8.17	Note:	Not Reported
Level reading date:	1987-09-10	Feet below surface:	Not Reported
Feet to sea level:	7.97	Note:	Not Reported
Level reading date:	1987-03-10	Feet below surface:	Not Reported
Feet to sea level:	7.79	Note:	Not Reported
Level reading date:	1986-09-10	Feet below surface:	Not Reported
Feet to sea level:	7.46	Note:	Not Reported
Level reading date:	1986-06-13	Feet below surface:	Not Reported
Feet to sea level:	7.59	Note:	Not Reported
Level reading date:	1985-12-03	Feet below surface:	Not Reported
Feet to sea level:	7.64	Note:	Not Reported
Level reading date:	1985-10-01	Feet below surface:	Not Reported
Feet to sea level:	7.57	Note:	Not Reported
Level reading date:	1985-05-21	Feet below surface:	Not Reported
Feet to sea level:	8.48	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	10.17	Note:	Not Reported
Level reading date:	1984-10-05	Feet below surface:	Not Reported
Feet to sea level:	9.78	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.27	Note:	Not Reported
Level reading date:	1984-03-16	Feet below surface:	Not Reported
Feet to sea level:	9.83	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	9.80	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	8.34	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	8.83	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	8.27	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	8.56	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	8.87	Note:	Not Reported
Level reading date:	1982-04-02	Feet below surface:	Not Reported
Feet to sea level:	9.08	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	8.77	Note:	Not Reported

Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	8.47	Note:	Not Reported
Level reading date:	1981-06-25	Feet below surface:	Not Reported
Feet to sea level:	8.96	Note:	Not Reported
Level reading date:	1981-03-27	Feet below surface:	Not Reported
Feet to sea level:	9.41	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	9.60	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	9.87	Note:	Not Reported
Level reading date:	1980-06-19	Feet below surface:	Not Reported
Feet to sea level:	10.29	Note:	Not Reported
Level reading date:	1980-03-13	Feet below surface:	Not Reported
Feet to sea level:	9.46	Note:	Not Reported
Level reading date:	1979-12-18	Feet below surface:	Not Reported
Feet to sea level:	10.02	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	1978-06-14	Feet below surface:	Not Reported
Feet to sea level:	10.18	Note:	Not Reported
Level reading date:	1977-03-29	Feet below surface:	Not Reported
Feet to sea level:	7.77	Note:	Not Reported
Level reading date:	1976-12-21	Feet below surface:	Not Reported
Feet to sea level:	8.00	Note:	Not Reported
Level reading date:	1976-09-22	Feet below surface:	Not Reported
Feet to sea level:	7.99	Note:	Not Reported
Level reading date:	1976-07-09	Feet below surface:	Not Reported
Feet to sea level:	7.97	Note:	Not Reported
Level reading date:	1975-12-16	Feet below surface:	Not Reported
Feet to sea level:	8.03	Note:	Not Reported
Level reading date:	1975-10-07	Feet below surface:	Not Reported
Feet to sea level:	8.41	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	7.50	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	7.85	Note:	Not Reported
Level reading date:	1974-12-20	Feet below surface:	Not Reported
Feet to sea level:	7.83	Note:	Not Reported
Level reading date:	1974-09-25	Feet below surface:	Not Reported
Feet to sea level:	7.62	Note:	Not Reported

Level reading date:	1974-09-05	Feet below surface:	Not Reported
Feet to sea level:	7.95	Note:	Not Reported
Level reading date:	1974-06-28	Feet below surface:	Not Reported
Feet to sea level:	7.98	Note:	Not Reported
Level reading date:	1974-03-19	Feet below surface:	Not Reported
Feet to sea level:	8.20	Note:	Not Reported
Level reading date:	1974-01-09	Feet below surface:	Not Reported
Feet to sea level:	8.24	Note:	Not Reported
Level reading date:	1973-09-25	Feet below surface:	Not Reported
Feet to sea level:	7.29	Note:	Not Reported
Level reading date:	1973-07-09	Feet below surface:	Not Reported
Feet to sea level:	7.77	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	7.58	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	7.37	Note:	Not Reported
Level reading date:	1972-09-29	Feet below surface:	Not Reported
Feet to sea level:	7.04	Note:	Not Reported
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	7.67	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	6.77	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	6.94	Note:	Not Reported
Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	7.01	Note:	Not Reported
Level reading date:	1971-07-28	Feet below surface:	Not Reported
Feet to sea level:	8.33	Note:	Not Reported
Level reading date:	1971-05-05	Feet below surface:	Not Reported
Feet to sea level:	7.33	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	5.38	Note:	Not Reported
Level reading date:	1971-02-09	Feet below surface:	Not Reported
Feet to sea level:	6.59	Note:	Not Reported
Level reading date:	1970-10-30	Feet below surface:	Not Reported
Feet to sea level:	6.38	Note:	Not Reported
Level reading date:	1970-05-08	Feet below surface:	Not Reported
Feet to sea level:	6.67	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	6.38	Note:	Not Reported
Level reading date:	1970-02-06	Feet below surface:	Not Reported
Feet to sea level:	5.97	Note:	Not Reported

Level reading date:	1969-11-10	Feet below surface:	Not Reported
Feet to sea level:	5.90	Note:	Not Reported
Level reading date:	1969-09-02	Feet below surface:	Not Reported
Feet to sea level:	5.69	Note:	Not Reported
Level reading date:	1969-08-04	Feet below surface:	Not Reported
Feet to sea level:	5.48	Note:	Not Reported
Level reading date:	1969-07-02	Feet below surface:	Not Reported
Feet to sea level:	5.14	Note:	Not Reported
Level reading date:	1969-05-28	Feet below surface:	Not Reported
Feet to sea level:	5.00	Note:	Not Reported
Level reading date:	1969-04-22	Feet below surface:	Not Reported
Feet to sea level:	4.99	Note:	Not Reported
Level reading date:	1969-04-01	Feet below surface:	Not Reported
Feet to sea level:	4.79	Note:	Not Reported
Level reading date:	1969-03-01	Feet below surface:	Not Reported
Feet to sea level:	4.59	Note:	Not Reported
Level reading date:	1969-01-30	Feet below surface:	Not Reported
Feet to sea level:	4.57	Note:	Not Reported
Level reading date:	1969-01-08	Feet below surface:	Not Reported
Feet to sea level:	4.39	Note:	Not Reported
Level reading date:	1968-12-03	Feet below surface:	Not Reported
Feet to sea level:	4.07	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	3.87	Note:	Not Reported
Level reading date:	1968-09-30	Feet below surface:	Not Reported
Feet to sea level:	3.94	Note:	Not Reported
Level reading date:	1968-08-28	Feet below surface:	Not Reported
Feet to sea level:	3.92	Note:	Not Reported
Level reading date:	1968-07-29	Feet below surface:	Not Reported
Feet to sea level:	4.13	Note:	Not Reported
Level reading date:	1968-06-26	Feet below surface:	Not Reported
Feet to sea level:	4.15	Note:	Not Reported
Level reading date:	1968-05-28	Feet below surface:	Not Reported
Feet to sea level:	4.12	Note:	Not Reported
Level reading date:	1968-04-22	Feet below surface:	Not Reported
Feet to sea level:	4.40	Note:	Not Reported
Level reading date:	1968-03-27	Feet below surface:	Not Reported
Feet to sea level:	4.29	Note:	Not Reported
Level reading date:	1968-03-06	Feet below surface:	Not Reported
Feet to sea level:	4.01	Note:	Not Reported
Level reading date:	1968-02-05	Feet below surface:	Not Reported
Feet to sea level:	4.29	Note:	Not Reported

Level reading date:	1968-01-02	Feet below surface:	Not Reported
Feet to sea level:	4.63	Note:	Not Reported
Level reading date:	1967-11-29	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	3.62	Note:	Not Reported
Level reading date:	1967-09-26	Feet below surface:	Not Reported
Feet to sea level:	3.82	Note:	Not Reported
Level reading date:	1967-09-07	Feet below surface:	Not Reported
Feet to sea level:	3.82	Note:	Not Reported
Level reading date:	1967-07-28	Feet below surface:	Not Reported
Feet to sea level:	3.56	Note:	Not Reported
Level reading date:	1967-07-06	Feet below surface:	Not Reported
Feet to sea level:	3.57	Note:	Not Reported
Level reading date:	1967-05-31	Feet below surface:	Not Reported
Feet to sea level:	3.67	Note:	Not Reported
Level reading date:	1967-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.38	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.48	Note:	Not Reported
Level reading date:	1967-02-24	Feet below surface:	Not Reported
Feet to sea level:	3.25	Note:	Not Reported
Level reading date:	1967-01-31	Feet below surface:	Not Reported
Feet to sea level:	1.93	Note:	Not Reported
Level reading date:	1966-12-23	Feet below surface:	Not Reported
Feet to sea level:	3.09	Note:	Not Reported
Level reading date:	1966-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1966-10-25	Feet below surface:	Not Reported
Feet to sea level:	2.68	Note:	Not Reported
Level reading date:	1966-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.66	Note:	Not Reported
Level reading date:	1966-08-29	Feet below surface:	Not Reported
Feet to sea level:	2.64	Note:	Not Reported
Level reading date:	1966-07-29	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1966-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.94	Note:	Not Reported
Level reading date:	1966-05-26	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1966-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported

Level reading date:	1966-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.31	Note:	Not Reported
Level reading date:	1966-03-02	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1966-01-28	Feet below surface:	Not Reported
Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1965-12-30	Feet below surface:	Not Reported
Feet to sea level:	3.41	Note:	Not Reported
Level reading date:	1965-12-02	Feet below surface:	Not Reported
Feet to sea level:	3.12	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	3.09	Note:	Not Reported
Level reading date:	1965-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1965-09-09	Feet below surface:	Not Reported
Feet to sea level:	3.09	Note:	Not Reported
Level reading date:	1965-07-23	Feet below surface:	Not Reported
Feet to sea level:	3.13	Note:	Not Reported
Level reading date:	1965-06-24	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported
Level reading date:	1965-05-24	Feet below surface:	Not Reported
Feet to sea level:	3.28	Note:	Not Reported
Level reading date:	1965-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.31	Note:	Not Reported
Level reading date:	1965-03-25	Feet below surface:	Not Reported
Feet to sea level:	3.03	Note:	Not Reported
Level reading date:	1965-02-24	Feet below surface:	Not Reported
Feet to sea level:	3.00	Note:	Not Reported
Level reading date:	1965-01-29	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1964-12-31	Feet below surface:	Not Reported
Feet to sea level:	2.49	Note:	Not Reported
Level reading date:	1964-11-25	Feet below surface:	Not Reported
Feet to sea level:	2.69	Note:	Not Reported
Level reading date:	1964-11-02	Feet below surface:	Not Reported
Feet to sea level:	2.72	Note:	Not Reported
Level reading date:	1964-10-01	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1964-09-02	Feet below surface:	Not Reported
Feet to sea level:	2.32	Note:	Not Reported
Level reading date:	1964-07-27	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported

Level reading date:	1964-07-06	Feet below surface:	Not Reported
Feet to sea level:	2.79	Note:	Not Reported
Level reading date:	1964-05-28	Feet below surface:	Not Reported
Feet to sea level:	2.74	Note:	Not Reported
Level reading date:	1964-04-23	Feet below surface:	Not Reported
Feet to sea level:	2.76	Note:	Not Reported
Level reading date:	1964-03-30	Feet below surface:	Not Reported
Feet to sea level:	2.85	Note:	Not Reported
Level reading date:	1964-02-28	Feet below surface:	Not Reported
Feet to sea level:	2.58	Note:	Not Reported
Level reading date:	1964-01-28	Feet below surface:	Not Reported
Feet to sea level:	2.45	Note:	Not Reported
Level reading date:	1963-12-31	Feet below surface:	Not Reported
Feet to sea level:	2.20	Note:	Not Reported
Level reading date:	1963-12-05	Feet below surface:	Not Reported
Feet to sea level:	2.14	Note:	Not Reported
Level reading date:	1963-11-05	Feet below surface:	Not Reported
Feet to sea level:	2.14	Note:	Not Reported
Level reading date:	1963-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.23	Note:	Not Reported
Level reading date:	1963-09-03	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1963-07-30	Feet below surface:	Not Reported
Feet to sea level:	2.43	Note:	Not Reported
Level reading date:	1963-07-02	Feet below surface:	Not Reported
Feet to sea level:	2.61	Note:	Not Reported
Level reading date:	1963-06-03	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1963-04-25	Feet below surface:	Not Reported
Feet to sea level:	3.04	Note:	Not Reported
Level reading date:	1963-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.04	Note:	Not Reported
Level reading date:	1963-02-28	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1963-01-31	Feet below surface:	Not Reported
Feet to sea level:	3.06	Note:	Not Reported
Level reading date:	1963-01-03	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1962-10-03	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported

Level reading date:	1962-08-31	Feet below surface:	Not Reported
Feet to sea level:	3.03	Note:	Not Reported
Level reading date:	1962-07-30	Feet below surface:	Not Reported
Feet to sea level:	3.45	Note:	Not Reported
Level reading date:	1962-07-02	Feet below surface:	Not Reported
Feet to sea level:	3.37	Note:	Not Reported
Level reading date:	1962-05-29	Feet below surface:	Not Reported
Feet to sea level:	4.36	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	3.75	Note:	Not Reported
Level reading date:	1962-03-27	Feet below surface:	Not Reported
Feet to sea level:	3.36	Note:	Not Reported
Level reading date:	1962-03-05	Feet below surface:	Not Reported
Feet to sea level:	3.27	Note:	Not Reported
Level reading date:	1962-01-31	Feet below surface:	Not Reported
Feet to sea level:	3.00	Note:	Not Reported
Level reading date:	1961-12-28	Feet below surface:	Not Reported
Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1961-11-28	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported
Level reading date:	1961-10-31	Feet below surface:	Not Reported
Feet to sea level:	2.42	Note:	Not Reported
Level reading date:	1961-09-28	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1961-08-31	Feet below surface:	Not Reported
Feet to sea level:	2.88	Note:	Not Reported
Level reading date:	1961-08-01	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1961-06-29	Feet below surface:	Not Reported
Feet to sea level:	2.60	Note:	Not Reported
Level reading date:	1961-05-31	Feet below surface:	Not Reported
Feet to sea level:	2.91	Note:	Not Reported
Level reading date:	1961-04-26	Feet below surface:	Not Reported
Feet to sea level:	2.61	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	2.43	Note:	Not Reported
Level reading date:	1961-03-01	Feet below surface:	Not Reported
Feet to sea level:	2.12	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	1.97	Note:	Not Reported
Level reading date:	1960-12-06	Feet below surface:	Not Reported
Feet to sea level:	1.57	Note:	Not Reported

Level reading date:	1960-11-02	Feet below surface:	Not Reported
Feet to sea level:	1.46	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	1.23	Note:	Not Reported
Level reading date:	1960-08-30	Feet below surface:	Not Reported
Feet to sea level:	1.09	Note:	Not Reported
Level reading date:	1960-08-02	Feet below surface:	Not Reported
Feet to sea level:	1.10	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1960-06-02	Feet below surface:	Not Reported
Feet to sea level:	1.44	Note:	Not Reported
Level reading date:	1960-05-04	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported
Level reading date:	1960-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.26	Note:	Not Reported
Level reading date:	1960-03-08	Feet below surface:	Not Reported
Feet to sea level:	1.16	Note:	Not Reported
Level reading date:	1960-01-27	Feet below surface:	Not Reported
Feet to sea level:	0.94	Note:	Not Reported
Level reading date:	1960-01-05	Feet below surface:	Not Reported
Feet to sea level:	0.93	Note:	Not Reported
Level reading date:	1959-12-01	Feet below surface:	Not Reported
Feet to sea level:	0.60	Note:	Not Reported
Level reading date:	1959-11-02	Feet below surface:	Not Reported
Feet to sea level:	0.71	Note:	Not Reported
Level reading date:	1959-10-06	Feet below surface:	Not Reported
Feet to sea level:	0.53	Note:	Not Reported
Level reading date:	1959-09-03	Feet below surface:	Not Reported
Feet to sea level:	0.73	Note:	Not Reported
Level reading date:	1959-08-04	Feet below surface:	Not Reported
Feet to sea level:	0.87	Note:	Not Reported
Level reading date:	1959-07-02	Feet below surface:	Not Reported
Feet to sea level:	1.12	Note:	Not Reported
Level reading date:	1959-06-01	Feet below surface:	Not Reported
Feet to sea level:	1.41	Note:	Not Reported
Level reading date:	1959-05-06	Feet below surface:	Not Reported
Feet to sea level:	1.36	Note:	Not Reported
Level reading date:	1959-04-03	Feet below surface:	Not Reported
Feet to sea level:	1.54	Note:	Not Reported
Level reading date:	1959-03-02	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported

Level reading date:	1959-01-29	Feet below surface:	Not Reported
Feet to sea level:	1.34	Note:	Not Reported
Level reading date:	1959-01-07	Feet below surface:	Not Reported
Feet to sea level:	1.47	Note:	Not Reported
Level reading date:	1958-10-30	Feet below surface:	Not Reported
Feet to sea level:	1.16	Note:	Not Reported
Level reading date:	1958-08-28	Feet below surface:	Not Reported
Feet to sea level:	0.94	Note:	Not Reported
Level reading date:	1958-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.14	Note:	Not Reported
Level reading date:	1958-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.14	Note:	Not Reported
Level reading date:	1958-05-29	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1958-05-01	Feet below surface:	Not Reported
Feet to sea level:	0.79	Note:	Not Reported
Level reading date:	1958-04-08	Feet below surface:	Not Reported
Feet to sea level:	0.59	Note:	Not Reported
Level reading date:	1958-03-03	Feet below surface:	Not Reported
Feet to sea level:	0.40	Note:	Not Reported
Level reading date:	1958-01-28	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1957-12-31	Feet below surface:	Not Reported
Feet to sea level:	-0.04	Note:	Not Reported
Level reading date:	1957-11-22	Feet below surface:	Not Reported
Feet to sea level:	-0.19	Note:	Not Reported
Level reading date:	1957-10-30	Feet below surface:	Not Reported
Feet to sea level:	-0.23	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-0.43	Note:	Not Reported
Level reading date:	1957-09-04	Feet below surface:	Not Reported
Feet to sea level:	-0.21	Note:	Not Reported
Level reading date:	1957-07-24	Feet below surface:	Not Reported
Feet to sea level:	-0.24	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	-0.12	Note:	Not Reported
Level reading date:	1957-05-28	Feet below surface:	Not Reported
Feet to sea level:	0.09	Note:	Not Reported
Level reading date:	1957-04-24	Feet below surface:	Not Reported
Feet to sea level:	0.17	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	0.07	Note:	Not Reported

Level reading date:	1957-02-27	Feet below surface:	Not Reported
Feet to sea level:	0.21	Note:	Not Reported
Level reading date:	1957-01-25	Feet below surface:	Not Reported
Feet to sea level:	-0.03	Note:	Not Reported
Level reading date:	1956-12-20	Feet below surface:	Not Reported
Feet to sea level:	-0.16	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	-0.18	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	-0.31	Note:	Not Reported
Level reading date:	1956-09-04	Feet below surface:	Not Reported
Feet to sea level:	-0.41	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-0.35	Note:	Not Reported
Level reading date:	1956-07-03	Feet below surface:	Not Reported
Feet to sea level:	-0.33	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.17	Note:	Not Reported
Level reading date:	1956-05-03	Feet below surface:	Not Reported
Feet to sea level:	-0.28	Note:	Not Reported
Level reading date:	1956-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.56	Note:	Not Reported
Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-0.69	Note:	Not Reported
Level reading date:	1956-02-03	Feet below surface:	Not Reported
Feet to sea level:	-0.96	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-1.11	Note:	Not Reported
Level reading date:	1955-12-02	Feet below surface:	Not Reported
Feet to sea level:	-1.43	Note:	Not Reported
Level reading date:	1955-11-04	Feet below surface:	Not Reported
Feet to sea level:	-1.66	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-1.88	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	-2.01	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	-1.97	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-1.71	Note:	Not Reported
Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	-1.47	Note:	Not Reported

Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	-1.54	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	-1.71	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-1.77	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-2.03	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	-2.29	Note:	Not Reported
Level reading date:	1954-10-28	Feet below surface:	Not Reported
Feet to sea level:	-2.61	Note:	Not Reported
Level reading date:	1954-10-05	Feet below surface:	Not Reported
Feet to sea level:	-2.79	Note:	Not Reported
Level reading date:	1954-08-25	Feet below surface:	Not Reported
Feet to sea level:	-2.62	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	-2.74	Note:	Not Reported

30
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828478**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 702. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	140	Well Hole Depth Units:	ft

I31
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828019**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1010. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	181	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J32
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828512**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 725. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	115	Well Hole Depth Units:	ft

J33
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828518**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 694. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	117	Well Hole Depth Units:	ft

K34
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000828532**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 731. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	210	Well Hole Depth Units:	ft

35
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828501**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 654. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	158	Well Hole Depth Units:	ft

K36
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828544**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 676. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	163	Well Hole Depth Units:	ft

37
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000827905**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 907. 1	Type:	Well
Description:	2301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	130
Well Hole Depth Units:	ft		

38
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828444**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 668. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	199	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

39
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828549**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 655. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	214	Well Hole Depth Units:	ft

40
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828443**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 20. 1	Type:	Well
Description:	2401	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	126
Well Depth Units:	ft	Well Hole Depth:	136
Well Hole Depth Units:	ft		

41
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828523**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 18. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

L42
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828020**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2512. 1	Type:	Well

Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	152	Well Hole Depth Units:	ft

L43
WSW **FED USGS** **USGS40000828021**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2513. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	130	Well Hole Depth Units:	ft

44
NNE **FED USGS** **USGS40000828558**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 659. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	170	Well Hole Depth Units:	ft

45
WNW **FED USGS** **USGS40000828410**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 669. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	182	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M46
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828587**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 656. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	159	Well Hole Depth Units:	ft

N47
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828183**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 720. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	103	Well Hole Depth Units:	ft

N48
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828193**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1091. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	124	Well Hole Depth Units:	ft

M49
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828602**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 290. 1	Type:	Well
Description:	0001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	104	Well Hole Depth Units:	ft

M50
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828606**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 277. 1	Type:	Well
Description:	5401	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	83	Well Depth Units:	ft
Well Hole Depth:	146	Well Hole Depth Units:	ft

51
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828601**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1073. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	120	Well Hole Depth Units:	ft

O52
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828620**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 320. 1	Type:	Well
Description:	5701	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	114	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O53
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828619**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 660. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	125	Well Hole Depth Units:	ft

O54
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828627**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 259. 1	Type:	Well
Description:	5901	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	86	Well Depth Units:	ft
Well Hole Depth:	113	Well Hole Depth Units:	ft

55
NNW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000125**

Well Number:	K003480	Owner:	Atlantic Savvy Car Wash Ltd.
Well Depth:	80	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

P56
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828254**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1069. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	60
Well Depth Units:	ft	Well Hole Depth:	Not Reported

Well Hole Depth Units: Not Reported

Ground water levels,Number of Measurements:	55	Level reading date:	1980-03-13
Feet below surface:	Not Reported	Feet to sea level:	1.31
Note:	Not Reported		

Level reading date:	1979-12-18	Feet below surface:	Not Reported
Feet to sea level:	2.00	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	1.80	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	2.50	Note:	Not Reported
Level reading date:	1979-03-26	Feet below surface:	Not Reported
Feet to sea level:	1.89	Note:	Not Reported
Level reading date:	1978-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.49	Note:	Not Reported
Level reading date:	1978-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1978-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1978-04-04	Feet below surface:	Not Reported
Feet to sea level:	2.97	Note:	Not Reported
Level reading date:	1978-01-03	Feet below surface:	Not Reported
Feet to sea level:	2.73	Note:	Not Reported
Level reading date:	1977-10-13	Feet below surface:	Not Reported
Feet to sea level:	2.65	Note:	Not Reported
Level reading date:	1977-07-07	Feet below surface:	Not Reported
Feet to sea level:	2.34	Note:	Not Reported
Level reading date:	1977-03-28	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1976-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.84	Note:	Not Reported
Level reading date:	1976-09-23	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported
Level reading date:	1976-06-28	Feet below surface:	Not Reported
Feet to sea level:	2.40	Note:	Not Reported
Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	2.35	Note:	Not Reported
Level reading date:	1975-12-30	Feet below surface:	Not Reported
Feet to sea level:	2.33	Note:	Not Reported
Level reading date:	1975-10-08	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported

Feet to sea level:	2.29	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	2.27	Note:	Not Reported
Level reading date:	1974-12-20	Feet below surface:	Not Reported
Feet to sea level:	2.38	Note:	Not Reported
Level reading date:	1974-09-05	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1973-10-02	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1973-07-09	Feet below surface:	Not Reported
Feet to sea level:	0.23	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	0.56	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.07	Note:	Not Reported
Level reading date:	1972-10-03	Feet below surface:	Not Reported
Feet to sea level:	0.50	Note:	Not Reported
Level reading date:	1972-07-11	Feet below surface:	Not Reported
Feet to sea level:	0.30	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	0.90	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	1.86	Note:	Not Reported
Level reading date:	1971-09-27	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	2.01	Note:	Not Reported
Level reading date:	1970-10-30	Feet below surface:	Not Reported
Feet to sea level:	1.94	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	1.75	Note:	Not Reported
Level reading date:	1969-11-10	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1969-09-03	Feet below surface:	Not Reported
Feet to sea level:	1.05	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1968-04-23	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1967-10-23	Feet below surface:	Not Reported
Feet to sea level:	1.46	Note:	Not Reported

Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.61	Note:	Not Reported
Level reading date:	1966-10-25	Feet below surface:	Not Reported
Feet to sea level:	-0.78	Note:	Not Reported
Level reading date:	1966-05-04	Feet below surface:	Not Reported
Feet to sea level:	1.46	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported
Level reading date:	1965-09-14	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1965-05-04	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1964-11-02	Feet below surface:	Not Reported
Feet to sea level:	1.28	Note:	Not Reported
Level reading date:	1964-04-23	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported
Level reading date:	1963-04-25	Feet below surface:	Not Reported
Feet to sea level:	1.75	Note:	Not Reported
Level reading date:	1961-12-28	Feet below surface:	Not Reported
Feet to sea level:	1.76	Note:	Not Reported
Level reading date:	1960-09-09	Feet below surface:	Not Reported
Feet to sea level:	0.73	Note:	Not Reported
Level reading date:	1960-01-11	Feet below surface:	Not Reported
Feet to sea level:	0.82	Note:	Not Reported
Level reading date:	1954-12-17	Feet below surface:	Not Reported
Feet to sea level:	0.06	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-0.11	Note:	Not Reported
Level reading date:	1953-01-15	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported

P57
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828200**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 700. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	116	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

58
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828339**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 703. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	138	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

296 4th Avenue
296 4th Avenue
Brooklyn, NY 11215

Inquiry Number: 07124126.2r
September 20, 2022

EDR Summary Radius Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1449
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2022 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

296 4TH AVENUE
BROOKLYN, NY 11215

COORDINATES

Latitude (North):	40.6755770 - 40ˆ 40' 32.07''
Longitude (West):	73.9850410 - 73ˆ 59' 6.14''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	585779.8
UTM Y (Meters):	4503028.0
Elevation:	23 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	TP
Source:	U.S. Geological Survey

Target Property:	W
Source:	U.S. Geological Survey

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150729, 20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	MAACO AUTO PAINTING	296 4TH AVE.	US AIRS, FINDS, ECHO		TP
A2	JEN JAY TRANSMISSION	296 4TH AVE	EDR Hist Auto		TP
A3	MAACO AUTO PAINTING	296 4TH AVE & 1ST ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST		TP
Reg	GOWANUS CANAL	BUTLER ST (BETWEEN B	NPL, SEMS, US ENG CONTROLS, US INST CONTROLS, ROD	Same	1037, 0.196, WSW
A4	CON EDISON	292 4TH AV	NY MANIFEST	Higher	1 ft.
A5	CON EDISON	292 4TH AV	NY MANIFEST	Higher	1 ft.
A6	MC DONALD'S	245 1ST STREET	NY Spills	Lower	40, 0.008, WNW
A7	STREET	1ST STREET/4TH AVE	NY Spills	Higher	60, 0.011, SSE
A8	3RD AVE YARD	1ST ST & 4TH AVE	NY Spills	Higher	93, 0.018, SSE
A9	MTA NYCT - 4TH AVE G	276 4TH AVE	RCRA-SQG	Higher	99, 0.019, ENE
B10	4TH AVE/GARFIELD ST	4TH AVE/GARFIELD ST	NY Spills	Higher	105, 0.020, ENE
A11	272 4TH AVENUE	272 4TH AVENUE	NY BROWNFIELDS, NY Spills	Higher	122, 0.023, NE
A12	CONSTRUCTION SITE	267 FOURTH AVENUE IN	NY Spills	Higher	123, 0.023, East
A13	275 FOURTH AVENUE DE	275 4TH AVE	RCRA-LQG	Higher	138, 0.026, ESE
A14	NORTH PETROLEUM CORP	275 FOURTH AVE	NY UST, NY AST	Higher	138, 0.026, ESE
A15	275 4TH AVE INVESTOR	275 4TH AVE	NY MANIFEST	Higher	138, 0.026, ESE
A16	275 4TH AVENUE	275 4TH AVENUE	NY VCP	Higher	138, 0.026, ESE
A17	DIANA FUEL CORP	275 4TH AVE	EDR Hist Auto	Higher	138, 0.026, ESE
A18	275 4TH AVENUE INVES	275 4TH AVENUE	PA MANIFEST	Higher	138, 0.026, ESE
A19	LOT 1,TAXBLOCK 964	275 4 AVENUE	NY E DESIGNATION	Higher	138, 0.026, ESE
A20	269-271 4TH AVENUE	271 4TH AVENUE	NY VCP	Higher	139, 0.026, ESE
A21	LOT 6,TAXBLOCK 964	271 4 AVENUE	NY E DESIGNATION	Higher	139, 0.026, ESE
A22	FORMER GAS STATION	269-271 4TH AVE	NY Spills	Higher	139, 0.026, ESE
A23	LOT 7,TAXBLOCK 964	269 4 AVENUE	NY E DESIGNATION	Higher	139, 0.026, ESE
A24	YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A25	CONSOLIDATED EDISON	222 FIRST STREET	NY MANIFEST	Lower	142, 0.027, West
A26	CON EDISON	222 FIRST ST	NY MANIFEST	Lower	142, 0.027, West
A27	CON EDISON VEHICLE 6	222 1ST ST	NY Spills	Lower	142, 0.027, West
A28	THIRD AVE YARD - SER	222 1ST STREET	NY Spills	Lower	142, 0.027, West
A29	THIRD AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A30	CON EDISON	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A31	THIRD AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A32	SERVICE BOX 3RD AVE	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A33	CON EDISON - 3RD AVE	222 1ST ST	RCRA-LQG, NJ MANIFEST	Lower	142, 0.027, West
A34	CON ED 3RD AVE STATI	222 1ST ST	NY Spills	Lower	142, 0.027, West
A35	COOLANT RELEASE FROM	222 1 STREET (THIRD	NY Spills	Lower	142, 0.027, West
A36	CONSOLIDATED EDISON	222 1ST ST	NY MANIFEST	Lower	142, 0.027, West
A37	CON ED THIRD AVE YAR	222 FIRST ST	NY Spills	Lower	142, 0.027, West
A38	CON-ED THIRD AVE YAR	222 FIRST ST	NY Spills	Lower	142, 0.027, West

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A39	CONSOLIDATED EDISON	222 FIRST ST	NY MANIFEST	Lower	142, 0.027, West
A40	CON ED 3RD AV YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A41	CON ED 3RD AV GARAGE	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A42	CON ED FACILITY	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A43	OIL LEAK FROM VEHICL	222 FIRST ST AT 3 AV	NY Spills	Lower	142, 0.027, West
A44	CON EDISON 3RD AVE Y	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A45	CON ED STATION	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A46	3RD AVENUE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A47	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A48	3RD AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A49	CON EDISON - OTHER -	222 1 ST	RCRA-LQG	Lower	142, 0.027, West
A50	THIRD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A51	3 QT ANTI-FREEZE FRO	222 FIRST ST. CON ED	NY Spills	Lower	142, 0.027, West
A52	3RD AVE SERVICE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A53	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A54	CON EDISON	222 FIRST ST	NY MANIFEST	Lower	142, 0.027, West
A55	CON EDISON TM439	222 1ST ST	RCRA NonGen / NLR, NY MANIFEST	Lower	142, 0.027, West
A56	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A57	3RD AVE YARD CON ED	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A58	222 1ST STREET	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A59	CON ED	222 1 ST	NY MANIFEST	Lower	142, 0.027, West
A60	CON EDISON	222 1ST ST	NY MANIFEST	Lower	142, 0.027, West
A61	THIRD AVENUE YARD	222 1ST STREET	NY Spills	Lower	142, 0.027, West
A62	CON ED	222 FIRST ST	NY Spills	Lower	142, 0.027, West
A63	222 FIRST STREET	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A64	3RD AVE FLUSH TRUCK	222 FIRST STREET	NY SWF/LF	Lower	142, 0.027, West
A65	3RD AV YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A66	3 AVE YARD	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A67	LEAK FROM VEHICLE IN	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A68	CON EDISON GARAGE	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A69	VEHICLE 60722 LOST H	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A70	THIRD AVENUE YARD	222 FIRST STREET	NY BROWNFIELDS	Lower	142, 0.027, West
A71	THIRD AVENUE YARD	222 FIRST STREET	NY TANKS, NY Spills	Lower	142, 0.027, West
A72	CON ED WORK / 3RD AV	222 1ST ST	NY Spills	Lower	142, 0.027, West
A73	FLUSH PIT	222 FIRST STREET	NY Spills	Lower	142, 0.027, West
A74	3RD AVE YARD	222 1ST ST	NY Spills	Lower	142, 0.027, West
A75	CON EDISON	221 1ST	NY MANIFEST	Lower	143, 0.027, WNW
A76	CON EDISON	221 1ST ST	NY Spills, NY MANIFEST	Lower	143, 0.027, WNW
A77	CON EDISON	221 1ST	RCRA NonGen / NLR	Lower	143, 0.027, WNW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A78	CON EDISON	221 1ST ST	RCRA NonGen / NLR	Lower	143, 0.027, WNW
B79	CON EDISON MANHOLE:	540 CARROLL ST	RCRA NonGen / NLR	Higher	145, 0.027, NNE
B80	CON EDISON	540 CARROLL ST	NY MANIFEST	Higher	145, 0.027, NNE
A81	220 1ST STREET	220 1ST STREET	NY Spills	Lower	149, 0.028, West
B82	LOT 1,TAXBLOCK 961	261 4 AVENUE	NY E DESIGNATION	Higher	164, 0.031, East
A83	FIVE GALLONS OF OIL	222 1 STREET	NY Spills	Lower	164, 0.031, SW
A84	SIX GAL HYDRAULIC FL	222 FIRST STREET & 3	NY Spills	Lower	164, 0.031, SW
A85	VEHICLE 60677	THIRD AVE YARD	NY Spills	Lower	164, 0.031, SW
A86	222 1ST STREET	CON EDSION	NY Spills	Lower	164, 0.031, SW
A87	HYDRAULIC OIL	3 AVE YARD NEW CONST	NY Spills	Lower	164, 0.031, SW
B88	RIDGE AUTO TRANSMISS	270 4TH AVE	EDR Hist Auto	Higher	166, 0.031, NE
B89	AUTO BODY CONCEPTS D	270 4TH AVE	RCRA NonGen / NLR	Higher	166, 0.031, NE
B90	LOT 2,TAXBLOCK 961	259 4 AVENUE	NY E DESIGNATION	Higher	180, 0.034, ENE
C91	ROMAN CATHOLIC CHURC	522 CARROLL ST	NY UST	Higher	192, 0.036, NNE
B92	CON EDISON	9 GARFIELD ST	NY MANIFEST	Higher	194, 0.037, East
B93	CON EDISON SERVICE B	9 GARFIELD ST	RCRA NonGen / NLR, FINDS	Higher	194, 0.037, East
C94	PS 418 K SCHOOL	512 CARROLL ST	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Lower	199, 0.038, North
C95	P.S. 372 (OUR LADY O	512 CARROLL STREET	NY Spills, NY LEAD	Lower	199, 0.038, North
C96	P.S. 372 (OUR LADY O	512 CARROLL STREET	NY AST	Lower	199, 0.038, North
C97	P.S. 372 (OUR LADY O	512 CARROLL STREET	NY UST	Lower	199, 0.038, North
B98	CON EDISON	CARROLL ST & 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	205, 0.039, NE
B99	CON EDISON	255 4TH AVE	NJ MANIFEST	Higher	208, 0.039, ENE
B100	CON EDISON	255 4TH AVE	RCRA NonGen / NLR	Higher	208, 0.039, ENE
B101	CON ED	255 4TH AVE	NY MANIFEST	Higher	208, 0.039, ENE
B102	LOT 69,TAXBLOCK 961	13 GARFIELD PLACE	NY E DESIGNATION	Higher	211, 0.040, East
C103	CON EDISON	DENTON ST & CARROLL	RCRA NonGen / NLR, FINDS, ECHO	Higher	220, 0.042, NNE
C104	CON EDISON	DENTON ST & CARROLL	NY MANIFEST	Higher	220, 0.042, NNE
C105	CON EDISON	DENTON ST & CARROLL	NJ MANIFEST	Higher	220, 0.042, NNE
B106	CON EDISON SERVICE B	12 GARFIELD PL	RCRA NonGen / NLR	Higher	224, 0.042, ESE
B107	CON EDISON - SERVICE	255 1ST ST	NY MANIFEST	Higher	242, 0.046, ESE
B108	LOT 67,TAXBLOCK 961	15 GARFIELD PLACE	NY E DESIGNATION, NY MANIFEST	Higher	253, 0.048, East
B109	4TH AVE	CARROLL ST & 4TH AVE	NY Spills	Higher	266, 0.050, ENE
B110	LOT 7,TAXBLOCK 961	566 CARROLL STREET	NY E DESIGNATION	Higher	275, 0.052, East
B111	566 CARROLL STREET	566 CARROLL STREET	NY VCP	Higher	275, 0.052, East
B112	LOT 21,TAXBLOCK 352	CARROLL STREET	NY E DESIGNATION	Higher	278, 0.053, ENE
D113	LOT 1,TAXBLOCK 969	283 4 AVENUE	NY E DESIGNATION	Higher	284, 0.054, SSE
E114	3RD AVE YARD	3RD AVE YARD	NY Spills	Lower	287, 0.054, WSW
B115	LOT 1,TAXBLOCK 958	253 4 AVENUE	NY E DESIGNATION	Higher	298, 0.056, ENE
D116	CON EDISON SERVICE B	100 4TH ST & 2ND AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	299, 0.057, South

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C117	CON EDISON	511 CARROLL ST	NY MANIFEST	Lower	306, 0.058, North
C118	CON EDISON	511 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	306, 0.058, North
C119	CON EDISON	511 CARROLL ST	NJ MANIFEST	Lower	306, 0.058, North
B120	NYCDOT BRIDGE BIN 22	PRESIDENT ST BRG OVE	RCRA NonGen / NLR	Higher	312, 0.059, NE
B121	LOT 2,TAXBLOCK 958	249 4 AVENUE	NY E DESIGNATION	Higher	314, 0.059, ENE
F122	3RD AV YARD INFO STO	M 222 1ST ST	NY Spills	Lower	316, 0.060, WNW
F123	COMMERCIAL BUILDING	14 WHITWELL PLACE	NY Spills	Lower	322, 0.061, NNW
G124	CON EDISON	22 GARFIELD ST	NY MANIFEST	Higher	347, 0.066, ESE
G125	CON EDISON	22 GARFIELD ST	NJ MANIFEST	Higher	347, 0.066, ESE
G126	CON EDISON	22 GARFIELD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	347, 0.066, ESE
H127	LOT 4,TAXBLOCK 958	245 4 AVENUE	NY E DESIGNATION	Higher	349, 0.066, ENE
H128	L&B AUTO REPAIR CORP	245 4TH AVENUE	NY AST	Higher	349, 0.066, ENE
H129	241 - 245 4TH AVENUE	245 4TH AVENUE	NY VCP	Higher	349, 0.066, ENE
D130	CON EDISON CO. OF NY	3RD AVE (BET. 3RD &	NY SWF/LF	Higher	360, 0.068, South
D131	LOT 7504,TAXBLOCK 97	302 2 STREET	NY E DESIGNATION	Higher	380, 0.072, South
H132	243 DEVELOPMENT LLC	243-245 4TH AVE	NY MANIFEST	Higher	384, 0.073, ENE
H133	LOT 5,TAXBLOCK 958	243 4 AVENUE	NY E DESIGNATION	Higher	384, 0.073, ENE
H134	245 4TH AVENUE LLC	243-245 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	384, 0.073, ENE
H135	2 FAMILY HOUSE	557 CARROLL ST	NY AST	Higher	386, 0.073, ENE
I136	505 CARROLL ST.	505 CARROLL STREET	NY AST	Lower	389, 0.074, NNW
I137	PROCIDA REALTY	505 CARROLL STREET	NY Spills	Lower	389, 0.074, NNW
E138	THIRD AV YARD	222 FIRST STREET	NY Spills	Lower	402, 0.076, West
E139	FLUSHPIT 3RD AVE YAR	222 FIRST STREET	NY Spills	Lower	402, 0.076, West
F140	CON EDISON	319 3 AVE	NY MANIFEST	Lower	412, 0.078, WNW
H141	CON EDISON	237 4TH AVE	PA MANIFEST	Higher	413, 0.078, NE
H142	LOT 7,TAXBLOCK 958	586 PRESIDENT STREET	NY E DESIGNATION	Higher	433, 0.082, ENE
H143	CON EDISON	586 PRESIDENT ST	NY MANIFEST	Higher	433, 0.082, ENE
D144	LOT 7502,TAXBLOCK 97	306 2 STREET	NY E DESIGNATION	Higher	438, 0.083, South
G145	CON EDISON	584 CARROLL ST	NY MANIFEST	Higher	440, 0.083, East
G146	CON EDISON	584 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	440, 0.083, East
J147	315 4TH AVE	315 4TH AVENUE	NY Spills	Higher	445, 0.084, South
G148	CON EDISON	586 CARROL ST	NJ MANIFEST	Higher	459, 0.087, East
G149	CON EDISON	586 CARROL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	459, 0.087, East
G150	CON EDISON	586 CARROL ST	NY MANIFEST	Higher	459, 0.087, East
I151	540 PRESIDENT STREET	540 PRESIDENT STREET	NY LTANKS	Lower	462, 0.087, North
F152	222 1ST ST	3RD AVE YARD	NY Spills	Lower	475, 0.090, WNW
F153	THIRD AVENUE YARD	THIRD AVENUE & FIRST	NY Spills	Lower	475, 0.090, WNW
F154	3RD AVE YARD	3RD AVE YARD	NY Spills	Lower	475, 0.090, WNW
H155	VAULT# TM0253	PRESIDENT ST & 4TH A	NY Spills	Higher	490, 0.093, ENE

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G156	CON EDISON	590 CARROLL ST	NY MANIFEST	Higher	497, 0.094, East
G157	CON EDISON	590 CARROLL ST	NJ MANIFEST	Higher	497, 0.094, East
G158	CON EDISON	590 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	497, 0.094, East
F159	FEEDER LEAK	3RD AVE & 1ST STREET	NY Spills	Lower	501, 0.095, WNW
F160	3RD AVE SERVICE CENT	3RD AVE & 1ST ST	NY Spills	Lower	501, 0.095, WNW
F161	CONSOLIDATED EDISON	3RD AVE & 1ST STREET	NY MANIFEST	Lower	501, 0.095, WNW
F162	MANHOLE # 65435	3RD AVE/1ST STREET	NY Spills	Lower	502, 0.095, WNW
J163	LOT 73,TAXBLOCK 974	303 3 STREET	NY E DESIGNATION	Higher	521, 0.099, South
D164	CON EDISON - SERVICE	328 2ND ST	NY MANIFEST	Higher	537, 0.102, SSE
D165	CON EDISON - SERVICE	328 2ND ST	RCRA-LQG	Higher	537, 0.102, SSE
K166	CON EDISON	577 CARROLL ST	NY MANIFEST	Higher	548, 0.104, East
K167	CON EDISON	577 CARROLL ST	NJ MANIFEST	Higher	548, 0.104, East
K168	CON EDISON	577 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	548, 0.104, East
I169	L.L.L. AUTO REPAIR I	528 PRESIDENT STREET	NY AST	Lower	549, 0.104, NNW
F170	CON EDISON	318 3RD AVE FRONT OF	NY MANIFEST	Lower	550, 0.104, WNW
F171	FINEST AUTO & RECOVE	310 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	550, 0.104, NW
F172	CLARIN TRUCK LEASING	312 3RD AVE	NY UST	Lower	566, 0.107, WNW
L173	CON EDISON - SERVICE	302 3RD AVE	NY MANIFEST	Lower	570, 0.108, NW
L174	CON EDISON - SERVICE	302 3RD AVE	RCRA-LQG	Lower	570, 0.108, NW
J175	MANHOLE 5436	4TH AVE/3RD ST	NY Spills	Higher	570, 0.108, South
M176	ABF FREIGHTS	545 PRESIDENT ST	NY Spills	Lower	573, 0.109, North
N177	2ND & 3RD AVE	2ND & 3RD AVE	NY Spills	Lower	573, 0.109, West
N178	MAN HOLE 5354	3RD AND AVE AND 2ND	NY Spills	Lower	581, 0.110, West
O179	B M T STOP DRY CLEAN	230 4TH AVE STE B	EDR Hist Cleaner	Higher	587, 0.111, NE
J180	CON EDISON SERVICE B	260 3RD ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Higher	614, 0.116, South
P181	CONSTRUCTION SITE	340 4TH AVE	NY Spills	Higher	630, 0.119, SSW
P182	PARKSIDE SERVICE CEN	340 4TH AVE	NY Spills	Higher	630, 0.119, SSW
P183	PARKSIDE SERVICE CEN	340 4TH AVENUE	NY UST	Higher	630, 0.119, SSW
P184	PARKSIDE SERVICE STA	340 FOURTH AVE	EDR Hist Auto	Higher	630, 0.119, SSW
L185	CON EDISON	284 THIRD AVE	NY MANIFEST	Lower	641, 0.121, NNW
L186	CON EDISON	284 3RD AVE	NY MANIFEST	Lower	641, 0.121, NNW
O187	CON EDISON	226 4TH AVE	PA MANIFEST	Higher	645, 0.122, NE
M188	CON EDISON SERVICE B	604 UNION ST	RCRA NonGen / NLR, NY MANIFEST	Higher	667, 0.126, NNE
Q189	276 3RD AVENUE	276 THIRD AVENUE	NY AST	Lower	682, 0.129, NNW
L190	JO-LEE TRUCKING	463 CARROLL ST	RCRA NonGen / NLR	Lower	713, 0.135, NW
O191	NYCT - UNION STATION	UNION ST & 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	718, 0.136, NE
M192	KLOR-DE CLEANERS	263 3RD AVENUE	NY DRYCLEANERS	Lower	720, 0.136, North
O193	CON EDISON MANHOLE:	4TH & UNION AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	723, 0.137, NE
M194	CON EDISON SERVICE B	578 UNION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	724, 0.137, North

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
N195	CON EDISON VAULT SUB	213 3RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	731, 0.138, West
R196	CON EDISON	3RD ST & 3RD AVE	NJ MANIFEST	Lower	739, 0.140, WSW
R197	VERIZON LOG 31756 MA	3RD ST & 3RD AVE	RCRA NonGen / NLR	Lower	739, 0.140, WSW
R198	CON EDISON	3RD ST & 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	739, 0.140, WSW
R199	CON EDISON	3RD ST & 3RD AVE	NY MANIFEST	Lower	739, 0.140, WSW
R200	CONSOLIDATED EDISON	3 AVE & 3 STREET & 6	NY MANIFEST	Lower	741, 0.140, WSW
P201	PEP BOYS #0247	354 4TH AVENUE	NY AST	Higher	748, 0.142, SSW
P202	PEP BOYS #0247	354 4TH AVENUE	NY UST	Higher	748, 0.142, SSW
P203	PEP BOYS 247	354 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	748, 0.142, SSW
P204	PEP BOYS #0247	354 4TH AVE	NY CBS, NY Spills	Higher	748, 0.142, SSW
P205	PEP BOYS #0247	354 4TH AVE	NY AST	Higher	748, 0.142, SSW
L206	LINDA TOOL & DIE COR	459 CARROLL ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	752, 0.142, NW
S207	CON EDISON	251 3RD AVE	NY MANIFEST	Lower	794, 0.150, North
S208	CON EDISON EXCAVATIO	251 3RD AVE	RCRA NonGen / NLR	Lower	794, 0.150, North
T209	HOLYLAND AUTO REPAIR	637 UNION STREET	NY AST	Lower	795, 0.151, NNE
Q210	RIDGE COMPLETE AUTO	264 THIRD AVENUE	NY AST	Lower	798, 0.151, NNW
P211	MAACO AUTO PAINTING	358 FOURTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	807, 0.153, SSW
P212	CON EDISON - MANHOLE	358 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	807, 0.153, SSW
M213	CON ED	617 UNION ST & 3RD A	NY MANIFEST	Lower	833, 0.158, North
M214	CON EDISON - UNION S	617 UNION STREET	PA MANIFEST	Lower	833, 0.158, North
R215	CON EDISON SERVICE B	210 3RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	839, 0.159, WSW
U216	CON EDISON SERVICE B	85-87 1ST AVE & 5TH	RCRA NonGen / NLR, FINDS	Higher	847, 0.160, SE
V217	CON EDISON - TRANSFO	5TH AVE & GARFIELD P	NY MANIFEST	Higher	849, 0.161, ESE
O218	204 4TH AVE LLC - BC	204 4TH AVE	RCRA-LQG	Higher	850, 0.161, NNE
O219	SPEEDWAY # 7835	204-222 FOURTH AVENU	NY UST	Higher	850, 0.161, NNE
O220	HESS#32530	204-222 FOURTH AVE	RCRA-VSQG, US AIRS, FINDS, ECHO, NY MANIFEST	Higher	850, 0.161, NNE
O221	MERRITT GAS STATION	204-222 4TH AVENUE	NY LTANKS, NY Spills	Higher	850, 0.161, NNE
O222	204 4TH AVENUE	204 4TH AVENUE	NY BROWNFIELDS	Higher	850, 0.161, NNE
W223	CON EDISON	451 CARROLL ST FRONT	NY MANIFEST	Lower	853, 0.162, NW
W224	CON EDISON	451 CARROLL ST FRONT	RCRA NonGen / NLR	Lower	853, 0.162, NW
W225	CON EDISON	451 CARROLL ST FRONT	NJ MANIFEST	Lower	853, 0.162, NW
S226	CON EDISON	617 UNION ST & 3RD A	RCRA NonGen / NLR, FINDS, ECHO	Lower	872, 0.165, North
Q227	CON EDISON	501 PRESIDENT ST	NY MANIFEST	Lower	876, 0.166, NNW
Q228	CON EDISON	501 PRESIDENT ST	RCRA NonGen / NLR	Lower	876, 0.166, NNW
Q229	CON EDISON	501 PRESIDENT ST	NJ MANIFEST	Lower	876, 0.166, NNW
X230	4TH & SACKETT STREET	4TH & SACKETT STREET	NY LTANKS	Higher	880, 0.167, NE
S231	SJ FUEL CO. INC.	601 UNION STREET	NY TANKS	Lower	886, 0.168, North
S232	A 2 Z ENVIRONMENTAL	601 UNION ST	RCRA NonGen / NLR	Lower	886, 0.168, North
W233	CON EDISON	450 CARROL ST	NY MANIFEST	Lower	888, 0.168, NW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Y234	RALPH'S CLEANERS	230 5TH AVE	NY DRYCLEANERS	Higher	900, 0.170, East
Y235	RALPHS CLEANERS	230 FIFTH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	900, 0.170, East
R236	216 3RD STREET	216 3RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	910, 0.172, West
W237	CON ED	443 CARROLL ST	NY MANIFEST	Lower	910, 0.172, NW
W238	CON EDISON	443 CARROLL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	910, 0.172, NW
R239	190-220 THIRD STREET	214 3RD ST	NJ MANIFEST	Lower	916, 0.173, West
R240	190-220 THIRD STREET	214 3RD ST	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	916, 0.173, West
T241	CONSOLIDATED EDISON	V5491-633 SACKETT ST	NY MANIFEST	Higher	923, 0.175, NNE
U242	JORDAN MALACHIE CLEA	295 5TH AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	925, 0.175, SE
U243	MALACHI DRY CLNR	279 5TH AVENUE	NY DRYCLEANERS	Higher	932, 0.177, SE
U244	JET FRENCH CLEANERS	279 5TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	932, 0.177, SE
Z245	BRIDGE FORD	343 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	943, 0.179, SSW
Z246	343 4TH AVENUE	343 4TH AVENUE	NY UST	Higher	943, 0.179, SSW
R247	ALL BORO'S	200 3RD ST	NY LTANKS	Lower	950, 0.180, West
AA248	CON EDISON	354 3RD ST	NY MANIFEST	Higher	950, 0.180, SSE
AA249	CON EDISON	354 3RD ST	RCRA NonGen / NLR	Higher	950, 0.180, SSE
AA250	CON EDISON	354 3RD ST	NJ MANIFEST	Higher	950, 0.180, SSE
W251	CON EDISON - SERVICE	484 PRESIDENT ST	RCRA-LQG	Lower	959, 0.182, NW
W252	CON EDISON - SERVICE	484 PRESIDENT ST	NY MANIFEST	Lower	959, 0.182, NW
Z253	BROOKLYN IGNITION &	370 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	966, 0.183, SSW
AB254	CON EDISON	688 SACKET ST	NY MANIFEST	Higher	975, 0.185, NE
AB255	CON EDISON	688 SACKETT ST	NY MANIFEST	Higher	975, 0.185, NE
AB256	CON EDISON	688 SACKETT ST	NY MANIFEST	Higher	975, 0.185, NE
AC257	CON EDISON SERVICE B	198 3RD ST	RCRA NonGen / NLR, NY MANIFEST	Lower	976, 0.185, West
Z258	SUSAN MAINTENANCE CO	374 4TH AVENUE	NY UST	Higher	989, 0.187, SSW
Z259	SUSAN MAINTENANCE	374 4TH AVE	RCRA-SQG, FINDS, ECHO, NJ MANIFEST, NY MANIFEST	Higher	989, 0.187, SSW
Z260	374 4TH AVENUE	374 4TH AVENUE	NY VCP	Higher	989, 0.187, SSW
Z261	SUSAN MAINTENANCE CO	374 4TH AVENUE	NY AST	Higher	989, 0.187, SSW
U262	CON EDISON	318 1 ST	NY MANIFEST	Higher	1009, 0.191, SE
S263	MATTHEWS INTERNATION	585 UNION ST	RCRA NonGen / NLR	Lower	1016, 0.192, NNW
X264	SEMPLE RIEGER CO	635 SACKETT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1022, 0.194, NNE
U265	32 UNIT 4 STORY WALK	325 1ST STREET	NY AST	Higher	1025, 0.194, ESE
U266	CON EDISON	365 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1030, 0.195, SE
U267	CON EDISON	365 2ND ST	NJ MANIFEST	Higher	1030, 0.195, SE
U268	CON ED	365 2ND ST	NY MANIFEST	Higher	1030, 0.195, SE
V269	640 CARROLL LLC	640 CARROLL STREET	NY AST	Higher	1042, 0.197, ESE
Z270	CON EDISON SERVICE B	209 5TH ST OPPOSITE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1053, 0.199, SSW
T271	617 SACKETT STREET R	617 SACKETT STREET	NY UST	Lower	1057, 0.200, NNE
AD272	220 3RD STREET	220 3RD STREET	NY UST	Lower	1059, 0.201, WSW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AD273	PIPPIN ENTERPRISES L	220 3RD ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1059, 0.201, WSW
AE274	585 UNION STREET	577-599 UNION STREET	NY BROWNFIELDS	Lower	1074, 0.203, NNW
Y275	670 PRESIDENT ST HOU	670 PRESIDENT STREET	NY AST	Higher	1079, 0.204, East
AF276	CON EDISON - EXCAVAT	232 3RD AVE	RCRA-LQG	Lower	1082, 0.205, North
AF277	CON EDISON	232 3RD AVE	NY MANIFEST	Lower	1082, 0.205, North
AC278	CON EDISON	227 3RD ST	NY MANIFEST	Lower	1082, 0.205, West
U279	CON EDISON	335 1ST ST	NJ MANIFEST	Higher	1093, 0.207, ESE
U280	CON EDISON	335 1ST ST	NY MANIFEST	Higher	1093, 0.207, ESE
U281	CON EDISON	335 1ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1093, 0.207, ESE
AA282	BHW NV ASSOCIATES	321 FIFTH AVENUE	NY AST	Higher	1096, 0.208, SSE
AC283	CON EDISON MANHOLE:	190 3RD ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Lower	1097, 0.208, West
W284	CRUSADER CANDLE CO I	325 NEVINS ST	NJ MANIFEST	Lower	1098, 0.208, NW
W285	325 NEVINS STREET	325 NEVINS STREET	NY LTANKS	Lower	1098, 0.208, NW
W286	CRUSADER CANDLE CO I	325 NEVINS ST	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Lower	1098, 0.208, NW
AF287	CON EDISON	SACKETT ST & 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1104, 0.209, North
AF288	CON EDISON	SACKETT ST & 3RD AVE	NJ MANIFEST	Lower	1104, 0.209, North
AF289	NYCDEP	SACKETT ST & 3RD AVE	NY MANIFEST	Lower	1104, 0.209, North
AG290	473 PRESIDENT STREET	473 PRESIDENT STREET	NY BROWNFIELDS	Lower	1107, 0.210, NNW
AG291	473 PRESIDENT STREET	473 PRESIDENT STREET	NY LTANKS, NY BROWNFIELDS, NY MANIFEST	Lower	1107, 0.210, NNW
AG292	473 PRESIDENT STREET	473 PRESIDENT ST	RCRA-LQG	Lower	1107, 0.210, NNW
AF293	BELL ATLANTIC-NY	SACKETT & 3 AVE MANH	NY MANIFEST	Lower	1108, 0.210, North
AH294	CON ED	CARROLL ST & NEVINS	NY MANIFEST	Lower	1110, 0.210, NW
AH295	CON EDISON	CARROLL ST & NEVINS	NY MANIFEST	Lower	1110, 0.210, NW
AH296	CON EDISON - TRANSFO	CARROLL ST & NEVINS	NJ MANIFEST	Lower	1110, 0.210, NW
AH297	CON EDISON	CARROLL ST & NEVINS	RCRA NonGen / NLR, FINDS, ECHO	Lower	1110, 0.210, NW
AH298	CON EDISON - TRANSFO	CARROLL ST & NEVINS	RCRA-LQG	Lower	1110, 0.210, NW
AH299	CON EDISON	CARROLL ST AND NEVIN	NY MANIFEST	Lower	1110, 0.210, NW
AH300	CON EDISON	CARROLL ST & NEVINS	NJ MANIFEST	Lower	1110, 0.210, NW
AH301	CON EDISON	CARROLL ST & NEVINS	NY MANIFEST	Lower	1110, 0.210, NW
AE302	473 PRESIDENT LLC -	514 UNION ST	RCRA-LQG	Lower	1113, 0.211, NNW
AE303	514 UNION STREET	514 UNION STREET	NY BROWNFIELDS	Lower	1113, 0.211, NNW
Y304	CON EDISON SERVICE B	674 PRESIDENT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1121, 0.212, East
AI305	CON EDISON	386 2ND ST	NY MANIFEST	Higher	1122, 0.213, SE
AD306	PARK SLOPE U-HAUL RE	389 3RD AVENUE	NY AST	Lower	1129, 0.214, WSW
AC307	VERIZON NEW YORK INC	175 THIRD ST	NY MANIFEST, NY SPDES	Lower	1130, 0.214, West
AC308	VERIZON NEW YORK INC	175 THIRD STREET	NY AST	Lower	1130, 0.214, West
AC309	NEW YORK TELEPHONE C	175 THIRD ST	RCRA NonGen / NLR	Lower	1130, 0.214, West
AC310	VERIZON NEW YORK INC	175 THIRD STREET	NY UST	Lower	1130, 0.214, West
AC311	175-225 3RD STREET	175-225 3RD STREET	NY BROWNFIELDS	Lower	1130, 0.214, West

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC312	175 3RD STREET	175 3RD STREET	NY LTANKS, NY Spills	Lower	1130, 0.214, West
AJ313	CON EDISON	676 PRESIDENT ST	NY MANIFEST	Higher	1138, 0.216, East
AJ314	CON EDISON	676 PRESIDENT ST	NJ MANIFEST	Higher	1138, 0.216, East
AJ315	CON EDISON	676 PRESIDENT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1138, 0.216, East
AK316	P.S. # 51- 350 5TH A	P.S. #51 - 350 5TH A	NY LTANKS	Higher	1139, 0.216, South
AL317	CON EDISON SERVICE B	726 SACKETT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1144, 0.217, ENE
318	207 CORP	207 5TH AVENUE	NY AST	Higher	1146, 0.217, East
AG319	PRESIDENT STREET POR	469 PRESIDENT STREET	NY BROWNFIELDS	Lower	1153, 0.218, NNW
AJ320	CON EDISON	675 PRESIDENT ST	NY MANIFEST	Higher	1177, 0.223, East
AJ321	CON EDISON	675 PRESIDENT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1177, 0.223, East
AJ322	CON EDISON	675 PRESIDENT ST	NJ MANIFEST	Higher	1177, 0.223, East
AM323	A SHAMOSH	620-628 DEGRAW STREE	NY UST, NY AST	Higher	1178, 0.223, NNE
AH324	GOWANUS VILLAGE I, L	420 CARROLL STREET	NY BROWNFIELDS, NY Spills	Lower	1182, 0.224, NW
AC325	RED HOOK CRUSHERS; I	186 3RD STREET	NY SWF/LF	Lower	1184, 0.224, West
AN326	CON EDISON	664 DEGRAW ST	NJ MANIFEST	Higher	1195, 0.226, NE
AN327	CON EDISON	664 DEGRAW ST	RCRA NonGen / NLR	Higher	1195, 0.226, NE
AN328	CON EDISON	664 DEGRAW ST	NY MANIFEST	Higher	1195, 0.226, NE
AG329	VERIZON	318 NEVINS STREET	NY LTANKS, NY Spills	Lower	1199, 0.227, NW
AG330	VERIZON NEW YORK INC	318 NEVINS STREET	NY AST	Lower	1199, 0.227, NW
AG331	VERIZON NEW YORK INC	318 NEVINS STREET	NY UST	Lower	1199, 0.227, NW
AG332	NEW YORK TELEPHONE C	318 NEVINS ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	1199, 0.227, NW
AK333	NYC DEPT OF EDUCATIO	350 5TH AVE	RCRA-SQG, FINDS, ECHO	Higher	1200, 0.227, SSE
AK334	K051	350 5TH AVENUE	NY UST	Higher	1200, 0.227, SSE
AO335	CON EDISON	298 5TH ST	NY MANIFEST	Higher	1200, 0.227, South
AO336	CON EDISON SERVICE B	298 5TH ST	RCRA NonGen / NLR	Higher	1200, 0.227, South
Z337	CON ED - V 3685	522 W 44 ST	RCRA NonGen / NLR	Higher	1206, 0.228, SSW
AA338	CON EDISON SERVICE B	315 4TH ST S	RCRA NonGen / NLR, NY MANIFEST	Higher	1207, 0.229, SSE
AG339	318 NEVINS STREET	300-344 NEVINS STREE	NY BROWNFIELDS	Lower	1218, 0.231, NW
AP340	KAM SERVICE CENTER I	363 4TH AVE	NY LTANKS, NY Spills, RCRA NonGen / NLR, FINDS,...	Higher	1225, 0.232, SSW
AP341	BP SS # 13397	363 FOURTH AVENUE	NY UST	Higher	1225, 0.232, SSW
AI342	CON EDISON	391 2ND ST	NY MANIFEST	Higher	1256, 0.238, SE
AI343	CON EDISON	391 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1256, 0.238, SE
AI344	CON EDISON	391 2ND ST	NJ MANIFEST	Higher	1256, 0.238, SE
AE345	PARK SLOPE PAINT STR	553 UNION ST	RCRA-SQG, NY MANIFEST, NJ MANIFEST	Lower	1257, 0.238, NNW
AK346	CON EDISON	314 5TH ST	NY MANIFEST	Higher	1262, 0.239, South
AK347	CON EDISON - SERVICE	314 5 ST	RCRA-LQG	Higher	1262, 0.239, South
AP348	AMOCO SERVICE STATIO	375-381 4TH AVE & 6T	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1263, 0.239, SSW
AE349	563 SACKETT STREET	563 SACKETT STREET	NY BROWNFIELDS	Lower	1266, 0.240, North
AH350	CON EDISON	408 CARROL ST	NY MANIFEST	Lower	1275, 0.241, NW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AH351	CON EDISON - MANHOLE	408 CARROL ST	RCRA-LQG	Lower	1275, 0.241, NW
AL352	CON EDISON SERVICE B	195 5TH AVE FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1282, 0.243, ENE
AP353	U-HAUL CO OF METRO N	259 6TH STREET	NY UST	Higher	1284, 0.243, SSW
AP354	U-HAUL	259 6TH ST	NY LTANKS	Higher	1284, 0.243, SSW
AP355	U-HAUL CORP	259 6TH ST - PARK SL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1284, 0.243, SSW
AN356	RINALDI RECYCLING CO	182 4TH AVE.	NY SWF/LF	Higher	1285, 0.243, NNE
357	NYSDOT 3RD ST BRIDGE	3RD ST BRG OVER GOWA	RCRA NonGen / NLR	Lower	1287, 0.244, WNW
AO358	CON EDISON MANHOLE:	267 6TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1292, 0.245, SSW
AE359	A & A BRAKE CO INC	560 SACKETT STREET	NY AST	Lower	1295, 0.245, NNW
AE360	A & A BRAKE CO INC	560 SACKETT STREET	NY UST	Lower	1295, 0.245, NNW
361	SOUTH BROOKLYN REALT	301 NEVINS STREET	NY UST	Lower	1299, 0.246, NNW
362	MESSINA	392 3RD ST	NY AST	Higher	1305, 0.247, SSE
AM363	AJR (COMMERCIAL BLDG	599 DEGRAW ST	NY LTANKS	Lower	1313, 0.249, NNE
AQ364	553 SACKETT STREET	553 SACKETT STREET	NY VCP	Lower	1320, 0.250, North
AI365	401 3RD STREET	401 3RD STREET	NY LTANKS	Higher	1365, 0.259, SE
AP366	FERRANTINO & CO	278 6TH ST	NY LTANKS	Higher	1397, 0.265, SSW
367	RINALDI RECYCLING CO	326 DOUGLASS STREET	NY SWRCY	Higher	1441, 0.273, NNE
368	CARROLL ST. TRANSFER	400 CARROLL ST	NY SWF/LF	Lower	1460, 0.277, NW
AR369	GOWANUS VILLAGE I	153 2ND ST A/K/A 322	NY INST CONTROL	Lower	1465, 0.277, WNW
AS370	280 DOUGLAS ST/PENSK	280 DOUGLAS ST/PENSK	NY LTANKS	Lower	1514, 0.287, North
AS371	280 DOUGLAS ST	280 DOUGLAS STREET	NY LTANKS, NY Spills	Lower	1514, 0.287, North
372	19 BERKELEY PL	19 BERKELEY PL	NY LTANKS, NY Spills	Higher	1528, 0.289, ENE
AQ373	FULTON MUNICIPAL WOR	NEVINS, DEGRAW AND S	EDR MGP	Lower	1530, 0.290, NNW
AT374	163 6TH STREET LLC	163 6TH ST	NY SWRCY, NY MANIFEST, NY SPDES	Lower	1597, 0.302, WSW
AT375	US RECYCLING INC	141 6TH STREET	NY SWRCY, NY Spills	Lower	1602, 0.303, WSW
AR376	141 3RD STREET	141 3RD STREET	NY BROWNFIELDS	Lower	1611, 0.305, WNW
AU377	GOWANUS CANAL CONSER	2 SECOND AVE.	NY SWF/LF	Lower	1651, 0.313, West
AU378	BK6 SALT LOT COMMUNI	2 SECOND AVENUE	NY SWF/LF	Lower	1651, 0.313, West
379	SPILL NUMBER 0209206	11 LINCOLN PLACE	NY LTANKS	Higher	1661, 0.315, ENE
AV380	FULTON WORKS	DEGRAW STREET AND NE	NY VCP	Lower	1661, 0.315, NNW
AV381	FULTON WORKS	DEGRAW STREET AND NE	EDR MGP	Lower	1672, 0.317, North
382	D GAVER & SONS INC	267 DOUGLASS ST	NY LTANKS, NY UST	Lower	1692, 0.320, North
AW383	450 UNION STREET	450 UNION STREET	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1710, 0.324, NW
AX384	365 BOND STREET	365 BOND STREET	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1712, 0.324, WNW
AY385	335 BOND STREET	335 BOND STREET	NY BROWNFIELDS	Lower	1721, 0.326, NW
AW386	BAYSIDE FUEL OIL DEP	510 SACKETT ST.	NY MOSF UST	Lower	1738, 0.329, NNW
AW387	BAYSIDE FUEL OIL DEP	510 SACKETT ST	NY MOSF, NY Spills	Lower	1738, 0.329, NNW
AY388	DENTS OUT AUTO BODY	327 BOND ST	SEMS-ARCHIVE, RCRA NonGen / NLR	Lower	1743, 0.330, NW
389	THIRD STREET GOWANUS	125 3RD STREET	NY BROWNFIELDS	Lower	1769, 0.335, WNW

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
390	225 6TH AVE.	225 6TH AVE	NY LTANKS	Higher	1777, 0.337, East
AT391	CONTAINER SERVICE CO	107 6TH STREET	NY SWF/LF, NY Spills, NY SPDES	Lower	1779, 0.337, WSW
AT392	106 6TH ST	106 6TH ST	NY LTANKS	Lower	1806, 0.342, WSW
AV393	CROSS BAY CONTRACTIN	242 NEVINS ST.	NY SWF/LF	Lower	1811, 0.343, NNW
AV394	ROYAL RECYCLING CORP	242 NEVINS STREET	NY SWF/LF	Lower	1811, 0.343, NNW
AV395	242 NEVINS STREET	242 NEVINS STREET	NY BROWNFIELDS, NY Spills	Lower	1811, 0.343, NNW
AX396	TOLL BROOKLYN, LP	64-98 1ST ST; 82-107	NY BROWNFIELDS	Lower	1820, 0.345, WNW
AZ397	OCEAN SUPPLY CO	437 3RD AVE	NY LTANKS	Lower	1828, 0.346, SW
AY398	388 CARROLL STREET A	388 CARROLL STREET A	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1828, 0.346, NW
BA399	BKLYN UNION GAS /CIT	6TH ST & 2ND AVE	SEMS-ARCHIVE	Lower	1835, 0.348, WSW
BA400	BUG, CITIZENS GATE S	6TH STREET AND 2ND A	NY HSWDS	Lower	1881, 0.356, WSW
AZ401	168 8TH STREET	168 8TH STREET	NY BROWNFIELDS	Lower	1921, 0.364, SW
402	126 4TH AVENUE - MIS	126 4TH AVENUE	NY LTANKS	Higher	1927, 0.365, NNE
403	236 8TH ST	236 8TH ST	NY LTANKS	Higher	1945, 0.368, SSW
404	INTERCONTINENTAL REC	??	NY SWF/LF	Lower	1957, 0.371, WSW
405	ECONOMY CLEANERS	123 5TH AVE	RCRA-VSQG, NY LTANKS, US AIRS, NY MANIFEST	Higher	1962, 0.372, ENE
BB406	233 NEVINS STREET PH	233 NEVINS STREET	NY VCP	Lower	1978, 0.375, North
407	SPILL NUMBER 9804333	705 CARROLL STREET	NY LTANKS, NY Spills	Higher	2004, 0.380, ESE
408	UNDERGROUND TANK	151-169 3RD AVE	NY LTANKS	Lower	2031, 0.385, NNE
BC409	PATTERSON CHEMICAL C	102 3RD ST	CORRACTS, RCRA NonGen / NLR, FINDS, ECHO	Lower	2079, 0.394, WNW
BD410	210 DOUGLASS STREET	210 DOUGLASS STREET	NY BROWNFIELDS	Lower	2105, 0.399, NNW
BC411	99 NORTH 4TH STREET	99 4TH STREET	NY VCP	Lower	2106, 0.399, WNW
BD412	FORMER O.Z. ELECTRIC	198 DOUGLASS STREET	NY SHWS, NY Spills	Lower	2136, 0.405, NNW
BB413	233 NEVINS STREET	236 BUTLER STREET	NY VCP	Lower	2143, 0.406, North
414	BALTIC RECYCLING COR	524-26 BALTIC STREET	NY SWF/LF	Lower	2144, 0.406, North
BB415	234 BUTLER STREET	234 BUTLER STREET	NY BROWNFIELDS	Lower	2152, 0.408, North
BE416	424 5TH AVENUE	424 5TH STREET	NY LTANKS	Higher	2163, 0.410, SSE
BD417	GOWANUS CANAL SITE	GOWANUS CANAL	NY SHWS	Lower	2202, 0.417, NNW
418	IESI (110 5TH ST.)(S	110 5TH STREET	NY SWF/LF, NY Spills	Lower	2216, 0.420, West
419	572 WARREN ST. HOUSE	572 WARREN ST	NY LTANKS, NY Spills	Higher	2234, 0.423, NNE
BE420	442 5TH ST	442 5TH ST	NY LTANKS	Higher	2300, 0.436, SSE
BF421	SPILL NUMBER 0212934	233 BUTLER ST	NY LTANKS	Lower	2308, 0.437, North
BG422	74-76 SOUTH SECOND S	74-76 SECOND STREET	NY VCP	Higher	2314, 0.438, WNW
423	124 LINCOLN PLACE	124 LINCOLN PLACE	NY LTANKS	Higher	2328, 0.441, East
BE424	APARTMENT BUILDING	446 5TH ST	NY LTANKS	Higher	2334, 0.442, SSE
425	US POST OFFICE	198 7TH AVENUE	NY LTANKS, NY Spills	Higher	2362, 0.447, SE
BH426	66 FOURTH STREET	66 4TH STREET	NY LTANKS, NY UST	Lower	2382, 0.451, West
427	STELLAR 341 LLC	341 10TH STREET	NY LTANKS, NY UST, NY AST	Higher	2403, 0.455, SSW
428	CVS PHARMACY #2498	341 9TH ST	SEMS-ARCHIVE, RCRA-VSQG	Higher	2407, 0.456, South

MAPPED SITES SUMMARY

Target Property Address:
296 4TH AVENUE
BROOKLYN, NY 11215

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BG429	DEL'S AUTO REPAIR	70 2ND ST/NEW UTRECH	NY LTANKS	Higher	2409, 0.456, WNW
430	GOWANUS HOUSING COMP	238 BOND ST	NY LTANKS	Lower	2419, 0.458, NNW
431	TTF	300 10TH ST	NY LTANKS	Higher	2435, 0.461, SSW
432	79-97 4TH AVENUE	85 4TH AVENUE	NY VCP	Higher	2467, 0.467, NNE
BH433	425 HOYT STREET	419-429 HOYT STREET	NY BROWNFIELDS	Lower	2484, 0.470, WNW
BF434	BASIN HAULAGE INC. I	462-470 BALTIC STREE	NY SWF/LF	Lower	2490, 0.472, North
435	125 THIRD AVENUE	125 3RD AVENUE	NY VCP	Higher	2520, 0.477, NNE
436	WYCKOFF GARDENS	185 NEVINS ST	NY LTANKS	Lower	2522, 0.478, North
437	SINSI RESIDENCE	112 ST MARKS PL	NY LTANKS	Higher	2532, 0.480, NE
438	498 3RD AVENUE	498 3RD AVENUE	NY LTANKS	Lower	2633, 0.499, SW
BI439	K - METROPOLITAN MGP	124-136 SECOND AVE	NY SHWS, NY BROWNFIELDS	Lower	2846, 0.539, WSW
BI440	BU-METROPOLITAN MGP	124-136 SECOND AVE	EDR MGP	Lower	2846, 0.539, WSW
441	FORMER CITIZEN GAS W	5TH STREET AND SMITH	EDR MGP	Lower	2972, 0.563, West
442	CARROLL GARDENS	CORNER OF 5TH STREET	NY DEL SHWS	Higher	3139, 0.595, WNW
443	USPS GOWANUS SITE. F	2ND AVENUE AND 12TH	EDR MGP	Lower	3369, 0.638, WSW
444	FORMER BARRETT MANUF	627 SMITH ST.	NY SHWS, NY BROWNFIELDS	Lower	4584, 0.868, WSW
BJ445	182 SIGOURNEY ST	182 SIGOURNEY ST	NY SHWS	Lower	4808, 0.911, WSW
BJ446	CHEMTURA 633 COURT S	633 COURT STREET	NY SHWS	Lower	4846, 0.918, WSW
BK447	643 COURT ST.	643 COURT ST.	NY SHWS	Lower	5020, 0.951, WSW
BK448	CHEM TURA	688-700 COURT ST	NY CBS UST, NY CBS, NY AST, NY DEL SHWS, RCRA...	Lower	5052, 0.957, WSW
449	SUNSET INDUSTRIAL PA	74 20TH ST	CORRACTS, RCRA-TSDF, RCRA-LQG, NY BROWNFIELDS,...	Lower	5149, 0.975, SW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
MAACO AUTO PAINTING 296 4TH AVE. BROOKLYN, NY 11215	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110001593339 FINDS Registry ID:: 110001593339 ECHO Registry ID: 110001593339	N/A
JEN JAY TRANSMISSION 296 4TH AVE BROOKLYN, NY 11215	EDR Hist Auto	N/A
MAACO AUTO PAINTING 296 4TH AVE & 1ST ST BROOKLYN, NY 11215	RCRA NonGen / NLR EPA ID:: NYD986925642 FINDS Registry ID:: 110008043900 ECHO Registry ID: 110008043900 NY MANIFEST EPA ID: NYD986925642	NYD986925642

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: A review of the NPL list, as provided by EDR, and dated 07/26/2022 has revealed that there is 1

NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***9***
Cerclis ID:: 206222				
EPA Id: NYN000206222				

Lists of Federal sites subject to CERCLA removals and CERCLA orders

SEMS: A review of the SEMS list, as provided by EDR, and dated 07/26/2022 has revealed that there is 1 SEMS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***9***
Site ID: 0206222				
EPA Id: NYN000206222				

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 07/26/2022 has revealed that there are 3 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #2498	***341 9TH ST***	***S 1/4 - 1/2 (0.456 mi.)***	***428***	***109***
Site ID: 0201536				
EPA Id: NYD042777128				

Lower Elevation	Address	Direction / Distance	Map ID	Page
DENTS OUT AUTO BODY	***327 BOND ST***	***NW 1/4 - 1/2 (0.330 mi.)***	***AY388***	***100***
Site ID: 0203501				
EPA Id: NYD986961167				
BKLYN UNION GAS /CIT	6TH ST & 2ND AVE	WSW 1/4 - 1/2 (0.348 mi.)	BA399	103
Site ID: 0201995				
EPA Id: NYD980532212				

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: A review of the CORRACTS list, as provided by EDR, and dated 06/20/2022 has revealed that there are 2 CORRACTS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PATTERSON CHEMICAL C	***102 3RD ST***	***WNW 1/4 - 1/2 (0.394 mi.)***	***BC409***	***105***

EPA ID:: NYD980592471				
SUNSET INDUSTRIAL PA EPA ID:: NYD091590471	***74 20TH ST***	***SW 1/2 - 1 (0.975 mi.)***	***449***	***114***

Lists of Federal RCRA generators

RCRA-LQG: A review of the RCRA-LQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 14 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
275 FOURTH AVENUE DE EPA ID:: NYD986914133	275 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A13	11
CON EDISON - SERVICE EPA ID:: NYP005093950	328 2ND ST	SSE 0 - 1/8 (0.102 mi.)	D165	46
204 4TH AVE LLC - BC EPA ID:: NYR000255687	204 4TH AVE	NNE 1/8 - 1/4 (0.161 mi.)	O218	58
CON EDISON - SERVICE EPA ID:: NYP004363230	314 5 ST	S 1/8 - 1/4 (0.239 mi.)	AK347	90

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - 3RD AVE EPA ID:: NYD000706218	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A33***	***16***
CON EDISON - OTHER - EPA ID:: NYP004851131	222 1 ST	W 0 - 1/8 (0.027 mi.)	A49	20
PS 418 K SCHOOL EPA ID:: NYR000199968	***512 CARROLL ST***	***N 0 - 1/8 (0.038 mi.)***	***C94***	***30***
CON EDISON - SERVICE EPA ID:: NYP005136561	302 3RD AVE	NW 0 - 1/8 (0.108 mi.)	L174	48
CON EDISON - SERVICE EPA ID:: NYP005072996	484 PRESIDENT ST	NW 1/8 - 1/4 (0.182 mi.)	W251	66
CON EDISON - EXCAVAT EPA ID:: NYP005022769	232 3RD AVE	N 1/8 - 1/4 (0.205 mi.)	AF276	73
473 PRESIDENT STREET EPA ID:: NYR000232116	473 PRESIDENT ST	NNW 1/8 - 1/4 (0.210 mi.)	AG292	77
CON EDISON - TRANSFO EPA ID:: NYP004734786	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH298	78
473 PRESIDENT LLC - EPA ID:: NYR000253203	514 UNION ST	NNW 1/8 - 1/4 (0.211 mi.)	AE302	79
CON EDISON - MANHOLE EPA ID:: NYP004342978	408 CARROL ST	NW 1/8 - 1/4 (0.241 mi.)	AH351	91

EXECUTIVE SUMMARY

RCRA-SQG: A review of the RCRA-SQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 5 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - 4TH AVE G EPA ID:: NYR000250654	276 4TH AVE	ENE 0 - 1/8 (0.019 mi.)	A9	10
SUSAN MAINTENANCE EPA ID:: NYR000076091	***374 4TH AVE***	***SSW 1/8 - 1/4 (0.187 mi.)***	***Z259***	***68***
NYC DEPT OF EDUCATIO EPA ID:: NYR000198952	***350 5TH AVE***	***SSE 1/8 - 1/4 (0.227 mi.)***	***AK333***	***86***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CRUSADER CANDLE CO I EPA ID:: NYD987005840	***325 NEVINS ST***	***NW 1/8 - 1/4 (0.208 mi.)***	***W286***	***75***
PARK SLOPE PAINT STR EPA ID:: NYR000170472	***553 UNION ST***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AE345***	***89***

RCRA-VSQG: A review of the RCRA-VSQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 4 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HESS#32530 EPA ID:: NYD982185563	***204-222 FOURTH AVE***	***NNE 1/8 - 1/4 (0.161 mi.)***	***O220***	***58***
JORDAN MALACHIE CLEA EPA ID:: NYR000087486	***295 5TH AVE***	***SE 1/8 - 1/4 (0.175 mi.)***	***U242***	***64***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LINDA TOOL & DIE COR EPA ID:: NYD987025822	***459 CARROLL ST***	***NW 1/8 - 1/4 (0.142 mi.)***	***L206***	***55***
NEW YORK TELEPHONE C EPA ID:: NYD987028016	***318 NEVINS ST***	***NW 1/8 - 1/4 (0.227 mi.)***	***AG332***	***86***

Federal institutional controls / engineering controls registries

US ENG CONTROLS: A review of the US ENG CONTROLS list, as provided by EDR, and dated 05/16/2022 has revealed that there is 1 US ENG CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL EPA ID:: NYN000206222 EPA ID:: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***9***

US INST CONTROLS: A review of the US INST CONTROLS list, as provided by EDR, and dated 05/16/2022 has revealed that there is 1 US INST CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***9***
EPA ID:: NYN000206222				

Lists of state- and tribal hazardous waste facilities

NY SHWS: A review of the NY SHWS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 7 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER O.Z. ELECTRIC	***198 DOUGLASS STREET***	***NNW 1/4 - 1/2 (0.405 mi.)***	***BD412***	***106***
Site Code: 450318				
GOWANUS CANAL SITE	GOWANUS CANAL	NNW 1/4 - 1/2 (0.417 mi.)	BD417	107
Site Code: 406956				
Class Code: Significant threat to the public health or environment - action required.				
K - METROPOLITAN MGP	***124-136 SECOND AVE***	***WSW 1/2 - 1 (0.539 mi.)***	***BI439***	***112***
Site Code: 372656				
Class Code: Significant threat to the public health or environment - action required.				
FORMER BARRETT MANUF	***627 SMITH ST.***	***WSW 1/2 - 1 (0.868 mi.)***	***444***	***113***
Site Code: 466165				
182 SIGOURNEY ST	182 SIGOURNEY ST	WSW 1/2 - 1 (0.911 mi.)	BJ445	113
Site Code: 499845				
CHEMTURA 633 COURT S	633 COURT STREET	WSW 1/2 - 1 (0.918 mi.)	BJ446	113
Site Code: 443256				
Class Code: Significant threat to the public health or environment - action required.				
643 COURT ST.	643 COURT ST.	WSW 1/2 - 1 (0.951 mi.)	BK447	113
Site Code: 498440				

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: A review of the NY SWF/LF list, as provided by EDR, and dated 06/29/2022 has revealed that there are 14 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON CO. OF NY	3RD AVE (BET. 3RD &	S 0 - 1/8 (0.068 mi.)	D130	38
RINALDI RECYCLING CO	182 4TH AVE.	NNE 1/8 - 1/4 (0.243 mi.)	AN356	92

Lower Elevation	Address	Direction / Distance	Map ID	Page
3RD AVE FLUSH TRUCK	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A64	24
RED HOOK CRUSHERS; I	186 3RD STREET	W 1/8 - 1/4 (0.224 mi.)	AC325	84
CARROLL ST. TRANSFER	400 CARROLL ST	NW 1/4 - 1/2 (0.277 mi.)	368	95

Lower Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL CONSER	2 SECOND AVE.	W 1/4 - 1/2 (0.313 mi.)	AU377	97
BK6 SALT LOT COMMUNI	2 SECOND AVENUE	W 1/4 - 1/2 (0.313 mi.)	AU378	97
CONTAINER SERVICE CO	***107 6TH STREET***	***WSW 1/4 - 1/2 (0.337 mi.)***	***AT391***	***100***
CROSS BAY CONTRACTIN	242 NEVINS ST.	NNW 1/4 - 1/2 (0.343 mi.)	AV393	101
ROYAL RECYCLING CORP	242 NEVINS STREET	NNW 1/4 - 1/2 (0.343 mi.)	AV394	101
INTERCONTINENTAL REC	??	WSW 1/4 - 1/2 (0.371 mi.)	404	104
BALTIC RECYCLING COR	524-26 BALTIC STREET	N 1/4 - 1/2 (0.406 mi.)	414	106
IESI (110 5TH ST.)(S	***110 5TH STREET***	***W 1/4 - 1/2 (0.420 mi.)***	***418***	***107***
BASIN HAULAGE INC. I	462-470 BALTIC STREE	N 1/4 - 1/2 (0.472 mi.)	BF434	111

Lists of state and tribal leaking storage tanks

NY LTANKS: A review of the NY LTANKS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 42 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERRITT GAS STATION	***204-222 4TH AVENUE***	***NNE 1/8 - 1/4 (0.161 mi.)***	***O221***	***59***
Spill Number/Closed Date: 9515732 / 1997-06-11				
Site ID: 204687				
Spill Date: 1996-03-07				
4TH & SACKETT STREET	4TH & SACKETT STREET	NE 1/8 - 1/4 (0.167 mi.)	X230	61
Spill Number/Closed Date: 9113310 / 1994-08-03				
Site ID: 221268				
Spill Date: 1992-03-31				
P.S. # 51- 350 5TH A	P.S. #51 - 350 5TH A	S 1/8 - 1/4 (0.216 mi.)	AK316	82
Spill Number/Closed Date: 9409320 / 1995-02-06				
Site ID: 105617				
Spill Date: 1994-10-12				
KAM SERVICE CENTER I	***363 4TH AVE***	***SSW 1/8 - 1/4 (0.232 mi.)***	***AP340***	***88***
Spill Number/Closed Date: 8901904 / 2016-02-04				
Site ID: 90896				
Spill Date: 1989-05-24				
U-HAUL	259 6TH ST	SSW 1/8 - 1/4 (0.243 mi.)	AP354	92
Spill Number/Closed Date: 9412186 / 2006-03-13				
Site ID: 225909				
Spill Date: 1994-12-12				
401 3RD STREET	401 3RD STREET	SE 1/4 - 1/2 (0.259 mi.)	AI365	94
Spill Number/Closed Date: 9310090 / 1993-11-19				
Site ID: 244717				
Spill Date: 1993-11-11				
FERRANTINO & CO	278 6TH ST	SSW 1/4 - 1/2 (0.265 mi.)	AP366	94
Spill Number/Closed Date: 9705330 / 2011-08-01				
Site ID: 304152				
Spill Date: 1997-08-01				
19 BERKELEY PL	***19 BERKELEY PL***	***ENE 1/4 - 1/2 (0.289 mi.)***	***372***	***96***
Spill Number/Closed Date: 0209599 / 2002-12-18				
Site ID: 238174				

Spill Date: 2002-12-18				
SPILL NUMBER 0209206 Spill Number/Closed Date: 0209206 / 2004-04-16 Site ID: 156887 Spill Date: 2002-12-07	11 LINCOLN PLACE	ENE 1/4 - 1/2 (0.315 mi.)	379	97
225 6TH AVE. Spill Number/Closed Date: 8705973 / 1992-11-19 Site ID: 163112 Spill Date: 1987-10-15	225 6TH AVE	E 1/4 - 1/2 (0.337 mi.)	390	100
126 4TH AVENUE - MIS Spill Number/Closed Date: 9505523 / 2013-01-17 Site ID: 261276 Spill Date: 1995-08-03	126 4TH AVENUE	NNE 1/4 - 1/2 (0.365 mi.)	402	103
236 8TH ST Spill Number/Closed Date: 9508664 / 1995-10-16 Site ID: 211107 Spill Date: 1995-10-15	236 8TH ST	SSW 1/4 - 1/2 (0.368 mi.)	403	103
ECONOMY CLEANERS Spill Number/Closed Date: 0507654 / 2005-11-30 Site ID: 353099 Spill Date: 2005-09-26	***123 5TH AVE***	***ENE 1/4 - 1/2 (0.372 mi.)***	***405***	***104***
SPILL NUMBER 9804333 Spill Number/Closed Date: 9311807 / 1994-01-05 Site ID: 213345 Spill Date: 1994-01-05	***705 CARROLL STREET***	***ESE 1/4 - 1/2 (0.380 mi.)***	***407***	***104***
424 5TH AVENUE Spill Number/Closed Date: 9412686 / 1994-12-21 Site ID: 306765 Spill Date: 1994-12-21	424 5TH STREET	SSE 1/4 - 1/2 (0.410 mi.)	BE416	107
572 WARREN ST. HOUSE Spill Number/Closed Date: 9105220 / 2005-03-08 Site ID: 115495 Spill Date: 1991-08-14	***572 WARREN ST***	***NNE 1/4 - 1/2 (0.423 mi.)***	***419***	***107***
442 5TH ST Spill Number/Closed Date: 9107178 / 1991-10-10 Site ID: 271727 Spill Date: 1991-10-03	442 5TH ST	SSE 1/4 - 1/2 (0.436 mi.)	BE420	108
124 LINCOLN PLACE Spill Number/Closed Date: 9502716 / 1995-06-02 Site ID: 145166 Spill Date: 1995-06-02	124 LINCOLN PLACE	E 1/4 - 1/2 (0.441 mi.)	423	108
APARTMENT BUILDING Spill Number/Closed Date: 0410001 / 2005-10-28 Site ID: 334901 Spill Date: 2004-12-03	446 5TH ST	SSE 1/4 - 1/2 (0.442 mi.)	BE424	108
US POST OFFICE Spill Number/Closed Date: 9007536 / 2009-10-06 Site ID: 92521 Spill Date: 1990-10-10	***198 7TH AVENUE***	***SE 1/4 - 1/2 (0.447 mi.)***	***425***	***109***
STELLAR 341 LLC	***341 10TH STREET***	***SSW 1/4 - 1/2 (0.455 mi.)***	***427***	***109***

Spill Number/Closed Date: 0413183 / 2005-11-09
Site ID: 339044
Spill Date: 2004-04-09

DEL'S AUTO REPAIR — 70 2ND ST/NEW UTRECH — WNW 1/4 - 1/2 (0.456 mi.) — BG429 — 110
Spill Number/Closed Date: 9713407 / 2003-03-03
Site ID: 319396
Spill Date: 1998-03-03

TTF — 300 10TH ST — SSW 1/4 - 1/2 (0.461 mi.) — 431 — 110
Spill Number/Closed Date: 1406432 / 2014-11-13
Site ID: 499901
Spill Date: 2014-09-16

SINSI RESIDENCE — 112 ST MARKS PL — NE 1/4 - 1/2 (0.480 mi.) — 437 — 111
Spill Number/Closed Date: 9600499 / 1996-04-11
Site ID: 208826
Spill Date: 1996-04-10

Lower Elevation	Address	Direction / Distance	Map ID	Page

540 PRESIDENT STREET — 540 PRESIDENT STREET — N 0 - 1/8 (0.087 mi.) — I151 — 43
Spill Number/Closed Date: 9211878 / 1993-01-18
Site ID: 262667
Spill Date: 1993-01-18

ALL BORO'S — 200 3RD ST — W 1/8 - 1/4 (0.180 mi.) — R247 — 66
Spill Number/Closed Date: 9702117 / 1999-08-22
Site ID: 253671
Spill Date: 1997-05-19

325 NEVINS STREET — 325 NEVINS STREET — NW 1/8 - 1/4 (0.208 mi.) — W285 — 75
Spill Number/Closed Date: 9501568 / 1995-05-08
Spill Number/Closed Date: 9508359 / 1995-10-09
Site ID: 266812
Site ID: 266813
Spill Date: 1995-05-08
Spill Date: 1995-10-09

473 PRESIDENT STREET — ***473 PRESIDENT STREET*** — ***NNW 1/8 - 1/4 (0.210 mi.)*** — ***AG291*** — ***76***
Spill Number/Closed Date: 9412605 / Not Reported
Site ID: 323409
Spill Date: 1994-12-20

175 3RD STREET — ***175 3RD STREET*** — ***W 1/8 - 1/4 (0.214 mi.)*** — ***AC312*** — ***81***
Spill Number/Closed Date: 9208180 / 1992-10-15
Site ID: 103805
Spill Date: 1992-10-14

VERIZON — ***318 NEVINS STREET*** — ***NW 1/8 - 1/4 (0.227 mi.)*** — ***AG329*** — ***85***
Spill Number/Closed Date: 0306012 / 2003-10-02
Site ID: 164586
Spill Date: 2003-09-06

AJR (COMMERCIAL BLDG — 599 DEGRAW ST — NNE 1/8 - 1/4 (0.249 mi.) — AM363 — 94
Spill Number/Closed Date: 0500453 / 2005-04-28
Site ID: 343388
Spill Date: 2005-04-11

280 DOUGLAS ST/PENSK — 280 DOUGLAS ST/PENSK — N 1/4 - 1/2 (0.287 mi.) — AS370 — 95
Spill Number/Closed Date: 9112095 / 1992-03-03

Site ID: 280189
Spill Date: 1992-02-25

280 DOUGLAS ST	***280 DOUGLAS STREET***	***N 1/4 - 1/2 (0.287 mi.)***	***AS371***	***95***
Spill Number/Closed Date: 9410669 / 1995-03-10 Site ID: 160988 Spill Date: 1994-11-10				
D GAVER & SONS INC	***267 DOUGLASS ST***	***N 1/4 - 1/2 (0.320 mi.)***	***382***	***98***
Spill Number/Closed Date: 8800904 / 1992-10-02 Site ID: 104086 Spill Date: 1988-04-28				
106 6TH ST	106 6TH ST	WSW 1/4 - 1/2 (0.342 mi.)	AT392	101
Spill Number/Closed Date: 9502574 / 1995-05-31 Site ID: 153670 Spill Date: 1995-05-31				
OCEAN SUPPLY CO	437 3RD AVE	SW 1/4 - 1/2 (0.346 mi.)	AZ397	102
Spill Number/Closed Date: 9905579 / 1999-09-22 Site ID: 306200 Spill Date: 1999-08-06				
UNDERGROUND TANK	151-169 3RD AVE	NNE 1/4 - 1/2 (0.385 mi.)	408	105
Spill Number/Closed Date: 1402248 / 2014-07-09 Spill Number/Closed Date: 0902974 / 2009-08-18 Site ID: 495561 Site ID: 415051 Spill Date: 2014-06-02 Spill Date: 2009-06-12				
SPILL NUMBER 0212934	233 BUTLER ST	N 1/4 - 1/2 (0.437 mi.)	BF421	108
Spill Number/Closed Date: 0212934 / 2003-09-03 Site ID: 180335 Spill Date: 2003-03-31				
66 FOURTH STREET	***66 4TH STREET***	***W 1/4 - 1/2 (0.451 mi.)***	***BH426***	***109***
Spill Number/Closed Date: 0106619 / 2003-11-17 Site ID: 228322 Spill Date: 2001-09-25				
GOWANUS HOUSING COMP	238 BOND ST	NNW 1/4 - 1/2 (0.458 mi.)	430	110
Spill Number/Closed Date: 0201330 / 2005-12-23 Spill Number/Closed Date: 0201191 / 2008-09-23 Site ID: 197021 Site ID: 224675 Spill Date: 2002-05-06 Spill Date: 2002-05-01				
WYCKOFF GARDENS	185 NEVINS ST	N 1/4 - 1/2 (0.478 mi.)	436	111
Spill Number/Closed Date: 9811464 / 1999-05-14 Site ID: 237645 Spill Date: 1998-12-11				
498 3RD AVENUE	498 3RD AVENUE	SW 1/4 - 1/2 (0.499 mi.)	438	112
Spill Number/Closed Date: 8809911 / 2021-08-31 Site ID: 66897 Spill Date: 1989-03-14				

EXECUTIVE SUMMARY

Lists of state and tribal registered storage tanks

NY UST: A review of the NY UST list, as provided by EDR, has revealed that there are 19 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NORTH PETROLEUM CORP	***275 FOURTH AVE***	***ESE 0 - 1/8 (0.026 mi.)***	***A14***	***12***
Database: UST, Date of Government Version: 06/21/2022				
ROMAN CATHOLIC CHURC	522 CARROLL ST	NNE 0 - 1/8 (0.036 mi.)	C91	30
Database: UST, Date of Government Version: 06/21/2022				
PARKSIDE SERVICE CEN	340 4TH AVENUE	SSW 0 - 1/8 (0.119 mi.)	P183	50
Database: UST, Date of Government Version: 06/21/2022				
PEP BOYS #0247	354 4TH AVENUE	SSW 1/8 - 1/4 (0.142 mi.)	P202	54
Database: UST, Date of Government Version: 06/21/2022				
SPEEDWAY # 7835	204-222 FOURTH AVENU	NNE 1/8 - 1/4 (0.161 mi.)	O219	58
Database: UST, Date of Government Version: 06/21/2022				
343 4TH AVENUE	343 4TH AVENUE	SSW 1/8 - 1/4 (0.179 mi.)	Z246	65
Database: UST, Date of Government Version: 06/21/2022				
SUSAN MAINTENANCE CO	374 4TH AVENUE	SSW 1/8 - 1/4 (0.187 mi.)	Z258	68
Database: UST, Date of Government Version: 06/21/2022				
A SHAMOSH	***620-628 DEGRAW STREE***	***NNE 1/8 - 1/4 (0.223 mi.)***	***AM323***	***84***
Database: UST, Date of Government Version: 06/21/2022				
K051	350 5TH AVENUE	SSE 1/8 - 1/4 (0.227 mi.)	AK334	87
Database: UST, Date of Government Version: 06/21/2022				
BP SS # 13397	363 FOURTH AVENUE	SSW 1/8 - 1/4 (0.232 mi.)	AP341	88
Database: UST, Date of Government Version: 06/21/2022				
U-HAUL CO OF METRO N	259 6TH STREET	SSW 1/8 - 1/4 (0.243 mi.)	AP353	91
Database: UST, Date of Government Version: 06/21/2022				

Lower Elevation	Address	Direction / Distance	Map ID	Page
P.S. 372 (OUR LADY O	512 CARROLL STREET	N 0 - 1/8 (0.038 mi.)	C97	31
Database: UST, Date of Government Version: 06/21/2022				
CLARIN TRUCK LEASING	312 3RD AVE	WNW 0 - 1/8 (0.107 mi.)	F172	47
Database: UST, Date of Government Version: 06/21/2022				
617 SACKETT STREET R	617 SACKETT STREET	NNE 1/8 - 1/4 (0.200 mi.)	T271	71
Database: UST, Date of Government Version: 06/21/2022				
220 3RD STREET	220 3RD STREET	WSW 1/8 - 1/4 (0.201 mi.)	AD272	72
Database: UST, Date of Government Version: 06/21/2022				
VERIZON NEW YORK INC	175 THIRD STREET	W 1/8 - 1/4 (0.214 mi.)	AC310	81
Database: UST, Date of Government Version: 06/21/2022				
VERIZON NEW YORK INC	318 NEVINS STREET	NW 1/8 - 1/4 (0.227 mi.)	AG331	86
Database: UST, Date of Government Version: 06/21/2022				
A & A BRAKE CO INC	560 SACKETT STREET	NNW 1/8 - 1/4 (0.245 mi.)	AE360	93
Database: UST, Date of Government Version: 06/21/2022				
SOUTH BROOKLYN REALT	301 NEVINS STREET	NNW 1/8 - 1/4 (0.246 mi.)	361	93
Database: UST, Date of Government Version: 06/21/2022				

EXECUTIVE SUMMARY

NY MOSF UST: A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY MOSF UST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP	510 SACKETT ST.	NNW 1/4 - 1/2 (0.329 mi.)	AW386	99

NY MOSF: A review of the NY MOSF list, as provided by EDR, and dated 06/21/2022 has revealed that there is 1 NY MOSF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP	***510 SACKETT ST***	***NNW 1/4 - 1/2 (0.329 mi.)***	***AW387***	***99***
Tank Status: Unregulated/Closed Facility Id: 2-1220				

NY CBS: A review of the NY CBS list, as provided by EDR, and dated 06/21/2022 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PEP BOYS #0247	***354 4TH AVE***	***SSW 1/8 - 1/4 (0.142 mi.)***	***P204***	***55***
Facility Status: Unregulated/Closed CBS Number: 2-000417				

NY AST: A review of the NY AST list, as provided by EDR, has revealed that there are 23 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NORTH PETROLEUM CORP	***275 FOURTH AVE***	***ESE 0 - 1/8 (0.026 mi.)***	***A14***	***12***
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-241849				
L&B AUTO REPAIR CORP	245 4TH AVENUE	ENE 0 - 1/8 (0.066 mi.)	H128	38
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-606714				
2 FAMILY HOUSE	557 CARROLL ST	ENE 0 - 1/8 (0.073 mi.)	H135	39
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-201928				
PEP BOYS #0247	354 4TH AVENUE	SSW 1/8 - 1/4 (0.142 mi.)	P201	54
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-032301				
PEP BOYS #0247	354 4TH AVE	SSW 1/8 - 1/4 (0.142 mi.)	P205	55
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-000417				
SUSAN MAINTENANCE CO	374 4TH AVENUE	SSW 1/8 - 1/4 (0.187 mi.)	Z261	69
Database: AST, Date of Government Version: 06/21/2022				

Facility Id: 2-611328

32 UNIT 4 STORY WALK Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-252794	325 1ST STREET	ESE 1/8 - 1/4 (0.194 mi.)	U265	70
640 CARROLL LLC Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-608751	640 CARROLL STREET	ESE 1/8 - 1/4 (0.197 mi.)	V269	71
670 PRESIDENT ST HOU Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-254460	670 PRESIDENT STREET	E 1/8 - 1/4 (0.204 mi.)	Y275	72
BHW NV ASSOCIATES Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-291412	321 FIFTH AVENUE	SSE 1/8 - 1/4 (0.208 mi.)	AA282	74
207 CORP Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-257176	207 5TH AVENUE	E 1/8 - 1/4 (0.217 mi.)	318	83
A SHAMOSH Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-611758	***620-628 DEGRAW STREE***	***NNE 1/8 - 1/4 (0.223 mi.)***	***AM323***	***84***
MESSINA Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-272094	392 3RD ST	SSE 1/8 - 1/4 (0.247 mi.)	362	93

Lower Elevation	Address	Direction / Distance	Map ID	Page
P.S. 372 (OUR LADY O Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-267562	512 CARROLL STREET	N 0 - 1/8 (0.038 mi.)	C96	31
505 CARROLL ST. Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-602516	505 CARROLL STREET	NNW 0 - 1/8 (0.074 mi.)	I136	40
L.L.L. AUTO REPAIR I Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-610816	528 PRESIDENT STREET	NNW 0 - 1/8 (0.104 mi.)	I169	47
276 3RD AVENUE Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-608461	276 THIRD AVENUE	NNW 1/8 - 1/4 (0.129 mi.)	Q189	51
HOLYLAND AUTO REPAIR Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-605796	637 UNION STREET	NNE 1/8 - 1/4 (0.151 mi.)	T209	56
RIDGE COMPLETE AUTO Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-611243	264 THIRD AVENUE	NNW 1/8 - 1/4 (0.151 mi.)	Q210	56
PARK SLOPE U-HAUL RE Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-612146	389 3RD AVENUE	WSW 1/8 - 1/4 (0.214 mi.)	AD306	80
VERIZON NEW YORK INC Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-344133	175 THIRD STREET	W 1/8 - 1/4 (0.214 mi.)	AC308	80
VERIZON NEW YORK INC Database: AST, Date of Government Version: 06/21/2022	318 NEVINS STREET	NW 1/8 - 1/4 (0.227 mi.)	AG330	85

Facility Id: 2-344265

A & A BRAKE CO INC	560 SACKETT STREET	NNW 1/8 - 1/4 (0.245 mi.)	AE359	93
Database: AST, Date of Government Version: 06/21/2022 Facility Id: 2-604492				

NY TANKS: A review of the NY TANKS list, as provided by EDR, has revealed that there are 2 NY TANKS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
THIRD AVENUE YARD	***222 FIRST STREET***	***W 0 - 1/8 (0.027 mi.)***	***A71***	***25***
Database: TANKS, Date of Government Version: 06/21/2022 Facility Id: 2-452726 Site Status: Active				
SJ FUEL CO. INC.	601 UNION STREET	N 1/8 - 1/4 (0.168 mi.)	S231	61
Database: TANKS, Date of Government Version: 06/21/2022 Facility Id: 2-601627 Site Status: Active				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: A review of the NY ENG CONTROLS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 4 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
190-220 THIRD STREET	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***64***
Site Code: 333299				
450 UNION STREET	***450 UNION STREET***	***NW 1/4 - 1/2 (0.324 mi.)***	***AW383***	***98***
Site Code: 507633				
365 BOND STREET	***365 BOND STREET***	***WNW 1/4 - 1/2 (0.324 mi.)***	***AX384***	***98***
Site Code: 478842				
388 CARROLL STREET A	***388 CARROLL STREET A***	***NW 1/4 - 1/2 (0.346 mi.)***	***AY398***	***102***
Site Code: 478612				

NY INST CONTROL: A review of the NY INST CONTROL list, as provided by EDR, and dated 05/09/2022 has revealed that there are 5 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
190-220 THIRD STREET	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***64***
Site Code: 333299				
GOWANUS VILLAGE I	153 2ND ST A/K/A 322	WNW 1/4 - 1/2 (0.277 mi.)	AR369	95

Site Code: 332623				
450 UNION STREET	***450 UNION STREET***	***NW 1/4 - 1/2 (0.324 mi.)***	***AW383***	***98***
Site Code: 507633				
365 BOND STREET	***365 BOND STREET***	***WNW 1/4 - 1/2 (0.324 mi.)***	***AX384***	***98***
Site Code: 478842				
388 CARROLL STREET A	***388 CARROLL STREET A***	***NW 1/4 - 1/2 (0.346 mi.)***	***AY398***	***102***
Site Code: 478612				

Lists of state and tribal voluntary cleanup sites

NY VCP: A review of the NY VCP list, as provided by EDR, has revealed that there are 13 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
275 4TH AVENUE	275 4TH AVENUE	ESE 0 - 1/8 (0.026 mi.)	A16	12
Database: VCP NYC, Date of Government Version: 06/06/2022				
269-271 4TH AVENUE	271 4TH AVENUE	ESE 0 - 1/8 (0.026 mi.)	A20	13
Database: VCP NYC, Date of Government Version: 06/06/2022				
566 CARROLL STREET	566 CARROLL STREET	E 0 - 1/8 (0.052 mi.)	B111	34
Database: VCP NYC, Date of Government Version: 06/06/2022				
241 - 245 4TH AVENUE	245 4TH AVENUE	ENE 0 - 1/8 (0.066 mi.)	H129	38
Database: VCP NYC, Date of Government Version: 06/06/2022				
374 4TH AVENUE	374 4TH AVENUE	SSW 1/8 - 1/4 (0.187 mi.)	Z260	69
Database: VCP NYC, Date of Government Version: 06/06/2022				
74-76 SOUTH SECOND S	74-76 SECOND STREET	WNW 1/4 - 1/2 (0.438 mi.)	BG422	108
Database: VCP NYC, Date of Government Version: 06/06/2022				
79-97 4TH AVENUE	85 4TH AVENUE	NNE 1/4 - 1/2 (0.467 mi.)	432	110
Database: VCP NYC, Date of Government Version: 06/06/2022				
125 THIRD AVENUE	125 3RD AVENUE	NNE 1/4 - 1/2 (0.477 mi.)	435	111
Database: VCP NYC, Date of Government Version: 06/06/2022				

Lower Elevation	Address	Direction / Distance	Map ID	Page
553 SACKETT STREET	553 SACKETT STREET	N 1/8 - 1/4 (0.250 mi.)	AQ364	94
Database: VCP NYC, Date of Government Version: 06/06/2022				
FULTON WORKS	DEGRAW STREET AND NE	NNW 1/4 - 1/2 (0.315 mi.)	AV380	97
Database: VCP, Date of Government Version: 05/09/2022				
Site Code: 57151				
233 NEVINS STREET PH	233 NEVINS STREET	N 1/4 - 1/2 (0.375 mi.)	BB406	104
Database: VCP NYC, Date of Government Version: 06/06/2022				
99 NORTH 4TH STREET	99 4TH STREET	WNW 1/4 - 1/2 (0.399 mi.)	BC411	106
Database: VCP NYC, Date of Government Version: 06/06/2022				
233 NEVINS STREET	236 BUTLER STREET	N 1/4 - 1/2 (0.406 mi.)	BB413	106
Database: VCP NYC, Date of Government Version: 06/06/2022				

Lists of state and tribal brownfield sites

NY BROWNFIELDS: A review of the NY BROWNFIELDS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 25 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
272 4TH AVENUE Site Code: 590723	***272 4TH AVENUE***	***NE 0 - 1/8 (0.023 mi.)***	***A11***	***11***
204 4TH AVENUE Site Code: 587854	204 4TH AVENUE	NNE 1/8 - 1/4 (0.161 mi.)	O222	59

Lower Elevation	Address	Direction / Distance	Map ID	Page
THIRD AVENUE YARD Site Code: 533255	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A70	25
190-220 THIRD STREET Site Code: 333299	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***64***
585 UNION STREET Site Code: 619763	577-599 UNION STREET	NNW 1/8 - 1/4 (0.203 mi.)	AE274	72
473 PRESIDENT STREET Site Code: 507634	473 PRESIDENT STREET	NNW 1/8 - 1/4 (0.210 mi.)	AG290	76
473 PRESIDENT STREET Site Code: 568180	***473 PRESIDENT STREET***	***NNW 1/8 - 1/4 (0.210 mi.)***	***AG291***	***76***
514 UNION STREET Site Code: 615885	514 UNION STREET	NNW 1/8 - 1/4 (0.211 mi.)	AE303	79
175-225 3RD STREET Site Code: 504582	175-225 3RD STREET	W 1/8 - 1/4 (0.214 mi.)	AC311	81
PRESIDENT STREET POR Site Code: 602138	469 PRESIDENT STREET	NNW 1/8 - 1/4 (0.218 mi.)	AG319	83
GOWANUS VILLAGE I, L Site Code: 356610	***420 CARROLL STREET***	***NW 1/8 - 1/4 (0.224 mi.)***	***AH324***	***84***
318 NEVINS STREET Site Code: 630084	300-344 NEVINS STREE	NW 1/8 - 1/4 (0.231 mi.)	AG339	88
563 SACKETT STREET Site Code: 507650	563 SACKETT STREET	N 1/8 - 1/4 (0.240 mi.)	AE349	90
141 3RD STREET Site Code: 624862	141 3RD STREET	WNW 1/4 - 1/2 (0.305 mi.)	AR376	97
450 UNION STREET Site Code: 507633	***450 UNION STREET***	***NW 1/4 - 1/2 (0.324 mi.)***	***AW383***	***98***
365 BOND STREET Site Code: 478842	***365 BOND STREET***	***WNW 1/4 - 1/2 (0.324 mi.)***	***AX384***	***98***
335 BOND STREET Site Code: 507653	335 BOND STREET	NW 1/4 - 1/2 (0.326 mi.)	AY385	99
THIRD STREET GOWANUS Site Code: 628534	125 3RD STREET	WNW 1/4 - 1/2 (0.335 mi.)	389	100
242 NEVINS STREET	***242 NEVINS STREET***	***NNW 1/4 - 1/2 (0.343 mi.)***	***AV395***	***101***

Site Code: 568573				
TOLL BROOKLYN, LP Site Code: 348572	64-98 1ST ST; 82-107	WNW 1/4 - 1/2 (0.345 mi.)	AX396	102
388 CARROLL STREET A Site Code: 478612	***388 CARROLL STREET A***	***NW 1/4 - 1/2 (0.346 mi.)***	***AY398***	***102***
168 8TH STREET Site Code: 568008 Site Code: 563661	168 8TH STREET	SW 1/4 - 1/2 (0.364 mi.)	AZ401	103
210 DOUGLASS STREET Site Code: 615221	210 DOUGLASS STREET	NNW 1/4 - 1/2 (0.399 mi.)	BD410	105
234 BUTLER STREET Site Code: 550328	234 BUTLER STREET	N 1/4 - 1/2 (0.408 mi.)	BB415	106
425 HOYT STREET Site Code: 507652	419-429 HOYT STREET	WNW 1/4 - 1/2 (0.470 mi.)	BH433	111

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY: A review of the NY SWRCY list, as provided by EDR, and dated 06/29/2022 has revealed that there are 3 NY SWRCY sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RINALDI RECYCLING CO	326 DOUGLASS STREET	NNE 1/4 - 1/2 (0.273 mi.)	367	94

Lower Elevation	Address	Direction / Distance	Map ID	Page
163 6TH STREET LLC	***163 6TH ST***	***WSW 1/4 - 1/2 (0.302 mi.)***	***AT374***	***96***
US RECYCLING INC	***141 6TH STREET***	***WSW 1/4 - 1/2 (0.303 mi.)***	***AT375***	***96***

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A review of the NY DEL SHWS list, as provided by EDR, and dated 05/09/2022 has revealed that there are 2 NY DEL SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CARROLL GARDENS Site Code Id: 224012	CORNER OF 5TH STREET	WNW 1/2 - 1 (0.595 mi.)	442	112

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHEM TURA	***688-700 COURT ST***	***WSW 1/2 - 1 (0.957 mi.)***	***BK448***	***114***

Records of Emergency Release Reports

NY Spills: A review of the NY Spills list, as provided by EDR, and dated 05/09/2022 has revealed that there are 75 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STREET Spill Number/Closed Date: 0404988 / 2004-08-06 Site ID: 276456 Spill Date: 2004-08-06	1ST STREET/4TH AVE	SSE 0 - 1/8 (0.011 mi.)	A7	10
3RD AVE YARD Spill Number/Closed Date: 0002643 / 2001-09-25 Site ID: 155576 Spill Date: 2000-06-02	1ST ST & 4TH AVE	SSE 0 - 1/8 (0.018 mi.)	A8	10
4TH AVE/GARFIELD ST Spill Number/Closed Date: 8404005 / 2020-04-29 Site ID: 192509 Spill Date: 1984-12-17	4TH AVE/GARFIELD ST	ENE 0 - 1/8 (0.020 mi.)	B10	11
272 4TH AVENUE Spill Number/Closed Date: 2005727 / Not Reported Site ID: 611527 Spill Date: 2020-09-23	***272 4TH AVENUE***	***NE 0 - 1/8 (0.023 mi.)***	***A11***	***11***
CONSTRUCTION SITE Spill Number/Closed Date: 0912838 / 2010-03-11 Site ID: 425747 Spill Date: 2010-03-10	267 FOURTH AVENUE IN	E 0 - 1/8 (0.023 mi.)	A12	11
FORMER GAS STATION Spill Number/Closed Date: 0501021 / 2006-02-20 Site ID: 344148 Spill Date: 2005-04-25	269-271 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A22	13
4TH AVE Spill Number/Closed Date: 0004550 / 2001-10-19 Site ID: 287775 Spill Date: 2000-07-15	CARROLL ST & 4TH AVE	ENE 0 - 1/8 (0.050 mi.)	B109	34
315 4TH AVE Spill Number/Closed Date: 9814678 / 1999-03-26 Site ID: 186475 Spill Date: 1999-03-09	315 4TH AVENUE	S 0 - 1/8 (0.084 mi.)	J147	42
VAULT# TM0253 Spill Number/Closed Date: 0400989 / 2004-07-20 Site ID: 317096 Spill Date: 2004-04-28	PRESIDENT ST & 4TH A	ENE 0 - 1/8 (0.093 mi.)	H155	44
MANHOLE 5436 Spill Number/Closed Date: 0412308 / 2005-02-18 Site ID: 337753 Spill Date: 2005-02-17	4TH AVE/3RD ST	S 0 - 1/8 (0.108 mi.)	J175	48
CONSTRUCTION SITE Spill Number/Closed Date: 1302908 / 2013-06-17 Site ID: 483360 Spill Date: 2013-06-17	340 4TH AVE	SSW 0 - 1/8 (0.119 mi.)	P181	49
PARKSIDE SERVICE CEN	340 4TH AVE	SSW 0 - 1/8 (0.119 mi.)	P182	49

Spill Number/Closed Date: 0704349 / 2014-03-28
Spill Number/Closed Date: 8911553 / 1990-03-08
Spill Number/Closed Date: 0801262 / 2008-05-01
Site ID: 384480
Site ID: 244057
Site ID: 397156
Spill Date: 2007-07-18
Spill Date: 1990-03-07
Spill Date: 2008-05-01

Lower Elevation	Address	Direction / Distance	Map ID	Page
MC DONALD'S Spill Number/Closed Date: 0551768 / 2013-10-07 Site ID: 361253 Spill Date: 2006-02-01	245 1ST STREET	WNW 0 - 1/8 (0.008 mi.)	A6	10
YARD Spill Number/Closed Date: 1105298 / 2011-10-28 Site ID: 452947 Spill Date: 2011-07-21	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A24	14
CON EDISON VEHICLE 6 Spill Number/Closed Date: 1110967 / 2012-01-17 Site ID: 458834 Spill Date: 2011-12-09	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A27	14
THIRD AVE YARD - SER Spill Number/Closed Date: 9808009 / 2017-06-08 Site ID: 299103 Spill Date: 1998-09-30	222 1ST STREET	W 0 - 1/8 (0.027 mi.)	A28	14
THIRD AVE YARD Spill Number/Closed Date: 0110159 / 2003-05-01 Site ID: 263575 Spill Date: 2002-01-22	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A29	15
CON EDISON Spill Number/Closed Date: 9510404 / 1995-11-20 Site ID: 299101 Spill Date: 1995-11-16	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A30	15
THIRD AVE YARD Spill Number/Closed Date: 0408750 / 2005-01-06 Site ID: 333489 Spill Date: 2004-11-08	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A31	15
SERVICE BOX 3RD AVE Spill Number/Closed Date: 9907981 / 2002-01-30 Site ID: 299104 Spill Date: 1999-09-30	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A32	15
CON ED 3RD AVE STATI Spill Number/Closed Date: 1601300 / 2017-03-28 Site ID: 526616 Spill Date: 2016-05-09	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A34	16
COOLANT RELEASE FROM Spill Number/Closed Date: 0700220 / 2007-05-23 Site ID: 379559 Spill Date: 2007-04-07	222 1 STREET (THIRD	W 0 - 1/8 (0.027 mi.)	A35	16
CON ED THIRD AVE YAR	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A37	17

Spill Number/Closed Date: 1105608 / 2011-10-04
Spill Number/Closed Date: 2104705 / 2021-10-04
Site ID: 453268
Site ID: 623525
Spill Date: 2011-08-17
Spill Date: 2021-08-18

CON-ED THIRD AVE YAR	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A38	17
Spill Number/Closed Date: 1110305 / 2012-01-17 Site ID: 458118 Spill Date: 2011-11-18				
CON ED 3RD AV YARD	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A40	17
Spill Number/Closed Date: 9913132 / 2000-02-18 Site ID: 263145 Spill Date: 2000-02-18				
CON ED 3RD AV GARAGE	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A41	18
Spill Number/Closed Date: 9607770 / 1998-05-27 Site ID: 276610 Spill Date: 1996-09-20				
CON ED FACILITY	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A42	18
Spill Number/Closed Date: 9811783 / 2003-02-14 Site ID: 263579 Spill Date: 1998-12-18				
OIL LEAK FROM VEHICL	222 FIRST ST AT 3 AV	W 0 - 1/8 (0.027 mi.)	A43	18
Spill Number/Closed Date: 0508341 / 2005-11-25 Site ID: 353906 Spill Date: 2005-10-12				
CON EDISON 3RD AVE Y	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A44	18
Spill Number/Closed Date: 9703946 / 2003-02-28 Site ID: 299102 Spill Date: 1997-07-01				
CON ED STATION	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A45	19
Spill Number/Closed Date: 1205717 / 2013-03-08 Site ID: 468682 Spill Date: 2012-09-08				
3RD AVENUE YARD	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A46	19
Spill Number/Closed Date: 9714230 / 1998-05-13 Site ID: 263578 Spill Date: 1998-03-24				
3RD AVE YARD	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A47	19
Spill Number/Closed Date: 0813445 / 2009-06-03 Site ID: 411134 Spill Date: 2009-03-13				
3RD AVE YARD	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A48	19
Spill Number/Closed Date: 0300475 / 2003-04-15 Spill Number/Closed Date: 0410262 / 2005-04-22 Spill Number/Closed Date: 1000131 / 2010-04-27 Spill Number/Closed Date: 1000132 / 2010-04-22 Spill Number/Closed Date: 0910207 / 2010-02-16 **Additional key fields are available in the Map Findings section* Site ID: 299100 Site ID: 335210				

Site ID: 427053
Site ID: 427054
Site ID: 422955
**Additional key fields are available in the Map Findings section*
Spill Date: 2003-04-14
Spill Date: 2004-12-15
Spill Date: 2010-04-04
Spill Date: 2009-12-15
Spill Date: 2000-02-14
**Additional key fields are available in the Map Findings section*

THIRD AVE YARD Spill Number/Closed Date: 1114458 / 2012-05-10 Site ID: 462517 Spill Date: 2012-03-29	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A50	21
3 QT ANTI-FREEZE FRO Spill Number/Closed Date: 0711576 / 2008-05-12 Site ID: 393082 Spill Date: 2008-02-02	222 FIRST ST. CON ED	W 0 - 1/8 (0.027 mi.)	A51	21
3RD AVE SERVICE YARD Spill Number/Closed Date: 9801450 / 2002-10-30 Site ID: 263140 Spill Date: 1998-05-03	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A52	21
3RD AVE YARD Spill Number/Closed Date: 0807096 / 2008-11-17 Site ID: 404414 Spill Date: 2008-09-24	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A53	21
3RD AVE YARD Spill Number/Closed Date: 1008213 / 2017-06-08 Site ID: 441688 Spill Date: 2010-11-05	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A56	22
3RD AVE YARD CON ED Spill Number/Closed Date: 9801934 / 1998-06-12 Site ID: 263141 Spill Date: 1998-05-14	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A57	22
222 1ST STREET Spill Number/Closed Date: 9415797 / 1998-02-13 Site ID: 201957 Spill Date: 1995-03-06	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A58	23
THIRD AVENUE YARD Spill Number/Closed Date: 1000930 / 2010-05-21 Site ID: 433623 Spill Date: 2010-04-23	222 1ST STREET	W 0 - 1/8 (0.027 mi.)	A61	23
CON ED Spill Number/Closed Date: 1104942 / 2011-09-07 Site ID: 452560 Spill Date: 2011-07-31	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A62	23
222 FIRST STREET Spill Number/Closed Date: 9706833 / 1997-09-10 Site ID: 263577 Spill Date: 1997-09-08	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A63	24
3RD AV YARD	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A65	24

Spill Number/Closed Date: 0007860 / 2001-12-14
Spill Number/Closed Date: 9614742 / 1997-03-25
Spill Number/Closed Date: 9603338 / 1996-08-22
Site ID: 263128
Site ID: 263136
Site ID: 276609
Spill Date: 2000-10-04
Spill Date: 1997-03-21
Spill Date: 1996-06-10

3 AVE YARD	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A66	24
Spill Number/Closed Date: 0513083 / 2006-04-21 Site ID: 359500 Spill Date: 2006-02-13				
LEAK FROM VEHICLE IN	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A67	25
Spill Number/Closed Date: 0514637 / 2006-06-14 Site ID: 361408 Spill Date: 2006-03-22				
CON EDISON GARAGE	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A68	25
Spill Number/Closed Date: 0602266 / 2006-10-05 Site ID: 364698 Spill Date: 2006-05-31				
VEHICLE 60722 LOST H	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A69	25
Spill Number/Closed Date: 0514814 / 2008-01-10 Site ID: 361624 Spill Date: 2006-03-27				
THIRD AVENUE YARD	***222 FIRST STREET***	***W 0 - 1/8 (0.027 mi.)***	***A71***	***25***
Spill Number/Closed Date: 0203307 / 2017-06-08 Site ID: 263576 Spill Date: 2002-06-27				
CON ED WORK / 3RD AV	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A72	26
Spill Number/Closed Date: 1301088 / 2013-07-10 Site ID: 481453 Spill Date: 2013-05-02				
FLUSH PIT	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A73	26
Spill Number/Closed Date: 9807969 / 2002-12-30 Site ID: 276613 Spill Date: 1998-09-27				
3RD AVE YARD	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A74	26
Spill Number/Closed Date: 1012255 / 2011-03-22 Site ID: 446173 Spill Date: 2011-03-10				
CON EDISON	***221 1ST ST***	***WNW 0 - 1/8 (0.027 mi.)***	***A76***	***27***
Spill Number/Closed Date: 9911979 / 2000-02-23 Site ID: 177460 Spill Date: 2000-01-17				
220 1ST STREET	220 1ST STREET	W 0 - 1/8 (0.028 mi.)	A81	28
Spill Number/Closed Date: 9207274 / 2008-09-19 Site ID: 153446 Spill Date: 1992-09-15				
FIVE GALLONS OF OIL	222 1 STREET	SW 0 - 1/8 (0.031 mi.)	A83	28
Spill Number/Closed Date: 0604245 / 2017-06-08				

Spill Number/Closed Date: 0512763 / 2006-04-12
Site ID: 367178
Site ID: 359135
Spill Date: 2006-06-28
Spill Date: 2006-02-03

SIX GAL HYDRAULIC FL	222 FIRST STREET & 3	SW 0 - 1/8 (0.031 mi.)	A84	28
Spill Number/Closed Date: 0705772 / 2007-11-08 Site ID: 386143 Spill Date: 2007-08-20				
VEHICLE 60677	THIRD AVE YARD	SW 0 - 1/8 (0.031 mi.)	A85	29
Spill Number/Closed Date: 0512797 / 2006-04-12 Site ID: 359174 Spill Date: 2006-02-04				
222 1ST STREET	CON EDSION	SW 0 - 1/8 (0.031 mi.)	A86	29
Spill Number/Closed Date: 9501055 / 2004-07-16 Site ID: 201439 Spill Date: 1995-04-25				
HYDRAULIC OIL	3 AVE YARD NEW CONST	SW 0 - 1/8 (0.031 mi.)	A87	29
Spill Number/Closed Date: 0505767 / 2005-08-11 Site ID: 350857 Spill Date: 2005-08-10				
P.S. 372 (OUR LADY O	***512 CARROLL STREET***	***N 0 - 1/8 (0.038 mi.)***	***C95***	***31***
Spill Number/Closed Date: 0402598 / 2021-10-20 Site ID: 288471 Spill Date: 2004-06-09				
3RD AVE YARD	3RD AVE YARD	WSW 0 - 1/8 (0.054 mi.)	E114	35
Spill Number/Closed Date: 9702955 / 2003-02-28 Spill Number/Closed Date: 1003520 / 2010-10-18 Spill Number/Closed Date: 9514611 / 2003-01-31 Site ID: 281782 Site ID: 436752 Site ID: 281779 Spill Date: 1997-06-09 Spill Date: 2010-06-29 Spill Date: 1996-02-15				
3RD AV YARD INFO STO	M 222 1ST ST	WNW 0 - 1/8 (0.060 mi.)	F122	37
Spill Number/Closed Date: 0105268 / 2001-08-15 Site ID: 243216 Spill Date: 2001-08-15				
COMMERCIAL BUILDING	14 WHITWELL PLACE	NNW 0 - 1/8 (0.061 mi.)	F123	37
Spill Number/Closed Date: 0606675 / 2009-03-17 Site ID: 370045 Spill Date: 2006-09-11				
PROCIDA REALTY	505 CARROLL STREET	NNW 0 - 1/8 (0.074 mi.)	I137	40
Spill Number/Closed Date: 0602894 / 2008-10-20 Site ID: 365475 Spill Date: 2006-06-15				
THIRD AV YARD	222 FIRST STREET	W 0 - 1/8 (0.076 mi.)	E138	40
Spill Number/Closed Date: 0001798 / 2000-06-20 Site ID: 276606 Spill Date: 2000-05-11				
FLUSHPIT 3RD AVE YAR	222 FIRST STREET	W 0 - 1/8 (0.076 mi.)	E139	40

Spill Number/Closed Date: 0009168 / 2000-11-14 Site ID: 263574 Spill Date: 2000-11-08				
222 1ST ST Spill Number/Closed Date: 9803310 / 1998-08-06 Site ID: 281783 Spill Date: 1998-06-12	3RD AVE YARD	WNW 0 - 1/8 (0.090 mi.)	F152	43
THIRD AVENUE YARD Spill Number/Closed Date: 9605550 / 1998-05-04 Site ID: 73086 Spill Date: 1996-07-30	THIRD AVENUE & FIRST	WNW 0 - 1/8 (0.090 mi.)	F153	43
3RD AVE YARD Spill Number/Closed Date: 9514614 / 2003-02-24 Spill Number/Closed Date: 9702275 / 2003-02-25 Site ID: 281780 Site ID: 281781 Spill Date: 1996-02-15 Spill Date: 1997-05-20	3RD AVE YARD	WNW 0 - 1/8 (0.090 mi.)	F154	43
FEEDER LEAK Spill Number/Closed Date: 1809345 / 2019-06-21 Site ID: 580185 Spill Date: 2018-12-05	3RD AVE & 1ST STREET	WNW 0 - 1/8 (0.095 mi.)	F159	45
3RD AVE SERVICE CENT Spill Number/Closed Date: 9608437 / 2004-09-02 Site ID: 203791 Spill Date: 1996-10-07	3RD AVE & 1ST ST	WNW 0 - 1/8 (0.095 mi.)	F160	45
MANHOLE # 65435 Spill Number/Closed Date: 0502530 / 2005-08-17 Site ID: 346909 Spill Date: 2005-06-02	3RD AVE/1ST STREET	WNW 0 - 1/8 (0.095 mi.)	F162	45
ABF FREIGHTS Spill Number/Closed Date: 2006668 / 2020-10-22 Site ID: 612520 Spill Date: 2020-10-22	545 PRESIDENT ST	N 0 - 1/8 (0.109 mi.)	M176	48
2ND & 3RD AVE Spill Number/Closed Date: 9914001 / 2003-08-08 Site ID: 126958 Spill Date: 2000-03-11	2ND & 3RD AVE	W 0 - 1/8 (0.109 mi.)	N177	48
MAN HOLE 5354 Spill Number/Closed Date: 1006176 / 2010-09-24 Site ID: 439522 Spill Date: 2010-09-04	3RD AND AVE AND 2ND	W 0 - 1/8 (0.110 mi.)	N178	49

Other Ascertainable Records

RCRA NonGen / NLR: A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/20/2022 has revealed that there are 73 RCRA NonGen / NLR sites within approximately 0.25 miles of the target

property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID:: NYP004571485	540 CARROLL ST	NNE 0 - 1/8 (0.027 mi.)	B79	27
AUTO BODY CONCEPTS D EPA ID:: NYR000060392	270 4TH AVE	NE 0 - 1/8 (0.031 mi.)	B89	29
CON EDISON SERVICE B EPA ID:: NYP004572756	***9 GARFIELD ST***	***E 0 - 1/8 (0.037 mi.)***	***B93***	***30***
CON EDISON EPA ID:: NYP004757563	***CARROLL ST & 4TH AVE***	***NE 0 - 1/8 (0.039 mi.)***	***B98***	***31***
CON EDISON EPA ID:: NYP004879932	255 4TH AVE	ENE 0 - 1/8 (0.039 mi.)	B100	32
CON EDISON EPA ID:: NYP004757555	***DENTON ST & CARROLL***	***NNE 0 - 1/8 (0.042 mi.)***	***C103***	***32***
CON EDISON SERVICE B EPA ID:: NYP005172960	12 GARFIELD PL	ESE 0 - 1/8 (0.042 mi.)	B106	33
CON EDISON SERVICE B EPA ID:: NYP004425880	***100 4TH ST & 2ND AVE***	***S 0 - 1/8 (0.057 mi.)***	***D116***	***35***
NYCDOT BRIDGE BIN 22 EPA ID:: NY0000375220	PRESIDENT ST BRG OVE	NE 0 - 1/8 (0.059 mi.)	B120	36
CON EDISON EPA ID:: NYP004738910	***22 GARFIELD ST***	***ESE 0 - 1/8 (0.066 mi.)***	***G126***	***38***
245 4TH AVENUE LLC EPA ID:: NYR000229906	***243-245 4TH AVE***	***ENE 0 - 1/8 (0.073 mi.)***	***H134***	***39***
CON EDISON EPA ID:: NYP004744215	***584 CARROLL ST***	***E 0 - 1/8 (0.083 mi.)***	***G146***	***42***
CON EDISON EPA ID:: NYP004743068	***586 CARROL ST***	***E 0 - 1/8 (0.087 mi.)***	***G149***	***42***
CON EDISON EPA ID:: NYP004744306	***590 CARROLL ST***	***E 0 - 1/8 (0.094 mi.)***	***G158***	***44***
CON EDISON EPA ID:: NYP004735734	***577 CARROLL ST***	***E 0 - 1/8 (0.104 mi.)***	***K168***	***46***
CON EDISON SERVICE B EPA ID:: NYP004429650	***260 3RD ST FRONT OF***	***S 0 - 1/8 (0.116 mi.)***	***J180***	***49***
CON EDISON SERVICE B EPA ID:: NYP004349064	***604 UNION ST***	***NNE 1/8 - 1/4 (0.126 mi.)***	***M188***	***51***
NYCT - UNION STATION EPA ID:: NYR000107938	***UNION ST & 4TH AVE***	***NE 1/8 - 1/4 (0.136 mi.)***	***O191***	***51***
CON EDISON MANHOLE: EPA ID:: NYP004318366	***4TH & UNION AVE***	***NE 1/8 - 1/4 (0.137 mi.)***	***O193***	***52***
PEP BOYS 247 EPA ID:: NYR000071936	***354 4TH AVE***	***SSW 1/8 - 1/4 (0.142 mi.)***	***P203***	***54***
MAACO AUTO PAINTING EPA ID:: NYD981488232	***358 FOURTH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P211***	***56***
CON EDISON - MANHOLE EPA ID:: NYP004130670	***358 4TH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P212***	***57***
CON EDISON SERVICE B	***85-87 1ST AVE & 5TH***	***SE 1/8 - 1/4 (0.160 mi.)***	***U216***	***58***

EPA ID:: NYP004485942				
RALPHS CLEANERS	***230 FIFTH AVE***	***E 1/8 - 1/4 (0.170 mi.)***	***Y235***	***62***
EPA ID:: NYD986951069				
JET FRENCH CLEANERS	***279 5TH AVE***	***SE 1/8 - 1/4 (0.177 mi.)***	***U244***	***65***
EPA ID:: NYR000016402				
BRIDGE FORD	***343 4TH AVE***	***SSW 1/8 - 1/4 (0.179 mi.)***	***Z245***	***65***
EPA ID:: NYD982280091				
CON EDISON	354 3RD ST	SSE 1/8 - 1/4 (0.180 mi.)	AA249	66
EPA ID:: NYP004783759				
BROOKLYN IGNITION &	***370 4TH AVE***	***SSW 1/8 - 1/4 (0.183 mi.)***	***Z253***	***67***
EPA ID:: NY0000228106				
SEMPLE RIEGER CO	***635 SACKETT ST***	***NNE 1/8 - 1/4 (0.194 mi.)***	***X264***	***69***
EPA ID:: NYD986891885				
CON EDISON	***365 2ND ST***	***SE 1/8 - 1/4 (0.195 mi.)***	***U266***	***70***
EPA ID:: NYP004825176				
CON EDISON SERVICE B	***209 5TH ST OPPOSITE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***Z270***	***71***
EPA ID:: NYP004307930				
CON EDISON	***335 1ST ST***	***ESE 1/8 - 1/4 (0.207 mi.)***	***U281***	***74***
EPA ID:: NYP004731998				
CON EDISON SERVICE B	***674 PRESIDENT ST***	***E 1/8 - 1/4 (0.212 mi.)***	***Y304***	***79***
EPA ID:: NYP004330726				
CON EDISON	***676 PRESIDENT ST***	***E 1/8 - 1/4 (0.216 mi.)***	***AJ315***	***82***
EPA ID:: NYP004738498				
CON EDISON SERVICE B	***726 SACKETT ST***	***ENE 1/8 - 1/4 (0.217 mi.)***	***AL317***	***82***
EPA ID:: NYP004349585				
CON EDISON	***675 PRESIDENT ST***	***E 1/8 - 1/4 (0.223 mi.)***	***AJ321***	***83***
EPA ID:: NYP004738811				
CON EDISON	664 DEGRAW ST	NE 1/8 - 1/4 (0.226 mi.)	AN327	85
EPA ID:: NYP004781910				
CON EDISON SERVICE B	298 5TH ST	S 1/8 - 1/4 (0.227 mi.)	AO336	87
EPA ID:: NYP004570321				
CON ED - V 3685	522 W 44 ST	SSW 1/8 - 1/4 (0.228 mi.)	Z337	87
EPA ID:: NYP000928358				
CON EDISON SERVICE B	***315 4TH ST S***	***SSE 1/8 - 1/4 (0.229 mi.)***	***AA338***	***87***
EPA ID:: NYP004337168				
KAM SERVICE CENTER I	***363 4TH AVE***	***SSW 1/8 - 1/4 (0.232 mi.)***	***AP340***	***88***
EPA ID:: NYD986988004				
CON EDISON	***391 2ND ST***	***SE 1/8 - 1/4 (0.238 mi.)***	***AI343***	***89***
EPA ID:: NYP004760401				
AMOCO SERVICE STATIO	***375-381 4TH AVE & 6T***	***SSW 1/8 - 1/4 (0.239 mi.)***	***AP348***	***90***
EPA ID:: NYD986933109				
CON EDISON SERVICE B	***195 5TH AVE FRONT OF***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AL352***	***91***
EPA ID:: NYP004326278				
U-HAUL CORP	***259 6TH ST - PARK SL***	***SSW 1/8 - 1/4 (0.243 mi.)***	***AP355***	***92***
EPA ID:: NY0000970509				
CON EDISON MANHOLE:	***267 6TH ST***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AO358***	***93***

EPA ID:: NYP004322004

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON TM439 EPA ID:: NYP004036729	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A55***	***22***
CON EDISON EPA ID:: NYP004772869	221 1ST	WNW 0 - 1/8 (0.027 mi.)	A77	27
CON EDISON EPA ID:: NYP004837696	221 1ST ST	WNW 0 - 1/8 (0.027 mi.)	A78	27
CON EDISON EPA ID:: NYP004757548	***511 CARROLL ST***	***N 0 - 1/8 (0.058 mi.)***	***C118***	***36***
FINEST AUTO & RECOVE EPA ID:: NYR000090431	***310 3RD AVE***	***NW 0 - 1/8 (0.104 mi.)***	***F171***	***47***
JO-LEE TRUCKING EPA ID:: NYR000131938	463 CARROLL ST	NW 1/8 - 1/4 (0.135 mi.)	L190	51
CON EDISON SERVICE B EPA ID:: NYP004376315	***578 UNION ST***	***N 1/8 - 1/4 (0.137 mi.)***	***M194***	***52***
CON EDISON VAULT SUB EPA ID:: NYP004476214	***213 3RD ST***	***W 1/8 - 1/4 (0.138 mi.)***	***N195***	***53***
VERIZON LOG 31756 MA EPA ID:: NYP000962894	3RD ST & 3RD AVE	WSW 1/8 - 1/4 (0.140 mi.)	R197	53
CON EDISON EPA ID:: NYP004743779	***3RD ST & 3RD AVE***	***WSW 1/8 - 1/4 (0.140 mi.)***	***R198***	***53***
CON EDISON EXCAVATIO EPA ID:: NYP004551230	251 3RD AVE	N 1/8 - 1/4 (0.150 mi.)	S208	56
CON EDISON SERVICE B EPA ID:: NYP004479192	***210 3RD ST***	***WSW 1/8 - 1/4 (0.159 mi.)***	***R215***	***57***
CON EDISON EPA ID:: NYP004818912	451 CARROLL ST FRONT	NW 1/8 - 1/4 (0.162 mi.)	W224	60
CON EDISON EPA ID:: NYP004836340	***617 UNION ST & 3RD A***	***N 1/8 - 1/4 (0.165 mi.)***	***S226***	***60***
CON EDISON EPA ID:: NYP004795480	501 PRESIDENT ST	NNW 1/8 - 1/4 (0.166 mi.)	Q228	61
A 2 Z ENVIRONMENTAL EPA ID:: NYR000187302	601 UNION ST	N 1/8 - 1/4 (0.168 mi.)	S232	62
216 3RD STREET EPA ID:: NYD001869049	***216 3RD ST***	***W 1/8 - 1/4 (0.172 mi.)***	***R236***	***62***
CON EDISON EPA ID:: NYP004827267	***443 CARROLL ST***	***NW 1/8 - 1/4 (0.172 mi.)***	***W238***	***63***
190-220 THIRD STREET EPA ID:: NYR000197178	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***64***
CON EDISON SERVICE B EPA ID:: NYP004479184	***198 3RD ST***	***W 1/8 - 1/4 (0.185 mi.)***	***AC257***	***68***
MATTHEWS INTERNATION EPA ID:: NYN008027997	585 UNION ST	NNW 1/8 - 1/4 (0.192 mi.)	S263	69
PIPPIN ENTERPRISES L	***220 3RD ST***	***WSW 1/8 - 1/4 (0.201 mi.)***	***AD273***	***72***

EPA ID:: NYD987023181				
CON EDISON MANHOLE: EPA ID:: NYP004479242	***190 3RD ST FRONT OF***	***W 1/8 - 1/4 (0.208 mi.)***	***AC283***	***74***
CON EDISON EPA ID:: NYP004841512	***SACKETT ST & 3RD AVE***	***N 1/8 - 1/4 (0.209 mi.)***	***AF287***	***75***
CON EDISON EPA ID:: NYP004822777	***CARROLL ST & NEVINS***	***NW 1/8 - 1/4 (0.210 mi.)***	***AH297***	***78***
NEW YORK TELEPHONE C EPA ID:: NYD987028008	175 THIRD ST	W 1/8 - 1/4 (0.214 mi.)	AC309	80
NYSDOT 3RD ST BRIDGE EPA ID:: NYD986975316	3RD ST BRG OVER GOWA	WNW 1/8 - 1/4 (0.244 mi.)	357	92

ROD: A review of the ROD list, as provided by EDR, and dated 07/26/2022 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOWANUS CANAL EPA ID:: NYN000206222	***BUTLER ST (BETWEEN B***	***WSW 1/8 - 1/4 (0.196 mi.)***	***0***	***9***

NY DRYCLEANERS: A review of the NY DRYCLEANERS list, as provided by EDR, and dated 08/30/2022 has revealed that there are 3 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RALPH'S CLEANERS Facility Id: 2-6103-00246	230 5TH AVE	E 1/8 - 1/4 (0.170 mi.)	Y234	62
MALACHI DRY CLNR Facility Id: 2-6103-00538	279 5TH AVENUE	SE 1/8 - 1/4 (0.177 mi.)	U243	65

Lower Elevation	Address	Direction / Distance	Map ID	Page
KLOR-DE CLEANERS Facility Id: 2-6103-00151	263 3RD AVENUE	N 1/8 - 1/4 (0.136 mi.)	M192	52

NY E DESIGNATION: A review of the NY E DESIGNATION list, as provided by EDR, and dated 03/22/2022 has revealed that there are 18 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 964	275 4 AVENUE	ESE 0 - 1/8 (0.026 mi.)	A19	13
LOT 6,TAXBLOCK 964	271 4 AVENUE	ESE 0 - 1/8 (0.026 mi.)	A21	13
LOT 7,TAXBLOCK 964	269 4 AVENUE	ESE 0 - 1/8 (0.026 mi.)	A23	13
LOT 1,TAXBLOCK 961	261 4 AVENUE	E 0 - 1/8 (0.031 mi.)	B82	28
LOT 2,TAXBLOCK 961	259 4 AVENUE	ENE 0 - 1/8 (0.034 mi.)	B90	30
LOT 69,TAXBLOCK 961	13 GARFIELD PLACE	E 0 - 1/8 (0.040 mi.)	B102	32

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 67,TAXBLOCK 961	***15 GARFIELD PLACE***	***E 0 - 1/8 (0.048 mi.)***	***B108***	***33***
LOT 7,TAXBLOCK 961	566 CARROLL STREET	E 0 - 1/8 (0.052 mi.)	B110	34
LOT 21,TAXBLOCK 352	CARROLL STREET	ENE 0 - 1/8 (0.053 mi.)	B112	34
LOT 1,TAXBLOCK 969	283 4 AVENUE	SSE 0 - 1/8 (0.054 mi.)	D113	34
LOT 1,TAXBLOCK 958	253 4 AVENUE	ENE 0 - 1/8 (0.056 mi.)	B115	35
LOT 2,TAXBLOCK 958	249 4 AVENUE	ENE 0 - 1/8 (0.059 mi.)	B121	37
LOT 4,TAXBLOCK 958	245 4 AVENUE	ENE 0 - 1/8 (0.066 mi.)	H127	38
LOT 7504,TAXBLOCK 97	302 2 STREET	S 0 - 1/8 (0.072 mi.)	D131	39
LOT 5,TAXBLOCK 958	243 4 AVENUE	ENE 0 - 1/8 (0.073 mi.)	H133	39
LOT 7,TAXBLOCK 958	586 PRESIDENT STREET	ENE 0 - 1/8 (0.082 mi.)	H142	41
LOT 7502,TAXBLOCK 97	306 2 STREET	S 0 - 1/8 (0.083 mi.)	D144	41
LOT 73,TAXBLOCK 974	303 3 STREET	S 0 - 1/8 (0.099 mi.)	J163	45

NY HSWDS: A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUG, CITIZENS GATE S	6TH STREET AND 2ND A	WSW 1/4 - 1/2 (0.356 mi.)	BA400	103

NY MANIFEST: A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 106 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004655908	292 4TH AV	0 - 1/8 (0.000 mi.)	A4	9
CON EDISON EPA ID: NYP004615274	292 4TH AV	0 - 1/8 (0.000 mi.)	A5	10
275 4TH AVE INVESTOR EPA ID: NYD986914133	275 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A15	12
CON EDISON EPA ID: NYP004571485	540 CARROLL ST	NNE 0 - 1/8 (0.027 mi.)	B80	27
CON EDISON EPA ID: NYP004572756	9 GARFIELD ST	E 0 - 1/8 (0.037 mi.)	B92	30
CON ED EPA ID: NYP004879932	255 4TH AVE	ENE 0 - 1/8 (0.039 mi.)	B101	32
CON EDISON EPA ID: NYP004757555	DENTON ST & CARROLL	NNE 0 - 1/8 (0.042 mi.)	C104	33
CON EDISON - SERVICE EPA ID: NYP004977890	255 1ST ST	ESE 0 - 1/8 (0.046 mi.)	B107	33
LOT 67,TAXBLOCK 961 EPA ID: NYP004980361	***15 GARFIELD PLACE***	***E 0 - 1/8 (0.048 mi.)***	***B108***	***33***
CON EDISON SERVICE B EPA ID: NYP004425880	***100 4TH ST & 2ND AVE***	***S 0 - 1/8 (0.057 mi.)***	***D116***	***35***
CON EDISON	22 GARFIELD ST	ESE 0 - 1/8 (0.066 mi.)	G124	37

EPA ID: NYP004738910				
243 DEVELOPMENT LLC EPA ID: NYR000229906	243-245 4TH AVE	ENE 0 - 1/8 (0.073 mi.)	H132	39
CON EDISON EPA ID: NYP004691457	586 PRESIDENT ST	ENE 0 - 1/8 (0.082 mi.)	H143	41
CON EDISON EPA ID: NYP004744215	584 CARROLL ST	E 0 - 1/8 (0.083 mi.)	G145	41
CON EDISON EPA ID: NYP004743068	586 CARROL ST	E 0 - 1/8 (0.087 mi.)	G150	43
CON EDISON EPA ID: NYP004744306	590 CARROLL ST	E 0 - 1/8 (0.094 mi.)	G156	44
CON EDISON - SERVICE EPA ID: NYP005093950	328 2ND ST	SSE 0 - 1/8 (0.102 mi.)	D164	46
CON EDISON EPA ID: NYP004735734	577 CARROLL ST	E 0 - 1/8 (0.104 mi.)	K166	46
CON EDISON SERVICE B EPA ID: NYP004429650	***260 3RD ST FRONT OF***	***S 0 - 1/8 (0.116 mi.)***	***J180***	***49***
CON EDISON SERVICE B EPA ID: NYP004349064	***604 UNION ST***	***NNE 1/8 - 1/4 (0.126 mi.)***	***M188***	***51***
NYCT - UNION STATION EPA ID: NYR000107938	***UNION ST & 4TH AVE***	***NE 1/8 - 1/4 (0.136 mi.)***	***O191***	***51***
CON EDISON MANHOLE: EPA ID: NYP004318366	***4TH & UNION AVE***	***NE 1/8 - 1/4 (0.137 mi.)***	***O193***	***52***
PEP BOYS 247 EPA ID: NYR000071936	***354 4TH AVE***	***SSW 1/8 - 1/4 (0.142 mi.)***	***P203***	***54***
MAACO AUTO PAINTING EPA ID: NYD981488232	***358 FOURTH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P211***	***56***
CON EDISON - MANHOLE EPA ID: NYP004130670	***358 4TH AVE***	***SSW 1/8 - 1/4 (0.153 mi.)***	***P212***	***57***
CON EDISON - TRANSFO EPA ID: NYP004964548	5TH AVE & GARFIELD P	ESE 1/8 - 1/4 (0.161 mi.)	V217	58
HESS#32530 EPA ID: NYD982185563	***204-222 FOURTH AVE***	***NNE 1/8 - 1/4 (0.161 mi.)***	***O220***	***58***
RALPHS CLEANERS EPA ID: NYD986951069	***230 FIFTH AVE***	***E 1/8 - 1/4 (0.170 mi.)***	***Y235***	***62***
CONSOLIDATED EDISON EPA ID: NYP004047791	V5491-633 SACKETT ST	NNE 1/8 - 1/4 (0.175 mi.)	T241	64
JORDAN MALACHIE CLEA EPA ID: NYR000087486	***295 5TH AVE***	***SE 1/8 - 1/4 (0.175 mi.)***	***U242***	***64***
JET FRENCH CLEANERS EPA ID: NYR000016402	***279 5TH AVE***	***SE 1/8 - 1/4 (0.177 mi.)***	***U244***	***65***
CON EDISON EPA ID: NYP004783759	354 3RD ST	SSE 1/8 - 1/4 (0.180 mi.)	AA248	66
BROOKLYN IGNITION & EPA ID: NY0000228106	***370 4TH AVE***	***SSW 1/8 - 1/4 (0.183 mi.)***	***Z253***	***67***
CON EDISON	688 SACKET ST	NE 1/8 - 1/4 (0.185 mi.)	AB254	67

EPA ID: NYP004704458				
CON EDISON EPA ID: NYP004707279 EPA ID: NYP004632907	688 SACKETT ST	NE 1/8 - 1/4 (0.185 mi.)	AB255	67
CON EDISON EPA ID: NYP004669222	688 SACKETT ST	NE 1/8 - 1/4 (0.185 mi.)	AB256	68
SUSAN MAINTENANCE EPA ID: NYR000076091	***374 4TH AVE***	***SSW 1/8 - 1/4 (0.187 mi.)***	***Z259***	***68***
CON EDISON EPA ID: NYP004592192	318 1 ST	SE 1/8 - 1/4 (0.191 mi.)	U262	69
SEMPLE RIEGER CO EPA ID: NYD986891885	***635 SACKETT ST***	***NNE 1/8 - 1/4 (0.194 mi.)***	***X264***	***69***
CON ED EPA ID: NYP004825176	365 2ND ST	SE 1/8 - 1/4 (0.195 mi.)	U268	71
CON EDISON SERVICE B EPA ID: NYP004307930	***209 5TH ST OPPOSITE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***Z270***	***71***
CON EDISON EPA ID: NYP004731998	335 1ST ST	ESE 1/8 - 1/4 (0.207 mi.)	U280	73
CON EDISON SERVICE B EPA ID: NYP004330726	***674 PRESIDENT ST***	***E 1/8 - 1/4 (0.212 mi.)***	***Y304***	***79***
CON EDISON EPA ID: NYP004592226	386 2ND ST	SE 1/8 - 1/4 (0.213 mi.)	AI305	80
CON EDISON EPA ID: NYP004738498	676 PRESIDENT ST	E 1/8 - 1/4 (0.216 mi.)	AJ313	81
CON EDISON SERVICE B EPA ID: NYP004349585	***726 SACKETT ST***	***ENE 1/8 - 1/4 (0.217 mi.)***	***AL317***	***82***
CON EDISON EPA ID: NYP004738811	675 PRESIDENT ST	E 1/8 - 1/4 (0.223 mi.)	AJ320	83
CON EDISON EPA ID: NYP004856769 EPA ID: NYP004781910	664 DEGRAW ST	NE 1/8 - 1/4 (0.226 mi.)	AN328	85
CON EDISON EPA ID: NYP004570321	298 5TH ST	S 1/8 - 1/4 (0.227 mi.)	AO335	87
CON EDISON SERVICE B EPA ID: NYP004337168	***315 4TH ST S***	***SSE 1/8 - 1/4 (0.229 mi.)***	***AA338***	***87***
CON EDISON EPA ID: NYP004760401	391 2ND ST	SE 1/8 - 1/4 (0.238 mi.)	AI342	89
CON EDISON EPA ID: NYP004363230	314 5TH ST	S 1/8 - 1/4 (0.239 mi.)	AK346	90
AMOCO SERVICE STATIO EPA ID: NYD986933109	***375-381 4TH AVE & 6T***	***SSW 1/8 - 1/4 (0.239 mi.)***	***AP348***	***90***
CON EDISON SERVICE B EPA ID: NYP004326278	***195 5TH AVE FRONT OF***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AL352***	***91***
U-HAUL CORP EPA ID: NY0000970509	***259 6TH ST - PARK SL***	***SSW 1/8 - 1/4 (0.243 mi.)***	***AP355***	***92***
CON EDISON MANHOLE: EPA ID: NYP004322004	***267 6TH ST***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AO358***	***93***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON	222 FIRST STREET	W 0 - 1/8 (0.027 mi.)	A25	14

EPA ID: NYD000706218				
CON EDISON EPA ID: NYP004704946	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A26	14
CONSOLIDATED EDISON EPA ID: NYP000920355	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A36	16
CONSOLIDATED EDISON EPA ID: NYP000706218	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A39	17
CON EDISON EPA ID: NYP004703534	222 FIRST ST	W 0 - 1/8 (0.027 mi.)	A54	22
CON EDISON TM439 EPA ID: NYP004036729	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A55***	***22***
CON ED EPA ID: NYP004851131	222 1 ST	W 0 - 1/8 (0.027 mi.)	A59	23
CON EDISON EPA ID: NYP004704771	222 1ST ST	W 0 - 1/8 (0.027 mi.)	A60	23
CON EDISON EPA ID: NYP004772869	221 1ST	WNW 0 - 1/8 (0.027 mi.)	A75	26
CON EDISON EPA ID: NYP004837696	***221 1ST ST***	***WNW 0 - 1/8 (0.027 mi.)***	***A76***	***27***
PS 418 K SCHOOL EPA ID: NYR000199968	***512 CARROLL ST***	***N 0 - 1/8 (0.038 mi.)***	***C94***	***30***
CON EDISON EPA ID: NYP004757548	511 CARROLL ST	N 0 - 1/8 (0.058 mi.)	C117	36
CON EDISON EPA ID: NYP004706313	319 3 AVE	WNW 0 - 1/8 (0.078 mi.)	F140	40
CONSOLIDATED EDISON EPA ID: NYP004155701	3RD AVE & 1ST STREET	WNW 0 - 1/8 (0.095 mi.)	F161	45
CON EDISON EPA ID: NYP004325122	318 3RD AVE FRONT OF	WNW 0 - 1/8 (0.104 mi.)	F170	47
CON EDISON - SERVICE EPA ID: NYP005136561	302 3RD AVE	NW 0 - 1/8 (0.108 mi.)	L173	48
CON EDISON EPA ID: NYP004974760	284 THIRD AVE	NNW 0 - 1/8 (0.121 mi.)	L185	50
CON EDISON EPA ID: NYP004959132	284 3RD AVE	NNW 0 - 1/8 (0.121 mi.)	L186	50
CON EDISON SERVICE B EPA ID: NYP004376315	***578 UNION ST***	***N 1/8 - 1/4 (0.137 mi.)***	***M194***	***52***
CON EDISON VAULT SUB EPA ID: NYP004476214	***213 3RD ST***	***W 1/8 - 1/4 (0.138 mi.)***	***N195***	***53***
CON EDISON EPA ID: NYP004743779	3RD ST & 3RD AVE	WSW 1/8 - 1/4 (0.140 mi.)	R199	54
CONSOLIDATED EDISON EPA ID: NYP004154290	3 AVE & 3 STREET & 6	WSW 1/8 - 1/4 (0.140 mi.)	R200	54
LINDA TOOL & DIE COR EPA ID: NYD987025822	***459 CARROLL ST***	***NW 1/8 - 1/4 (0.142 mi.)***	***L206***	***55***
CON EDISON	251 3RD AVE	N 1/8 - 1/4 (0.150 mi.)	S207	56

EPA ID: NYP004551230				
CON ED EPA ID: NYP004836340	617 UNION ST & 3RD A	N 1/8 - 1/4 (0.158 mi.)	M213	57
CON EDISON SERVICE B EPA ID: NYP004479192	***210 3RD ST***	***WSW 1/8 - 1/4 (0.159 mi.)***	***R215***	***57***
CON EDISON EPA ID: NYP004818912	451 CARROLL ST FRONT	NW 1/8 - 1/4 (0.162 mi.)	W223	60
CON EDISON EPA ID: NYP004795480	501 PRESIDENT ST	NNW 1/8 - 1/4 (0.166 mi.)	Q227	61
CON EDISON EPA ID: NYP004696415	450 CARROL ST	NW 1/8 - 1/4 (0.168 mi.)	W233	62
216 3RD STREET EPA ID: NYD001869049	***216 3RD ST***	***W 1/8 - 1/4 (0.172 mi.)***	***R236***	***62***
CON ED EPA ID: NYP004827627	443 CARROLL ST	NW 1/8 - 1/4 (0.172 mi.)	W237	63
190-220 THIRD STREET EPA ID: NYR000197178	***214 3RD ST***	***W 1/8 - 1/4 (0.173 mi.)***	***R240***	***64***
CON EDISON - SERVICE EPA ID: NYP005072996	484 PRESIDENT ST	NW 1/8 - 1/4 (0.182 mi.)	W252	67
CON EDISON SERVICE B EPA ID: NYP004479184	***198 3RD ST***	***W 1/8 - 1/4 (0.185 mi.)***	***AC257***	***68***
PIPPIN ENTERPRISES L EPA ID: NYD987023181	***220 3RD ST***	***WSW 1/8 - 1/4 (0.201 mi.)***	***AD273***	***72***
CON EDISON EPA ID: NYP005022769	232 3RD AVE	N 1/8 - 1/4 (0.205 mi.)	AF277	73
CON EDISON EPA ID: NYP004597928	227 3RD ST	W 1/8 - 1/4 (0.205 mi.)	AC278	73
CON EDISON MANHOLE: EPA ID: NYP004479242	***190 3RD ST FRONT OF***	***W 1/8 - 1/4 (0.208 mi.)***	***AC283***	***74***
CRUSADER CANDLE CO I EPA ID: NYD987005840	***325 NEVINS ST***	***NW 1/8 - 1/4 (0.208 mi.)***	***W286***	***75***
NYCDEP EPA ID: NYP010001790	SACKETT ST & 3RD AVE	N 1/8 - 1/4 (0.209 mi.)	AF289	76
473 PRESIDENT STREET EPA ID: NYR000232116	***473 PRESIDENT STREET***	***NNW 1/8 - 1/4 (0.210 mi.)***	***AG291***	***76***
BELL ATLANTIC-NY EPA ID: NYP000940593	SACKETT & 3 AVE MANH	N 1/8 - 1/4 (0.210 mi.)	AF293	77
CON ED EPA ID: NYP004822777	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH294	77
CON EDISON EPA ID: NYP004734786	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH295	77
CON EDISON EPA ID: NYP004698718	CARROLL ST AND NEVIN	NW 1/8 - 1/4 (0.210 mi.)	AH299	78
CON EDISON EPA ID: NYP004698700	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH301	79
VERIZON NEW YORK INC	***175 THIRD ST***	***W 1/8 - 1/4 (0.214 mi.)***	***AC307***	***80***

EPA ID: NYD987028008				
NEW YORK TELEPHONE C EPA ID: NYD987028016	***318 NEVINS ST***	***NW 1/8 - 1/4 (0.227 mi.)***	***AG332***	***86***
PARK SLOPE PAINT STR EPA ID: NYR000170472	***553 UNION ST***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AE345***	***89***
CON EDISON EPA ID: NYP004342978	408 CARROL ST	NW 1/8 - 1/4 (0.241 mi.)	AH350	91

NJ MANIFEST: A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 25 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004879932	255 4TH AVE	ENE 0 - 1/8 (0.039 mi.)	B99	32
CON EDISON EPA Id: NYP004757555	DENTON ST & CARROLL	NNE 0 - 1/8 (0.042 mi.)	C105	33
CON EDISON EPA Id: NYP004738910	22 GARFIELD ST	ESE 0 - 1/8 (0.066 mi.)	G125	37
CON EDISON EPA Id: NYP004743068	586 CARROL ST	E 0 - 1/8 (0.087 mi.)	G148	42
CON EDISON EPA Id: NYP004744306	590 CARROLL ST	E 0 - 1/8 (0.094 mi.)	G157	44
CON EDISON EPA Id: NYP004735734	577 CARROLL ST	E 0 - 1/8 (0.104 mi.)	K167	46
CON EDISON EPA Id: NYP004783759	354 3RD ST	SSE 1/8 - 1/4 (0.180 mi.)	AA250	66
SUSAN MAINTENANCE EPA Id: NYR000076091	***374 4TH AVE***	***SSW 1/8 - 1/4 (0.187 mi.)***	***Z259***	***68***
CON EDISON EPA Id: NYP004825176	365 2ND ST	SE 1/8 - 1/4 (0.195 mi.)	U267	70
CON EDISON EPA Id: NYP004731998	335 1ST ST	ESE 1/8 - 1/4 (0.207 mi.)	U279	73
CON EDISON EPA Id: NYP004738498	676 PRESIDENT ST	E 1/8 - 1/4 (0.216 mi.)	AJ314	82
CON EDISON EPA Id: NYP004738811	675 PRESIDENT ST	E 1/8 - 1/4 (0.223 mi.)	AJ322	84
CON EDISON EPA Id: NYP004781910	664 DEGRAW ST	NE 1/8 - 1/4 (0.226 mi.)	AN326	84
CON EDISON EPA Id: NYP004760401	391 2ND ST	SE 1/8 - 1/4 (0.238 mi.)	AI344	89

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - 3RD AVE EPA Id: NYD000706218	***222 1ST ST***	***W 0 - 1/8 (0.027 mi.)***	***A33***	***16***
CON EDISON	511 CARROLL ST	N 0 - 1/8 (0.058 mi.)	C119	36

EPA Id: NYP004757548				
CON EDISON EPA Id: NYP004743779	3RD ST & 3RD AVE	WSW 1/8 - 1/4 (0.140 mi.)	R196	53
CON EDISON EPA Id: NYP004818912	451 CARROLL ST FRONT	NW 1/8 - 1/4 (0.162 mi.)	W225	60
CON EDISON EPA Id: NYP004795480	501 PRESIDENT ST	NNW 1/8 - 1/4 (0.166 mi.)	Q229	61
190-220 THIRD STREET EPA Id: NYR000197178	214 3RD ST	W 1/8 - 1/4 (0.173 mi.)	R239	63
CRUSADER CANDLE CO I EPA Id: NYD987005840	325 NEVINS ST	NW 1/8 - 1/4 (0.208 mi.)	W284	74
CON EDISON EPA Id: NYP004841512	SACKETT ST & 3RD AVE	N 1/8 - 1/4 (0.209 mi.)	AF288	76
CON EDISON - TRANSFO EPA Id: NYP004734786	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH296	77
CON EDISON EPA Id: NYP004822777	CARROLL ST & NEVINS	NW 1/8 - 1/4 (0.210 mi.)	AH300	78
PARK SLOPE PAINT STR EPA Id: NYR000170472	***553 UNION ST***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AE345***	***89***

PA MANIFEST: A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 4 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
275 4TH AVENUE INVES Generator EPA Id: NYD986914133	275 4TH AVENUE	ESE 0 - 1/8 (0.026 mi.)	A18	12
CON EDISON Generator EPA Id: NYP005107804	237 4TH AVE	NE 0 - 1/8 (0.078 mi.)	H141	41
CON EDISON Generator EPA Id: NYP005107812	226 4TH AVE	NE 0 - 1/8 (0.122 mi.)	O187	51

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - UNION S Generator EPA Id: NYP004836340	617 UNION STREET	N 1/8 - 1/4 (0.158 mi.)	M214	57

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: A review of the EDR MGP list, as provided by EDR, has revealed that there are 5 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FULTON MUNICIPAL WOR	NEVINS, DEGRAW AND S	NNW 1/4 - 1/2 (0.290 mi.)	AQ373	96
FULTON WORKS	DEGRAW STREET AND NE	N 1/4 - 1/2 (0.317 mi.)	AV381	98
BU-METROPOLITAN MGP	124-136 SECOND AVE	WSW 1/2 - 1 (0.539 mi.)	BI440	112
FORMER CITIZEN GAS W	5TH STREET AND SMITH	W 1/2 - 1 (0.563 mi.)	441	112
USPS GOWANUS SITE. F	2ND AVENUE AND 12TH	WSW 1/2 - 1 (0.638 mi.)	443	113

EDR Hist Auto: A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DIANA FUEL CORP	275 4TH AVE	ESE 0 - 1/8 (0.026 mi.)	A17	12
RIDGE AUTO TRANSMISS	270 4TH AVE	NE 0 - 1/8 (0.031 mi.)	B88	29
PARKSIDE SERVICE STA	340 FOURTH AVE	SSW 0 - 1/8 (0.119 mi.)	P184	50

EDR Hist Cleaner: A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
B M T STOP DRY CLEAN	230 4TH AVE STE B	NE 0 - 1/8 (0.111 mi.)	O179	49

Count: 12 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S121986656	25 ST & 4TH AVENUE	25 ST & 4TH AVENUE		NY Spills
BROOKLYN	S105003695	USPS GOWANUS SITE, FORMER MGP METR	2ND AVENUE AND 12TH STREET	11215	NY VCP
BROOKLYN	S113917066	BROOKLYN MILITARY OCEAN TERMINAL	2ND AVE BTWN 57TH, 65TH STREET	11232	NY SHWS
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S113922111	455 SMITH STREET (VICHAR, INC.)	5TH STREET & SMITH STREET TO G	11231	NY VCP
BROOKLYN	S126022764	CONEY ISLAND, STILLWELL AND NEPTUN	BOUNDED BY STILLWELL AVE, NEPT		NY SWF/LF
BROOKLYN	S126023554	PAERDEGAT BASIN NORTH	BOUNDED PAERDEGAT BASIN, SEAVI		NY SWF/LF
BROOKLYN	1003864070	CARROL GARDEN	CORNER OF 5TH AND SMITH STREET	11231	SEMS-ARCHIVE
BROOKLYN	S113922123	FULTON MUNICIPAL WORKS	NEVINS, DEGRAW & SACKETT STS.	11201	NY VCP
BROOKLYN	S105972442	HAMILTON AVENUE PIERS/19TH & 18TH	REAR OF 566 HAMILTON AVENUE	11232	NY SHWS
BROOKLYN	S113922162	DANGMAN PARK	SHEEPSHEAD BAY ROAD & WEST 5TH	11215	NY VCP
BROOKLYN	S117535331	BASEMENT	925 UNION ST		NY LTANKS

OVERVIEW MAP - 07124126.2R



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	296 4th Avenue	CLIENT:	Haley & Aldrich, Inc.
ADDRESS:	296 4th Avenue Brooklyn NY 11215	CONTACT:	Sarah Commisso
		INQUIRY #:	07124126.2r
LAT/LONG:	40.675577 / 73.985041	DATE:	September 20, 2022 5:23 pm

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 07124126.2R



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 296 4th Avenue ADDRESS: 296 4th Avenue Brooklyn NY 11215 LAT/LONG: 40.675577 / 73.985041	CLIENT: Haley & Aldrich, Inc. CONTACT: Sarah Commisso INQUIRY #: 07124126.2r DATE: September 20, 2022 5:24 pm

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	1	0	0	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	1	0	NR	NR	1
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	3	NR	NR	3
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	1	1	NR	2
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		6	8	NR	NR	NR	14
RCRA-SQG	0.250		1	4	NR	NR	NR	5
RCRA-VSQG	0.250		0	4	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	1	0	NR	NR	1
US INST CONTROLS	0.500		0	1	0	NR	NR	1
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	0	2	5	NR	7
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		2	2	10	NR	NR	14
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		1	11	30	NR	NR	42
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		5	14	NR	NR	NR	19
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	1	NR	NR	1
NY MOSF	0.500		0	0	1	NR	NR	1
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		6	17	NR	NR	NR	23
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		1	1	NR	NR	NR	2
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	1	3	NR	NR	4
NY INST CONTROL	0.500		0	1	4	NR	NR	5
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		4	2	7	NR	NR	13
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		2	11	12	NR	NR	25
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	3	NR	NR	3
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	2	NR	2
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		75	NR	NR	NR	NR	75
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	21	52	NR	NR	NR	74
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	1	0	0	NR	1
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	1	NR	NR	NR	NR	NR	1
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	2	NR	NR	NR	NR	NR	2
DOCKET HWC	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UXO	1.000		0	0	0	0	NR	0
ECHO	TP	2	NR	NR	NR	NR	NR	2
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	3	NR	NR	NR	3
NY E DESIGNATION	0.125		18	NR	NR	NR	NR	18
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	1	NR	NR	1
NY MANIFEST	0.250	1	37	69	NR	NR	NR	107
NJ MANIFEST	0.250		8	17	NR	NR	NR	25
PA MANIFEST	0.250		3	1	NR	NR	NR	4
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	2	3	NR	5
EDR Hist Auto	0.125	1	3	NR	NR	NR	NR	4
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		8	194	224	80	11	0	517

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

MAACO AUTO PAINTING -296 4TH AVE
296 4TH AVE.
BROOKLYN, NY 11215

US AIRS
FINDS
ECHO

1006042115
N/A

Actual:
23 ft.

Click here for full text details

US AIRS
EPA plant ID: 110001593339

FINDS
Registry ID: 110001593339

ECHO
Registry ID 110001593339

A2
Target
Property

JEN JAY TRANSMISSION INC
296 4TH AVE
BROOKLYN, NY 11215

EDR Hist Auto

1022021870
N/A

Actual:
23 ft.

Click here for full text details

A3
Target
Property

MAACO AUTO PAINTING & BODYWORKS INC
296 4TH AVE & 1ST ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1000457406
NYD986925642

Actual:
23 ft.

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD986925642

FINDS
Registry ID: 110008043900

ECHO
Registry ID 110008043900

NY MANIFEST
EPA ID NYD986925642

NPL
Region
WSW
1/8-1/4
1037 ft.

GOWANUS CANAL
BUTLER ST (BETWEEN BOND ST AND NEVINS ST
BROOKLYN, NY 11231

Click here for full text details

NPL 1010782149
SEMS NYN000206222
US ENG CONTROLS
US INST CONTROLS
ROD
PRP
ICIS
FINDS
ECHO

NPL
Cerclis ID: 206222
EPA Id NYN000206222

SEMS
Site ID 0206222
EPA Id NYN000206222

US ENG CONTROLS
EPA ID: NYN000206222
EPA ID: NYN000206222

US INST CONTROLS
EPA ID: NYN000206222

ROD
EPA ID: NYN000206222

ICIS
FRS ID: 110033604197

FINDS
Registry ID: 110033604197

ECHO
Registry ID 110033604197

A4

< 1/8
1 ft.

Relative:
Higher

CON EDISON
292 4TH AV
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004655908

NY MANIFEST S117318093
N/A

A5
< 1/8
1 ft.

Relative: Higher

CON EDISON | **NY MANIFEST** | **S117314471**
292 4TH AV | **N/A**
BROOKLYN, NY 11201

Click here for full text details

NY MANIFEST
EPA ID NYP004615274

A6
WNW
< 1/8
0.008 mi.
40 ft.

Relative: Lower

MC DONALD'S | **NY Spills** | **S107658364**
245 1ST STREET | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY Spills
Spill Number/Closed Date 0551768 / 2013-10-07
Site ID 361253
Spill Date 2006-02-01

A7
SSE
< 1/8
0.011 mi.
60 ft.

Relative: Higher

STREET | **NY Spills** | **S106698101**
1ST STREET/4TH AVE | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0404988 / 2004-08-06
Site ID 276456
Spill Date 2004-08-06

A8
SSE
< 1/8
0.018 mi.
93 ft.

Relative: Higher

3RD AVE YARD | **NY Spills** | **S104653291**
1ST ST & 4TH AVE | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0002643 / 2001-09-25
Site ID 155576
Spill Date 2000-06-02

A9
ENE
< 1/8
0.019 mi.
99 ft.

Relative: Higher

MTA NYCT - 4TH AVE GARFIELD PL | **RCRA-SQG** | **1026834088**
276 4TH AVE | **NYR000250654**
BROOKLYN, NY 11215

Click here for full text details

RCRA-SQG
EPA Id NYR000250654

B10
ENE
< 1/8
0.020 mi.
105 ft.

Relative:
Higher

4TH AVE/GARFIELD ST
4TH AVE/GARFIELD ST
BROOKLYN, NY

NY Spills **S103483429**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 8404005 / 2020-04-29
Site ID 192509
Spill Date 1984-12-17

A11
NE
< 1/8
0.023 mi.
122 ft.

Relative:
Higher

272 4TH AVENUE
272 4TH AVENUE
BROOKLYN, NY 11215

NY BROWNFIELDS **S125465242**
NY Spills **N/A**

Click here for full text details

NY BROWNFIELDS
Site Code 590723

NY Spills
Spill Number/Closed Date 2005727 / Not Reported
Site ID 611527
Spill Date 2020-09-23

A12
East
< 1/8
0.023 mi.
123 ft.

Relative:
Higher

CONSTRUCTION SITE
267 FOURTH AVENUE IN BROOKLYN
BROOKLYN, NY

NY Spills **S110242972**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0912838 / 2010-03-11
Site ID 425747
Spill Date 2010-03-10

A13
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

275 FOURTH AVENUE DEV
275 4TH AVE
BROOKLYN, NY 11215

RCRA-LQG **1000446339**
NYD986914133

Click here for full text details

RCRA-LQG
EPA Id NYD986914133

A14
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

NORTH PETROLEUM CORP
275 FOURTH AVE
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-241849

NY UST **U003074454**
NY AST **N/A**

A15
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

275 4TH AVE INVESTORS LLC
275 4TH AVE
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYD986914133

NY MANIFEST **S119071837**
N/A

A16
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

275 4TH AVENUE
275 4TH AVENUE
NEW YORK CITY, NY

Click here for full text details

NY VCP **S118943374**
N/A

A17
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

DIANA FUEL CORP
275 4TH AVE
BROOKLYN, NY 11215

Click here for full text details

EDR Hist Auto **1021708330**
N/A

A18
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

275 4TH AVENUE INVESTORS LLC
275 4TH AVENUE
BROOKLYN, NY 11215

Click here for full text details

PA MANIFEST
Generator EPA Id NYD986914133

PA MANIFEST **S118888463**
N/A

A19
ESE
< 1/8
0.026 mi.
138 ft.

Relative:
Higher

LOT 1,TAXBLOCK 964
275 4 AVENUE
BROOKLYN, NY

Click here for full text details

NY E DESIGNATION

S109318007
N/A

A20
ESE
< 1/8
0.026 mi.
139 ft.

Relative:
Higher

269-271 4TH AVENUE
271 4TH AVENUE
NEW YORK CITY, NY

Click here for full text details

NY VCP

S125316959
N/A

A21
ESE
< 1/8
0.026 mi.
139 ft.

Relative:
Higher

LOT 6,TAXBLOCK 964
271 4 AVENUE
BROOKLYN, NY

Click here for full text details

NY E DESIGNATION

S108075323
N/A

A22
ESE
< 1/8
0.026 mi.
139 ft.

Relative:
Higher

FORMER GAS STATION
269-271 4TH AVE
BROOKLYN, NY

Click here for full text details

NY Spills

NY Spills
Spill Number/Closed Date 0501021 / 2006-02-20
Site ID 344148
Spill Date 2005-04-25

NY Spills

S106868437
N/A

A23
ESE
< 1/8
0.026 mi.
139 ft.

Relative:
Higher

LOT 7,TAXBLOCK 964
269 4 AVENUE
BROOKLYN, NY 11215

Click here for full text details

NY E DESIGNATION

S108075331
N/A

A24
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

YARD — **NY Spills** — **S111159555**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1105298 / 2011-10-28
Site ID 452947
Spill Date 2011-07-21

A25
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CONSOLIDATED EDISON — **NY MANIFEST** — **S120957304**
222 FIRST STREET — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYD000706218

A26
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON — **NY MANIFEST** — **S117058154**
222 FIRST ST — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004704946

A27
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON VEHICLE 6077 HYDRAULIC SPILL — **NY Spills** — **S121982275**
222 1ST ST — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1110967 / 2012-01-17
Site ID 458834
Spill Date 2011-12-09

A28
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVE YARD - SERVICE CENTER — **NY Spills** — **S121987815**
222 1ST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9808009 / 2017-06-08
Site ID 299103
Spill Date 1998-09-30

A29
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S121979436**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0110159 / 2003-05-01
Site ID 263575
Spill Date 2002-01-22

A30
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON
222 FIRST STREET
BROOKLYN, NY

NY Spills **S102238222**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9510404 / 1995-11-20
Site ID 299101
Spill Date 1995-11-16

A31
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S121980136**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0408750 / 2005-01-06
Site ID 333489
Spill Date 2004-11-08

A32
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

SERVICE BOX 3RD AVE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S104195828**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9907981 / 2002-01-30
Site ID 299104
Spill Date 1999-09-30

A33
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON - 3RD AVE | **RCRA-LQG** | **1000111635**
222 1ST ST | **NJ MANIFEST** | **NYD000706218**
BROOKLYN, NY 11215

Click here for full text details

RCRA-LQG
EPA Id NYD000706218

NJ MANIFEST
EPA Id NYD000706218

A34
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED 3RD AVE STATION | **NY Spills** | **S118638446**
222 1ST ST | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1601300 / 2017-03-28
Site ID 526616
Spill Date 2016-05-09

A35
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

COOLANT RELEASE FROM VEH 41130 | **NY Spills** | **S108635888**
222 1 STREET (THIRD AVE YARD) | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0700220 / 2007-05-23
Site ID 379559
Spill Date 2007-04-07

A36
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CONSOLIDATED EDISON | **NY MANIFEST** | **S105058470**
222 1ST ST | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP000920355

A37
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED THIRD AVE YARD — **NY Spills** — **S111159788**
222 FIRST ST — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1105608 / 2011-10-04
Spill Number/Closed Date 2104705 / 2021-10-04
Site ID 453268
Site ID 623525
Spill Date 2011-08-17
Spill Date 2021-08-18

A38
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON-ED THIRD AVE YARD — **NY Spills** — **S111319109**
222 FIRST ST — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1110305 / 2012-01-17
Site ID 458118
Spill Date 2011-11-18

A39
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CONSOLIDATED EDISON — **NY MANIFEST** — **S120957666**
222 FIRST ST — **N/A**
BROOKLYN, NY

Click here for full text details

NY MANIFEST
EPA ID NYP000706218

A40
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED 3RD AV YARD — **NY Spills** — **S104510043**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9913132 / 2000-02-18
Site ID 263145
Spill Date 2000-02-18

A41
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED 3RD AV GARAGE — **NY Spills** — **S121987241**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9607770 / 1998-05-27
Site ID 276610
Spill Date 1996-09-20

A42
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED FACILITY — **NY Spills** — **S103575627**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9811783 / 2003-02-14
Site ID 263579
Spill Date 1998-12-18

A43
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

OIL LEAK FROM VEHICLE 23089 — **NY Spills** — **S107415965**
222 FIRST ST AT 3 AVE — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0508341 / 2005-11-25
Site ID 353906
Spill Date 2005-10-12

A44
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON 3RD AVE YARD — **NY Spills** — **S121987460**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9703946 / 2003-02-28
Site ID 299102
Spill Date 1997-07-01

A45
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED STATION — **NY Spills** — **S112226482**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1205717 / 2013-03-08
Site ID 468682
Spill Date 2012-09-08

A46
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVENUE YARD — **NY Spills** — **S103036950**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9714230 / 1998-05-13
Site ID 263578
Spill Date 1998-03-24

A47
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE YARD — **NY Spills** — **S121981441**
222 1ST ST — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0813445 / 2009-06-03
Site ID 411134
Spill Date 2009-03-13

A48
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE YARD — **NY Spills** — **S102239537**
222 FIRST STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0300475 / 2003-04-15
Spill Number/Closed Date 0410262 / 2005-04-22
Spill Number/Closed Date 1000131 / 2010-04-27
Spill Number/Closed Date 1000132 / 2010-04-22
Spill Number/Closed Date 0910207 / 2010-02-16
Spill Number/Closed Date 9912931 / 2002-02-27
Spill Number/Closed Date 0002672 / 2001-09-25
Spill Number/Closed Date 0012324 / 2001-02-16
Spill Number/Closed Date 0202384 / 2002-08-21
Spill Number/Closed Date 9812500 / 2002-10-17
Spill Number/Closed Date 9900006 / 1999-04-02
Site ID 299100
Site ID 335210

3RD AVE YARD (Continued) **S102239537**

Site ID 427053
Site ID 427054
Site ID 422955
Site ID 263144
Site ID 263127
Site ID 263129
Site ID 263130
Site ID 263142
Site ID 263143
Site ID 263137
Site ID 263138
Site ID 263139
Site ID 263131
Site ID 263132
Site ID 263133
Site ID 263135
Site ID 412674
Site ID 438742
Site ID 276611
Site ID 276612
Site ID 276607
Site ID 276608
Spill Date 2003-04-14
Spill Date 2004-12-15
Spill Date 2010-04-04
Spill Date 2009-12-15
Spill Date 2000-02-14
Spill Date 2000-06-02
Spill Date 2001-02-16
Spill Date 2002-06-05
Spill Date 1999-01-09
Spill Date 1999-04-01
Spill Date 1997-05-30
Spill Date 1997-06-11
Spill Date 1998-01-26
Spill Date 2003-01-14
Spill Date 1996-03-25
Spill Date 1996-03-26
Spill Date 1996-10-30
Spill Date 2009-04-20
Spill Date 2010-08-14
Spill Date 1997-07-22
Spill Date 1997-10-17
Spill Date 2002-06-04
Spill Date 1996-02-08

A49
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON - OTHER - SPECIFY 0000 **RCRA-LQG** **1019325713**
222 1 ST **NYP004851131**
BROOKLYN, NY 11217

Click here for full text details

RCRA-LQG
EPA Id NYP004851131

A50
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVE YARD
222 1ST ST
BROOKLYN, NY

NY Spills | **S121982344**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 1114458 / 2012-05-10
Site ID 462517
Spill Date 2012-03-29

A51
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3 QT ANTI-FREEZE FROM COMPRESSOR
222 FIRST ST. CON ED'S THIRD AVE YARD
BROOKLYN, NY

NY Spills | **S108982705**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0711576 / 2008-05-12
Site ID 393082
Spill Date 2008-02-02

A52
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE SERVICE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills | **S103274076**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9801450 / 2002-10-30
Site ID 263140
Spill Date 1998-05-03

A53
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE YARD
222 1ST ST
BROOKLYN, NY

NY Spills | **S121981322**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0807096 / 2008-11-17
Site ID 404414
Spill Date 2008-09-24

A54
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON | **NY MANIFEST** | **S121967251**
222 FIRST ST | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004703534

A55
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON TM439 | **RCRA NonGen / NLR** | **1007207059**
222 1ST ST | **NY MANIFEST** | **NYP004036729**
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004036729

NY MANIFEST
EPA ID NYP004036729

A56
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE YARD | **NY Spills** | **S121981973**
222 1ST ST | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1008213 / 2017-06-08
Site ID 441688
Spill Date 2010-11-05

A57
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE YARD CON ED | **NY Spills** | **S103274365**
222 FIRST STREET | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9801934 / 1998-06-12
Site ID 263141
Spill Date 1998-05-14

A58
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

222 1ST STREET | **NY Spills** | **S121986827**
222 FIRST STREET | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9415797 / 1998-02-13
Site ID 201957
Spill Date 1995-03-06

A59
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED | **NY MANIFEST** | **S120957800**
222 1 ST | **N/A**
BROOKLYN, NY 11217

Click here for full text details

NY MANIFEST
EPA ID NYP004851131

A60
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON | **NY MANIFEST** | **S117537870**
222 1ST ST | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004704771

A61
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVENUE YARD | **NY Spills** | **S121981812**
222 1ST STREET | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1000930 / 2010-05-21
Site ID 433623
Spill Date 2010-04-23

A62
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED | **NY Spills** | **S111159307**
222 FIRST ST | **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1104942 / 2011-09-07
Site ID 452560
Spill Date 2011-07-31

A63
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

222 FIRST STREET
222 FIRST STREET
BROOKLYN, NY

NY Spills **S121987519**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9706833 / 1997-09-10
Site ID 263577
Spill Date 1997-09-08

A64
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE FLUSH TRUCK
222 FIRST STREET
BROOKLYN, NY 11215

NY SWF/LF **S117269722**
N/A

Click here for full text details

A65
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AV YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S103272845**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0007860 / 2001-12-14
Spill Number/Closed Date 9614742 / 1997-03-25
Spill Number/Closed Date 9603338 / 1996-08-22
Site ID 263128
Site ID 263136
Site ID 276609
Spill Date 2000-10-04
Spill Date 1997-03-21
Spill Date 1996-06-10

A66
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3 AVE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S107522901**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0513083 / 2006-04-21
Site ID 359500
Spill Date 2006-02-13

A67
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

LEAK FROM VEHICLE IN CON ED 3 AVE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S107657920**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0514637 / 2006-06-14
Site ID 361408
Spill Date 2006-03-22

A68
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON EDISON GARAGE
222 FIRST STREET
BROOKLYN, NY

NY Spills **S107788598**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0602266 / 2006-10-05
Site ID 364698
Spill Date 2006-05-31

A69
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

VEHICLE 60722 LOST HYDRAULIC FLUID
222 FIRST STREET
BROOKLYN, NY

NY Spills **S107658059**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0514814 / 2008-01-10
Site ID 361624
Spill Date 2006-03-27

A70
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVENUE YARD
222 FIRST STREET
BROOKLYN, NY 11215

NY BROWNFIELDS **S120706183**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 533255

A71
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

THIRD AVENUE YARD
222 FIRST STREET
BROOKLYN, NY 11215

NY TANKS **U001832241**
NY Spills **N/A**

Click here for full text details

NY TANKS
Site Status Active
Facility Id 2-452726

THIRD AVENUE YARD (Continued) **U001832241**

NY Spills
Spill Number/Closed Date 0203307 / 2017-06-08
Site ID 263576
Spill Date 2002-06-27

A72
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

CON ED WORK / 3RD AVE YARD **NY Spills** **S113493631**
222 1ST ST **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1301088 / 2013-07-10
Site ID 481453
Spill Date 2013-05-02

A73
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

FLUSH PIT **NY Spills** **S103484823**
222 FIRST STREET **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9807969 / 2002-12-30
Site ID 276613
Spill Date 1998-09-27

A74
West
< 1/8
0.027 mi.
142 ft.

Relative:
Lower

3RD AVE YARD **NY Spills** **S121982062**
222 1ST ST **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 1012255 / 2011-03-22
Site ID 446173
Spill Date 2011-03-10

A75
WNW
< 1/8
0.027 mi.
143 ft.

Relative:
Lower

CON EDISON **NY MANIFEST** **S119074730**
221 1ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004772869

A76
WNW
< 1/8
0.027 mi.
143 ft.

Relative:
Lower

CON EDISON
221 1ST ST
BROOKLYN, NY 11215

NY Spills **S104509159**
NY MANIFEST **N/A**

Click here for full text details

NY Spills
Spill Number/Closed Date 9911979 / 2000-02-23
Site ID 177460
Spill Date 2000-01-17

NY MANIFEST
EPA ID NYP004837696

A77
WNW
< 1/8
0.027 mi.
143 ft.

Relative:
Lower

CON EDISON
221 1ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1019902363**
NYP004772869

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004772869

A78
WNW
< 1/8
0.027 mi.
143 ft.

Relative:
Lower

CON EDISON
221 1ST ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1019325559**
NYP004837696

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004837696

B79
NNE
< 1/8
0.027 mi.
145 ft.

Relative:
Higher

CON EDISON MANHOLE: 22624
540 CARROLL ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1017779168**
NYP004571485

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004571485

B80
NNE
< 1/8
0.027 mi.
145 ft.

Relative:
Higher

CON EDISON
540 CARROLL ST
BROOKLYN, NY 11215

NY MANIFEST **S117064648**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004571485

A81
West
< 1/8
0.028 mi.
149 ft.

Relative:
Lower

220 1ST STREET
220 1ST STREET
BROOKLYN, NY

NY Spills | **S103560397**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9207274 / 2008-09-19
Site ID 153446
Spill Date 1992-09-15

B82
East
< 1/8
0.031 mi.
164 ft.

Relative:
Higher

LOT 1,TAXBLOCK 961
261 4 AVENUE
BROOKLYN, NY 11215

NY E DESIGNATION | **S108469613**
N/A

Click here for full text details

A83
SW
< 1/8
0.031 mi.
164 ft.

Relative:
Lower

FIVE GALLONS OF OIL IN SOIL
222 1 STREET
BROOKLYN, NY

NY Spills | **S108058550**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0604245 / 2017-06-08
Spill Number/Closed Date 0512763 / 2006-04-12
Site ID 367178
Site ID 359135
Spill Date 2006-06-28
Spill Date 2006-02-03

A84
SW
< 1/8
0.031 mi.
164 ft.

Relative:
Lower

SIX GAL HYDRAULIC FLUID FROM VEH
222 FIRST STREET & 3 AVENUE
BROOKLYN, NY

NY Spills | **S108763880**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0705772 / 2007-11-08
Site ID 386143
Spill Date 2007-08-20

A85
SW
< 1/8
0.031 mi.
164 ft.

Relative:
Lower

VEHICLE 60677
THIRD AVE YARD
BROOKLYN, NY

NY Spills | **S107522699**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0512797 / 2006-04-12
Site ID 359174
Spill Date 2006-02-04

A86
SW
< 1/8
0.031 mi.
164 ft.

Relative:
Lower

222 1ST STREET
CON EDSION
KINGS (County), NY

NY Spills | **S102150009**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9501055 / 2004-07-16
Site ID 201439
Spill Date 1995-04-25

A87
SW
< 1/8
0.031 mi.
164 ft.

Relative:
Lower

HYDRAULIC OIL
3 AVE YARD NEW CONST SITE
BROOKLYN, NY

NY Spills | **S106970838**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0505767 / 2005-08-11
Site ID 350857
Spill Date 2005-08-10

B88
NE
< 1/8
0.031 mi.
166 ft.

Relative:
Higher

RIDGE AUTO TRANSMISSION
270 4TH AVE
BROOKLYN, NY 11215

EDR Hist Auto | **1020259439**
N/A

Click here for full text details

B89
NE
< 1/8
0.031 mi.
166 ft.

Relative:
Higher

AUTO BODY CONCEPTS DBA ABC
270 4TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR | **1001229433**
NYR000060392

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000060392

B90
ENE
< 1/8
0.034 mi.
180 ft.

Relative:
Higher

LOT 2,TAXBLOCK 961
259 4 AVENUE
BROOKLYN, NY 11215

Click here for full text details

NY E DESIGNATION **S108075299**
N/A

C91
NNE
< 1/8
0.036 mi.
192 ft.

Relative:
Higher

ROMAN CATHOLIC CHURCH OF OUR L
522 CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

NY UST **U001839551**
N/A

B92
East
< 1/8
0.037 mi.
194 ft.

Relative:
Higher

CON EDISON
9 GARFIELD ST
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004572756

NY MANIFEST **S117064771**
N/A

B93
East
< 1/8
0.037 mi.
194 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 17869
9 GARFIELD ST
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004572756

FINDS
Registry ID: 110063836014

RCRA NonGen / NLR **1017779286**
FINDS **NYP004572756**

C94
North
< 1/8
0.038 mi.
199 ft.

Relative:
Lower

PS 418 K SCHOOL
512 CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

RCRA-LQG
EPA Id NYR000199968

FINDS
Registry ID: 110055471760

ECHO

RCRA-LQG **1016144416**
FINDS **NYR000199968**
ECHO
NY MANIFEST

PS 418 K SCHOOL (Continued) **1016144416**

Registry ID 110055471760

NY MANIFEST
EPA ID NYR000199968

C95 **P.S. 372 (OUR LADY OF PEACE)-K** **NY Spills** **S106469867**
North **512 CARROLL STREET** **NY LEAD** **N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
199 ft.

Relative:
Lower

Click here for full text details

NY Spills
Spill Number/Closed Date 0402598 / 2021-10-20
Site ID 288471
Spill Date 2004-06-09

C96 **P.S. 372 (OUR LADY OF PEACE) K 834** **NY AST** **A100295716**
North **512 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.038 mi.
199 ft.

Relative:
Lower

Click here for full text details

NY AST
Facility Id 2-267562

C97 **P.S. 372 (OUR LADY OF PEACE) K 834** **NY UST** **U004272241**
North **512 CARROLL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.038 mi.
199 ft.

Relative:
Lower

Click here for full text details

B98 **CON EDISON** **RCRA NonGen / NLR** **1018280848**
NE **CARROLL ST & 4TH AVE** **FINDS** **NYP004757563**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.039 mi.
205 ft.

Relative:
Higher

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004757563

FINDS
Registry ID: 110067682564

ECHO
Registry ID 110067682564

B99
ENE
< 1/8
0.039 mi.
208 ft.

Relative:
Higher

CON EDISON
255 4TH AVE
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004879932

NJ MANIFEST **S120678185**
N/A

B100
ENE
< 1/8
0.039 mi.
208 ft.

Relative:
Higher

CON EDISON
255 4TH AVE
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004879932

RCRA NonGen / NLR **1019326040**
NYP004879932

B101
ENE
< 1/8
0.039 mi.
208 ft.

Relative:
Higher

CON ED
255 4TH AVE
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004879932

NY MANIFEST **S118563785**
N/A

B102
East
< 1/8
0.040 mi.
211 ft.

Relative:
Higher

LOT 69,TAXBLOCK 961
13 GARFIELD PLACE
BROOKLYN, NY 11215

Click here for full text details

NY E DESIGNATION **S117676530**
N/A

C103
NNE
< 1/8
0.042 mi.
220 ft.

Relative:
Higher

CON EDISON
DENTON ST & CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004757555

FINDS
Registry ID: 110067682555

ECHO
Registry ID 110067682555

RCRA NonGen / NLR **1018280847**
FINDS **NYP004757555**
ECHO

C104
NNE
< 1/8
0.042 mi.
220 ft.

Relative:
Higher

CON EDISON
DENTON ST & CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004757555

NY MANIFEST **S118088208**
N/A

C105
NNE
< 1/8
0.042 mi.
220 ft.

Relative:
Higher

CON EDISON
DENTON ST & CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004757555

NJ MANIFEST **S120669566**
N/A

B106
ESE
< 1/8
0.042 mi.
224 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 17869
12 GARFIELD PL
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP005172960

RCRA NonGen / NLR **1025504515**
NYP005172960

B107
ESE
< 1/8
0.046 mi.
242 ft.

Relative:
Higher

CON EDISON - SERVICE BOX 38701
255 1ST ST
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004977890

NY MANIFEST **S120958944**
N/A

B108
East
< 1/8
0.048 mi.
253 ft.

Relative:
Higher

LOT 67,TAXBLOCK 961
15 GARFIELD PLACE
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004980361

NY E DESIGNATION **S108075326**
NY MANIFEST **N/A**

Map ID / Direction / Distance / Elevation	Site	Database(s)	EDR ID Number / EPA ID Number
B109 **ENE** **< 1/8** **0.050 mi.** **266 ft.** **Relative: Higher**	**4TH AVE** **CARROLL ST & 4TH AVE** **BROOKLYN, NY** **Click here for full text details** **NY Spills** Spill Number/Closed Date 0004550 / 2001-10-19 Site ID 287775 Spill Date 2000-07-15	**NY Spills**	**S104787288** **N/A**
B110 **East** **< 1/8** **0.052 mi.** **275 ft.** **Relative: Higher**	**LOT 7,TAXBLOCK 961** **566 CARROLL STREET** **BROOKLYN, NY 11215** **Click here for full text details**	**NY E DESIGNATION**	**S122872802** **N/A**
B111 **East** **< 1/8** **0.052 mi.** **275 ft.** **Relative: Higher**	**566 CARROLL STREET** **566 CARROLL STREET** **NEW YORK CITY, NY** **Click here for full text details**	**NY VCP**	**S118943359** **N/A**
B112 **ENE** **< 1/8** **0.053 mi.** **278 ft.** **Relative: Higher**	**LOT 21,TAXBLOCK 352** **CARROLL STREET** **BROOKLYN, NY** **Click here for full text details**	**NY E DESIGNATION**	**S108075330** **N/A**
D113 **SSE** **< 1/8** **0.054 mi.** **284 ft.** **Relative: Higher**	**LOT 1,TAXBLOCK 969** **283 4 AVENUE** **BROOKLYN, NY** **Click here for full text details**	**NY E DESIGNATION**	**S108469614** **N/A**

E114
WSW
< 1/8
0.054 mi.
287 ft.

Relative:
Lower

3RD AVE YARD
3RD AVE YARD
BROOKLYN, NY

NY Spills **S102239110**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9702955 / 2003-02-28
Spill Number/Closed Date 1003520 / 2010-10-18
Spill Number/Closed Date 9514611 / 2003-01-31
Site ID 281782
Site ID 436752
Site ID 281779
Spill Date 1997-06-09
Spill Date 2010-06-29
Spill Date 1996-02-15

B115
ENE
< 1/8
0.056 mi.
298 ft.

Relative:
Higher

LOT 1,TAXBLOCK 958
253 4 AVENUE
BROOKLYN, NY 11215

NY E DESIGNATION **S108469612**
N/A

Click here for full text details

D116
South
< 1/8
0.057 mi.
299 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 868
100 4TH ST & 2ND AVE
NEW YORK, NY 10003

RCRA NonGen / NLR **1016968949**
FINDS **NYP004425880**
ECHO
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004425880

FINDS
Registry ID: 110064110260

ECHO
Registry ID 110064110260

NY MANIFEST
EPA ID NYP004425880

C117
North
< 1/8
0.058 mi.
306 ft.

Relative:
Lower

CON EDISON
511 CARROLL ST
BROOKLYN, NY 11215

NY MANIFEST | **S118088207**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004757548

C118
North
< 1/8
0.058 mi.
306 ft.

Relative:
Lower

CON EDISON
511 CARROLL ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO
1018280846
NYP004757548

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004757548

FINDS
Registry ID: 110067682546

ECHO
Registry ID 110067682546

C119
North
< 1/8
0.058 mi.
306 ft.

Relative:
Lower

CON EDISON
511 CARROLL ST
BROOKLYN, NY 11215

NJ MANIFEST | **S120669565**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004757548

B120
NE
< 1/8
0.059 mi.
312 ft.

Relative:
Higher

NYCDOT BRIDGE BIN 2243210
PRESIDENT ST BRG OVER FRANKLIN
BROOKLYN, NY 11225

RCRA NonGen / NLR | **1000911985**
NY0000375220

Click here for full text details

RCRA NonGen / NLR
EPA Id NY0000375220

B121
ENE
< 1/8
0.059 mi.
314 ft.

Relative:
Higher

LOT 2,TAXBLOCK 958
249 4 AVENUE
BROOKLYN, NY 11215

NY E DESIGNATION

S108469616
N/A

Click here for full text details

F122
WNW
< 1/8
0.060 mi.
316 ft.

Relative:
Lower

3RD AV YARD INFO STOREROO
M 222 1ST ST
BROOKLYN, NY

NY Spills

S105141525
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0105268 / 2001-08-15
Site ID 243216
Spill Date 2001-08-15

F123
NNW
< 1/8
0.061 mi.
322 ft.

Relative:
Lower

COMMERCIAL BUILDING
14 WHITWELL PLACE
BROOKLYN, NY

NY Spills

S108130792
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0606675 / 2009-03-17
Site ID 370045
Spill Date 2006-09-11

G124
ESE
< 1/8
0.066 mi.
347 ft.

Relative:
Higher

CON EDISON
22 GARFIELD ST
BROOKLYN, NY 11215

NY MANIFEST

S117740711
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004738910

G125
ESE
< 1/8
0.066 mi.
347 ft.

Relative:
Higher

CON EDISON
22 GARFIELD ST
BROOKLYN, NY 11215

NJ MANIFEST

S120667931
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004738910

G126
ESE
< 1/8
0.066 mi.
347 ft.

Relative:
Higher

CON EDISON
22 GARFIELD ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO

1018279093
NYP004738910

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004738910

FINDS
Registry ID: 110067685865

ECHO
Registry ID 110067685865

H127
ENE
< 1/8
0.066 mi.
349 ft.

Relative:
Higher

LOT 4,TAXBLOCK 958
245 4 AVENUE
BROOKLYN, NY 11215

NY E DESIGNATION

S108469617
N/A

Click here for full text details

H128
ENE
< 1/8
0.066 mi.
349 ft.

Relative:
Higher

L&B AUTO REPAIR CORP. II
245 4TH AVENUE
BROOKLYN, NY 11215

NY AST

A100183296
N/A

Click here for full text details

NY AST
Facility Id 2-606714

H129
ENE
< 1/8
0.066 mi.
349 ft.

Relative:
Higher

241 - 245 4TH AVENUE
245 4TH AVENUE
NEW YORK CITY, NY

NY VCP

S125316943
N/A

Click here for full text details

D130
South
< 1/8
0.068 mi.
360 ft.

Relative:
Higher

CON EDISON CO. OF NY INC. @ F/T FACILITY
3RD AVE (BET. 3RD & 4TH)
BROOKLYN, NY 11215

NY SWF/LF

S105841902
N/A

Click here for full text details

D131
South
< 1/8
0.072 mi.
380 ft.

Relative:
Higher

LOT 7504,TAXBLOCK 974
302 2 STREET
BROOKLYN, NY 11215

NY E DESIGNATION

S113453326
N/A

Click here for full text details

H132
ENE
< 1/8
0.073 mi.
384 ft.

Relative:
Higher

243 DEVELOPMENT LLC
243-245 4TH AVE
BROOKLYN, NY 11215

NY MANIFEST

S120959647
N/A

Click here for full text details

NY MANIFEST
EPA ID NYR000229906

H133
ENE
< 1/8
0.073 mi.
384 ft.

Relative:
Higher

LOT 5,TAXBLOCK 958
243 4 AVENUE
BROOKLYN, NY

NY E DESIGNATION

S108469618
N/A

Click here for full text details

H134
ENE
< 1/8
0.073 mi.
384 ft.

Relative:
Higher

245 4TH AVENUE LLC
243-245 4TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO

1019909619
NYR000229906

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000229906

FINDS
Registry ID: 110070122146

ECHO
Registry ID 110070122146

H135
ENE
< 1/8
0.073 mi.
386 ft.

Relative:
Higher

2 FAMILY HOUSE
557 CARROLL ST
BROOKLYN, NY 11215

NY AST

U003128902
N/A

Click here for full text details

NY AST
Facility Id 2-201928

I136
NNW
< 1/8
0.074 mi.
389 ft.

Relative:
Lower

505 CARROLL ST.
505 CARROLL STREET
BROOKLYN, NY 11215

NY AST **A100173503**
N/A

Click here for full text details

NY AST
Facility Id 2-602516

I137
NNW
< 1/8
0.074 mi.
389 ft.

Relative:
Lower

PROCIDA REALTY
505 CARROLL STREET
BROOKLYN, NY

NY Spills **S107782960**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0602894 / 2008-10-20
Site ID 365475
Spill Date 2006-06-15

E138
West
< 1/8
0.076 mi.
402 ft.

Relative:
Lower

THIRD AV YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S104652697**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0001798 / 2000-06-20
Site ID 276606
Spill Date 2000-05-11

E139
West
< 1/8
0.076 mi.
402 ft.

Relative:
Lower

FLUSHPIT 3RD AVE YARD
222 FIRST STREET
BROOKLYN, NY

NY Spills **S104880303**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0009168 / 2000-11-14
Site ID 263574
Spill Date 2000-11-08

F140
WNW
< 1/8
0.078 mi.
412 ft.

Relative:
Lower

CON EDISON
319 3 AVE
BROOKLYN, NY 11215

NY MANIFEST **S117738130**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004706313

H141
NE
< 1/8
0.078 mi.
413 ft.

Relative:
Higher

CON EDISON
237 4TH AVE
BROOKLYN, NY 11215

PA MANIFEST **S123093387**
N/A

Click here for full text details

PA MANIFEST
Generator EPA Id NYP005107804

H142
ENE
< 1/8
0.082 mi.
433 ft.

Relative:
Higher

LOT 7,TAXBLOCK 958
586 PRESIDENT STREET
BROOKLYN, NY 11215

NY E DESIGNATION **S108469620**
N/A

Click here for full text details

H143
ENE
< 1/8
0.082 mi.
433 ft.

Relative:
Higher

CON EDISON
586 PRESIDENT ST
BROOKLYN, NY 11237

NY MANIFEST **S117536659**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004691457

D144
South
< 1/8
0.083 mi.
438 ft.

Relative:
Higher

LOT 7502,TAXBLOCK 974
306 2 STREET
BROOKLYN, NY 11215

NY E DESIGNATION **S111073086**
N/A

Click here for full text details

G145
East
< 1/8
0.083 mi.
440 ft.

Relative:
Higher

CON EDISON
584 CARROLL ST
BROOKLYN, NY 11215

NY MANIFEST **S117741205**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004744215

G146
East
< 1/8
0.083 mi.
440 ft.

Relative:
Higher

CON EDISON
584 CARROLL ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO

1018279590
NYP004744215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004744215

FINDS
Registry ID: 110067693151

ECHO
Registry ID 110067693151

J147
South
< 1/8
0.084 mi.
445 ft.

Relative:
Higher

315 4TH AVE
315 4TH AVENUE
BROOKLYN, NY

NY Spills

S104648674
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9814678 / 1999-03-26
Site ID 186475
Spill Date 1999-03-09

G148
East
< 1/8
0.087 mi.
459 ft.

Relative:
Higher

CON EDISON
586 CARROL ST
BROOKLYN, NY 11215

NJ MANIFEST

S120668296
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004743068

G149
East
< 1/8
0.087 mi.
459 ft.

Relative:
Higher

CON EDISON
586 CARROL ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO

1018279483
NYP004743068

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004743068

FINDS
Registry ID: 110067691297

ECHO
Registry ID 110067691297

G150
East
< 1/8
0.087 mi.
459 ft.

Relative:
Higher

CON EDISON — **NY MANIFEST** — **S117741098**
586 CARROL ST — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004743068

I151
North
< 1/8
0.087 mi.
462 ft.

Relative:
Lower

540 PRESIDENT STREET — **NY LTANKS** — **S102672075**
540 PRESIDENT STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9211878 / 1993-01-18
Site ID 262667
Spill Date 1993-01-18

F152
WNW
< 1/8
0.090 mi.
475 ft.

Relative:
Lower

222 1ST ST — **NY Spills** — **S103275170**
3RD AVE YARD — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9803310 / 1998-08-06
Site ID 281783
Spill Date 1998-06-12

F153
WNW
< 1/8
0.090 mi.
475 ft.

Relative:
Lower

THIRD AVENUE YARD — **NY Spills** — **S102401870**
THIRD AVENUE & FIRST STRE — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9605550 / 1998-05-04
Site ID 73086
Spill Date 1996-07-30

F154
WNW
< 1/8
0.090 mi.
475 ft.

Relative:
Lower

3RD AVE YARD — **NY Spills** — **S102239113**
3RD AVE YARD — **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 9514614 / 2003-02-24
Spill Number/Closed Date 9702275 / 2003-02-25

3RD AVE YARD (Continued) **S102239113**

Site ID 281780
Site ID 281781
Spill Date 1996-02-15
Spill Date 1997-05-20

H155
ENE
< 1/8
0.093 mi.
490 ft.

Relative:
Higher

VAULT# TM0253 **NY Spills** **S106468549**
PRESIDENT ST & 4TH AVE **N/A**
BROOKLYN, NY

Click here for full text details

NY Spills
Spill Number/Closed Date 0400989 / 2004-07-20
Site ID 317096
Spill Date 2004-04-28

G156
East
< 1/8
0.094 mi.
497 ft.

Relative:
Higher

CON EDISON **NY MANIFEST** **S117741213**
590 CARROLL ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004744306

G157
East
< 1/8
0.094 mi.
497 ft.

Relative:
Higher

CON EDISON **NJ MANIFEST** **S120668406**
590 CARROLL ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004744306

G158
East
< 1/8
0.094 mi.
497 ft.

Relative:
Higher

CON EDISON **RCRA NonGen / NLR** **1018279598**
590 CARROLL ST **FINDS** **NYP004744306**
BROOKLYN, NY 11215 **ECHO**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004744306

FINDS
Registry ID: 110067693213

ECHO
Registry ID 110067693213

F159
WNW
< 1/8
0.095 mi.
501 ft.

Relative:
Lower

FEEDER LEAK
3RD AVE & 1ST STREET
BROOKLYN, NY

NY Spills **S123659108**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 1809345 / 2019-06-21
Site ID 580185
Spill Date 2018-12-05

F160
WNW
< 1/8
0.095 mi.
501 ft.

Relative:
Lower

3RD AVE SERVICE CENTER
3RD AVE & 1ST ST
BROOKLYN, NY

NY Spills **S103569896**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9608437 / 2004-09-02
Site ID 203791
Spill Date 1996-10-07

F161
WNW
< 1/8
0.095 mi.
501 ft.

Relative:
Lower

CONSOLIDATED EDISON
3RD AVE & 1ST STREET
BROOKLYN, NY 11201

NY MANIFEST **S119073028**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004155701

F162
WNW
< 1/8
0.095 mi.
502 ft.

Relative:
Lower

MANHOLE # 65435
3RD AVE/1ST STREET
BROOKLYN, NY

NY Spills **S106968362**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0502530 / 2005-08-17
Site ID 346909
Spill Date 2005-06-02

J163
South
< 1/8
0.099 mi.
521 ft.

Relative:
Higher

LOT 73,TAXBLOCK 974
303 3 STREET
BROOKLYN, NY 11215

NY E DESIGNATION **S108075334**
N/A

Click here for full text details

D164
SSE
< 1/8
0.102 mi.
537 ft.

Relative:
Higher

CON EDISON - SERVICE BOX 38850
328 2ND ST
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP005093950

NY MANIFEST **S121968216**
N/A

D165
SSE
< 1/8
0.102 mi.
537 ft.

Relative:
Higher

CON EDISON - SERVICE BOX 38850
328 2ND ST
BROOKLYN, NY 11215

Click here for full text details

RCRA-LQG
EPA Id NYP005093950

RCRA-LQG **1024891294**
NYP005093950

K166
East
< 1/8
0.104 mi.
548 ft.

Relative:
Higher

CON EDISON
577 CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004735734

NY MANIFEST **S117740407**
N/A

K167
East
< 1/8
0.104 mi.
548 ft.

Relative:
Higher

CON EDISON
577 CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004735734

NJ MANIFEST **S120667643**
N/A

K168
East
< 1/8
0.104 mi.
548 ft.

Relative:
Higher

CON EDISON
577 CARROLL ST
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004735734

FINDS
Registry ID: 110067681155

ECHO

RCRA NonGen / NLR **1018278791**
FINDS **NYP004735734**
ECHO

CON EDISON (Continued) **1018278791**

Registry ID 110067681155

I169
NNW
< 1/8
0.104 mi.
549 ft.

Relative:
Lower

L.L.L. AUTO REPAIR INC. **NY AST** **A100320260**
528 PRESIDENT STREET **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-610816

F170
WNW
< 1/8
0.104 mi.
550 ft.

Relative:
Lower

CON EDISON **NY MANIFEST** **1016960520**
318 3RD AVE FRONT OF **N/A**
BROOKLYN, NY 11217

Click here for full text details

NY MANIFEST
EPA ID NYP004325122

F171
NW
< 1/8
0.104 mi.
550 ft.

Relative:
Lower

FINEST AUTO & RECOVERY **RCRA NonGen / NLR** **1004761790**
310 3RD AVE **FINDS** **NYR000090431**
BROOKLYN, NY 11215 **ECHO**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000090431

FINDS
Registry ID: 110004564953

ECHO
Registry ID 110004564953

F172
WNW
< 1/8
0.107 mi.
566 ft.

Relative:
Lower

CLARIN TRUCK LEASING CORP **NY UST** **U001839158**
312 3RD AVE **N/A**
BROOKLYN, NY 11215

Click here for full text details

L173
NW
< 1/8
0.108 mi.
570 ft.

Relative:
Lower

CON EDISON - SERVICE BOX 38958
302 3RD AVE
BROOKLYN, NY 11215

NY MANIFEST | **S121968633**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP005136561

L174
NW
< 1/8
0.108 mi.
570 ft.

Relative:
Lower

CON EDISON - SERVICE BOX 38958
302 3RD AVE
BROOKLYN, NY 11215

RCRA-LQG | **1024891701**
NYP005136561

Click here for full text details

RCRA-LQG
EPA Id NYP005136561

J175
South
< 1/8
0.108 mi.
570 ft.

Relative:
Higher

MANHOLE 5436
4TH AVE/3RD ST
BROOKLYN, NY

NY Spills | **S106866703**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0412308 / 2005-02-18
Site ID 337753
Spill Date 2005-02-17

M176
North
< 1/8
0.109 mi.
573 ft.

Relative:
Lower

ABF FREIGHTS
545 PRESIDENT ST
BROOKLYN, NY

NY Spills | **S126998057**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 2006668 / 2020-10-22
Site ID 612520
Spill Date 2020-10-22

N177
West
< 1/8
0.109 mi.
573 ft.

Relative:
Lower

2ND & 3RD AVE
2ND & 3RD AVE
BROOKLYN, NY

NY Spills | **S104510741**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 9914001 / 2003-08-08
Site ID 126958
Spill Date 2000-03-11

N178
West
< 1/8
0.110 mi.
581 ft.

Relative:
Lower

MAN HOLE 5354
3RD AND AVE AND 2ND STREET
BROOKLYN, NY

NY Spills **S110540059**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 1006176 / 2010-09-24
Site ID 439522
Spill Date 2010-09-04

O179
NE
< 1/8
0.111 mi.
587 ft.

Relative:
Higher

B M T STOP DRY CLEANERS INC
230 4TH AVE STE B
BROOKLYN, NY 11215

EDR Hist Cleaner **1019933779**
N/A

Click here for full text details

J180
South
< 1/8
0.116 mi.
614 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 75190
260 3RD ST FRONT OF
BROOKLYN, NY 11215

RCRA NonGen / NLR **1016969308**
NY MANIFEST **NYP004429650**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004429650

NY MANIFEST
EPA ID NYP004429650

P181
SSW
< 1/8
0.119 mi.
630 ft.

Relative:
Higher

CONSTRUCTION SITE
340 4TH AVE
BROOKLYN, NY

NY Spills **S113818062**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 1302908 / 2013-06-17
Site ID 483360
Spill Date 2013-06-17

P182
SSW
< 1/8
0.119 mi.
630 ft.

Relative:
Higher

PARKSIDE SERVICE CENTER
340 4TH AVE
BROOKLYN, NY

NY Spills **S108762756**
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0704349 / 2014-03-28

PARKSIDE SERVICE CENTER (Continued) **S108762756**

Spill Number/Closed Date 8911553 / 1990-03-08
Spill Number/Closed Date 0801262 / 2008-05-01
Site ID 384480
Site ID 244057
Site ID 397156
Spill Date 2007-07-18
Spill Date 1990-03-07
Spill Date 2008-05-01

P183
SSW
< 1/8
0.119 mi.
630 ft.

Relative:
Higher

PARKSIDE SERVICE CENTER **NY UST** **U001839590**
340 4TH AVENUE **N/A**
BROOKLYN, NY 11215

Click here for full text details

P184
SSW
< 1/8
0.119 mi.
630 ft.

Relative:
Higher

PARKSIDE SERVICE STATION **EDR Hist Auto** **1020972743**
340 FOURTH AVE **N/A**
BROOKLYN, NY 11215

Click here for full text details

L185
NNW
< 1/8
0.121 mi.
641 ft.

Relative:
Lower

CON EDISON **NY MANIFEST** **S119078278**
284 THIRD AVE **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004974760

L186
NNW
< 1/8
0.121 mi.
641 ft.

Relative:
Lower

CON EDISON **NY MANIFEST** **S118954154**
284 3RD AVE **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004959132

O187
NE
< 1/8
0.122 mi.
645 ft.

Relative:
Higher

CON EDISON
226 4TH AVE
BROOKLYN, NY 11215

PA MANIFEST | **S123093388**
N/A

Click here for full text details

PA MANIFEST
Generator EPA Id NYP005107812

M188
NNE
1/8-1/4
0.126 mi.
667 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 43332
604 UNION ST
BROOKLYN, NY 11231

RCRA NonGen / NLR
NY MANIFEST | **1016961963**
NYP004349064

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004349064

NY MANIFEST
EPA ID NYP004349064

Q189
NNW
1/8-1/4
0.129 mi.
682 ft.

Relative:
Lower

276 3RD AVENUE
276 THIRD AVENUE
BROOKLYN, NY 11215

NY AST | **A100353041**
N/A

Click here for full text details

NY AST
Facility Id 2-608461

L190
NW
1/8-1/4
0.135 mi.
713 ft.

Relative:
Lower

JO-LEE TRUCKING
463 CARROLL ST
BROOKLYN, NY 11215

RCRA NonGen / NLR | **1008374454**
NYR000131938

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000131938

O191
NE
1/8-1/4
0.136 mi.
718 ft.

Relative:
Higher

NYCT - UNION STATION R LINE
UNION ST & 4TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR
NY MANIFEST | **1005905708**
NYR000107938

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000107938

NY MANIFEST

NYCT - UNION STATION R LINE (Continued) **1005905708**

EPA ID NYR000107938

M192
North
1/8-1/4
0.136 mi.
720 ft.

Relative:
Lower

KLOR-DE CLEANERS **NY DRYCLEANERS** **S110247069**
263 3RD AVENUE **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY DRYCLEANERS
Facility Id 2-6103-00151

O193
NE
1/8-1/4
0.137 mi.
723 ft.

Relative:
Higher

CON EDISON MANHOLE: 2618 **RCRA NonGen / NLR** **1016454185**
4TH & UNION AVE **FINDS** **NYP004318366**
BROOKLYN, NY 11215 **ECHO**
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004318366

FINDS
Registry ID: 110056509773

ECHO
Registry ID 110056509773

NY MANIFEST
EPA ID NYP004318366

M194
North
1/8-1/4
0.137 mi.
724 ft.

Relative:
Lower

CON EDISON SERVICE BOX: 43335 **RCRA NonGen / NLR** **1016964719**
578 UNION ST **NY MANIFEST** **NYP004376315**
BROOKLYN, NY 11231

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004376315

NY MANIFEST
EPA ID NYP004376315

N195
West
1/8-1/4
0.138 mi.
731 ft.

Relative:
Lower

CON EDISON VAULT SUBMERSIBLE: 5837
213 3RD ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1016973813**
NY MANIFEST **NYP004476214**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004476214

NY MANIFEST
EPA ID NYP004476214

R196
WSW
1/8-1/4
0.140 mi.
739 ft.

Relative:
Lower

CON EDISON
3RD ST & 3RD AVE
BROOKLYN, NY 11215

NJ MANIFEST **S120668359**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004743779

R197
WSW
1/8-1/4
0.140 mi.
739 ft.

Relative:
Lower

VERIZON LOG 31756 MANHOLE 325
3RD ST & 3RD AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1014917856**
NYP000962894

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP000962894

R198
WSW
1/8-1/4
0.140 mi.
739 ft.

Relative:
Lower

CON EDISON
3RD ST & 3RD AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1018279550**
FINDS **NYP004743779**
ECHO

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004743779

FINDS
Registry ID: 110067692777

ECHO
Registry ID 110067692777

R199
WSW
1/8-1/4
0.140 mi.
739 ft.

Relative:
Lower

CON EDISON — **NY MANIFEST** — **S117741161**
3RD ST & 3RD AVE — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004743779

R200
WSW
1/8-1/4
0.140 mi.
741 ft.

Relative:
Lower

CONSOLIDATED EDISON — **NY MANIFEST** — **S108933201**
3 AVE & 3 STREET & 6 STREET — **N/A**
NEW YORKBROOKLYN, NY 11201

Click here for full text details

NY MANIFEST
EPA ID NYP004154290

P201
SSW
1/8-1/4
0.142 mi.
748 ft.

Relative:
Higher

PEP BOYS #0247 — **NY AST** — **A100520470**
354 4TH AVENUE — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-032301

P202
SSW
1/8-1/4
0.142 mi.
748 ft.

Relative:
Higher

PEP BOYS #0247 — **NY UST** — **U001831292**
354 4TH AVENUE — **N/A**
BROOKLYN, NY 11215

Click here for full text details

P203
SSW
1/8-1/4
0.142 mi.
748 ft.

Relative:
Higher

PEP BOYS 247 — **RCRA NonGen / NLR** — **1004761053**
354 4TH AVE — **FINDS** — **NYR000071936**
BROOKLYN, NY 11215 — **ECHO**
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000071936

FINDS
Registry ID: 110004553395

ECHO
Registry ID 110004553395

PEP BOYS 247 (Continued) **1004761053**

NY MANIFEST
EPA ID NYR000071936

P204
SSW
1/8-1/4
0.142 mi.
748 ft.

Relative:
Higher

PEP BOYS #0247
354 4TH AVE
BROOKLYN, NY 11215

NY CBS **S108410815**
NY Spills **N/A**

Click here for full text details

NY CBS
Facility Status Unregulated/Closed
CBS Number 2-000417

NY Spills
Spill Number/Closed Date 9800967 / 2002-03-19
Site ID 72114
Spill Date 1998-04-22

P205
SSW
1/8-1/4
0.142 mi.
748 ft.

Relative:
Higher

PEP BOYS #0247
354 4TH AVE
BROOKLYN, NY 11215

NY AST **A100520437**
N/A

Click here for full text details

NY AST
Facility Id 2-000417

L206
NW
1/8-1/4
0.142 mi.
752 ft.

Relative:
Lower

LINDA TOOL & DIE CORP
459 CARROLL ST
BROOKLYN, NY 11215

RCRA-VSQG **1000791081**
FINDS **NYD987025822**
ECHO
NY MANIFEST

Click here for full text details

RCRA-VSQG
EPA Id NYD987025822

FINDS
Registry ID: 110004499766

ECHO
Registry ID 110004499766

NY MANIFEST
EPA ID NYD987025822

S207
North
1/8-1/4
0.150 mi.
794 ft.

Relative:
Lower

CON EDISON
251 3RD AVE
BROOKLYN, NY 11215

NY MANIFEST **S117062742**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004551230

S208
North
1/8-1/4
0.150 mi.
794 ft.

Relative:
Lower

CON EDISON EXCAVATION: TRENCH
251 3RD AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1017777232**
NYP004551230

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004551230

T209
NNE
1/8-1/4
0.151 mi.
795 ft.

Relative:
Lower

HOLYLAND AUTO REPAIR INC.
637 UNION STREET
BROOKLYN, NY 11217

NY AST **A100178067**
N/A

Click here for full text details

NY AST
Facility Id 2-605796

Q210
NNW
1/8-1/4
0.151 mi.
798 ft.

Relative:
Lower

RIDGE COMPLETE AUTO
264 THIRD AVENUE
BROOKLYN, NY 11215

NY AST **A100348969**
N/A

Click here for full text details

NY AST
Facility Id 2-611243

P211
SSW
1/8-1/4
0.153 mi.
807 ft.

Relative:
Higher

MAACO AUTO PAINTING & BODYWORKS INC
358 FOURTH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1000174861**
NY MANIFEST **NYD981488232**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD981488232

NY MANIFEST
EPA ID NYD981488232

P212
SSW
1/8-1/4
0.153 mi.
807 ft.

Relative:
Higher

CON EDISON - MANHOLE 5437
358 4TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1010325649**
NY MANIFEST **NYP004130670**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004130670

NY MANIFEST
EPA ID NYP004130670

M213
North
1/8-1/4
0.158 mi.
833 ft.

Relative:
Lower

CON ED
617 UNION ST & 3RD AVE
BROOKLYN, NY 11215

NY MANIFEST **S118259711**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004836340

M214
North
1/8-1/4
0.158 mi.
833 ft.

Relative:
Lower

CON EDISON - UNION STREET
617 UNION STREET
BROOKLYN, NY 11215

PA MANIFEST **S123092918**
N/A

Click here for full text details

PA MANIFEST
Generator EPA Id NYP004836340

R215
WSW
1/8-1/4
0.159 mi.
839 ft.

Relative:
Lower

CON EDISON SERVICE BOX: 45290
210 3RD ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1016974108**
NY MANIFEST **NYP004479192**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004479192

NY MANIFEST
EPA ID NYP004479192

U216
SE
1/8-1/4
0.160 mi.
847 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 34336
85-87 1ST AVE & 5TH ST N OF
NEW YORK, NY 10003

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004485942

FINDS
Registry ID: 110063790045

RCRA NonGen / NLR
FINDS

1017771653
NYP004485942

V217
ESE
1/8-1/4
0.161 mi.
849 ft.

Relative:
Higher

CON EDISON - TRANSFORMER MANHOLE 320
5TH AVE & GARFIELD PL
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004964548

NY MANIFEST

S120958786
N/A

O218
NNE
1/8-1/4
0.161 mi.
850 ft.

Relative:
Higher

204 4TH AVE LLC - BCP REDEVELOPMENT PROJECT
204 4TH AVE
BROOKLYN, NY 11217

Click here for full text details

RCRA-LQG
EPA Id NYR000255687

RCRA-LQG

1027222223
NYR000255687

O219
NNE
1/8-1/4
0.161 mi.
850 ft.

Relative:
Higher

SPEEDWAY # 7835
204-222 FOURTH AVENUE
BROOKLYN, NY 11217

Click here for full text details

NY UST

U001835738
N/A

O220
NNE
1/8-1/4
0.161 mi.
850 ft.

Relative:
Higher

HESS#32530
204-222 FOURTH AVE
BROOKLYN, NY 11217

Click here for full text details

RCRA-VSQG
EPA Id NYD982185563

US AIRS
EPA plant ID: 110001572628

RCRA-VSQG
US AIRS
FINDS
ECHO
NY MANIFEST

1000263763
NYD982185563

HESS#32530 (Continued) **1000263763**

FINDS
Registry ID: 110001572628

ECHO
Registry ID 110001572628

NY MANIFEST
EPA ID NYD982185563

O221 **MERRITT GAS STATION** **NY LTANKS** **S104276740**
NNE **204-222 4TH AVENUE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.161 mi.
850 ft.

Relative:
Higher

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9515732 / 1997-06-11
Site ID 204687
Spill Date 1996-03-07

NY Spills
Spill Number/Closed Date 0210654 / 2003-11-03
Spill Number/Closed Date 9605719 / Not Reported
Spill Number/Closed Date 0602980 / 2006-09-12
Site ID 74469
Site ID 74470
Site ID 365575
Spill Date 2003-01-23
Spill Date 1996-08-02
Spill Date 2006-06-17

O222 **204 4TH AVENUE** **NY BROWNFIELDS** **S125298840**
NNE **204 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.161 mi.
850 ft.

Relative:
Higher

Click here for full text details

NY BROWNFIELDS
Site Code 587854

W223
NW
1/8-1/4
0.162 mi.
853 ft.

Relative:
Lower

CON EDISON
451 CARROLL ST FRONT OF
BROOKLYN, NY 11225

NY MANIFEST **S119077023**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004818912

W224
NW
1/8-1/4
0.162 mi.
853 ft.

Relative:
Lower

CON EDISON
451 CARROLL ST FRONT OF
BROOKLYN, NY 11225

RCRA NonGen / NLR **1019906244**
NYP004818912

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004818912

W225
NW
1/8-1/4
0.162 mi.
853 ft.

Relative:
Lower

CON EDISON
451 CARROLL ST FRONT OF
BROOKLYN, NY 11225

NJ MANIFEST **S120675005**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004818912

S226
North
1/8-1/4
0.165 mi.
872 ft.

Relative:
Lower

CON EDISON
617 UNION ST & 3RD AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1019907638**
FINDS **NYP004836340**
ECHO

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004836340

FINDS
Registry ID: 110069704519

ECHO
Registry ID 110069704519

Q227
NNW
1/8-1/4
0.166 mi.
876 ft.

Relative:
Lower

CON EDISON | **NY MANIFEST** | **S118256981**
501 PRESIDENT ST | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004795480

Q228
NNW
1/8-1/4
0.166 mi.
876 ft.

Relative:
Lower

CON EDISON | **RCRA NonGen / NLR** | **1019904241**
501 PRESIDENT ST | **NYP004795480**
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004795480

Q229
NNW
1/8-1/4
0.166 mi.
876 ft.

Relative:
Lower

CON EDISON | **NJ MANIFEST** | **S120672898**
501 PRESIDENT ST | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004795480

X230
NE
1/8-1/4
0.167 mi.
880 ft.

Relative:
Higher

4TH & SACKETT STREET | **NY LTANKS** | **S105053980**
4TH & SACKETT STREET | **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9113310 / 1994-08-03
Site ID 221268
Spill Date 1992-03-31

S231
North
1/8-1/4
0.168 mi.
886 ft.

Relative:
Lower

SJ FUEL CO. INC. | **NY TANKS** | **U003396247**
601 UNION STREET | **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY TANKS
Site Status Active
Facility Id 2-601627

S232
North
1/8-1/4
0.168 mi.
886 ft.

Relative:
Lower

A 2 Z ENVIRONMENTAL LLC
601 UNION ST
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000187302

Database(s): RCRA NonGen / NLR
EDR ID Number: 1014926942
EPA ID Number: NYR000187302

W233
NW
1/8-1/4
0.168 mi.
888 ft.

Relative:
Lower

CON EDISON
450 CARROL ST
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004696415

Database(s): NY MANIFEST
EDR ID Number: S117537111
EPA ID Number: N/A

Y234
East
1/8-1/4
0.170 mi.
900 ft.

Relative:
Higher

RALPH'S CLEANERS
230 5TH AVE
BROOKLYN, NY 11215

Click here for full text details

NY DRYCLEANERS
Facility Id 2-6103-00246

Database(s): NY DRYCLEANERS
EDR ID Number: S128781715
EPA ID Number: N/A

Y235
East
1/8-1/4
0.170 mi.
900 ft.

Relative:
Higher

RALPHS CLEANERS
230 FIFTH AVE
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD986951069

NY MANIFEST
EPA ID NYD986951069

Database(s): RCRA NonGen / NLR, NY MANIFEST
EDR ID Number: 1000552701
EPA ID Number: NYD986951069

R236
West
1/8-1/4
0.172 mi.
910 ft.

Relative:
Lower

216 3RD STREET
216 3RD ST
BROOKLYN, NY 11211

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD001869049

FINDS

Database(s): RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST
EDR ID Number: 1000195630
EPA ID Number: NYD001869049

216 3RD STREET (Continued) **1000195630**

Registry ID: 110004336193

ECHO
Registry ID 110004336193

NY MANIFEST
EPA ID NYD001869049

W237
NW
1/8-1/4
0.172 mi.
910 ft.

Relative:
Lower

CON ED **NY MANIFEST** **S118259177**
443 CARROLL ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004827627

W238
NW
1/8-1/4
0.172 mi.
910 ft.

Relative:
Lower

CON EDISON **RCRA NonGen / NLR** **1019906853**
443 CARROLL ST **FINDS** **NYP004827267**
BROOKLYN, NY 11209 **ECHO**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004827267

FINDS
Registry ID: 110069675435

ECHO
Registry ID 110069675435

R239
West
1/8-1/4
0.173 mi.
916 ft.

Relative:
Lower

190-220 THIRD STREET STORE LLC **NJ MANIFEST** **S117987466**
214 3RD ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYR000197178

R240
West
1/8-1/4
0.173 mi.
916 ft.

Relative:
Lower

190-220 THIRD STREET STORE LLC
214 3RD ST
BROOKLYN, NY 11215

NY ENG CONTROLS
NY INST CONTROL
NY BROWNFIELDS
RCRA NonGen / NLR
NY MANIFEST

1015747246
NYR000197178

Click here for full text details

NY ENG CONTROLS
Site Code 333299

NY INST CONTROL
Site Code 333299

NY BROWNFIELDS
Site Code 333299

RCRA NonGen / NLR
EPA Id NYR000197178

NY MANIFEST
EPA ID NYR000197178

T241
NNE
1/8-1/4
0.175 mi.
923 ft.

Relative:
Higher

CONSOLIDATED EDISON
V5491-633 SACKETT ST
BROOKLYN, NY 11201

NY MANIFEST

1009238380
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004047791

U242
SE
1/8-1/4
0.175 mi.
925 ft.

Relative:
Higher

JORDAN MALACHIE CLEANERS
295 5TH AVE
BROOKLYN, NY 11215

RCRA-VSQG
FINDS
ECHO
NY MANIFEST

1004761499
NYR000087486

Click here for full text details

RCRA-VSQG
EPA Id NYR000087486

FINDS
Registry ID: 110004563071

ECHO
Registry ID 110004563071

NY MANIFEST
EPA ID NYR000087486

U243
SE
1/8-1/4
0.177 mi.
932 ft.

Relative:
Higher

MALACHI DRY CLNR
279 5TH AVENUE
BROOKLYN, NY 11215

NY DRYCLEANERS **S110247207**
N/A

Click here for full text details

NY DRYCLEANERS
Facility Id 2-6103-00538

U244
SE
1/8-1/4
0.177 mi.
932 ft.

Relative:
Higher

JET FRENCH CLEANERS
279 5TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1004759636**
NY MANIFEST **NYR000016402**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYR000016402

NY MANIFEST
EPA ID NYR000016402

Z245
SSW
1/8-1/4
0.179 mi.
943 ft.

Relative:
Higher

BRIDGE FORD
343 4TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1000106506**
FINDS **NYD982280091**
ECHO

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD982280091

FINDS
Registry ID: 110004419745

ECHO
Registry ID 110004419745

Z246
SSW
1/8-1/4
0.179 mi.
943 ft.

Relative:
Higher

343 4TH AVENUE
343 4TH AVENUE
BROOKLYN, NY 11215

NY UST **U004045443**
N/A

Click here for full text details

R247
West
1/8-1/4
0.180 mi.
950 ft.

Relative:
Lower

ALL BORO'S
200 3RD ST
BROOKLYN, NY

NY LTANKS | **S102618894**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9702117 / 1999-08-22
Site ID 253671
Spill Date 1997-05-19

AA248
SSE
1/8-1/4
0.180 mi.
950 ft.

Relative:
Higher

CON EDISON
354 3RD ST
BROOKLYN, NY 11215

NY MANIFEST | **S119075356**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004783759

AA249
SSE
1/8-1/4
0.180 mi.
950 ft.

Relative:
Higher

CON EDISON
354 3RD ST
BROOKLYN, NY 11215

RCRA NonGen / NLR | **1019903291**
NYP004783759

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004783759

AA250
SSE
1/8-1/4
0.180 mi.
950 ft.

Relative:
Higher

CON EDISON
354 3RD ST
BROOKLYN, NY 11215

NJ MANIFEST | **S120671879**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004783759

W251
NW
1/8-1/4
0.182 mi.
959 ft.

Relative:
Lower

CON EDISON - SERVICE BOX 31652
484 PRESIDENT ST
BROOKLYN, NY 11215

RCRA-LQG | **1024891092**
NYP005072996

Click here for full text details

RCRA-LQG
EPA Id NYP005072996

W252
NW
1/8-1/4
0.182 mi.
959 ft.

Relative:
Lower

CON EDISON - SERVICE BOX 31652
484 PRESIDENT ST
BROOKLYN, NY 11215

NY MANIFEST **S121968007**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP005072996

Z253
SSW
1/8-1/4
0.183 mi.
966 ft.

Relative:
Higher

BROOKLYN IGNITION & SUPPLY
370 4TH AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR **1000890011**
FINDS **NY0000228106**
ECHO
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NY0000228106

FINDS
Registry ID: 110004314037

ECHO
Registry ID 110004314037

NY MANIFEST
EPA ID NY0000228106

AB254
NE
1/8-1/4
0.185 mi.
975 ft.

Relative:
Higher

CON EDISON
688 SACKET ST
BROOKLYN, NY 11217

NY MANIFEST **S117537840**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004704458

AB255
NE
1/8-1/4
0.185 mi.
975 ft.

Relative:
Higher

CON EDISON
688 SACKETT ST
BROOKLYN, NY 11217

NY MANIFEST **S117316060**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004707279
EPA ID NYP004632907

AB256
NE
1/8-1/4
0.185 mi.
975 ft.

Relative:
Higher

CON EDISON
688 SACKETT ST
BROOKLYN, NY

NY MANIFEST | **S117319232**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004669222

AC257
West
1/8-1/4
0.185 mi.
976 ft.

Relative:
Lower

CON EDISON SERVICE BOX: 45289
198 3RD ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
NY MANIFEST | **1016974107**
NYP004479184

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004479184

NY MANIFEST
EPA ID NYP004479184

Z258
SSW
1/8-1/4
0.187 mi.
989 ft.

Relative:
Higher

SUSAN MAINTENANCE CORP.
374 4TH AVENUE
BROOKLYN, NY 11215

NY UST | **U004277379**
N/A

Click here for full text details

Z259
SSW
1/8-1/4
0.187 mi.
989 ft.

Relative:
Higher

SUSAN MAINTENANCE
374 4TH AVE
BROOKLYN, NY 11215

RCRA-SQG | **1001493708**
FINDS | **NYR000076091**
ECHO
NJ MANIFEST
NY MANIFEST

Click here for full text details

RCRA-SQG
EPA Id NYR000076091

FINDS
Registry ID: 110004556016

ECHO
Registry ID 110004556016

NJ MANIFEST
EPA Id NYR000076091

NY MANIFEST

SUSAN MAINTENANCE (Continued) **1001493708**

EPA ID NYR000076091

Z260
SSW
1/8-1/4
0.187 mi.
989 ft.

Relative:
Higher

374 4TH AVENUE **NY VCP** **S128587696**
374 4TH AVENUE **N/A**
NEW YORK CITY, NY

Click here for full text details

Z261
SSW
1/8-1/4
0.187 mi.
989 ft.

Relative:
Higher

SUSAN MAINTENANCE CORP. **NY AST** **A100350449**
374 4TH AVENUE **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-611328

U262
SE
1/8-1/4
0.191 mi.
1009 ft.

Relative:
Higher

CON EDISON **NY MANIFEST** **S117066554**
318 1 ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004592192

S263
NNW
1/8-1/4
0.192 mi.
1016 ft.

Relative:
Lower

MATTHEWS INTERNATIONAL CASKET DIV **RCRA NonGen / NLR** **1018158807**
585 UNION ST **NYN008027997**
BROOKLYN, NY 11215

Click here for full text details

RCRA NonGen / NLR
EPA Id NYN008027997

X264
NNE
1/8-1/4
0.194 mi.
1022 ft.

Relative:
Higher

SEMPLE RIEGER CO **RCRA NonGen / NLR** **1000347934**
635 SACKETT ST **FINDS** **NYD986891885**
BROOKLYN, NY 11217 **ECHO**
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD986891885

FINDS

SEMPLE RIEGER CO (Continued) **1000347934**

Registry ID: 110004443273

ECHO
Registry ID 110004443273

NY MANIFEST
EPA ID NYD986891885

U265
ESE
1/8-1/4
0.194 mi.
1025 ft.

Relative:
Higher

32 UNIT 4 STORY WALK UP **NY AST** **U003388517**
325 1ST STREET **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-252794

U266
SE
1/8-1/4
0.195 mi.
1030 ft.

Relative:
Higher

CON EDISON **RCRA NonGen / NLR** **1019906687**
365 2ND ST **FINDS** **NYP004825176**
BROOKLYN, NY 11215 **ECHO**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004825176

FINDS
Registry ID: 110069668443

ECHO
Registry ID 110069668443

U267
SE
1/8-1/4
0.195 mi.
1030 ft.

Relative:
Higher

CON EDISON **NJ MANIFEST** **S120675483**
365 2ND ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004825176

U268
SE
1/8-1/4
0.195 mi.
1030 ft.

Relative:
Higher

CON ED — **NY MANIFEST** — **S118259038**
365 2ND ST — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004825176

V269
ESE
1/8-1/4
0.197 mi.
1042 ft.

Relative:
Higher

640 CARROLL LLC — **NY AST** — **A100292625**
640 CARROLL STREET — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-608751

Z270
SSW
1/8-1/4
0.199 mi.
1053 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 16194 — **RCRA NonGen / NLR** — **1016677230**
209 5TH ST OPPOSITE N — **FINDS** — **NYP004307930**
BROOKLYN, NY 11211 — **ECHO**
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004307930

FINDS
Registry ID: 110058878763

ECHO
Registry ID 110058878763

NY MANIFEST
EPA ID NYP004307930

T271
NNE
1/8-1/4
0.200 mi.
1057 ft.

Relative:
Lower

617 SACKETT STREET REALTY CORP. — **NY UST** — **U000394275**
617 SACKETT STREET — **N/A**
BROOKLYN, NY 11217

Click here for full text details

AD272
WSW
1/8-1/4
0.201 mi.
1059 ft.

Relative:
Lower

220 3RD STREET — **NY UST** — **U004067675**
220 3RD STREET — **N/A**
BROOKLYN, NY 11215

Click here for full text details

AD273
WSW
1/8-1/4
0.201 mi.
1059 ft.

Relative:
Lower

PIPPIN ENTERPRISES LTD — **RCRA NonGen / NLR** — **1000790830**
220 3RD ST — **FINDS** — **NYD987023181**
BROOKLYN, NY 11215 — **ECHO**
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD987023181

FINDS
Registry ID: 110004498552

ECHO
Registry ID 110004498552

NY MANIFEST
EPA ID NYD987023181

AE274
NNW
1/8-1/4
0.203 mi.
1074 ft.

Relative:
Lower

585 UNION STREET — **NY BROWNFIELDS** — **S127750710**
577-599 UNION STREET (AKA 586 SACKETT STREET) — **N/A**
BROOKLYN, NY 11217

Click here for full text details

NY BROWNFIELDS
Site Code 619763

Y275
East
1/8-1/4
0.204 mi.
1079 ft.

Relative:
Higher

670 PRESIDENT ST HOUSING CORP — **NY AST** — **U004077233**
670 PRESIDENT STREET — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-254460

AF276
North
1/8-1/4
0.205 mi.
1082 ft.

Relative:
Lower

CON EDISON - EXCAVATION OIL-O-STATIC — **RCRA-LQG** — **1024890651**
232 3RD AVE — **NYP005022769**
BROOKLYN, NY 11215

Click here for full text details

RCRA-LQG
EPA Id NYP005022769

AF277
North
1/8-1/4
0.205 mi.
1082 ft.

Relative:
Lower

CON EDISON — **NY MANIFEST** — **S120959323**
232 3RD AVE — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP005022769

AC278
West
1/8-1/4
0.205 mi.
1082 ft.

Relative:
Lower

CON EDISON — **NY MANIFEST** — **S117067066**
227 3RD ST — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004597928

U279
ESE
1/8-1/4
0.207 mi.
1093 ft.

Relative:
Higher

CON EDISON — **NJ MANIFEST** — **S120667299**
335 1ST ST — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NJ MANIFEST
EPA Id NYP004731998

U280
ESE
1/8-1/4
0.207 mi.
1093 ft.

Relative:
Higher

CON EDISON — **NY MANIFEST** — **S117740048**
335 1ST ST — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004731998

U281
ESE
1/8-1/4
0.207 mi.
1093 ft.

Relative:
Higher

CON EDISON
335 1ST ST
BROOKLYN, NY 11215

RCRA NonGen / NLR FINDS ECHO
1018278429
NYP004731998

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004731998

FINDS
Registry ID: 110067705601

ECHO
Registry ID 110067705601

AA282
SSE
1/8-1/4
0.208 mi.
1096 ft.

Relative:
Higher

BHW NV ASSOCIATES
321 FIFTH AVENUE
NEW YORK, NY 11215

NY AST
U004046147
N/A

Click here for full text details

NY AST
Facility Id 2-291412

AC283
West
1/8-1/4
0.208 mi.
1097 ft.

Relative:
Lower

CON EDISON MANHOLE: 45289
190 3RD ST FRONT OF
BROOKLYN, NY 11215

RCRA NonGen / NLR
NY MANIFEST
1016974113
NYP004479242

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004479242

NY MANIFEST
EPA ID NYP004479242

W284
NW
1/8-1/4
0.208 mi.
1098 ft.

Relative:
Lower

CRUSADER CANDLE CO INC
325 NEVINS ST
BROOKLYN, NY 11215

NJ MANIFEST
S117984914
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYD987005840

W285
NW
1/8-1/4
0.208 mi.
1098 ft.

Relative:
Lower

325 NEVINS STREET
325 NEVINS STREET
BROOKLYN, NY

NY LTANKS | **S102672916**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9501568 / 1995-05-08
Spill Number/Closed Date 9508359 / 1995-10-09
Site ID 266812
Site ID 266813
Spill Date 1995-05-08
Spill Date 1995-10-09

W286
NW
1/8-1/4
0.208 mi.
1098 ft.

Relative:
Lower

CRUSADER CANDLE CO INC
325 NEVINS ST
BROOKLYN, NY 11215

RCRA-SQG
FINDS
ECHO
NY MANIFEST

1000694280
NYD987005840

Click here for full text details

RCRA-SQG
EPA Id NYD987005840

FINDS
Registry ID: 110004491283

ECHO
Registry ID 110004491283

NY MANIFEST
EPA ID NYD987005840

AF287
North
1/8-1/4
0.209 mi.
1104 ft.

Relative:
Lower

CON EDISON
SACKETT ST & 3RD AVE
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO

1019908059
NYP004841512

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004841512

FINDS
Registry ID: 110069654350

ECHO
Registry ID 110069654350

AF288
North
1/8-1/4
0.209 mi.
1104 ft.

Relative:
Lower

CON EDISON
SACKETT ST & 3RD AVE
BROOKLYN, NY 11215

NJ MANIFEST **S120676968**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004841512

AF289
North
1/8-1/4
0.209 mi.
1104 ft.

Relative:
Lower

NYCDEP
SACKETT ST & 3RD AVE
BROOKLYN, NY 11201

NY MANIFEST **1009244330**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP010001790

AG290
NNW
1/8-1/4
0.210 mi.
1107 ft.

Relative:
Lower

473 PRESIDENT STREET
473 PRESIDENT STREET
BROOKLYN, NY 11215

NY BROWNFIELDS **S121933761**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 507634

AG291
NNW
1/8-1/4
0.210 mi.
1107 ft.

Relative:
Lower

473 PRESIDENT STREET - OFF-SITE
473 PRESIDENT STREET
BROOKLYN, NY 11215

NY LTANKS **S101508966**
NY BROWNFIELDS **N/A**
NY MANIFEST

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9412605 / Not Reported
Site ID 323409
Spill Date 1994-12-20

NY BROWNFIELDS
Site Code 568180

NY MANIFEST
EPA ID NYR000232116

AG292
NNW
1/8-1/4
0.210 mi.
1107 ft.

Relative:
Lower

473 PRESIDENT STREET LLC - BCP SITE #C224220
473 PRESIDENT ST
BROOKLYN, NY 11215

RCRA-LQG **1023679233**
NYR000232116

Click here for full text details

RCRA-LQG
EPA Id NYR000232116

AF293
North
1/8-1/4
0.210 mi.
1108 ft.

Relative:
Lower

BELL ATLANTIC-NY
SACKETT & 3 AVE MANHOLE
BROOKLYN, NY

NY MANIFEST **S109064589**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP000940593

AH294
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON ED
CARROLL ST & NEVINS ST
BROOKLYN, NY 11215

NY MANIFEST **S119077205**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004822777

AH295
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON
CARROLL ST & NEVINS ST
BROOKLYN, NY 11217

NY MANIFEST **S117740314**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004734786

AH296
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON - TRANSFORMER MANHOLE 0105
CARROLL ST & NEVINS ST
BROOKLYN, NY 11217

NJ MANIFEST **S120667553**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004734786

AH297
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON
CARROLL ST & NEVINS ST
BROOKLYN, NY 11215

RCRA NonGen / NLR
FINDS
ECHO

1019906589
NYP004822777

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004822777

FINDS
Registry ID: 110069664161

ECHO
Registry ID 110069664161

AH298
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON - TRANSFORMER MANHOLE 0105
CARROLL ST & NEVINS ST
BROOKLYN, NY 11217

RCRA-LQG

1018278697
NYP004734786

Click here for full text details

RCRA-LQG
EPA Id NYP004734786

AH299
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON
CARROLL ST AND NEVINS ST
BROOKLYN, NY 11231

NY MANIFEST

S117738027
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004698718

AH300
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON
CARROLL ST & NEVINS ST
BROOKLYN, NY 11215

NJ MANIFEST

S120675367
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004822777

AH301
NW
1/8-1/4
0.210 mi.
1110 ft.

Relative:
Lower

CON EDISON
CARROLL ST & NEVINS ST
BROOKLYN, NY 11215

NY MANIFEST **S117537323**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004698700

AE302
NNW
1/8-1/4
0.211 mi.
1113 ft.

Relative:
Lower

473 PRESIDENT LLC - BCP SITE #C224318
514 UNION ST
BROOKLYN, NY 11215

RCRA-LQG **1027099640**
NYR000253203

Click here for full text details

RCRA-LQG
EPA Id NYR000253203

AE303
NNW
1/8-1/4
0.211 mi.
1113 ft.

Relative:
Lower

514 UNION STREET
514 UNION STREET
BROOKLYN, NY 11215

NY BROWNFIELDS **S127750694**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 615885

Y304
East
1/8-1/4
0.212 mi.
1121 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 31672
674 PRESIDENT ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1016454644**
FINDS **NYP004330726**
ECHO
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004330726

FINDS
Registry ID: 110056499016

ECHO
Registry ID 110056499016

NY MANIFEST
EPA ID NYP004330726

AI305
SE
1/8-1/4
0.213 mi.
1122 ft.

Relative:
Higher

CON EDISON
386 2ND ST
BROOKLYN, NY 11215

NY MANIFEST | **S117066557**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004592226

AD306
WSW
1/8-1/4
0.214 mi.
1129 ft.

Relative:
Lower

PARK SLOPE U-HAUL RERS
389 3RD AVENUE
BROOKLYN, NY 11215

NY AST | **A100384621**
N/A

Click here for full text details

NY AST
Facility Id 2-612146

AC307
West
1/8-1/4
0.214 mi.
1130 ft.

Relative:
Lower

VERIZON NEW YORK INC NY35549
175 THIRD ST
BROOKLYN, NY 11215

NY MANIFEST | **U003074727**
NY SPDES | **N/A**

Click here for full text details

NY MANIFEST
EPA ID NYD987028008

NY SPDES
Permit Number NYR00F468

AC308
West
1/8-1/4
0.214 mi.
1130 ft.

Relative:
Lower

VERIZON NEW YORK INC-NY-35549
175 THIRD STREET
BROOKLYN, NY 11215

NY AST | **S116349274**
N/A

Click here for full text details

NY AST
Facility Id 2-344133

AC309
West
1/8-1/4
0.214 mi.
1130 ft.

Relative:
Lower

NEW YORK TELEPHONE CO
175 THIRD ST
BROOKLYN, NY 11215

RCRA NonGen / NLR | **1000791294**
NYD987028008

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD987028008

AC310
West
1/8-1/4
0.214 mi.
1130 ft.

Relative:
Lower

VERIZON NEW YORK INC-NY-35549
175 THIRD STREET
BROOKLYN, NY 11215

NY UST **U004330243**
N/A

Click here for full text details

AC311
West
1/8-1/4
0.214 mi.
1130 ft.

Relative:
Lower

175-225 3RD STREET
175-225 3RD STREET
BROOKLYN, NY 11215

NY BROWNFIELDS **S117535357**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 504582

AC312
West
1/8-1/4
0.214 mi.
1130 ft.

Relative:
Lower

175 3RD STREET
175 3RD STREET
BROOKLYN, NY

NY LTANKS **S104073401**
NY Spills **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9208180 / 1992-10-15
Site ID 103805
Spill Date 1992-10-14

NY Spills
Spill Number/Closed Date 9402981 / 2000-12-04
Spill Number/Closed Date 9706734 / 1997-09-05
Site ID 315352
Site ID 315353
Spill Date 1994-05-31
Spill Date 1997-09-05

AJ313
East
1/8-1/4
0.216 mi.
1138 ft.

Relative:
Higher

CON EDISON
676 PRESIDENT ST
BROOKLYN, NY 11215

NY MANIFEST **S117740672**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004738498

AJ314
East
1/8-1/4
0.216 mi.
1138 ft.

Relative:
Higher

CON EDISON
676 PRESIDENT ST
BROOKLYN, NY 11215

NJ MANIFEST **S120667898**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004738498

AJ315
East
1/8-1/4
0.216 mi.
1138 ft.

Relative:
Higher

CON EDISON
676 PRESIDENT ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1018279055**
FINDS **NYP004738498**
ECHO

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004738498

FINDS
Registry ID: 110067685543

ECHO
Registry ID 110067685543

AK316
South
1/8-1/4
0.216 mi.
1139 ft.

Relative:
Higher

P.S. # 51- 350 5TH AVE
P.S. #51 - 350 5TH AVE
BROOKLYN, NY

NY LTANKS **S105053994**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9409320 / 1995-02-06
Site ID 105617
Spill Date 1994-10-12

AL317
ENE
1/8-1/4
0.217 mi.
1144 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 44232
726 SACKETT ST
BROOKLYN, NY 11217

RCRA NonGen / NLR **1016455304**
FINDS **NYP004349585**
ECHO
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004349585

FINDS
Registry ID: 110056500914

ECHO
Registry ID 110056500914

CON EDISON SERVICE BOX: 44232 (Continued) **1016455304**

NY MANIFEST
EPA ID NYP004349585

318
East
1/8-1/4
0.217 mi.
1146 ft.

Relative:
Higher

207 CORP **NY AST** **A100301175**
207 5TH AVENUE **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY AST
Facility Id 2-257176

AG319
NNW
1/8-1/4
0.218 mi.
1153 ft.

Relative:
Lower

PRESIDENT STREET PORTFOLIO **NY BROWNFIELDS** **S126218335**
469 PRESIDENT STREET AND 532 UNION STREET **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY BROWNFIELDS
Site Code 602138

AJ320
East
1/8-1/4
0.223 mi.
1177 ft.

Relative:
Higher

CON EDISON **NY MANIFEST** **S117740701**
675 PRESIDENT ST **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY MANIFEST
EPA ID NYP004738811

AJ321
East
1/8-1/4
0.223 mi.
1177 ft.

Relative:
Higher

CON EDISON **RCRA NonGen / NLR** **1018279083**
675 PRESIDENT ST **FINDS** **NYP004738811**
BROOKLYN, NY 11215 **ECHO**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004738811

FINDS
Registry ID: 110067685785

ECHO
Registry ID 110067685785

AJ322
East
1/8-1/4
0.223 mi.
1177 ft.

Relative:
Higher

CON EDISON
675 PRESIDENT ST
BROOKLYN, NY 11215

NJ MANIFEST | **S120667922**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004738811

AM323
NNE
1/8-1/4
0.223 mi.
1178 ft.

Relative:
Higher

A SHAMOSH
620-628 DEGRAW STREET
BROOKLYN, NY 11217

NY UST | **U004189562**
NY AST | **N/A**

Click here for full text details

NY AST
Facility Id 2-611758

AH324
NW
1/8-1/4
0.224 mi.
1182 ft.

Relative:
Lower

GOWANUS VILLAGE I, LLC - 420 CARROLL STREET
420 CARROLL STREET
BROOKLYN, NY 11217

NY BROWNFIELDS | **S102145301**
NY Spills | **N/A**

Click here for full text details

NY BROWNFIELDS
Site Code 356610

NY Spills
Spill Number/Closed Date 8810095 / 1989-03-30
Site ID 90905
Spill Date 1989-03-30

AC325
West
1/8-1/4
0.224 mi.
1184 ft.

Relative:
Lower

RED HOOK CRUSHERS; INC.
186 3RD STREET
BROOKLYN, NY 11210

NY SWF/LF | **S105841237**
N/A

Click here for full text details

AN326
NE
1/8-1/4
0.226 mi.
1195 ft.

Relative:
Higher

CON EDISON
664 DEGRAW ST
BROOKLYN, NY 11217

NJ MANIFEST | **S120671714**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004781910

AN327
NE
1/8-1/4
0.226 mi.
1195 ft.

Relative:
Higher

CON EDISON
664 DEGRAW ST
BROOKLYN, NY 11217

RCRA NonGen / NLR **1019903138**
NYP004781910

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004781910

AN328
NE
1/8-1/4
0.226 mi.
1195 ft.

Relative:
Higher

CON EDISON
664 DEGRAW ST
BROOKLYN, NY 11217

NY MANIFEST **S118090559**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004856769
EPA ID NYP004781910

AG329
NW
1/8-1/4
0.227 mi.
1199 ft.

Relative:
Lower

VERIZON
318 NEVINS STREET
BROOKLYN, NY

NY LTANKS **S103274088**
NY Spills **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0306012 / 2003-10-02
Site ID 164586
Spill Date 2003-09-06

NY Spills
Spill Number/Closed Date 9801467 / 1998-05-05
Spill Number/Closed Date 9314103 / 2003-04-14
Spill Number/Closed Date 9208840 / 1992-10-30
Spill Number/Closed Date 9207367 / 2015-06-04
Site ID 67006
Site ID 296335
Site ID 319547
Site ID 319546
Spill Date 1998-05-04
Spill Date 1994-03-02
Spill Date 1992-10-30
Spill Date 1992-09-24

AG330
NW
1/8-1/4
0.227 mi.
1199 ft.

Relative:
Lower

VERIZON NEW YORK INC. (NY35570)
318 NEVINS STREET
BROOKLYN, NY 11215

NY AST **A100382320**
N/A

Click here for full text details

NY AST
Facility Id 2-344265

AG331
NW
1/8-1/4
0.227 mi.
1199 ft.

Relative:
Lower

VERIZON NEW YORK INC. (NY35570)
318 NEVINS STREET
BROOKLYN, NY 11215

NY UST **U004198767**
N/A

Click here for full text details

AG332
NW
1/8-1/4
0.227 mi.
1199 ft.

Relative:
Lower

NEW YORK TELEPHONE CO
318 NEVINS ST
BROOKLYN, NY 11215

RCRA-VSQG **1000791295**
FINDS **NYD987028016**
ECHO
NY MANIFEST

Click here for full text details

RCRA-VSQG
EPA Id NYD987028016

FINDS
Registry ID: 110004500825

ECHO
Registry ID 110004500825

NY MANIFEST
EPA ID NYD987028016

AK333
SSE
1/8-1/4
0.227 mi.
1200 ft.

Relative:
Higher

NYC DEPT OF EDUCATION - I S 51K
350 5TH AVE
BROOKLYN, NY 11215

RCRA-SQG **1016144316**
FINDS **NYR000198952**
ECHO

Click here for full text details

RCRA-SQG
EPA Id NYR000198952

FINDS
Registry ID: 110063898956

ECHO
Registry ID 110063898956

AK334
SSE
1/8-1/4
0.227 mi.
1200 ft.

Relative:
Higher

K051
350 5TH AVENUE
BROOKLYN, NY 11215

NY UST **U000418095**
N/A

Click here for full text details

AO335
South
1/8-1/4
0.227 mi.
1200 ft.

Relative:
Higher

CON EDISON
298 5TH ST
BROOKLYN, NY 11215

NY MANIFEST **S117064538**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004570321

AO336
South
1/8-1/4
0.227 mi.
1200 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 45986
298 5TH ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1017779065**
NYP004570321

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004570321

Z337
SSW
1/8-1/4
0.228 mi.
1206 ft.

Relative:
Higher

CON ED - V 3685
522 W 44 ST
NEW YORK, NY 10036

RCRA NonGen / NLR **1007205266**
NYP000928358

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP000928358

AA338
SSE
1/8-1/4
0.229 mi.
1207 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 37885
315 4TH ST S
BROOKLYN, NY 11232

RCRA NonGen / NLR **1016961208**
NY MANIFEST **NYP004337168**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004337168

NY MANIFEST
EPA ID NYP004337168

AG339
NW
1/8-1/4
0.231 mi.
1218 ft.

Relative:
Lower

318 NEVINS STREET
300-344 NEVINS STREET
BROOKLYN, NY 11215

NY BROWNFIELDS **S128529087**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 630084

AP340
SSW
1/8-1/4
0.232 mi.
1225 ft.

Relative:
Higher

KAM SERVICE CENTER INC
363 4TH AVE
BROOKLYN, NY 11234

NY LTANKS **1000556241**
NY Spills **NYD986988004**
RCRA NonGen / NLR
FINDS
ECHO

Click here for full text details

NY LTANKS
Spill Number/Closed Date 8901904 / 2016-02-04
Site ID 90896
Spill Date 1989-05-24

NY Spills
Spill Number/Closed Date 0307900 / 2003-10-27
Site ID 90895
Spill Date 2003-10-27

RCRA NonGen / NLR
EPA Id NYD986988004

FINDS
Registry ID: 110004483675

ECHO
Registry ID 110004483675

AP341
SSW
1/8-1/4
0.232 mi.
1225 ft.

Relative:
Higher

BP SS # 13397
363 FOURTH AVENUE
BROOKLYN, NY 11215

NY UST **U001837489**
N/A

Click here for full text details

AI342
SE
1/8-1/4
0.238 mi.
1256 ft.

Relative:
Higher

CON EDISON
391 2ND ST
BROOKLYN, NY 11215

NY MANIFEST **S118088476**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004760401

AI343
SE
1/8-1/4
0.238 mi.
1256 ft.

Relative:
Higher

CON EDISON
391 2ND ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1018281108**
FINDS **NYP004760401**
ECHO

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004760401

FINDS
Registry ID: 110067687211

ECHO
Registry ID 110067687211

AI344
SE
1/8-1/4
0.238 mi.
1256 ft.

Relative:
Higher

CON EDISON
391 2ND ST
BROOKLYN, NY 11215

NJ MANIFEST **S120669812**
N/A

Click here for full text details

NJ MANIFEST
EPA Id NYP004760401

AE345
NNW
1/8-1/4
0.238 mi.
1257 ft.

Relative:
Lower

PARK SLOPE PAINT STRIPPERS INC
553 UNION ST
BROOKLYN, NY 11215

RCRA-SQG **1012187182**
NY MANIFEST **NYR000170472**
NJ MANIFEST

Click here for full text details

RCRA-SQG
EPA Id NYR000170472

NY MANIFEST
EPA ID NYR000170472

NJ MANIFEST
EPA Id NYR000170472

AK346
South
1/8-1/4
0.239 mi.
1262 ft.

Relative:
Higher

CON EDISON
314 5TH ST
BROOKLYN, NY 11205

NY MANIFEST **S119073767**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004363230

AK347
South
1/8-1/4
0.239 mi.
1262 ft.

Relative:
Higher

CON EDISON - SERVICE BOX 45987
314 5 ST
BROOKLYN, NY 11205

RCRA-LQG **1016963307**
NYP004363230

Click here for full text details

RCRA-LQG
EPA Id NYP004363230

AP348
SSW
1/8-1/4
0.239 mi.
1263 ft.

Relative:
Higher

AMOCO SERVICE STATION
375-381 4TH AVE & 6TH ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1004757402**
FINDS **NYD986933109**
ECHO
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD986933109

FINDS
Registry ID: 110008045613

ECHO
Registry ID 110008045613

NY MANIFEST
EPA ID NYD986933109

AE349
North
1/8-1/4
0.240 mi.
1266 ft.

Relative:
Lower

563 SACKETT STREET
563 SACKETT STREET
BROOKLYN, NY 11215

NY BROWNFIELDS **S118141136**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 507650

AH350
NW
1/8-1/4
0.241 mi.
1275 ft.

Relative:
Lower

CON EDISON
408 CARROL ST
BROOKLYN, NY 11201

NY MANIFEST **1016961536**
N/A

Click here for full text details

NY MANIFEST
EPA ID NYP004342978

AH351
NW
1/8-1/4
0.241 mi.
1275 ft.

Relative:
Lower

CON EDISON - MANHOLE 4
408 CARROL ST
BROOKLYN, NY 11201

RCRA-LQG **1016961535**
NYP004342978

Click here for full text details

RCRA-LQG
EPA Id NYP004342978

AL352
ENE
1/8-1/4
0.243 mi.
1282 ft.

Relative:
Higher

CON EDISON SERVICE BOX: 45175
195 5TH AVE FRONT OF
BROOKLYN, NY 11217

RCRA NonGen / NLR **1016454433**
FINDS **NYP004326278**
ECHO
NY MANIFEST

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004326278

FINDS
Registry ID: 110056507506

ECHO
Registry ID 110056507506

NY MANIFEST
EPA ID NYP004326278

AP353
SSW
1/8-1/4
0.243 mi.
1284 ft.

Relative:
Higher

U-HAUL CO OF METRO NY
259 6TH STREET
BROOKLYN, NY 11215

NY UST **U000394587**
N/A

Click here for full text details

AP354
SSW
1/8-1/4
0.243 mi.
1284 ft.

Relative:
Higher

U-HAUL
259 6TH ST
BROOKLYN, NY

NY LTANKS | **S102672726**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9412186 / 2006-03-13
Site ID 225909
Spill Date 1994-12-12

AP355
SSW
1/8-1/4
0.243 mi.
1284 ft.

Relative:
Higher

U-HAUL CORP
259 6TH ST - PARK SLOPE
BROOKLYN, NY 11210

RCRA NonGen / NLR
FINDS
ECHO
NY MANIFEST

1000981347
NY0000970509

Click here for full text details

RCRA NonGen / NLR
EPA Id NY0000970509

FINDS
Registry ID: 110008108216

ECHO
Registry ID 110008108216

NY MANIFEST
EPA ID NY0000970509

AN356
NNE
1/8-1/4
0.243 mi.
1285 ft.

Relative:
Higher

RINALDI RECYCLING CO. INC.
182 4TH AVE.
BROOKLYN, NY 11217

NY SWF/LF | **S105842419**
N/A

Click here for full text details

357
WNW
1/8-1/4
0.244 mi.
1287 ft.

Relative:
Lower

NYSDOT 3RD ST BRIDGE & GOWANUS CANAL
3RD ST BRG OVER GOWANUS CANAL
BROOKLYN, NY 11201

RCRA NonGen / NLR | **1000555036**
NYD986975316

Click here for full text details

RCRA NonGen / NLR
EPA Id NYD986975316

AO358
SSW
1/8-1/4
0.245 mi.
1292 ft.

Relative:
Higher

CON EDISON MANHOLE: 5416
267 6TH ST
BROOKLYN, NY 11215

RCRA NonGen / NLR **1016960296**
NY MANIFEST **NYP004322004**

Click here for full text details

RCRA NonGen / NLR
EPA Id NYP004322004

NY MANIFEST
EPA ID NYP004322004

AE359
NNW
1/8-1/4
0.245 mi.
1295 ft.

Relative:
Lower

A & A BRAKE CO INC
560 SACKETT STREET
BROOKLYN, NY 11217

NY AST **A100349510**
N/A

Click here for full text details

NY AST
Facility Id 2-604492

AE360
NNW
1/8-1/4
0.245 mi.
1295 ft.

Relative:
Lower

A & A BRAKE CO INC
560 SACKETT STREET
BROOKLYN, NY 11217

NY UST **U003740198**
N/A

Click here for full text details

361
NNW
1/8-1/4
0.246 mi.
1299 ft.

Relative:
Lower

SOUTH BROOKLYN REALTY LLC
301 NEVINS STREET
BROOKLYN, NY 11217

NY UST **U003128182**
N/A

Click here for full text details

362
SSE
1/8-1/4
0.247 mi.
1305 ft.

Relative:
Higher

MESSINA
392 3RD ST
BROOKLYN, NY 11215

NY AST **U003386108**
N/A

Click here for full text details

NY AST
Facility Id 2-272094

AM363
NNE
1/8-1/4
0.249 mi.
1313 ft.

Relative:
Lower

AJR (COMMERCIAL BLDG.)
599 DEGRAW ST
BROOKLYN, NY

NY LTANKS | **S106869125**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0500453 / 2005-04-28
Site ID 343388
Spill Date 2005-04-11

AQ364
North
1/8-1/4
0.250 mi.
1320 ft.

Relative:
Lower

553 SACKETT STREET
553 SACKETT STREET
NEW YORK CITY, NY

NY VCP | **S128723346**
N/A

Click here for full text details

AI365
SE
1/4-1/2
0.259 mi.
1365 ft.

Relative:
Higher

401 3RD STREET
401 3RD STREET
BROOKLYN, NY

NY LTANKS | **S102672277**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9310090 / 1993-11-19
Site ID 244717
Spill Date 1993-11-11

AP366
SSW
1/4-1/2
0.265 mi.
1397 ft.

Relative:
Higher

FERRANTINO & CO
278 6TH ST
BROOKLYN, NY

NY LTANKS | **S102659626**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9705330 / 2011-08-01
Site ID 304152
Spill Date 1997-08-01

367
NNE
1/4-1/2
0.273 mi.
1441 ft.

Relative:
Higher

RINALDI RECYCLING CO.
326 DOUGLASS STREET
BROOKLYN, NY 11217

NY SWRCY | **S105842286**
N/A

Click here for full text details

368
NW
1/4-1/2
0.277 mi.
1460 ft.

Relative:
Lower

CARROLL ST. TRANSFER STATION — **NY SWF/LF** — **S105841710**
400 CARROLL ST — **N/A**
BROOKYN, NY 11215

Click here for full text details

AR369
WNW
1/4-1/2
0.277 mi.
1465 ft.

Relative:
Lower

GOWANUS VILLAGE I — **NY INST CONTROL** — **S121933912**
153 2ND ST A/K/A 322 3RD AVENUE — **N/A**
BROOKLYN, NY 11217

Click here for full text details

NY INST CONTROL
Site Code 332623

AS370
North
1/4-1/2
0.287 mi.
1514 ft.

Relative:
Lower

280 DOUGLAS ST/PENSKE — **NY LTANKS** — **S102671834**
280 DOUGLAS ST/PENSKE — **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9112095 / 1992-03-03
Site ID 280189
Spill Date 1992-02-25

AS371
North
1/4-1/2
0.287 mi.
1514 ft.

Relative:
Lower

280 DOUGLAS ST — **NY LTANKS** — **S101341149**
280 DOUGLAS STREET — **NY Spills** — **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9410669 / 1995-03-10
Site ID 160988
Spill Date 1994-11-10

NY Spills
Spill Number/Closed Date 9415539 / 1995-02-28
Spill Number/Closed Date 9310083 / 1993-11-18
Spill Number/Closed Date 9415530 / 1995-03-01
Site ID 121831
Site ID 121830
Site ID 160989
Spill Date 1995-02-28
Spill Date 1993-11-18

372
ENE
1/4-1/2
0.289 mi.
1528 ft.

Relative:
Higher

19 BERKELEY PL
19 BERKELEY PL
BROOKLYN, NY

NY LTANKS **S105997672**
NY Spills **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0209599 / 2002-12-18
Site ID 238174
Spill Date 2002-12-18

NY Spills
Spill Number/Closed Date 0209601 / 2010-10-26
Site ID 238175
Spill Date 2002-12-18

AQ373
NNW
1/4-1/2
0.290 mi.
1530 ft.

Relative:
Lower

FULTON MUNICIPAL WORKS
NEVINS, DEGRAW AND SACKETT STS.
BROOKLYN, NY 11217

EDR MGP **1008407890**
N/A

Click here for full text details

AT374
WSW
1/4-1/2
0.302 mi.
1597 ft.

Relative:
Lower

163 6TH STREET LLC
163 6TH ST
BROOKLYN, NY 11215

NY SWRCY **S117392702**
NY MANIFEST **N/A**
NY SPDES

Click here for full text details

NY MANIFEST
EPA ID NYR000232280

NY SPDES
Permit Number NYR00F428
Limit Set Status Flag A

AT375
WSW
1/4-1/2
0.303 mi.
1602 ft.

Relative:
Lower

US RECYCLING INC
141 6TH STREET
BROOKLYN, NY 11215

NY SWRCY **S103560390**
NY Spills **N/A**

Click here for full text details

NY Spills
Spill Number/Closed Date 9204442 / 1992-07-31
Site ID 202525
Spill Date 1992-07-15

AR376
WNW
1/4-1/2
0.305 mi.
1611 ft.

Relative:
Lower

141 3RD STREET — **NY BROWNFIELDS** — **S127990284**
141 3RD STREET — **N/A**
BROOKLYN, NY 11231

Click here for full text details

NY BROWNFIELDS
Site Code 624862

AU377
West
1/4-1/2
0.313 mi.
1651 ft.

Relative:
Lower

GOWANUS CANAL CONSERVANCY; INC. — **NY SWF/LF** — **S128178173**
2 SECOND AVE. — **N/A**
BROOKLYN, NY 11215

Click here for full text details

AU378
West
1/4-1/2
0.313 mi.
1651 ft.

Relative:
Lower

BK6 SALT LOT COMMUNITY COMPOST SITE — **NY SWF/LF** — **S128177808**
2 SECOND AVENUE — **N/A**
BROOKLYN, NY 11215

Click here for full text details

379
ENE
1/4-1/2
0.315 mi.
1661 ft.

Relative:
Higher

SPILL NUMBER 0209206 — **NY LTANKS** — **S105997531**
11 LINCOLN PLACE — **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0209206 / 2004-04-16
Site ID 156887
Spill Date 2002-12-07

AV380
NNW
1/4-1/2
0.315 mi.
1661 ft.

Relative:
Lower

FULTON WORKS — **NY VCP** — **S113922087**
DEGRAW STREET AND NEVINS STREET — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY VCP
Site Code 57151

AV381
North
1/4-1/2
0.317 mi.
1672 ft.

Relative:
Lower

FULTON WORKS
DEGRAW STREET AND NEVINS STREET
BROOKLYN, NY 11217

EDR MGP **1008407891**
N/A

Click here for full text details

382
North
1/4-1/2
0.320 mi.
1692 ft.

Relative:
Lower

D GAVER & SONS INC
267 DOUGLASS ST
BROOKLYN, NY 11217

NY LTANKS **U001831861**
NY UST **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 8800904 / 1992-10-02
Site ID 104086
Spill Date 1988-04-28

AW383
NW
1/4-1/2
0.324 mi.
1710 ft.

Relative:
Lower

450 UNION STREET
450 UNION STREET
BROOKLYN, NY 11231

NY ENG CONTROLS **S117936660**
NY INST CONTROL **N/A**
NY BROWNFIELDS

Click here for full text details

NY ENG CONTROLS
Site Code 507633

NY INST CONTROL
Site Code 507633

NY BROWNFIELDS
Site Code 507633

AX384
WNW
1/4-1/2
0.324 mi.
1712 ft.

Relative:
Lower

365 BOND STREET
365 BOND STREET
BROOKLYN, NY 11231

NY ENG CONTROLS **S106720972**
NY INST CONTROL **N/A**
NY BROWNFIELDS
NY Spills
NY E DESIGNATION
NY COOLING TOWERS

Click here for full text details

NY ENG CONTROLS
Site Code 478842

NY INST CONTROL
Site Code 478842

NY BROWNFIELDS
Site Code 478842

365 BOND STREET (Continued) **S106720972**

NY Spills
Spill Number/Closed Date 0407393 / 2015-11-06
Site ID 331823
Spill Date 2004-10-04

AY385 **335 BOND STREET** **NY BROWNFIELDS** **S117936667**
NW **335 BOND STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.326 mi.
1721 ft.

Relative:
Lower

Click here for full text details

NY BROWNFIELDS
Site Code 507653

AW386 **BAYSIDE FUEL OIL DEPOT CORP.** **NY MOSF UST** **S103275956**
NNW **510 SACKETT ST.** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.329 mi.
1738 ft.

Relative:
Lower

Click here for full text details

AW387 **BAYSIDE FUEL OIL DEPOT CORP.** **NY MOSF** **S109826460**
NNW **510 SACKETT ST** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11231**
0.329 mi.
1738 ft.

Relative:
Lower

Click here for full text details

NY MOSF
Facility Id 2-1220
Tank Status Unregulated/Closed

NY Spills
Spill Number/Closed Date 0902825 / 2012-02-06
Spill Number/Closed Date 9604267 / 1996-06-28
Spill Number/Closed Date 9011319 / 1991-01-25
Spill Number/Closed Date 0514992 / 2006-04-17
Spill Number/Closed Date 9011318 / 1991-01-26
Site ID 414889
Site ID 66574
Site ID 253424
Site ID 361851
Site ID 124793
Spill Date 2009-06-09
Spill Date 1996-06-28
Spill Date 1991-01-25
Spill Date 2006-03-28

AY388
NW
1/4-1/2
0.330 mi.
1743 ft.

Relative: Lower

DENTS OUT AUTO BODY LTD
327 BOND ST
BROOKLYN, NY 11215

SEMS-ARCHIVE
RCRA NonGen / NLR

1003864459
NYD986961167

Click here for full text details

SEMS-ARCHIVE
Site ID 0203501
EPA Id NYD986961167

RCRA NonGen / NLR
EPA Id NYD986961167

389
WNW
1/4-1/2
0.335 mi.
1769 ft.

Relative: Lower

THIRD STREET GOWANUS
125 3RD STREET
BROOKLYN, NY 11231

NY BROWNFIELDS

S128529086
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 628534

390
East
1/4-1/2
0.337 mi.
1777 ft.

Relative: Higher

225 6TH AVE.
225 6TH AVE
BROOKLYN, NY

NY LTANKS

S106703145
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 8705973 / 1992-11-19
Site ID 163112
Spill Date 1987-10-15

AT391
WSW
1/4-1/2
0.337 mi.
1779 ft.

Relative: Lower

CONTAINER SERVICE CORP.
107 6TH STREET
BROOKLYN, NY 11231

NY SWF/LF
NY Spills
NY SPDES

S104789732
N/A

Click here for full text details

NY Spills
Spill Number/Closed Date 0007253 / 2003-02-13
Spill Number/Closed Date 0030011 / 2003-09-08
Spill Number/Closed Date 0030027 / 2003-10-31
Spill Number/Closed Date 8700241 / 1987-04-09
Spill Number/Closed Date 9405982 / 2003-10-21
Spill Number/Closed Date 9406805 / 2003-09-08
Spill Number/Closed Date 9407020 / 2003-09-08
Site ID 298822
Site ID 180433
Site ID 180434
Site ID 180435
Site ID 180436

CONTAINER SERVICE CORP. (Continued) **S104789732**

Site ID 180437
Site ID 180438
Spill Date 2000-09-20
Spill Date 2000-07-05
Spill Date 2000-11-13
Spill Date 1987-04-08
Spill Date 1994-08-02
Spill Date 1994-08-19
Spill Date 1994-08-24

NY SPDES
Permit Number NY0201065
Limit Set Status Flag A

AT392
WSW
1/4-1/2
0.342 mi.
1806 ft.

Relative:
Lower

106 6TH ST **NY LTANKS** **S102660664**
106 6TH ST **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9502574 / 1995-05-31
Site ID 153670
Spill Date 1995-05-31

AV393
NNW
1/4-1/2
0.343 mi.
1811 ft.

Relative:
Lower

CROSS BAY CONTRACTING **NY SWF/LF** **S128177977**
242 NEVINS ST. **N/A**
BROOKLYN, NY 11217

Click here for full text details

AV394
NNW
1/4-1/2
0.343 mi.
1811 ft.

Relative:
Lower

ROYAL RECYCLING CORP. **NY SWF/LF** **S128178753**
242 NEVINS STREET **N/A**
BROOKLYN, NY 11217

Click here for full text details

AV395
NNW
1/4-1/2
0.343 mi.
1811 ft.

Relative:
Lower

242 NEVINS STREET **NY BROWNFIELDS** **S105841715**
242 NEVINS STREET **NY Spills** **N/A**
BROOKLYN, NY 11217

Click here for full text details

NY BROWNFIELDS
Site Code 568573

242 NEVINS STREET (Continued) **S105841715**

NY Spills
Spill Number/Closed Date 1103765 / 2011-08-05
Site ID 451337
Spill Date 2011-07-06

AX396
WNW
1/4-1/2
0.345 mi.
1820 ft.

Relative:
Lower

TOLL BROOKLYN, LP **NY BROWNFIELDS** **S113916457**
64-98 1ST ST; 82-107 1ST ST; 119-145 2ND ST; **N/A**
BROOKLYN, NY 11231

Click here for full text details

NY BROWNFIELDS
Site Code 348572

AZ397
SW
1/4-1/2
0.346 mi.
1828 ft.

Relative:
Lower

OCEAN SUPPLY CO **NY LTANKS** **S104191667**
437 3RD AVE **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9905579 / 1999-09-22
Site ID 306200
Spill Date 1999-08-06

AY398
NW
1/4-1/2
0.346 mi.
1828 ft.

Relative:
Lower

388 CARROLL STREET AND 363 BOND STREET **NY ENG CONTROLS** **S116041498**
388 CARROLL STREET AND 363 BOND STREET **NY INST CONTROL** **N/A**
BROOKLYN, NY 11231 **NY BROWNFIELDS**

Click here for full text details

NY ENG CONTROLS
Site Code 478612

NY INST CONTROL
Site Code 478612

NY BROWNFIELDS
Site Code 478612

BA399
WSW
1/4-1/2
0.348 mi.
1835 ft.

Relative:
Lower

BKLYN UNION GAS /CITIZENS GATE STA
6TH ST & 2ND AVE
BROOKLYN, NY 11215

SEMS-ARCHIVE | **1003863865**
NYD980532212

Click here for full text details

SEMS-ARCHIVE
Site ID 0201995
EPA Id NYD980532212

BA400
WSW
1/4-1/2
0.356 mi.
1881 ft.

Relative:
Lower

BUG, CITIZENS GATE STATION
6TH STREET AND 2ND AVENUE
BROOKLYN, NY 11215

NY HSWDS | **S108147010**
N/A

Click here for full text details

AZ401
SW
1/4-1/2
0.364 mi.
1921 ft.

Relative:
Lower

168 8TH STREET
168 8TH STREET
BROOKLYN, NY 11215

NY BROWNFIELDS | **S121933776**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 568008
Site Code 563661

402
NNE
1/4-1/2
0.365 mi.
1927 ft.

Relative:
Higher

126 4TH AVENUE - MISC
126 4TH AVENUE
BROOKLYN, NY

NY LTANKS | **S118953804**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9505523 / 2013-01-17
Site ID 261276
Spill Date 1995-08-03

403
SSW
1/4-1/2
0.368 mi.
1945 ft.

Relative:
Higher

236 8TH ST
236 8TH ST
BROOKLYN, NY

NY LTANKS | **S102233209**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9508664 / 1995-10-16
Site ID 211107
Spill Date 1995-10-15

404
WSW
1/4-1/2
0.371 mi.
1957 ft.

Relative:
Lower

INTERCONTINENTAL RECY.
??
??, NY 0

NY SWF/LF **S101649575**
N/A

Click here for full text details

405
ENE
1/4-1/2
0.372 mi.
1962 ft.

Relative:
Higher

ECONOMY CLEANERS
123 5TH AVE
BROOKLYN, NY 11217

RCRA-VSQG **1000318363**
NY LTANKS **NYD981085053**
US AIRS
NY MANIFEST

Click here for full text details

RCRA-VSQG
EPA Id NYD981085053

NY LTANKS
Spill Number/Closed Date 0507654 / 2005-11-30
Site ID 353099
Spill Date 2005-09-26

US AIRS
EPA plant ID: 110004384185

NY MANIFEST
EPA ID NYD981085053

BB406
North
1/4-1/2
0.375 mi.
1978 ft.

Relative:
Lower

233 NEVINS STREET PHASE II
233 NEVINS STREET
NEW YORK CITY, NY

NY VCP **S125316935**
N/A

Click here for full text details

407
ESE
1/4-1/2
0.380 mi.
2004 ft.

Relative:
Higher

SPILL NUMBER 9804333
705 CARROLL STREET
BROOKLYN, NY

NY LTANKS **S100782331**
NY Spills **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9311807 / 1994-01-05
Site ID 213345
Spill Date 1994-01-05

NY Spills
Spill Number/Closed Date 9804333 / 1998-07-07

SPILL NUMBER 9804333 (Continued) **S100782331**

Site ID 213346
Spill Date 1998-07-07

408
NNE
1/4-1/2
0.385 mi.
2031 ft.

Relative:
Lower

UNDERGROUND TANK **NY LTANKS** **S109829733**
151-169 3RD AVE **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 1402248 / 2014-07-09
Spill Number/Closed Date 0902974 / 2009-08-18
Site ID 495561
Site ID 415051
Spill Date 2014-06-02
Spill Date 2009-06-12

BC409
WNW
1/4-1/2
0.394 mi.
2079 ft.

Relative:
Lower

PATTERSON CHEMICAL CO INC **CORRACTS** **1000403436**
102 3RD ST **RCRA NonGen / NLR** **NYD980592471**
BROOKLYN, NY 11231 **FINDS**
ECHO

Click here for full text details

CORRACTS
EPA ID: NYD980592471

RCRA NonGen / NLR
EPA Id NYD980592471

FINDS
Registry ID: 110004387814

ECHO
Registry ID 110004387814

BD410
NNW
1/4-1/2
0.399 mi.
2105 ft.

Relative:
Lower

210 DOUGLASS STREET **NY BROWNFIELDS** **S127478129**
210 DOUGLASS STREET **N/A**
BROOKLYN, NY 11217

Click here for full text details

NY BROWNFIELDS
Site Code 615221

BC411
WNW
1/4-1/2
0.399 mi.
2106 ft.

Relative:
Lower

99 NORTH 4TH STREET
99 4TH STREET
NEW YORK CITY, NY

NY VCP **S125317258**
N/A

Click here for full text details

BD412
NNW
1/4-1/2
0.405 mi.
2136 ft.

Relative:
Lower

FORMER O.Z. ELECTRICAL
198 DOUGLASS STREET
BROOKLYN, NY 11217

NY SHWS **S108057803**
NY Spills **N/A**

Click here for full text details

NY SHWS
Site Code 450318

NY Spills
Spill Number/Closed Date 0603334 / 2021-03-30
Site ID 366030
Spill Date 2006-06-02

BB413
North
1/4-1/2
0.406 mi.
2143 ft.

Relative:
Lower

233 NEVINS STREET
236 BUTLER STREET
NEW YORK CITY, NY

NY VCP **S125316936**
N/A

Click here for full text details

414
North
1/4-1/2
0.406 mi.
2144 ft.

Relative:
Lower

BALTIC RECYCLING CORP.
524-26 BALTIC STREET
BROOKLYN, NY 11217

NY SWF/LF **S105841705**
N/A

Click here for full text details

BB415
North
1/4-1/2
0.408 mi.
2152 ft.

Relative:
Lower

234 BUTLER STREET
234 BUTLER STREET
BROOKLYN, NY 11217

NY BROWNFIELDS **S121102082**
N/A

Click here for full text details

NY BROWNFIELDS
Site Code 550328

BE416
SSE
1/4-1/2
0.410 mi.
2163 ft.

Relative:
Higher

424 5TH AVENUE — **NY LTANKS** — **S102660655**
424 5TH STREET — **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9412686 / 1994-12-21
Site ID 306765
Spill Date 1994-12-21

BD417
NNW
1/4-1/2
0.417 mi.
2202 ft.

Relative:
Lower

GOWANUS CANAL SITE — **NY SHWS** — **S110487590**
GOWANUS CANAL — **N/A**
BROOKLYN, NY, NY 11217

Click here for full text details

NY SHWS
Site Code 406956
Class Code Significant threat to the public health or environment - action required.

418
West
1/4-1/2
0.420 mi.
2216 ft.

Relative:
Lower

IESI (110 5TH ST.)(SPARTAN DISMANTLING INC) — **NY SWF/LF** — **S110540477**
110 5TH STREET — **NY Spills** — **N/A**
BROOKLYN, NY 11215

Click here for full text details

NY Spills
Spill Number/Closed Date 1006165 / 2010-09-07
Site ID 439511
Spill Date 2010-09-04

419
NNE
1/4-1/2
0.423 mi.
2234 ft.

Relative:
Higher

572 WARREN ST. HOUSES -NYCHA — **NY LTANKS** — **S102233327**
572 WARREN ST — **NY Spills** — **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9105220 / 2005-03-08
Site ID 115495
Spill Date 1991-08-14

NY Spills
Spill Number/Closed Date 9602519 / 2015-06-03
Site ID 115496
Spill Date 1996-05-22

BE420
SSE
1/4-1/2
0.436 mi.
2300 ft.

Relative:
Higher

442 5TH ST
442 5TH ST
BROOKLYN, NY

NY LTANKS **S100177053**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9107178 / 1991-10-10
Site ID 271727
Spill Date 1991-10-03

BF421
North
1/4-1/2
0.437 mi.
2308 ft.

Relative:
Lower

SPILL NUMBER 0212934
233 BUTLER ST
BROOKLYN, NY

NY LTANKS **S105998554**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0212934 / 2003-09-03
Site ID 180335
Spill Date 2003-03-31

BG422
WNW
1/4-1/2
0.438 mi.
2314 ft.

Relative:
Higher

74-76 SOUTH SECOND STREET
74-76 SECOND STREET
NEW YORK CITY, NY

NY VCP **S125317197**
N/A

Click here for full text details

423
East
1/4-1/2
0.441 mi.
2328 ft.

Relative:
Higher

124 LINCOLN PLACE
124 LINCOLN PLACE
BROOKLYN, NY

NY LTANKS **S101658343**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9502716 / 1995-06-02
Site ID 145166
Spill Date 1995-06-02

BE424
SSE
1/4-1/2
0.442 mi.
2334 ft.

Relative:
Higher

APARTMENT BUILDING
446 5TH ST
BROOKLYN, NY

NY LTANKS **S106737517**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0410001 / 2005-10-28
Site ID 334901
Spill Date 2004-12-03

425
SE
1/4-1/2
0.447 mi.
2362 ft.

Relative:
Higher

US POST OFFICE
198 7TH AVENUE
BROOKLYN, NY

NY LTANKS **S105141437**
NY Spills **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9007536 / 2009-10-06
Site ID 92521
Spill Date 1990-10-10

NY Spills
Spill Number/Closed Date 0105125 / 2009-12-14
Site ID 65316
Spill Date 2001-08-11

BH426
West
1/4-1/2
0.451 mi.
2382 ft.

Relative:
Lower

66 FOURTH STREET
66 4TH STREET
BROOKLYN, NY 11215

NY LTANKS **U003749712**
NY UST **N/A**

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0106619 / 2003-11-17
Site ID 228322
Spill Date 2001-09-25

427
SSW
1/4-1/2
0.455 mi.
2403 ft.

Relative:
Higher

STELLAR 341 LLC
341 10TH STREET
BROOKLYN, NY 11215

NY LTANKS **U003178461**
NY UST **N/A**
NY AST

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0413183 / 2005-11-09
Site ID 339044
Spill Date 2004-04-09

NY AST
Facility Id 2-115886

428
South
1/4-1/2
0.456 mi.
2407 ft.

Relative:
Higher

CVS PHARMACY #2498
341 9TH ST
BROOKLYN, NY 11215

SEMS-ARCHIVE **1000121612**
RCRA-VSQG **NYD042777128**

Click here for full text details

SEMS-ARCHIVE
Site ID 0201536
EPA Id NYD042777128

RCRA-VSQG

CVS PHARMACY #2498 (Continued) **1000121612**

EPA Id NYD042777128

BG429
WNW
1/4-1/2
0.456 mi.
2409 ft.

Relative:
Higher

DEL'S AUTO REPAIR **NY LTANKS** **S103037408**
70 2ND ST/NEW UTRECHT AVE **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9713407 / 2003-03-03
Site ID 319396
Spill Date 1998-03-03

430
NNW
1/4-1/2
0.458 mi.
2419 ft.

Relative:
Lower

GOWANUS HOUSING COMPLEX-NYCHA **NY LTANKS** **S105995765**
238 BOND ST **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 0201330 / 2005-12-23
Spill Number/Closed Date 0201191 / 2008-09-23
Site ID 197021
Site ID 224675
Spill Date 2002-05-06
Spill Date 2002-05-01

431
SSW
1/4-1/2
0.461 mi.
2435 ft.

Relative:
Higher

TTF **NY LTANKS** **S117364491**
300 10TH ST **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 1406432 / 2014-11-13
Site ID 499901
Spill Date 2014-09-16

432
NNE
1/4-1/2
0.467 mi.
2467 ft.

Relative:
Higher

79-97 4TH AVENUE **NY VCP** **S125317226**
85 4TH AVENUE **N/A**
NEW YORK CITY, NY

Click here for full text details

BH433
WNW
1/4-1/2
0.470 mi.
2484 ft.

Relative:
Lower

425 HOYT STREET | **NY BROWNFIELDS** | **S117936666**
419-429 HOYT STREET | **N/A**
BROOKLYN, NY 11231

Click here for full text details

NY BROWNFIELDS
Site Code 507652

BF434
North
1/4-1/2
0.472 mi.
2490 ft.

Relative:
Lower

BASIN HAULAGE INC. I | **NY SWF/LF** | **S105841893**
462-470 BALTIC STREET | **N/A**
BROOKLYN, NY 11217

Click here for full text details

435
NNE
1/4-1/2
0.477 mi.
2520 ft.

Relative:
Higher

125 THIRD AVENUE | **NY VCP** | **S125316811**
125 3RD AVENUE | **N/A**
NEW YORK CITY, NY

Click here for full text details

436
North
1/4-1/2
0.478 mi.
2522 ft.

Relative:
Lower

WYCKOFF GARDENS | **NY LTANKS** | **S104283696**
185 NEVINS ST | **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9811464 / 1999-05-14
Site ID 237645
Spill Date 1998-12-11

437
NE
1/4-1/2
0.480 mi.
2532 ft.

Relative:
Higher

SINSI RESIDENCE | **NY LTANKS** | **S102673358**
112 ST MARKS PL | **N/A**
BROOKLYN, NY

Click here for full text details

NY LTANKS
Spill Number/Closed Date 9600499 / 1996-04-11
Site ID 208826
Spill Date 1996-04-10

438
SW
1/4-1/2
0.499 mi.
2633 ft.

Relative: Lower

498 3RD AVENUE
498 3RD AVENUE
BROOKLYN, NY 11215

NY LTANKS **S100167654**
N/A

Click here for full text details

NY LTANKS
Spill Number/Closed Date 8809911 / 2021-08-31
Site ID 66897
Spill Date 1989-03-14

BI439
WSW
1/2-1
0.539 mi.
2846 ft.

Relative: Lower

K - METROPOLITAN MGP
124-136 SECOND AVE
BROOKLYN, NY 11215

NY SHWS **S108667326**
NY BROWNFIELDS **N/A**

Click here for full text details

NY SHWS
Site Code 372656
Class Code Significant threat to the public health or environment - action required.

NY BROWNFIELDS
Site Code 57384

BI440
WSW
1/2-1
0.539 mi.
2846 ft.

Relative: Lower

BU-METROPOLITAN MGP
124-136 SECOND AVE
BROOKLYN, NY 11215

EDR MGP **1008407883**
N/A

Click here for full text details

441
West
1/2-1
0.563 mi.
2972 ft.

Relative: Lower

FORMER CITIZEN GAS WORKS MGP SITE (CAROL
5TH STREET AND SMITH STREET TO GOWANUS CANAL
BROOKLYN, NY 11215

EDR MGP **1008407888**
N/A

Click here for full text details

442
WNW
1/2-1
0.595 mi.
3139 ft.

Relative: Higher

CARROLL GARDENS
CORNER OF 5TH STREET & SMITH STREET
BROOKLYN, NY

NY DEL SHWS **S105972444**
N/A

Click here for full text details

NY DEL SHWS
Site Code Id 224012

443
WSW
1/2-1
0.638 mi.
3369 ft.

Relative:
Lower

USPS GOWANUS SITE. FORMER MGP METROPOLIT
2ND AVENUE AND 12TH STREET
BROOKLYN, NY 11215

Click here for full text details

EDR MGP

1008407902
N/A

444
WSW
1/2-1
0.868 mi.
4584 ft.

Relative:
Lower

FORMER BARRETT MANUFACTURING CO.
627 SMITH ST.
BROOKLYN, NY 11231

Click here for full text details

NY SHWS
Site Code 466165

NY BROWNFIELDS
Site Code 476652

NY SHWS
NY BROWNFIELDS

S112818546
N/A

BJ445
WSW
1/2-1
0.911 mi.
4808 ft.

Relative:
Lower

182 SIGOURNEY ST
182 SIGOURNEY ST
BROOKLYN, NY 11231

Click here for full text details

NY SHWS
Site Code 499845

NY SHWS

S117667764
N/A

BJ446
WSW
1/2-1
0.918 mi.
4846 ft.

Relative:
Lower

CHEMTURA 633 COURT STREET
633 COURT STREET
BROOKLYN, NY 11231

Click here for full text details

NY SHWS
Site Code 443256
Class Code Significant threat to the public health or environment - action required.

NY SHWS

S113828311
N/A

BK447
WSW
1/2-1
0.951 mi.
5020 ft.

Relative:
Lower

643 COURT ST.
643 COURT ST.
BROOKLYN, NY 11231

Click here for full text details

NY SHWS
Site Code 498440

NY SHWS

S117269718
N/A

BK448
WSW
1/2-1
0.957 mi.
5052 ft.

Relative:
Lower

CHEM TURA
688-700 COURT ST
BROOKLYN, NY 11231

NY CBS UST **1001485652**
NY CBS **NY0001411404**
NY AST
NY DEL SHWS
RCRA NonGen / NLR

Click here for full text details

NY CBS UST
Id/Status: 2-000096 / CLOSED IN PLACE
Id/Status: 2-000096 / NO LONGER A MAJOR FACILITY
Tank Status 2
Facility Status 4
Facility Status 3

NY CBS
Facility Status Unregulated/Closed
CBS Number 2-000096

NY AST
Facility Id 2-000096

RCRA NonGen / NLR
EPA Id NY0001411404

449
SW
1/2-1
0.975 mi.
5149 ft.

Relative:
Lower

SUNSET INDUSTRIAL PARK
74 20TH ST
BROOKLYN, NY 11232

CORRACTS **1000224955**
RCRA-TSDF **NYD091590471**
RCRA-LQG
NY BROWNFIELDS
ICIS
FINDS
ECHO
NY MANIFEST

Click here for full text details

CORRACTS
EPA ID: NYD091590471

RCRA-TSDF
EPA Id NYD091590471

RCRA-LQG
EPA Id NYD091590471

NY BROWNFIELDS
Site Code 611063

ICIS
FRS ID: 110004374114

FINDS
Registry ID: 110004374114

SUNSET INDUSTRIAL PARK (Continued) **1000224955**

ECHO
Registry ID 110004374114

NY MANIFEST
EPA ID NYD091590471

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
NY	AIRS	Air Emissions Data	Department of Environmental Conservation	07/27/2022	07/27/2022	08/04/2022
NY	AST	Petroleum Bulk Storage	Department of Environmental Conservation	06/21/2022	06/21/2022	09/09/2022
NY	BROWNFIELDS	Brownfields Site List	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	CBS	Chemical Bulk Storage Site Listing	Department of Environmental Conservation	06/21/2022	06/21/2022	09/09/2022
NY	CBS AST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	CBS UST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	COAL ASH	Coal Ash Disposal Site Listing	Department of Environmental Conservation	06/23/2022	06/23/2022	09/09/2022
NY	COOLING TOWERS	Registered Cooling Towers	Department of Health	04/05/2022	04/13/2022	07/08/2022
NY	DEL SHWS	Delisted Registry Sites	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	DRYCLEANERS	Registered Drycleaners	Department of Environmental Conservation	08/30/2022	08/31/2022	09/07/2022
NY	E DESIGNATION	E DESIGNATION SITE LISTING	New York City Department of City Planning	03/22/2022	06/22/2022	06/28/2022
NY	ENG CONTROLS	Registry of Engineering Controls	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	ENV RES DECL	Environmental Restrictive Declarations	New York City Department of City Planning	03/22/2022	06/17/2022	09/02/2022
NY	ERP	Environmental Restoration Program Listing	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	Financial Assurance 1	Financial Assurance Information Listing	Department of Environmental Conservation	03/29/2022	03/31/2022	06/24/2022
NY	Financial Assurance 2	Financial Assurance Information Listing	Department of Environmental Conservation	06/11/2020	06/16/2020	09/02/2020
NY	HIST AST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006
NY	HIST LTANKS	Listing of Leaking Storage Tanks	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005
NY	HIST SPILLS	SPILLS Database	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005
NY	HIST UST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006
NY	HSWDS	Hazardous Substance Waste Disposal Site Inventory	Department of Environmental Conservation	01/01/2003	10/20/2006	11/30/2006
NY	INST CONTROL	Registry of Institutional Controls	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	LIENS	Spill Liens Information	Office of the State Comptroller	05/03/2022	05/05/2022	07/26/2022
NY	LTANKS	Spills Information Database	Department of Environmental Conservation	05/09/2022	05/11/2022	08/02/2022
NY	MOSF	Major Oil Storage Facility Site Listing	Department of Environmental Conservation	06/21/2022	06/21/2022	09/09/2022
NY	MOSF AST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF UST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	NY MANIFEST	Facility and Manifest Data	Department of Environmental Conservation	01/01/2019	10/29/2021	01/19/2022
NY	NYC LEAD	Lead-based Paint Testing Results	New York City Department of Education	04/04/2022	05/04/2022	07/26/2022
NY	NYC LEAD 2	Recent Lead Paint Violations	New York City Department of Housing Preservat	04/25/2022	05/04/2022	07/26/2022
NY	PFAS	PFAS Contamination Site Location Listing	Department of Environmental Conservation	01/16/2019	05/08/2019	06/24/2019
NY	PFAS 2	New York State Inactive Landfill Initiative	Department of Environmental Conservation	10/29/2021	11/19/2021	04/26/2022
NY	RES DECL	Restrictive Declarations Listing	NYC Department of City Planning	03/22/2022	06/14/2022	09/02/2022
NY	RGA HWS	Recovered Government Archive State Hazardous Waste Facilitie	Department of Environmental Conservation		07/01/2013	12/30/2013
NY	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Environmental Conservation		07/01/2013	01/10/2014
NY	SHWS	Inactive Hazardous Waste Disposal Sites in New York State	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	SPDES	State Pollutant Discharge Elimination System	Department of Environmental Conservation	03/25/2022	05/05/2022	05/18/2022
NY	SPILLS	Spills Information Database	Department of Environmental Conservation	05/09/2022	05/11/2022	08/02/2022
NY	SPILLS 80	SPILLS80 data from FirstSearch	FirstSearch	11/02/2010	01/03/2013	03/07/2013
NY	SPILLS 90	SPILLS90 data from FirstSearch	FirstSearch	12/14/2012	01/03/2013	02/12/2013
NY	SWF/LF	Facility Register	Department of Environmental Conservation	06/29/2022	06/30/2022	09/15/2022
NY	SWRCY	Registered Recycling Facility List	Department of Environmental Conservation	06/29/2022	06/30/2022	09/15/2022
NY	SWTIRE	Registered Waste Tire Storage & Facility List	Department of Environmental Conservation	02/27/2018	04/06/2018	06/08/2018
NY	TANKS	Storage Tank Faciliy Listing	Department of Environmental Conservation	06/21/2022	06/21/2022	09/09/2022
NY	UIC	Underground Injection Control Wells	Department of Environmental Conservation	05/30/2022	05/31/2022	08/17/2022
NY	UST	Petroleum Bulk Storage (PBS) Database	Department of Environmental Conservation	06/21/2022	06/21/2022	09/09/2022
NY	VAPOR REOPENED	Vapor Intrusion Legacy Site List	Department of Environmenal Conservation	01/01/2022	02/08/2022	05/06/2022

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
NY	VCP	Voluntary Cleanup Agreements	Department of Environmental Conservation	05/09/2022	05/11/2022	08/01/2022
NY	VCP NYC	Voluntary Cleanup Program Listing NYC	New York City Office of Environmental Protect	06/06/2022	06/07/2022	08/25/2022
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	ABANDONED MINES	Abandoned Mines	Department of Interior	06/14/2022	06/15/2022	08/22/2022
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2019	03/02/2022	03/25/2022
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2020	11/30/2021	02/22/2022
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	01/12/2017	03/05/2019	11/11/2019
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	03/31/2022	04/14/2022	07/12/2022
US	CORRACTS	Corrective Action Report	EPA	06/20/2022	06/21/2022	06/28/2022
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/06/2021	05/21/2021	08/11/2021
US	DOD	Department of Defense Sites	USGS	06/07/2021	07/13/2021	03/09/2022
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	01/02/2020	01/28/2020	04/17/2020
US	Delisted NPL	National Priority List Deletions	EPA	07/26/2022	08/02/2022	08/22/2022
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	04/02/2022	04/05/2022	06/28/2022
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EPA WATCH LIST	EPA WATCH LIST	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	06/14/2022	06/15/2022	06/21/2022
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	05/25/2021	06/24/2021	09/20/2021
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	04/02/2018	04/11/2018	11/06/2019
US	FEMA UST	Underground Storage Tank Listing	FEMA	10/14/2021	11/05/2021	02/01/2022
US	FINDS	Facility Index System/Facility Registry System	EPA	05/13/2022	05/18/2022	05/31/2022
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	05/11/2022	05/17/2022	07/29/2022
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	05/16/2022	05/17/2022	07/29/2022
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	07/26/2021	07/27/2021	10/22/2021
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	03/21/2022	03/21/2022	06/14/2022
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	04/01/2014	08/06/2014	01/29/2015
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	04/28/2021	06/11/2021	09/07/2021
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	04/20/2022	06/13/2022	08/16/2022
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	06/02/2022	06/13/2022	08/31/2022
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	04/11/2022	06/13/2022	08/16/2022
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	04/28/2022	06/13/2022	08/16/2022
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	04/14/2022	06/13/2022	08/16/2022
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	04/20/2022	06/13/2022	08/16/2022
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	04/08/2022	06/13/2022	08/16/2022
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	INDIAN RESERV	Indian Reservations	USGS	12/31/2014	07/14/2015	01/10/2017
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	04/07/2022	06/13/2022	08/16/2022
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	04/20/2022	06/13/2022	08/16/2022
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	06/02/2022	06/13/2022	08/31/2022

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 5	04/11/2022	06/13/2022	08/16/2022
US	INDIAN UST R6	Underground Storage Tanks on Indian Land	EPA Region 6	04/28/2022	06/13/2022	08/16/2022
US	INDIAN UST R7	Underground Storage Tanks on Indian Land	EPA Region 7	04/14/2022	06/13/2022	08/16/2022
US	INDIAN UST R8	Underground Storage Tanks on Indian Land	EPA Region 8	04/20/2022	06/13/2022	08/16/2022
US	INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	04/08/2022	06/13/2022	08/16/2022
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	07/26/2022	08/02/2022	08/22/2022
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	07/26/2022	08/02/2022	08/22/2022
US	LUCIS	Land Use Control Information System	Department of the Navy	05/16/2022	05/19/2022	07/29/2022
US	MINES MRDS	Mineral Resources Data System	USGS	04/06/2018	10/21/2019	10/24/2019
US	MINES VIOLATIONS	MSHA Violation Assessment Data	DOL, Mine Safety & Health Admi	03/21/2022	03/22/2022	03/25/2022
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	06/10/2022	06/14/2022	08/22/2022
US	NPL	National Priority List	EPA	07/26/2022	08/02/2022	08/22/2022
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	PADS	PCB Activity Database System	EPA	01/20/2022	01/20/2022	03/25/2022
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	09/13/2019	11/06/2019	02/10/2020
US	PCS	Permit Compliance System	EPA, Office of Water	07/14/2011	08/05/2011	09/29/2011
US	PCS ENF	Enforcement data	EPA	12/31/2014	02/05/2015	03/06/2015
US	PCS INACTIVE	Listing of Inactive PCS Permits	EPA	11/05/2014	01/06/2015	05/06/2015
US	PRP	Potentially Responsible Parties	EPA	07/26/2022	08/02/2022	08/31/2022
US	Proposed NPL	Proposed National Priority List Sites	EPA	07/26/2022	08/02/2022	08/22/2022
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RADINFO	Radiation Information Database	Environmental Protection Agency	07/01/2019	07/01/2019	09/23/2019
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	06/20/2022	06/21/2022	06/28/2022
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	06/20/2022	06/21/2022	06/28/2022
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	06/20/2022	06/21/2022	06/28/2022
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	06/20/2022	06/21/2022	06/28/2022
US	RCRA-VSQG	RCRA - Very Small Quantity Generators (Formerly Conditionall	Environmental Protection Agency	06/20/2022	06/21/2022	06/28/2022
US	RMP	Risk Management Plans	Environmental Protection Agency	04/27/2022	05/04/2022	05/10/2022
US	ROD	Records Of Decision	EPA	07/26/2022	08/02/2022	08/22/2022
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	01/01/2017	02/03/2017	04/07/2017
US	SEMS	Superfund Enterprise Management System	EPA	07/26/2022	08/02/2022	08/22/2022
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	07/26/2022	08/02/2022	08/22/2022
US	SSTS	Section 7 Tracking Systems	EPA	07/18/2022	07/18/2022	07/29/2022
US	TRIS	Toxic Chemical Release Inventory System	EPA	12/31/2018	08/14/2020	11/04/2020
US	TSCA	Toxic Substances Control Act	EPA	12/31/2016	06/17/2020	09/10/2020
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	08/30/2019	11/15/2019	01/28/2020
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (	EPA	10/12/2016	10/26/2016	02/03/2017
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	02/23/2022	03/10/2022	03/10/2022
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	04/30/2022	05/24/2022	07/29/2022
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	05/16/2022	05/24/2022	07/29/2022
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	06/20/2022	06/21/2022	08/31/2022
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	04/30/2022	05/24/2022	07/29/2022

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	US INST CONTROLS	Institutional Controls Sites List	Environmental Protection Agency	05/16/2022	05/24/2022	07/29/2022
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	08/03/2022	08/17/2022	08/31/2022
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	05/06/2020	05/27/2020	08/13/2020
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
US	UXO	Unexploded Ordnance Sites	Department of Defense	12/31/2020	01/11/2022	02/14/2022
CT	CT MANIFEST	Hazardous Waste Manifest Data	Department of Energy & Environmental Protecti	05/08/2022	05/09/2022	07/28/2022
NJ	NJ MANIFEST	Manifest Information	Department of Environmental Protection	12/31/2018	04/10/2019	05/16/2019
PA	PA MANIFEST	Manifest Information	Department of Environmental Protection	06/30/2018	07/19/2019	09/10/2019
RI	RI MANIFEST	Manifest information	Department of Environmental Management	12/31/2020	11/30/2021	02/18/2022
VT	VT MANIFEST	Hazardous Waste Manifest Data	Department of Environmental Conservation	10/28/2019	10/29/2019	01/09/2020
WI	WI MANIFEST	Manifest Information	Department of Natural Resources	05/31/2018	06/19/2019	09/03/2019
US	AHA Hospitals	Sensitive Receptor: AHA Hospitals	American Hospital Association, Inc.			
US	Medical Centers	Sensitive Receptor: Medical Centers	Centers for Medicare & Medicaid Services			
US	Nursing Homes	Sensitive Receptor: Nursing Homes	National Institutes of Health			
US	Public Schools	Sensitive Receptor: Public Schools	National Center for Education Statistics			
US	Private Schools	Sensitive Receptor: Private Schools	National Center for Education Statistics			
NY	Daycare Centers	Sensitive Receptor: Day Care Providers	Department of Health			
US	Flood Zones	100-year and 500-year flood zones	Emergency Management Agency (FEMA)			
US	NWI	National Wetlands Inventory	U.S. Fish and Wildlife Service			
NY	State Wetlands	Freshwater Wetlands	Department of Environmental Conservation			
US	Topographic Map		U.S. Geological Survey			
US	Oil/Gas Pipelines		Endeavor Business Media			
US	Electric Power Transmission Line Data		Endeavor Business Media			

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

296 4TH AVENUE
296 4TH AVENUE
BROOKLYN, NY 11215

TARGET PROPERTY COORDINATES

Latitude (North):	40.675577 - 40ˆ 40’ 32.08’’
Longitude (West):	73.985041 - 73ˆ 59’ 6.15’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	585779.8
UTM Y (Meters):	4503028.0
Elevation:	23 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019
West Map:	14317809 JERSEY CITY, NJ
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 23 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970211F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970203F	FEMA FIRM Flood data
3604970192F	FEMA FIRM Flood data
3604970063B	FEMA Q3 Flood data
3604970073B	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/4 - 1/2 Mile NW
Site Name:	Vidan Auto Salvage
Site EPA ID Number:	NYD986961167
Groundwater Flow Direction:	SW TOWARD THE NARROWS.
Inferred Depth to Water:	approximately 38 feet.
Hydraulic Connection:	The surficial aquifer and underlying aquifer are hydraulically connected.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000828170	0 - 1/8 Mile SSE
B4	USGS40000828295	0 - 1/8 Mile NNE
B5	USGS40000828296	0 - 1/8 Mile NNE
B6	USGS40000828294	0 - 1/8 Mile NNE
7	USGS40000828120	1/8 - 1/4 Mile South
8	USGS40000828114	1/4 - 1/2 Mile SSW
C9	USGS40000828117	1/4 - 1/2 Mile SW
C10	USGS40000828115	1/4 - 1/2 Mile SW
13	USGS40000828297	1/4 - 1/2 Mile WNW
14	USGS40000828092	1/4 - 1/2 Mile SSW
E15	USGS40000828284	1/4 - 1/2 Mile ENE
E16	USGS40000828293	1/4 - 1/2 Mile ENE
17	USGS40000828070	1/4 - 1/2 Mile SSE
F18	USGS40000828124	1/4 - 1/2 Mile WSW
F19	USGS40000828125	1/4 - 1/2 Mile WSW
20	USGS40000828469	1/4 - 1/2 Mile NNE
21	USGS40000828165	1/2 - 1 Mile West
26	USGS40000828265	1/2 - 1 Mile West
H27	USGS40000828451	1/2 - 1 Mile NE
I28	USGS40000828018	1/2 - 1 Mile SW
H29	USGS40000828468	1/2 - 1 Mile NE
30	USGS40000828478	1/2 - 1 Mile NW
I31	USGS40000828019	1/2 - 1 Mile SW
J32	USGS40000828512	1/2 - 1 Mile NNW
J33	USGS40000828518	1/2 - 1 Mile NNW
K34	USGS40000828532	1/2 - 1 Mile North
35	USGS40000828501	1/2 - 1 Mile NNW
K36	USGS40000828544	1/2 - 1 Mile North
37	USGS40000827905	1/2 - 1 Mile SSW
38	USGS40000828444	1/2 - 1 Mile NW
39	USGS40000828549	1/2 - 1 Mile North
40	USGS40000828443	1/2 - 1 Mile NE
41	USGS40000828523	1/2 - 1 Mile NNE
L42	USGS40000828020	1/2 - 1 Mile WSW
L43	USGS40000828021	1/2 - 1 Mile WSW
44	USGS40000828558	1/2 - 1 Mile NNE
45	USGS40000828410	1/2 - 1 Mile WNW
M46	USGS40000828587	1/2 - 1 Mile NNE
N47	USGS40000828183	1/2 - 1 Mile West
N48	USGS40000828193	1/2 - 1 Mile West
M49	USGS40000828602	1/2 - 1 Mile North
M50	USGS40000828606	1/2 - 1 Mile NNE
51	USGS40000828601	1/2 - 1 Mile NNE
O52	USGS40000828620	1/2 - 1 Mile North
O53	USGS40000828619	1/2 - 1 Mile NNE
O54	USGS40000828627	1/2 - 1 Mile North
P56	USGS40000828254	1/2 - 1 Mile West
P57	USGS40000828200	1/2 - 1 Mile West
58	USGS40000828339	1/2 - 1 Mile West

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	NYREG1000000232	0 - 1/8 Mile SE
A3	NYREG1000000233	0 - 1/8 Mile SE
D11	NYREG1000000080	1/4 - 1/2 Mile West
D12	NYREG1000000081	1/4 - 1/2 Mile West
G22	NYREG1000000090	1/2 - 1 Mile ENE
G23	NYREG1000000089	1/2 - 1 Mile ENE
G24	NYREG1000000158	1/2 - 1 Mile East
G25	NYREG1000000159	1/2 - 1 Mile East
55	NYREG1000000125	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 07124126.2r



0 1/4 1/2 1 Miles

- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	296 4th Avenue	CLIENT:	Haley & Aldrich, Inc.
ADDRESS:	296 4th Avenue Brooklyn NY 11215	CONTACT:	Sarah Commisso
		INQUIRY #:	07124126.2r
LAT/LONG:	40.675577 / 73.985041	DATE:	September 20, 2022 5:24 pm

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
A1 **SSE** **0 - 1/8 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828170**
A2 **SE** **0 - 1/8 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000232**
A3 **SE** **0 - 1/8 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000233**
B4 **NNE** **0 - 1/8 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828295**
B5 **NNE** **0 - 1/8 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828296**
B6 **NNE** **0 - 1/8 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828294**
7 **South** **1/8 - 1/4 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828120**
8 **SSW** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828114**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
C9 **SW** **1/4 - 1/2 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828117**
C10 **SW** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828115**
D11 **West** **1/4 - 1/2 Mile** **Lower**	Click here for full text details	**NY WELLS**	**NYREG1000000080**
D12 **West** **1/4 - 1/2 Mile** **Lower**	Click here for full text details	**NY WELLS**	**NYREG1000000081**
13 **WNW** **1/4 - 1/2 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828297**
14 **SSW** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828092**
E15 **ENE** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828284**
E16 **ENE** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828293**
17 **SSE** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828070**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
F18 **WSW** **1/4 - 1/2 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828124**
F19 **WSW** **1/4 - 1/2 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828125**
20 **NNE** **1/4 - 1/2 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828469**
21 **West** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828165**
G22 **ENE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000090**
G23 **ENE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000089**
G24 **East** **1/2 - 1 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000158**
G25 **East** **1/2 - 1 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000159**
26 **West** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828265**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
H27 **NE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828451**
I28 **SW** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828018**
H29 **NE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828468**
30 **NW** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828478**
I31 **SW** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828019**
J32 **NNW** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828512**
J33 **NNW** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828518**
K34 **North** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828532**
35 **NNW** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828501**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
K36 **North** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828544**
37 **SSW** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000827905**
38 **NW** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828444**
39 **North** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828549**
40 **NE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828443**
41 **NNE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828523**
L42 **WSW** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828020**
L43 **WSW** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828021**
44 **NNE** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828558**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
45 WNW 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828410**
M46 NNE 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828587**
N47 West 1/2 - 1 Mile Lower	Click here for full text details	**FED USGS**	**USGS40000828183**
N48 West 1/2 - 1 Mile Lower	Click here for full text details	**FED USGS**	**USGS40000828193**
M49 North 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828602**
M50 NNE 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828606**
51 NNE 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828601**
O52 North 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828620**
O53 NNE 1/2 - 1 Mile Higher	Click here for full text details	**FED USGS**	**USGS40000828619**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
O54 **North** **1/2 - 1 Mile** **Higher**	Click here for full text details	**FED USGS**	**USGS40000828627**
55 **NNW** **1/2 - 1 Mile** **Higher**	Click here for full text details	**NY WELLS**	**NYREG1000000125**
P56 **West** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828254**
P57 **West** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828200**
58 **West** **1/2 - 1 Mile** **Lower**	Click here for full text details	**FED USGS**	**USGS40000828339**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Lance, Samantha

From: George.Bogdan@dfs.ny.gov
Sent: Friday, September 9, 2022 12:25 PM
To: Lance, Samantha; George.Bogdan@dfs.ny.gov
Subject: your inquiry re specific property in Brooklyn FOIL-2022-092258-018114

CAUTION: External Email

Dear Ms. Lance;

You made the following Freedom of Information Law request to the NY State Department of Financial Services (DFS):

Any reports regarding property transactions, including deeds, leases, and mortgage documents for 296 4th Avenue/27 Denton Place, Brooklyn, NY

DFS does not maintain property records of this type, so DFS has no records responsive to your request. County Clerks maintain such property records (except for leases). In New York City, the NYC Department of Finance maintains these records. They are available online via ACCRIS: https://a836-acris.nyc.gov/CP/

Sincerely,
George Bogdan
DFS Records Access Officer

Tracking Number:FOIL-2022-092258-018114

Lance, Samantha

From: donotreply@records.nyc.gov
Sent: Monday, September 19, 2022 10:26 AM
To: Lance, Samantha
Subject: [OpenRecords] Response Added to FOIL-2022-810-04280 - Link

CAUTION: External Email

The Department of Buildings (DOB) has responded to your FOIL request FOIL-2022-810-04280 with the following link.

Permits link: https://a810-bisweb.nyc.gov/bisweb/PermitsInProcessIssuedByBinServlet?requestid=3&allbin=3330269

Please visit FOIL-2022-810-04280 to view additional information and take any necessary action.

Lance, Samantha

From: donotreply@records.nyc.gov
Sent: Monday, September 19, 2022 10:27 AM
To: Lance, Samantha
Subject: [OpenRecords] Response Added to FOIL-2022-810-04280 - Link

CAUTION: External Email

The Department of Buildings (DOB) has responded to your FOIL request FOIL-2022-810-04280 with the following link.

Jobs Link: https://a810-bisweb.nyc.gov/bisweb/JobsQueryByLocationServlet?requestid=3&allbin=3330269

Please visit FOIL-2022-810-04280 to view additional information and take any necessary action.

Lance, Samantha

From: donotreply@records.nyc.gov
Sent: Monday, September 19, 2022 10:34 AM
To: Lance, Samantha
Subject: [OpenRecords] Response Added to FOIL-2022-810-04280 - File

CAUTION: External Email

The Department of Buildings (DOB) has responded to your FOIL request FOIL-2022-810-04280 with the following file(s).

The file(s) listed below will not be publicly available on the OpenRecords portal.

- Certificate of Occupancy: B000075962.pdf
- Certificate of Occupancy: 301623722.pdf
- Certificate of Occupancy : B000075957.pdf
- Certificate of Occupancy: B000108643.pdf

Please visit FOIL-2022-810-04280 to view additional information and take any necessary action.

Lance, Samantha

From: donotreply@records.nyc.gov
Sent: Monday, September 19, 2022 10:39 AM
To: Lance, Samantha
Subject: [OpenRecords] Response Added to FOIL-2022-810-04280 - Offline Access Instructions

CAUTION: External Email

The Department of Buildings (DOB) has responded to your FOIL request FOIL-2022-810-04280 with the following instructions for offline access.

You were provided with direct links to the records available online. All other records were not responsive.

For the asbestos documents you can find in the Jobs link provided; under the virtual folder in each job number. You may also reach out to DEP(dept of environmental protection)

Please visit FOIL-2022-810-04280 to view additional information and take any necessary action.

Lance, Samantha

From: donotreply@records.nyc.gov
Sent: Monday, September 19, 2022 10:40 AM
To: Lance, Samantha
Subject: [OpenRecords] Request FOIL-2022-810-04280 Closed

CAUTION: External Email

The Department of Buildings (DOB) has **closed** your FOIL request FOIL-2022-810-04280 for the following reasons:

- Your request under the Freedom of Information Law (FOIL) is being closed. Your request is being fulfilled in part and denied in part. The Department is releasing a copy of the records we located. All other requested records were not found.
- Your request under the Freedom of Information Law (FOIL) is being closed because this agency does not have the records requested. You should direct your request to a different agency.
- Your request under the Freedom of Information Law (FOIL) is being closed because the document or information you requested is publicly available.

Please visit FOIL-2022-810-4280 to view additional information and take any necessary action. You have the right to appeal this determination by writing to Deborah Glikin, FOIL Appeals Officer, 280 Broadway, 7th Floor, New York, NY 10007 or you may email her at DGlikin@buildings.nyc.gov , within 30 days of the date of this letter.

Lance, Samantha

From: New York DEC FOIL Center <newyorkdec@govqa.us>
Sent: Tuesday, September 20, 2022 1:22 PM
To: Lance, Samantha
Subject: Freedom of Information Law Request :: W106707-092022

CAUTION: External Email

Region 2 - Long Island City
P: (718) 482-4912 | F:
www.dec.ny.gov

RE: PUBLIC RECORDS REQUEST of 9/20/2022, Reference # W106707-092022

Date: 09/20/2022

Dear Samantha Lance,

I write in response to your Freedom of Information Law (FOIL) request seeking:

> *Any environmental reports for 21 Denton Place, Brooklyn, NY pertaining to current or previous investigation, spills, or remediation. Reports we seek include any remedial investigation work plans, remedial investigation reports, remedial action work plans, remedial action reports, remedial closure reports, spill reports, and tank installation/closure documentation.*

Please be advised that a diligent search of the files maintained by DEC produced no responsive records.

If you believe you have been unlawfully denied access to responsive records, you have the right to appeal. Any such appeal must be submitted in writing and within thirty (30) days of the date of this email. Appeals must be directed to:

FOIL Appeals Officer
Office of General Counsel
New York State Department of Environmental Conservation
625 Broadway, 14th Floor
Albany, NY 12233-1500

Your FOIL request is now closed. If I can be of further assistance, please contact me at (718) 482-4912 and reference FOIL #W106707-092022, or simply reply to this email. Thank you.

Sincerely,

Region 2 FOIL Coordinator

Lance, Samantha

From: New York DEC FOIL Center <newyorkdec@govqa.us>
Sent: Tuesday, September 20, 2022 3:32 PM
To: Lance, Samantha
Subject: Freedom of Information Law Request :: W106708-092022

CAUTION: External Email

Region 2 - Long Island City
P: (718) 482-4912 | F:
www.dec.ny.gov

RE: PUBLIC RECORDS REQUEST of 9/20/2022, Reference # W106708-092022

Date: 09/20/2022

Dear Samantha Lance,

I write in response to your Freedom of Information Law (FOIL) request seeking:

> *Any environmental reports for 284 4th Avenue, Brooklyn, NY 11215 pertaining to current or previous investigation, spills, or remediation. Reports we seek include any remedial investigation work plans, remedial investigation reports, remedial action work plans, remedial action reports, remedial closure reports, spill reports, and tank installation/closure documentation.*

Please be advised that a diligent search of the files maintained by DEC produced no responsive records.

If you believe you have been unlawfully denied access to responsive records, you have the right to appeal. Any such appeal must be submitted in writing and within thirty (30) days of the date of this email. Appeals must be directed to:

FOIL Appeals Officer
Office of General Counsel
New York State Department of Environmental Conservation
625 Broadway, 14th Floor
Albany, NY 12233-1500

Your FOIL request is now closed. If I can be of further assistance, please contact me at (718) 482-4912 and reference FOIL #W106708-092022, or simply reply to this email. Thank you.

Sincerely,

Region 2 FOIL Coordinator

Lance, Samantha

From: New York DEC FOIL Center <newyorkdec@govqa.us>
Sent: Tuesday, September 20, 2022 3:33 PM
To: Lance, Samantha
Subject: Freedom of Information Law Request :: W106709-092022

CAUTION: External Email

Region 2 - Long Island City
P: (718) 482-4912 | F:
www.dec.ny.gov

RE: PUBLIC RECORDS REQUEST of 9/20/2022, Reference # W106709-092022

Date: 09/20/2022

Dear Samantha Lance,

I write in response to your Freedom of Information Law (FOIL) request seeking:

> *Any environmental reports for 290 4th Avenue, Brooklyn, NY 11215 pertaining to current or previous investigation, spills, or remediation. Reports we seek include any remedial investigation work plans, remedial investigation reports, remedial action work plans, remedial action reports, remedial closure reports, spill reports, and tank installation/closure documentation.*

Please be advised that a diligent search of the files maintained by DEC produced no responsive records.

If you believe you have been unlawfully denied access to responsive records, you have the right to appeal. Any such appeal must be submitted in writing and within thirty (30) days of the date of this email. Appeals must be directed to:

FOIL Appeals Officer
Office of General Counsel
New York State Department of Environmental Conservation
625 Broadway, 14th Floor
Albany, NY 12233-1500

Your FOIL request is now closed. If I can be of further assistance, please contact me at (718) 482-4912 and reference FOIL #W106709-092022, or simply reply to this email. Thank you.

Sincerely,

Region 2 FOIL Coordinator

Lance, Samantha

From: donotreply@records.nyc.gov
Sent: Friday, September 9, 2022 2:00 PM
To: Lance, Samantha
Subject: [OpenRecords] Request FOIL-2022-002-00726 Closed

CAUTION: External Email

The Mayor's Office of Environmental Remediation (OER) has **denied** your FOIL request FOIL-2022-002-00726 for the following reasons:

- A diligent search for records responsive to your request did not locate any such records. Accordingly, your request is denied.
- General information about E-Designation E-601 is available on OER's website at https://www1.nyc.gov/site/oer/remediation/ceqr-documents.page?borough=Brooklyn

Please visit FOIL-2022-002-00726 to view additional information and take any necessary action. You may appeal the decision to deny access to material that was redacted in part or withheld in entirety by contacting the agency's FOIL Appeals Officer: foil-oer@cityhall.nyc.gov within 30 days.

APPENDIX E
Site Photographs

296 4th Avenue
New York, NY
File No. 0206616
Date Photographs Taken: 28 September 2022



Photo 1: Entrance to Lot 6 on subject property from Denton Place, facing southeast

Photo 2: Tires stored on Lot 6 on subject property, facing south

Photo 3: Indications of an abandoned well and soil boring on Lot 6, facing north/northeast

Photo 4: 4th Avenue entrance to subject property building on Lot 1, facing northwest

Photo 5: View of car wash operation on Lot 1, facing north.



Photo 6: Staining observed inside subject property building on Lot 1, facing northwest

Photo 7: Staining observed in subject property building on Lot 1, facing northeast

Photo 8: Staining observed in subject property building on Lot 1, facing northeast



Photo 9: Electric lift inside subject property building on Lot 1, facing northeast

Photo 10: Store located on subject property Lot 1, facing northwest

Photo 11: Lot 34 on subject property, facing northwest

Photo 12: 4th Avenue entrance to subject property building on Lot 32, facing northwest

Photo 13: North-adjacent commercial and residential buildings, facing south/southwest

Photo 14: 4th Avenue, followed by east-adjacent mixed-use and commercial buildings, facing east/northeast

Photo 15: First Street, followed by south-adjacent commercial building, facing southwest

Photo 16: Denton Place, followed by west-adjacent public school, facing west