WEST 42nd STREET
MANUFACTURED GAS PLANT
SITE HISTORY REPORT

Prepared For:

ConEdison

Consolidated Edison Company of New York, Inc.

31-01 20th Avenue
Long Island City, New York 11105

Prepared By:

Parsons

290 Elwood Davis Road, Suite 312
Liverpool, New York 13088
Phone: (315) 451-9560
Fax: (315) 451-9570

AUGUST 2002

Report For:

WEST 42nd STREET MANUFACTURED GAS PLANT SITE HISTORY REPORT

Prepared For:

Consolidated Edison Company of New York, Inc.

31-01 20th Avenue
Long Island City, NY 11105

Prepared By:

PARSONS

290 Elwood Davis Road, Suite 312
Liverpool, New York 13088
Phone: (315) 451-9560
Fax: (315) 451-9570

REVIEWED AND APPROVED BY:

Project Manager: Matt B. Williams 8-5-02
Date

Technical Manager: Greg Morris 8/6/02
Date

AUGUST 2002

TABLE OF CONTENTS

Page

EXECUTIVE SUMMARY **E-1**

SECTION 1 OBJECTIVE **1-1**

1.1 PROJECT BACKGROUND 1-1

1.2 PURPOSE 1-1

1.3 INVESTIGATION METHODOLOGY 1-1

SECTION 2 PROPERTY DESCRIPTION **2-1**

2.1 PROPERTY DESCRIPTON 2-1

SECTION 3 CURRENT USAGE **3-1**

3.1 GENERAL 3-1

3.2 BLOCK 1089 LAND USE 3-1

3.3 BLOCK 1107 LAND USE 3-2

SECTION 4 SITE SETTING **4-1**

4.1 INTRODUCTION 4-1

4.2 DEMOGRAPHY 4-1

4.3 ZONING 4-1

4.4 CHARACTERISTICS OF NEIGHBORING PROPERTIES 4-2

4.5 TOPOGRAPHY AND SURFACE WATER DRAINAGE 4-2

4.6 REGIONAL GEOLOGY 4-3

4.7 SITE GEOLOGY 4-3

4.8 HYDROLOGY/HYDROGEOLOGY 4-3

SECTION 5 PAST OWNERSHIP **5-1**

5.1 INTRODUCTION 5-1

TABLE OF CONTENTS
(CONTINUED)

PAGE

5.2 PRE-MGP OWNERSHIP AND USE 5-1

5.3 MGP HISTORY 5-1

5.4 POST-MGP OWNERSHIP AND USE 5-4

5.5 SUMMARY 5-5

SECTION 6 PAST SITE OPERATIONS 6-1

6.1 INTRODUCTION 6-1

6.2 PRE-MGP OPERATIONS 6-1
6.2.1 Summary of Pre-MGP Operations 6-1
6.2.2 Pre-MGP Wastes and Byproducts 6-1

6.3 MGP OPERATIONS 6-2
6.3.1 Summary of Site Gas Production 6-2
6.3.2 Process Configurations 6-3
6.3.3 By-Products and Waste Disposal 6-4

6.4 POST-MGP OPERATIONS 6-5

6.5 SUMMARY OF OPERATIONAL HISTORY 6-6

SECTION 7 ENVIRONMENTAL/REGULATORY AGENCIES AND DATABASES 7-1

7.1 EDR PROFILE SEARCH 7-1

7.2 ADDITIONAL RECORDS SOURCES 7-3

SECTION 8 POTENTIAL RECEPTORS 8-1

8.1 SENSITIVE AREAS 8-1

SECTION 9 DISCUSSION AND CONCLUSIONS 9-1

9.1 DISCUSSION AND CONCLUSIONS 9-1

9.2 COMPLETENESS OF RESEARCH 9-2

TABLE OF CONTENTS
(CONTINUED)

PAGE

SECTION 10 SUMMARY OF HISTORICAL RESEARCH FINDINGS 10-1

10.0 PRIORITIZATION SUMMARY AND CONCLUSIONS 10-1

SECTION 11 REFERENCES 11-1

LIST OF TABLES

Table 3.1 Former MGP Lots In Block 1092 3-1

Table 4.1 Former MGP Lots In Block 1092 4-2

Table 4.2 Former MGP Lots In Block 1107 4-2

Table 5.1 Block 1089 – Property Transfers 5-5

Table 6.1 Gas Production at the West 42nd Street MGP (PSC Reports) 6-2

Table 6.2 Coal Gas Materials For Year (Psc 1908) 6-4

Table 6.3 Coal Gas Residuals For Year (Psc 1908) 6-5

Table 6.4 Block 1089 – Tax Lot 1 6-6

Table 6.5 Block 1089 – Tax Lot 3 6-7

Table 7.1 Summary of Environmental Database Findings (Mappable Sites) 7-2

Table 7.2 Summary Of Environmental Database Findings (Unmappable Sites) 7-3

Table 8.1 Potential Sensitive Receptors and Areas 8-1

Table 8.2 Potential Exposure Pathways 8-2

Table 10.1 Prioritization Criteria and Factors 10-1

TABLE OF CONTENTS
(CONTINUED)

LIST OF FIGURES

Figure 1 Site Location Map

Figure 2 Site Map

Figure 3 Site Map with Former Structures

Figure 4 1836 Colton Map

Figure 5 1865 Viele Map

Figure 6 1852 Dripps Map

Figure 7 1867 Dripps Map

Figure 8a and 8b 1871 Perris and Browne Map

Figure 9 1879 Taylor Bird's Eye View Drawing

Figure 10 1880 Perris and Browne Map

Figure 11 1890 Sanborn Map

Figure 12 1899 Sanborn Map

Figure 13a and 13b 1911 Sanborn Map

Figure 14a and 14b 1930 Sanborn Map

Figure 15a and 15b 1950 Sanborn Map

Figure 16a and 16b 1968 Sanborn Map

Figure 17a and 17b 1980 Sanborn Map

Figure 18a and 18b 1984 Sanborn Map

Figure 19a and 19b 1988 Sanborn Map

Figure 20a and 20b 1992 Sanborn Map

Figure 21a and 21b 1996 Sanborn Map

TABLE OF CONTENTS
(CONTINUED)

LIST OF APPENDICES

APPENDIX A SITE PHOTOGRAPHS

APPENDIX B EDR REPORT

APPENDIX C DATA

APPENDIX D TITLE SEARCH REPORT

EXECUTIVE SUMMARY

Consolidated Edison Company of New York (Con Edison) contracted Parsons to conduct historical research of former manufactured gas plants (MGPs) and associated facilities that were used either by Con Edison or predecessor companies of Con Edison. Parsons was assigned a group of sites located in the Borough of Manhattan. This report presents the results of the historical research conducted for the West 42nd Street MGP site. The objective of the MGP research is to obtain information necessary to rank and prioritize the sites for future investigation or other management actions under the pending Voluntary Cleanup Agreement (VAC) between Con Edison and the New York State Department of Environmental Conservation (NYSDEC). In order to meet this objective, data were compiled to provide information on site setting, current and past site ownership and use, MGP development and operations, site physiography and hydrogeology, potential on-site and off-site historic waste materials, and potential public and environmental receptors.

The West 42nd Street Gas Works is a former MGP that formerly existed on Block 1089 and the adjacent waterfront on Block 1107 in the Borough of Manhattan, New York City and New York County, New York. The construction of the West 42nd Street MGP began in 1860. The MGP operated from 1863 into the early 1920s. Block 1089 was sold to the New York Edison Company in 1923 who later sold the property to the New York Central Railroad Company in 1932. Block 1089 was sold to a series of real estate companies beginning in 1967. The rest of the former MGP is under 12th Avenue. The extreme eastern end of modern Pier 81 was part of the site. This area was used for unloading coal from docked barges along the waterfront and for naphtha tanks.

Construction of the basement and parking for the multiple-story River Place apartment and shopping complex on Tax Lot 1 in 1999 to 2000 likely removed all traces of the MGP in that location. The parking lot on Tax Lot 3, on the eastern end of the block, may retain remnants of the former MGP. The portion of the block now under 12th Avenue may also retain parts of the MGP, if they have not been destroyed by roadwork.

The historical research and site reconnaissance identified the following key items for consideration in the prioritization of the former MGP sites:

- The block containing the former West 42nd Street MGP was under water during the 1830s and 1840s, and filled by the 1850s. There was no known development on the property prior to the construction of the MGP beginning in 1860.
- The former West 42nd Street MGP operated from 1863 through the early 1920s on City Block 1089, the waterfront area west of Block 1089, and the area in-between that would become 12th Avenue. The Metropolitan Gas Light Company began production of coal gas in 1863. The Consolidated Gas Company, formed in 1884, continued the gas production. The MGP continued to produce gas from coal until the early 1920s.
- The lots from the former MGP were sold in 1924 and new structures were built on portions of the site after the MGP structures were razed. The disposition of wastes and

byproducts generated by the former MGP is not well documented. The disposition of the materials from the razed structures is not documented.

- Based on the site reconnaissance and historical research, there are no remaining structures at the ground surface that are associated with the former MGP. No visual evidence of impacts or MGP residuals were observed during the site reconnaissance visit.
- Areas of the site that have not had significant excavation and building (Lot 3) may retain subsurface remnants of the former MGP structures and may contain possible MGP residuals.
- The area surrounding the former West 42nd Street MGP is a mixed-use area formerly used for commercial, industrial, warehousing, and residential purposes dating back to the 1800's. The area is close to the Hudson River and piers. Land usage now includes the River Place high-rise apartments and shopping center, the World Yacht tour business, offices buildings, a FedEx shipping center, and a bus depot owned by the New York Transit Authority.
- The Environmental Data Resources, Inc. (EDR) report indicates the potential exists for spills and leaks from other sources within the area. The report identified 10 Resource Conservation and Recovery Information System (RCRIS) small quantity generators and 12 large quantity generators within 0.25 miles of the site. In addition, there are 24 underground storage tanks (USTs), one bulk chemical UST, and two bulk chemical aboveground storage tanks (ASTs) within 0.25 miles and 55 leaking tanks within 0.5 miles of the former MGP. There are two more former MGPs located within one mile of the West 42nd Street MGP.
- Previous investigations were conducted at the former West 42nd Street MGP, a 1995 investigation on Lot 1 prior to the construction of the high-rise apartments and in 2000 in anticipation of development on Lot 3 (Langan, 2002). The 2000 investigation on Lot 3 found SVOCs above NYSDEC TAGMs in soil samples and BTEX and metals in groundwater (Langan, 2002). The May 1994 Final Impact Statement for the Route 9A Reconstruction Project reported BTEX at 13 mg/kg in one groundwater sample collected between 41st and 42nd Street and PAHs were detected in soil samples collected between 41st Street and 46th Street (AKRF, 1994).
- The site is located in an area with mixed commercial and residential use. If impacts are present at the site, potential receptors would include workers, nearby residents, and tourists visiting the World Yacht tour operation and the River Place shopping area. In addition, a public school is approximately 0.25 miles northeast of the site. Most of the former site area is covered with pavement or buildings with the exception of landscaped areas on Lot 1 near the apartments. Exposure pathways for surface and subsurface soil are present. Workers conducting excavation or construction activities could encounter residues in the subsurface from past operations. There is no groundwater usage in the area being investigated.
- The Hudson River is within 200 feet of the former MGP and could be impacted if MGP residuals were migrating from the site or if past disposal practices lead to the disposal of MGP related materials in or near the Hudson River.

SECTION 1

OBJECTIVE

1.1 PROJECT BACKGROUND

Con Edison contracted Parsons to conduct historical research of former MGPs and associated facilities that were either owned by Con Edison or predecessor companies of Con Edison. Parsons was assigned a group of sites located in the Borough of Manhattan. This report presents results of the historical research conducted for the West 42nd Street MGP site located in the Hell's Kitchen section of Manhattan.

1.2 PURPOSE

This report documents results of the historical research completed on the West 42nd Street Former MGP site located between West 41st Street and West 42nd Street and 11th Avenue and 12th Avenue in western Manhattan, New York (Figure 1). All report figures are located between Section 11 and Appendix A. The purpose of the historical research was to:

- Determine the physical limits of the former MGP operations.
- Develop an understanding of past operations at the former MGP.
- Identify products, byproducts, waste handling procedures, waste streams and potential hazardous substances, and the usage of the site to assess potential impacts, if any, to adjacent properties and current site occupants.
- Develop historical and current site data that will support prioritization of the former MGP sites based on potential, actual, and perceived human health exposure risks, environmental impacts, sensitive receptors, current site usage, the surrounding community, potential for development, site control and ownership, and size of the former MGP operation.

1.3 INVESTIGATION METHODOLOGY

Investigations for this report consisted of: 1) historical research to summarize site ownership, occupancy, use, and operations over time (including pre-MGP use, use during MGP operation, and post-MGP use; 2) a site reconnaissance to determine current conditions and neighboring property use; and 3) review of federal, state, and local databases to assess other sites in the vicinity that may be impacting the former MGP site and the neighboring properties.

Research undertaken as part of this report included review of in-house documents and photographs provided by Con Edison, as well as materials gathered at the Municipal Archives of the City of New York, the Municipal Reference and Research Center of the City of New York, the New York City Recorder of Deeds office, the New York City Department of Buildings, the New York Public Library, the Library of Congress, the NYSDEC, the Environmental Protection Agency, and various web sites that post historical maps and journal articles. EDR compiled the radius search data for the site.

The following is a summary of the resources reviewed during the research and preparation of this report; a detailed list of references is provided in Section 11:

- Consolidated Edison internal records and files (including remediation files and reports, real estate records, in-plant property records, and historical photographs);
- Consolidated Edison personnel interviews;
- Historical maps, including Sanborn Fire Insurance Maps, Dripps Maps, Perris and Browne Insurance Maps, Bromley Atlases, and Taylor City Map;
- Deeds and site surveys for the properties;
- Nineteenth century tax assessment records;
- New York City Department of Buildings records;
- Books and articles detailing manufactured gas company histories and operating procedures;
- Manufactured gas industry publications (including the *American Gas Light Journal*, in later years called the *American Gas Journal*);
- Brown's Directory of American Gas Companies;
- Public Service Commission (PSC) reports;
- Nineteenth and twentieth century newspaper and journal articles (such as the *New York Times*);
- Environmental studies undertaken within and adjacent to the properties; and
- EDR radius search information.

Ms. Susan Shelton and Ms. Julie Abell Horn of Parsons conducted the site reconnaissance on April 10, 2002. Tasks included a windshield and pedestrian survey (where possible) of the property, photographing buildings, structures, and roadways on and adjacent to the former MGP site, documenting current conditions and possible receptors, and creating an overall site map.

SECTION 2

PROPERTY DESCRIPTION

2.1 PROPERTY DESCRIPTON

The former West 42nd Street MGP site is located in the Borough of Manhattan, New York City and New York County, New York (Figure 1). The former site occupied approximately five acres and consists of two modern Tax Lots on one city block, the waterfront property west of the block, and the street between them (Figure 2). Specifically, the former site includes all of Block 1089 (now designated Tax Lots 1 and 3), the waterfront property immediately west of Block 1089 (now included as part of Block 1107), and the stretch of 12th Avenue between Block 1089 and the waterfront. Block 1089 is bounded by West 41st Street on the south, West 42nd Street on the north, 11th Avenue on the east, and 12th Avenue on the west. It should be noted that the existing two Tax Lots were historically sold to the Metropolitan Gas Light Company (Con Edison's predecessor company) by individual owners. Section 5 of this report provides detailed histories of the Tax Lots. Figure 3 shows the current street configuration with an overlay of the former MGP structures.

SECTION 3

CURRENT USAGE

3.1 GENERAL

The current usage of the former MGP property was determined from a site reconnaissance conducted on April 10, 2002. The site reconnaissance was supplemented with title search information, tax map information, and aerial photographs. The site is located in a mixed usage area with commercial properties including store front retail facilities to the north, a commercial bus depot owned by the New York Transit Authority to the south, and a commercial yacht tour business located directly west of the site. Details of current land use are described in the following paragraphs. Photographs of the site are provided in the Photolog in Appendix A. Tables 3.1 and 3.2 present a summary of the current ownership and land usage.

3.2 BLOCK 1089 LAND USE

The majority of the former MGP site is on modern Block 1089, Tax Lots 1 and 3 (Figure 2). A high-rise apartment complex occupies approximately 90 percent of Tax Lot 1 (photographs 2, 3, 4, 5, 7, and 8). The remaining portion of the lot consists of a landscaped park-like area (photographs 7 and 8). Tax Lot 3 on the east end of Block 1089 supports a public parking lot (photographs 11, 12, and 19). Access to the public parking lot may be obtained from both 11th Avenue and 41st Street. During the site inspection performed on April 10, 2002, the parking lot on Tax Lot 3 appeared to encompass the entire Tax Lot. The parking lot consisted of concrete and asphalt pavement. In some areas, asphalt patch appeared to cover cracks and/or areas of degraded concrete. The surface of the parking area did not appear to be flat and even. Some areas of the parking lot appeared to gently undulant. The parking lot is in the same area as four former gasholders that were utilized during historic MGP site operations dating back to the mid-1800s.

Table 3.1 – Former MGP Lots In Block 1089

Lot Number	Current Owner	Current Usage
Lot 1	River Place I, LLC	High-rise apartment building.
Lot 3	River Place II, LLC	Concrete and asphalt parking lot.

Block 1089, Lots 1 and 3, C6-4 – General Central Commercial District with a restrictive declaration of D-129

No remnants of former MGP were observed on this block during the site inspection performed on April 10, 2002. Due to limited site access, the status and condition of the building interiors could not be verified. No hazardous waste and/or petroleum usage, storage, and/or disposal were observed at any of the structures on Block 1089 during the site visit. No municipal solid waste containers were observed along the exterior of the high-rise apartment building. With the exception of wind-blown refuse and general litter, the area appeared well maintained.

3.3 BLOCK 1107 LAND USE

Block 1107 is a portion of the existing waterfront located west of Blocks 1089. This area was historically part of MGP operations at the West 42nd Street MGP. The area is currently occupied by the West Side Highway and piers along the Hudson River. The World Yacht tour operation is located in this area along the waterfront (photographs 1 and 4).

SECTION 4

SITE SETTING

4.1 INTRODUCTION

This section describes the current zoning, characteristics of the neighboring properties, topography, demography, geology, and hydrogeology. Information in this section was developed during the site reconnaissance visit conducted on April 10, 2002 and through the collection and review of New York City tax and zoning files, historical reports, and the radius search report.

4.2 DEMOGRAPHY

The population of Manhattan Borough is 1,537,195 people. Census Tract 117 encompasses Block 1089 and the two blocks to the south and the four blocks to the east and southeast. According to the 2000 Census, Census Tract 117 is not very populous. The Census lists the total population as 340 people with a median age of 8.3 years. Approximately 55 percent of the residents are Black, 27 percent are White, and the remaining 18 percent are some other race(s). There are 23 renter-occupied housing units and one owner occupied unit. These statistics appear to be out of date or in error. The River Place apartment high-rise, on Block 1089 reportedly has 921 units. Assuming an occupancy of 1.8 people per unit, more than 1,600 people could be housed at the River Place apartments. Block 1089 borders Census Tract 129. Census Tract 129 encompasses 16 Blocks north and northeast of the former MGP. The population in Census Tract 129 is 4,457 people. The population is approximately 63 percent white with the rest of the population being ethnically diverse. The median age is 33.4 years. There are more male residents than female. There are 2,327 households in Tract 129. Approximately 85.5 percent of housing (1990 units) is renter occupied housing and 14.5 percent (337 units) is owner occupied. The average household size is 1.60 people (owner occupied) and 1.83 people (renter occupied). The demography of the West 42nd Street MGP area is likely more accurately represented by an average of the two Census Tracts.

4.3 ZONING

Within the general geographic area of the site, property usage is residential, light commercial, light manufacturing, and local service district. Tables 4.1 and 4.2 list the zoning for Tax Lot 1 and 3 in Block 1089, the area that comprises the former MGP site. The site is bordered to the east by 11th Avenue and to the west by 12th Avenue (12th Avenue).

Table 4.1 – Former MGP Lots In Block 1089

Lot Number	Current Zoning	Current Usage
Lot 1	C6-4, D-129	High-rise apartment building.
Lot 3	C6-4, D-129	Concrete and asphalt parking lot.

C6-4 – General Central Commercial District
D-129 – Restrictive Use Declaration

Table 4.2 – Former MGP Lots In Block 1107

Lot Number	Current Zoning	Current Usage
Not Identified	M2-3	Pier/Bulkhead

M2-3 –Manufacturing District

4.4 CHARACTERISTICS OF NEIGHBORING PROPERTIES

Within a one-quarter mile radius of the West 42nd Street site the neighboring properties consist of commercial properties, restaurants, retail stores, and a yacht tour operation. Commercial buildings are present to the east and south of the site along 11th Avenue and 41st Street. The World Yacht marina is located west of the site along the Hudson River with frontage along 12th Avenue. Store front retail facilities are located to the north of the site with frontage along 42nd Street. A commercial bus depot owned by the New York Transit Authority is located south of the site. It should be noted that store front retail facilities are also located on Tax Lot 1 at the base of the high-rise apartment building. During the site inspection, the area buildings were observed to be generally well maintained. The roadways were observed to be in good repair with few potholes. The area maintains a high population density due to the presence residential high-rises, office buildings, local attractions, and retail facilities as well as the influx of the workforce population on any given day of the workweek.

4.5 TOPOGRAPHY AND SURFACE WATER DRAINAGE

The general site topography is sloping from the east to west toward 12th Avenue and subsequently to the Hudson River. The elevation near the intersection of 42nd Street and 11th Avenue is approximately 17 feet above mean sea level (amsl) and the elevation near the intersection of 42nd Street and 12th Avenue is approximately 12 feet amsl.

Based upon observations made during the site reconnaissance visit, the apparent surface water drainage is west toward 12th Avenue and subsequently to the Hudson River. Storm sewers are present along 12th Avenue and 11th Avenue to collect surface water runoff from the adjacent side streets.

4.6 REGIONAL GEOLOGY

The bedrock underlying the project site is the Manhattan Formation, composed of gray to black mica schist that has been intensely folded and deformed by the two major episodes of mountain building during the Paleozoic Era, more than 200 million years ago. The depth of the bedrock surface in the project area varies from more than 150 feet below ground surface (bgs) in the Chelsea section approximately 2.1 miles to the southwest to near the surface in the Clinton area of Manhattan approximately 1.1 miles to the north (AKRF, 1994). Depths to bedrock in the site vicinity have been reported from 28 to 53 feet.

Bedrock is generally overlain by Pleistocene glacial deposits. During the past 35,000 years of the Pleistocene Epoch (the Ice Age), bedrock has been abraded and eroded by four episodes of glaciation. During the Wisconsonian Stage (the last of the four stages), large volumes of sand, gravel, and rock were deposited along the margins of the Hudson River Valley (AKRF, 1994).

4.7 SITE GEOLOGY

Boring logs from the Route 9a Reconstruction Project (AKRF, 1998) and a proprietary investigation conducted by Langan Engineering and Environmental Services, Inc in 2000 (Langan, 2002) provide information on the subsurface conditions at the former West 42nd Street MGP. The site and surrounding properties are underlain by fill and unconsolidated soils. Saturated soils were encountered at depths ranging from 5.5 to 19 feet bgs. Boring logs for the West 45th Street property three blocks north indicated the fill material beneath the site consists of gravel, brick, slag, concrete, and coal ash. Similar materials would be expected in the vicinity of the West 42nd Street site. Fill thinknesses ranged from approximately 15 to 20 feet on Block 1089. Organic material (4 to 10 feet thick) and sand and sand and gravel (2 to 15 feet thick) were encountered below the fill in borings. Bedrock was reported from 28 to 53 feet (Langan, 2002).

4.8 HYDROLOGY/HYDROGEOLOGY

Manhattan is an island of approximately 22 square miles and is surrounded by brackish or salty tidal water. The Hudson River is located less than 0.25 miles west of the site, and the East River is located less than two miles east of the site. The Hudson River is classified as an "I" surface water body adjacent to the West 42nd Street site (NYSDEC, 2001). Class I waters fall within the Interstate Sanitation District. Class I waters are suitable for secondary contact recreation and any other use except primary contact recreation and shellfishing for market purposes.

The area is characterized by a relatively mild climate with an average precipitation of approximately 45 inches per year. The primary source of groundwater is precipitation; however, recharge precipitation in Manhattan is probably much less than 50 percent of total recharge because the majority of surface area is paved. Secondary sources of groundwater recharge are leakage from sewer and water lines, and infiltration of surface water. Manhattan's drinking water is obtained from reservoirs located greater than 25 miles north of the city. No drinking water supply wells were identified in the vicinity of the site (EDR, 2002 and NYSDOH, 1982). The EDR report did identify a public water system location within 0.25 miles. However, this supply is actually located upstate in Liberty, New York. The supply owner apparently resides in the vicinity of the site. The usage of local groundwater is not likely since the public water

supply is readily available. However, the fresh groundwater would be compared to Class GA groundwater standards.

Prior to significant construction and development, Manhattan was drained by approximately 12 shallow creeks, which emptied into the Hudson, Harlem, and East Rivers. Most of these creeks are now filled in and covered by buildings and streets, but the location of the old channels may have some influence on the occurrence and movement of shallow groundwater in the region. Depths to groundwater at the former MGP were reported from 5.5 to 19 feet bgs based on boring log information (personal communication Langan, 2002). Groundwater is expected to flow in a westerly direction toward the Hudson River. Groundwater elevation contour maps were not available for the site.

SECTION 5

PAST OWNERSHIP

5.1 INTRODUCTION

This section describes the past ownership of the site. Ownership history is divided into three parts; pre-MGP, the MGP period, and post-MGP. In addition to the title search results that are presented in Appendix D, Sanborn Insurance Maps from 1890 to 1996 and other historical maps and atlases were used to develop the chain of ownership and evolution of site operations.

The former MGP site occupied two modern Tax Lots on Block 1089, plus the waterfront area immediately west of Block 1089, now part of larger Block 1107, and the street between Block 1089 and the waterfront (see Section 2.1).

5.2 PRE-MGP OWNERSHIP AND USE

Most of the West 42nd Street MGP site was originally under the Hudson River. Historic maps indicate that Block 1089 was under water (except for a small area at its eastern end) through the 1830s and 1840s. The 1836 Colton map (Figure 4) shows that the block had not yet been reclaimed from the Hudson River and was still under a portion of the river labeled Norton's Cove. The map also depicts an unnamed drainage emptying into the cove at the eastern side of what would become Block 1089. The 1865 Viele map (Figure 5), which shows the original topography and hydrology of Manhattan Island, confirms that the block was mostly under water and the outlet of the drainage.

By the 1850s, Block 1089 had been filled in, and was now solid ground adjacent to the river. However, there appears to have been no development on the block through the 1850s, as evidenced by the 1852 Dripps map (Figure 6), which shows no structures on the block, and tax assessment rolls, which indicate that in 1855 there were still no buildings on the block (Assessed Valuation of Real Estate 1855). This may be because during these years the property title was being contested in a chancery court case. In 1854, the matter finally was resolved, and in that year Charles Appleby purchased all of Block 1089 and the adjacent waterfront from the City of New York. By that time, Block 1089 had been filled in as far as the eastern line of what would become 12th Avenue, but Block 1107 was still under water.

5.3 MGP HISTORY

Charles Appleby sold all of Block 1089 and the portion of Block 1107 immediately west of Block 1089 to the Metropolitan Gas Light Company in 1860. The Metropolitan Gas Light Company was a new entity that had struggled throughout much of the late 1850s to secure a franchise allowing it to compete with the existing gas companies in Manhattan: the New York Gas Light Company (which served the area south of Canal Street), the Manhattan Gas Light Company (providing gas from Canal Street to 79th Street), and the Harlem Gas Light Company (covering the area north of 79th Street). Since the existing gas companies did not want to share their markets with a new company, they waged a number of legal battles to thwart the upstart

group. The result was that the Metropolitan obtained and then lost its charter several times, as the state legislature in Albany and the local government in New York City alternately approved and rejected the charter in a seemingly see-saw fashion. The final victory for the Metropolitan came in 1860, when the last of the state court's decisions was reversed and their charter finally was granted (Collins, 1934).

Construction of the Metropolitan's West 42nd Street MGP began in late 1860 and continued into 1861. By March 1861, the MGP was well underway and a contract had been made to excavate foundations for gasholders on site. It was expected that the plant would be operational by the end of 1861. However, the onset of the Civil War later that spring and the company's expensive startup costs affected the construction schedule's pace, so that a year later, in April 1862, work still had not been completed. Fortunately, finances improved for the Metropolitan during the ensuing months, and by the end of summer, brickwork for the four gas holders had been nearly completed, plans were underway to enlarge the retort house from 40 benches to 60 benches, and contracts were being made to obtain coal, and construct coal sheds and a pier. The company estimated gas production could begin in four or five months (Collins, 1934).

Once again, though, outside forces conspired to prevent gas manufacture from occurring at the West 42nd Street MGP as quickly as the Metropolitan had hoped. During the summer of 1862, the Manhattan Gas Light Company, which until then had controlled the territory between Canal and 79th streets, began talks with the Metropolitan to reach a deal by which both companies could operate simultaneously without competing for the same business. In August 1862, as meetings between the two companies progressed, the Metropolitan suspended laying its gas mains in the streets, and in September called off its order for additional pipe stock. Over the winter, with construction stalled, the two companies negotiated an agreement. By 1863, they had reached a compromise: the Manhattan would continue to serve the district from Grand and Canal streets to 34th Street, and the Metropolitan would gain rights to the area between 34th and 79th streets. After complicated financial negotiations were resolved, both companies began to move forward again. At the West 42nd Street MGP, the gasholders were completed by May 1863, and gas production began the following month. On June 25, 1863, the works began to supply coal gas to its first customers (Collins 1934).

The 1867 Dripps map (Figure 7) illustrates the original footprint of the West 42nd Street MGP. Comparison with the 1871 Perris and Browne map (Figures 8a and 8b) indicates the initial setup included a pier jutting into the Hudson River (within Block 1107) and a small structure within the future line of 12th Avenue. From the pier, coal would be unloaded from barges or smaller lighters and wheeled down a platform to a pair of coal houses on the western end of Block 1089. From the coal houses the material would be transported to a large retort house along the West 42nd Street frontage. The manufactured gas passed through a series of condensers at the eastern end of the retort house. The gas then was piped to the purifying house, a building located east of the retort house, and oriented north-south. Once the gas was purified, it was piped into four gasholders at the far eastern end of the block, where it awaited distribution to consumers. Each gasholder had a capacity of 250,000 cubic feet, for a combined capacity of 1,000,000 cubic feet (PSC 1908-1918). The 1871 Perris and Browne map (Figures 8a and 8b) indicates that by this year, the MGP had grown to include a second retort and condensing house along the West 41st Street frontage, and several coke vaults nearby.

During the early years of the West 42nd Street MGP's operation, local residents frequently complained of unpleasant odors emanating from the plant, which were attributed to the purifying house, labeled on the 1871 Perris and Browne map as the "Lime Houses." The Metropolitan used a process known as the "dry-lime" method of purifying gas. At a hearing called by the Board of Health in 1869, assistant engineer Samuel Perham explained the process in detail:

> The Company used the best of coals – Bogshead, canel coal, Armiston, Leutheon, St. Helen, Inchal, Lesmahago. The Company used what is called the "dry lime" process of purification of gas. Oyster shell lime is placed in large boxes and the gas passed through it; the sulfur and other impurities are to a great extent absorbed by the lime. The lime is used in this way until by a certain test it is found to have become so saturated with the impurities or "fouled," as it is termed in the MGP, that it will no longer answer the purpose, when it is taken out and a fresh supply of lime is substituted. The lime, which has thus used is thrown out into the yard from the purifiers, the odors from the substances it has absorbed passing off into the atmosphere. Finally this fouled lime is sold as a fertilizer. In the Summer these boxes of lime are changed once in two or three days; in the Winter, when the consumption of gas is much greater, the change is made about once in every twenty-four hours (*New York Times* February 14, 1869).

Other gas companies in the city had switched to less foul-smelling purifying processes, most notably the "Laming Process," named for a French inventor who had patented an iron oxide purification method in 1849, which was already widely used in Europe. The Metropolitan refused to change its purification process, citing the healthfulness of the odors with regard to certain diseases like whooping cough; patients who suffered from this affliction often visited the purification house for medical purposes, claimed the company (*New York Times* February 14, 1869). However, on December 23, 1871, an unexplained phenomenon caused the West 42nd Street MGP's purification house to explode, destroying the building and disrupting the supply of gas to much of the city for three days. A newspaper report said there was 12,000 cubic feet of gas in the gasholders at the time of the explosion (*New York Times* December 24, 1871). When the Metropolitan rebuilt its purifying house, it finally adopted the Laming process (Collins 1934).

The West 42nd Street MGP suffered a second explosion on May 28, 1877. On this day, an oil lighter was docked at the company pier, and its crew was pumping naphtha from barrels on the boat into underground storage tanks at the edge of the pier when a presumed spark from the Captain's illegally lit pipe ignited the fuel, burning the lighter to the water line and killing three men. A newspaper article explained that a small steam pump, using steam supplied by a boiler on the adjacent pier, was used to pump the naphtha from the lighter to the underground tanks (*New York Times* May 29, 1877; June 17, 1877).

The 1879 Taylor bird's eye drawing (Figure 9) and the 1880 Perris and Browne map (Figure 10) illustrate the final configuration of the West 42nd Street MGP. The new purifying house is shown in roughly the same location as the previously destroyed structure, although it is no longer labeled "Lime Houses" on the map, confirming the company's switch to the Laming process. The retorts on the West 41st Street side of the block have been enlarged as well. The

naphtha tanks at the edge of the pier are shown clearly on the map, where they simply are designated "tanks."

The 1890 Sanborn map (Figure 11) provides a few additional details about the West 42nd Street MGP, including the location of the underground naphtha tanks, now shown at the edge of the pier. All of the structures and property are attributed to the Consolidated Gas Company, the organization that was formed in 1884 and superceded the Metropolitan Gas Light Company, as well as five other local gas companies. The 1899 and 1911 Sanborn maps (Figures 12 and 13) reveal little change to the MGP layout during these years.

The West 42nd Street MGP operated through the early 1920s. In 1923, the Consolidated Gas Company sold all of Block 1089 to the New York Edison Company, another energy company that was later bought by Consolidated Gas. The PSC report for 1925 indicates the MGP was no longer in operation, suggesting the change in ownership corresponded with the end of the MGP's use/life.

5.4 POST-MGP OWNERSHIP AND USE

After demolition of the West 42nd Street MGP in the 1920s, Block 1089 supported a series of railroad-related structures through the mid-twentieth century. In 1927, the New York Edison Company sold all of Block 1089 to the New York State Realty and Terminal Company, who in turn sold the block to the New York Central Railroad Company in 1932. The 1930 Sanborn map (Figure 14a) illustrates that the block was now used as a railroad yard, owned by the New York Central Railroad [note: Sanborn maps frequently were updated between editions by "pasting over" portions of existing maps. Thus, the 1930 map likely represents the status of the area several years after the original publication date]. A gasoline station (including buried tanks) is depicted at the northeast corner of the block, at the intersection of West 42nd Street and 11th Avenue. A small one-story office is shown near the southeast corner of the block, and a one-story store and lunch building appears at the northwest corner of the block. Much of the block's remaining area is covered by railroad tracks. To the west of Block 1089, the 1930 Sanborn map indicates the former gas company pier was still extant, although the boiler house once situated on the pier had been demolished (Figure 14b). The projected location of the elevated highway that would become Route 9A (along the line of 12th Avenue) is shown on this edition as well.

The 1950 Sanborn map (Figure 15a) reveals that in 1940, a series of buildings attributed to the Railway Express Agency had been erected on Block 1089, replacing the gasoline station, other assorted buildings, and the railroad yard. A long, one-story "assorting station" was constructed along the center of the block, oriented east-west, with a two-story office attached to its eastern end, facing 11th Avenue. A one-story private garage was built along the 12th Avenue frontage, and eight gas tanks were located to the north of the garage. All of the buildings on the block are labeled as having concrete floors, concrete slab roofs over exposed steel, and brick walls. By this time, the former Consolidated Gas Company pier west of Block 1089 had been removed completely and the elevated highway along 12th Avenue, now called Miller Highway, had been constructed (Figure 15b).

The 1968 Sanborn map (Figure 16a) shows little change from the previous edition, but the 1980 Sanborn map (Figure 17a) indicates that all the structures on Block 1089 had now been

removed (the block was used for bus parking), and the 1984 through 1996 Sanborn maps (Figures 18a and b through 21a and b) show adjacent Miller Highway had been razed. Today, the 12th Avenue area supports multiple-lane, at-grade roadways separated by a wide median strip. The portion of Block 1107 formerly owned by the gas company is again under the waters of the Hudson River, after removal of the pier (Figures 20b and 21b).

Block 1089 had been owned by a series of railroad-affiliated entities through 1967. After this year, the block passed to a series of real estate companies. Both Tax Lots on the block currently are owned by River Place LLC, the developer that constructed the current building on Tax Lot 1, a high-rise apartment building (with basement) erected in 1999-2000, and that owns the at-grade, pay-parking lot on Tax Lot 3.

5.5 SUMMARY

Table 5.1 presents a summary of the significant property transfers on Block 1089 which occurred during the formation of the West 42nd Street MGP, during the operations of the MGP, and the dissolution of the MGP in the early 1920s.

Table 5.1 Block 1089 – Property Transfers

Date of Transaction	Tax Lots	Seller/Grantee	Purchaser/ Grantee	Comments
1854	Entire Block	City of New York	Charles Appleby	Settlement of chancery case
1860	Entire Block	Charles Appleby	Metropolitan Gas Light Co.	Also waterfront property west of Block 1089
1885	Entire Block	Metropolitan Gas Light Co.	Consolidated Gas Co.	Consolidated Gas Co. organized in 1884.
1924	Entire Block	Consolidated Gas Co.	New York Edison Co.	MGP shut down.
1927	Entire Block	New York Edison Co.	New York State Realty and Terminal Co.	
1932	Entire Block	New York State Realty and Terminal Co.	New York Central Railroad Co.	
1962	Entire Block	New York Central Railroad Co.	Cola Realty Corp.	
1962	Entire Block	Cola Realty Corp.	Railway Express Agency, Inc.	

Table 5.1 Block 1089 – Property Transfers (continued)

Date of Transaction	Tax Lots	Seller/Grantee	Purchaser/ Grantee	Comments
1967	Entire Block	Railway Express Agency, Inc.	Joseph D. Keenan and Roger Deed, Trustees	
1969	Entire Block	Joseph D. Keenan and Roger Deed, Trustees	Chrysler Realty Corp.	
1981	Entire Block	ABKO Properties, Inc. f/k/a Chrysler Realty Corp.	Ivory Forty-Two Realty Corp.	
1984	Entire Block	Ivory Forty-Two Realty Corp.	Silverstein 42nd Associates	
1996	Tax Lot 1	Silverstein 42nd Associates	River Place I, LLC	High-rise apartment building on property today.
1999	Tax Lot 3	Silverstein 42nd Associates	River Place II, LLC	Asphalt and concrete parking lot on property today.

SECTION 6

PAST SITE OPERATIONS

6.1 INTRODUCTION

This section describes the operations conducted at the former West 42nd Street MGP in addition to significant operations conducted before and after the MGP. This section is divided into three parts; pre-MGP operations, MGP operations, and Post MGP operations. Information used to develop the operational history was obtained from:

- Consolidated Edison internal records and files (including remediation files and reports, real estate records, in-plant property records, and historical photographs);
- Consolidated Edison personnel interviews;
- Historical maps, including Sanborn Fire Insurance Maps, Dripps Maps, Perris and Browne Insurance Maps, Bromley Atlases, and Taylor City Map;
- Books and articles detailing manufactured gas company histories and operating procedures;
- Manufactured gas industry publications (including the *American Gas Light Journal*, in later years called the *American Gas Journal*);
- Brown's Directory of American Gas Companies;
- PSC reports;
- Nineteenth and twentieth century newspaper and journal articles (such as the *New York Times*); and
- Environmental studies undertaken within and adjacent to the properties.

6.2 PRE-MGP OPERATIONS

6.2.1 Summary of Pre-MGP Operations

Prior to the existence of the West 42nd Street MGP, Block 1089 and the waterfront property west of the block were under the waters of the Hudson River through the 1830s and 1840s, filled in by the 1850s, but undeveloped through 1860, when the gas company acquired the land. Thus, the only known operation on the block involved landfilling associated with shoreline extension prior to the MGP's construction. Figures 4 through 6 illustrate the changing position of the shoreline during this period.

6.2.2 Pre-MGP Wastes and Byproducts

Since the West 42nd Street MGP blocks were undeveloped through 1860, it is unlikely that any wastes or byproducts exist from this period unless contaminated fill was used to reclaim this area from the Hudson River.

6.3 MGP OPERATIONS

6.3.1 Summary of Site Gas Production

The processes and practices described in the following sections are inferred from historic maps, Con Edison records, Collins (1934), PSC Records, Brown's Directories, Eng (1985), Hornby (1911), Alrich (1934), Downing (1934), Stewart (1958), and EEI (1984).

The West 42nd Street MGP manufactured retort or coal gas from 1863 through the early 1920s (Collins 1934, PSC 1907-1918, 1925). Anthracite coal for coal gas production was delivered by barges or lighters to the company's Hudson River pier, and then by cart to the plant itself. The coal was stored in two "coal houses" at the western end of the block, then transported to one of two retort houses (the first was along West 42nd Street, and later a second was built and enlarged along West 41st Street). At the eastern ends of the retort house were the condensers. After the condensers, the gas went through the purifying house, located east of the retort houses. The initial purifying house used the dry-lime process, whereas the second purifying house (built to replace the first one, after an explosion) used the Laming process. From the purifying house the gas went to the holders at the eastern end of the block for storage before being distributed to customers. During the period when the MGP operated on the site, four gasholders were available at the eastern end of the block, with a combined capacity of 1,000,000 cubic feet. The following text summarizes the coal gas manufacturing process, from delivery of the coal to the retorts, to the piping of gas to the holders.

Coal gas production quantities were listed in PSC reports beginning in 1907 (although not published for 1908-1910 and after 1911). A summary of available information on gas production for the West 42nd Street MGP, prior to its shutdown in the 1920s, is presented in Table 6.1. At this time, there were two coal gas plants operated by the Consolidated Gas Company in New York City. The West 42nd Street MGP had the capacity to produce about 47 percent of all coal gas manufactured by the company (PSC 1908). The West 42nd Street MGP contained three retort house configurations, described by PSC reports as 66 benches with 6 retorts each, 14 benches also with 6 retorts each, and 20 benches with 7 retorts each, for a grand total of 620 retorts on site (PSC 1908-1918).

TABLE 6.1

GAS PRODUCTION AT THE WEST 42nd STREET MGP (PSC REPORTS)

Year	Total Yearly Production	Daily Plant Capacity	Daily Average Production	Total Holder Capacity
1907	200,151,000 cu. ft. (6 months only)	4,500,000 cu. ft.	1,088,000 cu. ft.	1,000,000 cu. ft.
1911	415,582,000 cu. ft.	4,500,000 cu. ft.	1,139,000cu. ft.	1,000,000 cu. ft.

6.3.2 Process Configurations

As described above, coal gas was produced at the West 42nd Street site between 1863 and the early 1920s. Raw materials such as coal and naphtha were delivered by barge or lighter and

unloaded at the company's Hudson River pier, and may also have been delivered by rail, as tracks ran along 11th Avenue on the eastern side of the MGP. By-products may have been shipped from the plant by barge or rail also.

Typically, retorts were constructed of interlocking silica brickwork with the oven tapered from the top to bottom. The sides of the oven were heated with vertical flues containing "producer" or "oven gas." A boiler sometimes provided steam to the bottom of the retort during the latter stages of carbonization. The steam displaced residual coal gas and reacted with the hot coke to produce water gas to increase gas yield. The spent coal or coke was discharged through the bottom of the oven and immediately quenched with water to prevent combustion. The "oven" gas used to heat the retorts was generated in a producer oven. The oven produced gases by blowing air and a small amount of steam through the fuel bed. The fuel bed used to generate the "oven gas" was often coke (a by-product of the coal gas retort process). Due to the low heating value of the "oven gas," it was normally generated near the retorts (EEI, 1984).

The retort gas was passed through a series of processes to recover by-products and impurities. Once the raw gas was driven from the coal, it was drawn from the retort and through a tar condenser by exhaust fans. The tar condenser cooled the gas by indirect contact cooling water to remove heavy tars and water vapor. The gas was then driven through a washer or tar extractor, and a scrubber. The washer typically removed light oil from the gas stream by direct contact with ammonia liquor. The scrubber, located after the washer, removed ammonia from the gas stream by direct contact with water. The ammonia liquor was recycled for use in the washer or discharged to a tar well.

The final stage in the removal of impurities from the gas stream, purification, was the removal of carbon dioxide and sulfur. Sulfur was removed from the gas stream by the formation of calcium sulfate as the coal gas was passed through lime purifiers. After the dry-lime process ceased at the West 42nd Street MGP, the Laming method – an oxide purification process – was used. In the oxide purification process, gas was passed through iron oxide impregnated wood chips in purifier boxes. Hydrogen sulfide in the gas stream reacted with the iron oxide forming ferric sulfide. The iron oxide purifier material, when exhausted was regenerated by exposing it to air, producing iron oxide and sulfur. Eventually, the purifier material (oxide chips) was fouled by the accumulation of sulfur, tar, and ferrocyanides. The iron oxide purifier material was replaced with fresh purifier material. The purifier material usually consisted of clean gray iron borings free from steel, brass, and other metals. Small amounts of crystal rock salt were added. Rosin and gum free wood shavings were also added. Common ratios used in the purifiers were 500 pounds of iron oxide, 20 pounds of crystal rock salt and 10 bushels of wood shavings. The mixture was wet with water.

Gas was finally passed through a meter and into the distribution holders. At the West 42nd Street MGP, the four brick holders each had a capacity of 250,000 cubic feet, for a total of 1,000,000 cubic feet. Occasionally, the base of a holder required cleaning. Typically, a basket-shovel was employed to remove some of the mud and muck. The remaining mud and tar was pumped out and replaced by clean water (Nisbet-Latta 1907).

6.3.3 By-Products and Waste Disposal

A complete record of by-product quantities, reuse, sale, and disposal is not available. Although PSC reports list individual plant tar production, tar sales, coke production, and coke sales, these figures are not available until after the West 42nd Street MGP closed. During the period that the West 42nd Street MGP operated, PSC reports summarize byproduct output and sales for entire corporations only. For the Consolidated Gas Company, the PSC report indicates coal gas plant raw materials were gas coals, enriching coals, boiler fuel, gas oil, lime, and iron oxide. All of the coal gas residuals – coke, tar, ammoniacal liquor, and other carbon residuals – were offered for sale. The following tables, detailing coal gas materials (Table 6.2) and coal gas residuals (Table 6.3) are reproduced from the PSC report of 1907. At this time, the West 42nd Street MGP was one of two coal gas plants operated by the Consolidated Gas Company, and provided approximately 47 percent of the company's total coal gas capacity. The tables below summarize the company's total raw materials and residuals for 1906-1907.

TABLE 6.2
COAL GAS MATERIALS FOR YEAR (PSC 1908)

	On hand June 30, 1906	Received during year	Carbonized	Used elsewhere	On hand June 30, 1907	Average Cost
Gas coals (tons)	60,545.62	125,782	130,037.11	196.34	56,094.17	$3.10
Enriching coals (tons)	220.15				220.15	
Boiler fuel (tons)		1,448.25		1,137.33	310.92	
Gas oil (gals.)	123,660	3,881,026		3,878,330	126,356	$0.0457
Lime (bu.)	3,777	29,100		27,200	5,677	$0.0519
Iron oxide (bu.)	9,000	8,700		17,700		$0.01745

TABLE 6.3
COAL GAS RESIDUALS FOR YEAR (PSC 1908)

	On hand June 30, 1906	Made during year	Used	Sold	On hand June 30, 1907	Average Selling Price
Coke, net tons	2,818	100,823	49,920	53,517	204	$3.00
Tar (coal gas), gals.	32,299	1,843,249	1,350	1,826,809	47,389	
Ammoniacal Liquor (gals.)	69,530	5,676,763		5,696,257	50,036	
Other residuals (carbon), lbs.	66,265	122,090		125,280	63,075	$0.0085

Written information regarding waste or excess by-product disposal is not available. It is not known if purifier waste (usually iron oxide impregnated wood chips and/or spent lime) was stockpiled prior to or after use on-site. The disposal history of purifier waste is unknown.

6.4 POST-MGP OPERATIONS

Section 5.4 describes the history of the West 42nd Street MGP site footprint after the property was sold to other owners. The following is a summary of the post-MGP operations.

After demolition of the MGP, Block 1089 supported a railroad yard (tracks) with several small associated buildings, and a gasoline station during the 1930s. In 1940, the railroad yard complex and gasoline station were replaced by an "assorting station," office, and private garage belonging to the Railway Express Agency. The Railway Express Agency garage had associated USTs. These structures stood on the block for several decades. By the 1980s, the block was vacant and used for parking. In 1999-2000, a high-rise luxury apartment building was constructed on Tax Lot 1, which remains today. Tax Lot 3 is still used as a parking lot. Tax Lot 1 overlies the area of the MGP formerly containing the coal houses, the retort houses and condensers, the coke vaults, and most of the purifying house. The high-rise apartment building footprint overlies the former locations of the coal houses, parts of the retort houses, and parts of the coke vaults. Tax Lot 3 overlies the former location of the gasholders, and the eastern edge of the purifying house. It is likely that portions of the MGP may still exist beneath the current ground surface in areas where deep excavation or construction has not occurred, specifically in the center and eastern end of the block.

The portion of Block 1107 formerly owned by the Consolidated Gas Company once contained the company pier and several storage tanks. This pier has been completely removed, and the area that once contained the storage tanks is now underneath Marginal Street.

6.5 SUMMARY OF OPERATIONAL HISTORY

Tables 6.4 and 6.5 present a summary of the progression of the significant operations conducted on each of the tax lots that comprised the former West 42nd Street MGP. Details of the operations and historical progression have been presented in Sections 6.1 through 6.4.

Table 6.4 Block 1089 Tax Lot 1

Year	Usage	Owner	Comments
Pre-MGP	Under water until 1850s, undeveloped through 1860.	Various	
1861-1920s	MGP	Metropolitan Gas Light Co. then Consolidated Gas Co.	Lot contained coalhouses, retort houses and condensers, coke vaults, and portion of purifying houses.
1930s	Railroad yard (tracks) and buildings.	New York Central Railroad Co.	
1940-ca. 1970s	Assorting station, private garage.	Railway Express Agency	
Ca. 1970s-1999	Parking lot	Various	
1999-present	High-rise apartment building with basement, landscaped area.	River Place LLC	

Table 6.5 Block 1089 Tax Lot 3

Year	Usage	Owner	Comments
Pre-MGP	Under water until 1850s, undeveloped through 1860.	Various	
1861-1920s	MGP	Metropolitan Gas Light Co. then Consolidated Gas Co.	Lot contained portion of purifying houses and four gas holders
1930s	Railroad yard (tracks) and buildings, gasoline station.	New York Central Railroad Co.	
1940-ca. 1970s	Assorting station, office	Railway Express Agency	
Ca. 1970s-1999	Parking lot	Various	
1999-present	Parking lot	River Place LLC	

SECTION 7

ENVIRONMENTAL/REGULATORY AGENCIES AND DATABASES

7.1 EDR PROFILE SEARCH

A search of site environmental databases was conducted by EDR on March 18, 2002. The search included New York State and Federal databases. The complete listing of sites is presented in the EDR report in Appendix B. All sites identified in the EDR search report are at equal or higher elevation than the 42nd Street site.

Mappable Sites:

Mappable sites in the vicinity of the West 42nd Street site were identified on the area map provided in the EDR profile search. A summary of environmental database findings is presented in Table 7.1. A list of acronyms and definitions are included in the database search report in Appendix B.

The database search identified 12 large quantity and 10 small quantity sites where hazardous wastes are generated, transported, stored, treated, and/or disposed within 0.25 miles of the site. Fifty-five leaking tanks and 24 underground storage tanks were identified within 0.5 and 0.25 miles of the site respectively. One chemical bulk storage UST and two above ground chemical bulk storage tanks were identified within 0.25 miles of the site. The leaking tanks identified within 0.25 miles of the site have the potential to impact the site depending on the ages of the releases, types of releases, quantities of releases, and distances from the site. Current releases and associated impacts from the other sites listed have not been identified. Releases and associated impacts from these other sites described above would have the potential to impact the site if a release occurred.

It is also noteworthy that the EDR Proprietary Historical Databases revealed three coal gas sites within 1 mile of the site. The first location is the 42nd Street site, which is the subject of this report. The site consisted of gasholders and purifiers. The second was owned by Consolidated Gas Works and is located on the western side of 11th Avenue between 44th Street and 46th Street. The site extends to 12th Avenue. The third site was owned by the Equitable Gas Company and is located between 59th Street and 58th Street and between Amsterdam Avenue and West End Avenue. The site consisted of gasholders.

TABLE 7.1 SUMMARY OF ENVIRONMENTAL DATABASE FINDINGS (MAPPABLE SITES)

Jurisdiction	Program Database	Radius (Miles)	Number of Sites
Federal	NPL – National Priority List	1	0
	Proposed NPL – Proposed NPL Site	1	0
	CERCLIS – Comprehensive Environmental Response, Compensation, and Liability Information System	0.5	0
	CERC-NFRAP – CERCLIS No Further Action Planned	0.25	0
	CORRACTS – Corrective Action Report	1	0
	RCRIS-TSD – Resource Conservation and Recovery Information System	0.5	0
	RCRIS (Lg. Gen.) – RCRIS Large Quantity Generator	0.25	12
	RCRIS (Small Gen.) – RCRIS Small Quantity Generator	0.25	10
Federal Supplemental	CONSENT – Superfund (CERCLA) Consent Decrees	1	0
	ROD – Record of Decision	1	0
	Delisted NPL – NPL Deletions	1	0
	MINES – Mines Master Index File	0.25	0
State	SHWS – Inactive State Haz. Waste Disposal Sites in NYS-	1	0
	SWF/LF – Facility Register	0.5	0
	LTANKS – Leaking Storage Tank Incident Report Filed	0.5	55
	UST – Underground Storage Tank Database	0.25	24
	CBS UST – Underground Chemical Bulk Storage Tank	0.25	1
	MOSF AST – Major Oil Storage Facilities Database	0.5	0
	VCP – Voluntary Cleanup Agreement	0.5	0
State/Local Supplemental	HSWDS – Hazardous Substance Waste Disposal Site Inventory	0.5	0
	CBS AST – Above-ground Chemical Bulk Storage Tank	0.25	2
	MOSF AST – Major Oil Storage Facilities Database	0.5	0
EDR Proprietary	Coal Gas – Manufactured Gas (Coal Gas) Site	1	3

Unmappable Sites (Zip code ID)

Unmappable sites were identified on New York and Federal databases. The sites were not mappable because the addresses provided to EDR by regulatory agencies were incomplete. The

unmappable sites were identified by zip code, city name or county. Details on the unmappable sites are provided in the EDR Search Report in Appendix B and summarized in Table 7.2.

Table 7.2 Summary of Environmental Database Findings (Unmappable Sites)

Jurisdiction	Program Database	Radius (Miles)	Number of Sites
Federal	RCRIS-SQG, FINDS – Facility Index System		1
	FINDS, RCRIS-LQG		0
State	SHWS		4
	LTANKS		1
	NY Spills, LTANKS		1
	CBS AST		1
	UST		1

7.2 ADDITIONAL RECORDS SOURCES

Files at Con Edison and the Department of City Planning were searched for records of additional sites and results of sampling. A freedom of information request was filed with the NYSDEC that requested information on sites within the investigation area.

Langan Engineering and Environmental Services, Inc. conducted a site investigation at Lot 3 in 2000 for the current landowners, (Langan, 2002). The results of this investigation are proprietary. However, general information about the site was provided, (Langan, 2002). Twenty-six borings were drilled. The overburden materials consisted of up to 15 to 20 feet of fill, over 4 to 10 feet of native organic material and up to 2 to 15 feet of sand or sand and gravel. Bedrock was not encountered in the borings that were drilled as deep as 26 feet. The investigation encountered "coal tar" type materials and SVOCs in soil samples above NYSDEC TAGM values. BTEX and metals were detected in groundwater samples, (Langan, 2002).

An earlier investigation was conducted in 1995 on Lot 1 prior to the construction of the high-rise apartments. The depth to bedrock ranged from 28 to 53 feet. The upper bedrock consisted of decomposed mica schist and "hardpan". Areas of Lot 1 were excavated to approximately 8 feet prior to the construction of the apartments (Langan, 2002).

The May 1994 Final Impact Statement for the Route 9A Reconstruction Project presented summary results for soil vapor sampling, soil borings, and soil and groundwater sampling conducted between West 42nd and West 44th streets (AKRF, 1994). The soil gas survey did not detect any non-methane VOCs. PAHs were detected in soil samples collected throughout the area from 41st Street to 46th Street at concentrations ranging from 50 mg/kg to 166 mg/kg. BTEX (13 mg/kg) was detected at 40 feet in one soil sample (W-39) collected between 41st and 42nd Street. A sample collected at 42nd Street (H-40) did not contain VOCs so the source was

assumed to be south of 42nd Street. Metals were detected in all the soil samples from the area but at concentrations below RCRA EP Toxicity limits. A groundwater sample (W-39) collected during Phase 1A between 41st Street and 42nd Street contained BTEX, PAHs, and metals. The metals concentrations were above Class GA groundwater standards. However, this sample was turbid. No site-related organic compounds were detected in the second groundwater sample collected during Phase 1b. Only iron and manganese exceeded Class GA standards in filtered water samples.

SECTION 8

POTENTIAL RECEPTORS

8.1 SENSITIVE AREAS

Based upon the site reconnaissance conducted on April 10, 2002 and data reviews, sensitive areas and potential receptors were identified. Table 8.1 presents potential sensitive areas and possible receptors within 0.25 miles and Table 8.2 identifies possible pathways leading to impact.

TABLE 8.1 POTENTIAL SENSITIVE RECEPTORS AND AREAS

Sensitive Receptors (Human)	Distance From Site (miles)	Comments
Schools	<0.25	PS 51 Elias Howe School at West 45th St. near Amsterdam Ave.
Day Care Facilities	NA	None identified.
Parks	>0.25	Playground between 9th and 10th Ave. between 45th and 46th Street.
Libraries or Community Organizations	NA	None Identified
Tourist Attractions	<0.25	World Yacht boat tours west of site and River Place shopping center over site.
Sensitive Receptors/Habitats		
Water Bodies	<0.25	Hudson River
Wetlands	<0.25	Wetlands around piers in Hudson River.
Surrounding Land Use		
Residential Only	NA	
Mixed Residential and Commercial	<0.25	High rise housing and commercial usage. 340 people living in Census Tract 117 including site and 4,457 residents in Census Tract 129 bordering site to the north (Census, 2000).
Commercial/Industrial Only	NA	

Table 8.2 Potential Exposure Pathways

Pathway	Possible Exposure Yes/No	Comments
Soils		
Exposed Ground Surface	Yes	Approximately 10-percent of Tax Lot 1 is landscaped grounds for the apartment.
Subsurface	Yes	Excavators & site workers. Previous sampling indicated subsurface soils contained SVOCs and groundwater contained BTEX and metals at Lot 3. Soils were removed in localized areas to approximately 8 feet during construction on Lot 1.
Seeps/Vapors	Yes	Buildings have basements. Residues, if present, could seep into basements along with shallow groundwater, or as vapors.
Surface Water	**Miles**	**Comments**
Distance to Surface Water	<0.25 miles	Site runoff could reach the Hudson River via storm sewer discharges.
Distance to Surface Water Intakes	NA	No known intakes.
Distance to Wetlands	>0.5 miles <0.25 miles	The nearest Federal wetland is in Central Park 6,000 feet to the northeast. The EDR report also shows wetlands adjacent to the piers approximately 200 feet west of the site.
Contaminated Runoff Potential	No	Site is paved, occupied by buildings, or is vegetated. Contaminated runoff could occur during excavation if excavated soils are uncovered and runoff is not controlled.
Groundwater		
Groundwater Used for Drinking in Manhattan?	No	Area is in the NYC water supply area supplied by upstate reservoirs. Groundwater not used for drinking in Manhattan.
Drinking Water Wells	>12 miles	The nearest known drinking water wells are in the Jamaica-Queens Water Supply on Long Island. No potential impacts from the West 42nd Street site because of separation by the East River and groundwater divide. The public water system site identified in the EDR report is actually located upstate in Liberty, NY. The supply owner resides in the vicinity of the West 42nd Street site.
Depth to Aquifer Used for Drinking	NA	No drinking water aquifers used in site vicinity.

- Previous investigations were conducted at the former West 42nd Street MGP; a 1995 investigation on Lot 1, prior to the construction of the high-rise apartments, and a 2000 investigation in anticipation of redevelopment on Lot 3 (Langan, 2002). The 2000 investigation on Lot 3 found SVOCs above NYSDEC TAGMs in soil samples and BTEX and metals in groundwater (Langan, 2002). The May 1994 Final Impact Statement for the Route 9A Reconstruction Project reported BTEX, PAHs, and metals in one groundwater sample collected between 41st and 42nd Street and BTEX and PAHs were detected in soil samples collected between 41st Street and 46th Street (AKRF, 1994).
- The site is located in an area with mixed commercial and residential use. If impacts are present at the site, potential receptors would include workers, nearby residents, and tourists visiting the World Yacht tour operation and the River Place shopping area. In addition, a public school is approximately 0.25 miles northeast of the site. Most of the former site area is covered with pavement or buildings with the exception of landscaped areas on Lot 1 near the apartments. Exposure pathways for surface and subsurface soil are present. Workers conducting excavation or construction activities could encounter subsurface residues from past operations. There is no groundwater usage in the area being investigated.
- The Hudson River is within 200 feet of the former MGP and could be impacted if MGP residuals were migrating from the site or if past disposal practices lead to the disposal of MGP related materials in or near the Hudson River.

9.2 COMPLETENESS OF RESEARCH

Research undertaken as part of this report included review of in-house documents and photographs provided by Con Edison, as well as materials gathered at the Municipal Archives of the City of New York, the Municipal Reference and Research Center of the City of New York, the New York City Recorder of Deeds office, the New York City Department of Buildings, the New York Public Library, the Library of Congress, the New York State Department of Environmental Conservation, the Environmental Protection Agency, and various web sites that post historical maps and journal articles. EDR compiled the radius search data for the site.

The materials gathered to date provide a general synopsis of activities that occurred on the MGP site, both before its construction, during its operation, and after it was demolished and the property used for other purposes. The information compiled about the pre-MGP use and the post-MGP use is likely adequate for the purpose of this report. Information gaps still remain concerning specific operating procedures at the MGP itself, as well as byproduct production and disposal activities. Because the MGP operated during years when this information was not always published by the PSC, and since internal plant records do not survive for this MGP, it is unlikely these data will be recovered. However, second-hand accounts of the MGP and its operations may exist in newspaper or journal articles that have no indices and therefore are unlikely to be found without considerable additional time and effort.

SECTION 10

SUMMARY OF HISTORICAL RESEARCH FINDINGS

10.0 PRIORITIZATION SUMMARY AND CONCLUSIONS

The NYSDEC requested Con Edison perform historical research at former MGP related sites located within the greater New York City area. The historical research will support the prioritization of these former MGP and gas holder sites based on potential, actual, and perceived human health exposure risks, environmental impacts, sensitive receptors, current site usage, the surrounding community, potential for development, site control and ownership, and the size of the former MGP or gas holder operation. Table 10.1 presents a summary of factors that will be used in the prioritization of the sites.

Table 10.1 Prioritization Criteria and Factors

Prioritization Criteria	Prioritization Factors
Does Con Edison own and control access and site usage?	Con Edison does not currently own any of the former MGP parcels.
Relative size of the former MGP.	The former MGP site was approximately 5 acres and occupied modern Block 1089, the part of Block 1107 west of Block 1089, and the roadway area in-between which is currently under 12th Avenue.
Potential for development.	Tax Lot 1 was developed as a high-rise apartment with shopping and parking in the lower levels. There are apparently plans to develop Lot 3 based on the 2000 site investigation activities.
Current potential for direct exposure to impacted soils.	Exposure to impacted soils is possible. A portion of the site adjacent to the apartments is developed as a landscaped lawn area. No stressed vegetation or visually impacted soils were observed during the site reconnaissance. The potential exists for site workers to be exposed to subsurface soils while conducting excavations and other intrusive activities.
Potential for site actions to be triggered by other regulatory means.	The EDR radius search identified 12 RCRIS large quantity generators, 10 RCRIS small quantity generators, 55 leaking storage tank sites, 24 UST sites, 3 chemical bulk storage tanks, and 3 former coal gassification plants within 0.5 miles of the former MGP. Site investigations have been conducted for the current property owners (Langan, 2002). Results from these investigations could trigger regulatory actions.

Table 10.1 Prioritization Criteria and Factors (continued)

Prioritization Criteria	Prioritization Factors	
Presence and proximity of sensitive receptors.	Groundwater Use Aquifers	None
	Surface Water Bodies	The Hudson River is less than 0.25 miles west of the site.
	Groundwater Seepage Areas.	None
	Population	340 people in Census Tract 117 (includes site) and 4,457 people in Census Tract 129 (bordering tract to north). 1,537,195 people in Manhattan Borough.
	Playgrounds/Parks	The nearest playground and park are over 0.25 miles northeast of site and 0.5 miles north of site, respectively.
	Schools	The PS51 Elias Howe School is less than 0.25 miles northeast of the site.
	Residences	There are residences within 0.25 miles of the site (high-rise apartments on the former site).
	Gardens	No vegetable gardens. Lawn and landscaped areas are present on the site.
	Wetlands	The nearest Federal wetland is approximately 6,000 feet from the site in Central Park. The EDR report shows wetlands around the piers approximately 200 feet west of the site.
Physical Site Factors-	Topography	The site topography is gently sloping to the west. Drainage is expected to be radial to the nearest street.
	Soil Types and Permeability	The soils are fill with relatively high permeabilities. The site is covered limiting access and infiltration.
	Cover	The site is paved or covered with buildings with the exception of the landscaped area near the apartments.
	Depth to Groundwater	5.5 to 19 feet

Table 10.1 Prioritization Criteria and Factors (continued)

Prioritization Criteria	Prioritization Factors	
Physical Site Factors (continued)	Groundwater Use	No known use in vicinity.
	Surface Water Proximity and Use	The Hudson is less than 0.25 miles from the site. There are no known surface water intakes downstream of the site.
Presence of buildings with basements onsite or nearby. Volatilization/seepage exposure pathway to residents or workers.	There is parking under the apartments/stores at River Place located onsite. Neighboring buildings have basements. The potential for seepage/volatilization into basement areas exists if impacted soils are present.	
Ongoing or obvious impacts to surface water.	No impacts were observed in the Hudson River in the vicinity of the former MGP. Slight sheens would be expected in the vicinity of the yachts and ships at the World Yacht tour operation and as a result of normal shipping activities on the Hudson River.	
Degree and extent of impacts associated with other (non-MGP) site uses.	Impacts were not observed. BTEX reported by Langan (2002) and by AKRF (1994) could be related to petroleum tanks onsite during railroad operations after the closure of the MGP.	

SECTION 11

REFERENCES

Allee King Rosen & Fleming, Inc., (AKRF), 1994. *Route 9A Reconstruction Project: Final Environmental Impact Statement,* Prepared for the New York State Department of Transportation and Federal Highway Administration, May 1994.

Alrich, Herbert W., 1934. Gas Tanks Now & Then. *American Gas Journal* 140(5): 75-78, 148.

Assessed Valuation of Real Estate, 1855. On file at the Municipal Archives of the City of New York.

Bromley, George Washington and E. Robinson, 1879. *The Atlas of the Entire City of New York.* Volume 4. Bromley and Robinson Company, Philadelphia.

Brown's Directory, 1889-1899. *Brown's Directory of American Gas Companies, Gas Statistics.*

Census, 2000. US Census Bureau, 2000 Census Data, US Factfinder, http://factfinder.census.gov.

Collins, Frederick L., 1934. *Consolidated Gas Company of New York, A History.* Consolidated Gas Company, New York.

Colton, J.H., 1836. *City and County of New York.* J.H. Colton and Co., New York.

Consolidated Edison. Various internal records.

Downing, R.C., 1934. Developments in Condensing, Scrubbing and Purification of Gas. *American Gas Journal* 140(5): 63-66, 151.

Dripps, Matthew, 1852. *City of New York Extending Northward to Fiftieth Street.* Dripps and Company, New York.

Dripps, Matthew, 1867. *Plan of the City of New York from the Battery to Spuyten Duyvil Creek.* Dripps and Company, New York.

Edison Electric Institute (EEI), 1984. *Handbook on Manufactured Gas Plant Sites.* Prepared for the Utility Solid Waste Activities Group Superfund Committee, Washington, D.C., ERT Project No. P-D215.

Eng, Robert, 1985. *Survey of Town Gas and By-product Production and Locations in the U.S. (1880-1950).* Prepared by Radian Corporation for the Environmental Protection Agency, Research Triangle Park, NC.

Hornby, John, 1911. *A Text-Book of Gas Manufacture For Students*, Sixth Edition. G. Bell and Sons, Ltd., London.

Langan, 2002. Personal communication with Joel Landes of Langan Engineering and Environmental Services, Inc. on June 14, 2002.

n.d., The Gas Industry in the Route 9A Reconstruction Corridor of Manhattan. Undated report on file at Con Edison.

New York Times, 1869. The Gas Nuisance. *New York Times*, February 14, 1869.

New York Times, 1871. Bereft of Light. Terrific Explosion at the Metropolitan Gas Works, *New York Times,* December 24, 1871.

New York Times, 1877. Explosion of Naphtha, *New York Times,* May 29, 1877

New York Times, 1877. A Gas Company Censured, *New York Times,* June 17, 1877.

NYSDEC, 2001. 6 NYCRR Part 864, Reclassification of Fresh Surface Waters Lower Hudson River and Upper East River-Long Island Sound Drainage Basins, October 11, 2001.

Perris and Browne, 1871. *Insurance maps of the City of New York*. Perris and Browne, New York.

Perris and Browne, 1880. *Insurance maps of the City of New York*. Perris and Browne, New York.

Public Service Commission (PSC), 1907-1918. 1925, *Report of the Public Service Commission for the First District of the State of New York*. Public Service Commission, New York, NY.

Sanborn Map Company, 1890. *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1899. *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1911a. *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1911b. *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1930a. *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1930b. *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1950a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1950b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1968a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1968b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1980a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1980b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1984a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1984b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1988a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1988b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1992a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1992b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1996a, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Sanborn Map Company, 1996b, *Insurance Maps of the City of New York.* Sanborn Map Company, New York.

Stewart, E.G., 1958, *Town Gas, Its Manufacture and Distribution.* Her Majesty's Stationery Office, London.

Taylor, Will, 1879, *The City of New York*. Galt and Hoy, New York. On file at the Library of Congress American Memory website http://memory.loc.gov/.

USGS, 1979. USGS Topographic Quadrangle Map of Central Park, NY-NJ, photorevised 1979.

Viele, Egbert L., 1865, *Sanitary and Topographical Map of the City and Island of New York*. Mayer and Company, New York.

FIGURES





New York Quadrangle

LATITUDE: N40° 45" 41"
LONGITUDE: W73° 59' 58"

N

0.200 MI

Figure 1

CONSOLIDATED EDISON

NEW YORK, NEW YORK

SITE LOCATION MAP

FORMER WEST 42nd STREET GAS WORKS

PARSONS

DESIGN * RESEARCH * PLANNING

290 Elwood Davis Road, Suite 312, Liverpool, New York 13088 * (315) 451-9560

Offices in Principal Cities

P:\741280\CAD\42ND\SITELOC.PPT



FIGURE 2

CONSOLIDATED EDISON
NEW YORK, NY

SITE MAP - 2002

FORMER WEST 42nd STREET GAS WORKS

PARSONS

290 ELWOOD DAVIS ROAD, SUITE 312, LIVERPOOL, N.Y. 13088, PHONE 315-451-9560

No XREFs
P:\741280\CAD\42ND STREET\42-G01.DWG



LEGEND

- TAX BLOCK NUMBER
- TAX LOT NUMBER
- TAX LOT BOUNDARIES
- CURRENT FEATURES
- HISTORICAL FEATURES

100 50 0 100 200

SCALE: 1"=100'

FIGURE 3A

CONSOLIDATED EDISON
NEW YORK, NY
HISTORICAL AND CURRENT SITE FEATURES
FORMER WEST 42nd STREET GAS WORKS

PARSONS
290 ELWOOD DAVIS ROAD, SUITE 312, LIVERPOOL, N.Y. 13088, PHONE 315-451-9560

No XREFs
P:\741280\CAD\42ND STREET\42-003.DWG

Figure 4 (Colton 1836)



Figure 5 (Viele 1865)



Figure 6 (Dripps 1852)



Figure 7 (Dripps 1867)



Figure 8a (Perris and Browne 1871)



Figure 8b (Perris and Browne 1871)



Figure 9 (Taylor 1879)



Figure 10 (Perris and Browne 1880)





The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:
Copyright © 1890 The Sanborn Library, LLC DCM
Year EDR Research Associate



The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:
Copyright © 1890 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1899 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)



The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1899 The Sanborn Library, LLC DCM
Year EDR Research Associate


37
HUDSON
RIVER
TWELFTH
AVENUE
65
N.Y. ONTARIO & WESTERN R.R.
WEST SHORE R.R.
N.Y. CENTRAL LINES
FERRY TO WEEHAWKEN
TEMPORARY
CANARSIE TO 65th St.
STREET
FORTIETH
FORTY-FIRST
FORTY-SECOND
FORTY-THIRD
WEST
Coal Shed
Hide House
Boarding
Abattoir
Offices
Pens
Abattoir and Meat Packing
Pipe Fitting
Abattoirs Meat Packing
WESTERN STOCK YARDS. HOGS AND SHEEP PENS
Stock Yards
Coal Pockets
Retort House
Condensers
Purifying House
Office
CONSOLIDATED GAS COMPANY'S STATION
GAS HOLDER
METROPOLITAN STREET RAILWAY CO. (6TH ST. DIVISION) CAR HOUSE
Wagon House
Stable
Office
Wire House
Paint Shop
Car Cleaning and Inspection
Car Repairing and Inspection
Car Painting and Varnishing
Car Trimming and Upholstering
Car Repairing and Inspection
Car Cleaning



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1911 The Sanborn Library, LLC DCM

Year EDR Research Associate

Reproduction in whole or in part of any map of The Sanborn Library LLC may be prohibited without prior



The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:
Copyright © 1930 The Sanborn Library, LLC DCM

(512)
N.Y. CITY VOL. 5.

67

HUDSON RIVER

EXTERIOR WATER GRANT LINE 1871

29 PIERHEAD LINE 80 ESTABLISHED 1857 BY 81 SECRETARY OF WAR

66

CENTRAL RAILROAD OF NEW JERSEY – FREIGHT PIER

HUDSON RIVER DAY LINE – CENTRAL RAILROAD OF N.J. JOINT FREIGHT ROUTE – PASSENGER PIER. PASSENGER STEAMERS

68

FERRY TO WEEHAWKEN

FERRY TO WEEHAWKEN

CONSISTS OF N.Y. ONTARIO AND WESTERN R.R. WEST SHORE R.R. N.Y. CENTRAL LINES

MARGINAL STREET

RAMP UP HUDSON RIVER RAMP DOWN BOULEVARD

RAMP DOWN PROPOSED RAMP UP ELEVATED EXPRESS HIGHWAY

TWELFTH AVENUE

26

37

39TH ST.

40TH ST.

W. 41ST ST.

W. 42ND ST.

12" W. Pipe

6" W. Pipe

SCALE 50 Ft. to One Inch

The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1930 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1950 The Sanborn Library, LLC DCM
Year EDR Research Associate

(512)
N.Y. CITY VOL. 5.

67

ST. 064

HUDSON RIVER

EXPLANATION WATER DRAFT LINE

PIERHEAD LINE 80' ESTABLISHED 1937 BY SECRETARY OF WAR 81'

79

66

68

CITY PIER

HUDSON RIVER DAY LINE

FERRY TO WEEHAWKEN

FERRY TO WEEHAWKEN

N.Y. ONTARIO And WESTERN R.R.
W'ST SHORE R.R. N.Y. CENTRAL LINES

MARGINAL STREET

MILLER (12 HUDSON RIVER B'LV'D) HIGHWAY

TWELFTH AVENUE

W. 39 TH ST.

W. 40 TH ST.

W. 41 ST.

W. 42 ND ST.

26

37

The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1950 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)



The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1968 The Sanborn Library, LLC DCM
Year EDR Research Associate



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1968 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)

Reproduction in whole or in part of any map of The Sanborn Library, LLC may be prohibited without prior



The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1980 The Sanborn Library, LLC DCM
Year EDR Research Associate



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1980 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)

(512)
N.Y. CITY VOL. 3

67



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1984 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1984 The Sanborn Library, LLC DCM

(512)
N.Y. City Vol. 3.

67

H U D S O N R I V E R

661

1110

81

80

1107

665

66

68

HUDSON RIVER DAY LINE
SIGHTSEEING YACHTS INC.

MARGINAL

STREET

TWELFTH

AVENUE

26

37

W. 39th ST.

W. 40th ST.

W. 41st ST.

W. 42nd ST.

The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1988 The Sanborn Library, LLC DCM



The Sanborn Library, LLC

This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1988 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)

Reproduction in whole or in part of any map of The Sanborn Library, LLC may be prohibited without prior



© 1992 Sanborn Co., EDR Sanborn, Inc.

The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1992 The Sanborn Library, LLC DCM



© 1992 Sanborn Co., EDR Sanborn, Inc.

The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1992 The Sanborn Library, LLC DCM
Year EDR Research Associate



©1996 Sanborn Co., EDR Sanborn, Inc.

The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1996 The Sanborn Library, LLC DCM



© 1996 Sanborn Co., EDR Sanborn, Inc.

The Sanborn Library, LLC
This Sanborn® Map is a certified copy produced by Environmental Data Resources, Inc. under arrangement with The Sanborn Library, LLC. Information on this Sanborn® Map is derived from Sanborn field surveys conducted in:

Copyright © 1996 (Year) The Sanborn Library, LLC DCM (EDR Research Associate)

APPENDIX A

SITE PHOTOGRAPHS

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 1



Status as of: 4/10/02
Description: West Side Highway from Block 1089.
Photo by: Julie Abell Horn

Photo 2

Status as of: 4/10/02
Description: NW corner Block 1089.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 3



Status as of: 4/10/02
Description: SW corner Block 1089.
Photo by: Julie Abell Horn

Photo 4



Status as of: 4/10/02
Description: Across West Side Highway from Block 1089.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 58th Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 5



Status as of: 4/10/02
Description: Block 1089, parking lot under high rise apartment building.
Photo by: Julie Abell Horn

Photo 6



Status as of: 4/10/02
Description: Block 1089, parking lot under high rise apartment building.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 7



Status as of: 4/10/02
Description: Block 1089, landscaped area east of high rise apartment building.
Photo by: Julie Abell Horn

Photo 8

Status as of: 4/10/02
Description: Block 1089, landscaped area east of high rise apartment building, bermed up areas.
Photo by: Julie Abell Horn

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 9

Status as of: 4/10/02
Description: North side Block 1070, Fed Ex property on south side of 42nd Street.
Photo by: Julie Abell Horn

Photo 10

Status as of: 4/10/02
Description: North side Block 1070, Fed Ex property on south side of 42nd Street.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 11

Status as of: 4/10/02
Description: NE corner Block 1089, parking log.
Photo by: Julie Abell Horn

Photo 12

Status as of: 4/10/02
Description: East end Block 1089, parking lot.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 13

Status as of: 4/10/02
Description: NW corner Block 1070, Fed Ex building, 42nd Street / 11th Avenue.
Photo by: Julie Abell Horn

Photo 14



Status as of: 4/10/02
Description: SE corner Block 1070, 41st Street, Con Ed facility.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 15



Status as of: 4/10/02
Description: SE corner Block 1070, 41st Street / 11th Avenue.
Photo by: Julie Abell Horn

Photo 16

Status as of: 4/10/02
Description: Block 1070, north side of 41st Street, Con Ed Facility.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 17



Status as of: 4/10/02
Description: Block 1070, north side of 41st Street, Con Ed facility.
Photo by: Julie Abell Horn

Photo 18

Status as of: 4/10/02
Description: Block 1089, intersection of 41st Street / 11th Avenue in foreground, high rise in background.
Photo by: Julie Abell Horn

PHOTOGRAPHIC LOG
PARSONS

PROJECT: West 42nd Street
PROJECT #: 741280.04000

LOCATION:
CLIENT: Con Edison

Photo 19

Status as of: 4/10/02
Description: SE corner Block 1089. parking lot.
Photo by: Julie Abell Horn

APPENDIX B

EDR REPORT

APPENDIX C

DATA

PAHs were detected in many of the samples. The highest PAH levels were detected in surface and subsurface samples at Jane Street (BH-10, 320 ppm and 24 ppm) and subsurface samples at 18th Street (BH-14, 88 ppm, 85 ppm, and 19 ppm).

TPH was detected in all samples from BH-16 and BW-25 and in one sample each from BH-15 and BW-18. However, the TPH concentrations were fairly low, with the highest being 275 ppm in the 4- to 8-foot sample from BH-16.

Elevated levels of the metals arsenic, copper, lead, and zinc were detected in one or more samples. The subsurface samples near Horatio Street (BH-11) had the highest values. The highest lead level was detected in the 4- to 6-foot sample (2,410 ppm).

Low levels of cyanide was detected at West 18th Street (BH-14, surface, 1.1 ppm) and West 23rd Street (BW-18, 4 to 8 feet, 2.3 ppm).

Groundwater Analysis

One groundwater sample was collected from each of the five Phase 1B wells and from the seven Phase 1A wells in this segment. The Phase 1A well samples analyzed for total and dissolved metals.

VOCs were detected in all the groundwater samples. The sample from 16th Street (BW-13) contained 1,000 ppb of BTEX, and the sample from 26th Street (BW-24) had 226 ppb of BTEX. Between 2 to 15 ppb of BTEX were detected in the other samples. The sample from 16th Street (BW-13) also contained 63 ppb of PAHs, but the water had a turbidity value of 300 NTU. No PAHs were detected in the other samples. TPH was detected in three samples, 16th Street (BW-13, 3.7 ppm), 24th Street (BW-22, 3 ppm), and 26th Street (BW-24, 2.5 ppm). The sample from BW-13 was noted to have a strong petroleum odor during the sampling program.

Several metals—primarily iron and manganese, but also arsenic, barium, cadmium, copper, lead, mercury, and zinc—were detected at levels above the Class GA groundwater standards in the unfiltered samples collected from one or more of the new and existing wells. However, only iron and manganese exceeded this level in the filtered samples. Iron and manganese are not toxic and are included in the water standards because of aesthetic reasons.

E. CONVENTION CENTER: 29TH STREET TO 46TH STREET

GEOLOGY

Bedrock rises from about 125 feet beneath the surface at the southern end of the segment to about 50 feet between 40th and 41st Street and to only 15 or 20 feet beneath 46th Street. This is overlain by thin deposits of till and sand. Over the sand and till is organic silt about 10 to 30 feet thick. Miscellaneous fill, comprising dredged river sediments, construction debris, and coal plant ash, lies in thicknesses of 25 to 35 feet across the project corridor. North of 42nd Street, the bedrock is shallow, and the fill is typically 10 to 15 feet deep.

PHASE 1A SAMPLING RESULTS

Ten locations were sampled in this area: soil-gas survey was performed on the two blocks between 42nd and 44th Streets (G-41 and G-41b), surface and subsurface soil samples were collected from eight borings (H-35, H-36, H-37, W-38, W-39, H-40, H-42, and W-43) and groundwater samples were collected from three wells (W-38, W-39, and W-43).

The soil-gas survey did not detect any non-methane VOCs. An elevated level of methane was detected in one bore hole between 43rd and 44th Streets (G-41b) (> 10,000 ppm).

The soil analysis indicated the presence of PAHs in samples collected throughout this segment, particularly those from 41st to 46th Streets (H-40, 131 ppm, H-42, 166 ppm, and W-43, 50 ppm). Additionally, a sample from 40 feet below grade contained BTEX between 41st and 42nd Streets (W-39, 13 ppm). Total VOCs were detected at less than 1 ppm in all other samples. Metals were detected throughout the segment. No sample exceeded the RCRA EP Toxicity limits.

The groundwater analysis detected PAHs in samples collected from W-39 and W-43, but the sample had a turbidity value of 1,035 NTU. The sample from W-39 also contained low levels of BTEX. This area contained a storage system for gasoline and diesel fuel and a garage with buried gasoline tanks.

Several metals were detected at levels above the Class GA groundwater standards in samples collected from all three wells. However, the analysis was performed on only unfiltered samples.

PHASE 1B SAMPLING RESULTS

PROGRAM RATIONALE AND SCOPE

The Phase 1A data suggested the presence of VOCs, primarily BTEX, in the deep subsurface soil and groundwater between 40th and 41st Streets (W-39). The northern extent of this contamination was defined by the absence of any VOCs at 42nd Street (H-40). To better define the southern extent of this contamination, a groundwater monitoring well (BW-25) was installed between 39th and 40th Streets. Soil and groundwater samples were collected from this location and analyzed for TCL volatile and semivolatile organic compounds, TAL metals and cyanide, TPH, and TCLP parameters. Additionally, groundwater samples were collected from the three existing Phase 1A wells (W-38, W-39, and W-43) and analyzed for metals in filtered and unfiltered samples.

PROGRAM RESULTS

Soil Analysis

Four soil samples were collected from depths of 2 to 6 feet, 8 to 10 feet, 15 to 17 feet, and 28 to 32 feet for laboratory analysis from boring BW-25 between 39th and 40th

Streets. No VOCs were detected in any sample. PAHs were detected at less than 10 ppm total in the 2- to 6-foot and the 8- to 10-foot sample and were undetected in the deeper samples. Additionally, TPH and metals were detected at fairly low levels in all four samples. All TPH values were less than 100 ppm.

Groundwater Analysis

The only organic compounds detected in the groundwater sample was xylene at 3 ppb and bis(2-Ethylhexyl)phthalate at 34 ppb. These two compounds were also detected in the method blank and probably result from laboratory contamination. No PAHs or TPH were detected.

Metals analysis was performed on groundwater samples collected from four wells: well BW-25 and existing wells W-38, W-39, and W-43. Several metals were detected at levels above the Class GA groundwater standard in the unfiltered samples. However, only iron and manganese exceeded their standards in the filtered samples. Iron and manganese are not toxic and are included in the water standards because of aesthetic reasons.

F. CLINTON AREA: 46TH STREET TO 59TH STREET

GEOLOGY

Glacially abraded bedrock surface rises to within 5 feet of the ground surface beneath 51st Street to 54th Street and drops off to a depth of about 40 feet at the segment's northern end. Small pockets of sand are found over the bedrock. The fill beneath this segment comprises dredged river sediment, coal plant refuse, and construction debris and exists in thicknesses of approximately 5 to 25 feet, depending on the depth of the bedrock.

PHASE 1A SAMPLING RESULTS

Nine locations were sampled in this area. soil-gas samples were collected from between 47th and 48th Streets (G-43c), 50th and 51st Streets (G-44), 54th and 55th Streets (G-44b), 55th and 56th Streets (G-45a), and 56th and 57th Streets (G-45). Surface and subsurface soil samples were collected from four borings between 46th and 47th Streets (H-43b), 56th and 57th Streets (H-46), and two from between (58th and 59th Streets W-47, and H-48) as well as groundwater sampling from the one well (W-47).

The soil-gas survey did not detect non-methane VOCs on any of the five blocks. Elevated levels of methane was detected between 55th and 56th Streets (G-45a).

The soil analysis detected metals in some samples. All EP Toxicity metal levels were less than the RCRA limits.

Total VOCs were less than 1 ppm in all samples. Total PAHs were less than 10 ppm in all samples. PCBs were not detected in any samples.

Langan
Engineering and Environmental Services, P.C.

Bernard F Langan, P E
George E Dernck, P E
George P Kelley, P E
Michael A. Semeraro, Jr P E
David T. Gockel, P E.
Nicholas De Rose, P G
Cabot M Hudson, P E.

Andrew J. Ciancia, P.E
Gerard M Coscia P E
William G. Lothian, P.E
William F Mercurio, P E
Gerald J. Zamorella, C.E.A

Roger A. Archabal, P E
Gregory L. Biesiadecki, P E
Rudolph P. Frizzi, P E.
Ronald A Fuerst, C.L.A.
Cristina M Gonzalez, P E
Joel B. Landes, P.E
John J. McElroy, Jr., Ph.D P.E
Joseph E. Romano, P.L.S
Richard H. Zeigler, P E

CONSULTANT
Dennis J Leary, P E

March 19, 2001
1568902

Mr. Chi Chu
Silverstein Properties
521 Fifth Avenue
New York, New York 10175

Re: Summary of Environmental Investigation
West 41st Street and Eleventh Avenue
New York, New York

Dear Mr. Chu:

This letter has been prepared to summarize the results of investigations conducted along West 41st Street to characterize environmental conditions that may impact on the construction of a Con Edison utility vault. The utility vault will service the second phase of the two-phase River Place construction program that began in 1995. The project location is approximately the eastern half of the block between 41st and 42nd Streets and 11th and 12th Avenues. Construction of a residential high-rise on the western portion of the property has been completed and planning of the second phase of construction is proceeding. We understand the Con Ed vault is to have a total length of approximately 100 feet and is to be in the sidewalk area fronting West 41st Street.

INVESTIGATION

In March 2000, Langan advanced 6 borings (B-21, 22, 23, 24, 25 and 26) into competent bedrock on the 41st Street side of the property. Boring locations are shown on the attached drawing. During drilling of those borings, Langan observed conditions of the soil and collected 6 samples for chemical analysis from depths up to 27 feet below surface grade. Samples were analyzed for volatile and semi-volatile organic compounds in accordance with EPA Methodologies 8021, 8270 and TCLP metals. The results of the sample analysis are summarized and compared with NYSDEC STARS Guidance Values. STARS Guidance Values are the most stringent of NYS requirements for soil and groundwater.

Groundwater was encountered at a depth of approximately 10 feet below grade. Langan converted one of the borings into a monitoring well (B-22, MW-4) and sampled groundwater from this and one existing monitoring well at the southeast corner of the property near B-26 (MW-2). All sampled wells were properly developed before sampling. Groundwater samples were analyzed by USEPA methodology for parameters required by NYCDEP for discharge into the NYC combined sewer. The results are compared to the NYCDEP discharge criteria as well as NYSDEC STARS Guidance Values.

Logs for the six borings are provided in the Appendix A.

CELEBRATING 30 YEARS

RESULTS

- Stained and odorous material was observed in borings B-25 and B-26.
- No floating product was found in any of the existing or new monitoring wells.
- Four tables are provided showing analytical results for groundwater (Table 1) and Soil (Tables 2-4)

Levels of petroleum-related compounds that exceed NYS Cleanup Objectives and STARS Guidance Values were found in the soil to depth of the deepest boring. Groundwater was found to contain volatile organic compounds, particularly benzene, toluene, ethylbenzene and xylenes, and metals, including copper, lead, mercury and nickel that exceed NYS Ambient Water Quality Standards and STARS Guidance Values. All samples were below TCLP limits for hazardous waste.

We hope that this information is useful but we caution you that the data characterizes the areas where sampled only. Please call if we can be of any assistance.

Very truly yours,

Langan Engineering and Environmental Services, PC

Joel B. Landes, P.E.
Associate

cc. A. Ciancia



NOTES:

1. Boring locations are approximate.
2. Borings B1 through B26 were drilled by Warren-George, Inc. between 10 March and 14 April 2000 under the Full-Time controlled Inspection of Langan representatives.
6. Base site plan obtained from Costas Kondylis Architects, P.C.

Legend:

B1 - Boring and Well Location and Identification.

MW-2 - Monitoring Well.

—— - Aproximate Limits of Reference Site.

Langan
Engineering and Environmental Services

New York, NY Elmwood Park, NJ New Haven, CT Doylestown, PA Miami, FL

RIVER PLACE II

BORING LOCATION PLAN

NEW YORK — NEW YORK

PROJ. NO.	SCALE	DATE	FIG.
1568902	1" = 40'	3/19/2001	1

DATE	B6		MW2 MW3		B2		MW4 B22	
	DEPTH (FT)	ELEV (FT)	DEPTH (FT)	ELEV (FT)	DEPTH (FT)	ELEV (FT)	DEPTH (FT)	ELEV (FT)
03/15/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/15/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/16/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/17/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/20/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/21/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/22/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/23/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/24/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/27/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/28/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/29/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/30/2000	15.6	-3.4	20.4	-6.7	---	---	---	---
03/31/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	---	---
04/03/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	---	---
04/04/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/05/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/06/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/07/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/10/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/11/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/12/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/13/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
04/14/2000	15.6	-3.4	20.4	-6.7	5.6	5.7	9.7	2.8
06/08/2000	14.7	-2.5	19.2	-5.5	4.9	6.4	8.7	3.8

Depth (ft) is below ground surface
Elev (ft) is Manhattan Borough Datum

Langan
Engineering and Environmental Services
NEW YORK, NY · ELMWOOD PARK, NJ · NEW HAVEN, CT · DOYLESTOWN, PA · MIAMI, FL

RIVER PLACE II
GROUNDWATER LEVELS
MANHATTAN NEW YORK

PROJ. NO:	SCALE	DATE	
1568902	N.T.S.	725/00	TABLE 1

Table 1

Riv ce II

42nd St. and 11th Ave. NY, NY

Analytical Results for Water Samples

Sample Location	MW-2		MW4		Trip Blank	NYC DEP DISCHARGE AND DEWATERING REQUIREMENTS	NY State DEC Water Quality Regulations Groundwater Standards
Sampling Depth	25-30 ft		20-25 ft		198393		
Langan Sample Number	021-MW-2-GW1		019-MW-1-GW1		4/12/00		
Lab Sample Number	198645		198392		1.0		
Sampling Date	4/17/00		4/14/00		mg/l		
Unit	mg/l		mg/l			mg/l or ppm	(ppm)
Parameters		DF		DF			
Cadmium	0.0011	NA	0.0008 U	NA		< 2	0.005
Copper	0.0359	NA	[redacted]	NA		< 5	0.2
Lead	[redacted]	NA	[redacted]	NA		< 2	0.025
Mercury	0.0001 U	NA	[redacted]	NA		< 0.05	0.0007
Nickel	0.0161	NA	[redacted]	NA		< 3	0.1
Zinc	0.27	NA	1.22	NA		< 5	NA
Molybdenum	0.0174	NA	0.0065	NA		no limit	NA
Benzene	[redacted]	1.0	[redacted]	50.0	0.0003 U	< 0.01	0.001
Tolune	0.0003 U	1.0	[redacted]	50.0	0.0003 U	< 0.01	0.005
Ethylbenzene	0.0003 U	1.0	[redacted]	50.0	0.0003 U	< 0.01	NA
Xylene (total)	0.0003 U	1.0	[redacted]	50.0	0.0003 U	< 0.01	NA
Total Petroleum Hydrocarbon	1.0 U	NA	1.0 U	1.0		< 50	NA
Total Cyanide	0.01 U	1.0	0.44	2.0		NA	NA
Total Suspended Solid	0.13	1.0	0.445	1.0		no limit	NA
Oil and Grease	10.0 U	NA	10 U	1.0		no limit (15mg/l daily max)	NA
Chromium VI	0.010 U	1.0	0.001 U	1.0		< 5	NA
Cyanide Amenable	0.01 U	1.0	0.02	2.0		< 0.2	NA
pH	7.48	1.0	7.1	1.0		5<pH<11	6.5<pH<8.5
Ignitability (degrees F)	>160	1.0	>160	1.0		> 140 degrees F	NA
Pesticides/PCBs							0.1 ppb
Aroclor-1016	0.30 U	1.0	0.30 U	1.0			
Aroclor-1221	0.30 U	1.0	0.30 U	1.0			
Aroclor-1232	0.30 U	1.0	0.30 U	1.0			
Aroclor-1242	0.20 U	1.0	0.20 U	1.0			
Aroclor-1248	0.30 U	1.0	0.30 U	1.0			
Aroclor-1254	0.20 U	1.0	0.20 U	1.0			
Aroclor-1260	0.40 U	1.0	0.40 U	1.0			
Aroclor-1262	0.20 U	1.0	0.20 U	1.0			
Aroclor-1268	0.20 U	1.0	0.20 U	1.0			

U- The compound was not detected at the indicated concentration. DF- Dilution Factor

Note_1= Shaded values are those that exceed NY State DEC standards.

Note_3= Lab results were all converted to mg/l to be consistent with the NYCDEP concentration unit. Note_2= Bolded values are those that exceed NYC DEC Discharge standards.

Note_4= NY State DEC Water Quality Regulation values for groundwater values were all converted to mg/l to be consistent with the lab and NYCDEP concentration unit.

Table 2

River Place Phase II
42nd St. and 11th Ave.
New York, NY
Analytical Results for Volatile Organic Compounds in Soil Samples

Sample Location	B-21		B-23		B-25		B-25		B-25		B-26		NYS DEC TCLP Alternative Guidance Values (ppb)
Sample Depth (ft)	15-17 ft		25-27 ft		5-7 ft		15-17 ft		20-22 ft		21-22 ft		
Langan Sample Number	008_B-21_SS4		012_B-23_SS6		016_B-25_SS2		010_B-25_SS4		015_B-25_SS5		013_B-26_SS5		
Laboratory Sample Number	194976		197410		197414		194978		197413		197411		
Sampling Date	3/29/00		4/6/00		4/11/00		4/3/00		4/11/00		4/7/00		
Dilution Factor	1.0		50		50		1.0		5000		50		
Units	ug/kg		ug/kg		ug/kg		ug/kg		ug/kg		ug/kg		
Volatile Compounds (GC)													
Benzene	6.2	U	130	U	120	U	12		13000	U	[redacted]		14
Toluene	6.2	U	130	U	120	U	6.3	U	[redacted]		[redacted]		100
Ethylbenzene	6.2	U	[redacted]		120	U	6.3	U	[redacted]		[redacted]		100
Isopropylbenzene	6.2	U	[redacted]		120	U	6.3	U	13000	U	120	U	100
n - Propylbenzene	6.2	U	130	U	120	U	6.3	U	13000	U	120	U	100
1,3,5-Trimethylbenzene	6.2	U	130	U	120	U	6.3	U	13000	U	120	U	100
tert-Butylbenzene	6.2	U	130	U	120	U	6.3	U	13000	U	120	U	100
1,2,4-Trimethylbenzene	6.2	U	130	U	120	U	6.3	U	[redacted]		[redacted]		100
sec-Butylbenzene	6.2	U	130	U	120	U	6.3	U	13000	U	120	U	100
p-Isopropyltoluene	6.2	U	[redacted]		120	U	6.3	U	13000	U	120	U	100
n-Butylbenzene	6.2	U	130	U	120	U	6.3	U	13000	U	120	U	100
Naphthalene	42		[redacted]		[redacted]		24		[redacted]		[redacted]		200
MTBE	6.2	U	130	U	120	U	6.3	U	13000	U	120	U	1000
Total Xylenes	6.2	U	[redacted]		120	U	6.3	U	[redacted]		[redacted]		100

U- The compound was not detected at the indicated concentration.

J- Data indicates the presence of a compound that meets the identification criteria. The result is less than the quantitation limit but greater than zero. The concentration given is an approximate value.

B- The analyte was found in the laboratory blank as well as the sample. This indicates possible laboratory contamination of the environmental sample.

Notes= Shaded values are those that exceed applicable regulatory limits.

Table-3

River Place Phase II
42nd St. and 11th Ave. NY,NY
Analytical Results for Semi-Volatile Organic Compounds in Soil Samples

Sample Location	B-21	B-23	B-25	B-25	B-25	B-26	NYS DEC TCLP Alternative Guidance Values ppb	Human Health Guidance Values ppb
Sample Depth (ft)	15-17 ft	25-27 ft	5-7 ft	15-17 ft	20-22 ft	21-22 ft		
Langan Sample Number	008_B-21_SS4	012_B-23_SS6	016_B-25_SS2	010_B-25_SS4	015_B-25_SS5	013_B-26_SS5		
Laboratory Sample Number	194976	197410	197414	194978	197413	197411		
Sampling Date	3/29/00	4/6/00	4/11/00	4/3/00	4/11/00	4/7/00		
Dilution Factor	1.0	1.0	2.0	1.0	100	5.0		
Units	ug/kg	ug/kg	ug/kg	ug/kg	ug/kg	ug/kg		
Semivolatile Compounds (GC/MS)								
Naphtalene	1300	760	3800	240 J	220000	6600	200	300,000
Acenaphtalene	580	430 U	1900	50 J	43000	1800	400	500,000
Fluorene	690	430 U	1900	39 J	43000	1700	1000	300,000
Phenanthrene	2800	29 J	4700	300 J	43000	11000	1000	***
Anthracene	730	430 U	1900	93 J	43000	1800	1000	20,000,000
Fluoranthene	2700	22 J	10000	440	43000	16000	1000	3,000,000
Pyrene	2500	16 J	8700	360 J	34000	9200	1000	2,000,000
Benzo(a)anthracene (1)(2)	1200	43 U	4200	170	29000	4300	0.04	220
Chrysene (1)	1400	430 U	4200	190 J	28000	4000	0.04	***
Benzo(b)fluoranthene (1)(2)	1400	43 U	4400	180	22000	3600	0.04	220
Benzo(k)fluoranthene (1)(2)	670	43 U	2200	79	43000	1800	0.04	220
Benzo(a)pyrene (1)(2)	1300	43 U	4900	160	21000	3900	0.04	61
Indeno(1,2,3-cd)pyrene (1)(2)	830	43 U	3200	84	16000	2200	0.04	***
Dibenz(a,h)anthracene (1)(2)	200	43 J	1100	23 J	4300 U	370	1000	14
Benzo(g,h,i)perylene (1)(2)	830	430 U	2800	79 J	8000 J	940	0.04	***

U- The compound was not detected at the indicated concentration.

J- Data indicates the presence of a compound that meets the identification criteria. The result is less than the quantitation limit but greater than zero. The concentration given is an approximate value.

B- The analyte was found in the laboratory blank as well as the sample. This indicates possible laboratory contamination of the environmental sample.

Notes= Shaded values are those that exceed regulatory guidance limits.

(1) Due to the high detection limit for a sloild matrix, the TCLP Extraction Method must be used to demonstrate ground water quality protection for these compounds.

(2) For these 7 compounds Human Health Guidance Value will be the limiting factor for achieving acceptable cleanup levels.

***- No Guidance Value Identified in EPA Heast Report.

Table 4

River Place Phase II
42nd St. and 11th Ave.
New York, NY
Analytical Results for TCLP Metals

Sample Location	B-21	B-23	B-25	B-25	B-25	B-26	Hazardous Waste Regulatory Levels for Toxicity Characteristic (mg/l)
Sample Depth	16-17 ft	26-27 ft	5-7 ft	16-17 ft	20-22 ft	21-22 ft	
Langan Sample Number	008_B-21_SS4	012_B-23_SS6	016_B-25_SS2	010_B-25_SS4	015_B-25_SS5	013_B-26_SS5	
Lab Sample Number	194976	197410	197414	194976	197413	197411	
Sampling Date	3/29/00	4/7/00	4/11/00	4/3/00	4/11/00	4/7/00	
Dilution Factor	NA	NA	NA	NA	NA	NA	
Units	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	
Compounds							
Arsenic	0.35 B	0.016 U	0.016 U	0.20 U	0.016 U	0.016 U	5
Barium	6.5	12.5	9.8	5.5	8.8	11.8	100
Cadmium	0.006 U	0.002 U	0.002 U	0.006 U	0.002 U	0.002 U	1
Chromium	0.017 U	0.008 U	0.008 U	0.017 U	0.008 U	0.008 U	5
Lead	0.25 B	0.011 U	0.01 U	0.36 B	0.011 U	0.011 U	5
Mercury	0.0001 U	0.0001 U	0.0001 U	0.0001 U	0.0001 U	0.0001 U	0.2
Selenium	0.14 U	0.021 U	0.021 U	0.17 B	0.021 U	0.021 U	1
Silver	0.017 U	0.007 U	0.007 U	0.017 U	0.007 U	0.007 U	5

U- The compound was not detected at the indicated concentration.

J- Data indicates the presence of a compound that meets the identification criteria. The result is less than the quantitation limit but greater than zero. The concentration given is an approximate value.

B- The analyte was found in the laboratory blank as well as the sample. This indicates possible laboratory contamination of the environmental sample.

Notes- Shaded values are those that exceed applicable regulatory limits.

Langan
Engineering and Environmental Services, Inc.

LOG OF BORING M-21 SHEET 1 OF 13

PROJECT River Place II		PROJECT NO. 1568401	
LOCATION 42nd + 11th Ave. NY		ELEVATION AND DATUM 12.37	
DRILLING AGENCY Warren George		DATE STARTED 3/29/00	DATE FINISHED
DRILLING EQUIPMENT Diedrich D-50		COMPLETION DEPTH 49'	ROCK DEPTH 39'
SIZE AND TYPE OF BIT 4 5/8 Roller Bit		NO. SAMPLES DIST. 8	UNDIST. — CORE 2
CASING 4" Steel		WATER LEVEL FIRST —	COMPL — 24 HR. —
CASING HAMMER WEIGHT 140	DROP 30	FOREMAN Vinny Mitchell	
SAMPLER 2" OD Split Spoon		INSPECTOR Kris Regula	
SAMPLER HAMMER WEIGHT 40	DROP 30		

		SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO.LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLS/6in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL	11-65	Brown topsoil trace to some gravel, brick (FILL)	1	S5	1	2 IN	4 24 96 26	No odors 8:15 Sample was wet Split spoon was hammered through asphalt.
			2					
			3					
			4					
			5					
	11-65	Dark Gray SILT trace to some fine gravel, brick (FILL)	6	S4	2	3 IN	1 2 2 2	No odors 8:50 Sample was wet.
			7					Roller bitting down to ten feet
			8					
			9					
			10					
	11-65	Dark Gray SILT trace to some fine-medium sand, coarse-medium gravel	11	S5	3	6 IN	5 7 4 4	Sample was wet. 9:00 No odors present.
			12					
			13					

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 3/30/00

LOG OF BORING NO. B-21

SHEET 3 OF 3

Matl Symbol	N/COC	SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO.	TYPE	RECOV. FT.	PENETR. RESIST BLWS/IN.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
A N D	10-65	Dark Gray SAND trace to some silt, Clay	30					
			31	S5	7	24 IN	1 - - 22 26	Sample was wet 8:15am No odors present.
			32					
			33					
			34					
			35					
DEC. ROCK	4-05	Dark Gray Fine-medium sand trace to some coarse gravel	36	S6	8	5 IN	96 100/6"	Hammered hard 8:45am to drive PID=0 No odors, sample wet Hard drilling
			37					
			38					
			39					
GNEISSIC SCHIST/ GRANITIC PIGMENTITE	1-65	First 9 inches of Run Gneissic Schist White, light greenish/gray light orange with mixture of little schist and garnets	40 41 42 43 44	First Run	NX - Double Barrel	60"	REC: 57.5/60 = 94% RQD = 54/60 = 90%	coring started at 11:15 Speed increased at 11:25 after second foot of run. No fluid loss.
Granitic pigmentite	1-65	Light greenish/gray White Same as above.	45 46	Second Run	NX - Double Barrel	60"	REC: 100% RQD = 100%	

Langan
Engineering and Environmental Services, Inc.

JOB NO. 15688901
DATE 3/30/00

LOG OF BORING NO. B-21

SHEET 4 OF 4

Mat'l Symbol	NYCBC	SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO. LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLS/6 in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
GRANITIC GNEISS	1	65'- Same as above	46	SECOND RUN	NX - Core Barrel	60"	REC = 100% RQD = 100%	No fluid loss during coring.
			47					
			48					End of coring run
			49					
			50					
			51					
			52					
			53					
			54					
			55					
			56					
			57					
			58					
			59					
			60					
			61					
			62					

Langan
Engineering and Environmental Services, Inc.

LOG OF BORING B-22 SHEET 1 OF 3

PROJECT	River Place II	PROJECT NO.	1568901
LOCATION	42nd & 11th Ave. NY	ELEVATION AND DATUM	12.52
DRILLING AGENCY	Warren George, Inc	DATE STARTED 4/03/00	DATE FINISHED 4/4/00
DRILLING EQUIPMENT	Falling	COMPLETION DEPTH 42.5'	ROCK DEPTH 35'
SIZE AND TYPE OF BIT	4 5/8" Roller Bit	NO. SAMPLES DIST. 7 UNDIST. —	CORE 2
CASING	4" Steel	WATER LEVEL FIRST — COMPL. —	24 HR. —
CASING HAMMER	WEIGHT 140 DROP 30	FOREMAN	Vinny Mitchell
SAMPLER	2" OD Split Spoon	INSPECTOR	Kris Regula
SAMPLER HAMMER	WEIGHT 40 DROP 30		

Mat'l Symbol	USCS	SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BL/6 in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
								10:30
FILL	11-65	Light Brown Sand some coarse gravel (FILL)	1	SS 1	1	12 FN	6 18 15 11	12:25
			2					
			3					Roller bitting down
			4					
			5					
	11-65	Coarse Gravel trace peat (FILL)	6	SS 2	2	4 FN	10 7 3 2	Sample was wet. No odors present. 12:40
			7					
			8					
			9					
			10					
	11-65	Wood with trace fine Sand (FILL)	11	SS 3	3	12 FN	8 1 14 11	Sample was moist. No odors present 12:50
			12					
			13					
			14					

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 4/14/00

LOG OF BORING NO. B-22

SHEET 2 OF 3

Mat'l Symbol	NYCoC	SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLWS/in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL	11-65	Gray fine-medium sand trace to some gravel, brick (FILL)	15	SS	4	6 IN	12 7 6 6	Sample was wet. 1:05 No odors present.
			16					
			17					
			18					
			19					
			20					
	11-65	Wood (FILL)	21	SS	5	1 IN	100/2"	1:55 Hammer bounced continuously.
			22					
			23					
			24					
			25	Shelby	1	10 IN	WOH	Shelby tube with 10:35 a piston push device used.
RIVERA DEPOSIT	11-05	Dark Gray CLAY Dark Gray CLAY trace sand, silt peat fibers	26					
			27	SS		6 IN	WOH 2 2	Sample was wet. 10:50 No odors present
			28					
			29					
			30					
			31					

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE

LOG OF BORING NO. B-22
SHEET 3 OF 3

		SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLWS/in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
			30					
org. clay		Dark Gray CLAY, trace to some sand, peat fibers	31	SS	T	18 IN	1 1 7 17	
DEC. ROCK	4-45	Decomposed Mica Schist	32					
			33					
			34					
			35					
ROCK			36	FIRST RUN	Nx - Double Core Barrel	60"	REC = 100% RQD =	
			37					
			38					
			39					
			40					
			41	Second Run	Nx - Double Barrel	30"		
			42					
		END OF BORING @ D = 42.5'	43					
			44					
			45					
			46					

Langan
Engineering and Environmental Services, Inc.

LOG OF BORING B-23 SHEET 1 OF 4

PROJECT Warren George		PROJECT NO. 156890i	
LOCATION 42nd & 11th Ave. NY		ELEVATION AND DATUM 12.70	
DRILLING AGENCY Warren George		DATE STARTED 4/5/00	DATE FINISHED 4/5/00
DRILLING EQUIPMENT CME 8000		COMPLETION DEPTH 50'	ROCK DEPTH 35 ft
SIZE AND TYPE OF BIT 4 1/4 Roller Bit		NO. SAMPLES DIST. 7 UNDIST. —	CORE 2
CASING 4" Steel Casing Advancer		WATER LEVEL FIRST —	COMPL — 24 HR. —
CASING HAMMER WEIGHT 140	DROP 30	FOREMAN Tommy Gregory	
SAMPLER 2" OD Split Spoon		INSPECTOR Kris Regek	
SAMPLER HAMMER WEIGHT 140	DROP 30		

		SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BL/6 in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
								Drilled down to 1 foot.
FILL	11-65	Dark Gray Sand some coarse-fine gravel (FILL) B	1	S5	—	18 IN	2 13 13 15 12	9:00 Sample was Dry. No odors present.
			2					
			3					
			4					
	11-65	Black Topsoil trace fine gravel (FILL)	5	S6	2	1 IN	1 2 1	9:20 No odors present Sample was wet.
			6					
			7					
			8					
			9					
	11-65	Dark Gray/Brown fine - sand trace fine gravel (FILL)	10	S7	3	0 IN	27 7 6 3	No odors present Sample was moist. Roller bitting down to 25.'
			11					
			12					
			13					
			14					

Langan
Engineering and Environmental Services, Inc.

JOB NO. _____
DATE _____

LOG OF BORING NO. B-23

SHEET 2 OF 4

Mat'l Symbol	NYCBC	SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO.LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLWS/6in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL	11-65	Dark Gray SAND trace clay	15					
			16	SS	SPT	18"	5 7 7 9	Sample was wet No odors present. Roller bitting down to 20.'
			17					
			18					
			19					
			20					
FILL	11-65	Wood with some gray clay. trace sand	21	SS	SPT	5"	10/5"	No odors present Hammer/spoon kept bouncing.
			22					
			23					
			24					
			25					
Organic Clay	11-65	Dark Gray CLAY trace sand, peat fibers	26	SS	SPT	18"	WOR	Sample was moist. Environmental Sample taken
			27					
			28					
			29					
			30					
			31					

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE

LOG OF BORING NO. B-23
SHEET ____ OF ____

SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO.LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLS/6in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
	29					
	30					
Decomposed Black mica Schist Decomposed greenish Mica Schist with some clay	31	4-65	4-7	16in	25 87 100/1"	Sample was moist easily breakable. Roller bitting down to 35'. Rig is chattering
	32					
	33					
	34					
	35					
Highly Fractured Mica Schist Changind to Granite trace garnets	36	3-65	First Run Nx-Core Barrel 60"	REC = 52% RQD = 20%		Sample was washed away probable decomposed Mica Schist.
	37					
	38					
	39					
	40					
White/Pink Granite trace garnets Vertical Fracture on section of rock orange staining on joints	41	2-65	Second Run Nx-Core Barrel 60"	REC = 55%-95% RQD = 84%		
	42					
	43					
	44					
	45					
	46					

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 4/6/00

LOG OF BORING NO. B-23

SHEET 4 OF ___

SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLS/6 in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
	45					
White/pink granite trace garnets	46	1-6S	Third Run NX - Double Core Barrel	60"	REC = 100% RQD = 76%	No fluid loss during coring
	47					
	48					
	49					
	50					End of Boring.
	51					
	52					
	53					
	54					
	55					
	56					
	57					
	58					
	59					
	60					
	61					

GRANITE

Langan
Engineering and Environmental Services, Inc.

LOG OF BORING B-24 SHEET 1 OF 4

PROJECT RIVERPLACE		PROJECT NO. 15689901	
LOCATION 42ND St & 11TH AVE, MANHATTAN NY		ELEVATION AND DATUM 12.917	
DRILLING AGENCY WARREN GEORGE & INC.		DATE STARTED 04/11/00	DATE FINISHED 04/12/00
DRILLING EQUIPMENT FALING 1500 TRUCK MOUNTED DRILL Rig		COMPLETION DEPTH 60.0 FT	ROCK DEPTH 49.0 FT
SIZE AND TYPE OF BIT 4 7/8 & 6 1/4 TRICONE ROLLER BIT		NO. SAMPLES DIST. 10 UNDIST. 1 CORE 2	
CASING 3 7/8 & 4 INCH DIA FLUSH JOINT CASING		WATER LEVEL FIRST — COMPL — 24 HR. —	
CASING HAMMER WEIGHT DROP		FOREMAN VINNY MITCHEL/ MARTIN	
SAMPLER 24 IN SPLIT SPOON		INSPECTOR CYNTHIA BURZYNSKI	
SAMPLER HAMMER WEIGHT 140 # DROP 30 IN			

MAT'L SYMBOL	SAMPLE DESCRIPTION	CASING BLOWS	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLOS/in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL 11-65	ROLLER BIT THROUGH 12 IN CONCRETE SURFACE	CASING 3 7/8 IN SPLIT SPOON 2 IN	1					BEGAN DRILLING AT 715 04/11/00
	S-1 DK Gray Cf SAND Some mf Gravel Some Clayey Silt, tr brick frag fill 11-65		2	S-1	SS	15 IN	7 22 20 11	MIX MUD, ROLLER BIT TO 1 FT (dk. Brown wash)
			3					
			4					
			5					ROLLER BIT TO 5 FT (little wood in wash 5-7')
FILL 11-65	S-2 TOP 3 IN Gray brown mf SAND MID 3 IN DK BRAY CINDERS & WOOD Lt Clayey Silt. (SLIGHT ODOR) BOT 4 IN (SAME AS TOP 3 IN) (FILL), (11-65)		6	S-2	SS	15 IN	2 2 3 2	
			7					
			8					
			9					
			10					ROLLER BIT TO 10 FT
FILL 11-65	S-3 TOP 4 IN Gray Brown mf SAND BOT 10 IN Gray mf SAND Some Clayey Silt tr brick frag, Cinders (Slight ODOR) (FILL) (11-65)		11	S-3	SS	18 IN	5 9 9 7	
			12					
			13					
			14					

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 04/11/00

LOG OF BORING NO. B-24
SHEET 2 OF 4

MAT'L SYMBOL	WELL CASING	SAMPLE DESCRIPTION	CASING BLOWS	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLOWS/FT.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL	11-65	S-4 Same as above ~~for S-3 (bot)~~ w/ one piece of coal (Slight ~~Creosote~~ odor) (FILL) (11-65)	SPIN 5 IN DIA CASING 0 FT TO 20 FT	14 15 16 17 18 19 20	S-4	SS	4 IN	1 4 7	ROLLER BIT TO 15 FT
FILL	11-65	S-5 TOP 3 IN dk Gray Clay & Silt ~~trace~~ ~~BOT 12 IN~~ Dk Gray Cf SAND and Cinders, lt Clayey Silt (Creosote odor) FILL (11-65)		20 21 22 23 24 25	S-5	SS	15 IN	2 11 65	ROLLER BIT TO 20' (Creosote odor from 20 FT TO ___ SPIN 5 IN DIA CASING 0 FT TO 20 FT. ROLLER BIT TO 25'
Organic Clay	11-65	S-6 GRAY BROWN CLAY & SILT, lt ~~f SAND~~ ~~peat fibers~~ (11-65) (PPV = 0.25 - ~~0.5 tsf~~) U-1 (PISTON TUBE) Sample from BOT Same as above (PPV = 0.5 - 0.7 tsf)	SPIN 4 IN	25 26 27 28 29 30	S-6	SS	20 IN	1 1 2 2	BLOW PISTON TUBE w/ 12 10 PM U-1 EXTRACT U-1 12 40 PM
					U-1	PISTON	24 IN	P P P	
SAND	11-65	S-7 ~~TOP 6 IN~~ Same as above ~~BOT 18 IN~~		30 31	S-7	SS	24 IN	3 4 4 5	follow with S-7
									SPIN 5 IN DIA CASING

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 4/11/00

LOG OF BORING NO. B-24
SHEET 3 OF 4

WATER LEVEL OBSERVATIONS	SAMPLE DESCRIPTION	CASING BLOWS	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLOWS/FT.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
			32					ROLLER BIT to 35' Rig chattering at 34-
			33					
			34					
	S-8 Red Brown C-f SAND, l-m-f Gravel, tr Clayey Silt. (7-65)	5 P 1 2 4"	35	S-8	SS	14 IN	24 26 25 28	
			36					
			37					
			38					
			39					
	S-9 TOP 3 IN SAME AS ABOVE		40					ROLLER BIT to 40 FT
	Gray White & Red C-f GRAVEL lt c-f SAND, tr Silt (6-65)	5 P 1 2 4"	41	S-9	SS	12 IN	18 12 70 87	
			42					
			43					
			44					
			45					ROLLER BIT to 45 FT
	S-10 Red Brown C-f SAND and SILT & Clay, tr C-f Gravel		46	S-10	SS		78 100/3	ROLLER BIT and INSTALLED 4" CASING 0 - 49 FT
			47					
			48					
	DECOMPOSED		49					VERY HARD DRILLING FROM 49'

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 4/12/00

LOG OF BORING NO. B-24

SHEET 4 OF 4

MATL SYMBOL	SAMPLE DESCRIPTION	JOINTS	CASING	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLOW/in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
Soft Rock				49					ROLLER BIT TO 50'
				50					
ROCK	C-1 Dark Gray Mica Schist with 1/2" wide vein of White Gray Granite from — to (2-65)			51	C-1 50.0-55.0	NX DOUBLE CORE BAR	REC = 60/60 = 100%	RQD = 55/60 = 91%	BEGAN CORING ROCK 10:40 AM EXTRACTED ROCK C-1 11:20 AM
				52					
				53					
				54					
				55					
ROCK	C-2 Dark Gray Mica Schist (2-65)			56	C-2 55.0-60.0	NX	REC = 60/60 100%	RQD = 60/60 = 100%	BEGAN CORING ROCK @ 11:35 AM EXTRACTED ROCK C-2 12:35 PM
				57					
				58					
				59					
				60					
	END OF BOREHOLE AT 60.0 FT 2:40 PM 04/12/00 BOREHOLE BACKFILLED UPON COMPLETION 2:40 PM 04/12/00								

Langan
Engineering and Environmental Services, Inc.

LOG OF BORING B-25 SHEET 1 OF 4

PROJECT: RIVER PLACE		PROJECT NO.: 1568901	
LOCATION: 42ND ST & 11TH AVE, MANHATTAN NY		ELEVATION AND DATUM: 13.30	
DRILLING AGENCY: WARREN GEORGE INC.		DATE STARTED: 04/03/00	DATE FINISHED: 04/06/00
DRILLING EQUIPMENT: MOBILE TRUCK MOUNTED DRILL RIG		COMPLETION DEPTH: 51.0 FT	ROCK DEPTH: 49.5'
SIZE AND TYPE OF BIT: 4" DIA CASING AQUANEER W/ 3 7/8 IN ROLLER BIT		NO. SAMPLES: DIST. 8	UNDIST — CORE 3
CASING: 5 IN DIA, 4 IN DIA FLUSH JOINT CASING		WATER LEVEL: FIRST —	COMPL. — 24 HR. —
CASING HAMMER: WEIGHT: DROP:		FOREMAN: MARK ST. JOHN & TOM GREGORY / SEAN DALTON	
SAMPLER:		INSPECTOR: JIMMY MITCHELL / MARTIN C. BURZYNSKI	
SAMPLER HAMMER: WEIGHT 140# DROP 30 IN			

2 1/4 IN ROLLER BIT

MARK Symbol	NYC ASA MODIFIED	SAMPLE DESCRIPTION	CASING BLOWS	DEPTH SCALE	SAMPLES NO. LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETA. RESIST BLS/IN.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
		ROLLER BIT THROUGH 8" CONCRETE SURFACE (NO REBAR)		1					BEGAN DRILLING AT 04/03/00 930 AM.
FILL	11-65	S-1 DK. Gray, gray & DK Orange CINDERS, Some f SAND, little mf Gravel, tr brick & glass (Fill), (11-65)	SPIN 4 IN DIA CASING & ROLLER BIT TO 5 FT	2	S-1	SS	22 IN	9 10 7 4	ROLLER BIT TO 1 FT
				3					SPIN 4 IN DIA CASING AND ROLLER BIT TO 5 FT
				4					(Wash gray brown)
				5					(DRILL W/ FRESH WATER)
FILL	11-65	S-2 Gray Brown, DK Gray & White SILT & Clayey Some mf Sand, tr Cinders & brick fragments (Fill), (11-65)	SPIN 4 IN DIA CASING & ROLLER BIT TO 10'	6	S-2	SS	20 IN	4 4 5 5	
				7					
				8					
				9					
FILL w/ WOOD	11-65	S-3 Dk Red Brick fragments, Some Gray Brown Silt & Clay, tr. Wood (Vert Grain) tr mf Sand (FILL) (11-65).		10					
				11	S-3	SS	8 IN	8 6 5 3	
				12					
		Possible Sand & Gravel (See S-4)		13					RIG CHATTERING AT 13'-13.5'
				14					

Langan
Engineering and Environmental Services, Inc.

LRN 04/17/00

JOB NO. 156890\
DATE 04/03/00

LOG OF BORING NO. B-25
SHEET 2 OF 4

MATL SYMBOL	SAMPLE DESCRIPTION	CASING BLOWS	DEPTH SCALE	SAMPLES NO./LOC.	TYPE	RECOV. FT.	PENETR. RESIST BLOWS/FT.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
organic clay	B-4 Gray, SILTY CLAY, some f sand, lt wood (vert) tr m gravel	SPIN 4" & 5"	14 15 16 17 18 19	S-4	SS	15 IN	5 7 3 3	SPIN 4" OD CASING & ROLLER BIT TO 15' (WOOD IN WASH FROM 11 FT ±).
organic clay	S-5 20.0-20.3 Gray SILT & CLAY and m GRAVEL, (9-65) ~~to wood~~. (PILE)	SPIN 4" & 5"	20 21 22 23 24	S-5	SS	3 IN	100/4"	NOTES: Strong creasote odor in Sample S-5. SPIN 4" OD CASING (9" 20 FT - 20.5' CASING BROKE OFF AT TOP 6" .) ENCOUNTERED HARD WOOD OBSTRUCTION (possible Pile) AT 20.5
organic clay	S-6A TOP 15" Gray, SILT & CLAY; some Peat, some cf sand ppb 0.5 to 1.0 (9-65)	SPIN 4"	25 26	S-6	SS	21 IN	WOH 3 4 5	ROLLER BIT 20-25' (END OF WOOD AT 23')
Sand & Silt	S-6B BOT 6" Gray cf SAND, lt Silt & Clay (7-65)		27 28 29					Add mud at 23' ROLLER BIT TO 30' Color Change in Wash to red brown at 29'
	S-7 Red Brown cf SAND, lt Clayey Silt, tr f gravel (7-65)		30 31 32	S-7	SS	12 IN	10 11 10 10	ENDED DRILLING AT 04/03/00 3:05 pm

Langan
Engineering and Environmental Services, Inc.

JOB NO. 158901
DATE 04/04/00

LOG OF BORING NO. B-25

SHEET 3 OF 4

SAMPLE DESCRIPTION	DEPTH SCALE	SAMPLES NO. LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLOWS/FT.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
Sand, Gravel, Cobble, Silt, Clay	32					BEGAN DRILLING 04/04/00 AT 730 AM
	33					BEGAN MIXING MUD
C-1 34.0 - 35.6 Gray & White Gneissic Schist (Boulder (18 IN)) (6-65)	34	C-1 34.0 35.5	NW DOUBLE	Rec = 18"	RQD = N/A	ROLLER BIT to 34' RIG CHATTERING
Boulder 0-65	35					
= = Possible Hardpan	36					Red brown wash continued
Hardpan 5-65	37					
	38					
	39					
C-2 39.5-40.4 White & lt gray Granitic (cobble (4 IN)) over dk Red Sandstone (Cobble (5 IN)) (6-65)	40	C-2 39.5	Core NX	Rec 9"	RQD = N/A	
Cobble 5-65	41					
Hardpan 5-65	42					ROLLER BIT TO (45' Hard drilling), (red brown wash continued)
	43					
	44					
	45					
	46	S-8 5'	SS		30 6 100/4	
S-8 Red Brown cf Gravel some cf sand, little silt & clay (hardpan) 5-65	47					ROLLER BIT TO 47' Hard drilling
See Pg 4	48					Could not get Core barrel past 34'
	49					RIG BEGAN DRILLING AT

JOB NO. 158901

DATE 04/05/00

LOG OF BORING NO. B-25

SHEET 4 OF 4

MAT'L SYMBOL	USCS CODE	DESCRIPTION	CORING RATE	DEPTH SCALE	SAMPLES NO. LOG.	SAMPLES TYPE	SAMPLES RECOV. FT	SAMPLES PENETR RESIST BLOWS/ft.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
Hard Ang. Cobble		SPT 47 to 47.2		46					BEGAN DRILLING 04/05/00 800 AM
		47.0 - 48.5 white, Gray & Lt Gray Granitic PEGMATITE COBBLE (4 IN) and DK. Gray GNEISSIC SCHIST COBBLE (2½ IN)	3	47					FINISHED PULLING OUT 4 IN Ø CASING & CASING ADVANCER 1040 AM
HARD			3	48					
Cobble			4	49					
HARD			5	50					DRILLED TO 47 FT WITH 4 7/8 ROLLER BIT; INSTALLED 5 IN Ø CASING TO 25 FT, AND 4 IN Ø CASING TO 45 FT.
Rock	2-65		2	51	C-3 47.0'-51.5' NX DOUBLE TUBE Core = 92%			RQD = N/A	
		48.5 - 51.5 white & Lt Gray GRANITE with trace Gray Schist. (Bedrock) (22 IN) (Highly fractured from 48.5'-50.0') (2-65)		52					135 PM BEGAN CORING ROCK FROM 47 FT
		ENDED BOREHOLE AT 51.5 FT 04/06/00 830 AM							Core barrel blocked up at 51.5 FT
		BOREHOLE BACKFILLED UPON COMPLETION 04/06/00 1000 AM							EXTRACTED CORE BARREL 210 PM
									ENDED DRILLING 04/05/00 240 PM
									STARTED DRILLING (EXTRACTING CASING) 04/06/00 830 AM

Langan
Engineering and Environmental Services, Inc.

LOG OF BORING B-26 SHEET 1 OF 2

PROJECT	RIVERPARK	PROJECT NO.	168901
LOCATION	42ND ST & 11TH AVE, MANHATTAN NY	ELEVATION AND DATUM	13.06
DRILLING AGENCY	WARREN GEORGE INC.	DATE STARTED 04/06/00	DATE FINISHED 04/07/00
DRILLING EQUIPMENT	MOBILE TRUCK MOUNTED DRILL RIG	COMPLETION DEPTH 27.0'	ROCK DEPTH —
SIZE AND TYPE OF BIT	3 7/8, 2 7/8 TRICONE ROLLER BITS	NO. SAMPLES DIST. 6	UNDIST. — CORE —
CASING	7" & 5" DIA FLUSH JOINT CASING	WATER LEVEL FIRST —	COMPL. — 24 HR. —
CASING HAMMER	WEIGHT — DROP —	FOREMAN	VINNY MITCHEL/MARTIN
SAMPLER	24" SPLIT SPOON	INSPECTOR	CYNTHIA BUCZYNSKI
SAMPLER HAMMER	WEIGHT 140# DROP 30"		

MAT'L SYMBOL	NYC ADC CODE CLASS	SAMPLE DESCRIPTION	CASING BLOWS/FT	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLWS/in.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL	11-65	Rolled bit through 12" thick cone surface		1					BEGAN DRILLING 04/06/00 10:20 AM
		S-1 Brick, cinders & fr. of Sand (fill) (11-65)		2	S-1	SS	2"	2 6 1 2	Wash Gray brown
				3					Roller Bit to 1FT
FILL	11-65	S-2 NO RECOVERY		4					
				5					ROLLER BIT TO 5FT
				6	S-2	SS	0"	4 2 2 4	(wood & vertical grain) & brick in wash
				7					
				8					
				9					ROLLER BIT TO 10'
				10					
FILL	11-65	S-3 DK Gray CINDERS and cf Sand fill (11-65)		11	S-3	SS	20"	4 4 5 7	
				12					
				13					ROLLER BIT TO 15' + SPIN 5" IN DIA CASING 0 FT-15 FT.
				14					

Langan
Engineering and Environmental Services, Inc.

* REV 4/10/00

JOB NO. 1568901

DATE

LOG OF BORING NO. B-26

SHEET 2 OF 2

MATL Symbol	NYC BG CODE CLASS	SAMPLE DESCRIPTION	CASING Blows	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PEN/E.R. RESIST BLS/IN.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
FILL	11-65	S-4 Dk Gray mf GRAVEL some cinders some clay & SILT (fill) (11-65) Slight petroleum odor	SPIN IN 5 — SPIN IN 5	14 15 16 17	S-4	SS	7 IN	9 7 5 4	
FILL	11-65	S-5 TOP 12IN Dk Gray and Dk Red CINDERS, some mf Gravel, lt cf sand BOT 6IN Dk Gray SILT & Clay, some mf Sand, (slight petroleum odor) fill 11-65		18 19 20 21 22 23	S-5	SS	10 IN	7 28 25 17	ROLLER BIT TO 20 FT (CONTINUED WOOD FIBER GRAVEL IN WASH) SPIN 20' OF 5 IN CASING ENDED DRILLING 04/06/00 2:55 PM STARTED DRILLING 04/06/00 7:00 AM
FILL	11-65	S-6 TOP 6IN Brown Clayey Silt and cf Sand, fr Brick fill (11-65)		24 25					
SAND	7-65	BOT 12IN Brown cf SAND and Clayey Silt, lt f gravel		26	S-6	SS	18 IN	4 7 10 14	SPIN CASING TO 23 FT. COULD NOT ADVANCE PAST 23 FT. ROLLER BIT TO 25' TOOK SAMPLE S-6
		ENDED BOREHOLE AT 27 FT. 04/07/00 10:00 AM FLUSH		27 28 29 30 31 32					COULD NOT ADVANCE CASING, KICKING DUE TO OBSTRUCTION AT 25 FT, and at 20 FT ENDED BOREHOLE
		BOREHOLE BACKFILLED UPON COMPLETION 04/07/00 10:45 AM							

Langan
Engineering and Environmental Services, Inc.

JOB NO. 1568901
DATE 04/10/00

LOG OF BORING NO. B-26A
SHEET 3 OF 3

MATL SYMBOL	NYC BUILDING CODE CLASS	SAMPLE DESCRIPTION	JOINTS	DEPTH SCALE	SAMPLES NO./LOC.	SAMPLES TYPE	SAMPLES RECOV. FT.	SAMPLES PENETR. RESIST BLS/IN.	REMARKS (DRILLING FLUID, DEPTH OF CASING, CASING BLOWS, FLUID LOSS, ETC.)
	6-65			42					BEGAN DRILLING 7:15 AM 04/10/00
				43					RIG CHATTERING FROM 43 FT
				44					ROLLER BIT TO 45'
		S-4 Same as above		45	S-4	SS	5/24	100/5"	
				46					
				47					
				48					Harder drilling from 48' (was ~~lt. gray~~)
	4-65	DECOMPOSED SCHIST (4-65)		49					ROLLER ~~BIT~~ TO 50'
				50					BEGAN CORING ROCK AT 50.0 FT 1020 hrs
		C-1 50.0'-55.0' Medium Gray SCHIST (moderately fractured 50'-51')	6	51	C-1	NX DOUBLE BARREL CORE	REC = 58/60 = 97%	RQD = 41/60 = 69%	
			7	52					
			7	53					
			6	54					
			7	55					ENDED CORING C-1 11:15 AM
		C-2 55.0'-60.0' (same as above as for C-1)	6	56					BEGAN CORING AT 11:25 AM
			7	57					
			7	58	C-2	NX	REC = 57/60 = 95%	RQD = 48/60 = 80%	ENDED CORING C-2 12:10 PM
			7	59					PULLED CASING
			7	60					ENDED DRILLING 04/10/00
		ENDED BOREHOLE AT 60.0' 04/10/00 RECEIVED COMPLETE							

APPENDIX D

TITLE SEARCH REPORT

Commonwealth®
A LANDAMERICA™ COMPANY

Special Search No.: SS020418A

DEED CHAINS FOR WEST 42ND STREET WORKS

A. **Block 1089 Lot 1:**

1. **Grantor:** The Metropolitan Gas Light Company of the City of New York

   Grantee: The Consolidated Gas Company of New York,

   Deed dated 11/10/1884 and recorded on 1/30/1885 in Liber 1863 Cp 33.

2. **Grantor:** The Consolidated Gas Company of New York

   Grantee: The New York Edison Company

   Deed dated 10/13/1923 and recorded on 7/9/1924 in Liber 3427 Cp 474.

3. **Grantor:** The New York Edison Company

   Grantee: New York State Realty and Terminal Company

   Deed dated 10/20/1927 and recorded on 10/21/1927 in Liber 3619 Cp 439.

4. **Grantor:** New York State Realty and Terminal Company

   Grantee: The New York Central Railroad Company

   Deed dated 12/28/1932 and recorded on 12/29/1932 in Liber 3854 Cp 158.

5. **Grantor:** The New York Central Railroad Company

   Grantee: Cola Realty Corp.

   Deed dated 6/22/1962 and recorded on 7/6/1962 in Liber 5191 Cp 163.

6. **Grantor:** Cola Realty Corp.

Grantee: Railway Express Agency, Incorporated

Deed dated 7/2/1962 and recorded on 7/6/1962 in Liber 5191 Cp 166.

7. **Grantor:** Railway Express Agency, Incorporated

Grantee: Joseph D. Keenan and Roger Deed, Trustees
Under Terms Of A Certain Trust Agreement
dated 5/31/1967,

Deed dated 5/31/1967 and recorded on 6/7/1967 in Record Liber 189 Page 108.

8. **Grantor:** Joseph D. Keenan, Roger Deed, Trustees
Under Terms Of A Certain Trust Agreement
dated 5/31/1967,

Grantee: Chrysler Realty Corporation

Deed dated 6/30/1969 and recorded on 7/18/1969 in Reel 146 Page 1076.

9. **Grantor:** ABKO Properties, Inc.
f/k/a Chrysler Realty Corporation

Grantee: Ivory Forty-Two Realty Corp.

Deed dated 2/16/1981 and recorded on 3/5/1981 in Reel 557 Page 855.

10. **Grantor:** Ivory Forty-Two Realty Corp.

Grantee: Silverstein 42nd Associates

Deed dated 7/19/1984 and recorded on 7/24/1984 in Reel 816 Page 759.

11. **Grantor:** Silverstein 42nd Associates, L.P.

Grantee: River Place I LLC

Deed dated 12/26/1996 and recorded on 12/30/1996 in Reel 2406 Page 2363.

No further deeds found through March 25, 2002.

Commonwealth®
A LANDAMERICA COMPANY

Special Search No.: SS020418A

DEED CHAINS FOR WEST 42ND STREET WORKS

B. **Block 1089 Lot 3:**

Deeds 1 through 10 same as Block 1089 Lot 1 above, then:

11. **Grantor:** Silverstein 42nd Associates, L.P.

Grantee: River Place II LLC

Deed dated 6/14/1999 and recorded on 7/8/1999 in Reel 2909 Page 1057.

No further deeds found through March 25, 2002.

APPENDIX B

EDR REPORT

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

WEST 42ND STREET
MANHATTAN, NY 10036

COORDINATES

Latitude (North):	40.761100 - 40° 45' 40.0"
Longitude (West):	74.000100 - 74° 0' 0.4"
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	584398.9
UTM Y (Meters):	4512507.0

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	2440074-G1 WEEHAWKEN, NJ NY
Source:	USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL ---- National Priority List
Proposed NPL ---- Proposed National Priority List Sites
CERCLIS ---- Comprehensive Environmental Response, Compensation, and Liability Information System
CERC-NFRAP ---- CERCLIS No Further Remedial Action Planned
CORRACTS ---- Corrective Action Report
RCRIS-TSD ---- Resource Conservation and Recovery Information System
ERNS ---- Emergency Response Notification System

STATE ASTM STANDARD

SHWS ---- Inactive Hazardous Waste Disposal Sites in New York State
SWF/LF ---- Facility Register
MOSF UST ---- Major Oil Storage Facilities Database
VCP ---- Voluntary Cleanup Agreements
SWTIRE ---- Registered Waste Tire Storage & Facility List
SWRCY ---- Registered Recycling Facility List

EXECUTIVE SUMMARY

FEDERAL ASTM SUPPLEMENTAL

CONSENT..... Superfund (CERCLA) Consent Decrees
ROD..... Records Of Decision
Delisted NPL..... National Priority List Deletions
FINDS..... Facility Index System/Facility Identification Initiative Program Summary Report
HMIRS..... Hazardous Materials Information Reporting System
MLTS..... Material Licensing Tracking System
MINES..... Mines Master Index File
NPL Liens..... Federal Superfund Liens
PADS..... PCB Activity Database System
RAATS..... RCRA Administrative Action Tracking System
TRIS..... Toxic Chemical Release Inventory System
TSCA..... Toxic Substances Control Act
FTTS..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

HSWDS..... Hazardous Substance Waste Disposal Site Inventory
AST..... Petroleum Bulk Storage
MOSF AST..... Major Oil Storage Facilities Database
NY Spills..... Spills Information Database

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS 1 degree Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. EDR's definition of a site with an elevation equal to the target property includes a tolerance of +/- 10 feet. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property (by more than 10 feet). Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

FEDERAL ASTM STANDARD

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.

A review of the RCRIS-LQG list, as provided by EDR, and dated 06/21/2000 has revealed that there are 12 RCRIS-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
UNITED PARCEL SERVICE	*643 W 43RD ST*	*0 - 1/8 NNE*	*B5*	*12*
MOBIL OIL CORP	*42 ST 11TH AVE*	*0 - 1/8 ESE*	*C9*	*48*
UNITED PARCEL SERVICE	*525 11TH AVE*	*0 - 1/8 SSE*	*D11*	*50*

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
NYCT GREYHOUND BUS TERMINAL	***525 11TH AVE***	***0 - 1/8 SSE***	***D13***	***51***
EDISON PARKING LOT	***500-516 12TH AVE***	***1/8 - 1/4 WSW***	***F24***	***103***
PORT AUTH OF NY NJ 12TH AVE	***39TH ST 12TH AVE***	***1/8 - 1/4 WSW***	***F26***	***109***
CON EDISON - WEST 42ND ST SUB	***571 W 41ST ST***	***1/8 - 1/4 SE***	***28***	***114***
PORT AUTH OF NY NJ 11TH AVE	***11TH AVE 39TH ST***	***1/8 - 1/4 S***	***29***	***115***
TRAILWAYS INC	***544 W 41ST ST***	***1/8 - 1/4 SE***	***J36***	***121***
MILLER-GERALDI INC	***609 11TH AVE***	***1/8 - 1/4 NE***	***I41***	***134***
MERCEDES-BENZ MANHATTAN INC	***528 W 41ST ST***	***1/8 - 1/4 SE***	***J42***	***134***
MARTIN MANHATTAN ACURA	***11TH AVE W 46TH ST***	***1/8 - 1/4 NE***	***N58***	***163***

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.

A review of the RCRIS-SQG list, as provided by EDR, and dated 06/21/2000 has revealed that there are 10 RCRIS-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
NEW YORK TELEPHONE CO	***605 W 42ND ST***	***0 - 1/8 E***	***C6***	***46***
NYCTA - 11TH AVE BUS DEPOT MTA	525 11TH AVE	0 - 1/8 SSE	D15	85
MOBIL OIL CORP SS QDL	***561 11TH AVE***	***0 - 1/8 E***	***E16***	***85***
NEW YORK TELEPHONE CO	***604 W 43RD ST***	***0 - 1/8 ENE***	***E22***	***100***
CIRCLE LINE	***PIER 83 43RD ST***	***1/8 - 1/4 NW***	***31***	***115***
DEMARCO JOSEPH E	***595 11TH AVE***	***1/8 - 1/4 ENE***	***G32***	***116***
KELLERMANN PAINT CO INC	***605 W 45TH ST***	***1/8 - 1/4 NE***	***I38***	***123***
MY PRINT CO LIMIT	***711 12TH AVE PIER 88***	***1/8 - 1/4 NNE***	***L46***	***140***
A G F A DIV OF BAYER CORP	***711 12TH AVE PIER 92***	***1/8 - 1/4 NNE***	***L47***	***140***
MERCEDES BENZ MANHATTAN INC	***528 W 39TH ST***	***1/8 - 1/4 SSE***	***55***	***154***

STATE ASTM STANDARD

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 10/01/2001 has revealed that there are 55 LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
643 W 43RD ST/UPS	643 W 43RD ST	0 - 1/8 NNE	B4	10
VERIZON	605 WEST 42ND ST	0 - 1/8 E	C7	47
608 W 40 ST - MAN	608 W 40 ST	0 - 1/8 SSE	10	49
525 N 11TH AVE/MANH/GREYH	525 NORTH 11TH AVENUE	0 - 1/8 SSE	D12	50
MOBIL OIL CORP SS QDL	***561 11TH AVE***	***0 - 1/8 E***	***E16***	***85***
MOBIL S/S	561 11TH AVENUE	0 - 1/8 E	E17	91
MOBIL GAS STATION	561 11TH AVE	0 - 1/8 E	E18	92
523 11TH AV/GREYHOUND BUS	523 11TH AVENUE	0 - 1/8 SSE	D19	93
SILVERSTEIN 42ND ASSOC.	500-516 12TH AVE	1/8 - 1/4 WSW	F25	108
612 W 45TH ST/UPS	612 W 45TH ST	1/8 - 1/4 NE	I34	118
609-611 11TH ST	611 11TH AVENUE	1/8 - 1/4 NE	I45	139

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
711 12TH AVE/MANHATTAN	711 12TH AVENUE	1/8 - 1/4 NNE	L48	141
FDNY RESCUE 1	530 WEST 43RD ST	1/8 - 1/4 E	K49	142
PIER 90/MANHATTAN	PIER 90	1/8 - 1/4 N	51	147
METROPOLITAN LUMBER COMPANY	***617 11TH AVE***	***1/8 - 1/4 NE***	***N57***	***158***
APT BUILDING	545 WEST 45TH ST	1/4 - 1/2 ENE	59	164
Not reported	505-509 WEST 41ST ST	1/4 - 1/2 SE	M60	165
547 10TH AVENUE	547 10TH AVENUE	1/4 - 1/2 SE	61	166
639 11TH AVE./MAHATTAN	639 11TH AVE.	1/4 - 1/2 NE	62	167
509 WEST 38TH ST	509 WEST 38TH ST	1/4 - 1/2 SSE	63	168
Not reported	550 WEST 37TH ST	1/4 - 1/2 SSE	64	169
SERVICE STATION	624 10TH AVE	1/4 - 1/2 E	O65	170
HESS STATION #32215	***502 WEST 45TH ST***	***1/4 - 1/2 E***	***O66***	***171***
502 WEST 45TH ST/HESS	502 WEST 45TH STREET	1/4 - 1/2 E	O67	177
WEST 45TH ST & 10TH AVE	WEST 45TH ST / 10TH A	1/4 - 1/2 E	O68	178
450 W. 41ST STREET	450 W. 41ST STREET	1/4 - 1/2 ESE	69	179
BMW	547 WEST 47TH ST	1/4 - 1/2 ENE	70	180
624 WEST 48TH ST	624 WEST 48TH ST	1/4 - 1/2 NE	P71	181
NYNEX	624 W. 48TH STREET	1/4 - 1/2 NE	P72	182
AD SCHEUMANN LUMBER	524 WEST 36 TH STREET	1/4 - 1/2 S	73	183
475 10TH AVE/MANHATTAN	475 10TH AVENUE	1/4 - 1/2 SSE	Q74	184
466 10TH AVE/GASETERIA	466 10TH AVENUE	1/4 - 1/2 SSE	Q75	185
CONSTRUCTION SITE	529 WEST 35TH ST	1/4 - 1/2 S	76	186
PARKING LOT	618-628 W 49TH ST	1/4 - 1/2 NE	77	187
460 10TH AVE	460 10TH AVENUE	1/4 - 1/2 SSE	78	188
527 W 48TH ST	527 W 48TH ST	1/4 - 1/2 ENE	79	189
555 WEST 34TH ST/NYTEL	555 WEST 34TH STREET	1/4 - 1/2 S	R80	190
NYNEX	***555 W. 34TH ST***	***1/4 - 1/2 S***	***R81***	***191***
ROY WEIDENER MOTOR LINE	651 W 33ST,MARSHILLING	1/4 - 1/2 SSW	82	193
538 WEST 34TH ST/MANH	538 WEST 34TH STREET	1/4 - 1/2 S	R83	194
530 WEST 34TH ST/MANH	530 WEST 34TH STREET	1/4 - 1/2 S	S84	195
408 WEST 39TH ST	408 WEST 39TH ST	1/4 - 1/2 SE	T85	196
528 W 34TH ST	528 W 34TH ST	1/4 - 1/2 S	S86	197
PORT AUTH NY/NJ - MAN	W 39 ST / 9 AVE	1/4 - 1/2 SE	T87	198
436 TENTH AVENUE	436 TENTH AVENUE	1/4 - 1/2 S	U88	199
AMICO STATION	436 10TH AVE/34TH ST	1/4 - 1/2 S	U89	200
34TH ST. & 10TH AVE./AMOC	34TH ST. / 10TH AVE.	1/4 - 1/2 S	U90	202
34TH ST. AND 10TH AVE./AM	34TH ST. / 10TH AVE.	1/4 - 1/2 S	U91	203
429 WEST 36TH ST	429 WEST 36TH ST	1/4 - 1/2 SSE	92	204
725 10TH AVENUE	725 10TH AVENUE	1/4 - 1/2 ENE	93	205
MOBIL S/S	718 11TH AVENUE	1/4 - 1/2 NE	V94	206
MOBIL S/S	718 11TH AVENUE	1/4 - 1/2 NE	V95	207
MOBIL S/S	718 11TH AVENUE	1/4 - 1/2 NE	V96	208
37TH & 9TH ST/BKLYN	37TH / 9TH STREET	1/4 - 1/2 SE	97	210
416 WEST 47TH STREET	416 WEST 47TH ST	1/4 - 1/2 E	98	211

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, and dated 10/01/2001 has revealed that there are 24 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
MYRON GARFINKEL	627 WEST 42ND STREET	0 - 1/8 E	A2	7

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
NYNEX	615 W 42ND ST	0 - 1/8 E	A3	8
UNITED PARCEL SERVICE	***643 W 43RD ST***	***0 - 1/8 NNE***	***B5***	***12***
M.J. QUILL DEPOT	***525 ELEVENTH AVE***	***0 - 1/8 SSE***	***D14***	***52***
MOBIL OIL CORP SS QDL	***561 11TH AVE***	***0 - 1/8 E***	***E16***	***85***
NEW YORK TELEPHONE	***563 11TH AVE***	***0 - 1/8 E***	***E20***	***95***
BELL ATLANTIC	***604-628 WEST 43RD STREE***	***0 - 1/8 ENE***	***E21***	***97***
CONSULATE GENERAL OF P.R.CHINA	520 12TH AVE	1/8 - 1/4 WSW	F23	101
EDISON PARKING LOT	***500-516 12TH AVE***	***1/8 - 1/4 WSW***	***F24***	***103***
SILVERSTEIN PROPERTIES: YALE B	460 TWELFTH AVENUE	1/8 - 1/4 WSW	F27	109
RIVERBANK WEST	560 WEST 43RD STREET	1/8 - 1/4 E	H33	116
UNITED PARCEL SERVICE	612 WEST 45TH STREET	1/8 - 1/4 NE	I35	119
MERCHANDISING WORKSHOP INC	550 W 43RD ST	1/8 - 1/4 E	H37	122
MERCEDES/BENZ MANHATTAN INC	***536 W 41 ST***	***1/8 - 1/4 SE***	***J39***	***123***
SWING TIME LLC CORP.	609 11TH AVENUE	1/8 - 1/4 NE	I40	129
43RD PARKING CORP	541 W 43 ST	1/8 - 1/4 E	K43	135
MARVIN MITHELL	541 WEST 43RD STREET	1/8 - 1/4 E	K44	137
F.D.N.Y.-RESCUE CO. 1	***530 WEST 43RD STREET***	***1/8 - 1/4 E***	***K50***	***143***
AMERICAN RED CROSS EMERGENCY F	515 WEST 41ST STREET	1/8 - 1/4 SE	M52	148
I&G EXPRESS INC.	456 11TH AVENUE	1/8 - 1/4 S	53	149
TRAVEL INN HOTEL	515 WEST 42ND STREET	1/8 - 1/4 ESE	54	153
MERCEDES BENZ MANHATTAN INC	***528 W 39TH ST***	***1/8 - 1/4 SSE***	***55***	***154***
ANNEX BLDG	521 WEST 43TH STREET	1/8 - 1/4 E	56	156
METROPOLITAN LUMBER COMPANY	***617 11TH AVE***	***1/8 - 1/4 NE***	***N57***	***158***

CBS UST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the CBS UST list, as provided by EDR, and dated 10/01/2001 has revealed that there is 1 CBS UST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
M.J. QUILL DEPOT	***525 ELEVENTH AVE***	***0 - 1/8 SSE***	***D14***	***52***

STATE OR LOCAL ASTM SUPPLEMENTAL

CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the CBS AST list, as provided by EDR, and dated 10/01/2001 has revealed that there are 2 CBS AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
UNITED PARCEL SERVICE	***643 W 43RD ST***	***0 - 1/8 NNE***	***B5***	***12***
M.J. QUILL DEPOT	***525 ELEVENTH AVE***	***0 - 1/8 SSE***	***D14***	***52***

EXECUTIVE SUMMARY

PROPRIETARY DATABASES

Former Manufactured Gas (Coal Gas) Sites:

The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative

A review of the Coal Gas list, as provided by EDR, has revealed that there are 3 Coal Gas sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
CONSOLIDATED GAS CO.	600 W. 42ND ST.	0 - 1/8 ESE	C8	48
CONSOLIDATED GAS WORKS	589-625 ELEVENTH AVE.	1/8 - 1/4 ENE	G30	115
EQUITABLE GAS CO.	540 W. 59TH ST.	1/2 - 1 NE	99	212

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
NU METHOD DYEING & PROCESSING	SHWS
NU METHOD DYEING & PROCESSING	SHWS
48TH STREET PARKING LOT	SHWS
UNION CITY DEPARTMEN PUBLIC WORKS	SHWS
WALL STREET AND	LTANKS
57-15 49TH STREET	NY Spills, LTANKS
PIER 79	UST
43 WEST 61ST STREET ASSOCN	RCRIS-SQG, FINDS
WEST 57TH ST. CONCRETE CO.	CBS AST

OVERVIEW MAP - 745748.1s - Con-Edison Company



- ☆ Target Property
- ▲ Sites at elevations higher than or equal to the target property
- ◆ Sites at elevations lower than the target property
- ▲ Coal Gasification Sites
- National Priority List Sites
- Landfill Sites
- Power transmission lines
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone
- Wetlands

TARGET PROPERTY:	West 42nd Street Works	CUSTOMER:	Con-Edison Company
ADDRESS:	West 42nd Street	CONTACT:	Glen Katz
CITY/STATE/ZIP:	Manhattan NY 10036	INQUIRY #:	745748.1s
LAT/LONG:	40.7611 / 74.0001	DATE:	March 18, 2002 9:04 am

DETAIL MAP - 745748.1s - Con-Edison Company



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Coal Gasification Sites
- Sensitive Receptors
- National Priority List Sites
- Landfill Sites
- Power transmission lines
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone
- Wetlands

TARGET PROPERTY:	West 42nd Street Works	CUSTOMER:	Con-Edison Company
ADDRESS:	West 42nd Street	CONTACT:	Glen Katz
CITY/STATE/ZIP:	Manhattan NY 10036	INQUIRY #:	745748.1s
LAT/LONG:	40.7611 / 74.0001	DATE:	March 18, 2002 9:04 am

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL ASTM STANDARD								
NPL		1.000	0	0	0	0	NR	0
Proposed NPL		1.000	0	0	0	0	NR	0
CERCLIS		0.500	0	0	0	NR	NR	0
CERC-NFRAP		0.250	0	0	NR	NR	NR	0
CORRACTS		1.000	0	0	0	0	NR	0
RCRIS-TSD		0.500	0	0	0	NR	NR	0
RCRIS Lg. Quan. Gen.		0.250	4	8	NR	NR	NR	12
RCRIS Sm. Quan. Gen.		0.250	4	6	NR	NR	NR	10
ERNS		TP	NR	NR	NR	NR	NR	0
STATE ASTM STANDARD								
State Haz. Waste		1.000	0	0	0	0	NR	0
State Landfill		0.500	0	0	0	NR	NR	0
LTANKS		0.500	8	7	40	NR	NR	55
UST		0.250	7	17	NR	NR	NR	24
CBS UST		0.250	1	0	NR	NR	NR	1
MOSF UST		0.500	0	0	0	NR	NR	0
VCP		0.500	0	0	0	NR	NR	0
SWTIRE		0.500	0	0	0	NR	NR	0
SWRCY		0.500	0	0	0	NR	NR	0
FEDERAL ASTM SUPPLEMENTAL								
CONSENT		1.000	0	0	0	0	NR	0
ROD		1.000	0	0	0	0	NR	0
Delisted NPL		1.000	0	0	0	0	NR	0
FINDS		TP	NR	NR	NR	NR	NR	0
HMIRS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
MINES		0.250	0	0	NR	NR	NR	0
NPL Liens		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
STATE OR LOCAL ASTM SUPPLEMENTAL								
HSWDS		0.500	0	0	0	NR	NR	0
AST		TP	NR	NR	NR	NR	NR	0
CBS AST		0.250	2	0	NR	NR	NR	2
MOSF AST		0.500	0	0	0	NR	NR	0
NY Spills		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY HISTORICAL DATABASES								
Coal Gas		1.000	1	1	0	1	NR	3

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

AQUIFLOW - see EDR Physical Setting Source Addendum

TP = Target Property

NR = Not Requested at this Search Distance

* Sites may be listed in more than one database

1 **WEST 42ND ST SUB-STATION** **NY Spills** **S103937116**
WEST 42ND ST **N/A**
< 1/8 **MANHATTAN, NY**
1
Higher

SPILLS:

Spill Number:	9901561	Region of Spill:	2
Facility Contact:	CALLER	Facility Tele:	( ) -
Investigator:	O'CONNELL	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	CALLER	Spiller Phone:	Not reported
Spiller:	CON ED		
Spiller Address:	4 IRVING PLACE MANHATTAN, NY 10003		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	05/10/1999 14:30	Reported to Dept:	05/10/1999 15:28
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	07/31/2000
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	05/10/1999
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	1
Units:	Gallons
Unknown Qty Spilled:	Yes
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	TRANSFORMER OIL
Class Type:	Petroleum
Chem Abstract Service Number:	TRANSFORMER OIL
Last Date:	09/26/1994
Num Times Material Entry In File:	533

Remarks: con ed 124769. cleanup crew responding.
DEC Remarks: DEC INSPECTOR NOTES Stilla waiting info requested 6-22, reply on 7-02

WEST 42ND ST SUB-STATION (Continued) **S103937116**

indicated awaiting update from station manager CON ED E2MIS NOTES 5-26-99 5-10-99 14:30 Approx. 1 gal. transformer oil from transformer 6 FDR-38M44, in vault 6 Spiill is contained on concrete pad in metal e nclosure around transformer, pads installed to contain spill, no impact to waterway or sewer, sign placed. Chem Lab to take sample. MR. Pitre re ports unbale to determine where leak is located.

A2 **MYRON GARFINKEL** **UST** **U003312878**
East **627 WEST 42ND STREET** **N/A**
< 1/8 **NEW YORK, NY 10036**
346
Higher **Site 1 of 2 in cluster A**

PBS UST:

PBS Number:	2-603476	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	AZTEC METAL CO. (212) 293-2777		
Emergency Contact:	MYRON GARFINKLE (203) 866-2700		
Total Tanks:	1		
Owner:	MYRON GARFINKEL 6 POINT ROAD WILSON POINT NORWALK, CT 06854 (203) 866-2700		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MYRON GARFINKLE 6 POINT ROAD WILSON POINT NORWALK, CT 06854 (203) 866-2700		
Tank Status:	In Service		
Capacity (gals):	5000		
Tank Location:	UNDERGROUND		
Tank Id:	1	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	GALVANIZED STEEL
Tank External:	NONE/PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	12/27/1987
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	5000	Renewal Date:	Not reported
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	05/21/1998
Old PBS Number:	Not reported	Expiration Date:	05/12/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		

MYRON GARFINKEL (Continued) **U003312878**

Town or City:	NEW YORK CITY
Town or City Code:	01
County Code:	62
Region:	2

A3 **NYNEX** **UST** **U000417979**
East **615 W 42ND ST** **N/A**
< 1/8 **NEW YORK, NY 10036**
422
Higher **Site 2 of 2 in cluster A**

PBS UST:

PBS Number:	2-344648	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYNEX (718) 330-8383		
Emergency Contact:	NYNEX (718) 330-8383		
Total Tanks:	0		
Owner:	NYNEX 221 EAST 37TH STREET, 6TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	New York Telephone		
Mailing Address:	NYNEX ATTN: PETER T INGRASSIA 221 EAST 37TH STREET, 6TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Tank Status:	Closed - In Place		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1992	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	02/23/1993
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	12/14/1987
Old PBS Number:	Not reported	Expiration Date:	12/14/1992
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		

NYNEX (Continued) **U000417979**

Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-344648	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYNEX (718) 330-8383		
Emergency Contact:	NYNEX (718) 330-8383		
Total Tanks:	0		
Owner:	NYNEX 221 EAST 37TH STREET, 6TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	New York Telephone		
Mailing Address:	NYNEX ATTN: PETER T INGRASSIA 221 EAST 37TH STREET, 6TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Tank Status:	Closed - In Place		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1993	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	02/23/1993
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	12/14/1987
Old PBS Number:	Not reported	Expiration Date:	12/14/1992
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-344648	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201

NYNEX (Continued) **U000417979**

Operator:	NYNEX (718) 330-8383		
Emergency Contact:	NYNEX (718) 330-8383		
Total Tanks:	0		
Owner:	NYNEX 221 EAST 37TH STREET, 6TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	New York Telephone		
Mailing Address:	NYNEX ATTN: PETER T INGRASSIA 221 EAST 37TH STREET, 6TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Tank Status:	Closed - In Place		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1993	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	02/23/1993
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	12/14/1987
Old PBS Number:	Not reported	Expiration Date:	12/14/1992
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

B4 **643 W 43RD ST/UPS** **LTANKS** **S100493387**
NNE **643 W 43RD ST** **N/A**
< 1/8 **NYC, NY**
430
Higher **Site 1 of 2 in cluster B**

LTANKS:

Spill Number:	9200470	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	SWIS:	62

643 W 43RD ST/UPS (Continued) **S100493387**

Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	Not reported		
Spiller Address:	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/07/1995		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	06/15/1991 12:00	Reported to Dept:	04/13/1992 12:08
Cleanup Ceased:	08/07/1995		
Last Inspection:	Not reported		

Cleanup Meets Standard:	True
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	08/16/1995
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	04/16/1992
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	-1
Units:	Not reported
Unknown Qty Spilled:	-1
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	DIESEL
Class Type:	Petroleum
Chem Abstract Service Number:	DIESEL
Last Date:	07/28/1994
Num Times Material Entry In File:	10625

DEC Remarks: Not reported
Spill Cause: HIRED CONTRACTOR TO PULL TANK.

Spill Number:	9202362	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported

643 W 43RD ST/UPS (Continued) **S100493387**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller: Not reported
Spiller Address: Not reported
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 03/31/1995
Spill Cause: Tank Failure
Resource Affected: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Notifier: Responsible Party
PBS Number: Not reported
Spill Date: 05/22/1992 09:00
Reported to Dept: 05/28/1992 11:23
Cleanup Ceased: 03/31/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 03/31/1995
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/02/1992
Date Region Sent Summary to Central Office: Not reported
Tank Test:
  PBS Number: Not reported
  Tank Number: Not reported
  Test Method: Not reported
  Capacity of Failed Tank: Not reported
  Leak Rate Failed Tank: Not reported
  Gross Leak Rate: Not reported
Material:
  Material Class Type: 1
  Quantity Spilled: -1
  Units: Not reported
  Unknown Qty Spilled: -1
  Quantity Recovered: 0
  Unknown Qty Recovered: False
  Material: GASOLINE
  Class Type: Petroleum
  Chem Abstract Service Number: GASOLINE
  Last Date: 09/29/1994
  Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: EXCAVATING CONTAMINATED SOIL TO TANK TOP-25 TANKS TO BE CLOSED. STOCKPILING SOIL; WILL SAMPLE TEST DISPOSE. SEE 9200470

B5 **UNITED PARCEL SERVICE** **FINDS 1000398410**
NNE **643 W 43RD ST** **RCRIS-LQG NYD006991673**
< 1/8 **NEW YORK, NY 10036** **UST**
430 **CBS AST**
Higher **Site 2 of 2 in cluster B** **AST**

UNITED PARCEL SERVICE (Continued) **1000398410**

RCRIS:
Owner: UNITED PARCEL SERVICE
(212) 555-1212

Contact: DOMINIC PIAZZA
(212) 560-6335

Record Date: 07/30/1986
Classification: Large Quantity Generator, Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
National Emissions Trends (NET)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CBS AST:

CBS Number:	2-000334	Telephone:	(212) 631-6326
Owner:	NUBEE, INC. 643 WEST 43 STREET NEW YORK, NY 10036 (212) 631-6446		
Facility Status:	Active		
Total Tanks	1		
Tank Status:	In Service		
Tank Error Status:	No Missing Data		
Tank Location:	Aboveground		
Install Date:	09/93		
Capacity (Gal):	500		
Tank Type:	Steel/carbon steel		
Substance:	Single Hazardous Substance on DEC List		
Extrnl Protection:	None		
Intrnl Protection:	None		
Tank Containment:	Double-Walled		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	None		
Pipe External:	None		
Pipe Containment:	None	Haz Percent:	50
Leak Detection:	None		
Overfill Protection:	4/4		
Chemical:	Ethylene glycol	Tank Closed:	Not reported
PBS Number:	2-600720	SWIS Code:	6201
Federal ID:	Not reported		
MOSF Number:	Not reported	CAS Number:	107211
SPDES Number:	Not reported	ICS Number:	Not reported
Facility Type:	Other		
Operator:	TOM SAVAGE	Facility Town:	NEW YORK CITY
Emrgncy Contact:	GENE ASCHOFF	Emrgncy Phone:	(212) 631-6444
Certified Date:	03/27/2001	Expiration Date:	01/31/2003
Owner type:	Corporate/Commercial		
Owner Sub Type:	Not reported		

UNITED PARCEL SERVICE (Continued) **1000398410**

Mail Name: UNITED PARCEL SERVICE, INC.
Mail Contact: DISTRICT PLANT ENGINEERING
643 WEST 43 STREET
NEW YORK, NY 10036
Mail Phone: (212) 631-6446
Tank Secret: False
Date Entered: 01/31/1997 09:06:59
Last Test: Not reported
Due Date: Not reported
Pipe Flag: False
Owner Mark: 1
Renew Date: Not reported
Date Expired: Not reported
Is it There: False
Is Updated: False
Owner Status: F
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Total Capacity of All Active Tanks(gal): 500
Unique Tank Id Number: AST-1
Date Pre-Printed Renewal App Form Was Last Printed: 11/02/2000

PBS UST:
PBS Number: 2-600720
CBS Number: Not reported
SPDES Number: Not reported
SWIS ID: 6201
Operator: THOMAS J. SAVAGE
(212) 631-6446
Emergency Contact: PAUL MCDONALD
(212) 631-6444
Total Tanks: 5
Owner: NUBEE INC
643 WEST 43RD STREET
NEW YORK, NY 10036
(212) 631-6446
Owner Type: Corporate/Commercial
Owner Mark: First Owner
Owner Subtype: Not reported
Mailing Address: UNITED PARCEL SERVICE
ATTN: PLANT ENGINEERING DEPT
FIFTH FLOOR
643 WEST 43RD STREET
NEW YORK, NY 10036
(212) 631-6444
Tank Status: In Service
Capacity (gals): 15000
Tank Location: UNDERGROUND
Tank Id: 3
Install Date: 12/01/1961
Tank Type: Steel/carbon steel
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Internal: FIBERGLASS LINER [FRP]
Pipe Internal: NONE
Pipe Location: Underground
Pipe Type: FIBERGLASS [FRP]
Tank External: NONE/IMPRESSED CURRENT
Missing Data for Tank: No Missing Data
Pipe External: NONE/NONE
Second Containment: NONE/DOUBLED-WALLED TANK
Leak Detection: INTERSTITIAL MONITORING/IN-TANK SYSTEM
Overfill Prot: High Level Alarm
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Dead Letter: False
Owner Screen: No data missing
FAMT: Fiscal amount for registration fee is correct
Total Capacity: 38500
Renewal Date: 01/02/1997

UNITED PARCEL SERVICE (Continued) **1000398410**

Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/25/1999
Old PBS Number:	Not reported	Expiration Date:	04/17/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	THOMAS J. SAVAGE (212) 631-6446		
Emergency Contact:	PAUL MCDONALD (212) 631-6444		
Total Tanks:	5		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6446		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	UNITED PARCEL SERVICE ATTN: PLANT ENGINEERING DEPT FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6444		
Tank Status:	In Service		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	1	Install Date:	09/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Prot:	High Level Alarm	Dispenser:	Submersible
Date Tested:	04/01/1998	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	TANKOLOGY [VACUTECT]
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	38500	Renewal Date:	01/02/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/25/1999
Old PBS Number:	Not reported	Expiration Date:	04/17/2002
Inspected Date:	Not reported	Inspector:	Not reported

UNITED PARCEL SERVICE (Continued) **1000398410**

Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	THOMAS J. SAVAGE (212) 631-6446		
Emergency Contact:	PAUL MCDONALD (212) 631-6444		
Total Tanks:	5		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6446		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	UNITED PARCEL SERVICE ATTN: PLANT ENGINEERING DEPT FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6444		
Tank Status:	In Service		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	2	Install Date:	09/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Prot:	High Level Alarm	Dispenser:	Submersible
Date Tested:	04/01/1999	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	TANKOLOGY [VACUTECT]
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	38500	Renewal Date:	01/02/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/25/1999
Old PBS Number:	Not reported	Expiration Date:	04/17/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		

UNITED PARCEL SERVICE (Continued) **1000398410**

County Code:	62		
Region:	2		
PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	THOMAS J. SAVAGE (212) 631-6446		
Emergency Contact:	PAUL MCDONALD (212) 631-6444		
Total Tanks:	5		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6446		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	UNITED PARCEL SERVICE ATTN: PLANT ENGINEERING DEPT FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6444		
Tank Status:	In Service		
Capacity (gals):	15000		
Tank Location:	UNDERGROUND		
Tank Id:	4	Install Date:	12/01/1961
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	FIBERGLASS LINER [FRP]	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	NONE/IMPRESSED CURRENT		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Prot:	High Level Alarm	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	38500	Renewal Date:	01/02/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/25/1999
Old PBS Number:	Not reported	Expiration Date:	04/17/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

CBS AST:

CBS Number:	2-000334	Telephone:	(212) 631-6326
Owner:	NUBEE, INC.		

UNITED PARCEL SERVICE (Continued) **1000398410**

643 WEST 43 STREET
NEW YORK, NY 10036
(212) 631-6446

Facility Status:	Active		
Total Tanks	1		
Tank Status:	In Service		
Tank Error Status:	No Missing Data		
Tank Location:	Aboveground		
Install Date:	09/93		
Capacity (Gal):	500		
Tank Type:	Steel/carbon steel		
Substance:	Single Hazardous Substance on DEC List		
Extrnl Protection:	None		
Intrnl Protection:	None		
Tank Containment:	Double-Walled		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	None		
Pipe External:	None		
Pipe Containment:	None	Haz Percent:	50
Leak Detection:	None		
Overfill Protection:	4/4		
Chemical:	Ethylene glycol	Tank Closed:	Not reported
PBS Number:	2-600720	SWIS Code:	6201
Federal ID:	Not reported		
MOSF Number:	Not reported	CAS Number:	107211
SPDES Number:	Not reported	ICS Number:	Not reported
Facility Type:	Other		
Operator:	TOM SAVAGE	Facility Town:	NEW YORK CITY
Emrgncy Contact:	GENE ASCHOFF	Emrgncy Phone:	(212) 631-6444
Certified Date:	03/27/2001	Expiration Date:	01/31/2003
Owner type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Mail Name:	UNITED PARCEL SERVICE, INC.		
Mail Contact:	DISTRICT PLANT ENGINEERING 643 WEST 43 STREET NEW YORK, NY 10036		
Mail Phone:	(212) 631-6446		
Tank Secret:	False	Date Entered:	01/31/1997 09:06:59
Last Test:	Not reported	Due Date:	Not reported
Pipe Flag:	False	Owner Mark:	1
Renew Date:	Not reported	Date Expired:	Not reported
Is it There:	False	Is Updated:	False
Owner Status:	F		

Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Total Capacity of All Active Tanks(gal):	500
Unique Tank Id Number:	AST-1
Date Pre-Printed Renewal App Form Was Last Printed:	11/02/2000

PBS AST:

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		

UNITED PARCEL SERVICE (Continued) **1000398410**

Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	001		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		

UNITED PARCEL SERVICE (Continued) **1000398410**

Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	002		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported

UNITED PARCEL SERVICE (Continued) **1000398410**

Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	003		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported

UNITED PARCEL SERVICE (Continued) **1000398410**

SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	004		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

UNITED PARCEL SERVICE (Continued) **1000398410**

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	005		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		

UNITED PARCEL SERVICE (Continued) **1000398410**

Region: 2
Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	006		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		

UNITED PARCEL SERVICE (Continued) **1000398410**

Town or City Code: 01
County Code: 62
Region: 2
Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	007		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		

UNITED PARCEL SERVICE (Continued) **1000398410**

Tank Screen: No data missing
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2
Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	008		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		

UNITED PARCEL SERVICE (Continued) **1000398410**

Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct: True			
PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	009		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997

UNITED PARCEL SERVICE (Continued) **1000398410**

Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct:	True		
PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	010		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002

UNITED PARCEL SERVICE (Continued) **1000398410**

Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	011		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		

UNITED PARCEL SERVICE (Continued) **1000398410**

Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	012		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET		

UNITED PARCEL SERVICE (Continued) **1000398410**

	NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct: True			
PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC		
	643 WEST 43RD STREET		
	NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	013		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		

UNITED PARCEL SERVICE (Continued) **1000398410**

Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	014		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported

UNITED PARCEL SERVICE (Continued) **1000398410**

Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	015		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported

UNITED PARCEL SERVICE (Continued) **1000398410**

Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	016		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		

UNITED PARCEL SERVICE (Continued) **1000398410**

Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	017		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		

UNITED PARCEL SERVICE (Continued) **1000398410**

Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	018		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		

UNITED PARCEL SERVICE (Continued) **1000398410**

Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	019		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		

UNITED PARCEL SERVICE (Continued) **1000398410**

Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	020		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		

UNITED PARCEL SERVICE (Continued) **1000398410**

Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	021		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		

UNITED PARCEL SERVICE (Continued) **1000398410**

Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	022		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		

UNITED PARCEL SERVICE (Continued) **1000398410**

Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	023		

UNITED PARCEL SERVICE (Continued) **1000398410**

Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		

UNITED PARCEL SERVICE (Continued) **1000398410**

Total Capacity:	38500		
Tank ID:	024		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		

UNITED PARCEL SERVICE (Continued) **1000398410**

Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	025		
Capacity (Gal):	550		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	4 - Subpart 360-14 only (active)		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		

UNITED PARCEL SERVICE (Continued) **1000398410**

Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	028		
Capacity (Gal):	15000		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	NOS 1,2, OR 4 FUEL OIL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1961		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING		
Tank Containment:	EARTHEN DIKE		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Not reported		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	DOUBLE BOTTOM		
Overfill Protection:	Vent Whistle		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	05/01/1992	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR 643 WEST 43RD STREET NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600720	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	NUBEE INC 643 WEST 43RD STREET		

UNITED PARCEL SERVICE (Continued) **1000398410**

	NEW YORK, NY 10036		
Owner Phone:	(212) 631-6446		
Facility Phone:	(212) 631-6446		
Operator:	THOMAS J. SAVAGE		
Emergency Name:	PAUL MCDONALD		
Emergency Phone:	(212) 631-6444		
Total Tanks:	5		
Total Capacity:	38500		
Tank ID:	5		
Capacity (Gal):	500		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	USED OIL		
Tank Type:	Steel/carbon steel		
Install Date:	09/01/1993		
Tank Internal:	NONE		
Tank External:	NONE/NONE		
Tank Containment:	DOUBLED-WALLED TANK		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Leak Detection:	NONE		
Overfill Protection:	High Level Alarm		
Dispenser Method:	None		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	UNITED PARCEL SERVICE		
Mailing Address:	FIFTH FLOOR		
	643 WEST 43RD STREET		
	NEW YORK, NY 10036		
Mailing Contact:	PLANT ENGINEERING DEPT		
Mailing Telephone:	(212) 631-6444		
Owner Mark:	First Owner	Expiration Date:	04/17/2002
Certification Flag:	False	Certification Date:	06/25/1999
Renew Flag:	False	Renew Date:	01/02/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

C6 **NEW YORK TELEPHONE CO** **RCRIS-SQG 1000791570**
East **605 W 42ND ST** **FINDS NYD987030830**
< 1/8 **NEW YORK, NY 10036**
485
Higher **Site 1 of 4 in cluster C**

NEW YORK TELEPHONE CO (Continued) **1000791570**

RCRIS:
Owner: NEW YORK TELEPHONE CO
(212) 555-1212

Contact: KENNY JAMES
(212) 767-8120

Record Date: 03/15/1993
Classification: Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

C7 East < 1/8 485 Higher **VERIZON** **LTANKS** **S105055196**
605 WEST 42ND ST **N/A**
MANHATTAN, NY

Site 2 of 4 in cluster C

LTANKS:

Spill Number:	0103392	Region of Spill:	2
Facility Contact:	JOHN QUATRALE	Facility Tele:	(212) 338-7141
Investigator:	TIBBE	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	JOHN QUATRALE	Spiller Phone:	(212) 338-7141
Spiller:	VERIZON		
Spiller Address:	-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	06/28/2001 08:15	Reported to Dept:	06/28/2001 09:35
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	07/06/2001
Is Updated:	False

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/28/2001
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported

VERIZON (Continued) **S105055196**

Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 20
Units: Gallons
Unknown Qty Spilled: 20
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: SOME PRODUCT WASHED DOWN DRAIN THAT LEADS TO SEWER - TANK FAILED ON VEHI CLE - MIROY CONTACTED FOR CLEAN UP

C8 **CONSOLIDATED GAS CO.** **Coal Gas** **G000000365**
ESE **600 W. 42ND ST.** **N/A**
< 1/8 **NEW YORK, NY 10036**
512
Higher **Site 3 of 4 in cluster C**

COAL GAS SITE DESCRIPTION:
Site is on the eastern half of the block formed by 42nd St., 11th Ave. and 41st St. Site consisted of Gas Holders and purifying buildings. (B17, 18)

©Copyright 1993 Real Property Scan, Inc.

C9 **MOBIL OIL CORP** **FINDS** **1000708510**
ESE **42 ST 11TH AVE** **RCRIS-LQG** **NYD982719270**
< 1/8 **NEW YORK, NY 10036**
515
Higher **Site 4 of 4 in cluster C**

RCRIS:
Owner: MOBIL OIL CORP
(212) 555-1212
Contact: ROSEANN PAVARO
(516) 371-0248
Record Date: 12/06/1988
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

MOBIL OIL CORP (Continued) — **1000708510**

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

---

10 | **608 W 40 ST - MAN** | **LTANKS** | **S102671470**
SSE | **608 W 40 ST** | **N/A**
< 1/8 | **MANHATTAN, NY**
546
Higher

LTANKS:

Spill Number:	8909404	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	FINGER	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	Not reported		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/16/1997		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/27/1989 12:00	Reported to Dept:	12/28/1989 12:01
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	10/17/1997
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	12/28/1989
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	15
Units:	Gallons
Unknown Qty Spilled:	15
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	#4 FUEL OIL
Class Type:	Petroleum
Chem Abstract Service Number:	#4 FUEL OIL

608 W 40 ST - MAN (Continued) **S102671470**

Last Date: 12/05/1994
Num Times Material Entry In File: 1751
DEC Remarks: Not reported
Spill Cause: CUSTOMER ORDERED 2K GALS - TK OVERFILL @ 1.2K - ESCAPE FROM VENT - MY-ST IC SENDS CLEANUP CREW, BUT CUSTOMER HAD ALREADY HOSED DOWN SPILL SPRE AD OVER LARGE AREA - NY SANIT PUTS DOWN SAND

D11 **UNITED PARCEL SERVICE** **FINDS 1000398448**
SSE **525 11TH AVE** **RCRIS-LQG NYD986903003**
< 1/8 **NEW YORK, NY 10036**
554
Higher **Site 1 of 6 in cluster D**

RCRIS:
Owner: GREYHOUND CORP
(212) 555-1212

Contact: PAUL IACOBINO
(212) 560-6157

Record Date: 05/30/1990
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

D12 **525 N 11TH AVE/MANH/GREYH** **LTANKS S104275659**
SSE **525 NORTH 11TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
554
Higher **Site 2 of 6 in cluster D**

LTANKS:

Spill Number:	9101412	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TANG	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(214) 744-6521
Spiller:	GREYHOUND		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	05/03/1991 16:30	Reported to Dept:	05/03/1991 18:08
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		

525 N 11TH AVE/MANH/GREYH (Continued) **S104275659**

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/03/1992
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/08/1991
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 3
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: ANTIFREEZE
Class Type: Non Pet/Non Haz
Chem Abstract Service Number: ANTIFREEZE
Last Date: Not reported
Num Times Material Entry In File: 0
DEC Remarks: Not reported
Spill Cause: 5K TANK FAILED TEST,NO ACTION YET DETERMINED.

D13 **NYCT GREYHOUND BUS TERMINAL** **FINDS 1001124837**
SSE **525 11TH AVE** **RCRIS-LQG NYR000031609**
< 1/8 **NEW YORK, NY 10036**
554
Higher **Site 3 of 6 in cluster D**

RCRIS:
Owner: NEW YORK CITY TRANSIT
(718) 694-5290
Contact: JOE DINACRAM
(212) 307-5976
Record Date: 10/30/1996
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Biennial Reporting System (BRS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

D14 **M.J. QUILL DEPOT** **UST** **U003107136**
SSE **525 ELEVENTH AVE** **CBS UST** **N/A**
< 1/8 **NEW YORK, NY 10018** **CBS AST**
554 **AST**
Higher **Site 4 of 6 in cluster D**

CBS UST:

CBS Number:	2-000311	ICS No:	Not reported
PBS No:	2-236144	MOSF No:	Not reported
Region:	STATE	Town:	NEW YORK CITY
Operator:	NYC TRANSIT	Facility Tel:	(718) 243-4581
Emergency Contact:	HOWARD MATZA, (718) 243-4581		
Certification Date:	03/10/2000	Expiration Date:	05/21/2002
Owner:	NEW YORK CITY TRANSIT		
Owner Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11201		
Owner Phone	(718) 243-4581		
Owner Type:	State Government		
Facility Type:	MUNICIPALITY		
Mail To:	NEW YORK CITY TRANSIT		
Mail Address	370 JAY STREET ROOM 819 BROOKLYN, NY 11201 ATTN: MR. HOWARD MATZA (718) 243-4581		
SPDES No:	Not reported	Facility Status:	NO LONGER A MAJOR FACILITY
Owner Subtype:	None		
Tank Status:	In Service		
Tank Error Status:	No Missing Data		
Total Tanks:	1	Capacity:	5000 Gals
Tank Location:	Underground		
Install Date:	00/00		
CAS No:	107211		
Substance:	Single Hazardous Substance on DEC List		
Tank Type:	Steel/carbon steel	2nd Containmt:	None
Tank Internal:	None	Pipe Type:	STEEL/IRON
Tank External:	Painted/Asphalt Coating		
Pipe Internal:	None	Pipe Location:	Aboveground/Underground Combination
Pipe External:	Painted/Asphalt Coating		
Pipe Containment:	None	Haz Percent:	100
Leak Detection:	None		
Overfill Protection:	0		
Chemical:	Ethylene glycol	Tank Closed:	04/97
Tank Secret:	False	Date Entered:	05/20/1996 13:15:30
Last Test:	Not reported	Due Date:	Not reported
SWIS Code:	6201		
Cert Flag:	False		
Case No:	Not reported	Reserve Flag:	True
Pipe Flag:	False	Federal Amt:	True
Is it There:	False	Is Updated:	False
Owner Mark:	1	Lat/Long:	Not reported
Renew Date:	Not reported	Date Expired:	Not reported
Total Capacity:	1500		
Tank Number:	1		

CBS Number:	2-000311	ICS No:	Not reported
PBS No:	2-236144	MOSF No:	Not reported
Region:	STATE	Town:	NEW YORK CITY
Operator:	NYC TRANSIT	Facility Tel:	(718) 243-4581

M.J. QUILL DEPOT (Continued) **U003107136**

Emergency Contact:	HOWARD MATZA, (718) 243-4581		
Certification Date:	03/10/2000	Expiration Date:	05/21/2002
Owner:	NEW YORK CITY TRANSIT		
Owner Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11201		
Owner Phone	(718) 243-4581		
Owner Type:	State Government		
Facility Type:	MUNICIPALITY		
Mail To:	NEW YORK CITY TRANSIT		
Mail Address	370 JAY STREET ROOM 819 BROOKLYN, NY 11201 ATTN: MR. HOWARD MATZA (718) 243-4581		
SPDES No:	Not reported	Facility Status:	NO LONGER A MAJOR FACILITY
Owner Subtype:	None		
Tank Status:	In Service		
Tank Error Status:	No Missing Data		
Total Tanks:	1	Capacity:	5000 Gals
Tank Location:	Underground		
Install Date:	00/00		
CAS No:	107211		
Substance:	Single Hazardous Substance on DEC List		
Tank Type:	Steel/carbon steel	2nd Containmt:	None
Tank Internal:	None	Pipe Type:	STEEL/IRON
Tank External:	Painted/Asphalt Coating		
Pipe Internal:	None	Pipe Location:	Aboveground/Underground Combination
Pipe External:	Painted/Asphalt Coating		
Pipe Containment:	None	Haz Percent:	100
Leak Detection:	None		
Overfill Protection:	0		
Chemical:	Ethylene glycol	Tank Closed:	04/97
Tank Secret:	False	Date Entered:	05/20/1996 13:15:43
Last Test:	Not reported	Due Date:	Not reported
SWIS Code:	6201		
Cert Flag:	False		
Case No:	Not reported	Reserve Flag:	True
Pipe Flag:	False	Federal Amt:	True
Is it There:	False	Is Updated:	False
Owner Mark:	1	Lat/Long:	Not reported
Renew Date:	Not reported	Date Expired:	Not reported
Total Capacity:	1500		
Tank Number:	2		

CBS AST:

CBS Number:	2-000311	Telephone:	(718) 243-4581
Owner:	NEW YORK CITY TRANSIT 370 JAY STREET ROOM 819 BROOKLYN, NY 11201 (718) 243-4581		
Facility Status:	Active		
Total Tanks	1		
Tank Status:	In Service		
Tank Error Status:	No Missing Data		
Tank Location:	Aboveground		
Install Date:	04/97		
Capacity (Gal):	1500		
Tank Type:	Steel/carbon steel		

M.J. QUILL DEPOT (Continued) **U003107136**

Substance:	Single Hazardous Substance on DEC List		
Extrnl Protection:	Painted/Asphalt Coating		
Intrnl Protection:	None		
Tank Containment:	Double-Walled		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	None		
Pipe External:	Painted/Asphalt Coating		
Pipe Containment:	None	Haz Percent:	100
Leak Detection:	Electronic/In-tank System		
Overfill Protection:	3/3		
Chemical:	Ethylene glycol	Tank Closed:	Not reported
PBS Number:	2-236144	SWIS Code:	6201
Federal ID:	Not reported		
MOSF Number:	Not reported	CAS Number:	107211
SPDES Number:	Not reported	ICS Number:	Not reported
Facility Type:	Municipality		
Operator:	NYC TRANSIT	Facility Town:	NEW YORK CITY
Emrgncy Contact:	HOWARD MATZA	Emrgncy Phone:	(718) 243-4581
Certified Date:	03/10/2000	Expiration Date:	05/21/2002
Owner type:	State Government		
Owner Sub Type:	None		
Mail Name:	NEW YORK CITY TRANSIT		
Mail Contact:	MR. HOWARD MATZA 370 JAY STREET ROOM 819 BROOKLYN, NY 11201		
Mail Phone:	(718) 243-4581		
Tank Secret:	False	Date Entered:	04/01/1997 13:54:55
Last Test:	Not reported	Due Date:	Not reported
Pipe Flag:	False	Owner Mark:	1
Renew Date:	Not reported	Date Expired:	Not reported
Is it There:	False	Is Updated:	False
Owner Status:	F		

Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Total Capacity of All Active Tanks(gal):	1500
Unique Tank Id Number:	CBS-WSD-1
Date Pre-Printed Renewal App Form Was Last Printed:	02/01/2000

PBS UST:

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYC TRANSIT AUTHORITY (212) 690-0602		
Emergency Contact:	HOWARD MATZA (718) 243-4581		
Total Tanks:	9		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201 (718) 243-4581		
Owner Type:	Local Government		
Owner Mark:	Second Owner		
Owner Subtype:	Not reported		
Mailing Address:	NYC TRANSIT AUTHORITY ATTN: JOSEPHINE BROWN 370 JAY STREET		

M.J. QUILL DEPOT (Continued) **U003107136**

ROOM 819
BROOKLYN, NY 11210
(718) 243-4581

Tank Status:	Closed - Removed		
Capacity (gals):	15000		
Tank Location:	UNDERGROUND		
Tank Id:	WSD-1	Install Date:	09/01/1969
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Above/Underground Combination	Pipe Type:	STEEL/IRON
Tank External:	NONE/PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/OTHER		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	10/01/1997	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	87500	Renewal Date:	05/31/2001
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/22/2001
Old PBS Number:	Not reported	Expiration Date:	05/31/2006
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :	Not reported		

M.J. QUILL DEPOT (Continued) **U003107136**

SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362
	DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYC TRANSIT AUTHORITY (212) 690-0602		
Emergency Contact:	HOWARD MATZA (718) 243-4581		
Total Tanks:	9		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201 (718) 243-4581		
Owner Type:	Local Government		
Owner Mark:	Second Owner		
Owner Subtype:	Not reported		
Mailing Address:	NYC TRANSIT AUTHORITY ATTN: JOSEPHINE BROWN 370 JAY STREET ROOM 819 BROOKLYN, NY 11210 (718) 243-4581		
Tank Status:	Closed - Removed		
Capacity (gals):	17000		
Tank Location:	UNDERGROUND		
Tank Id:	WSD-2	Install Date:	09/01/1969
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Above/Underground Combination	Pipe Type:	STEEL/IRON
Tank External:	NONE/PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/OTHER		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	10/01/1997	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	87500	Renewal Date:	05/31/2001

M.J. QUILL DEPOT (Continued) **U003107136**

Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/22/2001
Old PBS Number:	Not reported	Expiration Date:	05/31/2006
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362 DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYC TRANSIT AUTHORITY (212) 690-0602		

M.J. QUILL DEPOT (Continued) **U003107136**

Emergency Contact:	HOWARD MATZA (718) 243-4581		
Total Tanks:	9		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201 (718) 243-4581		
Owner Type:	Local Government		
Owner Mark:	Second Owner		
Owner Subtype:	Not reported		
Mailing Address:	NYC TRANSIT AUTHORITY ATTN: JOSEPHINE BROWN 370 JAY STREET ROOM 819 BROOKLYN, NY 11210 (718) 243-4581		
Tank Status:	Closed - Removed		
Capacity (gals):	18000		
Tank Location:	UNDERGROUND		
Tank Id:	WSD-3	Install Date:	09/01/1969
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Above/Underground Combination	Pipe Type:	STEEL/IRON
Tank External:	NONE/PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/OTHER		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	10/01/1997	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	87500	Renewal Date:	05/31/2001
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/22/2001
Old PBS Number:	Not reported	Expiration Date:	05/31/2006
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported

M.J. QUILL DEPOT (Continued) **U003107136**

Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362 DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYC TRANSIT AUTHORITY (212) 690-0602		
Emergency Contact:	HOWARD MATZA (718) 243-4581		
Total Tanks:	9		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201 (718) 243-4581		
Owner Type:	Local Government		
Owner Mark:	Second Owner		
Owner Subtype:	Not reported		
Mailing Address:	NYC TRANSIT AUTHORITY ATTN: JOSEPHINE BROWN 370 JAY STREET ROOM 819 BROOKLYN, NY 11210 (718) 243-4581		
Tank Status:	Closed - Removed		
Capacity (gals):	15000		
Tank Location:	UNDERGROUND		
Tank Id:	WSD-4	Install Date:	09/01/1969
Tank Type:	Steel/carbon steel	Product Stored:	LUBE OIL
Tank Internal:	NONE	Pipe Internal:	NONE

M.J. QUILL DEPOT (Continued) **U003107136**

Pipe Location:	Above/Underground Combination	Pipe Type:	STEEL/IRON
Tank External:	NONE/PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/OTHER		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	10/01/1997	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	87500	Renewal Date:	05/31/2001
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/22/2001
Old PBS Number:	Not reported	Expiration Date:	05/31/2006
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :	Not reported		
SPDES Number:	Not reported		
Lat/Long :	Not reported		
County Facility:	6201		
Facility Phone :	(212) 971-6386		
Num of Active Tanks :	13		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	P O BOX 660362 DALLAS, TX 75266		

M.J. QUILL DEPOT (Continued) **U003107136**

Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	NYC TRANSIT AUTHORITY (212) 690-0602		
Emergency Contact:	HOWARD MATZA (718) 243-4581		
Total Tanks:	9		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201 (718) 243-4581		
Owner Type:	Local Government		
Owner Mark:	Second Owner		
Owner Subtype:	Not reported		
Mailing Address:	NYC TRANSIT AUTHORITY ATTN: JOSEPHINE BROWN 370 JAY STREET ROOM 819 BROOKLYN, NY 11210 (718) 243-4581		
Tank Status:	Closed - Removed		
Capacity (gals):	5000		
Tank Location:	UNDERGROUND		
Tank Id:	011	Install Date:	09/01/1969
Tank Type:	Steel/carbon steel	Product Stored:	LUBE OIL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Above/Underground Combination	Pipe Type:	STEEL/IRON
Tank External:	NONE/PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	09/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	87500	Renewal Date:	05/31/2001
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/22/2001
Old PBS Number:	Not reported	Expiration Date:	05/31/2006
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		

M.J. QUILL DEPOT (Continued) **U003107136**

Town or City Code: 01
County Code: 62
Region: 2

PBS OWNHIST
Operator: VICTOR FETTER
Emergency: VICTOR FETTER
Emergency Tel: (212) 971-6386 Old PBSNO: Not reported
Facility Type: OTHER
Facility Owner: GREYHOUND LINES, INC
Facility Address: 525 ELEVENTH AVE
525 11TH AVE
NEW YORK, NY 10018
Inspector: Not reported Inspect Date: Not reported
Insp Result: Not reported Federal ID: 86-0572343
Owner: GREYHOUND LINES, INC
Owner Tel: (214) 698-4673 Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mail Address: GREYHOUND LINES, INC
P O BOX 660362
DALLAS, TX 75266
RITA FELTON
(214) 698-4673
Owner Mark: First Owner
Certify Date: 07/07/1997 Expiration: 07/07/1997
Total Capacity (Gal): 157700
CBS Registration Num : Not reported
SPDES Number: Not reported
Lat/Long : Not reported
County Facility: 6201
Facility Phone : (212) 971-6386
Num of Active Tanks : 13
Facility Owner: GREYHOUND LINES, INC
Facility Address: P O BOX 660362
DALLAS, TX 75266
Owner Phone: (214) 698-4673
Facility Status: 1
Certificate Needs Printed : False
Renewal Printed : False
Pre-printed Renewal Form Last Printed : Not reported
Fiscal Amt For Registration Fee Pbsrect: True
Dt Ownership Transfer Occurr in Computer : 05/31/1996
Facility Record Updated: True

This is the most recent NY PBS data for this site.
The NY PBS database contains 9 additional records for this site.
Please contact your EDR Account Executive for more information.

CBS AST:
CBS Number: 2-000311 Telephone: (718) 243-4581
Owner: NEW YORK CITY TRANSIT
370 JAY STREET ROOM 819
BROOKLYN, NY 11201
(718) 243-4581
Facility Status: Active
Total Tanks 1
Tank Status: In Service

M.J. QUILL DEPOT (Continued) **U003107136**

Tank Error Status:	No Missing Data		
Tank Location:	Aboveground		
Install Date:	04/97		
Capacity (Gal):	1500		
Tank Type:	Steel/carbon steel		
Substance:	Single Hazardous Substance on DEC List		
Extrnl Protection:	Painted/Asphalt Coating		
Intrnl Protection:	None		
Tank Containment:	Double-Walled		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	None		
Pipe External:	Painted/Asphalt Coating		
Pipe Containment:	None	Haz Percent:	100
Leak Detection:	Electronic/In-tank System		
Overfill Protection:	3/3		
Chemical:	Ethylene glycol	Tank Closed:	Not reported
PBS Number:	2-236144	SWIS Code:	6201
Federal ID:	Not reported		
MOSF Number:	Not reported	CAS Number:	107211
SPDES Number:	Not reported	ICS Number:	Not reported
Facility Type:	Municipality		
Operator:	NYC TRANSIT	Facility Town:	NEW YORK CITY
Emrgncy Contact:	HOWARD MATZA	Emrgncy Phone:	(718) 243-4581
Certified Date:	03/10/2000	Expiration Date:	05/21/2002
Owner type:	State Government		
Owner Sub Type:	None		
Mail Name:	NEW YORK CITY TRANSIT		
Mail Contact:	MR. HOWARD MATZA 370 JAY STREET ROOM 819 BROOKLYN, NY 11201		
Mail Phone:	(718) 243-4581		
Tank Secret:	False	Date Entered:	04/01/1997 13:54:55
Last Test:	Not reported	Due Date:	Not reported
Pipe Flag:	False	Owner Mark:	1
Renew Date:	Not reported	Date Expired:	Not reported
Is it There:	False	Is Updated:	False
Owner Status:	F		

Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Total Capacity of All Active Tanks(gal):	1500
Unique Tank Id Number:	CBS-WSD-1
Date Pre-Printed Renewal App Form Was Last Printed:	02/01/2000

PBS AST:

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		

M.J. QUILL DEPOT (Continued) **U003107136**

Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	004		
Capacity (Gal):	1000		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	09/01/1969		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/IN-TANK SYSTEM		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	08/01/1996	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		

M.J. QUILL DEPOT (Continued) **U003107136**

Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362 DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	005		
Capacity (Gal):	1000		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		

M.J. QUILL DEPOT (Continued) **U003107136**

Install Date:	09/01/1969		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/IN-TANK SYSTEM		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	08/01/1996	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

M.J. QUILL DEPOT (Continued) **U003107136**

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362
	DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	007		
Capacity (Gal):	1000		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	LUBE OIL		
Tank Type:	Steel/carbon steel		
Install Date:	09/01/1969		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Above/Underground Combination		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/OTHER		
Overfill Protection:	None		
Dispenser Method:	Submersible		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	09/01/1996	Test Method:	Not reported

M.J. QUILL DEPOT (Continued) **U003107136**

Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362 DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False

M.J. QUILL DEPOT (Continued) **U003107136**

Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	008		
Capacity (Gal):	500		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	UNLEADED GASOLINE		
Tank Type:	Steel/carbon steel		
Install Date:	09/01/1969		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/IN-TANK SYSTEM		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	06/01/1997	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		

M.J. QUILL DEPOT (Continued) **U003107136**

Dead Letter: False
Facility Screen: No data missing
Owner Screen: Minor data missing
Tank Screen: No data missing
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2
Fiscal Amount for Registration Fee is Correct: True

PBS OWNHIST
Operator: VICTOR FETTER
Emergency: VICTOR FETTER
Emergency Tel: (212) 971-6386 Old PBSNO: Not reported
Facility Type: OTHER
Facility Owner: GREYHOUND LINES, INC
Facility Address: 525 ELEVENTH AVE
525 11TH AVE
NEW YORK, NY 10018
Inspector: Not reported Inspect Date: Not reported
Insp Result: Not reported Federal ID: 86-0572343
Owner: GREYHOUND LINES, INC
Owner Tel: (214) 698-4673 Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mail Address: GREYHOUND LINES, INC
P O BOX 660362
DALLAS, TX 75266
RITA FELTON
(214) 698-4673
Owner Mark: First Owner
Certify Date: 07/07/1997 Expiration: 07/07/1997
Total Capacity (Gal): 157700
CBS Registration Num : Not reported
SPDES Number: Not reported
Lat/Long : Not reported
County Facility: 6201
Facility Phone : (212) 971-6386
Num of Active Tanks : 13
Facility Owner: GREYHOUND LINES, INC
Facility Address: P O BOX 660362
DALLAS, TX 75266
Owner Phone: (214) 698-4673
Facility Status: 1
Certificate Needs Printed : False
Renewal Printed : False
Pre-printed Renewal Form Last Printed : Not reported
Fiscal Amt For Registration Fee Pbsrect: True
Dt Ownership Transfer Occurr in Computer : 05/31/1996
Facility Record Updated: True

PBS Number: 2-236144 CBS Number: Not reported
SPDES Number: Not reported SWIS Code: 6201
Federal ID: Not reported Previous PBS#: Not reported
Facility Status: 3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).
Facility Type: TRUCKING/TRANSPORTATION

M.J. QUILL DEPOT (Continued) **U003107136**

Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	009		
Capacity (Gal):	500		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	LUBE OIL		
Tank Type:	Steel/carbon steel		
Install Date:	09/01/1969		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/IN-TANK SYSTEM		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	08/01/1996	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee Is Correct: True

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported

M.J. QUILL DEPOT (Continued) **U003107136**

Facility Type:	OTHER		
Facility Owner:		GREYHOUND LINES, INC	
Facility Address:		525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018	
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :		Not reported	
SPDES Number:		Not reported	
Lat/Long :		Not reported	
County Facility:		6201	
Facility Phone :		(212) 971-6386	
Num of Active Tanks :		13	
Facility Owner:		GREYHOUND LINES, INC	
Facility Address:		P O BOX 660362 DALLAS, TX 75266	
Owner Phone:		(214) 698-4673	
Facility Status:		1	
Certificate Needs Printed :		False	
Renewal Printed :		False	
Pre-printed Renewal Form Last Printed :		Not reported	
Fiscal Amt For Registration Fee Pbsrect:		True	
Dt Ownership Transfer Occurr in Computer :		05/31/1996	
Facility Record Updated:		True	

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	010		

M.J. QUILL DEPOT (Continued) **U003107136**

Capacity (Gal):	500		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	LUBE OIL		
Tank Type:	Steel/carbon steel		
Install Date:	09/01/1969		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/IN-TANK SYSTEM		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	08/01/1996	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266		

M.J. QUILL DEPOT (Continued) **U003107136**

RITA FELTON
(214) 698-4673

Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362
	DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported

Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Type:	TRUCKING/TRANSPORTATION
Owner Type:	Local Government
Owner Sub Type:	Not reported
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201
Owner Phone:	(718) 243-4581
Facility Phone:	(212) 690-0602
Operator:	NYC TRANSIT AUTHORITY
Emergency Name:	HOWARD MATZA
Emergency Phone:	(718) 243-4581
Total Tanks:	9
Total Capacity:	87500
Tank ID:	WSD-5
Capacity (Gal):	20000
Missing Data for Tank :	No data missing
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Install Date:	06/01/1997
Tank Internal:	NONE
Tank External:	NONE/PAINTED/ASPHALT COATING
Tank Containment:	NONE/CONCRETE DIKE
Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground
Pipe Internal:	NONE
Pipe External:	NONE/PAINTED/ASPHALT COATING
Leak Detection:	NONE/OTHER

M.J. QUILL DEPOT (Continued) **U003107136**

Overfill Protection:	Catch Basin, Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct:	True		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :	Not reported		
SPDES Number:	Not reported		
Lat/Long :	Not reported		
County Facility:	6201		
Facility Phone :	(212) 971-6386		
Num of Active Tanks :	13		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	P O BOX 660362		

M.J. QUILL DEPOT (Continued) **U003107136**

	DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	WSD-6		
Capacity (Gal):	20000		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	NOS 1,2, OR 4 FUEL OIL		
Tank Type:	Steel/carbon steel		
Install Date:	06/01/1997		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/CONCRETE DIKE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/OTHER		
Overfill Protection:	Catch Basin, Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006

M.J. QUILL DEPOT (Continued) **U003107136**

Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct:	True		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :	Not reported		
SPDES Number:	Not reported		
Lat/Long :	Not reported		
County Facility:	6201		
Facility Phone :	(212) 971-6386		
Num of Active Tanks :	13		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	P O BOX 660362 DALLAS, TX 75266		
Owner Phone:	(214) 698-4673		
Facility Status:	1		
Certificate Needs Printed :	False		
Renewal Printed :	False		
Pre-printed Renewal Form Last Printed :	Not reported		
Fiscal Amt For Registration Fee Pbsrect:	True		
Dt Ownership Transfer Occurr in Computer :	05/31/1996		
Facility Record Updated:	True		

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported

M.J. QUILL DEPOT (Continued) **U003107136**

Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	WSD-7		
Capacity (Gal):	2000		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	USED OIL		
Tank Type:	Steel/carbon steel		
Install Date:	10/01/1997		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/DOUBLED-WALLED TANK		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Protection:	Catch Basin, High Level Alarm		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

M.J. QUILL DEPOT (Continued) **U003107136**

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		

CBS Registration Num :	Not reported
SPDES Number:	Not reported
Lat/Long :	Not reported
County Facility:	6201
Facility Phone :	(212) 971-6386
Num of Active Tanks :	13
Facility Owner:	GREYHOUND LINES, INC
Facility Address:	P O BOX 660362 DALLAS, TX 75266
Owner Phone:	(214) 698-4673
Facility Status:	1
Certificate Needs Printed :	False
Renewal Printed :	False
Pre-printed Renewal Form Last Printed :	Not reported
Fiscal Amt For Registration Fee Pbsrect:	True
Dt Ownership Transfer Occurr in Computer :	05/31/1996
Facility Record Updated:	True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		

M.J. QUILL DEPOT (Continued) **U003107136**

Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	WSD-8		
Capacity (Gal):	4000		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LUBE OIL		
Tank Type:	Steel/carbon steel		
Install Date:	10/01/1997		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/DOUBLED-WALLED TANK		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Protection:	Catch Basin, High Level Alarm		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		

M.J. QUILL DEPOT (Continued) **U003107136**

Mail Address: GREYHOUND LINES, INC
P O BOX 660362
DALLAS, TX 75266
RITA FELTON
(214) 698-4673
Owner Mark: First Owner
Certify Date: 07/07/1997 Expiration: 07/07/1997
Total Capacity (Gal): 157700
CBS Registration Num : Not reported
SPDES Number: Not reported
Lat/Long : Not reported
County Facility: 6201
Facility Phone : (212) 971-6386
Num of Active Tanks : 13
Facility Owner: GREYHOUND LINES, INC
Facility Address: P O BOX 660362

DALLAS, TX 75266
Owner Phone: (214) 698-4673
Facility Status: 1
Certificate Needs Printed : False
Renewal Printed : False
Pre-printed Renewal Form Last Printed : Not reported
Fiscal Amt For Registration Fee Pbsrect: True
Dt Ownership Transfer Occurr in Computer : 05/31/1996
Facility Record Updated: True

PBS Number: 2-236144 CBS Number: Not reported
SPDES Number: Not reported SWIS Code: 6201
Federal ID: Not reported Previous PBS#: Not reported
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Type: TRUCKING/TRANSPORTATION
Owner Type: Local Government
Owner Sub Type: Not reported
Owner: NYC TRANSIT AUTHORITY
370 JAY STREET, ROOM 819
BROOKLYN, NY 11201
Owner Phone: (718) 243-4581
Facility Phone: (212) 690-0602
Operator: NYC TRANSIT AUTHORITY
Emergency Name: HOWARD MATZA
Emergency Phone: (718) 243-4581
Total Tanks: 9
Total Capacity: 87500
Tank ID: WSD-9
Capacity (Gal): 1500
Missing Data for Tank : No data missing
Tank Location: ABOVEGROUND
Product Stored: OTHER
Tank Type: Steel/carbon steel
Install Date: 10/01/1997
Tank Internal: NONE
Tank External: NONE/PAINTED/ASPHALT COATING
Tank Containment: NONE/DOUBLED-WALLED TANK
Pipe Type: STEEL/IRON
Pipe Location: Aboveground

M.J. QUILL DEPOT (Continued) **U003107136**

Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Protection:	Catch Basin, High Level Alarm		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		
Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct:	True		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :	Not reported		
SPDES Number:	Not reported		
Lat/Long :	Not reported		
County Facility:	6201		
Facility Phone :	(212) 971-6386		
Num of Active Tanks :	13		

M.J. QUILL DEPOT (Continued) **U003107136**

Facility Owner: GREYHOUND LINES, INC
Facility Address: P O BOX 660362

DALLAS, TX 75266
Owner Phone: (214) 698-4673
Facility Status: 1
Certificate Needs Printed : False
Renewal Printed : False
Pre-printed Renewal Form Last Printed : Not reported
Fiscal Amt For Registration Fee Pbsrect: True
Dt Ownership Transfer Occurr in Computer : 05/31/1996
Facility Record Updated: True

PBS Number:	2-236144	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	5		
Facility Type:	TRUCKING/TRANSPORTATION		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	NYC TRANSIT AUTHORITY 370 JAY STREET, ROOM 819 BROOKLYN, NY 11201		
Owner Phone:	(718) 243-4581		
Facility Phone:	(212) 690-0602		
Operator:	NYC TRANSIT AUTHORITY		
Emergency Name:	HOWARD MATZA		
Emergency Phone:	(718) 243-4581		
Total Tanks:	9		
Total Capacity:	87500		
Tank ID:	WSD-10		
Capacity (Gal):	100		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	NOS 1,2, OR 4 FUEL OIL		
Tank Type:	Concrete		
Install Date:	10/01/1997		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/DOUBLED-WALLED TANK		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/INTERSTITIAL MONITORING		
Overfill Protection:	Product Level Gauge, High Level Alarm		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	08/01/1996	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	NYC TRANSIT AUTHORITY		
Mailing Address:	370 JAY STREET ROOM 819 BROOKLYN, NY 11210		
Mailing Contact:	JOSEPHINE BROWN		

M.J. QUILL DEPOT (Continued) **U003107136**

Mailing Telephone:	(718) 243-4581		
Owner Mark:	Second Owner	Expiration Date:	05/31/2006
Certification Flag:	False	Certification Date:	06/22/2001
Renew Flag:	False	Renew Date:	05/31/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	Minor data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
Fiscal Amount for Registration Fee is Correct:	True		

PBS OWNHIST

Operator:	VICTOR FETTER		
Emergency:	VICTOR FETTER		
Emergency Tel:	(212) 971-6386	Old PBSNO:	Not reported
Facility Type:	OTHER		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	525 ELEVENTH AVE 525 11TH AVE NEW YORK, NY 10018		
Inspector:	Not reported	Inspect Date:	Not reported
Insp Result:	Not reported	Federal ID:	86-0572343
Owner:	GREYHOUND LINES, INC		
Owner Tel:	(214) 698-4673	Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported		
Mail Address:	GREYHOUND LINES, INC P O BOX 660362 DALLAS, TX 75266 RITA FELTON (214) 698-4673		
Owner Mark:	First Owner		
Certify Date:	07/07/1997	Expiration:	07/07/1997
Total Capacity (Gal):	157700		
CBS Registration Num :	Not reported		
SPDES Number:	Not reported		
Lat/Long :	Not reported		
County Facility:	6201		
Facility Phone :	(212) 971-6386		
Num of Active Tanks :	13		
Facility Owner:	GREYHOUND LINES, INC		
Facility Address:	P O BOX 660362 DALLAS, TX 75266		
Owner Phone:	(214) 698-4673		
Facility Status:	1		
Certificate Needs Printed :	False		
Renewal Printed :	False		
Pre-printed Renewal Form Last Printed :	Not reported		
Fiscal Amt For Registration Fee Pbsrect:	True		
Dt Ownership Transfer Occurr in Computer :	05/31/1996		
Facility Record Updated:	True		

D15 **NYCTA - 11TH AVE BUS DEPOT MTA** **RCRIS-SQG** **1000441458**
SSE **525 11TH AVE** **NYD980755441**
< 1/8 **NEW YORK, NY 10018**
554
Higher **Site 5 of 6 in cluster D**

RCRIS:
Owner: NEW YORK CITY TRANSIT AUTHORITY - MTA
(718) 243-4581

Contact: CHARLES BURRUS
(718) 243-4581

Record Date: 08/04/1995
Classification: Small Quantity Generator

BIENNIAL REPORTS:
Last Biennial Reporting Year: 1999

Waste	Quantity (Lbs)	Waste	Quantity (Lbs)
D001	4000.00	D002	0.00
D005	4000.00	D007	4000.00
F003	4000.00	F005	4000.00

Used Oil Recyc: No

Violation Status: Violations exist

Regulation Violated:	Not reported
Area of Violation:	Generator-All Requirements
Date Violation Determined:	08/13/1990
Priority of Violation:	Low
Schedule Date to Achieve Compliance:	Not reported
Actual Date Achieved Compliance:	Not reported

There are 1 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Non-Financial Record Review	Generator-All Requirements	

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

E16 **MOBIL OIL CORP SS QDL** **RCRIS-SQG** **1000253419**
East **561 11TH AVE** **FINDS** **NYD986962322**
< 1/8 **NEW YORK, NY 10036** **UST**
573 **LTANKS**
Higher **Site 1 of 6 in cluster E**

RCRIS:
Owner: MOBIL OIL CORP
(703) 849-3330

Contact: ROSEANN FAVARO
(703) 849-3330

Record Date: 04/10/1991
Classification: Small Quantity Generator

MOBIL OIL CORP SS QDL (Continued) **1000253419**

Used Oil Recyc: No

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site:
AIRS Facility System (AIRS/AFS)
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

LTANKS:

Spill Number:	9905507	Region of Spill:	2
Facility Contact:	MARCO	Facility Tele:	Not reported
Investigator:	O'DOWD	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	MARCO	Spiller Phone:	Not reported
Spiller:	MOBIL		
Spiller Address:	561 11 AVE MANHATTAN, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	08/06/1999 13:30	Reported to Dept:	08/06/1999 13:48
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	08/09/1999
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	08/06/1999
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Petro-Tite
Capacity of Failed Tank:	4000
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	0
Units:	Gallons
Unknown Qty Spilled:	No
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum

MOBIL OIL CORP SS QDL (Continued) **1000253419**

Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: LEAK IS AT SUBMERSIABLE PUMP

PBS UST:

PBS Number:	2-157937	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BILL HARAJLI (212) 563-0199		
Emergency Contact:	MOBIL OIL CORP. (800) 662-4567		
Total Tanks:	5		
Owner:	EXXONMOBIL OIL CORPORATION 3225 GALLOWS RD. FAIRFAX, VA 22037 (703) 849-5862		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Mobil Oil Company		
Mailing Address:	EXXONMOBIL OIL CORP ATTN: NORMA E. HILL P. O. BOX 142667 AUSTIN, TX 78714 (800) 800-4133		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	12/01/1972
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1986	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

MOBIL OIL CORP SS QDL (Continued) **1000253419**

PBS Number:	2-157937	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BILL HARAJLI (212) 563-0199		
Emergency Contact:	MOBIL OIL CORP. (800) 662-4567		
Total Tanks:	5		
Owner:	EXXONMOBIL OIL CORPORATION 3225 GALLOWS RD. FAIRFAX, VA 22037 (703) 849-5862		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Mobil Oil Company		
Mailing Address:	EXXONMOBIL OIL CORP ATTN: NORMA E. HILL P. O. BOX 142667 AUSTIN, TX 78714 (800) 800-4133		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	12/01/1962
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	3	Dispenser:	Gravity
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1986	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS Number:	2-157937	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BILL HARAJLI (212) 563-0199		
Emergency Contact:	MOBIL OIL CORP.		

MOBIL OIL CORP SS QDL (Continued) **1000253419**

	(800) 662-4567		
Total Tanks:	5		
Owner:	EXXONMOBIL OIL CORPORATION 3225 GALLOWS RD. FAIRFAX, VA 22037 (703) 849-5862		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Mobil Oil Company		
Mailing Address:	EXXONMOBIL OIL CORP ATTN: NORMA E. HILL P. O. BOX 142667 AUSTIN, TX 78714 (800) 800-4133		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	12/01/1962
Tank Type:	Steel/carbon steel	Product Stored:	OTHER
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	3	Dispenser:	Gravity
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1986	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-157937	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BILL HARAJLI (212) 563-0199		
Emergency Contact:	MOBIL OIL CORP. (800) 662-4567		
Total Tanks:	5		
Owner:	EXXONMOBIL OIL CORPORATION 3225 GALLOWS RD. FAIRFAX, VA 22037 (703) 849-5862		

MOBIL OIL CORP SS QDL (Continued) **1000253419**

Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Mobil Oil Company		
Mailing Address:	EXXONMOBIL OIL CORP ATTN: NORMA E. HILL P. O. BOX 142667 AUSTIN, TX 78714 (800) 800-4133		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	004	Install Date:	12/01/1962
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1986	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-157937	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BILL HARAJLI (212) 563-0199		
Emergency Contact:	MOBIL OIL CORP. (800) 662-4567		
Total Tanks:	5		
Owner:	EXXONMOBIL OIL CORPORATION 3225 GALLOWS RD. FAIRFAX, VA 22037 (703) 849-5862		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Mobil Oil Company		
Mailing Address:	EXXONMOBIL OIL CORP ATTN: NORMA E. HILL P. O. BOX 142667		

MOBIL OIL CORP SS QDL (Continued) **1000253419**

AUSTIN, TX 78714
(800) 800-4133

Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	005	Install Date:	12/01/1962
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1986	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

This is the most recent NY PBS data for this site.
The NY PBS database contains 13 additional records for this site.
Please contact your EDR Account Executive for more information.

E17 **MOBIL S/S** **LTANKS** **S100168133**
East **561 11TH AVENUE** **N/A**
< 1/8 **NEW YORK, NY**
573
Higher **Site 2 of 6 in cluster E**

LTANKS:

Spill Number:	9009655	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	SIGONA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	MIKE MEOLA	Spiller Phone:	(212) 563-0199
Spiller:	EXXONMOBIL CORP.		
Spiller Address:	464 DOUGHTY BLVD. INWOOD, NY 11096		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		

MOBIL S/S (Continued) **S100168133**

Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/05/1990 13:30
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 11/06/2000
Is Updated: False
Resource Affected: Groundwater
Spill Source: Gas Station
PBS Number: 2-157937
Reported to Dept: 12/05/1990 15:07
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/12/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: reassigned from Sullivan to Sigona on 11/6/00
Spill Cause: LINE TEST, FAILED PETRO TITE, LEAK RATE -.26GPH, GASSERVICE TO REPAIR RETEST, TONY KHOURY FIELD ENGINEER) 516-239-0266.

E18 **MOBIL GAS STATION** **LTANKS** **S103824901**
East **561 11TH AVE** **N/A**
< 1/8 **NEW YORK, NY**
573
Higher **Site 3 of 6 in cluster E**

LTANKS:
Spill Number: 9900078
Facility Contact: Not reported
Investigator: SIGONA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: MIKE MEOLA
Spiller: EXXONMOBIL CORP
Spiller Address: 464 DOUGHTY BLVD.
INWOOD, NY 11096
Region of Spill: 2
Facility Tele: Not reported
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

MOBIL GAS STATION (Continued) **S103824901**

Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 04/02/1999 12:15
Cleanup Ceased: Not reported
Last Inspection: Not reported
Resource Affected: On Land
Spill Source: Gas Station
PBS Number: 2-157937
Reported to Dept: 04/02/1999 12:45
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 11/06/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/02/1999
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: 1
Test Method: Tankology [Vacutect]
Capacity of Failed Tank: 4000
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Talk Test Failures only pass or fail
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Reassigned from O Dowd to Sigona on 11/6/00
Spill Cause: DOUBLE WALLED STEEL TANK. LEAK IS FROM INNER TO OUTER WALL.

D19 **523 11TH AV/GREYHOUND BUS** **LTANKS** **S101340929**
SSE **523 11TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
576
Higher **Site 6 of 6 in cluster D**

LTANKS:
Spill Number: 8904384
Facility Contact: Not reported
Investigator: TIBBE
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GREYHOUND BUS- NYCTA
Spiller Address: Not reported
Region of Spill: 2
Facility Tele: Not reported
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (214) 744-6452

523 11TH AV/GREYHOUND BUS (Continued) **S101340929**

Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 08/02/1989 12:10
Cleanup Ceased: Not reported
Last Inspection: Not reported
Resource Affected: Groundwater
Spill Source: Non Major Facility > 1,100 gallons
PBS Number: Not reported
Reported to Dept: 08/02/1989 12:33
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/28/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/03/1989
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 500
Units: Pounds
Unknown Qty Spilled: 500
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: Petroleum
Chem Abstract Service Number: UNKNOWN PETROLEUM
Last Date: 09/29/1994
Num Times Material Entry In File: 16414
Material Class Type: 1
Quantity Spilled: 0
Units: Pounds
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: MOTOR OIL
Class Type: Petroleum
Chem Abstract Service Number: MOTOR OIL
Last Date: 07/28/1994
Num Times Material Entry In File: 508
DEC Remarks: 01/13/95: SPILL REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 01/13/95. TRA NSFEREWD FROM HALE TO TIBBE ON 12/28/00. INVESTIGATION ONGOING.
Spill Cause: CONTAINED IN CLAY SOIL. OIL IN GROUNDWATER WINSTON CONTRACTOR HIRED TO P UMP OIL OUT OF THE CONTAMINATION. FACILITY SOLD TO MATA/NYCTA)

Map ID / Direction / Distance / Distance (ft.) / Elevation	Site	Database(s)	EDR ID Number / EPA ID Number
E20 East < 1/8 590 Higher	**NEW YORK TELEPHONE** **563 11TH AVE** **NEW YORK, NY 10036** **Site 4 of 6 in cluster E**	**UST** **AST**	**U001831391** **N/A**

PBS UST:

PBS Number:	2-044563	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BELL ATLANTIC (800) 696-3973		
Emergency Contact:	BELL ATLANTIC (800) 386-9639		
Total Tanks:	2		
Owner:	BELL ATLANTIC 221 EAST 37TH STREET NEW YORK, NY 10016 (800) 386-9639		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	New York Telephone		
Mailing Address:	BELL ATLANTIC ATTN: KETHLEEN TOBIN 221 EAST 37TH STREET 4TH FLOOR NEW YORK, NY 10016 (212) 338-6731		
Tank Status:	In Service		
Capacity (gals):	2500		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	001	Install Date:	12/01/1966
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE		
Second Containment:	VAULT		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge, Vent Whistle	Dispenser:	Gravity
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	5000	Renewal Date:	08/08/2001
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/04/1997
Old PBS Number:	Not reported	Expiration Date:	12/30/2001
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

NEW YORK TELEPHONE (Continued) **U001831391**

PBS AST:

PBS Number:	2-044563	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	OTHER		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	New York Telephone		
Owner:	BELL ATLANTIC 221 EAST 37TH STREET NEW YORK, NY 10016		
Owner Phone:	(800) 386-9639		
Facility Phone:	(800) 696-3973		
Operator:	BELL ATLANTIC		
Emergency Name:	BELL ATLANTIC		
Emergency Phone:	(800) 386-9639		
Total Tanks:	2		
Total Capacity:	5000		
Tank ID:	002		
Capacity (Gal):	2500		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	NOS 1,2, OR 4 FUEL OIL		
Tank Type:	Steel/carbon steel		
Install Date:	07/01/1998		
Tank Internal:	NONE		
Tank External:	PAINTED/ASPHALT COATING/NONE		
Tank Containment:	DOUBLED-WALLED TANK/NONE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/NONE		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Dispenser Method:	None		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	BELL ATLANTIC		
Mailing Address:	221 EAST 37TH STREET 4TH FLOOR NEW YORK, NY 10016		
Mailing Contact:	KETHLEEN TOBIN		
Mailing Telephone:	(212) 338-6731		
Owner Mark:	First Owner	Expiration Date:	12/30/2001
Certification Flag:	False	Certification Date:	06/04/1997
Renew Flag:	True	Renew Date:	08/08/2001
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		

NEW YORK TELEPHONE (Continued) **U001831391**

County Code: 62
Region: 2
Fiscal Amount for Registration Fee is Correct: True

E21 **BELL ATLANTIC** **UST U001841980**
ENE **604-628 WEST 43RD STREET** **AST N/A**
< 1/8 **NEW YORK, NY 10036**
612
Higher **Site 5 of 6 in cluster E**

PBS UST:

PBS Number:	2-601561	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BELL ATLANTIC (888) 696-3973		
Emergency Contact:	BELL ATLANTIC (800) 386-9639		
Total Tanks:	4		
Owner:	BELL ATLANTIC 221 E. 37TH ST, 4TH FLOOR NEW YORK, NY 10016 (800) 386-9639		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	BELL ATLANTIC ATTN: KATHLEEN TOBIN 221 EAST 37TH STREET, 4TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Tank Status:	In Service		
Capacity (gals):	2500		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	09/01/1993
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	UNLEADED GASOLINE
Tank Internal:	FIBERGLASS LINER [FRP]	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	FIBERGLASS		
Missing Data for Tank:	No Missing Data		
Pipe External:	FIBERGLASS		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Prot:	High Level Alarm, Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	7775	Renewal Date:	Not reported
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/05/1998
Old PBS Number:	Not reported	Expiration Date:	08/06/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	UTILITY		
Town or City:	NEW YORK CITY		
Town or City Code:	01		

BELL ATLANTIC (Continued) **U001841980**

County Code:	62		
Region:	2		
PBS Number:	2-601561	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BELL ATLANTIC (888) 696-3973		
Emergency Contact:	BELL ATLANTIC (800) 386-9639		
Total Tanks:	4		
Owner:	BELL ATLANTIC 221 E. 37TH ST, 4TH FLOOR NEW YORK, NY 10016 (800) 386-9639		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	BELL ATLANTIC ATTN: KATHLEEN TOBIN 221 EAST 37TH STREET, 4TH FLOOR NEW YORK, NY 10016 (212) 338-7881		
Tank Status:	In Service		
Capacity (gals):	2500		
Tank Location:	UNDERGROUND		
Tank Id:	004	Install Date:	09/01/1993
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	UNLEADED GASOLINE
Tank Internal:	FIBERGLASS LINER [FRP]	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	FIBERGLASS		
Missing Data for Tank:	No Missing Data		
Pipe External:	FIBERGLASS		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING/IN-TANK SYSTEM		
Overfill Prot:	High Level Alarm, Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	7775	Renewal Date:	Not reported
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/05/1998
Old PBS Number:	Not reported	Expiration Date:	08/06/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	UTILITY		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-601561	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BELL ATLANTIC		

BELL ATLANTIC (Continued) **U001841980**

(888) 696-3973
Emergency Contact: BELL ATLANTIC
(800) 386-9639
Total Tanks: 4
Owner: BELL ATLANTIC
221 E. 37TH ST, 4TH FLOOR
NEW YORK, NY 10016
(800) 386-9639
Owner Type: Corporate/Commercial
Owner Mark: First Owner
Owner Subtype: Not reported
Mailing Address: BELL ATLANTIC
ATTN: KATHLEEN TOBIN
221 EAST 37TH STREET, 4TH FLOOR
NEW YORK, NY 10016
(212) 338-7881
Tank Status: In Service
Capacity (gals): 2500
Tank Location: UNDERGROUND
Tank Id: 005 Install Date: 09/01/1993
Tank Type: Fiberglass reinforced plastic [FRP] Product Stored: UNLEADED GASOLINE
Tank Internal: FIBERGLASS LINER [FRP] Pipe Internal: NONE
Pipe Location: Underground Pipe Type: FIBERGLASS [FRP]
Tank External: FIBERGLASS
Missing Data for Tank: No Missing Data
Pipe External: FIBERGLASS
Second Containment: NONE/DOUBLED-WALLED TANK
Leak Detection: INTERSTITIAL MONITORING/IN-TANK SYSTEM
Overfill Prot: High Level Alarm, Product Level Gauge Dispenser: Suction
Date Tested: Not reported Next Test Date: Not reported
Date Closed: Not reported Test Method: Not reported
Deleted: False Updated: True
Dead Letter: False Owner Screen: No data missing
FAMT: Fiscal amount for registration fee is correct
Total Capacity: 7775 Renewal Date: Not reported
Tank Screen: Minor data missing Federal ID: Not reported
Renew Flag: Renwal has not been printed Facility Screen: No data missing
Certification Flag: False Certification Date: 08/05/1998
Old PBS Number: Not reported Expiration Date: 08/06/2003
Inspected Date: Not reported Inspector: Not reported
Inspection Result: Not reported
Lat/long: Not reported
Facility Type: UTILITY
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2

PBS AST:
PBS Number: 2-601561 CBS Number: Not reported
SPDES Number: Not reported SWIS Code: 6201
Federal ID: Not reported Previous PBS#: Not reported
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Type: UTILITY
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Owner: BELL ATLANTIC

BELL ATLANTIC (Continued) **U001841980**

221 E. 37TH ST, 4TH FLOOR
NEW YORK, NY 10016

Owner Phone:	(800) 386-9639		
Facility Phone:	(888) 696-3973		
Operator:	BELL ATLANTIC		
Emergency Name:	BELL ATLANTIC		
Emergency Phone:	(800) 386-9639		
Total Tanks:	4		
Total Capacity:	7775		
Tank ID:	006		
Capacity (Gal):	275		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	USED OIL		
Tank Type:	Stainless steel alloy		
Install Date:	08/01/1993		
Tank Internal:	OTHER		
Tank External:	NONE/JACKETED		
Tank Containment:	NONE/DOUBLED-WALLED TANK		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge, Catch Basin		
Dispenser Method:	Not reported		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	BELL ATLANTIC		
Mailing Address:	221 EAST 37TH STREET, 4TH FLOOR NEW YORK, NY 10016		
Mailing Contact:	KATHLEEN TOBIN		
Mailing Telephone:	(212) 338-7881		
Owner Mark:	First Owner	Expiration Date:	08/06/2003
Certification Flag:	False	Certification Date:	08/05/1998
Renew Flag:	False	Renew Date:	/ /
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	Minor data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

E22 **NEW YORK TELEPHONE CO** **RCRIS-SQG 1000791572**
ENE **604 W 43RD ST** **FINDS NYD987030855**
< 1/8 **NEW YORK, NY 10036**
612
Higher **Site 6 of 6 in cluster E**

NEW YORK TELEPHONE CO (Continued) **1000791572**

RCRIS:
Owner: NEW YORK TELEPHONE CO
(212) 555-1212
Contact: KENNY JAMES
(212) 767-8120
Record Date: 03/15/1993
Classification: Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

F23 **CONSULTATE GENERAL OF P.R.CHINA** **UST** **U002034235**
WSW **520 12TH AVE** **N/A**
1/8-1/4 **NY, NY 10036**
696
Higher **Site 1 of 5 in cluster F**

PBS UST:

PBS Number:	2-601887	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	YANG, JING PING (212) 868-7752		
Emergency Contact:	LI, ZHIEN JIANG (212) 330-7401		
Total Tanks:	2		
Owner:	FOREIN MIN. OF P.R. OF CHINA 520 12TH AVE NY, NY 10036 (212) 330-7401		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	CONSULATE GEN. OF PEOPLES REPUBLIC OF CHINA ATTN: LI,ZHEN JIANG 520 12TH AVE NY, NY 10036 (212) 330-7401		
Tank Status:	In Service		
Capacity (gals):	10000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	High Level Alarm, Product Level Gauge	Dispenser:	Suction

CONSULATE GENERAL OF P.R.CHINA (Continued) **U002034235**

Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	06/07/1999
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	07/30/1999
Old PBS Number:	Not reported	Expiration Date:	06/13/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-601887	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	YANG, JING PING (212) 868-7752		
Emergency Contact:	LI, ZHIEN JIANG (212) 330-7401		
Total Tanks:	2		
Owner:	FOREIN MIN. OF P.R. OF CHINA 520 12TH AVE NY, NY 10036 (212) 330-7401		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	CONSULATE GEN. OF PEOPLES REPUBLIC OF CHINA ATTN: LI,ZHEN JIANG 520 12TH AVE NY, NY 10036 (212) 330-7401		
Tank Status:	In Service		
Capacity (gals):	10000		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	High Level Alarm, Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	20000	Renewal Date:	06/07/1999

CONSULATE GENERAL OF P.R.CHINA (Continued) **U002034235**

Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	07/30/1999
Old PBS Number:	Not reported	Expiration Date:	06/13/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

F24 **EDISON PARKING LOT** **FINDS 1000990443**
WSW **500-516 12TH AVE** **RCRIS-LQG NYR000004028**
1/8-1/4 **NEW YORK, NY 10036** **UST**
752
Higher **Site 2 of 5 in cluster F**

RCRIS:
Owner: SILVERSTEIN PROPERTIES INC
(212) 551-7300

Contact: BRIAN COLLINS
(201) 643-2884

Record Date: 05/02/1995
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

PBS UST:

PBS Number:	2-602201	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BRIAN COLLINS (201) 643-2884		
Emergency Contact:	BRIAN COLLINS (201) 643-2884		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES, INC. 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7300		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	ROSENMON & COLIN ATTN: MR. RICHARD G. LELAND 575 MADISON AVENUE NEW YORK, NY 10022 (212) 940-8700		
Tank Status:	Closed - Removed		

EDISON PARKING LOT (Continued) **1000990443**

Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/VAULT		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	05/01/1995	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	05/02/2000
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-602201	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BRIAN COLLINS (201) 643-2884		
Emergency Contact:	BRIAN COLLINS (201) 643-2884		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES, INC. 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7300		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	ROSENMON & COLIN ATTN: MR. RICHARD G. LELAND 575 MADISON AVENUE NEW YORK, NY 10022 (212) 940-8700		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON

EDISON PARKING LOT (Continued) **1000990443**

Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/VAULT		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	05/01/1995	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	05/02/2000
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-602201	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BRIAN COLLINS (201) 643-2884		
Emergency Contact:	BRIAN COLLINS (201) 643-2884		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES, INC. 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7300		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	ROSENMON & COLIN ATTN: MR. RICHARD G. LELAND 575 MADISON AVENUE NEW YORK, NY 10022 (212) 940-8700		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/VAULT		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction

EDISON PARKING LOT (Continued) **1000990443**

Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	05/01/1995	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	05/02/2000
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-602201	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BRIAN COLLINS (201) 643-2884		
Emergency Contact:	BRIAN COLLINS (201) 643-2884		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES, INC. 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7300		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	ROSENMON & COLIN ATTN: MR. RICHARD G. LELAND 575 MADISON AVENUE NEW YORK, NY 10022 (212) 940-8700		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	004	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/VAULT		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	05/01/1995	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported

EDISON PARKING LOT (Continued) **1000990443**

Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	05/02/2000
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-602201	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BRIAN COLLINS (201) 643-2884		
Emergency Contact:	BRIAN COLLINS (201) 643-2884		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES, INC. 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7300		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	ROSENMON & COLIN ATTN: MR. RICHARD G. LELAND 575 MADISON AVENUE NEW YORK, NY 10022 (212) 940-8700		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	005	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/VAULT		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	05/01/1995	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	05/02/2000
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		

EDISON PARKING LOT (Continued) **1000990443**

Lat/long: Not reported
Facility Type: OTHER
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2

This is the most recent NY PBS data for this site.
The NY PBS database contains 11 additional records for this site.
Please contact your EDR Account Executive for more information.

F25 **SILVERSTEIN 42ND ASSOC.** **LTANKS** **S104275739**
WSW **500-516 12TH AVE** **N/A**
1/8-1/4 **MANHATTAN, NY**
752
Higher **Site 3 of 5 in cluster F**

LTANKS:

Spill Number:	9504838	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MULQUEEN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(212) 940-8700
Spiller:	ROSENMAN & COLIN		
Spiller Address:	575 MADISON AVE NEW YORK, NY 10022-2585		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	07/03/1996		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	07/20/1995 16:00	Reported to Dept:	07/20/1995 16:46
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	07/03/1996
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	08/15/1995
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	-1

SILVERSTEIN 42ND ASSOC. (Continued) **S104275739**

Units:	Gallons	
Unknown Qty Spilled:	-1	
Quantity Recovered:	0	
Unknown Qty Recovered:	False	
Material:	DIESEL	
Class Type:	Petroleum	
Chem Abstract Service Number:		DIESEL
Last Date:		07/28/1994
Num Times Material Entry In File:		10625
Material Class Type:	1	
Quantity Spilled:	0	
Units:	Gallons	
Unknown Qty Spilled:	No	
Quantity Recovered:	0	
Unknown Qty Recovered:	False	
Material:	GASOLINE	
Class Type:	Petroleum	
Chem Abstract Service Number:		GASOLINE
Last Date:		09/29/1994
Num Times Material Entry In File:		21329

DEC Remarks: SITE OF FORMER COAL GASIFICATION PLANT WAS INVESTIGATED BY HAZ. WASTE REM. BUT FOUND NO 371 WASTES. SOILS AROUND USTS WERE STOCKPILED AND REM OVED, GROUNDWATER HAD MINOR AMOUNTS OF BENZENE ALONG NORTH WEST CORNER O F SITE. F T MODEL INDICATES THATT CONCENTRATIONS WILL NOT IMPACT SENSI TIVE RECEPTORS - NFA. 7/16/98 mmm:FILE TRANSFERED TO NYS RECORDS CENT ER BOX 306858.

Spill Cause: SOIL CONTAMINATION/ GROUND WATER CONTAMINATION FOUND DURING TANK REMOVAL FROM MAY 8TH TO MAY 25TH, 1995

F26 **PORT AUTH OF NY NJ 12TH AVE 39** **FINDS 1000390991**
WSW **39TH ST 12TH AVE** **RCRIS-LQG NYD981483290**
1/8-1/4 **NEW YORK, NY 10018**
755
Higher **Site 4 of 5 in cluster F**

RCRIS:
Owner: PORT AUTHORITY OF NY & NJ
(212) 555-1212

Contact: HCONTFIRST HCONTLAST
(201) 348-3573

Record Date: 04/25/1986
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

F27 **SILVERSTEIN PROPERTIES: YALE BUILDING** **UST U003065922**
WSW **460 TWELFTH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
770
Higher **Site 5 of 5 in cluster F**

SILVERSTEIN PROPERTIES: YALE BUILDING (Continued) **U003065922**

PBS UST:

PBS Number:	2-602646	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	JACK PIERSON (212) 695-4463		
Emergency Contact:	JACK PIERSON (212) 695-4463		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7346		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SILVERSTEIN PROPERTIES ATTN: WILLIAM R. DACUNTO, RPA 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7346		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	12/01/1964
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	NONE
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	03/28/2001
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS Number:	2-602646	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	JACK PIERSON (212) 695-4463		
Emergency Contact:	JACK PIERSON		

SILVERSTEIN PROPERTIES: YALE BUILDING (Continued) **U003065922**

(212) 695-4463
Total Tanks: 0
Owner: SILVERSTEIN PROPERTIES
521 FIFTH AVENUE
NEW YORK, NY 10175
(212) 551-7346
Owner Type: Corporate/Commercial
Owner Mark: First Owner
Owner Subtype: Not reported
Mailing Address: SILVERSTEIN PROPERTIES
ATTN: WILLIAM R. DACUNTO, RPA
521 FIFTH AVENUE
NEW YORK, NY 10175
(212) 551-7346
Tank Status: Closed - Removed
Capacity (gals): 550
Tank Location: UNDERGROUND
Tank Id: 002 Install Date: 12/01/1964
Tank Type: Steel/carbon steel Product Stored: DIESEL
Tank Internal: NONE Pipe Internal: NONE
Pipe Location: Aboveground Pipe Type: NONE
Tank External: NONE/SACRIFICIAL ANODE
Missing Data for Tank: No Missing Data
Pipe External: NONE/NONE
Second Containment: NONE/NONE
Leak Detection: NONE/NONE
Overfill Prot: None Dispenser: Suction
Date Tested: Not reported Next Test Date: Not reported
Date Closed: 03/01/1996 Test Method: Not reported
Deleted: False Updated: True
Dead Letter: False Owner Screen: Minor data missing
FAMT: Fiscal amount for registration fee is correct
Total Capacity: 0 Renewal Date: Not reported
Tank Screen: 0 Federal ID: Not reported
Renew Flag: Renwal has not been printed Facility Screen: No data missing
Certification Flag: False Certification Date: Not reported
Old PBS Number: Not reported Expiration Date: 03/28/2001
Inspected Date: Not reported Inspector: Not reported
Inspection Result: Not reported
Lat/long: Not reported
Facility Type: TRUCKING/TRANSPORTATION
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2

PBS Number: 2-602646 CBS Number: Not reported
SPDES Number: Not reported SWIS ID: 6201
Operator: JACK PIERSON
(212) 695-4463
Emergency Contact: JACK PIERSON
(212) 695-4463
Total Tanks: 0
Owner: SILVERSTEIN PROPERTIES
521 FIFTH AVENUE
NEW YORK, NY 10175
(212) 551-7346

SILVERSTEIN PROPERTIES: YALE BUILDING (Continued) **U003065922**

Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SILVERSTEIN PROPERTIES ATTN: WILLIAM R. DACUNTO, RPA 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7346		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	12/01/1964
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	NONE
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	03/28/2001
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-602646	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	JACK PIERSON (212) 695-4463		
Emergency Contact:	JACK PIERSON (212) 695-4463		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7346		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SILVERSTEIN PROPERTIES ATTN: WILLIAM R. DACUNTO, RPA 521 FIFTH AVENUE		

SILVERSTEIN PROPERTIES: YALE BUILDING (Continued) **U003065922**

NEW YORK, NY 10175
(212) 551-7346

Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	004	Install Date:	12/01/1964
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	NONE
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	03/28/2001
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-602646	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	JACK PIERSON (212) 695-4463		
Emergency Contact:	JACK PIERSON (212) 695-4463		
Total Tanks:	0		
Owner:	SILVERSTEIN PROPERTIES 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7346		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SILVERSTEIN PROPERTIES ATTN: WILLIAM R. DACUNTO, RPA 521 FIFTH AVENUE NEW YORK, NY 10175 (212) 551-7346		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	005	Install Date:	12/01/1964

SILVERSTEIN PROPERTIES: YALE BUILDING (Continued) **U003065922**

Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	NONE
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	03/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	03/28/2001
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

This is the most recent NY PBS data for this site.
The NY PBS database contains 9 additional records for this site.
Please contact your EDR Account Executive for more information.

---

28 **CON EDISON - WEST 42ND ST SUB** **FINDS 1000833493**
SE **571 W 41ST ST** **RCRIS-LQG NYD987023892**
1/8-1/4 **NEW YORK, NY 10036**
815
Higher

RCRIS:
Owner: CONSOLIDATED EDISON
(212) 555-1212

Contact: ROBERT KEEGAN
(212) 460-4833

Record Date: 12/16/1992
Classification: Large Quantity Generator, Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

CON EDISON - WEST 42ND ST SUB (Continued) **1000833493**

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

29
South
1/8-1/4
816
Higher

PORT AUTH OF NY NJ 11TH AVE 39 **FINDS** **1000390995**
11TH AVE 39TH ST **RCRIS-LQG** **NYD981483332**
NEW YORK, NY 10018

RCRIS:
Owner: PORT AUTHORITY OF NY & NJ
(212) 555-1212

Contact: HCONTFIRST CALO
(201) 348-3573

Record Date: 04/25/1986
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Biennial Reporting System (BRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

G30
ENE
1/8-1/4
859
Higher

CONSOLIDATED GAS WORKS **Coal Gas** **G000000364**
589-625 ELEVENTH AVE. **N/A**
NEW YORK, NY 10036

Site 1 of 2 in cluster G

COAL GAS SITE DESCRIPTION:
Site is on the western side of 11th Ave., between 44th St. and 46th St. Site extends to 12th Ave. (B17)

©Copyright 1993 Real Property Scan, Inc.

31
NW
1/8-1/4
883
Higher

CIRCLE LINE **RCRIS-SQG** **1000871471**
PIER 83 43RD ST **FINDS** **NY0000055616**
NEW YORK, NY 10036

CIRCLE LINE (Continued) **1000871471**

RCRIS:
Owner: CIRCLE LINE SIGHTSEEING
(212) 555-1212

Contact: DOUG FEDDER
(212) 630-8117

Record Date: 11/17/1993
Classification: Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

G32 **DEMARCO JOSEPH E** **RCRIS-SQG 1000554867**
ENE **595 11TH AVE** **FINDS NYD986973568**
1/8-1/4 **NEW YORK, NY 10036**
923
Higher **Site 2 of 2 in cluster G**

RCRIS:
Owner: JOSEPH E DEMARCO
(212) 315-3350

Contact: JOSEP E DEMARCO
(212) 315-3350

Record Date: 10/15/1991
Classification: Conditionally Exempt Small Quantity Generator, Hazardous Waste Transporter
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

H33 **RIVERBANK WEST** **UST U001840846**
East **560 WEST 43RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10019**
950
Higher **Site 1 of 2 in cluster H**

PBS UST:

PBS Number:	2-477419	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	MARNI BERK (212) 629-5990		
Emergency Contact:	SCOTT WARSHAW (212) 265-5900		
Total Tanks:	2		

RIVERBANK WEST (Continued) **U001840846**

Owner:	MASS MUTUA LIFE INSURANCE CO. 142 WEST 57TH STREET - 15TH FLOOR NEW YORK, NY 10019 (212) 265-5990		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MANHATTAN PACIFIC MGNT CO, INC. ATTN: SCOTT WARSHAW 142 WEST 57TH STREET - 15TH FL NEW YORK, NY 10019 (212) 265-5990		
Tank Status:	In Service		
Capacity (gals):	15000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	08/01/1986
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	08/01/2001
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	False
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	30000	Renewal Date:	08/12/1999
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	09/25/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	APARTMENT BUILDING		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-477419	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	MARNI BERK (212) 629-5990		
Emergency Contact:	SCOTT WARSHAW (212) 265-5900		
Total Tanks:	2		
Owner:	MASS MUTUA LIFE INSURANCE CO. 142 WEST 57TH STREET - 15TH FLOOR NEW YORK, NY 10019 (212) 265-5990		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		

RIVERBANK WEST (Continued) **U001840846**

Owner Subtype:	Not reported		
Mailing Address:	MANHATTAN PACIFIC MGNT CO, INC. ATTN: SCOTT WARSHAW 142 WEST 57TH STREET - 15TH FL NEW YORK, NY 10019 (212) 265-5990		
Tank Status:	In Service		
Capacity (gals):	15000		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	08/01/1986
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	08/01/2001
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	False
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	30000	Renewal Date:	08/12/1999
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/29/1999
Old PBS Number:	Not reported	Expiration Date:	09/25/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	APARTMENT BUILDING		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

I34 **612 W 45TH ST/UPS** **LTANKS** **S102671711**
NE **612 W 45TH ST** **N/A**
1/8-1/4 **NYC, NY**
1034
Higher **Site 1 of 6 in cluster I**

LTANKS:

Spill Number:	9104075	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	SULLIVAN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UPS		
Spiller Address:	643 W 43RD ST NY, NY 10036		
Spill Class:	Known release that creates a file or hazard. (Highly Improbable)		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Overfill	Resource Affected:	On Land

612 W 45TH ST/UPS (Continued) **S102671711**

Water Affected: Not reported
Spill Notifier: Other
Spill Date: 07/15/1991 16:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/16/1995
Is Updated: False
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 07/16/1991 13:59
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/17/1991
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: DISCOVERED CONTAMINATED SOIL WHILE REMOVING 12 550 GAL TANKS. 2 HAD VISIBLE CORROSION LEAKS. SOIL BEING STOCKPILED AND SAMPLED FOR DISPOSAL SITE

I35 **UNITED PARCEL SERVICE** **UST U001330111**
NE **612 WEST 45TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
1034
Higher **Site 2 of 6 in cluster I**

PBS UST:
PBS Number: 2-601418
SPDES Number: Not reported
Operator: TOM SAVAGE
(212) 631-6446
Emergency Contact: PAUL MCDONALD
(212) 631-6444
Total Tanks: 2
Owner: NUBEE INC.
643 WEST 43RD STREET
NEW YORK, NY 10036
(212) 631-6446
Owner Type: Not reported
CBS Number: Not reported
SWIS ID: 6201

UNITED PARCEL SERVICE (Continued) **U001330111**

Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	UNITED PARCEL SERVICE ATTN: FACILITY ENGINEER 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6446		
Tank Status:	In Service		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	01/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	FIBERGLASS LINER [FRP]
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	FIBERGLASS		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Prot:	High Level Alarm	Dispenser:	Submersible
Date Tested:	04/01/1999	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	TANKOLOGY [VACUTECT]
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	8000	Renewal Date:	01/02/1998
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/25/1999
Old PBS Number:	Not reported	Expiration Date:	03/31/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-601418	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	TOM SAVAGE (212) 631-6446		
Emergency Contact:	PAUL MCDONALD (212) 631-6444		
Total Tanks:	2		
Owner:	NUBEE INC. 643 WEST 43RD STREET NEW YORK, NY 10036 (212) 631-6446		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	UNITED PARCEL SERVICE ATTN: FACILITY ENGINEER 643 WEST 43RD STREET NEW YORK, NY 10036		

UNITED PARCEL SERVICE (Continued) **U001330111**

(212) 631-6446

Tank Status:	In Service		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	01/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	FIBERGLASS LINER [FRP]
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Tank External:	SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	FIBERGLASS		
Second Containment:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Prot:	High Level Alarm	Dispenser:	Submersible
Date Tested:	04/01/1999	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	TANKOLOGY [VACUTECT]
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	8000	Renewal Date:	01/02/1998
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	06/25/1999
Old PBS Number:	Not reported	Expiration Date:	03/31/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

J36 **TRAILWAYS INC** **FINDS 1000254768**
SE **544 W 41ST ST** **RCRIS-LQG NYD981483514**
1/8-1/4 **NEW YORK, NY 10036**
1036
Higher **Site 1 of 3 in cluster J**

RCRIS:

Owner: TRAILWAYS INC
(212) 555-1212

Contact: BUD BUSBY
(201) 656-3440

Record Date: 04/30/1986
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

TRAILWAYS INC (Continued) **1000254768**

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

H37 **MERCHANDISING WORKSHOP INC** **UST U000404667**
East **550 W 43RD ST** **N/A**
1/8-1/4 **NY, NY 10036**
1036
Higher **Site 2 of 2 in cluster H**

PBS UST:

PBS Number:	2-370258	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BARNEY GORGONE (212) 239-4646		
Emergency Contact:	NORMAN ALSHOOLER PRESIDENT (212) 490-1046		
Total Tanks:	1		
Owner:	MERCHANDISING WORKSHOP INC 550 W 43RD ST NY, NY 10036 (212) 239-4646		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MERCHANDISING WORKSHOP INC 550 W 43RD ST NY, NY 10036 (212) 239-4646		
Tank Status:	In Service		
Capacity (gals):	7500		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	False
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	7500	Renewal Date:	12/02/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	01/16/1998
Old PBS Number:	Not reported	Expiration Date:	02/03/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		

MERCHANDISING WORKSHOP INC (Continued) **U000404667**

Town or City Code: 01
County Code: 62
Region: 2

I38 **KELLERMANN PAINT CO INC** **RCRIS-SQG 1000281117**
NE **605 W 45TH ST** **FINDS NYD001641828**
1/8-1/4 **NEW YORK, NY 10036**
1056
Higher **Site 3 of 6 in cluster I**

RCRIS:
Owner: Not reported
Contact: GEORGE KELLERMANN
(212) 265-5036
Record Date: 07/09/1980
Classification: Small Quantity Generator, Hazardous Waste Transporter
Used Oil Recyc: No
Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

J39 **MERCEDES/BENZ MANHATTAN INC** **UST U003074760**
SE **536 W 41 ST** **AST N/A**
1/8-1/4 **NEW YORK, NY 10036**
1080
Higher **Site 2 of 3 in cluster J**

PBS UST:

PBS Number:	2-426962	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	MR. STEPHAN ALTRICHTER (212) 629-1606		
Emergency Contact:	MR. MICHAEL KEENAN (212) 629-1600		
Total Tanks:	3		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 760-0600		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MERCEDES/BENZ MANHATTAN INC ATTN: MR. THOM LOPEZ 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 629-1612		
Tank Status:	Closed - Removed		
Capacity (gals):	1100		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported

MERCEDES/BENZ MANHATTAN INC (Continued) **U003074760**

Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	4500	Renewal Date:	09/29/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/15/1999
Old PBS Number:	Not reported	Expiration Date:	12/14/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS Number:	2-426962	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	MR. STEPHAN ALTRICHTER (212) 629-1606		
Emergency Contact:	MR. MICHAEL KEENAN (212) 629-1600		
Total Tanks:	3		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 760-0600		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MERCEDES/BENZ MANHATTAN INC ATTN: MR. THOM LOPEZ 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 629-1612		
Tank Status:	Closed - Removed		
Capacity (gals):	1100		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	OTHER
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		

MERCEDES/BENZ MANHATTAN INC (Continued) **U003074760**

Second Containment:	VAULT		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	4500	Renewal Date:	09/29/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/15/1999
Old PBS Number:	Not reported	Expiration Date:	12/14/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-426962	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	MR. STEPHAN ALTRICHTER (212) 629-1606		
Emergency Contact:	MR. MICHAEL KEENAN (212) 629-1600		
Total Tanks:	3		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 760-0600		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MERCEDES/BENZ MANHATTAN INC ATTN: MR. THOM LOPEZ 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 629-1612		
Tank Status:	Closed - Removed		
Capacity (gals):	1100		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	003	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	OTHER
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	EXCAVATION LINER		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True

MERCEDES/BENZ MANHATTAN INC (Continued) **U003074760**

Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	4500	Renewal Date:	09/29/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/15/1999
Old PBS Number:	Not reported	Expiration Date:	12/14/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS AST:

PBS Number:	2-426962	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	OTHER		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036		
Owner Phone:	(212) 760-0600		
Facility Phone:	(212) 629-1606		
Operator:	MR. STEPHAN ALTRICHTER		
Emergency Name:	MR. MICHAEL KEENAN		
Emergency Phone:	(212) 629-1600		
Total Tanks:	3		
Total Capacity:	4500		
Tank ID:	001		
Capacity (Gal):	2000		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	OTHER		
Tank Type:	Steel/carbon steel		
Install Date:	04/01/1991		
Tank Internal:	Not reported		
Tank External:	Not reported		
Tank Containment:	CONCRETE DIKE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Not reported		
Pipe Internal:	Not reported		
Pipe External:	Not reported		
Leak Detection:	OTHER		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Submersible		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	MERCEDES/BENZ MANHATTAN INC		

MERCEDES/BENZ MANHATTAN INC (Continued) **U003074760**

Mailing Address:	536 WEST 41ST STREET NEW YORK, NY 10036		
Mailing Contact:	MR. THOM LOPEZ		
Mailing Telephone:	(212) 629-1612		
Owner Mark:	First Owner	Expiration Date:	12/14/2002
Certification Flag:	False	Certification Date:	10/15/1999
Renew Flag:	True	Renew Date:	09/29/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	Minor data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-426962	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	OTHER		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036		
Owner Phone:	(212) 760-0600		
Facility Phone:	(212) 629-1606		
Operator:	MR. STEPHAN ALTRICHTER		
Emergency Name:	MR. MICHAEL KEENAN		
Emergency Phone:	(212) 629-1600		
Total Tanks:	3		
Total Capacity:	4500		
Tank ID:	002		
Capacity (Gal):	2000		
Missing Data for Tank :	Minor data missing		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Product Stored:	OTHER		
Tank Type:	Steel/carbon steel		
Install Date:	04/01/1991		
Tank Internal:	Not reported		
Tank External:	Not reported		
Tank Containment:	CONCRETE DIKE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Not reported		
Pipe Internal:	Not reported		
Pipe External:	Not reported		
Leak Detection:	OTHER		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported

MERCEDES/BENZ MANHATTAN INC (Continued) **U003074760**

Result of Inspection:	Not reported		
Mailing Name:	MERCEDES/BENZ MANHATTAN INC		
Mailing Address:	536 WEST 41ST STREET NEW YORK, NY 10036		
Mailing Contact:	MR. THOM LOPEZ		
Mailing Telephone:	(212) 629-1612		
Owner Mark:	First Owner	Expiration Date:	12/14/2002
Certification Flag:	False	Certification Date:	10/15/1999
Renew Flag:	True	Renew Date:	09/29/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	Minor data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-426962	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	OTHER		
Owner Type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036		
Owner Phone:	(212) 760-0600		
Facility Phone:	(212) 629-1606		
Operator:	MR. STEPHAN ALTRICHTER		
Emergency Name:	MR. MICHAEL KEENAN		
Emergency Phone:	(212) 629-1600		
Total Tanks:	3		
Total Capacity:	4500		
Tank ID:	003		
Capacity (Gal):	500		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	LUBE OIL		
Tank Type:	Steel/carbon steel		
Install Date:	02/01/1991		
Tank Internal:	NONE		
Tank External:	NONE		
Tank Containment:	NONE/CONCRETE DIKE		
Pipe Type:	STEEL/IRON		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Leak Detection:	OTHER		
Overfill Protection:	Product Level Gauge		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported

MERCEDES/BENZ MANHATTAN INC (Continued) **U003074760**

Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	MERCEDES/BENZ MANHATTAN INC		
Mailing Address:	536 WEST 41ST STREET NEW YORK, NY 10036		
Mailing Contact:	MR. THOM LOPEZ		
Mailing Telephone:	(212) 629-1612		
Owner Mark:	First Owner	Expiration Date:	12/14/2002
Certification Flag:	False	Certification Date:	10/15/1999
Renew Flag:	True	Renew Date:	09/29/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	Minor data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

I40 **SWING TIME LLC CORP.** **UST** **U003697798**
NE **609 11TH AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
1097
Higher **Site 4 of 6 in cluster I**

PBS UST:

PBS Number:	2-604187	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6101
Operator:	ROBERT GANS (212) 246-9090		
Emergency Contact:	ROBERT GANS (212) 272-9494		
Total Tanks:	0		
Owner:	ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SWING TINE LLC, CORP ATTN: ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	None	Pipe Type:	NONE
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		

SWING TIME LLC CORP. (Continued) **U003697798**

Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	None
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	07/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	True	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	08/09/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	61		
Region:	2		
PBS Number:	2-604187	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6101
Operator:	ROBERT GANS (212) 246-9090		
Emergency Contact:	ROBERT GANS (212) 272-9494		
Total Tanks:	0		
Owner:	ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SWING TINE LLC, CORP ATTN: ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	None	Pipe Type:	NONE
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	None
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	07/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	True	Owner Screen:	Minor data missing

SWING TIME LLC CORP. (Continued) **U003697798**

FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	08/09/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	61		
Region:	2		
PBS Number:	2-604187	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6101
Operator:	ROBERT GANS (212) 246-9090		
Emergency Contact:	ROBERT GANS (212) 272-9494		
Total Tanks:	0		
Owner:	ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SWING TINE LLC, CORP ATTN: ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	None	Pipe Type:	NONE
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	None
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	07/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	True	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	08/09/2004

SWING TIME LLC CORP. (Continued) **U003697798**

Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	61		
Region:	2		
PBS Number:	2-604187	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6101
Operator:	ROBERT GANS (212) 246-9090		
Emergency Contact:	ROBERT GANS (212) 272-9494		
Total Tanks:	0		
Owner:	ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SWING TINE LLC, CORP ATTN: ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	004	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	None	Pipe Type:	NONE
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	None
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	07/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	True	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	08/09/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		

SWING TIME LLC CORP. (Continued) **U003697798**

County Code:	61		
Region:	2		
PBS Number:	2-604187	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6101
Operator:	ROBERT GANS (212) 246-9090		
Emergency Contact:	ROBERT GANS (212) 272-9494		
Total Tanks:	0		
Owner:	ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Owner Type:	Not reported		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	SWING TINE LLC, CORP ATTN: ROBERT GANS 609 11TH AVENUE NEW YORK, NY 10036 (212) 272-9494		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	005	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	None	Pipe Type:	NONE
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	None
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	07/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	True	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	08/09/2004
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	61		
Region:	2		

SWING TIME LLC CORP. (Continued) **U003697798**

This is the most recent NY PBS data for this site.
The NY PBS database contains 5 additional records for this site.
Please contact your EDR Account Executive for more information.

I41 **MILLER-GERALDI INC** **FINDS** **1000281064**
NE **609 11TH AVE** **RCRIS-LQG** **NYD012149340**
1/8-1/4 **NEW YORK, NY 10036**
1097
Higher **Site 5 of 6 in cluster I**

RCRIS:
Owner: SUN OIL COMPANY OF PENNSYLVANIA
(212) 555-1212

Contact: HOWARD ALGEO
(215) 688-8200

Record Date: 08/18/1980
Classification: Large Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

J42 **MERCEDES-BENZ MANHATTAN INC** **FINDS** **1000168670**
SE **528 W 41ST ST** **RCRIS-LQG** **NYD981138472**
1/8-1/4 **NEW YORK, NY 10036**
1112
Higher **Site 3 of 3 in cluster J**

RCRIS:
Owner: Not reported

Contact: WILLIE KRAUSE
(212) 760-0678

Record Date: 10/15/1985
Classification: Large Quantity Generator, Small Quantity Generator
Used Oil Recyc: No

Violation Status: Violations exist

Regulation Violated:	Not reported
Area of Violation:	Generator-All Requirements
Date Violation Determined:	08/26/1994
Priority of Violation:	Low
Schedule Date to Achieve Compliance:	09/26/1994
Actual Date Achieved Compliance:	10/11/1994
Enforcement Action:	Written Informal
Enforcement Action Date:	08/26/1994
Proposed Monetary Penalty:	Not reported
Final Monetary Penalty:	Not reported
Regulation Violated:	Not reported
Area of Violation:	Generator-Land Ban Requirements
Date Violation Determined:	08/26/1994

MERCEDES-BENZ MANHATTAN INC (Continued) **1000168670**

Priority of Violation:	Low
Schedule Date to Achieve Compliance:	09/26/1994
Actual Date Achieved Compliance:	10/11/1994
Enforcement Action:	Written Informal
Enforcement Action Date:	08/26/1994
Proposed Monetary Penalty:	Not reported
Final Monetary Penalty:	Not reported

There are 2 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Compliance Evaluation Inspection (CEI)	Generator-All Requirements	10/11/1994
	Generator-Land Ban Requirements	10/11/1994

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

K43 East 1/8-1/4 1124 Higher **43RD PARKING CORP** **UST U000399370**
541 W 43 ST **N/A**
NY, NY 10036

Site 1 of 4 in cluster K

PBS UST:

PBS Number:	2-296473	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	43-44 MGT (212) 643-2062		
Emergency Contact:	GAUY SPINDLA (212) 643-8631		
Total Tanks:	2		
Owner:	43RD PARKING CORP 541 W 43 ST NY, NY 10036 (212) 643-2062		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	43RD PARKING CORP 541 W 43 ST NY, NY 10036 (212) 643-2062		
Tank Status:	Temporarily Out of Service		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	OTHER		
Leak Detection:	NONE		

43RD PARKING CORP (Continued) **U000399370**

Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	12/27/1987
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	8000	Renewal Date:	06/11/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	12/01/2000
Old PBS Number:	Not reported	Expiration Date:	07/07/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-296473	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	43-44 MGT (212) 643-2062		
Emergency Contact:	GAUY SPINDLA (212) 643-8631		
Total Tanks:	2		
Owner:	43RD PARKING CORP 541 W 43 ST NY, NY 10036 (212) 643-2062		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	43RD PARKING CORP 541 W 43 ST NY, NY 10036 (212) 643-2062		
Tank Status:	Temporarily Out of Service		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	OTHER		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	12/27/1987
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	8000	Renewal Date:	06/11/1997

43RD PARKING CORP (Continued) **U000399370**

Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	12/01/2000
Old PBS Number:	Not reported	Expiration Date:	07/07/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

K44 **MARVIN MITHELL** **UST** **U003418632**
East **541 WEST 43RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
1124
Higher **Site 2 of 4 in cluster K**

PBS UST:

PBS Number:	2-603858	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	GARY SPINDLER (212) 643-2062		
Emergency Contact:	MARVIN MITCHEL (212) 362-4455		
Total Tanks:	0		
Owner:	MARVIN MITCHELL 157 CONGRESS STREET BROOKLYN, NY 11201 (718) 624-3859		
Owner Type:	Private Resident		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MARVIN MITCHELL ATTN: MARVIN MITCHELL 2112 BROADWAY #413 NEW YORK, NY 10023 (212) 362-4455		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	GALVANIZED STEEL
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	01/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported

MARVIN MITHELL (Continued) **U003418632**

Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	12/29/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	Not reported		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-603858	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	GARY SPINDLER (212) 643-2062		
Emergency Contact:	MARVIN MITCHEL (212) 362-4455		
Total Tanks:	0		
Owner:	MARVIN MITCHELL 157 CONGRESS STREET BROOKLYN, NY 11201 (718) 624-3859		
Owner Type:	Private Resident		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MARVIN MITCHELL ATTN: MARVIN MITCHELL 2112 BROADWAY #413 NEW YORK, NY 10023 (212) 362-4455		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	GALVANIZED STEEL
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	01/01/1999	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	Minor data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	12/29/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		

MARVIN MITHELL (Continued) **U003418632**

Facility Type: Not reported
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2

I45 **609-611 11TH ST** **LTANKS** **S101509072**
NE **611 11TH AVENUE** **N/A**
1/8-1/4 **MANHATTAN, NY**
1127
Higher **Site 6 of 6 in cluster I**

LTANKS:

Spill Number:	9501693	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TIBBE	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	Not reported		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	05/09/1995 11:00	Reported to Dept:	05/10/1995 11:28
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/16/1995
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/18/1995
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Gallons
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum

609-611 11TH ST (Continued) **S101509072**

Chem Abstract Service Number:		GASOLINE
Last Date:		09/29/1994
Num Times Material Entry In File:		21329
Material Class Type:	1	
Quantity Spilled:	0	
Units:	Not reported	
Unknown Qty Spilled:	No	
Quantity Recovered:	0	
Unknown Qty Recovered:	False	
Material:	WASTE OIL	
Class Type:	Petroleum	
Chem Abstract Service Number:		WASTE OIL
Last Date:		09/27/1994
Num Times Material Entry In File:		9509

DEC Remarks: Not reported
Spill Cause: ENVIRONMENTAL SITE STUDY DONE - GROUND CONTAMINATION FOUND RESULTING FRO M TANK LEAKING. PROPERTY IS ABANDONED GAS STATION. 10TH AVE CORP. O WNER ISAAC GATWEN, 18 WOODHAVEN, NEW YORK CITY

L46 **MY PRINT CO LIMIT** **RCRIS-SQG 1001090372**
NNE **711 12TH AVE PIER 88** **FINDS NYR000022095**
1/8-1/4 **NEW YORK, NY 10019**
1213
Higher **Site 1 of 3 in cluster L**

RCRIS:
Owner: MY PRINT CO
(212) 555-1212

Contact: JEFF DUTZLER
(516) 832-7095

Record Date: 04/11/1996
Classification: Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

L47 **A G F A DIV OF BAYER CORP** **RCRIS-SQG 1001119664**
NNE **711 12TH AVE PIER 92** **FINDS NYR000029546**
1/8-1/4 **NEW YORK, NY 10019**
1213
Higher **Site 2 of 3 in cluster L**

A G F A DIV OF BAYER CORP (Continued) **1001119664**

RCRIS:
Owner: THE PORT AUTHORITY OF NY & NJ
(201) 216-2966
Contact: ELENA POWER
(508) 658-5600
Record Date: 09/23/1996
Classification: Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

L48 **711 12TH AVE/MANHATTAN** **LTANKS** **S100167579**
NNE **711 12TH AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
1213
Higher **Site 3 of 3 in cluster L**

LTANKS:

Spill Number:	8804962	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	BATTISTA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NYC/PORT AUTH. OF NY/NJ		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	2-365874
Spill Date:	09/07/1988 15:00	Reported to Dept:	09/07/1988 16:07
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	11/27/1992
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	09/08/1988
Date Region Sent Summary to Central Office:	Not reported

Tank Test:
PBS Number: Not reported

711 12TH AVE/MANHATTAN (Continued) **S100167579**

Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: #4 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #4 FUEL OIL
Last Date: 12/05/1994
Num Times Material Entry In File: 1751
DEC Remarks: Not reported
Spill Cause: 7.5K TANK SYSTEM FAILED HORNER EZY WITH A LEAK RATE OF .07996GPH, LEAKIS POSSIBLY FROM ABOVEGROUND PIPING, TO PUMP TANK AND INVESTIGATE.

K49 **FDNY RESCUE 1** **LTANKS** **S102660118**
East **530 WEST 43RD ST** **N/A**
1/8-1/4 **MANHATTEN, NY**
1213
Higher **Site 3 of 4 in cluster K**

LTANKS:
Spill Number: 9706580
Facility Contact: TONY MARINO
Investigator: KRIMGOLD
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: TONY MARINO
Spiller: NYC DEPT OF DESIGN/CONSTR
Spiller Address: 30-30 THOMPSON AV 5TH FL
LONG ISLAND CITY, NY 11101
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 07/06/1999
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 09/02/1997 14:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/06/1999
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/02/1997
Date Region Sent Summary to Central Office: Not reported
Region of Spill: 2
Facility Tele: (718) 391-1062
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (718) 391-1062
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 09/02/1997 14:36

FDNY RESCUE 1 (Continued) **S102660118**

Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: DIESEL
Class Type: Petroleum
Chem Abstract Service Number: DIESEL
Last Date: 07/28/1994
Num Times Material Entry In File: 10625
DEC Remarks: URS performed investigation. No further action required.
Spill Cause: SAMPLES FOUND CONTAMINATED SOIL ON SITE

K50 **F.D.N.Y.-RESCUE CO. 1** **UST U003178521**
East **530 WEST 43RD STREET** **AST N/A**
1/8-1/4 **NEW YORK, NY 10036**
1213
Higher **Site 4 of 4 in cluster K**

PBS UST:
PBS Number: 2-600574
SPDES Number: Not reported
Operator: COMPANY OFFICER
(212) 570-4204
Emergency Contact: F.D.N.Y.
(718) 403-1580
Total Tanks: 2
Owner: F.D.N.Y.
250 LIVINGSTON STREET
BROOKLYN, NY 11201
(718) 403-1580
Owner Type: Local Government
Owner Mark: First Owner
Owner Subtype: Not reported
Mailing Address: F.D.N.Y.
250 LIVINGSTON STREET
BROOKLYN, NY 11201
(718) 403-4202
Tank Status: Closed - In Place
Capacity (gals): 500
Tank Location: UNDERGROUND
Tank Id: 001
Tank Type: Steel/carbon steel
Tank Internal: NONE
Pipe Location: Aboveground
Tank External: NONE/SACRIFICIAL ANODE
Missing Data for Tank: No Missing Data
Pipe External: FIBERGLASS/JACKETED
Second Containment: NONE/VAULT
Leak Detection: NONE/IN-TANK SYSTEM

CBS Number: Not reported
SWIS ID: 6201
Install Date: 12/01/1989
Product Stored: DIESEL
Pipe Internal: NONE
Pipe Type: GALVANIZED STEEL

F.D.N.Y.-RESCUE CO. 1 (Continued) **U003178521**

Overfill Prot:	High Level Alarm, Vent Whistle	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	1100	Renewal Date:	04/25/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	12/27/1991
Old PBS Number:	Not reported	Expiration Date:	12/27/1996
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-600574	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	COMPANY OFFICER (212) 570-4204		
Emergency Contact:	F.D.N.Y. (718) 403-1580		
Total Tanks:	2		
Owner:	F.D.N.Y. 250 LIVINGSTON STREET BROOKLYN, NY 11201 (718) 403-1580		
Owner Type:	Local Government		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	F.D.N.Y. 250 LIVINGSTON STREET BROOKLYN, NY 11201 (718) 403-4202		
Tank Status:	Closed - In Place		
Capacity (gals):	500		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	12/01/1989
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	GALVANIZED STEEL
Tank External:	NONE/SACRIFICIAL ANODE		
Missing Data for Tank:	No Missing Data		
Pipe External:	FIBERGLASS/JACKETED		
Second Containment:	NONE/VAULT		
Leak Detection:	NONE/IN-TANK SYSTEM		
Overfill Prot:	High Level Alarm	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	11/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	1100	Renewal Date:	04/25/1997

F.D.N.Y.-RESCUE CO. 1 (Continued) **U003178521**

Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	12/27/1991
Old PBS Number:	Not reported	Expiration Date:	12/27/1996
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS AST:

PBS Number:	2-600574	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	OTHER		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	F.D.N.Y. 250 LIVINGSTON STREET BROOKLYN, NY 11201		
Owner Phone:	(718) 403-1580		
Facility Phone:	(212) 570-4204		
Operator:	COMPANY OFFICER		
Emergency Name:	F.D.N.Y.		
Emergency Phone:	(718) 403-1580		
Total Tanks:	2		
Total Capacity:	1100		
Tank ID:	003		
Capacity (Gal):	550		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1996		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/OTHER		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/INTERSTITIAL MONITORING		
Overfill Protection:	High Level Alarm		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	F.D.N.Y.		
Mailing Address:	250 LIVINGSTON STREET BROOKLYN, NY 11201		
Mailing Contact:	Not reported		

F.D.N.Y.-RESCUE CO. 1 (Continued) **U003178521**

Mailing Telephone:	(718) 403-4202		
Owner Mark:	First Owner	Expiration Date:	12/27/1996
Certification Flag:	False	Certification Date:	12/27/1991
Renew Flag:	True	Renew Date:	04/25/1997
Lat/Long:	Not reported		
Dead Letter:	False		
Facility Screen:	No data missing		
Owner Screen:	No data missing		
Tank Screen:	No data missing		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

Fiscal Amount for Registration Fee is Correct: True

PBS Number:	2-600574	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS Code:	6201
Federal ID:	Not reported	Previous PBS#:	Not reported
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.		
Facility Type:	OTHER		
Owner Type:	Local Government		
Owner Sub Type:	Not reported		
Owner:	F.D.N.Y. 250 LIVINGSTON STREET BROOKLYN, NY 11201		
Owner Phone:	(718) 403-1580		
Facility Phone:	(212) 570-4204		
Operator:	COMPANY OFFICER		
Emergency Name:	F.D.N.Y.		
Emergency Phone:	(718) 403-1580		
Total Tanks:	2		
Total Capacity:	1100		
Tank ID:	004		
Capacity (Gal):	550		
Missing Data for Tank :	No data missing		
Tank Location:	ABOVEGROUND		
Product Stored:	DIESEL		
Tank Type:	Steel/carbon steel		
Install Date:	12/01/1996		
Tank Internal:	NONE		
Tank External:	NONE/PAINTED/ASPHALT COATING		
Tank Containment:	NONE/OTHER		
Pipe Type:	GALVANIZED STEEL		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE/PAINTED/ASPHALT COATING		
Leak Detection:	NONE/INTERSTITIAL MONITORING		
Overfill Protection:	High Level Alarm		
Dispenser Method:	Suction		
Date Tested:	/ /	Next Test Date:	/ /
Date Closed:	/ /	Test Method:	Not reported
Updated:	True	Deleted:	False
Date Inspected:	Not reported	Inspector:	Not reported
Result of Inspection:	Not reported		
Mailing Name:	F.D.N.Y.		
Mailing Address:	250 LIVINGSTON STREET		

F.D.N.Y.-RESCUE CO. 1 (Continued) **U003178521**

BROOKLYN, NY 11201
Mailing Contact: Not reported
Mailing Telephone: (718) 403-4202
Owner Mark: First Owner
Certification Flag: False
Renew Flag: True
Lat/Long: Not reported
Dead Letter: False
Facility Screen: No data missing
Owner Screen: No data missing
Tank Screen: No data missing
Town or City: NEW YORK CITY
Town or City Code: 01
County Code: 62
Region: 2
Fiscal Amount for Registration Fee is Correct: True

Expiration Date: 12/27/1996
Certification Date: 12/27/1991
Renew Date: 04/25/1997

---

51 North 1/8-1/4 1245 Higher **PIER 90/MANHATTAN** **LTANKS S100145208**
PIER 90 **N/A**
NEW YORK, NY

LTANKS:
Spill Number: 8804853
Facility Contact: Not reported
Investigator: SIGONA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: Not reported
Spiller Address: Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/14/1994
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 09/01/1988 16:00
Cleanup Ceased: 11/14/1994
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/15/1994
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/02/1988
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0

Region of Spill: 2
Facility Tele: Not reported
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 09/01/1988 16:38

PIER 90/MANHATTAN (Continued) **S100145208**

Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: #4 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #4 FUEL OIL
Last Date: 12/05/1994
Num Times Material Entry In File: 1751
DEC Remarks: Not reported
Spill Cause: 7.5K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK.

M52 **AMERICAN RED CROSS EMERGENCY FAM. CENTER** **UST** **U001837881**
SE **515 WEST 41ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
1257
Higher **Site 1 of 2 in cluster M**

PBS UST:

PBS Number:	2-407216	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	AMERICAN RED CROSS (212) 714-2870		
Emergency Contact:	HERMINE E. BOWENS (212) 714-2870		
Total Tanks:	1		
Owner:	FICO REALTY C/O WELLINGTON HOTEL 871 7TH NEW YORK, NY 10019 (212) 714-2870		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	AMERICAN RED CROSS ATTN: CHAPTER DIRECTOR 515 WEST 41ST STREET NEW YORK, NY 10019 (212) 714-2870		
Tank Status:	In Service		
Capacity (gals):	10000		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	GROUNDWATER WELL		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True

AMERICAN RED CROSS EMERGENCY FAM. CENTER (Continued) **U001837881**

Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	10000	Renewal Date:	09/29/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	07/20/2001
Old PBS Number:	Not reported	Expiration Date:	12/14/2007
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

53 South 1/8-1/4 1261 Higher

I&G EXPRESS INC. **UST** **U003749734**
456 11TH AVENUE **N/A**
NEW YORK, NY 10018

PBS UST:

PBS Number:	2-604710	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	ARI ZUBLI (212) 695-6262		
Emergency Contact:	ARI ZUBLI (212) 695-6262		
Total Tanks:	0		
Owner:	U&I REALTY INC. 456 11TH AVENUE NEW YORK, NY 10018 (212) 695-6262		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	GUARDIAN BROKERAGE ATTN: ARI ZUBLI PO BOX 2009 GREAT NECK, NY 11022 (212) 695-6262		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	1	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	Not reported	Dispenser:	Not reported
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	09/01/2000	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing

I&G EXPRESS INC. (Continued) **U003749734**

FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	10/02/2005
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-604710	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	ARI ZUBLI (212) 695-6262		
Emergency Contact:	ARI ZUBLI (212) 695-6262		
Total Tanks:	0		
Owner:	U&I REALTY INC. 456 11TH AVENUE NEW YORK, NY 10018 (212) 695-6262		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	GUARDIAN BROKERAGE ATTN: ARI ZUBLI PO BOX 2009 GREAT NECK, NY 11022 (212) 695-6262		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	2	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	Not reported	Dispenser:	Not reported
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	09/01/2000	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	10/02/2005

I&G EXPRESS INC. (Continued) **U003749734**

Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-604710	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	ARI ZUBLI (212) 695-6262		
Emergency Contact:	ARI ZUBLI (212) 695-6262		
Total Tanks:	0		
Owner:	U&I REALTY INC. 456 11TH AVENUE NEW YORK, NY 10018 (212) 695-6262		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	GUARDIAN BROKERAGE ATTN: ARI ZUBLI PO BOX 2009 GREAT NECK, NY 11022 (212) 695-6262		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	3	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	Not reported	Dispenser:	Not reported
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	09/01/2000	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	10/02/2005
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		

I&G EXPRESS INC. (Continued) **U003749734**

County Code:	62		
Region:	2		
PBS Number:	2-604710	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	ARI ZUBLI (212) 695-6262		
Emergency Contact:	ARI ZUBLI (212) 695-6262		
Total Tanks:	0		
Owner:	U&I REALTY INC. 456 11TH AVENUE NEW YORK, NY 10018 (212) 695-6262		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	GUARDIAN BROKERAGE ATTN: ARI ZUBLI PO BOX 2009 GREAT NECK, NY 11022 (212) 695-6262		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	4	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	Not reported	Dispenser:	Not reported
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	09/01/2000	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	10/02/2005
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-604710	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	ARI ZUBLI		

I&G EXPRESS INC. (Continued) **U003749734**

	(212) 695-6262		
Emergency Contact:	ARI ZUBLI		
	(212) 695-6262		
Total Tanks:	0		
Owner:	U&I REALTY INC.		
	456 11TH AVENUE		
	NEW YORK, NY 10018		
	(212) 695-6262		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	GUARDIAN BROKERAGE		
	ATTN: ARI ZUBLI		
	PO BOX 2009		
	GREAT NECK, NY 11022		
	(212) 695-6262		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	5	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	Not reported
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	Not reported		
Leak Detection:	Not reported		
Overfill Prot:	Not reported	Dispenser:	Not reported
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	09/01/2000	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	10/02/2005
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

This is the most recent NY PBS data for this site.
The NY PBS database contains 2 additional records for this site.
Please contact your EDR Account Executive for more information.

---

54 **TRAVEL INN HOTEL** **UST** **U000393917**
ESE **515 WEST 42ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
1264
Higher

TRAVEL INN HOTEL (Continued) **U000393917**

PBS UST:

PBS Number:	2-055239	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	ALVIN WIDEMAN (212) 695-7171		
Emergency Contact:	ANTONIO LAHOZ (212) 594-4923		
Total Tanks:	1		
Owner:	FICO REALTY 515 WEST 42ND STREET NEW YORK, NY 10036 (212) 695-7171		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	FICO REALTY ATTN: RONALD DOMB 515 WEST 42ND STREET NEW YORK, NY 10036 (212) 695-7171		
Tank Status:	In Service		
Capacity (gals):	10000		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	OTHER		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	False
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	10000	Renewal Date:	08/08/2001
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	True	Certification Date:	Not reported
Old PBS Number:	Not reported	Expiration Date:	12/30/2006
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

---

55 **MERCEDES BENZ MANHATTAN INC** **RCRIS-SQG 1000168671**
SSE **528 W 39TH ST** **UST NYD982739245**
1/8-1/4 **NEW YORK, NY 10036**
1279
Higher

MERCEDES BENZ MANHATTAN INC (Continued) **1000168671**

RCRIS:
Owner: M-B NORTH AMERICA
(212) 555-1212
Contact: L LANE
(212) 629-1608
Record Date: 08/07/1989
Classification: Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

PBS UST:

PBS Number:	2-016063	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	STEPHAN ALTRICNTER (212) 629-1606		
Emergency Contact:	MICHAEL KEENAN (212) 629-1600		
Total Tanks:	1		
Owner:	MERCEDES/BENZ MANHATTAN INC 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 760-0600		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	MERCEDES/BENZ MANHATTAN INC ATTN: MR. TOM LOPEZ 536 WEST 41ST STREET NEW YORK, NY 10036 (212) 629-1612		
Tank Status:	In Service		
Capacity (gals):	7500		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	False
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	7500	Renewal Date:	08/12/1997
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	10/06/1997
Old PBS Number:	Not reported	Expiration Date:	10/23/2002

MERCEDES BENZ MANHATTAN INC (Continued) **1000168671**

Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

56 East 1/8-1/4 1283 Higher

ANNEX BLDG **UST** **U001840312**
521 WEST 43TH STREET **N/A**
NEW YORK CITY, NY 10036

PBS UST:

PBS Number:	2-456985	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	N Y P L (212) 714-8519		
Emergency Contact:	SECURITY-N Y P L (212) 930-0513		
Total Tanks:	2		
Owner:	NEW YORK PUBLIC LIBRARY 11 WEST 40TH STREET NEW YORK CITY, NY 10018 (212) 930-0977		
Owner Type:	Local Government		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	NEW YORK PUBLIC LIBRARY 11 WEST 40TH STREET NEW YORK CITY, NY 10018 (212) 930-0977		
Tank Status:	In Service		
Capacity (gals):	1400		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	001	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	NONE		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	11400	Renewal Date:	01/18/1994
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	05/15/2000
Old PBS Number:	Not reported	Expiration Date:	12/06/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		

ANNEX BLDG (Continued) **U001840312**

Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-456985	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	N Y P L (212) 714-8519		
Emergency Contact:	SECURITY-N Y P L (212) 930-0513		
Total Tanks:	2		
Owner:	NEW YORK PUBLIC LIBRARY 11 WEST 40TH STREET NEW YORK CITY, NY 10018 (212) 930-0977		
Owner Type:	Local Government		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	NEW YORK PUBLIC LIBRARY 11 WEST 40TH STREET NEW YORK CITY, NY 10018 (212) 930-0977		
Tank Status:	In Service		
Capacity (gals):	10000		
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS		
Tank Id:	002	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	Not reported		
Overfill Prot:	Product Level Gauge	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	11400	Renewal Date:	01/18/1994
Tank Screen:	Minor data missing	Federal ID:	Not reported
Renew Flag:	Renwal has been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	05/15/2000
Old PBS Number:	Not reported	Expiration Date:	12/06/2003
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

N57 METROPOLITAN LUMBER COMPANY **UST 1000791013**
NE 617 11TH AVE **LTANKS N/A**
1/8-1/4 NEW YORK, NY 10036
1308
Higher Site 1 of 2 in cluster N

LTANKS:

Spill Number:	9707347	Region of Spill:	2
Facility Contact:	BOB GANS	Facility Tele:	(212) 246-9090
Investigator:	TOMASELLO	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	BOB GANS	Spiller Phone:	(212) 246-9090
Spiller:	METROPOLITAN LUMBER CO		
Spiller Address:	617 11TH AV MANHATTEN, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/08/1998		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	09/22/1997 13:30	Reported to Dept:	09/22/1997 15:08
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	01/16/1998
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	09/22/1997
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	0
Units:	Gallons
Unknown Qty Spilled:	No
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

DEC Remarks: VACANT LOT ADJACENT TO METROPOLITAN LUMBER. REMEDIATION PERFORMED BY OWNER.

METROPOLITAN LUMBER COMPANY (Continued) **1000791013**

Spill Cause: WORKERS LOCATED 8 550 GALLON UNDERGROUND GAS TANKS AND THERE IS SOIL CON TAMINATION AROUND THE TANKS - CHRIS TOMESSELO HAS BEEN NOTIFIED FROM DEC R-2

PBS UST:

PBS Number:	2-601335	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BOB GANS (212) 246-9090		
Emergency Contact:	BOB GANS (212) 246-9090		
Total Tanks:	0		
Owner:	METROPOLITAN LUMBER COMPANY 617 11TH AVE NEW YORK, NY 10036 (212) 246-9090		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	METROPOLITAN LUMBER CO. ATTN: BOB GANS 617 11TH AVENUE NEW YORK, NY 10036 (212) 243-9090		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	01	Install Date:	10/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	12/04/1997
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	02/19/1993
Old PBS Number:	Not reported	Expiration Date:	02/19/1998
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

PBS Number:	2-601335	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201

METROPOLITAN LUMBER COMPANY (Continued) **1000791013**

Operator:	BOB GANS (212) 246-9090		
Emergency Contact:	BOB GANS (212) 246-9090		
Total Tanks:	0		
Owner:	METROPOLITAN LUMBER COMPANY 617 11TH AVE NEW YORK, NY 10036 (212) 246-9090		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	METROPOLITAN LUMBER CO. ATTN: BOB GANS 617 11TH AVENUE NEW YORK, NY 10036 (212) 243-9090		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	02	Install Date:	10/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	12/04/1997
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	02/19/1993
Old PBS Number:	Not reported	Expiration Date:	02/19/1998
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-601335	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BOB GANS (212) 246-9090		
Emergency Contact:	BOB GANS (212) 246-9090		
Total Tanks:	0		
Owner:	METROPOLITAN LUMBER COMPANY		

METROPOLITAN LUMBER COMPANY (Continued) **1000791013**

617 11TH AVE
NEW YORK, NY 10036
(212) 246-9090

Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	METROPOLITAN LUMBER CO. ATTN: BOB GANS 617 11TH AVENUE NEW YORK, NY 10036 (212) 243-9090		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	03	Install Date:	10/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	12/04/1997
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	02/19/1993
Old PBS Number:	Not reported	Expiration Date:	02/19/1998
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-601335	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BOB GANS (212) 246-9090		
Emergency Contact:	BOB GANS (212) 246-9090		
Total Tanks:	0		
Owner:	METROPOLITAN LUMBER COMPANY 617 11TH AVE NEW YORK, NY 10036 (212) 246-9090		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		

METROPOLITAN LUMBER COMPANY (Continued) **1000791013**

Mailing Address:	METROPOLITAN LUMBER CO. ATTN: BOB GANS 617 11TH AVENUE NEW YORK, NY 10036 (212) 243-9090		
Tank Status:	Closed - Removed		
Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	04	Install Date:	10/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	12/04/1997
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	02/19/1993
Old PBS Number:	Not reported	Expiration Date:	02/19/1998
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-601335	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	BOB GANS (212) 246-9090		
Emergency Contact:	BOB GANS (212) 246-9090		
Total Tanks:	0		
Owner:	METROPOLITAN LUMBER COMPANY 617 11TH AVE NEW YORK, NY 10036 (212) 246-9090		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	METROPOLITAN LUMBER CO. ATTN: BOB GANS 617 11TH AVENUE NEW YORK, NY 10036 (212) 243-9090		
Tank Status:	Closed - Removed		

METROPOLITAN LUMBER COMPANY (Continued) **1000791013**

Capacity (gals):	550		
Tank Location:	UNDERGROUND		
Tank Id:	05	Install Date:	10/01/1992
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	NONE/NONE		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE/NONE		
Second Containment:	NONE/NONE		
Leak Detection:	NONE/NONE		
Overfill Prot:	None	Dispenser:	Submersible
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	0	Renewal Date:	12/04/1997
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	02/19/1993
Old PBS Number:	Not reported	Expiration Date:	02/19/1998
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	TRUCKING/TRANSPORTATION		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

This is the most recent NY PBS data for this site.
The NY PBS database contains 4 additional records for this site.
Please contact your EDR Account Executive for more information.

N58 **MARTIN MANHATTAN ACURA** **FINDS 1000411902**
NE **11TH AVE W 46TH ST** **RCRIS-LQG NYD986884096**
1/8-1/4 **NEW YORK, NY 10019**
1309
Higher **Site 2 of 2 in cluster N**

RCRIS:
Owner: MARK ELLIOT
(212) 555-1212

Contact: RAY MIRRA
(212) 581-6690

Record Date: 10/26/1989
Classification: Large Quantity Generator, Small Quantity Generator
Used Oil Recyc: No

Violation Status: No violations found

NY MANIFEST
Additional detail is available in NY MANIFEST. Please contact your EDR Account Executive for more information.

MARTIN MANHATTAN ACURA (Continued) **1000411902**

FINDS:
Other Pertinent Environmental Activity Identified at Site:
Resource Conservation and Recovery Act Information system (RCRAINFO)

---

59 **APT BUILDING** **LTANKS** **S102560347**
ENE **545 WEST 45TH ST** **N/A**
1/4-1/2 **MANHATTEN, NY**
1351
Higher

LTANKS:

Spill Number:	9711326	Region of Spill:	2
Facility Contact:	NONE	Facility Tele:	Not reported
Investigator:	MARTINKAT	SWIS:	61
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	CHARLIE	Spiller Phone:	(718) 932-9075
Spiller:	MYSTIC OIL		
Spiller Address:	19-01 STEINWAY ST ASTORIA, NT		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/09/1998		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	01/09/1998 09:50	Reported to Dept:	01/09/1998 10:02
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	01/15/1998
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	01/09/1998
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	5
Units:	Gallons
Unknown Qty Spilled:	5
Quantity Recovered:	5
Unknown Qty Recovered:	False
Material:	#4 FUEL OIL
Class Type:	Petroleum

APT BUILDING (Continued) **S102560347**

Chem Abstract Service Number: #4 FUEL OIL
Last Date: 12/05/1994
Num Times Material Entry In File: 1751
DEC Remarks: Not reported
Spill Cause: DRIVER OVERFILLED TANK ONTO SIDEWALK SPILL IS ALL CONTAINED AND BEING CL EANED UP

M60 **LTANKS** **S104620828**
SE **505-509 WEST 41ST ST** **N/A**
1/4-1/2 **MANHATTEN, NY**
1358
Higher **Site 2 of 2 in cluster M**

LTANKS:

Spill Number:	9912551	Region of Spill:	2
Facility Contact:	MIMI SOTIRIOU	Facility Tele:	(800) 899-2577
Investigator:	ROMMEL	SWIS:	61
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	MIMI SOTIRIOU	Spiller Phone:	(800) 899-2577
Spiller:	Not reported		
Spiller Address:	505-509 WEST 41ST ST MANHATTEN, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	02/03/2000 10:00	Reported to Dept:	02/03/2000 10:16
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/04/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/03/2000
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False

(Continued) **S104620828**

Material: #2 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #2 FUEL OIL
Last Date: 12/07/1994
Num Times Material Entry In File: 24464
DEC Remarks: Not reported
Spill Cause: Not reported

---

61 **547 10TH AVENUE** **LTANKS** **S101658388**
SE **547 10TH AVENUE** **N/A**
1/4-1/2 **MANHATTAN, NY**
1410
Higher

LTANKS:
Spill Number: 9503865
Facility Contact: Not reported
Investigator: MULQUEEN
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: UNKNOWN
Spiller Address: Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 06/29/1995 10:50
Cleanup Ceased: Not reported
Last Inspection: Not reported
Region of Spill: 2
Facility Tele: Not reported
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported
Resource Affected: On Land
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 06/29/1995 10:50
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: Not reported
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/01/1995
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Gallons
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False

547 10TH AVENUE (Continued) **S101658388**

Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: CALLER COMPANY REMOVING TANKS - OLD GAS STATION - CALLER FOUND CONTAMINATION ON A PID METER - REQ. DEC TO CALL 516/864-1772.

---

62 **639 11TH AVE./MAHATTAN** **LTANKS** **S100167441**
NE **639 11TH AVE.** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
1497
Higher

LTANKS:

Spill Number:	8706049	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MULQUEEN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(212) 247-2532
Spiller:	MR. GUTMAN		
Spiller Address:	639 11TH AVE. N.Y., NY		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	07/31/1997		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	2-346810
Spill Date:	10/16/1987 11:00	Reported to Dept:	10/19/1987 08:15
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/06/1997
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/19/1987
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Pounds
Unknown Qty Spilled: -1

639 11TH AVE./MAHATTAN (Continued) **S100167441**

Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: 09/27/95: WAS A BATTISTA SPILL MULQUEEN TOOK OVER IN REF. TO SPILL 950 4912. TRIED TO CONTACT OWNER NUMEROUS TIMES, NO REPLY. AFTER CONSIDE RING THE FACT THAT THE SPILL HAS OCCURRED A LONG TIME AGO, AND THE SPILL REMARKS INDICATE NO LONG-TERM FOLLLOW-UP IS NEEDED. THIS SPILL HAS BEEN CLOSED.
Spill Cause: NYCFD WAS AT SIGHT FOR TEST, MR. GUTMAN TO ARRANGE TO UNCOVER AND REP AIR LEAK.

---

63 **509 WEST 38TH ST** **LTANKS** **S102672971**
SSE **509 WEST 38TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
1535
Higher

LTANKS:
Spill Number: 9505232
Facility Contact: Not reported
Investigator: MARTINKAT
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: 5 STAR HOSP. INC
Spiller Address: SAME
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 07/28/1995
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 07/27/1995 21:00
Cleanup Ceased: 07/28/1995
Last Inspection: Not reported
Region of Spill: 2
Facility Tele: Not reported
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported
Resource Affected: In Sewer
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 07/28/1995 14:34
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/17/1995
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

509 WEST 38TH ST (Continued) **S102672971**

Material:
Material Class Type: 1
Quantity Spilled: 150
Units: Gallons
Unknown Qty Spilled: 150
Quantity Recovered: 150
Unknown Qty Recovered: False
Material: #2 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #2 FUEL OIL
Last Date: 12/07/1994
Num Times Material Entry In File: 24464
DEC Remarks: Not reported
Spill Cause: CLEAN UP DONE BY AL EASTMAN/NYCDEP ALREADY ON SCENE - E-W TO 11TH AVE D EP WAS THERE LAST NIGHT - OVERFILL THRU VENT ONTO SIDEWALK THEN ST., RUN NING WEST INTO SEWER.

---

64 **LTANKS** **S104877490**
SSE **550 WEST 37TH ST** **N/A**
1/4-1/2 **MANHATTEN, NY**
1614
Higher

LTANKS:
Spill Number: 0010648
Facility Contact: STAN SUCHARSKI
Investigator: SIGONA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: PHIL RAZZUTO
Spiller: CLASSIC SANATION CO
Spiller Address: 99 RT 3
CLIFTON, NJ 07014
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 12/22/2000 11:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Region of Spill: 2
Facility Tele: (631) 586-4900
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (973) 470-2551
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/22/2000 13:50
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 01/09/2001
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/22/2000
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported

(Continued) **S104877490**

Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: On December 22, 2000, DEC Sigona) observed the excavation and removal o f 4 x 550 gallon USTs. The contents of 3 x 550 gallon USTs was found to contain a mixture of gsaoline and water. 1 x 550 gallon UST contained wa ter only. The excavation was beinng performed by Fenely Nicol for Pub lic Parking, Inc. The project was also supervised by DEC contractor EAR under PIN project for Jacob Javits Spill cleanup.
Spill Cause: DURING TANK REMOVAL SOIL CONTAMINATION HAS BEEN DISCOVERED. CONTAMINATI ON IS ON TOP OF TANKS. AREA TO BE EXCAVATED AND FURTHER SAMPLING/TESTI NG TO BE DONE. NO CALL BACK REQUESTED. CALLER HAS BEEN IN CONTACT WITH REGION 2 OFFICE.

O65 **SERVICE STATION** **LTANKS** **S103037879**
East **624 10TH AVE** **N/A**
1/4-1/2 **MANHATTEN, NY**
1623
Higher **Site 1 of 4 in cluster O**

LTANKS:
Spill Number: 9713164
Region of Spill: 2
Facility Contact: FLORA GANDELMAN
Facility Tele: (212) 582-5790
Investigator: MULQUEEN
SWIS: 62
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: JP YOUNG
Spiller Phone: (212) 629-5890
Spiller: JP YOUNG
Spiller Address: 408 8TH AVE SUITE 206
MANHATTEN, NY
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/22/1998
Spill Cause: Tank Failure
Resource Affected: Air
Water Affected: Not reported
Spill Source: Gas Station
Spill Notifier: Other
PBS Number: Not reported
Spill Date: 02/25/1998 14:15
Reported to Dept: 02/25/1998 14:17
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True

SERVICE STATION (Continued) **S103037879**

Spill Record Last Update: 02/25/1999
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/25/1998
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: CONTAMINATED SOILS EXCAVATED DOWN TO BEDROCK SURFACE. BEDROCK INSPECTED BY MULQUEEN. BEDROCK SURFACE HAD CHANNELS CUT IN IT AND GROUNDWATER WAS DIRECTED TO SEWER SYSTEM. NO FURTHER ACTIONS REQUIRED.
Spill Cause: pulling tanks vapor complaints from neighbors

O66 **HESS STATION #32215** **UST U003178494**
East **502 WEST 45TH ST** **LTANKS N/A**
1/4-1/2 **NEW YORK, NY 10036**
1658
Higher **Site 2 of 4 in cluster O**

LTANKS:
Spill Number: 8807538
Region of Spill: 2
Facility Contact: Not reported
Facility Tele: Not reported
Investigator: TOMASELLO
SWIS: 62
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: Not reported
Spiller Phone: (212) 245-6594
Spiller: SAME
Spiller Address: Not reported
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Resource Affected: Groundwater
Water Affected: Not reported
Spill Source: Gas Station
Spill Notifier: Tank Tester
PBS Number: 2-338613
Spill Date: 12/13/1988 14:30
Reported to Dept: 12/13/1988 15:31
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported

HESS STATION #32215 (Continued) **U003178494**

Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/04/1995
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/21/1988
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: DIESEL
Class Type: Petroleum
Chem Abstract Service Number: DIESEL
Last Date: 07/28/1994
Num Times Material Entry In File: 10625
DEC Remarks: Not reported
Spill Cause: 2 4K TANKS SYPHONED TOGETHER FAILED PETRO. L R = -0.554 GPH. ORIG. INVESTIGATED BY GRATHWOL

PBS UST:

PBS Number:	2-338613	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	SITE MANAGER (212) 245-6594		
Emergency Contact:	AMERADA HESS CORPORATION (732) 750-6000		
Total Tanks:	4		
Owner:	AMERADA HESS CORPORATION 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6000		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	AMERADA HESS CORP ATTN: JANICE FLAHERTY 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6350		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	001	Install Date:	12/01/1980
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		

HESS STATION #32215 (Continued) **U003178494**

Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	Not reported		
Overfill Prot:	Product Level Gauge	Dispenser:	Submersible
Date Tested:	11/01/1995	Next Test Date:	Not reported
Date Closed:	04/01/1997	Test Method:	USTest 2000
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	40000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/31/2000
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-338613	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	SITE MANAGER (212) 245-6594		
Emergency Contact:	AMERADA HESS CORPORATION (732) 750-6000		
Total Tanks:	4		
Owner:	AMERADA HESS CORPORATION 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6000		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	AMERADA HESS CORP ATTN: JANICE FLAHERTY 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6350		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	002	Install Date:	12/01/1980
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	Not reported		
Overfill Prot:	Product Level Gauge	Dispenser:	Gravity
Date Tested:	11/01/1995	Next Test Date:	Not reported

HESS STATION #32215 (Continued) **U003178494**

Date Closed:	04/01/1997	Test Method:	USTest 2000
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	40000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/31/2000
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-338613	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	SITE MANAGER (212) 245-6594		
Emergency Contact:	AMERADA HESS CORPORATION (732) 750-6000		
Total Tanks:	4		
Owner:	AMERADA HESS CORPORATION 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6000		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	AMERADA HESS CORP ATTN: JANICE FLAHERTY 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6350		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	003	Install Date:	12/01/1980
Tank Type:	Steel/carbon steel	Product Stored:	UNLEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	Not reported		
Overfill Prot:	Product Level Gauge	Dispenser:	Gravity
Date Tested:	11/01/1995	Next Test Date:	Not reported
Date Closed:	04/01/1997	Test Method:	USTest 2000
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	40000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported

HESS STATION #32215 (Continued) **U003178494**

Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/31/2000
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-338613	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	SITE MANAGER (212) 245-6594		
Emergency Contact:	AMERADA HESS CORPORATION (732) 750-6000		
Total Tanks:	4		
Owner:	AMERADA HESS CORPORATION 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6000		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	AMERADA HESS CORP ATTN: JANICE FLAHERTY 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6350		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	004	Install Date:	12/01/1980
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	Not reported		
Overfill Prot:	Product Level Gauge	Dispenser:	Gravity
Date Tested:	11/01/1995	Next Test Date:	Not reported
Date Closed:	04/01/1997	Test Method:	USTest 2000
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	40000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/31/2000
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		

HESS STATION #32215 (Continued) **U003178494**

Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		
PBS Number:	2-338613	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	6201
Operator:	SITE MANAGER (212) 245-6594		
Emergency Contact:	AMERADA HESS CORPORATION (732) 750-6000		
Total Tanks:	4		
Owner:	AMERADA HESS CORPORATION 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6000		
Owner Type:	Corporate/Commercial		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	AMERADA HESS CORP ATTN: JANICE FLAHERTY 1 HESS PLAZA WOODBRIDGE, NJ 07095 (732) 750-6350		
Tank Status:	Closed - Removed		
Capacity (gals):	4000		
Tank Location:	UNDERGROUND		
Tank Id:	005	Install Date:	12/01/1980
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	2	Pipe Type:	GALVANIZED STEEL
Tank External:	Not reported		
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	VAULT		
Leak Detection:	Not reported		
Overfill Prot:	Product Level Gauge	Dispenser:	Submersible
Date Tested:	11/01/1995	Next Test Date:	Not reported
Date Closed:	04/01/1997	Test Method:	USTest 2000
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	No data missing
FAMT:	Fiscal amount for registration fee is correct		
Total Capacity:	40000	Renewal Date:	08/12/1997
Tank Screen:	No data missing	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date:	08/31/2000
Old PBS Number:	Not reported	Expiration Date:	10/29/2002
Inspected Date:	Not reported	Inspector:	Not reported
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	RETAIL GASOLINE SALES		
Town or City:	NEW YORK CITY		
Town or City Code:	01		
County Code:	62		
Region:	2		

HESS STATION #32215 (Continued) **U003178494**

This is the most recent NY PBS data for this site.
The NY PBS database contains 9 additional records for this site.
Please contact your EDR Account Executive for more information.

O67 **502 WEST 45TH ST/HESS** **LTANKS** **S104275524**
East **502 WEST 45TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
1658
Higher **Site 3 of 4 in cluster O**

LTANKS:

Spill Number:	8807198	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	SULLIVAN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	HESS OIL		
Spiller Address:	502 WEST 45TH STREET NEW YORK, N.Y.		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	2-338613
Spill Date:	11/30/1988 14:00	Reported to Dept:	12/01/1988 07:01
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	04/15/1997
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	12/01/1988
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	0
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	-1
Units:	Pounds
Unknown Qty Spilled:	-1
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum

502 WEST 45TH ST/HESS (Continued) **S104275524**

Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: Not reported

O68 **WEST 45TH ST & 10TH AVE** **LTANKS** **S100167849**
East **WEST 45TH ST / 10TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
1676
Higher **Site 4 of 4 in cluster O**

LTANKS:

Spill Number:	9000492	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TOMASELLO	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	HESS		
Spiller Address:	Not reported		
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	08/02/1993		
Spill Cause:	Tank Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Local Agency	PBS Number:	Not reported
Spill Date:	04/14/1990 16:40	Reported to Dept:	04/14/1990 16:00
Cleanup Ceased:	08/02/1993		
Last Inspection:	Not reported		

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/02/1993
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/11/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum

WEST 45TH ST & 10TH AVE (Continued) **S100167849**

Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: 08/02/93: WATER ANALYSIS INSIGNIGICANT RESULTS TIGHTNESS TEST 1989 TIGHT . CHRIS TOMASELLO O.K.
Spill Cause: TANK LEAKING, GAS ODOR IN WATER, LEAKING TO TRACKS BELOW, SAMPLE TAKENOF WATER, DEC TO INVESTIGATE FURTHER.

---

69 ESE 1/4-1/2 1727 Higher **450 W. 41ST STREET** **LTANKS S102233197**
450 W. 41ST STREET **N/A**
MANHATTAN, NY

LTANKS:
Spill Number: 9504490
Facility Contact: DAVID RECINO
Investigator: SIGONA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: HUNTER COLLEGE
Spiller Address: 450 WEST 41ST STREET
NEW YORK, NY
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt: Not reported
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 07/14/1995 11:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Region of Spill: 2
Facility Tele: (212) 356-0648
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported
Resource Affected: Groundwater
Spill Source: Non Major Facility > 1,100 gallons
PBS Number: Not reported
Reported to Dept: 07/14/1995 12:28
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/03/1996
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/10/1995
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Gallons
Unknown Qty Spilled: -1
Quantity Recovered: 0

450 W. 41ST STREET (Continued) **S102233197**

Unknown Qty Recovered: False
Material: #6 FUEL OIL
Class Type:
Chem Abstract Service Number: #6 FUEL OIL
Last Date: 07/28/1994
Num Times Material Entry In File: 2190
DEC Remarks: Dec Sigona met with Dormitory Authority staffon July 17, 1995. Meeting included David Recino Dormitory Authority), E. Dowd Hunter College), Ro y Fein ig Rose, Beaton Rose), R. Dib Aqua-X. Investigation found oi l leak in tank. product leaked tosoil and surrounding water table. Ins pection of Con Ed vault outside of the building revealed 6 fuel was se eping into vault. Notified Con Ed who sent personnel to respond and d ocument. Telephone call on 1/3/96 found that Woodward-Clyde wasawarde d bid to provide investigation of the spill. They will start advancing borings on the week of January 8, 1996. I requested that I could be pre sent to observe the installation of monitoring wells. Roy Fein ig will be overseeing the work andl asked David Recino to have him call me ASAP to set up the drilling apointment.
Spill Cause: TANK WAS EMPTIED AND CLEANED DURING A TEST TODAY - THEY FOUND AN UNKNOWN AMOUNT OF OIL UNDER TANK. CALLED DAVID KATZEN, PREPARING TO ABANDON TANK - CLEANED OUT HTE TANK - DRILLED INSIDE THE TANK.

---

70 ENE 1/4-1/2 1749 Higher **BMW** **LTANKS** **S102660130**
547 WEST 47TH ST **N/A**
MANHATTEN, NY

LTANKS:
Spill Number: 9707785
Facility Contact: ROBERT PORTEESE
Investigator: TOMASELLO
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: QUAKER STATE
Spiller Address: 225 E JOHN CARPENTER FREE WAY IRVING, TX 75062
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/01/1997
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 10/01/1997 12:45
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/26/1998
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/01/1997

Region of Spill: 2
Facility Tele: (212) 586-2269
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 10/01/1997 14:38

BMW (Continued) **S102660130**

Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 270
Units: Gallons
Unknown Qty Spilled: 270
Quantity Recovered: 270
Unknown Qty Recovered: False
Material: TRANSMISSION FLUID
Class Type: Petroleum
Chem Abstract Service Number: TRANSMISSION FLUID
Last Date: 07/28/1994
Num Times Material Entry In File: 295
DEC Remarks: JIM CANTELMO 212)-586-2269. PUT CO. CLEANING 250 GAL. TANK L250M NOT EM PTY. SPILL IN SERVICE SHOP HALL WAY OFF MAIN SJOP. PAINTED CONCREATE FLO OR NO SUMP PUMPS. CLEANED BY SPILLER.
Spill Cause: QUAKER STATE FILLING STORAGE TANK AND SEAM IN TANK BROKE CAUSING SPILL INSIDE DEALERSHIP - SPILL CONTAINED INSIDE WITH SPEEDI DRY AND BEING CL EANED UP

P71 **624 WEST 48TH ST** **LTANKS** **S102147958**
NE **624 WEST 48TH ST** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
1762
Higher **Site 1 of 2 in cluster P**

LTANKS:
Spill Number: 8709100
Region of Spill: 2
Facility Contact: Not reported
Facility Tele: Not reported
Investigator: BATTISTA
SWIS: 62
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller: NEW YORK TELEPHONE
Spiller Address: 624 WEST 48TH ST
NEW YORK, N.Y.
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 02/23/1993
Spill Cause: Tank Test Failure
Resource Affected: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Notifier: Tank Tester
PBS Number: 2-344818
Spill Date: 01/25/1988 14:45
Reported to Dept: 01/25/1988 14:54
Cleanup Ceased: 02/23/1993
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported

624 WEST 48TH ST (Continued) **S102147958**

UST Involvement: False
Spill Record Last Update: 07/18/1996
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/26/1988
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Pounds
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: #2 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #2 FUEL OIL
Last Date: 12/07/1994
Num Times Material Entry In File: 24464
DEC Remarks: 02/25/93: 4X550 GAS PASSED IN9/87 REFER TO SPILL 8709100. 02/25/93: 4X 550 GAS PASSED IN9/87.
Spill Cause: 7.5K TANK ISOLATED FROM PIPING, FAILED PETRO TITE TEST WITH A LEAK RAT E OF -.395GPH.

P72 **NYNEX** **LTANKS** **S104073408**
NE **624 W. 48TH STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
1762
Higher **Site 2 of 2 in cluster P**

LTANKS:

Spill Number:	9408956	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TIBBE	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NYNEX		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/06/1996		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	10/05/1994 10:07	Reported to Dept:	10/05/1994 11:07
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		

NYNEX (Continued) **S104073408**

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/17/1997
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/02/1994
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Pounds
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: #2 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #2 FUEL OIL
Last Date: 12/07/1994
Num Times Material Entry In File: 24464
DEC Remarks: Not reported
Spill Cause: WILL INVESTIGATE-POSS. REPLACE TANK

---

73 South 1/4-1/2 1823 Higher **AD SCHEUMANN LUMBER** **LTANKS** **S102233238**
524 WEST 36 TH STREET **N/A**
NEW YORK, NY

LTANKS:

Spill Number:	9510491	Region of Spill:	2
Facility Contact:	ALAN	Facility Tele:	(212) 594-5555
Investigator:	MULQUEEN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SAME		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/16/1998		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	11/17/1995 17:24	Reported to Dept:	11/20/1995 16:41
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		

AD SCHEUMANN LUMBER (Continued) **S102233238**

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 01/16/1998
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/20/1995
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: 1/16/98 CROSS REFERENCED TO SPILL NUMBER 9610133. O DOWD)
Spill Cause: THE TANK POSSIBLY LEAKED.THE TANK IS IN THE GROUND.THEY ARE DOING TESTS ON THE TANK TO DETERMINE IF IT IS THE TANK OR THE LINE.

Q74 **475 10TH AVE/MANHATTAN** **LTANKS** **S100167935**
SSE **475 10TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
1901
Higher **Site 1 of 2 in cluster Q**

LTANKS:
Spill Number: 9003992
Region of Spill: 2
Facility Contact: Not reported
Facility Tele: Not reported
Investigator: ROMMEL
SWIS: 62
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller: GASETERIA GAS STATION
Spiller Address: 466 10TH AVENUE
NEW YORK, N. Y.
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 01/26/1996
Spill Cause: Tank Failure
Resource Affected: Air
Water Affected: Not reported
Spill Source: Gas Station
Spill Notifier: DEC
PBS Number: Not reported
Spill Date: 07/11/1990 10:30
Reported to Dept: 07/11/1990 10:50
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False

475 10TH AVE/MANHATTAN (Continued) **S100167935**

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 01/26/1996
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/11/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Pounds
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
Material Class Type: 1
Quantity Spilled: 0
Units: Pounds
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: VAPORS (PETROLEUM)
Class Type: Petroleum
Chem Abstract Service Number: VAPORS (PETROLEUM)
Last Date: Not reported
Num Times Material Entry In File: 18
DEC Remarks: 07/11/90: DEC SIGONA) RESPONDING WITH NYCDEP NYCFD. Closed and cros s referenced to spill 8909614. JMR)
Spill Cause: SEEPAGE IN BASEMENT FROM EXISTING GASOLINE STATION LEAK CAUSING PEOPLE T O BECOME SICK. SIGONA)

Q75 **466 10TH AVE/GASETERIA** **LTANKS** **S100167794**
SSE **466 10TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
1978
Higher **Site 2 of 2 in cluster Q**

LTANKS:

Spill Number:	8909614	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ROMMEL	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported

466 10TH AVE/GASETERIA (Continued) **S100167794**

Spiller Contact: Not reported Spiller Phone: (718) 361-8811
Spiller: GASETERIA OIL CORP
Spiller Address: Not reported
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Failure Resource Affected: Groundwater
Water Affected: Not reported Spill Source: Gas Station
Spill Notifier: DEC PBS Number: Not reported
Spill Date: 01/04/1990 08:15 Reported to Dept: 01/05/1990 15:24
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/08/1995
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/17/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Not reported
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: 01/05/90: 6) MONITORING WELLS INSTALLED,OIL TANKS BEING TESTED BY CONTR ACTORS TRINITY FENLEY NICOL), ALL TANKS PUMPED CLEANED, REPAIRING WATER MAIN.
Spill Cause: GASOLINE ENTERED BUILDING 478 10TH AVE SEWER SYSTEM, 3) OFFICE BL DGS 475, 478, 483 10TH AVE) EVACUATED, EXPLOSIVE CONDITIONS IN SEWE R, DEC LOCAL AGENCIES ON SCENE. SIGONA)

---

76 South 1/4-1/2 2015 Higher **CONSTRUCTION SITE** **LTANKS S105055174**
529 WEST 35TH ST **N/A**
MANHATTAN, NY

LTANKS:
Spill Number: 0103274 Region of Spill: 2
Facility Contact: GARY ZAID Facility Tele: (212) 736-1626
Investigator: DEMEO SWIS: 62

CONSTRUCTION SITE (Continued) **S105055174**

Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller: UNKNOWN
Spiller Address: -
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Failure
Resource Affected: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Notifier: Other
PBS Number: Not reported
Spill Date: 06/25/2001 17:00
Reported to Dept: 06/25/2001 17:07
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/26/2001
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/25/2001
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: #2 FUEL OIL
Class Type: Petroleum
Chem Abstract Service Number: #2 FUEL OIL
Last Date: 12/07/1994
Num Times Material Entry In File: 24464
DEC Remarks: Not reported
Spill Cause: SOIL SAMPLE RESULTS FROM REMOVAL OF 3 TANKS AT LOCATION. NO VISABLE SIGNS OF CONTAMINATION.

77
NE
1/4-1/2
2026
Higher

PARKING LOT **LTANKS** **S104877137**
618-628 W 49TH ST **N/A**
NEW YORK, NY

LTANKS:
Spill Number: 0008970
Region of Spill: 2
Facility Contact: SAL RUSSO
Facility Tele: (516) 239-8823

PARKING LOT (Continued) **S104877137**

Investigator:	SIGONA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	SAL RUSSO	Spiller Phone:	(516) 239-8823
Spiller:	PARKING LOT..		
Spiller Address:	618-628 W 49TH ST NEW YORK, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Local Agency	PBS Number:	Not reported
Spill Date:	11/01/2000 15:30	Reported to Dept:	11/02/2000 11:55
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	08/15/2001
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	11/02/2000
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	0
Units:	Gallons
Unknown Qty Spilled:	No
Quantity Recovered:	0
Unknown Qty Recovered:	True
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

DEC Remarks: On Auguts 15, 2001, DEC Sigona received spill closure report from AKRF d ated August 14, 2001. See file for details and copy of report.

Spill Cause: UNDERGROUND STORAGE TANK FAILED OVER TIME AND CAUSED SOIL CONTAMINATION - SOIL WILL BE STOCKPILED

---

78 **460 10TH AVE** **LTANKS** **S102672733**
SSE **460 10TH AVENUE** **N/A**
1/4-1/2 **MANHATTAN, NY**
2031
Higher

460 10TH AVE (Continued) **S102672733**

LTANKS:

Spill Number:	9412295	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TOMASELLO	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(212) 490-0660
Spiller:	SIVERSTEIN PROPERTIES		
Spiller Address:	5215 5TH AVE NEW YORK, NY 10175		
Spill Class:	Not reported		
Spill Closed Dt:	12/20/1994		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Affected Persons	PBS Number:	Not reported
Spill Date:	12/14/1994 09:00	Reported to Dept:	12/14/1994 10:48
Cleanup Ceased:	12/20/1994		
Last Inspection:	Not reported		

Cleanup Meets Standard:	True
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	02/28/1995
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	01/30/1995
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	400
Units:	Gallons
Unknown Qty Spilled:	400
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	#4 FUEL OIL
Class Type:	Petroleum
Chem Abstract Service Number:	#4 FUEL OIL
Last Date:	12/05/1994
Num Times Material Entry In File:	1751

DEC Remarks: Not reported

Spill Cause: CUSTOMER OVERORDERED - SPILL CONTAINED ON ROAD PAVEMENT-SUPER FUEL CONTA ININGABC TANK AT SITE 718/272-2800

---

79 ENE 1/4-1/2 2058 Higher

527 W 48TH ST
527 W 48TH ST
MANHATTEN, NY

LTANKS S102662820
N/A

527 W 48TH ST (Continued) **S102662820**

LTANKS:

Spill Number:	9612403	Region of Spill:	2
Facility Contact:	CHARLIE BOETTIGER	Facility Tele:	(718) 932-9075
Investigator:	MULQUEEN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	CHARLIE BOETTIGER	Spiller Phone:	Not reported
Spiller:	MYSTIC OIL		
Spiller Address:	19-01 STEINWAY ST ASTORIA, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/21/1997		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	01/17/1997 07:20	Reported to Dept:	01/17/1997 07:30
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	01/21/1997
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	01/17/1997
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	5
Units:	Gallons
Unknown Qty Spilled:	5
Quantity Recovered:	5
Unknown Qty Recovered:	False
Material:	#2 FUEL OIL
Class Type:	Petroleum
Chem Abstract Service Number:	#2 FUEL OIL
Last Date:	12/07/1994
Num Times Material Entry In File:	24464

DEC Remarks: Not reported

Spill Cause: DRIVER OVERFILLED TANK - SPILL ON CONCRETE BEING CLEANED UP

R80 **555 WEST 34TH ST/NYTEL** **LTANKS** **S104275609**
South **555 WEST 34TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
2185
Higher **Site 1 of 3 in cluster R**

555 WEST 34TH ST/NYTEL (Continued) **S104275609**

LTANKS:

Spill Number:	9007995	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TIBBE	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(718) 336-8474
Spiller:	NYTEL		
Spiller Address:	Not reported		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/06/1996		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	10/22/1990 16:00	Reported to Dept:	10/22/1990 16:03
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	04/17/1997
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	11/05/1990
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	0
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	-1
Units:	Pounds
Unknown Qty Spilled:	-1
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

DEC Remarks: Not reported

Spill Cause: 2) 4K TANKS FAILED VACU TECH, POSSIBLE LINE FAILURES.

R81 **NYNEX** **NY Spills** **S104073407**
South **555 W. 34TH ST** **LTANKS** **N/A**
1/4-1/2 **MANHATTEN, NY**
2185
Higher **Site 2 of 3 in cluster R**

NYNEX (Continued) **S104073407**

SPILLS:

Spill Number:	9614443	Region of Spill:	2
Facility Contact:	JAMES FREER	Facility Tele:	(212) 971-9910
Investigator:	TIBBE	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	JAMES FREER	Spiller Phone:	(212) 971-9910
Spiller:	NYNEX		
Spiller Address:	555 W. 34TH ST NEW YORK, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	03/13/1997		
Spill Cause:	Unknown	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	03/13/1997 16:30	Reported to Dept:	03/13/1997 17:13
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	03/17/1997
Is Updated:	False

Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	03/13/1997
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	1
Units:	Gallons
Unknown Qty Spilled:	Yes
Quantity Recovered:	1
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

Remarks: NYNEX REPORTED SPILL OF GASOLINE WITH NO CAUSE. CLEANUP COMPLETE.
DEC Remarks: CLOSED, SEND TO TIBBE FOR INF. PURPOSES.

LTANKS:

Spill Number:	9512079	Region of Spill:	2
Facility Contact:	ROBERT BALDEZ	Facility Tele:	(212) 756-9450

NYNEX (Continued) **S104073407**

Investigator:	KRIMGOLD	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	ROBERT BALDEZ	Spiller Phone:	(212) 756-9450
Spiller:	NYNEX		
Spiller Address:	555 W. 34TH ST MANHATTEN, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/26/1995		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	12/26/1995 07:18	Reported to Dept:	12/26/1995 11:09
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	02/01/1996
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	12/26/1995
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	2
Units:	Gallons
Unknown Qty Spilled:	2
Quantity Recovered:	2
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

DEC Remarks:	LEAKING VEHICLE - VEHICLE WAS TOWED AWAY FOR FIXING
Spill Cause:	LEAKING FUEL TANK SMALL LEAK ALL CLEANED UP

---

82 SSW 1/4-1/2 2235 Higher **ROY WEIDENER MOTOR LINE** **LTANKS S100142897**
651 W 33ST,MARSHILLING YD **N/A**
NYC, NY

LTANKS:

Spill Number:	8907931	Region of Spill:	2

ROY WEIDENER MOTOR LINE (Continued) **S100142897**

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	SIGONA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(615) 586-0561
Spiller:	ROY WEIDENER MOTOR LINE		
Spiller Address:	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	11/09/1989		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	11/08/1989 14:00	Reported to Dept:	11/08/1989 15:00
Cleanup Ceased:	11/09/1989		
Last Inspection:	Not reported		

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 11/29/1989
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/13/1989
Date Region Sent Summary to Central Office: Not reported
Tank Test:
- PBS Number: Not reported
- Tank Number: Not reported
- Test Method: Not reported
- Capacity of Failed Tank: Not reported
- Leak Rate Failed Tank: Not reported
- Gross Leak Rate: Not reported

Material:
- Material Class Type: 1
- Quantity Spilled: 90
- Units: Gallons
- Unknown Qty Spilled: 90
- Quantity Recovered: 0
- Unknown Qty Recovered: False
- Material: DIESEL
- Class Type: Petroleum
- Chem Abstract Service Number: DIESEL
- Last Date: 07/28/1994
- Num Times Material Entry In File: 10625

DEC Remarks: / / : SOIL PLACED ON PLASTIC AND WILL BE REMOVED BY CHEMICAL CONTRACTORS,AS APPROVED BY SIGONA.
Spill Cause: 20-30 YARDS OF CONTAMINATED SOIL.

R83 **538 WEST 34TH ST/MANH** **LTANKS** **S104275572**
South **538 WEST 34TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
2243
Higher **Site 3 of 3 in cluster R**

LTANKS:

Spill Number:	9000078	Region of Spill:	2

538 WEST 34TH ST/MANH (Continued) **S104275572**

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	TOMASELLO	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(212) 683-1370
Spiller:	Not reported		
Spiller Address:	Not reported		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Affected Persons	PBS Number:	Not reported
Spill Date:	03/14/1990 12:00	Reported to Dept:	04/04/1990 08:38
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/20/1992
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/08/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
- PBS Number: Not reported
- Tank Number: Not reported
- Test Method: Not reported
- Capacity of Failed Tank: Not reported
- Leak Rate Failed Tank: Not reported
- Gross Leak Rate: Not reported

Material:
- Material Class Type: 1
- Quantity Spilled: -1
- Units: Not reported
- Unknown Qty Spilled: -1
- Quantity Recovered: 0
- Unknown Qty Recovered: False
- Material: GASOLINE
- Class Type: Petroleum
- Chem Abstract Service Number: GASOLINE
- Last Date: 09/29/1994
- Num Times Material Entry In File: 21329

DEC Remarks: Not reported
Spill Cause: TANKS TO BE CLOSED IN PLACE, CONTAMINATED SOIL WAS DISCOVERED.

S84 **530 WEST 34TH ST/MANH** **LTANKS** **S104275563**
South **530 WEST 34TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
2275
Higher **Site 1 of 2 in cluster S**

LTANKS:
Spill Number: 8910499 Region of Spill: 2

530 WEST 34TH ST/MANH (Continued) **S104275563**

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	WILSON	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(212) 564-2570
Spiller:	Not reported		
Spiller Address:	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	02/02/1990		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Tank Truck
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	02/02/1990 12:35	Reported to Dept:	02/02/1990 13:20
Cleanup Ceased:	02/02/1990		
Last Inspection:	Not reported		

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/05/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
- PBS Number: Not reported
- Tank Number: Not reported
- Test Method: Not reported
- Capacity of Failed Tank: Not reported
- Leak Rate Failed Tank: Not reported
- Gross Leak Rate: Not reported

Material:
- Material Class Type: 1
- Quantity Spilled: 20
- Units: Gallons
- Unknown Qty Spilled: 20
- Quantity Recovered: 0
- Unknown Qty Recovered: False
- Material: #6 FUEL OIL
- Class Type:
- Chem Abstract Service Number: #6 FUEL OIL
- Last Date: 07/28/1994
- Num Times Material Entry In File: 2190

DEC Remarks: Not reported
Spill Cause: INACCURATE GAUGE RESULTING IN OVERFILL ON SIDEWALK, CONTAINED ON DEWALK, SPILL CLEANED UP WITH SPEEDY DRY. SI

T85 **408 WEST 39TH ST** **LTANKS S102662822**
SE **408 WEST 39TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
2278
Higher **Site 1 of 2 in cluster T**

LTANKS:
Spill Number: 9612460 Region of Spill: 2

408 WEST 39TH ST (Continued) **S102662822**

Facility Contact:	CHARLIE BOETTIGER	Facility Tele:	(718) 932-9075
Investigator:	MULQUEEN	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	CHARLIE BOETTIGER	Spiller Phone:	(718) 932-9075
Spiller:	Not reported		
Spiller Address:	408 WEST 39TH ST MANHATTAN		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/13/1997		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	01/18/1997 11:00	Reported to Dept:	01/18/1997 11:32
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	02/13/1997
Is Updated:	False

Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	01/18/1997
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	5
Units:	Gallons
Unknown Qty Spilled:	5
Quantity Recovered:	5
Unknown Qty Recovered:	False
Material:	#4 FUEL OIL
Class Type:	Petroleum
Chem Abstract Service Number:	#4 FUEL OIL
Last Date:	12/05/1994
Num Times Material Entry In File:	1751

DEC Remarks:	Not reported
Spill Cause:	CLEANUP IN PROGRESS

S86 **528 W 34TH ST** **LTANKS** **S102672155**
South **528 W 34TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
2283
Higher **Site 2 of 2 in cluster S**

528 W 34TH ST (Continued) **S102672155**

LTANKS:

Spill Number:	9300804	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMMISA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	WHALECO		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	04/16/1993		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Tank Truck
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	04/16/1993 12:00	Reported to Dept:	04/16/1993 12:03
Cleanup Ceased:	04/16/1993		
Last Inspection:	Not reported		

Cleanup Meets Standard:	True
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	07/20/1993
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	04/21/1993
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	5
Units:	Gallons
Unknown Qty Spilled:	5
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	#2 FUEL OIL
Class Type:	Petroleum
Chem Abstract Service Number:	#2 FUEL OIL
Last Date:	12/07/1994
Num Times Material Entry In File:	24464

DEC Remarks: Not reported
Spill Cause: CONTAINED IN SIDEWALK SENDING SPILL TEAM TO CLEANUP

T87 **PORT AUTH NY/NJ - MAN** **LTANKS S100145904**
SE **W 39 ST / 9 AVE** **N/A**
1/4-1/2 **MANHATTAN, NY**
2375
Higher **Site 2 of 2 in cluster T**

PORT AUTH NY/NJ - MAN (Continued) **S100145904**

LTANKS:

Spill Number:	8911942	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	FINGER	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(201) 348-3543
Spiller:	PORT AUTH		
Spiller Address:	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	03/16/1990 10:00	Reported to Dept:	03/16/1990 14:32
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	False
Spill Record Last Update:	08/16/1995
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	03/16/1990
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	200
Units:	Gallons
Unknown Qty Spilled:	200
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	#2 FUEL OIL
Class Type:	Petroleum
Chem Abstract Service Number:	#2 FUEL OIL
Last Date:	12/07/1994
Num Times Material Entry In File:	24464

DEC Remarks: Not reported

Spill Cause: SET UP FOR AIR PRESSURE TEST WHEN THEY NOTICED A DISCREPANCY ON STICK TE ST - APPROX 200 GALS UNACCOUNTED FOR - AMOUNT OF SPILL NOT DETERMIN-ED.

U88 **436 TENTH AVENUE** **LTANKS S101658469**
South **436 TENTH AVENUE** **N/A**
1/4-1/2 **MANHATTAN, NY**
2384
Higher **Site 1 of 4 in cluster U**

436 TENTH AVENUE (Continued) **S101658469**

LTANKS:

Spill Number:	9506257	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'DOWD	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SAME		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	08/21/1995 14:30	Reported to Dept:	08/21/1995 14:59
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Is Updated:	False		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/27/1995		
Date Region Sent Summary to Central Office:	Not reported		

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	0
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	-1
Units:	Gallons
Unknown Qty Spilled:	-1
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	UNKNOWN PETROLEUM
Class Type:	Petroleum
Chem Abstract Service Number:	UNKNOWN PETROLEUM
Last Date:	09/29/1994
Num Times Material Entry In File:	16414

DEC Remarks: Not reported
Spill Cause: TANKS WERE OINSPECTED AND BOTH FAILED

U89 **AMICO STATION** **LTANKS** **S104191607**
South **436 10TH AVE/34TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
2384
Higher **Site 2 of 4 in cluster U**

AMICO STATION (Continued) **S104191607**

LTANKS:

Spill Number:	9905246	Region of Spill:	2
Facility Contact:	JULIO CALDER	Facility Tele:	(718) 389-4910
Investigator:	SACCACIO	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 509-6661
Spiller:	CONSOLIDATED TRANSPORTATI		
Spiller Address:	ON		
	ENWOOD LONG ISLAND, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/27/1999		
Spill Cause:	Tank Overfill	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	08/01/1999 01:00	Reported to Dept:	08/01/1999 01:26
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard:	False
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	08/27/1999
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	08/01/1999
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	20
Units:	Gallons
Unknown Qty Spilled:	20
Quantity Recovered:	0
Unknown Qty Recovered:	True
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

DEC Remarks: 8/27/99 - Saccacio - on 7/31/99 I called the caller and he said that spe edy-dry had been applied and that a cleanup crew was enroute. Called th e spiller Tmore) and he said that he contracted tyree to do the cleanup . I asked him to send me a letterr certifing the spill had been cleaned up. I called him and left him a messsage on 8/27/99 reminding him I nee d that letter to close out the spill

AMICO STATION (Continued) **S104191607**

Spill Cause: tank was overfilled at location - speedy dry applied - cleanup crew enro ute - some material may have flowed into storm drain and street update 0400 hrs - spill only 5-7 gal all cleaned up - none entered waterway

---

U90 **34TH ST. & 10TH AVE./AMOC** **LTANKS** **S100143829**
South **34TH ST. / 10TH AVE.** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
2408
Higher **Site 3 of 4 in cluster U**

LTANKS:

Spill Number:	8705645	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Not reported	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	AMOCO		
Spiller Address:	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	10/05/1987		
Spill Cause:	Tank Failure	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Tank Truck
Spill Notifier:	Citizen	PBS Number:	2-337870
Spill Date:	10/05/1987 13:45	Reported to Dept:	10/05/1987 14:35
Cleanup Ceased:	10/05/1987		
Last Inspection:	Not reported		

Cleanup Meets Standard:	True
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	05/02/1989
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	10/07/1987
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	0
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	50
Units:	Gallons
Unknown Qty Spilled:	50
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994
Num Times Material Entry In File:	21329

34TH ST. & 10TH AVE./AMOC (Continued) **S100143829**

DEC Remarks: Not reported
Spill Cause: TANK OVERFILL ONE OR TWO TIMES A WEEK DURING SERVICE, APPROXIMATELY 50 GALLONS.

U91 **34TH ST. AND 10TH AVE./AM** **LTANKS** **S102671194**
South **34TH ST. / 10TH AVE.** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
2408
Higher **Site 4 of 4 in cluster U**

LTANKS:

Spill Number:	8704567	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Not reported	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	AMOCO GAS STATION		
Spiller Address:	34TH ST.& 10TH AVE. N.Y., NY		
Spill Class:	Not reported		
Spill Closed Dt:	09/01/1987		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	09/01/1987 22:45	Reported to Dept:	09/01/1987 22:52
Cleanup Ceased:	09/01/1987		
Last Inspection:	Not reported		

Cleanup Meets Standard:	True
Recommended Penalty:	No Penalty
Spiller Cleanup Date:	Not reported
Enforcement Date:	Not reported
Investigation Complete:	Not reported
UST Involvement:	True
Spill Record Last Update:	10/07/1988
Is Updated:	False
Corrective Action Plan Submitted:	Not reported
Date Spill Entered In Computer Data File:	09/10/1987
Date Region Sent Summary to Central Office:	Not reported

Tank Test:

PBS Number:	Not reported
Tank Number:	Not reported
Test Method:	Not reported
Capacity of Failed Tank:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	1
Quantity Spilled:	1
Units:	Not reported
Unknown Qty Spilled:	Yes
Quantity Recovered:	0
Unknown Qty Recovered:	False
Material:	GASOLINE
Class Type:	Petroleum
Chem Abstract Service Number:	GASOLINE
Last Date:	09/29/1994

34TH ST. AND 10TH AVE./AM (Continued) **S102671194**

Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: TANK TRUCK LICENSE PLATE AP7359) INVOLVED IN TANK OVERFILL.

---

92 SSE 1/4-1/2 2452 Higher **429 WEST 36TH ST** **LTANKS S102448051**
429 WEST 36TH ST **N/A**
MANHATTEN, NY

LTANKS:

Spill Number:	9610098	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'DOWD	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	MICHAEL MICHALOFSKY	Spiller Phone:	(212) 889-4444
Spiller:	KINNEY PARKING		
Spiller Address:	429 WEST 36TH ST MANHATTEN, NY 10018		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	11/13/1996 10:00	Reported to Dept:	11/13/1996 10:58
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/04/1996
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/13/1996
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE

429 WEST 36TH ST (Continued) **S102448051**

Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: Not reported
Spill Cause: two 250 gallon tanks which were o/s since 1985 are being tested to re opened water was put into tanks and they did not hold drilling to b e done today

---

93 ENE 1/4-1/2 2532 Higher **725 10TH AVENUE** **LTANKS** **S102672235**
725 10TH AVENUE **N/A**
MANHATTAN, NY

LTANKS:

Spill Number:	9308145	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMMISA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Spiller Address:	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/05/1993		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	10/05/1993 09:25	Reported to Dept:	10/05/1993 09:39
Cleanup Ceased:	10/05/1993		
Last Inspection:	Not reported		

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/05/1993
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 25
Units: Gallons
Unknown Qty Spilled: 25
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: #4 FUEL OIL

725 10TH AVENUE (Continued) **S102672235**

Class Type: Petroleum
Chem Abstract Service Number: #4 FUEL OIL
Last Date: 12/05/1994
Num Times Material Entry In File: 1751
DEC Remarks: Not reported
Spill Cause: GUAGE MALFUNCTION - GAVE WRONG ON HANDING - SENT SPILL CREW - WILL APPLY SPEEDY DRY.

V94 **MOBIL S/S** **LTANKS** **S101103233**
NE **718 11TH AVENUE** **N/A**
1/4-1/2 **NEW YORK, NY**
2560
Higher **Site 1 of 3 in cluster V**

LTANKS:
Spill Number: 9400944
Facility Contact: MIKE MEOLA
Investigator: SIGONA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: MIKE MEOLA
Spiller: EXXONMOBIL
Spiller Address: 464 DOUGHTY BLVD
INWOOD, NY 11096
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 03/29/1995
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/19/1994 12:00
Cleanup Ceased: 03/29/1995
Last Inspection: Not reported
Region of Spill: 2
Facility Tele: (516) 371-1527
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 371-1527
Resource Affected: On Land
Spill Source: Gas Station
PBS Number: 2-157899
Reported to Dept: 04/20/1994 09:20
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 09/25/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/29/1994
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0

MOBIL S/S (Continued) **S101103233**

Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: 03/29/95: SEE SPILL NUMBER 8904939. 10/10/95: This is additional in formation about material spilled from the translation of the old spill f ile: WATER IN TANK. This spill was reassigned to DEC Sigona from O Dowd on Sept 2000. Also see spill nnos. 0007323, 9009654, 9400944, 9505594 , and 8904939.
Spill Cause: CALLER REPORTED 2 INCHES OF WATER IN GAGE TANK. NO OTHER AGENCIES NO SET ON DATE. NO CALL.

V95 **MOBIL S/S** **LTANKS** **S100167717**
NE **718 11TH AVENUE** **N/A**
1/4-1/2 **NEW YORK, NY**
2560
Higher **Site 2 of 3 in cluster V**

LTANKS:
Spill Number: 8904939
Region of Spill: 2
Facility Contact: MIKE MEOLA
Facility Tele: (516) 371-1527
Investigator: SIGONA
SWIS: 62
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: MIKE MEOLA
Spiller Phone: (516) 371-1527
Spiller: EXXONMOBIL
Spiller Address: 464 DOUGHTY BLVD
INWOOD, NY 11096
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Resource Affected: On Land
Water Affected: Not reported
Spill Source: Gas Station
Spill Notifier: Responsible Party
PBS Number: 2-157899
Spill Date: 08/17/1989 12:00
Reported to Dept: 08/18/1989 08:44
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 09/25/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/29/1989
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

MOBIL S/S (Continued) **S100167717**

Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: This spill investigation was reassigned from Sullivan, O Dowd to DEC Sig ona on Sept 22, 2000. Also, see spill Nos. 0007323, 9009654, 9400944, 9 505594 for further details on this location.
Spill Cause: TANK FAILED PETRO TITE TEST, IN PROCESS OF EXCAVATING TANK TOP, WILL IS OLATE RETEST,RETESTED ON 1/5/91 .

V96 **MOBIL S/S** **LTANKS** **S100168132**
NE **718 11TH AVENUE** **N/A**
1/4-1/2 **NEW YORK, NY**
2560
Higher **Site 3 of 3 in cluster V**

LTANKS:
Spill Number: 9009654
Facility Contact: MIKE MEOLA
Investigator: SIGONA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: MIKE MEOLA
Spiller: EXXONMOBIL
Spiller Address: 464 DOUGHTY BLVD INWOOD, NY 11096
Spill Class: Not reported
Spill Closed Dt: 01/29/1991
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/05/1990 12:30
Cleanup Ceased: 01/29/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 09/25/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/12/1990
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported

Region of Spill: 2
Facility Tele: (516) 371-1527
SWIS: 62
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 371-1527

Resource Affected: Groundwater
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 12/05/1990 15:02

MOBIL S/S (Continued) **S100168132**

Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 0
Units: Gallons
Unknown Qty Spilled: No
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: DEC Sullivan was originally assigned to the spill, and transferred to DE C Sigona on Sept. 2000. Also, See spill nos. 0007323, 9400944, 9505594, , 8904939.
Spill Cause: LINE TEST, FAILED PETRO TITE, SUPER REGULAR NO LEAD, SUPER)-.017GPH REGULAR NO LEAD) -.21GPH, TYREE TO REPAIR RETEST, TONY KHOURY FIEL D ENGINEER) 516-239-0266,1/5 RETESTED,PASSED,PETROTITE.

Spill Number: 9505594
Region of Spill: 2
Facility Contact: MIKE MEOLA
Facility Tele: (516) 371-1527
Investigator: SIGONA
SWIS: 62
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Spiller Contact: Not reported
Spiller Phone: (516) 239-7792
Spiller: MOBIL OIL CORP
Spiller Address: 464 DOUGHTY BLVD
INWOOD, NEW YORK 11096
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/22/1996
Spill Cause: Tank Overfill
Resource Affected: On Land
Water Affected: Not reported
Spill Source: Gas Station
Spill Notifier: Other
PBS Number: 2-157899
Spill Date: 08/05/1995 23:16
Reported to Dept: 08/05/1995 23:44
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 09/25/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/14/1995
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported
Tank Number: Not reported
Test Method: Not reported

MOBIL S/S (Continued) **S100168132**

Capacity of Failed Tank: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: 20
Units: Gallons
Unknown Qty Spilled: 20
Quantity Recovered: 0
Unknown Qty Recovered: True
Material: GASOLINE
Class Type: Petroleum
Chem Abstract Service Number: GASOLINE
Last Date: 09/29/1994
Num Times Material Entry In File: 21329
DEC Remarks: CLEANED BY RP COPY TO KERRI). This spill was reassigned to DEC Sigona on Sept 2000. Also see spill nos. 0007323, 9009654, 9400944, and 890493 9.
Spill Cause: OVERFILLED UNDER GROUND TANK - CLEANUP CREW RESPONDING

---

97 SE 1/4-1/2 2564 Higher **37TH & 9TH ST/BKLYN** **LTANKS** **S100146830**
37TH / 9TH STREET **N/A**
NEW YORK CITY, NY

LTANKS:
Spill Number: 9012156
Facility Contact: Not reported
Investigator: TIBBE
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: NYCTA
Spiller Address: Not reported
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 02/21/1991 16:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 12/28/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/15/1991
Date Region Sent Summary to Central Office: Not reported
Tank Test:
PBS Number: Not reported

Region of Spill: 2
Facility Tele: Not reported
SWIS: 61
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 02/22/1991 07:14

37TH & 9TH ST/BKLYN (Continued) **S100146830**

Tank Number: Not reported
Test Method: Not reported
Capacity of Failed Tank: 0
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
Material:
Material Class Type: 1
Quantity Spilled: -1
Units: Pounds
Unknown Qty Spilled: -1
Quantity Recovered: 0
Unknown Qty Recovered: False
Material: DIESEL
Class Type: Petroleum
Chem Abstract Service Number: DIESEL
Last Date: 07/28/1994
Num Times Material Entry In File: 10625
DEC Remarks: TANK REPLACED. CLOSURE INVESTIGATION PENDING.
Spill Cause: 7.5K TANK FAILED PETRO TITE WITH A LEAK RATE OF -.241GPH,NYCFD ON ENE. SC

---

98 East 1/4-1/2 2599 Higher **416 WEST 47TH STREET** **LTANKS** **S104278720**
416 WEST 47TH ST **N/A**
NEW YORK, NY

LTANKS:

Spill Number:	9909811	Region of Spill:	2
Facility Contact:	VITO CUTUGNO	Facility Tele:	(718) 631-3108
Investigator:	SIGONA	SWIS:	62
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	VITO CUTUGNO	Spiller Phone:	(718) 631-3108
Spiller:	GRL PROPERTY INVESTORS		
Spiller Address:	214-57 27TH AVENUE BAYSIDE, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Tank Tester	PBS Number:	2-602413
Spill Date:	11/12/1999 11:45	Reported to Dept:	11/12/1999 12:43
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/14/2000
Is Updated: False
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/12/1999
Date Region Sent Summary to Central Office: Not reported

416 WEST 47TH STREET (Continued) **S104278720**

Tank Test:
- PBS Number: Not reported
- Tank Number: 1
- Test Method: Horner EZ Check
- Capacity of Failed Tank: 2500
- Leak Rate Failed Tank: 0.00
- Gross Leak Rate: Talk Test Failures only pass or fail

Material:
- Material Class Type: 1
- Quantity Spilled: 0
- Units: Gallons
- Unknown Qty Spilled: No
- Quantity Recovered: 0
- Unknown Qty Recovered: True
- Material: #4 FUEL OIL
- Class Type: Petroleum
- Chem Abstract Service Number: #4 FUEL OIL
- Last Date: 12/05/1994
- Num Times Material Entry In File: 1751

DEC Remarks: DEC Sigona sent letter to GRL Property investors on 11/26/99 requesting that the leaking vent pipe be capped and the existing 1 inch vent line b e replaced with a properly si ed vent pipe to the front of the building. In addition, the DEC will requeest that another precision tightness test be performed to confirm that there is no leak in the system.

Spill Cause: DEC Sigona requested that tank testor report this spill to hotline

---

99 NE 1/2-1 4742 Higher **EQUITABLE GAS CO.** **Coal Gas** **G000000366**
540 W. 59TH ST. **N/A**
NEW YORK, NY 10019

COAL GAS SITE DESCRIPTION:
Site is between 59th St. and 58th St. and between Amsterdam Ave. and West End Ave. Site consisted of Gas Holders. (B17)

©Copyright 1993 Real Property Scan, Inc.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
MANHATTAN	S105135532	WALL STREET AND	PEARL STREET		LTANKS	0106540
MANHATTAN	S100494356	57-15 49TH STREET	57-15 49TH STREET		NY Spills, LTANKS	9209704
NEW YORK	1000436338	43 WEST 61ST STREET ASSOCN	10 COLUMBUS CIR STE 23	10019	RCRIS-SQG, FINDS	
NEW YORK	S102639394	WEST 57TH ST. CONCRETE CO.	PIER 95 / HUDSON RIVER	10019	CBS AST	2-000180
NEW YORK	U000414045	PIER 79	WEST STREET @ 39TH STREET	10018	UST	2-600655
UNION CITY	S105005673	NU METHOD DYEING & PROCESSING	128 44TH / 119 TO 121 45TH S	07087	SHWS	NJD001642396
UNION CITY	S105005674	NU METHOD DYEING & PROCESSING	128 44TH / 119 TO 121 45TH S	07087	SHWS	NJD001642396
UNION CITY	S105007453	48TH STREET PARKING LOT	48TH ST	07087	SHWS	NJL800370322
UNION CITY	S105006971	UNION CITY DEPARTMEN PUBLIC WORKS	3910 PALSADE AVE	07087	SHWS	NJL800061400

EPA Waste Codes Addendum

Code	Description
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D005	BARIUM
D007	CHROMIUM
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List
Source: EPA
Telephone: N/A
National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/29/02
Date Made Active at EDR: 02/25/02
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/04/02
Elapsed ASTM days: 21
Date of Last EDR Contact: 02/04/02

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 8
Telephone: 303-312-6774

EPA Region 4
Telephone 404-562-8033

Proposed NPL: Proposed National Priority List Sites
Source: EPA
Telephone: N/A

Date of Government Version: 01/17/02
Date Made Active at EDR: 02/25/02
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/04/02
Elapsed ASTM days: 21
Date of Last EDR Contact: 02/04/02

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System
Source: EPA
Telephone: 703-413-0223
CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/21/01
Date Made Active at EDR: 02/04/02
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 12/26/01
Elapsed ASTM days: 40
Date of Last EDR Contact: 12/26/01

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned
Source: EPA
Telephone: 703-413-0223
As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

Date of Government Version: 11/21/01
Date Made Active at EDR: 02/04/02
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 12/26/01
Elapsed ASTM days: 40
Date of Last EDR Contact: 12/16/01

CORRACTS: Corrective Action Report
Source: EPA
Telephone: 800-424-9346
CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/14/01
Date Made Active at EDR: 01/14/02
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 11/14/01
Elapsed ASTM days: 61
Date of Last EDR Contact: 11/14/01

RCRIS: Resource Conservation and Recovery Information System
Source: EPA/NTIS
Telephone: 800-424-9346
Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 06/21/00
Date Made Active at EDR: 07/31/00
Database Release Frequency: Varies
Date of Data Arrival at EDR: 07/10/00
Elapsed ASTM days: 21
Date of Last EDR Contact: 01/14/02

ERNS: Emergency Response Notification System
Source: EPA/NTIS
Telephone: 202-260-2342
Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 08/08/00
Date Made Active at EDR: 09/06/00
Database Release Frequency: Varies
Date of Data Arrival at EDR: 08/11/00
Elapsed ASTM days: 26
Date of Last EDR Contact: 02/01/02

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System
Source: EPA/NTIS
Telephone: 800-424-9346
The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/99
Database Release Frequency: Biennially
Date of Last EDR Contact: 12/17/01
Date of Next Scheduled EDR Contact: 03/18/02

CONSENT: Superfund (CERCLA) Consent Decrees
Source: EPA Regional Offices
Telephone: Varies
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: N/A
Database Release Frequency: Varies
Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

ROD: Records Of Decision
Source: NTIS
Telephone: 703-416-0223
Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 09/30/00
Database Release Frequency: Annually

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

DELISTED NPL: National Priority List Deletions
Source: EPA
Telephone: N/A
The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/29/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/04/02
Date of Next Scheduled EDR Contact: 05/06/02

FINDS: Facility Index System/Facility Identification Initiative Program Summary Report
Source: EPA
Telephone: N/A
Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 10/29/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

HMIRS: Hazardous Materials Information Reporting System
Source: U.S. Department of Transportation
Telephone: 202-366-4526
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/30/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/21/02
Date of Next Scheduled EDR Contact: 04/22/02

MLTS: Material Licensing Tracking System
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/25/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

MINES: Mines Master Index File
Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959

Date of Government Version: 12/14/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/02/02
Date of Next Scheduled EDR Contact: 04/01/02

NPL LIENS: Federal Superfund Liens
Source: EPA
Telephone: 205-564-4267
Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91
Database Release Frequency: No Update Planned
Date of Last EDR Contact: 02/26/02
Date of Next Scheduled EDR Contact: 05/27/02

PADS: PCB Activity Database System
Source: EPA
Telephone: 202-260-3936
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/30/01
Database Release Frequency: Annually
Date of Last EDR Contact: 02/12/02
Date of Next Scheduled EDR Contact: 05/13/02

RAATS: RCRA Administrative Action Tracking System
Source: EPA
Telephone: 202-564-4104
RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95
Database Release Frequency: No Update Planned
Date of Last EDR Contact: 12/11/01
Date of Next Scheduled EDR Contact: 03/11/02

TRIS: Toxic Chemical Release Inventory System
Source: EPA
Telephone: 202-260-1531
Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/99
Database Release Frequency: Annually
Date of Last EDR Contact: 12/26/01
Date of Next Scheduled EDR Contact: 03/25/02

TSCA: Toxic Substances Control Act
Source: EPA
Telephone: 202-260-5521
Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/98
Database Release Frequency: Every 4 Years
Date of Last EDR Contact: 01/22/02
Date of Next Scheduled EDR Contact: 04/22/02

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-564-2501
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/11/02
Database Release Frequency: Quarterly
Date of Last EDR Contact: 12/26/01
Date of Next Scheduled EDR Contact: 03/25/02

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA
Telephone: 202-564-2501

Date of Government Version: 01/14/02
Database Release Frequency: Quarterly
Date of Last EDR Contact: 12/26/01
Date of Next Scheduled EDR Contact: 03/25/02

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF NEW YORK ASTM STANDARD RECORDS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State
Source: Department of Environmental Conservation
Telephone: 518-402-9553
State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 04/01/01
Date Made Active at EDR: 10/31/01
Database Release Frequency: Annually
Date of Data Arrival at EDR: 10/11/01
Elapsed ASTM days: 20
Date of Last EDR Contact: 02/25/02

SWF/LF: Facility Register
Source: Department of Environmental Conservation
Telephone: 518-457-2051
Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/31/00
Date Made Active at EDR: 03/02/01
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 02/06/01
Elapsed ASTM days: 24
Date of Last EDR Contact: 02/05/02

LTANKS: Spills Information Database
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 10/01/01
Date Made Active at EDR: 12/20/01
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 11/26/01
Elapsed ASTM days: 24
Date of Last EDR Contact: 01/29/02

UST: Petroleum Bulk Storage (PBS) Database
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 10/01/01
Date Made Active at EDR: 12/12/01
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 11/26/01
Elapsed ASTM days: 16
Date of Last EDR Contact: 01/29/02

CBS UST: Chemical Bulk Storage Database
Source: NYSDEC
Telephone: 518-402-9549
Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 10/01/01
Date Made Active at EDR: 12/12/01
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 11/26/01
Elapsed ASTM days: 16
Date of Last EDR Contact: 01/29/02

MOSF UST: Major Oil Storage Facilities Database
Source: NYSDEC
Telephone: 518-402-9549
Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 10/01/01
Date Made Active at EDR: 12/12/01
Database Release Frequency: Quarterly
Date of Data Arrival at EDR: 11/26/01
Elapsed ASTM days: 16
Date of Last EDR Contact: 01/29/02

VCP: Voluntary Cleanup Agreements
Source: Department of Environmental Conservation
Telephone: 518-402-9711
The voluntary remedial program uses private monies to get contaminated sites r emediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

Date of Government Version: 12/18/01
Date Made Active at EDR: 01/14/02
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 12/26/01
Elapsed ASTM days: 19
Date of Last EDR Contact: 12/18/01

SWRCY: Registered Recycling Facility List
Source: Department of Environmental Conservation
Telephone: 518-402-8705

Date of Government Version: 07/17/00
Date Made Active at EDR: 09/13/00
Database Release Frequency: Semi-Annually
Date of Data Arrival at EDR: 08/24/00
Elapsed ASTM days: 20
Date of Last EDR Contact: 02/21/02

SWTIRE: Registered Waste Tire Storage & Facility List
Source: Department of Environmental Conservation
Telephone: 518-402-8694

Date of Government Version: 09/01/01
Date Made Active at EDR: 11/30/01
Database Release Frequency: Annually
Date of Data Arrival at EDR: 11/19/01
Elapsed ASTM days: 11
Date of Last EDR Contact: 02/18/02

STATE OF NEW YORK ASTM SUPPLEMENTAL RECORDS

HSWDS: Hazardous Substance Waste Disposal Site Inventory
Source: Department of Environmental Conservation
Telephone: 518-402-9564
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites which U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared.

Date of Government Version: 12/31/01
Database Release Frequency: Annually
Date of Last EDR Contact: 03/04/02
Date of Next Scheduled EDR Contact: 06/03/02

AST: Petroleum Bulk Storage
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Registered Aboveground Storage Tanks.

Date of Government Version: 10/01/01
Database Release Frequency: Quarterly
Date of Last EDR Contact: 01/29/02
Date of Next Scheduled EDR Contact: 04/29/02

CBS AST: Chemical Bulk Storage Database
Source: NYSDEC
Telephone: 518-402-9549
Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 10/01/01
Database Release Frequency: Quarterly
Date of Last EDR Contact: 01/29/02
Date of Next Scheduled EDR Contact: 04/29/02

MOSF AST: Major Oil Storage Facilities Database
Source: NYSDEC
Telephone: 518-402-9549
Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 10/01/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/29/02
Date of Next Scheduled EDR Contact: 04/29/02

SPILLS: Spills Information Database
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 10/01/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/29/02
Date of Next Scheduled EDR Contact: 04/29/02

LOCAL RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
Source: Cortland County Health Department
Telephone: 607-753-5035

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/05/02
Date of Next Scheduled EDR Contact: 06/03/02

Cortland County Storage Tank Listing
Source: Cortland County Health Department
Telephone: 607-753-5035

Date of Government Version: 01/02/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/05/02
Date of Next Scheduled EDR Contact: 06/03/02

NASSAU COUNTY:

Registered Tank Database
Source: Nassau County Health Department
Telephone: 516-571-3314

Date of Government Version: 08/28/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/05/02
Date of Next Scheduled EDR Contact: 05/06/02

Registered Tank Database
Source: Nassau County Health Department
Telephone: 516-571-3314

Date of Government Version: 08/28/01
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/05/02
Date of Next Scheduled EDR Contact: 05/06/02

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
Source: Rockland County Health Department
Telephone: 914-364-2605

Date of Government Version: 01/23/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

Petroleum Bulk Storage Database
Source: Rockland County Health Department
Telephone: 914-364-2605

Date of Government Version: 01/23/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/07/02
Date of Next Scheduled EDR Contact: 04/08/02

SUFFOLK COUNTY:

Storage Tank Database
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521

Date of Government Version: 03/01/99
Database Release Frequency: Annually

Date of Last EDR Contact: 03/05/02
Date of Next Scheduled EDR Contact: 06/03/02

Storage Tank Database
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521

Date of Government Version: 03/01/99
Database Release Frequency: Annually

Date of Last EDR Contact: 03/05/02
Date of Next Scheduled EDR Contact: 06/03/02

WESTCHESTER COUNTY:

Petroleum Bulk Storage Database
Source: Dept. of Environmental Conservation
Telephone: 914-637-4895

Date of Government Version: 06/19/98
Database Release Frequency: Varies

Date of Last EDR Contact: 03/05/02
Date of Next Scheduled EDR Contact: 06/03/02

Petroleum Bulk Storage Database
Source: Dept. of Environmental Conservation
Telephone: 914-637-4895

Date of Government Version: 06/19/98
Database Release Frequency: Varies

Date of Last EDR Contact: 03/05/02
Date of Next Scheduled EDR Contact: 06/03/02

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 1999 from the U.S. Fish and Wildlife Service.

New York Facility and Manifest Data
Source: NYSDEC
Telephone: 518-457-6585
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

GEOCHECK®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

WEST 42ND STREET WORKS
WEST 42ND STREET
MANHATTAN, NY 10036

TARGET PROPERTY COORDINATES

Latitude (North):	40.761101 - 40° 45' 40.0"
Longitude (West):	74.000099 - 74° 0' 0.4"
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	584398.9
UTM Y (Meters):	4512507.0

EDR's GeoCheck Physical Setting Source Addendum has been developed to assist the environmental professional with the collection of physical setting source information in accordance with ASTM 1527-00, Section 7.2.3. Section 7.2.3 requires that a current USGS 7.5 Minute Topographic Map (or equivalent, such as the USGS Digital Elevation Model) be reviewed. It also requires that one or more additional physical setting sources be sought when (1) conditions have been identified in which hazardous substances or petroleum products are likely to migrate to or from the property, and (2) more information than is provided in the current USGS 7.5 Minute Topographic Map (or equivalent) is generally obtained, pursuant to local good commercial or customary practice, to assess the impact of migration of recognized environmental conditions in connection with the property. Such additional physical setting sources generally include information about the topographic, hydrologic, hydrogeologic, and geologic characteristics of a site, and wells in the area.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata. EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

USGS TOPOGRAPHIC MAP ASSOCIATED WITH THIS SITE

Target Property: 2440074-G1 WEEHAWKEN, NJ NY
Source: USGS 7.5 min quad index

GENERAL TOPOGRAPHIC GRADIENT AT TARGET PROPERTY

Target Property: General West

Source: General Topographic Gradient has been determined from the USGS 1 Degree Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
NEW YORK, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 3604970031B / CBPP

Additional Panels in search area:
3604970030B / CBPP
3604970038B / CBPP
3604970039B / CBPP
3402290001B / CBPP
3402280001B / CBPP
3402220001B / CBPP

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
WEEHAWKEN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Site-Specific Hydrogeological Data*:

Search Radius:	2.0 miles
Location Relative to TP:	1/2 - 1 Mile South
Site Name:	MANHATTAN GENERAL MAIL FACILITY
Site EPA ID Number:	NY6180000352
Groundwater Flow Direction:	NOT AVAILABLE.
Inferred Depth to Water:	not available. Saturated layers impacted by salt water intrusion are present in the overburden. It is generally inferred that the depth to the uppermost 'aquifer' is greater than 70 feet at the surface of the bedrock/sediment interface.
Hydraulic Connection:	Detailed hydraulic connection information is not available. Glacial till and outwash deposit sediments overlie the Manhattan Schist, the uppermost bedrock unit at the site. The surface elevation of bedrock decreases to the southwest of the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 2.000 Miles.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
2	1 - 2 Miles WNW	Varies

For additional site information, refer to Physical Setting Source Map Findings.

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT **GEOLOGIC AGE IDENTIFICATION**

Era:	Paleozoic	Category:	Stratified Sequence
System:	Ordovicias		
Series:	Lower Ordovician and Cambrian carbonate rocks		
Code:	OC *(decoded above as Era, System & Series)*		

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

* ©1996 Site-specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: loamy sand
silt loam
sandy loam
fine sandy loam

Surficial Soil Types: loamy sand
silt loam
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: very gravelly - loamy sand
unweathered bedrock
stratified
sandy loam

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

According to ASTM E 1527-00, Section 7.2.2, "one or more additional state or local sources of environmental records may be checked, in the discretion of the environmental professional, to enhance and supplement federal and state sources... Factors to consider in determining which local or additional state records, if any, should be checked include (1) whether they are reasonably ascertainable, (2) whether they are sufficiently useful, accurate, and complete in light of the objective of the records review (see 7.1.1), and (3) whether they are obtained, pursuant to local, good commercial or customary practice." One of the record sources listed in Section 7.2.2 is water well information. Water well information can be used to assist the environmental professional in assessing sources that may impact groundwater flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NY0002714	1/4 - 1/2 Mile North

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 745748.1s

0 1/2 1 2 Miles

- Major Roads
- Contour Lines
- (W) Water Wells
- (P) Public Water Supply Wells
- Groundwater Flow Direction
- (GI) Indeterminate Groundwater Flow at Location
- (GV) Groundwater Flow Varies at Location
- Cluster of Multiple Icons
- (◎) Earthquake epicenter, Richter 5 or greater
- (HD) Closest Hydrogeological Data

TARGET PROPERTY:	West 42nd Street Works	CUSTOMER:	Con-Edison Company
ADDRESS:	West 42nd Street	CONTACT:	Glen Katz
CITY/STATE/ZIP:	Manhattan NY 10036	INQUIRY #:	745748.1s
LAT/LONG:	40.7611 / 74.0001	DATE:	March 18, 2002 9:05 am

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation		Database	EDR ID Number
1 **North** **1/4 - 1/2 Mile** **Higher**		**FRDS PWS**	**NY0002714**

PWS ID:	NY0002714	PWS Status:	Active
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	CAMP COMANCHE LIBERTY, NY 12754		
Addressee / Facility:	System Owner/Responsible Party BURNS DAVID C/O DAVID BURNS 424 WEST 51 STREET NEW YORK, NY 10019		
Addressee / Facility:	System Owner/Responsible Party BURNS DAVID C/O DAVID BURNS 424 WEST 51 STREET NEW YORK, NY 10019		
Facility Latitude:	Not Reported	Facility Longitude:	Not Reported
City Served:	LIBERTY (T)		
Treatment Class	Not Reported	Population:	Not Reported

PWS currently has or had major violation(s) or enforcement: No

2 **WNW** **1 - 2 Miles** **Higher**	Site ID:	88-06-73-1416	**AQUIFLOW**	**63612**
	Groundwater Flow:	Varies		
	Shallowest Water Table Depth:	3.52		
	Deepest Water Table Depth:	9.68		
	Average Water Table Depth:	Not Reported		
	Date:	07/1999		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for NEW YORK County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 1999 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the national Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

New York Radon Basement Screening Results
Source: New York Department of Health
Telephone: 518-402-7556

New York Facility and Manifest Data
Source: NYSDEC
Telephone: 518-457-6585
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

RADON

Area Radon Information: The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones: Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration