PHASE I ENVIRONMENTAL SITE ASSESSMENT

for

375 LAFAYETTE STREET
New York, New York County, New York

Prepared For:

Kaufman New Ventures
450 Seventh Avenue
New York, New York

Prepared By:

Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.
300 Kimball Drive
Parsippany, New Jersey 07054
NJ Certificate of Authorization No: 24GA27996400

Amanda Forsburg, CHMM
Project Scientist

Steven Ciambruschini, P.G.
Principal / Vice President

Commencement Date: 24 May 2018
Final Report Completion: 20 June 2018

100732401

LANGAN

TABLE OF CONTENTS

Page No.

EXECUTIVE SUMMARY i

1.0 INTRODUCTION 1

2.0 RELIANCE/LIMITATIONS 1

3.0 SITE DESCRIPTION 3

4.0 GEOLOGIC AND HYDROGEOLOGIC CONDITIONS 4

5.0 USER PROVIDED INFORMATION 5

5.1 Title Records 5

5.2 Environmental Liens or Activity and Use Limitations 5

5.3 Specialized Knowledge 5

5.4 Valuation Reduction for Environmental Issues 6

5.5 Commonly Known Information 6

5.6 Documentation Provided by the User 6

6.0 REVIEW OF PREVIOUS LAND USE 7

6.1 Sanborn Fire Insurance Maps 7

6.2 City Directory Search 11

7.0 REGULATORY DATABASE SEARCH 13

8.0 GOVERNMENT AGENCY RECORDS REVIEW 30

9.0 SITE RECONNAISSANCE 34

10.0 ADDITIONAL ISSUES 36

10.1 Wetlands/Floodplain Designation 36

10.2 Protected Endangered Species / Critical Habitats 36

10.3 Asbestos 36

10.4 Lead-based Paint 37

TABLE OF CONTENTS

10.5 Lead in Drinking Water 37

10.6 Indoor Air / Microbial Assessment (Mold) 37

10.7 Radon 37

10.8 Historical and Archaeological Review 38

11.0 DEVIATIONS 39

12.0 FINDINGS/OPINIONS 40

13.0 CONCLUSIONS 41

14.0 QUALIFICATIONS / CERTIFICATION 43

TABLE OF CONTENTS

LIST OF TABLES

Table 1 **List of Contacts**

LIST OF FIGURES

Figure 1 **Site Location Map**
Figure 2 **Tax Map**
Figure 3 **Zoning Map**

APPENDICES

Appendix A **User Questionnaire**
Appendix B **Property Owner/Operator/Key Site Manager Questionnaire**
Appendix C **Sanborn Maps**
Appendix D **City Directory Search**
Appendix E **Environmental Database Radius Report**
Appendix F **Government Correspondence and Records**
Appendix G **Site Photographs**
Appendix H **Langan Resumes**

EXECUTIVE SUMMARY

This Phase I Environmental Site Assessment (ESA) was prepared by Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. on behalf of Kaufman New Ventures (Kaufman) to identify current or potential environmental concerns and Recognized Environmental Conditions (RECs) at the ±19,775 square foot site consisting of the property at 375 Lafayette Street (Block 531, Lots 17, 52, and 56) located in New York, New York. The ESA included a site inspection, review of historical information, completion of a federal/state/local environmental database search, and interviews with local and state agencies to assess current and past site conditions.

The subject property is currently developed with an asphalt-paved parking lot at street level and contains a one-story attendant's building and above-grade lifts for parking. The car parking lifts contain above-grade hydraulic pistons connected to a hydraulic oil compressor with built-in reservoir tank on top of a concrete pad in the northwest portion of the site.

Based on information obtained during the visual inspection of the subject property, review of environmental databases and historic information, and contact with federal/state/local official agencies, the following recognized environmental conditions (RECs), de minimis conditions, and business environmental risks that may impact proposed redevelopment of the site were identified:

Recognized Environmental Conditions

A REC is defined as the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. It is the opinion of the environmental professional that the following represent RECs:

Potential Impacts From Current and Historical Site Use

Based on observations made during the site inspection, the potential exists for the current use of above-grade hydraulic lifts and potential former use of subgrade hydraulic oil distribution piping associated with the above-grade hydraulic pistons to have an adverse impact to soil and groundwater conditions at the site. Some localized staining was observed on the lifts in the vicinity of the hydraulic pistons which are connected to a hydraulic compressor through a network of above grade metal hydraulic lines. One metal grate was observed in the southeast corner of the parking lot that contained two capped

metal hydraulic lines that entered a piping conduit approximately 2-feet below street level. Remnant hydraulic lines may potentially be present beneath the site.

Based on the review of historical Sanborn Fire Insurance Maps and radius report records between at least 1950 and 1972, the western portion of the subject property was formerly occupied by a gasoline filling station with two one-story service garages. No underground storage tanks were identified on the Sanborn Maps and no registered tanks were identified in the radius report. Due to the historical site use as a gasoline filling station, the potential exists for gasoline underground storage tanks (USTs) or associated impacted soil and groundwater to remain in the subsurface of the subject property which may not have been properly closed or removed in accordance with New York State Department of Environmental Conservation (NYSDEC) regulations.

Other historical subject property operations with potential to cause adverse impacts include a printing company on the eastern portion of the subject property at 36 Great Jones Street in 1921 (as identified on the Sanborn Maps) and an electronics company identified at 30 Great Jones Street in the radius report. Records associated with the electronics company included generation and disposal of hazardous waste used in electroplating operations between 1984 and 2007. A formal enforcement action filed against the Concord Electronics Corporation in 1985. Although all formal enforcement actions and written informal violations issued to the Concord Electronics Corporation reportedly achieved compliance, no documentation was provided regarding the nature of the violations issued, corrective measures taken, or potential impacts to subsurface conditions as a result of former electronics manufacture at this site.

Due to the potential use of chemicals associated with historical and current operations and the duration of these activities and the potential for gasoline USTs to be present in the subsurface, it is the opinion of the environmental professional that the historical and current site use has the potential to impact subsurface conditions at the site. As such, the historical and current use of the subject property is considered a REC.

Business Environmental Risks

A BER is defined as a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice. Consideration of BER issues may involve addressing one or more non-scope considerations. It is the opinion of the environmental professional that the following represent business environmental risks:

Surrounding Sites

Based on the review of historical Sanborn Maps and the radius report, at least six gasoline filling stations and automotive repair facilities were located adjacent to or in the close vicinity of the subject property between 1921 and 2005. The radius report documented the tank removal and remediation of some of these sites; however, there is potential for off-site impacts associated with these sites to adversely impact the subject property. Subsurface impacts were identified at three former gasoline filling stations to the south and west of the subject property based on NYSDEC Spill case narratives provided in the radius report. Furthermore, the number of properties involving the use of aboveground storage tanks (ASTs), USTs, spills, and the generation and disposal of hazardous waste on adjacent properties and the surrounding area represent a business environmental risk due to the potential for offsite migration of contaminants to impact sub-slab soil, soil vapor, and/or groundwater below the subject property, and may impact future site redevelopment activities.

Historic Urban Fill

Based on the urban density of the area, it is likely that the subject site area contains historic urban fill which is typically characterized by elevated concentrations of poly-aromatic hydrocarbons (PAHs) and metals. The presence of fill will require implementation of soil handling and management procedures to address excavation, reuse, handling, and possible offsite disposal of this material if the site were to be redeveloped.

Potential Presence of Undocumented Underground Storage Tanks

While no evidence of USTs was observed during the site inspection, the building at the site has historically been operated for commercial, light manufacturing, and residential uses and as a gasoline filling station. Due to this historical use of the site and the previous development prior to the current parking facility, it is the opinion of the environmental professional that the potential presence of heating oil USTs beneath the lots or adjacent sidewalks represents a business environmental risk. During any proposed site redevelopment a contingency plan to properly remove and dispose of any USTs that may be encountered in accordance with state and local regulations should be employed.

De Minimis Conditions

A de minimis condition is defined as a condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. It is the opinion of the environmental professional that the following represent de minimis conditions:

Hydraulic Oil Release

Evidence of a minor release of hydraulic oil limited to small isolated areas in the vicinity of above-grade hydraulic pistons connected to car parking lifts was observed during site reconnaissance. Staining was observed on the asphalt pavement, and on the metal structure of the lifts throughout the property. Sheen was observed on pooled rainwater in isolated areas near the hydraulic lifts. The parking lot is paved with asphalt and no cracking or penetrations in the vicinity of the lifts were observed. There was no evidence of a substantial release that would impact the subsurface of the subject property and require a regulatory response related to the use of the current hydraulic lift system.

1.0 INTRODUCTION

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) has completed a Phase I Environmental Site Assessment (ESA) of a ±19,775 square foot site located at 375 Lafayette Street, New York, New York (Figure 1).

This ESA was conducted to identify current or potential environmental concerns and/or Recognized Environmental Conditions (RECs) resulting from past or current activities on the subject property, as well as to evaluate immediately surrounding environs with the potential to impact upon the property. The assessment consisted of a site reconnaissance of all accessible property areas, a review of State and Federal environmental databases as they concern the subject property and surrounding areas, contact with Federal, State and local agencies, a review of Sanborn Fire Insurance Maps of the subject property and surrounding areas, and a review of local/county records.

The ESA was conducted in a manner consistent with industry standard and practice and in accordance with the Standards of the American Society for Testing and Materials (ASTM) E1527-13 Standard Practice for Environmental Site Assessments. Any deviations from this practice are provided in Section 11.0 of this report.

2.0 RELIANCE/LIMITATIONS

This ESA report was prepared for Kaufman New Ventures (Kaufman), for the Proposed 375 Lafayette Street Development and for the objectives of due diligence. The report is intended to be used in its entirety. Excerpts taken from this report are not necessarily representative of the assessment findings. Langan cannot assume responsibility for use of this report for any property other than the subject property addressed herein, or by any third party without a written authorization from Langan.

Langan's scope of services, as described in the proposal dated 24 May 2018, was limited to that agreed to with Kaufman and no other services beyond those explicitly stated are implied. No exploratory borings, sampling of soil, soil vapor, or groundwater, or laboratory analysis were performed by Langan as part of the scope of services.

This Phase I ESA was not intended to be a definitive investigation of possible environmental impacts at the subject property. The purpose of this investigation was limited to determining if there is reason to suspect the possibility of Recognized Environmental Conditions (RECs) at the subject property. It should be understood that even the most comprehensive Phase I ESA may fail to detect environmental liabilities at a particular site. Therefore, Langan cannot "insure" or "certify" that the subject property is free of environmental impacts. No expressed or implied representation or warranty is included or intended in this report, except that our services were performed, within the limits prescribed by our client, with the customary thoroughness and competence of our profession. The user is cautioned that federal, state, and local laws may impose environmental obligations that are beyond the scope of ASTM Practice E 1527-13.

The conclusions, opinions and recommendations provided in this report are based solely on the following activities:

- Visual observations of the subject property and the immediate vicinity at the time of Langan's site visit;
- Review of relevant available historical information; and,
- Correspondence and/or discussion with personnel knowledgeable about the site.

The conclusions, opinions and recommendations are intended exclusively for the purpose stated herein, at the specified subject property, as it existed at the time of our site visit.

The User is responsible for the review and identification of environmental liens, activity, and use limitations, and for ascertaining reasons for significantly lower purchase property price in accordance with Section 6 of ASTM E 1527-13. A questionnaire covering these above-concerns was provided to Kaufman and completed by the general counsel for Edison Properties, LLC and is included as Appendix A. In addition, a similar questionnaire was provided to Mr. Naveen Liyanaarachchi, the assistant site manager for the subject property, and is included as Appendix B. If any of these above-concerns were uncovered during the course of the Phase I ESA, they are addressed in this report.

The report findings are based in part on information provided by local, county and state officials and environmental databases from Federal and State sources. Langan assumes no responsibility for the accuracy and completeness of this information. Visual observations discussed in this report represent conditions at the time of the site inspection and may not be representative of the past or future site conditions.

As per ASTM E1527-13, Phase I ESA Report deviations, as well as professional opinions regarding these deviations, are listed in Section 11.0.

This ESA has been prepared for the sole use of Kaufman. This ESA should not be relied upon by other parties without the express consent of Langan and Kaufman. In accordance with Section 4.6 of ASTM E 1527-13 and 40 CFR §312.20, a Phase I ESA may be considered valid for one year starting from the commencement date of the assessment listed on the front cover of this report. The formal property acquisition/real estate transaction must take place during this period. However, the following components must be conducted or updated within 180 days (six months) prior to the date of the property acquisition/real estate transaction:

- Interviews with past and present owners, operators and occupants;
- Searches for recorded environmental cleanup liens;
- Review of governmental records;
- Site Reconnaissance of the property and adjoining properties; and,
- The declaration by the Environmental Professional.

3.0 SITE DESCRIPTION

The subject property is designated as Block 531, Lots 17, 52, and 56 by the New York City Department of Finance (Figure 2). The site is currently occupied by an Edison Park Fast car parking lot that consists of an asphalt paved lot at street level, a one-story parking attendants' building along Great Jones Street, a hydraulic oil generator with internal reservoir, above-grade hydraulic oil distribution piping, and above-grade four-level car racks that each contain a hydraulic piston built into the frame of each parking bay. Localized minor staining was observed on the parking racks in the vicinity of the hydraulic pistons, and on the asphalt pavement below. The western portion of subject property was historically occupied by a gasoline filling station between 1950 and 1969 according to historical resources reviewed as part of this Phase I ESA.

The subject property is bound to north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial and office building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by seven lots containing a 13-story mixed-use commercial and office building, two six-story and one three-story mixed-use commercial and residential buildings, one seven-story residential building, two seven-story industrial/manufacturing buildings, and an active construction site. The subject property is bordered to the west by Lafayette Street underlain by the NYCTA 4, 5, 6-Subway tunnel, followed by a six-story mixed-use commercial and office building.

The property is currently zoned as a manufacturing district (M1-5B) according the New York City Department of City Planning zoning map dated 11 October 2012.

4.0 GEOLOGIC AND HYDROGEOLOGIC CONDITIONS

For the purpose of report completeness and to better understand the subsurface conditions, the geologic conditions in the general area of the subject property are discussed in this section.

The "Surficial Geologic Map of New York" by the New York State Museum State Geological Survey indicates that the surficial geology at the site consists of till which is generally an impermeable layer comprised of poorly sorted and variably sized clasts. The subject property is located within an area where bedrock may be present within 1- to 3-meters of surface grade and may sporadically outcrop from the surface. According to the "Bedrock and Engineering Geologic Maps of New York County and Parts of Kings and Queens Counties, New York, and Parts of Bergen and Hudson Counties, New Jersey" by Charles A. Baskerville the site is underlain by the Hartland Formation which consists of interbedded units of feldspar, schist, and amphibolite.

Test borings were completed in the vicinity of the subject property during a geotechnical investigation conducted by Langan in 2004 at a site located approximately 250-feet to the south of the subject property on Bond Street. The site subsurface conditions documented during this geotechnical investigation consisted of a 15- to 17-foot thick layer of miscellaneous fill underlain by successive layers of sand, fine sand, and mica schist bedrock. Rock was typically encountered at depths that ranged from 68- to 74-feet below grade. Groundwater was measured in observations wells installed as part of the geotechnical investigation at approximately 43-feet below grade.

The subject property is topographically at a higher elevation than much of the surrounding area. Based on site/area topography in the vicinity of the subject property and the surrounding area observed during the site inspection, groundwater flow within the overburden material is generally anticipated to be to the east, towards the East River.

5.0 USER PROVIDED INFORMATION

A questionnaire was completed by the general counsel for Edison Properties, LLC and is included in Appendix A. Information obtained from this questionnaire is discussed in the sections below. Documents provided by the User are discussed in this section.

5.1 Title Records

A Title Search was not provided by the User for this ESA. Langan completed a limited review of available online records maintained by the New York City Department of Finance to determine current and former site ownership. These records are discussed in Section 8.0.

5.2 Environmental Liens or Activity and Use Limitations

Reasonably ascertainable recorded land title records and lien records that are filed under federal, tribal, state, or local law should be reviewed to identify environmental liens or activity and use limitations, if any, that are currently recorded against the property. Any environmental liens or activity and use limitations are required to be reported to the Environmental Professional conducting the ESA per ASTM E1527-13.

No environmental liens or use limitations (engineering or institutional controls) were identified for the subject property in the EDR report or by the User. Information regarding the 'E'-designation status of the property can be found in Section 8 of this report.

5.3 Specialized Knowledge

Specialized knowledge is defined by ASTM E 1527-13 as *"any specialized knowledge or experience that is material to recognized environmental conditions in connection with the property*". For example, a User is involved in the same line of business as current or former occupants of the property or adjoining

property and has specialized knowledge of the chemicals and processes used in this line of business.

The User did not provide specialized knowledge material related to recognized environmental conditions in connection with the property as part of this ESA.

5.4 Valuation Reduction for Environmental Issues

In a transaction involving the purchase of a parcel of commercial real estate, the User shall consider the relationship of the purchase price of the property to the fair market value of the property if the property was not affected by hazardous substances or petroleum products. The User should try to identify an explanation for a lower price which does not reasonably reflect fair market value if the property were not contaminated.

The User indicated that no valuation reduction for environmental issues occurred for the ground lease of the subject property.

5.5 Commonly Known Information

If the user is aware of any commonly known or reasonably ascertainable information within the local community about the property that is material to recognized environmental conditions in connection with the property, it is the User's responsibility to communicate such information. This information may include past uses of the property, specific chemicals that were used on site, spills or releases or environmental cleanups that have taken place.

No additional information regarding the environmental condition of the subject site was provided to Langan.

5.6 Documentation Provided by the User

No additional information regarding the environmental condition of the subject site was provided to Langan.

6.0 REVIEW OF PREVIOUS LAND USE

Historic Sanborn Fire Insurance Maps and City Directory Information were requested from Environmental Data Resources (EDR) of Shelton, Connecticut. Provided are descriptions of the materials provided by these resources.

6.1 Sanborn Fire Insurance Maps

Sanborn Fire Insurance Maps of the subject property and surrounding area dated 1895, 1904, 1921, 1950, 1969, 1975, 1979, 1980, 1983, 1985, 1987, 1988, 1991, 1992, 1993, 1994, 1995, 1996, 2001, 2002, 2003, 2004, and 2005 were obtained from Environmental Data Resources and reviewed as part of this ESA. Copies of Sanborn Maps are provided in Appendix C.

Subject Property

In 1895 the subject property is developed with five four-story buildings of unspecified use in the eastern portion of the site, and the Mission of the Immaculate Virgin church building on the western portion of the site. Three horizontal boilers are shown in the Lafayette Place roadway to the west of the church building. The number of stories is not labeled for the church building, which contains one elevator. In 1904, the church building is labeled as a three- to eight-story building with two basement levels; two horizontal boilers are shown in the Lafayette Place roadway to the west of the church building. An eight-story commercial building with one basement level, an elevator, and loading flats is shown in the center of the subject property, and one horizontal boiler is shown in the Great Jones Street roadway south of the commercial building. The remaining four-story buildings are now shown with basement levels. Three are labeled for commercial use with loading flats and one is labeled for mixed commercial and residential use. In 1921, the church building is labeled as vacant and the four-story commercial building at 36 Great Jones Street is labeled as a printer; the former mixed-use building is now labeled for commercial use with loading flats.

In 1950, the church building on the western portion of the subject property is no longer shown, and has been replaced by a filling station with two one-story service garages on the northern and eastern portions of the lot and a one-story commercial building connecting the two. Conditions on the eastern portion of the subject property are similar to those shown on the 1921 Sanborn Map, with the exception that the printer is no longer labeled. The horizontal boilers formerly

located in the Great Jones Street and Lafayette Street (formerly Lafayette Place) roadways are no longer shown on the 1950 Sanborn Map. In 1969, the four-story buildings with basements have been demolished and are replaced with a parking lot; conditions on the remainder of the subject property are consistent with those shown on the 1950 Sanborn Map. In 1975, the gasoline filling station, one-story service garages, and one-story commercial building have been removed and replaced with a parking lot; a small one-story structure, most likely an attendants' booth, is shown on the northwest corner of the parking lot. Conditions shown on the remainder of the subject property are consistent with those shown on the 1969 Sanborn Map. Conditions shown on the 1979 through 2005 Sanborn Maps are consistent with those shown on the 1969 Sanborn Map with the exception that the one-story building formerly on the western portion of the site is not shown on the 1992 through 1995 Sanborn Maps, and is shown in the southwest corner of the parking lot on the 1996 through 2005 Sanborn Maps.

Adjacent North

Properties adjacent to the north of the subject property on the 1895 Sanborn Map include a five-story convent and two-story chapel connected to the Mission of the Immaculate Virgin church, and four four-story buildings of unspecified use. In 1904, the convent is shown with two basement levels, and the chapel with one basement level. Two of the four-story buildings are shown with basements levels and are labeled for mixed commercial and residential use and commercial use, both with loading flats. The remaining two former four-story buildings have been replaced with one eight-story commercial building with loading flats containing two elevators and one basement level.

Conditions shown on the 1921 and 1950 Sanborn Maps are similar to those shown on the 1904 Sanborn Map, with the exception that one of the four-story buildings is shown as a vacant lot in 1950 and one of the four-story buildings is now labeled as a five-story building with a basement. On the 1969 Sanborn Map, the convent and chapel buildings are now labeled as unspecified flats and the five-story building has been removed and the parcel is identified a parking lot. The former convent is labeled as a warehouse and residential building on the 1975 Sanborn Map; no other changes are shown. In 1979, the eight-story commercial building is now labeled for as mixed-use commercial, residential, and unspecified manufacturing. Conditions shown on the 1980 through 2005 Sanborn Maps are consistent with those shown on the 1979 Sanborn Map with

the exception that the five-story former convent building is now labeled as mixed-use commercial and lofts from 1992 to 2005.

Adjacent East

Properties adjacent to the east of the subject property on the 1895 Sanborn Map include a seven-story building of unspecified use with one elevator and the rear yard of a four-story building of unspecified use. On the 1904 Sanborn Maps, the seven-story building is labeled for commercial use with loading flats and one basement level and the rear yard has been developed with a building addition. Conditions on the 1921 through 2005 Sanborn Maps are similar to those shown on the 1904 Sanborn Map.

Adjacent South

Properties adjacent to the south of the subject property shown on the 1895 Sanborn Map include two seven-story buildings, one six-story building, two three-story buildings, and three five-story buildings of unspecified use. A three-story building labeled as Fire Patrol is also shown. Four of the buildings contain elevators. On the 1904 Sanborn Map, the Lafayette Place roadway has been extended to the south past Great Jones Street. Adjacent properties to the south include nine three- to seven-story commercial buildings with one or two basement levels; mixed use commercial/residential us is labeled for two buildings, commercial use is labeled at one of the buildings, commercial use with loading flats is labeled at five of the buildings, and commercial use with manufacturing flats is labeled at two of the buildings. One of the buildings is identified as a stable and the fire patrol building remains labeled. The westernmost property is mostly vacant and labeled as packing boxes with a small one-story commercial building.

Conditions shown for adjacent properties on the 1921 Sanborn Map are generally consistent with those shown on the 1904 Sanborn Map with the exception that a mixed-use commercial and residential property is labeled as a warehouse with auto storage. A gasoline station containing two 550-gallon gasoline tanks is labeled southwest of the intersection of Lafayette Street and Great Jones Street (366 Lafayette Street) and a gasoline station and automobile service shop with three 275-gallon buried gasoline tanks is shown northeast of the intersection of Bond Street and Lafayette Street (357-371 Lafayette Street). On the 1950 Sanborn Map, the gasoline filling station shown on the 1921 Sanborn Map is expanded to include the majority of the eastern side of the

Lafayette Street frontage between Bond Street and Great Jones Street and the gasoline filling station shown at 366 Lafayette Street is expanded to occupy the entire western Lafayette Street frontage between Bond Street and Great Jones Street. Adjacent properties to the south now include automobile service and automobile repair facilities (21 and 25 Great Jones Street), a motor freight station, and an unspecified flat with a garage on the first floor. In 1969, the automobile repair facility to the south is no longer shown and a second garage is labeled. The northern portion of the gasoline filling station at 366-372 Lafayette Street is labeled as an automobile laundry until 1991 when it is shown as automobile repair. Conditions shown on the 1975 through 1996 Sanborn Maps are generally consistent with the 1969 Sanborn Map. The gasoline filling station and one-story automobile service building along Lafayette Street is shown as a vacant lot on the 2001 Sanborn Map; no other notable chances are shown through 2005.

Adjacent West

On the 1895 Sanborn Map, adjacent properties to the west across Lafayette Place include one five-story building of unspecified use containing two elevators. In 1904, the building is labeled as a six-story commercial building with loading flats and a basement. Although not adjacent to the subject property, a four-story building with two basement levels labeled as "Whiting Manufacturing Co. – Silversmiths" is shown northwest of the subject property at 9-13 Lafayette Place. Conditions shown on the 1921 Sanborn Map are consistent with those shown on the 1904 Sanborn Map; the Whiting Manufacturing Co. building is now labeled for unspecified commercial use with loading flats. Conditions shown through the 2005 Sanborn Map are generally consistent with those shown on the 1921 Sanborn Map.

Sanborn Map Review Conclusions

Based on the identification of a gasoline filling station on the western portion of the subject property between 1950 and 1969, it is in the opinion of the environmental professional that the historical site operations may have adversely impacted subsurface conditions at the subject property and, therefore represents a REC. Additionally, based on the identification of gasoline filling stations, automobile repair garages, and auto washes to the south and southwest of the subject property, it is in the opinion of the environmental professional that the potential for off-site migration of contaminants to impact

sub-slab soil, soil vapor, and/or groundwater below the subject property represents a BER.

6.2 City Directory Search

City directory information was obtained from EDR in an attempt to identify past uses of the subject property and establishments in the surrounding area. As provided in the City Directory Abstract (Appendix D), business directories including city, cross-reference and telephone directories were reviewed. City directories include the site address for the years 1920 through 2014 including 1920, 1923, 1927, 1934, 1938, 1942, 1947, 1950, 1956, 1958, 1963, 1968, 1973, 1978, 1983, 1998, 2000, 2006, 2010, and 2014.

The City Directory Report for the subject property listings consists primarily of commercial and light manufacturing listings including clothing manufacturers, hat manufacturers, electronics manufacturers, and paper companies. The following historic listings refer to businesses of potential concern that were formerly located on the subject property:

Address	Business Name	Listing Date
30 Great Jones Street	Concord Electronics Corp.	2000-2006
	Bernhardt Zine Paper Co. Inc.	1938-1973
	Ainsley Hat Co. Inc.	1938-1963
	Art Corrugated Co.	1938-1968
	Miller Hat Co. Inc.	1947-1958
	Empire Raincoat Co.	1947
	Bay MFG Co.	1942
	Pennant Hat Co.	1938
	Crown Hat Frame Co.	1927
	Elgin Hat Frame Co. Inc.	1927
	Lucie Gustav Paper	1927
	Solash Barnet Caps	1927
	Success Hat Co	1927
32 Great Jones Street	A & M Metal Polishing	1956-1958
36 Great Jones Street	Gelman MFG Co.	1947-1950
	Mandel & Levine Printers	1927
38 Great Jones Street	Bond Service & Repair Corp.	1938-1956

Historical site operations including paper and textile manufacturing, electronics manufacture, and hat making may potentially involve the storage, generation, and disposal of hazardous materials. The Concord Electronics Co. was identified in the radius report as a hazardous waste generator between 1980 and 2007 for the generation and disposal of electroplating solutions, and received a formal enforcement action in 1985. No records were identified for the paper and textile manufacturing companies, or the hat making companies in the radius report.

Listings over the years for surrounding properties identified businesses of potential concern including: auto repair and service (1938-1942, 1998-2000), gasoline filling stations (1938-1947), trucking companies (1938-1998), publishing and printing companies (1927-1988), silversmiths and metal stamping (1938-1958), clothing dyers (1938), textile manufacturing (1968), and plastic manufacturing (1947-1968).

The trucking company, located at 37 Great Jones Street, is shown as a motor freight station on the 1950 Sanborn Map, but is not associated with records of petroleum storage, release, or the generation and disposal of hazardous waste. The auto repair facilities, 25 Great Jones Street, 33 Great Jones Street, and 35 Great Jones Street were confirmed on historic Sanborn Maps as auto repair facilities or garages between 1921 and 1950. Additionally, the address 371 Lafayette Street, listed in the City Directory Abstract as "Car Land" in 1998 and 2000, is shown on the 1996 Sanborn Map as an unspecified commercial building attached to an auto repair facility and a gasoline filling station. Potential subsurface impacts associated with the gasoline filling station and auto repair facilities at 363-371 Lexington Avenue, adjacent to the south of the subject property, are discussed in detail below.

City Directory Review Conclusions

It is the opinion of the environmental professional that potential for adverse impacts to the subsurface of the subject property associated with the former gasoline filling stations and auto repair facilities located adjacent to the subject property and in the surrounding area are moderate and could potentially affect subsurface conditions on the subject property. As such, potential impacts from surrounding sites represents a business environmental risk.

7.0 REGULATORY DATABASE SEARCH

A database search report that identifies sites listed on state and federal databases within the ASTM-required radii was obtained for the property from Environmental Data Resources, Inc. (EDR) of Shelton, Connecticut. A copy of EDR's complete report is provided as Appendix E.

The report included the following databases specified by the ASTM Phase I protocol as well as non-ASTM databases (not listed):

RECOMMENDED/**REQUIRED** SEARCH DISTANCES
1.0-mile
Federal National Priority List (NPL)
Federal RCRA CORRACTS Facilities List
State- and Tribal-Equivalent NPL
0.5-mile
Federal Delisted NPL
Federal CERCLIS/SEMS**
Federal CERCLIS NFRAP List/SEMS-Archive**
Federal RCRA non-CORRACTS TSD Facilities List
State- and Tribal-Equivalent CERCLIS
State and Tribal Landfill and/or Solid Waste Disposal Site Lists
State and Tribal Leaking Underground Storage Tanks (LUSTs)
State and Tribal Voluntary Cleanup Sites
State and Tribal Brownfields Sites
Subject Property and Adjacent Properties Only
Federal RCRA Generators List
State and Tribal Registered Storage Tanks
Subject Property Only
Federal ERNS List
Federal Institutional Controls/Engineering Controls Registries
State and Tribal Institutional Controls/Engineering Controls Registries

* A description of these databases and a complete listing of sites identified on the above-referenced databases is provided in the EDR Report.

** As of March 2016, SEMS replaced the CERCLIS database and SEMS-Archive replaced the CERCLIS NFRAP database.

Subject Property

Addresses associated with the subject property including 375-379 Lafayette Street, 30 Great Jones Street, and 379 Lafayette Street are identified in the following databases in the radius report:

- EDR Historical Auto Stations (EDR Hist Auto);
- NY Aboveground Storage Tanks (NY AST);
- NY Spills Database (NY Spills);
- Resource Conservation and Recovery Act (RCRA) Small Quantity Generator (SQG);
- United States Environmental Protection Agency (USEPA) Enforcement and Compliance History Online (ECHO);
- USEPA Facility Index System (FINDS);
- USEPA Integrated Compliance Information System (ICIS); and,
- NY Manifest, PA Manifest, RI Manifest, and NJ Manifest Databases.

The subject property was identified in the EDR Hist Auto database as the H B Service Center gasoline service station that operated at 375-379 Lafayette Street between 1969 and 1972. According to a review of historical Sanborn Maps, a gasoline station was shown on the subject property at 375-379 Lafayette Street on the 1950 and 1969 Sanborn Maps.

The subject property is identified in the NY AST database as an unregulated/closed site registered in the NYSDEC Petroleum Bulk Storage (PBS) Program as Facility No. 2-207543 for one 1,500-gallon No. 2 fuel oil AST in the former apartment/office building located at 30 Great Jones Street. According to the radius report, the AST was installed in November 1976 and removed in May 2008. This address is also identified in the NY Spills database for the release of 10-gallons of No. 2 fuel oil that occurred on 13 December 2002 as the result of human error and assigned Spill No. 0209425 by NYSDEC. Based on the NYSDEC case narrative provided in the radius report, No. 2 fuel oil was spilled into a basement vent. Following a cleanup and on-site inspection by NSYDEC, Spill No. 0209425 was administratively closed on 13 January 2004.

Concord Electronics Corp., located at 30 Great Jones Street, is listed in the RCRA SQG, NY Manifest, RI Manifest, ICIS, FINDS, and ECHO databases for forms received by the USEPA on 1 January 2007 classifying the site as a SQG of waste impacted with hazardous concentrations of an unspecified type of waste. Historical

generator information classified the site as a Large Quantity Generator (LQG) in 2006 for the generation of waste impacted with hazardous concentrations of arsenic, cadmium, chromium, lead, silver, wastewater treatment sludges from electroplating operations, corrosive waste, and reactive waste. This site is also identified as a SQG in 2006 and as an LQG of the hazardous waste types listed above from 1992 to 2004. Historical generator information also classified the site as a LQG of waste impacted with hazardous concentrations of copper cyanide, potassium cyanide, silver cyanide, and sodium cyanide in 1980. Written informal violations were issued to the site in 1984, 1995, and 2005, all of which achieved compliance. This facility is listed in the RI Manifest database for the disposal of hazardous sludges used in electroplating operations between 1990 and 1998, and in the NY Manifest database for the disposal of hazardous sludges used in electroplating operations between 2004 and 2007

The Concord Electronics Corp. is listed in the FINDS database for being tracked through the USEPA Toxics Release Inventory System and through the RCRA Program as a biennial reporter. According to the radius report, a formal enforcement action was filed in December 1985 and the site ceased reporting as a hazardous waste biennial reporter in January 2006. North American Industry Classification System (NAICS) codes provided in the radius report identify the site as machine shops (332710) and electroplating, plating, polishing, anodizing, and coloring (332813). No additional information was provided in the radius report, or in records maintained online by USEPA regarding the outcome of the formal enforcement action filed against the Concord Electronics Corporation in 1985.

The subject property address 379 Lafayette Street is also identified in the RCRA Non-Generators/No Longer Reporting (NonGen/NLR), FINDS, ECHO, and Manifest databases associated with Con Edison Manhole: 59368. As the Con Edison manhole is likely beneath the street or sidewalk adjacent to the subject property, it is discussed in the surrounding properties section below.

Based on the historical use of the subject property as the H B Service Center gasoline service station between 1969 and 1971, and use of the subject property for the manufacture of electrical components including on-site electroplating operations between 1984 and 2007, it is in the opinion of the environmental professional that historic site use has the potential for adverse effects to the soil, groundwater, and/or soil vapor quality at the site; therefore, historical use of the subject property is identified as a REC.

Surrounding Properties

Based on the large number of database records identified within one mile of the subject property (1,146), Langan limited the review of surrounding properties to adjacent sites and sites within 1/8-mile from the subject property. It is the environmental professional's opinion that based on the dense development of the site area, and former, current and proposed use of the site that the review of the database pertaining to this more limited area is appropriate.

Langan evaluated the following to determine whether additional environmental records with respect to these facilities, including the orphan sites, should be reviewed:

- Case status (i.e., whether a No Further Action letter has been issued or a case has been closed);
- Type of database and whether the presence of soil or ground water contamination is known;
- Distance of the site from the subject property; and,
- Whether the site is upgradient or downgradient of the subject property based on local topography and the anticipated eastern groundwater flow direction.

Database	No. of Sites within 1-mile	Adjacent sites (Y/N)	No. of Adjacent Sites
NPL	1	N	--

Database	No. of Sites within 1/2-mile	Adjacent sites (Y/N)	No. of Adjacent Sites
RCRA-TSDF	e0	N	0

Database	No. of Sites Reported	Adjacent sites (Y/N)	No. of Adjacent Sites
RCRA LQG	9	N	0
RCRA SQG	11	N	0
RCRA CESQG	11	N	0
RCRA NonGen/NLR	231	Y	6
NY SHWS	1	N	0
NY RES DECL	1	N	0
NY VCP	17	N	0
US BROWNFIELDS	2	N	0
ROD	1	N	0

Database	No. of Sites Reported	Adjacent sites (Y/N)	No. of Adjacent Sites
ICIS	1	Y	0
CONSENT	1	N	0
FUSRAP	2	N	0
NY UST	34	Y	1
NY MOSF UST	1	N	0
NY AST	171	Y	3
NY MOSF AST	1	N	0
MANIFEST	438	Y	11
NY Drycleaners	3	N	0
NY E Designation	4	N	0
EDR MGP	5	N	0
EDR Hist Auto	11	Y	3
EDR Hist Cleaner	5	N	0

Database	No. of Sites within 1/8-mile	No. Cases Open/Closed	Open Upgradient Cases	No of Adjacent Sites
NY LTANKS	7	0 / 7	0	2
NY Spills	50	1 / 52	0	2

Langan reviewed the information provided using the above criteria and the findings for adjacent and notable records are discussed below.

Hudson River PCB Contamination

The Hudson River PCB Site is identified as a 200-miles stretch of the river that is impacted by 1.1 million pounds of PCBs discharged by General Electric Co. over thirty years. PCBs adhered to sediments and accumulated downstream of the discharge. The removal of Fort Edward Dam in 1973 resulted in the remobilization and downstream distribution of sediments that had accumulated upstream of the dam. River scouring and erosion have also contributed to redistribution. Non-aqueous phase PCB-bearing oils leaking into the river serve as a continuing source of contamination. Forty hot spots have been identified as sediments containing greater than 50 parts per million PCBs. The Hudson River PCB Site is found in the following databases: National Priorities List, Comprehensive Environmental Response, Compensation, and Liability Information System, RCRA Large-Quantity Generators, US Engineering Controls, US Institutional Controls, NY Historic Leaking Tanks, CONSENT, Record of Decision, and NY Manifest.

It is the opinion of the environmental professional that the potential for adverse environmental impacts to the subject property from these listings is low.

Center Street Associates / Post Brothers Service Station – 363-371 Lafayette Street

The Center Street Associates / Post Brothers Service Station site, located adjacent to the south and hydraulically cross-gradient from the subject property at 363-371 Lafayette Street is identified in the NY UST, NY LTANKS, and EDR Hist Auto databases according to the radius report. This site is identified in the EDR Hist Auto database as 371 Lafayette, a gasoline service station that operated between 1987 and 1994, and as Post Bros. Service Station Inc., a gasoline service station that operated from 1969 to 1976 and 1980 to 1986. The site is listed in the NY UST database as an unregulated/closed site registered in the NYSDEC PBS Program as Facility No. 2-349836 for six 550-gallon gasoline USTs installed in August 1962 and removed in September 2000. A tank test failure was reported to NYSDEC on 19 April 1994 and assigned Spill No. 9400935 as identified in the NY LTANKS database. A subsurface investigation was completed in May 2002 and included installation of two soil borings to evaluate potential subsurface gasoline impacts associated with the failed UST. According to the NYSDEC case narrative provided in the radius report, no visual or olfactory indications of petroleum contamination were observed in either of the soil borings completed; one of the soil borings encountered a sand layer between 22- and 28-feet below street level that was determined to be clean sand backfill associated with construction of the NYCTA Subway Line below Lafayette Street. Sample analytical results were not provided in the radius report, and NYSDEC administratively closed the LTANKS Spill case on 17 May 2002. Although not associated with the address range of the Center Street Associates/Post Brothers Service Station site, two complaints were reported to NYSDEC at the intersection of Lafayette Street and Bond Street related to gasoline odors infiltrating into building basements. Spill No. 9306682 was assigned by NYSDEC on 31 August 1993 and Spill No. 9400898 was assigned by NYSDEC on 19 April 1994 both related to intrusion of gasoline fumes into the basement of 20 Bond Street, located approximately 224-feet southwest and hydraulically upgradient from the subject property. No further information was provided in the radius report; NYSDEC administratively closed Spill No. 9306682 on 3 September 1993 and administratively closed Spill No. 9400898 on 19 June 1994.

Although soil impacts were not identified during a limited subsurface investigation at this former gasoline filling station, soil boring locations were not provided for review and groundwater samples were not collected. Based on the potential for this site to impact regional groundwater quality, it is in the opinion of the environmental

professional that the potential for adverse impacts to the subject property from this site is moderate.

Former Gasoline and Automotive Repair Facilities

The sites discussed below were identified on the Sanborn Fire Insurance Maps as filling stations or automotive repair facilities and are associated with regulatory records as identified in the radius report.

Former Penske – 40 Bond Street

The former Penske trucking site, located approximately 242-feet south and hydraulically cross-gradient from the subject property at 40 Bond Street is shown as a parking lot with one-story building of unspecified use on historical Sanborn Maps between 1921 and 2004. This site is identified in the NY Spills database for identification of gasoline and diesel impacts in soil and groundwater associated with seven 550-gallon USTs removed from the site in 1994; NYSDEC assigned Spill No. 0330066 on 11 February 2004 referencing a release date of 28 June 1994. According to the NYSDEC case narrative provided in the radius report, a UST closure report was never submitted documenting the removal of the seven 550-gallon USTs, prompting additional investigation and reporting during redevelopment of the site with a residential building circa 2004. A Phase II subsurface investigation was completed that included delineation of soil impacts to the extent possible; however, no additional information was provided related to the extent or limitations of the delineation completed. Excavation was completed for site redevelopment and 16 post-excavation soil end-point samples were collected in June 2006. A waterproofing/vapor barrier system and active sub-slab depressurization system were incorporated into site development and NYSDEC administratively closed Spill No. 0330066 on 18 September 2008.

Harry's Automotive Repair / Panoramic Auto Service Inc. – 10-12 Bond Street

The Harry Automotive Repair / Panoramic Auto Service Inc. site, located approximately 240-feet west-southwest and hydraulically cross-gradient of the subject property at 10-12 Bond Street is identified in the EDR Hist Auto database as Harry's Service Station Inc., Harry's Automotive Repair Corp., Amsterdam Mercantile Operating Corp., S&P Automotive, S&P Automotive Enterprises, Amsterdam Merc Operating, Panoramic Auto Service Station, and Apollo Towing Inc. listed as gasoline service stations and/or general automotive repair shops that operated between 1971 and 2003. This location is also shown as a filling station on historic Sanborn Maps between 1950 and 2005.

This site is identified in the NY UST database as 10-12 Bond Street Partners, LLC for three 2,000-gallon USTs of unknown content installed in January 1991 and closed-in-place in October 2006. The former gasoline station is listed in the NYSDEC Spills database as "Con Edison" but is related to the former gasoline station based on the information provided. According to the radius report, a caller advised that there was an ongoing problem at the gasoline service station at 10 Bond Street and NYSDEC assigned Spill No. 9710410 on 10 December 1997. No further information was provided and NYSDEC administratively closed the spill on 10 December 1997. Subsequently, Spill No. 0608806 was assigned by NYSDEC on 31 October 2006 based on soil analytical results collected from the vicinity of three USTs reportedly closed in October 2006. According to the NYSDEC case narrative for Spill No. 9710410, three USTs and connective piping passed a tightness test and were filled with concrete slurry. Soil borings completed around the USTs and dispenser islands did not identify exceedances of NYSDEC Technical and Administrative Guidance Memorandum (TAGM 4046) cleanup criteria. NYSDEC administratively closed Spill No. 0608806 on 15 April 2008 following receipt of a UST closure report and soil sample analytical results.

A&P Service Station – 8 Bond Street

The A&P Service Station, located approximately 349-feet south-southwest and hydraulically downgradient of the subject property is identified in the NY UST database for four 550-gallon gasoline USTs and one 550-gallon UST of unknown contents installed in 1961 and converted to non-regulated use in October 1993. This site is identified in the NY Spills database for two reports of gasoline fumes in the basement of the 8 Bond Street building reported to NYSDEC and assigned Spill Nos. 9707585 and 9707584 on 26 September 1997. According to the NYSDEC case narrative for Spill No. 9707585 provided in the radius report, gasoline vapors were reportedly intruding into the basement of 8 Bond Street from the gasoline station at the adjacent 10-12 Bond Street site discussed above. The potential vapor intrusion pathway was identified to be a leaking sewer main servicing both buildings; vapors subsided following actions to seal the leaking sewer main and NYSDEC administratively closed Spill No. 9707585 on 25 February 1998. As Spill No. 9707584 was a duplicate report of Spill No. 9707585, it was administratively closed by NYSDEC on 26 September 1997 referencing Spill No. 9707585.

Former Gasoline Station - 372 Lafayette Street

The 372 Lafayette Street site, located approximately 86-feet west-northwest and hydraulically cross-gradient from the subject property is listed in the NY UST, NY Spills, and NY VCP databases. According to the NYSDEC Spills case narrative

provided in the radius report, the former gasoline station site was being redeveloped in 2013 and a total of five 5,000-gallon USTs of unknown contents, five USTs of unknown contents and capacity, and eleven 550-gallon USTs presumed to have been filled with gasoline. Excavation for site development was performed under oversight of the New York City Office of Environmental Remediation (NYCOER) via the E-Designation and NY Voluntary Cleanup Program (VCP).

NYSDEC was notified when two 550-gallon USTs removed from the excavation were observed to have holes in the bottoms with underlying soil impacts; as such, Spill No. 1304085 was assigned on 16 July 2013. A total of approximately 530-tons of petroleum impacted soil were removed from the removal excavation of the 11 550-gallon USTs, which are registered in the NYSDEC PBS database as closed-removed in March 2013 and July 2013. Excavation for removal of the USTs was completed to approximately 8-feet below sidewalk grade, and additional excavation for site redevelopment under an NYCOER-approved Remedial Action Work Plan (RAWP) was completed to a depth of approximately 13-feet below sidewalk grade. Endpoint samples collected from the bottom of the development excavation did not detect exceedances for VOCs and SVOCs. Minor petroleum impacts including ethylbenzene, and xylenes were detected in groundwater at the site, but were not required to be investigated or remediated by NYSDEC. Several low-level VOCs (unspecified) were also detected in soil vapor; as such, the proposed building included incorporation of a waterproofing/vapor barrier system and a passive sub-slab depressurization system (SSDS) below the building foundation. As excavation for site redevelopment achieved removal of the contamination source, and future building occupants are protected from residual impacts in groundwater and soil vapor by the vapor barrier system and passive SSDS, NYSDEC administratively closed Spill No. 1304085 on 22 May 2015.

RCRA Non-Generators/No Longer Reporting (NonGen/NLR)

The RCRA NonGen database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). RCRA Non-Generators do not currently generate hazardous waste.

According to EDR, there are 231 RCRA NonGen/NLR sites reported within 1/4-mile of the subject property with 69 RCRA NonGen/NLR sites within 1/8-mile of the subject property. The following RCRA NonGen/NLR sites are located adjacent to the subject property:

- Petersburg Press Inc. – 380 Lafayette Street
- NYU – 383 Lafayette Street
- Con Edison Manhole: 59368 – 379 Lafayette Street
- Con Edison Manhole: 35859 – Northeast Corner of Lafayette Street and Great Jones Street
- Con Edison – 30-32 East 4th Street
- Con Edison Service Box: 35864 – 33 Great Jones Street

Petersburg Press Inc., located adjacent to the west and hydraulically cross-gradient from the subject property at 380 Lafayette Street is identified in the RCRA NonGen/NLR database for forms received by the USEPA on 1 January 2007 classifying the site as a non-generator of hazardous waste. Historical generator information classified the site as a verified non-generator in 2006 and as a conditionally exempt small quantity generator (CESQG) on 29 July 1996. This site is also identified in the NY Manifest database for the disposal of ignitable waste in 1996. No violations were reported for this facility. This address is also listed in the NY AST database as discussed below.

The New York University site, located adjacent to the north and hydraulically cross-gradient from the subject property at 383 Lafayette Street is listed in the RCRA NonGen/NLR database for forms received by the USEPA on 20 June 2016 classifying the site as a non-generator of hazardous waste. Historical generator information classified the site as a large quantity generator (LQG) of soils, solids, sludges, clothing, rags, and dredge material impacted with polychlorinated biphenyls (PCBs) in 2016, and of waste impacted with hazardous concentrations of lead in 2016 and 2014. According to the 2017 hazardous waste biennial reporting year, this site generated 97,645 pounds of waste impacted with lead. No violations were reported for this facility. The NYU site is listed in the NY Manifest and NJ Manifest databases for disposal of an unreported type of hazardous waste in 2015. This site is also identified in the NY AST database as discussed below.

Con Edison Manhole: 59368, located adjacent to the northwest of the subject property and Con Edison Manhole: 35859, located adjacent to the west of the subject property, are both hydraulically cross-gradient from the subject property and identified in the RCRA NonGen/NLR database for forms received by the USEPA on 6 March 2012 and 23 June 2011, respectively, classifying these sites as non-generators of hazardous waste. Historical generator information classified Con Edison Manhole: 59368 as a non-generator in June 2011 and as a CESQG of an unspecified type of hazardous

waste in May 2011. Historical generator information classified Con Edison Manhole: 35859 as a CESQG of an unreported type of hazardous waste in May 2011. Both of these Con Edison Manhole sites were listed in the NY Manifest and NJ Manifest databases for disposal of waste impacted with hazardous concentrations of lead in 2011. No violations were reported for either facility.

The Con Edison Site at 30-32 East 4th Street, located adjacent to the north and hydraulically cross-gradient from the subject property is listed in the RCRA NonGen/NLR database for forms received by the USEPA on 6 October 2015 classifying the site as a non-generator of hazardous waste. Historical generator information classified the site as a SQG of an unreported type of hazardous waste in October 2015. This site is listed in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead in 2015, and in the FINDS and ECHO databases for being active in the RCRA Program. No violations were reported for this facility.

The Con Edison Service Box: 35864, located adjacent to the south and hydraulically cross-gradient from the subject property is identified in the RCRA NonGen/NLR database for forms received by the USEPA in 2012, classifying the site as a non-generator of hazardous waste. Historical generator information classified the site as a CESQG of an unreported type of hazardous waste in 2012. This facility is listed in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead in 2012. No violations were reported for this facility.

Due to the lack of violations for these facilities and isolated hazardous waste generation and disposal associated with Con Edison sites, it is in the opinion of the environmental professional that the potential for adverse impacts to the subject property from these sites is low.

NY UST

The UST database contains USTs registered with the NYSDEC under the PBS division. These USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the NYSDEC PBS Database.

According to the Radius Report provided by EDR, there are 34 NY UST sites within 1/4-mile of the subject property. The only site located adjacent to the subject property is the 231 Centre Street Associates site, located at 371 Lafayette Street which is discussed in detail above. Additionally, former gasoline stations and/or

automotive repair sites at 8 Bond Street, 10-12 Bond Street, and 372 Lafayette Street, although not adjacent to the subject property, are discussed in detail above.

The following NY UST sites located within 1/8-mile of the subject property are associated with NY Spills or LTANKS cases:

- Lafayette Women's Shelter – 350 Lafayette Street
- Kalodop Park Corp. – 403 Lafayette Street
- Former Cooper Hotel – 2 Cooper Square
- National Audubon Society – 700 Broadway
- Downtown Automotive Inc. – 326 Bowery Street
- 30 Cooper Square

Each of these sites are located over 250-feet from the subject property and are associated with closed or inactive USTs, with the exception of the Lafayette Women's Shelter locate approximately 272-feet west-southwest and hydraulically downgradient from the subject property at 350 Lafayette Street. The Lafayette Women's Shelter is listed in the NY UST database for one 2,500-gallon No. 2 fuel oil UST installed in January 1970. This site is identified in the NY LTANKS database due to a tank overfill that was reported to NYSDEC on 21 January 1992 and assigned Spill No. 9110940. All of the NY Spills and/or NY LTANKS cases associated with the above-listed sites were administratively closed by NYSDEC between 1992 and 2017.

Based on the historical gasoline filling stations and/or automotive repair facilities identified in the NY UST database that are discussed in detail above, it is in the opinion of the environmental professional that the potential for subsurface impacts to the subject property from these adjacent and/or notable sites is moderate.

NY AST

The Aboveground Storage Tank (AST) database contains NYSDEC registered ASTs. ASTs are regulated under Subtitle I of RCRA. The information for this database comes from the NYSDEC PBS Database.

According to the Radius Report provided by EDR, there are 171 NY AST sites located within 1/4-mile of the subject property. The following NY AST sites are located adjacent to the subject property:

- S.E.G. Holdings LLC – 380 Lafayette Street
- New York University – 383 Lafayette Street
- 28-30 E. 4th Street Housing Corp. – 28-30 East 4th Street

S.E.G. Holdings LLC, located adjacent to the north-northwest and hydraulically upgradient from the subject property at 380 Lafayette Street is identified in the NY AST database for one 5,000-gallon No. 2 fuel oil AST installed in January 1970.

The New York University site, located adjacent to the north and hydraulically upgradient from the subject property at 383 Lafayette Street is identified in the NY AST database for one 1,500-gallon AST containing No. 2 fuel oil installed in February 1956 and closed-removed in September 2014.

The 28-30 E. 4th Street Housing Corp. site, located adjacent to the northeast and hydraulically upgradient from the subject property is identified in the NY AST database for one 1,500-gallon No. 2 fuel oil AST installed in August 2005. This site is also identified in the NY Spills database for the release of approximately 4-gallons of No. 4 fuel oil as the result of a tank overfill due to a defective level gauge. The release was reported to NYSDEC and assigned Spill No. 9911688 on 26 February 2003. According to the NYSDEC case narrative provided in the radius report, an unspecified amount of petroleum reached a floor drain; however, following a reported cleanup NYSDEC administratively closed Spill No. 9911688 on 26 February 2003.

It is in the opinion of the environmental professional that the potential for adverse impacts from these sites is low.

MANIFEST

The NY Manifest, NJ Manifest, RI Manifest, and PA Manifest databases list and track hazardous waste from the generator through transporters to a TSD facility.

According to the radius report, there are 331 NY Manifest, 9 PA Manifest, 2 RI Manifest, and 96 NJ Manifest sites within 1/4-mile of the subject property. The following Manifest sites are located adjacent to the subject property:

- Con Edison Manhole:59368 – 379 Lafayette Street
- Con Edison Manhole: 35859 – Northeast Intersection of Lafayette Street and Great Jones Road
- Petersburg Press Inc. – 380 Lafayette Street

- Con Edison – 30-32 East 4th Street
- Con Edison – 22 East 4th Street
- NYU – 383 Lafayette Street
- Con Edison Service Box: 35864 – 33 Great Jones Street

The Con Edison Manhole: 59368 site, located adjacent to the west of the subject property, and the Con Edison Manhole: 35859 site, located adjacent to the southwest of the subject property, are identified in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead in 2011.

The Petersburg Press Inc. site, located adjacent to the west of the subject property is identified in the NY Manifest database for the disposal of non-listed ignitable waste in 1996.

The Con Edison site, located adjacent to the north of the subject property at 30-32 East 4th Street is identified in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead and an unreported type of hazardous waste in 2015.

The Con Edison site located adjacent to the north of the subject property at 22 East 4th Street is identified in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead in 2014.

The NYU site, located adjacent to the north of the subject property at 383 Lafayette Street is identified in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead in 2015, and for disposal of an unreported type of hazardous waste in 2014.

Con Edison Service Box: 35864, located adjacent to the south of the subject property at 33 Great Jones Street, is identified in the NY Manifest and NJ Manifest databases for the disposal of waste impacted with hazardous concentrations of lead in 2012.

No violations were reported for these facilities.

Due to the lack of violations for these facilities, it is in the opinion of the environmental professional that the potential for adverse impacts to the subject property from these sites is low.

EDR Hist Auto

EDR searched selected national collections of business directories and collected listings of potential gas station/filling station/service station sites. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

According to the Radius Report provided by EDR, there are 11 EDR Hist Auto sites located within 1/8-mile of the subject property. The following EDR Hist Auto sites are located adjacent to the subject property and are discussed in detail at the beginning of this section:

- 371 Lafayette Street
- Post Bros. Service Station Inc. – 363-371 Lafayette Street
- Post Bros. Service Station – 361 Lafayette Street

These sites are discussed in detail in detail at the beginning of this section.

NY LTANKS

The NY LTANKS database contains an inventory of reported leaking storage tank incidents from April 1986 to the present. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents identified within this database are either tank test failures, tank failures or tank overfills.

According to the Radius Report provided by EDR, there are 7 NY LTANKS sites located within 1/8-mile of the subject property; each of the spill cases associated with these sites was administratively closed between 1992 and 2013. The following NY LTANKS sites are located adjacent to the subject property:

- 371 Lafayette Street
- 30 East 4th Street

The 371 Lafayette Street site is associated with the former Center Street Associates / Post Brothers Service Station site located adjacent to the south of the subject property and is discussed in detail at the beginning of this section.

The 30 East 4th Street site is identified in the NY LTANKS database for the release of an unspecified amount of No. 4 fuel oil that occurred during a tank overfill on 19 May 1999 and was assigned Spill No. 9502124 by NYSDEC. According to the NYSDEC case narrative provided by EDR, Spill No. 9502124 was administratively closed by NYSDEC on 19 May 1995 following a reported cleanup. No additional information was provided.

It is in the opinion of the environmental professional that the potential for subsurface impacts to the subject property from the 371 Lafayette Street site is moderate, as discussed in detail at the beginning of this section.

NY Spills

The NY Spills database includes data collected on spills reported to NYSDEC. It includes spills active as of April 1, 1986, as well as spills occurring since this date.

According to the radius report provided by EDR, there are 50 NY Spills sites located within 1/8-mile of the subject property; each of the NY Spills cases were administratively closed between 1992 and 2017, with the exception of the Commercial building at 644 Broadway. This site is listed in the NY Spills database for the release of approximately 100-gallons of No. 2 fuel oil onto the concrete basement floor of a commercial building during a fuel delivery that occurred on 29 January 2018 and was assigned Spill No. 1709872 by NYSDEC. According to the NYSDEC case narrative provided in the radius report, the release was attributed to a ruptured fill line that spilled the fuel oil onto the concrete basement floor and caused odors to permeate the building. A site inspection including screening within the occupied spaces of the building using a photoionization detector (PID) was completed; however, no additional information was provided regarding cleanup activities completed associated with the release.

The following NY Spills sites are located adjacent to the subject property:

- Harwood Property – 25 Great Jones Street
- Spill Number 9911688 – 38-30 East 4th Street

The Harwood Property, located adjacent to the south of the subject property is listed in the NY Spills database for the deliberate release of an unspecified quantity of chemical agents used in photographic development reported to NYSDEC on 24 May 1996 and assigned Spill No. 9604778. According to the NYSDEC case narrative provided in the radius report, the tenant deliberately spilled the unspecified amount of photography development chemicals during an eviction from the property. A cleanup was reportedly completed and NYSDEC administratively closed Spill No. 9604778 on 12 July 1996. No further information was provided.

Spill Number 9911688, located adjacent to the north of the subject property is listed in the NY Spills database for the release of approximately 5-gallons of No. 4 fuel oil that occurred during a tank overfill on 7 January 2000 and was assigned Spill No. 9911688 by NYSDEC. The overfill was reportedly attributed to a faulty gauge and an unspecified amount of petroleum affected a floor drain. No additional information was provided and NYSDEC administratively closed Spill No. 9911688 on 26 February 2003.

Government Databases Review Conclusions

The following adjacent sites (described in detail above) could potentially impact subsurface conditions at the subject property, groundwater in particular, and may pose a moderate risk to the subject property and future redevelopment activities:

- Center Street Associates / Post Brothers Service Station – 363-371 Lafayette Street
- Former Penske – 40 Bond Street
- Harry's Automotive Repair / Panoramic Auto Service Inc. – 10-12 Bond Street
- A&P Service Station – 8 Bond Street
- Former Gasoline Station – 372 Lafayette Street

Based on Langan's review of the sites identified above, environmental impacts to the subject property from the remainder of these sites are not anticipated. However, it should be noted that 1,146 sites were identified in the radius report and the potential exists that these urban sites may have a cumulative impact on regional groundwater quality. It is the opinion of the environmental profession that this represents a business environmental risk.

Additionally, the potential for vapor intrusion impacts to the subject property from onsite or nearby sources was evaluated. No specific potential vapor intrusion concerns (pVICs) were identified as part of this Phase I ESA; however, it should be noted that due to the

number of spill sites identified in the area of the subject property and the associated potential for groundwater impacts in the site area, vapor intrusion issues at the site may exist.

8.0 GOVERNMENT AGENCY RECORDS REVIEW

Federal, state and local agencies were contacted via written correspondence, telephone interviews and/or personnel interviews regarding records of environmental concerns, violations, and/or permits, or any other potentially environmentally-relevant records on the subject property. In additional, government information that was readily available online on government websites was also reviewed. A listing of agencies/individuals contacted by Langan as part of this ESA is provided in Table 1. Copies of government correspondence are provided in Appendix F.

US Environmental Protection Agency (USEPA)

The USEPA online FOIL request form was submitted for the subject property. In a letter dated 12 June 2018, Langan received a response from the USEPA indicating that all records are publically available on the online database (https://www.epa.gov/enviro/frs-query-page). According to the USEPA database, no records are available for the subject property. If any additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

Langan also reviewed the RCRAInfo Search, Enforcement and Compliance History Online, and the Superfund Enterprise Management System (SEMS) databases maintained online by USEPA. The subject property was identified on the USEPA ECHO database confirmed the records identified in the radius report.

US Fish and Wildlife Service (US FWS)

Information regarding critical habitats or endangered species with the vicinity of the subject property was obtained from the US FWS Information Service Information for Planning and Conservation online database (https://ecos.fws.gov/ipac/). No Federally-listed or proposed endangered or threatened species were known to exist at the subject property.

New York State Department of Environmental Conservation Region 2

Fawzy Abdelsadek, the Regional Enforcement Coordinator, was contacted by Langan and written file review requests were submitted for the subject property. In an email

dated 4 June 2018 Langan received a response acknowledging receipt of the request. If any additional pertinent information is provided subsequent to issuance of this report, it will be provided as an addendum. Langan also reviewed the Environmental Site Database records maintained online by the NYSDEC which confirmed the records identified in the radius report.

NYSDEC Division of Fish, Wildlife, & Marine Resources

Langan reviewed records maintained online on the NYSDEC Environmental Resource Mapper (http://www.dec.ny.gov/gis/erm/) which revealed that no state-designated significant natural communities and rare plants and animals are found in the vicinity of the subject property. Based on these results, a written records request was not submitted.

New York State Department of Health (NYSDOH)

The NYSDOH Records Access Officer was contacted by Langan and a written file review request was submitted for the subject property. To date, no response has been received by Langan regarding this request. If any additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum

New York City Department of Environmental Protection (NYCDEP)

The NYCDEP online FOIL request form was submitted for the subject property. In a letter dated 1 February 2013, Langan received acknowledgement from the NYCDEP of the records request. In a letter dated 7 February 2013 Langan received a response from the NYCDEP Division of Pollution Control and Monitoring indicating that no records are available for the subject property. If any additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

According to records maintained online by the NYCDEP Clean Air Tracking System (CATS), two cancelled applications for a boiler fired by No. 2 fuel oil dated December 1998 and September 1983 are documented for the subject property at 30 Great Jones Street.

New York City Department of Health & Mental Hygiene (NYC DOHMH)

Ms. Rene Bryant, the NYC DOHMH Records Access Officer, was contacted by Langan and a written file review request was submitted for the subject property. To date, no response has been received by Langan regarding this request. If any additional pertinent

information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

New York City Department of City Planning (NYC DCP)

An electronic version (effective zoning date 11 October 2012) of the NYC Zoning Map for the subject property was downloaded from the NYC DCP website (http://www.nyc.gov/html/dcp/html/zone/zh_zmaptable.shtml).

New York City Mayor's Office of Environmental Coordination (NYC MOEC)

Records maintained online by NYC MOEC through the CEQR Access Portal (https://a002-ceqraccess.nyc.gov/ceqr/) were reviewed on 11 June 2018. The subject property was not identified as being a part of the CEQR program.

'E'-Designation Status

The New York City Department of City Planning coordinated a program identifying properties for special environmental concerns based on documented historical use, neighborhood noise concerns, and neighborhood air quality issues. These properties are identified on 'E'-designated sites on zoning maps and in the NYC Department of Buildings (NYCDOB) Building Information System (BIS) database. The NYCDOB is restricted from issuing building permits for the property until the NYC Mayor's Office of Environmental Remediation (NYC OER) has reviewed information prepared by an environmental professional and made a determination to issue of "Notice-of-No-Objection" or a "Notice-to-Proceed" to the NYCDOB. Prior to the NYCOER's creation in 2008, the NYC Department of Environmental Protection (NYCDEP) conducted these reviews.

Langan reviewed the following information sources to determine if the subject property is listed as an 'E'-designated property: CEQR Environmental Designations List dated 6 June 2018 (http://www1.nyc.gov/assets/planning/download/pdf/zoning/zoning-text/appendixc_tab1.pdf?r=031416), CEQR Restrictive Declaration List dated 15 May 2018 (http://www1.nyc.gov/assets/planning/download/pdf/zoning/zoning-text/appendixc_tab2.pdf?v=020416), and NYCDOB BIS on 8 June 2018 (http://a810-bisweb.nyc.gov/bisweb/bispi00.jsp). The subject property was not listed as an E'-designated site based on these resources.

Fire Department of New York City (FDNY)

Information regarding the presence of petroleum or chemical storage tanks was requested from the FDNY. To date, no response has been received to our written

request to the New York City Fire Department. If any additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

New York City Department of Buildings (NYC DOB)

Langan completed a limited review of available records maintained online by the NYC DOB. Certificates of Occupancy for Lot 17 (375-379 Lafayette Street) identified the site at a gasoline service station in 1931 and 1938. Subsequent Certificates of Occupancy classified the site as a parking lot with one-story temporary shelter for attendants between 1972 and 2010.

New York City Department of Finance (NYC DOF)

Langan completed a limited review of available records maintained online by the NYC DOF to determine current and former site ownership (http://www.nyc.gov/html/dof/html/home/home.shtml). According to the DOF, Lots 17 and 52 of the subject property are currently owned by 375 Lafayette Street Properties, LLC, and Lot 56 is currently owned by SP Great Jones, LLC. Former ownership history obtained from is summarized in the following table:

Address	Owner's Name	Date of Ownership
375 Lafayette Street (Lot 17)	Mobil Oil Corporation	Prior to 6/30/1971
	Edison Jones Corp.	6/30/1971
	Edison Washington Corp.	12/29/1971
	Abbie G. Goteman Trust	2/7/1974
	375 Lafayette Street Properties, LLC	10/1/1998
30 Great Jones Street (Lot 56)	30 Great Jones St. Corp.	Prior to 11/8/1976
	Harcy Realty Corp.	11/8/1976
	SP Great Jones, LLC	9/19/2007
32 Great Jones Street (Lot 52)	Millou Realty Corp.	Prior to 4/26/1971
	Edison Jones Corp.	4/26/1971
	Abbie G. Gottesman Trust	2/7/1974
	375 Lafayette Street Properties, LLC	10/1/1998

The ownership information listed above provides no additional information regarding environmental conditions related to past usage different than represented by review of other historical information sources.

9.0 SITE RECONNAISSANCE

Langan conducted an inspection of the site on 4 June 2018. The inspection included a walk-through inspection of the entire site for the purposes of identifying Recognized Environmental Conditions (RECs). Typical RECs may include:

Drum storage	Dumpsters	Aboveground storage tanks	Stained areas
Drains and Sumps	Wells	Underground storage tanks	Pump stations
Waste piles	Landfills	Loading and transfer areas	Boiler rooms
Pits, Ponds, Lagoons	Swales	Process air vents	Process sinks
Storm sewers	Trenches	Detention ponds	PCBs
Impoundments	Lagoons	Floor drains and piping	Transformers
Septic systems	Dry wells	Waste treatment areas	Capacitors
Rail spurs	Incinerators	Compressor discharges	Odors
Pools of liquid	Wastewater	Stressed vegetation	Surface waters

Limiting conditions encountered during the inspection of the site included the following:

- An on-site hydraulic oil compressor connected to the above-grade car parking racks was in operation and could not be inspected for internal leaks; and,
- Accumulated debris in the bottom of a concrete lined pit in the southeast corner of the subject property prevented inspection of the integrity of the bottom of the pit.

Photographs of the subject property taken during the site inspection are provided in Appendix G. Langan was accompanied by Naveen Liyanaarachchi, assistant manager of the parking facility, who provided access to onsite buildings and answered questions during the site inspection. A questionnaire was completed by the site manager and is included as Appendix B. The inspection included a walk-through inspection of the entire site for the purposes of identifying Recognized Environmental Conditions (RECs) as detailed below.

The subject property is currently an asphalt-paved parking lot at street level that contains a one-story parking attendant's office on the southern portion of the property. Incoming electric and water service connections feeding the on-site building were observed on the southern and western faces of the one-story building. Four-level metal car parking racks were observed throughout the subject property, with each parking bay containing one to two hydraulic pistons mounted within the metal rack support structure. Localized staining indicative of minor hydraulic oil leaks were observed

throughout the property; however, stained areas were observed on top of asphalt pavement which is in good condition with minimal cracking observed. Hydraulic oil is supplied to the above-grade lifts from a hydraulic oil compressor with internal hydraulic oil reservoir located on the northwest portion of the subject property. The hydraulic oil compressor could not be opened for inspection; however, it was located on a concrete pad with minimal staining observed in the vicinity of the compressor. Metal distribution piping connects the above-grade hydraulic oil compressor with the hydraulic pistons at each lift bay and traverses the property along the northern boundary. No staining was observed at connection points in the above-grade hydraulic lines.

One small metal grate with localized staining was observed in the southeast corner of the subject property, covering an approximately 6-cubic foot concrete lined pit. Two hydraulic connections not in use were observed at pavement level, continued below grade within the concrete lined pit, and entered an approximately 4-inch piping conduit in the western sidewall of the pit. A termination point of the piping conduit and hydraulic lines was not observed during the site inspection, and may be buried below the parking lot.

The integrity of the bottom of the concrete lined pit could not be determined due to an accumulation of sediment and debris within the pit. According to on-site personnel, the former use of the pit and lines was unknown. Sheen was observed on accumulated water in the vicinity of the pit and hydraulic pistons connected to the car parking racks.

Adjacent Properties

A visual inspection of adjoining properties from the subject property line, public rights-of-way or other vantage point (e.g. aerial photography) including a visual inspection where hazardous substances may be or may have been stored, treated, handled or disposed was also conducted.

Limiting conditions encountered during the inspection of adjoining properties were encountered due to the dense urban nature of the surrounding areas which only allowed for limited line of sight that did not extend to areas where hazardous materials or substances might be stored.

Properties located adjacent to the subject property consist of commercial and residential buildings. Fill ports and vent pipes were identified in the sidewalk in front of the adjacent properties to the north at 381 Lafayette Street and 28-30 East 4th Street, to the east of the subject property at 42 Great Jones Road and 48 Great Jones Road, and

south of the subject property across Great Jones Road at 35, 43, and 47 Great Jones Road. Additionally a vent pipe was observed in the sidewalk in front of 47 Great Jones Road, but no fill port was observed in the adjacent sidewalk.

10.0 ADDITIONAL ISSUES

The following items fall outside the scope of ASTM 1527-13, however Langan can and often does provide these services to its clients if specifically requested and included in the proposed scope of work or are issues that may impact current or proposed site use.

10.1 Wetlands/Floodplain Designation

Langan reviewed United States Fish and Wildlife National Wetland Inventory (NWI) and New York State Freshwater Wetlands maps. Based on these documents no mapped wetlands are listed on the subject property. No evidence of the presence of existing onsite wetlands was identified during Langan's site inspection.

10.2 Protected Endangered Species / Critical Habitats

A determination regarding the potential presence of protected or endangered species and critical habitats on or near the subject property was not conducted as part of this ESA. This determination is often required in order to receive state or federal grants, loans, and/or permits.

Based on historic use of the subject property and the current condition and urban setting of the site, the potential presence of threatened or endangered (T&E) species on the site is low. A request for information regarding T&E species on the site was provided to the United States Fish and Wildlife Service (USFWS). This correspondence is discussed in detail in Section 8.0.

10.3 Asbestos

In 1973, use of sprayed on fireproofing on structural building components was prohibited by the EPA. On July 12, 1989, EPA issued a final rule banning most friable asbestos-containing products. The following specific asbestos-containing products remain banned: flooring felt, roll board, and corrugated, commercial, or specialty paper. In addition, the regulation continues to ban the use of asbestos in products that have not historically contained asbestos, otherwise referred to as "new uses" of asbestos. Use of asbestos

in textured paint and in patching compounds used on wall and ceiling joints was banned in 1977.

The subject property is currently developed with an asphalt-paved parking lot and contains a one-story parking attendant's booth and metal car parking racks; as such, the potential for potential asbestos containing materials to exist at the subject property is low.

10.4 Lead-based Paint

In 1977, the Consumer Product Safety Commission (CPSC) banned the use of lead based paint (LBP) in housing and restricted maximum levels in lead in new residential paint to less than 0.05% by weight. A lead-based paint inspection was not conducted as part of this ESA. Based on the current use of the subject property as an asphalt-paved parking lot at street level with the only site building being a one-story parking attendant's booth, the potential for the presence of LBP in the one-story building is low. However, the metal car parking lifts were observed to be painted and are typically disassembled and reused between parking facilities. As such, the potential exists for LBP to be present on the above-grade parking structures. Painted surfaces on the above-grade car parking structures generally appeared to be in good condition, with little paint peeling and cracking.

10.5 Lead in Drinking Water

A lead in drinking water survey of the existing building was not conducted as part of this ESA.

10.6 Indoor Air / Microbial Assessment (Mold)

A mold survey of the existing building was not conducted as part of this ESA.

10.7 Radon

The subject property is located in a Tier 3 Zone as identified by USEPA based on sampling conducted of buildings within the site area. The Tier 3 Zone is considered an area of low radon gas intrusion potential with typically concentrations less than 2 pCi/liter. A radon survey of the existing building was not conducted as part of this ESA. Radon test results from adjacent or surrounding properties are not necessarily indicative of radon conditions on the

subject property. As no building specific radon survey documentation was provided to Langan, no opinion regarding potential risks associated with radon gas exposure can be made.

As per USEPA guidelines, the only way to assess potential radon gas exposure risks is to conduct a radon assessment. In addition, the US EPA recommends that follow-up tests on large buildings should be conducted when major modifications are made either to the building structure or HVAC system or the HVAC system's operation settings.

10.8 Historical and Archaeological Review

Langan reviewed the NYCityMap (http://maps.nyc.gov/doitt/nycitymap/) to review the potential presence of historical landmark buildings or historic districts near the subject property. The 376-380 Lafayette Street building, located adjacent to the west of the subject property across Lafayette Street, is a city landmark designated on 17 May 1966 by the New York City Landmarks Preservation Commission (NYCLPC). The Firehouse Engine Co. Thirty-Three building, located to the west of the subject property on Block 531 at 42 Great Jones Street is a city landmark designated on 12 November 1968. The subject property is located within the NoHo Historic District Extension (LP-02287), which was designed as a historic district by the NYCLPC on 13 May 2008.

In addition, Langan reviewed the NYCLPC online historic maps (https://nyclpc.maps.arcgis.com/apps/webappviewer/index.html?id=93a88691cace4067828b1eede432022b) which confirmed the location of the subject property within the NoHO Historic District Extension.

Langan also reviewed the NYSHPO online database (http://nysparks.com/shpo/online-tools/). As of 13 June 2018, the adjacent property to the west of the subject property across Lafayette Street at 376-380 Lafayette Street is identified in the NYSHPO database as a National Register Listed site as of 28 December 1979, and as a State Register Listed site as of 23 June 1980. The Firehouse: Engine Co. 33 building, to the west of the subject property at 44 Great Jones Street is identified in the NYSHPO database as a National Register Listed site as of 16 March 1972 and as a State Register Listed site as of 23 June 1980.

Additionally, the adjacent property to the north of the subject property at 381 Lafayette Street is identified in the NYSHPO database as "undetermined," meaning that the NYSHPO is aware of the historic status of the buildings but does not have enough information to make a determination about a landmark status.

11.0 DEVIATIONS

This Phase I ESA conforms with ASTM with the following deviations noted:

- Property use was only determined back to 1895, not to first development, as historical property records were not reasonably available;
- Data gaps in excess of 5 years were encountered during the review of historic resources where property usage was apparently inconsistent between 1921 and 1950;
- Government agencies that have not responded to record review inquiries are listed above - additional pertinent information provided to Langan subsequent to the issuance of this report will be provided in an addendum;
- Limited access was provided to the existing buildings as part of this ESA access as identified in Section 9.0;
- Based on the large number of database records identified within one mile of the subject property (1,146), Langan limited the review of surrounding properties to adjacent sites and sites within 1/8-mile from the subject property.
- An assessment of the current property value versus the proposed sale price of the property was not completed as this information was not provided by the User;
- Interviews of former business operators were not conducted; and,
- Interviews of property owners were not conducted;

It is the opinion of the reviewing Environmental Professional that the above-deficiencies will not detrimentally affect the identification of potential recognized environmental conditions. This opinion is based on the following factors:

- The site was historically occupied by a gasoline filling station and auto repair facilities from at least 1950 to 1972 following the data gap between 1921 and 1950. Although the presence of the on-site gasoline filling station was not

identified on historic Sanborn Maps prior to 1950, it is in the opinion of the environmental professional that this will not detrimentally affect the identification of potential recognized environmental conditions.

- Langan limited the database review to adjacent sites and sites within 1/8-mile from the subject property. It is the environmental professional's opinion that based on the dense development of the site area, and former, current and proposed use of the site that the review of the database pertaining to this more limited area is appropriate and will not detrimentally affect the identification of potential recognized environmental conditions.

12.0 FINDINGS/OPINIONS

Based on information obtained during the visual inspection of the subject property, review of environmental databases and historic information, and contact with federal/state/local official agencies, the following recognized environmental conditions (RECs), de minimis conditions, and business environmental risks that may impact proposed redevelopment of the site were identified:

1. Potential impacts from current and historical site use;
2. Potential impacts from current and historical operations conducted at adjacent and nearby properties;
3. Potential presence of historic fill material;
4. Potential presence of undocumented underground storage tanks; and,
5. Minor hydraulic oil release and staining.

It is the opinion of the environmental professional that historical site operations as a gasoline filling station (1950-1972) an electronics manufacturer including electroplating operations (1960-2007), paper manufacturing (1938-1973), a printing company (1927), and hat making (1927-1963) involving the storage, generation, and release of hazardous wastes and current site operations as a parking lot including the use and storage of hydraulic oil have the potential to have adversely impacted the subsurface; therefore, Finding 1 represents a REC. It is in the opinion of the environmental professional that historic site operations conducted at adjacent and nearby properties including six gasoline filling stations and/or auto repair facilities between 1921 and 2005, have the potential to have impacted regional groundwater conditions; however, as these impacts are common to densely developed urban areas and may only affect site redevelopment

activities, Finding 2 is identified as a business environmental risk (BER). It is the opinion of the environmental professional that historic fill may be present in the subsurface at the site which would impact any future site redevelopment considerations. As this condition is consistent in the urban setting that the subject property is located in, Finding 3 represents a BER. It is the opinion of the environmental professional that undocumented heating oil USTs may be present at the subject property associated with former residential, commercial, and light manufacturing buildings. Therefore, Finding 4 represents a business environmental risk. Localized staining on top of asphalt and/or concrete surfaces were observed during the site inspection associated with abovegrade hydraulic pistons and distribution lines; therefore, Finding 5 represents a De Minimis condition.

13.0 CONCLUSIONS

Langan has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-13 of a ±19,741-square foot site located at 375 Lafayette Street, New York, New York, the subject property. Any exceptions to, or deletions from, this practice are described in Section 11.0 of this report. Based on information obtained during the visual inspection of the subject property, review of environmental databases and historic information, and contact with federal/state/local official agencies, this assessment has revealed the following recognized environmental conditions (RECs) in connection with the property:

Recognized Environmental Conditions

It is the opinion of the environmental professional that the following represent RECs:

Potential Impacts from Current and Historical Site Use

Based on the review of historic Sanborn Maps and the radius report, the western portion of the subject property was occupied by a gasoline filling station with two one-story auto service buildings between at least 1950 and 1972. No UST registration documents were identified for the subject property in the radius report, or in the NYSDEC PBS on-line database including any documentation of closure or removal of USTs associated with the former gasoline filling station. Due to the historical site use as a gasoline filling station and current site use as a parking lot at street level with no basement level, the potential exists for gasoline USTs to remain in the subsurface of the subject property which may not have been properly closed or removed in accordance with NYSDEC regulations.

Other historical subject property operations with potential to cause adverse impacts to the subsurface include a printing company on the eastern portion of the subject property at 36 Great Jones Street in 1921 as identified on the Sanborn Maps and an electronics company identified at 30 Great Jones Street in the radius report. Records associated with the electronics company included generation and disposal of hazardous waste used in electroplating operations between 1984 and 2007 and a formal enforcement action filed against the Concord Electronics Corporation in 1985. Although all formal enforcement actions and written informal violations issued to the Concord Electronics Corporation achieved compliance, no documentation was provided regarding the nature of the violations issued, corrective measures taken, or potential impacts to subsurface conditions as a result of former electronics manufacture at this site.

Due to the potential use of chemicals associated with historical and current operations and the duration of these activities and the potential for gasoline USTs to be present in the subsurface, it is the opinion of the environmental professional that the historical and current site use has the potential to impact subsurface conditions at the site. As such, the historical and current use of the subject property is considered a REC.

14.0 QUALIFICATIONS / CERTIFICATION

The following professionals assisted in the completion of this report.

We, the undersigned, declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property as documented in Appendix H. We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Site Inspection and Report Written By:




Matthew Oleske
Senior Staff Engineer

Report Reviewed By:



Amanda Forsburg, CHMM
Project Scientist



Steven A. Ciambruschini, P.G., L.E.P.
Principal / Vice President

NJ Certificate of Authorization No. 24GA27996400
\\langan.com\data\PAR\data4\100732401\Project Data_Discipline\Environmental\Reports\2018-06 - Phase I ESA\375 Lafayette Phase I ESA_FINAL 2018-06-20.docx

TABLES

TABLE 1
TABLE OF CONTACTS

Federal

United States Environmental Protection Agency
Region 2 (NJ, NY, PR, VI)
https://foiaonline.regulations.gov/foia/action/public/home

United States Fish and Wildlife Service
https://ecos.fws.gov/ipac/gettingStarted/map

State

New York State Department of Environmental Conservation – Region II
http://www.dec.ny.gov/public/103696.html

Records Access Office
New York State Department of Health
Corning Tower, Room 2364
Albany, New York 12237-0044
foil@health.ny.gov

The New York Natural Heritage Program
http://www.dec.ny.gov/gis/erm/
http://nynhp.org/ProjectScreening

City


New York City Mayor's Office of Environmental Coordination
http://www.nyc.gov/html/oec/html/ceqr/ceqr_access.shtml

New York City Department of Environmental Protection
http://www.nyc.gov/html/dep/html/contact_us/foil.shtml

Ms. Renee Bryant, Records Access Officer
New York City Department of Health and Mental Hygiene
Gotham Center
42-09 28th Street, 14th Floor, CN31
Long Island City, NY 11101
recordsaccess@health.nyc.gov

Ms. Leslie Ifill
Fire Department of New York City
FDNY Bureau of Legal Affairs
Public Records Unit
9 MetroTech Center, 4th Floor
Brooklyn, NY 11201

FIGURES



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK


Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM



Notes:
1.World street basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online.
2. Parcel information from MapPLUTO 17v1.1 copyrighted by the New York City Department of Planning.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56


MANHATTAN NEW YORK

Drawing Title
TAX MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=200'
Drawn By	ATR
Last Revised	6/12/2018
Figure	2

© 2013 Langan

Click blue outline on map to view diagram of **proposed** zoning change


C1-6
C6-4A
C1-9
TA
C2-8A
R8
R7-2
R6
R6B
R6A
C6-1
C6-2
C6-4
C6-2A
C6-2M
C6-3A
C6-3X
C6-4X
C6-2G
C4-4A
C1-7
C1-8
C1-9A
C1-6A
C1-7A
C1-8A
C2-7
C2-6
C2-5
R8A
R8B
R7A
R7B
R9A
R8X
LH-1
LC
LI
M1-5A
M1-5B
M1-5M
M1-1
M1-2
M3-1
M3-2
MX-8
M1-2/R6A
M1-2/R6B
M1-2/R6
M1-1/R6A
M3-1/R6B
US
LA
TOMPKINS SQUARE
INLET PARK
HAMILTON FISH PARK
GRAND FERRY PARK
EAST RIVER PARK AND BULKHEAD
EAST RIVER
BOROUGH OF QUEENS
BOROUGH OF BROOKLYN
PIERHEAD
BULKHEAD
U.S. PIERHEAD LINE
U.S. BULKHEAD LINE
M.H.W.L.
M.L.W.L.
P.W.S.L.
U.S. HARBOR LINE
WASHINGTON SQUARE PARK
UNION SQUARE
FOURTH AVENUE
FIFTH AVENUE
BROADWAY
BOWERY
FIRST AVENUE
AVENUE A
AVENUE B
AVENUE C
AVENUE D
DELANCEY STREET
HOUSTON STREET
EAST 13TH STREET
EAST 14TH STREET
EAST 23RD STREET
EAST 34TH STREET
EAST 42ND STREET
EAST 59TH STREET
EAST 72ND STREET
EAST 96TH STREET
EAST 116TH STREET
EAST 125TH STREET
EAST 138TH STREET
EAST 149TH STREET
EAST 161ST STREET
EAST 169TH STREET
EAST 177TH STREET
EAST 181ST STREET
EAST 191ST STREET
EAST 193RD STREET
EAST 200TH STREET
EAST 207TH STREET
EAST 215TH STREET
EAST 225TH STREET
EAST 233RD STREET
EAST 239TH STREET
EAST 241ST STREET
EAST 245TH STREET
EAST 250TH STREET
EAST 257TH STREET
EAST 263RD STREET
EAST 270TH STREET
EAST 277TH STREET
EAST 281ST STREET
EAST 287TH STREET
EAST 289TH STREET
EAST 294TH STREET
EAST 296TH STREET
EAST 299TH STREET
EAST 303RD STREET
EAST 305TH STREET
EAST 309TH STREET
EAST 311TH STREET
EAST 313TH STREET
EAST 315TH STREET
EAST 317TH STREET
EAST 319TH STREET
EAST 321ST STREET
EAST 323RD STREET
EAST 325TH STREET
EAST 327TH STREET
EAST 329TH STREET
EAST 331ST STREET
EAST 333RD STREET
EAST 335TH STREET
EAST 337TH STREET
EAST 339TH STREET
EAST 341ST STREET
EAST 343RD STREET
EAST 345TH STREET
EAST 347TH STREET
EAST 349TH STREET
EAST 351ST STREET
EAST 353RD STREET
EAST 355TH STREET
EAST 357TH STREET
EAST 359TH STREET
EAST 361ST STREET
EAST 363RD STREET
EAST 365TH STREET
EAST 367TH STREET
EAST 369TH STREET
EAST 371ST STREET
EAST 373RD STREET
EAST 375TH STREET
EAST 377TH STREET
EAST 379TH STREET
EAST 381ST STREET
EAST 383RD STREET
EAST 385TH STREET
EAST 387TH STREET
EAST 389TH STREET
EAST 391ST STREET
EAST 393RD STREET
EAST 395TH STREET
EAST 397TH STREET
EAST 399TH STREET
EAST 401ST STREET
EAST 403RD STREET
EAST 405TH STREET
EAST 407TH STREET
EAST 409TH STREET
EAST 411TH STREET
EAST 413TH STREET
EAST 415TH STREET
EAST 417TH STREET
EAST 419TH STREET
EAST 421ST STREET
EAST 423RD STREET
EAST 425TH STREET
EAST 427TH STREET
EAST 429TH STREET
EAST 431ST STREET
EAST 433RD STREET
EAST 435TH STREET
EAST 437TH STREET
EAST 439TH STREET
EAST 441ST STREET
EAST 443RD STREET
EAST 445TH STREET
EAST 447TH STREET
EAST 449TH STREET
EAST 451ST STREET
EAST 453RD STREET
EAST 455TH STREET
EAST 457TH STREET
EAST 459TH STREET
EAST 461ST STREET
EAST 463RD STREET
EAST 465TH STREET
EAST 467TH STREET
EAST 469TH STREET
EAST 471ST STREET
EAST 473RD STREET
EAST 475TH STREET
EAST 477TH STREET
EAST 479TH STREET
EAST 481ST STREET
EAST 483RD STREET
EAST 485TH STREET
EAST 487TH STREET
EAST 489TH STREET
EAST 491ST STREET
EAST 493RD STREET
EAST 495TH STREET
EAST 497TH STREET
EAST 499TH STREET
EAST 501ST STREET
EAST 503RD STREET
EAST 505TH STREET
EAST 507TH STREET
EAST 509TH STREET
EAST 511TH STREET
EAST 513TH STREET
EAST 515TH STREET
EAST 517TH STREET
EAST 519TH STREET
EAST 521ST STREET
EAST 523RD STREET
EAST 525TH STREET
EAST 527TH STREET
EAST 529TH STREET
EAST 531ST STREET
EAST 533RD STREET
EAST 535TH STREET
EAST 537TH STREET
EAST 539TH STREET
EAST 541ST STREET
EAST 543RD STREET
EAST 545TH STREET
EAST 547TH STREET
EAST 549TH STREET
EAST 551ST STREET
EAST 553RD STREET
EAST 555TH STREET
EAST 557TH STREET
EAST 559TH STREET
EAST 561ST STREET
EAST 563RD STREET
EAST 565TH STREET
EAST 567TH STREET
EAST 569TH STREET
EAST 571ST STREET
EAST 573RD STREET
EAST 575TH STREET
EAST 577TH STREET
EAST 579TH STREET
EAST 581ST STREET
EAST 583RD STREET
EAST 585TH STREET
EAST 587TH STREET
EAST 589TH STREET
EAST 591ST STREET
EAST 593RD STREET
EAST 595TH STREET
EAST 597TH STREET
EAST 599TH STREET
EAST 601ST STREET
EAST 603RD STREET
EAST 605TH STREET
EAST 607TH STREET
EAST 609TH STREET
EAST 611TH STREET
EAST 613TH STREET
EAST 615TH STREET
EAST 617TH STREET
EAST 619TH STREET
EAST 621ST STREET
EAST 623RD STREET
EAST 625TH STREET
EAST 627TH STREET
EAST 629TH STREET
EAST 631ST STREET
EAST 633RD STREET
EAST 635TH STREET
EAST 637TH STREET
EAST 639TH STREET
EAST 641ST STREET
EAST 643RD STREET
EAST 645TH STREET
EAST 647TH STREET
EAST 649TH STREET
EAST 651ST STREET
EAST 653RD STREET
EAST 655TH STREET
EAST 657TH STREET
EAST 659TH STREET
EAST 661ST STREET
EAST 663RD STREET
EAST 665TH STREET
EAST 667TH STREET
EAST 669TH STREET
EAST 671ST STREET
EAST 673RD STREET
EAST 675TH STREET
EAST 677TH STREET
EAST 679TH STREET
EAST 681ST STREET
EAST 683RD STREET
EAST 685TH STREET
EAST 687TH STREET
EAST 689TH STREET
EAST 691ST STREET
EAST 693RD STREET
EAST 695TH STREET
EAST 697TH STREET
EAST 699TH STREET
EAST 701ST STREET
EAST 703RD STREET
EAST 705TH STREET
EAST 707TH STREET
EAST 709TH STREET
EAST 711TH STREET
EAST 713TH STREET
EAST 715TH STREET
EAST 717TH STREET
EAST 719TH STREET
EAST 721ST STREET
EAST 723RD STREET
EAST 725TH STREET
EAST 727TH STREET
EAST 729TH STREET
EAST 731ST STREET
EAST 733RD STREET
EAST 735TH STREET
EAST 737TH STREET
EAST 739TH STREET
EAST 741ST STREET
EAST 743RD STREET
EAST 745TH STREET
EAST 747TH STREET
EAST 749TH STREET
EAST 751ST STREET
EAST 753RD STREET
EAST 755TH STREET
EAST 757TH STREET
EAST 759TH STREET
EAST 761ST STREET
EAST 763RD STREET
EAST 765TH STREET
EAST 767TH STREET
EAST 769TH STREET
EAST 771ST STREET
EAST 773RD STREET
EAST 775TH STREET
EAST 777TH STREET
EAST 779TH STREET
EAST 781ST STREET
EAST 783RD STREET
EAST 785TH STREET
EAST 787TH STREET
EAST 789TH STREET
EAST 791ST STREET
EAST 793RD STREET
EAST 795TH STREET
EAST 797TH STREET
EAST 799TH STREET
EAST 801ST STREET
EAST 803RD STREET
EAST 805TH STREET
EAST 807TH STREET
EAST 809TH STREET
EAST 811TH STREET
EAST 813TH STREET
EAST 815TH STREET
EAST 817TH STREET
EAST 819TH STREET
EAST 821ST STREET
EAST 823RD STREET
EAST 825TH STREET
EAST 827TH STREET
EAST 829TH STREET
EAST 831ST STREET
EAST 833RD STREET
EAST 835TH STREET
EAST 837TH STREET
EAST 839TH STREET
EAST 841ST STREET
EAST 843RD STREET
EAST 845TH STREET
EAST 847TH STREET
EAST 849TH STREET
EAST 851ST STREET
EAST 853RD STREET
EAST 855TH STREET
EAST 857TH STREET
EAST 859TH STREET
EAST 861ST STREET
EAST 863RD STREET
EAST 865TH STREET
EAST 867TH STREET
EAST 869TH STREET
EAST 871ST STREET
EAST 873RD STREET
EAST 875TH STREET
EAST 877TH STREET
EAST 879TH STREET
EAST 881ST STREET
EAST 883RD STREET
EAST 885TH STREET
EAST 887TH STREET
EAST 889TH STREET
EAST 891ST STREET
EAST 893RD STREET
EAST 895TH STREET
EAST 897TH STREET
EAST 899TH STREET
EAST 901ST STREET
EAST 903RD STREET
EAST 905TH STREET
EAST 907TH STREET
EAST 909TH STREET
EAST 911TH STREET
EAST 913TH STREET
EAST 915TH STREET
EAST 917TH STREET
EAST 919TH STREET
EAST 921ST STREET
EAST 923RD STREET
EAST 925TH STREET
EAST 927TH STREET
EAST 929TH STREET
EAST 931ST STREET
EAST 933RD STREET
EAST 935TH STREET
EAST 937TH STREET
EAST 939TH STREET
EAST 941ST STREET
EAST 943RD STREET
EAST 945TH STREET
EAST 947TH STREET
EAST 949TH STREET
EAST 951ST STREET
EAST 953RD STREET
EAST 955TH STREET
EAST 957TH STREET
EAST 959TH STREET
EAST 961ST STREET
EAST 963RD STREET
EAST 965TH STREET
EAST 967TH STREET
EAST 969TH STREET
EAST 971ST STREET
EAST 973RD STREET
EAST 975TH STREET
EAST 977TH STREET
EAST 979TH STREET
EAST 981ST STREET
EAST 983RD STREET
EAST 985TH STREET
EAST 987TH STREET
EAST 989TH STREET
EAST 991ST STREET
EAST 993RD STREET
EAST 995TH STREET
EAST 997TH STREET
EAST 999TH STREET
EAST 1001ST STREET
EAST 1003RD STREET
EAST 1005TH STREET
EAST 1007TH STREET
EAST 1009TH STREET
EAST 1011TH STREET
EAST 1013TH STREET
EAST 1015TH STREET
EAST 1017TH STREET
EAST 1019TH STREET
EAST 1021ST STREET
EAST 1023RD STREET
EAST 1025TH STREET
EAST 1027TH STREET
EAST 1029TH STREET
EAST 1031ST STREET
EAST 1033RD STREET
EAST 1035TH STREET
EAST 1037TH STREET
EAST 1039TH STREET
EAST 1041ST STREET
EAST 1043RD STREET
EAST 1045TH STREET
EAST 1047TH STREET
EAST 1049TH STREET
EAST 1051ST STREET
EAST 1053RD STREET
EAST 1055TH STREET
EAST 1057TH STREET
EAST 1059TH STREET
EAST 1061ST STREET
EAST 1063RD STREET
EAST 1065TH STREET
EAST 1067TH STREET
EAST 1069TH STREET
EAST 1071ST STREET
EAST 1073RD STREET
EAST 1075TH STREET
EAST 1077TH STREET
EAST 1079TH STREET
EAST 1081ST STREET
EAST 1083RD STREET
EAST 1085TH STREET
EAST 1087TH STREET
EAST 1089TH STREET
EAST 1091ST STREET
EAST 1093RD STREET
EAST 1095TH STREET
EAST 1097TH STREET
EAST 1099TH STREET
EAST 1101ST STREET
EAST 1103RD STREET
EAST 1105TH STREET
EAST 1107TH STREET
EAST 1109TH STREET
EAST 1111TH STREET
EAST 1113TH STREET
EAST 1115TH STREET
EAST 1117TH STREET
EAST 1119TH STREET
EAST 1121ST STREET
EAST 1123RD STREET
EAST 1125TH STREET
EAST 1127TH STREET
EAST 1129TH STREET
EAST 1131ST STREET
EAST 1133RD STREET
EAST 1135TH STREET
EAST 1137TH STREET
EAST 1139TH STREET
EAST 1141ST STREET
EAST 1143RD STREET
EAST 1145TH STREET
EAST 1147TH STREET
EAST 1149TH STREET
EAST 1151ST STREET
EAST 1153RD STREET
EAST 1155TH STREET
EAST 1157TH STREET
EAST 1159TH STREET
EAST 1161ST STREET
EAST 1163RD STREET
EAST 1165TH STREET
EAST 1167TH STREET
EAST 1169TH STREET
EAST 1171ST STREET
EAST 1173RD STREET
EAST 1175TH STREET
EAST 1177TH STREET
EAST 1179TH STREET
EAST 1181ST STREET
EAST 1183RD STREET
EAST 1185TH STREET
EAST 1187TH STREET
EAST 1189TH STREET
EAST 1191ST STREET
EAST 1193RD STREET
EAST 1195TH STREET
EAST 1197TH STREET
EAST 1199TH STREET
EAST 1201ST STREET
EAST 1203RD STREET
EAST 1205TH STREET
EAST 1207TH STREET
EAST 1209TH STREET
EAST 1211TH STREET
EAST 1213TH STREET
EAST 1215TH STREET
EAST 1217TH STREET
EAST 1219TH STREET
EAST 1221ST STREET
EAST 1223RD STREET
EAST 1225TH STREET
EAST 1227TH STREET
EAST 1229TH STREET
EAST 1231ST STREET
EAST 1233RD STREET
EAST 1235TH STREET
EAST 1237TH STREET
EAST 1239TH STREET
EAST 1241ST STREET
EAST 1243RD STREET
EAST 1245TH STREET
EAST 1247TH STREET
EAST 1249TH STREET
EAST 1251ST STREET
EAST 1253RD STREET
EAST 1255TH STREET
EAST 1257TH STREET
EAST 1259TH STREET
EAST 1261ST STREET
EAST 1263RD STREET
EAST 1265TH STREET
EAST 1267TH STREET
EAST 1269TH STREET
EAST 1271ST STREET
EAST 1273RD STREET
EAST 1275TH STREET
EAST 1277TH STREET
EAST 1279TH STREET
EAST 1281ST STREET
EAST 1283RD STREET
EAST 1285TH STREET
EAST 1287TH STREET
EAST 1289TH STREET
EAST 1291ST STREET
EAST 1293RD STREET
EAST 1295TH STREET
EAST 1297TH STREET
EAST 1299TH STREET
EAST 1301ST STREET
EAST 1303RD STREET
EAST 1305TH STREET
EAST 1307TH STREET
EAST 1309TH STREET
EAST 1311TH STREET
EAST 1313TH STREET
EAST 1315TH STREET
EAST 1317TH STREET
EAST 1319TH STREET
EAST 1321ST STREET
EAST 1323RD STREET
EAST 1325TH STREET
EAST 1327TH STREET
EAST 1329TH STREET
EAST 1331ST STREET
EAST 1333RD STREET
EAST 1335TH STREET
EAST 1337TH STREET
EAST 1339TH STREET
EAST 1341ST STREET
EAST 1343RD STREET
EAST 1345TH STREET
EAST 1347TH STREET
EAST 1349TH STREET
EAST 1351ST STREET
EAST 1353RD STREET
EAST 1355TH STREET
EAST 1357TH STREET
EAST 1359TH STREET
EAST 1361ST STREET
EAST 1363RD STREET
EAST 1365TH STREET
EAST 1367TH STREET
EAST 1369TH STREET
EAST 1371ST STREET
EAST 1373RD STREET
EAST 1375TH STREET
EAST 1377TH STREET
EAST 1379TH STREET
EAST 1381ST STREET
EAST 1383RD STREET
EAST 1385TH STREET
EAST 1387TH STREET
EAST 1389TH STREET
EAST 1391ST STREET
EAST 1393RD STREET
EAST 1395TH STREET
EAST 1397TH STREET
EAST 1399TH STREET
EAST 1401ST STREET
EAST 1403RD STREET
EAST 1405TH STREET
EAST 1407TH STREET
EAST 1409TH STREET
EAST 1411TH STREET
EAST 1413TH STREET
EAST 1415TH STREET
EAST 1417TH STREET
EAST 1419TH STREET
EAST 1421ST STREET
EAST 1423RD STREET
EAST 1425TH STREET
EAST 1427TH STREET
EAST 1429TH STREET
EAST 1431ST STREET
EAST 1433RD STREET
EAST 1435TH STREET
EAST 1437TH STREET
EAST 1439TH STREET
EAST 1441ST STREET
EAST 1443RD STREET
EAST 1445TH STREET
EAST 1447TH STREET
EAST 1449TH STREET
EAST 1451ST STREET
EAST 1453RD STREET
EAST 1455TH STREET
EAST 1457TH STREET
EAST 1459TH STREET
EAST 1461ST STREET
EAST 1463RD STREET
EAST 1465TH STREET
EAST 1467TH STREET
EAST 1469TH STREET
EAST 1471ST STREET
EAST 1473RD STREET
EAST 1475TH STREET
EAST 1477TH STREET
EAST 1479TH STREET
EAST 1481ST STREET
EAST 1483RD STREET
EAST 1485TH STREET
EAST 1487TH STREET
EAST 1489TH STREET
EAST 1491ST STREET
EAST 1493RD STREET
EAST 1495TH STREET
EAST 1497TH STREET
EAST 1499TH STREET
EAST 1501ST STREET
EAST 1503RD STREET
EAST 1505TH STREET
EAST 1507TH STREET
EAST 1509TH STREET
EAST 1511TH STREET
EAST 1513TH STREET
EAST 1515TH STREET
EAST 1517TH STREET
EAST 1519TH STREET
EAST 1521ST STREET
EAST 1523RD STREET
EAST 1525TH STREET
EAST 1527TH STREET
EAST 1529TH STREET
EAST 1531ST STREET
EAST 1533RD STREET
EAST 1535TH STREET
EAST 1537TH STREET
EAST 1539TH STREET
EAST 1541ST STREET
EAST 1543RD STREET
EAST 1545TH STREET
EAST 1547TH STREET
EAST 1549TH STREET
EAST 1551ST STREET
EAST 1553RD STREET
EAST 1555TH STREET
EAST 1557TH STREET
EAST 1559TH STREET
EAST 1561ST STREET
EAST 1563RD STREET
EAST 1565TH STREET
EAST 1567TH STREET
EAST 1569TH STREET
EAST 1571ST STREET
EAST 1573RD STREET
EAST 1575TH STREET
EAST 1577TH STREET
EAST 1579TH STREET
EAST 1581ST STREET
EAST 1583RD STREET
EAST 1585TH STREET
EAST 1587TH STREET
EAST 1589TH STREET
EAST 1591ST STREET
EAST 1593RD STREET
EAST 1595TH STREET
EAST 1597TH STREET
EAST 1599TH STREET
EAST 1601ST STREET
EAST 1603RD STREET
EAST 1605TH STREET
EAST 1607TH STREET
EAST 1609TH STREET
EAST 1611TH STREET
EAST 1613TH STREET
EAST 1615TH STREET
EAST 1617TH STREET
EAST 1619TH STREET
EAST 1621ST STREET
EAST 1623RD STREET
EAST 1625TH STREET
EAST 1627TH STREET
EAST 1629TH STREET
EAST 1631ST STREET
EAST 1633RD STREET
EAST 1635TH STREET
EAST 1637TH STREET
EAST 1639TH STREET
EAST 1641ST STREET
EAST 1643RD STREET
EAST 1645TH STREET
EAST 1647TH STREET
EAST 1649TH STREET
EAST 1651ST STREET
EAST 1653RD STREET
EAST 1655TH STREET
EAST 1657TH STREET
EAST 1659TH STREET
EAST 1661ST STREET
EAST 1663RD STREET
EAST 1665TH STREET
EAST 1667TH STREET
EAST 1669TH STREET
EAST 1671ST STREET
EAST 1673RD STREET
EAST 1675TH STREET
EAST 1677TH STREET
EAST 1679TH STREET
EAST 1681ST STREET
EAST 1683RD STREET
EAST 1685TH STREET
EAST 1687TH STREET
EAST 1689TH STREET
EAST 1691ST STREET
EAST 1693RD STREET
EAST 1695TH STREET
EAST 1697TH STREET
EAST 1699TH STREET
EAST 1701ST STREET
EAST 1703RD STREET
EAST 1705TH STREET
EAST 1707TH STREET
EAST 1709TH STREET
EAST 1711TH STREET
EAST 1713TH STREET
EAST 1715TH STREET
EAST 1717TH STREET
EAST 1719TH STREET
EAST 1721ST STREET
EAST 1723RD STREET
EAST 1725TH STREET
EAST 1727TH STREET
EAST 1729TH STREET
EAST 1731ST STREET
EAST 1733RD STREET
EAST 1735TH STREET
EAST 1737TH STREET
EAST 1739TH STREET
EAST 1741ST STREET
EAST 1743RD STREET
EAST 1745TH STREET
EAST 1747TH STREET
EAST 1749TH STREET
EAST 1751ST STREET
EAST 1753RD STREET
EAST 1755TH STREET
EAST 1757TH STREET
EAST 1759TH STREET
EAST 1761ST STREET
EAST 1763RD STREET
EAST 1765TH STREET
EAST 1767TH STREET
EAST 1769TH STREET
EAST 1771ST STREET
EAST 1773RD STREET
EAST 1775TH STREET
EAST 1777TH STREET
EAST 1779TH STREET
EAST 1781ST STREET
EAST 1783RD STREET
EAST 1785TH STREET
EAST 1787TH STREET
EAST 1789TH STREET
EAST 1791ST STREET
EAST 1793RD STREET
EAST 1795TH STREET
EAST 1797TH STREET
EAST 1799TH STREET
EAST 1801ST STREET
EAST 1803RD STREET
EAST 1805TH STREET
EAST 1807TH STREET
EAST 1809TH STREET
EAST 1811TH STREET
EAST 1813TH STREET
EAST 1815TH STREET
EAST 1817TH STREET
EAST 1819TH STREET
EAST 1821ST STREET
EAST 1823RD STREET
EAST 1825TH STREET
EAST 1827TH STREET
EAST 1829TH STREET
EAST 1831ST STREET
EAST 1833RD STREET
EAST 1835TH STREET
EAST 1837TH STREET
EAST 1839TH STREET
EAST 1841ST STREET
EAST 1843RD STREET
EAST 1845TH STREET
EAST 1847TH STREET
EAST 1849TH STREET
EAST 1851ST STREET
EAST 1853RD STREET
EAST 1855TH STREET
EAST 1857TH STREET
EAST 1859TH STREET
EAST 1861ST STREET
EAST 1863RD STREET
EAST 1865TH STREET
EAST 1867TH STREET
EAST 1869TH STREET
EAST 1871ST STREET
EAST 1873RD STREET
EAST 1875TH STREET
EAST 1877TH STREET
EAST 1879TH STREET
EAST 1881ST STREET
EAST 1883RD STREET
EAST 1885TH STREET
EAST 1887TH STREET
EAST 1889TH STREET
EAST 1891ST STREET
EAST 1893RD STREET
EAST 1895TH STREET
EAST 1897TH STREET
EAST 1899TH STREET
EAST 1901ST STREET
EAST 1903RD STREET
EAST 1905TH STREET
EAST 1907TH STREET
EAST 1909TH STREET
EAST 1911TH STREET
EAST 1913TH STREET
EAST 1915TH STREET
EAST 1917TH STREET
EAST 1919TH STREET
EAST 1921ST STREET
EAST 1923RD STREET
EAST 1925TH STREET
EAST 1927TH STREET
EAST 1929TH STREET
EAST 1931ST STREET
EAST 1933RD STREET
EAST 1935TH STREET
EAST 1937TH STREET
EAST 1939TH STREET
EAST 1941ST STREET
EAST 1943RD STREET
EAST 1945TH STREET
EAST 1947TH STREET
EAST 1949TH STREET
EAST 1951ST STREET
EAST 1953RD STREET
EAST 1955TH STREET
EAST 1957TH STREET
EAST 1959TH STREET
EAST 1961ST STREET
EAST 1963RD STREET
EAST 1965TH STREET
EAST 1967TH STREET
EAST 1969TH STREET
EAST 1971ST STREET
EAST 1973RD STREET
EAST 1975TH STREET
EAST 1977TH STREET
EAST 1979TH STREET
EAST 1981ST STREET
EAST 1983RD STREET
EAST 1985TH STREET
EAST 1987TH STREET
EAST 1989TH STREET
EAST 1991ST STREET
EAST 1993RD STREET
EAST 1995TH STREET
EAST 1997TH STREET
EAST 1999TH STREET
EAST 2001ST STREET
EAST 2003RD STREET
EAST 2005TH STREET
EAST 2007TH STREET
EAST 2009TH STREET
EAST 2011TH STREET
EAST 2013TH STREET
EAST 2015TH STREET
EAST 2017TH STREET
EAST 2019TH STREET
EAST 2021ST STREET
EAST 2023RD STREET
EAST 2025TH STREET
EAST 2027TH STREET
EAST 2029TH STREET
EAST 2031ST STREET
EAST 2033RD STREET
EAST 2035TH STREET
EAST 2037TH STREET
EAST 2039TH STREET
EAST 2041ST STREET
EAST 2043RD STREET
EAST 2045TH STREET
EAST 2047TH STREET
EAST 2049TH STREET
EAST 2051ST STREET
EAST 2053RD STREET
EAST 2055TH STREET
EAST 2057TH STREET
EAST 2059TH STREET
EAST 2061ST STREET
EAST 2063RD STREET
EAST 2065TH STREET
EAST 2067TH STREET
EAST 2069TH STREET
EAST 2071ST STREET
EAST 2073RD STREET
EAST 2075TH STREET
EAST 2077TH STREET
EAST 2079TH STREET
EAST 2081ST STREET
EAST 2083RD STREET
EAST 2085TH STREET
EAST 2087TH STREET
EAST 2089TH STREET
EAST 2091ST STREET
EAST 2093RD STREET
EAST 2095TH STREET
EAST 2097TH STREET
EAST 2099TH STREET
EAST 2101ST STREET
EAST 2103RD STREET
EAST 2105TH STREET
EAST 2107TH STREET
EAST 2109TH STREET
EAST 2111TH STREET
EAST 2113TH STREET
EAST 2115TH STREET
EAST 2117TH STREET
EAST 2119TH STREET
EAST 2121ST STREET
EAST 2123RD STREET
EAST 2125TH STREET
EAST 2127TH STREET
EAST 2129TH STREET
EAST 2131ST STREET
EAST 2133RD STREET
EAST 2135TH STREET
EAST 2137TH STREET
EAST 2139TH STREET
EAST 2141ST STREET
EAST 2143RD STREET
EAST 2145TH STREET
EAST 2147TH STREET
EAST 2149TH STREET
EAST 2151ST STREET
EAST 2153RD STREET
EAST 2155TH STREET
EAST 2157TH STREET
EAST 2159TH STREET
EAST 2161ST STREET
EAST 2163RD STREET
EAST 2165TH STREET
EAST 2167TH STREET
EAST 2169TH STREET
EAST 2171ST STREET
EAST 2173RD STREET
EAST 2175TH STREET
EAST 2177TH STREET
EAST 2179TH STREET
EAST 2181ST STREET
EAST 2183RD STREET
EAST 2185TH STREET
EAST 2187TH STREET
EAST 2189TH STREET
EAST 2191ST STREET
EAST 2193RD STREET
EAST 2195TH STREET
EAST 2197TH STREET
EAST 2199TH STREET
EAST 2201ST STREET
EAST 2203RD STREET
EAST 2205TH STREET
EAST 2207TH STREET
EAST 2209TH STREET
EAST 2211TH STREET
EAST 2213TH STREET
EAST 2215TH STREET
EAST 2217TH STREET
EAST 2219TH STREET
EAST 2221ST STREET
EAST 2223RD STREET
EAST 2225TH STREET
EAST 2227TH STREET
EAST 2229TH STREET
EAST 2231ST STREET
EAST 2233RD STREET
EAST 2235TH STREET
EAST 2237TH STREET
EAST 2239TH STREET
EAST 2241ST STREET
EAST 2243RD STREET
EAST 2245TH STREET
EAST 2247TH STREET
EAST 2249TH STREET
EAST 2251ST STREET
EAST 2253RD STREET
EAST 2255TH STREET
EAST 2257TH STREET
EAST 2259TH STREET
EAST 2261ST STREET
EAST 2263RD STREET
EAST 2265TH STREET
EAST 2267TH STREET
EAST 2269TH STREET
EAST 2271ST STREET
EAST 2273RD STREET
EAST 2275TH STREET
EAST 2277TH STREET
EAST 2279TH STREET
EAST 2281ST STREET
EAST 2283RD STREET
EAST 2285TH STREET
EAST 2287TH STREET
EAST 2289TH STREET
EAST 2291ST STREET
EAST 2293RD STREET
EAST 2295TH STREET
EAST 2297TH STREET
EAST 2299TH STREET
EAST 2301ST STREET
EAST 2303RD STREET
EAST 2305TH STREET
EAST 2307TH STREET
EAST 2309TH STREET
EAST 2311TH STREET
EAST 2313TH STREET
EAST 2315TH STREET
EAST 2317TH STREET
EAST 2319TH STREET
EAST 2321ST STREET
EAST 2323RD STREET
EAST 2325TH STREET
EAST 2327TH STREET
EAST 2329TH STREET
EAST 2331ST STREET
EAST 2333RD STREET
EAST 2335TH STREET
EAST 2337TH STREET
EAST 2339TH STREET
EAST 2341ST STREET
EAST 2343RD STREET
EAST 2345TH STREET
EAST 2347TH STREET
EAST 2349TH STREET
EAST 2351ST STREET
EAST 2353RD STREET
EAST 2355TH STREET
EAST 2357TH STREET
EAST 2359TH STREET
EAST 2361ST STREET
EAST 2363RD STREET
EAST 2365TH STREET
EAST 2367TH STREET
EAST 2369TH STREET
EAST 2371ST STREET
EAST 2373RD STREET
EAST 2375TH STREET
EAST 2377TH STREET
EAST 2379TH STREET
EAST 2381ST STREET
EAST 2383RD STREET
EAST 2385TH STREET
EAST 2387TH STREET
EAST 2389TH STREET
EAST 2391ST STREET
EAST 2393RD STREET
EAST 2395TH STREET
EAST 2397TH STREET
EAST 2399TH STREET
EAST 2401ST STREET
EAST 2403RD STREET
EAST 2405TH STREET
EAST 2407TH STREET
EAST 2409TH STREET
EAST 2411TH STREET
EAST 2413TH STREET
EAST 2415TH STREET
EAST 2417TH STREET
EAST 2419TH STREET
EAST 2421ST STREET
EAST 2423RD STREET
EAST 2425TH STREET
EAST 2427TH STREET
EAST 2429TH STREET
EAST 2431ST STREET
EAST 2433RD STREET
EAST 2435TH STREET
EAST 2437TH STREET
EAST 2439TH STREET
EAST 2441ST STREET
EAST 2443RD STREET
EAST 2445TH STREET
EAST 2447TH STREET
EAST 2449TH STREET
EAST 2451ST STREET
EAST 2453RD STREET
EAST 2455TH STREET
EAST 2457TH STREET
EAST 2459TH STREET
EAST 2461ST STREET
EAST 2463RD STREET
EAST 2465TH STREET
EAST 2467TH STREET
EAST 2469TH STREET
EAST 2471ST STREET
EAST 2473RD STREET
EAST 2475TH STREET
EAST 2477TH STREET
EAST 2479TH STREET
EAST 2481ST STREET
EAST 2483RD STREET
EAST 2485TH STREET
EAST 2487TH STREET
EAST 2489TH STREET
EAST 2491ST STREET
EAST 2493RD STREET
EAST 2495TH STREET
EAST 2497TH STREET
EAST 2499TH STREET
EAST 2501ST STREET
EAST 2503RD STREET
EAST 2505TH STREET
EAST 2507TH STREET
EAST 2509TH STREET
EAST 2511TH STREET
EAST 2513TH STREET
EAST 2515TH STREET
EAST 2517TH STREET
EAST 2519TH STREET
EAST 2521ST STREET
EAST 2523RD STREET
EAST 2525TH STREET
EAST 2527TH STREET
EAST 2529TH STREET
EAST 2531ST STREET
EAST 2533RD STREET
EAST 2535TH STREET
EAST 2537TH STREET
EAST 2539TH STREET
EAST 2541ST STREET
EAST 2543RD STREET
EAST 2545TH STREET
EAST 2547TH STREET
EAST 2549TH STREET
EAST 2551ST STREET
EAST 2553RD STREET
EAST 2555TH STREET
EAST 2557TH STREET
EAST 2559TH STREET
EAST 2561ST STREET
EAST 2563RD STREET
EAST 2565TH STREET
EAST 2567TH STREET
EAST 2569TH STREET
EAST 2571ST STREET
EAST 2573RD STREET
EAST 2575TH STREET
EAST 2577TH STREET
EAST 2579TH STREET
EAST 2581ST STREET
EAST 2583RD STREET
EAST 2585TH STREET
EAST 2587TH STREET
EAST 2589TH STREET
EAST 2591ST STREET
EAST 2593RD STREET
EAST 2595TH STREET
EAST 2597TH STREET
EAST 2599TH STREET
EAST 2601ST STREET
EAST 2603RD STREET
EAST 2605TH STREET
EAST 2607TH STREET
EAST 2609TH STREET
EAST 2611TH STREET
EAST 2613TH STREET
EAST 2615TH STREET
EAST 2617TH STREET
EAST 2619TH STREET
EAST 2621ST STREET
EAST 2623RD STREET
EAST 2625TH STREET
EAST 2627TH STREET
EAST 2629TH STREET
EAST 2631ST STREET
EAST 2633RD STREET
EAST 2635TH STREET
EAST 2637TH STREET
EAST 2639TH STREET
EAST 2641ST STREET
EAST 2643RD STREET
EAST 2645TH STREET
EAST 2647TH STREET
EAST 2649TH STREET
EAST 2651ST STREET
EAST 2653RD STREET
EAST 2655TH STREET
EAST 2657TH STREET
EAST 2659TH STREET
EAST 2661ST STREET
EAST 2663RD STREET
EAST 2665TH STREET
EAST 2667TH STREET
EAST 2669TH STREET
EAST 2671ST STREET
EAST 2673RD STREET
EAST 2675TH STREET
EAST 2677TH STREET
EAST 2679TH STREET
EAST 2681ST STREET
EAST 2683RD STREET
EAST 2685TH STREET
EAST 2687TH STREET
EAST 2689TH STREET
EAST 2691ST STREET
EAST 2693RD STREET
EAST 2695TH STREET
EAST 2697TH STREET
EAST 2699TH STREET
EAST 2701ST STREET
EAST 2703RD STREET
EAST 2705TH STREET
EAST 2707TH STREET
EAST 2709TH STREET
EAST 2711TH STREET
EAST 2713TH STREET
EAST 2715TH STREET
EAST 2717TH STREET
EAST 2719TH STREET
EAST 2721ST STREET
EAST 2723RD STREET
EAST 2725TH STREET
EAST 2727TH STREET
EAST 2729TH STREET
EAST 2731ST STREET
EAST 2733RD STREET
EAST 2735TH STREET
EAST 2737TH STREET
EAST 2739TH STREET
EAST 2741ST STREET
EAST 2743RD STREET
EAST 2745TH STREET
EAST 2747TH STREET
EAST 2749TH STREET
EAST 2751ST STREET
EAST 2753RD STREET
EAST 2755TH STREET
EAST 2757TH STREET
EAST 2759TH STREET
EAST 2761ST STREET
EAST 2763RD STREET
EAST 2765TH STREET
EAST 2767TH STREET
EAST 2769TH STREET
EAST 2771ST STREET
EAST 2773RD STREET
EAST 2775TH STREET
EAST 2777TH STREET
EAST 2779TH STREET
EAST 2781ST STREET
EAST 2783RD STREET
EAST 2785TH STREET
EAST 2787TH STREET
EAST 2789TH STREET
EAST 2791ST STREET
EAST 2793RD STREET
EAST 2795TH STREET
EAST 2797TH STREET
EAST 2799TH STREET
EAST 2801ST STREET
EAST 2803RD STREET
EAST 2805TH STREET
EAST 2807TH STREET
EAST 2809TH STREET
EAST 2811TH STREET
EAST 2813TH STREET
EAST 2815TH STREET
EAST 2817TH STREET
EAST 2819TH STREET
EAST 2821ST STREET
EAST 2823RD STREET
EAST 2825TH STREET
EAST 2827TH STREET
EAST 2829TH STREET
EAST 2831ST STREET
EAST 2833RD STREET
EAST 2835TH STREET
EAST 2837TH STREET
EAST 2839TH STREET
EAST 2841ST STREET
EAST 2843RD STREET
EAST 2845TH STREET
EAST 2847TH STREET
EAST 2849TH STREET
EA

APPENDIX A

USER QUESTIONNAIRE

LANGAN

ASTM PRACTICE E 1527-13: USER/CLIENT QUESTIONNAIRE

Please complete the below form and return to
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.

Providing the following information (if available) to the environmental professional (Langan) is one of the requirements to qualify for one of the *Landowner Liability Protections* offered under CERCLA. Missing or incomplete information could result in a determination that "all appropriate inquiry" is not complete.

General Information

User/Client Name (s): Edison 44 Party, LLC

Property Name:

Address: 325 Lafayette Street, NY, NY

Property Type: Party Hall

Type of Property Transaction:

Purchase of property	☐
Financing of property	☐
Sale of property	☐
Ground Lease	☒
Build to Suit Lease	☐
Other_____	

Reason Why Phase I ESA is required: Ground Lease

Site Contact (s): Separately provided

Required Information

The citation at the end of each item (e.g. 40 CFR 312.XX) is the section of EPA's November 1, 2005 AAI Final Rule which discusses that item.

	Yes	No
(1.) Environmental cleanup liens that are filed or recorded against the site (40 CFR 312.25). Did a search of recorded land title records (or judicial records where appropriate) identify any environmental liens filed or recorded against the property under federal, tribal, state or local law?	☐	☒

No search has been done by User

	Yes	No
(2.) Activity and Land Use (AUL) limitations that are in place on the site or that have been filed or recorded in a registry (40 CFR 312.26). Did a search of recorded land title records (or judicial records where appropriate) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law?	☐	☒

No search has been done by User

LANGAN

	Yes	No
(3.) Specialized knowledge or experience of the person seeking to qualify for LLP (40 CFR 312.28).		
Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	☒	☐
(4.) Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29).	**Yes**	**No**
(a.) Does the ~~purchase~~ price being paid for this property reasonably reflect the fair market value of the property? [If no, proceed to Parts 4a and 4b.]	☒	☐
(b.) If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?	☐	☐
(c.) Identify an explanation for the lower price and provide a written record of such explanation as an attachment.		
(5.) Commonly known or reasonably known or reasonably ascertainable information about the property (40 CFR 312.30).	**Yes**	**No**
Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example,	☐	☒
(a.) Do you know the past uses of the property?	☒	☐
(b.) Do you know of specific chemicals that are present or once were present at the property?	☐	☒
(c.) Do you know of spills or other chemical releases that have taken place at the property?	☐	☒
(d.) Do you know of any environmental cleanups that have taken place at the property?	☐	☒
(6.) The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate Investigation (40 CFR 312.31).	**Yes**	**No**
Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property?	☐	☒

SIGNATURE:

It is understood that the information presented in this form is an integral part of the Phase I ESA process and that Langan will evaluate and rely on this information in the development of the final Phase I ESA report.

Completed By: Victoria Morris

Print/Type Name:

Title: Board Council

Company: Eden Prairie, LLC

Date: 6/8/2018

APPENDIX B

PROPERTY OWNER / OPERATOR / KEY SITE MANAGER QUESTIONNAIRE

LANGAN

ASTM PRACTICE E 1527-13:
OWNER/OPERATOR/SITE-MANAGER QUESTIONNAIRE

Please complete the below form and return to
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.

Project Location/Address: 325 Lafayette St.
Edison Park East.
NY NY.

ASTM E-1527-13, Section 9.4

Are you aware of any of the following located on the subject property:

Pits, Ponds, or Lagoons?	Yes ☐	No ☑
Stained Soil or Pavement? minor- hydraulic piston/sheen on asphalt	Yes ☑	No ☐
Stressed Vegetation?	Yes ☐	No ☑
Solid Waste (including trash, construction debris, or demolition debris)?	Yes ☐	No ☑
Wastewater or Discharges into Drains, Ditches, Underground Injection System, or Stream?	Yes ☐	No ☑
Wells (including dry wells, irrigation wells, injection wells, abandoned wells, or other wells)?	Yes ☐	No ☑
Septic Systems or Cesspools?	Yes ☐	No ☑

ASTM E-1527-13, Section 10.9

Do you know of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the property?	Yes ☐	No ☑
Do you know of any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the property?	Yes ☐	No ☑
Do you know of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?	Yes ☐	No ☑

ASTM E-1527-13, Section 10.8

Are you aware if any of the documents listed below exists and if so, whether copies can and will be provided to the Consultant performing the ESA?

	Unaware	Document Exists	Copy will be provided
Environmental site assessment reports	☑	☐	☐
Environmental compliance audit reports	☑	☐	☐
Environmental permits (such as solid waste disposal permits, hazardous waste disposal permits, NPDES permits, wastewater permits, underground injection permits)	☑	☐	☐
Registrations for underground and aboveground storage tanks	☑	☐	☐
Material safety data sheets	☑	☐	☐
Community-right-to-know plan	☑	☐	☐
Safety plans; preparedness and prevention plans; spill prevention, countermeasure and control plans, facility response plan, etc.	☑	☐	☐
Reports regarding hydrogeologic conditions on the property or surrounding area	☑	☐	☐
Notices or other correspondence from any governmental agency relating to past or current violations of environmental laws with respect to the property or relating to environmental liens encumbering the property	☑	☐	☐
Hazardous waste generator notices or reports	☑	☐	☐
Geotechnical studies	☑	☐	☐
Risk Assessments	☑	☐	☐
Recorded Activity and Use Limitations	☑	☐	☐
Environmental Cleanup Reports	☑	☐	☐

Do you have contact information for the prior owner of the property? **Yes** ☐ **No** ☑
If yes, please provide information below:

Prior Owner's Name _____

Contact person _____

Address _____

_____

Telephone _____

Do you have contact information for the prior occupant of the property? **Yes** ☐ **No** ☑
If yes, please provide information below:

Prior Occupant's Name _____

Contact person _____

Address _____

_____

Telephone _____

Do you have information on the prior facility manager of the property? **Yes** ☐ **No** ☑
If yes, please provide information below:

Prior Facility Manager's Name _____

Contact person _____

Address _____

_____

Telephone _____

This form was completed by:

Property Owner ☐ Operator ☑ Key Site Manager ☐ User ☐ EP ☑

Name: NAVEEN LIYANAARACHCHI EDISON PARK FIRST ASST. MGR.

Address: _____

_____

Signature: MATTHEW OLESKE (LANGAN) with NAVEEN LIYANAARACHCHI Date: 6/4/2018

LANGAN

APPENDIX C

SANBORN MAPS

375 Lafayette Street

375 Lafayette Street

New York, NY 10003

Inquiry Number: 5314975.3

May 30, 2018

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

05/30/18

Site Name:

375 Lafayette Street
375 Lafayette Street
New York, NY 10003
EDR Inquiry # 5314975.3

Client Name:

Langan Engineering
300 Kimball Drive, 4th Floor
Parsippany, NJ 07054-2172
Contact: Amanda Forsburg

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Langan Engineering were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 5C59-46DD-B5D3

PO # NA

Project NA

Maps Provided:

2005	1993	1979	1904
2004	1992	1976	1895
2003	1991	1975	
2002	1988	1969	
2001	1987	1950	
1996	1985	1944	
1995	1983	1921	
1994	1980	1920	

Sanborn® Library search results

Certification #: 5C59-46DD-B5D3

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Langan Engineering (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2005 Source Sheets


Volume 2, Sheet 17
2005-2006


Volume 3, Sheet 9
2005-2006


Volume 3, Sheet 10
2005-2006



Volume 3, Sheet 24
2005-2006

2004 Source Sheets


Volume 3, Sheet 9
2004


Volume 3, Sheet 10
2004


Volume 3, Sheet 24
2004


Volume 2, Sheet 17
2004


2003 Source Sheets


Volume 3, Sheet 9
2003


Volume 3, Sheet 10
2003


Volume 3, Sheet 24
2003



Volume 1S, Sheet xxxx
2003


Volume 2, Sheet 17
2003

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2002 Source Sheets


Volume 2, Sheet 17
2002


Volume 3, Sheet 9
2002


Volume 3, Sheet 10
2002


Volume 3, Sheet 24
2002


2001 Source Sheets


Volume 3, Sheet 9
2001


Volume 3, Sheet 10
2001


Volume 3, Sheet 24
2001

1996 Source Sheets


Volume 3, Sheet 9
1996


Volume 3, Sheet 10
1996



Volume 3, Sheet 24
1996

1995 Source Sheets


Volume 3, Sheet 9
1995


Volume 3, Sheet 10
1995



Volume 3, Sheet 24
1995


Volume 2, Sheet 17
1995


Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets


Volume 3, Sheet 9
1994


Volume 3, Sheet 10
1994


Volume 3, Sheet 24
1994


Volume 2, Sheet 17
1994

1993 Source Sheets


Volume 3, Sheet 9
1993


Volume 3, Sheet 10
1993


Volume 3, Sheet 24
1993

1992 Source Sheets



Volume 3, Sheet 9
1992


Volume 3, Sheet 10
1992


Volume 3, Sheet 24
1992



Volume 2, Sheet 17
1992

1991 Source Sheets


Volume 2, Sheet 9
1991


Volume 2, Sheet 17
1991


Volume 3, Sheet 9
1991



Volume 3, Sheet 10
1991


Volume 3, Sheet 24
1991

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1988 Source Sheets


Volume 2, Sheet 9
1988



Volume 2, Sheet 17
1988


Volume 3, Sheet 9
1988


Volume 3, Sheet 10
1988


Volume 3, Sheet 24
1988

1987 Source Sheets



Volume 2, Sheet 17
1987


Volume 3, Sheet 9
1987


Volume 3, Sheet 10
1987


Volume 3, Sheet 24
1987


1985 Source Sheets


Volume 3, Sheet 9
1985


Volume 3, Sheet 10
1985



Volume 3, Sheet 24
1985

1983 Source Sheets


Volume 2, Sheet 9
1983


Volume 3, Sheet 9
1983


Volume 3, Sheet 10
1983


Volume 3, Sheet 24
1983


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1980 Source Sheets



Volume 1S, Sheet xxxx
1980


Volume 2, Sheet xxxx
1980


Volume 2, Sheet 9
1980


Volume 3, Sheet 24
1980



Volume 3, Sheet xxxx
1980


Volume 3, Sheet 9
1980


Volume 3, Sheet 10
1980

1979 Source Sheets


Volume 3, Sheet 24
1979


Volume 3, Sheet 9
1979


Volume 3, Sheet 10
1979


1976 Source Sheets


Volume 2, Sheet 9
1976

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1975 Source Sheets


Volume 3, Sheet 24
1975


Volume 3, Sheet 9
1975


Volume 3, Sheet 10
1975

1969 Source Sheets



Volume 3, Sheet 9
1969


Volume 3, Sheet 10
1969



Volume 3, Sheet 24
1969


1950 Source Sheets


Volume 3, Sheet xxxx
1950



Volume 3, Sheet 9
1950


Volume 3, Sheet 10
1950


Volume 3, Sheet 24
1950


Volume 2, Sheet 17
1950


Volume 2, Sheet xxxx
1950


Volume 2, Sheet 9
1950


Volume 1S, Sheet xxxx
1950

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1944 Source Sheets




Volume 2, Sheet xxxx
1944




Volume 2, Sheet 17
1944


1921 Source Sheets



Volume 3, Sheet 9
1921




Volume 3, Sheet 10
1921



Volume 3, Sheet 24
1921

1920 Source Sheets



Volume 2, Sheet 17
1920

1904 Source Sheets



Volume 3, Sheet 9
1904



Volume 3, Sheet 10
1904




Volume 3, Sheet 24
1904

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1895 Source Sheets




Volume 3, Sheet 29
1895



Volume 3, Sheet 49
1895



Volume 3, Sheet 53
1895




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 2, Sheet 17

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 2, Sheet 17
Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #5C59-46DD-B5D3

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 2, Sheet 17
Volume 1S, Sheet xxxx
Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 2, Sheet 17

N




Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

0 Feet 150 300 600

N

Certified Sanborn® Map

1995




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 2, Sheet 17
Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 2, Sheet 17
Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N




Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #	5C59-46DD-B5D3
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600






Volume 2, Sheet 17
Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N


HEBREW UNION COLLEGE BROOKDALE CENTER
STREET
EAST
LAFAYETTE
COOPER
(BOWERY)
FOURTH
GREAT JONES
STREET
COOPER SQUARE
BOND
ST.
STREET
GREAT JONES
STREET
BOND
STREET
JONES AL (SHINBONE AL)
THIRD
EAST
STREET
BOWERY
SECOND
N.Y. MARBLE
535
530
529
458
PARK'G
PARK'G
PARK'G




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 2, Sheet 17
Volume 2, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #	5C59-46DD-B5D3
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 2, Sheet 17

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1985

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1983

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 2, Sheet 9

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 3, Sheet xxxx
Volume 3, Sheet 24
Volume 2, Sheet 9
Volume 2, Sheet xxxx
Volume 1S, Sheet xxxx

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 3, Sheet 24

N




Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1975

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 3, Sheet 24

N




Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1969

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1S, Sheet xxxx
Volume 2, Sheet 9
Volume 2, Sheet xxxx
Volume 2, Sheet 17
Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9
Volume 3, Sheet xxxx


N




Site Name: 375 Lafayette Street
Address: 375 Lafayette Street
City, ST, ZIP: New York, NY 10003
Client: Langan Engineering
EDR Inquiry: 5314975.3
Order Date: 05/30/2018
Certification #: 5C59-46DD-B5D3
Copyright 1921

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9


N



Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1904


This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 24
Volume 3, Sheet 10
Volume 3, Sheet 9

0 Feet 150 300 600




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	375 Lafayette Street
Address:	375 Lafayette Street
City, ST, ZIP:	New York, NY 10003
Client:	Langan Engineering
EDR Inquiry:	5314975.3
Order Date:	05/30/2018
Certification #:	5C59-46DD-B5D3
Copyright	1895

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 3, Sheet 53
Volume 3, Sheet 49
Volume 3, Sheet 29

0 Feet 150 300 600

N

APPENDIX D

CITY DIRECTORY SEARCH

375 Lafayette Street
375 Lafayette Street
New York, NY 10003

Inquiry Number: 5314975.5
June 08, 2018

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.


Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1920 through 2014. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2014	EDR Digital Archive	-	X	X	-
	EDR Digital Archive	X	X	X	-
2010	EDR Digital Archive	-	X	X	-
	EDR Digital Archive	X	X	X	-
2006	Hill-Donnelly Information Services	X	X	X	-
2000	Cole Information Services	X	X	X	-
1998	NYNEX Telephone	-	X	X	-
	NYNEX Telephone	X	X	X	-
1996	NYNEX	-	-	-	-
1993	NYNEX Telephone	-	X	X	-
1988	NYNEX Telephone	-	X	X	-
1983	New York Telephone	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1983	New York Telephone	X	X	X	-
1978	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1973	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1968	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1963	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1958	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1956	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1950	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1947	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1942	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1938	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1931	Manhattan and Bronx Directory Publishing Company Residential Directory	-	X	X	-
1927	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1923	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1920	R. L. Polk & Co.	X	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
372 Lafayette Street	Client Entered	X
30 Great Jones Street	Client Entered	X
371 Lafayette Street	Client Entered	X
383 Lafayette Street	Client Entered	X
33 Great Jones Street	Client Entered	X
361 Lafayette Street	Client Entered	
30 East 4th Street	Client Entered	X
363 Lafayette Street	Client Entered	X
41 Great Jones Street	Client Entered	X
379 Lafayette Street	Client Entered	

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

375 Lafayette Street
New York, NY 10003

FINDINGS DETAIL

Target Property research detail.

GREAT JONES

30 GREAT JONES

Year	*Uses*	*Source*
1978	MEYER DAVID	New York Telephone
	MOHR PAUL	New York Telephone
	RALPH STEVE	New York Telephone
	WENK J	New York Telephone
1973	BERNHARDT ZINE PAPR CO INC	New York Telephone
1968	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZIDN PAPR CO INC	New York Telephone
	ZINN BERNCARDT PAPR CO INC	New York Telephone
1963	AINSLEY HAT CO INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	MILLER HAT CO	New York Telephone
	SALCO BEDSPREADS INC	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1958	AINSLEY HAT CO INC	New York Telephone
	AT COMGATED CO	New York Telephone
	BERNHARDT L ZLNN PAPR CO INC	New York Telephone
	CRESCENT LEATHER PARING & EMBOSSING CO INC	New York Telephone
	LOYAL UNIFORM CORP	New York Telephone
	MILLER HAT CO	New York Telephone
	MILLER LOUIS & MAX CORP	New York Telephone
	SALCO BEDSPREADS INC	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1956	AINSLEY HAT CO INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone

FINDINGS

Year	Uses	Source
1956	CARLJANA FASHIONS INC	New York Telephone
	CRESCENT LEATHER PARING & EMBOSSING CO INC	New York Telephone
	MILLER HAT CO	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1950	AINSLEY HAT CO INC	New York Telephone
	ARNO GARMENT CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	CARLIANA FASHIONS INC	New York Telephone
	CAROL PK FASHIONS INC	New York Telephone
	GRAMERCY PAPR CO	New York Telephone
	GREAT JONES PANTS CO	New York Telephone
	LOYAL UNIFORM CORP	New York Telephone
	MILLER HAT CO	New York Telephone
	R & R GARMENT CO	New York Telephone
1947	AINSLEY HAT CO INC	New York Telephone
	ARNO GARMENT CO	New York Telephone
	ARNO MODES INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	EMPIRE RAINCOAT CO INC	New York Telephone
	FORMAN LOUIS PANTS	New York Telephone
	GRAMERCY PAPR CO	New York Telephone
	GREAT JONES SPORTSWR CO	New York Telephone
	METTER FRED HUDHGS	New York Telephone
	MILLER HAT CO	New York Telephone
	MILWALL TRADING CORP	New York Telephone
	ROYAL UNIFORM CO	New York Telephone
	S & J NOVELTY CO	New York Telephone
	WALSTATTER M R AUCTNR	New York Telephone
1942	AINSLEY HAT CO INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BAY MFG CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	MAID-RITE HANDBAG CO	New York Telephone
	MILLER HAT CO	New York Telephone
	ROYAL UNIFORM CO	New York Telephone
	SHENFELD MAX B	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone

FINDINGS

Year	Uses	Source
1938	AINSLEY HAT CO	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO	New York Telephone
	MODERN WINDOW DISPLAYS CO	New York Telephone
	PENNANT HAT CO	New York Telephone
	ROYAL UNIFORM CO	New York Telephone
1934	Bernhardt Zinn Paper Co Inc Paul Zinn pres David Bernhardt sec treas whol	R. L. Polk & Co.
	Camillo Jas Potenza & Camillo	R. L. Polk & Co.
	Cohen Jennie v pres Asco Cap Co Inc	R. L. Polk & Co.
	Cohen Louis pres sec treas Asco Cap Co Inc	R. L. Polk & Co.
	Goodman Saml Reliable Coat Contractors	R. L. Polk & Co.
	Hershbain Ychael Bessie contr mfg	R. L. Polk & Co.
	Hubbell & Cossick hat block mfrs	R. L. Polk & Co.
	Oliveri C Clothing mfr	R. L. Polk & Co.
	Potenza & Camillo John Potenza and Jas Camillo clothing mfrs	R. L. Polk & Co.
	Potenza John Potenza & Camillo	R. L. Polk & Co.
	Reliable Coats Co Harry Pirosnik Abr Schneider Abr Lipshitz and Saml Gutman coat mfrs	R. L. Polk & Co.
	Rosen Ray Solrose Millinery Co	R. L. Polk & Co.
	Solrose Millinery Co RTN Barnet Solash Roy Rosen mlnry	R. L. Polk & Co.
	Steinfeld Abram coat ansd suit mfr	R. L. Polk & Co.
	Zinn Paul pres Bernhardt Zinn Paper Co Inc	R. L. Polk & Co.
1927	BAR MUSICAL NOVELTY CO INC	New York Telephone
	BOULEVARD COAT CO	New York Telephone
	CROWN HAT FRAME CO	New York Telephone
	Elgin Hat Frame Co Inc	New York Telephone
	LUCIE GUSTAV PAPER	New York Telephone
	Solash Barnet caps	New York Telephone
	SUCCESS HAT CO	New York Telephone
1923	Crown Hat Frame Co RTN Abr Clare Ralphe Vitaghan & Saml King	R. L. Polk & Co.
	Geisler & Lewis Max Geisler Rueben Lewis dress trim	R. L. Polk & Co.
	Geislinger Fred garageman PO h Yonkers NY	R. L. Polk & Co.
	Independent Coat & Suit House RTN Philip Siden Max Sanger	R. L. Polk & Co.
	Kling Saml Crown Hat & Frame Co	R. L. Polk & Co.

Year	Uses	Source
1923	Siden Philip Independent Coat & Suit House	R. L. Polk & Co.
	Slutzkin & Safire Saml Slutzkin and Saml Safire ladies hats	R. L. Polk & Co.
	Slutzkin Saml Slutzkin & Safire	R. L. Polk & Co.
	Solash & Tetensky Barnet Solash Abr Tatensky hats	R. L. Polk & Co.
	Urwitz & Rosenberg Jacob Urwitz only clothing	R. L. Polk & Co.
1920	Bathkoff Robt Paramount Hat Co	R. L. Polk & Co.
	Crown Hat Frame Co RTN Abr Clare Ralph Vitagliano	R. L. Polk & Co.
	Herman Isaac pres H R & S Hat & Cap Co Inc	R. L. Polk & Co.
	Krotoskys L Sons Sol Krotosky glass	R. L. Polk & Co.
	Paramount Hat Co RTN Isidore Weinstein Louis Levine & Robt Rathkoff	R. L. Polk & Co.
	Slutzkin & Safire Saml Slutzkin Saml Safire hats	R. L. Polk & Co.
	Solash & Tetensky Barnet Solash & Abe Tetencky hats	R. L. Polk & Co.
	Stoller Frank caps	R. L. Polk & Co.
	Urwitz & Rosernberg Jacob Urwitz Jacob Rosenberg clothing	R. L. Polk & Co.

GREAT JONES ST

30 GREAT JONES ST

Year	Uses	Source
2006	Concord Electronics Corp	Hill-Donnelly Information Services
2000	CONCORD ELCTRMCS	Cole Information Services
1927	Bar Musical Novelty Co Inc	New York Telephone
	Boulevard Coat Co	New York Telephone

Great Jones Street

30 Great Jones Street

Year	Uses	Source
2006	Concord Electronics Corp	Hill-Donnelly Information Services
2000	CONCORD ELCTRMCS	Cole Information Services
1978	MEYER DAVID	New York Telephone
	MOHR PAUL	New York Telephone
	RALPH STEVE	New York Telephone
	WENK J	New York Telephone

FINDINGS

Year	Uses	Source
1973	BERNHARDT ZINE PAPR CO INC	New York Telephone
1968	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZIDN PAPR CO INC	New York Telephone
	ZINN BERNCARDT PAPR CO INC	New York Telephone
1963	AINSLEY HAT CO INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	MILLER HAT CO	New York Telephone
	SALCO BEDSPREADS INC	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1958	AINSLEY HAT CO INC	New York Telephone
	AT COMGATED CO	New York Telephone
	BERNHARDT L ZLNN PAPR CO INC	New York Telephone
	CRESCENT LEATHER PARING & EMBOSSING CO INC	New York Telephone
	LOYAL UNIFORM CORP	New York Telephone
	MILLER HAT CO	New York Telephone
	MILLER LOUIS & MAX CORP	New York Telephone
	SALCO BEDSPREADS INC	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1956	AINSLEY HAT CO INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	CARLJANA FASHIONS INC	New York Telephone
	CRESCENT LEATHER PARING & EMBOSSING CO INC	New York Telephone
	MILLER HAT CO	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1950	AINSLEY HAT CO INC	New York Telephone
	ARNO GARMENT CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	CARLIANA FASHIONS INC	New York Telephone
	CAROL PK FASHIONS INC	New York Telephone
	GRAMERCY PAPR CO	New York Telephone
	GREAT JONES PANTS CO	New York Telephone
	LOYAL UNIFORM CORP	New York Telephone
	MILLER HAT CO	New York Telephone
	R & R GARMENT CO	New York Telephone
1947	AINSLEY HAT CO INC	New York Telephone

FINDINGS

Year	Uses	Source
1947	ARNO GARMENT CO	New York Telephone
	ARNO MODES INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	EMPIRE RAINCOAT CO INC	New York Telephone
	FORMAN LOUIS PANTS	New York Telephone
	GRAMERCY PAPR CO	New York Telephone
	GREAT JONES SPORTSWR CO	New York Telephone
	METTER FRED HUDHGS	New York Telephone
	MILLER HAT CO	New York Telephone
	MILWALL TRADING CORP	New York Telephone
	ROYAL UNIFORM CO	New York Telephone
	S & J NOVELTY CO	New York Telephone
	WALSTATTER M R AUCTNR	New York Telephone
1942	AINSLEY HAT CO INC	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BAY MFG CO	New York Telephone
	BERNHARDT ZINN PAPR CO INC	New York Telephone
	MAID-RITE HANDBAG CO	New York Telephone
	MILLER HAT CO	New York Telephone
	ROYAL UNIFORM CO	New York Telephone
	SHENFELD MAX B	New York Telephone
	ZINN BERNHARDT PAPR CO INC	New York Telephone
1938	AINSLEY HAT CO	New York Telephone
	ART CORRUGATED CO	New York Telephone
	BERNHARDT ZINN PAPR CO	New York Telephone
	MODERN WINDOW DISPLAYS CO	New York Telephone
	PENNANT HAT CO	New York Telephone
	ROYAL UNIFORM CO	New York Telephone
1934	Bernhardt Zinn Paper Co Inc Paul Zinn pres David Bernhardt sec treas whol	R. L. Polk & Co.
	Camillo Jas Potenza & Camillo	R. L. Polk & Co.
	Cohen Jennie v pres Asco Cap Co Inc	R. L. Polk & Co.
	Cohen Louis pres sec treas Asco Cap Co Inc	R. L. Polk & Co.
	Goodman Saml Reliable Coat Contractors	R. L. Polk & Co.
	Hershbain Ychael Bessie contr mfg	R. L. Polk & Co.
	Hubbell & Cossick hat block mfrs	R. L. Polk & Co.
	Oliveri C Clothing mfr	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Potenza & Camillo John Potenza and Jas Camillo clothing mfrs	R. L. Polk & Co.
	Potenza John Potenza & Camillo	R. L. Polk & Co.
	Reliable Coats Co Harry Pirosnik Abr Schneider Abr Lipshitz and Saml Gutman coat mfrs	R. L. Polk & Co.
	Rosen Ray Solrose Millinery Co	R. L. Polk & Co.
	Solrose Millinery Co RTN Barnet Solash Roy Rosen mlnry	R. L. Polk & Co.
	Steinfeld Abram coat ansd suit mfr	R. L. Polk & Co.
	Zinn Paul pres Bernhardt Zinn Paper Co Inc	R. L. Polk & Co.
1927	BAR MUSICAL NOVELTY CO INC	New York Telephone
	Boulevard Coat Co	New York Telephone
	CROWN HAT FRAME CO	New York Telephone
	Elgin Hat Frame Co Inc	New York Telephone
	LUCIE GUSTAV PAPER	New York Telephone
	Solash Barnet caps	New York Telephone
	SUCCESS HAT CO	New York Telephone
1923	Crown Hat Frame Co RTN Abr Clare Ralphe Vitaghan & Saml King	R. L. Polk & Co.
	Geisler & Lewis Max Geisler Rueben Lewis dress trim	R. L. Polk & Co.
	Geislinger Fred garageman PO h Yonkers NY	R. L. Polk & Co.
	Independent Coat & Suit House RTN Philip Siden Max Sanger	R. L. Polk & Co.
	Kling Saml Crown Hat & Frame Co	R. L. Polk & Co.
	Siden Philip Independent Coat & Suit House	R. L. Polk & Co.
	Slutzkin & Safire Saml Slutzkin and Saml Safire ladies hats	R. L. Polk & Co.
	Slutzkin Saml Slutzkin & Safire	R. L. Polk & Co.
	Solash & Tetensky Barnet Solash Abr Tatensky hats	R. L. Polk & Co.
	Urwitz & Rosenberg Jacob Urwitz only clothing	R. L. Polk & Co.
1920	Bathkoff Robt Paramount Hat Co	R. L. Polk & Co.
	Crown Hat Frame Co RTN Abr Clare Ralph Vitagliano	R. L. Polk & Co.
	Herman Isaac pres H R & S Hat & Cap Co Inc	R. L. Polk & Co.
	Krotoskys L Sons Sol Krotosky glass	R. L. Polk & Co.
	Paramount Hat Co RTN Isidore Weinstein Louis Levine & Robt Rathkoff	R. L. Polk & Co.
	Slutzkin & Safire Saml Slutzkin Saml Safire hats	R. L. Polk & Co.

Year	Uses	Source
1920	Solash & Tetensky Barnet Solash & Abe Tetencky hats	R. L. Polk & Co.
	Stoller Frank caps	R. L. Polk & Co.
	Urwitz & Rosernberg Jacob Urwitz Jacob Rosenberg clothing	R. L. Polk & Co.

LAFAYETTE

371 LAFAYETTE

Year	Uses	Source
1998	CAR LAND	NYNEX Telephone
	GURU FOODS & SNOWBALLS	NYNEX Telephone
1983	Jones Diner	New York Telephone

375 LAFAYETTE

Year	Uses	Source
1938	GENSHEIMER H SEWG MACH ATTACHMENTS	New York Telephone
1920	Duffy Timothy lab	R. L. Polk & Co.
	Fitzpatrick Mallick jr	R. L. Polk & Co.
	Stillwell Alf P clk	R. L. Polk & Co.

LAFAYETTE ST

371 LAFAYETTE ST

Year	Uses	Source
2000	CAR LAND	Cole Information Services
	JONES DINER	Cole Information Services
	LAFAYETTE CAR STER	Cole Information Services

Lafayette St

375 Lafayette St

Year	Uses	Source
2014	EDISON PROPERTIES LLC	EDR Digital Archive
2010	EDISON PROPERTIES LLC	EDR Digital Archive

LAFAYETTE ST

375 LAFAYETTE ST

Year	Uses	Source
2006	Edison Park Fast i s	Hill-Donnelly Information Services

Year	Uses	Source
2000	EDISON PARK FAST	Cole Information Services

Lafayette Street

371 Lafayette Street

Year	Uses	Source
2000	CAR LAND	Cole Information Services
	JONES DINER	Cole Information Services
	LAFAYETTE CAR STER	Cole Information Services
1998	CAR LAND	NYNEX Telephone
	GURU FOODS & SNOWBALLS	NYNEX Telephone
1983	Jones Diner	New York Telephone

379 Lafayette Street

Year	Uses	Source

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

E 4 ST

15 E 4 ST

Year	Uses	Source
1998	OTHER MUSIC INC	NYNEX Telephone
1993	ISLAND TRADING CORNP	NYNEX Telephone
1973	THOET HERBERT H BUYR	New York Telephone
	SHEGRYN OLGA	New York Telephone
	MARKETING TOOLS INC	New York Telephone
	DELBOVE HUGO	New York Telephone
1968	ALBER MUSIC CORP	New York Telephone
1958	LAWSON HERMAN J SR	New York Telephone
1950	ELLIMAN DOUGLAS L & CO INC RLES	New York Telephone

17 E 4 ST

Year	Uses	Source
1998	DOLLHOUSE	NYNEX Telephone
1988	RUDDER RICHARD	NYNEX Telephone
1983	FKNER A B	New York Telephone
1978	TYRRELL L	New York Telephone
1973	A & G CREATIONS INC	New York Telephone
1963	GARFEM DAVID	New York Telephone
	HABIB IDA MRS	New York Telephone
1958	GOLDSCHLAGER HARRY	New York Telephone
1950	LACH H	New York Telephone
	LEVY IRWIN S	New York Telephone
	SALEEBY JOHN A INC MARGE	New York Telephone
1947	LB OIL CO INC	New York Telephone
1942	FLYNN MALLON J INS	New York Telephone
	TUCKER RICHD D B	New York Telephone

19 E 4 ST

Year	Uses	Source
1973	TRANSPARENCIES INC	New York Telephone
1950	BRITCHKY ISIDORE	New York Telephone

FINDINGS

20 E 4 ST

Year	Uses	Source
1998	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
	URBAN LAWRENCE	NYNEX Telephone
1993	A 1 LANDMARK PRESS INC	NYNEX Telephone
1978	NATL RGSTR PUBLSHG CLONC	New York Telephone
1973	KAUFMAN FREDC S	New York Telephone
	EATON W HERBERT MRS	New York Telephone
	BURGESS LEE	New York Telephone
1968	KILDEA YORK	New York Telephone
	GOLDRING GERTRUDE MRS	New York Telephone
	ABRAHAM CHAS	New York Telephone
1958	LOWE TESSIE MRS	New York Telephone
1942	SELTZERS LAUNDRY SVCE	New York Telephone
1938	GREENE JACK INC MILNRY	New York Telephone

21 E 4 ST

Year	Uses	Source
1998	GRAJ AND GUSTAVSEN DESIGN	NYNEX Telephone
	HOLLANDER EDMUND L A DESIGN PC	NYNEX Telephone
	MARLON INC	NYNEX Telephone
	STOLTZMAN MARION	NYNEX Telephone
1993	KATZENSTEIN DAVID STUDIO	NYNEX Telephone
	LACY BILL DESIGN	NYNEX Telephone
	MARLON INC	NYNEX Telephone
	OGILVIE PETER	NYNEX Telephone
	STOLTZMAN MARLON	NYNEX Telephone
	STUDIO ONE INC	NYNEX Telephone
	WOODS MACKINTOSH ARCHITECTS	NYNEX Telephone
	ASTI TOURS ANNE STORCH INTERNATL	NYNEX Telephone
	BAY LINENS INC	NYNEX Telephone
	FIFTH AV FILM LTD	NYNEX Telephone
	GLAVLANO MARCO	NYNEX Telephone
	HOLLANDER EDMUNDO L A DESIGN PC	NYNEX Telephone
1988	APPLIED PUBLSHNG TECHNOLOGIES	NYNEX Telephone
	BESTINFO INC	NYNEX Telephone
	CHINA SEAS INC	NYNEX Telephone
	CONACCHIA PRESS INC	NYNEX Telephone

FINDINGS

Year	Uses	Source
1988	ELECTRONIC DIRECTIONS GROUP	NYNEX Telephone
	KATZENSTEIN DAVID STUDIO	NYNEX Telephone
1983	APEX PRESS	New York Telephone
	CHINA SEAS INC	New York Telephone
	LAUREL BINDERY INC	New York Telephone
	SHEPHERD GALLERY ASSOCS	New York Telephone
1978	CONSTANT CLEANG CONTRCTRS INC	New York Telephone
	LAUREL BINDERY INC	New York Telephone
1973	BEEBER ROBT J	New York Telephone
	CONSTANT CLEANG CONTRCTRS INC	New York Telephone
	FINKEL BERNARD A ATTY	New York Telephone
	LAUREL BINDERY INC	New York Telephone
	SHULSINGER BROS INC PRNTRS	New York Telephone
1968	BATES G M B	New York Telephone
	BATES GRIFFIN MILLER CO PRNTRS	New York Telephone
	GRIFFIN MILLER BATES CO INC PRNTRS	New York Telephone
	LAUREL BINDERY INC	New York Telephone
	SHULSINGER BROS INC PRNTRS	New York Telephone
1963	HALDEMAN MARY E	New York Telephone
	JONIS PUBLSHG CO INC	New York Telephone
	LAUREL BINDERY INC	New York Telephone
	LION THE PRNTR	New York Telephone
	MERCANTILE IMPORT & EXPORT PART CORP	New York Telephone
	SHULSINGER BROS SALES DIV	New York Telephone
	SHULSINGER BROS LINOTYPING & PUBLSHG CO	New York Telephone
1958	LAUREL BINDERY INC	New York Telephone
	LION THE PRNTR	New York Telephone
	MUECK-CARY CO LNC SILVRSMTHS	New York Telephone
	SHUASINGER BROS LLNOTYPLNG & PUBLSHG CO	New York Telephone
	SHUASINGER BROS LLNOTYPLNG & PUBLSHG CO	New York Telephone
1956	CONGRESS CRAVAT CO	New York Telephone
	LAUREL BINDERY INC	New York Telephone
	MUECK-CARY CO INC SILVRSMTHS	New York Telephone
	PARAMOUNT CRAVAT CO INC	New York Telephone
	SHULSINGER BROS LINOTVOING & PUBSHG CO	New York Telephone

FINDINGS

Year	Uses	Source
1956	SHULSINGER BROS LINOTVOING & PUBSHG CO	New York Telephone
1950	MUECK CARY CO INC SILVRSMTHS	New York Telephone
	PARAMOUNT CRAVAT CO INC	New York Telephone
	PICKWICK CO MENS NECKWR	New York Telephone
	SHULSINGER BROS LINOTYPLNG & PUBLSLG CO	New York Telephone
1947	MUECK-CARY CO E INC SILVRSMTHS	New York Telephone
	PARAMOUNT CRAVAT CO INC	New York Telephone
	PICKWICK CO MENS NECKWR	New York Telephone
	SHULSINGER BROS LINOTYPIMG & PUBLSHG CO	New York Telephone
1942	GREEN PUBLICATIONS INC	New York Telephone
	WRIGHT PLASTICS INC	New York Telephone
	AMER METAL SPINNING &STAMPING CO INC	New York Telephone
	GREEN CHAS CO SMPL CDS	New York Telephone
1938	AMER METAL SPINNING & STAMPING CO INC	New York Telephone
	FLORIN MURRAY B	New York Telephone
	FLORIN PRESS PRNTRS	New York Telephone
	GLOBE RULING & BINDING CO	New York Telephone
	RELIABLE BKBNDG CO	New York Telephone
1927	APRIL PHIL	New York Telephone
	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	GOULD M P CO ADVTG	New York Telephone
	HILL ARTHUR PRINTER	New York Telephone
	NOVELTY COMPACT LEATHER CO	New York Telephone
	SIMON ADVTG & PRINTG SERV INC	New York Telephone
	STREEP & HILL INC PRINTERS	New York Telephone
	TAYLOR F W TRUCKMAN	New York Telephone

22 E 4 ST

Year	Uses	Source
1993	RON WOLFSON STUDIO	NYNEX Telephone
	KATY K DESIGNS	NYNEX Telephone
	SCREAMING MIMI	NYNEX Telephone
1973	SELIGMAN BERNARD L ATTY	New York Telephone
1968	MATHIAS JAS H ATTY	New York Telephone
1963	TOWEL SUPL CORP	New York Telephone

FINDINGS

Year	Uses	Source
1963	TOWEL SUPL CORP	New York Telephone

23 E 4 ST

Year	Uses	Source
1998	ACHILLES ANGONS	NYNEX Telephone
	BIOBOX INC	NYNEX Telephone
	BLUNT RECORDINGS	NYNEX Telephone
	BLUNT RECORDINGS	NYNEX Telephone
	CADWAY DESIGN	NYNEX Telephone
	EHRENKRANTZ & ECKSTUT	NYNEX Telephone
	HELPERN ARCHITECTS PC	NYNEX Telephone
	HUNT LINNA ARCHITECT	NYNEX Telephone
	HUNTS ARCHITECTS	NYNEX Telephone
	KATZENSTEMN DAVID STUDIO	NYNEX Telephone
	RICHARDSON ALAN PHOTGRPHY	NYNEX Telephone
	SHOOT DIGITAL	NYNEX Telephone
	STUDIO ONE INC	NYNEX Telephone
	TEEVEE TOONS INC	NYNEX Telephone
	TVT RECORDS	NYNEX Telephone
	ZENREICH MICHAEL ARCHT	NYNEX Telephone
1993	ECKSTUT STANTON SAIA	NYNEX Telephone
	EHRENKRANTZ & ECKSTUT	NYNEX Telephone
	EHRENKRANTZ EZRA SAIA	NYNEX Telephone
	HELPERN ARCHITECTS PC	NYNEX Telephone
	HUNT LINNA ARCHTECT	NYNEX Telephone
	HUNTS ARCHITECTS	NYNEX Telephone
	JERRY STYLE	NYNEX Telephone
	JERRYSTYLE	NYNEX Telephone
	KUHN DENNIS SAIA	NYNEX Telephone
	MALIN & KNECHT	NYNEX Telephone
	PARSONS JEFF AIM	NYNEX Telephone
	RICHARDSON ALAN PHOTGRPHY	NYNEX Telephone
	TEEVEE TOONS INC	NYNEX Telephone
	TVT RECORDS	NYNEX Telephone
	ZENREICH MICHAEL ARCHT	NYNEX Telephone
	ZENREICH MICHAEL FAX	NYNEX Telephone
1983	ED BINDERY	New York Telephone
1978	APEX PRESS	New York Telephone

FINDINGS

Year	Uses	Source
1978	COLONIAL OUT OF PRINT BOOK SVCE INC	New York Telephone
	ED BINDERY	New York Telephone
	KINS-LEAR GRAPHICS INC	New York Telephone
	SCHEINBAUM AL B	New York Telephone
1973	COLONIAL OUT OF PRINT BOOK SVCE INC	New York Telephone
	LITT HERBERT C	New York Telephone
	NORMAC PRNTNG & ENVELOPE CORP	New York Telephone
	SCHEINBAUM AL B	New York Telephone
	YOUNG BINDRY CO MFG	New York Telephone
	YOUNG E M B	New York Telephone
1968	COLONIAL BOOK SVCE	New York Telephone
	GLADSTONE SIDNEY B	New York Telephone
	SCHEINBAUM AL B	New York Telephone
	SHERNOFF ARTHUR TEXTLS	New York Telephone
	SHERNOFF MURRAY M TEXTLS	New York Telephone
	YOUNG BINDRY CO MFG	New York Telephone
	YOUNG E M B	New York Telephone
1963	AMI PRNTNG CO	New York Telephone
	COLONIAL BOOK SVCE	New York Telephone
	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	YOUNG BINDRY INC	New York Telephone
	YOUNG E M B	New York Telephone
1958	COLONIAL BOOK SVCE	New York Telephone
	CRITERION LLNOTYPING & PRNTNG CO	New York Telephone
	SCHEINBAUM AL B	New York Telephone
	YOUNG BINDRY INC	New York Telephone
	YOUNG E M B	New York Telephone
1956	COLONIAL BOOK SVCE	New York Telephone
	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	SCHEINBAUM AL B	New York Telephone
	YOUNG BINDRY INC	New York Telephone
	YOUNG E M B	New York Telephone
1950	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	ELECTRON ELEVATOR CO INC	New York Telephone
	MANHATN LINOTYPE SUPL INC	New York Telephone

Year	Uses	Source
1950	YOUNG BINDRY INC	New York Telephone
	YOUNG E M B	New York Telephone
1947	ART MENU PRESS	New York Telephone
	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	ELECTRON ELEVATOR CO INC	New York Telephone
	MANHATN LINOTYPE SUPL INC	New York Telephone
	MENU ART PRESS	New York Telephone
1942	MENART PRNTNG CO	New York Telephone
	MENU ART PRESS	New York Telephone
	SHULSINGER BROS LINOTYPING & PUBLSHG CO	New York Telephone
	ART MENU PRESS	New York Telephone
	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	CRITERION PUBLSHG CO	New York Telephone
1938	BRADEN BROS INC MFG STATNRS	New York Telephone
	COPPOLA JOHN TRUCKMAN	New York Telephone
	CRITERION LINOTYPING & PRNTNG CO	New York Telephone
	RELIABLE SILK DYEING CO	New York Telephone
	RELIABLE STRAW DYEING CO	New York Telephone
1927	BROWN M B PTG & BDG CO	New York Telephone
	DE VINNE PRESS	New York Telephone
	HARMON & IRWIN INC BK BNDRS	New York Telephone

24 E 4 ST

Year	Uses	Source
1973	ALBI LOIS	New York Telephone
1942	GUBIN SELMA	New York Telephone
	MARX JOSEF	New York Telephone
	ORLINICK SAML	New York Telephone
1938	NEUMANN ALWIN A & SON HATS FLWRS & FTHRS	New York Telephone
	NEUMANN CURT W HATS	New York Telephone
	NEUMANN CURT W HATS FLWRS & FTHRS	New York Telephone
	ROSENBLUM PRESS	New York Telephone
1927	NEUMANN A A & SONS LDS HATS & MILNRY	New York Telephone
	NEUMANN ALWIN A HATS FLWRS & FTHRS	New York Telephone

FINDINGS

Year	Uses	Source
1927	NEUMANN CURT W LDS HATS REMODELED	New York Telephone
	TIERNEY W R	New York Telephone
	VALOVITZ NATLHAN TRUSS MFR	New York Telephone
	VALOW SURGICAL APPLIANCE ISC	New York Telephone

25 E 4 ST

Year	Uses	Source
1988	BAKER STEVEN	NYNEX Telephone
	DRAMATIS PERSONAE INC	NYNEX Telephone
	EULENSPIEGEL SOCIETY INC	NYNEX Telephone
	HENDRA J	NYNEX Telephone
	HEUMANN NELSON	NYNEX Telephone
	KATZ LEANDRO	NYNEX Telephone
	MCMURRAY RUTH	NYNEX Telephone
	MILNE DAVID	NYNEX Telephone
	OTT JOHN	NYNEX Telephone
	SELTZER K	NYNEX Telephone
1983	DRAMATIS PERSONAE INC	New York Telephone
	HENDRA J	New York Telephone
	KATZ LEO	New York Telephone
	MCMURRAY RUTH	New York Telephone
	MILNE DAVID	New York Telephone
	OTT JOHN	New York Telephone
	SELTZER K	New York Telephone
1978	HENDRA ANTHONY	New York Telephone
	KATZ LEO 5	New York Telephone
	MC MURRAY RUTH	New York Telephone
	MILNE DAVID	New York Telephone
	NATIONAL ARTS THEATRE	New York Telephone
	OTT JOHN	New York Telephone
	SELTZER K	New York Telephone
	STEINBERG RON H	New York Telephone
1973	BARER MARSHALL	New York Telephone
	CALUMET ROBE COINC	New York Telephone
	DRAPER DANA	New York Telephone
	MCMURRAY RUTH	New York Telephone
	MILNE DAVID	New York Telephone
	PAGE ROBERT	New York Telephone

FINDINGS

Year	Uses	Source
1973	ROTH RICHARD	New York Telephone
1968	CALUMET ROBE CO INC	New York Telephone
	COLONIAL UNIFORM SALES CO	New York Telephone
	GOLDCREST PAPR & TWIIIE CO	New York Telephone
	HERCULES PACKAGING CO	New York Telephone
	MESSING HEADWR	New York Telephone
	MONOS PAPR CO	New York Telephone
	NEEDLE NOVELTY CORO	New York Telephone
1963	MEYEROWITZ & RYMAN HEADWR	New York Telephone
	PAPR & TWINE CO	New York Telephone
	S & SON INC SOLES	New York Telephone
	MONOS PAPR CO	New York Telephone
	R & F SLIDE FASTENER CO MFRS	New York Telephone
	WICK ART INC	New York Telephone
	WICK HENRY A SCRNS & GREETG CDS	New York Telephone
	CUMET ROHE CO INC	New York Telephone
	D R C SPORTSWR CO	New York Telephone
	FREEMAN OWENS	New York Telephone
	GOLCREST PAPR & TWINE CO	New York Telephone
	HERCULES PACKAGING CO	New York Telephone
	HEADWR	New York Telephone
1958	A & J COAT CO	New York Telephone
	AXELROD MORRIS CAP CO	New York Telephone
	CALUMET ROBE CO INC	New York Telephone
	CREATIVE SCREEN PRNTRS	New York Telephone
	D R C SPORTSWR CO	New York Telephone
	IDEAL CAP CO	New York Telephone
	MESSING HEADWR	New York Telephone
	MEYEROWLTZ & RYMAN HEADWR	New York Telephone
	MUTUAL CAP & HAT CO	New York Telephone
	ROOD S ARTSTS SUPLS	New York Telephone
1956	A & J COAT CO	New York Telephone
	ACADEMY SALES ML ORDR	New York Telephone
	CALUMET ROBE CO INC	New York Telephone
	D R C SPORTSWR CO	New York Telephone
	IDEAL CAP CO	New York Telephone
	MESSING HEADWR	New York Telephone
	MEYEROWITZ & RYMAN HEADWR	New York Telephone

FINDINGS

Year	Uses	Source
1956	MUTUAL CAP & HAT CO	New York Telephone
	NOEL MFG CO INC ELEC FLASHRS	New York Telephone
	STYLE-RITE HEADWEAR CORP	New York Telephone
1950	MEYEROWITZ & RYMAN HEADWR	New York Telephone
	MUTUAL CAP & HAT CO	New York Telephone
	PLASTIC BOTTLE CORP	New York Telephone
	CALBEMET ROBE CO INC	New York Telephone
	D R C SPORTSWR CO	New York Telephone
	G E COAT CO	New York Telephone
	GLIEDMAN & MESSING MFRS CAPS	New York Telephone
	GULF CHEMCL CORP	New York Telephone
	IDEAL BUTTON CO	New York Telephone
	JUDELSHON OSCAR I INC MACHNSTS	New York Telephone
1947	D R C SPORTSWR CO	New York Telephone
	G E COAT CO	New York Telephone
	GLIEDMAN & MESSING MFRS CAPS	New York Telephone
	GULF CHEMCL CORP	New York Telephone
	JUDELSHON O I MACHNST	New York Telephone
	LEADER ROBE CO THE	New York Telephone
	MEYEROWITZ & RYMAN HEADWR	New York Telephone
	MUTUAL CAP & HAT CO	New York Telephone
	POWER MASTER DRIVES	New York Telephone
1942	LYNN & BARTON CHEMCLS	New York Telephone
	MEYEROWITZ A HEADW	New York Telephone
	MUTUAL CAP &HAT CO	New York Telephone
	POWER-MASTER DRIVES	New York Telephone
	RAPPAPORT &FELDMAN HEADWR	New York Telephone
	SANLEA HAT CO	New York Telephone
	ALBERT BROS ATTYS	New York Telephone
	ALBERT HENRY B ATTY	New York Telephone
	ALBERT HERMAN M ATTY	New York Telephone
	ALBERT IRVING L ATTY	New York Telephone
	EXCELLENT SPORTWR CO	New York Telephone
	FOX EMBLEM CORP	New York Telephone
	GLIEDMAN & MESSING MFRS CAPS	New York Telephone
	GULF CHEMCL CO	New York Telephone
	JUDELSHON O I MACHNST	New York Telephone
1938	ABBATE COAT CONTRACTG CO	New York Telephone

Year	Uses	Source
1938	ACE EMBLEM	New York Telephone
	GLIEDMAN & MESSING MFRS HATS & CAPS	New York Telephone
	JUDELSHON O I MACHINIST	New York Telephone
	LAUFER JACK PILWS	New York Telephone
	MUTUAL CAP & HAT CO	New York Telephone
	POWER-MASTER DRIVES	New York Telephone
	SANLEA HAT CO	New York Telephone
	SCHAEFER S HATS	New York Telephone
1927	ABBATE COAT CONTRCTG CO	New York Telephone
	BELGIUM COAT FORM CO	New York Telephone
	CENTRAL CAP CO	New York Telephone
	ART INSTITIUTE	New York Telephone
	DIAMOND HYMAN LTHER GOODS	New York Telephone
	EXCHANGE KNITTING MILLS	New York Telephone
	FREEMAN H J PICTURE FRAMES	New York Telephone
	GLIEDMAN & MESSING MFRS HATS & CAPS	New York Telephone
	OVAL HAT & CAP CO	New York Telephone
	PHOENIX LEATHER INC	New York Telephone

26 E 4 ST

Year	Uses	Source
1958	BUCHNER MORRIS B	New York Telephone
1950	RAYFIELD HERMAN M	New York Telephone
1947	GLOBE PHOTO NOVELTY CO	New York Telephone
	RENNERT CO THE FURN PADS	New York Telephone
1942	BIGGART SOLAR PRINT CO	New York Telephone
	GARTENZAUN HANS FETHRS	New York Telephone
	GLOBE PHOTO NOVELTY CO	New York Telephone
1938	GLOBE PHOTO NOVELTY CO	New York Telephone
	FOXHAN MFG CO	New York Telephone
	BIGGART SOLAR PRINT CO	New York Telephone
1927	RITTEL & SLUTZKY HATS	New York Telephone
	FELDMAN WM VEST COATS	New York Telephone
	BIGGART SOLAR PRINTING CO	New York Telephone

27 E 4 ST

Year	Uses	Source
1988	COOPER SQ TIRE EXCH	NYNEX Telephone

FINDINGS

Year	Uses	Source
1988	DIANE FOOD PRODS	NYNEX Telephone
1983	WOLNICK ELIZABETH A	New York Telephone
1947	ALLIES TAXI CO	New York Telephone
	RIO CAB CORP	New York Telephone
1942	DE SANTIS IRON WKS	New York Telephone
	POLLACK ISIDORE BAGS	New York Telephone
1938	SCHROEDER HARRY ELEC CONTR	New York Telephone
	DE SANTIS IRON WKS	New York Telephone
1927	CENTRAL HAT FRAME CO	New York Telephone
	WORONER S RESTAURANT	New York Telephone

28 E 4 ST

Year	Uses	Source
1998	GASKEL ROBERT E	NYNEX Telephone
	PLANTWORKS INC	NYNEX Telephone
	E 4 ST HOUSING CORP	NYNEX Telephone
1993	APOLLO FILMS CO	NYNEX Telephone
	CELETANO MARK	NYNEX Telephone
	PLANTWORKS INC	NYNEX Telephone
	E 4 ST HOUSING CORP	NYNEX Telephone
1988	BOOKHARDT F B	NYNEX Telephone
	COOPER K	NYNEX Telephone
	FAGIN J E	NYNEX Telephone
	FREDERICK JON	NYNEX Telephone
	GASKELL R E	NYNEX Telephone
	GREENLEAF FREDRICK P	NYNEX Telephone
	GRIFFIN GEORGE	NYNEX Telephone
	KALLAS JOHN	NYNEX Telephone
	KARWOSKI RICHARD	NYNEX Telephone
	MALABRIGO MARK	NYNEX Telephone
	MC CRLEY N L	NYNEX Telephone
	MC KNIGHT SANDRA	NYNEX Telephone
	STONE K	NYNEX Telephone
	STONE LOUIS A	NYNEX Telephone
	E 4 ST HOUSING CORP	NYNEX Telephone
	WECHSBERG ORIN	NYNEX Telephone
1983	KALLAS JOHN	New York Telephone
	KARWOSKI RICHARD	New York Telephone
	MC CARLEY N L	New York Telephone

FINDINGS

Year	Uses	Source
1983	WECHSBERG ORIN	New York Telephone
	BOOKHARDT F B	New York Telephone
	COOPER K	New York Telephone
	FIERING A M	New York Telephone
	GASKELL R E	New York Telephone
	GREENLEAF FREDRICK P	New York Telephone
	GRIFFIN GEORGE	New York Telephone
	JOROB REALTY CORP	New York Telephone
1978	KARWOSKI RICHARD	New York Telephone
	KEPNER M	New York Telephone
	METROPOLIS PHOTOPLAYS	New York Telephone
	WIRLS DOUGLAS N	New York Telephone
	BOOKHARDT F B	New York Telephone
	CENTER FOR INTERNATIONAL ARTS	New York Telephone
	COOPER K	New York Telephone
	FROMBOLUTI LONA	New York Telephone
	GASKELL R E	New York Telephone
	GREENLEAF FREDRICK P	New York Telephone
	GRIFFIN GEORGE C	New York Telephone
	JOROB REALTY CORP	New York Telephone
	KALLAS JOHN	New York Telephone
1973	BEUCHAT CARMEN	New York Telephone
	CO KNIT NOVELTY CO INC	New York Telephone
	DANCO PRESS	New York Telephone
	GOODDEN C	New York Telephone
	JOROB REALTY CORP	New York Telephone
	LEO SILVERSTONE B	New York Telephone
	MASON MOORE TRACY INC PRNTNG PRESS MACHNSTS	New York Telephone
	MATTA GORDON	New York Telephone
	RAPID ENVELOPE & OFFSET CO	New York Telephone
	SPIEGEL BRUCE	New York Telephone
	TRADE PRNTNG CARP	New York Telephone
1968	BUCHNER MORRIS B	New York Telephone
	CO-KNIT NOVELTY COLNC	New York Telephone
	DANCO PRESS	New York Telephone
	FLORETTE LEATHR GOODS CORO	New York Telephone
	GENL PRATNG CO	New York Telephone
	LEO SILVERSTONE B	New York Telephone

FINDINGS

Year	Uses	Source
1968	LOYAL UNIFORM CORP	New York Telephone
	MASON MOORE TRACY INC PRINTING PRESS MACHUSLS	New York Telephone
	RAPID ENVELOPE & & OFFSET CO	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	TRADE PRNTNG CORP	New York Telephone
	WALTCO INC PLSTCS	New York Telephone
	WALTZER FRANCES INTR DECRTR	New York Telephone
1963	BUCHNER MORRIS B	New York Telephone
	CO-KNIT NOVELTY CO INC	New York Telephone
	DE VINCENZO VINCENT COATS	New York Telephone
	GENL PRNTNG CO	New York Telephone
	GRUMET ZACHARY	New York Telephone
	LEO SILVERSTONE B	New York Telephone
	MASON MOORE TRACY INC PRINTG PRESS MACHNSTS	New York Telephone
	ROALCO HEADWR INC	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	RUBIN MORRIS M	New York Telephone
	TRADE PRNTNG CORP	New York Telephone
	WALTCO INC PLSTCS	New York Telephone
	WALTZER FRANCES INTR DECRTR	New York Telephone
1958	CO-KNIT NOVELTY CO INC	New York Telephone
	DE VINCENZO & SON CONTRS	New York Telephone
	KIRP HARRY T ATTY	New York Telephone
	LEO SILVERSTONE B	New York Telephone
	LUKBROD HAT & CAP CO	New York Telephone
	RAPPAPORT H & CO SWETBNDS & SHEEPSKIN	New York Telephone
	RODRIGUES BENANGGO	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	TRACY A H MACHNST	New York Telephone
	TRADE PRNTNG CORP	New York Telephone
	WALTZER FRANCES LNTR DECRTR	New York Telephone
1956	ARTCRAFTSMEN INC FCTY	New York Telephone
	DE VINCENZO & SON CONTRS	New York Telephone
	KAPP MAX DOLLS EYES	New York Telephone
	KIRP HARRY T ATTY	New York Telephone
	MARKS CHAS B MUSIC PUBR	New York Telephone

FINDINGS

Year	Uses	Source
1956	MASON MOORE TRACY INC PRINTG PRESS MACHNSTS	New York Telephone
	MCKINLEY PUBLISHERS INC	New York Telephone
	RAPPAPORT H & CO SWETBNDS & SHEEPSKIN	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	ROSENBERG SMITH CORP YARNS	New York Telephone
	SMITH DAVID R YRNS	New York Telephone
	TRACY A H MACHNST	New York Telephone
	WALTCO INC PLSTCS	New York Telephone
	WALTZER FRANCES INTR DECRTR	New York Telephone
1950	ARTCRAFTSMEN INC FCTY	New York Telephone
	DEO VICENZO & SON CONTRS	New York Telephone
	KAPP MAX DOLLS RYES	New York Telephone
	LUKBROD HAT & CAX CO	New York Telephone
	MASON MOORE TRACY INC PRINTG PRESS MACHNSTS	New York Telephone
	RAPPAPORT H & CO SWETBNDS & SHEEPSKLN	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	WALTCO INC PISTCS	New York Telephone
	WALTZER FRANCES INTR DECRTR	New York Telephone
1947	KAPP MAX DOLLS EYES	New York Telephone
	KOERNER & KIEFFER	New York Telephone
	LUKBROD HAT & CAP CO	New York Telephone
	MASON MOORE TRACY INC PRINTG PRESS MACHNSTS	New York Telephone
	RAPPAPORT H & CO SWETBNDS	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	TRACY A H MACHNST	New York Telephone
	WALTCO INC PLSTCS	New York Telephone
	ARTCRAFTSMEN INC FCTY	New York Telephone
	DE VINCENZO & YULA CONTRS	New York Telephone
	F & G DOLL SHOES CO	New York Telephone
1942	ARTCRAFTSMEN	New York Telephone
	BOW SOLDER PRODS CO INC	New York Telephone
	F&G DOLL SHOES CO	New York Telephone
	KAPP MAX DOLLS EYES	New York Telephone
	KOERNER & KIEFFER	New York Telephone
	LEVINE H CLKS	New York Telephone

FINDINGS

Year	Uses	Source
1942	LUKBROD HAT & CAP CO	New York Telephone
	MASON MOORE TRACY INC PRINTG PRESS MACHNSTS	New York Telephone
	MOOS ARTHUR ADVTG	New York Telephone
	RAPPAPORT H SWETBNDS	New York Telephone
	ROLLING EYES MFG CO	New York Telephone
	SEIDENBERG BROS HAIR GDS	New York Telephone
	TRACY A H MACHNST	New York Telephone
1938	AY-ONE HANDBAG CO	New York Telephone
	BWAY RUBBER NOVELTY CO	New York Telephone
	EASTERN BOX SPECIALTIES INC	New York Telephone
	F & G DOLL SHOES CO	New York Telephone
	HOFFMAN S SCHOENBERG CAPS	New York Telephone
	KOERNER & KIEFFER	New York Telephone
	KRAUS HANDBAG CO INC	New York Telephone
	MASON MOORE TRACY INC PRINTG PRESS MACHNSTS	New York Telephone
	SEIDENBERG BROS HAIR GDS	New York Telephone
	TRACY A H MACHNST	New York Telephone
1927	ACKERMAN SAML HATS CAPS	New York Telephone
	ACKERMAN & WIENER HATS CAPS	New York Telephone
	ALPEROVICH M PRNTR	New York Telephone
	BELAIEF MICHAEL G CAPS	New York Telephone
	DAVIDSON LOUIS PRINTER	New York Telephone
	ENTWISTLE MASON & MOORE	New York Telephone
	FORMAN LOUIS TROUSERS	New York Telephone
	GINZBERG S PRNTR	New York Telephone
	HEBREW MONOTYPE PRESS INC	New York Telephone
	HIGH GRADE COAT FRONT CO	New York Telephone
	KOATOFF MAYER PRNTR	New York Telephone
	KOERNER & KIEFFER	New York Telephone
	MARKOWITZ LOUIS ARTIST	New York Telephone
	MASON & MOORE	New York Telephone
	NIEDERMAN & WALDSMAN BOYS CLTHG	New York Telephone
	PARGMENT ISIDOR PRINTER	New York Telephone
	PLANET CAP WORKS	New York Telephone
	SCHOTTENFELD & FRIDKIN HATS & CAPS	New York Telephone
	SHULDNER M CO BONNET WIRE	New York Telephone

Year	Uses	Source
1927	TRIO PRESS INC PRINTERS	New York Telephone

29 E 4 ST

Year	Uses	Source
1998	OLD MERCHANT S HOUSE	NYNEX Telephone
1993	OLD MERCHANT S HOUSE	NYNEX Telephone
1988	OLD MERCHANT S HOUSE	NYNEX Telephone
1983	OLD MERCHANT S HOUSE	New York Telephone
1978	OLD MERCHANTS HOUSE	New York Telephone
	SCHATTMAN STEPHEN L	New York Telephone
1973	NEWBURGER ROBT L	New York Telephone
	OLD MERCHANTS HOUSE	New York Telephone
1968	OLD MERCHANTS HOUSE	New York Telephone
	VERNADAKIS ANDRE	New York Telephone
1963	OLD MERCH S HOUSE	New York Telephone
1958	OLD MERCH S HOUSE	New York Telephone
1956	OLD MERCH S HOUSE	New York Telephone
1950	OLD MERCHS HOUSE	New York Telephone
1947	OLD MERCH S HOUSE	New York Telephone
1942	OLD MERCH S HOUSE	New York Telephone
1938	CASE H P	New York Telephone
1931	ANSBOROUGH JOHN P	Manhattan and Bronx Directory Publishing Company Residential Directory

23R E 4 ST

Year	Uses	Source
1950	SPIELER PHILIP	New York Telephone

E 4O

15 E 4O

Year	Uses	Source
1927	SCHERMERHORN RICHD JR LANDSCP-ARCHT	New York Telephone

E 4TH

17 E 4TH

Year	Uses	Source
1923	Levy Louis mens furngs	R. L. Polk & Co.
1920	Zucker Jos L embroidorers	R. L. Polk & Co.

FINDINGS

20 E 4TH

Year	Uses	Source
1934	Hetters M Sons RTN Gemsco Inc emblems mfrs	R. L. Polk & Co.
1920	Knight Marion A indexer H W Wilson Co	R. L. Polk & Co.

21 E 4TH

Year	Uses	Source
1934	Hill Arth Inc NY Arth Hill pres Jos D Jackson v pres H Modery sec treas printing	R. L. Polk & Co.
	Criterion Linotyping & Printing Co Inc NY cap $20000 Isadore Strugatz pres John Glassman sec treas	R. L. Polk & Co.
	Cronau Printing Co RTN Danl Krainman sec	R. L. Polk & Co.
	Globe Ruling Co RTN Saml Silverman paper rulers	R. L. Polk & Co.
	Jackson Jos D v pres Arth Hill Inc	R. L. Polk & Co.
	Reliable Bookbinding Co RTN David Bernstein	R. L. Polk & Co.
	Tex Tone Paper Products Co RTN Albert M Konocky	R. L. Polk & Co.
1927	Taylor F W truckman	New York Telephone
	Streep & Hill Inc printers	New York Telephone
	Simon Advtg & Printg Serv Inc	New York Telephone
	Novelty Compact Leather Co	New York Telephone
	Hill Arthur printer	New York Telephone
	Gould M P Co advtg	New York Telephone
	Mailing & shipping dept	New York Telephone
	Criterion Linotyping & Prntng Co	New York Telephone
	April Phil	New York Telephone
1923	Taylor Frank W truckmn	R. L. Polk & Co.
	Streep & Hill Inc NY Arth Hill pres Michl Streep treas printing	R. L. Polk & Co.
	Monte Christi Panama Hat Co NY Philip April pres Jos Levy treas	R. L. Polk & Co.
	Harmon & Irwin Inc N Y Martin J Harmon pres Arth R Irwin sec bkbndrs	R. L. Polk & Co.
	Hall Frank W c/o pub Co Inc	R. L. Polk & Co.
	Droste Roberta Open Door Gift Shop	R. L. Polk & Co.
1920	Bergwald Material Co RTN Saml S Waldmann	R. L. Polk & Co.
	Bergwardt Max Perfect Art Embroidery h Elizabeth NJ	R. L. Polk & Co.

Year	Uses	Source
1920	Monte Christi Panama Hat Co NY Philip April pres Jos Levy v p treas	R. L. Polk & Co.
	Reilly Electrotype Co Inc NY Jos Reilly pres Louis Carlo sec treas	R. L. Polk & Co.
	Tissue Paper Syndicate NY Max P Weinberg pres M J Weinberg sec treas	R. L. Polk & Co.
	Weinberg Julius pres Grand Union Folding Box Co Inc	R. L. Polk & Co.

23 E 4TH

Year	Uses	Source
1934	Chelsea Dye Works Milton Geller	R. L. Polk & Co.
	Brown M B Printing Co M B Brown	R. L. Polk & Co.
	Brown M B M B Brown Printing Co	R. L. Polk & Co.
1927	Harmon & Irwin Inc bk bndrs	New York Telephone
	De Vinne Press	New York Telephone
	Brown M B Ptg & Bdg Co	New York Telephone
1923	Waldman Jos Nicderman & Waldman	R. L. Polk & Co.
	Rubin I Co RTN Isaac Rubin Abr Zimmon Edw L Gilliams Jr electrotypers	R. L. Polk & Co.
1920	Rubin I Co RTN Isaac Rubin Abr Zimmon Edw L Gilliams Jr electrotypers	R. L. Polk & Co.

24 E 4TH

Year	Uses	Source
1934	Rosenblum Press Inc NY; cap $10 000 Morris Rosenblum pres Rose Rosenblum sec treas printing	R. L. Polk & Co.
	Neumann A Julius Pollak & Sons Inc r Weehawken NJ	R. L. Polk & Co.
	Neumans Hats Curt W Neuman hats	R. L. Polk & Co.
	Neuman Curt W Neuman Hats	R. L. Polk & Co.
1927	Neumann A A & Sons lds hats & milnry	New York Telephone
	Neumann Alwin A hats flwrs & fthrs	New York Telephone
	Neumann Curt W lds hats remodeled	New York Telephone
	Tierney W r	New York Telephone
	Valovitz Natlhan truss mfr	New York Telephone
	Valow Surgical Appliance Isc	New York Telephone
1923	Neumanns Alwin A Sons Walter P & Curt W Neumann mlnry	R. L. Polk & Co.
	Neumann Walter P Alwrin A Neumann & Sons	R. L. Polk & Co.
	Neumann Alwin A & Sons Aalwin A Hedwig S & Curt W Neumann ladies hats	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1920	Neumann Alvin A & Son Curt W & Alvin A art flowers	R. L. Polk & Co.

25 E 4TH

Year	Uses	Source
1934	Sacks D Co David Sacks cap mfrs	R. L. Polk & Co.
	Marie Hat Co RTN Geo Handler	R. L. Polk & Co.
	Gliedman & Messing Selig Gliedman Morris Messing cap mfrs	R. L. Polk & Co.
	Abbate Coat Contracting Co TN Louis Abbate	R. L. Polk & Co.
1927	Phoenix Leather Inc	New York Telephone
	Oval Hat & Cap Co	New York Telephone
	Gliedman & Messing mfrs hats & caps	New York Telephone
	Freeman H J picture frames	New York Telephone
	Exchange Knitting Mills	New York Telephone
	Diamond Hyman lther goods	New York Telephone
	Art Institiute	New York Telephone
	C tailor	New York Telephone
	Belgium Coat Form Co	New York Telephone
	Abbate Coat Contrctg Co	New York Telephone
1923	Wiener S & Son Saml & Morris hat mfrs	R. L. Polk & Co.
	Diamond Hyman leather gds	R. L. Polk & Co.
	Acme Cap Mfg Co RTN Carl Eisernberg Saml Ratz	R. L. Polk & Co.
1920	Wiener S & Son Saml & Morris hat mfrs	R. L. Polk & Co.
	White & Frieman Inc N Y Saml Frieman pres Saml White sec hats	R. L. Polk & Co.
	Phoenix Leather Goods Corp NY Hyman Diamond pres Sam Slotoloff v p Abr Schneider sec treas	R. L. Polk & Co.
	Phenix Leather Goods Corp Inc NY Hyman Diamond pres Abram Schneider sec & treas	R. L. Polk & Co.
	Great Jones Headwear Co Inc NY Morris Reiser pres Meyer Brizel Sec Oscar Schwartz treas	R. L. Polk & Co.
	Goldman S & Bro Simon & Wm clothing	R. L. Polk & Co.
	Diamond Hyman belts	R. L. Polk & Co.
	Belfast Millinery Co Inc NY Abr Friedman pres	R. L. Polk & Co.
	Begun & Co Inc NY Wm Begun pres Jos Lechowitzky sec & treas hats	R. L. Polk & Co.

FINDINGS

26 E 4TH

Year	*Uses*	*Source*
1934	Biggart Solar Print Co Inc NY cap $2500 Jas Biggat pres treas Estelle L Biggart v pres Estelle E Monkan sec enlargements	R. L. Polk & Co.
	Klinitzhy Saml tailor	R. L. Polk & Co.
1927	Rittel & Slutzky hats	New York Telephone
	Feldman Wm vest coats	New York Telephone
	Biggart Solar Printing Co	New York Telephone
1923	K R Cloak Co RTN Barnttt Kaplan	R. L. Polk & Co.
	Kaplan Barnett G R Cloak Co	R. L. Polk & Co.
	S & Z Cloak Co RTN Sol Schiffman Hyman Fischbaum	R. L. Polk & Co.
	Shapses & Cooperman Max Shapses HArry Cooperman childrens coats	R. L. Polk & Co.
1920	Excello Kntting Mills RTN David Wilson	R. L. Polk & Co.
	Gottlieb S & H Sarah & Harry Gottlieb hat linings	R. L. Polk & Co.
	Belowsk & Goldberg Isidore Belowsky jacob Goldberg Cap mfrs	R. L. Polk & Co.
	Butler L W Co RTN Louis W Butler	R. L. Polk & Co.

27 E 4TH

Year	*Uses*	*Source*
1934	Desantis Iron Works RTN Jerome DeSantis	R. L. Polk & Co.
1927	Woroner S restaurant	New York Telephone
	Central Hat Frame Co	New York Telephone
1923	Sendar Cap Co RTNPaul Sendar	R. L. Polk & Co.
	Friedman H & Co RTN Hyman Friedman clothing	R. L. Polk & Co.
1920	Weiner Wm Alaska hat Co	R. L. Polk & Co.
	Sendar Cay Co RTN Philip Sendar	R. L. Polk & Co.
	Lilly Jas	R. L. Polk & Co.
	Lewis Morris D Sterling Canvas Co	R. L. Polk & Co.
	Kaufman Sarah Mrs sec treas M Kaufman Co Inc	R. L. Polk & Co.
	Kaufman Morris pres M Kaufman Co Inc	R. L. Polk & Co.
	Kaminstein Bros Morris Hyman & Abraham caps	R. L. Polk & Co.
	Friedman H & Co Hyman Friedman clothing	R. L. Polk & Co.
	Friedman Hyman H Friedman & Co	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1920	Alaska Hat Co TN Louis Abrams & Wm Wiener	R. L. Polk & Co.

28 E 4TH

Year	Uses	Source
1934	Brescia Vincent errand boy Trio Press Inc	R. L. Polk & Co.
	Goldstein Jacob mgr M Kuppersmit	R. L. Polk & Co.
	Kuppersmith Max Anna tailor	R. L. Polk & Co.
	Mason Mooie Tracy Inc NY Wm O Mason pres Arch H Tracy v pres Frank Danshar sec mach	R. L. Polk & Co.
	Mason Wm O pres Mason Moore Tracy Inc	R. L. Polk & Co.
1927	High Grade Coat Front Co	New York Telephone
	Kastner Wolf r	New York Telephone
	Ackerman Saml hats caps	New York Telephone
	Ackerman & Wiener hats caps	New York Telephone
	Alperovich M prntr	New York Telephone
	Belaief Michael G caps	New York Telephone
	Davidson Louis printer	New York Telephone
	Entwistle Mason & Moore	New York Telephone
	Forman Louis trousers	New York Telephone
	Ginzberg S prntr	New York Telephone
	Hebrew Monotype Press Inc	New York Telephone
	Schottenfeld & Fridkin hats & caps	New York Telephone
	Shuldner M Co bonnet wire	New York Telephone
	Trio Press Inc printers	New York Telephone
	Koatoff Mayer prntr	New York Telephone
	Koerner & Kieffer	New York Telephone
	Markowitz Louis artist	New York Telephone
	Mason & Moore	New York Telephone
	Niederman & Waldsman boys clthg	New York Telephone
	Pargment Isidor printer	New York Telephone
	Planet Cap Works	New York Telephone
1923	Beck Louis hats and caps	R. L. Polk & Co.
	Cohen R & Co RTN Rubin & Meyer Cohen clothing	R. L. Polk & Co.
	Comfort Style Clothes RTN Adolph Wolf clothing	R. L. Polk & Co.
	Cutler & Gillman Isidor Cutler Harry Gillman coat fronts	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1923	Feedelman & Shatz Chas Feedelman Lousi Shatz hats & caps	R. L. Polk & Co.
	Gelman Saml coat fronis	R. L. Polk & Co.
	Grevstone Hat Co Inc NY	R. L. Polk & Co.
	Mason & Moore Inc N Y Wm O Mason pres Geo Chapman sec Wm A Moore treas ptg mchy	R. L. Polk & Co.
	Mason & Moore Realty Corp N Y Wm O Mason pres Geo Chapman sec Wm A Moore treas	R. L. Polk & Co.
	Massy David Royal Novelty House	R. L. Polk & Co.
	Niederman Max Niederman & Waldman	R. L. Polk & Co.
	Niederman & Waldman RTN Max Niederman Jos Waldman	R. L. Polk & Co.
	Royal Novelty House RTN David Mast Harry Orshansky Benj Hass novelties	R. L. Polk & Co.
	Shatz Louis c/o Fredkman & Shaiz	R. L. Polk & Co.
	Shuldner M Co RTN Michl Shuldner wire	R. L. Polk & Co.
1920	Finesilver & Levinson Inc NY Harry Finesilver pres Chas Levinson treas clothing mfrs	R. L. Polk & Co.
	Feinberg Alex	R. L. Polk & Co.
	Sea Island Thread Co N Y Bennett Fertig pres Sol Mann v p Alex Femberg sec treas	R. L. Polk & Co.
	Sea Tang Oyster Co N Y A M Porth pres Julian A Gregory sec Andrew F Skinner treas ft Pike	R. L. Polk & Co.

29 E 4TH

Year	Uses	Source
1931	Ansborough John P	Manhattan and Bronx Directory Publishing Company Residential Directory
1920	Juliani Frank M L Haulage Co h Bkn	R. L. Polk & Co.
	Juliand Laura O tchr PS	R. L. Polk & Co.

E 4TH F

20 E 4TH F

Year	Uses	Source
1934	Quinlan Inc NY Frank C Quinlan pres treas Josephine G Quinlan v pres sec tailor mer	R. L. Polk & Co.

FINDINGS

E 4TH FL

15 E 4TH FL

Year	Uses	Source
1934	McClelland Nancy Inc NY cap $ 75 000 Nancy V McClelland pres treas Jas F McClelland v pres Francis D Gilbert sec int decrs	R. L. Polk & Co.
	Hancock A D Anne sten r Yonkers NY	R. L. Polk & Co.
	Darson V toilet prepatins	R. L. Polk & Co.
	Hanco Negligee Co H Hancrow & Co Inc	R. L. Polk & Co.
1920	DeCain Mace tailor	R. L. Polk & Co.

17 E 4TH FL

Year	Uses	Source
1934	Manhattan Buckle & Trimning Co RTN Adolph Waldman	R. L. Polk & Co.

20 E 4TH FL

Year	Uses	Source
1934	Schwinn Carl W mer tailor	R. L. Polk & Co.
	Ramig F A Co RTN Fredk A Ramiz laces	R. L. Polk & Co.

21 E 4TH FL

Year	Uses	Source
1934	Oshima Kano Oshima Art Galleries h Carmel NY	R. L. Polk & Co.
	Oshima Art Galleries RTN Kano Oshima pictures engravings dlrs	R. L. Polk & Co.
	MacCreogh Gordon artist	R. L. Polk & Co.

22 E 4TH FL

Year	Uses	Source
1934	Rath Gerda sec Max Glaesel	R. L. Polk & Co.
	Manhattan Binding Works RTN Rubin Kulchin	R. L. Polk & Co.
	Courtney Mme Inc NY Charlotte Courtney prestresas corsetiore	R. L. Polk & Co.
	Charlotte Mme Charlotte Courtney corsetiere	R. L. Polk & Co.

23 E 4TH FL

Year	Uses	Source
1934	Venice Art Linens NY: Vincente Consolazio	R. L. Polk & Co.

Year	Uses	Source
1934	Alvin Needlecraft Co RTN Camillo L Liberati Doselina Consolazio	R. L. Polk & Co.
	Barad David sec treas Traders Import & Export Co Inc	R. L. Polk & Co.

24 E 4TH FL

Year	Uses	Source
1934	Smith Raymond treas Ivan T Johnson Co Inc	R. L. Polk & Co.
	Silver Tone Fabrics Co RTN Benj Resnick	R. L. Polk & Co.
	Potter Erford M v pres Ivan T Johnson Co Inc	R. L. Polk & Co.
	Johnson Ivan T Co Inc NY cap 120 000 Ivan T Johnson pres Erford M Potter v pres Emma C Case sec Raymond Smith treas electrioc meter service	R. L. Polk & Co.
	Johnson Ivan T pres Ivan T Johnson Co Inc	R. L. Polk & Co.
	Galotta and Jess Marie Galotta Jessie Marks drsmkrs	R. L. Polk & Co.
	Case Emma C sec Ivan T Johnson Co Inc	R. L. Polk & Co.

26 E 4TH FL

Year	Uses	Source
1934	Glencross Geo W Glencross & Carpentier Engraving Co	R. L. Polk & Co.
	Abkowitz Jos Pauline contr	R. L. Polk & Co.
	Carpentier Eug G Glencross & Carpentier Engraving Co	R. L. Polk & Co.
1923	Leventritt Row RTN decorator	R. L. Polk & Co.

27 E 4TH FL

Year	Uses	Source
1934	Howard Co The RTN Jos Howard needlewk	R. L. Polk & Co.
	Howard Jos The Howard Co	R. L. Polk & Co.
1923	Tri Arts Press Inc NY F Wm Shaefor pres Emmy Wahl sec	R. L. Polk & Co.
1920	Tri Arts Press Inc N Y F W Schaefer pres E Wahl sec treas	R. L. Polk & Co.

28 E 4TH FL

Year	Uses	Source
1934	Rinkle Beni sec treas L H Cohen Co inc	R. L. Polk & Co.

Year	Uses	Source
1934	Cohen L H Co Inc NY cpa $ 25 000 Lauis Jacob pres Benj Rinkle sec treas photo frames	R. L. Polk & Co.

29 E 4TH FL

Year	Uses	Source
1934	Black F Le Mar sec K & B Electrical Equipt Co Inc	R. L. Polk & Co.
	Bayart Mme Florence Bayart drsmkr	R. L. Polk & Co.
	Levin Jos Meta ladies scarfs	R. L. Polk & Co.

E 4TH FL 10

15 E 4TH FL 10

Year	Uses	Source
1934	Parisian Chic Silk Undeswear Co RTN Morris Bienstock	R. L. Polk & Co.

E 4TH FL H BKN

22 E 4TH FL H BKN

Year	Uses	Source
1923	Rosenblum Pinkus tailor	R. L. Polk & Co.

E 4TH FL H DO

20 E 4TH FL H DO

Year	Uses	Source
1934	Hammer Frank H dentist	R. L. Polk & Co.

26 E 4TH FL H DO

Year	Uses	Source
1923	Georgenne Mme hats gowns	R. L. Polk & Co.

E 4TH FL H HACKENSACK NJ

24 E 4TH FL H HACKENSACK NJ

Year	Uses	Source
1934	Weigl Geo mach	R. L. Polk & Co.

FINDINGS

E 4TH H BKN

25 E 4TH H BKN

Year	Uses	Source
1923	Blank David TN coats	R. L. Polk & Co.

28 E 4TH H BKN

Year	Uses	Source
1923	Wolf Adolph clothing	R. L. Polk & Co.

E 4TH H DO

27 E 4TH H DO

Year	Uses	Source
1923	Woronock David sec Alsenstein & Worenock & Sons Inc h Bkn	R. L. Polk & Co.
	Waroner Saml restr	R. L. Polk & Co.
	Woronock Morris treas Alsenstein & Woronock & Sona Inc Bkn	R. L. Polk & Co.
1920	Werner Saml restr	R. L. Polk & Co.

E 4TH H IRVINGTON NY

27 E 4TH H IRVINGTON NY

Year	Uses	Source
1923	Harmon Arthur L archt	R. L. Polk & Co.

E 4TH R LAKEWOOD NJ

26 E 4TH R LAKEWOOD NJ

Year	Uses	Source
1934	Feinman Harry vest mfr	R. L. Polk & Co.

E 4TH R PARK RIDGE NJ

25 E 4TH R PARK RIDGE NJ

Year	Uses	Source
1934	Judelshon Nina sten Oscar I Judelshon	R. L. Polk & Co.

FINDINGS

E 4th St

14 E 4th St

Year	Uses	Source
2014	INGLETON ROSEMARIE M D	EDR Digital Archive
	FEWELL CHRISTINE PHD	EDR Digital Archive
	VARGA MICHAEL P PHD	EDR Digital Archive
	KAPLAN JOHN INTGRTD FLNG THRPY	EDR Digital Archive
	LEMBERSKY PAUL	EDR Digital Archive
	TFL-US INCORPORATED	EDR Digital Archive
	ARFA-LAW PC	EDR Digital Archive
	ISRAEL MATZ HEBREW CLASSICS	EDR Digital Archive
	LOSCALZO ANTHONY	EDR Digital Archive
	URBAN GOLF ACADEMY	EDR Digital Archive
	SILK BUILDING CONDOMINIUM	EDR Digital Archive
	TODD MCNIFF MD PC	EDR Digital Archive
	LAURIE BLMNFELD CONSULTING INC	EDR Digital Archive
	MODERN VINTAGE RECORDINGS LLC	EDR Digital Archive
	PORTRAITS BY VALERIE	EDR Digital Archive
	PARTY SHOPS PLUS INC	EDR Digital Archive
	GROOVY BOOTS PRODUCTIONS INC	EDR Digital Archive
	CENTER FOR ENVMTL THRPUTICS IN	EDR Digital Archive
	GERE PRODUCTIONS	EDR Digital Archive
	CHAN DANIEL K ENGINEERING	EDR Digital Archive
	SOLO CREATIONS INC	EDR Digital Archive
	PRIMAL THERAPIST	EDR Digital Archive
	PINKYOTTO INC	EDR Digital Archive
	PINKYOTTO HOLDING CORPORATION	EDR Digital Archive
	ROBERT F CARR DR	EDR Digital Archive
	SIMPAO ELLEN PHD	EDR Digital Archive
	MASSEY CARLA	EDR Digital Archive
	GHOSTORCHID INC	EDR Digital Archive
	SHAPIRO SUE A PHD	EDR Digital Archive
	DAVID DAWES NEE II FOUNDATION	EDR Digital Archive
	CAROL GLASSMAN DSW	EDR Digital Archive
	DAVIS PAUL	EDR Digital Archive
	DES MARK INC	EDR Digital Archive
	CONTENT CORPS LLC	EDR Digital Archive
	CLOSETHOP LLC	EDR Digital Archive

FINDINGS

Year	Uses	Source
2014	CANARELLI JOSEPH	EDR Digital Archive
	SYNTHETICMESS	EDR Digital Archive
	CUTTING ROOM INC	EDR Digital Archive
	CUTTING ROOM RECORDING STUDIO	EDR Digital Archive
	YOUNG STANTON	EDR Digital Archive
	ESSENTIAL PUBLICATIONS US LLC	EDR Digital Archive
	V 2 RECORDS INC	EDR Digital Archive
	INGLETON ROSEMARIE M D	EDR Digital Archive
	TODD MCNIFF MD PC	EDR Digital Archive
	SILK BUILDING CONDOMINIUM	EDR Digital Archive
	ARFA-LAW PC	EDR Digital Archive
	VARGA MICHAEL P PHD	EDR Digital Archive
	FEWELL CHRISTINE PHD	EDR Digital Archive
	KAPLAN JOHN INTGRTD FLNG THRPY	EDR Digital Archive
	ISRAEL MATZ HEBREW CLASSICS	EDR Digital Archive
	LOSCALZO ANTHONY	EDR Digital Archive
	URBAN GOLF ACADEMY	EDR Digital Archive
	TFL-US INCORPORATED	EDR Digital Archive
	LAURIE BLMNFELD CONSULTING INC	EDR Digital Archive
	MODERN VINTAGE RECORDINGS LLC	EDR Digital Archive
	LEMBERSKY PAUL	EDR Digital Archive
	YOUNG STANTON	EDR Digital Archive
	PORTRAITS BY VALERIE	EDR Digital Archive
	PARTY SHOPS PLUS INC	EDR Digital Archive
	GROOVY BOOTS PRODUCTIONS INC	EDR Digital Archive
	CENTER FOR ENVMTL THRPUTICS IN	EDR Digital Archive
	GERE PRODUCTIONS	EDR Digital Archive
	CHAN DANIEL K ENGINEERING	EDR Digital Archive
	SOLO CREATIONS INC	EDR Digital Archive
	PRIMAL THERAPIST	EDR Digital Archive
	PINKYOTTO INC	EDR Digital Archive
	PINKYOTTO HOLDING CORPORATION	EDR Digital Archive
	ROBERT F CARR DR	EDR Digital Archive
	SIMPAO ELLEN PHD	EDR Digital Archive
	MASSEY CARLA	EDR Digital Archive
	CLOSETHOP LLC	EDR Digital Archive
	CANARELLI JOSEPH	EDR Digital Archive
	CUTTING ROOM INC	EDR Digital Archive

FINDINGS

Year	Uses	Source
2014	CUTTING ROOM RECORDING STUDIO	EDR Digital Archive
	SYNTHETICMESS	EDR Digital Archive
	GHOSTORCHID INC	EDR Digital Archive
	SHAPIRO SUE A PHD	EDR Digital Archive
	DAVID DAWES NEE II FOUNDATION	EDR Digital Archive
	CAROL GLASSMAN DSW	EDR Digital Archive
	DAVIS PAUL	EDR Digital Archive
	DES MARK INC	EDR Digital Archive
	CONTENT CORPS LLC	EDR Digital Archive
	ESSENTIAL PUBLICATIONS US LLC	EDR Digital Archive
	V 2 RECORDS INC	EDR Digital Archive
2010	SILK BUILDING CONDOMINIUM	EDR Digital Archive
	INSPIRING SPACES	EDR Digital Archive
	OVERALL CONSTR INCORPORATED	EDR Digital Archive
	PLUMBING SEWER DRAIN 24 HRS	EDR Digital Archive
	A MIDTOWN 42ND STREET PLUMBING	EDR Digital Archive
	URBAN GOLF ACADEMY	EDR Digital Archive
	ISRAEL MATZ HEBREW CLASSICS	EDR Digital Archive
	276 THROOP AVE LLC	EDR Digital Archive
	INGLETON ROSEMARIE M D	EDR Digital Archive
	VILLAGE WINE IMPORTS LTD	EDR Digital Archive
	SYNTHETICMESS	EDR Digital Archive
	CUTTING ROOM INC	EDR Digital Archive
	CUTTING ROOM RECORDING STUDIO	EDR Digital Archive
	DOWD IRENE	EDR Digital Archive
	YOUNG STANTON	EDR Digital Archive
	TANGLED TAXI LLC	EDR Digital Archive
	ESSIE TAXI INC	EDR Digital Archive
	DANS TAXI INC	EDR Digital Archive
	SHAPIRO SUE A PHD	EDR Digital Archive
	CAROL GLASSMAN DSW	EDR Digital Archive
	DOW JULIA	EDR Digital Archive
	CENTER FOR ENVMTL THRPUTICS IN	EDR Digital Archive
	DAVIS PAUL	EDR Digital Archive
	GERE PRODUCTIONS	EDR Digital Archive
	POLY HEALTH MEDIA	EDR Digital Archive
	CANARELLI JOSEPH	EDR Digital Archive
	PORTRAITS BY VALERIE	EDR Digital Archive

FINDINGS

Year	Uses	Source
2010	DES MARK INC	EDR Digital Archive
	MAGAZINERADAR INC	EDR Digital Archive
	GROOVY BOOTS PRODUCTIONS INC	EDR Digital Archive
	FACING HISTORY AND OURSELVES N	EDR Digital Archive
	SGH HOLDINGS USA INC	EDR Digital Archive
	CHAN DANIEL K ENGINEERING	EDR Digital Archive
	SIMPAO ELLEN PHD	EDR Digital Archive
	MASSEY CARLA	EDR Digital Archive
	ROBERT F CARR DR	EDR Digital Archive
	BLYN ARTHUR E	EDR Digital Archive
	BERKOWITZ ALAN S ATTY AT LAW	EDR Digital Archive
	LOSCALZO & LOSCALZO PC	EDR Digital Archive
	GILANI RESTAURANT GROUP INC	EDR Digital Archive
	WALKER MEDIA	EDR Digital Archive
	SHORETZ AND CO	EDR Digital Archive
	INTEGRAL RESEARCH INC	EDR Digital Archive
	PRIMAL THERAPIST	EDR Digital Archive
	DAVID DAWES NEE II FOUNDATION	EDR Digital Archive
	URBAN GOLF ACADEMY	EDR Digital Archive
	ISRAEL MATZ HEBREW CLASSICS	EDR Digital Archive
	LOSCALZO ANTHONY	EDR Digital Archive
	MAC SOUND INC	EDR Digital Archive
	MANICK ASIF INC	EDR Digital Archive
	ARFA-LAW PC	EDR Digital Archive
	LAURIE BLMNFELD CONSULTING INC	EDR Digital Archive
	KAPLAN JOHN INTGRTD FLNG THRPY	EDR Digital Archive
	SILK BUILDING CONDOMINIUM	EDR Digital Archive
	FEWELL CHRISTINE PHD	EDR Digital Archive
	LEMBERSKY PAUL	EDR Digital Archive
	INSPIRING SPACES	EDR Digital Archive
	OVERALL CONSTR INCORPORATED	EDR Digital Archive
	PLUMBING SEWER DRAIN 24 HRS	EDR Digital Archive
	A MIDTOWN 42ND STREET PLUMBING	EDR Digital Archive
	COMPLETE FINANCIAL SERVICES	EDR Digital Archive
	276 THROOP AVE LLC	EDR Digital Archive
	DAVID DAWES NEE II FOUNDATION	EDR Digital Archive
	SYNTHETICMESS	EDR Digital Archive
	CUTTING ROOM INC	EDR Digital Archive

FINDINGS

Year	Uses	Source
2010	CUTTING ROOM RECORDING STUDIO	EDR Digital Archive
	DOWD IRENE	EDR Digital Archive
	YOUNG STANTON	EDR Digital Archive
	ESSIE TAXI INC	EDR Digital Archive
	DANS TAXI INC	EDR Digital Archive
	TANGLED TAXI LLC	EDR Digital Archive
	SHAPIRO SUE A PHD	EDR Digital Archive
	CAROL GLASSMAN DSW	EDR Digital Archive
	DOW JULIA	EDR Digital Archive
	CENTER FOR ENVMTL THRPUTICS IN	EDR Digital Archive
	DAVIS PAUL	EDR Digital Archive
	GERE PRODUCTIONS	EDR Digital Archive
	POLY HEALTH MEDIA	EDR Digital Archive
	CANARELLI JOSEPH	EDR Digital Archive
	PORTRAITS BY VALERIE	EDR Digital Archive
	DES MARK INC	EDR Digital Archive
	MAGAZINERADAR INC	EDR Digital Archive
	GROOVY BOOTS PRODUCTIONS INC	EDR Digital Archive
	FACING HISTORY AND OURSELVES N	EDR Digital Archive
	SGH HOLDINGS USA INC	EDR Digital Archive
	CHAN DANIEL K ENGINEERING	EDR Digital Archive
	INGLETON ROSEMARIE M D	EDR Digital Archive
	VILLAGE WINE IMPORTS LTD	EDR Digital Archive
	SIMPAO ELLEN PHD	EDR Digital Archive
	MASSEY CARLA	EDR Digital Archive
	ROBERT F CARR DR	EDR Digital Archive
	SHORETZ AND CO	EDR Digital Archive
	BERKOWITZ ALAN S ATTY AT LAW	EDR Digital Archive
	LOSCALZO & LOSCALZO PC	EDR Digital Archive
	BLYN ARTHUR E	EDR Digital Archive
	WALKER MEDIA	EDR Digital Archive
	GILANI RESTAURANT GROUP INC	EDR Digital Archive
	INTEGRAL RESEARCH INC	EDR Digital Archive
	PRIMAL THERAPIST	EDR Digital Archive
	LAURIE BLMNFELD CONSULTING INC	EDR Digital Archive
	LEMBERSKY PAUL	EDR Digital Archive
	ARFA-LAW PC	EDR Digital Archive
	LOSCALZO ANTHONY	EDR Digital Archive

Year	Uses	Source
2010	MANICK ASIF INC	EDR Digital Archive
	MAC SOUND INC	EDR Digital Archive
	FEWELL CHRISTINE PHD	EDR Digital Archive
	KAPLAN JOHN INTGRTD FLNG THRPY	EDR Digital Archive
	COMPLETE FINANCIAL SERVICES	EDR Digital Archive

15 E 4th St

Year	Uses	Source
2014	OTHER MUSIC LLC	EDR Digital Archive
	OTHER MUSIC LLC	EDR Digital Archive
2010	OTHER MUSIC LLC	EDR Digital Archive
	ZYZY AUTOMOTIVE ELECTRICAL	EDR Digital Archive
	OTHER MUSIC LLC	EDR Digital Archive
	ZYZY AUTOMOTIVE ELECTRICAL	EDR Digital Archive

E 4TH ST

15 E 4TH ST

Year	Uses	Source
2006	Other Music Inc 2 R	Hill-Donnelly Information Services
	Zyzy Automotive Electrical	Hill-Donnelly Information Services
2000	OTHER MUSIC INC	Cole Information Services

E 4th St

17 E 4th St

Year	Uses	Source
2010	JDM PARTNERS INC	EDR Digital Archive
	JDM PARTNERS INC	EDR Digital Archive

E 4TH ST

17 E 4TH ST

Year	Uses	Source
2006	No Current Listing	Hill-Donnelly Information Services
2000	DOLLHOUSE	Cole Information Services

20 E 4TH ST

Year	Uses	Source
2006	Tower Records/video/books	Hill-Donnelly Information Services

Year	Uses	Source
2006	Tower Record Clearance Outlet	Hill-Donnelly Information Services
2000	TOWER RECORDS VID	Cole Information Services

E 4th St

21 E 4th St

Year	Uses	Source
2014	PRODJECT LLC	EDR Digital Archive
	FOURTH STREET REALTY HOLDING C	EDR Digital Archive
	HELPERN ARCHITECTS PC	EDR Digital Archive
	CAPELIN COMMUNICATIONS INC	EDR Digital Archive
	CMB REALTY	EDR Digital Archive
	LDM WINES INC	EDR Digital Archive
	CHELSEA COMPUTER INC	EDR Digital Archive
	PRODJECT LLC	EDR Digital Archive
	FOURTH STREET REALTY HOLDING C	EDR Digital Archive
	CHELSEA COMPUTER INC	EDR Digital Archive
	LDM WINES INC	EDR Digital Archive
	HELPERN ARCHITECTS PC	EDR Digital Archive
	CAPELIN COMMUNICATIONS INC	EDR Digital Archive
	CMB REALTY	EDR Digital Archive
2010	CHELSEA COMPUTER INC	EDR Digital Archive
	LDM WINES INC	EDR Digital Archive
	PIQUANT PRODUCTIONS LLC	EDR Digital Archive
	DIVINE STUDIO	EDR Digital Archive
	ONE REALTY	EDR Digital Archive
	HELPERN ARCHITECTS PC	EDR Digital Archive
	LUCE GROUP LLC	EDR Digital Archive
	FOURTH STREET REALTY HOLDING C	EDR Digital Archive
	TALLAWAH STUDIOS & GALLERY	EDR Digital Archive
	GRAJ + GUSTAVSEN INC	EDR Digital Archive
	ONE REALTY	EDR Digital Archive
	HELPERN ARCHITECTS PC	EDR Digital Archive
	LUCE GROUP LLC	EDR Digital Archive
	LDM WINES INC	EDR Digital Archive
	PIQUANT PRODUCTIONS LLC	EDR Digital Archive
	DIVINE STUDIO	EDR Digital Archive
	CHELSEA COMPUTER INC	EDR Digital Archive
	FOURTH STREET REALTY HOLDING C	EDR Digital Archive

Year	Uses	Source
2010	TALLAWAH STUDIOS & GALLERY	EDR Digital Archive
	GRAJ + GUSTAVSEN INC	EDR Digital Archive

E 4TH ST

21 E 4TH ST

Year	Uses	Source
2006	Product Link 2 P	Hill-Donnelly Information Services
	Piquant Productions LLC	Hill-Donnelly Information Services
	Louis Dressner Selections	Hill-Donnelly Information Services
	Helpern Architects 2 P o	Hill-Donnelly Information Services
	Chelsea Computer Inc 15 s	Hill-Donnelly Information Services
2000	MARKA INC	Cole Information Services
	ONE REALTY INC	Cole Information Services
	PRODUCT LINK	Cole Information Services
	TLLWH STDS & GLILRY	Cole Information Services
	GRAJ & GSTVSN DSGN	Cole Information Services
	MAIKAV INC	Cole Information Services
1983	Apex Press	New York Telephone
	China Seas Inc	New York Telephone
	Laurel Bindery Inc	New York Telephone
	Shepherd Gallery Assocs	New York Telephone

22 E 4TH ST

Year	Uses	Source
2006	No Current Listing	Hill-Donnelly Information Services

E 4th St

23 E 4th St

Year	Uses	Source
2014	LOCUSTS ON HUDSON	EDR Digital Archive
	HOTELS AB LLC	EDR Digital Archive
	STANDARD INTERNATIONAL MGT LLC	EDR Digital Archive
	HOTELSAB LLC	EDR Digital Archive
	ANDRE BALAZS PROPERTIES	EDR Digital Archive
	PRINCE ACQUISITION ASSOC L P	EDR Digital Archive
	STANDARD HOLDINGS LLC	EDR Digital Archive
	GROUP 99 LLC	EDR Digital Archive
	SODISC LLC	EDR Digital Archive

FINDINGS

Year	Uses	Source
2014	LOCUSTS ON HUDSON	EDR Digital Archive
	HOTELS AB LLC	EDR Digital Archive
	STANDARD INTERNATIONAL MGT LLC	EDR Digital Archive
	HOTELSAB LLC	EDR Digital Archive
	ANDRE BALAZS PROPERTIES	EDR Digital Archive
	PRINCE ACQUISITION ASSOC L P	EDR Digital Archive
	STANDARD HOLDINGS LLC	EDR Digital Archive
	GROUP 99 LLC	EDR Digital Archive
	PLENTY WORKS INC	EDR Digital Archive
	ORCHARD ENTERPRISES NY INC	EDR Digital Archive
	INDEPENDENT ONLINE DSTRIBUTION	EDR Digital Archive
	EHRENKRANTZ ECKSTUT	EDR Digital Archive
	EHRENKRANTZ ECKSTUT	EDR Digital Archive
	INDEPENDENT ONLINE DSTRIBUTION	EDR Digital Archive
	SODISC LLC	EDR Digital Archive
	PLENTY WORKS INC	EDR Digital Archive
	ORCHARD ENTERPRISES NY INC	EDR Digital Archive
2010	BLUNT RECORDINGS	EDR Digital Archive
	ORCHARD ENTERPRISES INC	EDR Digital Archive
	DIGITAL RIGHTS AGENCY INC	EDR Digital Archive
	PLENTY WORKS INC	EDR Digital Archive
	KATZENSTEIN DAVID STUDIO	EDR Digital Archive
	DASHBE INC	EDR Digital Archive
	SODISC LLC	EDR Digital Archive
	CAPELIN COMMUNICATIONS INC	EDR Digital Archive
	CITIZEN STOCK LLC	EDR Digital Archive
	EHRENKRANTZ ECKSTUT	EDR Digital Archive
	EHRENKRANTZ ECKSTUT	EDR Digital Archive
	CITIZEN STOCK LLC	EDR Digital Archive
	ORCHARD ENTERPRISES INC	EDR Digital Archive
	BLUNT RECORDINGS	EDR Digital Archive
	DIGITAL RIGHTS AGENCY INC	EDR Digital Archive
	PLENTY WORKS INC	EDR Digital Archive
	KATZENSTEIN DAVID STUDIO	EDR Digital Archive
	DASHBE INC	EDR Digital Archive
	STANDARD HOLDINGS LLC	EDR Digital Archive
	PRINCE ACQUISITION ASSOC L P	EDR Digital Archive
	BALASZ INVESTORS MIAMI LESSEE	EDR Digital Archive

Year	Uses	Source
2010	HOTELS AB LLC	EDR Digital Archive
	HOTELSAB LLC	EDR Digital Archive
	ANDRE BALAZS PROPERTIES	EDR Digital Archive
	BALAZS HOLDING LLC	EDR Digital Archive
	LOCUSTS ON HUDSON	EDR Digital Archive
	GROUP 99 LLC	EDR Digital Archive
	AB GREEN RALEIGH OPERATOR INC	EDR Digital Archive
	SODISC LLC	EDR Digital Archive
	CAPELIN COMMUNICATIONS INC	EDR Digital Archive
	STANDARD HOLDINGS LLC	EDR Digital Archive
	PRINCE ACQUISITION ASSOC L P	EDR Digital Archive
	HOTELSAB LLC	EDR Digital Archive
	ANDRE BALAZS PROPERTIES	EDR Digital Archive
	HOTELS AB LLC	EDR Digital Archive
	BALAZS HOLDING LLC	EDR Digital Archive
	BALASZ INVESTORS MIAMI LESSEE	EDR Digital Archive
	LOCUSTS ON HUDSON	EDR Digital Archive
	GROUP 99 LLC	EDR Digital Archive
	AB GREEN RALEIGH OPERATOR INC	EDR Digital Archive

E 4TH ST

23 E 4TH ST

Year	Uses	Source
2006	Alan Richardson Studio is	Hill-Donnelly Information Services
	David Katzenstein Studio	Hill-Donnelly Information Services
	Ehrenkrantz Eckstut & Kuhn	Hill-Donnelly Information Services
	Katz Architecture & Project	Hill-Donnelly Information Services
	Shoot Digital 2 S	Hill-Donnelly Information Services
	Studio One Inc	Hill-Donnelly Information Services
	TVT Records s	Hill-Donnelly Information Services
2000	ACHILLEOS ANTONIS	Cole Information Services
	BIO BOX INC	Cole Information Services
	BLUNT RECORDINGS	Cole Information Services
	TVT RECORDS	Cole Information Services
	TVT RECORDS	Cole Information Services
	TVT CATLG ENTRPRSSA	Cole Information Services
	TEEVEE TOONS INC	Cole Information Services
	SHOOT DIGITAL	Cole Information Services

Year	Uses	Source
2000	RCHRDSN ALAN	Cole Information Services
	KTZNSTN DAVID STD	Cole Information Services
	HELPERN ARCHTCTS	Cole Information Services
	EHRNKRNTZ & ECKSTUT	Cole Information Services
	BLUNT RECORDINGS	Cole Information Services
1983	ED Bindery	New York Telephone

24 E 4TH ST

Year	Uses	Source
2006	Na L	Hill-Donnelly Information Services

E 4th St

25 E 4th St

Year	Uses	Source
2014	IVRY JUDITH	EDR Digital Archive
	ROMAN & WILLIAMS INC	EDR Digital Archive
	ROMAN & WILLIAMS INC	EDR Digital Archive
	IVRY JUDITH	EDR Digital Archive
2010	IVRY JUDITH	EDR Digital Archive
	ROMAN & WILLIAMS INC	EDR Digital Archive
	KELLETT DEREK F	EDR Digital Archive
	ROMAN & WILLIAMS INC	EDR Digital Archive
	KELLETT DEREK F	EDR Digital Archive
	IVRY JUDITH	EDR Digital Archive

E 4TH ST

25 E 4TH ST

Year	Uses	Source
2006	h Standefer Robin A	Hill-Donnelly Information Services
	H Ivry Judith A	Hill-Donnelly Information Services
	H Iberti J E P A	Hill-Donnelly Information Services
	h Dropkin F A 00oo	Hill-Donnelly Information Services
	h Alesch Stephen AC	Hill-Donnelly Information Services
	Roman & Williams Is	Hill-Donnelly Information Services
2000	ROBIN STANDEFER	Cole Information Services
	ROBIN STANDEFER	Cole Information Services
	WILLIAM PIERCE	Cole Information Services
	DAVID MILNE	Cole Information Services

FINDINGS

Year	Uses	Source
2000	LEANDRO KATZ	Cole Information Services
	JUDITH IVRY	Cole Information Services
	J E IBERTI	Cole Information Services
	J HENDRA	Cole Information Services
	F DROPKIN	Cole Information Services
	PETER BOWEN	Cole Information Services
	STEPHEN ALESCH	Cole Information Services
1983	Hendra J	New York Telephone
	Katz Leo	New York Telephone
	Mc Murray Ruth	New York Telephone
	Milne David	New York Telephone
	Seltzer K	New York Telephone
	Ott John	New York Telephone
	Dramatis Personae Inc	New York Telephone

27 E 4TH ST

Year	Uses	Source
2006	No Current Listing	Hill-Donnelly Information Services
1983	Wolnick Elizabeth A	New York Telephone

28 E 4TH ST

Year	Uses	Source
2006	Multi Unit Address	Hill-Donnelly Information Services
	E 4 St Housing Corp I F	Hill-Donnelly Information Services
	h Buturovic Edin VA o	Hill-Donnelly Information Services
	h Chaung Che & Mary VA	Hill-Donnelly Information Services
	Number 7 E Frua Carlo A	Hill-Donnelly Information Services
	Number 5 E Kallas John A	Hill-Donnelly Information Services
	Number 2 E Krupnick Neil A	Hill-Donnelly Information Services
	Number 6 E H Kuo Shida C	Hill-Donnelly Information Services
	Plantworks Inc	Hill-Donnelly Information Services
	Number 8 W h Stone K	Hill-Donnelly Information Services
	Number 8 W h Stone K	Hill-Donnelly Information Services
	Number 8 E Yen Amy A	Hill-Donnelly Information Services
	h Zanardi Claudia	Hill-Donnelly Information Services
2000	F B BOOKHARDT	Cole Information Services
	CHE CHAUNNG	Cole Information Services
	OLGA DEE	Cole Information Services
	MARY DEL MONICO	Cole Information Services

FINDINGS

Year	Uses	Source
2000	CARLO FRUA	Cole Information Services
	R E GASKELL	Cole Information Services
	J C KALLAS	Cole Information Services
	JOHN KALLAS	Cole Information Services
	NEIL KRUPNICK	Cole Information Services
	SHIDA KUO	Cole Information Services
	LOUISE LOENING	Cole Information Services
	LOUISE LOENING	Cole Information Services
	NICHOLAS QUENNELL	Cole Information Services
	B SILVER	Cole Information Services
	K STONE	Cole Information Services
	WILLIAM WASHBURN	Cole Information Services
	ANN WEISER	Cole Information Services
	CLAUDIA ZANARDI	Cole Information Services
	GASKELL ROBERT E	Cole Information Services
	PLANTWORKS INC	Cole Information Services
	E ST HSNG CORP	Cole Information Services
1983	Bookhardt F B	New York Telephone
	Cooper K	New York Telephone
	Fiering A M	New York Telephone
	Gaskell R E	New York Telephone
	Greenleaf Fredrick P	New York Telephone
	Griffin George	New York Telephone
	Jorob Realty Corp	New York Telephone
	Kallas John	New York Telephone
	Karwoski Richard	New York Telephone
	Mc Carley N L	New York Telephone
	Wechsberg Orin	New York Telephone

29 E 4TH ST

Year	Uses	Source
2006	Merchants House Museum	Hill-Donnelly Information Services
	Mechants House o	Hill-Donnelly Information Services
2000	MERCHANTS HSE MUS	Cole Information Services
	N Y PARKS & RCRTN	Cole Information Services
1983	Old Merchants House	New York Telephone

FINDINGS

30 E 4TH ST

Year	Uses	Source
2014	JONATHAN BRBARA SLVER FNDATION	EDR Digital Archive
2010	GREEK WRITERS GUILD AMER INC	EDR Digital Archive
	JONATHAN BRBARA SLVER FNDATION	EDR Digital Archive

E 4TH ST FL 4

30 E 4TH ST FL 4

Year	Uses	Source
2010	DOROTHYS DOOR	EDR Digital Archive

East 4th Street

30 East 4th Street

Year	Uses	Source
2006	Hayes Dorothy E 1 s	Hill-Donnelly Information Services
	Hayes Dorothy E Prof Graphic	Hill-Donnelly Information Services
	Silver B C os	Hill-Donnelly Information Services
	Tankersley G A	Hill-Donnelly Information Services
2000	G TANKERSLEY	Cole Information Services
	HAYES D PRO GRPHC	Cole Information Services
1983	Howell James A	New York Telephone
	Quenneli Nicholas	New York Telephone
	Silver B	New York Telephone
1973	BENSINGER DONALD	New York Telephone
1958	SPIELBERG MILTON B	New York Telephone
1934	Crawford Sherman W dentist	R. L. Polk & Co.
	Hoving Hannes dentist	R. L. Polk & Co.
	Hooing Hannes dentist	R. L. Polk & Co.
	Knapp Wm J v pres Union Carbide & Carbon Corp	R. L. Polk & Co.
	Belle Art Mfg Co TN Thos J Moosey table Covers	R. L. Polk & Co.
	Moser B Moser & Goldstein	R. L. Polk & Co.
	Moser & Goldstein B Moser J Goldstein mlnry mfrs	R. L. Polk & Co.
	Auslander Seymour Adele T leather goods mfrs	R. L. Polk & Co.
	Rooney Rose M P tel opr	R. L. Polk & Co.
	Lloyd Scarf & Novelty Co RTN Rosalind Lyoyd Albin womans furn gds	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1927	Mercantile Hat Mfg Co	New York Telephone
	Qualions Anthony r	New York Telephone
	Axell Bernard L H electrcn	New York Telephone
	Residence	New York Telephone
1923	Feedelman Maniloff Cap Co Inc N Y Chas Maniliff pres Louis Shatz sec Chas Feedelman treas	R. L. Polk & Co.
	Kaufman & Friedman RTN Abr Kaufman Hyman Friedman collars	R. L. Polk & Co.
	Carnival & Bazaar Supply Co RTN Harry J Hall	R. L. Polk & Co.
	Beck & Belaief Louis Beck & Michl G Belaief hats and caps	R. L. Polk & Co.
1920	LIBERTY MUTUAL INSURANCE CO Mass Walter S Bucklin Pres C E Woodward Sec O H Simmo s Treas Charles R Wilder District Manager	R. L. Polk & Co.
	Nicholas Cloak & Suit Co Inc NY Nicholas Cruasale pres Julius Chomor v p Geo Byron sec Max Weiss treas	R. L. Polk & Co.
	Radner Mendel carp	R. L. Polk & Co.
	Rosenthal Jos & Co Jos Rosenthal & Jos Lacoff clothing	R. L. Polk & Co.
	Goldstein Morris clothing mfr	R. L. Polk & Co.
	Schweiger N Hat Co Morris Frankelstein Nathan Schweiger ladies hats	R. L. Polk & Co.
	Shuldner M Co RTN Michl Shuldner bonnet wire	R. L. Polk & Co.
	Feedelman Maniloff Cap Co Inc NY Chas Maniloff pres Chas Feedelman treas Louis Shatz sec	R. L. Polk & Co.
	Finesilver Isidor clothing mfr	R. L. Polk & Co.
	Finkelstein Morris N Schweiger Rat Co	R. L. Polk & Co.
	Kassel Harry B pants	R. L. Polk & Co.
	Mason & Moore Inc NY Wm O Mason pres Wm A Moore treas Geo Chapman sec printing machy	R. L. Polk & Co.
	Mason & Moore Realty Corp NY Wm O Mason pres Wm A Moore sec treas	R. L. Polk & Co.
	Endler Ruben cloaks	R. L. Polk & Co.
	Endler Rubin Hamilton & Endler h Lawrence LI	R. L. Polk & Co.

GREAT JONES

4 GREAT JONES

Year	*Uses*	*Source*
1993	FINE ART SVCES OF NY INC	NYNEX Telephone
	GOLDMAN STUART A	NYNEX Telephone
	QUARRY PRODUCTIONS	NYNEX Telephone
	STUART GOLDMAN PRODUCTION INC	NYNEX Telephone
1988	ANDREWS TOM	NYNEX Telephone
	BEERY ITZHAK	NYNEX Telephone
	BOHARY D	NYNEX Telephone
	FINE ART SVCES OF N Y INC	NYNEX Telephone
	GOLDMAN STUART A	NYNEX Telephone
	GOLDMAN STUART A B	NYNEX Telephone
	LEVESON KENNETH	NYNEX Telephone
	MANNHARDT K	NYNEX Telephone
	SHESTACK M B	NYNEX Telephone
	STUART GOLDMAN PRODUCTION INC	NYNEX Telephone
	TRIANGLE CENTER THE	NYNEX Telephone
1983	BEERY LTZHAK	New York Telephone
	CLAYWORKS STUDIO WORKSHOP INC	New York Telephone
	GOLDMAN STUART A	New York Telephone
	GOLDMAN STUART A B	New York Telephone
	JURICK S	New York Telephone
	LEVESON KENNETH	New York Telephone
	MULTI-MEDIA MASTERS	New York Telephone
	NY EXPERIMENTAL GLASS WORKSHOP	New York Telephone
	PETERSON SUSAN	New York Telephone
	PUBLICATION ARTS WORKSHOP	New York Telephone
1978	CLAYWORKS KENNETH	New York Telephone
	JURICK S	New York Telephone
	STEWART JOHN W	New York Telephone
	WALDO MAJE	New York Telephone
1973	GIFFORD JESSIE	New York Telephone
	LUDMER HENRY C	New York Telephone
	MILSTEIN EMANUEL	New York Telephone
1963	HORN M H WOOL	New York Telephone
	TEXTILE CLIPPINGS INC	New York Telephone
	SPRING & WIRE FORM INC	New York Telephone

FINDINGS

Year	Uses	Source
1958	FINKELSTEIN DISPLAY RACKS	New York Telephone
	FINKELSTEIN M RUBR EASELS	New York Telephone
	HORN M H WOOL	New York Telephone
	M & S LINGERIE INC	New York Telephone
	SILVERSTEIN BROS REMNANS	New York Telephone
	TEXTILE CLIPPINGS INC	New York Telephone
	TEXTILE DIE CUTTING CO OFC	New York Telephone
	ZLOTCHIN S REMNANTS	New York Telephone
1956	FINKELSTEIN DISPLAY RACKS	New York Telephone
	FINKELSTEIN M RUBR EASELS	New York Telephone
	HORN M H WOOL	New York Telephone
	M & S LINGERIE INC	New York Telephone
	SILVERSTEIN BROS REMNANTS	New York Telephone
	TEXTILE DIE CUTTING CO OFC	New York Telephone
	WARACH JOS WOOLN CLIPS	New York Telephone
	ZLOTCHIN S REMNANTS	New York Telephone
1950	ACE WOOL STOCK CO INC	New York Telephone
	ELL BEE WOOL STOCK CO	New York Telephone
	INTERSTATE WOOL CO	New York Telephone
	MIGDAL BROS WOOLN CLIPNGS	New York Telephone
	SILVERSTEIN BROS REMNANTS	New York Telephone
	TEXTILE DIE CUTTING CO OFC	New York Telephone
	WARACH JOS WOOLN CLIPS	New York Telephone
	ZLIOTCHIN S REMNANTS	New York Telephone
1947	BRITCHKY ISIDORE WOOLN CLIPNGS	New York Telephone
	EL-BEE WOOL STOCK CO	New York Telephone
	SILVERSTEIN BROS REMNANTS	New York Telephone
	WARACH JOS RAGS	New York Telephone
1942	BRITCHKY ISIDORE WOOLN CLIPNGS	New York Telephone
	BWAY NOVELTY CO	New York Telephone
	SILVERSTEIN BENJ WL STCK	New York Telephone
	SILVERSTEIN & BERGER	New York Telephone
	SILVERSTEIN I REMNANTS	New York Telephone
	WARACH JOS RAGS	New York Telephone
	ZLOTCHIN S REMNANTS	New York Telephone
1938	BRITCHKY ISIDORE RAGS	New York Telephone
	CHAMISH & YOUBERG RAGS	New York Telephone
	MIGDAL BROS LAGS	New York Telephone

Year	Uses	Source
1938	SILVERSTEIN BENJ WL STCK	New York Telephone
	SILVERSTEIN & BERGER	New York Telephone
1923	Improved Aluminum Tip Co TN Aaron H Wolff	R. L. Polk & Co.
	Wolff A H Gas Radiator Co NY Aaron H Wolff pres Saul K Wolff sec M S Wolff treas	R. L. Polk & Co.
1920	Aetna Paper Supply Co RTN Saml K Wolff	R. L. Polk & Co.
	Friedman Paul & Co Paul Friedman Louis Zeitzew hat frames	R. L. Polk & Co.
	Goldberg Louis Goldberg & Martin	R. L. Polk & Co.
	Goldberg & Martin Louis Goldberg Samuel Martin clothing	R. L. Polk & Co.
	Improved Aluminum Tin Co RTN Aaron H Wolff	R. L. Polk & Co.
	Leblang Abr coats	R. L. Polk & Co.
	Meyer Chas Tailoring Co RTN Chas Meyer Jacob Lamkay	R. L. Polk & Co.
	Wolff A H Gas Radiator Co N Y Aaron H Wolff pres Saml H Wolff sec max S Wolff treas	R. L. Polk & Co.
	Zeitzew Louis Paul Friedman & Co	R. L. Polk & Co.

6 GREAT JONES

Year	Uses	Source
1934	Wonder Bar Radio Co RTN; Ola C Cool	R. L. Polk & Co.

9 GREAT JONES

Year	Uses	Source
1998	J H MURRAY CORP	NYNEX Telephone
	GJ BAR & RESTAURANT INC	NYNEX Telephone
	ROILTON LTD	NYNEX Telephone
	SAR CONSTR CORP	NYNEX Telephone
1993	ACME BAR & GRILL INC	NYNEX Telephone
	J H MURRAY CORP	NYNEX Telephone
	ROLITON LTD	NYNEX Telephone
1988	COVEY ELIZABETH	NYNEX Telephone
	MURRAY JAMES	NYNEX Telephone
	ROLITON LTD	NYNEX Telephone
	STAN S ACME BAR & GRILL	NYNEX Telephone
	TOBIAS JULIUS	NYNEX Telephone
	VON RINGELHEIM PAUL	NYNEX Telephone

FINDINGS

Year	Uses	Source
1983	BEN YUTER CO INC	New York Telephone
	COVEY SHAN	New York Telephone
	JORDAN COML REFRIGERATOR CO	New York Telephone
	TOBIAS JULIAS	New York Telephone
	VON RINGELHEIM PAUL	New York Telephone
	YUTER BEN CO INC	New York Telephone
1978	BEN YUTER COLNC	New York Telephone
	COVEY SNAN	New York Telephone
	JORDAN COMI REFRIGERATOR CO	New York Telephone
	MURRAY F	New York Telephone
	THE BEN YUTER CO INC	New York Telephone
	VON RINGELHEIM PAUL	New York Telephone
1973	LAMY NOAH	New York Telephone
	MONK MEREDITH	New York Telephone
	JORDAN COML REFRIGETRATOR CO	New York Telephone
1958	BULOS NATHAN DIE CUTNG	New York Telephone
	FIT-WELL SHIRT & SPORTSWR INC	New York Telephone
	GOLDSTEIN JACK HATS	New York Telephone
	GORDON K HAT LTHR	New York Telephone
	JEFFERSON SCREW CORP	New York Telephone
	MONTICELLO SPECIALTLES CO BRASS PARTS	New York Telephone
	PENTAGON FASTENERS CORP	New York Telephone
	WEAR WELL SPORTSWR CO	New York Telephone
1956	BULOS NATHAN DIE CUTNG	New York Telephone
	GORDON IRVING ACCTNT	New York Telephone
	GORDON K HAT ITHR	New York Telephone
	JEFFERSON SCREW CO	New York Telephone
	KOCH LESTER B	New York Telephone
	MONTICELLO SPECIALTIES CO BRASS PARTS	New York Telephone
	WEAR WELL SPORTWR CO	New York Telephone
1950	BULOS NATHAN DIE CUTNA	New York Telephone
	GORDON K HAT ITHR	New York Telephone
	HAUPTMAN CALENDAR CO	New York Telephone
	HAUPTMAN I IMPRINTING	New York Telephone
	ROSEN CO BRASSIERES	New York Telephone
	ZU ZU BRA ZEERS	New York Telephone
1947	HAUPTMAN CALENDAR CO	New York Telephone

FINDINGS

Year	Uses	Source
1947	HAUPTMAN I IMPRINTING	New York Telephone
	JONAS B CO MFRS	New York Telephone
	MEISELS JOS RAINWR	New York Telephone
	PLUVUS RAINWEAR & SPORTSWR CO	New York Telephone
	ROSEN CO BRASSIERES	New York Telephone
	WALDMAN SIDNEY FURS	New York Telephone
1942	GORDON KAY HAT LTHR	New York Telephone
	HAUPTMAN CALENDAR CO	New York Telephone
	HAUPTMAN I IMPRNTING	New York Telephone
	SILK SCREEN REPRODUCTION CO	New York Telephone
1938	PIONEER PAPR CO	New York Telephone
1934	Goetschins John mgr Macnutt Watts & Tankard Co Inc	R. L. Polk & Co.
	Goetschins Luella sec treas J H Goetschins Co Inc r Montclair NJ	R. L. Polk & Co.
	Goldberg Jacob Hockstein & Goldberg	R. L. Polk & Co.
	Hockstein & Goldberg Wm Hockstein and Jacob Goldberg pants	R. L. Polk & Co.
	Huckster W R Mrs r Hotel Devon	R. L. Polk & Co.
	Rosenblum Julius Pioneer Paper Co	R. L. Polk & Co.
1927	ACE PAPER CO	New York Telephone
	CHARLESTON HAT CO	New York Telephone
	GOLDBERG JACOB BOYS SUITS	New York Telephone
	K & S HAT & CAP CO	New York Telephone
	MACNUTT CO ELEC CONTRS	New York Telephone
	MACNUTT-WATTS & TANKARD INC ELEC ENGRS & CONTR	New York Telephone
	PROGRESS PAPER MILLS	New York Telephone
	TANKARD L F ELEC CONTR	New York Telephone
	WATTS H W ELEC CONTR	New York Telephone
	Ace Paper Co	New York Telephone
	Charleston Hat Co	New York Telephone
	Goldberg Jacob boys suits	New York Telephone
	Mac Nutt Co elec contrs	New York Telephone
	Mac Nutt Watts & Tankard Inc elec engrs & contr	New York Telephone
	Progress Paper Mills	New York Telephone
	Tankard L F elec contr	New York Telephone
	Watts H W elec contr	New York Telephone
1923	Blum & Spiselman Louis Blum Saml Spiselman clothing	R. L. Polk & Co.

Year	Uses	Source
1923	Dunn Bros David & Louis boys clothing	R. L. Polk & Co.
	Macnutt Watts & Tankard Inc Del Loren C MacNutt pres Lawrence F Tankard v p Horace W Wasta sec elec contra	R. L. Polk & Co.
	Rudinsky Chas Chas Rudinsky & Son	R. L. Polk & Co.
	Rudinsky Chas & Son Chas & Chas Rudinsky jr clothing	R. L. Polk & Co.
	Wolf Jos L cotton gds	R. L. Polk & Co.
1920	Blum & Spiselman Louis Blum Saml Spiselman Julius G Lowenberg clothing	R. L. Polk & Co.
	Dunn Louis clothing	R. L. Polk & Co.
	MacNutt Watts & Tankard Inc NY Loran C MacNutt pres Lawrence F Tankard v p Horace W Watts sec treas elec contrs	R. L. Polk & Co.
	Rudinsky Chas clothing	R. L. Polk & Co.

11 GREAT JONES

Year	Uses	Source
1923	Clover Fancy Feather Co RTN Sol Goldman Max G Walzman	R. L. Polk & Co.
	Deitchman Hyman ladies hats	R. L. Polk & Co.
	Fisleman Saml Flour Hat Co	R. L. Polk & Co.
	Flower Hat Co RTNHarry B Goldman Saml Fishman	R. L. Polk & Co.
	Goldman Harry B Flower Hat Co	R. L. Polk & Co.
	Goldman & Waltzman Sol Goldman Max G Waltzman feathers	R. L. Polk & Co.
	Kivowitz & Padover Saml Kivowitz Meyer Padover feathers	R. L. Polk & Co.
	Nassau Printing Co RTN H Schwarz	R. L. Polk & Co.
	Schwarz H Nassau Printing Co	R. L. Polk & Co.
1920	F & S Novelty Co RTN Sol Friedman & Max Scharewitz artificial flwrs	R. L. Polk & Co.
	Friedman Sol F & S Novelty Co	R. L. Polk & Co.
	Gross Max feathers	R. L. Polk & Co.
	Kirschner & Terner Saml Kirschner Isaac Terner furs	R. L. Polk & Co.
	Schaiewitz Max F & S Novelty Co	R. L. Polk & Co.
	Tiefenbrun & Gross Samuel Tiefenbrun Victor Gross feathers	R. L. Polk & Co.

18 GREAT JONES

Year	Uses	Source
1958	GOTTLIEB JACOB CAPT	New York Telephone

FINDINGS

21 GREAT JONES

Year	*Uses*	*Source*
1950	BC & K DINER INC	New York Telephone
1947	BC & K DINER INC	New York Telephone
1942	JONES DINER INC	New York Telephone
1920	Stern Morris restr	R. L. Polk & Co.

23 GREAT JONES

Year	*Uses*	*Source*
1938	KELLER BROS SUIT CASES	New York Telephone
	KRAVITZ FRANK FNTNS	New York Telephone
	NATL CARBONIC GAS & SVCE	New York Telephone
	SCHWARTZ DAVID WOOLN STK	New York Telephone
	SCHWARTZ J WIN STOCK	New York Telephone
1934	Ploxin Jacob Superior Luggage Co	R. L. Polk & Co.
	Ploy Herta clk Met Life Ins Co r Ridgefield NJ	R. L. Polk & Co.
	Rothberg Sidney S Inc NY cap $10000 Sidney S Rothberg pres treas glass	R. L. Polk & Co.
	Catalano Steven	R. L. Polk & Co.
	Cohen Meyer bkbndr	R. L. Polk & Co.
	Keller Bros Isidore and Wm Keller Isaac Schindler mfrs suit cases	R. L. Polk & Co.
1927	Acme Seal & Label Co	New York Telephone
	Cohen & Cohen bk bndrs	New York Telephone
	College Press printing	New York Telephone
	Jasper Israel wln stk	New York Telephone
	Quality Die Cutting Co	New York Telephone
	Quality Die Cutting Co	New York Telephone
	Rabro Co Ins	New York Telephone
	Troeger Herman printer	New York Telephone
	Vallone J	New York Telephone
	Vallone J	New York Telephone
	Washington Die Cutting Co	New York Telephone
	ACME SEAL & LABEL CO	New York Telephone
	COHEN & COHEN BK BNDRS	New York Telephone
	COLLEGE PRESS PRINTING	New York Telephone
	JASPER ISRAEL WLN STK	New York Telephone
	QUALITY DIE CUTTING CO	New York Telephone
	QUALITY DIE CUTTING CO	New York Telephone
	RABRO CO INS	New York Telephone

FINDINGS

Year	Uses	Source
1927	REGAL CAP CO	New York Telephone
	TROEGER HERMAN PRINTER	New York Telephone
	VALLONE J	New York Telephone
	VALLONE J	New York Telephone
	WASHINGTON DIE CUTTING CO	New York Telephone
1923	American Feather Duster Co RTN Michl Greenberg	R. L. Polk & Co.
	Geneva Hat Mfg Co Inc NY	R. L. Polk & Co.
	Jasper Woolen Stoek Co RTN Israel Jasper	R. L. Polk & Co.
	Kerner Harry Parisian Leather Goods Mfg Co	R. L. Polk & Co.
	Klucher Jacob I Triumph Bow Mfg Co	R. L. Polk & Co.
	Kowaisky Lifshin new clippings	R. L. Polk & Co.
	Parisi Leather Goods Mfg Co RTN Saml Rothman & Harry Kerner	R. L. Polk & Co.
	Rabinowitz Bros Saml & Jacob druggist	R. L. Polk & Co.
	Rabro Co Inc NY J Rabinowitz pres S Rabinowitz sec drugs	R. L. Polk & Co.
	Rosen D & Co David Rosen Max Bobsky Harry Silbert hat frames	R. L. Polk & Co.
	Rothman Saml Parisian Leather Goods Mfg Co	R. L. Polk & Co.
	Schwartzberg Hyman Triumph Bow Mfg Co	R. L. Polk & Co.
	Strumpf Nathan caps	R. L. Polk & Co.
	Triumph Bow Mfg Co RTN Jacob I Klucher Hyman Schwartzberg	R. L. Polk & Co.
1920	American Feather Duster Co RTN Michael Greenberg	R. L. Polk & Co.
	Friedman Morris J Ace Printing Co	R. L. Polk & Co.
	Ginzberg Sol foatners	R. L. Polk & Co.
	Jasper Israel pres treas Jasper Woolen Stock Co	R. L. Polk & Co.
	Regal Cap Co RTN Nathan Strumpf	R. L. Polk & Co.
	Rosen D & Co David Rosen Max Babsky hat frames	R. L. Polk & Co.
	Russo Antonio fruit	R. L. Polk & Co.
	Schlesinger Saml trimming	R. L. Polk & Co.
	Simkoff Edw W Ace Printing Co	R. L. Polk & Co.

25 GREAT JONES

Year	*Uses*	*Source*
1998	MINAGAWA ART LINES	NYNEX Telephone
1993	MINAGAWA ART LINES	NYNEX Telephone
1988	MINAGAWA ART LINES	NYNEX Telephone
1983	DAVEY S ROBERT B	New York Telephone
	HOROWITZ CHARLES & SONS INC	New York Telephone
	LEATHERCRAFTERS SUPL CO-DIV OF RONI INDUSTRIES INC	New York Telephone
	RONI INDUSTRIES INC	New York Telephone
1978	HOROWITZ CHARLES & SONS INC	New York Telephone
	LEATHERCRAFTERS SUPL CO DIV OF RONI INDUSTRIES INC	New York Telephone
	RONT INDUSTRIES INC	New York Telephone
1973	LEATHERCRAFTERS SUPL CO	New York Telephone
1950	WINNER ADOINIMENTS INC	New York Telephone
1947	LUCCHESI BROS REPRS	New York Telephone
	LUCCHESI BROS REPRS	New York Telephone
	WINNER ADORNMENTS INC	New York Telephone
1942	LUCCHESI ANDREW AUTO REPRS	New York Telephone
	LUCCHESI BROS AUTO REPRS	New York Telephone
1934	Borough Paper Co TN Julius and Sadie Kafka	R. L. Polk & Co.
	Continental Carton Co RTN Irving Bekoff	R. L. Polk & Co.
	Kalfka Julius pres Borough Paper Co Inc	R. L. Polk & Co.
	Kalfka Sadie sec Borough Paper Co Inc	R. L. Polk & Co.
	Ledner R & S R Ledner leather novelties	R. L. Polk & Co.
1927	Kassan & Pasternak caps	New York Telephone
	Plushat Co Inc	New York Telephone
	Sachs S cap satin lngs	New York Telephone
	KASSAN & PASTERNAK CAPS	New York Telephone
	PLUSHAT CO INC	New York Telephone
	SACHS S CAP SATIN LNGS	New York Telephone
1923	Paramount Cap Works RTN Julius Levien Isaac Gold	R. L. Polk & Co.
	Posner Saml paper bags	R. L. Polk & Co.
	Sachs Sol cap Hnings	R. L. Polk & Co.
	Eastern Hat & Cap Co Inc NY David Kaplan pres	R. L. Polk & Co.
	Kessler Max buttons	R. L. Polk & Co.

Year	Uses	Source
1923	Moldauer & Adler Oscar Moldauer Sol Adler hats and caps	R. L. Polk & Co.
1920	Eastern Hat & Cap Mfg Co Inc NY David Kaplan pres Abr Rabinoff v p Isidor Block treas Harry Scolnick sec	R. L. Polk & Co.
	Jaffe Sol furrier	R. L. Polk & Co.
	Jasper Woolen Stock Co NY Israel Jasper pres treas Ida Jasper sec	R. L. Polk & Co.
	Kayess Auto Delivery Co	R. L. Polk & Co.
	Koger Jno tailor	R. L. Polk & Co.
	New York Rubber Hat Co RTN Julius Simmons	R. L. Polk & Co.
	Paramount Cap Works RTN Julius Levien Isaac Gold	R. L. Polk & Co.
	Plushat Co Inc Sol Sachs pres Jacob Levitt sec Max Simon treas ladies hats	R. L. Polk & Co.
	Sachs Sol hatters matls	R. L. Polk & Co.
	Scolnik Harry sec Eastern Hat & Cap Co Inc	R. L. Polk & Co.

27 GREAT JONES

Year	Uses	Source
1998	G D M CONSTRUCTION SERVICE S INC	NYNEX Telephone
	GREAT JONES FURNITURE	NYNEX Telephone
1958	ETNA TOOL & DIE CO	New York Telephone
1956	ETNA TOOL & DIE CO	New York Telephone
	MILLER THOS C VENTLATG	New York Telephone
	MILLER THOMAS C INC ELECTRCN	New York Telephone
1950	B & Z BUYING SVCE INC	New York Telephone
	BENIT MORRIS EXPTR	New York Telephone
	BEN ITZHAK M EXPTR	New York Telephone
1942	J&W PAPR CO INC	New York Telephone
	SW PAPR CO	New York Telephone
	SELTZER BROS FURS	New York Telephone
	SELTZER WALTER FURS	New York Telephone
1934	Linette Paper Cutter Co Inc NY Nathan Linetzky pres Jacob Linetzky sec Wm Weisburd tres	R. L. Polk & Co.
	Linetzky Jacob sec Linette Paper Cutter Co	R. L. Polk & Co.
	Star Paper & Twine Co Inc NY: cap $5.000 Saml Leiman pres	R. L. Polk & Co.

Year	Uses	Source
1934	West Shore Paper Co Inc NY; cap $75 000 Max Schlanger pres Jacob Linetsky sec Nathan Linetsky treas	R. L. Polk & Co.
1927	SENECA FOLDING PAPER BOX CO	New York Telephone
1923	Isaacs Hattie Isaacs Paper Co	R. L. Polk & Co.
	Isaacs Paper Co TN Hattie Isaacs paper twine	R. L. Polk & Co.
	Reliance Bag & Twine Mills Max L Weill	R. L. Polk & Co.
	Reliance Paper & Twine Mill TN M L Well	R. L. Polk & Co.
1920	Gerofsky Bros Inc NY Harry Gerofsky pres Benj L Gerofsky sec Herman Gerofsky treas paper stock	R. L. Polk & Co.

29 GREAT JONES

Year	Uses	Source
1958	PERLOV J CO WHOL CROKRY	New York Telephone
1956	PERLOV J CO WHOL CROKRY	New York Telephone
1950	PERLOV J CO WHOL CROKRY	New York Telephone
1947	PERLOV J WHOL CRKRY	New York Telephone
1942	MAJESTIC COPPER STORE FRONT CO INC	New York Telephone
	PERLOV J WHOL CROKRY	New York Telephone
	RENT COLLECTION SVCE BUR	New York Telephone
1938	MAJESTIC COPPER STORE FRONT CO INC	New York Telephone
	PERLOV J WHOL CROKRY	New York Telephone
	RENT COLLECTION SVCE BUR	New York Telephone
1934	Perlov J Inc NY Jos Perlov pres Leo Sumin sec tress crockery	R. L. Polk & Co.
1927	Ideal Coat Front Co	New York Telephone
	N S Jewelry Case Co	New York Telephone
	DOYLE J MARVIN SHT STEEL	New York Telephone
	IDEAL COAT FRONT CO	New York Telephone
	N S JEWELRY CASE CO	New York Telephone
	NATL DOLL OUTFIT & INFANTS WEAR CO	New York Telephone
	Doyle J Marvin sht steel	New York Telephone
1923	Ideal Coat Front Co RTN Harry A Cohen & Abr Ziegler	R. L. Polk & Co.
	Klein Bros Hyman & Chas hats	R. L. Polk & Co.
	N & S Jewelry Case Co Abr Nathanson Sam Sprintzen Herman Hellperin	R. L. Polk & Co.

Year	Uses	Source
1923	Standard Importing & Jobbinging House RTN Albert Adrams Jacob Abrahams	R. L. Polk & Co.
	Weinberg & Glasser Isidors Weinberg Abr Glasser clothing	R. L. Polk & Co.
	Good Value HAt & Cap Mfg Co Inc N Y Ahe Steingold pres Herman Rosenzweig sec Meyer Lazerson treas	R. L. Polk & Co.
	Finklestein J & Co Jacob Finklesteim caps	R. L. Polk & Co.
1920	Heisenberg Karl Oneko Mfg Co	R. L. Polk & Co.
	Heisenbutal Fred clk Irving Nat Bank h JC	R. L. Polk & Co.
	Oneko Mfg Co RTN Karl Heisenberg bralds	R. L. Polk & Co.
	Weinberg & Glasser Isidor Weinberg Abrat Glasser clothing	R. L. Polk & Co.

31 GREAT JONES

Year	Uses	Source
1998	OX CART STUDIO	NYNEX Telephone
	SWEENEY CONSTRUCTIMN INC	NYNEX Telephone
1988	CHARLESWORTH SARAH	NYNEX Telephone
	CIARLO FRANCO	NYNEX Telephone
1983	CIARLO FRANCO	New York Telephone
	HUNT BRYAN	New York Telephone
1978	CIARLO FRANCO	New York Telephone
	HUNT BRYAN	New York Telephone
1973	SCOTT TRNCKG CO	New York Telephone
1968	KAPLAN LEO HAIR GDS	New York Telephone
1963	HALLORAN CARTING CO	New York Telephone
	KAPLAN LEO HAIR GDS	New York Telephone
1958	SIFER SAML CAPS	New York Telephone
	KAPLAN LEO HAIR GDS	New York Telephone
	B & TRIANPTNI CO	New York Telephone
1956	GOODMAN H HUMANS HAIR GDS	New York Telephone
	KAPLAN LEO HAIR GDS	New York Telephone
	B & N TRANSPTN CO	New York Telephone
1950	KAPLAN LEO HAIR GDS	New York Telephone
	GOODMAN H HUMAN HAIR GDS	New York Telephone
	B & N EXPIESS INC	New York Telephone
1947	B & N EXPRESS INC	New York Telephone
	L GANZ HAT & NOVELTY CO	New York Telephone
1942	EGAN HAROLD	New York Telephone

Year	Uses	Source
1942	GORECKA ERICA HANKA	New York Telephone
	KIRISHJIAN VAHE	New York Telephone
	M & A TRUCKING CO	New York Telephone
1934	Bernhardt David sec treas Barnhardt Zinn Paper Co Inc	R. L. Polk & Co.
1927	Spelecy Kate Mrs r	New York Telephone
	Allen Wm mfr hats caps	New York Telephone
	Peoples Sylvia Miss r	New York Telephone
	ALLEN WM MFR HATS CAPS	New York Telephone
	PEOPLES SYLVIA MISS R	New York Telephone
	SPELECY KATE MRS R	New York Telephone
1920	Allen Wm caps	R. L. Polk & Co.
	Spelecy Michl W firm of W J Buckley	R. L. Polk & Co.

32 GREAT JONES

Year	Uses	Source
1983	EDISON PARKING CORP-	New York Telephone
1978	EDISON PARKING CORP-	New York Telephone
1973	EDISON PARKING CORP	New York Telephone
1958	A & M METAL POLISHING CO	New York Telephone
	DOUBLE DEE ROOFING & SHEET METAL CO	New York Telephone
	W & M HEADWR CO	New York Telephone
1956	A & M METAL POLISHING CO	New York Telephone
	CHARLES HEADWR CO	New York Telephone
	DOUBLE DEE ROEFING & SHEET METAL CO	New York Telephone
1950	A & M METAL POLISHING CO	New York Telephone
	CHARLES HEADWR CO	New York Telephone
1947	A & M POLISHING CO	New York Telephone
	ARROW FROZEN FOOD CABINETS INC	New York Telephone
	ARROW SHEET METAL WKS	New York Telephone
1938	ERDHEIM & WOHL SHEET METL	New York Telephone
	SOLOMON SAML B	New York Telephone
	STUYVESANT PAPR & SUPL CORP	New York Telephone
1934	J & S Supply Co Inc NY Yeta Solomon sec Saml Solomon v pes Saml Solomon treas paper products	R. L. Polk & Co.
	Perelstein M M Perelstein & Sons	R. L. Polk & Co.

Year	Uses	Source
1934	Perelstein M & Sons Inc NY cap $10 000 David Perelstein pres sec Benj Perelstein v pres treas woolen remnant	R. L. Polk & Co.
	Solomon Saml v pres treas J & S Supply Co Inc	R. L. Polk & Co.
1927	Steier Louis fringes	New York Telephone
	STEIER LOUIS FRINGES	New York Telephone
1923	Acme Hat & Cap Co RTN Saml Wisansky	R. L. Polk & Co.
	Ashkenas Bros Saml & Saul Ashkenas infants clothing	R. L. Polk & Co.
	G T D Co RTNBenj Goodman Sam Titensky Louis Doniger hats	R. L. Polk & Co.
	Lipman Sol Co Inc NY Sol Lipman pres sec Chas Lipman v p treas imprs & whse	R. L. Polk & Co.
	Marcus & Sabrin Morris Marcus Paul Sabrin sweat bands	R. L. Polk & Co.
	Star Mfg Co RTN Sam Kirshner & Morris Molinsky caps & hats	R. L. Polk & Co.
1920	Hinerfeld Benj woolens	R. L. Polk & Co.
	Hinerfeld Jos woolens	R. L. Polk & Co.
	Lacijan Jno & Co Jno Lacijan mlnry gds	R. L. Polk & Co.
	Volk Wm J & Co Wm J Volk Jno Lacijan straw hats	R. L. Polk & Co.

33 GREAT JONES

Year	Uses	Source
1998	SCOTT JOS TRUCKING CORP	NYNEX Telephone
1993	SCOTT JOS TRUCKING CORP	NYNEX Telephone
1988	SCOTT TRUCKG CO	NYNEX Telephone
1983	SCOTT TRUCKG CO	New York Telephone
1978	SCOTT TRUCKG CO	New York Telephone
1968	LOSACK TRUCKING GO	New York Telephone
1963	LOSACK TRUCKING CO	New York Telephone
1958	LOSACK TRUCKING CO	New York Telephone
1956	GEORGE S TRUCKING OFC	New York Telephone
	GEORGE S TRUCKING OFC	New York Telephone
1950	GEORGE S TRUCKING	New York Telephone
1947	MS FORWARDING CORP OFC	New York Telephone
1942	JOE S AUTO REPAIR SVCE	New York Telephone
	STOPPIELLO FANNY TRUKNG	New York Telephone
1938	DURABLE AUTO TRUCKING CO	New York Telephone
	JIMMY S MOTOR SVCE	New York Telephone

Year	Uses	Source
1938	MONROE MOVING VAN CO	New York Telephone
	STOPPIELLO FANNY TRUKNG	New York Telephone
1934	Joes Auto Repair Jos Reizman	R. L. Polk & Co.
1923	Progressive Leather Sweets Co RTN Jack Nish	R. L. Polk & Co.

34 GREAT JONES

Year	Uses	Source
1958	BEYER JOHN	New York Telephone
	GONSHACK I CAP MFR	New York Telephone
	GREENBAUM D REMNTS	New York Telephone
1956	COHEN & KATZ COTTN GDS	New York Telephone
	GONSHACK I CAP MFR	New York Telephone
	MARGOHIN PHILIP HEATING	New York Telephone
	MARLIN PLUMBING & HEATING CORP	New York Telephone
1950	COHEN & KATZ COTTN GDS	New York Telephone
	GONSHACK I CAP MFR	New York Telephone
	MAN ALEXNDR	New York Telephone
	POLISH PINNEA CO	New York Telephone
	PL-TEN PRESS	New York Telephone
1947	COHEN & KATZ COTTN GDS	New York Telephone
	CROWN PLATING CORP	New York Telephone
	GONSHACK I CAP MFR	New York Telephone
	POLISH PRNTNG CO	New York Telephone
	PYL-TEN PRESS	New York Telephone
1942	BANKO N P PRNTNG	New York Telephone
	COHEN & KATZ COTTN GDS	New York Telephone
	GONSHACK I CAP MFR	New York Telephone
1938	COHEN & KATZ COTTN GDS	New York Telephone
1934	Cohen & Katz Inc NY cap 100 sh npv David Cohen pres Benj Cohen v pres Louis Cohen treas capes trmgs	R. L. Polk & Co.
	Treuhaft Louis Gt Jones Grill	R. L. Polk & Co.
1927	ADJUSTABLE ENGINERR S CAP CORP	New York Telephone
1923	Cohen & Katz David Cohen Jos Katz cotton gds	R. L. Polk & Co.
	Elk & Son Harry L & Nathan L hats	R. L. Polk & Co.
	Elkan Benno v p International Minerals & Metals Corp h Larthmont NY	R. L. Polk & Co.
	Janov Simon restr	R. L. Polk & Co.

Year	Uses	Source
1920	Cohen & Katz David Cohen Jos Katz cotton gds	R. L. Polk & Co.
	Janov Simon delicatessen	R. L. Polk & Co.
	Victoria & Rossano Jessie Victoria Virginia Rossano mlnr gds	R. L. Polk & Co.
	Wild Hat Mfg Co RTN Saul Wild & Jas H Clifford	R. L. Polk & Co.

35 GREAT JONES

Year	Uses	Source
1998	CEDES INC	NYNEX Telephone
	LOCAM	NYNEX Telephone
1988	NIELSEN C	NYNEX Telephone
	NIELSEN TODD	NYNEX Telephone
1983	CHRISTOPHER I M	New York Telephone
	DANIEL L E	New York Telephone
	FROLICK SPECIALTIES	New York Telephone
	KIRWAN PETER	New York Telephone
	NOBLE TERRY	New York Telephone
1978	D & W ROBES	New York Telephone
	FROLICK SPECIALTIES	New York Telephone
1973	D & W ROBES	New York Telephone
	FROLICK SPECIALTIES	New York Telephone
1968	FROLICK SPECIALTIES	New York Telephone
1963	FROLICH WM H MRS	New York Telephone
1958	ALLEN E W CO B	New York Telephone
	FROLICK SPECIALTIES	New York Telephone
	HOFFMAN PASTRY	New York Telephone
	KAY ADVTG CAP CO	New York Telephone
	MIL-BAR HEADWEAR CO	New York Telephone
	PROGRESS ELECTRIC LIGHT INC	New York Telephone
1956	ALLEN E W CO B	New York Telephone
	FROLICK SPECIALTIES	New York Telephone
	GLOBE STATARY CO	New York Telephone
	H & H STATNRY CO INC	New York Telephone
	KAY ADVTG CAP CO	New York Telephone
	NISSENBAUM MAX HATS	New York Telephone
	SCHEINKER ILYA MECH ENGNRNG	New York Telephone
	UNITED STATNRY CO	New York Telephone
1950	ARGOSY SPORTSWR INC SHRVRM	New York Telephone

FINDINGS

Year	Uses	Source
1950	DE LUXE UPHLSTRG CO	New York Telephone
	DE LUXE UPHLSTRG CO	New York Telephone
	KAY ADVTG CAP CO	New York Telephone
	NISSENBAUMN MAX HATS	New York Telephone
	PREMIUM HOUSE	New York Telephone
	SCHEINKER ILYA MECH ENGNRNG	New York Telephone
	SCHWARTZ JOS WOOLN STK	New York Telephone
	STINGO ERMANNO J PLSTCS	New York Telephone
	STRAUS & STINGO INC PLSTCS	New York Telephone
1947	DARITE MFG CO INC OFC	New York Telephone
	KROYD MFG CO INC WAREHSE	New York Telephone
	METROPOLITN PLASTIC PRODS CO	New York Telephone
	NISSENBAUM MAX HATS	New York Telephone
	PARKER LUGGAGE CO	New York Telephone
	SCHWARTZ JOS WOOLN STK	New York Telephone
	SEL CO SUITCSES	New York Telephone
	SOLVEX PRODS CORP CHEMSTS	New York Telephone
	STERLING LUGGAGE CO INC	New York Telephone
	STRAUS & STINGO INC PLSTCS	New York Telephone
	SWARTZ TOM TUCKER SEWING	New York Telephone
	VICTOR FELLING CO	New York Telephone
1942	AA MILL SUPL CO	New York Telephone
	INDUSTRL WASTE CORP	New York Telephone
	KARP KARL RAGS	New York Telephone
	KLEIN ISADORE RAGS	New York Telephone
	NY PENN RAG CO	New York Telephone
	SCHWARTZ DAVID WOOLN STK	New York Telephone
	SCHWARTZ J WOOLN STK	New York Telephone
1938	IUDUSTRL WASTE CORP	New York Telephone
	KARP KARL RAGS	New York Telephone
1934	New York Diet & Sttomping Co RTN John Reuter	R. L. Polk & Co.
	Electric Display Corp	R. L. Polk & Co.
	Evergreen Nurseries Inc NY cap $10 000 Bernard H Goldenson pres treas	R. L. Polk & Co.
	F & S Rubber Co RTN Phil Epstein	R. L. Polk & Co.
	Irving Paper & Twine Co RTN Irving I	R. L. Polk & Co.
	Lafayette Lighting Equip Co Julius Goldstein lamps	R. L. Polk & Co.
1927	Abrahams S	New York Telephone

FINDINGS

Year	Uses	Source
1927	Brown Paper Co	New York Telephone
	Princess Hat Frame Co	New York Telephone
	Sunshine Hat Co	New York Telephone
	Superior Paper Co	New York Telephone
	ABRAHAMS S	New York Telephone
	BROWN PAPER CO	New York Telephone
	PRINCESS HAT FRAME CO	New York Telephone
	PUBLIC HEADWEAR CO	New York Telephone
	SUNSHINE HAT CO	New York Telephone
	SUPERIOR PAPER CO	New York Telephone
1923	Cohen Jos acct	R. L. Polk & Co.
	Eastern Twine Mills Inc NY Abr Miness pres Sol Abrahams v p Nathan Miness sec treas twine	R. L. Polk & Co.
	Eleanor Hat Frame Co RTN Jack Shore Lillian Lien	R. L. Polk & Co.
	Elhay Hat Frame Co RTN Loluis & Jos Zeitzew	R. L. Polk & Co.
	Goldstein Jos Merit Hat Frame Co	R. L. Polk & Co.
	Lieberman Mildred sec Supreme Cap Mfg Co Inc	R. L. Polk & Co.
	Marchetti R & Bro Rocco and Nicholas Marchetti book gilders	R. L. Polk & Co.
	Merit Hat Frame Co RTN Jos Goldstein	R. L. Polk & Co.
	Miller Louis pres treas Supreme Cap Mfg Co	R. L. Polk & Co.
	Seltzer Bros Jacob & Max Seltzer trimmings	R. L. Polk & Co.
	Seltzer Max Seltzer Bros	R. L. Polk & Co.
	Superior Paper Co RTN Abr and Nathan Miness paper and twine jobbers	R. L. Polk & Co.
	Supreme Cap Mfg Co Inc NY Louis Miller pres treas Jos Getzooff v p Mildred Lieberman sec	R. L. Polk & Co.
1920	Bernard Morris Lucille Hat Co	R. L. Polk & Co.
	Dryer Jos ladies hats	R. L. Polk & Co.
	E D A Novelty Co RTN Edw Hillman Davis Dlugoff	R. L. Polk & Co.
	Eastern Envelope Co Inc NY Wm Zuckerman pres Maurice Newman sec & treas	R. L. Polk & Co.
	Geber J B Co Inc Jos B Geber pres Barnett K Ryskind sec treas lamp shades	R. L. Polk & Co.
	Hillman E L bags	R. L. Polk & Co.

Year	Uses	Source
1920	Kaplan Max Lucille Hat Co	R. L. Polk & Co.
	Marchetti R & Bro Rocco & Nicholas bkgilders	R. L. Polk & Co.
	Rivoll Hat Co Inc N Y Leon Rothenberg pres Saml Myer sec Saml Silverstein treas	R. L. Polk & Co.
	Ruderman Jacob Lucille Hat Co	R. L. Polk & Co.
	Superior Paper Co RTN Abram Miness	R. L. Polk & Co.

36 GREAT JONES

Year	Uses	Source
1958	DO RIT NOVELLY CORP	New York Telephone
	GREENBAUM D REMNTS	New York Telephone
	VEROLETTE NOVELTIES CORP	New York Telephone
1956	LIEBMAN ROSE HATS	New York Telephone
	VEROLETTE NOVELTIES CORP	New York Telephone
1950	VEROLETTE NOVELTIES CORP	New York Telephone
	LIEBMAN ROSE HATS	New York Telephone
	GELMAN MFG CO	New York Telephone
1947	LIEBMAN ROSE HATS	New York Telephone
	LETTY HAT CO	New York Telephone
	GELMAN MFG CO	New York Telephone
1942	GELMAN MFG CO	New York Telephone
	HENDLER SIDNEY MILNRY	New York Telephone
1938	ALDIN MILLINERY & HATTERS SUPL CO	New York Telephone
	NY FLOCKING CO	New York Telephone
	STAR CUTTING CO	New York Telephone
1934	Star Cutting Co RTN: Alex Dinoff Harry Rosenberg	R. L. Polk & Co.
1927	MANDEL & LEVINE PRNTRS	New York Telephone
	MANDEL & LEVINE PRNTRS	New York Telephone
	WERNER BROS CAP FROUTS	New York Telephone
	Werner Bros cap frouts	New York Telephone
	Mandel & Levine prntrs	New York Telephone
	Mandel & Levine prntrs	New York Telephone
1923	Cohn Victor Metropolitan Caster & Wheel Co	R. L. Polk & Co.
	G P S Headwear Mfg Co Inc NY Jos Goodman pres Morris Singer v p Saml Pessin sec caps	R. L. Polk & Co.
	Mandel & Levine Saml Mandel Jas Levine printers	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1923	Metropolitan Basket Co RTN Aaron & Victor Cohen	R. L. Polk & Co.
	Metropolitan Caster & Weel Co RTN Victor Cohn	R. L. Polk & Co.
	Pacific Hat Co RTN Manny Schantz Henry Blicker mf ladies hats	R. L. Polk & Co.
1920	Mandel & Levine Saml Mandel Jas Levine printers	R. L. Polk & Co.
	Pacific Hat Co RTN Max Schwartz Louis J Wank Mae D White Leo Gottesman Abr Eisen & Hy Bleecker	R. L. Polk & Co.
	Rubenstein & Felier Isaac Rubenstein Jos Feiner hats	R. L. Polk & Co.

37 GREAT JONES

Year	Uses	Source
1963	STEEL PARTS MFG CO INC	New York Telephone
	REVERE METAL ART CO INC	New York Telephone
	CONCORD ELECTRNCS CORP	New York Telephone
1958	STEEL PARTS MFG CO INC	New York Telephone
	REVERE METAL ART CO INC	New York Telephone
1956	RED BALL EXPRESS & FORWARDING INC	New York Telephone
1950	RED BALL VAN LINES	New York Telephone
1947	RED BALL VAN LINES	New York Telephone
1942	RED BALL VAN LINES	New York Telephone
	RED BALL VAN LINES	New York Telephone
1938	KASS IRVING H ENAMLWARE	New York Telephone
	CONSOLIDATD COMMODITIES CORP	New York Telephone

38 GREAT JONES

Year	Uses	Source
1958	AMER HAT CO	New York Telephone
	BEALS ALLAN E & SON SALES REPS	New York Telephone
	BENGAL CAP CU	New York Telephone
	BOND SVCE & REPR CORP	New York Telephone
	BOTTLE CAPPING MACH WKS	New York Telephone
	COPELAND E W PUMPS	New York Telephone
	KANZE EDW J MGTRS	New York Telephone
	LEVIEN JULIUS E REMNANTS	New York Telephone
	NEMO HAT CO	New York Telephone
1956	AMER HAT CO	New York Telephone

FINDINGS

Year	Uses	Source
1956	BENGAL CAP CO	New York Telephone
	BOND SVCE & REPR CORP	New York Telephone
	BOTTLE CAPPING MACH WKS	New York Telephone
	COPELAND E W PUMPS	New York Telephone
	GOTTLIEB JACOB HATS CAPS	New York Telephone
	KANZE EDW J MOTRSA	New York Telephone
	LEVIEN JULIUS E REMNANTS	New York Telephone
	NEMO HAT CO	New York Telephone
1950	BOND SVCE & REPR CORP	New York Telephone
	BOTTLE CAPPING MACH WKS	New York Telephone
	COPELAND E W PUMPS	New York Telephone
	KANZE EDW J MOTRS	New York Telephone
	NEMO HAT CO	New York Telephone
	BEALS ALLEN E & SON SALES REPS	New York Telephone
	BEDELL BROS WOOLNS	New York Telephone
	BENGAL CAP CO	New York Telephone
1947	BEALS ALLEN E & SON SALES REPS	New York Telephone
	BEDELL BROS WOOLNS	New York Telephone
	BENGAL CAP CO	New York Telephone
	BOND SVCE & REPR CORP	New York Telephone
	BOTTLE CAPPING MACH WKS	New York Telephone
	COPELAND E W PUMPS	New York Telephone
	FELDMAN J LININGS	New York Telephone
	KANZE EDW J MOTRS	New York Telephone
1942	BEALS ALLEN E & SON SALES REPS	New York Telephone
	BOND SVCE &REPR CORP	New York Telephone
	BOTTLE CAPPING MACH WKS	New York Telephone
	COPELAND E W PUMPS	New York Telephone
	KANZE EDW J MOTRS	New York Telephone
1938	BOND SVCE & REPR CORP	New York Telephone
	BOTTLE CAPPING MACH WKS	New York Telephone
	COPELAND E W PUMPS	New York Telephone
	JAFFIN MAX CTN GDS	New York Telephone
1934	Bottle Capping Machine Works RTN Edwin W Copeland mfrs	R. L. Polk & Co.
	Copeland Electric Cellar Drainer Co Inc NY Edw W Copeland pres mfrs water pumps	R. L. Polk & Co.
	Diesel Packing & Rubber Co Inc Y rubber packing dirs	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Hicks Robt B pumping equipment & repairing	R. L. Polk & Co.
	McCormick Vincent sec Bond Service & Repair Corp	R. L. Polk & Co.
	Muster G F pres Diesel Packing & Rubber Co	R. L. Polk & Co.
	Treuhaft Benj Treuhaft Bros	R. L. Polk & Co.
	Treuhaft Bros Julius & Benj truckmn	R. L. Polk & Co.
	Treuhaft Julius Treuhaft Bros	R. L. Polk & Co.
	Wendland Wm A v pres Bond Service & Repair Corp	R. L. Polk & Co.
1927	Jaffin Max ctn gds	New York Telephone
	Rothenberg B basket mfr	New York Telephone
	Treuhaft Bros truckmen	New York Telephone
	Wardel Headwear Co	New York Telephone
	ARTCRAFT BELT CO	New York Telephone
	JAFFIN MAX CTN GDS	New York Telephone
	ROTHENBERG B BASKET MFR	New York Telephone
	TREUHAFT BROS TRUCKMEN	New York Telephone
	WARDEL HEADWEAR CO	New York Telephone
1923	Cortland Motor Express Co RTN Max Samuels	R. L. Polk & Co.
	Jaffin Max cotton gds	R. L. Polk & Co.
	Osterman Simon Sobel Cap Mfg Co	R. L. Polk & Co.
	Sobel Cap Mfg Co TN Jack Sobel Simon Ostorman	R. L. Polk & Co.
	Sobel Jack Soble Cap Mgf Co	R. L. Polk & Co.
	Treuhaft Bros Louis Treuhaft truckmn	R. L. Polk & Co.
1920	Friedman Pearl & Gallack Jos Friedman Oscar Pearl & Louis Gallack hand bags	R. L. Polk & Co.
	Jaffin Max cotton gds	R. L. Polk & Co.
	K & S Hat & Cap Co NY Jacob Kutlowitz pres Saml Kutlowitz sec Maurice Silver treas	R. L. Polk & Co.
	Marcus Gordon & Co Morris Marcus Abram Gordon & Paul Sabrin trimming	R. L. Polk & Co.
	Rothenberg Benj baskets	R. L. Polk & Co.
	Treuhaft Saml Treubaft Bros	R. L. Polk & Co.

39 GREAT JONES

Year	Uses	Source
1993	KIDD JOHN PHOTGR	NYNEX Telephone
	KIDD JOHN PHOTOGRAPHER	NYNEX Telephone

FINDINGS

Year	Uses	Source
1988	ALDERSON D	NYNEX Telephone
	GOOD JOHN	NYNEX Telephone
	JOHN GOOD GALLERY	NYNEX Telephone
	KILLCOMMONS JEANNE	NYNEX Telephone
	KILLY CORP	NYNEX Telephone
	KING KEVIN N	NYNEX Telephone
	KLAINBERG ADOLF	NYNEX Telephone
	MONTE ELISA	NYNEX Telephone
	MOORE M A	NYNEX Telephone
	RENTMEESTER A C	NYNEX Telephone
	WILDMAN E	NYNEX Telephone
1983	ALDERSON D	New York Telephone
	KLAINBERG ADOLF	New York Telephone
	MONTE ELISA	New York Telephone
	PERNA THOMAS	New York Telephone
	WILDMAN E	New York Telephone
1978	ALDERSON D	New York Telephone
	KLAINBERG ADOLF	New York Telephone
	MONTE ELISA	New York Telephone
	STONE JESSE BURTON LTD	New York Telephone
	WILDMAN E	New York Telephone
1958	MOINESTER ISAAC ENVLPS	New York Telephone
	REX ENVELOPE CO	New York Telephone
	RUBENS CO THE YRNS	New York Telephone
	RUBANS EDW J YRNS	New York Telephone
1956	A-ABLE STEEL RULE DIE CO	New York Telephone
	ABLE HEAT SEALING DIE CO	New York Telephone
	ABLE STEEL RULE DIE CO	New York Telephone
	AMER BEDDING CO INC	New York Telephone
	HELENEK WIRE FRAME CO	New York Telephone
	LIBERTY CUTTING DIE CO	New York Telephone
	M & C PRINT CO INC	New York Telephone
1950	AMER BEDDING CO INC	New York Telephone
	BARRY FASHIONS HNDBGS	New York Telephone
	BOND FLOWER & FEATHER CO	New York Telephone
	MAJESTIC WIRE FRAME CO	New York Telephone
	MOTOOL MACH CO INC	New York Telephone
	SERV ALL LOOSE LEAF CORP	New York Telephone

FINDINGS

Year	Uses	Source
1947	ALVIN SHOES	New York Telephone
	ASTERBLOOM L C B	New York Telephone
	ASTERCRAFT PRODS LTHR GDS	New York Telephone
	INTERNATL SHOULDER PAD CO INC	New York Telephone
	KAYGEE NOVELTIES INC	New York Telephone
	KIRSCHNER SAML & SONS INC GLAZRS	New York Telephone
	MAJESTIC WIRE FERAME CO	New York Telephone
	PATCO STORE FRONT CO	New York Telephone
	ZEIDMAN PHILLIP B	New York Telephone
1938	KIRSCHNER SAML GLZR	New York Telephone
1934	Balicks Max Son Herman Balik glass dir	R. L. Polk & Co.
1927	BARSKY & FARBER HEADWR	New York Telephone
	METROPOLITAN BASKET CO	New York Telephone
	METROPOLITAN CASTER & WHEEL CO	New York Telephone
	N Y TRIMMING CO INC	New York Telephone
	SER COAT CO COAT CONTRS	New York Telephone
	ZAGOR DAVID L MILL ENDS-	New York Telephone
	Barsky & Farber headwr	New York Telephone
	Metropolitan Basket Co	New York Telephone
	Metropolitan Caster & Wheel Co	New York Telephone
	N Y Trimming Co Inc	New York Telephone
	Ser Coat Co coat contrs	New York Telephone
1923	Berg Jos C sec Phoenix Hat Co Inc	R. L. Polk & Co.
	Central Cap Co RTN Louis Chased	R. L. Polk & Co.
	Light Moses G pres Phoenx Hat Co Inc	R. L. Polk & Co.
	Milford Hat Co Inc NY Saml Schreiber pres Harry Schulman sec Chas Groff treas mlnrs	R. L. Polk & Co.
	Phoenix Hat Co Inc N Y Moe C Leight Pres Jos C Berg sec	R. L. Polk & Co.
	Safe Pack Mills Inc Boston Mass Fred Schenkelberger mgr waterproof paper	R. L. Polk & Co.
	Treo Hat Co Inc NY Louis Lieban pres sec childrens hats	R. L. Polk & Co.
1920	Central Cap Co RTN Philip Shuffman & Saml Chosed	R. L. Polk & Co.
	Chosed Saml Centl Cap Co	R. L. Polk & Co.
	Equity Hat Co RTN Morris Feltmann	R. L. Polk & Co.
	Feltmann Morris Equity Hat Co	R. L. Polk & Co.
	Gordonc Julius clothing	R. L. Polk & Co.

Year	Uses	Source
1920	Kleinberg Serwer Inc NY Isidor Kleinberg pres Hyman Kleinberg sec treas caps	R. L. Polk & Co.
	Safepae Mills Inc Boston Mass Benj Schwartz mgr paper	R. L. Polk & Co.
	Shuffman Plilip Central Cap Co	R. L. Polk & Co.
	Treo Hat Co Inc NY Louis Lieban pres Anna Gluck sec Adolph Arlof treas	R. L. Polk & Co.

41 GREAT JONES

Year	Uses	Source
1998	DIMENSIONS IN GLASS LTD	NYNEX Telephone
	PULVERMACHER R DESIGNS INC	NYNEX Telephone
	RANDI JAY	NYNEX Telephone
1993	DIMENSIONS IN GLASS LTD	NYNEX Telephone
	PULVERMACHER R DESIGNS INC	NYNEX Telephone
	RANDI JAY	NYNEX Telephone
1988	DIMENSIONS IN GLASS LTD	NYNEX Telephone
	KYLE LEIGH	NYNEX Telephone
	MCCARTHY JAMES K	NYNEX Telephone
	PULVERMACHER R DESIGNS INC	NYNEX Telephone
	RANDI JAY	NYNEX Telephone
	STEINMAN STEVEN	NYNEX Telephone
1983	EVSTIS O	New York Telephone
	FILCO MFG CO LIHR	New York Telephone
	MC CARTHY JAMES K	New York Telephone
	STEINMAN STEVEN	New York Telephone
	WESTON M	New York Telephone
	Filco Mfg Co lihr	New York Telephone
1978	BURGESS PAMELA	New York Telephone
	CAMPBELL N	New York Telephone
	EVSTIS O	New York Telephone
	KOBLAND K	New York Telephone
	MCCARTHY J	New York Telephone
	WANNER D	New York Telephone
	WESTON M	New York Telephone
1973	CHITTAMS NATHANIEL B	New York Telephone
	KAISER ROBERT	New York Telephone
	NATHANIEL CHITTAMS CUSTOM INTRS	New York Telephone
	SPROTE EOIN	New York Telephone
1968	ACME SANDBLASTING COLNC	New York Telephone

FINDINGS

Year	Uses	Source
1968	GOLDBERG BEN TRIMNGS	New York Telephone
1963	ACME SANDBLASTING CO INC	New York Telephone
	GOLDBERG BEN TRIMNGS	New York Telephone
	TAINERS	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
1958	ACME SANDBLASTING CO INC	New York Telephone
	GOLDBERG BEN TRIMINGS	New York Telephone
	LUCID CONTAINERS	New York Telephone
	ORIGINAL HEADWR CO	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
1956	CONCORD METAL ART CO	New York Telephone
	CONCORD PEN CO INC	New York Telephone
	GOLDBERG BEN TRIMNGS	New York Telephone
	QUICK LITE CO	New York Telephone
	REVERE METAL ART CO INC	New York Telephone
	SURE-FIRE PENCIL CO INC	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
1950	GOLDBERG BEN TRNINGS	New York Telephone
	LEINWAND WM HRDWR	New York Telephone
	MAZZE IMPORT & EXPORT CO	New York Telephone
	PROGRESSIVE LEATHER SWEATS CO	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
1947	CONCORD METAL ART CO	New York Telephone
	GOLDBERG BEN TRIMNGS	New York Telephone
	LILLING ABRAHAM B	New York Telephone
	LOUMAC COATED FABRICS CO	New York Telephone
	PROESSIVE LEATHER SWEATS CO	New York Telephone
	S & M LEATHER GOODS CO HNDBGS	New York Telephone
	SELTZER BROS FURS	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
1942	AMER BABY WEAR CO	New York Telephone
	EIBSCHUTZ HYMAN BUTNS	New York Telephone
	FASHION SPECIALTY CO	New York Telephone
	GOLDBERG BEN TIMINGS	New York Telephone
	MADE RIGHT DOLL ACCESSOIES CO	New York Telephone
	METROPOLITN BASKET CO	New York Telephone
	METROPOLITN CASTER & WHEEL CO	New York Telephone
	PROGRESSIVE LEATHER SWEATS CO	New York Telephone

FINDINGS

Year	Uses	Source
1942	TITENSKY A & SONS CAPS	New York Telephone
1938	BENGAL CAP CO	New York Telephone
	COHN ARON BASKETS	New York Telephone
	DECKER ALVIN NOVLTS	New York Telephone
	EIBSCHUTZ HYMAN BUTTONS	New York Telephone
	METROPOLITN BASKET CO	New York Telephone
	METROPOLITN CASTES & WHEEL CO	New York Telephone
	PARAMOUNT CAP WKS	New York Telephone
	PROGRESSIVE LEATHER SWEATERS CO	New York Telephone
	S K HAT CO	New York Telephone
	TITENSKY ABRAHAM HATS & CAPS	New York Telephone
1934	Goldstein Cap Co Inc NY cap $10 000 Hyman M Goldstein pres Jos Shakrefsky sec treas cap mfrs	R. L. Polk & Co.
	Metropolitan Basket Co RTN Aaron Cohn	R. L. Polk & Co.
	Metropolitan Caster & Wheel Co RTN Victor Cohn founders	R. L. Polk & Co.
	Schwartzsbard Harold Staple Cap Wks	R. L. Polk & Co.
1927	PARAMOUNT CAP WORKS	New York Telephone
	PROGRESSIVE LEATHER SWEATS CO	New York Telephone
	TITENSKY & SON HATS CAPS	New York Telephone
	WEITZMAN A & SONS PAPERS & TWINE	New York Telephone
	Paramount Cap Works	New York Telephone
	Progressive Leather Sweats Co	New York Telephone
	Titensky & Son hats caps	New York Telephone
1923	Clover Cloak & Suit Co Inc N Y Isidore Lerner pres Isidore Cohen v p cloaks & suits	R. L. Polk & Co.
	Cohen Isidore v p Clover Cloak & Suit Co Inc	R. L. Polk & Co.
	Exchange Towel Service Corp N Y Isaac Hirschler pres Win Coorer v p Wm Fuchus sec	R. L. Polk & Co.
	Fuchs Wm sec Exclusive Towel Service Corp	R. L. Polk & Co.
	Hookman Jacob caps	R. L. Polk & Co.
	Ideal Hat Frame Co RTNIsador Milgraum Hat frames	R. L. Polk & Co.
	Schneider Benj vests	R. L. Polk & Co.
	Alaska Sales Co Inc N Y Harry Harris pres Leo Harrison treas furs	R. L. Polk & Co.

Year	Uses	Source
1923	Allen Wm hat mfr	R. L. Polk & Co.
1920	Buras Jno L Alaska Fur & Trading Co	R. L. Polk & Co.
	Foster Robt Royal Cloak Co	R. L. Polk & Co.
	Harris Jacob Alaska Fur & Trading Co	R. L. Polk & Co.
	Ideal Hat Frame Co RTN Isidor Milgraum	R. L. Polk & Co.
	Meshorer Harry Royal Cloak Co	R. L. Polk & Co.
	Model Paper Box Co inc NY Saml Mutnick pres Isrel Solmanson sec treas	R. L. Polk & Co.
	Royal Cloak Co RTN Harry Meshorer Robt Foster	R. L. Polk & Co.

43 GREAT JONES

Year	Uses	Source
1988	ARMSTRONG SARA G	NYNEX Telephone
	BRANDT HELENE	NYNEX Telephone
	FROMBOLUTI I	NYNEX Telephone
	GREENE ART ASSOC	NYNEX Telephone
	KACERE JOHN	NYNEX Telephone
	LEICHT WILLIAM S	NYNEX Telephone
	LEICHT WILLIAM S	NYNEX Telephone
	LETTS K	NYNEX Telephone
	SUTTA JANET	NYNEX Telephone
	WOHLBERG BEN F	NYNEX Telephone
1983	BRANDT HELENE	New York Telephone
	FROMBOLUTI I	New York Telephone
	GREENE ART ASSOC	New York Telephone
	KACERE J	New York Telephone
	LEICHT WILLIAM S	New York Telephone
	LEICHT WILLIAM S	New York Telephone
	LETTS K	New York Telephone
	SUTTA JANET	New York Telephone
	SUTTA JANET	New York Telephone
	WOHLBERG BEN F	New York Telephone
1978	GARREN E	New York Telephone
	MIGLIORELLI GEORGE	New York Telephone
	REHL R	New York Telephone
	SIRAISI N	New York Telephone
	WOHLBERG BEN F	New York Telephone
1963	BORCHARDT OTTO IMPTRS	New York Telephone
	MILTENBERG E INC IMPTRS EXPTRS	New York Telephone

FINDINGS

Year	Uses	Source
1963	RIE PAUL A SHELLS	New York Telephone
1958	MILTENBERG E INC LMPTRS EXPTRS	New York Telephone
	RIE PAUL A SHELLS	New York Telephone
	SCHWABE ERWIN B	New York Telephone
1956	MILTENBERG E INC IMPTRS EXPTRS	New York Telephone
	SCHWABE ERWIN B	New York Telephone
1950	MILTENBERG E INC IMPTS EXPTS	New York Telephone
	SCHWABE ERWIN B	New York Telephone
1947	SCHWABE ERWIN B	New York Telephone
	MILTENBERG E INC IMPTRS	New York Telephone
1942	MILTENBERG E INC IMPTRS	New York Telephone
	SCHWABE ERWIN B	New York Telephone
1938	MILTENBERG E INC IMPTRA	New York Telephone
1934	Hanseatic Cane Works Karl Husselravh chair cane	R. L. Polk & Co.
	Marquart H E sec E Miltenberg Inc	R. L. Polk & Co.
	Miltenberg E Inc NY cap $500 000 Emil Miltenberg pres H E Marquart sec Robt E Nelson treas imptrs	R. L. Polk & Co.
	Miltenberg Emil pres E Miltenberg Inc	R. L. Polk & Co.
	Nelson Robt E treas E Miltenberg Inc	R. L. Polk & Co.
	Raw Material Trading Co Inc NY Karl Husselrath pres treas importers	R. L. Polk & Co.
1927	Spice dept	New York Telephone
	Miltenberg E Inc imprtrs	New York Telephone
	Warehouse	New York Telephone
	Miltenberg E Inc imprtrs	New York Telephone
	MILTENBERG E INC IMPRTRS	New York Telephone
	MILTENBERG E INC IMPRTRS	New York Telephone
	MILTENBERG E INC IMPRTRS	New York Telephone
	Miltenberg E Inc imprtrs	New York Telephone

45 GREAT JONES

Year	Uses	Source
1998	GREAT JONES LUMBR CORP	NYNEX Telephone
1983	Rosenzweig I rl est	New York Telephone
	GREAT JONES LUMBER CORP	New York Telephone
	ROSENZWEIG I RL EST	New York Telephone
1978	ROSENZWEIG I RL EST	New York Telephone
1973	ROSENZWEIG I RLEST	New York Telephone

Year	Uses	Source
1968	GREAT JONES LUMBR CORA	New York Telephone
1963	GREAT JONES LUMBR CORP	New York Telephone
	ROSENZWEIG I RL EST	New York Telephone
1958	GREAT JONES LUMNBR CORP	New York Telephone
	ROSENZWEIG I RL EST	New York Telephone
1956	GREAT JONES LUMBR CO INC	New York Telephone
	ROSENZWEIG I RL EST	New York Telephone
1950	GREAT JONES LUMBR CO INC	New York Telephone
	ROSENZWEIG I RLEST	New York Telephone
1947	GREAT JONES LUMBR CO INC	New York Telephone
1942	GREAT JONES LUMBR CO INC	New York Telephone
1938	GREAT JONES LUMBR CO INC	New York Telephone
1934	Fisher Louis Louis Fisher & Co	R. L. Polk & Co.
	Fisher Louis & Co Louis Fisher off partitions	R. L. Polk & Co.
	Goldman Herman sec treas Rosenzweig Lumber Co Inc	R. L. Polk & Co.
1927	Rosenzweig I lumber	New York Telephone
	ROSENZWEIG I LUMBER	New York Telephone
1923	Rosenzweig Lumber Co RTN Isaac Rosenzweig	R. L. Polk & Co.
1920	Rosenzweig & Elson Isaac Rosenzweig Isaac Elson lumber	R. L. Polk & Co.

47 GREAT JONES

Year	Uses	Source
1998	INTERNATIONAL THEATRE INST OF THE US	NYNEX Telephone
	NEW FESTIVAL THE	NYNEX Telephone
	PAN ASIAN REPERTORY THEATRE	NYNEX Telephone
	TRINITY/LAMAMA PERFORMING ARTS PROGRAM THE	NYNEX Telephone
1993	PAN ASIAN REPERTORY THEATRE	NYNEX Telephone
1988	DIAMOND ROYALS LOUISE	NYNEX Telephone
	FELDMAN FLOYD E	NYNEX Telephone
	KAPELL MARTIN H	NYNEX Telephone
	PAN ASIAN REPERTORY THEARTE OFC	NYNEX Telephone
	ROYALS DEMETRIA	NYNEX Telephone
1983	GOOD OLD LOWER EAST SIDE INC	New York Telephone
	LA MAMA EXPERIMENTAL THEATRE-CETA	New York Telephone

FINDINGS

Year	Uses	Source
1983	PAN ASIAN REPERTORY THEATRE INC	New York Telephone
	PAN ASIAN REPERTORY THEATRE INC	New York Telephone
	YACOUBI AHMED	New York Telephone
1978	FORD WIL	New York Telephone
	YACOUBI AHMED	New York Telephone
1973	BATES A K	New York Telephone
	ROACH TOM	New York Telephone
	SAV-MORE SLIGHTLY USED CORRUGATED BOX CO INC	New York Telephone
	YACOUBI AHMED	New York Telephone
1968	ROZBERN KINITG MILLS INC	New York Telephone
1963	BRABANT NEEDLE CO INC	New York Telephone
	BROWN PAPER CO INC	New York Telephone
	ROBERN KNITG MILLS INC	New York Telephone
	STYLEBEST KNITG MILLS INC FCTY	New York Telephone
1958	ART CRAFT LEATHER GOODS	New York Telephone
	BRABANT NEEDLE CO INC	New York Telephone
	BROWN PAPER C0 INC	New York Telephone
	CLAUDIA HATS INC	New York Telephone
	STYLEBEST KNITTING MILLS INC	New York Telephone
1956	ART CRAFT LEATHER GOODS	New York Telephone
	BRABANT NEEDLE CO INC	New York Telephone
	BROWN PAPER CO INC	New York Telephone
	ROZBERN KNITTING MILLS INC	New York Telephone
	STYLEBEST KNITTING MILLS INC	New York Telephone
1950	ALLIED LOOSE LEAF CORP	New York Telephone
	BRABANT NEEDLE CO INC	New York Telephone
	CHRIS CRAFT ENGINE SVCE	New York Telephone
	COLUIBIAN BRASS FOUNDRY	New York Telephone
	DECKER LEATHER PRODS CO	New York Telephone
	SALES PRESENTATIONS INC	New York Telephone
	STYLEMASTER LEATHERCRAFT CORP	New York Telephone
	STYLEMASTER LEATHERCRAFT CORP	New York Telephone
	SUTTER BROS MFRS AGRS	New York Telephone
1947	SALES PRESENTATIONS INC	New York Telephone
	SUTTER BROS MFRS AGTS	New York Telephone
	ALLIED LOOSE LEAF CORP	New York Telephone
	BRABANT NEEDLE CO	New York Telephone
	COLUMBIAN BRASS FOUNDRY	New York Telephone

FINDINGS

Year	Uses	Source
1947	DECKER LEATHER PRODS CO	New York Telephone
	HOLLY CARBURETOR SALES & SVCE	New York Telephone
1942	ALLIED LOOSE LEAF CORP	New York Telephone
	BRABANT NEEDLE CO	New York Telephone
	CHRYSLER MARINE SALES & SVCE	New York Telephone
	COLUMBIAN BRASS FOUNDRY	New York Telephone
	HOLLY CARBURETOR SALES & SVCE	New York Telephone
	SALES PRESENTATIONS INC	New York Telephone
	SOIFER MEYER VESTS	New York Telephone
	SUTTER BROS MFRSAGTS	New York Telephone
1938	ALLIED LOOSE LEAF CORP	New York Telephone
	BRABANT NEEDLE CO	New York Telephone
	CHRYSLER MARINE SALES & SVCE	New York Telephone
	COLUMBIAN BRASS FOUNDRY	New York Telephone
	HOLLY CARBURETOR SALES & SVCE	New York Telephone
	MURAUNSKI JOHN F B	New York Telephone
	NAPOLI & SOIFER VESTS	New York Telephone
	SOIFER & NAPOLI CO VESTS	New York Telephone
	SUTTER BROS MFRS AGTS	New York Telephone
1934	Chrysler Marine Sales and Service Suttor Bros reps	R. L. Polk & Co.
	Columbian Brass Foundry of NY TN John A and Alphonse Sutter	R. L. Polk & Co.
	Holly Carburetor Sales Service Detroit Mich Sutter Bros NY mgrs	R. L. Polk & Co.
	Innovation Novelty Co RTN Hyman Mendel	R. L. Polk & Co.
1927	Rosenblatt Max trimgs	New York Telephone
	United Passementery Factory	New York Telephone
	Utility Printing Co	New York Telephone
	Wolfson & Shapiro wsale grocers	New York Telephone
	ROSENBLATT MAX TRIMGS	New York Telephone
	UNITED PASSEMENTERY FACTORY	New York Telephone
	UTILITY PRINTING CO	New York Telephone
	WOLFSON & SHAPIRO WSALE GROCERS	New York Telephone
1923	Brabant Needle Co Inc NY Alf Brabant pres Jas R Brabant treas	R. L. Polk & Co.
	Brabant Wm clk L F Rothchild & Co h Woodhaven BQ	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1923	Brabec Anton Doubrava & Brabec Flush BQ	R. L. Polk & Co.
	Insted Leather Co RTN Carrie Scheuer	R. L. Polk & Co.
	Processed Leather Co RTN Carrie Scheuer	R. L. Polk & Co.
	Rosenblatt Max trimmings	R. L. Polk & Co.
	Shapiro Louis Wolfson & Shapiro	R. L. Polk & Co.
	United Passementery Co RTN Max Rosenblatt trimmings	R. L. Polk & Co.
	Wolfson & Shapiro Barnett Wolfson Louis Shapiro Whol gros	R. L. Polk & Co.
	Wolpiro Realty Co Inc	R. L. Polk & Co.
1920	Elish A paper	R. L. Polk & Co.
	Insted Leather Co RTN inf unobtainable	R. L. Polk & Co.
	Wolfson & shapiro Bernett Wolfson Louis Shapiro whol gro	R. L. Polk & Co.

GREAT JONES %

29 GREAT JONES %

Year	Uses	Source
1923	ELLENWOOD & DOYLE INC NY J Raymond Ellenwood Pres Treas J Marvin Doyle V Pres Guy Carr Sec Sheet Metal Tin Plate	R. L. Polk & Co.
1920	ELLENWOOD & DOYLE INC NY J Raymond Ellenwood Pres Treas J Marvin Doyle V Pres Guy C Carr sec Sheet Metal Tin Plate	R. L. Polk & Co.

47 GREAT JONES %

Year	Uses	Source
1920	BERGER MATTHEW M Proprietor McKenna & Phelps Paper Label and Die Cutting Calendar and Novelty Mfg Roll Paper Splitting	R. L. Polk & Co.
	ELISH H M & Co Harry M Elish Paper Mfrs and Dealers	R. L. Polk & Co.
	BRABANT NEEDLE CO NY Alfred Brabant Pres Augustus F Brabant V P Jas R Brabant Sec Treas Needle Mfrs and Needle Books	R. L. Polk & Co.

FINDINGS

Great Jones St

4 Great Jones St

Year	Uses	Source
2014	BOSS PROPERTY ADVISORS LLC	EDR Digital Archive
	BOSS PROPERTY ADVISORS LLC	EDR Digital Archive
2010	BOSS PROPERTY ADVISORS LLC	EDR Digital Archive
	CERITIFIED PROPERTY DATA SVCS	EDR Digital Archive
	BOSS PROPERTY ADVISORS LLC	EDR Digital Archive
	CERITIFIED PROPERTY DATA SVCS	EDR Digital Archive

GREAT JONES ST

4 GREAT JONES ST

Year	Uses	Source
2006	h Bogawa Roddy	Hill-Donnelly Information Services
	Beery Itzhak	Hill-Donnelly Information Services
	Goldman/taylor Entertainment	Hill-Donnelly Information Services
	Walsh A&J	Hill-Donnelly Information Services
	h Walsh Ann & James A	Hill-Donnelly Information Services
2000	APARTMENTS	Cole Information Services
1983	Beery Itzhak	New York Telephone
	Clayworks Studio Workshop Inc	New York Telephone
	Goldman Stuart A	New York Telephone
	Goldman Stuart A b	New York Telephone
	Jurick S	New York Telephone
	Leveson Kenneth	New York Telephone
	Multi Media Masters	New York Telephone
	NY Experimental Glass Workshop	New York Telephone
	Peterson Susan	New York Telephone
	Publication Arts Workshop	New York Telephone
	Shestack M B	New York Telephone

Great Jones St

5 Great Jones St

Year	Uses	Source
2014	ALPERT NEWSPAPER DELIVERY SVC	EDR Digital Archive
	GREAT JONES LUMBER CORP	EDR Digital Archive
	ALPERT NEWSPAPER DELIVERY SVC	EDR Digital Archive

Year	Uses	Source
2014	GREAT JONES LUMBER CORP	EDR Digital Archive
2010	GREAT JONES LUMBER CORP	EDR Digital Archive
	ALPERT NEWSPAPER DELIVERY SVC	EDR Digital Archive
	HILOFILMS INC	EDR Digital Archive
	STEIN DAVID	EDR Digital Archive
	GREAT JONES LUMBER CORP	EDR Digital Archive
	ALPERT NEWSPAPER DELIVERY SVC	EDR Digital Archive
	HILOFILMS INC	EDR Digital Archive
	STEIN DAVID	EDR Digital Archive

7 Great Jones St

Year	Uses	Source
2014	DIANE KOLYER PRODUCTIONS	EDR Digital Archive
	DESIGNS BY SEVESTET LTD	EDR Digital Archive
	DIANE KOLYER PRODUCTIONS	EDR Digital Archive
	CFA MANAGEMENT	EDR Digital Archive
	DANIEL S HL PHD PSYCHOLOGY PC	EDR Digital Archive
	DESIGNS BY SEVESTET LTD	EDR Digital Archive
	CFA MANAGEMENT	EDR Digital Archive
	DANIEL S HL PHD PSYCHOLOGY PC	EDR Digital Archive
2010	DANIEL S HL PHD PSYCHOLOGY PC	EDR Digital Archive
	CFA MANAGEMENT	EDR Digital Archive
	DESIGNS BY SEVESTET LTD	EDR Digital Archive
	DANIEL S HL PHD PSYCHOLOGY PC	EDR Digital Archive
	CFA MANAGEMENT	EDR Digital Archive
	DIANE KOLYER PRODUCTIONS	EDR Digital Archive
	DESIGNS BY SEVESTET LTD	EDR Digital Archive
	DIANE KOLYER PRODUCTIONS	EDR Digital Archive

GREAT JONES ST

8 GREAT JONES ST

Year	Uses	Source
2000	PHIL ABRAHAM	Cole Information Services
	VILLAGE COMPUTERS	Cole Information Services
	JUDIT GERRARD	Cole Information Services
	BRIAN GLASSER	Cole Information Services
	DIANE KOLYER	Cole Information Services
	PRAWAT LAUCHAROEN	Cole Information Services

Year	Uses	Source
2000	C LEE	Cole Information Services
	104 C MAXWELL	Cole Information Services
	J MEINICK	Cole Information Services
	2 DAVID NICHTEM	Cole Information Services
	DAN STRAW	Cole Information Services
	3 ROBERT TAN	Cole Information Services
	COMPUTER VILLAGE	Cole Information Services
	COMPUTERS	Cole Information Services
	COMPUTRS	Cole Information Services
	L COPEN	Cole Information Services

Great Jones St

9 Great Jones St

Year	Uses	Source
2014	ACE OF CLUBS	EDR Digital Archive
	COVEY DESIGNS	EDR Digital Archive
	VICTORIA KEEN DESIGN INC	EDR Digital Archive
	COVEY DESIGNS	EDR Digital Archive
	VICTORIA KEEN DESIGN INC	EDR Digital Archive
	ACE OF CLUBS	EDR Digital Archive
2010	COVEY DESIGNS	EDR Digital Archive
	MOTOR ROOM RECORDS	EDR Digital Archive
	ACE OF CLUBS	EDR Digital Archive
	9 G J BAR & RESTAURANT INC	EDR Digital Archive
	ACE OF CLUBS	EDR Digital Archive
	9 G J BAR & RESTAURANT INC	EDR Digital Archive
	COVEY DESIGNS	EDR Digital Archive
	MOTOR ROOM RECORDS	EDR Digital Archive

GREAT JONES ST

9 GREAT JONES ST

Year	Uses	Source
2006	Ace Of Clubs 28 a	Hill-Donnelly Information Services
	Murray James	Hill-Donnelly Information Services
	Murray James H AA es	Hill-Donnelly Information Services
	Roliton Limited IO	Hill-Donnelly Information Services
	h Tobias 3ulius Aa	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2006	h Covey Elizabeth Aa	Hill-Donnelly Information Services
2000	6 ELIZABETH COVEY	Cole Information Services
	HELEN T DALY	Cole Information Services
	2 JAMES H MURRAY	Cole Information Services
	5 JULIUS TOBIAS	Cole Information Services
	TAKAKO TSUJI T	Cole Information Services
	ACME BAR & GRILL	Cole Information Services
	J H MURRAY CORP	Cole Information Services
	ROLITON LTD	Cole Information Services
	SAR CONSTR CORP	Cole Information Services
1983	Ben Yuter Co Inc	New York Telephone
	Covey Shan	New York Telephone
	Jordan Coml Refrigerator Co	New York Telephone
	Tobias Julias	New York Telephone
	Yuter Ben Co Inc	New York Telephone
1927	K & S Hat & Cap Co	New York Telephone

Great Jones St

11 Great Jones St

Year	Uses	Source
2010	G K AUTO MOTOR	EDR Digital Archive
	ZP AUTO INC	EDR Digital Archive
	G K AUTO MOTOR	EDR Digital Archive
	ZP AUTO INC	EDR Digital Archive

GREAT JONES ST

11 GREAT JONES ST

Year	Uses	Source
2006	Z P Auto Inc I s	Hill-Donnelly Information Services

23 GREAT JONES ST

Year	Uses	Source
1927	Regal Cap Co	New York Telephone

25 GREAT JONES ST

Year	Uses	Source
1983	Leathercrafters Supl Co Div Of Roni Industries Inc	New York Telephone

Year	Uses	Source
1983	Horowitz Charles & Sons Inc	New York Telephone
	Davey S Robert b	New York Telephone
	Roni Industries Inc	New York Telephone

Great Jones St

27 Great Jones St

Year	Uses	Source
2014	CETLL INC	EDR Digital Archive
	CETLL INC	EDR Digital Archive
2010	CETLL INC	EDR Digital Archive
	YOONKIDS INC	EDR Digital Archive
	CETLL INC	EDR Digital Archive
	YOONKIDS INC	EDR Digital Archive

GREAT JONES ST

27 GREAT JONES ST

Year	Uses	Source
2006	Number 5 W Boswell Frances	Hill-Donnelly Information Services
	Number 4 WYoon CD	Hill-Donnelly Information Services
	Number PH H Stewart S R A	Hill-Donnelly Information Services
	Number 4 E H Smith William C	Hill-Donnelly Information Services
	Number 3 E H Quint J E	Hill-Donnelly Information Services
	Number 2 E H Houtenbos Rob B v	Hill-Donnelly Information Services
	Number 5 E h Eitel Mitchell	Hill-Donnelly Information Services
	Number 3 W H Cullman E	Hill-Donnelly Information Services
	Chase Jenny oo	Hill-Donnelly Information Services
	Multi Unit Address	Hill-Donnelly Information Services
2000	J E LVN BLDR INC	Cole Information Services
1927	Seneca Folding Paper Box Co	New York Telephone

Great Jones St

29 Great Jones St

Year	Uses	Source
2014	BARBARA MICHELLE JACOBS	EDR Digital Archive
	GREAT JONES SPA LLC	EDR Digital Archive
	BARBARA MICHELLE JACOBS	EDR Digital Archive
	GREAT JONES SPA LLC	EDR Digital Archive

Year	Uses	Source
2010	GREAT JONES SPA LLC	EDR Digital Archive
	GREAT JONES SPA LLC	EDR Digital Archive

GREAT JONES ST

29 GREAT JONES ST

Year	Uses	Source
2006	Great Jones Spa 2s	Hill-Donnelly Information Services
2000	GREAT JONES SPA	Cole Information Services
1927	Natl Doll Outfit & Infants Wear Co	New York Telephone

Great Jones St

31 Great Jones St

Year	Uses	Source
2014	SWEENEY & CONROY INC	EDR Digital Archive
	SWEENEY CONSTRUCTION INC	EDR Digital Archive
	FIVE POINTS RESTAURANT	EDR Digital Archive
	SWEENEY & CONROY INC	EDR Digital Archive
	SWEENEY CONSTRUCTION INC	EDR Digital Archive
	FIVE POINTS RESTAURANT	EDR Digital Archive
2010	FIVE POINTS RESTAURANT	EDR Digital Archive
	GREAT JONES ST REALTY CORP	EDR Digital Archive
	SWEENEY & CONROY INC	EDR Digital Archive
	SWEENEY CONSTRUCTION INC	EDR Digital Archive
	FIVE POINTS RESTAURANT	EDR Digital Archive
	GREAT JONES ST REALTY CORP	EDR Digital Archive
	SWEENEY & CONROY INC	EDR Digital Archive
	SWEENEY CONSTRUCTION INC	EDR Digital Archive

GREAT JONES ST

31 GREAT JONES ST

Year	Uses	Source
2006	Sweeney Construction Inc	Hill-Donnelly Information Services
	Five Points Restaurant 2 R oo	Hill-Donnelly Information Services
	h Charlesworth S	Hill-Donnelly Information Services
2000	VICTORIA FREEMAN	Cole Information Services
	SWEENAY CONST INC	Cole Information Services
	OX CART STUDIO	Cole Information Services

Year	Uses	Source
2000	FIVE POINTS	Cole Information Services
1983	Hunt Bryan	New York Telephone
	Ciarlo Franco	New York Telephone

33 GREAT JONES ST

Year	Uses	Source
2014	TRINITY ENTERPRISES INC	EDR Digital Archive
2010	TRINITY ENTERPRISES INC	EDR Digital Archive
2006	Trinine Enterprises	Hill-Donnelly Information Services
2000	TRINITY ENTRPRSS	Cole Information Services
1983	Scott Truckg Co	New York Telephone

34 GREAT JONES ST

Year	Uses	Source
1927	Adjustable Enginerrs Cap Corp	New York Telephone

35 GREAT JONES ST

Year	Uses	Source
2006	Locam	Hill-Donnelly Information Services
	Locam	Hill-Donnelly Information Services
	Takamichi Salon 15s	Hill-Donnelly Information Services
2000	FL MICHAEL BONT	Cole Information Services
	6 C NIELSON	Cole Information Services
	CEDES INC	Cole Information Services
	LOCAM	Cole Information Services
	LOCAM	Cole Information Services
1983	Christopher I M	New York Telephone
	Daniel L E	New York Telephone
	Frolick Specialties	New York Telephone
	Kirwan Peter	New York Telephone
	Nielsen C	New York Telephone
	Noble Terry	New York Telephone

38 GREAT JONES ST

Year	Uses	Source
1927	Artcraft Belt Co	New York Telephone

39 GREAT JONES ST

Year	Uses	Source
2006	Multi Unit Address	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2006	Cazzaniga Luigi	Hill-Donnelly Information Services
	H Connors Michael	Hill-Donnelly Information Services
	Klalnberg Adolf	Hill-Donnelly Information Services
	Number 4 h Klainberg Adolf A	Hill-Donnelly Information Services
	Klainberg Adolf	Hill-Donnelly Information Services
	Number 2 Latham Mike v A	Hill-Donnelly Information Services
	Number 7 h Mcalpin Loring	Hill-Donnelly Information Services
	h Monte Elise A	Hill-Donnelly Information Services
	Number 6 Tibell Lena	Hill-Donnelly Information Services
2000	APARTMENTS	Cole Information Services
	5 LUIGI CAZZANIGA	Cole Information Services
	MICHAEL CONNORS	Cole Information Services
	MERYL EMMERTON	Cole Information Services
	MAXINE HENRYSON	Cole Information Services
	A KLAINBERG	Cole Information Services
	ADOLF KLAINBERG	Cole Information Services
	LORING MC ALPIN H	Cole Information Services
	A3 ELISA MONTE	Cole Information Services
	PAUL SPARKS	Cole Information Services
	D ALDERSON	Cole Information Services
1983	Alderson D	New York Telephone
	Hansen Stephen	New York Telephone
	Klainberg Adolf	New York Telephone
	Monte Elisa	New York Telephone
	Perna Thomas	New York Telephone
	Wildman E	New York Telephone
1927	Zagor David L mill ends	New York Telephone

40 GREAT JONES ST

Year	Uses	Source
2006	Multi Unit Address	Hill-Donnelly Information Services
	h Bonino Fernanda a	Hill-Donnelly Information Services
	h Childs C F A	Hill-Donnelly Information Services
	Ellen Caroline 10 o	Hill-Donnelly Information Services
	Ellen Caroline A	Hill-Donnelly Information Services
	Number 6 h Finneran Kathleen Young & Wil	Hill-Donnelly Information Services
	Number 4 Homans John	Hill-Donnelly Information Services
	Number 3 Lande Jerome VA	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2006	Number 7 Manhattan Model Shop	Hill-Donnelly Information Services
	Number 1 Studio 40 1 P	Hill-Donnelly Information Services
2000	C F CHILDS	Cole Information Services
	A4 A BRITZMAN	Cole Information Services
	A4 JOHN HOMANS	Cole Information Services
	ELLEN CAROLINE	Cole Information Services
	FINNERAN KTHLN YNG	Cole Information Services
	FINNERAN WILLIAM J	Cole Information Services
	MANHATTAN MDL SHP	Cole Information Services
	STUDIO INC	Cole Information Services
1983	Tumsuden R	New York Telephone
	Childs C F	New York Telephone
	Cunningham Bruce	New York Telephone
	Finneran Kathleen Young	New York Telephone
	Finneran William J	New York Telephone
	Manhattan Express Bicycle Shop	New York Telephone
	MANHATTAN MODEL SHOP	New York Telephone
	Miller Linda	New York Telephone
1927	Arkadia Paper Pruducts Corp	New York Telephone
	Crown Hat & Cap Co	New York Telephone

41 GREAT JONES ST

Year	Uses	Source
2014	OOTA INC	EDR Digital Archive
2010	OOTA INC	EDR Digital Archive
2006	Marie Saeki Public Relations	Hill-Donnelly Information Services
	Acme Sandblasting Co Inc	Hill-Donnelly Information Services
	Heidelberg Hillary VA	Hill-Donnelly Information Services
	MS Sales	Hill-Donnelly Information Services
2000	3 JAMES K MCCARTHY	Cole Information Services
	5FL STEVEN STEINMAN	Cole Information Services
	ACME SNDBLSTNG CO	Cole Information Services
	LEIGH KYLE	Cole Information Services
1983	Evstis O	New York Telephone
	Mc Carthy James K	New York Telephone
	Steinman Steven	New York Telephone
	Weston M	New York Telephone
1927	Weitzman A & Sons papers & twine	New York Telephone

FINDINGS

43 GREAT JONES ST

Year	Uses	Source
2006	h Brandt Helene A	Hill-Donnelly Information Services
	h Guattl Albano VA	Hill-Donnelly Information Services
	h Hamilton Peter a	Hill-Donnelly Information Services
	h Hoffman Peter	Hill-Donnelly Information Services
	Sharp C	Hill-Donnelly Information Services
	h Shiflett D E A	Hill-Donnelly Information Services
2000	APARTMENTS	Cole Information Services
	HELENE BRANDT	Cole Information Services
	MOSES CHAO	Cole Information Services
	4 PETER GREENE	Cole Information Services
	ALBANO GUATTI	Cole Information Services
	3 ALBANO GUATTI	Cole Information Services
	JOHN KACERE	Cole Information Services
	ANDREW KEATING	Cole Information Services
	D E SHIFLETT	Cole Information Services
	JANET SUTTA	Cole Information Services
1983	Brandt Helene	New York Telephone
	Fromboluti I	New York Telephone
	Greene Art Assoc	New York Telephone
	Kacere J	New York Telephone
	Leicht William S	New York Telephone
	Leicht William S	New York Telephone
	Letts K	New York Telephone
	Sutta Janet	New York Telephone
	Sutta Janet	New York Telephone
	Wohlberg Ben F	New York Telephone

45 GREAT JONES ST

Year	Uses	Source
2006	Great Jones Lumber Corp	Hill-Donnelly Information Services
2000	GREAT JNS LMBR CRP	Cole Information Services
1983	Great Jones Lumber Corp	New York Telephone

47 GREAT JONES ST

Year	Uses	Source
2006	Ping Chong & Co is	Hill-Donnelly Information Services
	h Schellenbaum Tim VA	Hill-Donnelly Information Services
	h Ugurlu Zishan a	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2006	Milroy Mark v	Hill-Donnelly Information Services
	H Capoccia DA	Hill-Donnelly Information Services
2000	GENJI ITO	Cole Information Services
	TIM SCHELLENBAUM	Cole Information Services
	ZISHAN UGURLU	Cole Information Services
	DAVID GRDN PCK UP	Cole Information Services
	INTRNTNL THTR INST	Cole Information Services
	THE NEW FESTIVAL	Cole Information Services
	PON ASIAN RPRTRY	Cole Information Services
	PICK UP PERFORM	Cole Information Services
	PING CHONG & CO	Cole Information Services
	THE TRINITY/LMM	Cole Information Services
1983	Good Old Lower East Side Inc	New York Telephone
	La Mama Experimental Theatre Ceta	New York Telephone
	Pan Asian Repertory Theatre Inc	New York Telephone
	Pan Asian Repertory Theatre Inc	New York Telephone
	Yacoubi Ahmed	New York Telephone

GREAT JONES ST APT 2

41 GREAT JONES ST APT 2

Year	Uses	Source
2014	ANDREW BERNSTEIN INC	EDR Digital Archive
	JENNY CHASE INC	EDR Digital Archive
2010	JENNY CHASE INC	EDR Digital Archive
	ANDREW BERNSTEIN INC	EDR Digital Archive
	MARIE SAEKI PUBLIC RELATIONS	EDR Digital Archive

GREAT JONES ST APT 3

41 GREAT JONES ST APT 3

Year	Uses	Source
2014	ARNOLD S WARWICK & CO LTD	EDR Digital Archive
2010	TRACE INC	EDR Digital Archive
	ACME SANDBLASTING CO INC	EDR Digital Archive

FINDINGS

GREAT JONES ST APT 4

41 GREAT JONES ST APT 4

Year	Uses	Source
2014	DOGFISH PICTURES LLC	EDR Digital Archive

GREAT JONES ST APT 5

41 GREAT JONES ST APT 5

Year	Uses	Source
2014	GOAT BARN PRODUCTIONS	EDR Digital Archive
	ACROSS BRIDGE LLC	EDR Digital Archive

GREAT JONES ST FRNT 1

41 GREAT JONES ST FRNT 1

Year	Uses	Source
2014	PRINCE TOWER TENANTS CORP	EDR Digital Archive

Great Jones Street

33 Great Jones Street

Year	Uses	Source
2006	Trinine Enterprises	Hill-Donnelly Information Services
2000	TRINITY ENTRPRSS	Cole Information Services
1998	SCOTT JOS TRUCKING CORP	NYNEX Telephone
1993	SCOTT JOS TRUCKING CORP	NYNEX Telephone
1988	SCOTT TRUCKG CO	NYNEX Telephone
1983	SCOTT TRUCKG CO	New York Telephone
	Scott Truckg Co	New York Telephone
1978	SCOTT TRUCKG CO	New York Telephone
1968	LOSACK TRUCKING GO	New York Telephone
1963	LOSACK TRUCKING CO	New York Telephone
1958	LOSACK TRUCKING CO	New York Telephone
1956	GEORGE S TRUCKING OFC	New York Telephone
	GEORGE S TRUCKING OFC	New York Telephone
1950	GEORGE S TRUCKING	New York Telephone
1947	MS FORWARDING CORP OFC	New York Telephone
1942	JOE S AUTO REPAIR SVCE	New York Telephone
	STOPPIELLO FANNY TRUKNG	New York Telephone
1938	MONROE MOVING VAN CO	New York Telephone

FINDINGS

Year	Uses	Source
1938	DURABLE AUTO TRUCKING CO	New York Telephone
	JIMMY S MOTOR SVCE	New York Telephone
	STOPPIELLO FANNY TRUKNG	New York Telephone
1934	Joes Auto Repair Jos Reizman	R. L. Polk & Co.
1923	Progressive Leather Sweets Co RTN Jack Nish	R. L. Polk & Co.

41 Great Jones Street

Year	Uses	Source
2006	Acme Sandblasting Co Inc	Hill-Donnelly Information Services
	Heidelberg Hillary VA	Hill-Donnelly Information Services
	MS Sales	Hill-Donnelly Information Services
	Marie Saeki Public Relations	Hill-Donnelly Information Services
2000	LEIGH KYLE	Cole Information Services
	3 JAMES K MCCARTHY	Cole Information Services
	5FL STEVEN STEINMAN	Cole Information Services
	ACME SNDBLSTNG CO	Cole Information Services
1998	DIMENSIONS IN GLASS LTD	NYNEX Telephone
	PULVERMACHER R DESIGNS INC	NYNEX Telephone
	RANDI JAY	NYNEX Telephone
1993	DIMENSIONS IN GLASS LTD	NYNEX Telephone
	PULVERMACHER R DESIGNS INC	NYNEX Telephone
	RANDI JAY	NYNEX Telephone
1988	PULVERMACHER R DESIGNS INC	NYNEX Telephone
	STEINMAN STEVEN	NYNEX Telephone
	RANDI JAY	NYNEX Telephone
	DIMENSIONS IN GLASS LTD	NYNEX Telephone
	KYLE LEIGH	NYNEX Telephone
	MCCARTHY JAMES K	NYNEX Telephone
1983	Filco Mfg Co lihr	New York Telephone
	Weston M	New York Telephone
	Evstis O	New York Telephone
	Mc Carthy James K	New York Telephone
	Steinman Steven	New York Telephone
	MC CARTHY JAMES K	New York Telephone
	WESTON M	New York Telephone
	EVSTIS O	New York Telephone
	FILCO MFG CO LIHR	New York Telephone
	STEINMAN STEVEN	New York Telephone

FINDINGS

Year	Uses	Source
1978	KOBLAND K	New York Telephone
	WANNER D	New York Telephone
	BURGESS PAMELA	New York Telephone
	WESTON M	New York Telephone
	EVSTIS O	New York Telephone
	CAMPBELL N	New York Telephone
	MCCARTHY J	New York Telephone
1973	NATHANIEL CHITTAMS CUSTOM INTRS	New York Telephone
	SPROTE EOIN	New York Telephone
	CHITTAMS NATHANIEL B	New York Telephone
	KAISER ROBERT	New York Telephone
1968	ACME SANDBLASTING COLNC	New York Telephone
	GOLDBERG BEN TRIMNGS	New York Telephone
1963	TAINERS	New York Telephone
	GOLDBERG BEN TRIMNGS	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
	ACME SANDBLASTING CO INC	New York Telephone
1958	ACME SANDBLASTING CO INC	New York Telephone
	ORIGINAL HEADWR CO	New York Telephone
	LUCID CONTAINERS	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
	GOLDBERG BEN TRIMINGS	New York Telephone
1956	GOLDBERG BEN TRIMNGS	New York Telephone
	REVERE METAL ART CO INC	New York Telephone
	QUICK LITE CO	New York Telephone
	CONCORD PEN CO INC	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
	SURE-FIRE PENCIL CO INC	New York Telephone
	CONCORD METAL ART CO	New York Telephone
1950	LEINWAND WM HRDWR	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
	GOLDBERG BEN TRNINGS	New York Telephone
	MAZZE IMPORT & EXPORT CO	New York Telephone
	PROGRESSIVE LEATHER SWEATS CO	New York Telephone
1947	LOUMAC COATED FABRICS CO	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
	S & M LEATHER GOODS CO HNDBGS	New York Telephone
	GOLDBERG BEN TRIMNGS	New York Telephone

FINDINGS

Year	Uses	Source
1947	PROESSIVE LEATHER SWEATS CO	New York Telephone
	SELTZER BROS FURS	New York Telephone
	CONCORD METAL ART CO	New York Telephone
	LILLING ABRAHAM B	New York Telephone
1942	METROPOLITN BASKET CO	New York Telephone
	TITENSKY A & SONS CAPS	New York Telephone
	AMER BABY WEAR CO	New York Telephone
	EIBSCHUTZ HYMAN BUTNS	New York Telephone
	FASHION SPECIALTY CO	New York Telephone
	PROGRESSIVE LEATHER SWEATS CO	New York Telephone
	METROPOLITN CASTER & WHEEL CO	New York Telephone
	GOLDBERG BEN TIMINGS	New York Telephone
	MADE RIGHT DOLL ACCESSOIES CO	New York Telephone
1938	METROPOLITN BASKET CO	New York Telephone
	METROPOLITN CASTES & WHEEL CO	New York Telephone
	COHN ARON BASKETS	New York Telephone
	BENGAL CAP CO	New York Telephone
	DECKER ALVIN NOVLTS	New York Telephone
	PARAMOUNT CAP WKS	New York Telephone
	TITENSKY ABRAHAM HATS & CAPS	New York Telephone
	EIBSCHUTZ HYMAN BUTTONS	New York Telephone
	PROGRESSIVE LEATHER SWEATERS CO	New York Telephone
	S K HAT CO	New York Telephone
1934	Metropolitan Basket Co RTN Aaron Cohn	R. L. Polk & Co.
	Metropolitan Caster & Wheel Co RTN Victor Cohn founders	R. L. Polk & Co.
	Goldstein Cap Co Inc NY cap $10 000 Hyman M Goldstein pres Jos Shakrefsky sec treas cap mfrs	R. L. Polk & Co.
	Schwartzsbard Harold Staple Cap Wks	R. L. Polk & Co.
1927	Weitzman A & Sons papers & twine	New York Telephone
	Progressive Leather Sweats Co	New York Telephone
	Titensky & Son hats caps	New York Telephone
	Paramount Cap Works	New York Telephone
	PARAMOUNT CAP WORKS	New York Telephone
	PROGRESSIVE LEATHER SWEATS CO	New York Telephone
	TITENSKY & SON HATS CAPS	New York Telephone
	WEITZMAN A & SONS PAPERS & TWINE	New York Telephone

Year	Uses	Source
1923	Clover Cloak & Suit Co Inc N Y Isidore Lerner pres Isidore Cohen v p cloaks & suits	R. L. Polk & Co.
	Cohen Isidore v p Clover Cloak & Suit Co Inc	R. L. Polk & Co.
	Exchange Towel Service Corp N Y Isaac Hirschler pres Win Coorer v p Wm Fuchus sec	R. L. Polk & Co.
	Ideal Hat Frame Co RTNIsador Milgraum Hat frames	R. L. Polk & Co.
	Schneider Benj vests	R. L. Polk & Co.
	Alaska Sales Co Inc N Y Harry Harris pres Leo Harrison treas furs	R. L. Polk & Co.
	Allen Wm hat mfr	R. L. Polk & Co.
	Fuchs Wm sec Exclusive Towel Service Corp	R. L. Polk & Co.
	Hookman Jacob caps	R. L. Polk & Co.
1920	Royal Cloak Co RTN Harry Meshorer Robt Foster	R. L. Polk & Co.
	Ideal Hat Frame Co RTN Isidor Milgraum	R. L. Polk & Co.
	Buras Jno L Alaska Fur & Trading Co	R. L. Polk & Co.
	Foster Robt Royal Cloak Co	R. L. Polk & Co.
	Harris Jacob Alaska Fur & Trading Co	R. L. Polk & Co.
	Meshorer Harry Royal Cloak Co	R. L. Polk & Co.
	Model Paper Box Co inc NY Saml Mutnick pres Isrel Solmanson sec treas	R. L. Polk & Co.

JONES

9 GT JONES

Year	Uses	Source
1950	GORDON IRVING ACCTNT	New York Telephone

4 GREAT JONES

Year	Uses	Source
1988	SHESTACK VICTORIA	NYNEX Telephone
1983	SHESTACK M B	New York Telephone

LAFAYETTE

363 LAFAYETTE

Year	Uses	Source
1998	THE SMALL FURNITURE STORE	NYNEX Telephone

FINDINGS

Year	Uses	Source
1993	THE SMALL FURNITURE STORE	NYNEX Telephone
1983	NICK & GEORGE	New York Telephone
	Post Bros Svce Stas Inc ofc	New York Telephone
1938	MORRIS GAS STAS	New York Telephone

368 LAFAYETTE

Year	Uses	Source
1927	SUPREME GAS STATION	New York Telephone

372 LAFAYETTE

Year	Uses	Source
1983	Noho Collision Corp	New York Telephone
	MEINEKE DISCOUNT MUFFLERS	New York Telephone

376 LAFAYETTE

Year	Uses	Source
1927	WOLFF A H GAS RADIATOR CO THE	New York Telephone
	SAUNDERS G W & CO WOOLENS	New York Telephone
	AMER GAS PRODUCTS CORP	New York Telephone

380 LAFAYETTE

Year	Uses	Source
1998	GENTIEU PENNY STUDIO	NYNEX Telephone
	GLYNN MICHAEL ARCHITECTS	NYNEX Telephone
	GORLIN ALEXANDER ARCHITECT	NYNEX Telephone
	HART JOHN	NYNEX Telephone
	HART SHARP ENTERTAINMENT	NYNEX Telephone
	JEFFERY FEINGOLD ARCHITECT	NYNEX Telephone
	JOHNSON TIM	NYNEX Telephone
	KILLER FILMS	NYNEX Telephone
	KILLER FILMS	NYNEX Telephone
	KUHL WOLFGANG DESIGN	NYNEX Telephone
	MARBLE ARCH DESIGNS INC	NYNEX Telephone
	MCCRUM & KORZILIUS ARCHITECTURE	NYNEX Telephone
	PIX PRODUCERS INC	NYNEX Telephone
	RHZ	NYNEX Telephone
	SELECT EQUITY	NYNEX Telephone
	STEINBERG CAROL J LAWYER	NYNEX Telephone
	STUDIO SOFLAID	NYNEX Telephone

FINDINGS

Year	*Uses*	*Source*
1998	TIME CAFE	NYNEX Telephone
	ART CRAFT WALLETS	NYNEX Telephone
	B LAB INC	NYNEX Telephone
	BARBARA VON SCHREIBER LTD	NYNEX Telephone
	BLOCKBUSTERS PRODUCTIONS	NYNEX Telephone
	CLOISTERS CONSTRUCTION CO	NYNEX Telephone
	DECONSTRUCTION	NYNEX Telephone
	FEZ	NYNEX Telephone
1993	BARBARA VON SCHREIBER LTD	NYNEX Telephone
	BELL AND BUCHANAN	NYNEX Telephone
	ELECTRO KINETICS PARTNERSHIP	NYNEX Telephone
	ESQ CAPADE INC	NYNEX Telephone
	GENTIEU PENNY STUDIO	NYNEX Telephone
	GORLIN ALEXANDER ARCHITECT	NYNEX Telephone
	JEFFREY FEINGOLD ARCHITECT	NYNEX Telephone
	KNOCKOUT INC	NYNEX Telephone
	LAFAYETTE BLUEPRINT	NYNEX Telephone
	MANOCO-VIOLA INCORPORATED	NYNEX Telephone
	MARC CHARBONNET	NYNEX Telephone
	MICHEAL GLYNN DESIGN ASSOCS	NYNEX Telephone
	OLIVER WILLIAMS STUDIO	NYNEX Telephone
	QUINA FONSECA HATS	NYNEX Telephone
	SOKOLOFF NIEL	NYNEX Telephone
	SWEENY WALTER DESIGN	NYNEX Telephone
	TIME CAFE	NYNEX Telephone
1983	HARROLD BARBARA	New York Telephone
	Advani Haresh	New York Telephone
	Art Craft Wallets Inc	New York Telephone
	Autowash Systems	New York Telephone
	Bournique & Watkinson engravrs	New York Telephone
	Car Wash Equip Co Of NY	New York Telephone
	Colin Cooke Studio	New York Telephone
	Cooke Colin	New York Telephone
	Cooke Vickie Emerson	New York Telephone
	Educational Alliance Program	New York Telephone
	EN SPACE TYPOGRAPHERS INC	New York Telephone
	Kinlon Indstries Inc	New York Telephone
	Thomas & Walters Inc	New York Telephone

Year	Uses	Source
1983	Watkinson & Bournique engravrs	New York Telephone
	Worth Dstrbtrs Inc	New York Telephone
1927	RO GO CLOTHING CO	New York Telephone

381 LAFAYETTE

Year	Uses	Source
1963	ST JOSEPH S UNION	New York Telephone
1958	ST JOSEPHS UNION	New York Telephone
1956	ST JOSEPH S UNION	New York Telephone
1950	ST JOSEPH S UNION	New York Telephone
1947	ST JOSEPH S UNION	New York Telephone
1942	ST JOSEPH S UNION	New York Telephone
1938	MISSION OF THE IMMACULATE VIRGIN	New York Telephone
	FITZPATRICK MALLICK J REV B	New York Telephone
	ST JOSEPH S UNION	New York Telephone
1931	FLYNN THOS F	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	MISSION OF THE IMMACULATE VIRGIN	New York Telephone
	ST JOSEPH S UNION	New York Telephone
1920	Sisters of St Francis	R. L. Polk & Co.

382 LAFAYETTE

Year	Uses	Source
1998	SCREAMING MIMI	NYNEX Telephone
	SCHUMER ARTEN	NYNEX Telephone
	RON CALDWEIL JEWELRY AT SCREAMING MIMI S	NYNEX Telephone
	ANDREWS BLDG CORP	NYNEX Telephone
	CONDOMINIUM CO	NYNEX Telephone
1993	SCHUMER ARLEN	NYNEX Telephone
	ANDREWS BLDG CORP	NYNEX Telephone
1983	Moldow Wm envelopes	New York Telephone
1927	COHN ATTLEE PRESS	New York Telephone
	SCHNEIDERMAN A PRNTR	New York Telephone
	SCHNEIDER PRESS	New York Telephone
	QUEEN HAT CO	New York Telephone
	MOTHGUARD LABORATORIES INC	New York Telephone
	METROPOLITAN PRESS	New York Telephone
1920	Smith H Frank Paper & Ink Publishing Co	R. L. Polk & Co.
	Saxon Trousers Co TN Harry Sacksman	R. L. Polk & Co.

383 LAFAYETTE

Year	*Uses*	*Source*
1998	446 REALTY ASSOCS	NYNEX Telephone
	GOTHAM PAPER CO INC	NYNEX Telephone
	GREG SPOTTS ENTERTAINMENT INC	NYNEX Telephone
	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
1993	CTM BROCHURE DISPLAY INC	NYNEX Telephone
	CITY IN THE POCKET	NYNEX Telephone
	CTM BROCHURE DISPLAY	NYNEX Telephone
	446 REALTY ASSOCS	NYNEX Telephone
	GOTHAM PAPER CO INC	NYNEX Telephone
	HOUSE CLOTHING	NYNEX Telephone
	JANETTE BECKMAN PHOTOGRAPHY	NYNEX Telephone
	PERLMAN DICK ASSOCS INC	NYNEX Telephone
	TOWER BOOKS	NYNEX Telephone
	TOWER RECORDS/VIDEO RECORDS	NYNEX Telephone
	CTM BROCHURE DISPLAY MANHATTAN	NYNEX Telephone
1983	Adding & Bkkeepg Mach Corp	New York Telephone
	ADDRESSING MACHINE EQUIP CO DIV OF I O A DATA CORP	New York Telephone
	I O A DATA CORP	New York Telephone
	I O A Leasing Div Of I O A Data Corp	New York Telephone
	INTERNATIONAL OFC APLNCS DIV OF I O A DATA CORP	New York Telephone
	International Ofc Apincs Inc	New York Telephone
	Pearls Of Majorca	New York Telephone
	Rubenstein Jos adrsg mache	New York Telephone
	Rubenstein Stuart	New York Telephone
	Rubinstein Stuart	New York Telephone

384 LAFAYETTE

Year	*Uses*	*Source*
1973	ELLBERGER MORRIS LUNCHNET	New York Telephone

388 LAFAYETTE

Year	*Uses*	*Source*
1983	Broadway Assocs	New York Telephone

389 LAFAYETTE

Year	Uses	Source
1942	PYRAMID PROCESS CO	New York Telephone
1938	PYRAMID PROCESS CO	New York Telephone
	HUBBS CHAS F & CO PAPER	New York Telephone
1934	Newell Edgar G treas Oberly & Newell	R. L. Polk & Co.
1927	HUBBS CHAS F & CO PAPER-	New York Telephone

392 LAFAYETTE

Year	Uses	Source
1927	HUSTWICK & STEVENS INC PRNTG & LITHOGRAPHING INKS	New York Telephone
	O BRIEN C J PRINTER	New York Telephone
1923	STEVENS J CRAWFORD Treas Coy Hunt & Co	R. L. Polk & Co.

393 LAFAYETTE

Year	Uses	Source
1998	ANTIQUARIAN TRADERS	NYNEX Telephone
1950	NAYLOR GEN M	New York Telephone
1947	NAYLOR GEO M B	New York Telephone
1942	NAYLOR GEO M B	New York Telephone
1938	NAYLOR GEO M B	New York Telephone
	FAIRBANKS CO THE VALVES DART UNIONS HAND TRUCKS F	New York Telephone
1927	NO LAFAYETTE ST BLDG	New York Telephone

395 LAFAYETTE

Year	Uses	Source
1927	CHAMPION FLEXIBLE GLUE CORP	New York Telephone

LAFAYETTE %

376 LAFAYETTE %

Year	Uses	Source
1920	BISHOP & BABCOCK CO THE Cleveland O Wm C Linehan Mgr Beer Pumps Oxy Cutting and Welding and Heating Specialties	R. L. Polk & Co.

FINDINGS

386 LAFAYETTE %

Year	Uses	Source
1923	HAVILAND SHADE ROLLER CO INC N Y Marston Haviland pres treas Frost Haviland V pres Frank Twyer fort sec Spring Shade Rollers	R. L. Polk & Co.

392 LAFAYETTE %

Year	Uses	Source
1923	RENOLDS IRA S V Pres Coy Hurt & Co	R. L. Polk & Co.
	COY HUNT & CO N Y G Alf Knoche Pres Ira S Renolds V Pres John W Edington Sec J Crawford Stevens Treas Twines Yarns Etc	R. L. Polk & Co.
1920	COY HUNT & CO INC NY Robert L Cone Pres Treas Hamilton T Disbrow V Pres G A Knoche Sec & Gen Mgr Cornelius Ostrander Asst Treas Paper Mtrs Dealers in Twines Yarns Etc	R. L. Polk & Co.

LAFAYETTE ST

363 LAFAYETTE ST

Year	Uses	Source
2000	THE SMALL FURN STR	Cole Information Services
1927	Morris Edw	New York Telephone
	Bond Street Gas & Oil Sta Inc	New York Telephone

368 LAFAYETTE ST

Year	Uses	Source
1927	Supreme Gas Station	New York Telephone

Lafayette St

372 Lafayette St

Year	Uses	Source
2010	LAFAYETTE MUFFLER INC	EDR Digital Archive
	MEINEKE CAR CARE CENTER	EDR Digital Archive
	LAFAYETTE MUFFLER INC	EDR Digital Archive
	MEINEKE CAR CARE CENTER	EDR Digital Archive

FINDINGS

LAFAYETTE ST

372 LAFAYETTE ST

Year	Uses	Source
2006	Meineke Car Care Ctr Is	Hill-Donnelly Information Services
2000	MEINEKE DISCOUNT	Cole Information Services
	Z P AUTO INC	Cole Information Services
	G K AUTO MOTORS	Cole Information Services

Lafayette St

376 Lafayette St

Year	Uses	Source
2010	SPACE INITIATIVES LLC	EDR Digital Archive
	SPACE INITIATIVES LLC	EDR Digital Archive

LAFAYETTE ST

376 LAFAYETTE ST

Year	Uses	Source
2006	378 No Current Listing	Hill-Donnelly Information Services
1927	Maine Mills Woolens Co	New York Telephone
	Amer Gas Products Corp	New York Telephone
	Saunders G W & Co woolens	New York Telephone
	Saffer Louis & Co clthg	New York Telephone
	Wolff A H Gas Radiator Co The	New York Telephone

Lafayette St

380 Lafayette St

Year	Uses	Source
2014	SCARSDALE PICTURES INC	EDR Digital Archive
	NATALIETOBIER	EDR Digital Archive
	S E G HOLDINGS LLC	EDR Digital Archive
	TERTE RACHEL	EDR Digital Archive
	NOHO HOSPITALITY LLC	EDR Digital Archive
	SEG PARTNERS LP	EDR Digital Archive
	LAFAYETTE STREET FUND II LP	EDR Digital Archive
	SEG PARTNERS II LP	EDR Digital Archive
	LAFAYETTE STREET FUND LP	EDR Digital Archive
	SELECT EQUITY GROUP LP	EDR Digital Archive

FINDINGS

Year	Uses	Source
2014	MEYERS CHARNA J	EDR Digital Archive
	ROSENZWEIG DEBRA DR	EDR Digital Archive
	MICHAEL VNNOY ADAMS DPHIL LCSW	EDR Digital Archive
	GREEN APPLE GROUP	EDR Digital Archive
	FEZ	EDR Digital Archive
	LURE SB LLC	EDR Digital Archive
	FISHTANK LIMITED PARTNERSHIP	EDR Digital Archive
	SOUTH ON SEVENTH LLC	EDR Digital Archive
	MEYERS CHARNA J	EDR Digital Archive
	ROSENZWEIG DEBRA DR	EDR Digital Archive
	MICHAEL VNNOY ADAMS DPHIL LCSW	EDR Digital Archive
	GREEN APPLE GROUP	EDR Digital Archive
	LAFAYETTE STREET FUND II LP	EDR Digital Archive
	SEG PARTNERS LP	EDR Digital Archive
	SEG PARTNERS II LP	EDR Digital Archive
	LAFAYETTE STREET FUND LP	EDR Digital Archive
	SELECT EQUITY GROUP LP	EDR Digital Archive
	FEZ	EDR Digital Archive
	LURE SB LLC	EDR Digital Archive
	FISHTANK LIMITED PARTNERSHIP	EDR Digital Archive
	SOUTH ON SEVENTH LLC	EDR Digital Archive
	SCARSDALE PICTURES INC	EDR Digital Archive
	NATALIETOBIER	EDR Digital Archive
	TERTE RACHEL	EDR Digital Archive
	S E G HOLDINGS LLC	EDR Digital Archive
	NOHO HOSPITALITY LLC	EDR Digital Archive
2010	FISHTANK LIMITED PARTNERSHIP	EDR Digital Archive
	SOUTH ON SEVENTH LLC	EDR Digital Archive
	FEZ	EDR Digital Archive
	MEYERS CHARNA J	EDR Digital Archive
	ROSENZWEIG DEBRA DR	EDR Digital Archive
	ART CRAFT WALLETS INC	EDR Digital Archive
	TEEN FILMS INC	EDR Digital Archive
	WINDOW PANE PICTURES INC	EDR Digital Archive
	VACHON PRODUCTIONS INC	EDR Digital Archive
	LACE CURTAIN PRODUCTIONS INC	EDR Digital Archive
	QUEEN JANE DISTRIBUTION INC	EDR Digital Archive
	GENTIEU PENNY STUDIO	EDR Digital Archive

FINDINGS

Year	Uses	Source
2010	PIX PRODUCERS INC	EDR Digital Archive
	JOHMAN USA INC	EDR Digital Archive
	JOHNMAN USA INC	EDR Digital Archive
	DEL REALTY COMPANY INC	EDR Digital Archive
	SELECT EQUITY GROUP INC	EDR Digital Archive
	NATALIETOBIER	EDR Digital Archive
	SCARSDALE PICTURES INC	EDR Digital Archive
	TIERRA INNOVATION	EDR Digital Archive
	MULTI PURPOSE INC	EDR Digital Archive
	S E G HOLDINGS LLC	EDR Digital Archive
	NATALIETOBIER	EDR Digital Archive
	TIERRA INNOVATION	EDR Digital Archive
	MULTI PURPOSE INC	EDR Digital Archive
	SCARSDALE PICTURES INC	EDR Digital Archive
	S E G HOLDINGS LLC	EDR Digital Archive
	FISHTANK LIMITED PARTNERSHIP	EDR Digital Archive
	SOUTH ON SEVENTH LLC	EDR Digital Archive
	FEZ	EDR Digital Archive
	MEYERS CHARNA J	EDR Digital Archive
	ROSENZWEIG DEBRA DR	EDR Digital Archive
	ART CRAFT WALLETS INC	EDR Digital Archive
	TEEN FILMS INC	EDR Digital Archive
	WINDOW PANE PICTURES INC	EDR Digital Archive
	VACHON PRODUCTIONS INC	EDR Digital Archive
	SELECT EQUITY GROUP INC	EDR Digital Archive
	LACE CURTAIN PRODUCTIONS INC	EDR Digital Archive
	QUEEN JANE DISTRIBUTION INC	EDR Digital Archive
	GENTIEU PENNY STUDIO	EDR Digital Archive
	PIX PRODUCERS INC	EDR Digital Archive
	JOHMAN USA INC	EDR Digital Archive
	JOHNMAN USA INC	EDR Digital Archive
	DEL REALTY COMPANY INC	EDR Digital Archive

LAFAYETTE ST

380 LAFAYETTE ST

Year	Uses	Source
2006	Jerimie Sherry va	Hill-Donnelly Information Services
	Jerimie Sherry IP	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2006	John Averitt Architects LP	Hill-Donnelly Information Services
	Number 203 Karaoke Champ 1 os	Hill-Donnelly Information Services
	Number 202 Killer Films s	Hill-Donnelly Information Services
	Marina! Franco	Hill-Donnelly Information Services
	Meyers Charna 3 IS	Hill-Donnelly Information Services
	Meyers Chama J VA	Hill-Donnelly Information Services
	Multi Purpose Inc	Hill-Donnelly Information Services
	Penny Gentieu Studio	Hill-Donnelly Information Services
	Number 5 Pix Producers Inc i s	Hill-Donnelly Information Services
	Rosenzweig Debra Dr v	Hill-Donnelly Information Services
	Rosenzweig Debra PHD	Hill-Donnelly Information Services
	Sarah Hill CSW	Hill-Donnelly Information Services
	Number 6 Select Equity 2 F	Hill-Donnelly Information Services
	Stoddard Designs & Dvlpmnt	Hill-Donnelly Information Services
	Studio Sofield VA	Hill-Donnelly Information Services
	Thorsdottir Anna K	Hill-Donnelly Information Services
	Time Cafe	Hill-Donnelly Information Services
	Visitation Alternatives	Hill-Donnelly Information Services
	Multi Unit Address	Hill-Donnelly Information Services
	Antar Deborah v A	Hill-Donnelly Information Services
	Number 4 Art Craft Leather Goods Inc	Hill-Donnelly Information Services
	Buchthal Stanley F	Hill-Donnelly Information Services
	Cohen Naomi a	Hill-Donnelly Information Services
	Cohen Naomi P	Hill-Donnelly Information Services
	Number S Colin Cooke Studio I s	Hill-Donnelly Information Services
	Creating Media LLC 10 os	Hill-Donnelly Information Services
	Davis & Jerimie IP	Hill-Donnelly Information Services
	Evenitt James	Hill-Donnelly Information Services
	Hart Sharp Video is	Hill-Donnelly Information Services
	Heraty Hall LL Pi P	Hill-Donnelly Information Services
	Jennifer Katz CSW I P	Hill-Donnelly Information Services
2000	FRANCO MARINAI	Cole Information Services
	NEIL SOKOLOFF	Cole Information Services
	ANNA K THORSDOTTIR	Cole Information Services
	ART CRFT LTHR GDS	Cole Information Services
	ART CRFT WILTS INC	Cole Information Services
	AVERITT ASSOCS	Cole Information Services
	B LAB INC	Cole Information Services

Year	Uses	Source
2000	BLCKBSTRS PRDCTNS	Cole Information Services
	CLOISTERS CONST	Cole Information Services
	COLE JEFFREY ARCHT	Cole Information Services
	COOKE COLIN STUDIO	Cole Information Services
	DARWISH STUDIO	Cole Information Services
	DECONSTRUCTION	Cole Information Services
	ENDEAVOR	Cole Information Services
	FEZ	Cole Information Services
	GENTIEU PENNY STD	Cole Information Services
	GLYNN MICHAEL	Cole Information Services
	HART JOHN	Cole Information Services
	HART SHARP ENTRTN	Cole Information Services
	JEFFREY FEINGOLD	Cole Information Services
	JOHNSON TIM	Cole Information Services
	KILLER FILMS	Cole Information Services
	KUHL WOLFGANG DSGN	Cole Information Services
	LUBRANO CVRR DSGNS	Cole Information Services
	MCCRUM & KRZIS ARCH	Cole Information Services
	MODE CONST CORP	Cole Information Services
	PIX PRODUCERS INC	Cole Information Services
	REICH MALINDA	Cole Information Services
	ROBERTFARRELL	Cole Information Services
	SELECT EQUITY	Cole Information Services
	STEINBERG C LAWYER	Cole Information Services
	STUDIO SOFIELD	Cole Information Services
	THUY HA DESIGNS	Cole Information Services
	TIME CAFE	Cole Information Services
	VALENTINE ANTHONY	Cole Information Services
1983	Harrold Barbara	New York Telephone
1927	Haviland Shade Roller Co	New York Telephone
	Ro Go Clothing Co	New York Telephone
	Rubenstein L fcy cases	New York Telephone

Lafayette St

381 Lafayette St

Year	Uses	Source
2014	ROBERT RAUSCHENBERG INC	EDR Digital Archive
	ROBERT RAUSCHENBERG INC	EDR Digital Archive

Year	Uses	Source
2010	ROBERT RAUSCHENBERG INC	EDR Digital Archive
	CHANGE INC	EDR Digital Archive
	ROBERT RAUSCHENBERG INC	EDR Digital Archive
	CHANGE INC	EDR Digital Archive

LAFAYETTE ST

381 LAFAYETTE ST

Year	Uses	Source
2006	NOa	Hill-Donnelly Information Services
1931	Flynn Thos F	Manhattan and Bronx Directory Publishing Company Residential Directory
1927	Saint Josephs Union	New York Telephone
	Mission of the Immaculate Virgin	New York Telephone
	Fitzpatrick Mallick J Rev	New York Telephone

Lafayette St

382 Lafayette St

Year	Uses	Source
2014	77 PERRY REALTY CORP	EDR Digital Archive
	BOARD OF MANAGERS OF THE CHRIS	EDR Digital Archive
	T ST A L INC	EDR Digital Archive
	STEPHEN PEVNER INC	EDR Digital Archive
	KESSLER PHILLIP	EDR Digital Archive
	SCREAMING MIMI INC	EDR Digital Archive
	77 PERRY REALTY CORP	EDR Digital Archive
	BOARD OF MANAGERS OF THE CHRIS	EDR Digital Archive
	T ST A L INC	EDR Digital Archive
	STEPHEN PEVNER INC	EDR Digital Archive
	KESSLER PHILLIP	EDR Digital Archive
	SCREAMING MIMI INC	EDR Digital Archive
2010	SCREAMING MIMI INC	EDR Digital Archive
	1 CITY TOWING RECOVERY	EDR Digital Archive
	T ST A L INC	EDR Digital Archive
	STEPHEN PEVNER INC	EDR Digital Archive
	BOARD OF MANAGERS OF THE CHRIS	EDR Digital Archive
	77 PERRY REALTY CORP	EDR Digital Archive
	SCREAMING MIMI INC	EDR Digital Archive
	1 CITY TOWING RECOVERY	EDR Digital Archive

Year	Uses	Source
2010	T ST A L INC	EDR Digital Archive
	STEPHEN PEVNER INC	EDR Digital Archive
	BOARD OF MANAGERS OF THE CHRIS	EDR Digital Archive
	77 PERRY REALTY CORP	EDR Digital Archive

LAFAYETTE ST

382 LAFAYETTE ST

Year	Uses	Source
2006	Number 8 h Pevner Stephen	Hill-Donnelly Information Services
	Number 8 Saint is	Hill-Donnelly Information Services
	Screaming Mimi 1 R	Hill-Donnelly Information Services
	Number 9 H Sugg John	Hill-Donnelly Information Services
	Sugg John T o	Hill-Donnelly Information Services
	Number 2 H Kessler P	Hill-Donnelly Information Services
	Multi Unit Address	Hill-Donnelly Information Services
	Condominium Co IF	Hill-Donnelly Information Services
	Alexanian David 0 o	Hill-Donnelly Information Services
	Alexanian David	Hill-Donnelly Information Services
	Number 4 Appen Ben A	Hill-Donnelly Information Services
	Number 8 h Fedushin Boris Ivan A	Hill-Donnelly Information Services
2000	CONDOMINIUM	Cole Information Services
	SCREAMING MIMI	Cole Information Services
	SCHUMER ARLEN	Cole Information Services
	9 JOHN T SUGG	Cole Information Services
	9 BORIS I FEDUSHIN	Cole Information Services
	JOHN SUGG	Cole Information Services
1927	Standard Elec & Repr Co	New York Telephone
	Schneiderman A prntr	New York Telephone
	Schneider Press	New York Telephone
	Queen Hat Co	New York Telephone
	Pumphrey Edw P ruling	New York Telephone
	Mothguard Laboratories Inc	New York Telephone
	Metropolitan Press	New York Telephone
	Greenberg Saml clthg	New York Telephone
	Greenberg Saml clthg	New York Telephone
	Cohn Henry printing	New York Telephone
	Cohn Attlee Press	New York Telephone
	Bernstein Julius C prntr	New York Telephone

FINDINGS

Lafayette St

383 Lafayette St

Year	Uses	Source
2014	332 E 4TH ST ASSOCIATES	EDR Digital Archive
	NEW YORK UNIVERSITY	EDR Digital Archive
	JOSEPH & SADIE RUBENSTEIN FDN	EDR Digital Archive
	332 E 4TH ST ASSOCIATES	EDR Digital Archive
	NEW YORK UNIVERSITY	EDR Digital Archive
	JOSEPH & SADIE RUBENSTEIN FDN	EDR Digital Archive
2010	JOSEPH & SADIE RUBENSTEIN FDN	EDR Digital Archive
	332 E 4TH ST ASSOCIATES	EDR Digital Archive
	JOSEPH & SADIE RUBENSTEIN FDN	EDR Digital Archive
	332 E 4TH ST ASSOCIATES	EDR Digital Archive

LAFAYETTE ST

383 LAFAYETTE ST

Year	Uses	Source
2006	Emergency Towing 24 Hour	Hill-Donnelly Information Services
	International Office Appls	Hill-Donnelly Information Services
	Tower Records Video Books BKS	Hill-Donnelly Information Services
2000	RUBINSTEIN STUART	Cole Information Services
	TOWER RECORDS VID	Cole Information Services
	TOWER SALES & RNTNG	Cole Information Services
	TOWER RECORDS VID	Cole Information Services
	RUBENSTEIN STUART	Cole Information Services
	CAN RESOURCES INC	Cole Information Services
	446 REALTY ASSOCS	Cole Information Services
	GOTHAM PPR CO INC	Cole Information Services
	I-O-A DATA CORP	Cole Information Services
	INTRNTNL OFC DV	Cole Information Services
1927	Borough Audit Co	New York Telephone

384 LAFAYETTE ST

Year	Uses	Source
2006	Tower Records Video Books BKS	Hill-Donnelly Information Services
	386 No Current Listing	Hill-Donnelly Information Services
	Tower Records Video Books BKS	Hill-Donnelly Information Services

FINDINGS

389 LAFAYETTE ST

Year	*Uses*	*Source*
1934	Schaefer John br mgr Oberly & Newell	R. L. Polk & Co.
1927	Angier Corporation The	New York Telephone
	Hubbs Chas F & Co paper	New York Telephone

390 LAFAYETTE ST

Year	*Uses*	*Source*
2006	No Current Listing	Hill-Donnelly Information Services

393 LAFAYETTE ST

Year	*Uses*	*Source*
2006	Victor Transmission i s	Hill-Donnelly Information Services
1927	No	New York Telephone

510 LAFAYETTE ST

Year	*Uses*	*Source*
2000	PETER GREENBERG	Cole Information Services
	SPIVAK H B & ASSOCS	Cole Information Services
	PLOUGH PNNY PRTNRS	Cole Information Services
	POINT DESIGN INC	Cole Information Services
	PRAEDIUM GROUP THE	Cole Information Services
	PRODUCER SOURCE	Cole Information Services
	PRGRSSV FBR PRDCTS	Cole Information Services
	PSNY	Cole Information Services
	Q & A LIC SHOWROOM	Cole Information Services
	QUINTO & COMPANY	Cole Information Services
	RAINFOREST FNDTN	Cole Information Services
	REMEDE LTD	Cole Information Services
	REMEDE CLY LIGHT	Cole Information Services
	RESEARCH	Cole Information Services
	ROBERT GRAY	Cole Information Services
	ROBERTS STEPHEN	Cole Information Services
	ROBERTS STEPHEN	Cole Information Services
	RON OSTERMAN & CO	Cole Information Services
	ROOTS	Cole Information Services
	ROOTS AMERICA INC	Cole Information Services
	ROSENBLATT M ATY	Cole Information Services
	ROZIER CHRLS DSGA	Cole Information Services
	R S A USA INC	Cole Information Services

Year	Uses	Source
2000	SANCHEZ MDLN ARCHT	Cole Information Services
	SRGSS MRC ARCHTCTS	Cole Information Services
	SEPTEMBER PRDCTNS	Cole Information Services
	SMITCH LESLIE	Cole Information Services
	SMITH CANDIDA	Cole Information Services
	PETRONIO JMS DSGN	Cole Information Services

Lafayette Street

363 Lafayette Street

Year	Uses	Source
2000	THE SMALL FURN STR	Cole Information Services
1998	THE SMALL FURNITURE STORE	NYNEX Telephone
1993	THE SMALL FURNITURE STORE	NYNEX Telephone
1983	NICK & GEORGE	New York Telephone
	Post Bros Svce Stas Inc ofc	New York Telephone
1938	MORRIS GAS STAS	New York Telephone
1927	Morris Edw	New York Telephone
	Bond Street Gas & Oil Sta Inc	New York Telephone

372 Lafayette Street

Year	Uses	Source
2006	Meineke Car Care Ctr Is	Hill-Donnelly Information Services
2000	G K AUTO MOTORS	Cole Information Services
	MEINEKE DISCOUNT	Cole Information Services
	Z P AUTO INC	Cole Information Services
1983	MEINEKE DISCOUNT MUFFLERS	New York Telephone
	Noho Collision Corp	New York Telephone

383 Lafayette Street

Year	Uses	Source
2006	Tower Records Video Books BKS	Hill-Donnelly Information Services
	Emergency Towing 24 Hour	Hill-Donnelly Information Services
	International Office Appls	Hill-Donnelly Information Services
2000	446 REALTY ASSOCS	Cole Information Services
	CAN RESOURCES INC	Cole Information Services
	GOTHAM PPR CO INC	Cole Information Services
	I-O-A DATA CORP	Cole Information Services
	INTRNTNL OFC DV	Cole Information Services
	RUBENSTEIN STUART	Cole Information Services

FINDINGS

Year	Uses	Source
2000	RUBINSTEIN STUART	Cole Information Services
	TOWER RECORDS VID	Cole Information Services
	TOWER SALES & RNTNG	Cole Information Services
	TOWER RECORDS VID	Cole Information Services
1998	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
	446 REALTY ASSOCS	NYNEX Telephone
	GREG SPOTTS ENTERTAINMENT INC	NYNEX Telephone
	GOTHAM PAPER CO INC	NYNEX Telephone
	TOWER RECORDS-VIDEO-BOOKS	NYNEX Telephone
1993	PERLMAN DICK ASSOCS INC	NYNEX Telephone
	446 REALTY ASSOCS	NYNEX Telephone
	CTM BROCHURE DISPLAY INC	NYNEX Telephone
	CTM BROCHURE DISPLAY	NYNEX Telephone
	GOTHAM PAPER CO INC	NYNEX Telephone
	HOUSE CLOTHING	NYNEX Telephone
	JANETTE BECKMAN PHOTOGRAPHY	NYNEX Telephone
	TOWER BOOKS	NYNEX Telephone
	TOWER RECORDS/VIDEO RECORDS	NYNEX Telephone
	CITY IN THE POCKET	NYNEX Telephone
	CTM BROCHURE DISPLAY MANHATTAN	NYNEX Telephone
1983	I O A DATA CORP	New York Telephone
	I O A Leasing Div Of I O A Data Corp	New York Telephone
	ADDRESSING MACHINE EQUIP CO DIV OF I O A DATA CORP	New York Telephone
	Adding & Bkkeepg Mach Corp	New York Telephone
	INTERNATIONAL OFC APLNCS DIV OF I O A DATA CORP	New York Telephone
	International Ofc Apincs Inc	New York Telephone
	Pearls Of Majorca	New York Telephone
	Rubinstein Stuart	New York Telephone
	Rubenstein Stuart	New York Telephone
	Rubenstein Jos adrsg mache	New York Telephone
1927	Borough Audit Co	New York Telephone

FINDINGS

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
375 Lafayette Street	1996, 1993, 1988, 1931

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
11 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927
11 Great Jones St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
11 GREAT JONES ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
11 Great Jones St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
14 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
14 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
15 E 4 ST	2014, 2010, 2006, 2000, 1996, 1988, 1983, 1978, 1963, 1956, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
15 E 4O	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
15 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923
15 E 4TH FL 10	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
15 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
15 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
15 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
17 E 4 ST	2014, 2010, 2006, 2000, 1996, 1993, 1968, 1956, 1938, 1934, 1931, 1927, 1923, 1920
17 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927
17 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
17 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
17 E 4th St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
17 E 4th St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
18 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
19 E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1968, 1963, 1958, 1956, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
20 E 4 ST	2014, 2010, 2006, 2000, 1996, 1988, 1983, 1963, 1956, 1950, 1947, 1934, 1931, 1927, 1923, 1920
20 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923
20 E 4TH F	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
20 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
20 E 4TH FL H DO	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
20 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
21 E 4 ST	2014, 2010, 2006, 2000, 1996, 1934, 1931, 1923, 1920
21 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
21 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
21 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
21 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
21 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
21 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1938, 1934, 1931, 1927, 1923
22 E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1988, 1983, 1978, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
22 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
22 E 4TH FL H BKN	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1920
22 E 4TH ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
23 E 4 ST	2014, 2010, 2006, 2000, 1996, 1988, 1934, 1931, 1923, 1920
23 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
23 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
23 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
23 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
23 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
23 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1931
23 GREAT JONES ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
23R E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
24 E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1968, 1963, 1958, 1956, 1950, 1947, 1934, 1931, 1923, 1920
24 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
24 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
24 E 4TH FL H HACKENSACK NJ	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
24 E 4TH ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
25 E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1934, 1931, 1923, 1920
25 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
25 E 4TH H BKN	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1920
25 E 4TH R PARK RIDGE NJ	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
25 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
25 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
25 E 4th St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
25 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1968, 1963, 1958, 1956, 1938, 1931
25 GREAT JONES ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
26 E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1956, 1934, 1931, 1923, 1920
26 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
26 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1920
26 E 4TH FL H DO	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1920
26 E 4TH R LAKEWOOD NJ	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
27 E 4 ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1934, 1931, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
27 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
27 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927
27 E 4TH H DO	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927
27 E 4TH H IRVINGTON NY	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1920
27 E 4TH ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
27 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1947, 1938, 1931
27 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
27 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
27 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
28 E 4 ST	2014, 2010, 2006, 2000, 1996, 1934, 1931, 1923, 1920
28 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931
28 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
28 E 4TH H BKN	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1920
28 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
29 E 4 ST	2014, 2010, 2006, 2000, 1996, 1934, 1927, 1923, 1920
29 E 4TH	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1927, 1923
29 E 4TH FL	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
29 E 4TH ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
29 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1931
29 GREAT JONES %	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927
29 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
29 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
29 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
30 E 4TH ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
30 E 4TH ST FL 4	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
30 East 4th Street	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1968, 1963, 1956, 1950, 1947, 1942, 1938, 1931
31 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1993, 1938, 1931, 1923
31 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
31 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
31 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
32 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1968, 1963, 1942, 1931
33 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1973, 1931, 1927, 1920
33 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
33 GREAT JONES ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
33 Great Jones Street	2014, 2010, 1996, 1973, 1931, 1927, 1920
34 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1931
34 GREAT JONES ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
35 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1993, 1931
35 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
36 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1931
361 Lafayette Street	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
363 LAFAYETTE	2014, 2010, 2006, 2000, 1996, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1934, 1931, 1927, 1923, 1920
363 LAFAYETTE ST	2014, 2010, 2006, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
363 Lafayette Street	2014, 2010, 2006, 1996, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1934, 1931, 1923, 1920
368 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
368 LAFAYETTE ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
37 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1934, 1931, 1927, 1923, 1920
372 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
372 LAFAYETTE ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
372 Lafayette St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
372 Lafayette St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
372 Lafayette Street	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
376 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
376 LAFAYETTE %	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
376 LAFAYETTE ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
376 Lafayette St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
376 Lafayette St	2014, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
38 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1931
38 GREAT JONES ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
380 LAFAYETTE	2014, 2010, 2006, 2000, 1996, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
380 LAFAYETTE ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
380 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
380 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
381 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1934, 1923
381 LAFAYETTE ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1923, 1920
381 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
381 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
382 LAFAYETTE	2014, 2010, 2006, 2000, 1996, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923
382 LAFAYETTE ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
382 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
382 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
383 LAFAYETTE	2014, 2010, 2006, 2000, 1996, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
383 LAFAYETTE ST	2014, 2010, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
383 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
383 Lafayette St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
383 Lafayette Street	2014, 2010, 1996, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
384 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
384 LAFAYETTE ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
386 LAFAYETTE %	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1920
388 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
389 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1931, 1923, 1920
389 LAFAYETTE ST	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1923, 1920
39 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1973, 1968, 1963, 1942, 1931
39 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
390 LAFAYETTE ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
392 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1920
392 LAFAYETTE %	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927
393 LAFAYETTE	2014, 2010, 2006, 2000, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1934, 1931, 1923, 1920
393 LAFAYETTE ST	2014, 2010, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
395 LAFAYETTE	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
4 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1968, 1934, 1931, 1927
4 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
4 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
4 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
4 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
40 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
41 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1931
41 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
41 GREAT JONES ST	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

FINDINGS

Address Researched	Address Not Identified in Research Source
41 GREAT JONES ST APT 2	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
41 GREAT JONES ST APT 3	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
41 GREAT JONES ST APT 4	2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
41 GREAT JONES ST APT 5	2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
41 GREAT JONES ST FRNT 1	2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
41 Great Jones Street	2014, 2010, 1996, 1931
43 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1973, 1968, 1931, 1923, 1920
43 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
45 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1993, 1988, 1931
45 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
47 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1931
47 GREAT JONES %	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923
47 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
5 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
5 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
510 LAFAYETTE ST	2014, 2010, 2006, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
6 GREAT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1931, 1927, 1923, 1920
7 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
7 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
8 GREAT JONES ST	2014, 2010, 2006, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
9 GREAT JONES	2014, 2010, 2006, 2000, 1996, 1968, 1963, 1931
9 GREAT JONES ST	2014, 2010, 1998, 1996, 1993, 1988, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1923, 1920
9 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
9 Great Jones St	2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1950, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920
9 GT JONES	2014, 2010, 2006, 2000, 1998, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1963, 1958, 1956, 1947, 1942, 1938, 1934, 1931, 1927, 1923, 1920

APPENDIX E

ENVIRONMENTAL DATABASE RADIUS REPORT

LANGAN

375 Lafayette Street
375 Lafayette Street
New York, NY 10003

Inquiry Number: 5314975.2s
May 30, 2018

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	2102
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-10
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

375 LAFAYETTE STREET
NEW YORK, NY 10003

COORDINATES

Latitude (North):	40.7272960 - 40˚ 43' 38.26''
Longitude (West):	73.9931620 - 73˚ 59' 35.38''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	585027.6
UTM Y (Meters):	4508761.0
Elevation:	42 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940597 BROOKLYN, NY
Version Date:	2013
Southwest Map:	6048959 JERSEY CITY, NJ
Version Date:	2014

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150729, 20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	H B SERVICE CENTER	375-9 LAFAYETTE ST	EDR Hist Auto		TP
Reg	HUDSON RIVER PCBS	NO STREET APPLICABLE	NPL, SEMS, RCRA-SQG, US ENG CONTROLS, US INST...	Same	5183, 0.982, West
A2	CONCORD ELECTRONICS	30 GREAT JONES STREE	ICIS, FINDS, ECHO	Higher	1 ft.
A3	371 LAFAYETTE ST.	371 LAFAYETTE ST.	NY LTANKS	Higher	1 ft.
A4	231 CENTRE STREET AS	371 LAFAYETTE ST	NY UST	Higher	1 ft.
A5	30 GREAT JONES ST	30 GREAT JONES ST	NY AST	Higher	1 ft.
A6	371 LAFAYETTE	371 LAFAYETTE ST	EDR Hist Auto	Higher	1 ft.
A7	SPILL NUMBER 0209425	30 GREAT JONES ST	NY Spills	Higher	1 ft.
A8	CON EDISON MANHOLE 5	379 LAFAYETTE ST	FINDS, ECHO	Higher	1 ft.
A9	CON EDISON MANHOLE 5	379 LAFAYETTE ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1 ft.
A10	HARWOOD PROPERTY	25 GREAT JONES ST	NY Spills	Higher	41, 0.008, WSW
A11	FDNY - ENG 33	42 GREAT JONES ST	NY AST	Higher	45, 0.009, SE
A12	CON EDISON MANHOLE 3	LAFAYETTE ST & GREAT	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	53, 0.010, West
A13	S.E.G. 380 HOLDINGS	380 LAFAYETTE STREET	NY AST	Higher	58, 0.011, NNW
A14	PETERSBURG PRESS INC	380 LAFAYETTE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	58, 0.011, NNW
A15	CON EDISON	34 4TH ST	NY MANIFEST	Higher	59, 0.011, East
A16	34 EAST 4TH STREET	34 EAST 4TH STREET	NY AST	Higher	59, 0.011, East
A17	CON EDISON	30-32 E 4TH ST & BOW	RCRA NonGen / NLR, FINDS, ECHO	Higher	65, 0.012, East
A18	CON EDISON	30-32 E 4TH ST & BOW	NJ MANIFEST	Higher	65, 0.012, East
A19	CON EDISON	30-32 E 4TH ST & BOW	NY MANIFEST	Higher	65, 0.012, East
A20	CON EDISON	22 E 4 ST	NY MANIFEST	Higher	66, 0.013, NE
A21	CON EDISON	22 E 4 ST	NY MANIFEST	Higher	66, 0.013, NE
A22	NYU	383 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Higher	71, 0.013, NNE
A23	NEW YORK UNIVERSITY	383 LAFAYETTE STREET	NY AST	Higher	71, 0.013, NNE
A24	NYU	383 LAFAYETTE ST	NJ MANIFEST	Higher	71, 0.013, NNE
A25	28-30 E 4TH ST HOUSI	28-30 EAST 4TH ST	NY AST	Higher	83, 0.016, East
A26	SPILL NUMBER 9911688	28-30 E 4TH ST	NY Spills	Higher	83, 0.016, East
A27	30 EAST 4TH STREET	30 EAST 4TH STREET	NY LTANKS	Higher	83, 0.016, East
A28	CONCORD ELECTRONICS	GREAT JONES STREET	RCRA-SQG, RI MANIFEST, PA MANIFEST, NY MANIFEST	Higher	84, 0.016, SSE
A29	CON EDISON SERVICE B	378 LAFAYETTE ST FRO	NJ MANIFEST	Higher	86, 0.016, WNW
A30	CON EDISON SERVICE B	378 LAFAYETTE ST FRO	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	86, 0.016, WNW
A31	CON EDISON MANHOLE 5	372 LAFAYETTE ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	86, 0.016, WNW
A32	372 LAFAYETTE ST	372 LAFAYETTE STREET	NY UST	Higher	86, 0.016, WNW
A33	WASTE OIL SPILL AT G	372 LAFEYETTE ST	NY Spills	Higher	86, 0.016, WNW
A34	372 LAFAYETTE STREET	372 LAFAYETTE STREET	NY VCP	Higher	86, 0.016, WNW
A35	CON EDISON SERVICE B	372 LAFAYETTE ST FRO	NJ MANIFEST	Higher	86, 0.016, WNW
A36	CON EDISON SERVICE B	372 LAFAYETTE ST FRO	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	86, 0.016, WNW
B37	CON EDISON	38 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	97, 0.018, East
A38	CON EDISON SERVICE B	33 GREAT JONES ST	RCRA NonGen / NLR, NY MANIFEST	Higher	100, 0.019, South

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A39	CON EDISON SERVICE B	33 GREAT JONES ST	NJ MANIFEST	Higher	100, 0.019, South
A40	POST BROS SERVICE ST	363-371 LAFAYETTE ST	EDR Hist Auto	Higher	103, 0.020, SW
A41	SMOOTH TOOTH ENTERPR	41 GREAT JONES ST	EDR Hist Cleaner	Higher	105, 0.020, SSE
A42	POST BROS SERVICE ST	361 LAFAYETTE ST	EDR Hist Auto	Higher	114, 0.022, SW
B43	43 GREAT JONES STREE	43 GREAT JONES STREE	NY AST	Higher	117, 0.022, SSE
B44	LOFT BUILDING	43 GREAT JONES STREE	NY Spills	Higher	117, 0.022, SSE
A45	41 GREAT JONES HOLDI	41 GREAT JONES STREE	NY AST	Higher	118, 0.022, SSE
B46	48 TENANTS CORP	48 GREAT JONES STREE	NY AST	Higher	122, 0.023, SE
B47	APARTMENT BLDG TTF	48 GREAT JONES ST	NY LTANKS	Higher	122, 0.023, SE
A48	KALODOP PARK CORP	27 EAST 4TH STREET	NY UST	Higher	135, 0.026, NE
A49	CON EDISON - GAS MAI	E 4TH ST AND LAFAYET	NJ MANIFEST	Higher	141, 0.027, North
A50	CON EDISON SERVICE B	E 4TH ST & LAFAYETTE	NJ MANIFEST	Higher	141, 0.027, North
A51	E 4TH ST & LAFAYETTE	E 4TH ST & LAFAYETTE	NY Spills	Higher	141, 0.027, North
A52	CON EDISON SERVICE B	EAST 4 ST & LAFAYETT	RCRA NonGen / NLR	Higher	141, 0.027, North
A53	CON EDISON - GAS MAI	E 4TH ST AND LAFAYET	RCRA-LQG, NY MANIFEST	Higher	141, 0.027, North
A54	CON EDISION - MH3792	EAST 4TH STREET AND	RCRA NonGen / NLR, NY MANIFEST	Higher	146, 0.028, North
B55	CON EDISON SERVICE B	47 GREAT JONES ST	RCRA NonGen / NLR, NY MANIFEST	Higher	151, 0.029, SSE
A56	217199; 6 GREAT JONE	6 GREAT JONES ST	NY Spills	Lower	157, 0.030, WNW
B57	MERCHANTS HOUSE	29 E 4TH ST	RCRA-CESQG, NY MANIFEST	Higher	179, 0.034, ENE
B58	LOT 67,TAXBLOCK 544	37 EAST 4 STREET	NY RES DECL	Higher	187, 0.035, ENE
B59	OZY MANDIUS REALTY	348 BOWERY ST	NY Spills	Higher	200, 0.038, ESE
B60	INTERSECTION	BOWERY / 3RD ST	NY Spills	Lower	206, 0.039, ESE
C61	20 BOND ST. CR. LAFA	20 BOND ST.CR. LAFAY	NY Spills	Higher	224, 0.042, SW
C62	20 BOND STREET	20 BOND STREET	NY Spills	Higher	224, 0.042, SW
D63	VICTOR TRANSMISSIONS	393 LAFAYETTE ST	EDR Hist Auto	Higher	224, 0.042, NNE
B64	SUPERIOR GULF STATIO	360 BOWERY	EDR Hist Auto	Lower	228, 0.043, ESE
E65	SILK BUILDING CONDOM	14 E 4TH ST	NY AST	Lower	236, 0.045, NNW
C66	FORMER PENSKE	40 BOND STREET	NY Spills	Higher	242, 0.046, South
C67	3 GREAT JONES TENANT	3 GREAT JONES STREET	NY AST	Lower	243, 0.046, West
C68	RESIDENTIAL BLDG	24 BOND ST	NY Spills	Higher	243, 0.046, SSW
C69	HARRY AUTOMOTIVE REP	10-12 BOND ST	EDR Hist Auto	Lower	254, 0.048, WSW
C70	CON EDISON	10 BOND ST	NY Spills, NY MANIFEST	Lower	254, 0.048, WSW
C71	10-12 BOND STREET PE	10 BOND STREET	NY UST	Lower	254, 0.048, WSW
C72	PANORAMIC AUTO SERVI	10 BOND ST	RCRA NonGen / NLR	Lower	254, 0.048, WSW
C73	CON EDISON SERVICE B	10 BOND ST	RCRA NonGen / NLR	Lower	254, 0.048, WSW
F74	42 BOND ST	42 BOND ST	NY AST	Higher	261, 0.049, South
C75	NEW YORK CITY OF HUM	350 LAFAYETTE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	276, 0.052, WSW
C76	LAFAYETTE WOMEN SHEL	350 LAFAYETTE STREET	NY UST	Lower	276, 0.052, WSW
C77	350 LAFAYETTE ST/SHE	350 LAFAYETTE ST/SHE	NY LTANKS	Lower	276, 0.052, WSW

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C78	KAMPO CULTURAL CENTE	31 BOND STREET	NY AST	Higher	284, 0.054, SSW
C79	CON EDISON SERVICE B	6 BOND ST	RCRA NonGen / NLR, NY MANIFEST	Lower	291, 0.055, WSW
F80	50 BOND STREET	50 BOND STREET	NY AST	Higher	296, 0.056, SSE
E81	688 BROADWAY 1 GREAT	688 BROADWAY	RCRA-LQG, FINDS, ECHO	Lower	299, 0.057, NW
E82	DOWNTOWN RE HOLDINGS	688 BROADWAY	PA MANIFEST	Lower	299, 0.057, NW
E83	LOT 4,TAXBLOCK 531	688 BROADWAY	NY E DESIGNATION	Lower	299, 0.057, NW
E84	688 BROADWAY	688 BROADWAY	NY VCP	Lower	299, 0.057, NW
E85	DOWNTOWN RE HOLDINGS	688 BROADWAY	NY MANIFEST	Lower	299, 0.057, NW
B86	BOWERY AND 4TH STREE	BOWERY AND 4TH STREE	RCRA NonGen / NLR, NY MANIFEST	Lower	300, 0.057, East
C87	SPILL NUMBER 9801771	22 BOND ST	NY Spills	Higher	300, 0.057, SW
F88	CON EDISON	342 BOWERY	NJ MANIFEST	Higher	301, 0.057, SE
F89	CON EDISON	342 BOWERY	RCRA NonGen / NLR, FINDS, ECHO	Higher	301, 0.057, SE
F90	CON EDISON	342 BOWERY	NY MANIFEST	Higher	301, 0.057, SE
G91	CON EDISON MANHOLE:	GREAT JONES ST & BOW	RCRA NonGen / NLR, NY MANIFEST	Lower	304, 0.058, SE
D92	FISHER REALTY CORP	401 LAFAYETTE ST	NY AST	Higher	308, 0.058, NNE
E93	CON EDISON SERVICE B	11 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	310, 0.059, NNW
B94	MARTYS QUICKSTART IN	1 COOPER SQUARE	EDR Hist Auto	Lower	315, 0.060, East
F95	SUNOCO STATION	THE BOWERY AND SECON	NY Spills	Higher	320, 0.061, SE
F96	GAS STATION	BOND ST / BOWERY	NY Spills	Higher	320, 0.061, SE
F97	MANHOLE #26829	BOND ST, SWC BOWERY	NY Spills	Higher	320, 0.061, SE
E98	682 TENANT CORP.	682 BROADWAY	NY AST	Lower	322, 0.061, WNW
D99	PARKING GARAGE	403 LAFAYETTE ST	NY Spills	Higher	322, 0.061, NNE
D100	KALODOP PARK CORP.	403 LAFAYETTE STREET	NY UST	Higher	322, 0.061, NNE
F101	CON EDISON	340 BOWERY	NY MANIFEST	Higher	323, 0.061, SE
F102	CON EDISON	340 BOWERY	RCRA NonGen / NLR, FINDS, ECHO	Higher	323, 0.061, SE
F103	CON EDISON	340 BOWERY	NJ MANIFEST	Higher	323, 0.061, SE
F104	340 BOWERY	340 BOWERY	NY Spills	Higher	344, 0.065, SSE
D105	CON EDISON	402 LAFAYETTE ST	NY MANIFEST	Higher	344, 0.065, NNE
C106	A&P SERVICE STATION	8 BOND ST	NY UST	Lower	349, 0.066, WSW
C107	BASEMENT OF	8 BOND ST	NY Spills	Lower	349, 0.066, WSW
F108	CON EDISON SERVICE B	334 BOWERY FRONT OF	NJ MANIFEST	Higher	355, 0.067, SSE
F109	CON EDISON SERVICE B	334 BOWERY FRONT OF	NJ MANIFEST	Higher	355, 0.067, SSE
C110	PENSKE TRUCK LEASING	23 BOND STREET	NY UST, NY AST	Higher	357, 0.068, SSW
C111	CON EDISON SERVICE B	23 BOND ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Higher	357, 0.068, SSW
C112	CON EDISON SERVICE B	23 BOND ST FRONT OF	NJ MANIFEST	Higher	357, 0.068, SSW
C113	PENSKE TRUCK LEASING	23 BOND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	357, 0.068, SSW
B114	54 EAST 4 ST	54 EAST 4 ST	NY AST	Lower	358, 0.068, ESE
G115	HOMELESS SHELTER	I/F/O 8 EAST 3RD ST	NY Spills	Lower	359, 0.068, ESE
H116	39 EAST 4TH ST.	39 EAST 4TH STREET	NY UST	Lower	364, 0.069, ENE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H117	FORMER COOPER HOTEL	2 COOPER SQUARE	NY UST, NY AST	Lower	364, 0.069, ENE
H118	FORMER HOTEL	2 COOPER SQUARE	NY Spills	Lower	364, 0.069, ENE
F119	CON EDISON SERVICE B	39 BOND ST	RCRA NonGen / NLR, NY MANIFEST	Higher	365, 0.069, South
E120	700 BROADWAY/MANHATT	700 BROADWAY	NY Spills	Lower	367, 0.070, NNW
E121	NATIONAL AUDUBON SOC	700 BROADWAY	NY UST	Lower	367, 0.070, NNW
C122	CON EDISON SERVICE B	19 BOND ST FRONT OF	NJ MANIFEST	Higher	374, 0.071, SW
C123	CON EDISON SERVICE B	19 BOND ST FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	374, 0.071, SW
F124	35 BOND STREET CORP.	35 BOND ST	NY AST	Higher	375, 0.071, South
F125	SPILL NUMBER 9908485	35 BOND ST	NY Spills	Higher	375, 0.071, South
H126	CON EDISON	11 COOPER SQ FRONT O	NY MANIFEST	Lower	376, 0.071, East
H127	CON EDISON SERVICE B	11 COOPER SQ FRONT O	RCRA NonGen / NLR	Lower	376, 0.071, East
C128	SPILL NUMBER 9813854	1 BOND ST APT #6C	NY Spills	Lower	382, 0.072, WSW
D129	708 BROADWAY	708 BROADWAY	NY AST	Higher	383, 0.073, NNE
I130	JORDAN REALTY LLC	676 BROADWAY	NY AST	Lower	392, 0.074, West
C131	VAULT 9133	3 BOND ST	NY Spills	Lower	393, 0.074, WSW
I132	684 BROADWAY OWNERS	684 BROADWAY	NY AST	Lower	399, 0.076, WNW
E133	CON EDISON SERVICE B	686-88 BROADWAY & GT	RCRA NonGen / NLR, NY MANIFEST	Lower	400, 0.076, WNW
D134	409 LAFAYETTE ST ASS	409 LAFAYETTE ST	NY AST	Lower	401, 0.076, NNE
H135	SPILL NUMBER 0204004	20 COOPER SQUARE	NY Spills	Lower	402, 0.076, ENE
H136	NY UNIV	20 COOPER SQ	NY AST, NY Spills	Lower	402, 0.076, ENE
I137	Z. BUILDING CORP.	680 BROADWAY	NY AST	Lower	409, 0.077, WNW
I138	CONSOLIDATED EDISON	F/O 680 BROADWAY	NY MANIFEST	Lower	409, 0.077, WNW
I139	CONSOLIDATED EDISON	F/O 680 BROADWAY	NY MANIFEST	Lower	409, 0.077, WNW
C140	CONSOLIDATED EDISON	346 LAFFAYETTE ST	NY MANIFEST	Lower	414, 0.078, SW
H141	CON EDISON GAS MAIN	COOPER SQ & E 5TH ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	416, 0.079, ENE
H142	CON EDISON EXCAVATIO	COOPER SQ & E 5TH ST	NJ MANIFEST	Lower	416, 0.079, ENE
H143	CON EDISON EXCAVATIO	COOPER SQUARE AND EA	RCRA NonGen / NLR, NY MANIFEST	Lower	416, 0.079, ENE
H144	CON EDISON SERVICE B	237 E 5TH ST & COOPE	RCRA NonGen / NLR, FINDS	Lower	416, 0.079, ENE
F145	CON EDISON SERVICE B	334 BOWERY FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Higher	421, 0.080, SSE
F146	CON EDISON SERVICE B	334 BOWERY FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	421, 0.080, SSE
H147	SPILL NUMBER 0004644	16-20 COOPER SQ	NY Spills	Lower	422, 0.080, ENE
I148	CON EDISON - SERVICE	GREAT JONES ST AND B	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Lower	423, 0.080, WNW
I149	219641; GREAT JONES	GREAT JONES ST AND B	NY Spills	Lower	423, 0.080, WNW
I150	VERIZON LOG 32884	BROADWAY & GREAT JON	RCRA NonGen / NLR, NY MANIFEST	Lower	423, 0.080, WNW
I151	214191; GREAT JONES	GREAT JONES ST AND B	NY Spills	Lower	423, 0.080, WNW
F152	SERVICE STATION	326 BOWERY AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	424, 0.080, SSE
F153	DOWNTOWN AUTOMOTIVE,	326 BOWERY	NY UST, NY Spills	Higher	424, 0.080, SSE
F154	SPOT SERVICE STATION	326 BOWERY	EDR Hist Auto	Higher	424, 0.080, SSE
H155	CON EDISON SERVICE B	15 COOPER SQ FRONT O	RCRA NonGen / NLR	Lower	426, 0.081, ENE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H156	CON EDISON	15 COOPER SQ FRONT O	NY MANIFEST	Lower	426, 0.081, ENE
I157	TM 3691	1 WEST 3RD STREET	NY Spills	Lower	430, 0.081, WNW
E158	CON EDISON - SERVICE	691 BROADWAY	NY MANIFEST	Lower	440, 0.083, NW
E159	CON EDISON GAS DRIP	E 4TH ST & BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	445, 0.084, NW
E160	CON EDISON GAS MAIN	WEST 4TH STREET AND	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	445, 0.084, NW
E161	CON EDISON GAS DRIP	E 4TH ST & BROADWAY	NJ MANIFEST	Lower	445, 0.084, NW
E162	CON EDISON - TRANSFO	E 4TH ST & BROADWAY	NY MANIFEST	Lower	445, 0.084, NW
E163	CON EDISON GAS MAIN	W 4TH ST & BROADWAY	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	445, 0.084, NW
E164	214224; E 4 ST AND B	E 4 ST AND BROADWAY	NY Spills	Lower	445, 0.084, NW
E165	CON EDISON	BROADWAY & E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	445, 0.084, NW
E166	4TH ST & B'WAY/NAT'L	4TH ST & BROADWAY	NY Spills	Lower	445, 0.084, NW
C167	SERVICE BOX 37911	BLEECKER ST/LAFAYETT	NY Spills	Lower	448, 0.085, SW
E168	704 BROADWAY	704 BROADWAY	NY LTANKS	Lower	457, 0.087, NNW
E169	704 BROADWAY CONDOMI	704 BROADWAY	NY AST	Lower	457, 0.087, NNW
F170	CON EDISON SERVICE B	59 BOND ST FRONT OF	NJ MANIFEST	Higher	475, 0.090, SSE
F171	CON EDISON SERVICE B	59 BOND ST FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	475, 0.090, SSE
E172	APARTMENT	2-4 ST NICHOLAS PLAC	NY LTANKS	Lower	479, 0.091, NW
H173	30 COOPER SQ.	30 COOPER SQUARE	NY UST, NY AST, NY Spills	Lower	482, 0.091, ENE
J174	59 EAST 4 STREET	59 EAST 4TH STREET	NY AST	Lower	483, 0.091, East
H175	CON EDISION	27 COOPER SQ	NY MANIFEST	Lower	487, 0.092, ENE
H176	COOPERS SQUARE HOTEL	27 COOPERS SQUARE	NY Spills	Lower	487, 0.092, ENE
F177	17-19 BLEECKER STREE	17-19 BLEECKER STREE	NY AST	Higher	488, 0.092, South
I178	V6421	3 W. 3RD STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	491, 0.093, WNW
H179	34 COOPER SQUARE	34 COOPER SQUARE	NY AST	Lower	493, 0.093, NE
H180	CON EDISON SERVICE B	34 COOPER SQ FRONT O	RCRA NonGen / NLR, FINDS	Lower	493, 0.093, NE
H181	CON EDISON	34 COOPER SQ FRONT O	NY MANIFEST	Lower	493, 0.093, NE
J182	56 EAST 4TH STREET	56 EAST 4TH STREET	NY AST	Lower	493, 0.093, ESE
I183	670 BROADWAY	670 BROADWAY	NY AST	Lower	494, 0.094, West
G184	WYOMING ARTS, CONDOM	5 EAST 3RD STREET	NY AST	Lower	496, 0.094, ESE
G185	5 EAST THIRD STREET	5 E THIRD STREET	NY AST	Lower	496, 0.094, ESE
F186	CON EDISON SERVICE B	23 BLEECKER ST	NJ MANIFEST	Higher	497, 0.094, South
F187	CON EDISON SERVICE B	23 BLEECKER ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	497, 0.094, South
K188	RESIDENTS	33 BLEECKER STREET	NY Spills	Higher	500, 0.095, SSW
K189	CON EDISON	33 BLEECKER ST FRONT	NY MANIFEST	Higher	500, 0.095, SSW
K190	33 BLEECKER STREET C	33 BLEECKER STREET	NY AST	Higher	500, 0.095, SSW
K191	CON EDISON MANHOLE:	33 BLEECKER ST FRON	RCRA NonGen / NLR	Higher	500, 0.095, SSW
G192	CON EDISON SERVICE B	331 BOWERY FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	503, 0.095, SE
G193	CON EDISON SERVICE B	331 BOWERY FRONT OF	NJ MANIFEST	Lower	503, 0.095, SE
L194	712-714 BROADWAY COR	714 BROADWAY	NY AST	Lower	504, 0.095, NNW

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M195	MANHOLE #31124	CROSBY ST/BLEECKER S	NY Spills	Lower	504, 0.095, WSW
F196	SPILL NUMBER 0211638	17-19 BLEECKER ST	NY Spills	Higher	511, 0.097, South
N197	IN ROADWAY	BOND/BOWERY INTERSEC	NY Spills	Higher	515, 0.098, SSE
G198	335 BOWERY OPERATING	335 BOWERY	NY UST	Lower	516, 0.098, SE
G199	335 BOWERY OPERATING	335 BOWERY	EDR Hist Auto	Lower	516, 0.098, SE
G200	CON EDISON	335 BOWERY	NY MANIFEST	Lower	516, 0.098, SE
H201	CON EDISON SERVICE B	36 COOPER SQ FRONT O	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	518, 0.098, ENE
H202	CON EDISON SERVICE B	36 COOPER SQ FRONT O	NJ MANIFEST	Lower	518, 0.098, ENE
L203	VERSAKLEEN DRY CLEAN	8 W 4TH ST	EDR Hist Cleaner	Lower	519, 0.098, NW
G204	CITY OF N.Y. DEPT OF	7 EAST 3RD STREET	NY AST	Lower	521, 0.099, ESE
I205	ALCON ENGRAVERS INC	656 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	525, 0.099, WSW
L206	CON EDISON	699 BROADWAY	NJ MANIFEST	Lower	530, 0.100, NNW
L207	CON EDISON	699 BROADWAY	NY MANIFEST	Lower	530, 0.100, NNW
L208	CON EDISON	699 BROADWAY	RCRA NonGen / NLR	Lower	530, 0.100, NNW
H209	CON EDISON SERVICE B	40 COOPER SQ FRONT O	RCRA NonGen / NLR, FINDS	Lower	538, 0.102, NE
H210	CON EDISON	40 COOPER SQ FRONT O	NY MANIFEST	Lower	538, 0.102, NE
G211	SPILL NUMBER 9812634	8 EAST 3RD ST	NY Spills	Lower	538, 0.102, SE
G212	MEN'S SHELTER	8 EAST 3RD STREET	NY AST	Lower	538, 0.102, SE
N213	CON EDISON SERVICE B	327 BOWERY FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	539, 0.102, SE
N214	CON EDISON SERVICE B	327 BOWERY FRONT OF	NJ MANIFEST	Lower	539, 0.102, SE
L215	718 APT INC	718 BROADWAY	NY AST	Lower	539, 0.102, North
K216	49 BLEECKER ST	49 BLEECKER STREET	NY AST	Higher	539, 0.102, SSW
L217	PARKING GARAGE	714 BROADWAY	NY Spills	Lower	541, 0.102, NNW
J218	60 EAST 4TH STREET	60 EAST 4TH STREET	NY AST	Lower	544, 0.103, ESE
M219	CON EDISON	65 BLEEKER STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	554, 0.105, SW
K220	CON EDISON GAS DRIP:	BLECKER ST & ELIZABE	RCRA NonGen / NLR, NY MANIFEST	Higher	554, 0.105, South
K221	CON EDISON GAS DRIP:	BLECKER ST & ELIZABE	NJ MANIFEST	Higher	554, 0.105, South
K222	CON EDISON SERVICE B	BLEECKER ST & ELIZAB	RCRA NonGen / NLR, NY MANIFEST	Higher	554, 0.105, South
O223	419 LAFAYETTE STREET	419 LAFAYETTE STREET	NY AST	Lower	561, 0.106, NNE
J224	COOPER SQ MHA	59 -61 EAST 4TH ST.	NY AST	Lower	563, 0.107, ESE
J225	216 EAST 5TH ST	216 EAST 5TH STREET	NY AST	Lower	566, 0.107, East
M226	JOHNS DRY CLEANERS C	652 BROADWAY	EDR Hist Cleaner	Lower	566, 0.107, WSW
J227	67 EAST 4TH STREET	67 EAST 4TH STREET	NY AST	Lower	566, 0.107, ESE
L228	WASHINGTON PLACE APT	716 BROADWAY	NY AST	Lower	568, 0.108, NNW
L229	MEYER COMPLEX	2-6 WASHINGTON PLACE	NY AST	Lower	569, 0.108, NNW
H230	207 EAST 5TH ST	207 EAST 5TH ST	NY AST	Lower	574, 0.109, ENE
H231	COOPER 25 ASSOCIATES	25 COOPER SQUARE	NY UST, NY AST	Lower	583, 0.110, ENE
J232	218 EAST 5TH STREET	218 EAST 5TH STREET	NY AST	Lower	588, 0.111, East
J233	236 E 5TH ST	236 E 5TH ST	NY AST	Lower	588, 0.111, East

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
J234	WHALEDENT INTL	236 5TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	588, 0.111, East
N235	CON EDISON SERVICE B	8 E 2ND ST & BOWERY	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	589, 0.112, SSE
J236	69 EAST 4TH STREET	69 EAST 4TH STREET	NY AST	Lower	590, 0.112, ESE
K237	CON EDISON MANHOLE:	341 LAFAYETTE ST FRO	RCRA NonGen / NLR, NY MANIFEST	Higher	592, 0.112, SW
J238	LOT 18,TAXBLOCK 459	64 EAST 4 STREET	NY E DESIGNATION	Lower	593, 0.112, ESE
K239	CON EDISON SERVICE B	BLEECKER ST & LAFAYE	RCRA NonGen / NLR, NY MANIFEST	Higher	597, 0.113, SW
K240	MTA NYCT BLEECKER ST	BLEECKER & LAFAYETTE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	597, 0.113, SW
K241	CONSOLIDATED EDISON	333 LAFAYETTE ST	NY MANIFEST	Higher	603, 0.114, SW
K242	36 BLEECKER ST	36 BLEECKER STREET	NY AST	Higher	605, 0.115, SSW
J243	211 EAST 5TH STREET	211 EAST 5TH STREET	NY AST	Lower	610, 0.116, East
K244	SHEEN CENTER	18 BLEECKER STREET	NY UST	Higher	613, 0.116, South
J245	LOT 51,TAXBLOCK 460	71 EAST 4 STREET	NY E DESIGNATION	Lower	614, 0.116, ESE
K246	PLANNED PARENTHOOD O	26 BLEECKER STREET	NY AST	Higher	615, 0.116, South
M247	APARTMENT	648 BROADWAY	NY LTANKS	Lower	615, 0.116, WSW
M248	648 BROADWAY	648 BROADWAY	NY AST	Lower	615, 0.116, WSW
J249	CONSOLIDATED EDISON	V44150-66 E 4TH ST	NY MANIFEST	Lower	616, 0.117, ESE
K250	36 BLEECKER ST	36 BLEECKER STREET	NY UST	Higher	622, 0.118, SSW
L251	NEW YORK UNIVERSITY	2-4 WASHINGTON PL	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Lower	624, 0.118, NNW
K252	CON EDISON - MANHOLE	40 BLEECKER ST	NY MANIFEST	Higher	627, 0.119, SSW
M253	BLEECKER TOWER TENAN	644 BROADWAY	NY AST	Lower	627, 0.119, WSW
M254	COMMERCIAL	644 BROADWAY	NY Spills	Lower	627, 0.119, WSW
M255	SPILL NUMBER 0209371	644 BROADWAY	NY Spills	Lower	627, 0.119, WSW
K256	CON EDISON	42 BLEECKER ST	NY MANIFEST	Higher	628, 0.119, SSW
M257	652 BROADWAY	652 BROADWAY	NY AST	Lower	630, 0.119, WSW
P258	GOUVERNEUR & CO	10 BLEECKER ST APT 4	EDR Hist Cleaner	Higher	631, 0.120, South
J259	66 68 E 4TH STREET E	66 E 4TH ST	EDR Hist Auto	Lower	631, 0.120, ESE
K260	CON EDISON	48 BLEEKER ST	RCRA NonGen / NLR, NY MANIFEST	Higher	635, 0.120, SSW
J261	215 E. 5TH ST	215 E. 5TH ST	NY Spills	Lower	636, 0.120, East
M262	CON EDISON SERVICE B	657 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	638, 0.121, West
M263	CON EDISON SERVICE B	657 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	638, 0.121, West
M264	BROADWAY CLEANERS IN	657 BROADWAY	EDR Hist Cleaner	Lower	638, 0.121, West
N265	321 BOWERY COURT LLC	321 BOWERY STREET	NY Spills	Lower	638, 0.121, SSE
O266	CON EDISON SERVICE B	428 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	648, 0.123, NNE
O267	428-430 LAFAYETTE ST	428-430 LAFAYETTE ST	NY AST	Lower	648, 0.123, NNE
O268	CON EDISON SERVICE B	428 LAFAYETTE ST	NJ MANIFEST	Lower	648, 0.123, NNE
Q269	CON EDISON BENZENE A	COOPER SQ & EAST 6TH	NY Spills	Lower	648, 0.123, ENE
J270	LOT 23,TAXBLOCK 460	224 EAST 5 STREET	NY E DESIGNATION	Lower	655, 0.124, East
M271	65 BLEECKER STREET	65 BLEECKER STREET	NY AST	Lower	657, 0.124, WSW
M272	CON EDISON SERVICE B	653 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	658, 0.125, West

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q273	CON EDISON VAULT: 99	41 COOPER SQ	RCRA NonGen / NLR, FINDS	Lower	659, 0.125, ENE
Q274	CON EDISON	41 COOPER SQ VAULT 9	NY MANIFEST	Lower	659, 0.125, ENE
Q275	CON EDISON VAULT: 99	41 COOPER SQ	RCRA NonGen / NLR, FINDS	Lower	659, 0.125, ENE
Q276	CON EDISON VAULT: 93	41 COOPER SQ VAULT 9	RCRA NonGen / NLR	Lower	659, 0.125, ENE
Q277	CON EDISON	41 COOPER SQ	NY MANIFEST	Lower	659, 0.125, ENE
Q278	CON EDISION	41 COOPER SQ	NY MANIFEST	Lower	659, 0.125, ENE
Q279	COOPER UNION ENGINEE	41 COOPER SQ	RCRA-SQG, FINDS	Lower	659, 0.125, ENE
Q280	CON EDISON SERVICE B	41-55 COOPER SQ FRON	RCRA NonGen / NLR, NY MANIFEST	Lower	659, 0.125, ENE
Q281	CON EDISON SERVICE B	41-55 COOPER SQ FRON	NJ MANIFEST	Lower	659, 0.125, ENE
Q282	CON EDISON VAULT: 99	41 COOPER SQ VAULT 9	RCRA NonGen / NLR, FINDS	Lower	659, 0.125, ENE
R283	CON EDISON	250 MERCER ST	NY MANIFEST	Lower	661, 0.125, WNW
J284	75 EAST 4TH STREET	75 EAST 4TH STREET	NY AST	Lower	662, 0.125, ESE
S285	THE NOHO STAR BUILDI	54 BLEECKER STREET (	NY AST	Higher	668, 0.127, SW
O286	V3178	423 LAFAYETTE STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	670, 0.127, NNE
O287	CON EDISON	430 LAFAYETTE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	674, 0.128, NNE
O288	CON EDISON	430 LAFAYETTE ST	NY MANIFEST	Lower	674, 0.128, NNE
O289	CON EDISON	430 LAFAYETTE ST	NJ MANIFEST	Lower	674, 0.128, NNE
N290	BREMEN HOUSE INC.	312 BOWERY	NY AST	Higher	676, 0.128, South
L291	NEW YORK UNIVERSITY	726 BROADWAY	NY MANIFEST	Lower	676, 0.128, North
L292	NEW YORK UNIVERSITY	726-730 BROADWAY	NY AST	Lower	676, 0.128, North
L293	NEW YORK UNIVERSITY	726 BROADWAY	RCRA-CESQG	Lower	676, 0.128, North
Q294	CON EDISON	208 E 6TH ST & 2ND A	NY MANIFEST	Lower	677, 0.128, ENE
K295	CON EDISON	316 MOTT ST & HOUSTO	NY MANIFEST	Higher	679, 0.129, South
K296	NEW MOTT APARTMENT C	316 MOTT STREET	NY AST	Higher	679, 0.129, South
O297	JOSEPH PAPP PUBLIC T	425 LAFAYETTE STREET	NY UST, NY AST	Lower	682, 0.129, NNE
O298	CONSOLIDATED EDISON	425 LAFAYETTE ST	NY MANIFEST	Lower	682, 0.129, NNE
O299	CON EDISON MANHOLE 3	425 LAFAYETTE ST	NJ MANIFEST	Lower	682, 0.129, NNE
O300	CON EDISON MANHOLE 3	425 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	682, 0.129, NNE
J301	CON EDISON SERVICE B	228 E 5TH ST FRONT O	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	683, 0.129, East
J302	CON EDISON SERVICE B	228 E 5TH ST FRONT O	NJ MANIFEST	Lower	683, 0.129, East
N303	317 BOWERY	317 BOWERY	NY UST	Lower	694, 0.131, SSE
R304	250 MERCER SQ OWNER	250 MERCER ST	NY AST	Lower	695, 0.132, WNW
K305	304 MULBERRY STREET	304 MULBERRY STREET	NY AST	Higher	695, 0.132, SSW
T306	H21 EAST 3RD STREET	21 EAST 3RD STREET	NY AST	Lower	696, 0.132, ESE
Q307	50 COOPER SQUARE	50 COOPER SQUARE	NY AST	Lower	697, 0.132, NE
M308	CON EDISON SERVICE B	166-168 CROSBY ST &	RCRA NonGen / NLR, NY MANIFEST	Lower	697, 0.132, SW
M309	CON ED	164 CROSBY ST	NY MANIFEST	Lower	698, 0.132, SW
M310	CON EDISON SERVICE B	647 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	699, 0.132, WSW
R311	NEW YORK UNIVERSITY	251 MERCER ST	NY Spills, RCRA NonGen / NLR, NY MANIFEST	Lower	701, 0.133, WNW

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
R312	NYU CENTRAL PLANT	251 MERCER ST	NY LTANKS, NY Spills, US AIRS, NY AIRS	Lower	701, 0.133, WNW
R313	CENTRAL HEATING PLAN	251 MERCER STREET	NY UST	Lower	701, 0.133, WNW
R314	CENTRAL HEATING PLAN	251 MERCER STREET	NY AST	Lower	701, 0.133, WNW
O315	CON EDISON SERVICE B	429 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	702, 0.133, NNE
L316	CON EDISON	717 BROADWAY	NY MANIFEST	Lower	706, 0.134, North
L317	NYU WASHINGTON SQUAR	715 BROADWAY	NY AST	Lower	711, 0.135, North
L318	NYU TISCH SCHOOL OF	721-725 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	718, 0.136, North
U319	SPILL NUMBER 0000672	77 BLEECKER ST	NY LTANKS	Lower	718, 0.136, West
U320	CON EDISON	F/O 377 BLEEKER ST	NY MANIFEST	Lower	718, 0.136, West
U321	77 BLEECKER ST CORP	77 BLEECKER STREET	NY AST	Lower	718, 0.136, West
M322	640 REALTY & 86 REAL	640 BROADWAY	NY AST	Lower	725, 0.137, WSW
M323	CON EDISON SERVICE B	640 BROADWAY FRONT O	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	725, 0.137, WSW
N324	CON EDISON SERVICE B	307 BOWERY FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	726, 0.138, SSE
O325	APARTMENT COMPLEX	434 LAFAYETTE ST	NY LTANKS	Lower	728, 0.138, NNE
M326	CON EDISON	BLEEKER ST & BROADWA	NY MANIFEST	Lower	729, 0.138, WSW
M327	CON EDISON	BROADWAY & BLEEKER S	NY MANIFEST	Lower	729, 0.138, WSW
M328	CON EDISON MANHOLE 5	BROADWAY & BLEEKER S	RCRA NonGen / NLR, NJ MANIFEST	Lower	729, 0.138, WSW
Q329	C-SQUAREWOOD LLC	52-62 COOPER SQ	RCRA NonGen / NLR, FINDS, ECHO	Lower	729, 0.138, NE
K330	CON EDISON	315 MOTT ST	NJ MANIFEST	Higher	735, 0.139, SSW
K331	CON EDISON	315 MOTT ST	NY MANIFEST	Higher	735, 0.139, SSW
K332	CON EDISON	315 MOTT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	735, 0.139, SSW
U333	CON ED - V 2708	71 BLEEKER ST	RCRA NonGen / NLR, NY MANIFEST	Lower	743, 0.141, WSW
V334	CON EDISON SERVICE B	216 E 6 ST FRONT OF	NJ MANIFEST	Lower	744, 0.141, ENE
V335	CON EDISON SERVICE B	216 E 6 ST FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	744, 0.141, ENE
K336	ELG MOTT STREET LLC	LFG MOTT STREET, LLC	NY UST	Higher	750, 0.142, SSW
P337	OUR LADY OF LORETO R	309 ELIZABETH ST	NY UST	Higher	751, 0.142, South
O338	COMMERCIAL BUILDING	440 LAFAYETTE AVE	NY LTANKS	Lower	760, 0.144, NNE
O339	CON EDISON MANHOLE 3	436 LAFAYETTE ST	NJ MANIFEST	Lower	760, 0.144, NNE
O340	LAFAYETTE ASTOR ASSO	436-440 LAFAYETTE ST	NY AST	Lower	760, 0.144, NNE
O341	CON EDISON	F/O 436 LAFAYETTE ST	NY MANIFEST	Lower	760, 0.144, NNE
O342	CON EDISON MANHOLE:	436 LAFFAYETTE AVE S	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	760, 0.144, NNE
O343	CON EDISON MANHOLE 3	436 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	760, 0.144, NNE
O344	CON EDISON MANHOLE:	436 LAFFAYETTE AVE S	NJ MANIFEST	Lower	760, 0.144, NNE
O345	CON EDISON - MANHOLE	436 LAFAYETTE ST AND	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Lower	760, 0.144, NNE
O346	CON EDISON	436 LAFAYETTE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	760, 0.144, NNE
W347	THE 62 COOPER SQUARE	54-62 COOPER SQUARE	NY AST	Lower	760, 0.144, NE
P348	303 ELIZABETH ST.	303 ELIZABETH ST.	NY LTANKS	Higher	761, 0.144, South
M349	OFFICE BUILDING	636 BROADWAY	NY LTANKS, NY Spills	Lower	766, 0.145, WSW
M350	636 BROADWAY ASSOCIA	636 BROADWAY, SUITE	NY UST	Lower	766, 0.145, WSW

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M351	CON EDISON	636 BROADWAY	NY Spills, NY MANIFEST	Lower	766, 0.145, WSW
M352	636 BROADWAY ASSOCIA	636 BROADWAY, SUITE	NY AST	Lower	766, 0.145, WSW
Q353	CON EDISON	14 TARAS SCHEVCHENKO	NY MANIFEST	Lower	768, 0.145, ENE
Q354	CON EDISON	14 TARAS SCHEVCHENKO	NY MANIFEST	Lower	768, 0.145, ENE
Q355	CON EDISON	14 TARAS SCHEVCHENKO	NY MANIFEST	Lower	768, 0.145, ENE
Q356	CON EDISON	14 TARAS SCHEVCHENKO	NY MANIFEST	Lower	768, 0.145, ENE
P357	CON EDISON	306 MOTT ST	NY MANIFEST	Higher	770, 0.146, SSW
P358	CON EDISON	306 MOTT ST	NJ MANIFEST	Higher	770, 0.146, SSW
P359	CON EDISON	306 MOTT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	770, 0.146, SSW
P360	SOHO COURT	301 ELIZABETH STREET	NY AST	Higher	770, 0.146, South
S361	DEMAIMON CORP	156 CROSBY STREET	NY AST	Higher	771, 0.146, SW
S362	159-02 CROSS BAY BLV	159-02 CROSS BAY BLV	NY LTANKS	Higher	771, 0.146, SW
W363	CON EDISON	56 COOPER SQ	NY MANIFEST	Lower	773, 0.146, NE
W364	CON EDISON	56 COOPER SQ	NY MANIFEST	Lower	773, 0.146, NE
S365	325 LAFAYETTE TENANT	325/331 LAFAYETTE ST	NY AST	Higher	773, 0.146, SW
X366	736 BROADWAY BUILDIN	736 BROADWAY	NY AST	Lower	773, 0.146, North
V367	CON EDISON	229 E 5TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	779, 0.148, East
V368	CON EDISON	229 E 5TH ST	NJ MANIFEST	Lower	779, 0.148, East
V369	CON EDISON	229 E 5TH ST	NY MANIFEST	Lower	779, 0.148, East
S370	CON EDISON	324 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Higher	782, 0.148, SW
X371	CON EDISON SERVICE B	736 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	782, 0.148, North
T372	CON EDISON	85 E 4TH ST	NJ MANIFEST	Lower	784, 0.148, ESE
T373	CON EDISON SERVICE B	85 E 4TH ST & COOPER	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	784, 0.148, ESE
T374	CON EDISON	85 E 4TH ST	RCRA NonGen / NLR	Lower	784, 0.148, ESE
P375	SPILL NUMBER 9411282	ELIZABETH ST & HOUST	NY LTANKS	Higher	785, 0.149, South
P376	CON EDISON SERVICE B	308 BOWERY & HOUSTON	RCRA NonGen / NLR, NY MANIFEST	Higher	790, 0.150, SSE
T377	CON EDISON	30 E 3RD ST	NY MANIFEST	Lower	792, 0.150, SE
T378	30 EAST 3RD STREET	30 EAST 3RD STREET	NY LTANKS	Lower	792, 0.150, SE
S379	CONSOLIDATED EDISON-	323 LAFAYETTE	NY MANIFEST	Higher	793, 0.150, SW
Y380	632 BROADWAY	632 BROADWAY	NY AST	Lower	801, 0.152, WSW
Y381	CON EDISION - MH 272	634 BROADWAY 634 BRO	RCRA NonGen / NLR, NY MANIFEST	Lower	801, 0.152, WSW
P382	CON EDISON	3 E 1ST ST	NY MANIFEST	Higher	802, 0.152, SSE
X383	CORINNE OFFSET INC	737 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	803, 0.152, North
X384	CON EDISON SERVICE B	738 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	805, 0.152, North
Z385	CON EDISON - E 2ND	26 E 2ND ST	PA MANIFEST	Lower	807, 0.153, SE
P386	CON EDISON SERVICE B	302 BOWERY FRONT OF	NJ MANIFEST	Higher	812, 0.154, South
P387	CON EDISON SERVICE B	302 BOWERY FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	812, 0.154, South
S388	LAFAYETTE AUTO REPAI	321 LAFAYETTE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	813, 0.154, SW
AA389	CVPII LLC CHRYSTIE P	5 EAST 1ST STREET	NY AST	Higher	814, 0.154, SSE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AB390	SCHULMANN PROPERTIES	302 MOTT STREET	NY AST	Higher	816, 0.155, SSW
AB391	CON EDISON SERVICE B	302 MOTT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	816, 0.155, SSW
W392	CON EDISON SERVICE B	439 LAFAYETTE ST	RCRA NonGen / NLR, NY MANIFEST	Lower	821, 0.155, NNE
V393	CON EDISON SERVICE B	222 E 6 ST FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	821, 0.155, East
V394	CON EDISON SERVICE B	222 E 6 ST FRONT OF	NJ MANIFEST	Lower	821, 0.155, East
V395	MORTON TABAK	233 EAST 5TH STREET	NY AST	Lower	822, 0.156, East
AB396	CON EDISON	298 MULBERRY ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	827, 0.157, SSW
AB397	CVS # 10407	298 MULBERRY STREET	PA MANIFEST	Higher	827, 0.157, SSW
AB398	CON EDISON	298 MULBERRY ST	NJ MANIFEST	Higher	827, 0.157, SSW
AB399	CON EDISON	298 MULBERRY ST	NY MANIFEST	Higher	827, 0.157, SSW
AB400	CVS PHARMACY #10407	298 MULBERRY ST	RCRA-LQG, NY MANIFEST	Higher	827, 0.157, SSW
T401	CON EDISON	82 E 4TH ST	RCRA NonGen / NLR	Lower	827, 0.157, ESE
T402	CON EDISON	82 E 4TH ST	NJ MANIFEST	Lower	827, 0.157, ESE
AA403	CON EDISON SERVICE B	6 E 1ST ST	RCRA NonGen / NLR, NY MANIFEST	Lower	829, 0.157, SSE
AA404	CON EDISON SERVICE B	6 E 1ST ST	NJ MANIFEST	Lower	829, 0.157, SSE
S405	CON EDISON	305 MULBERRY ST	NY MANIFEST	Higher	830, 0.157, SW
S406	CON EDISON	305 MULBERRY ST	NJ MANIFEST	Higher	830, 0.157, SW
S407	CON EDISON	305 MULBERRY ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	830, 0.157, SW
V408	226 E. 6TH ST.	226 E. 6TH STREET	NY AST	Lower	835, 0.158, East
U409	BAHMAN CLEANERS	210 MERCER ST	NY Spills, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	836, 0.158, West
U410	BAHMAN CLEANERS	210 MERCER STREET	NY DRYCLEANERS	Lower	836, 0.158, West
Z411	SLOYER-FORMAN, INC.	21 EAST 2ND STREET	NY AST	Lower	836, 0.158, SE
U412	215 MERCER ST	215 MERCER ST	RCRA-CESQG	Lower	837, 0.159, West
V413	CON EDISON MANHOLE:	235 W 5OTH ST FRONT	NJ MANIFEST	Lower	844, 0.160, East
V414	235 EAST 5TH STREET	235 EAST 5TH STREET	NY AST	Lower	844, 0.160, East
AB415	298 MULBERRY STREET	298 MULBERRY STREET	NY AST	Higher	848, 0.161, SSW
V416	ORDER OF ST BASIL	215 E 6TH ST	NY AST	Lower	854, 0.162, ENE
Z417	CON EDISON	30 E 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	854, 0.162, SE
Z418	CON EDISON	30 E 2ND ST	NJ MANIFEST	Lower	854, 0.162, SE
Z419	CON EDISON	30 E 2ND ST	NY MANIFEST	Lower	854, 0.162, SE
V420	228 EAST 6TH STREET	228 EAST 6TH STREET	NY AST	Lower	854, 0.162, East
AC421	CON EDISON	69 2ND AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	855, 0.162, ESE
AC422	CON EDISON	69 2ND AVE	NJ MANIFEST	Lower	855, 0.162, ESE
Y423	628 BROADWAY, SUITE	628 BROADWAY	NY AST	Lower	856, 0.162, WSW
AC424	69 SECOND AVENUE, LL	69 2ND AVENUE	NY AST	Lower	859, 0.163, ESE
AC425	CON ED	69 2ND AVE	NY Spills, NY MANIFEST	Lower	859, 0.163, ESE
AD426	CON EDISON	7 WASHINGTON TERR &	NY MANIFEST	Lower	860, 0.163, NNW
AD427	7 WASHINGTON PLACE	7 WASHINGTON PLACE	NY AST	Lower	860, 0.163, NNW
T428	CON EDISON	36 E 3RD ST	NY MANIFEST	Lower	861, 0.163, SE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
U429	88 BLEECKER ST OWNER	88 BLEECKER ST	NY AST	Lower	865, 0.164, WSW
T430	57 2ND AVE	57 SECOND AVENUE	NY AST	Lower	866, 0.164, ESE
AE431	237 EAST REALTY LLC	237 EAST 5TH ST	NY AST	Lower	868, 0.164, East
X432	740 BROADWAY	740 BROADWAY	NY UST	Lower	869, 0.165, North
X433	ABOVE GROUND TANK	740 BROADWAY	NY LTANKS	Lower	869, 0.165, North
X434	CON EDISON	744 BROADWAY	NY MANIFEST	Lower	869, 0.165, North
W435	54-62 COOPERS SQUARE	62 COOPERS SQUARE	NY LTANKS	Lower	878, 0.166, NE
W436	CON EDISON	62 COOPER SQUARE	NY MANIFEST	Lower	878, 0.166, NE
T437	CON EDISON	86 E 4 ST	NY MANIFEST	Lower	881, 0.167, ESE
Y438	CON EDISION - MH2722	626 BROADWAY AND E.H	RCRA NonGen / NLR, NY MANIFEST	Lower	881, 0.167, WSW
Y439	CON EDISON MANHOLE 2	626 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	881, 0.167, WSW
Z440	32-34 E 2 ST	32-34 EAST 2ND STREE	NY AST	Lower	884, 0.167, SE
AC441	CON EDISON SERVICE B	73-75 2ND AVE & 4TH	NJ MANIFEST	Lower	885, 0.168, ESE
T442	CON EDISON	45 2ND AVE	NY MANIFEST	Lower	886, 0.168, SE
AF443	CON EDISON	29 W 4TH ST	RCRA NonGen / NLR	Lower	888, 0.168, NW
AF444	CON ED	29 W 4TH ST	NY MANIFEST	Lower	888, 0.168, NW
AF445	CON EDISON	29 W 4TH ST	NJ MANIFEST	Lower	888, 0.168, NW
U446	CON EDISON	96 BLEEKER ST	NY MANIFEST	Lower	893, 0.169, WSW
Z447	CON EDISON SERVICE B	41 E 2ND AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	896, 0.170, SE
Z448	CON EDISON	41 2 AV	NY MANIFEST	Lower	896, 0.170, SE
V449	232 EQUITIES CORPORA	232 EAST 6TH ST	NY AST	Lower	896, 0.170, East
U450	CON EDISON SERVICE B	226-28 MERCER ST & B	RCRA NonGen / NLR, FINDS	Lower	908, 0.172, West
AD451	NYU	14 WASHINGTON PLACE	NY AST	Lower	910, 0.172, NW
Y452	MOKLAM ENTERPRISES I	622 BROADWAY	NY AST	Lower	911, 0.173, WSW
Y453	MOKLAM ENTERPRISES I	622 BROADWAY	PA MANIFEST	Lower	911, 0.173, WSW
Y454	MOKLAM BUILDING	622 BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	911, 0.173, WSW
Y455	BEST BUY	622 BROADWAY	RCRA-CESQG, NY MANIFEST	Lower	911, 0.173, WSW
AC456	99 E 4 ST	99 EAST 4TH STREET	NY AST	Lower	914, 0.173, ESE
AC457	CON EDISON	73-75 2ND AVE & 4TH	NY MANIFEST	Lower	915, 0.173, ESE
X458	CON EDISON SERVICE B	749-51 W BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	919, 0.174, North
AB459	CON EDISON	316 MOTT ST & HOUSTO	RCRA NonGen / NLR, FINDS, ECHO	Higher	919, 0.174, SSW
AA460	CON EDISON	9 E 1ST ST	NY MANIFEST	Lower	923, 0.175, SSE
T461	EAST VILLAGE REALTY	53 2ND AVENUE A/K/A	NY AST	Lower	925, 0.175, SE
V462	ORDER OF ST. BASIL	16-22 E 7TH ST	NY AST	Lower	926, 0.175, ENE
AC463	CON EDISON SERVICE B	69-71 2ND AVE & 4TH	RCRA NonGen / NLR	Lower	927, 0.176, ESE
AC464	CON EDISON	69-71 2ND AVE & 4TH	NY MANIFEST	Lower	927, 0.176, ESE
AD465	NEW YORK UNIVERSITY	15 WASHINGTON PLACE	NY AST	Lower	929, 0.176, NNW
Y466	AMOCO GAS STATION	620 BROADWAY	NY LTANKS, NY Spills	Lower	933, 0.177, SW
AC467	CON EDISON	EAST 4 ST & 2ND AV	NY MANIFEST	Lower	934, 0.177, ESE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC468	CON EDISON SERVICE B	E 4TH ST & 2 ND AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	934, 0.177, ESE
AC469	CON EDISON SERVICE B	83-85 2ND AVE & 4TH	RCRA NonGen / NLR, FINDS	Lower	934, 0.177, ESE
AC470	CON EDISON SERVICE B	79 2ND AVE & 4TH ST	RCRA NonGen / NLR, FINDS	Lower	934, 0.177, ESE
AC471	CON EDISON SERVICE B	73-75 2ND AVE & 4TH	RCRA NonGen / NLR, FINDS	Lower	934, 0.177, ESE
AG472	CON EDISON SERVICE B	30 E 7TH ST & HALL P	RCRA NonGen / NLR, FINDS	Lower	936, 0.177, ENE
T473	CON EDISON MANHOLE 5	E 3RD ST & 2ND AVE S	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	937, 0.177, SE
Y474	627 BROADWAY	627 BROADWAY	NY AST	Lower	937, 0.177, WSW
Y475	JIM HENSON CO THE	627 BROADWAY - 9TH F	RCRA NonGen / NLR, NY MANIFEST	Lower	937, 0.177, WSW
AF476	CON EDISON	WEST 4TH AVE & GREEN	NY MANIFEST	Lower	937, 0.177, NW
AF477	CON EDISON SERVICE B	WEST 4TH AVE & GREEN	RCRA NonGen / NLR, FINDS	Lower	937, 0.177, NW
AF478	CON EDISON	WEST 4TH AVE & GREEN	NY MANIFEST	Lower	937, 0.177, NW
AF479	CON EDISON SERVICE B	WEST 4TH AVE & GREEN	RCRA NonGen / NLR	Lower	937, 0.177, NW
AF480	CON EDISON	WEST 4TH AVE & GREEN	NY MANIFEST	Lower	937, 0.177, NW
AF481	CON EDISON SERVICE B	WEST 4TH AVE & GREEN	RCRA NonGen / NLR	Lower	937, 0.177, NW
T482	CON EDISON	E 3 ST & 2 AVE	NY MANIFEST	Lower	939, 0.178, SE
AF483	CON EDISON SERVICE B	237 GREENE ST & 4TH	RCRA NonGen / NLR, FINDS	Lower	939, 0.178, NW
AH484	COOPER UNION SCHOOL	50 ASTOR PL	RCRA-SQG, FINDS, ECHO	Lower	940, 0.178, NNE
AH485	COOPER UNION ADVANCE	50 ASTOR PL	NY MANIFEST	Lower	940, 0.178, NNE
AD486	285 MERCER STREET	285 MERCER STREET	NY AST	Lower	943, 0.179, NNW
X487	CON EDISON	292 MERCER ST	NY MANIFEST	Lower	945, 0.179, North
AD488	11 WAVERLY ASSOC	11 WAVERLY PL	NY LTANKS	Lower	947, 0.179, NNW
AD489	ELEVEN WAVERLY ASSOC	11 WAVERLY PL	NY AST	Lower	947, 0.179, NNW
AB490	CONED	MOTT ST & HOUSTON ST	NY MANIFEST	Higher	948, 0.180, SSW
AI491	NYCTA - BROADWAY & L	E HOUSTON & CROSBY S	RCRA-SQG, NY MANIFEST	Higher	952, 0.180, SW
AD492	NEW YORK UNIVERSITY	12-16 WAVERLY PL	RCRA-SQG, NY MANIFEST	Lower	954, 0.181, NNW
X493	CONSOLIDATED EDISON	BROADWAY & ASTOR PLA	NY MANIFEST	Lower	956, 0.181, North
AC494	77 SECOND LLC	77 2ND AVENUE	NY AST	Lower	957, 0.181, ESE
AA495	AVALON BOWERY PLACE	11 EAST FIRST STREET	NY AST	Lower	959, 0.182, SSE
AE496	CON EDISON	95 2ND AVE	NY MANIFEST	Lower	963, 0.182, East
AG497	CON EDISON	61 COOPER SQ	NY MANIFEST	Lower	965, 0.183, NE
Z498	PETCO STORE #5816	31 2ND AVE	RCRA-CESQG, FINDS, ECHO	Lower	965, 0.183, SE
AD499	CON EDISON	12 WAVERLY PL	RCRA NonGen / NLR	Lower	968, 0.183, NNW
AD500	CON EDISON	12 WAVERLY PL	NJ MANIFEST	Lower	968, 0.183, NNW
AD501	NEW YORK UNIVERSITY	12-16 WAVERLY PLACE	NY MANIFEST	Lower	968, 0.183, NNW
AH502	CON EDISON VAULT: 96	51 ASTOR PL	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	979, 0.185, NNE
AH503	NYCDEP - HAZARDOUS M	51 ASTOR PL RM 643	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	979, 0.185, NNE
AH504	MINSKOFF EQUITY BLDG	51 ASTOR PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	979, 0.185, NNE
AH505	CON EDISON VAULT: 96	51 ASTOR PL	RCRA NonGen / NLR, NY MANIFEST	Lower	979, 0.185, NNE
AC506	91 EAST 4TH ST	91 EAST 4TH ST	NY LTANKS	Lower	980, 0.186, ESE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC507	LEONARD FRANZBLAU	91 EAST 4TH STREET	NY UST	Lower	980, 0.186, ESE
AC508	RESIDENTIAL	91 EAST 4TH STREET	NY LTANKS	Lower	980, 0.186, ESE
AI509	AMOCO	610 BROADWAY	NY LTANKS, NY Spills	Lower	984, 0.186, SW
AI510	CON EDISON	610 BROADWAY	NY MANIFEST	Lower	984, 0.186, SW
AI511	AMOCO SERVICE STATIO	610 BROADWAY	NY UST	Lower	984, 0.186, SW
AI512	CON EDISON	610 BROADWAY	RCRA NonGen / NLR	Lower	984, 0.186, SW
AI513	CON EDISON	610 BROADWAY	NJ MANIFEST	Lower	984, 0.186, SW
AI514	TRIBECA GAS INC	610 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	984, 0.186, SW
AH515	CON EDISON SERVICE B	444 LAFAYETTE ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	989, 0.187, NNE
Z516	CON EDISON SERVICE B	44 E 2ND ST & 2ND AV	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NJ...	Lower	991, 0.188, SE
AH517	CON EDISON SERVICE B	LAFAYETTE ST & ASTOR	RCRA NonGen / NLR, NY MANIFEST	Lower	991, 0.188, NNE
AH518	MTA NYCT ASTOR PL ST	ASTOR PL & LAFAYETTE	NJ MANIFEST	Lower	991, 0.188, NNE
AH519	MTA NYCT ASTOR PL ST	ASTOR PL & LAFAYETTE	RCRA NonGen / NLR, NY MANIFEST	Lower	991, 0.188, NNE
AH520	CONSOLIDATED EDISON	LAFAYETTE ST & ASTOR	NY MANIFEST	Lower	991, 0.188, NNE
AH521	CON EDISON MANHOLE:	E LAFAYETTE ST & AST	RCRA NonGen / NLR, NY MANIFEST	Lower	991, 0.188, NNE
AH522	CON EDISON	LAFAYETTE ST & ASTOR	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	991, 0.188, NNE
AH523	CON EDISON MANHOLE:	ASTOR PL & LAFAYETTE	RCRA NonGen / NLR	Lower	991, 0.188, NNE
AH524	CON EDISON GAS DRIP	ASTOR PL & LAFAYETTE	RCRA NonGen / NLR, NY MANIFEST	Lower	991, 0.188, NNE
AH525	CON EDISON MANHOLE:	LAFAYETTE ST & ASTOR	RCRA NonGen / NLR, NY MANIFEST	Lower	991, 0.188, NNE
AH526	CON EDISON	ASTOR PL & LAFAYETTE	NY MANIFEST	Lower	991, 0.188, NNE
AJ527	40-42 EAST 3RD STREE	40-42 EAST 3RD STREE	NY AST	Lower	991, 0.188, SE
Y528	625 BROADWAY	625 BROADWAY	NY AST	Lower	992, 0.188, WSW
AI529	CONSOLIDATED EDISON	LAFAYETTE ST & HOUST	NY MANIFEST	Higher	992, 0.188, SW
AC530	CONSOLIDATED EDISON	E 5TH & 2ND AVE	NY MANIFEST	Lower	993, 0.188, East
AC531	CON EDISON	2ND AVE & 5TH ST	NY MANIFEST	Lower	993, 0.188, East
AC532	CON EDISON SERVICE B	2ND AVE & 5TH ST	RCRA NonGen / NLR, FINDS	Lower	993, 0.188, East
AC533	CON EDISON	66 2ND AVE	NY MANIFEST	Lower	995, 0.188, ESE
AC534	300 EAST FIFTH STREE	300 EAST 5TH STREET	NY AST	Lower	995, 0.188, East
AC535	CON EDISON	64 2ND AVE	NY MANIFEST	Lower	995, 0.188, ESE
AC536	60-SECOND AVE CORP	60 SECOND AVE	NY AST	Lower	996, 0.189, ESE
Z537	CON EDISON	48 2ND AVE	NY MANIFEST	Lower	996, 0.189, SE
Y538	CON EDISON SERVICE B	623 BROADWAY FRONT	RCRA NonGen / NLR, NY MANIFEST	Lower	1003, 0.190, WSW
Y539	ISE REALTY GROUP, IN	623 BROADWAY	NY AST	Lower	1003, 0.190, WSW
Z540	CLOSED-LACKOF RECENT	44 SECOND AVENUE	NY LTANKS	Lower	1004, 0.190, SE
AC541	74 CLEANERS INC	74 SECOND AVE	RCRA-CESQG, NY MANIFEST	Lower	1009, 0.191, ESE
AC542	ALICE/HANNA/74 DRY C	74 SECOND AVE	NY DRYCLEANERS	Lower	1009, 0.191, ESE
Z543	CON EDISON	42 2ND AVE	NY MANIFEST	Lower	1009, 0.191, SE
AE544	CONSOLIDATED EDISON	255-261 NO. 6TH ST.	NY MANIFEST	Lower	1010, 0.191, East
AE545	CON EDISION - TM2828	255-261 NO. 6TH ST.	RCRA NonGen / NLR	Lower	1010, 0.191, East

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Z546	CON EDISON	27 2ND AVE	NY MANIFEST	Lower	1011, 0.191, SE
AK547	CON EDISON - VAULT 8	39 W3 ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1015, 0.192, WNW
AH548	V3554	75-20 ASTORIA BOULEV	RCRA NonGen / NLR, NY MANIFEST	Lower	1018, 0.193, NNE
Z549	CON EDISON SERVICE B	38 2ND AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1019, 0.193, SE
AB550	55 HOUSTON REALTY LL	55 EAST HOUSTON STRE	NY AST	Higher	1020, 0.193, SSW
AC551	CON EDISON	80 2ND AVE	NY MANIFEST	Lower	1024, 0.194, ESE
AF552	NEW YORK UNIVERSITY	35 W 4TH ST	RCRA-CESQG, FINDS, ECHO	Lower	1025, 0.194, NW
AL553	CON EDISON	23 2ND AVE	NY MANIFEST	Lower	1027, 0.195, SSE
AD554	NEW YORK UNIVERSITY	16 WAVERLY PLACE	NY AST	Lower	1027, 0.195, NNW
X555	APARTMENT HOUSE	300 MERCER STREET	NY UST	Lower	1029, 0.195, North
X556	APHRODITE FRENCH CLE	300 MERCER ST #1	NY DRYCLEANERS	Lower	1029, 0.195, North
X557	APT BUILDING TTF	300 MERCER ST	NY LTANKS	Lower	1029, 0.195, North
AM558	CON EDISON SERVICE B	41 E HOUSTON ST	NJ MANIFEST	Higher	1031, 0.195, SSW
AM559	CON EDISON SERVICE B	41 E HOUSTON ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1031, 0.195, SSW
AN560	LESTER/GLASSNER	36 EAST 7TH STREET	NY AST	Lower	1031, 0.195, ENE
AI561	GASETERIA	21 EAST HOUSTON STRE	NY LTANKS	Higher	1031, 0.195, SW
AI562	B P PRODUCTS NORTH A	21 E HOUSTON ST	RCRA-SQG, NY MANIFEST, NJ MANIFEST	Higher	1031, 0.195, SW
Y563	CABLE BUILDING	611 BROADWAY	NY AST	Lower	1031, 0.195, WSW
AL564	CON EDISON	15 E 1ST ST	NY MANIFEST	Lower	1032, 0.195, SSE
AC565	CON EDISON	84 2ND AVE	NY MANIFEST	Lower	1036, 0.196, ESE
AO566	CON EDISON - SERVICE	BOWERY AND E HOUSTON	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Higher	1037, 0.196, South
AF567	CONSOLIDATED EDISON	58 W 4OTH ST	NY MANIFEST	Lower	1037, 0.196, NW
AF568	CON ED	45 WEST 4TH ST	NY MANIFEST	Lower	1039, 0.197, NW
AJ569	CON EDISON	44 E 3RD ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1040, 0.197, SE
AJ570	CON EDISON	44 E 3RD ST	NY MANIFEST	Lower	1040, 0.197, SE
AJ571	CON EDISON	44 E 3RD ST	NJ MANIFEST	Lower	1040, 0.197, SE
AO572	CONSOLIDATED EDISON	HOUSTON ST & BOWERY	NY MANIFEST	Higher	1048, 0.198, South
AO573	CONSOLIDATED EDISON	BOWERY ST & E HOUSTO	NY MANIFEST	Higher	1048, 0.198, South
AP574	CON EDISON SERVICE B	COOPER SQ & ASTOR PL	RCRA NonGen / NLR, FINDS	Lower	1049, 0.199, NE
AP575	CON EDISON GAS DRIP:	COOPER SQ & W 4TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1049, 0.199, NE
AH576	CON EDISON SERVICE B	754 E BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	1050, 0.199, North
AQ577	N Y U	4 WASHINGTON SQUARE	NY AST	Lower	1054, 0.200, West
AI578	300 LAFAYETTE STREET	300 LAFAYETTE STREET	NY VCP	Higher	1056, 0.200, SW
AJ579	50 E 3RD ST	50 E 3RD ST	NY AST	Lower	1058, 0.200, SE
AB580	ALMARK HOLDING	284 MOTT STREET	NY AST	Higher	1060, 0.201, SSW
AG581	CON EDISON SERVICE B	2-4 ST MARKS	RCRA NonGen / NLR, NY MANIFEST	Lower	1063, 0.201, NE
AO582	CON EDISON	284 BOWERY	PA MANIFEST	Higher	1065, 0.202, South
AH583	CON EDISON GAS MAIN:	755 BROADWAY	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	1066, 0.202, North
AF584	NEW YORK UNIVERSITY	40 W 4TH ST	RCRA-SQG, NY MANIFEST	Lower	1073, 0.203, NW

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AI585	295 LAFAYETTE ST.	295 LAFAYETTE ST.	NY LTANKS	Higher	1076, 0.204, SW
AI586	GIGANTE VAZ & PARTNE	295 LAFAYETTE ST - 7	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1076, 0.204, SW
AI587	PRATT INSTITUTE - PU	295 LAFAYETTE ST 2ND	RCRA NonGen / NLR, ICIS, FINDS, ECHO, NY MANIFEST,...	Higher	1076, 0.204, SW
AI588	PUCK BUILDING	295 LAFAYETTE STREET	NY AST	Higher	1076, 0.204, SW
AE589	92 2ND AVENUE	92 SECOND AVENUE	NY AST	Lower	1077, 0.204, East
AE590	RED HOUSE REALTY COR	317 EAST 5TH STREET	NY AST	Lower	1077, 0.204, East
AR591	CON EDISON	297 MERCER ST	NY MANIFEST	Lower	1077, 0.204, North
AC592	CON ED	97 E 4TH ST	NY MANIFEST	Lower	1078, 0.204, ESE
AC593	CON EDISON	97 E 4TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1078, 0.204, ESE
AC594	CON EDISON	97 E 4TH ST	NY MANIFEST	Lower	1078, 0.204, ESE
AC595	CON EDISON	97 E 4TH ST	NJ MANIFEST	Lower	1078, 0.204, ESE
AO596	266 ELIZABETH ST	266 ELIZABETH ST	NY AST	Higher	1080, 0.205, South
AJ597	47 EAST 3RD STREET	47 EAST 3RD STREET	NY AST	Lower	1084, 0.205, ESE
AP598	248 NORTH 8TH STREET	248 NORTH 8TH STREET	NY VCP	Lower	1085, 0.205, NE
AE599	309 E. 5TH STREET	309 EAST FIFTH STREE	NY AST	Lower	1085, 0.205, East
AG600	CON EDISON SERVICE B	6-8 ST MARKS	RCRA NonGen / NLR, NY MANIFEST	Lower	1086, 0.206, ENE
AL601	24 SECOND AVE MOBIL	24 SECOND AVE & 1ST	NY LTANKS	Lower	1087, 0.206, SSE
AL602	WESTFIELD SECOND ASS	24 2ND AVE	NY UST	Lower	1087, 0.206, SSE
AL603	CON EDISON	24 2 AVE	NY E DESIGNATION, NY MANIFEST	Lower	1087, 0.206, SSE
AL604	GAS STATION	24 SECOND AVE	NY LTANKS	Lower	1087, 0.206, SSE
AL605	24 SECOND AVENUE OWN	24 SECOND AVENUE	NY UST	Lower	1087, 0.206, SSE
AG606	ST MARKS HOTEL	2 ST. MARKS PLACE	NY AST	Lower	1089, 0.206, NE
AL607	CON EDISON	28 2ND AVE	NY MANIFEST	Lower	1091, 0.207, SE
AH608	CON EDISON VAULT: 13	136 E 8TH ST FRONT O	RCRA NonGen / NLR, NY MANIFEST	Lower	1092, 0.207, NNE
AH609	CON EDISON VAULT: 33	136 E 8TH ST FRONT O	RCRA NonGen / NLR, NY MANIFEST	Lower	1092, 0.207, NNE
AP610	CON EDISON - MH 2434	2-4 ALBANY STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	1092, 0.207, NE
AI611	BP LAFAYETTE (FORMER	21 EAST HOUSTON STRE	NY UST, NY Spills	Lower	1093, 0.207, SW
AP612	CON EDISON MANHOLE:	E COOPER SQ & 4TH AV	NJ MANIFEST	Lower	1096, 0.208, NE
AP613	CON EDISON	4TH AVE & COOPER SQ	NJ MANIFEST	Lower	1096, 0.208, NE
AP614	CON EDISON	4TH AVE & COOPER SQ	NY MANIFEST	Lower	1096, 0.208, NE
AP615	CON EDISON	4TH AVE & COOPER SQ	RCRA NonGen / NLR, FINDS, ECHO	Lower	1096, 0.208, NE
AP616	MTA NYCT ASTOR PLACE	ASTOR PL & 4TH AVE	RCRA NonGen / NLR	Lower	1096, 0.208, NE
AP617	CON EDISON MANHOLE:	E COOPER SQ & 4TH AV	RCRA NonGen / NLR	Lower	1096, 0.208, NE
AO618	268 ELIZABETH ST PRO	268 ELIZABETH ST	NY AST	Higher	1097, 0.208, South
AM619	GOTTLIEB W REAL ESTA	284 MULBERRY ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1099, 0.208, SSW
AM620	285 MOTT ST	285 MOTT ST	NY AST	Higher	1100, 0.208, SSW
AP621	1-4 MILLIGAN PLACE	1-4 MILLIGAN PLACE	NY LTANKS	Lower	1102, 0.209, NE
AQ622	NEW YORK UNIVERSITY	1-4 WASHINGTON SQUAR	RCRA-SQG, NY MANIFEST	Lower	1103, 0.209, West
AP623	286-292 NORTH 8TH ST	286-292 NORTH 8TH ST	NY VCP	Lower	1105, 0.209, NE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AL624	CON EDISON	EAST 1ST ST & 2ND AV	NY MANIFEST	Lower	1106, 0.209, SSE
AL625	CON EDISON - 1ST	E 1ST & 2ND AVE	PA MANIFEST	Lower	1106, 0.209, SSE
AL626	CON EDISON SERVICE B	9 2ND AVE FRONT OF	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1107, 0.210, SSE
AE627	CON EDISON	208 E 6TH ST & 2ND A	RCRA NonGen / NLR, FINDS, ECHO	Lower	1109, 0.210, East
AP628	207 NORTH 8TH STREET	207 NORTH 8TH STREET	NY VCP	Lower	1113, 0.211, NE
AE629	CON EDISON MANHOLE	E 6 ST & 2ND AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1114, 0.211, East
AE630	CON EDISON SERVICE B	E 6TH ST & 2ND AVE	RCRA NonGen / NLR, FINDS	Lower	1114, 0.211, East
AE631	CON EDISON	E 6TH ST & 2ND AVE	NY MANIFEST	Lower	1114, 0.211, East
AG632	8 ST. MARKS PLACE	8 ST. MARKS PLACE	NY AST	Lower	1116, 0.211, ENE
AP633	219-223 NORTH 8TH ST	219-223 NORTH 8TH ST	NY VCP	Lower	1116, 0.211, NE
AS634	FILLMORE EAST APARTM	105 2ND AVENUE (223-	NY AST	Lower	1123, 0.213, East
AL635	CON ED	20 EAST 1ST ST	NY MANIFEST	Lower	1125, 0.213, SSE
AK636	CON EDISON - MANHOLE	100 W 4 ST	NY MANIFEST	Lower	1125, 0.213, NW
AG637	10 ST MARKS PL	10 ST MARKS PL	NY AST	Lower	1126, 0.213, ENE
AP638	1 ASTOR PLACE	1 ASTOR PLACE	NY AST	Lower	1126, 0.213, NE
AP639	CON EDISON	2-3 GREENWICH ST	NY MANIFEST	Lower	1126, 0.213, NE
AP640	CON EDISON SERVICE B	COOPER SQ & ST MARK	RCRA NonGen / NLR, NY MANIFEST	Lower	1127, 0.213, NE
AP641	CON EDISON	ASTOR PL & 3RD AVE	NY MANIFEST	Lower	1127, 0.213, NE
AP642	CON EDISON TRENCH: O	3RD AVE & ASTOR PL	RCRA NonGen / NLR, FINDS	Lower	1127, 0.213, NE
AP643	CON ED	3RD AVE & SAINT MARK	NY MANIFEST	Lower	1127, 0.213, NE
AP644	CON EDISON	3RD AVE & SAINT MARK	NJ MANIFEST	Lower	1127, 0.213, NE
AP645	CON EDISON - MANHOLE	ASTOR PL & 3RD AVE	RCRA-LQG	Lower	1127, 0.213, NE
AP646	CON EDISON	3RD AVE & SAINT MARK	RCRA NonGen / NLR	Lower	1127, 0.213, NE
AP647	CON EDISON SERVICE B	ST MARKS PL & COOPER	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1127, 0.213, NE
AP648	CON EDISON	ASTOR PLACE AND 3RD	NY MANIFEST	Lower	1127, 0.213, NE
AP649	CON EDISON	ASTOR PL & 3RD AVE	RCRA NonGen / NLR	Lower	1127, 0.213, NE
AP650	CON EDISON	3RD AVE & ASTOR PL	NY MANIFEST	Lower	1127, 0.213, NE
AI651	MOBIL S/S	137-02 CROSS BAY BLV	NY LTANKS, NY Spills	Lower	1128, 0.214, SW
AP652	CON EDISION - V9216	ST.MARKS PL. AND 3RD	RCRA NonGen / NLR, NY MANIFEST	Lower	1131, 0.214, NE
AR653	CON EDISON SERVICE B	18 WAVERLY PL & GREE	RCRA NonGen / NLR, FINDS	Lower	1131, 0.214, NNW
AR654	CON EDISON SERVICE B	261-63 GREENE ST & W	RCRA NonGen / NLR, FINDS	Lower	1131, 0.214, NNW
AL655	24 SECOND AVENUE OWN	24 2ND AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1132, 0.214, SE
AL656	24 SECOND AVENUE OWN	24 2ND AVE	NY Spills, NY MANIFEST	Lower	1132, 0.214, SE
AR657	SNUG HARBOR OWNERS I	303 MERCER STREET	NY AST	Lower	1134, 0.215, North
AT658	CON EDISON	302 E 5TH ST	NY MANIFEST	Lower	1135, 0.215, ESE
AI659	CON EDISON	19 E HOUSTON ST	RCRA NonGen / NLR	Lower	1136, 0.215, SW
AI660	MC 19 EAST HOUSTON L	19 E HOUSTON ST	RCRA NonGen / NLR	Lower	1136, 0.215, SW
AI661	19 EAST HOUSTON STRE	19 EAST HOUSTON STRE	US BROWNFIELDS	Lower	1136, 0.215, SW
AI662	MC 19 EAST HOUSTON L	19 E HOUSTON ST	NY MANIFEST	Lower	1136, 0.215, SW

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AI663	CON EDISON	19 E HOUSTON ST	NY MANIFEST	Lower	1136, 0.215, SW
AI664	CON EDISON	19 E HOUSTON ST	NJ MANIFEST	Lower	1136, 0.215, SW
AT665	108 EAST FOURTH LLC	108 EAST 4TH STREET	NY AST	Lower	1136, 0.215, ESE
AT666	CON ED	88 E 4TH ST	NY MANIFEST	Lower	1136, 0.215, ESE
AP667	CLOSED-LACKOF RECENT	275 NORTH 8TH ST.	NY LTANKS	Lower	1137, 0.215, NE
AT668	CON EDISON SERVICE B	94 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1139, 0.216, ESE
AT669	94 E. 4TH ST	94 EAST 4TH STREET	NY AST	Lower	1139, 0.216, ESE
AJ670	CHURCH OF THE NATIVI	44 2ND AVENUE	NY UST, NY AST	Lower	1142, 0.216, SE
AL671	126TH DEPOT	24-60 2ND AVE	NY LTANKS	Lower	1147, 0.217, SE
AU672	CON EDISON	HOUSTON ST & BROADWA	RCRA NonGen / NLR, NY MANIFEST	Lower	1148, 0.217, SW
AJ673	59-61 E 3 ST ASSOC	59-61 EAST 3RD STREE	NY AST	Lower	1149, 0.218, ESE
AT674	CON ED	90 E 4TH ST	NY MANIFEST	Lower	1150, 0.218, ESE
AV675	GEORGETOWN PLAZA	60 EAST 8TH STREET	NY AST	Lower	1150, 0.218, North
AL676	CON EDISON	47 E 2ND ST	NY MANIFEST	Lower	1157, 0.219, SE
AT677	304 EAST 5TH STREET	304 EAST 5TH STREET	NY AST	Lower	1160, 0.220, ESE
AV678	CON EDISON - SERVICE	BROADWAY & E 8 ST	NJ MANIFEST	Lower	1160, 0.220, North
AV679	CON EDISON	BROADWAY & E 8TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1160, 0.220, North
AV680	NYCT - 8TH ST STA N&	E 8TH ST & BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	1160, 0.220, North
AV681	CON EDISON	BROADWAY & E 8 ST	NY MANIFEST	Lower	1160, 0.220, North
AV682	CON EDISON - SERVICE	BROADWAY & E 8 ST	RCRA-LQG	Lower	1160, 0.220, North
AU683	CONSOLIDATED EDISON	V5990-W 88TH ST & BR	NY MANIFEST	Lower	1163, 0.220, SW
AN684	TISCH SCHOOL OF THE	111 SECOND AVENUE	NY UST	Lower	1163, 0.220, East
AN685	NYU - TTF	111 2ND AVE	NY LTANKS	Lower	1163, 0.220, East
AN686	NYU	111 2ND AVENUE	NY LTANKS	Lower	1163, 0.220, East
AW687	CON ED	80 WASHINGTON SQ E S	NY MANIFEST	Lower	1168, 0.221, NW
AW688	CON EDISON	85 WASHINGTON SQ W	NJ MANIFEST	Lower	1168, 0.221, NW
AW689	CON EDISON	85 WASHINGTON SQ W	NY MANIFEST	Lower	1168, 0.221, NW
AW690	CON EDISON	85 WASHINGTON SQ W	RCRA NonGen / NLR, FINDS, ECHO	Lower	1168, 0.221, NW
AN691	CON EDISON	115 2ND AVE	NY MANIFEST	Lower	1169, 0.221, East
AN692	CON EDISON	115 2 AVE	NY MANIFEST	Lower	1169, 0.221, East
AN693	CON EDISON	115 2ND AVE	NJ MANIFEST	Lower	1169, 0.221, East
AN694	CON EDISON	115 2ND AVE	RCRA NonGen / NLR	Lower	1169, 0.221, East
AL695	CON ED	26 EAST 1ST ST	NY MANIFEST	Lower	1170, 0.222, SE
AH696	CON EDISON SERVICE B	69 E 8 ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1170, 0.222, NNE
AL697	34 EAST 1ST STREET	34 E. 1 ST BTWN 1ST	NY LTANKS	Lower	1178, 0.223, SSE
AM698	CON EDISON SERVICE B	276 MULBERRY ST	RCRA NonGen / NLR	Lower	1179, 0.223, SSW
AM699	CON EDISON SERVICE B	276 MULBERRY ST	RCRA NonGen / NLR	Lower	1179, 0.223, SSW
AM700	CON EDISON	276 MULBERRY ST	NY MANIFEST	Lower	1179, 0.223, SSW
AX701	CLOSED-LACKOF RECENT	49 SOUTH 2ND STREET	NY LTANKS	Lower	1184, 0.224, SE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AX702	TATE & LYLE NORTH AM	49 SOUTH SECOND STRE	NY MOSF AST	Lower	1184, 0.224, SE
AX703	TATE & LYLE NORTH AM	49 SOUTH SECOND STRE	NY MOSF UST	Lower	1184, 0.224, SE
AN704	41-43 EAST 7TH STREE	41-43 EAST 7TH STREE	NY AST	Lower	1184, 0.224, ENE
AS705	CON EDISON	302 E 6TH ST	NY MANIFEST	Lower	1185, 0.224, East
AW706	CON EDISON	W 4TH ST & WASHINGTO	RCRA NonGen / NLR, FINDS, ECHO	Lower	1187, 0.225, NW
AM707	CON EDISON - MATT ST	279 MATT ST	PA MANIFEST	Higher	1189, 0.225, SSW
AM708	CON EDISON	279 MOTT ST	NY MANIFEST	Higher	1189, 0.225, SSW
AU709	CON EDISON MANHOLE:	1 W HOUSTON ST FRONT	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	1192, 0.226, SW
AY710	22 ST MARKS PLACE LP	22 ST MARKS PLACE	NY AST	Lower	1194, 0.226, ENE
AW711	CONSOLIDATED EDISON	WASH SQ E & W 4TH ST	NY MANIFEST	Lower	1196, 0.227, NW
AS712	104 SECOND AVE	104 SECOND AVE	NY AST	Lower	1196, 0.227, East
AT713	CON ED	98 E 4TH ST	NY MANIFEST	Lower	1202, 0.228, ESE
AT714	9TH PCT	321 EAST 5TH STREET	NY AST	Lower	1203, 0.228, ESE
AJ715	TOMAR EQUITIES, LLC	60 EAST 3RD STREET	NY AST	Lower	1205, 0.228, SE
AU716	600 BROADWAY	600 BROADWAY	NY AST	Lower	1206, 0.228, SW
AN717	24 ST. MARK'S PLACE	24 ST MARKS PLACE	NY AST	Lower	1207, 0.229, ENE
AN718	TANK TEST FAILURE -	24 ST MARK'S PLACE	NY LTANKS	Lower	1207, 0.229, ENE
AN719	24 ST MARKS PLACE	24 ST MARKS PLACE	NY LTANKS	Lower	1207, 0.229, ENE
AV720	CON EDISON SERVICE B	759 W BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	1207, 0.229, North
AV721	CON EDISON MANHOLE 5	759 BROADWAY	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1207, 0.229, North
AV722	CON EDISON MANHOLE 5	759 BROADWAY & 8TH S	RCRA NonGen / NLR, NY MANIFEST	Lower	1207, 0.229, North
AV723	CON EDISON SERVICE B	759 W BROADWAY	NJ MANIFEST	Lower	1207, 0.229, North
AZ724	CON EDISON	27 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1211, 0.229, NE
AZ725	CON EDISON	27 3RD AVE	NJ MANIFEST	Lower	1211, 0.229, NE
AZ726	CON EDISON	27 3RD AVE	NY MANIFEST	Lower	1211, 0.229, NE
AM727	ST PATRICKS YOUTH CE	268 MULBERRY ST	NY UST	Lower	1211, 0.229, SSW
AO728	CON EDISON	279 BOWERY	NJ MANIFEST	Higher	1212, 0.230, South
AO729	CON EDISON	279 BOWERY	RCRA NonGen / NLR	Higher	1212, 0.230, South
AO730	CON ED	279 BOWERY	NY MANIFEST	Higher	1212, 0.230, South
BA731	CON EDISON SERVICE B	100 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1214, 0.230, ESE
AN732	CON ED	119 2ND AVE & 7TH ST	NY Spills, NY MANIFEST	Lower	1216, 0.230, ENE
AS733	SELF RELIANCE NY FED	108 SECOND AVENUE	NY AST	Lower	1218, 0.231, East
AW734	NEW YORK UNIVERSITY	100 WASHINGTON SQUAR	RCRA-LQG, ICIS, FINDS, ECHO, NJ MANIFEST, NY...	Lower	1219, 0.231, NW
AN735	A.B. IBIBASSI REALTY	26 ST MARKS PL	NY AST	Lower	1220, 0.231, ENE
AQ736	ROADWAY/PARKING LOT	110 BLEECKER ST	NY LTANKS	Lower	1221, 0.231, West
BB737	NYCT - 2ND AVE STATI	2ND AVE & HOUSTON ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1222, 0.231, SSE
AV738	CON EDISON SERVICE B	61 E 8TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1224, 0.232, North
AL739	CON EDISON	34 E 1ST ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1225, 0.232, SE
AL740	CON EDISON	34 E 1ST ST	NJ MANIFEST	Lower	1225, 0.232, SE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AL741	CON EDISON	34 E 1ST ST	NY MANIFEST	Lower	1225, 0.232, SE
AU742	598 BROADWAY REALTY	598 BROADWAY	NY AST	Lower	1229, 0.233, SW
AL743	CON EDISON SERVICE B	29 E 1ST ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1232, 0.233, SSE
BA744	CON EDISON SERVICE B	102 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1233, 0.234, ESE
AX745	CON EDISON	53 E 2ND ST	NY MANIFEST	Lower	1233, 0.234, SE
BC746	KMART CORPORATION #7	770 BROADWAY	RCRA-SQG, NY MANIFEST	Lower	1236, 0.234, NNE
BC747	AOL, INC.	770 BROADWAY	NY AST	Lower	1236, 0.234, NNE
BC748	770 BROADWAY COMPANY	770 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO	Lower	1236, 0.234, NNE
AT749	CON EDISON	106 E 4TH ST	NY MANIFEST	Lower	1239, 0.235, ESE
AT750	CON EDISON	106 E 4 ST	NY MANIFEST	Lower	1239, 0.235, ESE
AO751	CON EDISON	269 BOWERY	RCRA NonGen / NLR, FINDS, ECHO	Higher	1241, 0.235, South
AO752	CON EDISON	269 BOWERY	NJ MANIFEST	Higher	1241, 0.235, South
AO753	CON EDISON	269 BOWERY	NY MANIFEST	Higher	1241, 0.235, South
AR754	CON ED	58 E 8TH ST	NY MANIFEST	Lower	1244, 0.236, North
AN755	30 ST MARKS PLACE	30 ST MARKS PLACE	NY AST	Lower	1248, 0.236, ENE
AL756	CON EDISON SERVICE B	14 E 2ND ST OPPOSITE	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	1249, 0.237, SSE
BD757	CON EDISON MANHOLE 3	JERSEY ST & CROSBY S	RCRA NonGen / NLR	Lower	1252, 0.237, SW
BD758	CONED	E INT JERSEY ST & CR	NY MANIFEST	Lower	1252, 0.237, SW
BA759	CON EDISON	65 E 3RD ST	NY MANIFEST	Lower	1257, 0.238, ESE
BA760	66-68 EAST 3RD STREE	66-68 EAST 3RD STREE	NY AST	Lower	1258, 0.238, SE
BA761	CON EDISON	66 E 3RD ST	NY MANIFEST	Lower	1258, 0.238, SE
BE762	CON EDISON	268 BOWERY	RCRA NonGen / NLR, FINDS, ECHO	Higher	1259, 0.238, South
BE763	CON ED	268 BOWERY	NY MANIFEST	Higher	1259, 0.238, South
BE764	CON EDISON	268 BOWERY	NY MANIFEST	Higher	1259, 0.238, South
BE765	CON EDISON	268 BOWERY	RCRA NonGen / NLR	Higher	1259, 0.238, South
BE766	CON EDISON	268 BOWERY	NJ MANIFEST	Higher	1259, 0.238, South
BE767	CON EDISON	268 BOWERY	NJ MANIFEST	Higher	1259, 0.238, South
AS768	CON EDISON	E 7TH ST & 2ND AVE	NJ MANIFEST	Lower	1260, 0.239, East
AS769	CON EDISON	EAST 7TH ST & 2ND AV	RCRA NonGen / NLR	Lower	1260, 0.239, East
AS770	CON ED	EAST 7TH ST & 2ND AV	NY MANIFEST	Lower	1260, 0.239, East
AS771	CON EDISON SERVICE B	E 7TH ST & 2ND AVE N	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NJ...	Lower	1260, 0.239, East
BE772	250 ELIZABETH STREET	250 ELIZABETH STREET	NY AST	Higher	1260, 0.239, South
BA773	CON EDISON	104 E 4TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1261, 0.239, ESE
BA774	CON EDISON SERVICE B	104 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1261, 0.239, ESE
BA775	104 E 4TH ST REALTY	104 E 4TH ST	NY AST	Lower	1261, 0.239, ESE
BA776	CON EDISON	104 E 4TH ST	NJ MANIFEST	Lower	1261, 0.239, ESE
BC777	M R C MGMT	770 BROADWAY	NY MANIFEST	Lower	1262, 0.239, NNE
BC778	KMART # 7777	770 BROADWAY	PA MANIFEST	Lower	1262, 0.239, NNE
AN779	32 ST MARKS PLACE	32 ST MARKS PLACE	NY AST	Lower	1263, 0.239, ENE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AL780	CON EDISON	33 E 1ST ST	NY MANIFEST	Lower	1270, 0.241, SSE
AU781	CON EDISON SERVICE B	599-601 BROADWAY & P	RCRA NonGen / NLR, NY MANIFEST	Lower	1274, 0.241, WSW
AU782	C F A CORP OF ILLINO	599 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1274, 0.241, WSW
AU783	599 BROADWAY	599 BROADWAY	NY AST	Lower	1274, 0.241, WSW
AU784	TANK TEST FAIL	599 BROADWAY	NY LTANKS	Lower	1274, 0.241, WSW
AR785	CON EDISON	50 E 8TH ST	NY MANIFEST	Lower	1277, 0.242, North
AR786	8TH ST OWNERS CORP	50-54 E 8TH ST	NY AST	Lower	1277, 0.242, North
AY787	CON EDISON SERVICE B	34 ST MARKS PL	RCRA NonGen / NLR, NY MANIFEST	Lower	1278, 0.242, ENE
BB788	CON EDISON - MANHOLE	109-11 E HOUSTON ST	NY MANIFEST	Lower	1279, 0.242, SSE
BF789	CON EDISON MANHOLE 3	W HOUSTON ST & MERCE	RCRA NonGen / NLR, NY MANIFEST	Lower	1280, 0.242, WSW
AX790	FIRS GARDEN CORPORAT	38 EAST FIRST STREET	NY AST	Lower	1281, 0.243, SE
AV791	CON EDISON SERVICE B	59 E 8 ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Lower	1284, 0.243, North
AU792	594 BROADWAY BROADWA	594 BROADWAY	NY AST	Lower	1286, 0.244, SW
AU793	PORTOFOTO INC	596 BROADWAY 1ST FLO	RCRA NonGen / NLR, FINDS, ECHO	Lower	1286, 0.244, SW
AO794	CON EDISON SERVICE B	265 BOWERY STANTON S	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1287, 0.244, South
AY795	GIOIA PROPERTIES	17 ST MARKS PLACE	NY AST	Lower	1287, 0.244, ENE
AX796	CON EDISON	61 2ND AVE & E 3RD S	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1291, 0.245, SE
AZ797	CON EDISON SERVICE B	29 3RD AVE FRONT OF	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1296, 0.245, NE
AZ798	29 THIRD AVE CORP	29 THIRD AVE	NY AST	Lower	1296, 0.245, NE
AZ799	CON EDISON SERVICE B	29 3RD AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1296, 0.245, NE
AZ800	CON EDISON SERVICE B	29 3RD AVE FRONT OF	NJ MANIFEST	Lower	1296, 0.245, NE
AR801	FAUST BROS INC	48 E 8TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1297, 0.246, North
802	125 SECOND AVE	125 SECOND AVENUE	NY AST	Lower	1298, 0.246, ENE
AY803	CON EDISON	21 SAINT MARKS PL	RCRA NonGen / NLR, FINDS, ECHO	Lower	1302, 0.247, ENE
AY804	CON EDISON	21 SAINT MARKS PL	NJ MANIFEST	Lower	1302, 0.247, ENE
AV805	CON EDISON SERVICE B	765 W BROADWAY	NJ MANIFEST	Lower	1302, 0.247, NNE
AV806	CON EDISON SERVICE B	765 W BROADWAY	RCRA NonGen / NLR, NY MANIFEST	Lower	1302, 0.247, NNE
BA807	70 EAST THIRD STREET	70 EAST THIRD STREET	NY AST	Lower	1303, 0.247, SE
BA808	CON EDISON	OPP 108 E 4TH ST	NY MANIFEST	Lower	1304, 0.247, ESE
AV809	CON EDISON SERVICE B	55 E 8TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1307, 0.248, North
AX810	NEW AMSTERDAM THEATE	40 1ST ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1307, 0.248, SE
AY811	CON EDISON	19 ST MARKS PL	NY MANIFEST	Lower	1309, 0.248, ENE
812	314 EAST 6TH STREET	314 EAST 6TH STREET	NY AST	Lower	1309, 0.248, East
AY813	CON EDISON	23 SAINT MARKS PL	RCRA NonGen / NLR, FINDS, ECHO	Lower	1310, 0.248, ENE
AY814	CON EDISON	23 SAINT MARKS PL	NY MANIFEST	Lower	1310, 0.248, ENE
AY815	CON EDISON	23 SAINT MARKS PL	NJ MANIFEST	Lower	1310, 0.248, ENE
816	CON EDISON	52 WEST 3RD STREET	NY MANIFEST	Lower	1311, 0.248, WNW
AX817	RUSSIAN ORTHODOX CAT	59 EAST 2ND STREET	NY AST	Lower	1311, 0.248, SE
AX818	CON EDISON SERVICE B	59 E 2ND ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1311, 0.248, SE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
819	ST PATRICK'S CHURCH	264 MULBERRY ST	NY UST	Lower	1317, 0.249, SSW
BA820	NYC DEPT OF EDUCATIO	113 E 4TH ST	RCRA-SQG, FINDS, ECHO	Lower	1317, 0.249, ESE
BA821	NYC DEPT OF EDUCATIO	113 E 4TH ST	NY MANIFEST	Lower	1317, 0.249, ESE
BA822	CON EDISON	113 E 4 ST	NY MANIFEST	Lower	1317, 0.249, ESE
BA823	CON EDISON SERVICE B	113 E 4TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1317, 0.249, ESE
BA824	P.S. 751 (CAR/DEV/OL	113 EAST 4TH STREET	NY AST	Lower	1317, 0.249, ESE
BG825	1 UNIVERSITY PLACE	1 UNIVERSITY PLACE	NY AST	Lower	1320, 0.250, NNW
826	ABOVE GROUND TTF	39 EAST FIRST STREET	NY LTANKS	Lower	1346, 0.255, SSE
AZ827	212-218 NORTH 9TH ST	212-218 NORTH 9TH ST	NY VCP	Lower	1369, 0.259, NE
BD828	OLMSTEAD PROPERTIES,	584 BROADWAY	NY LTANKS	Lower	1387, 0.263, SW
BF829	181 MERCER STREET	181 MERCER STREET	NY VCP	Lower	1395, 0.264, WSW
BG830	NEW YORK UNIVERSITY	1ST AVE/30TH-33RD ST	NY LTANKS	Lower	1396, 0.264, NNW
BH831	72 SOUTH SECOND STRE	72 SOUTH SECOND STRE	NY VCP	Lower	1428, 0.270, SE
832	BASEMENT	60 EAST 9TH ST	NY LTANKS, NY Spills	Lower	1429, 0.271, North
833	NYU FACILITY	7-13 WASHINGTON SQUA	NY LTANKS	Lower	1449, 0.274, NW
BF834	165 MERCER ST	165 MERCER ST	NY LTANKS	Lower	1454, 0.275, WSW
BI835	RESIDENCE	51 E 7TH ST	NY LTANKS	Lower	1460, 0.277, East
BI836	SPILL NUMBER 9913513	51 EAST 7TH ST	NY LTANKS	Lower	1460, 0.277, East
BH837	APARTMENT BLDG	86 E 3RD ST	NY LTANKS	Lower	1503, 0.285, ESE
BD838	BROAD PRINT REALITY	112 CROSBY ST	NY LTANKS	Lower	1514, 0.287, SW
BJ839	FORMER MOBIL S/S#17-	37 WEST HOUSTON ST	NY LTANKS, NY Spills	Lower	1523, 0.288, WSW
BF840	APARTMENT	142-44 GREENE STREET	NY LTANKS	Lower	1536, 0.291, WSW
BK841	BASEMENT - TTF	141 2ND AVE	NY LTANKS	Lower	1558, 0.295, ENE
BI842	61 EAST 7TH ST	61 EAST 7TH ST	NY LTANKS, NY Spills	Lower	1560, 0.295, East
843	SPILL NUMBER 0004317	91 EAST 3RD ST	NY LTANKS	Lower	1572, 0.298, ESE
BK844	235-263 NORTH 9TH ST	235-263 NORTH 9TH ST	NY VCP	Lower	1588, 0.301, ENE
845	AMOCO	62 PRINCE STREET	NY LTANKS, NY Spills	Lower	1639, 0.310, SW
BK846	SPILL NUMBER 0302699	291 EAST 9TH STREET	NY LTANKS	Lower	1645, 0.312, ENE
BK847	BASEMENT - TTF	145 2ND AVE	NY LTANKS	Lower	1649, 0.312, ENE
BH848	HITCHINGS RES	87 EAST 2ND ST	NY LTANKS, NY Spills	Lower	1656, 0.314, SE
849	SPILL NUMBER 9814449	30 EAST 9TH ST	NY LTANKS	Lower	1657, 0.314, North
BL850	APARTMENT BUILDING	85 4TH AVE	NY LTANKS	Lower	1661, 0.315, NNE
851	85-09 1ST AVENUE	85-09 1ST AVENUE	NY LTANKS	Lower	1680, 0.318, ESE
BM852	107 EAST 10TH STREET	107 EAST 10TH ST	NY LTANKS	Lower	1695, 0.321, NE
BJ853	150 WOOSTER STREET	150 WOOSTER STREET	NY VCP	Lower	1698, 0.322, WSW
BM854	103 EAST 10TH ST	103 EAST 10TH ST	NY LTANKS	Lower	1698, 0.322, NE
BM855	103 EAST 10TH STREET	103 E.10TH ST	NY LTANKS, NY LIENS, NY Spills	Lower	1698, 0.322, NE
BL856	85-89 4TH AVENUE	85-89 4TH AVENUE	NY VCP	Lower	1705, 0.323, NNE
BM857	SPILL NUMBER 0208470	105 E 10TH ST	NY LTANKS, NY Spills	Lower	1707, 0.323, NE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
858	NY UNIVERSITY	WEST 3RD ST/THOMPSON	NY LTANKS	Lower	1763, 0.334, NW
BL859	116 E 11TH ST	116 E 11TH ST	NY LTANKS	Lower	1790, 0.339, NE
860	109 PRINCE ST	109 PRINCE ST	NY LTANKS	Lower	1809, 0.343, WSW
861	UNDERGROUND	156 2ND AVE	NY LTANKS, NY Spills	Lower	1833, 0.347, ENE
862	APARTMENT- TTF	332 E 9TH ST	NY LTANKS	Lower	1837, 0.348, ENE
BL863	SUBSTATION	4TH AVE & 11TH ST	NY LTANKS	Lower	1842, 0.349, NNE
864	SPILL NUMBER 0301866	200 E 11TH ST	NY LTANKS	Lower	1852, 0.351, NE
BN865	SPILL NUMBER 0212755	80 EAST 11TH STREET	NY LTANKS	Lower	1882, 0.356, North
BO866	183 CHRYSTIE STREET	183 CHRYSTIE STREET	NY LTANKS	Higher	1913, 0.362, South
BO867	LOT 35,TAXBLOCK 426	183 CHRYSTIE STREET	NY LTANKS, NY E DESIGNATION	Higher	1913, 0.362, South
BP868	TTF	547 BROADWAY	NY LTANKS	Lower	1937, 0.367, SW
BN869	SPILL NUMBER 0109418	58 E. 11TH ST	NY LTANKS	Lower	1939, 0.367, North
870	MELTZER-HERNANDEZ (G	189 ALLEN STREET (HE	NY LTANKS, NY UST	Lower	1997, 0.378, SSE
BQ871	MELZER-HERNANDEZ (GO	94 EAST 1ST STREET (	NY LTANKS, NY UST, NY Spills	Lower	1997, 0.378, SE
BP872	114 MERCER STREET	114 MERCER STREET	NY LTANKS	Lower	2008, 0.380, SW
BR873	231 EAST 11TH ST	231 EAST 11TH ST	NY LTANKS, NY Spills	Lower	2011, 0.381, NE
BP874	JOANNA / RESIDENTIAL	110 MERCER ST	NY LTANKS	Lower	2043, 0.387, SW
BN875	TTF	61 EAST 11TH STREET	NY LTANKS	Lower	2051, 0.388, North
876	171 SULLIVAN ST	171 SULLIVAN ST	NY LTANKS, NY Spills	Lower	2072, 0.392, West
BO877	ON PROPERTY	7 RIVINGTON ST	NY LTANKS	Lower	2089, 0.396, South
BQ878	96 NORTH 1ST STREET	96 NORTH 1ST STREET	NY VCP	Lower	2103, 0.398, SE
BR879	APT. BUILDING TTF	222 EAST 12TH ST	NY LTANKS	Lower	2110, 0.400, NE
880	APARTMENT	126 MACDOUGAL ST	NY LTANKS	Lower	2115, 0.401, WNW
881	APARTMENT COMPLEX -	11 EAST 10 TH STREET	NY LTANKS	Lower	2116, 0.401, North
BS882	77 EAST 12 OWNERS IN	77 EAST 12TH STREET	NY LTANKS, NY UST	Lower	2142, 0.406, NNE
BS883	X	112 4TH AVE	NY LTANKS	Lower	2149, 0.407, NNE
884	THE DERMOT COMPANY	229 EAST 12TH STREET	NY LTANKS, NY AST	Lower	2154, 0.408, NE
BT885	68-70 SPRING STREET	68-70 SPRING STREET	NY VCP	Lower	2160, 0.409, SW
BU886	SPILL NUMBER 0106344	20 5TH AV	NY LTANKS	Lower	2162, 0.409, NNW
BT887	66 CROSBY ST/MANHATT	66 CROSBY STREET	NY LTANKS	Lower	2164, 0.410, SW
BR888	CAPRI APARTMENTS	232 EAST 12TH ST	NY LTANKS	Lower	2166, 0.410, NE
BU889	24 FIFTH AVE	24 5TH AVE	NY LTANKS, NY Spills	Lower	2172, 0.411, NNW
890	SPILL NUMBER 0307474	305 EAST 11TH ST	NY LTANKS	Lower	2178, 0.412, ENE
891	APARTMENT BUILDING	159 PRINCE STREET	NY LTANKS	Lower	2184, 0.414, WSW
892	IFO 111 E7TH ST	IFO 111 E.7TH ST	NY LTANKS	Lower	2224, 0.421, East
893	UNKNOWN RESIDENCE	173 ELIZABETH ST	NY LTANKS	Lower	2234, 0.423, SSW
894	ABOVE GROUND TANK	121 SPRING ST	NY LTANKS	Lower	2243, 0.425, WSW
895	APT COMPLEX TTF	37 WASHINGTON SQ WES	NY LTANKS	Lower	2250, 0.426, NW
BS896	830 BROADWAY/PRETIUM	830 BROADWAY	NY LTANKS	Lower	2267, 0.429, NNE

MAPPED SITES SUMMARY

Target Property Address:
375 LAFAYETTE STREET
NEW YORK, NY 10003

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BV897	105 WOOSTER STREET	105 WOOSTER STREET	NY LTANKS	Lower	2274, 0.431, WSW
898	APARTMENT BLDG - TTF	340 E 11TH ST	NY LTANKS	Lower	2314, 0.438, ENE
899	APARTMENT BLDG	141 EAST 3RD ST	NY LTANKS	Lower	2322, 0.440, ESE
BW900	COMMERCIAL SASSAN SA	158 FIRST AVE	NY LTANKS	Lower	2326, 0.441, East
BX901	31 E 12TH ST	31 E 12TH ST	NY LTANKS	Lower	2345, 0.444, North
BX902	31 EAST 12TH STREET	31 EAST 12TH ST	NY LTANKS	Lower	2345, 0.444, North
BY903	512 BROADWAY	512 BROADWAY	NY LTANKS, NY Spills	Lower	2365, 0.448, SW
BU904	10 WEST 10TH ST	10 WEST 10TH ST	NY LTANKS, NY Spills	Lower	2367, 0.448, NNW
BZ905	39 5TH AVENUE	39 5TH AVENUE	NY LTANKS	Lower	2371, 0.449, NNW
BV906	COMMERCIAL BUILDING	145 SPRING ST	NY LTANKS	Lower	2399, 0.454, WSW
907	ON SIDEWALK	240 E 13TH ST	NY LTANKS, NY Spills	Lower	2437, 0.462, NE
BV908	PROPERTIES SOLUTIONS	155 SPRING STREET	NY LTANKS	Lower	2445, 0.463, WSW
BW909	260 EAST 10TH ST	260 EAST 10TH ST	NY LTANKS	Lower	2449, 0.464, East
BY910	HSR CORP	503-511 BROADWAY	NY LTANKS	Lower	2477, 0.469, SW
911	179 MULBERRY ST	179 MULBERRY ST	NY LTANKS	Lower	2496, 0.473, SSW
912	LAFAYETTE STREET SCH	205 LAFAYETTE STREET	US BROWNFIELDS	Lower	2509, 0.475, SSW
BZ913	47-27 5TH STREET	47-27 5TH STREET	NY VCP	Lower	2512, 0.476, North
BY914	TTF	496 BROADWAY	NY LTANKS	Lower	2541, 0.481, SW
915	13 E. 12TH STREET	13 E. 12TH STREET	NY LTANKS	Lower	2542, 0.481, North
BY916	42 CROSBY STREET	42 CROSBY STREET	NY VCP	Lower	2543, 0.482, SW
917	DELANCEY ST AND	2ND AVE TRACK 3 F LI	NY LTANKS	Lower	2543, 0.482, South
CA918	LITTLE RED SCHOOL HO	272 6TH AVENUE	NY LTANKS	Lower	2564, 0.486, WNW
CA919	LITTLE RED SCHOOL HO	272 6TH AVE	NY LTANKS	Lower	2564, 0.486, WNW
920	J. PALULIW	433 EAST 9TH STREET	NY LTANKS	Lower	2567, 0.486, East
CB921	TTF	65 GREENE STREET	NY LTANKS	Lower	2576, 0.488, SW
922	PS 19-M	185 1ST AVE	NY LTANKS	Lower	2583, 0.489, ENE
CB923	APT BUILDING	62 GREENE ST	NY LTANKS	Lower	2587, 0.490, SW
924	BUILDING	38 CROSBY ST	NY LTANKS	Lower	2600, 0.492, SW
925	SPILL NUMBER 0112067	2 KING ST	NY LTANKS	Lower	2624, 0.497, West
926	MARKITE CO.	155 WAVERLY PLACE	FUSRAP	Lower	3048, 0.577, NW
927	LEDOUX AND CO.	155 AVENUE OF THE AM	FUSRAP	Lower	3212, 0.608, WSW
928	CON EDISON - HESTER	HESTER STREET	EDR MGP	Lower	3522, 0.667, SSW
929	CON EDISON - CANAL S	CANAL STREET	EDR MGP	Lower	3679, 0.697, SSW
930	HUDSON DRY CLEANERS	462 HUDSON STREET	NY SHWS, NY DRYCLEANERS	Lower	3925, 0.743, WNW
931	CON EDISON - EAST 17	EAST 17TH - EAST 18T	EDR MGP	Lower	4448, 0.842, ENE
932	CON EDISON - EAST 21	EAST 20TH - EAST 22N	EDR MGP	Lower	5000, 0.947, ENE
933	CON EDISON - CROSS/L	60 CENTRE ST	EDR MGP	Lower	5180, 0.981, SSW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
H B SERVICE CENTER 375-9 LAFAYETTE ST NEW YORK, NY 10007	EDR Hist Auto	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF ---- Facility Register

State and tribal leaking storage tank lists

INDIAN LUST ---- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---- Underground Storage Tank Listing
NY CBS UST ---- Chemical Bulk Storage Database
NY MOSF ---- Major Oil Storage Facility Site Listing
NY CBS ---- Chemical Bulk Storage Site Listing
NY CBS AST ---- Chemical Bulk Storage Database
INDIAN UST ---- Underground Storage Tanks on Indian Land
NY TANKS ---- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY ENG CONTROLS ---- Registry of Engineering Controls
NY INST CONTROL ---- Registry of Institutional Controls

State and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY BROWNFIELDS ---- Brownfields Site List
NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---- Registered Waste Tire Storage & Facility List
NY SWRCY ---- Registered Recycling Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database

NY HIST AST - Historical Petroleum Bulk Storage Database

Local Land Records

LIENS 2 - CERCLA Lien Information

Records of Emergency Release Reports

HMIRS - Hazardous Materials Information Reporting System
NY Hist Spills - SPILLS Database
NY SPILLS 90 - SPILLS 90 data from FirstSearch
NY SPILLS 80 - SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS - Formerly Used Defense Sites
DOD - Department of Defense Sites
SCRD DRYCLEANERS - State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR - Financial Assurance Information
EPA WATCH LIST - EPA WATCH LIST
2020 COR ACTION - 2020 Corrective Action Program List
TSCA - Toxic Substances Control Act
TRIS - Toxic Chemical Release Inventory System
SSTS - Section 7 Tracking Systems
RMP - Risk Management Plans
RAATS - RCRA Administrative Action Tracking System
PADS - PCB Activity Database System
FTTS - FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS - Material Licensing Tracking System
COAL ASH DOE - Steam-Electric Plant Operation Data
COAL ASH EPA - Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER - PCB Transformer Registration Database
RADINFO - Radiation Information Database
HIST FTTS - FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS - Incident and Accident Data
INDIAN RESERV - Indian Reservations
UMTRA - Uranium Mill Tailings Sites
LEAD SMELTERS - Lead Smelter Sites
US MINES - Mines Master Index File
ABANDONED MINES - Abandoned Mines
UXO - Unexploded Ordnance Sites
DOCKET HWC - Hazardous Waste Compliance Docket Listing
FUELS PROGRAM - EPA Fuels Program Registered Listing
NY COAL ASH - Coal Ash Disposal Site Listing
NY Financial Assurance - Financial Assurance Information Listing
NY HSWDS - Hazardous Substance Waste Disposal Site Inventory
NY SPDES - State Pollutant Discharge Elimination System
NY VAPOR REOPENED - Vapor Intrusion Legacy Site List
NY UIC - Underground Injection Control Wells

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS - Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 12/11/2017 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS	***NO STREET APPLICABLE***	***W 1/2 - 1 (0.982 mi.)***	***0***	***8***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/11/2017 has revealed that there are 9 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - GAS MAI	***E 4TH ST AND LAFAYET***	***N 0 - 1/8 (0.027 mi.)***	***A53***	***140***
CVS PHARMACY #10407	***298 MULBERRY ST***	***SSW 1/8 - 1/4 (0.157 mi.)***	***AB400***	***1022***
CON EDISON - SERVICE	***BOWERY AND E HOUSTON***	***S 1/8 - 1/4 (0.196 mi.)***	***AO566***	***1363***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
688 BROADWAY 1 GREAT	***688 BROADWAY***	***NW 0 - 1/8 (0.057 mi.)***	***E81***	***189***
CON EDISON - SERVICE	***GREAT JONES ST AND B***	***WNW 0 - 1/8 (0.080 mi.)***	***I148***	***335***
CON EDISON - MANHOLE	***436 LAFAYETTE ST AND***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O345***	***917***
CON EDISON - MANHOLE	ASTOR PL & 3RD AVE	NE 1/8 - 1/4 (0.213 mi.)	AP645	1518

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - SERVICE	BROADWAY & E 8 ST	N 1/8 - 1/4 (0.220 mi.)	AV682	1596
NEW YORK UNIVERSITY	***100 WASHINGTON SQUAR***	***NW 1/8 - 1/4 (0.231 mi.)***	***AW734***	***1690***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/11/2017 has revealed that there are 11 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONCORD ELECTRONICS	***GREAT JONES STREET***	***SSE 0 - 1/8 (0.016 mi.)***	***A28***	***78***
NYCTA - BROADWAY & L	***E HOUSTON & CROSBY S***	***SW 1/8 - 1/4 (0.180 mi.)***	***AI491***	***1187***
B P PRODUCTS NORTH A	***21 E HOUSTON ST***	***SW 1/8 - 1/4 (0.195 mi.)***	***AI562***	***1352***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEW YORK UNIVERSITY	***2-4 WASHINGTON PL***	***NNW 0 - 1/8 (0.118 mi.)***	***L251***	***573***
COOPER UNION ENGINEE	***41 COOPER SQ***	***ENE 0 - 1/8 (0.125 mi.)***	***Q279***	***619***
COOPER UNION SCHOOL	***50 ASTOR PL***	***NNE 1/8 - 1/4 (0.178 mi.)***	***AH484***	***1174***
NEW YORK UNIVERSITY	***12-16 WAVERLY PL***	***NNW 1/8 - 1/4 (0.181 mi.)***	***AD492***	***1190***
NEW YORK UNIVERSITY	***40 W 4TH ST***	***NW 1/8 - 1/4 (0.203 mi.)***	***AF584***	***1397***
NEW YORK UNIVERSITY	***1-4 WASHINGTON SQUAR***	***W 1/8 - 1/4 (0.209 mi.)***	***AQ622***	***1481***
KMART CORPORATION #7	***770 BROADWAY***	***NNE 1/8 - 1/4 (0.234 mi.)***	***BC746***	***1742***
NYC DEPT OF EDUCATIO	***113 E 4TH ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***BA820***	***1886***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/11/2017 has revealed that there are 11 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MERCHANTS HOUSE	***29 E 4TH ST***	***ENE 0 - 1/8 (0.034 mi.)***	***B57***	***149***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEW YORK UNIVERSITY	726 BROADWAY	N 1/8 - 1/4 (0.128 mi.)	L293	644
215 MERCER ST	215 MERCER ST	W 1/8 - 1/4 (0.159 mi.)	U412	1049
BEST BUY	***622 BROADWAY***	***WSW 1/8 - 1/4 (0.173 mi.)***	***Y455***	***1125***
PETCO STORE #5816	***31 2ND AVE***	***SE 1/8 - 1/4 (0.183 mi.)***	***Z498***	***1202***
CON EDISON VAULT: 96	***51 ASTOR PL***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH502***	***1208***
74 CLEANERS INC	***74 SECOND AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***AC541***	***1312***
NEW YORK UNIVERSITY	***35 W 4TH ST***	***NW 1/8 - 1/4 (0.194 mi.)***	***AF552***	***1332***
CON EDISON GAS MAIN:	***755 BROADWAY***	***N 1/8 - 1/4 (0.202 mi.)***	***AH583***	***1395***
CON EDISON MANHOLE:	***1 W HOUSTON ST FRONT***	***SW 1/8 - 1/4 (0.226 mi.)***	***AU709***	***1638***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B	***14 E 2ND ST OPPOSITE***	***SSE 1/8 - 1/4 (0.237 mi.)***	***AL756***	***1763***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/12/2018 has revealed that there is 1 NY SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUDSON DRY CLEANERS Site Code: 486480	***462 HUDSON STREET***	***WNW 1/2 - 1 (0.743 mi.)***	***930***	***2098***

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/12/2018 has revealed that there are 130 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
371 LAFAYETTE ST. Date Closed: 2002-05-17 Site ID: 170514 Program Number: 9400935	371 LAFAYETTE ST.	0 - 1/8 (0.000 mi.)	A3	28
30 EAST 4TH STREET Date Closed: 1995-05-19 Site ID: 169169 Program Number: 9502124	30 EAST 4TH STREET	E 0 - 1/8 (0.016 mi.)	A27	77
APARTMENT BLDG TTF Date Closed: 2013-01-29 Site ID: 462646 Program Number: 1200036	48 GREAT JONES ST	SE 0 - 1/8 (0.023 mi.)	B47	131
303 ELIZABETH ST. Date Closed: 1992-11-19 Date Closed: 1992-11-16 Site ID: 270112 Site ID: 271130 Program Number: 8704231	303 ELIZABETH ST.	S 1/8 - 1/4 (0.144 mi.)	P348	924

Program Number: 8705585				
159-02 CROSS BAY BLV Date Closed: 1988-11-13 Site ID: 94717 Program Number: 8806752	159-02 CROSS BAY BLV	SW 1/8 - 1/4 (0.146 mi.)	S362	951
SPILL NUMBER 9411282 Date Closed: 2004-01-13 Site ID: 153267 Program Number: 9411282	ELIZABETH ST & HOUST	S 1/8 - 1/4 (0.149 mi.)	P375	974
GASETERIA Date Closed: 2006-03-20 Site ID: 162605 Program Number: 0230042	21 EAST HOUSTON STRE	SW 1/8 - 1/4 (0.195 mi.)	AI561	1350
295 LAFAYETTE ST. Date Closed: 1994-01-21 Site ID: 167565 Program Number: 9214395	295 LAFAYETTE ST.	SW 1/8 - 1/4 (0.204 mi.)	AI585	1402
183 CHRYSTIE STREET Date Closed: 1996-11-22 Site ID: 219443 Program Number: 9512158	183 CHRYSTIE STREET	S 1/4 - 1/2 (0.362 mi.)	BO866	1992
LOT 35,TAXBLOCK 426 Date Closed: 1995-11-29 Site ID: 219442 Program Number: 9510876	***183 CHRYSTIE STREET***	***S 1/4 - 1/2 (0.362 mi.)***	***BO867***	***1994***

Lower Elevation	Address	Direction / Distance	Map ID	Page
350 LAFAYETTE ST/SHE Date Closed: 1992-01-22 Site ID: 83567 Program Number: 9110940	350 LAFAYETTE ST/SHE	WSW 0 - 1/8 (0.052 mi.)	C77	183
704 BROADWAY Date Closed: 2013-11-29 Site ID: 218411 Program Number: 0004513	704 BROADWAY	NNW 0 - 1/8 (0.087 mi.)	E168	378
APARTMENT Date Closed: 2008-01-11 Site ID: 336772 Program Number: 0411548	2-4 ST NICHOLAS PLAC	NW 0 - 1/8 (0.091 mi.)	E172	386
APARTMENT Date Closed: 1999-02-10 Site ID: 234503 Program Number: 9813389	648 BROADWAY	WSW 0 - 1/8 (0.116 mi.)	M247	565
NYU CENTRAL PLANT Date Closed: 2001-08-21 Site ID: 141532 Program Number: 0007785	***251 MERCER ST***	***WNW 1/8 - 1/4 (0.133 mi.)***	***R312***	***688***
SPILL NUMBER 0000672 Date Closed: 2004-04-26 Site ID: 86275	77 BLEECKER ST	W 1/8 - 1/4 (0.136 mi.)	U319	865

Program Number: 0000672				
APARTMENT COMPLEX Date Closed: 1996-12-30 Site ID: 170205 Program Number: 9514652	434 LAFAYETTE ST	NNE 1/8 - 1/4 (0.138 mi.)	O325	878
COMMERCIAL BUILDING Date Closed: 2008-10-06 Site ID: 395591 Program Number: 0713774	440 LAFAYETTE AVE	NNE 1/8 - 1/4 (0.144 mi.)	O338	901
OFFICE BUILDING Date Closed: 2006-05-04 Date Closed: 1997-04-28 Site ID: 339041 Site ID: 100275 Program Number: 0413180 Program Number: 9701173	***636 BROADWAY***	***WSW 1/8 - 1/4 (0.145 mi.)***	***M349***	***927***
30 EAST 3RD STREET Date Closed: 2005-08-04 Site ID: 70393 Program Number: 0106303	30 EAST 3RD STREET	SE 1/8 - 1/4 (0.150 mi.)	T378	979
ABOVE GROUND TANK Date Closed: 2014-12-23 Site ID: 500389 Program Number: 1406897	740 BROADWAY	N 1/8 - 1/4 (0.165 mi.)	X433	1086
54-62 COOPERS SQUARE Date Closed: 1999-05-10 Site ID: 314704 Program Number: 9811435	62 COOPERS SQUARE	NE 1/8 - 1/4 (0.166 mi.)	W435	1090
AMOCO GAS STATION Date Closed: 2001-07-11 Site ID: 187139 Program Number: 9913713	***620 BROADWAY***	***SW 1/8 - 1/4 (0.177 mi.)***	***Y466***	***1145***
11 WAVERLY ASSOC Date Closed: 2005-11-21 Site ID: 178153 Program Number: 9801971	11 WAVERLY PL	NNW 1/8 - 1/4 (0.179 mi.)	AD488	1181
91 EAST 4TH ST Date Closed: 2004-07-27 Site ID: 82922 Program Number: 0307640	91 EAST 4TH ST	ESE 1/8 - 1/4 (0.186 mi.)	AC506	1229
RESIDENTIAL Date Closed: 2017-02-24 Site ID: 326541 Program Number: 0210175	91 EAST 4TH STREET	ESE 1/8 - 1/4 (0.186 mi.)	AC508	1233
AMOCO Date Closed: 2003-12-24 Date Closed: 2003-11-06 Site ID: 164986 Site ID: 164987 Program Number: 0104555 Program Number: 0209761	***610 BROADWAY***	***SW 1/8 - 1/4 (0.186 mi.)***	***AI509***	***1235***
CLOSED-LACKOF RECENT	44 SECOND AVENUE	SE 1/8 - 1/4 (0.190 mi.)	Z540	1311

Date Closed: 2003-03-03 Site ID: 214063 Program Number: 9801146				
APT BUILDING TTF Date Closed: 2015-02-05 Site ID: 437192 Program Number: 1003940	300 MERCER ST	N 1/8 - 1/4 (0.195 mi.)	X557	1340
24 SECOND AVE MOBIL Date Closed: 1991-05-02 Site ID: 91409 Program Number: 9010367	24 SECOND AVE & 1ST	SSE 1/8 - 1/4 (0.206 mi.)	AL601	1438
GAS STATION Date Closed: 1996-06-11 Site ID: 295854 Program Number: 9603385	24 SECOND AVE	SSE 1/8 - 1/4 (0.206 mi.)	AL604	1443
1-4 MILLIGAN PLACE Date Closed: 1996-04-24 Site ID: 171104 Program Number: 9601200	1-4 MILLIGAN PLACE	NE 1/8 - 1/4 (0.209 mi.)	AP621	1480
MOBIL S/S Date Closed: 2017-05-12 Site ID: 298849 Program Number: 8706157	***137-02 CROSS BAY BLV***	***SW 1/8 - 1/4 (0.214 mi.)***	***AI651***	***1528***
CLOSED-LACKOF RECENT Date Closed: 2003-03-04 Site ID: 176330 Program Number: 8706710	275 NORTH 8TH ST.	NE 1/8 - 1/4 (0.215 mi.)	AP667	1566
126TH DEPOT Date Closed: 2005-02-22 Site ID: 334066 Program Number: 0409201	24-60 2ND AVE	SE 1/8 - 1/4 (0.217 mi.)	AL671	1576
NYU - TTF Date Closed: 2010-07-06 Site ID: 412176 Program Number: 0900252	111 2ND AVE	E 1/8 - 1/4 (0.220 mi.)	AN685	1601
NYU Date Closed: 2005-07-27 Site ID: 157657 Program Number: 0402181	111 2ND AVENUE	E 1/8 - 1/4 (0.220 mi.)	AN686	1603
34 EAST 1ST STREET Date Closed: 2003-03-03 Site ID: 237521 Program Number: 9701768	34 E. 1 ST BTWN 1ST	SSE 1/8 - 1/4 (0.223 mi.)	AL697	1618
CLOSED-LACKOF RECENT Date Closed: 2003-03-14 Date Closed: 2003-03-13 Site ID: 73688 Site ID: 265300 Program Number: 8807845 Program Number: 8706162	49 SOUTH 2ND STREET	SE 1/8 - 1/4 (0.224 mi.)	AX701	1623
TANK TEST FAILURE -	24 ST MARK'S PLACE	ENE 1/8 - 1/4 (0.229 mi.)	AN718	1657

Site ID: 444005 Program Number: 1010402				
24 ST MARKS PLACE Date Closed: 2003-06-13 Site ID: 143501 Program Number: 0010130	24 ST MARKS PLACE	ENE 1/8 - 1/4 (0.229 mi.)	AN719	1658
ROADWAY/PARKING LOT Date Closed: 2006-01-24 Site ID: 357309 Program Number: 0511206	110 BLEECKER ST	W 1/8 - 1/4 (0.231 mi.)	AQ736	1722
TANK TEST FAIL Date Closed: 2014-09-25 Site ID: 497400 Program Number: 1404020	599 BROADWAY	WSW 1/8 - 1/4 (0.241 mi.)	AU784	1817
ABOVE GROUND TTF Date Closed: 2015-11-17 Site ID: 473262 Program Number: 1210187	39 EAST FIRST STREET	SSE 1/4 - 1/2 (0.255 mi.)	826	1897
OLMSTEAD PROPERTIES, Date Closed: 2013-12-17 Site ID: 486965 Program Number: 1306357	584 BROADWAY	SW 1/4 - 1/2 (0.263 mi.)	BD828	1900
NEW YORK UNIVERSITY Date Closed: 1995-05-15 Site ID: 110229 Program Number: 9501895	1ST AVE/30TH-33RD ST	NNW 1/4 - 1/2 (0.264 mi.)	BG830	1903
BASEMENT Date Closed: 2015-09-17 Site ID: 494471 Program Number: 1401198	***60 EAST 9TH ST***	***N 1/4 - 1/2 (0.271 mi.)***	***832***	***1905***
NYU FACILITY Date Closed: 2003-08-11 Site ID: 99990 Program Number: 9416113	7-13 WASHINGTON SQUA	NW 1/4 - 1/2 (0.274 mi.)	833	1909
165 MERCER ST Date Closed: 1996-05-28 Site ID: 89426 Program Number: 9601951	165 MERCER ST	WSW 1/4 - 1/2 (0.275 mi.)	BF834	1910
RESIDENCE Date Closed: 2003-08-22 Site ID: 295238 Program Number: 9913497	51 E 7TH ST	E 1/4 - 1/2 (0.277 mi.)	BI835	1911
SPILL NUMBER 9913513 Date Closed: 2000-02-29 Site ID: 77298 Program Number: 9913513	51 EAST 7TH ST	E 1/4 - 1/2 (0.277 mi.)	BI836	1912
APARTMENT BLDG Date Closed: 2015-12-18 Site ID: 507803 Program Number: 1501578	86 E 3RD ST	ESE 1/4 - 1/2 (0.285 mi.)	BH837	1913
BROAD PRINT REALITY	112 CROSBY ST	SW 1/4 - 1/2 (0.287 mi.)	BD838	1915

Date Closed: 2006-02-06 Site ID: 359169 Program Number: 0512792				
FORMER MOBIL S/S#17- Date Closed: 2015-06-01 Site ID: 306206 Program Number: 8803871	***37 WEST HOUSTON ST***	***WSW 1/4 - 1/2 (0.288 mi.)***	***BJ839***	***1916***
APARTMENT Date Closed: 2006-10-13 Site ID: 371408 Program Number: 0607628	142-44 GREENE STREET	WSW 1/4 - 1/2 (0.291 mi.)	BF840	1922
BASEMENT - TTF Site ID: 444006 Program Number: 1010403	141 2ND AVE	ENE 1/4 - 1/2 (0.295 mi.)	BK841	1923
61 EAST 7TH ST Date Closed: 2006-01-09 Site ID: 342871 Program Number: 0500005	***61 EAST 7TH ST***	***E 1/4 - 1/2 (0.295 mi.)***	***BI842***	***1924***
SPILL NUMBER 0004317 Date Closed: 2004-01-23 Site ID: 61149 Program Number: 0004317	91 EAST 3RD ST	ESE 1/4 - 1/2 (0.298 mi.)	843	1926
AMOCO Date Closed: 2004-04-28 Site ID: 143437 Program Number: 8709385	***62 PRINCE STREET***	***SW 1/4 - 1/2 (0.310 mi.)***	***845***	***1928***
SPILL NUMBER 0302699 Date Closed: 2003-12-15 Site ID: 107141 Program Number: 0302699	291 EAST 9TH STREET	ENE 1/4 - 1/2 (0.312 mi.)	BK846	1931
BASEMENT - TTF Site ID: 444007 Program Number: 1010404	145 2ND AVE	ENE 1/4 - 1/2 (0.312 mi.)	BK847	1932
HITCHINGS RES Date Closed: 1999-05-20 Site ID: 79235 Program Number: 9812332	***87 EAST 2ND ST***	***SE 1/4 - 1/2 (0.314 mi.)***	***BH848***	***1933***
SPILL NUMBER 9814449 Date Closed: 1999-03-23 Site ID: 163694 Program Number: 9814449	30 EAST 9TH ST	N 1/4 - 1/2 (0.314 mi.)	849	1935
APARTMENT BUILDING Date Closed: 2011-07-11 Site ID: 368911 Program Number: 0605695	85 4TH AVE	NNE 1/4 - 1/2 (0.315 mi.)	BL850	1936
85-09 1ST AVENUE Date Closed: 1992-09-30 Site ID: 170432 Program Number: 8802622	85-09 1ST AVENUE	ESE 1/4 - 1/2 (0.318 mi.)	851	1940
107 EAST 10TH STREET	107 EAST 10TH ST	NE 1/4 - 1/2 (0.321 mi.)	BM852	1941

Date Closed: 2003-11-17 Site ID: 191695 Program Number: 9704339				
103 EAST 10TH ST Date Closed: 2005-03-14 Site ID: 155770 Program Number: 9807065	103 EAST 10TH ST	NE 1/4 - 1/2 (0.322 mi.)	BM854	1943
103 EAST 10TH STREET Date Closed: 2015-12-23 Site ID: 117758 Program Number: 9913474	***103 E.10TH ST***	***NE 1/4 - 1/2 (0.322 mi.)***	***BM855***	***1944***
SPILL NUMBER 0208470 Date Closed: 2003-03-17 Site ID: 331436 Program Number: 9611157	***105 E 10TH ST***	***NE 1/4 - 1/2 (0.323 mi.)***	***BM857***	***1978***
NY UNIVERSITY Date Closed: 2002-05-20 Site ID: 251943 Program Number: 0110099	WEST 3RD ST/THOMPSON	NW 1/4 - 1/2 (0.334 mi.)	858	1980
116 E 11TH ST Date Closed: 1991-11-12 Site ID: 319633 Program Number: 9108578	116 E 11TH ST	NE 1/4 - 1/2 (0.339 mi.)	BL859	1981
109 PRINCE ST Date Closed: 2002-12-27 Site ID: 246381 Program Number: 9205530	109 PRINCE ST	WSW 1/4 - 1/2 (0.343 mi.)	860	1982
UNDERGROUND Date Closed: 2011-04-12 Site ID: 376114 Program Number: 0611420	***156 2ND AVE***	***ENE 1/4 - 1/2 (0.347 mi.)***	***861***	***1983***
APARTMENT- TTF Date Closed: 2006-04-27 Site ID: 344329 Program Number: 0501168	332 E 9TH ST	ENE 1/4 - 1/2 (0.348 mi.)	862	1987
SUBSTATION Date Closed: 2002-08-05 Site ID: 157318 Program Number: 0200225	4TH AVE & 11TH ST	NNE 1/4 - 1/2 (0.349 mi.)	BL863	1989
SPILL NUMBER 0301866 Date Closed: 2003-08-07 Site ID: 137439 Program Number: 0301866	200 E 11TH ST	NE 1/4 - 1/2 (0.351 mi.)	864	1990
SPILL NUMBER 0212755 Date Closed: 2004-01-07 Site ID: 292802 Program Number: 0212755	80 EAST 11TH STREET	N 1/4 - 1/2 (0.356 mi.)	BN865	1991
TTF Date Closed: 2016-02-03 Site ID: 505512 Program Number: 1411718	547 BROADWAY	SW 1/4 - 1/2 (0.367 mi.)	BP868	1995
SPILL NUMBER 0109418	58 E. 11TH ST	N 1/4 - 1/2 (0.367 mi.)	BN869	1996

Date Closed: 2003-03-10 Site ID: 97042 Program Number: 0109418				
MELTZER-HERNANDEZ (G Date Closed: 1995-04-20 Date Closed: 1995-06-21 Site ID: 200757 Site ID: 200758 Site ID: 200759 Program Number: 9001939 Program Number: 9007076 Program Number: 9100612	***189 ALLEN STREET (HE***	***SSE 1/4 - 1/2 (0.378 mi.)***	***870***	***1997***
MELZER-HERNANDEZ (GO Date Closed: 2009-07-07 Date Closed: 2004-04-09 Date Closed: 1997-04-07 Site ID: 328653 Site ID: 290409 Site ID: 235062 Program Number: 0104813 Program Number: 9001822 Program Number: 8911775	***94 EAST 1ST STREET (***	***SE 1/4 - 1/2 (0.378 mi.)***	***BQ871***	***2003***
114 MERCER STREET Date Closed: 2004-11-22 Date Closed: 1992-10-12 Site ID: 334057 Site ID: 165107 Program Number: 0409192 Program Number: 9208021	114 MERCER STREET	SW 1/4 - 1/2 (0.380 mi.)	BP872	2011
231 EAST 11TH ST Date Closed: 2008-12-04 Site ID: 404317 Program Number: 0807005	***231 EAST 11TH ST***	***NE 1/4 - 1/2 (0.381 mi.)***	***BR873***	***2013***
JOANNA / RESIDENTIAL Date Closed: 2013-05-22 Site ID: 463379 Program Number: 1200725	110 MERCER ST	SW 1/4 - 1/2 (0.387 mi.)	BP874	2016
TTF Site ID: 560854 Program Number: 1706536	61 EAST 11TH STREET	N 1/4 - 1/2 (0.388 mi.)	BN875	2017
171 SULLIVAN ST Date Closed: 2002-04-09 Site ID: 209542 Program Number: 0009608	***171 SULLIVAN ST***	***W 1/4 - 1/2 (0.392 mi.)***	***876***	***2018***
ON PROPERTY Date Closed: 2017-05-24 Site ID: 545768 Program Number: 1700746	7 RIVINGTON ST	S 1/4 - 1/2 (0.396 mi.)	BO877	2021
APT. BUILDING TTF Date Closed: 2009-08-27 Site ID: 418269 Program Number: 0905974	222 EAST 12TH ST	NE 1/4 - 1/2 (0.400 mi.)	BR879	2024
APARTMENT	126 MACDOUGAL ST	WNW 1/4 - 1/2 (0.401 mi.)	880	2025

Date Closed: 2011-05-25 Site ID: 417080 Program Number: 0904868				
APARTMENT COMPLEX - Date Closed: 2015-02-19 Site ID: 161486 Program Number: 9612302	11 EAST 10 TH STREET	N 1/4 - 1/2 (0.401 mi.)	881	2026
77 EAST 12 OWNERS IN Date Closed: 2015-05-19 Site ID: 504752 Program Number: 1411008	***77 EAST 12TH STREET***	***NNE 1/4 - 1/2 (0.406 mi.)***	***BS882***	***2028***
X Date Closed: 2004-10-18 Site ID: 107845 Program Number: 0300357	112 4TH AVE	NNE 1/4 - 1/2 (0.407 mi.)	BS883	2031
THE DERMOT COMPANY Date Closed: 2009-01-20 Site ID: 397432 Program Number: 0801496	***229 EAST 12TH STREET***	***NE 1/4 - 1/2 (0.408 mi.)***	***884***	***2033***
SPILL NUMBER 0106344 Date Closed: 2002-05-15 Site ID: 78648 Program Number: 0106344	20 5TH AV	NNW 1/4 - 1/2 (0.409 mi.)	BU886	2037
66 CROSBY ST/MANHATT Date Closed: 1989-02-27 Site ID: 114804 Program Number: 8809170	66 CROSBY STREET	SW 1/4 - 1/2 (0.410 mi.)	BT887	2038
CAPRI APARTMENTS Date Closed: 2004-07-22 Site ID: 115105 Program Number: 0208805	232 EAST 12TH ST	NE 1/4 - 1/2 (0.410 mi.)	BR888	2039
24 FIFTH AVE Date Closed: 2003-04-28 Site ID: 193832 Program Number: 0106144	***24 5TH AVE***	***NNW 1/4 - 1/2 (0.411 mi.)***	***BU889***	***2041***
SPILL NUMBER 0307474 Date Closed: 2004-01-09 Site ID: 131118 Program Number: 0307474	305 EAST 11TH ST	ENE 1/4 - 1/2 (0.412 mi.)	890	2046
APARTMENT BUILDING Date Closed: 2006-09-25 Site ID: 353498 Program Number: 0507990	159 PRINCE STREET	WSW 1/4 - 1/2 (0.414 mi.)	891	2047
IFO 111 E7TH ST Date Closed: 2000-02-17 Site ID: 129838 Program Number: 9912647	IFO 111 E.7TH ST	E 1/4 - 1/2 (0.421 mi.)	892	2050
UNKNOWN RESIDENCE Date Closed: 2007-06-11 Site ID: 369117 Program Number: 0605862	173 ELIZABETH ST	SSW 1/4 - 1/2 (0.423 mi.)	893	2051
ABOVE GROUND TANK	121 SPRING ST	WSW 1/4 - 1/2 (0.425 mi.)	894	2052

Date Closed: 2017-06-21 Site ID: 544687 Program Number: 1700092				
APT COMPLEX TTF Date Closed: 2016-03-30 Site ID: 480970 Program Number: 1300635	37 WASHINGTON SQ WES	NW 1/4 - 1/2 (0.426 mi.)	895	2054
830 BROADWAY/PRETIUM Date Closed: 1988-11-15 Date Closed: 2001-11-06 Site ID: 196674 Site ID: 196675 Program Number: 8806438 Program Number: 8807426	830 BROADWAY	NNE 1/4 - 1/2 (0.429 mi.)	BS896	2055
105 WOOSTER STREET Date Closed: 2003-02-10 Site ID: 217084 Program Number: 9212937	105 WOOSTER STREET	WSW 1/4 - 1/2 (0.431 mi.)	BV897	2058
APARTMENT BLDG - TTF Date Closed: 2015-03-06 Site ID: 476012 Program Number: 1212854	340 E 11TH ST	ENE 1/4 - 1/2 (0.438 mi.)	898	2059
APARTMENT BLDG Date Closed: 2002-10-23 Site ID: 154414 Program Number: 0007066	141 EAST 3RD ST	ESE 1/4 - 1/2 (0.440 mi.)	899	2060
COMMERCIAL SASSAN SA Date Closed: 2017-04-06 Site ID: 538353 Program Number: 1609563	158 FIRST AVE	E 1/4 - 1/2 (0.441 mi.)	BW900	2061
31 E 12TH ST Date Closed: 2005-11-01 Site ID: 74731 Program Number: 9913336	31 E 12TH ST	N 1/4 - 1/2 (0.444 mi.)	BX901	2063
31 EAST 12TH STREET Date Closed: 2000-03-07 Site ID: 118045 Program Number: 9913000	31 EAST 12TH ST	N 1/4 - 1/2 (0.444 mi.)	BX902	2064
512 BROADWAY Date Closed: 1994-03-25 Site ID: 103353 Program Number: 9315173	***512 BROADWAY***	***SW 1/4 - 1/2 (0.448 mi.)***	***BY903***	***2065***
10 WEST 10TH ST Date Closed: 2005-08-24 Site ID: 99707 Program Number: 0205121	***10 WEST 10TH ST***	***NNW 1/4 - 1/2 (0.448 mi.)***	***BU904***	***2067***
39 5TH AVENUE Date Closed: 1994-03-08 Site ID: 295304 Program Number: 9313956	39 5TH AVENUE	NNW 1/4 - 1/2 (0.449 mi.)	BZ905	2069
COMMERCIAL BUILDING	145 SPRING ST	WSW 1/4 - 1/2 (0.454 mi.)	BV906	2070

Date Closed: 2011-12-20 Site ID: 458099 Program Number: 1110287				
ON SIDEWALK Date Closed: 2001-02-06 Site ID: 84167 Program Number: 0011558	***240 E 13TH ST***	***NE 1/4 - 1/2 (0.462 mi.)***	***907***	***2071***
PROPERTIES SOLUTIONS Date Closed: 2007-11-23 Site ID: 360975 Program Number: 0514284	155 SPRING STREET	WSW 1/4 - 1/2 (0.463 mi.)	BV908	2073
260 EAST 10TH ST Date Closed: 1995-03-31 Site ID: 145786 Program Number: 9416858	260 EAST 10TH ST	E 1/4 - 1/2 (0.464 mi.)	BW909	2074
HSR CORP Date Closed: 2015-11-17 Site ID: 515135 Program Number: 1507638	503-511 BROADWAY	SW 1/4 - 1/2 (0.469 mi.)	BY910	2075
179 MULBERRY ST Date Closed: 1995-06-19 Site ID: 325857 Program Number: 9502099	179 MULBERRY ST	SSW 1/4 - 1/2 (0.473 mi.)	911	2077
TTF Site ID: 486362 Program Number: 1305781	496 BROADWAY	SW 1/4 - 1/2 (0.481 mi.)	BY914	2081
13 E. 12TH STREET Date Closed: 1992-09-08 Site ID: 220273 Program Number: 9206642	13 E. 12TH STREET	N 1/4 - 1/2 (0.481 mi.)	915	2082
DELANCEY ST AND Date Closed: 2003-11-12 Site ID: 300893 Program Number: 9906932	2ND AVE TRACK 3 F LI	S 1/4 - 1/2 (0.482 mi.)	917	2084
LITTLE RED SCHOOL HO Date Closed: 2006-06-30 Site ID: 147642 Program Number: 0209396	272 6TH AVENUE	WNW 1/4 - 1/2 (0.486 mi.)	CA918	2085
LITTLE RED SCHOOL HO Date Closed: 2008-05-29 Site ID: 387510 Program Number: 0706903	272 6TH AVE	WNW 1/4 - 1/2 (0.486 mi.)	CA919	2087
J. PALULIW Date Closed: 1995-02-09 Site ID: 145111 Program Number: 9414756	433 EAST 9TH STREET	E 1/4 - 1/2 (0.486 mi.)	920	2089
TTF Date Closed: 2015-12-17 Site ID: 466068 Program Number: 1203271	65 GREENE STREET	SW 1/4 - 1/2 (0.488 mi.)	CB921	2090
PS 19-M	185 1ST AVE	ENE 1/4 - 1/2 (0.489 mi.)	922	2091

Date Closed: 2005-12-19 Site ID: 168156 Program Number: 0005678				
APT BUILDING Date Closed: 2014-04-11 Site ID: 487621 Program Number: 1306972	62 GREENE ST	SW 1/4 - 1/2 (0.490 mi.)	CB923	2093
BUILDING Date Closed: 2005-02-08 Site ID: 139377 Program Number: 0312394	38 CROSBY ST	SW 1/4 - 1/2 (0.492 mi.)	924	2094
SPILL NUMBER 0112067 Date Closed: 2002-07-22 Site ID: 236703 Program Number: 0112067	2 KING ST	W 1/4 - 1/2 (0.497 mi.)	925	2095

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 34 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
231 CENTRE STREET AS Database: UST, Date of Government Version: 03/26/2018	371 LAFAYETTE ST	0 - 1/8 (0.000 mi.)	A4	30
372 LAFAYETTE ST Database: UST, Date of Government Version: 03/26/2018	372 LAFAYETTE STREET	WNW 0 - 1/8 (0.016 mi.)	A32	102
KALODOP PARK CORP Database: UST, Date of Government Version: 03/26/2018	27 EAST 4TH STREET	NE 0 - 1/8 (0.026 mi.)	A48	132
KALODOP PARK CORP. Database: UST, Date of Government Version: 03/26/2018	403 LAFAYETTE STREET	NNE 0 - 1/8 (0.061 mi.)	D100	222
PENSKE TRUCK LEASING Database: UST, Date of Government Version: 03/26/2018	***23 BOND STREET***	***SSW 0 - 1/8 (0.068 mi.)***	***C110***	***244***
DOWNTOWN AUTOMOTIVE, Database: UST, Date of Government Version: 03/26/2018	***326 BOWERY***	***SSE 0 - 1/8 (0.080 mi.)***	***F153***	***345***
SHEEN CENTER Database: UST, Date of Government Version: 03/26/2018	18 BLEECKER STREET	S 0 - 1/8 (0.116 mi.)	K244	561
36 BLEECKER ST Database: UST, Date of Government Version: 03/26/2018	36 BLEECKER STREET	SSW 0 - 1/8 (0.118 mi.)	K250	570
ELG MOTT STREET LLC Database: UST, Date of Government Version: 03/26/2018	LFG MOTT STREET, LLC	SSW 1/8 - 1/4 (0.142 mi.)	K336	897
OUR LADY OF LORETO R Database: UST, Date of Government Version: 03/26/2018	309 ELIZABETH ST	S 1/8 - 1/4 (0.142 mi.)	P337	899

Lower Elevation	Address	Direction / Distance	Map ID	Page
10-12 BOND STREET PE Database: UST, Date of Government Version: 03/26/2018	10 BOND STREET	WSW 0 - 1/8 (0.048 mi.)	C71	170

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
LAFAYETTE WOMEN SHEL Database: UST, Date of Government Version: 03/26/2018	350 LAFAYETTE STREET	WSW 0 - 1/8 (0.052 mi.)	C76	181
A&P SERVICE STATION Database: UST, Date of Government Version: 03/26/2018	8 BOND ST	WSW 0 - 1/8 (0.066 mi.)	C106	236
39 EAST 4TH ST. Database: UST, Date of Government Version: 03/26/2018	39 EAST 4TH STREET	ENE 0 - 1/8 (0.069 mi.)	H116	262
FORMER COOPER HOTEL Database: UST, Date of Government Version: 03/26/2018	***2 COOPER SQUARE***	***ENE 0 - 1/8 (0.069 mi.)***	***H117***	***265***
NATIONAL AUDUBON SOC Database: UST, Date of Government Version: 03/26/2018	700 BROADWAY	NNW 0 - 1/8 (0.070 mi.)	E121	276
30 COOPER SQ. Database: UST, Date of Government Version: 03/26/2018	***30 COOPER SQUARE***	***ENE 0 - 1/8 (0.091 mi.)***	***H173***	***387***
335 BOWERY OPERATING Database: UST, Date of Government Version: 03/26/2018	335 BOWERY	SE 0 - 1/8 (0.098 mi.)	G198	436
COOPER 25 ASSOCIATES Database: UST, Date of Government Version: 03/26/2018	***25 COOPER SQUARE***	***ENE 0 - 1/8 (0.110 mi.)***	***H231***	***516***
JOSEPH PAPP PUBLIC T Database: UST, Date of Government Version: 03/26/2018	***425 LAFAYETTE STREET***	***NNE 1/8 - 1/4 (0.129 mi.)***	***O297***	***651***
317 BOWERY Database: UST, Date of Government Version: 03/26/2018	317 BOWERY	SSE 1/8 - 1/4 (0.131 mi.)	N303	664
CENTRAL HEATING PLAN Database: UST, Date of Government Version: 03/26/2018	251 MERCER STREET	WNW 1/8 - 1/4 (0.133 mi.)	R313	828
636 BROADWAY ASSOCIA Database: UST, Date of Government Version: 03/26/2018	636 BROADWAY, SUITE	WSW 1/8 - 1/4 (0.145 mi.)	M350	931
740 BROADWAY Database: UST, Date of Government Version: 03/26/2018	740 BROADWAY	N 1/8 - 1/4 (0.165 mi.)	X432	1084
LEONARD FRANZBLAU Database: UST, Date of Government Version: 03/26/2018	91 EAST 4TH STREET	ESE 1/8 - 1/4 (0.186 mi.)	AC507	1231
AMOCO SERVICE STATIO Database: UST, Date of Government Version: 03/26/2018	610 BROADWAY	SW 1/8 - 1/4 (0.186 mi.)	AI511	1241
APARTMENT HOUSE Database: UST, Date of Government Version: 03/26/2018	300 MERCER STREET	N 1/8 - 1/4 (0.195 mi.)	X555	1337
WESTFIELD SECOND ASS Database: UST, Date of Government Version: 03/26/2018	24 2ND AVE	SSE 1/8 - 1/4 (0.206 mi.)	AL602	1439
24 SECOND AVENUE OWN Database: UST, Date of Government Version: 03/26/2018	24 SECOND AVENUE	SSE 1/8 - 1/4 (0.206 mi.)	AL605	1445
BP LAFAYETTE (FORMER Database: UST, Date of Government Version: 03/26/2018	***21 EAST HOUSTON STRE***	***SW 1/8 - 1/4 (0.207 mi.)***	***AI611***	***1459***
CHURCH OF THE NATIVI Database: UST, Date of Government Version: 03/26/2018	***44 2ND AVENUE***	***SE 1/8 - 1/4 (0.216 mi.)***	***AJ670***	***1572***
TISCH SCHOOL OF THE Database: UST, Date of Government Version: 03/26/2018	111 SECOND AVENUE	E 1/8 - 1/4 (0.220 mi.)	AN684	1599
ST PATRICKS YOUTH CE Database: UST, Date of Government Version: 03/26/2018	268 MULBERRY ST	SSW 1/8 - 1/4 (0.229 mi.)	AM727	1673
ST PATRICK'S CHURCH Database: UST, Date of Government Version: 03/26/2018	264 MULBERRY ST	SSW 1/8 - 1/4 (0.249 mi.)	819	1884

EXECUTIVE SUMMARY

NY MOSF UST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY MOSF UST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TATE & LYLE NORTH AM	49 SOUTH SECOND STRE	SE 1/8 - 1/4 (0.224 mi.)	AX703	1629

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 171 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
30 GREAT JONES ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-207543	30 GREAT JONES ST	0 - 1/8 (0.000 mi.)	A5	35
FDNY - ENG 33 Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-600571	42 GREAT JONES ST	SE 0 - 1/8 (0.009 mi.)	A11	44
S.E.G. 380 HOLDINGS Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607417	380 LAFAYETTE STREET	NNW 0 - 1/8 (0.011 mi.)	A13	50
34 EAST 4TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-604601	34 EAST 4TH STREET	E 0 - 1/8 (0.011 mi.)	A16	57
NEW YORK UNIVERSITY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607297	383 LAFAYETTE STREET	NNE 0 - 1/8 (0.013 mi.)	A23	70
28-30 E 4TH ST HOUSI Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-189200	28-30 EAST 4TH ST	E 0 - 1/8 (0.016 mi.)	A25	74
43 GREAT JONES STREE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-603940	43 GREAT JONES STREE	SSE 0 - 1/8 (0.022 mi.)	B43	124
41 GREAT JONES HOLDI Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607239	41 GREAT JONES STREE	SSE 0 - 1/8 (0.022 mi.)	A45	127
48 TENANTS CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-247596	48 GREAT JONES STREE	SE 0 - 1/8 (0.023 mi.)	B46	129
42 BOND ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-611369	42 BOND ST	S 0 - 1/8 (0.049 mi.)	F74	176
KAMPO CULTURAL CENTE Database: AST, Date of Government Version: 03/26/2018	31 BOND STREET	SSW 0 - 1/8 (0.054 mi.)	C78	184

Facility Id: 2-321427				
50 BOND STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607147	50 BOND STREET	SSE 0 - 1/8 (0.056 mi.)	F80	189
FISHER REALTY CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-032522	401 LAFAYETTE ST	NNE 0 - 1/8 (0.058 mi.)	D92	210
PENSKE TRUCK LEASING Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-401269	***23 BOND STREET***	***SSW 0 - 1/8 (0.068 mi.)***	***C110***	***244***
35 BOND STREET CORP. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-329193	35 BOND ST	S 0 - 1/8 (0.071 mi.)	F124	282
708 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-481904	708 BROADWAY	NNE 0 - 1/8 (0.073 mi.)	D129	289
17-19 BLEECKER STREE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-604129	17-19 BLEECKER STREE	S 0 - 1/8 (0.092 mi.)	F177	401
33 BLEECKER STREET C Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607052	33 BLEECKER STREET	SSW 0 - 1/8 (0.095 mi.)	K190	424
49 BLEECKER ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-108278	49 BLEECKER STREET	SSW 0 - 1/8 (0.102 mi.)	K216	487
36 BLEECKER ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-604840	36 BLEECKER STREET	SSW 0 - 1/8 (0.115 mi.)	K242	557
PLANNED PARENTHOOD O Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608739	26 BLEECKER STREET	S 0 - 1/8 (0.116 mi.)	K246	563
THE NOHO STAR BUILDI Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-342319	54 BLEECKER STREET (	SW 1/8 - 1/4 (0.127 mi.)	S285	629
BREMEN HOUSE INC. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607171	312 BOWERY	S 1/8 - 1/4 (0.128 mi.)	N290	637
NEW MOTT APARTMENT C Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-600778	316 MOTT STREET	S 1/8 - 1/4 (0.129 mi.)	K296	649
304 MULBERRY STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607424	304 MULBERRY STREET	SSW 1/8 - 1/4 (0.132 mi.)	K305	668
SOHO COURT Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-603100	301 ELIZABETH STREET	S 1/8 - 1/4 (0.146 mi.)	P360	947
DEMAIMON CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-233889	156 CROSBY STREET	SW 1/8 - 1/4 (0.146 mi.)	S361	949
325 LAFAYETTE TENANT Database: AST, Date of Government Version: 03/26/2018	325/331 LAFAYETTE ST	SW 1/8 - 1/4 (0.146 mi.)	S365	955

Facility Id: 2-607479

CVPII LLC CHRYSTIE P | 5 EAST 1ST STREET | SSE 1/8 - 1/4 (0.154 mi.) | AA389 | 1000
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-610027

SCHULMANN PROPERTIES | 302 MOTT STREET | SSW 1/8 - 1/4 (0.155 mi.) | AB390 | 1002
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-248630

298 MULBERRY STREET | 298 MULBERRY STREET | SSW 1/8 - 1/4 (0.161 mi.) | AB415 | 1054
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-607425

55 HOUSTON REALTY LL | 55 EAST HOUSTON STRE | SSW 1/8 - 1/4 (0.193 mi.) | AB550 | 1328
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-610765

ALMARK HOLDING | 284 MOTT STREET | SSW 1/8 - 1/4 (0.201 mi.) | AB580 | 1390
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-605402

PUCK BUILDING | 295 LAFAYETTE STREET | SW 1/8 - 1/4 (0.204 mi.) | AI588 | 1414
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-402052

266 ELIZABETH ST | 266 ELIZABETH ST | S 1/8 - 1/4 (0.205 mi.) | AO596 | 1429
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-611945

268 ELIZABETH ST PRO | 268 ELIZABETH ST | S 1/8 - 1/4 (0.208 mi.) | AO618 | 1472
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-403261

285 MOTT ST | 285 MOTT ST | SSW 1/8 - 1/4 (0.208 mi.) | AM620 | 1478
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-235261

250 ELIZABETH STREET | 250 ELIZABETH STREET | S 1/8 - 1/4 (0.239 mi.) | BE772 | 1788
Database: AST, Date of Government Version: 03/26/2018
Facility Id: 2-607344

Lower Elevation	Address	Direction / Distance	Map ID	Page
SILK BUILDING CONDOM	14 E 4TH ST	NNW 0 - 1/8 (0.045 mi.)	E65	157
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-319465				
3 GREAT JONES TENANT	3 GREAT JONES STREET	W 0 - 1/8 (0.046 mi.)	C67	162
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605096				
682 TENANT CORP.	682 BROADWAY	WNW 0 - 1/8 (0.061 mi.)	E98	218
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-602716				
54 EAST 4 ST	54 EAST 4 ST	ESE 0 - 1/8 (0.068 mi.)	B114	259
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-160776				
FORMER COOPER HOTEL	***2 COOPER SQUARE***	***ENE 0 - 1/8 (0.069 mi.)***	***H117***	***265***
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-610850				
JORDAN REALTY LLC	676 BROADWAY	W 0 - 1/8 (0.074 mi.)	I130	291
Database: AST, Date of Government Version: 03/26/2018				

Facility Id: 2-236411				
684 BROADWAY OWNERS Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-602825 Facility Id: 2-197025	684 BROADWAY	WNW 0 - 1/8 (0.076 mi.)	I132	294
409 LAFAYETTE ST ASS Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-335657	409 LAFAYETTE ST	NNE 0 - 1/8 (0.076 mi.)	D134	301
NY UNIV Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-234664	***20 COOPER SQ***	***ENE 0 - 1/8 (0.076 mi.)***	***H136***	***305***
Z. BUILDING CORP. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-251704	680 BROADWAY	WNW 0 - 1/8 (0.077 mi.)	I137	309
704 BROADWAY CONDOMI Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-256277	704 BROADWAY	NNW 0 - 1/8 (0.087 mi.)	E169	380
30 COOPER SQ. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-457299 Facility Id: 2-607037	***30 COOPER SQUARE***	***ENE 0 - 1/8 (0.091 mi.)***	***H173***	***387***
59 EAST 4 STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-606886	59 EAST 4TH STREET	E 0 - 1/8 (0.091 mi.)	J174	395
34 COOPER SQUARE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608744	34 COOPER SQUARE	NE 0 - 1/8 (0.093 mi.)	H179	405
56 EAST 4TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605709	56 EAST 4TH STREET	ESE 0 - 1/8 (0.093 mi.)	J182	410
670 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608613	670 BROADWAY	W 0 - 1/8 (0.094 mi.)	I183	412
WYOMING ARTS, CONDOM Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-610364	5 EAST 3RD STREET	ESE 0 - 1/8 (0.094 mi.)	G184	414
5 EAST THIRD STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-606868	5 E THIRD STREET	ESE 0 - 1/8 (0.094 mi.)	G185	416
712-714 BROADWAY COR Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-328200	714 BROADWAY	NNW 0 - 1/8 (0.095 mi.)	L194	431
CITY OF N.Y. DEPT OF Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-601040	7 EAST 3RD STREET	ESE 0 - 1/8 (0.099 mi.)	G204	464
MEN'S SHELTER Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-601677	8 EAST 3RD STREET	SE 0 - 1/8 (0.102 mi.)	G212	478
718 APT INC Database: AST, Date of Government Version: 03/26/2018	718 BROADWAY	N 0 - 1/8 (0.102 mi.)	L215	485

Facility Id: 2-318833				
60 EAST 4TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605711	60 EAST 4TH STREET	ESE 0 - 1/8 (0.103 mi.)	J218	490
419 LAFAYETTE STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-603577	419 LAFAYETTE STREET	NNE 0 - 1/8 (0.106 mi.)	O223	501
COOPER SQ MHA Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-470511	59 -61 EAST 4TH ST.	ESE 0 - 1/8 (0.107 mi.)	J224	503
216 EAST 5TH ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-061905	216 EAST 5TH STREET	E 0 - 1/8 (0.107 mi.)	J225	505
67 EAST 4TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605712	67 EAST 4TH STREET	ESE 0 - 1/8 (0.107 mi.)	J227	507
WASHINGTON PLACE APT Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608819	716 BROADWAY	NNW 0 - 1/8 (0.108 mi.)	L228	509
MEYER COMPLEX Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607711	2-6 WASHINGTON PLACE	NNW 0 - 1/8 (0.108 mi.)	L229	512
207 EAST 5TH ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-155446	207 EAST 5TH ST	ENE 0 - 1/8 (0.109 mi.)	H230	514
COOPER 25 ASSOCIATES Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-116653	***25 COOPER SQUARE***	***ENE 0 - 1/8 (0.110 mi.)***	***H231***	***516***
218 EAST 5TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-610200	218 EAST 5TH STREET	E 0 - 1/8 (0.111 mi.)	J232	523
236 E 5TH ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-296481	236 E 5TH ST	E 0 - 1/8 (0.111 mi.)	J233	525
69 EAST 4TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605710	69 EAST 4TH STREET	ESE 0 - 1/8 (0.112 mi.)	J236	534
211 EAST 5TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-374784	211 EAST 5TH STREET	E 0 - 1/8 (0.116 mi.)	J243	559
648 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608614	648 BROADWAY	WSW 0 - 1/8 (0.116 mi.)	M248	566
BLEECKER TOWER TENAN Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-315397	644 BROADWAY	WSW 0 - 1/8 (0.119 mi.)	M253	579
652 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-294667	652 BROADWAY	WSW 0 - 1/8 (0.119 mi.)	M257	586
428-430 LAFAYETTE ST Database: AST, Date of Government Version: 03/26/2018	428-430 LAFAYETTE ST	NNE 0 - 1/8 (0.123 mi.)	O267	600

Facility Id: 2-612347				
65 BLEECKER STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-057614	65 BLEECKER STREET	WSW 0 - 1/8 (0.124 mi.)	M271	605
75 EAST 4TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-601046	75 EAST 4TH STREET	ESE 1/8 - 1/4 (0.125 mi.)	J284	627
NEW YORK UNIVERSITY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-244384	726-730 BROADWAY	N 1/8 - 1/4 (0.128 mi.)	L292	641
JOSEPH PAPP PUBLIC T Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-601956	***425 LAFAYETTE STREET***	***NNE 1/8 - 1/4 (0.129 mi.)***	***O297***	***651***
250 MERCER SQ OWNER Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-146439	250 MERCER ST	WNW 1/8 - 1/4 (0.132 mi.)	R304	666
H21 EAST 3RD STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605708	21 EAST 3RD STREET	ESE 1/8 - 1/4 (0.132 mi.)	T306	671
50 COOPER SQUARE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608743	50 COOPER SQUARE	NE 1/8 - 1/4 (0.132 mi.)	Q307	673
CENTRAL HEATING PLAN Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-480614 Facility Id: 2-043982	251 MERCER STREET	WNW 1/8 - 1/4 (0.133 mi.)	R314	837
NYU WASHINGTON SQUAR Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-611130	715 BROADWAY	N 1/8 - 1/4 (0.135 mi.)	L317	852
77 BLEECKER ST CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-202584	77 BLEECKER STREET	W 1/8 - 1/4 (0.136 mi.)	U321	868
640 REALTY & 86 REAL Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-609725	640 BROADWAY	WSW 1/8 - 1/4 (0.137 mi.)	M322	870
LAFAYETTE ASTOR ASSO Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-242527	436-440 LAFAYETTE ST	NNE 1/8 - 1/4 (0.144 mi.)	O340	905
THE 62 COOPER SQUARE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-600834	54-62 COOPER SQUARE	NE 1/8 - 1/4 (0.144 mi.)	W347	922
636 BROADWAY ASSOCIA Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-609099	636 BROADWAY, SUITE	WSW 1/8 - 1/4 (0.145 mi.)	M352	935
736 BROADWAY BUILDIN Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-245879	736 BROADWAY	N 1/8 - 1/4 (0.146 mi.)	X366	957
632 BROADWAY Database: AST, Date of Government Version: 03/26/2018	632 BROADWAY	WSW 1/8 - 1/4 (0.152 mi.)	Y380	981

Facility Id: 2-202827				
MORTON TABAK Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-240079	233 EAST 5TH STREET	E 1/8 - 1/4 (0.156 mi.)	V395	1013
226 E. 6TH ST. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605634	226 E. 6TH STREET	E 1/8 - 1/4 (0.158 mi.)	V408	1042
SLOYER-FORMAN, INC. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-291803	21 EAST 2ND STREET	SE 1/8 - 1/4 (0.158 mi.)	Z411	1047
235 EAST 5TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-241636	235 EAST 5TH STREET	E 1/8 - 1/4 (0.160 mi.)	V414	1052
ORDER OF ST BASIL Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-148814	215 E 6TH ST	ENE 1/8 - 1/4 (0.162 mi.)	V416	1056
228 EAST 6TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-241938	228 EAST 6TH STREET	E 1/8 - 1/4 (0.162 mi.)	V420	1062
628 BROADWAY, SUITE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608650	628 BROADWAY	WSW 1/8 - 1/4 (0.162 mi.)	Y423	1066
69 SECOND AVENUE, LL Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-602930	69 2ND AVENUE	ESE 1/8 - 1/4 (0.163 mi.)	AC424	1068
7 WASHINGTON PLACE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-602057	7 WASHINGTON PLACE	NNW 1/8 - 1/4 (0.163 mi.)	AD427	1074
88 BLEECKER ST OWNER Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-267864	88 BLEECKER ST	WSW 1/8 - 1/4 (0.164 mi.)	U429	1078
57 2ND AVE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-213829	57 SECOND AVENUE	ESE 1/8 - 1/4 (0.164 mi.)	T430	1080
237 EAST REALTY LLC Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-314439	237 EAST 5TH ST	E 1/8 - 1/4 (0.164 mi.)	AE431	1082
32-34 E 2 ST Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-116742	32-34 EAST 2ND STREE	SE 1/8 - 1/4 (0.167 mi.)	Z440	1098
232 EQUITIES CORPORA Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-197521	232 EAST 6TH ST	E 1/8 - 1/4 (0.170 mi.)	V449	1113
NYU Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-034932	14 WASHINGTON PLACE	NW 1/8 - 1/4 (0.172 mi.)	AD451	1116
MOKLAM ENTERPRISES I Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-607720	622 BROADWAY	WSW 1/8 - 1/4 (0.173 mi.)	Y452	1119
99 E 4 ST Database: AST, Date of Government Version: 03/26/2018	99 EAST 4TH STREET	ESE 1/8 - 1/4 (0.173 mi.)	AC456	1128

Facility Id: 2-600847				
EAST VILLAGE REALTY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-604946	53 2ND AVENUE A/K/A	SE 1/8 - 1/4 (0.175 mi.)	T461	1136
ORDER OF ST. BASIL Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-149691	16-22 E 7TH ST	ENE 1/8 - 1/4 (0.175 mi.)	V462	1138
NEW YORK UNIVERSITY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-034940	15 WASHINGTON PLACE	NNW 1/8 - 1/4 (0.176 mi.)	AD465	1143
627 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-202800	627 BROADWAY	WSW 1/8 - 1/4 (0.177 mi.)	Y474	1159
285 MERCER STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-601833	285 MERCER STREET	NNW 1/8 - 1/4 (0.179 mi.)	AD486	1178
ELEVEN WAVERLY ASSOC Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-292222	11 WAVERLY PL	NNW 1/8 - 1/4 (0.179 mi.)	AD489	1183
77 SECOND LLC Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-214965	77 2ND AVENUE	ESE 1/8 - 1/4 (0.181 mi.)	AC494	1195
AVALON BOWERY PLACE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-610503	11 EAST FIRST STREET	SSE 1/8 - 1/4 (0.182 mi.)	AA495	1197
40-42 EAST 3RD STREE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605748	40-42 EAST 3RD STREE	SE 1/8 - 1/4 (0.188 mi.)	AJ527	1285
625 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-297259	625 BROADWAY	WSW 1/8 - 1/4 (0.188 mi.)	Y528	1288
300 EAST FIFTH STREE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-399396	300 EAST 5TH STREET	E 1/8 - 1/4 (0.188 mi.)	AC534	1298
60-SECOND AVE CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-159190	60 SECOND AVE	ESE 1/8 - 1/4 (0.189 mi.)	AC536	1302
ISE REALTY GROUP, IN Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-480533	623 BROADWAY	WSW 1/8 - 1/4 (0.190 mi.)	Y539	1309
NEW YORK UNIVERSITY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-601889	16 WAVERLY PLACE	NNW 1/8 - 1/4 (0.195 mi.)	AD554	1335
LESTER/GLASSNER Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-404578 Facility Id: 2-257702	36 EAST 7TH STREET	ENE 1/8 - 1/4 (0.195 mi.)	AN560	1345
CABLE BUILDING Database: AST, Date of Government Version: 03/26/2018	611 BROADWAY	WSW 1/8 - 1/4 (0.195 mi.)	Y563	1358

Facility Id: 2-100455				
N Y U	4 WASHINGTON SQUARE	W 1/8 - 1/4 (0.200 mi.)	AQ577	1384
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-034835				
50 E 3RD ST	50 E 3RD ST	SE 1/8 - 1/4 (0.200 mi.)	AJ579	1388
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-364762				
92 2ND AVENUE	92 SECOND AVENUE	E 1/8 - 1/4 (0.204 mi.)	AE589	1417
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605806				
RED HOUSE REALTY COR	317 EAST 5TH STREET	E 1/8 - 1/4 (0.204 mi.)	AE590	1419
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605762				
47 EAST 3RD STREET	47 EAST 3RD STREET	ESE 1/8 - 1/4 (0.205 mi.)	AJ597	1431
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-214973				
309 E. 5TH STREET	309 EAST FIFTH STREE	E 1/8 - 1/4 (0.205 mi.)	AE599	1433
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-399361				
ST MARKS HOTEL	2 ST. MARKS PLACE	NE 1/8 - 1/4 (0.206 mi.)	AG606	1449
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608643				
8 ST. MARKS PLACE	8 ST. MARKS PLACE	ENE 1/8 - 1/4 (0.211 mi.)	AG632	1497
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-609552				
FILLMORE EAST APARTM	105 2ND AVENUE (223-	E 1/8 - 1/4 (0.213 mi.)	AS634	1501
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-209503				
10 ST MARKS PL	10 ST MARKS PL	ENE 1/8 - 1/4 (0.213 mi.)	AG637	1505
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-117447				
1 ASTOR PLACE	1 ASTOR PLACE	NE 1/8 - 1/4 (0.213 mi.)	AP638	1507
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-612516				
SNUG HARBOR OWNERS I	303 MERCER STREET	N 1/8 - 1/4 (0.215 mi.)	AR657	1550
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-092193				
108 EAST FOURTH LLC	108 EAST 4TH STREET	ESE 1/8 - 1/4 (0.215 mi.)	AT665	1563
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-214930				
94 E. 4TH ST	94 EAST 4TH STREET	ESE 1/8 - 1/4 (0.216 mi.)	AT669	1570
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-609268				
CHURCH OF THE NATIVI	***44 2ND AVENUE***	***SE 1/8 - 1/4 (0.216 mi.)***	***AJ670***	***1572***
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-080896				
59-61 E 3 ST ASSOC	59-61 EAST 3RD STREE	ESE 1/8 - 1/4 (0.218 mi.)	AJ673	1579
Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-090174				
GEORGETOWN PLAZA	60 EAST 8TH STREET	N 1/8 - 1/4 (0.218 mi.)	AV675	1583
Database: AST, Date of Government Version: 03/26/2018				

Facility Id: 2-055069				
304 EAST 5TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-149179	304 EAST 5TH STREET	ESE 1/8 - 1/4 (0.220 mi.)	AT677	1586
41-43 EAST 7TH STREE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-605752	41-43 EAST 7TH STREE	ENE 1/8 - 1/4 (0.224 mi.)	AN704	1631
22 ST MARKS PLACE LP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-099538	22 ST MARKS PLACE	ENE 1/8 - 1/4 (0.226 mi.)	AY710	1641
104 SECOND AVE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-610848	104 SECOND AVE	E 1/8 - 1/4 (0.227 mi.)	AS712	1644
9TH PCT Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-342823	321 EAST 5TH STREET	ESE 1/8 - 1/4 (0.228 mi.)	AT714	1648
TOMAR EQUITIES, LLC Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-214922	60 EAST 3RD STREET	SE 1/8 - 1/4 (0.228 mi.)	AJ715	1651
600 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608888	600 BROADWAY	SW 1/8 - 1/4 (0.228 mi.)	AU716	1653
24 ST. MARK'S PLACE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-281085	24 ST MARKS PLACE	ENE 1/8 - 1/4 (0.229 mi.)	AN717	1655
SELF RELIANCE NY FED Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-090182	108 SECOND AVENUE	E 1/8 - 1/4 (0.231 mi.)	AS733	1688
A.B. IBIBASSI REALTY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-611722	26 ST MARKS PL	ENE 1/8 - 1/4 (0.231 mi.)	AN735	1720
598 BROADWAY REALTY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-612666	598 BROADWAY	SW 1/8 - 1/4 (0.233 mi.)	AU742	1732
AOL, INC. Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-610143 Facility Id: 2-611274	770 BROADWAY	NNE 1/8 - 1/4 (0.234 mi.)	BC747	1745
30 ST MARKS PLACE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-091456	30 ST MARKS PLACE	ENE 1/8 - 1/4 (0.236 mi.)	AN755	1761
66-68 EAST 3RD STREE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-606758	66-68 EAST 3RD STREE	SE 1/8 - 1/4 (0.238 mi.)	BA760	1770
104 E 4TH ST REALTY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-153281	104 E 4TH ST	ESE 1/8 - 1/4 (0.239 mi.)	BA775	1795
32 ST MARKS PLACE Database: AST, Date of Government Version: 03/26/2018	32 ST MARKS PLACE	ENE 1/8 - 1/4 (0.239 mi.)	AN779	1805

Facility Id: 2-091448

599 BROADWAY Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-201804	599 BROADWAY	WSW 1/8 - 1/4 (0.241 mi.)	AU783	1815
8TH ST OWNERS CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-292206	50-54 E 8TH ST	N 1/8 - 1/4 (0.242 mi.)	AR786	1819
FIRS GARDEN CORPORAT Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-237000	38 EAST FIRST STREET	SE 1/8 - 1/4 (0.243 mi.)	AX790	1827
594 BROADWAY BROADWA Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-082694	594 BROADWAY	SW 1/8 - 1/4 (0.244 mi.)	AU792	1831
GIOIA PROPERTIES Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-160490	17 ST MARKS PLACE	ENE 1/8 - 1/4 (0.244 mi.)	AY795	1838
29 THIRD AVE CORP Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-338516	29 THIRD AVE	NE 1/8 - 1/4 (0.245 mi.)	AZ798	1845
125 SECOND AVE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-092649	125 SECOND AVENUE	ENE 1/8 - 1/4 (0.246 mi.)	802	1854
70 EAST THIRD STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-602139	70 EAST THIRD STREET	SE 1/8 - 1/4 (0.247 mi.)	BA807	1862
314 EAST 6TH STREET Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-061697	314 EAST 6TH STREET	E 1/8 - 1/4 (0.248 mi.)	812	1872
RUSSIAN ORTHODOX CAT Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-608199	59 EAST 2ND STREET	SE 1/8 - 1/4 (0.248 mi.)	AX817	1879
P.S. 751 (CAR/DEV/OL Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-604838	113 EAST 4TH STREET	ESE 1/8 - 1/4 (0.249 mi.)	BA824	1893
1 UNIVERSITY PLACE Database: AST, Date of Government Version: 03/26/2018 Facility Id: 2-045705	1 UNIVERSITY PLACE	NNW 1/8 - 1/4 (0.250 mi.)	BG825	1895

NY MOSF AST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY MOSF AST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TATE & LYLE NORTH AM	49 SOUTH SECOND STRE	SE 1/8 - 1/4 (0.224 mi.)	AX702	1625

Facility Status: 1
Facility Status: 1

State and tribal institutional control / engineering control registries

NY RES DECL: A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

A review of the NY RES DECL list, as provided by EDR, has revealed that there is 1 NY RES DECL site within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 67,TAXBLOCK 544	37 EAST 4 STREET	ENE 0 - 1/8 (0.035 mi.)	B58	152
Database: ENV RES DECL, Date of Government Version: 06/27/2017				

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 17 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
372 LAFAYETTE STREET	372 LAFAYETTE STREET	WNW 0 - 1/8 (0.016 mi.)	A34	112
Database: VCP NYC, Date of Government Version: 03/26/2018				
300 LAFAYETTE STREET	300 LAFAYETTE STREET	SW 1/8 - 1/4 (0.200 mi.)	AI578	1387
Database: VCP NYC, Date of Government Version: 03/26/2018				

Lower Elevation	Address	Direction / Distance	Map ID	Page
688 BROADWAY	688 BROADWAY	NW 0 - 1/8 (0.057 mi.)	E84	197
Database: VCP NYC, Date of Government Version: 03/26/2018				
248 NORTH 8TH STREET	248 NORTH 8TH STREET	NE 1/8 - 1/4 (0.205 mi.)	AP598	1433
Database: VCP NYC, Date of Government Version: 03/26/2018				
286-292 NORTH 8TH ST	286-292 NORTH 8TH ST	NE 1/8 - 1/4 (0.209 mi.)	AP623	1484
Database: VCP NYC, Date of Government Version: 03/26/2018				
207 NORTH 8TH STREET	207 NORTH 8TH STREET	NE 1/8 - 1/4 (0.211 mi.)	AP628	1491
Database: VCP NYC, Date of Government Version: 03/26/2018				
219-223 NORTH 8TH ST	219-223 NORTH 8TH ST	NE 1/8 - 1/4 (0.211 mi.)	AP633	1499
Database: VCP NYC, Date of Government Version: 03/26/2018				
212-218 NORTH 9TH ST	212-218 NORTH 9TH ST	NE 1/4 - 1/2 (0.259 mi.)	AZ827	1900
Database: VCP NYC, Date of Government Version: 03/26/2018				
181 MERCER STREET	181 MERCER STREET	WSW 1/4 - 1/2 (0.264 mi.)	BF829	1902
Database: VCP NYC, Date of Government Version: 03/26/2018				

Lower Elevation	Address	Direction / Distance	Map ID	Page
72 SOUTH SECOND STRE Database: VCP NYC, Date of Government Version: 03/26/2018	72 SOUTH SECOND STRE	SE 1/4 - 1/2 (0.270 mi.)	BH831	1904
235-263 NORTH 9TH ST Database: VCP NYC, Date of Government Version: 03/26/2018	235-263 NORTH 9TH ST	ENE 1/4 - 1/2 (0.301 mi.)	BK844	1927
150 WOOSTER STREET Database: VCP NYC, Date of Government Version: 03/26/2018	150 WOOSTER STREET	WSW 1/4 - 1/2 (0.322 mi.)	BJ853	1942
85-89 4TH AVENUE Database: VCP NYC, Date of Government Version: 03/26/2018	85-89 4TH AVENUE	NNE 1/4 - 1/2 (0.323 mi.)	BL856	1977
96 NORTH 1ST STREET Database: VCP NYC, Date of Government Version: 03/26/2018	96 NORTH 1ST STREET	SE 1/4 - 1/2 (0.398 mi.)	BQ878	2023
68-70 SPRING STREET Database: VCP NYC, Date of Government Version: 03/26/2018	68-70 SPRING STREET	SW 1/4 - 1/2 (0.409 mi.)	BT885	2036
47-27 5TH STREET Database: VCP NYC, Date of Government Version: 03/26/2018	47-27 5TH STREET	N 1/4 - 1/2 (0.476 mi.)	BZ913	2080
42 CROSBY STREET Database: VCP NYC, Date of Government Version: 03/26/2018	42 CROSBY STREET	SW 1/4 - 1/2 (0.482 mi.)	BY916	2083

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 01/19/2018 has revealed that there are 2 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
19 EAST HOUSTON STRE	19 EAST HOUSTON STRE	SW 1/8 - 1/4 (0.215 mi.)	AI661	1556
LAFAYETTE STREET SCH	205 LAFAYETTE STREET	SSW 1/4 - 1/2 (0.475 mi.)	912	2078

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/12/2018 has revealed that there are 50 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPILL NUMBER 0209425 Date Closed: 2004-01-13	30 GREAT JONES ST	0 - 1/8 (0.000 mi.)	A7	37

Spill Number: 0209425 Site ID: 147649				
HARWOOD PROPERTY Date Closed: 1996-07-12 Spill Number: 9604778 Site ID: 75430	25 GREAT JONES ST	WSW 0 - 1/8 (0.008 mi.)	A10	43
SPILL NUMBER 9911688 Date Closed: 2003-02-26 Spill Number: 9911688 Site ID: 305454	28-30 E 4TH ST	E 0 - 1/8 (0.016 mi.)	A26	76
WASTE OIL SPILL AT G Date Closed: 2015-05-22 Spill Number: 1304085 Site ID: 484597	372 LAFEYETTE ST	WNW 0 - 1/8 (0.016 mi.)	A33	110
LOFT BUILDING Date Closed: 2007-03-06 Spill Number: 0613089 Site ID: 378055	43 GREAT JONES STREE	SSE 0 - 1/8 (0.022 mi.)	B44	126
E 4TH ST & LAFAYETTE Date Closed: 1992-07-07 Spill Number: 9203983 Site ID: 149163	E 4TH ST & LAFAYETTE	N 0 - 1/8 (0.027 mi.)	A51	138
OZY MANDIUS REALTY Date Closed: 2013-08-08 Spill Number: 0808740 Site ID: 406147	348 BOWERY ST	ESE 0 - 1/8 (0.038 mi.)	B59	153
20 BOND ST. CR. LAFA Date Closed: 1993-09-03 Spill Number: 9306682 Site ID: 315381	20 BOND ST.CR. LAFAY	SW 0 - 1/8 (0.042 mi.)	C61	155
20 BOND STREET Date Closed: 1994-06-19 Spill Number: 9400898 Site ID: 306475	20 BOND STREET	SW 0 - 1/8 (0.042 mi.)	C62	156
FORMER PENSKE Date Closed: 2008-09-18 Spill Number: 0330066 Site ID: 167408	40 BOND STREET	S 0 - 1/8 (0.046 mi.)	C66	160
RESIDENTIAL BLDG Date Closed: 1997-02-21 Spill Number: 9613681 Site ID: 133060	24 BOND ST	SSW 0 - 1/8 (0.046 mi.)	C68	165
SPILL NUMBER 9801771 Date Closed: 1998-05-11 Date Closed: 1998-05-21 Spill Number: 9801771 Spill Number: 9802317 Site ID: 285235 Site ID: 284400	22 BOND ST	SW 0 - 1/8 (0.057 mi.)	C87	202
SUNOCO STATION Date Closed: 1998-04-01	THE BOWERY AND SECON	SE 0 - 1/8 (0.061 mi.)	F95	215

Spill Number: 9713749 Site ID: 59489				
GAS STATION Date Closed: 2000-12-22 Spill Number: 0030033 Site ID: 297178	BOND ST / BOWERY	SE 0 - 1/8 (0.061 mi.)	F96	216
MANHOLE #26829 Date Closed: 2006-01-11 Spill Number: 0506036 Site ID: 351166	BOND ST, SWC BOWERY	SE 0 - 1/8 (0.061 mi.)	F97	217
PARKING GARAGE Date Closed: 2006-01-31 Spill Number: 0209806 Site ID: 128572	403 LAFAYETTE ST	NNE 0 - 1/8 (0.061 mi.)	D99	220
340 BOWERY Date Closed: 1992-06-26 Spill Number: 9203601 Site ID: 166376	340 BOWERY	SSE 0 - 1/8 (0.065 mi.)	F104	233
SPILL NUMBER 9908485 Date Closed: 1999-10-13 Spill Number: 9908485 Site ID: 268512	35 BOND ST	S 0 - 1/8 (0.071 mi.)	F125	284
DOWNTOWN AUTOMOTIVE, Date Closed: 2017-01-18 Spill Number: 9706763 Site ID: 253569	***326 BOWERY***	***SSE 0 - 1/8 (0.080 mi.)***	***F153***	***345***
RESIDENTS Date Closed: 2001-09-26 Spill Number: 0106638 Site ID: 250155	33 BLEECKER STREET	SSW 0 - 1/8 (0.095 mi.)	K188	421
SPILL NUMBER 0211638 Date Closed: 2003-11-13 Spill Number: 0211638 Site ID: 247263	17-19 BLEECKER ST	S 0 - 1/8 (0.097 mi.)	F196	434
IN ROADWAY Date Closed: 2010-03-22 Spill Number: 0913422 Site ID: 426366	BOND/BOWERY INTERSEC	SSE 0 - 1/8 (0.098 mi.)	N197	435

Lower Elevation	Address	Direction / Distance	Map ID	Page
217199; 6 GREAT JONE Date Closed: 2009-07-28 Spill Number: 0914270 Site ID: 433005	6 GREAT JONES ST	WNW 0 - 1/8 (0.030 mi.)	A56	148
INTERSECTION Date Closed: 2004-08-25 Spill Number: 0404425 Site ID: 265321	BOWERY / 3RD ST	ESE 0 - 1/8 (0.039 mi.)	B60	154
CON EDISON Date Closed: 1997-12-10	***10 BOND ST***	***WSW 0 - 1/8 (0.048 mi.)***	***C70***	***167***

Date Closed: 2008-04-15 Spill Number: 9710410 Spill Number: 0608806 Site ID: 74312 Site ID: 372842				
BASEMENT OF Date Closed: 1997-09-26 Date Closed: 1998-02-25 Spill Number: 9707584 Spill Number: 9707585 Site ID: 150434 Site ID: 284299	8 BOND ST	WSW 0 - 1/8 (0.066 mi.)	C107	240
HOMELESS SHELTER Date Closed: 2010-05-26 Spill Number: 1002106 Site ID: 435205	I/F/O 8 EAST 3RD ST	ESE 0 - 1/8 (0.068 mi.)	G115	261
FORMER HOTEL Date Closed: 2009-05-20 Spill Number: 0802061 Site ID: 398133	2 COOPER SQUARE	ENE 0 - 1/8 (0.069 mi.)	H118	270
700 BROADWAY/MANHATT Date Closed: 1998-02-04 Spill Number: 9003151 Site ID: 290665	700 BROADWAY	NNW 0 - 1/8 (0.070 mi.)	E120	275
SPILL NUMBER 9813854 Date Closed: 2003-03-04 Spill Number: 9813854 Site ID: 120559	1 BOND ST APT #6C	WSW 0 - 1/8 (0.072 mi.)	C128	288
VAULT 9133 Date Closed: 2013-08-15 Spill Number: 1303593 Site ID: 484086	3 BOND ST	WSW 0 - 1/8 (0.074 mi.)	C131	293
SPILL NUMBER 0204004 Date Closed: 2003-05-16 Spill Number: 0204004 Site ID: 246396	20 COOPER SQUARE	ENE 0 - 1/8 (0.076 mi.)	H135	304
NY UNIV Date Closed: 2013-07-03 Spill Number: 1205385 Site ID: 468321	***20 COOPER SQ***	***ENE 0 - 1/8 (0.076 mi.)***	***H136***	***305***
SPILL NUMBER 0004644 Date Closed: 2002-11-27 Spill Number: 0004644 Site ID: 286853	16-20 COOPER SQ	ENE 0 - 1/8 (0.080 mi.)	H147	334
219641; GREAT JONES Date Closed: 2009-12-31 Spill Number: 0914664 Site ID: 433766	GREAT JONES ST AND B	WNW 0 - 1/8 (0.080 mi.)	I149	339
214191; GREAT JONES Date Closed: 2008-10-28 Spill Number: 0814546	GREAT JONES ST AND B	WNW 0 - 1/8 (0.080 mi.)	I151	342

Site ID: 432692				
TM 3691 Date Closed: 2004-08-20 Spill Number: 0401482 Site ID: 99690	1 WEST 3RD STREET	WNW 0 - 1/8 (0.081 mi.)	I157	359
214224; E 4 ST AND B Date Closed: 2008-10-26 Spill Number: 0814548 Site ID: 432696	E 4 ST AND BROADWAY	NW 0 - 1/8 (0.084 mi.)	E164	373
4TH ST & B'WAY/NAT'L Date Closed: 1996-10-23 Spill Number: 9107147 Site ID: 197267	4TH ST & BROADWAY	NW 0 - 1/8 (0.084 mi.)	E166	376
SERVICE BOX 37911 Date Closed: 2003-07-28 Spill Number: 0103876 Site ID: 81004	BLEECKER ST/LAFAYETT	SW 0 - 1/8 (0.085 mi.)	C167	377
30 COOPER SQ. Date Closed: 2006-11-13 Spill Number: 0609172 Site ID: 373313	***30 COOPER SQUARE***	***ENE 0 - 1/8 (0.091 mi.)***	***H173***	***387***
COOPERS SQUARE HOTEL Date Closed: 2006-12-12 Spill Number: 0604726 Site ID: 367757	27 COOPERS SQUARE	ENE 0 - 1/8 (0.092 mi.)	H176	399
MANHOLE #31124 Date Closed: 2004-01-08 Spill Number: 9812624 Site ID: 177195	CROSBY ST/BLEECKER S	WSW 0 - 1/8 (0.095 mi.)	M195	433
SPILL NUMBER 9812634 Date Closed: 1999-01-14 Date Closed: 2006-05-23 Spill Number: 9812634 Spill Number: 0601756 Site ID: 160868 Site ID: 364059	8 EAST 3RD ST	SE 0 - 1/8 (0.102 mi.)	G211	476
PARKING GARAGE Date Closed: 2014-07-08 Spill Number: 1403725 Site ID: 497092	714 BROADWAY	NNW 0 - 1/8 (0.102 mi.)	L217	489
COMMERCIAL Spill Number: 1709872 Site ID: 566338	644 BROADWAY	WSW 0 - 1/8 (0.119 mi.)	M254	581
SPILL NUMBER 0209371 Date Closed: 2002-12-12 Spill Number: 0209371 Site ID: 165999	644 BROADWAY	WSW 0 - 1/8 (0.119 mi.)	M255	583
215 E. 5TH ST Date Closed: 1995-11-14 Spill Number: 9510011 Site ID: 137877	215 E. 5TH ST	E 0 - 1/8 (0.120 mi.)	J261	591
321 BOWERY COURT LLC	321 BOWERY STREET	SSE 0 - 1/8 (0.121 mi.)	N265	596

Date Closed: 2002-08-30
Spill Number: 0107529
Site ID: 215077

CON EDISON BENZENE A Date Closed: 2011-08-09 Spill Number: 1102669 Site ID: 450189	COOPER SQ & EAST 6TH	ENE 0 - 1/8 (0.123 mi.)	Q269	603

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/11/2017 has revealed that there are 231 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE 5	***379 LAFAYETTE ST***	***0 - 1/8 (0.000 mi.)***	***A9***	***39***
CON EDISON MANHOLE 3	***LAFAYETTE ST & GREAT***	***W 0 - 1/8 (0.010 mi.)***	***A12***	***47***
PETERSBURG PRESS INC	***380 LAFAYETTE ST***	***NNW 0 - 1/8 (0.011 mi.)***	***A14***	***53***
CON EDISON	***30-32 E 4TH ST & BOW***	***E 0 - 1/8 (0.012 mi.)***	***A17***	***59***
NYU	***383 LAFAYETTE ST***	***NNE 0 - 1/8 (0.013 mi.)***	***A22***	***66***
CON EDISON SERVICE B	***378 LAFAYETTE ST FRO***	***WNW 0 - 1/8 (0.016 mi.)***	***A30***	***96***
CON EDISON MANHOLE 5	***372 LAFAYETTE ST***	***WNW 0 - 1/8 (0.016 mi.)***	***A31***	***99***
CON EDISON SERVICE B	***372 LAFAYETTE ST FRO***	***WNW 0 - 1/8 (0.016 mi.)***	***A36***	***115***
CON EDISON	***38 E 4TH ST***	***E 0 - 1/8 (0.018 mi.)***	***B37***	***117***
CON EDISON SERVICE B	***33 GREAT JONES ST***	***S 0 - 1/8 (0.019 mi.)***	***A38***	***119***
CON EDISON SERVICE B	EAST 4 ST & LAFAYETT	N 0 - 1/8 (0.027 mi.)	A52	139
CON EDISION - MH3792	***EAST 4TH STREET AND***	***N 0 - 1/8 (0.028 mi.)***	***A54***	***145***
CON EDISON SERVICE B	***47 GREAT JONES ST***	***SSE 0 - 1/8 (0.029 mi.)***	***B55***	***146***
CON EDISON	***342 BOWERY***	***SE 0 - 1/8 (0.057 mi.)***	***F89***	***205***
CON EDISON	***340 BOWERY***	***SE 0 - 1/8 (0.061 mi.)***	***F102***	***231***
CON EDISON SERVICE B	***23 BOND ST FRONT OF***	***SSW 0 - 1/8 (0.068 mi.)***	***C111***	***251***
PENSKE TRUCK LEASING	***23 BOND ST***	***SSW 0 - 1/8 (0.068 mi.)***	***C113***	***255***
CON EDISON SERVICE B	***39 BOND ST***	***S 0 - 1/8 (0.069 mi.)***	***F119***	***273***
CON EDISON SERVICE B	***19 BOND ST FRONT OF***	***SW 0 - 1/8 (0.071 mi.)***	***C123***	***280***
CON EDISON SERVICE B	***334 BOWERY FRONT OF***	***SSE 0 - 1/8 (0.080 mi.)***	***F145***	***329***
CON EDISON SERVICE B	***334 BOWERY FRONT OF***	***SSE 0 - 1/8 (0.080 mi.)***	***F146***	***331***
SERVICE STATION	***326 BOWERY AVE***	***SSE 0 - 1/8 (0.080 mi.)***	***F152***	***343***
CON EDISON SERVICE B	***59 BOND ST FRONT OF***	***SSE 0 - 1/8 (0.090 mi.)***	***F171***	***383***
CON EDISON SERVICE B	***23 BLEECKER ST***	***S 0 - 1/8 (0.094 mi.)***	***F187***	***420***
CON EDISON MANHOLE:	33 BLEECKER ST FRON	SSW 0 - 1/8 (0.095 mi.)	K191	426
CON EDISON GAS DRIP:	***BLECKER ST & ELIZABE***	***S 0 - 1/8 (0.105 mi.)***	***K220***	***495***
CON EDISON SERVICE B	***BLEECKER ST & ELIZAB***	***S 0 - 1/8 (0.105 mi.)***	***K222***	***498***
CON EDISON MANHOLE:	***341 LAFAYETTE ST FRO***	***SW 0 - 1/8 (0.112 mi.)***	***K237***	***536***
CON EDISON SERVICE B	***BLEECKER ST & LAFAYE***	***SW 0 - 1/8 (0.113 mi.)***	***K239***	***539***
MTA NYCT BLEECKER ST	***BLEECKER & LAFAYETTE***	***SW 0 - 1/8 (0.113 mi.)***	***K240***	***541***
CON EDISON	***48 BLEEKER ST***	***SSW 0 - 1/8 (0.120 mi.)***	***K260***	***589***
CON EDISON SERVICE B	***307 BOWERY FRONT OF***	***SSE 1/8 - 1/4 (0.138 mi.)***	***N324***	***875***
CON EDISON	***315 MOTT ST***	***SSW 1/8 - 1/4 (0.139 mi.)***	***K332***	***888***
CON EDISON	***306 MOTT ST***	***SSW 1/8 - 1/4 (0.146 mi.)***	***P359***	***946***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	***324 LAFAYETTE ST***	***SW 1/8 - 1/4 (0.148 mi.)***	***S370***	***963***
CON EDISON SERVICE B	***308 BOWERY & HOUSTON***	***SSE 1/8 - 1/4 (0.150 mi.)***	***P376***	***975***
CON EDISON SERVICE B	***302 BOWERY FRONT OF***	***S 1/8 - 1/4 (0.154 mi.)***	***P387***	***994***
LAFAYETTE AUTO REPAI	***321 LAFAYETTE ST***	***SW 1/8 - 1/4 (0.154 mi.)***	***S388***	***997***
CON EDISON SERVICE B	***302 MOTT ST***	***SSW 1/8 - 1/4 (0.155 mi.)***	***AB391***	***1005***
CON EDISON	***298 MULBERRY ST***	***SSW 1/8 - 1/4 (0.157 mi.)***	***AB396***	***1015***
CON EDISON	***305 MULBERRY ST***	***SW 1/8 - 1/4 (0.157 mi.)***	***S407***	***1041***
CON EDISON	***316 MOTT ST & HOUSTO***	***SSW 1/8 - 1/4 (0.174 mi.)***	***AB459***	***1133***
CON EDISON SERVICE B	***41 E HOUSTON ST***	***SSW 1/8 - 1/4 (0.195 mi.)***	***AM559***	***1343***
GIGANTE VAZ & PARTNE	***295 LAFAYETTE ST - 7***	***SW 1/8 - 1/4 (0.204 mi.)***	***AI586***	***1403***
PRATT INSTITUTE - PU	***295 LAFAYETTE ST 2ND***	***SW 1/8 - 1/4 (0.204 mi.)***	***AI587***	***1406***
GOTTLIEB W REAL ESTA	***284 MULBERRY ST***	***SSW 1/8 - 1/4 (0.208 mi.)***	***AM619***	***1475***
CON EDISON	279 BOWERY	S 1/8 - 1/4 (0.230 mi.)	AO729	1677
CON EDISON	***269 BOWERY***	***S 1/8 - 1/4 (0.235 mi.)***	***AO751***	***1755***
CON EDISON	***268 BOWERY***	***S 1/8 - 1/4 (0.238 mi.)***	***BE762***	***1774***
CON EDISON	268 BOWERY	S 1/8 - 1/4 (0.238 mi.)	BE765	1778
CON EDISON SERVICE B	***265 BOWERY STANTON S***	***S 1/8 - 1/4 (0.244 mi.)***	***AO794***	***1835***

Lower Elevation	Address	Direction / Distance	Map ID	Page
PANORAMIC AUTO SERVI	10 BOND ST	WSW 0 - 1/8 (0.048 mi.)	C72	173
CON EDISON SERVICE B	10 BOND ST	WSW 0 - 1/8 (0.048 mi.)	C73	175
NEW YORK CITY OF HUM	***350 LAFAYETTE ST***	***WSW 0 - 1/8 (0.052 mi.)***	***C75***	***178***
CON EDISON SERVICE B	***6 BOND ST***	***WSW 0 - 1/8 (0.055 mi.)***	***C79***	***186***
BOWERY AND 4TH STREE	***BOWERY AND 4TH STREE***	***E 0 - 1/8 (0.057 mi.)***	***B86***	***200***
CON EDISON MANHOLE:	***GREAT JONES ST & BOW***	***SE 0 - 1/8 (0.058 mi.)***	***G91***	***208***
CON EDISON SERVICE B	***11 E 4TH ST***	***NNW 0 - 1/8 (0.059 mi.)***	***E93***	***212***
CON EDISON SERVICE B	11 COOPER SQ FRONT O	E 0 - 1/8 (0.071 mi.)	H127	287
CON EDISON SERVICE B	***686-88 BROADWAY & GT***	***WNW 0 - 1/8 (0.076 mi.)***	***E133***	***299***
CON EDISON GAS MAIN	***COOPER SQ & E 5TH ST***	***ENE 0 - 1/8 (0.079 mi.)***	***H141***	***315***
CON EDISON EXCAVATIO	***COOPER SQUARE AND EA***	***ENE 0 - 1/8 (0.079 mi.)***	***H143***	***325***
CON EDISON SERVICE B	***237 E 5TH ST & COOPE***	***ENE 0 - 1/8 (0.079 mi.)***	***H144***	***328***
VERIZON LOG 32884	***BROADWAY & GREAT JON***	***WNW 0 - 1/8 (0.080 mi.)***	***I150***	***340***
CON EDISON SERVICE B	15 COOPER SQ FRONT O	ENE 0 - 1/8 (0.081 mi.)	H155	357
CON EDISON GAS DRIP	***E 4TH ST & BROADWAY***	***NW 0 - 1/8 (0.084 mi.)***	***E159***	***361***
CON EDISON GAS MAIN	***WEST 4TH STREET AND***	***NW 0 - 1/8 (0.084 mi.)***	***E160***	***363***
CON EDISON GAS MAIN	***W 4TH ST & BROADWAY***	***NW 0 - 1/8 (0.084 mi.)***	***E163***	***369***
CON EDISON	***BROADWAY & E 4TH ST***	***NW 0 - 1/8 (0.084 mi.)***	***E165***	***374***
V6421	***3 W. 3RD STREET***	***WNW 0 - 1/8 (0.093 mi.)***	***I178***	***403***
CON EDISON SERVICE B	***34 COOPER SQ FRONT O***	***NE 0 - 1/8 (0.093 mi.)***	***H180***	***407***
CON EDISON SERVICE B	***331 BOWERY FRONT OF***	***SE 0 - 1/8 (0.095 mi.)***	***G192***	***427***
CON EDISON SERVICE B	***36 COOPER SQ FRONT O***	***ENE 0 - 1/8 (0.098 mi.)***	***H201***	***459***
ALCON ENGRAVERS INC	***656 BROADWAY***	***WSW 0 - 1/8 (0.099 mi.)***	***I205***	***466***
CON EDISON	699 BROADWAY	NNW 0 - 1/8 (0.100 mi.)	L208	473
CON EDISON SERVICE B	***40 COOPER SQ FRONT O***	***NE 0 - 1/8 (0.102 mi.)***	***H209***	***473***
CON EDISON SERVICE B	***327 BOWERY FRONT OF***	***SE 0 - 1/8 (0.102 mi.)***	***N213***	***481***
CON EDISON	***65 BLEEKER STREET***	***SW 0 - 1/8 (0.105 mi.)***	***M219***	***493***
WHALEDENT INTL	***236 5TH AVE***	***E 0 - 1/8 (0.111 mi.)***	***J234***	***527***
CON EDISON SERVICE B	***8 E 2ND ST & BOWERY***	***SSE 0 - 1/8 (0.112 mi.)***	***N235***	***531***
CON EDISON SERVICE B	***657 BROADWAY***	***W 0 - 1/8 (0.121 mi.)***	***M262***	***592***
CON EDISON SERVICE B	***657 BROADWAY***	***W 0 - 1/8 (0.121 mi.)***	***M263***	***594***
CON EDISON SERVICE B	***428 LAFAYETTE ST***	***NNE 0 - 1/8 (0.123 mi.)***	***O266***	***598***
CON EDISON SERVICE B	***653 BROADWAY***	***W 0 - 1/8 (0.125 mi.)***	***M272***	***607***
CON EDISON VAULT: 99	***41 COOPER SQ***	***ENE 0 - 1/8 (0.125 mi.)***	***Q273***	***609***
CON EDISON VAULT: 99	***41 COOPER SQ***	***ENE 0 - 1/8 (0.125 mi.)***	***Q275***	***612***
CON EDISON VAULT: 93	41 COOPER SQ VAULT 9	ENE 0 - 1/8 (0.125 mi.)	Q276	613

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B	***41-55 COOPER SQ FRON***	***ENE 0 - 1/8 (0.125 mi.)***	***Q280***	***621***
CON EDISON VAULT: 99	***41 COOPER SQ VAULT 9***	***ENE 0 - 1/8 (0.125 mi.)***	***Q282***	***624***
V3178	***423 LAFAYETTE STREET***	***NNE 1/8 - 1/4 (0.127 mi.)***	***O286***	***631***
CON EDISON	***430 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.128 mi.)***	***O287***	***633***
CON EDISON MANHOLE 3	***425 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.129 mi.)***	***O300***	***658***
CON EDISON SERVICE B	***228 E 5TH ST FRONT O***	***E 1/8 - 1/4 (0.129 mi.)***	***J301***	***660***
CON EDISON SERVICE B	***166-168 CROSBY ST &***	***SW 1/8 - 1/4 (0.132 mi.)***	***M308***	***675***
CON EDISON SERVICE B	***647 BROADWAY***	***WSW 1/8 - 1/4 (0.132 mi.)***	***M310***	***680***
NEW YORK UNIVERSITY	***251 MERCER ST***	***WNW 1/8 - 1/4 (0.133 mi.)***	***R311***	***682***
CON EDISON SERVICE B	***429 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.133 mi.)***	***O315***	***848***
NYU TISCH SCHOOL OF	***721-725 BROADWAY***	***N 1/8 - 1/4 (0.136 mi.)***	***L318***	***861***
CON EDISON SERVICE B	***640 BROADWAY FRONT O***	***WSW 1/8 - 1/4 (0.137 mi.)***	***M323***	***872***
CON EDISON MANHOLE 5	***BROADWAY & BLEEKER S***	***WSW 1/8 - 1/4 (0.138 mi.)***	***M328***	***882***
C-SQUAREWOOD LLC	***52-62 COOPER SQ***	***NE 1/8 - 1/4 (0.138 mi.)***	***Q329***	***884***
CON ED - V 2708	***71 BLEEKER ST***	***WSW 1/8 - 1/4 (0.141 mi.)***	***U333***	***890***
CON EDISON SERVICE B	***216 E 6 ST FRONT OF***	***ENE 1/8 - 1/4 (0.141 mi.)***	***V335***	***894***
CON EDISON MANHOLE:	***436 LAFFAYETTE AVE S***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O342***	***909***
CON EDISON MANHOLE 3	***436 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O343***	***912***
CON EDISON	***436 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O346***	***921***
CON EDISON	***229 E 5TH ST***	***E 1/8 - 1/4 (0.148 mi.)***	***V367***	***960***
CON EDISON SERVICE B	***736 BROADWAY***	***N 1/8 - 1/4 (0.148 mi.)***	***X371***	***966***
CON EDISON SERVICE B	***85 E 4TH ST & COOPER***	***ESE 1/8 - 1/4 (0.148 mi.)***	***T373***	***969***
CON EDISON	85 E 4TH ST	ESE 1/8 - 1/4 (0.148 mi.)	T374	973
CON EDISION - MH 272	***634 BROADWAY 634 BRO***	***WSW 1/8 - 1/4 (0.152 mi.)***	***Y381***	***983***
CORINNE OFFSET INC	***737 BROADWAY***	***N 1/8 - 1/4 (0.152 mi.)***	***X383***	***987***
CON EDISON SERVICE B	***738 BROADWAY***	***N 1/8 - 1/4 (0.152 mi.)***	***X384***	***990***
CON EDISON SERVICE B	***439 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.155 mi.)***	***W392***	***1007***
CON EDISON SERVICE B	***222 E 6 ST FRONT OF***	***E 1/8 - 1/4 (0.155 mi.)***	***V393***	***1009***
CON EDISON	82 E 4TH ST	ESE 1/8 - 1/4 (0.157 mi.)	T401	1033
CON EDISON SERVICE B	***6 E 1ST ST***	***SSE 1/8 - 1/4 (0.157 mi.)***	***AA403***	***1035***
BAHMAN CLEANERS	***210 MERCER ST***	***W 1/8 - 1/4 (0.158 mi.)***	***U409***	***1043***
CON EDISON	***30 E 2ND ST***	***SE 1/8 - 1/4 (0.162 mi.)***	***Z417***	***1058***
CON EDISON	***69 2ND AVE***	***ESE 1/8 - 1/4 (0.162 mi.)***	***AC421***	***1064***
CON EDISION - MH2722	***626 BROADWAY AND E.H***	***WSW 1/8 - 1/4 (0.167 mi.)***	***Y438***	***1094***
CON EDISON MANHOLE 2	***626 BROADWAY***	***WSW 1/8 - 1/4 (0.167 mi.)***	***Y439***	***1096***
CON EDISON	29 W 4TH ST	NW 1/8 - 1/4 (0.168 mi.)	AF443	1104
CON EDISON SERVICE B	***41 E 2ND AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***Z447***	***1109***
CON EDISON SERVICE B	***226-28 MERCER ST & B***	***W 1/8 - 1/4 (0.172 mi.)***	***U450***	***1115***
MOKLAM BUILDING	***622 BROADWAY***	***WSW 1/8 - 1/4 (0.173 mi.)***	***Y454***	***1122***
CON EDISON SERVICE B	***749-51 W BROADWAY***	***N 1/8 - 1/4 (0.174 mi.)***	***X458***	***1131***
CON EDISON SERVICE B	69-71 2ND AVE & 4TH	ESE 1/8 - 1/4 (0.176 mi.)	AC463	1140
CON EDISON SERVICE B	***E 4TH ST & 2 ND AVE***	***ESE 1/8 - 1/4 (0.177 mi.)***	***AC468***	***1148***
CON EDISON SERVICE B	***83-85 2ND AVE & 4TH***	***ESE 1/8 - 1/4 (0.177 mi.)***	***AC469***	***1150***
CON EDISON SERVICE B	***79 2ND AVE & 4TH ST***	***ESE 1/8 - 1/4 (0.177 mi.)***	***AC470***	***1152***
CON EDISON SERVICE B	***73-75 2ND AVE & 4TH***	***ESE 1/8 - 1/4 (0.177 mi.)***	***AC471***	***1153***
CON EDISON SERVICE B	***30 E 7TH ST & HALL P***	***ENE 1/8 - 1/4 (0.177 mi.)***	***AG472***	***1154***
CON EDISON MANHOLE 5	***E 3RD ST & 2ND AVE S***	***SE 1/8 - 1/4 (0.177 mi.)***	***T473***	***1155***
JIM HENSON CO THE	***627 BROADWAY - 9TH F***	***WSW 1/8 - 1/4 (0.177 mi.)***	***Y475***	***1161***
CON EDISON SERVICE B	***WEST 4TH AVE & GREEN***	***NW 1/8 - 1/4 (0.177 mi.)***	***AF477***	***1165***
CON EDISON SERVICE B	WEST 4TH AVE & GREEN	NW 1/8 - 1/4 (0.177 mi.)	AF479	1168
CON EDISON SERVICE B	WEST 4TH AVE & GREEN	NW 1/8 - 1/4 (0.177 mi.)	AF481	1171
CON EDISON SERVICE B	***237 GREENE ST & 4TH***	***NW 1/8 - 1/4 (0.178 mi.)***	***AF483***	***1173***
CON EDISON	12 WAVERLY PL	NNW 1/8 - 1/4 (0.183 mi.)	AD499	1205
NYCDEP - HAZARDOUS M	***51 ASTOR PL RM 643***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH503***	***1217***
MINSKOFF EQUITY BLDG	***51 ASTOR PL***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH504***	***1222***
CON EDISON VAULT: 96	***51 ASTOR PL***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH505***	***1227***

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	610 BROADWAY	SW 1/8 - 1/4 (0.186 mi.)	AI512	1252
TRIBECA GAS INC	***610 BROADWAY***	***SW 1/8 - 1/4 (0.186 mi.)***	***AI514***	***1255***
CON EDISON SERVICE B	***444 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***AH515***	***1258***
CON EDISON SERVICE B	***44 E 2ND ST & 2ND AV***	***SE 1/8 - 1/4 (0.188 mi.)***	***Z516***	***1262***
CON EDISON SERVICE B	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH517***	***1265***
MTA NYCT ASTOR PL ST	***ASTOR PL & LAFAYETTE***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH519***	***1269***
CON EDISON MANHOLE:	***E LAFAYETTE ST & AST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH521***	***1273***
CON EDISON	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH522***	***1275***
CON EDISON MANHOLE:	ASTOR PL & LAFAYETTE	NNE 1/8 - 1/4 (0.188 mi.)	AH523	1279
CON EDISON GAS DRIP	***ASTOR PL & LAFAYETTE***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH524***	***1280***
CON EDISON MANHOLE:	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH525***	***1282***
CON EDISON SERVICE B	***2ND AVE & 5TH ST***	***E 1/8 - 1/4 (0.188 mi.)***	***AC532***	***1294***
CON EDISON SERVICE B	***623 BROADWAY FRONT***	***WSW 1/8 - 1/4 (0.190 mi.)***	***Y538***	***1307***
CON EDISION - TM2828	255-261 NO. 6TH ST.	E 1/8 - 1/4 (0.191 mi.)	AE545	1319
CON EDISON - VAULT 8	***39 W3 ST***	***WNW 1/8 - 1/4 (0.192 mi.)***	***AK547***	***1321***
V3554	***75-20 ASTORIA BOULEV***	***NNE 1/8 - 1/4 (0.193 mi.)***	***AH548***	***1324***
CON EDISON SERVICE B	***38 2ND AVE***	***SE 1/8 - 1/4 (0.193 mi.)***	***Z549***	***1326***
CON EDISON	***44 E 3RD ST***	***SE 1/8 - 1/4 (0.197 mi.)***	***AJ569***	***1370***
CON EDISON SERVICE B	***COOPER SQ & ASTOR PL***	***NE 1/8 - 1/4 (0.199 mi.)***	***AP574***	***1378***
CON EDISON GAS DRIP:	***COOPER SQ & W 4TH ST***	***NE 1/8 - 1/4 (0.199 mi.)***	***AP575***	***1379***
CON EDISON SERVICE B	***754 E BROADWAY***	***N 1/8 - 1/4 (0.199 mi.)***	***AH576***	***1382***
CON EDISON SERVICE B	***2-4 ST MARKS***	***NE 1/8 - 1/4 (0.201 mi.)***	***AG581***	***1392***
CON EDISON	***97 E 4TH ST***	***ESE 1/8 - 1/4 (0.204 mi.)***	***AC593***	***1424***
CON EDISON SERVICE B	***6-8 ST MARKS***	***ENE 1/8 - 1/4 (0.206 mi.)***	***AG600***	***1435***
CON EDISON VAULT: 13	***136 E 8TH ST FRONT O***	***NNE 1/8 - 1/4 (0.207 mi.)***	***AH608***	***1452***
CON EDISON VAULT: 33	***136 E 8TH ST FRONT O***	***NNE 1/8 - 1/4 (0.207 mi.)***	***AH609***	***1454***
CON EDISON - MH 2434	***2-4 ALBANY STREET***	***NE 1/8 - 1/4 (0.207 mi.)***	***AP610***	***1457***
CON EDISON	***4TH AVE & COOPER SQ***	***NE 1/8 - 1/4 (0.208 mi.)***	***AP615***	***1469***
MTA NYCT ASTOR PLACE	ASTOR PL & 4TH AVE	NE 1/8 - 1/4 (0.208 mi.)	AP616	1470
CON EDISON MANHOLE:	E COOPER SQ & 4TH AV	NE 1/8 - 1/4 (0.208 mi.)	AP617	1472
CON EDISON SERVICE B	***9 2ND AVE FRONT OF***	***SSE 1/8 - 1/4 (0.210 mi.)***	***AL626***	***1487***
CON EDISON	***208 E 6TH ST & 2ND A***	***E 1/8 - 1/4 (0.210 mi.)***	***AE627***	***1490***
CON EDISON MANHOLE	***E 6 ST & 2ND AVE***	***E 1/8 - 1/4 (0.211 mi.)***	***AE629***	***1492***
CON EDISON SERVICE B	***E 6TH ST & 2ND AVE***	***E 1/8 - 1/4 (0.211 mi.)***	***AE630***	***1494***
CON EDISON SERVICE B	***COOPER SQ & ST MARK***	***NE 1/8 - 1/4 (0.213 mi.)***	***AP640***	***1510***
CON EDISON TRENCH: O	***3RD AVE & ASTOR PL***	***NE 1/8 - 1/4 (0.213 mi.)***	***AP642***	***1514***
CON EDISON	3RD AVE & SAINT MARK	NE 1/8 - 1/4 (0.213 mi.)	AP646	1520
CON EDISON SERVICE B	***ST MARKS PL & COOPER***	***NE 1/8 - 1/4 (0.213 mi.)***	***AP647***	***1520***
CON EDISON	ASTOR PL & 3RD AVE	NE 1/8 - 1/4 (0.213 mi.)	AP649	1525
CON EDISION - V9216	***ST.MARKS PL. AND 3RD***	***NE 1/8 - 1/4 (0.214 mi.)***	***AP652***	***1537***
CON EDISON SERVICE B	***18 WAVERLY PL & GREE***	***NNW 1/8 - 1/4 (0.214 mi.)***	***AR653***	***1540***
CON EDISON SERVICE B	***261-63 GREENE ST & W***	***NNW 1/8 - 1/4 (0.214 mi.)***	***AR654***	***1541***
24 SECOND AVENUE OWN	***24 2ND AVE***	***SE 1/8 - 1/4 (0.214 mi.)***	***AL655***	***1542***
CON EDISON	19 E HOUSTON ST	SW 1/8 - 1/4 (0.215 mi.)	AI659	1554
MC 19 EAST HOUSTON L	19 E HOUSTON ST	SW 1/8 - 1/4 (0.215 mi.)	AI660	1554
CON EDISON SERVICE B	***94 E 4TH ST***	***ESE 1/8 - 1/4 (0.216 mi.)***	***AT668***	***1568***
CON EDISON	***HOUSTON ST & BROADWA***	***SW 1/8 - 1/4 (0.217 mi.)***	***AU672***	***1577***
CON EDISON	***BROADWAY & E 8TH ST***	***N 1/8 - 1/4 (0.220 mi.)***	***AV679***	***1590***
NYCT - 8TH ST STA N&	***E 8TH ST & BROADWAY***	***N 1/8 - 1/4 (0.220 mi.)***	***AV680***	***1592***
CON EDISON	***85 WASHINGTON SQ W***	***NW 1/8 - 1/4 (0.221 mi.)***	***AW690***	***1609***
CON EDISON	115 2ND AVE	E 1/8 - 1/4 (0.221 mi.)	AN694	1614
CON EDISON SERVICE B	***69 E 8 ST***	***NNE 1/8 - 1/4 (0.222 mi.)***	***AH696***	***1616***
CON EDISON SERVICE B	276 MULBERRY ST	SSW 1/8 - 1/4 (0.223 mi.)	AM698	1619
CON EDISON SERVICE B	276 MULBERRY ST	SSW 1/8 - 1/4 (0.223 mi.)	AM699	1620
CON EDISON	***W 4TH ST & WASHINGTO***	***NW 1/8 - 1/4 (0.225 mi.)***	***AW706***	***1635***
CON EDISON SERVICE B	***759 W BROADWAY***	***N 1/8 - 1/4 (0.229 mi.)***	***AV720***	***1659***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE 5	***759 BROADWAY***	***N 1/8 - 1/4 (0.229 mi.)***	***AV721***	***1661***
CON EDISON MANHOLE 5	***759 BROADWAY & 8TH S***	***N 1/8 - 1/4 (0.229 mi.)***	***AV722***	***1665***
CON EDISON	***27 3RD AVE***	***NE 1/8 - 1/4 (0.229 mi.)***	***AZ724***	***1668***
CON EDISON SERVICE B	***100 E 4TH ST***	***ESE 1/8 - 1/4 (0.230 mi.)***	***BA731***	***1679***
NYCT - 2ND AVE STATI	***2ND AVE & HOUSTON ST***	***SSE 1/8 - 1/4 (0.231 mi.)***	***BB737***	***1724***
CON EDISON SERVICE B	***61 E 8TH ST***	***N 1/8 - 1/4 (0.232 mi.)***	***AV738***	***1726***
CON EDISON	***34 E 1ST ST***	***SE 1/8 - 1/4 (0.232 mi.)***	***AL739***	***1729***
CON EDISON SERVICE B	***29 E 1ST ST***	***SSE 1/8 - 1/4 (0.233 mi.)***	***AL743***	***1735***
CON EDISON SERVICE B	***102 E 4TH ST***	***ESE 1/8 - 1/4 (0.234 mi.)***	***BA744***	***1737***
770 BROADWAY COMPANY	***770 BROADWAY***	***NNE 1/8 - 1/4 (0.234 mi.)***	***BC748***	***1750***
CON EDISON MANHOLE 3	JERSEY ST & CROSBY S	SW 1/8 - 1/4 (0.237 mi.)	BD757	1766
CON EDISON	EAST 7TH ST & 2ND AV	E 1/8 - 1/4 (0.239 mi.)	AS769	1782
CON EDISON SERVICE B	***E 7TH ST & 2ND AVE N***	***E 1/8 - 1/4 (0.239 mi.)***	***AS771***	***1784***
CON EDISON	***104 E 4TH ST***	***ESE 1/8 - 1/4 (0.239 mi.)***	***BA773***	***1790***
CON EDISON SERVICE B	***104 E 4TH ST***	***ESE 1/8 - 1/4 (0.239 mi.)***	***BA774***	***1792***
CON EDISON SERVICE B	***599-601 BROADWAY & P***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AU781***	***1808***
C F A CORP OF ILLINO	***599 BROADWAY***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AU782***	***1811***
CON EDISON SERVICE B	***34 ST MARKS PL***	***ENE 1/8 - 1/4 (0.242 mi.)***	***AY787***	***1822***
CON EDISON MANHOLE 3	***W HOUSTON ST & MERCE***	***WSW 1/8 - 1/4 (0.242 mi.)***	***BF789***	***1824***
CON EDISON SERVICE B	***59 E 8 ST FRONT OF***	***N 1/8 - 1/4 (0.243 mi.)***	***AV791***	***1829***
PORTOFOTO INC	***596 BROADWAY 1ST FLO***	***SW 1/8 - 1/4 (0.244 mi.)***	***AU793***	***1833***
CON EDISON	***61 2ND AVE & E 3RD S***	***SE 1/8 - 1/4 (0.245 mi.)***	***AX796***	***1840***
CON EDISON SERVICE B	***29 3RD AVE FRONT OF***	***NE 1/8 - 1/4 (0.245 mi.)***	***AZ797***	***1844***
CON EDISON SERVICE B	***29 3RD AVE***	***NE 1/8 - 1/4 (0.245 mi.)***	***AZ799***	***1847***
FAUST BROS INC	***48 E 8TH ST***	***N 1/8 - 1/4 (0.246 mi.)***	***AR801***	***1851***
CON EDISON	***21 SAINT MARKS PL***	***ENE 1/8 - 1/4 (0.247 mi.)***	***AY803***	***1857***
CON EDISON SERVICE B	***765 W BROADWAY***	***NNE 1/8 - 1/4 (0.247 mi.)***	***AV806***	***1860***
CON EDISON SERVICE B	***55 E 8TH ST***	***N 1/8 - 1/4 (0.248 mi.)***	***AV809***	***1866***
NEW AMSTERDAM THEATE	***40 1ST ST***	***SE 1/8 - 1/4 (0.248 mi.)***	***AX810***	***1868***
CON EDISON	***23 SAINT MARKS PL***	***ENE 1/8 - 1/4 (0.248 mi.)***	***AY813***	***1874***
CON EDISON SERVICE B	***59 E 2ND ST***	***SE 1/8 - 1/4 (0.248 mi.)***	***AX818***	***1881***
CON EDISON SERVICE B	***113 E 4TH ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***BA823***	***1890***

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 01/09/2018 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS	***NO STREET APPLICABLE***	***W 1/2 - 1 (0.982 mi.)***	***0***	***8***

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 11/18/2016 has revealed that there is 1 ICIS site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONCORD ELECTRONICS	***30 GREAT JONES STREE***	***0 - 1/8 (0.000 mi.)***	***A2***	***26***

EXECUTIVE SUMMARY

CONSENT: Major Legal settlements that establish responsibility and standards for cleanup at NPL (superfund) sites. Released periodically by U.S. District Courts after settlement by parties to litigation matters.

A review of the CONSENT list, as provided by EDR, and dated 12/31/2017 has revealed that there is 1 CONSENT site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUDSON RIVER PCBS	***NO STREET APPLICABLE***	***W 1/2 - 1 (0.982 mi.)***	***0***	***8***

FUSRAP: DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

A review of the FUSRAP list, as provided by EDR, and dated 12/23/2016 has revealed that there are 2 FUSRAP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARKITE CO.	155 WAVERLY PLACE	NW 1/2 - 1 (0.577 mi.)	926	2097
LEDOUX AND CO.	155 AVENUE OF THE AM	WSW 1/2 - 1 (0.608 mi.)	927	2097

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 02/21/2018 has revealed that there are 2 FINDS sites within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONCORD ELECTRONICS	***30 GREAT JONES STREE***	***0 - 1/8 (0.000 mi.)***	***A2***	***26***
CON EDISON MANHOLE 5	***379 LAFAYETTE ST***	***0 - 1/8 (0.000 mi.)***	***A8***	***38***

ECHO: ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

A review of the ECHO list, as provided by EDR, and dated 01/13/2018 has revealed that there are 2 ECHO sites within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONCORD ELECTRONICS	***30 GREAT JONES STREE***	***0 - 1/8 (0.000 mi.)***	***A2***	***26***
CON EDISON MANHOLE 5	***379 LAFAYETTE ST***	***0 - 1/8 (0.000 mi.)***	***A8***	***38***

EXECUTIVE SUMMARY

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 11/22/2017 has revealed that there are 3 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAHMAN CLEANERS Facility Id: 2-6205-00920	210 MERCER STREET	W 1/8 - 1/4 (0.158 mi.)	U410	1047
ALICE/HANNA/74 DRY C Facility Id: 2-6206-00504	74 SECOND AVE	ESE 1/8 - 1/4 (0.191 mi.)	AC542	1316
APHRODITE FRENCH CLE Facility Id: ---	300 MERCER ST #1	N 1/8 - 1/4 (0.195 mi.)	X556	1340

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 02/14/2018 has revealed that there are 4 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 4,TAXBLOCK 531	688 BROADWAY	NW 0 - 1/8 (0.057 mi.)	E83	197
LOT 18,TAXBLOCK 459	64 EAST 4 STREET	ESE 0 - 1/8 (0.112 mi.)	J238	538
LOT 51,TAXBLOCK 460	71 EAST 4 STREET	ESE 0 - 1/8 (0.116 mi.)	J245	563
LOT 23,TAXBLOCK 460	224 EAST 5 STREET	E 0 - 1/8 (0.124 mi.)	J270	604

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 331 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE 5 EPA ID: NYP004236016	***379 LAFAYETTE ST***	***0 - 1/8 (0.000 mi.)***	***A9***	***39***
CON EDISON MANHOLE 3 EPA ID: NYP004236024	***LAFAYETTE ST & GREAT***	***W 0 - 1/8 (0.010 mi.)***	***A12***	***47***
PETERSBURG PRESS INC EPA ID: NYR000027342	***380 LAFAYETTE ST***	***NNW 0 - 1/8 (0.011 mi.)***	***A14***	***53***
CON EDISON EPA ID: NYP004741401	34 4TH ST	E 0 - 1/8 (0.011 mi.)	A15	56
CON EDISON EPA ID: NYP004848372	30-32 E 4TH ST & BOW	E 0 - 1/8 (0.012 mi.)	A19	62
CON EDISON EPA ID: NYP004677084	22 E 4 ST	NE 0 - 1/8 (0.013 mi.)	A20	63
CON EDISON EPA ID: NYP004677092	22 E 4 ST	NE 0 - 1/8 (0.013 mi.)	A21	65
NYU EPA ID: NYR000209866	***383 LAFAYETTE ST***	***NNE 0 - 1/8 (0.013 mi.)***	***A22***	***66***
CONCORD ELECTRONICS	***GREAT JONES STREET***	***SSE 0 - 1/8 (0.016 mi.)***	***A28***	***78***

EPA ID: NYD003925070				
CON EDISON SERVICE B EPA ID: NYP004274429	***378 LAFAYETTE ST FRO***	***WNW 0 - 1/8 (0.016 mi.)***	***A30***	***96***
CON EDISON MANHOLE 5 EPA ID: NYP004236057	***372 LAFAYETTE ST***	***WNW 0 - 1/8 (0.016 mi.)***	***A31***	***99***
CON EDISON SERVICE B EPA ID: NYP004265450	***372 LAFAYETTE ST FRO***	***WNW 0 - 1/8 (0.016 mi.)***	***A36***	***115***
CON EDISON EPA ID: NYP004206274	***38 E 4TH ST***	***E 0 - 1/8 (0.018 mi.)***	***B37***	***117***
CON EDISON SERVICE B EPA ID: NYP004249254	***33 GREAT JONES ST***	***S 0 - 1/8 (0.019 mi.)***	***A38***	***119***
CON EDISON - GAS MAI EPA ID: NYP004223681 EPA ID: NYP004194312	***E 4TH ST AND LAFAYET***	***N 0 - 1/8 (0.027 mi.)***	***A53***	***140***
CON EDISION - MH3792 EPA ID: NYP004093316	***EAST 4TH STREET AND***	***N 0 - 1/8 (0.028 mi.)***	***A54***	***145***
CON EDISON SERVICE B EPA ID: NYP004446639	***47 GREAT JONES ST***	***SSE 0 - 1/8 (0.029 mi.)***	***B55***	***146***
MERCHANTS HOUSE EPA ID: NYR000143768	***29 E 4TH ST***	***ENE 0 - 1/8 (0.034 mi.)***	***B57***	***149***
CON EDISON EPA ID: NYP004754321	342 BOWERY	SE 0 - 1/8 (0.057 mi.)	F90	206
CON EDISON EPA ID: NYP004754339	340 BOWERY	SE 0 - 1/8 (0.061 mi.)	F101	229
CON EDISON EPA ID: NYP004596144	402 LAFAYETTE ST	NNE 0 - 1/8 (0.065 mi.)	D105	234
CON EDISON SERVICE B EPA ID: NYP004274940	***23 BOND ST FRONT OF***	***SSW 0 - 1/8 (0.068 mi.)***	***C111***	***251***
PENSKE TRUCK LEASING EPA ID: NYD981563455	***23 BOND ST***	***SSW 0 - 1/8 (0.068 mi.)***	***C113***	***255***
CON EDISON SERVICE B EPA ID: NYP004410379	***39 BOND ST***	***S 0 - 1/8 (0.069 mi.)***	***F119***	***273***
CON EDISON SERVICE B EPA ID: NYP004274924	***19 BOND ST FRONT OF***	***SW 0 - 1/8 (0.071 mi.)***	***C123***	***280***
CON EDISON SERVICE B EPA ID: NYP004274395	***334 BOWERY FRONT OF***	***SSE 0 - 1/8 (0.080 mi.)***	***F145***	***329***
CON EDISON SERVICE B EPA ID: NYP004274403	***334 BOWERY FRONT OF***	***SSE 0 - 1/8 (0.080 mi.)***	***F146***	***331***
CON EDISON SERVICE B EPA ID: NYP004275384	***59 BOND ST FRONT OF***	***SSE 0 - 1/8 (0.090 mi.)***	***F171***	***383***
CON EDISON SERVICE B EPA ID: NYP004280129	***23 BLEECKER ST***	***S 0 - 1/8 (0.094 mi.)***	***F187***	***420***
CON EDISON EPA ID: NYP004481255	33 BLEECKER ST FRONT	SSW 0 - 1/8 (0.095 mi.)	K189	422
CON EDISON GAS DRIP: EPA ID: NYP004267464	***BLECKER ST & ELIZABE***	***S 0 - 1/8 (0.105 mi.)***	***K220***	***495***
CON EDISON SERVICE B	***BLEECKER ST & ELIZAB***	***S 0 - 1/8 (0.105 mi.)***	***K222***	***498***

EPA ID: NYP004478913				
CON EDISON MANHOLE: EPA ID: NYP004431268	***341 LAFAYETTE ST FRO***	***SW 0 - 1/8 (0.112 mi.)***	***K237***	***536***
CON EDISON SERVICE B EPA ID: NYP004478921	***BLEECKER ST & LAFAYE***	***SW 0 - 1/8 (0.113 mi.)***	***K239***	***539***
MTA NYCT BLEECKER ST EPA ID: NYR000037051	***BLEECKER & LAFAYETTE***	***SW 0 - 1/8 (0.113 mi.)***	***K240***	***541***
CONSOLIDATED EDISON EPA ID: NYP004253449	333 LAFAYETTE ST	SW 0 - 1/8 (0.114 mi.)	K241	555
CON EDISON - MANHOLE EPA ID: NYP005008129	40 BLEECKER ST	SSW 0 - 1/8 (0.119 mi.)	K252	579
CON EDISON EPA ID: NYP004704680	42 BLEECKER ST	SSW 0 - 1/8 (0.119 mi.)	K256	584
CON EDISON EPA ID: NYP004205498	***48 BLEEKER ST***	***SSW 0 - 1/8 (0.120 mi.)***	***K260***	***589***
CON EDISON EPA ID: NYP004734976	316 MOTT ST & HOUSTO	S 1/8 - 1/4 (0.129 mi.)	K295	647
CON EDISON SERVICE B EPA ID: NYP004274858	***307 BOWERY FRONT OF***	***SSE 1/8 - 1/4 (0.138 mi.)***	***N324***	***875***
CON EDISON EPA ID: NYP004735361	315 MOTT ST	SSW 1/8 - 1/4 (0.139 mi.)	K331	887
CON EDISON EPA ID: NYP004735379	306 MOTT ST	SSW 1/8 - 1/4 (0.146 mi.)	P357	943
CON EDISON EPA ID: NYP004208233	***324 LAFAYETTE ST***	***SW 1/8 - 1/4 (0.148 mi.)***	***S370***	***963***
CON EDISON SERVICE B EPA ID: NYP004474078	***308 BOWERY & HOUSTON***	***SSE 1/8 - 1/4 (0.150 mi.)***	***P376***	***975***
CONSOLIDATED EDISON- EPA ID: NYP004254975	323 LAFAYETTE	SW 1/8 - 1/4 (0.150 mi.)	S379	980
CON EDISON EPA ID: NYP004591319	3 E 1ST ST	SSE 1/8 - 1/4 (0.152 mi.)	P382	986
CON EDISON SERVICE B EPA ID: NYP004265179	***302 BOWERY FRONT OF***	***S 1/8 - 1/4 (0.154 mi.)***	***P387***	***994***
LAFAYETTE AUTO REPAI EPA ID: NYD982790214	***321 LAFAYETTE ST***	***SW 1/8 - 1/4 (0.154 mi.)***	***S388***	***997***
CON EDISON SERVICE B EPA ID: NYP004294799	***302 MOTT ST***	***SSW 1/8 - 1/4 (0.155 mi.)***	***AB391***	***1005***
CON EDISON EPA ID: NYP004739264	298 MULBERRY ST	SSW 1/8 - 1/4 (0.157 mi.)	AB399	1021
CVS PHARMACY #10407 EPA ID: NYR000211128	***298 MULBERRY ST***	***SSW 1/8 - 1/4 (0.157 mi.)***	***AB400***	***1022***
CON EDISON EPA ID: NYP004736435	305 MULBERRY ST	SW 1/8 - 1/4 (0.157 mi.)	S405	1038
CONED EPA ID: NYP004174702	MOTT ST & HOUSTON ST	SSW 1/8 - 1/4 (0.180 mi.)	AB490	1185
NYCTA - BROADWAY & L	***E HOUSTON & CROSBY S***	***SW 1/8 - 1/4 (0.180 mi.)***	***AI491***	***1187***

EPA ID: NYR000015172				
CONSOLIDATED EDISON EPA ID: NYP004150702	LAFAYETTE ST & HOUST	SW 1/8 - 1/4 (0.188 mi.)	AI529	1290
CON EDISON SERVICE B EPA ID: NYP004246726	***41 E HOUSTON ST***	***SSW 1/8 - 1/4 (0.195 mi.)***	***AM559***	***1343***
B P PRODUCTS NORTH A EPA Id: NYR000126698	***21 E HOUSTON ST***	***SW 1/8 - 1/4 (0.195 mi.)***	***AI562***	***1352***
CON EDISON - SERVICE EPA Id: NYP004174777	***BOWERY AND E HOUSTON***	***S 1/8 - 1/4 (0.196 mi.)***	***AO566***	***1363***
CONSOLIDATED EDISON EPA ID: NYP004133948	HOUSTON ST & BOWERY	S 1/8 - 1/4 (0.198 mi.)	AO572	1375
CONSOLIDATED EDISON EPA ID: NYP004134110	BOWERY ST & E HOUSTO	S 1/8 - 1/4 (0.198 mi.)	AO573	1377
GIGANTE VAZ & PARTNE EPA ID: NYD001360494	***295 LAFAYETTE ST - 7***	***SW 1/8 - 1/4 (0.204 mi.)***	***AI586***	***1403***
PRATT INSTITUTE - PU EPA Id: NYR000100867 Manifest Document Number: 000066632UIS	***295 LAFAYETTE ST 2ND***	***SW 1/8 - 1/4 (0.204 mi.)***	***AI587***	***1406***
GOTTLIEB W REAL ESTA EPA ID: NYR000002188	***284 MULBERRY ST***	***SSW 1/8 - 1/4 (0.208 mi.)***	***AM619***	***1475***
CON EDISON EPA ID: NYP004721700	279 MOTT ST	SSW 1/8 - 1/4 (0.225 mi.)	AM708	1636
CON ED EPA ID: NYP004803540	279 BOWERY	S 1/8 - 1/4 (0.230 mi.)	AO730	1677
CON EDISON EPA ID: NYP004725180	269 BOWERY	S 1/8 - 1/4 (0.235 mi.)	AO753	1758
CON ED EPA ID: NYP004833501	268 BOWERY	S 1/8 - 1/4 (0.238 mi.)	BE763	1775
CON EDISON EPA ID: NYP004766481	268 BOWERY	S 1/8 - 1/4 (0.238 mi.)	BE764	1776
CON EDISON SERVICE B EPA ID: NYP004201273	***265 BOWERY STANTON S***	***S 1/8 - 1/4 (0.244 mi.)***	***AO794***	***1835***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004543518	***10 BOND ST***	***WSW 0 - 1/8 (0.048 mi.)***	***C70***	***167***
NEW YORK CITY OF HUM EPA ID: NYD986984805	***350 LAFAYETTE ST***	***WSW 0 - 1/8 (0.052 mi.)***	***C75***	***178***
CON EDISON SERVICE B EPA ID: NYP004290441	***6 BOND ST***	***WSW 0 - 1/8 (0.055 mi.)***	***C79***	***186***
DOWNTOWN RE HOLDINGS EPA ID: NYR000217752	688 BROADWAY	NW 0 - 1/8 (0.057 mi.)	E85	198
BOWERY AND 4TH STREE EPA ID: NYP004031068	***BOWERY AND 4TH STREE***	***E 0 - 1/8 (0.057 mi.)***	***B86***	***200***
CON EDISON MANHOLE: EPA ID: NYP004360459	***GREAT JONES ST & BOW***	***SE 0 - 1/8 (0.058 mi.)***	***G91***	***208***
CON EDISON SERVICE B	***11 E 4TH ST***	***NNW 0 - 1/8 (0.059 mi.)***	***E93***	***212***

EPA ID: NYP004433637				
CON EDISON EPA ID: NYP004484739	11 COOPER SQ FRONT O	E 0 - 1/8 (0.071 mi.)	H126	285
CON EDISON SERVICE B EPA ID: NYP004479952	***686-88 BROADWAY & GT***	***WNW 0 - 1/8 (0.076 mi.)***	***E133***	***299***
CONSOLIDATED EDISON EPA ID: NYP000237164	F/O 680 BROADWAY	WNW 0 - 1/8 (0.077 mi.)	I138	311
CONSOLIDATED EDISON EPA ID: NYP004237164	F/O 680 BROADWAY	WNW 0 - 1/8 (0.077 mi.)	I139	312
CONSOLIDATED EDISON EPA ID: NYP004175022	346 LAFFAYETTE ST	SW 0 - 1/8 (0.078 mi.)	C140	313
CON EDISON GAS MAIN EPA ID: NYP004237834	***COOPER SQ & E 5TH ST***	***ENE 0 - 1/8 (0.079 mi.)***	***H141***	***315***
CON EDISON EXCAVATIO EPA ID: NYP004235941	***COOPER SQUARE AND EA***	***ENE 0 - 1/8 (0.079 mi.)***	***H143***	***325***
CON EDISON - SERVICE EPA Id: NYP004188025	***GREAT JONES ST AND B***	***WNW 0 - 1/8 (0.080 mi.)***	***I148***	***335***
VERIZON LOG 32884 EPA ID: NYP000963322	***BROADWAY & GREAT JON***	***WNW 0 - 1/8 (0.080 mi.)***	***I150***	***340***
CON EDISON EPA ID: NYP004484747	15 COOPER SQ FRONT O	ENE 0 - 1/8 (0.081 mi.)	H156	358
CON EDISON - SERVICE EPA ID: NYP004900153	691 BROADWAY	NW 0 - 1/8 (0.083 mi.)	E158	360
CON EDISON GAS DRIP EPA ID: NYP004249221	***E 4TH ST & BROADWAY***	***NW 0 - 1/8 (0.084 mi.)***	***E159***	***361***
CON EDISON GAS MAIN EPA ID: NYP004235586	***WEST 4TH STREET AND***	***NW 0 - 1/8 (0.084 mi.)***	***E160***	***363***
CON EDISON - TRANSFO EPA ID: NYP004922876	E 4TH ST & BROADWAY	NW 0 - 1/8 (0.084 mi.)	E162	369
CON EDISON GAS MAIN EPA ID: NYP004223251	***W 4TH ST & BROADWAY***	***NW 0 - 1/8 (0.084 mi.)***	***E163***	***369***
CON EDISON EPA ID: NYP004208084	***BROADWAY & E 4TH ST***	***NW 0 - 1/8 (0.084 mi.)***	***E165***	***374***
CON EDISION EPA ID: NYP004591533	27 COOPER SQ	ENE 0 - 1/8 (0.092 mi.)	H175	397
V6421 EPA ID: NYP004033858	***3 W. 3RD STREET***	***WNW 0 - 1/8 (0.093 mi.)***	***I178***	***403***
CON EDISON EPA ID: NYP004489316	34 COOPER SQ FRONT O	NE 0 - 1/8 (0.093 mi.)	H181	408
CON EDISON SERVICE B EPA ID: NYP004274916	***331 BOWERY FRONT OF***	***SE 0 - 1/8 (0.095 mi.)***	***G192***	***427***
CON EDISON EPA ID: NYP004586996	335 BOWERY	SE 0 - 1/8 (0.098 mi.)	G200	458
CON EDISON SERVICE B EPA ID: NYP004276044	***36 COOPER SQ FRONT O***	***ENE 0 - 1/8 (0.098 mi.)***	***H201***	***459***
ALCON ENGRAVERS INC	***656 BROADWAY***	***WSW 0 - 1/8 (0.099 mi.)***	***I205***	***466***

EPA ID: NYD001507250				
CON EDISON EPA ID: NYP004803516	699 BROADWAY	NNW 0 - 1/8 (0.100 mi.)	L207	471
CON EDISON EPA ID: NYP004489498	40 COOPER SQ FRONT O	NE 0 - 1/8 (0.102 mi.)	H210	475
CON EDISON SERVICE B EPA ID: NYP004274882	***327 BOWERY FRONT OF***	***SE 0 - 1/8 (0.102 mi.)***	***N213***	***481***
CON EDISON EPA ID: NYP004148326	***65 BLEEKER STREET***	***SW 0 - 1/8 (0.105 mi.)***	***M219***	***493***
WHALEDENT INTL EPA ID: NYD000708289	***236 5TH AVE***	***E 0 - 1/8 (0.111 mi.)***	***J234***	***527***
CON EDISON SERVICE B EPA ID: NYP004215513	***8 E 2ND ST & BOWERY***	***SSE 0 - 1/8 (0.112 mi.)***	***N235***	***531***
CONSOLIDATED EDISON EPA ID: NYP004052742	V44150-66 E 4TH ST	ESE 0 - 1/8 (0.117 mi.)	J249	569
NEW YORK UNIVERSITY EPA ID: NYD986963205	***2-4 WASHINGTON PL***	***NNW 0 - 1/8 (0.118 mi.)***	***L251***	***573***
CON EDISON SERVICE B EPA ID: NYP004416020	***657 BROADWAY***	***W 0 - 1/8 (0.121 mi.)***	***M262***	***592***
CON EDISON SERVICE B EPA ID: NYP004462529	***657 BROADWAY***	***W 0 - 1/8 (0.121 mi.)***	***M263***	***594***
CON EDISON SERVICE B EPA ID: NYP004250148	***428 LAFAYETTE ST***	***NNE 0 - 1/8 (0.123 mi.)***	***O266***	***598***
CON EDISON SERVICE B EPA ID: NYP004416004	***653 BROADWAY***	***W 0 - 1/8 (0.125 mi.)***	***M272***	***607***
CON EDISON EPA ID: NYP004534418	41 COOPER SQ VAULT 9	ENE 0 - 1/8 (0.125 mi.)	Q274	610
CON EDISON EPA ID: NYP004854358 EPA ID: NYP004854366 EPA ID: NYP004854382 EPA ID: NYP004854390 EPA ID: NYP004528667 **Additional key fields are available in the Map Findings section*	41 COOPER SQ	ENE 0 - 1/8 (0.125 mi.)	Q277	614
CON EDISION EPA ID: NYP004591558 EPA ID: NYR000144261	41 COOPER SQ	ENE 0 - 1/8 (0.125 mi.)	Q278	617
CON EDISON SERVICE B EPA ID: NYP004276036	***41-55 COOPER SQ FRON***	***ENE 0 - 1/8 (0.125 mi.)***	***Q280***	***621***
CON EDISON EPA ID: NYP004586988	250 MERCER ST	WNW 1/8 - 1/4 (0.125 mi.)	R283	625
V3178 EPA ID: NYP004047338	***423 LAFAYETTE STREET***	***NNE 1/8 - 1/4 (0.127 mi.)***	***O286***	***631***
CON EDISON EPA ID: NYP004758447	430 LAFAYETTE ST	NNE 1/8 - 1/4 (0.128 mi.)	O288	634
NEW YORK UNIVERSITY EPA ID: NYR000230839	726 BROADWAY	N 1/8 - 1/4 (0.128 mi.)	L291	639
CON EDISON	208 E 6TH ST & 2ND A	ENE 1/8 - 1/4 (0.128 mi.)	Q294	646

EPA ID: NYP004778890				
CONSOLIDATED EDISON EPA ID: NYP004250262	425 LAFAYETTE ST	NNE 1/8 - 1/4 (0.129 mi.)	O298	655
CON EDISON MANHOLE 3 EPA ID: NYP004246361	***425 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.129 mi.)***	***O300***	***658***
CON EDISON SERVICE B EPA ID: NYP004275624	***228 E 5TH ST FRONT O***	***E 1/8 - 1/4 (0.129 mi.)***	***J301***	***660***
CON EDISON SERVICE B EPA ID: NYP004472445 EPA ID: NYP004854630	***166-168 CROSBY ST &***	***SW 1/8 - 1/4 (0.132 mi.)***	***M308***	***675***
CON ED EPA ID: NYP004854515	164 CROSBY ST	SW 1/8 - 1/4 (0.132 mi.)	M309	678
CON EDISON SERVICE B EPA ID: NYP004416038	***647 BROADWAY***	***WSW 1/8 - 1/4 (0.132 mi.)***	***M310***	***680***
NEW YORK UNIVERSITY EPA ID: NYR000075762	***251 MERCER ST***	***WNW 1/8 - 1/4 (0.133 mi.)***	***R311***	***682***
CON EDISON SERVICE B EPA ID: NYP004426011	***429 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.133 mi.)***	***O315***	***848***
CON EDISON EPA ID: NYP004857199	717 BROADWAY	N 1/8 - 1/4 (0.134 mi.)	L316	850
NYU TISCH SCHOOL OF EPA ID: NYR000021386	***721-725 BROADWAY***	***N 1/8 - 1/4 (0.136 mi.)***	***L318***	***861***
CON EDISON EPA ID: NYP004406484	F/O 377 BLEEKER ST	W 1/8 - 1/4 (0.136 mi.)	U320	866
CON EDISON SERVICE B EPA ID: NYP004243499	***640 BROADWAY FRONT O***	***WSW 1/8 - 1/4 (0.137 mi.)***	***M323***	***872***
CON EDISON EPA ID: NYP004604450	BLEEKER ST & BROADWA	WSW 1/8 - 1/4 (0.138 mi.)	M326	879
CON EDISON EPA ID: NYP004664751	BROADWAY & BLEEKER S	WSW 1/8 - 1/4 (0.138 mi.)	M327	880
CON ED - V 2708 EPA ID: NYP004005997 EPA ID: NYP004397378	***71 BLEEKER ST***	***WSW 1/8 - 1/4 (0.141 mi.)***	***U333***	***890***
CON EDISON SERVICE B EPA ID: NYP004275640	***216 E 6 ST FRONT OF***	***ENE 1/8 - 1/4 (0.141 mi.)***	***V335***	***894***
CON EDISON EPA ID: NYP004698262	F/O 436 LAFAYETTE ST	NNE 1/8 - 1/4 (0.144 mi.)	O341	908
CON EDISON MANHOLE: EPA ID: NYP004256947	***436 LAFFAYETTE AVE S***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O342***	***909***
CON EDISON MANHOLE 3 EPA ID: NYP004250254 EPA ID: NYP004802914	***436 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O343***	***912***
CON EDISON - MANHOLE EPA Id: NYP004175162	***436 LAFAYETTE ST AND***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O345***	***917***
CON EDISON EPA ID: NYP004588554	***636 BROADWAY***	***WSW 1/8 - 1/4 (0.145 mi.)***	***M351***	***933***
CON EDISON	14 TARAS SCHEVCHENKO	ENE 1/8 - 1/4 (0.145 mi.)	Q353	937

EPA ID: NYP004711099				
CON EDISON EPA ID: NYP004711032	14 TARAS SCHEVCHENKO	ENE 1/8 - 1/4 (0.145 mi.)	Q354	939
CON EDISON EPA ID: NYP004711073	14 TARAS SCHEVCHENKO	ENE 1/8 - 1/4 (0.145 mi.)	Q355	940
CON EDISON EPA ID: NYP004711057	14 TARAS SCHEVCHENKO	ENE 1/8 - 1/4 (0.145 mi.)	Q356	942
CON EDISON EPA ID: NYP004591651	56 COOPER SQ	NE 1/8 - 1/4 (0.146 mi.)	W363	952
CON EDISON EPA ID: NYP004591640	56 COOPER SQ	NE 1/8 - 1/4 (0.146 mi.)	W364	954
CON EDISON EPA ID: NYP004832024	229 E 5TH ST	E 1/8 - 1/4 (0.148 mi.)	V369	962
CON EDISON SERVICE B EPA ID: NYP004430419	***736 BROADWAY***	***N 1/8 - 1/4 (0.148 mi.)***	***X371***	***966***
CON EDISON SERVICE B EPA ID: NYP004777074 EPA ID: NYP004480042	***85 E 4TH ST & COOPER***	***ESE 1/8 - 1/4 (0.148 mi.)***	***T373***	***969***
CON EDISON EPA ID: NYP004588299	30 E 3RD ST	SE 1/8 - 1/4 (0.150 mi.)	T377	977
CON EDISION - MH 272 EPA ID: NYP004071627	***634 BROADWAY 634 BRO***	***WSW 1/8 - 1/4 (0.152 mi.)***	***Y381***	***983***
CORINNE OFFSET INC EPA ID: NYR000055574	***737 BROADWAY***	***N 1/8 - 1/4 (0.152 mi.)***	***X383***	***987***
CON EDISON SERVICE B EPA ID: NYP004356457	***738 BROADWAY***	***N 1/8 - 1/4 (0.152 mi.)***	***X384***	***990***
CON EDISON SERVICE B EPA ID: NYP004426029	***439 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.155 mi.)***	***W392***	***1007***
CON EDISON SERVICE B EPA ID: NYP004275657	***222 E 6 ST FRONT OF***	***E 1/8 - 1/4 (0.155 mi.)***	***V393***	***1009***
CON EDISON SERVICE B EPA ID: NYP004250072	***6 E 1ST ST***	***SSE 1/8 - 1/4 (0.157 mi.)***	***AA403***	***1035***
BAHMAN CLEANERS EPA ID: NYD053264925	***210 MERCER ST***	***W 1/8 - 1/4 (0.158 mi.)***	***U409***	***1043***
CON EDISON EPA ID: NYP004723425	30 E 2ND ST	SE 1/8 - 1/4 (0.162 mi.)	Z419	1060
CON ED EPA ID: NYP004834012	***69 2ND AVE***	***ESE 1/8 - 1/4 (0.163 mi.)***	***AC425***	***1071***
CON EDISON EPA ID: NYP004563722	7 WASHINGTON TERR &	NNW 1/8 - 1/4 (0.163 mi.)	AD426	1073
CON EDISON EPA ID: NYP004588307	36 E 3RD ST	SE 1/8 - 1/4 (0.163 mi.)	T428	1077
CON EDISON EPA ID: NYP004656757	744 BROADWAY	N 1/8 - 1/4 (0.165 mi.)	X434	1088
CON EDISON EPA ID: NYP004504247	62 COOPER SQUARE	NE 1/8 - 1/4 (0.166 mi.)	W436	1091
CON EDISON	86 E 4 ST	ESE 1/8 - 1/4 (0.167 mi.)	T437	1092

EPA ID: NYP004591673				
CON EDISION - MH2722 EPA ID: NYP004072955	***626 BROADWAY AND E.H***	***WSW 1/8 - 1/4 (0.167 mi.)***	***Y438***	***1094***
CON EDISON MANHOLE 2 EPA ID: NYP004141164	***626 BROADWAY***	***WSW 1/8 - 1/4 (0.167 mi.)***	***Y439***	***1096***
CON EDISON EPA ID: NYP004863706 EPA ID: NYP004586806	45 2ND AVE	SE 1/8 - 1/4 (0.168 mi.)	T442	1102
CON ED EPA ID: NYP004821118	29 W 4TH ST	NW 1/8 - 1/4 (0.168 mi.)	AF444	1105
CON EDISON EPA ID: NYP004855470	96 BLEEKER ST	WSW 1/8 - 1/4 (0.169 mi.)	U446	1108
CON EDISON SERVICE B EPA ID: NYP004416319	***41 E 2ND AVE***	***SE 1/8 - 1/4 (0.170 mi.)***	***Z447***	***1109***
CON EDISON EPA ID: NYP004586798	41 2 AV	SE 1/8 - 1/4 (0.170 mi.)	Z448	1112
MOKLAM BUILDING EPA ID: NYR000213413	***622 BROADWAY***	***WSW 1/8 - 1/4 (0.173 mi.)***	***Y454***	***1122***
BEST BUY EPA ID: NYR000173773	***622 BROADWAY***	***WSW 1/8 - 1/4 (0.173 mi.)***	***Y455***	***1125***
CON EDISON EPA ID: NYP004492203	73-75 2ND AVE & 4TH	ESE 1/8 - 1/4 (0.173 mi.)	AC457	1130
CON EDISON SERVICE B EPA ID: NYP004395513	***749-51 W BROADWAY***	***N 1/8 - 1/4 (0.174 mi.)***	***X458***	***1131***
CON EDISON EPA ID: NYP004591301	9 E 1ST ST	SSE 1/8 - 1/4 (0.175 mi.)	AA460	1135
CON EDISON EPA ID: NYP004492195	69-71 2ND AVE & 4TH	ESE 1/8 - 1/4 (0.176 mi.)	AC464	1141
CON EDISON EPA ID: NYP004585980	EAST 4 ST & 2ND AV	ESE 1/8 - 1/4 (0.177 mi.)	AC467	1147
CON EDISON SERVICE B EPA ID: NYP004480034	***E 4TH ST & 2 ND AVE***	***ESE 1/8 - 1/4 (0.177 mi.)***	***AC468***	***1148***
CON EDISON MANHOLE 5 EPA ID: NYP004243226	***E 3RD ST & 2ND AVE S***	***SE 1/8 - 1/4 (0.177 mi.)***	***T473***	***1155***
JIM HENSON CO THE EPA ID: NYR000134601	***627 BROADWAY - 9TH F***	***WSW 1/8 - 1/4 (0.177 mi.)***	***Y475***	***1161***
CON EDISON EPA ID: NYP004487526	WEST 4TH AVE & GREEN	NW 1/8 - 1/4 (0.177 mi.)	AF476	1164
CON EDISON EPA ID: NYP004487534	WEST 4TH AVE & GREEN	NW 1/8 - 1/4 (0.177 mi.)	AF478	1167
CON EDISON EPA ID: NYP004487518	WEST 4TH AVE & GREEN	NW 1/8 - 1/4 (0.177 mi.)	AF480	1169
CON EDISON EPA ID: NYP004600508	E 3 ST & 2 AVE	SE 1/8 - 1/4 (0.178 mi.)	T482	1172
COOPER UNION ADVANCE EPA ID: NYR000066779	50 ASTOR PL	NNE 1/8 - 1/4 (0.178 mi.)	AH485	1176
CON EDISON	292 MERCER ST	N 1/8 - 1/4 (0.179 mi.)	X487	1180

EPA ID: NYP004613451				
NEW YORK UNIVERSITY	***12-16 WAVERLY PL***	***NNW 1/8 - 1/4 (0.181 mi.)***	***AD492***	***1190***
EPA ID: NYP004791612				
CONSOLIDATED EDISON	BROADWAY & ASTOR PLA	N 1/8 - 1/4 (0.181 mi.)	X493	1194
EPA ID: NYP004231072				
CON EDISON	95 2ND AVE	E 1/8 - 1/4 (0.182 mi.)	AE496	1199
EPA ID: NYP004589800				
CON EDISON	61 COOPER SQ	NE 1/8 - 1/4 (0.183 mi.)	AG497	1201
EPA ID: NYP004856447				
NEW YORK UNIVERSITY	12-16 WAVERLY PLACE	NNW 1/8 - 1/4 (0.183 mi.)	AD501	1207
EPA ID: NYR000160069				
CON EDISON VAULT: 96	***51 ASTOR PL***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH502***	***1208***
EPA ID: NYD980766604				
EPA ID: NYP000778514				
NYCDEP - HAZARDOUS M	***51 ASTOR PL RM 643***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH503***	***1217***
EPA ID: NYD986896686				
MINSKOFF EQUITY BLDG	***51 ASTOR PL***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH504***	***1222***
EPA ID: NYP010001030				
EPA ID: NYP000772061				
EPA ID: NYP000773457				
EPA ID: NYP000774042				
EPA ID: NYP000774687				
**Additional key fields are available in the Map Findings section*				
CON EDISON VAULT: 96	***51 ASTOR PL***	***NNE 1/8 - 1/4 (0.185 mi.)***	***AH505***	***1227***
EPA ID: NYP004384574				
CON EDISON	610 BROADWAY	SW 1/8 - 1/4 (0.186 mi.)	AI510	1240
EPA ID: NYP004765228				
TRIBECA GAS INC	***610 BROADWAY***	***SW 1/8 - 1/4 (0.186 mi.)***	***AI514***	***1255***
EPA ID: NYD986988061				
CON EDISON SERVICE B	***444 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***AH515***	***1258***
EPA ID: NYP004242285				
CON EDISON SERVICE B	***44 E 2ND ST & 2ND AV***	***SE 1/8 - 1/4 (0.188 mi.)***	***Z516***	***1262***
EPA Id: NYP004241550				
CON EDISON SERVICE B	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH517***	***1265***
EPA ID: NYP004396537				
MTA NYCT ASTOR PL ST	***ASTOR PL & LAFAYETTE***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH519***	***1269***
EPA ID: NYR000095208				
CONSOLIDATED EDISON	LAFAYETTE ST & ASTOR	NNE 1/8 - 1/4 (0.188 mi.)	AH520	1272
EPA ID: NYP004075396				
CON EDISON MANHOLE:	***E LAFAYETTE ST & AST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH521***	***1273***
EPA ID: NYP004429452				
CON EDISON	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH522***	***1275***
EPA ID: NYP004214615				
CON EDISON GAS DRIP	***ASTOR PL & LAFAYETTE***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH524***	***1280***
EPA ID: NYP004201687				
CON EDISON MANHOLE:	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH525***	***1282***
EPA ID: NYP004425187				
CON EDISON	ASTOR PL & LAFAYETTE	NNE 1/8 - 1/4 (0.188 mi.)	AH526	1284

EPA ID: NYP004536868				
CONSOLIDATED EDISON EPA ID: NYP004049755	E 5TH & 2ND AVE	E 1/8 - 1/4 (0.188 mi.)	AC530	1291
CON EDISON EPA ID: NYP004492237	2ND AVE & 5TH ST	E 1/8 - 1/4 (0.188 mi.)	AC531	1293
CON EDISON EPA ID: NYP004586962 EPA ID: NYP004855421	66 2ND AVE	ESE 1/8 - 1/4 (0.188 mi.)	AC533	1295
CON EDISON EPA ID: NYP004855405	64 2ND AVE	ESE 1/8 - 1/4 (0.188 mi.)	AC535	1300
CON EDISON EPA ID: NYP004588273 EPA ID: NYP004855439	48 2ND AVE	SE 1/8 - 1/4 (0.189 mi.)	Z537	1304
CON EDISON SERVICE B EPA ID: NYP004429395	***623 BROADWAY FRONT***	***WSW 1/8 - 1/4 (0.190 mi.)***	***Y538***	***1307***
74 CLEANERS INC EPA ID: NYD034343657	***74 SECOND AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***AC541***	***1312***
CON EDISON EPA ID: NYP004586814	42 2ND AVE	SE 1/8 - 1/4 (0.191 mi.)	Z543	1316
CONSOLIDATED EDISON EPA ID: NYP004079448	255-261 NO. 6TH ST.	E 1/8 - 1/4 (0.191 mi.)	AE544	1317
CON EDISON EPA ID: NYP004589925	27 2ND AVE	SE 1/8 - 1/4 (0.191 mi.)	Z546	1320
CON EDISON - VAULT 8 EPA ID: NYP004128641	***39 W3 ST***	***WNW 1/8 - 1/4 (0.192 mi.)***	***AK547***	***1321***
V3554 EPA ID: NYP004040085	***75-20 ASTORIA BOULEV***	***NNE 1/8 - 1/4 (0.193 mi.)***	***AH548***	***1324***
CON EDISON SERVICE B EPA ID: NYP004434460	***38 2ND AVE***	***SE 1/8 - 1/4 (0.193 mi.)***	***Z549***	***1326***
CON EDISON EPA ID: NYP004589826	80 2ND AVE	ESE 1/8 - 1/4 (0.194 mi.)	AC551	1330
CON EDISON EPA ID: NYP004589917	23 2ND AVE	SSE 1/8 - 1/4 (0.195 mi.)	AL553	1334
CON EDISON EPA ID: NYP004591707	15 E 1ST ST	SSE 1/8 - 1/4 (0.195 mi.)	AL564	1360
CON EDISON EPA ID: NYP004589834	84 2ND AVE	ESE 1/8 - 1/4 (0.196 mi.)	AC565	1362
CONSOLIDATED EDISON EPA ID: NYP004056966	58 W 4OTH ST	NW 1/8 - 1/4 (0.196 mi.)	AF567	1367
CON ED EPA ID: NYP004856256	45 WEST 4TH ST	NW 1/8 - 1/4 (0.197 mi.)	AF568	1369
CON EDISON EPA ID: NYP004588422 EPA ID: NYP004810277	44 E 3RD ST	SE 1/8 - 1/4 (0.197 mi.)	AJ570	1371
CON EDISON GAS DRIP: EPA ID: NYP004258901	***COOPER SQ & W 4TH ST***	***NE 1/8 - 1/4 (0.199 mi.)***	***AP575***	***1379***
CON EDISON SERVICE B	***754 E BROADWAY***	***N 1/8 - 1/4 (0.199 mi.)***	***AH576***	***1382***

EPA ID: NYP004395539				
CON EDISON SERVICE B EPA ID: NYP004395604	***2-4 ST MARKS***	***NE 1/8 - 1/4 (0.201 mi.)***	***AG581***	***1392***
CON EDISON GAS MAIN: EPA ID: NYP004304556	***755 BROADWAY***	***N 1/8 - 1/4 (0.202 mi.)***	***AH583***	***1395***
NEW YORK UNIVERSITY EPA ID: NYD986963213	***40 W 4TH ST***	***NW 1/8 - 1/4 (0.203 mi.)***	***AF584***	***1397***
CON EDISON EPA ID: NYP004591509	297 MERCER ST	N 1/8 - 1/4 (0.204 mi.)	AR591	1421
CON ED EPA ID: NYP004856355	97 E 4TH ST	ESE 1/8 - 1/4 (0.204 mi.)	AC592	1422
CON EDISON EPA ID: NYP004775912 EPA ID: NYP004855546	97 E 4TH ST	ESE 1/8 - 1/4 (0.204 mi.)	AC594	1425
CON EDISON SERVICE B EPA ID: NYP004395612	***6-8 ST MARKS***	***ENE 1/8 - 1/4 (0.206 mi.)***	***AG600***	***1435***
CON EDISON EPA ID: NYP004586970	***24 2 AVE***	***SSE 1/8 - 1/4 (0.206 mi.)***	***AL603***	***1442***
CON EDISON EPA ID: NYP004586954	28 2ND AVE	SE 1/8 - 1/4 (0.207 mi.)	AL607	1451
CON EDISON VAULT: 13 EPA ID: NYP004367637	***136 E 8TH ST FRONT O***	***NNE 1/8 - 1/4 (0.207 mi.)***	***AH608***	***1452***
CON EDISON VAULT: 33 EPA ID: NYP004367629	***136 E 8TH ST FRONT O***	***NNE 1/8 - 1/4 (0.207 mi.)***	***AH609***	***1454***
CON EDISON - MH 2434 EPA ID: NYP004108353	***2-4 ALBANY STREET***	***NE 1/8 - 1/4 (0.207 mi.)***	***AP610***	***1457***
CON EDISON EPA ID: NYP004842965	4TH AVE & COOPER SQ	NE 1/8 - 1/4 (0.208 mi.)	AP614	1467
NEW YORK UNIVERSITY EPA ID: NYR000160077	***1-4 WASHINGTON SQUAR***	***W 1/8 - 1/4 (0.209 mi.)***	***AQ622***	***1481***
CON EDISON EPA ID: NYP004714853	EAST 1ST ST & 2ND AV	SSE 1/8 - 1/4 (0.209 mi.)	AL624	1485
CON EDISON SERVICE B EPA ID: NYP004239602	***9 2ND AVE FRONT OF***	***SSE 1/8 - 1/4 (0.210 mi.)***	***AL626***	***1487***
CON EDISON MANHOLE EPA ID: NYP004200051	***E 6 ST & 2ND AVE***	***E 1/8 - 1/4 (0.211 mi.)***	***AE629***	***1492***
CON EDISON EPA ID: NYP004486080	E 6TH ST & 2ND AVE	E 1/8 - 1/4 (0.211 mi.)	AE631	1495
CON ED EPA ID: NYP004856454	20 EAST 1ST ST	SSE 1/8 - 1/4 (0.213 mi.)	AL635	1503
CON EDISON - MANHOLE EPA ID: NYP004955090	100 W 4 ST	NW 1/8 - 1/4 (0.213 mi.)	AK636	1504
CON EDISON EPA ID: NYP004594610	2-3 GREENWICH ST	NE 1/8 - 1/4 (0.213 mi.)	AP639	1509
CON EDISON SERVICE B EPA ID: NYP004395588	***COOPER SQ & ST MARK***	***NE 1/8 - 1/4 (0.213 mi.)***	***AP640***	***1510***
CON EDISON	ASTOR PL & 3RD AVE	NE 1/8 - 1/4 (0.213 mi.)	AP641	1513

EPA ID: NYP004784393				
CON ED EPA ID: NYP004827663	3RD AVE & SAINT MARK	NE 1/8 - 1/4 (0.213 mi.)	AP643	1515
CON EDISON SERVICE B EPA ID: NYP004225975	***ST MARKS PL & COOPER***	***NE 1/8 - 1/4 (0.213 mi.)***	***AP647***	***1520***
CON EDISON EPA ID: NYP004629523	ASTOR PLACE AND 3RD	NE 1/8 - 1/4 (0.213 mi.)	AP648	1524
CON EDISON EPA ID: NYP004494662	3RD AVE & ASTOR PL	NE 1/8 - 1/4 (0.213 mi.)	AP650	1526
CON EDISION - V9216 EPA ID: NYP004086062	***ST.MARKS PL. AND 3RD***	***NE 1/8 - 1/4 (0.214 mi.)***	***AP652***	***1537***
24 SECOND AVENUE OWN EPA ID: NYR000225318	***24 2ND AVE***	***SE 1/8 - 1/4 (0.214 mi.)***	***AL656***	***1544***
CON EDISON EPA ID: NYP004590048	302 E 5TH ST	ESE 1/8 - 1/4 (0.215 mi.)	AT658	1552
MC 19 EAST HOUSTON L EPA ID: NYR000227553	19 E HOUSTON ST	SW 1/8 - 1/4 (0.215 mi.)	AI662	1559
CON EDISON EPA ID: NYP004797775	19 E HOUSTON ST	SW 1/8 - 1/4 (0.215 mi.)	AI663	1560
CON ED EPA ID: NYP004856348	88 E 4TH ST	ESE 1/8 - 1/4 (0.215 mi.)	AT666	1565
CON EDISON SERVICE B EPA ID: NYP004293858	***94 E 4TH ST***	***ESE 1/8 - 1/4 (0.216 mi.)***	***AT668***	***1568***
CON EDISON EPA ID: NYP004163325	***HOUSTON ST & BROADWA***	***SW 1/8 - 1/4 (0.217 mi.)***	***AU672***	***1577***
CON ED EPA ID: NYP004855538	90 E 4TH ST	ESE 1/8 - 1/4 (0.218 mi.)	AT674	1581
CON EDISON EPA ID: NYP004587119	47 E 2ND ST	SE 1/8 - 1/4 (0.219 mi.)	AL676	1585
CON EDISON EPA ID: NYP004161998	***BROADWAY & E 8TH ST***	***N 1/8 - 1/4 (0.220 mi.)***	***AV679***	***1590***
NYCT - 8TH ST STA N& EPA ID: NYR000094573	***E 8TH ST & BROADWAY***	***N 1/8 - 1/4 (0.220 mi.)***	***AV680***	***1592***
CON EDISON EPA ID: NYP004858124	BROADWAY & E 8 ST	N 1/8 - 1/4 (0.220 mi.)	AV681	1595
CONSOLIDATED EDISON EPA ID: NYP004115689	V5990-W 88TH ST & BR	SW 1/8 - 1/4 (0.220 mi.)	AU683	1598
CON ED EPA ID: NYP004107793	80 WASHINGTON SQ E S	NW 1/8 - 1/4 (0.221 mi.)	AW687	1605
CON EDISON EPA ID: NYP004824591	85 WASHINGTON SQ W	NW 1/8 - 1/4 (0.221 mi.)	AW689	1607
CON EDISON EPA ID: NYP004789509	115 2ND AVE	E 1/8 - 1/4 (0.221 mi.)	AN691	1610
CON EDISON EPA ID: NYP004589818	115 2 AVE	E 1/8 - 1/4 (0.221 mi.)	AN692	1611
CON ED	26 EAST 1ST ST	SE 1/8 - 1/4 (0.222 mi.)	AL695	1615

EPA ID: NYP004856470				
CON EDISON SERVICE B EPA ID: NYP004395687	***69 E 8 ST***	***NNE 1/8 - 1/4 (0.222 mi.)***	***AH696***	***1616***
CON EDISON EPA ID: NYP004423935	276 MULBERRY ST	SSW 1/8 - 1/4 (0.223 mi.)	AM700	1621
CON EDISON EPA ID: NYP004863680	302 E 6TH ST	E 1/8 - 1/4 (0.224 mi.)	AS705	1633
CON EDISON MANHOLE: EPA ID: NYP004283859	***1 W HOUSTON ST FRONT***	***SW 1/8 - 1/4 (0.226 mi.)***	***AU709***	***1638***
CONSOLIDATED EDISON EPA ID: NYP004107892	WASH SQ E & W 4TH ST	NW 1/8 - 1/4 (0.227 mi.)	AW711	1643
CON ED EPA ID: NYP004856363	98 E 4TH ST	ESE 1/8 - 1/4 (0.228 mi.)	AT713	1646
CON EDISON SERVICE B EPA ID: NYP004395547	***759 W BROADWAY***	***N 1/8 - 1/4 (0.229 mi.)***	***AV720***	***1659***
CON EDISON MANHOLE 5 EPA ID: NYP004244539	***759 BROADWAY***	***N 1/8 - 1/4 (0.229 mi.)***	***AV721***	***1661***
CON EDISON MANHOLE 5 EPA ID: NYP004142832	***759 BROADWAY & 8TH S***	***N 1/8 - 1/4 (0.229 mi.)***	***AV722***	***1665***
CON EDISON EPA ID: NYP004753836 EPA ID: NYP004760104	27 3RD AVE	NE 1/8 - 1/4 (0.229 mi.)	AZ726	1670
CON EDISON SERVICE B EPA ID: NYP004428504	***100 E 4TH ST***	***ESE 1/8 - 1/4 (0.230 mi.)***	***BA731***	***1679***
CON ED EPA ID: NYP004761243	***119 2ND AVE & 7TH ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AN732***	***1681***
NEW YORK UNIVERSITY EPA ID: NYD981566607	***100 WASHINGTON SQUAR***	***NW 1/8 - 1/4 (0.231 mi.)***	***AW734***	***1690***
NYCT - 2ND AVE STATI EPA ID: NYR000091355	***2ND AVE & HOUSTON ST***	***SSE 1/8 - 1/4 (0.231 mi.)***	***BB737***	***1724***
CON EDISON SERVICE B EPA ID: NYP004396644	***61 E 8TH ST***	***N 1/8 - 1/4 (0.232 mi.)***	***AV738***	***1726***
CON EDISON EPA ID: NYP004774543	34 E 1ST ST	SE 1/8 - 1/4 (0.232 mi.)	AL741	1731
CON EDISON SERVICE B EPA ID: NYP004430732	***29 E 1ST ST***	***SSE 1/8 - 1/4 (0.233 mi.)***	***AL743***	***1735***
CON EDISON SERVICE B EPA ID: NYP004856371 EPA ID: NYP004427910	***102 E 4TH ST***	***ESE 1/8 - 1/4 (0.234 mi.)***	***BA744***	***1737***
CON EDISON EPA ID: NYP004702536	53 E 2ND ST	SE 1/8 - 1/4 (0.234 mi.)	AX745	1740
KMART CORPORATION #7 EPA ID: NYR000031930	***770 BROADWAY***	***NNE 1/8 - 1/4 (0.234 mi.)***	***BC746***	***1742***
CON EDISON EPA ID: NYP004856389	106 E 4TH ST	ESE 1/8 - 1/4 (0.235 mi.)	AT749	1752
CON EDISON EPA ID: NYP004591681	106 E 4 ST	ESE 1/8 - 1/4 (0.235 mi.)	AT750	1754
CON ED	58 E 8TH ST	N 1/8 - 1/4 (0.236 mi.)	AR754	1759

EPA ID: NYP004855843				
CON EDISON SERVICE B EPA ID: NYP004305124	***14 E 2ND ST OPPOSITE***	***SSE 1/8 - 1/4 (0.237 mi.)***	***AL756***	***1763***
CONED EPA ID: NYP004146874	E INT JERSEY ST & CR	SW 1/8 - 1/4 (0.237 mi.)	BD758	1767
CON EDISON EPA ID: NYP004588406 EPA ID: NYP004862092	65 E 3RD ST	ESE 1/8 - 1/4 (0.238 mi.)	BA759	1767
CON EDISON EPA ID: NYP004588430	66 E 3RD ST	SE 1/8 - 1/4 (0.238 mi.)	BA761	1772
CON ED EPA ID: NYP004828507	EAST 7TH ST & 2ND AV	E 1/8 - 1/4 (0.239 mi.)	AS770	1784
CON EDISON SERVICE B EPA Id: NYP004242160	***E 7TH ST & 2ND AVE N***	***E 1/8 - 1/4 (0.239 mi.)***	***AS771***	***1784***
CON EDISON SERVICE B EPA ID: NYP004427951 EPA ID: NYP004842114	***104 E 4TH ST***	***ESE 1/8 - 1/4 (0.239 mi.)***	***BA774***	***1792***
M R C MGMT EPA ID: NYR000070060	770 BROADWAY	NNE 1/8 - 1/4 (0.239 mi.)	BC777	1798
CON EDISON EPA ID: NYP004591723	33 E 1ST ST	SSE 1/8 - 1/4 (0.241 mi.)	AL780	1807
CON EDISON SERVICE B EPA ID: NYP004471199	***599-601 BROADWAY & P***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AU781***	***1808***
C F A CORP OF ILLINO EPA ID: NYR000045047	***599 BROADWAY***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AU782***	***1811***
CON EDISON EPA ID: NYP004858140	50 E 8TH ST	N 1/8 - 1/4 (0.242 mi.)	AR785	1818
CON EDISON SERVICE B EPA ID: NYP004394482	***34 ST MARKS PL***	***ENE 1/8 - 1/4 (0.242 mi.)***	***AY787***	***1822***
CON EDISON - MANHOLE EPA ID: NYP004990642	109-11 E HOUSTON ST	SSE 1/8 - 1/4 (0.242 mi.)	BB788	1824
CON EDISON MANHOLE 3 EPA ID: NYP004243556	***W HOUSTON ST & MERCE***	***WSW 1/8 - 1/4 (0.242 mi.)***	***BF789***	***1824***
CON EDISON SERVICE B EPA ID: NYP004396651	***59 E 8 ST FRONT OF***	***N 1/8 - 1/4 (0.243 mi.)***	***AV791***	***1829***
CON EDISON EPA ID: NYP004202156	***61 2ND AVE & E 3RD S***	***SE 1/8 - 1/4 (0.245 mi.)***	***AX796***	***1840***
CON EDISON SERVICE B EPA ID: NYP004276481	***29 3RD AVE FRONT OF***	***NE 1/8 - 1/4 (0.245 mi.)***	***AZ797***	***1844***
CON EDISON SERVICE B EPA ID: NYP004395661	***29 3RD AVE***	***NE 1/8 - 1/4 (0.245 mi.)***	***AZ799***	***1847***
FAUST BROS INC EPA ID: NYD078873320	***48 E 8TH ST***	***N 1/8 - 1/4 (0.246 mi.)***	***AR801***	***1851***
CON EDISON SERVICE B EPA ID: NYP004395554	***765 W BROADWAY***	***NNE 1/8 - 1/4 (0.247 mi.)***	***AV806***	***1860***
CON EDISON EPA ID: NYP004856397	OPP 108 E 4TH ST	ESE 1/8 - 1/4 (0.247 mi.)	BA808	1865
CON EDISON SERVICE B	***55 E 8TH ST***	***N 1/8 - 1/4 (0.248 mi.)***	***AV809***	***1866***

EPA ID: NYP004396636				
CON EDISON EPA ID: NYP004593265	19 ST MARKS PL	ENE 1/8 - 1/4 (0.248 mi.)	AY811	1870
CON EDISON EPA ID: NYP004819169	23 SAINT MARKS PL	ENE 1/8 - 1/4 (0.248 mi.)	AY814	1875
CON EDISON EPA ID: NYP004704698	52 WEST 3RD STREET	WNW 1/8 - 1/4 (0.248 mi.)	816	1878
CON EDISON SERVICE B EPA ID: NYP004435194	***59 E 2ND ST***	***SE 1/8 - 1/4 (0.248 mi.)***	***AX818***	***1881***
NYC DEPT OF EDUCATIO EPA ID: NYR000224444	113 E 4TH ST	ESE 1/8 - 1/4 (0.249 mi.)	BA821	1887
CON EDISON EPA ID: NYP004591327	113 E 4 ST	ESE 1/8 - 1/4 (0.249 mi.)	BA822	1889
CON EDISON SERVICE B EPA ID: NYP004300430	***113 E 4TH ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***BA823***	***1890***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2016 has revealed that there are 9 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CONCORD ELECTRONICS EPA ID: NYD003925070	***GREAT JONES STREET***	***SSE 0 - 1/8 (0.016 mi.)***	***A28***	***78***
CVS # 10407 Generator EPA Id: NYR000211128	298 MULBERRY STREET	SSW 1/8 - 1/4 (0.157 mi.)	AB397	1017
CON EDISON Generator EPA Id: NYP004718573	284 BOWERY	S 1/8 - 1/4 (0.202 mi.)	AO582	1394
CON EDISON - MATT ST Generator EPA Id: NYP004721700	279 MATT ST	SSW 1/8 - 1/4 (0.225 mi.)	AM707	1636

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
DOWNTOWN RE HOLDINGS Generator EPA Id: NYR000217752	688 BROADWAY	NW 0 - 1/8 (0.057 mi.)	E82	192
CON EDISON - E 2ND Generator EPA Id: NYP004713921	26 E 2ND ST	SE 1/8 - 1/4 (0.153 mi.)	Z385	992
MOKLAM ENTERPRISES I Generator EPA Id: NYR000213413	622 BROADWAY	WSW 1/8 - 1/4 (0.173 mi.)	Y453	1121
CON EDISON - 1ST Generator EPA Id: NYP004714853	E 1ST & 2ND AVE	SSE 1/8 - 1/4 (0.209 mi.)	AL625	1486
KMART # 7777 Generator EPA Id: NYR000031930	770 BROADWAY	NNE 1/8 - 1/4 (0.239 mi.)	BC778	1800

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 2 RI MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONCORD ELECTRONICS EPA ID: NYD003925070	***GREAT JONES STREET***	***SSE 0 - 1/8 (0.016 mi.)***	***A28***	***78***
PRATT INSTITUTE - PU EPA Id: NYR000100867 Manifest Document Number: 000066632UIS	***295 LAFAYETTE ST 2ND***	***SW 1/8 - 1/4 (0.204 mi.)***	***AI587***	***1406***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2016 has revealed that there are 96 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE 5 EPA ID: NYP004236016	***379 LAFAYETTE ST***	***0 - 1/8 (0.000 mi.)***	***A9***	***39***
CON EDISON MANHOLE 3 EPA ID: NYP004236024	***LAFAYETTE ST & GREAT***	***W 0 - 1/8 (0.010 mi.)***	***A12***	***47***
CON EDISON EPA Id: NYP004848372	30-32 E 4TH ST & BOW	E 0 - 1/8 (0.012 mi.)	A18	61
NYU EPA Id: NYR000209866	383 LAFAYETTE ST	NNE 0 - 1/8 (0.013 mi.)	A24	72
CON EDISON SERVICE B EPA Id: NYP004274429	378 LAFAYETTE ST FRO	WNW 0 - 1/8 (0.016 mi.)	A29	95
CON EDISON MANHOLE 5 EPA ID: NYP004236057	***372 LAFAYETTE ST***	***WNW 0 - 1/8 (0.016 mi.)***	***A31***	***99***
CON EDISON SERVICE B EPA Id: NYP004265450	372 LAFAYETTE ST FRO	WNW 0 - 1/8 (0.016 mi.)	A35	113
CON EDISON SERVICE B EPA Id: NYP004249254	33 GREAT JONES ST	S 0 - 1/8 (0.019 mi.)	A39	122
CON EDISON - GAS MAI EPA Id: NYP004194312	E 4TH ST AND LAFAYET	N 0 - 1/8 (0.027 mi.)	A49	135
CON EDISON SERVICE B EPA Id: NYP004223681	E 4TH ST & LAFAYETTE	N 0 - 1/8 (0.027 mi.)	A50	137
CON EDISON EPA Id: NYP004754321	342 BOWERY	SE 0 - 1/8 (0.057 mi.)	F88	204
CON EDISON EPA Id: NYP004754339	340 BOWERY	SE 0 - 1/8 (0.061 mi.)	F103	232
CON EDISON SERVICE B EPA Id: NYP004274403	334 BOWERY FRONT OF	SSE 0 - 1/8 (0.067 mi.)	F108	242
CON EDISON SERVICE B EPA Id: NYP004274395	334 BOWERY FRONT OF	SSE 0 - 1/8 (0.067 mi.)	F109	243
CON EDISON SERVICE B	23 BOND ST FRONT OF	SSW 0 - 1/8 (0.068 mi.)	C112	253

EPA Id: NYP004274940				
CON EDISON SERVICE B EPA Id: NYP004274924	19 BOND ST FRONT OF	SW 0 - 1/8 (0.071 mi.)	C122	278
CON EDISON SERVICE B EPA Id: NYP004275384	59 BOND ST FRONT OF	SSE 0 - 1/8 (0.090 mi.)	F170	382
CON EDISON SERVICE B EPA Id: NYP004280129	23 BLEECKER ST	S 0 - 1/8 (0.094 mi.)	F186	418
CON EDISON GAS DRIP: EPA Id: NYP004267464	BLECKER ST & ELIZABE	S 0 - 1/8 (0.105 mi.)	K221	497
MTA NYCT BLEECKER ST EPA ID: NYR000037051	***BLEECKER & LAFAYETTE***	***SW 0 - 1/8 (0.113 mi.)***	***K240***	***541***
CON EDISON EPA Id: NYP004735361	315 MOTT ST	SSW 1/8 - 1/4 (0.139 mi.)	K330	886
CON EDISON EPA Id: NYP004735379	306 MOTT ST	SSW 1/8 - 1/4 (0.146 mi.)	P358	945
CON EDISON SERVICE B EPA Id: NYP004265179	302 BOWERY FRONT OF	S 1/8 - 1/4 (0.154 mi.)	P386	993
CON EDISON EPA Id: NYP004739264	298 MULBERRY ST	SSW 1/8 - 1/4 (0.157 mi.)	AB398	1020
CON EDISON EPA Id: NYP004736435	305 MULBERRY ST	SW 1/8 - 1/4 (0.157 mi.)	S406	1040
CON EDISON SERVICE B EPA Id: NYP004246726	41 E HOUSTON ST	SSW 1/8 - 1/4 (0.195 mi.)	AM558	1342
B P PRODUCTS NORTH A EPA Id: NYR000126698	***21 E HOUSTON ST***	***SW 1/8 - 1/4 (0.195 mi.)***	***AI562***	***1352***
CON EDISON - SERVICE EPA Id: NYP004174777	***BOWERY AND E HOUSTON***	***S 1/8 - 1/4 (0.196 mi.)***	***AO566***	***1363***
CON EDISON EPA Id: NYP004803540	279 BOWERY	S 1/8 - 1/4 (0.230 mi.)	AO728	1675
CON EDISON EPA Id: NYP004725180	269 BOWERY	S 1/8 - 1/4 (0.235 mi.)	AO752	1757
CON EDISON EPA Id: NYP004833501	268 BOWERY	S 1/8 - 1/4 (0.238 mi.)	BE766	1779
CON EDISON EPA Id: NYP004766481	268 BOWERY	S 1/8 - 1/4 (0.238 mi.)	BE767	1780
CON EDISON SERVICE B EPA ID: NYP004201273	***265 BOWERY STANTON S***	***S 1/8 - 1/4 (0.244 mi.)***	***AO794***	***1835***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON GAS MAIN EPA ID: NYP004237834	***COOPER SQ & E 5TH ST***	***ENE 0 - 1/8 (0.079 mi.)***	***H141***	***315***
CON EDISON EXCAVATIO EPA Id: NYP004235941	COOPER SQ & E 5TH ST	ENE 0 - 1/8 (0.079 mi.)	H142	321
CON EDISON - SERVICE EPA Id: NYP004188025	***GREAT JONES ST AND B***	***WNW 0 - 1/8 (0.080 mi.)***	***I148***	***335***
CON EDISON GAS MAIN	***WEST 4TH STREET AND***	***NW 0 - 1/8 (0.084 mi.)***	***E160***	***363***

EPA ID: NYP004235586				
CON EDISON GAS DRIP EPA Id: NYP004249221	E 4TH ST & BROADWAY	NW 0 - 1/8 (0.084 mi.)	E161	367
CON EDISON GAS MAIN EPA ID: NYP004223251	***W 4TH ST & BROADWAY***	***NW 0 - 1/8 (0.084 mi.)***	***E163***	***369***
CON EDISON SERVICE B EPA Id: NYP004274916	331 BOWERY FRONT OF	SE 0 - 1/8 (0.095 mi.)	G193	429
CON EDISON SERVICE B EPA Id: NYP004276044	36 COOPER SQ FRONT O	ENE 0 - 1/8 (0.098 mi.)	H202	462
CON EDISON EPA Id: NYP004803516	699 BROADWAY	NNW 0 - 1/8 (0.100 mi.)	L206	470
CON EDISON SERVICE B EPA Id: NYP004274882	327 BOWERY FRONT OF	SE 0 - 1/8 (0.102 mi.)	N214	484
CON EDISON SERVICE B EPA ID: NYP004215513	***8 E 2ND ST & BOWERY***	***SSE 0 - 1/8 (0.112 mi.)***	***N235***	***531***
CON EDISON SERVICE B EPA Id: NYP004250148	428 LAFAYETTE ST	NNE 0 - 1/8 (0.123 mi.)	O268	602
CON EDISON SERVICE B EPA Id: NYP004276036	41-55 COOPER SQ FRON	ENE 0 - 1/8 (0.125 mi.)	Q281	623
CON EDISON EPA Id: NYP004758447	430 LAFAYETTE ST	NNE 1/8 - 1/4 (0.128 mi.)	O289	636
CON EDISON MANHOLE 3 EPA Id: NYP004246361	425 LAFAYETTE ST	NNE 1/8 - 1/4 (0.129 mi.)	O299	656
CON EDISON SERVICE B EPA Id: NYP004275624	228 E 5TH ST FRONT O	E 1/8 - 1/4 (0.129 mi.)	J302	662
CON EDISON SERVICE B EPA ID: NYP004243499	***640 BROADWAY FRONT O***	***WSW 1/8 - 1/4 (0.137 mi.)***	***M323***	***872***
CON EDISON MANHOLE 5 EPA Id: NYP004215869	***BROADWAY & BLEEKER S***	***WSW 1/8 - 1/4 (0.138 mi.)***	***M328***	***882***
CON EDISON SERVICE B EPA Id: NYP004275640	216 E 6 ST FRONT OF	ENE 1/8 - 1/4 (0.141 mi.)	V334	893
CON EDISON MANHOLE 3 EPA Id: NYP004802914 EPA Id: NYP004250254	436 LAFAYETTE ST	NNE 1/8 - 1/4 (0.144 mi.)	O339	903
CON EDISON MANHOLE: EPA Id: NYP004256947	436 LAFFAYETTE AVE S	NNE 1/8 - 1/4 (0.144 mi.)	O344	916
CON EDISON - MANHOLE EPA Id: NYP004175162	***436 LAFAYETTE ST AND***	***NNE 1/8 - 1/4 (0.144 mi.)***	***O345***	***917***
CON EDISON EPA Id: NYP004832024	229 E 5TH ST	E 1/8 - 1/4 (0.148 mi.)	V368	961
CON EDISON EPA Id: NYP004777074	85 E 4TH ST	ESE 1/8 - 1/4 (0.148 mi.)	T372	968
CON EDISON SERVICE B EPA Id: NYP004275657	222 E 6 ST FRONT OF	E 1/8 - 1/4 (0.155 mi.)	V394	1012
CON EDISON EPA Id: NYP004877155	82 E 4TH ST	ESE 1/8 - 1/4 (0.157 mi.)	T402	1033
CON EDISON SERVICE B	6 E 1ST ST	SSE 1/8 - 1/4 (0.157 mi.)	AA404	1037

EPA Id: NYP004250072				
CON EDISON MANHOLE: EPA Id: NYP004270179	235 W 5OTH ST FRONT	E 1/8 - 1/4 (0.160 mi.)	V413	1050
CON EDISON EPA Id: NYP004723425	30 E 2ND ST	SE 1/8 - 1/4 (0.162 mi.)	Z418	1059
CON EDISON EPA Id: NYP004834012	69 2ND AVE	ESE 1/8 - 1/4 (0.162 mi.)	AC422	1065
CON EDISON SERVICE B EPA Id: NYP004492203	73-75 2ND AVE & 4TH	ESE 1/8 - 1/4 (0.168 mi.)	AC441	1100
CON EDISON EPA Id: NYP004821118	29 W 4TH ST	NW 1/8 - 1/4 (0.168 mi.)	AF445	1107
CON EDISON MANHOLE 5 EPA ID: NYP004243226	***E 3RD ST & 2ND AVE S***	***SE 1/8 - 1/4 (0.177 mi.)***	***T473***	***1155***
CON EDISON EPA Id: NYP004791612	12 WAVERLY PL	NNW 1/8 - 1/4 (0.183 mi.)	AD500	1206
CON EDISON EPA Id: NYP004765228	610 BROADWAY	SW 1/8 - 1/4 (0.186 mi.)	AI513	1253
CON EDISON SERVICE B EPA ID: NYP004242285	***444 LAFAYETTE ST***	***NNE 1/8 - 1/4 (0.187 mi.)***	***AH515***	***1258***
CON EDISON SERVICE B EPA Id: NYP004241550	***44 E 2ND ST & 2ND AV***	***SE 1/8 - 1/4 (0.188 mi.)***	***Z516***	***1262***
MTA NYCT ASTOR PL ST EPA Id: NYR000095208	ASTOR PL & LAFAYETTE	NNE 1/8 - 1/4 (0.188 mi.)	AH518	1268
CON EDISON EPA ID: NYP004214615	***LAFAYETTE ST & ASTOR***	***NNE 1/8 - 1/4 (0.188 mi.)***	***AH522***	***1275***
CON EDISON EPA Id: NYP004810277	44 E 3RD ST	SE 1/8 - 1/4 (0.197 mi.)	AJ571	1374
CON EDISON EPA Id: NYP004775912	97 E 4TH ST	ESE 1/8 - 1/4 (0.204 mi.)	AC595	1428
CON EDISON MANHOLE: EPA Id: NYP004280277	E COOPER SQ & 4TH AV	NE 1/8 - 1/4 (0.208 mi.)	AP612	1465
CON EDISON EPA Id: NYP004842965	4TH AVE & COOPER SQ	NE 1/8 - 1/4 (0.208 mi.)	AP613	1466
CON EDISON SERVICE B EPA ID: NYP004239602	***9 2ND AVE FRONT OF***	***SSE 1/8 - 1/4 (0.210 mi.)***	***AL626***	***1487***
CON EDISON EPA Id: NYP004827663	3RD AVE & SAINT MARK	NE 1/8 - 1/4 (0.213 mi.)	AP644	1517
CON EDISON SERVICE B EPA ID: NYP004225975	***ST MARKS PL & COOPER***	***NE 1/8 - 1/4 (0.213 mi.)***	***AP647***	***1520***
CON EDISON EPA Id: NYP004797775	19 E HOUSTON ST	SW 1/8 - 1/4 (0.215 mi.)	AI664	1562
CON EDISON - SERVICE EPA Id: NYP004858124	BROADWAY & E 8 ST	N 1/8 - 1/4 (0.220 mi.)	AV678	1588
CON EDISON EPA Id: NYP004824591	85 WASHINGTON SQ W	NW 1/8 - 1/4 (0.221 mi.)	AW688	1606
CON EDISON	115 2ND AVE	E 1/8 - 1/4 (0.221 mi.)	AN693	1613

EPA Id: NYP004789509				
CON EDISON MANHOLE 5 EPA ID: NYP004244539	***759 BROADWAY***	***N 1/8 - 1/4 (0.229 mi.)***	***AV721***	***1661***
CON EDISON SERVICE B EPA Id: NYP004395547	759 W BROADWAY	N 1/8 - 1/4 (0.229 mi.)	AV723	1667
CON EDISON EPA Id: NYP004753836	27 3RD AVE	NE 1/8 - 1/4 (0.229 mi.)	AZ725	1669
NEW YORK UNIVERSITY EPA ID: NYD981566607	***100 WASHINGTON SQUAR***	***NW 1/8 - 1/4 (0.231 mi.)***	***AW734***	***1690***
CON EDISON EPA Id: NYP004774543	34 E 1ST ST	SE 1/8 - 1/4 (0.232 mi.)	AL740	1730
CON EDISON EPA Id: NYP004828507	E 7TH ST & 2ND AVE	E 1/8 - 1/4 (0.239 mi.)	AS768	1781
CON EDISON SERVICE B EPA Id: NYP004242160	***E 7TH ST & 2ND AVE N***	***E 1/8 - 1/4 (0.239 mi.)***	***AS771***	***1784***
CON EDISON EPA Id: NYP004842114	104 E 4TH ST	ESE 1/8 - 1/4 (0.239 mi.)	BA776	1797
CON EDISON EPA ID: NYP004202156	***61 2ND AVE & E 3RD S***	***SE 1/8 - 1/4 (0.245 mi.)***	***AX796***	***1840***
CON EDISON SERVICE B EPA Id: NYP004276481	29 3RD AVE FRONT OF	NE 1/8 - 1/4 (0.245 mi.)	AZ800	1850
CON EDISON EPA Id: NYP004807723	21 SAINT MARKS PL	ENE 1/8 - 1/4 (0.247 mi.)	AY804	1858
CON EDISON SERVICE B EPA Id: NYP004395554	765 W BROADWAY	NNE 1/8 - 1/4 (0.247 mi.)	AV805	1859
CON EDISON EPA Id: NYP004819169	23 SAINT MARKS PL	ENE 1/8 - 1/4 (0.248 mi.)	AY815	1877

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 5 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - HESTER	HESTER STREET	SSW 1/2 - 1 (0.667 mi.)	928	2098
CON EDISON - CANAL S	CANAL STREET	SSW 1/2 - 1 (0.697 mi.)	929	2098
CON EDISON - EAST 17	EAST 17TH - EAST 18T	ENE 1/2 - 1 (0.842 mi.)	931	2100

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - EAST 21	EAST 20TH - EAST 22N	ENE 1/2 - 1 (0.947 mi.)	932	2100
CON EDISON - CROSS/L	60 CENTRE ST	SSW 1/2 - 1 (0.981 mi.)	933	2101

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 10 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
371 LAFAYETTE	371 LAFAYETTE ST	0 - 1/8 (0.000 mi.)	A6	37
POST BROS SERVICE ST	363-371 LAFAYETTE ST	SW 0 - 1/8 (0.020 mi.)	A40	123
POST BROS SERVICE ST	361 LAFAYETTE ST	SW 0 - 1/8 (0.022 mi.)	A42	123
VICTOR TRANSMISSIONS	393 LAFAYETTE ST	NNE 0 - 1/8 (0.042 mi.)	D63	157
SPOT SERVICE STATION	326 BOWERY	SSE 0 - 1/8 (0.080 mi.)	F154	356

Lower Elevation	Address	Direction / Distance	Map ID	Page
SUPERIOR GULF STATIO	360 BOWERY	ESE 0 - 1/8 (0.043 mi.)	B64	157
HARRY AUTOMOTIVE REP	10-12 BOND ST	WSW 0 - 1/8 (0.048 mi.)	C69	166
MARTYS QUICKSTART IN	1 COOPER SQUARE	E 0 - 1/8 (0.060 mi.)	B94	215
335 BOWERY OPERATING	335 BOWERY	SE 0 - 1/8 (0.098 mi.)	G199	458
66 68 E 4TH STREET E	66 E 4TH ST	ESE 0 - 1/8 (0.120 mi.)	J259	588

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 5 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SMOOTH TOOTH ENTERPR	41 GREAT JONES ST	SSE 0 - 1/8 (0.020 mi.)	A41	123
GOUVERNEUR & CO	10 BLEECKER ST APT 4	S 0 - 1/8 (0.120 mi.)	P258	588


Lower Elevation	Address	Direction / Distance	Map ID	Page
VERSAKLEEN DRY CLEAN	8 W 4TH ST	NW 0 - 1/8 (0.098 mi.)	L203	463
JOHNS DRY CLEANERS C	652 BROADWAY	WSW 0 - 1/8 (0.107 mi.)	M226	507
BROADWAY CLEANERS IN	657 BROADWAY	W 0 - 1/8 (0.121 mi.)	M264	596

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 6 records.

Site Name	Database(s)
EDGEMERE LANDFILL	NY SHWS, NY VAPOR REOPENED
WEST 9TH STREET GW	NY SHWS
76TH ST BET. BROADWAY	NY LTANKS
DERMONT CO - TTF	NY LTANKS
WILLIAMSBURGE	NY HSWDS
PROPOSED FEDERAL EXPRESS DISTRIBUT	NY VCP

OVERVIEW MAP - 5314975.2S



0 1/4 1/2 1 Miles


- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands
- Upgradient Area

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	375 Lafayette Street	CLIENT:	Langan Engineering
ADDRESS:	375 Lafayette Street New York NY 10003	CONTACT:	Amanda Forsburg
LAT/LONG:	40.727296 / 73.993162	INQUIRY #:	5314975.2s
		DATE:	May 30, 2018 7:39 am

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5314975.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	375 Lafayette Street	CLIENT:	Langan Engineering
ADDRESS:	375 Lafayette Street New York NY 10003	CONTACT:	Amanda Forsburg
LAT/LONG:	40.727296 / 73.993162	INQUIRY #:	5314975.2s
		DATE:	May 30, 2018 7:41 am

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	0.001		0	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		3	6	NR	NR	NR	9
RCRA-SQG	0.250		3	8	NR	NR	NR	11
RCRA-CESQG	0.250		1	10	NR	NR	NR	11
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	0	1	NR	1
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		7	34	89	NR	NR	130
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250		17	17	NR	NR	NR	34
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	1	0	NR	NR	1
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	0	NR	NR	NR	0
NY AST	0.250		61	110	NR	NR	NR	171
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	1	0	NR	NR	1
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		1	NR	NR	NR	NR	1
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		2	5	10	NR	NR	17
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	0	0	NR	NR	0
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	1	1	NR	NR	2
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125		50	NR	NR	NR	NR	50
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		69	162	NR	NR	NR	231
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	1	NR	1
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		1	NR	NR	NR	NR	1
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	1	NR	1
INDIAN RESERV	0.001		0	NR	NR	NR	NR	0
FUSRAP	1.000		0	0	0	2	NR	2
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.001		0	NR	NR	NR	NR	0
FINDS	0.001		2	NR	NR	NR	NR	2
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		2	NR	NR	NR	NR	2
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	3	NR	NR	NR	3
NY E DESIGNATION	0.125		4	NR	NR	NR	NR	4

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		85	246	NR	NR	NR	331
PA MANIFEST	0.250		2	7	NR	NR	NR	9
RI MANIFEST	0.250		1	1	NR	NR	NR	2
NJ MANIFEST	0.250		33	63	NR	NR	NR	96
NY SPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	5	NR	5
EDR Hist Auto	0.125	1	10	NR	NR	NR	NR	11
EDR Hist Cleaner	0.125		5	NR	NR	NR	NR	5
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0
NY RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		1	359	675	100	11	0	1146

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **H B SERVICE CENTER** **EDR Hist Auto** **1021433216**
Target **375-9 LAFAYETTE ST** **N/A**
Property **NEW YORK, NY 10007**

Site 1 of 50 in cluster A

Actual: **42 ft.**

EDR Hist Auto

Year:	Name:	Type:
1969	H B SERVICE CENTER	Gasoline Service Stations
1970	H B SERVICE CENTER	Gasoline Service Stations
1971	H B SERVICE CENTER	Gasoline Service Stations
1972	H B SERVICE CENTER	Gasoline Service Stations

NPL **HUDSON RIVER PCBS** **NPL** **1000384273**
Region **NO STREET APPLICABLE** **SEMS** **NYD980763841**
West **HUDSON RIVER, NY 12801** **RCRA-SQG**
1/2-1 **US ENG CONTROLS**
5183 ft. **US INST CONTROL**
NY Spills
ROD
PRP
CONSENT

NPL:

EPA ID:	NYD980763841
Cerclis ID:	202229
EPA Region:	2
Federal:	N
Final Date:	1984-09-21 00:00:00
Site Score:	54.659999999999997
Latitude:	43.110199999999999
Longitude:	-73.576499999999996

Category Details:

NPL Status:	Currently on the Final NPL
Category Description:	Depth To Aquifer-<= 10 Feet
Category Value:	0

NPL Status:	Currently on the Final NPL
Category Description:	Distance To Nearest Population-> 0 And <= 1/4 Mile
Category Value:	10

Site Details:

Site Name:	HUDSON RIVER PCBS
Site Status:	Final
Site Zip:	12801
Site City:	HUDSON RIVER
Site State:	NY
Federal Site:	No
Site County:	WASHINGTON
EPA Region:	02
Date Proposed:	09/08/83
Date Deleted:	Not reported
Date Finalized:	09/21/84

Substance Details:

NPL Status:	Currently on the Final NPL

HUDSON RIVER PCBS (Continued) **1000384273**

Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Currently on the Final NPL
Substance ID: A046
Substance: POLYCHLORINATED BIPHENYLS
CAS #: 1336-36-3
Pathway: AIR PATHWAY
Scoring: 4

NPL Status: Currently on the Final NPL
Substance ID: A046
Substance: POLYCHLORINATED BIPHENYLS
CAS #: 1336-36-3
Pathway: SURFACE WATER PATHWAY
Scoring: 4

Summary Details:

Conditions at listing September 1983): The Hudson River PCBs Site is a 40-mile stretch of the Hudson River between Mechanicville and Fort Edward, New York. General Electric Co. discharged an estimated l.l million pounds of PCBs into this stretch of river. The State has identified 40 hot spots, defined as sediments contaminated with greater than 50 parts per million ppm) of PCBs. Also included in the site are five remnant areas, which are river sediments exposed when thelevel of the river was lowered due to removal of the Fort Edward Dam. The State has taken initial measures to stabili e the remnant areas from erosion. In September 1980, Congress passed an amendment to the Clean Water Act CWA) that included the Hudson River PCB Reclamation Demonstration Project. Under this legislation, the EPA Administrator could authori e a 75 percent grant, not to exceed 20 million. EPA issued a final Environmental Impact Statement in October 1982 evaluating various dredging alternatives for a demonstration project. EPA has prepared a feasibility study to evaluate alternative remedial actions under CERCLA. The Administrator has determined that CERCLA funds may be used for remedial action atthe remnant areas and for evaluating the effectiveness of the water supply system at Waterford, New York. Status June 1984): EPA has completed a draft feasibility study identifying alternatives for remedial action. A search for partiespotentially responsible for wastes associated with the site has been completed, and EPA has sent letters to two potentially responsible parties notifying them of possible legal action under CERCLA.

Site Status Details:
NPL Status: Final
Proposed Date: 09/08/1983
Final Date: 09/21/1984
Deleted Date: Not reported

Narratives Details:
NPL Name: HUDSON RIVER PCBS
City: HUDSON RIVER
State: NY

HUDSON RIVER PCBS (Continued) **1000384273**

SEMS:
- Site ID: 202229
- EPA ID: NYD980763841
- Cong District: 21
- FIPS Code: 36115
- Latitude: 43.110199999999999
- Longitude: -73.576499999999996
- FF: N
- NPL: Currently on the Final NPL
- Non NPL Status: Not reported

SEMS Detail:
- Region: 2
- Site ID: 202229
- EPA ID: NYD980763841
- Site Name: HUDSON RIVER PCBS
- NPL: F
- FF: N
- OU: 0
- Action Code: DS
- Action Name: DISCVRY
- SEQ: 1
- Start Date: 1983-07-01 00:00:00
- Finish Date: 7/1/1983
- Qual: Not reported
- Current Action Lead: EPA Perf

- Region: 2
- Site ID: 202229
- EPA ID: NYD980763841
- Site Name: HUDSON RIVER PCBS
- NPL: F
- FF: N
- OU: 3
- Action Code: RS
- Action Name: RV ASSESS
- SEQ: 3
- Start Date: 1998-06-03 00:00:00
- Finish Date: 6/24/1999
- Qual: Not reported
- Current Action Lead: EPA Perf

- Region: 2
- Site ID: 202229
- EPA ID: NYD980763841
- Site Name: HUDSON RIVER PCBS
- NPL: F
- FF: N
- OU: 0
- Action Code: CR
- Action Name: CI
- SEQ: 1
- Start Date: 1991-09-30 00:00:00
- Finish Date: Not reported
- Qual: Not reported
- Current Action Lead: EPA Perf

HUDSON RIVER PCBS (Continued) **1000384273**

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 2
Action Code: RO
Action Name: ROD
SEQ: 2
Start Date: 2002-02-01 00:00:00
Finish Date: 2/1/2002
Qual: R
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 1
Action Code: RO
Action Name: ROD
SEQ: 1
Start Date: 1984-09-25 00:00:00
Finish Date: 9/25/1984
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 0
Action Code: RS
Action Name: RV ASSESS
SEQ: 1
Start Date: 1990-04-17 00:00:00
Finish Date: 8/21/1990
Qual: S
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 0
Action Code: NF
Action Name: NPL FINL
SEQ: 1
Start Date: 1984-09-21 00:00:00
Finish Date: 9/21/1984

HUDSON RIVER PCBS (Continued) **1000384273**

Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	CO
Action Name:	RI/FS
SEQ:	2
Start Date:	1990-07-25 00:00:00
Finish Date:	2/1/2002
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	AR
Action Name:	ADMIN REC
SEQ:	1
Start Date:	1992-04-24 00:00:00
Finish Date:	Not reported
Qual:	E
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	RA
Action Name:	RA
SEQ:	3
Start Date:	2008-12-04 00:00:00
Finish Date:	12/23/2009
Qual:	FR
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	RA
Action Name:	RA

HUDSON RIVER PCBS (Continued) **1000384273**

SEQ: 2
Start Date: 2008-05-09 00:00:00
Finish Date: 11/24/2009
Qual: FR
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 0
Action Code: MA
Action Name: ST COOP
SEQ: 2
Start Date: 1991-02-22 00:00:00
Finish Date: 4/3/2007
Qual: Not reported
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 0
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1983-08-01 00:00:00
Finish Date: 9/1/1983
Qual: H
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 0
Action Code: AR
Action Name: ADMIN REC
SEQ: 2
Start Date: 2000-03-28 00:00:00
Finish Date: Not reported
Qual: V
Current Action Lead: EPA Perf

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N

HUDSON RIVER PCBS (Continued) **1000384273**

OU:	1
Action Code:	RD
Action Name:	RD
SEQ:	2
Start Date:	1989-02-02 00:00:00
Finish Date:	6/5/1989
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	1
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	1984-03-30 00:00:00
Finish Date:	9/25/1984
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	SS
Action Name:	ESI RI
SEQ:	1
Start Date:	2002-06-30 00:00:00
Finish Date:	8/31/2005
Qual:	W
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	TG
Action Name:	TA GRANT
SEQ:	1
Start Date:	1995-09-29 00:00:00
Finish Date:	9/20/2005
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841

HUDSON RIVER PCBS (Continued) **1000384273**

Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	3
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	4
Start Date:	1998-10-14 00:00:00
Finish Date:	1/7/1999
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	3
Action Code:	RV
Action Name:	RMVL
SEQ:	1
Start Date:	1999-10-06 00:00:00
Finish Date:	9/14/2001
Qual:	S
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	FE
Action Name:	5 YEAR
SEQ:	1
Start Date:	2012-06-01 00:00:00
Finish Date:	6/1/2012
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1983-09-01 00:00:00
Finish Date:	9/1/1983
Qual:	L
Current Action Lead:	EPA Perf

HUDSON RIVER PCBS (Continued) **1000384273**

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	CR
Action Name:	CI
SEQ:	2
Start Date:	2002-03-25 00:00:00
Finish Date:	11/2/2006
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	3
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	2
Start Date:	1992-11-19 00:00:00
Finish Date:	12/1/1992
Qual:	S
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	NP
Action Name:	PROPOSED
SEQ:	1
Start Date:	1983-09-08 00:00:00
Finish Date:	9/8/1983
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	CR
Action Name:	CI
SEQ:	3
Start Date:	2005-11-07 00:00:00
Finish Date:	Not reported

HUDSON RIVER PCBS (Continued) **1000384273**

Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	4
Action Code:	BD
Action Name:	PRP RI/FS
SEQ:	1
Start Date:	2008-09-08 00:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	1
Action Code:	BF
Action Name:	PRP RA
SEQ:	2
Start Date:	1990-09-28 00:00:00
Finish Date:	9/29/1992
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	1
Action Code:	BE
Action Name:	PRP RD
SEQ:	1
Start Date:	1989-05-18 00:00:00
Finish Date:	1/7/1991
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	1
Action Code:	BF
Action Name:	PRP RA

HUDSON RIVER PCBS (Continued) **1000384273**

SEQ: 1
Start Date: 1989-10-13 00:00:00
Finish Date: 9/29/1992
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 0
Action Code: PJ
Action Name: RP EM REM
SEQ: 1
Start Date: 2007-08-24 00:00:00
Finish Date: 8/27/2007
Qual: C
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 2
Action Code: BE
Action Name: PRP RD
SEQ: 6
Start Date: 2003-08-14 00:00:00
Finish Date: 4/26/2011
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N
OU: 4
Action Code: BB
Action Name: PRP RV
SEQ: 1
Start Date: 2007-09-11 00:00:00
Finish Date: 4/10/2012
Qual: S
Current Action Lead: EPA Ovrsght

Region: 2
Site ID: 202229
EPA ID: NYD980763841
Site Name: HUDSON RIVER PCBS
NPL: F
FF: N

HUDSON RIVER PCBS (Continued) **1000384273**

OU:	2
Action Code:	BF
Action Name:	PRP RA
SEQ:	4
Start Date:	2010-12-31 00:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	BF
Action Name:	PRP RA
SEQ:	3
Start Date:	2005-09-06 00:00:00
Finish Date:	9/4/2012
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	BE
Action Name:	PRP RD
SEQ:	3
Start Date:	2002-07-23 00:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	2
Action Code:	BE
Action Name:	PRP RD
SEQ:	4
Start Date:	2003-08-14 00:00:00
Finish Date:	1/25/2008
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841

HUDSON RIVER PCBS (Continued) **1000384273**

Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	1
Action Code:	BE
Action Name:	PRP RD
SEQ:	2
Start Date:	1989-09-27 00:00:00
Finish Date:	9/28/1990
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	0
Action Code:	EL
Action Name:	PRP CR
SEQ:	1
Start Date:	1989-07-07 00:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	2
Site ID:	202229
EPA ID:	NYD980763841
Site Name:	HUDSON RIVER PCBS
NPL:	F
FF:	N
OU:	1
Action Code:	RD
Action Name:	RD
SEQ:	1
Start Date:	1984-09-28 00:00:00
Finish Date:	5/18/1990
Qual:	Not reported
Current Action Lead:	St Perf

RCRA-SQG:

Date form received by agency:	03/03/2014
Facility name:	GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Facility address:	446 LOCK 8 WAY HUDSON FALLS, NY 12839
EPA ID:	NYD980763841
Mailing address:	BROADWAY BLDG 40 FORT EDWARD, NY 12828
Contact:	JAY SNOW
Contact address:	BROADWAY BLDG 40 FORT EDWARD, NY 12828
Contact country:	US

HUDSON RIVER PCBS (Continued) **1000384273**

Contact telephone: 518-746-5678
Contact email: JAY.SNOW@GE.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: GE HUDSON RIVER SEDIMENT REMEDIATION
Owner/operator address: BROADWAY
FORT EDWARD, NY 12828
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/23/2007
Owner/Op end date: Not reported

Owner/operator name: GE HUDSON RIVER SEDIMENT REMEDIATION
Owner/operator address: BROADWAY
FORT EDWARD, NY 12828
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/23/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D006
. Waste name: CADMIUM

HUDSON RIVER PCBS (Continued) **1000384273**

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: B007
. Waste name: B007

Historical Generators:
Date form received by agency: 03/01/2012
Site name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Classification: Large Quantity Generator

. Waste code: B002
. Waste name: B002

. Waste code: B007
. Waste name: B007

Date form received by agency: 03/03/2010
Site name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Classification: Large Quantity Generator

. Waste code: B007
. Waste name: B007

Date form received by agency: 08/29/2008
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) SUPERFUND USEPA
Classification: Large Quantity Generator

Date form received by agency: 01/01/2007
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Classification: Large Quantity Generator

Violation Status: No violations found

US ENG CONTROLS:
EPA ID: NYD980763841
Site ID: 0202229
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
HUDSON RIVER, NY 12801
EPA Region: 02
County: WASHINGTON
Event Code: Not reported
Actual Date: 12/30/2001

HUDSON RIVER PCBS (Continued) **1000384273**

Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Containment, (N.O.S.)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: No Action
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Revegetation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Slope Stabilization
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Dewatering
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002

HUDSON RIVER PCBS (Continued) **1000384273**

Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Disposal
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Excavation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Solidification/Stabilization (Ex-Situ)
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Surface Water
Engineering Control: Monitoring
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Surface Water
Engineering Control: Natural Attenuation
Contact Name: Not reported
Contact Phone and Ext: Not reported
Event Code Description: Not reported

US INST CONTROL:
EPA ID: NYD980763841
Site ID: 0202229
Name: HUDSON RIVER PCBS
Action Name: RECORD OF DECISION
Address: NO STREET APPLICABLE
HUDSON RIVER, NY 12801
EPA Region: 02
County: WASHINGTON

HUDSON RIVER PCBS (Continued) **1000384273**

Event Code: Not reported
Inst. Control: Fishing Advisory
Actual Date: 12/30/2001
Complet. Date: 02/01/2002
Operable Unit: 02
Contaminated Media : Surface Water
Contact Name : Not reported
Contact Phone and Ext : Not reported
Event Code Description: Not reported

SPILLS:
Facility ID: 0308107
Facility Type: ER
Spill Number: 0308107
DER Facility ID: 278391
Site ID: 237813
DEC Region: 3
Closed Date: 2003-10-31
Spill Cause: Abandoned Drums
Spill Class: D4
SWIS: 6000
Spill Date: 2003-10-31
Investigator: rxamato
Referred To: Not reported
Reported to Dept: 2003-10-31
CID: 297
Water Affected: HUDSON RIVER
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-10-31
Spill Record Last Update: 2003-11-06
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: PETTY OFFFICER HAWKINS
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SMITH 10/31/03: MEG hired by USCG to remove test and dispose. Container did not leak."
Remarks: "CALL TO NRC REPORTING A 55 GALLON DRUM OF UNKNOWN PETROLEUM FLOATING - USCG IS REPOSNDING TO THE SITE"

All Materials:
Site ID: 237813
Operable Unit ID: 874400
Operable Unit: 01
Material ID: 501630
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum

HUDSON RIVER PCBS (Continued) **1000384273**

Quantity: 55.00
Units: G
Recovered: .00
Oxygenate: Not reported

ROD:
Full-text of USEPA Record of Decision(s) is available from EDR.

PRP:
PRP name: DELAWARE AND HUDSON RAILWAY CO INC
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GOLUB PROPERTIES OF WATERVLIET INC
NEW YORK STATE CANAL CORPORATION
NIAGARA MOHAWK POWER COMPANY
TOWN OF HALFMOON NEW YORK
VILLAGE OF STILLWATER
WATER COMMISSIONERS OF THE TOWN OF WATERFORD

CONSENT:
EPA ID: NYD980763841
Site ID: 0284
Case Title: U.S.V. GENERAL ELECTRIC COMPANY (HUDSON RIVER) (EPA-SUPERFUND)
Court Num: 05-1270
District: New York, North
Entered Date: 11/02/06
Full-text of the consent decree for this site issued by the United States District Court is available from EDR. Contact your EDR Account Executive.

A2 **CONCORD ELECTRONICS CORP** **ICIS 1016199001**
30 GREAT JONES STREET **FINDS N/A**
< 1/8 **NEW YORK CITY, NY 10012** **ECHO**
1 ft.

Site 2 of 50 in cluster A

Relative: Higher
Actual: 42 ft.

ICIS:
Enforcement Action ID: 02-1985-0018
FRS ID: 110004342177
Action Name: CONCORD ELECTRONICS CORP.
Facility Name: CONCORD ELECTRONIC CORP
Facility Address: 30 GREAT JONES ST
NY CITY, NY 10012
Enforcement Action Type: Civil Judicial Action
Facility County: NEW YORK
Program System Acronym: ICIS
Enforcement Action Forum Desc: Judicial
EA Type Code: CIV
Facility SIC Code: 3643

CONCORD ELECTRONICS CORP (Continued) **1016199001**

Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.727164
Longitude in Decimal Degrees: -73.993404
Permit Type Desc: Not reported
Program System Acronym: 15457
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: CONCORD ELECTRONICS CORP
Address: 30 GREAT JONES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3643

Facility Name: CONCORD ELECTRONICS CORP
Address: 30 GREAT JONES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3643

Facility Name: CONCORD ELECTRONICS CORP
Address: 30 GREAT JONES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3643

Facility Name: CONCORD ELECTRONICS CORP
Address: 30 GREAT JONES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3643

Facility Name: CONCORD ELECTRONICS CORP
Address: 30 GREAT JONES STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3643

FINDS:

Registry ID: 110004342177

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CONCORD ELECTRONICS CORP (Continued) **1016199001**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016199001
Registry ID:	110004342177
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004342177

A3 **371 LAFAYETTE ST.** **NY LTANKS** **S101103145**
371 LAFAYETTE ST. **N/A**
< 1/8 **NEW YORK, NY**
1 ft.

Site 3 of 50 in cluster A

Relative: Higher
Actual: 42 ft.

LTANKS:

Facility ID:	9400935
Site ID:	170514
Closed Date:	2002-05-17
Spill Number:	9400935
Spill Date:	1994-04-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	1994-04-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

371 LAFAYETTE ST. (Continued) **S101103145**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-04-29
Spill Record Last Update:	2002-11-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143480
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 10/10/95: This is additional information about material spilled from the translation of the old spill file: TTF. 4/11/02 TRANSFERRED FROM O DOWD TO TIPPLE 5/1/02 SHAINDEL ENVIRONMENTAL KEN FRIEDMAN BEGINS DRILLING TO DO SITE ASSESSMENT, TIPLE WITNESSED FIRST BORING INSTALLATION. THERE WAS NO VISUAL OR OLFACTORY INDICATION OF PETROLEUM CONTAMINATION IN THE CONTINUOUSLY SAMPLED BORING. 5/2/02 KEN FRIEDMAN CALLED AT 7:45 AM TO INFORM ME THAT IN THE SECOND BORING A CLEAN SAND FILL(SIMILAR TO THAT USED AS BACKFILL MATERIAL IN SUBWAY CONSTRUCTION) WAS ENCOUNTERED AT 22 FOOT AND CONTINUED THROUGH TO 28 FOOT. WHEN THE DRILLERS PULLED THE SPOON FROM THE HOLE AT 28 FOOT THERE WAS AIR ESCAPING FROM THE BORING HOLE AS THE SUBWAY TRAIN APPROACHED THE SITE, AND THERE WAS A PROMINANT VIBRATION ON THE STEEL AS THE TRAINS PASSED. THE SITE IS ADJACENT TO THE SUBWAY, BOTH MR. FRIEDMAN AND I BELIEVE THAT THIS HOLE IS COMPLETED AND HE WILL ATTEMPT TO ATTAIN A GROUNDWATER SAMPLE FROM THE NEXT BORING. THE SITE IS NARROW AND AND THE SUBWAY IS PARTIALLY UNDER PART OF THE SITE. IF A WATER SAMPLE IS ATTAINABLE WITHOUT COMPRIMISING THE SUBWAY STRUCTUER IT WILL BE. MR.FRIEDMAN IS RESEARCHING THE POSSIBILITY OF A DEWATERING SUMP IN THE SUBWAY ALONG THE SITE TO POSSIBLY FIND ANOTHER WAY TO ATTAIN A GROUNDWATER SAMPLE REPRESENTATIVE OF THE SITE. 5/3/02 no sump associated with subway, apparently there is no dewatering necessary at this site. 5/16/02 left message for Kevin Hale to take a look at the report sent to him...concurs with no further action on this site "
Remarks:	"NYC FD NOTIFIED. NO CALL"

All TTF:

Facility ID:	9400935
Spill Number:	9400935
Spill Tank Test:	1542632
Site ID:	170514
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

371 LAFAYETTE ST. (Continued) **S101103145**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 170514
Operable Unit ID: 998336
Operable Unit: 01
Material ID: 384706
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

A4 **231 CENTRE STREET ASSOCIATES** **NY UST** **U000409052**
371 LAFAYETTE ST **N/A**
< 1/8 **NEW YORK, NY 10012**
1 ft.

Site 4 of 50 in cluster A

Relative: Higher
Actual: 42 ft.

UST:
Id/Status: 2-349836 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585001.03583
UTM Y: 4508963.69238
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 17237
Affiliation Type: Facility Owner
Company Name: 231 CENTRE STREET ASSOCIATES
Contact Type: Not reported
Contact Name: Not reported
Address1: 575 8TH AVE. 24FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 564-6662
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 17237
Affiliation Type: Mail Contact
Company Name: 231 CENTRE STREET ASSOCIATES
Contact Type: Not reported
Contact Name: SHERRON SMITH

231 CENTRE STREET ASSOCIATES (Continued) **U000409052**

Address1:	575 8TH AVE
Address2:	24 FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 564-6662
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17237
Affiliation Type:	Facility Operator
Company Name:	231 CENTRE STREET ASSOCIATES
Contact Type:	Not reported
Contact Name:	SHERRON SMITH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 564-6662
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17237
Affiliation Type:	Emergency Contact
Company Name:	231 CENTRE STREET ASSOCIATES
Contact Type:	Not reported
Contact Name:	SHERRON SMITH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 564-6662
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	33634
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1962
Date Tank Closed:	09/01/2000
Registered:	True
Tank Location:	Underground

231 CENTRE STREET ASSOCIATES (Continued) **U000409052**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping

Tank Number: 002
Tank ID: 33635
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1962
Date Tank Closed: 09/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Number: 003
Tank ID: 33636
Tank Status: Closed - Removed

231 CENTRE STREET ASSOCIATES (Continued) **U000409052**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1962
Date Tank Closed:	09/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping

Tank Number:	004
Tank ID:	33637
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1962
Date Tank Closed:	09/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None

231 CENTRE STREET ASSOCIATES (Continued) **U000409052**

D00 - Pipe Type - No Piping

Tank Number: 005
Tank ID: 33638
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1962
Date Tank Closed: 09/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping

Tank Number: 006
Tank ID: 33639
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1962
Date Tank Closed: 09/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None

231 CENTRE STREET ASSOCIATES (Continued) **U000409052**

I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

A5 **30 GREAT JONES ST** **NY AST** **U003386276**
30 GREAT JONES ST **N/A**
< 1/8 **NEW YORK, NY 10012**
1 ft.

Site 5 of 50 in cluster A

Relative: Higher
Actual: 42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-207543
Program Type:	PBS
UTM X:	585068.40751
UTM Y:	4508958.91419
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7371
Affiliation Type:	Facility Operator
Company Name:	30 GREAT JONES ST
Contact Type:	Not reported
Contact Name:	HARAY CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-6571
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-01-06

Site Id:	7371
Affiliation Type:	Emergency Contact
Company Name:	SP GREAT JONES,LLC C/O THE CORNERSTONE GROUP
Contact Type:	Not reported
Contact Name:	JOE PIPIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(973) 643-7700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS

30 GREAT JONES ST (Continued) **U003386276**

Date Last Modified: 2009-01-06

Site Id: 7371
Affiliation Type: Mail Contact
Company Name: EDISON CONSTR. MGT.
Contact Type: Not reported
Contact Name: JOE PIPIA
Address1: 100 WASHINGTON STREET
Address2: Not reported
City: NEWARK
State: NJ
Zip Code: 07102
Country Code: 001
Phone: (973) 643-7700
EMail: JOEP@EDPROP.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2009-01-06

Site Id: 7371
Affiliation Type: Facility Owner
Company Name: SP GREAT JONES,LLC C/O THE CORNERSTONE GROUP
Contact Type: PRES
Contact Name: KEVIN MALONEY
Address1: 570 7TH AVE SUITE 500
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (973) 643-7700
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2009-01-06

Tank Info:

Tank Number: 001
Tank Id: 9605
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron

30 GREAT JONES ST (Continued) **U003386276**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/16/1976
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/08/2008
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

A6 **371 LAFAYETTE** **EDR Hist Auto** **1020605204**
371 LAFAYETTE ST **N/A**
< 1/8 **NEW YORK, NY 10012**
1 ft.

Site 6 of 50 in cluster A

Relative: EDR Hist Auto
Higher

Actual: **42 ft.**

Year:	Name:	Type:
1987	371 LAFAYETTE	Gasoline Service Stations
1988	371 LAFAYETTE	Gasoline Service Stations
1989	371 LAFAYETTE	Gasoline Service Stations
1990	371 LAFAYETTE	Gasoline Service Stations
1991	371 LAFAYETTE	Gasoline Service Stations
1992	371 LAFAYETTE	Gasoline Service Stations
1993	371 LAFAYETTE	Gasoline Service Stations
1994	371 LAFAYETTE	Gasoline Service Stations

A7 **SPILL NUMBER 0209425** **NY Spills** **S106010033**
30 GREAT JONES ST **N/A**
< 1/8 **NEW YORK CITY, NY**
1 ft.

Site 7 of 50 in cluster A

Relative: SPILLS:
Higher

Actual: **42 ft.**

Facility ID:	0209425
Facility Type:	ER
Spill Number:	0209425
DER Facility ID:	125695
Site ID:	147649
DEC Region:	2
Closed Date:	2004-01-13
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	3101
Spill Date:	2002-12-13
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2002-12-13
CID:	365
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party

SPILL NUMBER 0209425 (Continued) **S106010033**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-13
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	PARK AVENUE ASSOCIATES
Spiller Address:	431 E 165TH ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE DEC Sigona called Larry Ahearn and Gabe (917)270-6045 and requested cleanup in response to inspection by DEC Tipple on 12/13/2002 at 11:45 AM. Additional cleanup required. Park Avenue Oil Company (RP) to send contractor from Bronx. Tipple to perform follow-up inspection. tipple visited site/ spill cleaned//nfa"
Remarks:	"Driver went to the wrong address to make a delivery - spill went into a vent that goes to the basement - they did the clean up "

All Materials:

Site ID:	147649
Operable Unit ID:	860771
Operable Unit:	01
Material ID:	565802
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

A8 **CON EDISON MANHOLE 59368** **FINDS 1014810415**
379 LAFAYETTE ST **ECHO N/A**
< 1/8 **NEW YORK, NY 10003**
1 ft.

Site 8 of 50 in cluster A

Relative: Higher

Actual: 42 ft.

FINDS:

Registry ID: 110043664326

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CON EDISON MANHOLE 59368 (Continued) **1014810415**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1014810415
Registry ID: 110043664326
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110043664326

A9 **CON EDISON MANHOLE 59368** **RCRA NonGen / NLR** **1014919435**
379 LAFAYETTE ST **NJ MANIFEST** **NYP004236016**
< 1/8 **NEW YORK, NY 10003** **NY MANIFEST**
1 ft.

Site 9 of 50 in cluster A

Relative: Higher
Actual: 42 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/06/2012
Facility name: CON EDISON MANHOLE 59368
Site name: CON EDISON - MANHOLE 59368
Facility address: 379 LAFAYETTE ST
NEW YORK, NY 10003
EPA ID: NYP004236016
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: DENNIS HUACON
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 212-460-2757
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE, 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/24/2011
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE, 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private

CON EDISON MANHOLE 59368 (Continued) **1014919435**

Owner/Operator Type: Operator
Owner/Op start date: 05/24/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 06/23/2011
Site name: CON EDISON MANHOLE 59368
Classification: Not a generator, verified

Date form received by agency: 05/24/2011
Site name: CON EDISON MANHOLE 59368
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004236016
Mail Address: IRVING PLAZA RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: TONI-ANN FRANZONE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007658393JJK
EPA ID: NYP004236016
Date Shipped: 5/24/2011

CON EDISON MANHOLE 59368 (Continued) **1014919435**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	3,000.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004236016
Facility Status:	Not reported
Location Address 1:	379 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CON EDISON MANHOLE 59368 (Continued) **1014919435**

Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004236016
Mailing Name:	CONSOLIDATED EDISON - MH 59368
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/24/2011
Trans1 Recv Date:	05/24/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/24/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004236016
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658393JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON MANHOLE 59368 (Continued) **1014919435**

Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A10
WSW
< 1/8
0.008 mi.
41 ft.

HARWOOD PROPERTY
25 GREAT JONES ST
NEW YORK, NY

Site 10 of 50 in cluster A

NY Spills **S102240446**
N/A

Relative:
Higher

Actual:
42 ft.

SPILLS:

Facility ID:	9604778
Facility Type:	ER
Spill Number:	9604778
DER Facility ID:	70604
Site ID:	75430
DEC Region:	2
Closed Date:	1996-07-12
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	3101
Spill Date:	1996-05-24
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1996-07-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-12
Spill Record Last Update:	1996-08-26
Spiller Name:	Not reported
Spiller Company:	PDI PHOTO LABS/RYM PHOTO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	DANIEL HARWOOD
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG CALLED TOM McGLENNON, FINLEY & NICOL WILL CLEAN UP THE RESIDUAL SPILL TODAY, AND WILL FORWARD DEC THE CLEANUP REPORT & ANY MANIFEST - REFERRED TO HWR"
Remarks:	"upon evicition spiller dumped chemicals - dep was notified "

All Materials:

Site ID:	75430

HARWOOD PROPERTY (Continued) **S102240446**

Operable Unit ID:	1032431
Operable Unit:	01
Material ID:	347538
Material Code:	1444A
Material Name:	photo fixer
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	75430
Operable Unit ID:	1032431
Operable Unit:	01
Material ID:	347537
Material Code:	1441A
Material Name:	photo chemicals
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	75430
Operable Unit ID:	1032431
Operable Unit:	01
Material ID:	347536
Material Code:	0989A
Material Name:	fixer film devel
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A11 **FDNY - ENG 33** **NY AST** **A100194049**
SE **42 GREAT JONES ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.009 mi.
45 ft. **Site 11 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-600571
Program Type:	PBS
UTM X:	585116.56656
UTM Y:	4508928.15957
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	22552

FDNY - ENG 33 (Continued) **A100194049**

Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	FDNY MAINTENANCE DIVISION
Address1:	48-34 35TH STRET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-06-22

Site Id:	22552
Affiliation Type:	Facility Operator
Company Name:	ENGINE COMPANY 33
Contact Type:	Not reported
Contact Name:	COMPANY OFFICER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 570-4233
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22552
Affiliation Type:	Emergency Contact
Company Name:	FIRE DEPARTMENT CITY OF NEW YORK
Contact Type:	Not reported
Contact Name:	FDNY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-06-22

Site Id:	22552
Affiliation Type:	Facility Owner
Company Name:	FIRE DEPARTMENT CITY OF NEW YORK
Contact Type:	Not reported
Contact Name:	JOSEPH M. MASTROPIETRO
Address1:	9 METROTECH CENTER
Address2:	Not reported

FDNY - ENG 33 (Continued) **A100194049**

City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-06-22

Tank Info:

Tank Number:	001
Tank Id:	43018
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1977
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/08/2003
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	43019
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)
H99 - Tank Leak Detection - Other

FDNY - ENG 33 (Continued) **A100194049**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
I02 - Overfill - High Level Alarm

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	diesel

A12 **CON EDISON MANHOLE 35859** **RCRA NonGen / NLR** **1014919436**
West **LAFAYETTE ST & GREAT JONES NE** **NJ MANIFEST** **NYP004236024**
< 1/8 **NEW YORK, NY 10012** **NY MANIFEST**
0.010 mi.
53 ft. **Site 12 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/23/2011
Facility name:	CON EDISON MANHOLE 35859
Facility address:	LAFAYETTE ST & GREAT JONES NE COR NEW YORK, NY 10012
EPA ID:	NYP004236024
Mailing address:	IRVING PLAZA RM 828 NEW YORK, NY 10003
Contact:	TONI-ANN FRANZONE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9450
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON MANHOLE 35859 (Continued) **1014919436**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/24/2011
Site name: CON EDISON MANHOLE 35859
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004236024
Mail Address: IRVING PLAZA RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: TONI-ANN FRANZONE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007658392JJK
EPA ID: NYP004236024
Date Shipped: 5/24/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported

CON EDISON MANHOLE 35859 (Continued) **1014919436**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2,000.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004236024
Facility Status:	Not reported
Location Address 1:	N/E/C LAFAYETTE ST & GREAT JONES ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTEN
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004236024
Mailing Name:	CONSOLIDATED EDISON - MH 35859
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/24/2011

CON EDISON MANHOLE 35859 (Continued) **1014919436**

Trans1 Recv Date:	05/24/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/24/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004236024
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658392JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A13 **S.E.G. 380 HOLDINGS LLC** **NY AST** **A100293746**
NNW **380 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.011 mi.
58 ft. **Site 13 of 50 in cluster A**

Relative: **Higher**
Actual: **42 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607417
Program Type:	PBS
UTM X:	585047.26303

S.E.G. 380 HOLDINGS LLC (Continued) **A100293746**

UTM Y: 4509054.68780
Expiration Date: 05/21/2022
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 29270
Affiliation Type: Mail Contact
Company Name: HSC MANAGEMENT CORP.
Contact Type: Not reported
Contact Name: JOSH KOPPEL
Address1: 850 BRONX RIVER ROAD
Address2: #108
City: YONKERS
State: NY
Zip Code: 10708
Country Code: 001
Phone: (914) 237-1600
EMail: JOSH.KOPPEL@HSCMANAGEMENT.COM
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-28

Site Id: 29270
Affiliation Type: Facility Operator
Company Name: S.E.G. 380 HOLDINGS LLC
Contact Type: Not reported
Contact Name: EMIL COBIC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 634-7867
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-28

Site Id: 29270
Affiliation Type: Emergency Contact
Company Name: S.E.G. 380 HOLDINGS, LLC
Contact Type: Not reported
Contact Name: JOSH KOPPEL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 237-1600
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-28

Site Id: 29270
Affiliation Type: Facility Owner

S.E.G. 380 HOLDINGS LLC (Continued) **A100293746**

Company Name:	S.E.G. 380 HOLDINGS, LLC
Contact Type:	MANAGING AGENT
Contact Name:	JOSH KOPPEL
Address1:	850 BRONX RIVER ROAD
Address2:	Not reported
City:	YONKERS
State:	NY
Zip Code:	10708
Country Code:	001
Phone:	(914) 237-1600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-28

Tank Info:

Tank Number:	001
Tank Id:	62919
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1970
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	08/28/2017
Material Name:	#2 fuel oil (on-site consumption)

A14 **PETERSBURG PRESS INC** **RCRA NonGen / NLR** **1004759960**
NNW **380 LAFAYETTE ST** **FINDS** **NYR000027342**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.011 mi. **NY MANIFEST**
58 ft. **Site 14 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PETERSBURG PRESS INC
Facility address:	380 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYR000027342
Mailing address:	LAFAYETTE ST NEW YORK, NY 10003
Contact:	PERRY TYMESON
Contact address:	LAFAYETTE ST NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-420-0890
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DEL REALTY
Owner/operator address:	380 LAFAYETTE ST NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-674-3332
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	DEL REALTY
Owner/operator address:	380 LAFAYETTE ST NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-674-3332
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

PETERSBURG PRESS INC (Continued) **1004759960**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PETERSBURG PRESS INC
Classification: Not a generator, verified

Date form received by agency: 07/29/1996
Site name: PETERSBURG PRESS INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004527030

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759960
Registry ID: 110004527030
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004527030

NY MANIFEST:
Country: USA
EPA ID: NYR000027342
Facility Status: Not reported
Location Address 1: 380 LAFAYETTE STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003

PETERSBURG PRESS INC (Continued) **1004759960**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000027342
Mailing Name: PETERSBURG PRESS
Mailing Contact: PERRY TYMESON
Mailing Address 1: 380 LAFAYETTE STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124200890

NY MANIFEST:
Document ID: NYB8039088
Manifest Status: K
seq: Not reported
Year: 1996
Trans1 State ID: JA334
Trans2 State ID: T405YXNJ
Generator Ship Date: 08/15/1996
Trans1 Recv Date: 08/15/1996
Trans2 Recv Date: 08/26/1996
TSD Site Recv Date: 08/26/1996
Part A Recv Date: 09/12/1996
Part B Recv Date: 09/24/1996
Generator EPA ID: NYR000027342
Trans1 EPA ID: NJD986607380
Trans2 EPA ID: NJD986607380
TSDF ID 1: NYD057770109
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

PETERSBURG PRESS INC (Continued) **1004759960**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A15 **CON EDISON** **NY MANIFEST** **U003740225**
East **34 4TH ST** **N/A**
< 1/8 **NEW YORK, NY 10009**
0.011 mi.
59 ft. **Site 15 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004741401
Facility Status:	Not reported
Location Address 1:	34 4 ST
Code:	BP
Location Address 2:	SB840
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004741401
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/03/2015
Trans1 Recv Date:	03/03/2015
Trans2 Recv Date:	03/05/2015
TSD Site Recv Date:	03/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004741401
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610881GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **U003740225**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

A16 **34 EAST 4TH STREET** **NY AST** **U004079522**
East **34 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.011 mi.
59 ft. **Site 16 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604601
Program Type:	PBS
UTM X:	585100.29694
UTM Y:	4508976.68313
Expiration Date:	07/03/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	26472
Affiliation Type:	Facility Owner
Company Name:	EAST FOURTH CORP.
Contact Type:	AGENT
Contact Name:	CATHERINE ECONOMAKIS
Address1:	138 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY

34 EAST 4TH STREET (Continued) **U004079522**

Zip Code:	11201
Country Code:	001
Phone:	(718) 625-4114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-05-13

Site Id:	26472
Affiliation Type:	Mail Contact
Company Name:	GRANITE INTERNATIONAL MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	CATHERINE ECONOMAKIS
Address1:	138 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 625-4114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-05-13

Site Id:	26472
Affiliation Type:	Facility Operator
Company Name:	34 EAST 4TH STREET
Contact Type:	Not reported
Contact Name:	GRANITE INT'L MGMT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 625-4114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26472
Affiliation Type:	Emergency Contact
Company Name:	EAST FOURTH CORP.
Contact Type:	Not reported
Contact Name:	CATHERINE ECONOMAKIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 625-4114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA

34 EAST 4TH STREET (Continued) **U004079522**

Date Last Modified: 2015-06-25

Tank Info:

Tank Number:	001
Tank Id:	58319
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/25/2003
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

A17 **CON EDISON** **RCRA NonGen / NLR** **1019908652**
East **30-32 E 4TH ST & BOWERY ST** **FINDS** **NYP004848372**
< 1/8 **NEW YORK, NY 10013** **ECHO**
0.012 mi.
65 ft. **Site 17 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/06/2015
Facility name:	CON EDISON
Facility address:	30-32 E 4TH ST & BOWERY ST NEW YORK, NY 10013
EPA ID:	NYP004848372
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON (Continued) **1019908652**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/06/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069680562

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908652
Registry ID:	110069680562
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069680562

A18
East
< 1/8
0.012 mi.
65 ft.

CON EDISON
30-32 E 4TH ST & BOWERY ST
NEW YORK, NY 10013

Site 18 of 50 in cluster A

NJ MANIFEST | **S120677575**
N/A

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004848372
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612421GBF
EPA ID:	NYP004848372
Date Shipped:	10/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120677575**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

A19 **CON EDISON** **NY MANIFEST** **S119078189**
East **30-32 E 4TH ST & BOWERY ST** **N/A**
< 1/8 **NEW YORK, NY 10013**
0.012 mi.
65 ft. **Site 19 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004848372
Facility Status:	Not reported
Location Address 1:	30 E 4TH ST
Code:	BP
Location Address 2:	SB 840
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004848372
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	10/05/2015
Trans1 Recv Date:	10/05/2015
Trans2 Recv Date:	10/12/2015
TSD Site Recv Date:	10/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004848372
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S119078189**

Manifest Tracking Number:	002612421GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

A20 **CON EDISON** **NY MANIFEST** **S117535583**
NE **22 E 4 ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.013 mi.
66 ft. **Site 20 of 50 in cluster A**

Relative: NY MANIFEST:
Higher

Country:	USA
EPA ID:	NYP004677084
Facility Status:	Not reported
Location Address 1:	22 E 4 ST
Code:	BP
Location Address 2:	VS2007
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

Actual: NY MANIFEST:
42 ft.

EPAID:	NYP004677084
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON

CON EDISON (Continued) **S117535583**

Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677084
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609590GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117535583**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A21 **CON EDISON** **NY MANIFEST** **S117535584**
NE **22 E 4 ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.013 mi.
66 ft. **Site 21 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004677092
Facility Status:	Not reported
Location Address 1:	22 E 4 ST
Code:	BP
Location Address 2:	V4714
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004677092
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2014
Trans1 Recv Date:	10/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004677092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609591GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S117535584**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A22 **NYU** **RCRA NonGen / NLR** **1016974527**
NNE **383 LAFAYETTE ST** **NY MANIFEST** **NYR000209866**
< 1/8 **NEW YORK, NY 10003**
0.013 mi.
71 ft. **Site 22 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/20/2016
Facility name:	NYU
Facility address:	383 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYR000209866
Mailing address:	ASTOR PL - EH&S 6TH FL NEW YORK, NY 10003
Contact:	ZACK KORENSTEIN
Contact address:	ASTOR PL - EH&S 6TH FL NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-998-1450
Contact email:	ZACK.KORENSTEIN@NYU.EDU
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK UNIVERSITY

NYU (Continued) **1016974527**

Owner/operator address: WASHINGTON SQUARE SOUTH
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/09/2014
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: WASHINGTON SQUARE SOUTH
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/09/2014
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: WASHINGTON SQ
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-998-1450
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/09/2014
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: WASHINGTON SQ
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-998-1450
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/09/2014
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No

NYU (Continued) **1016974527**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 02/29/2016
Site name: NYU - 383 LAFAYETTE
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

. Waste code: B007
. Waste name: B007

Date form received by agency: 06/10/2014
Site name: NYU
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 97645

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000209866
Facility Status: Not reported
Location Address 1: 383 LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:

NYU (Continued) **1016974527**

EPAID:	NYR000209866
Mailing Name:	NYU
Mailing Contact:	NEW YORK UNIVERSITY
Mailing Address 1:	10 ASTOR PLACE - 6TH FLOOR
Mailing Address 2:	ENV HEALTH & SAFETY
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129928276

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2016
Trans1 Recv Date:	04/22/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000209866
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	008937511FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	285
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported

NYU (Continued) **1016974527**

Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
13 additional NY_MANIFEST: record(s) in the EDR Site Report.

A23 **NEW YORK UNIVERSITY** **NY AST** **A100301205**
NNE **383 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.013 mi.
71 ft. **Site 23 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-607297
Program Type: PBS
UTM X: 585045.26298
UTM Y: 4509074.42668
Expiration Date: N/A
Site Type: School

Affiliation Records:
Site Id: 29150
Affiliation Type: Mail Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: ENVIRONMENTAL HEALTH AND SAFETY
Address1: 10 ASTOR PLACE
Address2: 6TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 998-1450
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-07-16

Site Id: 29150
Affiliation Type: Facility Operator
Company Name: NEW YORK UNIV.
Contact Type: Not reported
Contact Name: VANGEL FIGUEROA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 998-5279
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis

NEW YORK UNIVERSITY (Continued) **A100301205**

Date Last Modified: 2007-01-08

Site Id: 29150
Affiliation Type: Facility Owner
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: Not reported
Address1: 70 WASHINGTON SQUARE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 998-1450
EMail: Not reported
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2016-05-19

Site Id: 29150
Affiliation Type: Emergency Contact
Company Name: NEW YORK UNIV.
Contact Type: Not reported
Contact Name: PUBLIC SAFETY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 998-2222
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-10-07

Tank Info:

Tank Number: 001
Tank Id: 62704
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 3

NEW YORK UNIVERSITY (Continued) **A100301205**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/15/1956
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/15/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

A24 **NYU** **NJ MANIFEST** **S120679007**
NNE **383 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.013 mi.
71 ft. **Site 24 of 50 in cluster A**

Relative: **Higher**
Actual: **42 ft.**

NJ MANIFEST:

EPA Id:	NYR000209866
Mail Address:	ASTOR PL
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ZACK KORENSTEIN
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	008229107FLE
EPA ID:	NYR000209866
Date Shipped:	7/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	MAC300016672
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

NYU (Continued) **S120679007**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	008229102FLE
EPA ID:	NYR000209866
Date Shipped:	7/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	MAC300016672
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

NYU (Continued) **S120679007**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

A25 **28-30 E 4TH ST HOUSING CORP** **NY AST** **U000396289**
East **28-30 EAST 4TH ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.016 mi.
83 ft. **Site 25 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-189200
Program Type:	PBS
UTM X:	585063.23932
UTM Y:	4509071.29965
Expiration Date:	06/05/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5769
Affiliation Type:	Facility Owner
Company Name:	28 E 4TH ST HOUSING CORP
Contact Type:	PROPERTY MANAGER
Contact Name:	FIHLO THOMAS
Address1:	28-30 EAST 4TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-10

Site Id:	5769
Affiliation Type:	Mail Contact
Company Name:	C/O ANDREWS ORGANIZATION
Contact Type:	Not reported
Contact Name:	28-30 E. 4TH ST HOUSING CORP
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR

28-30 E 4TH ST HOUSING CORP (Continued) **U000396289**

Date Last Modified: 2017-07-10

Site Id: 5769
Affiliation Type: Facility Operator
Company Name: 28-30 E 4TH ST HOUSING CORP
Contact Type: Not reported
Contact Name: ROBERT JOYNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 674-0929
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 2007-05-08

Site Id: 5769
Affiliation Type: Emergency Contact
Company Name: 28 E 4TH ST HOUSING CORP
Contact Type: Not reported
Contact Name: ANDREWS BUILDING CORP.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-07-10

Tank Info:

Tank Number: 001
Tank Id: 6399
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle

28-30 E 4TH ST HOUSING CORP (Continued) **U000396289**

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/22/2005
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	07/10/2017
Material Name:	#2 fuel oil (on-site consumption)

A26 **SPILL NUMBER 9911688** **NY Spills** **S104650125**
East **28-30 E 4TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.016 mi.
83 ft. **Site 26 of 50 in cluster A**

Relative: **Higher**

Actual: **42 ft.**

SPILLS:

Facility ID:	9911688
Facility Type:	ER
Spill Number:	9911688
DER Facility ID:	246742
Site ID:	305454
DEC Region:	2
Closed Date:	2003-02-26
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-01-07
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-01-07
CID:	312
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-07
Spill Record Last Update:	2003-02-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	28-30 E 4TH ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"DEFECTIVE GAUGE IN THE BLDG - GOT INTO THE DRAIN - CLEAN UP SHORTLY"

All Materials:

SPILL NUMBER 9911688 (Continued) **S104650125**

Site ID:	305454
Operable Unit ID:	1086289
Operable Unit:	01
Material ID:	297139
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A27 **30 EAST 4TH STREET** **NY LTANKS** **S102672929**
East **30 EAST 4TH STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.016 mi.
83 ft. **Site 27 of 50 in cluster A**

Relative: LTANKS:
Higher

Facility ID:	9502124
Site ID:	169169
Closed Date:	1995-05-19
Spill Number:	9502124
Spill Date:	1995-05-19
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1995-05-19
SWIS:	0301
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1995-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-24
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	142452
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"SIDEWALK CLEANED - SPEEDY DRY - 10 FAMILY HOME APT BUILDING"

Actual:
42 ft.

All Materials:

30 EAST 4TH STREET (Continued) **S102672929**

Site ID:	169169
Operable Unit ID:	1013186
Operable Unit:	01
Material ID:	367192
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A28 **CONCORD ELECTRONICS CORPORATION** **RCRA-SQG** **1000180263**
SSE **GREAT JONES STREET** **RI MANIFEST** **NYD003925070**
< 1/8 **NEW YORK, NY 10012** **PA MANIFEST**
0.016 mi. **NY MANIFEST**
84 ft. **Site 28 of 50 in cluster A**

Relative: **Higher**

Actual: **42 ft.**

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	CONCORD ELECTRONICS CORPORATION
Facility address:	GREAT JONES STREET NEW YORK, NY 10012
EPA ID:	NYD003925070
Contact:	HARRY LALL
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-777-6571
Telephone ext.:	LALL
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CONCORD ELECTRIC
Owner/operator address:	GREAT JONES ST NEW YORK CITY, NY 10012
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1960
Owner/Op end date:	Not reported

Owner/operator name:	HARRY KASON

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/15/2006
Site name: CONCORD ELECTRONICS CORPORATION
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F006

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Date form received by agency: 02/14/2006
Site name: CONCORD ELECTRONICS CORPORATION
Classification: Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: CONCORD ELECTRONICS CORP
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F006
. Waste name: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Date form received by agency: 02/26/2002
Site name: CONCORD ELECTRONICS
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: CONCORD ELECTRONICS
Classification: Large Quantity Generator

Date form received by agency: 02/27/1998
Site name: CONCORD ELECTRONICS
Classification: Large Quantity Generator

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Date form received by agency: 03/28/1996
Site name: CONCORD ELECTRONICS
Classification: Large Quantity Generator

Date form received by agency: 03/30/1994
Site name: CONCORD ELECTRONICS
Classification: Large Quantity Generator

Date form received by agency: 02/28/1992
Site name: CONCORD
Classification: Large Quantity Generator

Date form received by agency: 08/18/1980
Site name: CONCORD ELECTRONIC CORP
Classification: Large Quantity Generator

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P104
. Waste name: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Facility Has Received Notices of Violations:
Regulation violated: SR - 372.2(b)(2)(i), (ii)
Area of violation: Generators - General
Date violation determined: 02/03/2005
Date achieved compliance: 04/28/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/15/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(iii)(e)(2)(iii)
Area of violation: Generators - General
Date violation determined: 02/03/2005
Date achieved compliance: 04/28/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/15/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Regulation violated: SR - 372.2(a)(8)(iii)(e)(2)(ii)
Area of violation: Generators - General
Date violation determined: 02/03/2005
Date achieved compliance: 04/28/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/15/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.3(g)(1)(i),(iii),(iv)
Area of violation: Generators - General
Date violation determined: 02/03/2005
Date achieved compliance: 04/28/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/15/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/11/1995
Date achieved compliance: 02/08/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/11/1995
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 09/19/1984
Date achieved compliance: 06/21/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/28/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Evaluation Action Summary:

Evaluation date:	02/03/2005
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	04/28/2005
Evaluation lead agency:	State

Evaluation date:	11/27/1995
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	02/08/1996
Evaluation lead agency:	State

Evaluation date:	09/19/1984
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - General
Date achieved compliance:	06/21/1985
Evaluation lead agency:	State

RI MANIFEST:

EPA Id:	NYD003925070
GEN Cert Date:	10/18/1990
Manifest Document Number:	RIB0011712
Waste Description:	POISON LIQ
TSDF Id:	RID001200252
TSDF Name:	TECHNIC
Qty:	115
WT/Vol Units:	G
TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Item Number:	2
Transporter 2 Name:	Not reported
Transporter Name 2:	FREEHOLD
Transporter EPAID:	NJD054126164
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIB0011712
Quarter:	Not reported
Waste Description:	POISON LIQ
Transporter Contact Name:	Not reported
Quantity:	115
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	FREEHOLD
Billing Name:	Not reported
Transporter EPA ID:	NJD054126164
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/18/1990
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIB0011712
Quarter:	Not reported
Waste Description:	SILVER CYANIDE
Transporter Contact Name:	Not reported
Quantity:	125
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	FREEHOLD
Billing Name:	Not reported
Transporter EPA ID:	NJD054126164
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/18/1990
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	D003
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC INC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIH0002568
Quarter:	Not reported
Waste Description:	POT CYN
Transporter Contact Name:	Not reported
Quantity:	110
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	TRI-STATE MOTOR TRANSIT

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Billing Name:	Not reported
Transporter EPA ID:	MOD095038998
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/12/1998
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	D003
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC INC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIC0026924
Quarter:	Not reported
Waste Description:	POT METALLIC
Transporter Contact Name:	Not reported
Quantity:	21
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	FREEHOLD CARTAGE INC
Billing Name:	Not reported
Transporter EPA ID:	NJD054126164
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	5/5/1994
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Waste Code1:	F007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIB0011712
Quarter:	Not reported
Waste Description:	POISON LIQ
Transporter Contact Name:	Not reported
Quantity:	115
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	FREEHOLD
Billing Name:	Not reported
Transporter EPA ID:	NJD054126164
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/18/1990
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIB0011712
Quarter:	Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Waste Description:	SILVER CYANIDE
Transporter Contact Name:	Not reported
Quantity:	125
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	FREEHOLD
Billing Name:	Not reported
Transporter EPA ID:	NJD054126164
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/18/1990
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	D003
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC INC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIH0002568
Quarter:	Not reported
Waste Description:	POT CYN
Transporter Contact Name:	Not reported
Quantity:	110
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	TRI-STATE MOTOR TRANSIT
Billing Name:	Not reported
Transporter EPA ID:	MOD095038998
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/12/1998
Facility Receipt Date:	Not reported
Fee:	Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	F007
Waste Code2:	D003
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	TECHNIC INC
TSDF Id:	RID001200252
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD003925070
Manifest Docket Number:	RIC0026924
Quarter:	Not reported
Waste Description:	POT METALLIC
Transporter Contact Name:	Not reported
Quantity:	21
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	FREEHOLD CARTAGE INC
Billing Name:	Not reported
Transporter EPA ID:	NJD054126164
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	5/5/1994
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Manifest Details:

Year:	2007
Manifest Number:	000410121JJK
Manifest Type:	Not reported
Generator EPA Id:	NYD003925070
Generator Date:	04/12/2007
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Contact Phone: 212-777-6571
TSD EPA Id: PAD981038227
TSD Date: Not reported
TSD Facility Name: WORLD RESOURCES CO
TSD Facility Address: 170 WALNUT LANE
TSD Facility City: POTTSVILLE
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: F006
Container Number: 1
Container Type: Burlap, cloth, paper or plastic bags
Waste Quantity: 1
Unit: Cubic Yards
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2007
Manifest Number: 000411410JJK
Manifest Type: Not reported
Generator EPA Id: NYD003925070
Generator Date: 01/16/2007
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: 212-777-6571
TSD EPA Id: PAD981038227
TSD Date: Not reported
TSD Facility Name: WORLD RESOURCES CO
TSD Facility Address: 170 WALNUT LANE
TSD Facility City: POTTSVILLE
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: F006
Container Number: 3
Container Type: Burlap, cloth, paper or plastic bags
Waste Quantity: 3
Unit: Cubic Yards
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: PAH244729
Manifest Type: TSD Copy
Generator EPA Id: NYD003925070
Generator Date: 05/09/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: PAD981038227
TSD Date: Not reported

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

TSD Facility Name:	WORLD RESOURCES CO
TSD Facility Address:	170 WALNUT LANE
TSD Facility City:	POTTSVILLE
TSD Facility State:	PA
Facility Telephone:	212-777-6571
Page Number:	1
Line Number:	1
Waste Number:	F006
Container Number:	3
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	3
Unit:	Cubic Yards
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000410118JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYD003925070
Generator Date:	10/24/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD981038227
TSD Date:	Not reported
TSD Facility Name:	WORLD RESOURCES CO
TSD Facility Address:	170 WALNUT LANE
TSD Facility City:	POTTSVILLE
TSD Facility State:	PA
Facility Telephone:	212-777-6571
Page Number:	1
Line Number:	1
Waste Number:	F006
Container Number:	2
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	2
Unit:	Cubic Yards
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	PAH244728
Manifest Type:	TSD Copy
Generator EPA Id:	NYD003925070
Generator Date:	08/01/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD981038227
TSD Date:	Not reported
TSD Facility Name:	WORLD RESOURCES CO
TSD Facility Address:	170 WALNUT LANE
TSD Facility City:	POTTSVILLE

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

TSD Facility State:	PA
Facility Telephone:	212-777-6571
Page Number:	1
Line Number:	1
Waste Number:	F006
Container Number:	2
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	2
Unit:	Cubic Yards
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2006
Manifest Number:	PAH244730
Manifest Type:	TSD Copy
Generator EPA Id:	NYD003925070
Generator Date:	02/15/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD981038227
TSD Date:	Not reported
TSD Facility Name:	WORLD RESOURCES CO
TSD Facility Address:	170 WALNUT LANE
TSD Facility City:	POTTSVILLE
TSD Facility State:	PA
Facility Telephone:	212-777-6571
Page Number:	1
Line Number:	1
Waste Number:	F006
Container Number:	4
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	4
Unit:	Cubic Yards
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2005
Manifest Number:	PAH190778
Manifest Type:	TSD Copy
Generator EPA Id:	NYD003925070
Generator Date:	03/15/2005
Mailing Address:	30 GREAT JONES ST
Mailing City,St,Zip:	NEW YORK, NY 10012
Contact Name:	Not reported
Contact Phone:	212-777-6571
TSD EPA Id:	PAD981038227
TSD Date:	03/15/2005
TSD Facility Name:	W R C PROCESSING CO / WORLD RESOURCES CO
TSD Facility Address:	170 WALNUT LN
TSD Facility City:	POTTSVILLE
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Line Number: 1
Waste Number: F006
Container Number: 3
Container Type: Burlap, cloth, paper or plastic bags
Waste Quantity: 3
Unit: Cubic Yards
Handling Code: Not reported
TSP EPA Id: NJD054126164
Date TSP Sig: 03/15/2005

Year: 2004
Manifest Number: PAG470131
Manifest Type: TSD Copy
Generator EPA Id: NYD003925070
Generator Date: 12/16/2004
Mailing Address: 30 GREAT JONES ST
Mailing City,St,Zip: NEW YORK, NY 10012
Contact Name: Not reported
Contact Phone: 212-777-6571
TSD EPA Id: PAD981038227
TSD Date: 12/17/2004
TSD Facility Name: W R C PROCESSING CO / WORLD RESOURCES CO
TSD Facility Address: 170 WALNUT LN
TSD Facility City: POTTSVILLE
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: F006
Container Number: 3
Container Type: Burlap, cloth, paper or plastic bags
Waste Quantity: 3
Unit: Cubic Yards
Handling Code: Not reported
TSP EPA Id: NJD054126164
Date TSP Sig: 12/16/2004

Year: 2004
Manifest Number: PAH021012
Manifest Type: TSD Copy
Generator EPA Id: NYD003925070
Generator Date: 06/30/2004
Mailing Address: 30 GREAT JONES ST
Mailing City,St,Zip: NEW YORK, NY 10012
Contact Name: Not reported
Contact Phone: 212-777-6571
TSD EPA Id: PAD981038227
TSD Date: 07/01/2004
TSD Facility Name: W R C PROCESSING CO / WORLD RESOURCES CO
TSD Facility Address: 170 WALNUT LN
TSD Facility City: POTTSVILLE
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: F006
Container Number: 3

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	3
Unit:	Cubic Yards
Handling Code:	Not reported
TSP EPA Id:	NJD054126164
Date TSP Sig:	06/30/2004

NY MANIFEST:

Country:	USA
EPA ID:	NYD003925070
Facility Status:	Not reported
Location Address 1:	30 GREAT JONES ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	1115

NY MANIFEST:

EPAID:	NYD003925070
Mailing Name:	KB - SQUARED INC
Mailing Contact:	JACK KESSIAN
Mailing Address 1:	P O BOX 162
Mailing Address 2:	Not reported
Mailing City:	HARRINGTON PARK
Mailing State:	NJ
Mailing Zip:	07640
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127776571

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009869825
Generator Ship Date:	05/07/2007
Trans1 Recv Date:	05/07/2007
Trans2 Recv Date:	05/11/2007
TSD Site Recv Date:	05/16/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003925070
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD000648451
TSDF ID 2:	Not reported
Manifest Tracking Number:	000617492FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CONCORD ELECTRONICS CORPORATION (Continued) **1000180263**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
214 additional NY_MANIFEST: record(s) in the EDR Site Report.

A29 **CON EDISON SERVICE BOX: 37920** **NJ MANIFEST** **S117986772**
WNW **378 LAFAYETTE ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.016 mi.
86 ft. **Site 29 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004274429
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456399JJK
EPA ID:	NYP004274429
Date Shipped:	10/17/2012
TSDF EPA ID:	NJD002200046

CON EDISON SERVICE BOX: 37920 (Continued) **S117986772**

Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	500.00 Pounds

A30 **CON EDISON SERVICE BOX: 37920** **RCRA NonGen / NLR** **1016148818**
WNW **378 LAFAYETTE ST FRONT OF** **FINDS** **NYP004274429**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.016 mi. **NY MANIFEST**
86 ft. **Site 30 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 37920
Facility address:	378 LAFAYETTE ST FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004274429

CON EDISON SERVICE BOX: 37920 (Continued) **1016148818**

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: BENJAMIN BAMONTE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-894-9549
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/17/2012
Site name: CON EDISON SERVICE BOX: 37920
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055456956

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148818
Registry ID: 110055456956
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055456956

CON EDISON SERVICE BOX: 37920 (Continued) **1016148818**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004274429
Facility Status:	Not reported
Location Address 1:	F/O 378 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004274429
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/2012
Trans1 Recv Date:	10/17/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004274429
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456399JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported

CON EDISON SERVICE BOX: 37920 (Continued) **1016148818**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A31 **CON EDISON MANHOLE 59696** **RCRA NonGen / NLR** **1014919439**
WNW **372 LAFAYETTE ST** **NJ MANIFEST** **NYP004236057**
< 1/8 **NEW YORK, NY 10012** **NY MANIFEST**
0.016 mi.
86 ft. **Site 31 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/24/2011
Facility name:	CON EDISON MANHOLE 59696
Facility address:	372 LAFAYETTE ST NEW YORK, NY 10012
EPA ID:	NYP004236057
Mailing address:	IRVING PLAZA RM 828 NEW YORK, NY 10003
Contact:	TONI-ANN FRANZONE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9450
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON MANHOLE 59696 (Continued) **1014919439**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/25/2011
Site name: CON EDISON MANHOLE 59696
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004236057
Mail Address: IRVING PLAZA RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: TONI-ANN FRANZONE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007658394JJK
EPA ID: NYP004236057
Date Shipped: 5/25/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported

CON EDISON MANHOLE 59696 (Continued) **1014919439**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2,000.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004236057
Facility Status:	Not reported
Location Address 1:	S/E/C LAFAYETTE & GREAT JONES ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTEN
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004236057
Mailing Name:	CONSOLIDATED EDISON - MH 59696
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported

CON EDISON MANHOLE 59696 (Continued) **1014919439**

Generator Ship Date:	05/25/2011
Trans1 Recv Date:	05/25/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/25/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004236057
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658394JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A32 **372 LAFAYETTE ST** **NY UST** **U004197460**
WNW **372 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10001**
0.016 mi.
86 ft. **Site 32 of 50 in cluster A**

Relative: UST:
Higher

Id/Status:	2-612028 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

Actual:
42 ft.

372 LAFAYETTE ST (Continued) **U004197460**

UTM X: 584978.24469
UTM Y: 4508971.05531
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 482149
Affiliation Type: Facility Owner
Company Name: RUSABO 368, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 7001 BRUSHHOLLOW RD
Address2: Not reported
City: WESTBURY
State: NY
Zip Code: 11590
Country Code: 001
Phone: (516) 338-8700
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2013-10-08

Site Id: 482149
Affiliation Type: Mail Contact
Company Name: GREAT JONES LAFAYETTE, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 225 WEST 35TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 631-0203 221
EMail: NS@KANOREI.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2013-10-08

Site Id: 482149
Affiliation Type: Facility Operator
Company Name: 372 LAFAYETTE ST
Contact Type: Not reported
Contact Name: NOAM SHEMEL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 631-0203 221
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2013-10-08

Site Id: 482149
Affiliation Type: Emergency Contact

372 LAFAYETTE ST (Continued) **U004197460**

Company Name:	RUSABO 368, LLC.
Contact Type:	Not reported
Contact Name:	NOAM SHEMEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 631-0203
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-05-21

Tank Info:

Tank Number:	001
Tank ID:	248335
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/05/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Number:	002
Tank ID:	248336
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/05/2013
Registered:	True

372 LAFAYETTE ST (Continued) **U004197460**

Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Number: 003
Tank ID: 248337
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/05/2013
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Number: 004
Tank ID: 248338

372 LAFAYETTE ST (Continued) **U004197460**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/05/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Number:	005
Tank ID:	248339
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/05/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

372 LAFAYETTE ST (Continued) **U004197460**

J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Number:	006
Tank ID:	248340
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/05/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Number:	007
Tank ID:	250167
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/22/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

372 LAFAYETTE ST (Continued) **U004197460**

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Number:	008
Tank ID:	250168
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/22/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Number:	009
Tank ID:	250169
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/22/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

372 LAFAYETTE ST (Continued) **U004197460**

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number:	010
Tank ID:	250170
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/22/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Number:	011
Tank ID:	250171
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/22/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

372 LAFAYETTE ST (Continued) **U004197460**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

A33 **WASTE OIL SPILL AT GREAT JONES LAFEYETTE LLC** **NY Spills** **S113819127**
WNW **372 LAFEYETTE ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.016 mi.
86 ft. **Site 33 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

SPILLS:

Facility ID:	1304085
Facility Type:	ER
Spill Number:	1304085
DER Facility ID:	439750
Site ID:	484597
DEC Region:	2
Closed Date:	2015-05-22
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2013-07-16
Investigator:	RJFENG
Referred To:	Not reported
Reported to Dept:	2013-07-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-07-16
Spill Record Last Update:	2015-05-22
Spiller Name:	RENE KAHN
Spiller Company:	GREAT JONES LAFEYETTE LLC
Spiller Address:	372 LAFEYETTE ST
Spiller Company:	999

WASTE OIL SPILL AT GREAT JONES LAFEYETTE LLC (Continued) **S113819127**

Contact Name: RENE KAHN
DEC Memo: "7/16/2013 - Feng - DEC J. Vought and J. Feng spoke to Ray Kahn of ESPL Environmental Services (212-330-7501, rkahn@espl.com). The site is under construction activities. They knew there were tanks. They found (5) 5,000-gallon tanks previously. They did more work and found (5) more tanks. These tanks are believed were used for gasoline. Gasoline related VOCs were detected in soil. No spill has been called in for the discovery of these tnaks. The site was formerly a gasoline station. This site is an E-Designated site with NYC environmental program and also a BCP project with NYCOER. The site is developed into commercial and residential use. Vapor barrier and passive SSDS to be installed underneath the building. The NYCOER approved RAWP which calls for excavation. The waste oil tank was found during the excavation and spill was called in. The excavation is 20-30 feet and endpoint will be taken. Contac information: Noam Shemel Great Jones Lafeyette LLC 225 West 35th Street New York, NY 10001 (212) 631-0203 Called NYSOER Shaminder Chawla and Hena. According to them, the entire site will be excavated to 15 feet. They have discussed this site with Bob Cozzy and Jane O'Connell before they found those tanks. Hena will send us the approve RAWP to see if DEC has any concern and need something more. NYSDEC may need to deal with the offsite issue. 7/29/2013 - conference call with Ray Kahn of ESPL, Hannah Moore and Shaminder Chawla of NYCOER. The 11 tanks were removed and the excavation was extended down to 8 feet. No endpoint samples have been collected due to the anticipated excavation for site development. The site is now 3 feet below street level. The piling is started but not completed yet. No vapor complaint have been awared of so far. DEC required further investigation, i.e. borings and endpoint samples. 7/31/2013 - conference call with Hannah Moore and Shaminder Chawla. DEC requires at least 2 soil borings in the former tank field area, register the tanks and will conduct site visit upon the reach of expected excavation depth. 8/1/2013 - sent letter requiring site investigation to Great Jones Lafayette LLC (the developer) and cc ESPL and OER. DEC requires soil boring in the west side of southern tank group and at former soil vapor SV-2 location, soil and groundwater samples to be taken. DEC also require the rest of the tanks to be registered and notification when reach the limit of the excavation. Work plan by the end of 8/2013. 10/2/2013 - reviewed Tank Closure Report, dated September 2013, by ESPL. On 7/12/2013, 5 tanks Tank 007-011, 550-gallon, were removed from the southwest portion of the site. Tank 010 and 011 were observed to have holes on bottom of the tanks. The excavation was 30x30 and 8 feet deep. On 7/17/2013, a total of 527.87 tons (manifests dated 7/17/2013 and 7/22/2013)of impacted soil was removed from the site for disposal at Clean Earth of Carteret. email Ray Kahn of ESPL 1) Section 6, the excavated area for each tank group (southwest and middle of the site) was approximately 30x30 feet and approx. 8 feet deep. Any excavation in the middle of the site? 2) How many tons of soil have been removed? 527.87 or 492 tons? While most of the soil were transported on 7/17/2013 as the manifests indicated, why there is one truck load on 7/22/2013? Is it from the same excavation? 3) When the previous found (6) 550-gallons USTs were removed other than the reported (5) 550-gallons USTs? Why not included these 6 tanks removal into this report? also required update for the required investigation work plan. 5/22/2015 - Reviewed spill history and discussed with J. Vought. Spill is closed based on: 1) All sources have been removed. (6) 550-gallon gasoline USTs were removed in March 2013. (5)

WASTE OIL SPILL AT GREAT JONES LAFEYETTE LLC (Continued) **S113819127**

550-gallon gasoline USTs were removed in July 2013, and a total of 527.87 tons of impacted soil was excavated and disposed offsite. 2) Additional soil was excavated for site development under the NYCOER approved RAWP. The excavation depth was 13 feet for foundation and a cellar. Endpoint samples were collected at the terminus of the developmental excavation. No VOCs or SVOCs excceedances. 3) Soil sampling results indicated some SVOCs compounds and metals exceedances in the soil samples collected from the top 2 feet which will be excavated and removed as developmental excavation will be advanced to 13 feet. And the soil samples collected from depth of 34-38 feet show all non-detected of VOCs and SVOCs. 4) Groundwater sampling indicated there are still minor petroleum impacts. BTEX concentration, i.e. 16 ug/L ethylbenzene and 75 ug/L xylenes were detected which do not warranted further investigation and remediation. 5) Metal compounds in soil at 13 feet, i.e. 163 mg/kg lead and 1.03 mg/kg mercury. And metal dissolved in groundwater were detected, i.e. 0.043 mg/L lead. These levels of metals in soil and groundwater are not in a level that concerns shall be raised thus no further action is required. 6) Soil vapor samples were collected also. Low level of several VOCs were detected. The new building will require the removal of the USTs and excavation of 13 feet which will remove the source of the soil vapor contamination. 7) Vapor barrier and passive SSDS were installed for the new building that would protect occupants from exposure to the residual contaminants. 8) Inclusion of remaining contamination language in the spill closure letter in case site is redeveloped. Spill Closure letter to Great Jones Lafayette LLC and ESPL. Spill is closed. "

Remarks: "during excavation a tank was found, unk amt"

All Materials:

Site ID:	484597
Operable Unit ID:	1234275
Operable Unit:	01
Material ID:	2233282
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A34 **372 LAFAYETTE STREET** **NY VCP** **S118943212**
WNW **372 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.016 mi.
86 ft. **Site 34 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

VCP NYC:

Project ID:	13CVCP073M
Project Name:	372 LAFAYETTE STREET
Project Address:	372 LAFAYETTE STREET
Borough:	MANHATTAN

VCP NYC:

Project ID:	13CVCP073M
File Name:	2012-08-15.RIR

372 LAFAYETTE STREET (Continued) **S118943212**

URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-08-15.13CVCP073M.372_Lafayette_Street.RIR.pdf

Project ID: 13CVCP073M
File Name: 2012-11-16.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-11-16.13CVCP073M.RAWP_Final.pdf

Project ID: 13CVCP073M
File Name: 2012-08-15.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-08-15.12CVCP073M.372_Lafayette_Street.FactSheet1.pdf

Project ID: 13CVCP073M
File Name: 2012-08-17.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-08-17.13CVCP073M.372_Lafayette_Street.Translated_FactSheet1.pdf

Project ID: 13CVCP073M
File Name: 2012-08-17.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-08-17.13CVCP073M.372_Lafayette_Street.Translated_Community_Protection_Statement.pdf

Project ID: 13CVCP073M
File Name: 2012-12-10.FactSheet2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-12-10.13CVCP073M.FactSheet2.pdf

Project ID: 13CVCP073M
File Name: 2012-12-11.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-12-11.13CVCP073M.372_Lafayette_Street.Translated_FactSheet2.pdf

Project ID: 13CVCP073M
File Name: 2012-11-19.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/13CVCP073M/2012-11-19.13CVCP073M.Decision_Document.pdf

---

A35 **CON EDISON SERVICE BOX: 37918** **NJ MANIFEST** **S117985997**
WNW **372 LAFAYETTE ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.016 mi.
86 ft. **Site 35 of 50 in cluster A**

Relative: NJ MANIFEST:
Higher
Actual: EPA Id: NYP004265450
42 ft. Mail Address: IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: BENJAMIN BAMONTE
Comments: Not reported
SIC Code: Not reported
County: NY061

CON EDISON SERVICE BOX: 37918 (Continued) **S117985997**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010464329JJK
EPA ID:	NYP004265450
Date Shipped:	8/28/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

A36 **CON EDISON SERVICE BOX: 37918** **RCRA NonGen / NLR** **1016143762**
WNW **372 LAFAYETTE ST FRONT OF** **FINDS** **NYP004265450**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.016 mi. **NY MANIFEST**
86 ft. **Site 36 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 37918
Facility address:	372 LAFAYETTE ST FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004265450
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/28/2012
Site name:	CON EDISON SERVICE BOX: 37918
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110064101984

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 37918 (Continued) **1016143762**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016143762
Registry ID:	110064101984
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110064101984

NY MANIFEST:

Country:	USA
EPA ID:	NYP004265450
Facility Status:	Not reported
Location Address 1:	F/O 372 LAFAYETTE ST
Code:	BP
Location Address 2:	SERV BOX 37918
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004265450
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2012
Trans1 Recv Date:	08/28/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004265450
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010464329JJK
Import Indicator:	N
Export Indicator:	N

CON EDISON SERVICE BOX: 37918 (Continued) **1016143762**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

B37 **CON EDISON** **RCRA NonGen / NLR** **1014398275**
East **38 E 4TH ST** **NY MANIFEST** **NYP004206274**
< 1/8 **NEW YORK, NY 10001**
0.018 mi.
97 ft. **Site 1 of 14 in cluster B**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/04/2010
Facility name:	CON EDISON
Facility address:	38 E 4TH ST NEW YORK, NY 10001
EPA ID:	NYP004206274
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	917-559-8971
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON (Continued) **1014398275**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004206274
Facility Status: Not reported
Location Address 1: 38 W 4TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004206274
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: THOMAS TEELING
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2010
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/04/2010
Trans1 Recv Date: 05/04/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004206274

CON EDISON (Continued) **1014398275**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001439643FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	130.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

A38 **CON EDISON SERVICE BOX 35864** **RCRA NonGen / NLR** **1015746925**
South **33 GREAT JONES ST** **NY MANIFEST** **NYP004249254**
< 1/8 **NEW YORK, NY 10012**
0.019 mi.
100 ft. **Site 37 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/05/2012
Facility name:	CON EDISON SERVICE BOX 35864
Facility address:	33 GREAT JONES ST
	NEW YORK, NY 10012
EPA ID:	NYP004249254
Mailing address:	4 IRVING PL, RM 828
	NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported
	Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549

CON EDISON SERVICE BOX 35864 (Continued) **1015746925**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/06/2012
Site name: CON EDISON SERVICE BOX 35864
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004249254
Facility Status: Not reported
Location Address 1: F/O GREAT JONES ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004249254
Mailing Name: CONSOLIDATED EDISON - SERV BOX 35864
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported

CON EDISON SERVICE BOX 35864 (Continued) **1015746925**

Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2012
Trans1 Recv Date:	03/06/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/08/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004249254
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007019393JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A39 **CON EDISON SERVICE BOX 35864** **NJ MANIFEST** **S117985197**
South **33 GREAT JONES ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.019 mi.
100 ft. **Site 38 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004249254
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007019393JJK
EPA ID:	NYP004249254
Date Shipped:	3/6/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX 35864 (Continued) **S117985197**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 500.00 Pounds

A40 **POST BROS SERVICE STATION INC** **EDR Hist Auto** **1020373656**
SW **363-371 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.020 mi.
103 ft. **Site 39 of 50 in cluster A**

Relative: EDR Hist Auto
Higher

Actual: **42 ft.**

Year:	Name:	Type:
1980	POST BROS SERVICE STATION INC	Gasoline Service Stations
1982	POST BROS SERVICE STATION INC	Gasoline Service Stations
1983	POST BROS SERVICE STATION INC	Gasoline Service Stations
1985	POST BROS SERVICE STATION INC	Gasoline Service Stations
1986	POST BROS SERVICE STATION INC	Gasoline Service Stations

A41 **SMOOTH TOOTH ENTERPRISES INC** **EDR Hist Cleaner** **1020089506**
SSE **41 GREAT JONES ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.020 mi.
105 ft. **Site 40 of 50 in cluster A**

Relative: EDR Hist Cleaner
Higher

Actual: **42 ft.**

Year:	Name:	Type:
1969	SMOOTH TOOTH ENTERPRISES INC	Drycleaning Plants, Except Rugs
1970	SMOOTH TOOTH ENTERPRISES INC	Drycleaning Plants, Except Rugs

---

A42 **POST BROS SERVICE STATION** **EDR Hist Auto** **1021626026**
SW **361 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.022 mi.
114 ft. **Site 41 of 50 in cluster A**

Relative: EDR Hist Auto
Higher

Actual: **42 ft.**

Year:	Name:	Type:
1969	POST BROS SERVICE STATION INC	Gasoline Service Stations
1969	POST BROS SERVICE STATION	Gasoline Service Stations
1970	POST BROS SERVICE STATION INC	Gasoline Service Stations
1971	POST BROS SERVICE STATION INC	Gasoline Service Stations

POST BROS SERVICE STATION (Continued) **1021626026**

1972	POST BROS SERVICE STATION INC	Gasoline Service Stations
1973	POST BROS SERVICE STATION INC	Gasoline Service Stations
1974	POST BROS SERVICE STATION INC	Gasoline Service Stations
1975	POST BROS SERVICE STATION INC	Gasoline Service Stations
1976	POST BROS SERVICE STATION INC	Gasoline Service Stations

B43 **43 GREAT JONES STREET** **NY AST** **A100139031**
SSE **43 GREAT JONES STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.022 mi.
117 ft. **Site 2 of 14 in cluster B**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603940
Program Type:	PBS
UTM X:	585108.30901
UTM Y:	4508919.07222
Expiration Date:	02/24/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	25833
Affiliation Type:	Facility Owner
Company Name:	43 GREAT JONES STREET OWNERS CORP.
Contact Type:	PRESIDENT
Contact Name:	PETER HAMILTON
Address1:	43 GREAT JONES ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(917) 754-6236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-02-13

Site Id:	25833
Affiliation Type:	Mail Contact
Company Name:	43 GREAT JONES ST. OWNERS CORP.
Contact Type:	Not reported
Contact Name:	PETER HAMILTON, PRESIDENT
Address1:	43 GREAT JONES STREET
Address2:	#6
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 505-7286
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-02-13

43 GREAT JONES STREET (Continued) **A100139031**

Site Id:	25833
Affiliation Type:	Facility Operator
Company Name:	43 GREAT JONES STREET
Contact Type:	Not reported
Contact Name:	DREW SHIFLETT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-9552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25833
Affiliation Type:	Emergency Contact
Company Name:	43 GREAT JONES STREET OWNERS CORP.
Contact Type:	Not reported
Contact Name:	PETER HAMILTON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 505-7286
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-02-23

Tank Info:

Tank Number:	001
Tank Id:	56101
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location: 1

43 GREAT JONES STREET (Continued) **A100139031**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/15/1985
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

B44 **LOFT BUILDING** **NY Spills** **S107783196**
SSE **43 GREAT JONES STREET** **N/A**
< 1/8 **NEW YORK, NY**
0.022 mi.
117 ft. **Site 3 of 14 in cluster B**

Relative: **Higher**
Actual: **42 ft.**

SPILLS:

Facility ID:	0613089
Facility Type:	ER
Spill Number:	0613089
DER Facility ID:	327602
Site ID:	378055
DEC Region:	2
Closed Date:	2007-03-06
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2007-03-06
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-03-06
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-03-06
Spill Record Last Update:	2007-03-06
Spiller Name:	RICH TURCHIANO
Spiller Company:	LOFT BUILDING
Spiller Address:	43 GREAT JONES STREET
Spiller Company:	001
Contact Name:	RICH TURCHIANO
DEC Memo:	"Sangesland spoke to building owner Peter Hamilton (917-754-6236) He said there was a small spill in the basement that was cleaned up with speedie dry. Madison oil will come back in a couple of days to take away the used speedie dry. They have also hired a plumber to trace the lines to look for the leak."
Remarks:	"PIPING ON TANK SEEMS TO BE LEAKING: THEY WILL GO INVESTIGATE AND GET

LOFT BUILDING (Continued) **S107783196**

BACK WITH UPDATES:"

All Materials:

Site ID:	378055
Operable Unit ID:	1135569
Operable Unit:	01
Material ID:	2125484
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A45 **41 GREAT JONES HOLDINGS LLC** **NY AST** **A100194256**
SSE **41 GREAT JONES STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.022 mi.
118 ft. **Site 42 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607239
Program Type:	PBS
UTM X:	585057.55388
UTM Y:	4508909.31003
Expiration Date:	12/03/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29092
Affiliation Type:	Mail Contact
Company Name:	BLUMENFELD DEVELOPMENT GROUP
Contact Type:	Not reported
Contact Name:	ROBERT ANDERSON
Address1:	300 ROBBINS LANE
Address2:	Not reported
City:	SYOSSET
State:	NY
Zip Code:	11791
Country Code:	001
Phone:	(516) 921-0800
EMail:	REANDERSON@BDG.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-28

Site Id:	29092
Affiliation Type:	Facility Operator
Company Name:	41 GREAT JONES HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	ROBERT ANDERSON
Address1:	Not reported
Address2:	Not reported

41 GREAT JONES HOLDINGS LLC (Continued) **A100194256**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 624-1983
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-28

Site Id:	29092
Affiliation Type:	Emergency Contact
Company Name:	41 GREAT JONES HOLDINGS, LLC
Contact Type:	Not reported
Contact Name:	ROBERT ANDERSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 624-1983
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-28

Site Id:	29092
Affiliation Type:	Facility Owner
Company Name:	41 GREAT JONES HOLDINGS, LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	ROBERT ANDERSON
Address1:	300 ROBBINS LANE
Address2:	Not reported
City:	SYOSSET
State:	NY
Zip Code:	11791
Country Code:	001
Phone:	(516) 921-0800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-09-28

Tank Info:

Tank Number:	001
Tank Id:	62597
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser

41 GREAT JONES HOLDINGS LLC (Continued) **A100194256**

C03 - Pipe Location - Aboveground/Underground Combination
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/16/2000
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

B46 **48 TENANTS CORP** **NY AST** **U003392821**
SE **48 GREAT JONES STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.023 mi.
122 ft. **Site 4 of 14 in cluster B**

Relative: **Higher**
Actual: **42 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-247596
Program Type:	PBS
UTM X:	585095.03794
UTM Y:	4508916.46104
Expiration Date:	10/23/2017
Site Type:	Private Residence

Affiliation Records:

Site Id:	9741
Affiliation Type:	Facility Owner
Company Name:	48 TENANTS CORP
Contact Type:	MGR
Contact Name:	DIANE HUNT
Address1:	48 GREAT JONES STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 260-5420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-10-09

Site Id:	9741

48 TENANTS CORP (Continued) **U003392821**

Affiliation Type:	Mail Contact
Company Name:	48 TENANTS CORP
Contact Type:	Not reported
Contact Name:	DIANE HUNT
Address1:	% ANDREWS BUILDING CORP.
Address2:	666 BROADWAY, 12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	DHUNT@ANDREWSBC.COM
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-10-09

Site Id:	9741
Affiliation Type:	Facility Operator
Company Name:	48 TENANTS CORP
Contact Type:	Not reported
Contact Name:	48 TENANTS CORP CO-OP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-10-09

Site Id:	9741
Affiliation Type:	Emergency Contact
Company Name:	48 TENANTS CORP
Contact Type:	Not reported
Contact Name:	DIANE HUNT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-10-09

Tank Info:

Tank Number:	001
Tank Id:	25479
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

48 TENANTS CORP (Continued) **U003392821**

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H99 - Tank Leak Detection - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/25/1977
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

B47 **APARTMENT BLDG TTF** **NY LTANKS** **S111836467**
SE **48 GREAT JONES ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.023 mi.
122 ft. **Site 5 of 14 in cluster B**

Relative: **Higher**
Actual: **42 ft.**

LTANKS:

Facility ID:	1200036
Site ID:	462646
Closed Date:	2013-01-29
Spill Number:	1200036
Spill Date:	2011-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2012-04-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-03

APARTMENT BLDG TTF (Continued) **S111836467**

Spill Record Last Update:	2013-01-29
Spiller Name:	MARK SALAMACK
Spiller Company:	APARTMENT BLDG
Spiller Address:	48 GREAT JONES ST
Spiller County:	999
Spiller Contact:	MARK SALAMACK
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	417055
DEC Memo:	"Sangesland spoke to Mark at PTC. Mark said that PTC was a sub contractor. PTC tested the tank - it failed. Demar Plumbing (212 614-9717) replaced a vent line thru the wall w/Black iron pipe on 4/5/12. PTC tested again - it failed. Demar replaced the fill pipe (direct fill thru wall - no buried) on 4/26/12. PTC tested again afternoon of 4/26/12 - Passed. No contamination found during repairs - spill closed. "
Remarks:	"Failed test. Unknown further action at this point."

All Materials:

Site ID:	462646
Operable Unit ID:	1212737
Operable Unit:	01
Material ID:	2210605
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A48 **KALODOP PARK CORP** **NY UST** **U004047312**
NE **27 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.026 mi.
135 ft. **Site 43 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

UST:

Id/Status:	2-609136 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585053.77791
UTM Y:	4509024.23164
Site Type:	Other

Affiliation Records:

Site Id:	30982
Affiliation Type:	Facility Owner
Company Name:	40 PARK IT MANAGEMENT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	250 W 26TH ST
Address2:	Not reported
City:	NEW YORK

KALODOP PARK CORP (Continued) **U004047312**

State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 929-9404
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 30982
Affiliation Type: Mail Contact
Company Name: PARK IT MANAGEMENT
Contact Type: Not reported
Contact Name: GARY SPINDLER
Address1: 250 WEST 26TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 929-9404
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 30982
Affiliation Type: Facility Operator
Company Name: KALODOP PARK CORP
Contact Type: Not reported
Contact Name: MIKE IBRAHIM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 254-1263
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 30982
Affiliation Type: Emergency Contact
Company Name: 40 PARK IT MANAGEMENT
Contact Type: Not reported
Contact Name: GARY SPINDLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 929-9404
EMail: Not reported
Fax Number: Not reported

KALODOP PARK CORP (Continued) **U004047312**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 66536
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 002
Tank ID: 66537
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

KALODOP PARK CORP (Continued) **U004047312**

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	003
Tank ID:	66538
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

A49 **CON EDISON - GAS MAIN NONE** **NJ MANIFEST** **S120665791**
North **E 4TH ST AND LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.027 mi.
141 ft. **Site 44 of 50 in cluster A**

Relative: **Higher**
Actual: **42 ft.**

NJ MANIFEST:

EPA Id:	NYP004194312
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported

CON EDISON - GAS MAIN NONE (Continued) **S120665791**

County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001085788GBF
EPA ID:	NYP004194312
Date Shipped:	09/16/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/16/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/25/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	1590 K

A50
North
< 1/8
0.027 mi.
141 ft.

CON EDISON SERVICE BOX 37926
E 4TH ST & LAFAYETTE ST
NEW YORK, NY 10003

Site 45 of 50 in cluster A

NJ MANIFEST **S120665841**
N/A

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004223681
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	SEAN FERNANDEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655696JJK
EPA ID:	NYP004223681
Date Shipped:	1/11/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX 37926 (Continued) **S120665841**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2,500.00 Pounds

A51 **E 4TH ST & LAFAYETTE** **NY Spills** **S102143080**
North **E 4TH ST & LAFAYETTE** **N/A**
< 1/8 **NYC, NY**
0.027 mi.
141 ft. **Site 46 of 50 in cluster A**

Relative: **Higher**
Actual: **42 ft.**

SPILLS:

Facility ID:	9203983
Facility Type:	ER
Spill Number:	9203983
DER Facility ID:	126906
Site ID:	149163
DEC Region:	2
Closed Date:	1992-07-07
Spill Cause:	Unknown
Spill Class:	B4
SWIS:	3101
Spill Date:	1992-07-06
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1992-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	1992-07-07
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-08
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"SANITATION CLEANING."

All Materials:

Site ID:	149163

E 4TH ST & LAFAYETTE (Continued) **S102143080**

Operable Unit ID:	971379
Operable Unit:	01
Material ID:	411750
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A52 **CON EDISON SERVICE BOX 37926** **RCRA NonGen / NLR** **1014918749**
North **EAST 4 ST & LAFAYETTE ST** **NYP004223681**
< 1/8 **NEW YORK, NY 10003**
0.027 mi.
141 ft. **Site 47 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/06/2012
Facility name:	CON EDISON SERVICE BOX 37926
Site name:	CON EDISON - SERVICE BOX 37926
Facility address:	EAST 4 ST & LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004223681
Mailing address:	IRVING PLACE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE, 15TH FL NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/11/2011
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE, 15TH FL NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported

CON EDISON SERVICE BOX 37926 (Continued) **1014918749**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/11/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 02/10/2011
Site name: CON EDISON SERVICE BOX 37926
Classification: Not a generator, verified

Date form received by agency: 01/11/2011
Site name: CON EDISON SERVICE BOX 37926
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

A53 **CON EDISON - GAS MAIN NONE** **RCRA-LQG** **1014397114**
North **E 4TH ST AND LAFAYETTE ST** **NY MANIFEST** **NYP004194312**
< 1/8 **NEW YORK, NY 10003**
0.027 mi.
141 ft. **Site 48 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA-LQG:
Date form received by agency: 03/23/2010
Facility name: CON EDISON - GAS MAIN NONE
Facility address: E 4TH ST AND LAFAYETTE ST
NEW YORK, NY 10003
EPA ID: NYP004194312
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-2808

CON EDISON - GAS MAIN NONE (Continued) **1014397114**

Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/15/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/15/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

CON EDISON - GAS MAIN NONE (Continued) **1014397114**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D018
. Waste name: BENZENE

. Waste code: B007
. Waste name: B007

Historical Generators:
Date form received by agency: 09/15/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004223681
Facility Status: Not reported
Location Address 1: EAST 4 ST & LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004223681
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602757

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/11/2011
Trans1 Recv Date: 01/11/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/14/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004223681

CON EDISON - GAS MAIN NONE (Continued) **1014397114**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655696JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYP004194312
Facility Status:	Not reported
Location Address 1:	E 4TH ST AND LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004194312
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON - GAS MAIN NONE (Continued) **1014397114**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2009
Trans1 Recv Date:	09/16/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004194312
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001085788GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2618.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON - GAS MAIN NONE (Continued) **1014397114**

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

A54 **CON EDISION - MH37925** **RCRA NonGen / NLR** **1007208589**
North **EAST 4TH STREET AND LAFAYETTE** **NY MANIFEST** **NYP004093316**
< 1/8 **NEW YORK, NY 10003**
0.028 mi.
146 ft. **Site 49 of 50 in cluster A**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/02/2002
Facility name:	CON EDISION - MH37925
Facility address:	EAST 4TH STREET AND LAFAYETTE NEW YORK, NY 10003
EPA ID:	NYP004093316
Mailing address:	IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/01/2002
Site name:	CON EDISION - MH37925
Classification:	Not a generator, verified
Date form received by agency:	05/31/2002
Site name:	CON EDISION - MH37925
Classification:	Large Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

CON EDISION - MH37925 (Continued) **1007208589**

Country:	USA
EPA ID:	NYP004093316
Facility Status:	Not reported
Location Address 1:	EAST 4TH STREET AND LAFAYETTE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004093316
Mailing Name:	CON EDISION - MH37925
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

B55 **CON EDISON SERVICE BOX: 35866** **RCRA NonGen / NLR** **1016970932**
SSE **47 GREAT JONES ST** **NY MANIFEST** **NYP004446639**
< 1/8 **NEW YORK, NY 10012**
0.029 mi.
151 ft. **Site 6 of 14 in cluster B**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/20/2014
Facility name:	CON EDISON SERVICE BOX: 35866
Facility address:	47 GREAT JONES ST NEW YORK, NY 10012
EPA ID:	NYP004446639
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

CON EDISON SERVICE BOX: 35866 (Continued) **1016970932**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/20/2014
Site name:	CON EDISON SERVICE BOX: 35866
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004446639
Facility Status:	Not reported
Location Address 1:	47 GREAT JONES ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004446639
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2014
Trans1 Recv Date:	02/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004446639
Trans1 EPA ID:	Not reported

CON EDISON SERVICE BOX: 35866 (Continued) **1016970932**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002330258GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

A56 **217199; 6 GREAT JONES ST** **NY Spills** **S110307210**
WNW **6 GREAT JONES ST** **N/A**
< 1/8 **NEW YORK, NY**
0.030 mi.
157 ft. **Site 50 of 50 in cluster A**

Relative: **Lower**
Actual: **41 ft.**

SPILLS:

Facility ID:	0914270
Facility Type:	ER
Spill Number:	0914270
DER Facility ID:	387019
Site ID:	433005
DEC Region:	2
Closed Date:	2009-07-28
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	2009-06-17
Investigator:	DMPOKRZY
Referred To:	Not reported

217199; 6 GREAT JONES ST (Continued) **S110307210**

Reported to Dept:	2009-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-04-16
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	433005
Operable Unit ID:	1183916
Operable Unit:	01
Material ID:	2178143
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

B57 **MERCHANTS HOUSE** **RCRA-CESQG** **1010328556**
ENE **29 E 4TH ST** **NY MANIFEST** **NYR000143768**
< 1/8 **NEW YORK, NY 10003**
0.034 mi.
179 ft. **Site 7 of 14 in cluster B**

Relative:
Higher

Actual:
42 ft.

RCRA-CESQG:

Date form received by agency:	01/04/2007
Facility name:	MERCHANTS HOUSE
Facility address:	29 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYR000143768
Mailing address:	BRIDGEWATER ST BROOKLYN, NY 11222
Contact:	BOGDAN SZCZUREK
Contact address:	BRIDGEWATER ST BROOKLYN, NY 11222
Contact country:	US
Contact telephone:	718-599-3718
Contact email:	RMCBOB@EARTHLINK.NET
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator

MERCHANTS HOUSE (Continued) **1010328556**

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYC DEPT OF PARKS & RECREATION
Owner/operator address:	OLMSTED CENTER CORONA PARK
	FLUSHING, NY 11368
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	12/28/2006
Owner/Op end date:	Not reported

Owner/operator name:	REGIONAL MANAGEMENT & CONSULTING INC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/28/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

MERCHANTS HOUSE (Continued) **1010328556**

Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 01/03/2007
Site name: MERCHANTS HOUSE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/03/2007
Site name: MERCHANTS HOUSE
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000143768
Facility Status: Not reported
Location Address 1: 29 E 4TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000143768
Mailing Name: MERCHANTS HOUSE
Mailing Contact: MERCHANTS HOUSE
Mailing Address 1: 29 E 4TH ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187606761

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2007
Trans1 State ID: NYR000081570
Trans2 State ID: NYD049178296
Generator Ship Date: 01/24/2007
Trans1 Recv Date: 01/24/2007
Trans2 Recv Date: 02/16/2007
TSD Site Recv Date: 02/27/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143768

MERCHANTS HOUSE (Continued) **1010328556**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX480000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	000078452JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	440
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

B58 **LOT 67,TAXBLOCK 544** **NY RES DECL** **S116290996**
ENE **37 EAST 4 STREET** **N/A**
< 1/8 **MANHATTAN, NY 10003**
0.035 mi.
187 ft. **Site 8 of 14 in cluster B**

Relative: **Higher**
Actual: **42 ft.**

ENV RES DECL:

Borough:	MN
Tax Block:	544
Tax Lot:	67
Reference Number:	R-121
Date Recorded:	6/25/2007
Satisfaction Date:	Not reported
CEQR Number:	07DCP049M
Application Number:	060525 ZSM
Recording Reference Number:	2007000325395
Type:	Hazmat
Lot Remediation Date:	Not reported

B59 **OZY MANDIUS REALTY** **NY Spills** **S109373258**
ESE **348 BOWERY ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.038 mi.
200 ft. **Site 9 of 14 in cluster B**

Relative:
Higher

Actual:
42 ft.

SPILLS:

Facility ID:	0808740
Facility Type:	ER
Spill Number:	0808740
DER Facility ID:	355410
Site ID:	406147
DEC Region:	2
Closed Date:	2013-08-08
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2008-11-03
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2008-11-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-11-03
Spill Record Last Update:	2013-08-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ROCKY WENSKUS
DEC Memo:	"contact owner: Anthony Morano=- 212-645-9545 6 West 14th St. 2nd Floor, Ny, NY 10011 05-19-2010- DECPiper sent csl. DECPiperreceived and reviewed UST closure report. Based on work to date, this spill is closed. See edocs if warranted. "
Remarks:	"CALLER STATES THAT THEY WERE DOING SOIL BORING AND FOUND SOIL CONTAMINATION. CLEAN UP IS PENDING."

All Materials:

Site ID:	406147
Operable Unit ID:	1162754
Operable Unit:	01
Material ID:	2154034
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

B60
ESE
< 1/8
0.039 mi.
206 ft.

INTERSECTION
BOWERY / 3RD ST
MANHATTAN, NY

Site 10 of 14 in cluster B

NY Spills **S106471409**
N/A

Relative:
Lower

Actual:
41 ft.

SPILLS:

Facility ID:	0404425
Facility Type:	ER
Spill Number:	0404425
DER Facility ID:	216204
Site ID:	265321
DEC Region:	2
Closed Date:	2004-08-25
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-07-24
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-07-24
CID:	72
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-24
Spill Record Last Update:	2004-08-25
Spiller Name:	DOREEN BOATSWAIN
Spiller Company:	NYC TRANSIT BUS 1004
Spiller Address:	370 JAY ST RM 819
Spiller Company:	001
Contact Name:	DOREEN BOATSWAIN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Spill from bus. Most of the product entered the sewer. DEP was not notified."
Remarks:	"Ruptured hose caused unknown amount of antifreeze to spill onto roadway, from transit bus. Some antifreeze also spilled into sewer."

All Materials:

Site ID:	265321
Operable Unit ID:	887347
Operable Unit:	01
Material ID:	488422
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

C61 **20 BOND ST. CR. LAFAYETTE** **NY Spills** **S102146951**
SW **20 BOND ST.CR. LAFAYETTE** **N/A**
< 1/8 **MANHATTAN, NY**
0.042 mi.
224 ft. **Site 1 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

SPILLS:

Facility ID:	9306682
Facility Type:	ER
Spill Number:	9306682
DER Facility ID:	254265
Site ID:	315381
DEC Region:	2
Closed Date:	1993-09-03
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	1993-08-31
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1993-08-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	1993-09-03
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-09-01
Spill Record Last Update:	1998-02-11
Spiller Name:	Not reported
Spiller Company:	SUSPECT GAS STA.
Spiller Address:	GREAT JONES & LAFAYETTE S
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"ODOR ONGOING FOR ~2 DAYS REFERRED NOTIFIER TO CONTACT DEP COMPLAINT LINE AND DEPT OF PUBLIC HEALTH - NOTIFIER CALL BACK - CAOMPLAIN ABOUT GASOLINE ODOR IN BASEMENT, NOTIFIED NY FD & DEP.TOMASELLO RESP"

All Materials:

Site ID:	315381
Operable Unit ID:	987935
Operable Unit:	01
Material ID:	396533
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

C62 **20 BOND STREET** **NY Spills** **S102148127**
SW **20 BOND STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.042 mi.
224 ft. **Site 2 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

SPILLS:

Facility ID:	9400898
Facility Type:	ER
Spill Number:	9400898
DER Facility ID:	247516
Site ID:	306475
DEC Region:	2
Closed Date:	1994-06-19
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	1994-04-19
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1994-04-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-02
Spill Record Last Update:	1998-02-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"GAS STA. BEHIND STUDIO- SEAPAGE OF FUMES COME IN THROUGH BASEMENT. CALL BACK WANTED MARK TIBBEY."

All Materials:

Site ID:	306475
Operable Unit ID:	994615
Operable Unit:	01
Material ID:	384670
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D63 **VICTOR TRANSMISSIONS** **EDR Hist Auto** **1021562260**
NNE **393 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.042 mi.
224 ft. **Site 1 of 7 in cluster D**

Relative: EDR Hist Auto
Higher

Actual: Year: Name: Type:
42 ft. 2002 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops
2003 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops
2004 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops
2005 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops
2006 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops
2007 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops
2008 VICTOR TRANSMISSIONS Automotive Transmission Repair Shops

---

B64 **SUPERIOR GULF STATION** **EDR Hist Auto** **1021714908**
ESE **360 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.043 mi.
228 ft. **Site 11 of 14 in cluster B**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
41 ft. 1969 SUPERIOR GULF STATION Gasoline Service Stations
1970 SUPERIOR GULF STATION Gasoline Service Stations
1971 SUPERIOR GULF STATION Gasoline Service Stations
1972 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1973 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1974 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1975 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1976 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1977 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1978 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1979 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1980 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1982 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1983 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1985 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1986 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1987 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations
1988 CRAFTSMAN SERVICE CENTER INC Gasoline Service Stations

E65 **SILK BUILDING CONDOMINIUM** **NY AST** **U004077678**
NNW **14 E 4TH ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.045 mi.
236 ft. **Site 1 of 23 in cluster E**

Relative: AST:
Lower

Actual:
41 ft.

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-319465
Program Type:	PBS
UTM X:	585003.88984

SILK BUILDING CONDOMINIUM (Continued) **U004077678**

UTM Y: 4509075.74337
Expiration Date: 01/07/1993
Site Type: Unknown

Affiliation Records:

Site Id: 14777
Affiliation Type: Facility Owner
Company Name: SILK BUILDING CONDOMINIUM
Contact Type: Not reported
Contact Name: Not reported
Address1: %CASDALE RLTY/80 EAST 11TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 705-4600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 14777
Affiliation Type: Mail Contact
Company Name: SILK BUILDING CONDOMINIUM
Contact Type: Not reported
Contact Name: Not reported
Address1: %CASDALE RLTY/80 EAST 11TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 705-4600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 14777
Affiliation Type: Facility Operator
Company Name: SILK BUILDING CONDOMINIUM
Contact Type: Not reported
Contact Name: FELIX VOSQUEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 777-6035
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 14777
Affiliation Type: Emergency Contact

SILK BUILDING CONDOMINIUM (Continued) **U004077678**

Company Name:	SILK BUILDING CONDOMINIUM
Contact Type:	Not reported
Contact Name:	CASDALE REALTY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 705-4600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	26141
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

C66 **FORMER PENSKE** **NY Spills** **S106382647**
South **40 BOND STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.046 mi.
242 ft. **Site 3 of 28 in cluster C**

Relative: **Higher**

Actual: **43 ft.**

SPILLS:

Facility ID:	0330066
Facility Type:	ER
Spill Number:	0330066
DER Facility ID:	141051
Site ID:	167408
DEC Region:	2
Closed Date:	2008-09-18
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	1994-06-28
Investigator:	skcarlso
Referred To:	NFA
Reported to Dept:	2004-02-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-11
Spill Record Last Update:	2008-09-18
Spiller Name:	RICHARD SAUT
Spiller Company:	PENSKE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RICHARD SAUT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per ROmmel. 10/14/04 Reassigned from Rommel to Sun. 10/22/04 Joe Sun called Penske's Environmental Engineer (Richard Saut) today and asked if they have ever submitted the Tank Closure Assessment Report for the seven (7)550-gallon underground storage tanks removed in 1994. He will check their record and get back to me next Monday. 10/28/04 Sun sent a letter to Richard Saut of Penske (previous owner) and two current owners, Michael Bogin of 23 BOnd Strret, and Ira Drukier of 40 Bond Strret, requiring them to submit the following documents by December 19, 2004: 1)Complete delineation of soil and groundwater contamination, 2) Investigation summary report, including a detailed description of a vapor mitigation efforts used in the construction of the residence including the installation of vapor barriers and/or sub-foundation venting systems, 3)Remedial action plan and Operation and Monitoring Plan (OMMP) and Surrounding property sketch. 11/12/04 Sun sent a letter to both Richard Saut of Penske and Michael bogin of current owner's Attorney and informed them that the Department approved that groundwater samples are not required for the property located at 23 Bond Street, Manhattan, NY based on the following subsurface investigations: 1)Tank Excavation Assessment by Handex,

FORMER PENSKE (Continued) **S106382647**

dated 11/18/03, and 3)Environmental Review by Environmental Compliance Inc., dated 12/24/03. 1/4/05 File Update by Sun: Since the concentrations of BTEX and Base Neutrals of soil samples taken from 23 Bond Street are all below NYS Recommended Soil Cleanup Objectives for Gasoline Contaminated Soils (TAGM 4046), the spill is now only applied to 40 Bond Strret. 10/05/05-File Update by Sun: On 10/05/05, Sun sent a letter to Joel Landes of Langan, the consultant for the property owner informing him that the New York State Department of Environmental Conservation (the Department) has received the Revised Phase II Site Investigation Report dated September 2, 2005 for this site. The Department has reviewed the report and contamination has been delineated to the extent possible. The Department requested that a Remedial Action Plan be submitted by October 31 2005 for review and approval. (Sun) 10/18/2005: Project reassigned from Sun to Andersen. 10/09/2005: RAP reviewed and approved. Recommended additions included 1) DER-10 method of soil sampling 2) 3 months of indoor air sampling after construction of the building. (S.Andersen) 1/27/06: Received a phone message from Joel Landes on Langan stating that excavation and implementation of the RAP has begun. The Project Manager of the project is John Gavras, phone: 212-479-5406. 2/27/06: Received a phone call from John Gavres. Will send excavation report and electronic copy of RAP. His contact info is as follows: John M. Gavras, PG, CPG PROJECT MANAGER Direct: 212.479.5406 Cell: 917.968.6779 LANGAN ENGINEERING & ENVIRONMENTAL SERVICES Tel: 212.479.5400 Fax: 212.479.5444 21 Penn Plaza 360 West 31st Street, 8th Floor New York, NY 10001-27278 www.langan.com 6/1/06: Left a voice message for John Gavres to followup on status of excavation. 6/2/06: Received voice message from Jamie Barr (212-479-5449). Excavation is nearly completed. 16 endpoint samples were taken and a report is in preparation. The vapor barrier was installed. 8/9/06: Left a message with Jamie Barr to followup on status of remediation report. 8/10/06: Received phone call from Jamie Barr. Report is in preparation and will be submitted in one months time. 9/19/06: Left voice message with Jamie Barr to followup on status of excavation report. 9/21/06: Spoke to Jamie Barr. They are waiting for sources of clean topsoil. Report will be finalized with topsoil manifests when filling with topsoil is completed. 10/30/06: Left voice message with Jamie Barr to followup on the status of the remediation report. 11/13/06: Left voice message with Jamie Barr to followup on the status of the remediation report. 11/27/06: Spoke to Jamie Barr. They are still waiting for clean fill at the site. Report cannot be completed until fill is received. Construction delays are delaying project completion. They hope to have the project completed by the end of the year. 1/22/07: Spoke to Jamie Barr. Report preparation delayed waiting for certain aspects of construction to be completed. 3/1/07: Left message for Jamie Barr to followup on report preparation. 3/27/07: Left voice message for Jamie Barr to followup on report preparation. 4/5/07: Left voice message for Jamie Barr to followup on overdue remedial action report. 4/5/07: Spoke to Jamie Barr. Report expected in two weeks. 5/10/07: left message for jamie barr to followup on RAR 5/21/07: spoke to jamie barr - report will be submitted next week, lead exceedance? 6/12/07: Emailed Jamie Barr to followup on RAR. (jbarr@langan.com) Received email from Jamie Barr, report will be submitted in 1.5 weeks. 7/30/07: Emailed Jamie Barr to followup on RAR submission. 8/7/07: Received email from Jamie Barr, RAR is in preparation. 9/12/07: Emailed Jamie Barr to followup on RAR submittal. 9/14/07: Received email from Jamie Barr. Report will be

FORMER PENSKE (Continued) **S106382647**

submitted next week. 9/24/07: Received FER. 10/9/07: Mercury and sVOC remained after excavation and redevelopment. An active SSDS was installed. Sent letter indicating a Site Management Plan is required. Letter sent via email and hard copy. 10/10/07: Spoke to Jamie Barr. A site management plan will be submitted. 4/9/08 - Carlson: Left voice message for Jamie Barr. The SMP is overdue. 4/24/08 - Carlson: Received phone message from Jamie Barr. 4/28/08 - Carlson: Left voice message for jamie Barr. Need to schedule a phone conversation to discuss SMP. Spoke to Jamie Barr. An SMP will be submitted. 7/23/08 - Carlson: Sent letter to Jamie Barr requiring submittal of SMP by 8/6/08. 7/28/08 - Carlson: Received phone message from John Gavras. He will be handling SMP. 7/29/08 - Carlson: Spoke to John Gavras. SMP submittal date extended to 8/13/08. 9/18/08 - Carlson: Reviewed SMP. Annual reports will not be required for this site. NFA required. Issued letter approving SMP and indicating NFA is required. A proposal must be submitted to the Department to shutdown the SSDS at the site."

Remarks: "SOIL CONTAMINATION DISCOVERED DURING TANK REMOVAL. NEEDS GROUNDWATER INVESTIGATION."

All Materials:

Site ID:	167408
Operable Unit ID:	880630
Operable Unit:	01
Material ID:	496571
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	167408
Operable Unit ID:	880630
Operable Unit:	01
Material ID:	496572
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C67 **3 GREAT JONES TENANTS CORP.** **NY AST** **A100175403**
West **3 GREAT JONES STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.046 mi.
243 ft. **Site 4 of 28 in cluster C**

Relative: AST:
Lower

Region:	STATE
DEC Region:	2
Site Status:	Active

Actual:
41 ft.

3 GREAT JONES TENANTS CORP. (Continued) **A100175403**

Facility Id: 2-605096
Program Type: PBS
UTM X: 584965.57927
UTM Y: 4509006.36133
Expiration Date: 02/01/2021
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 26965
Affiliation Type: Facility Owner
Company Name: 3 GREAT JONES TENANTS CORP.
Contact Type: AGENT
Contact Name: ROBERT WILSON
Address1: 3 GREAT JONES STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: LSZINOMA
Date Last Modified: 2016-02-01

Site Id: 26965
Affiliation Type: Mail Contact
Company Name: ANDREWS BUILDING CORPORATION
Contact Type: Not reported
Contact Name: ANDREWS ORGANIZATION
Address1: 666 BROADWAY
Address2: 12TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: LSZINOMA
Date Last Modified: 2016-02-01

Site Id: 26965
Affiliation Type: Facility Operator
Company Name: 3 GREAT JONES TENANTS CORP.
Contact Type: Not reported
Contact Name: ROBERT WILSON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

3 GREAT JONES TENANTS CORP. (Continued) **A100175403**

Site Id:	26965
Affiliation Type:	Emergency Contact
Company Name:	3 GREAT JONES TENANTS CORP.
Contact Type:	Not reported
Contact Name:	EUGENE ANDREWS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	59428
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1976
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LSZINOMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

C68 **RESIDENTIAL BLDG** **NY Spills** **S102662863**
SSW **24 BOND ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.046 mi.
243 ft. **Site 5 of 28 in cluster C**

Relative: Higher

Actual: 42 ft.

SPILLS:

Facility ID:	9613681
Facility Type:	ER
Spill Number:	9613681
DER Facility ID:	114518
Site ID:	133060
DEC Region:	2
Closed Date:	1997-02-21
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	3101
Spill Date:	1997-02-21
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1997-02-21
CID:	252
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-21
Spill Record Last Update:	1997-02-24
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	GEORGE WACHTEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"CALLER DISCOVERED TWO BAGS OF WHAT APPEARS TO BE ASBESTOS LEFT ON SIDE WALK IFO RESIDENTAIL BLDG-CALLER MOVED THEM CLOSER TO BLDG-REQ CALL BACK FROM DEC REP**********"

All Materials:

Site ID:	133060
Operable Unit ID:	1045095
Operable Unit:	01
Material ID:	338787
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C69 **HARRY AUTOMOTIVE REPAIR CORP** **EDR Hist Auto** **1020897338**
WSW **10-12 BOND ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.048 mi.
254 ft. **Site 6 of 28 in cluster C**

Relative: EDR Hist Auto
Lower

Actual:
41 ft.

Year:	Name:	Type:
1971	HARRYS SERVICE STATION INC	Gasoline Service Stations
1972	HARRYS SERVICE STATION INC	Gasoline Service Stations
1973	HARRYS SERVICE STATION INC	Gasoline Service Stations
1974	HARRYS SERVICE STATION INC	Gasoline Service Stations
1975	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1976	HARRYS SERVICE STATION	Gasoline Service Stations
1977	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1978	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1979	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1980	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1982	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1983	AMSTERDAM MRCNTL OPRTNG CRP	Gasoline Service Stations
1983	HARRY AUTOMOTIVE REPAIR CORP	Gasoline Service Stations
1985	S & P AUTOMOTIVE	Gasoline Service Stations
1985	AMSTERDAM MRCNTL OPRTNG	Gasoline Service Stations
1986	AMSTERDAM MERC OPERATING*	Gasoline Service Stations
1986	S & P AUTOMOTIVE ENTERPRISES	Gasoline Service Stations
1987	AMSTERDAM MERC OPERATING*	Gasoline Service Stations
1987	S & P AUTOMOTIVE ENTERPRISES	Gasoline Service Stations
1988	AMSTERDAM MERC OPERATING	Gasoline Service Stations
1988	S & P AUTOMOTIVE ENTERPRISES	Gasoline Service Stations
1989	S & P AUTOMOTIVE ENTERPRISES	Gasoline Service Stations
1989	AMSTERDAM MERC OPERATING	Gasoline Service Stations
1990	AMSTERDAM MERC OPERATING	Gasoline Service Stations
1990	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1991	AMSTERDAM MERC OPERATING	Gasoline Service Stations
1991	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1992	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1992	AMSTERDAM MERC OPERATING	Gasoline Service Stations
1993	AMSTERDAM MERC OPERATING	Gasoline Service Stations
1993	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1994	AMSTERDAM MERCANTILE OPERATING	Gasoline Service Stations
1994	APOLLO TOWING INC	General Automotive Repair Shops
1995	AMSTERDAM MERCANTILE OPERATING	Gasoline Service Stations
1996	AMSTERDAM MERCANTILE OPERATING	Gasoline Service Stations
1996	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1997	AMSTERDAM MERCANTILE OPERATING	Gasoline Service Stations
1997	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1998	AMSTERDAM MERCANTILE OPERATING	Gasoline Service Stations
1998	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1999	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
1999	AMSTERDAM MERCANTILE OPERATING	Gasoline Service Stations
2000	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
2001	ALLIANCE AUTOMOTIVE ENTPS	General Automotive Repair Shops
2001	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
2002	ALLIANCE AUTOMOTIVE ENTPS	General Automotive Repair Shops
2002	PANORAMIC AUTO SERVICE STATION	Gasoline Service Stations
2003	ALLIANCE AUTOMOTIVE ENTPS	General Automotive Repair Shops

C70 **CON EDISON** **NY Spills** **S102961938**
WSW **10 BOND ST** **NY MANIFEST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.048 mi.
254 ft. **Site 7 of 28 in cluster C**

Relative: **Lower**

Actual: **41 ft.**

SPILLS:

Facility ID:	9710410
Facility Type:	ER
Spill Number:	9710410
DER Facility ID:	69771
Site ID:	74312
DEC Region:	2
Closed Date:	1997-12-10
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1997-12-10
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-12-10
CID:	201
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-10
Spill Record Last Update:	2002-03-05
Spiller Name:	UNK
Spiller Company:	GARY'S GARAGE
Spiller Address:	10 BOND STREET
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"CALLER ADVISED THAT THIS IS AN ONGOING PROBLEM"

All Materials:

Site ID:	74312
Operable Unit ID:	1056791
Operable Unit:	01
Material ID:	328707
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0608806
Facility Type:	ER
Spill Number:	0608806
DER Facility ID:	326428

CON EDISON (Continued) **S102961938**

Site ID:	372842
DEC Region:	2
Closed Date:	2008-04-15
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-10-31
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2006-10-31
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-31
Spill Record Last Update:	2008-04-15
Spiller Name:	Not reported
Spiller Company:	UNKOWN.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RAY KAHN
DEC Memo:	"12/05/06 Rahman- Tank closure report will be sent to DEC shortly. Report in edocs. 04/01/08 Former gas station.3 UST on site, tested in August 2006, all passed.Tanks/all lines connected with tanks were filled with concrete slurry.Soil borings performed around tank came back clean.Suspected dispenser island area(SB2,SB2A,SB2B) were investigated and level of contamination is below TAGM.Site will be developed for residential /commmercial purposes.ESPL will oversee environmental issues while site development.ESPL(Ray Kahn) has been advised to notify DEC if there is any contamination observed.3 MW onsite were dry while sampling.Spill closed.(sr)"
Remarks:	"HISTORICAL SPILL TIME OCCURED UNKOWN; TANK WAS TESTED AND PASSED BUT SOIL SURRAOUNDING IT TESTED SLIGHTLY ABOVE TAGM LEVELS; SOURCE ELIMINATED;"

All Materials:

Site ID:	372842
Operable Unit ID:	1130575
Operable Unit:	01
Material ID:	2120246
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

CON EDISON (Continued) **S102961938**

Country: USA
EPA ID: NYP004543518
Facility Status: Not reported
Location Address 1: 10 BOND ST
Code: BP
Location Address 2: SB 26601
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004543518
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/27/2014
Trans1 Recv Date: 05/27/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/28/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004543518
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013245830JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S102961938**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C71 **10-12 BOND STREET PERTNERS, LLC** **NY UST** **U004077966**
WSW **10 BOND STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.048 mi.
254 ft. **Site 8 of 28 in cluster C**

Relative: **Lower**
Actual: **41 ft.**

UST:

Id/Status:	2-600062 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584948.40893
UTM Y:	4508934.77930
Site Type:	Other

Affiliation Records:

Site Id:	22049
Affiliation Type:	Facility Owner
Company Name:	10-12 BOND STREET, LLC
Contact Type:	PRESIDENT
Contact Name:	BENJAMIN SOLEIMANI
Address1:	276 N. HENRY ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 349-0555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-02-01

Site Id:	22049
Affiliation Type:	Mail Contact
Company Name:	176 N HENRY STREET LLC

10-12 BOND STREET PERTNERS, LLC (Continued) **U004077966**

Contact Type:	Not reported
Contact Name:	DIDAR SINGH
Address1:	276 NORTH HENRY STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 349-0555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-02-11

Site Id:	22049
Affiliation Type:	Facility Operator
Company Name:	10-12 BOND STREET PERTNERS, LLC
Contact Type:	Not reported
Contact Name:	10-12 BOND STREET PARTNERS LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 686-2500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-02-01

Site Id:	22049
Affiliation Type:	Emergency Contact
Company Name:	10-12 BOND STREET, LLC
Contact Type:	Not reported
Contact Name:	BENJAMIN SOLEIMANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 686-2500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-02-01

Tank Info:

Tank Number:	001
Tank ID:	41218
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	01/01/1991
Date Tank Closed:	10/03/2006

10-12 BOND STREET PERTNERS, LLC (Continued) **U004077966**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	21
Date Test:	08/17/2006
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Number:	002
Tank ID:	41219
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	01/01/1991
Date Tank Closed:	10/03/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	21
Date Test:	08/17/2006
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction Dispenser

10-12 BOND STREET PERTNERS, LLC (Continued) **U004077966**

G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None

Tank Number:	003
Tank ID:	41220
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	01/01/1991
Date Tank Closed:	10/03/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	21
Date Test:	08/17/2006
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

C72 **PANORAMIC AUTO SERVICE INC** **RCRA NonGen / NLR** **1000551837**
WSW **10 BOND ST** **NYD986942043**
< 1/8 **NEW YORK, NY 10012**
0.048 mi.
254 ft. **Site 9 of 28 in cluster C**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PANORAMIC AUTO SERVICE INC
Facility address:	10 BOND ST NEW YORK, NY 10012-2312
EPA ID:	NYD986942043
Mailing address:	BOND ST NEW YORK, NY 10012
Contact:	Not reported
Contact address:	BOND ST NEW YORK, NY 10012
Contact country:	US
Contact telephone:	Not reported

PANORAMIC AUTO SERVICE INC (Continued) **1000551837**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ISAK GUTMAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ISAK GUTMAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PANORAMIC AUTO SERVICE INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PANORAMIC AUTO SERVICE INC

PANORAMIC AUTO SERVICE INC (Continued) **1000551837**

Classification: Not a generator, verified

Date form received by agency: 02/25/1991
Site name: PANORAMIC AUTO SERVICE INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

C73 **CON EDISON SERVICE BOX: 26601** **RCRA NonGen / NLR** **1017776493**
WSW **10 BOND ST** **NYP004543518**
< 1/8 **NEW YORK, NY 10012**
0.048 mi.
254 ft. **Site 10 of 28 in cluster C**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/27/2014
Facility name: CON EDISON SERVICE BOX: 26601
Facility address: 10 BOND ST
NEW YORK, NY 10012
EPA ID: NYP004543518
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/27/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 05/27/2014

CON EDISON SERVICE BOX: 26601 (Continued) **1017776493**

Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

F74 **42 BOND ST** **NY AST** **A100350477**
South **42 BOND ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.049 mi.
261 ft. **Site 1 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611369
Program Type: PBS
UTM X: 585041.52873
UTM Y: 4508840.64568
Expiration Date: 12/27/2021
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 435823
Affiliation Type: Facility Owner
Company Name: JATO REALTY CORP
Contact Type: AGENT
Contact Name: FRED FRAGANO
Address1: 250 PARK AVE, SUITE 1901
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10177
Country Code: 001
Phone: (212) 972-5900
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-02-10

Site Id: 435823
Affiliation Type: Mail Contact
Company Name: R.A. COHEN AND ASSOCIATES
Contact Type: Not reported
Contact Name: FRED FRAGANO
Address1: 250 PARK AVE, SUITE 1901
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10177
Country Code: 001
Phone: (212) 972-5900
EMail: FRED@RACOHEN.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-02-10

Site Id: 435823
Affiliation Type: Facility Operator

42 BOND ST (Continued) **A100350477**

Company Name:	42 BOND ST
Contact Type:	Not reported
Contact Name:	MICHAEL VIEIRA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 940-0532
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-02-10

Site Id:	435823
Affiliation Type:	Emergency Contact
Company Name:	???
Contact Type:	Not reported
Contact Name:	FRED FRAGANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 835-9526
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-06-08

Tank Info:

Tank Number:	001
Tank Id:	234803
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
J02 - Dispenser - Suction Dispenser
B05 - Tank External Protection - Jacketed
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

42 BOND ST (Continued) **A100350477**

Install Date:	01/01/1965
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

C75 **NEW YORK CITY OF HUMAN RESOURCES ADMIN** **RCRA NonGen / NLR** **1004758169**
WSW **350 LAFAYETTE ST** **FINDS** **NYD986984805**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.052 mi. **NY MANIFEST**
276 ft. **Site 11 of 28 in cluster C**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NEW YORK CITY OF HUMAN RESOURCES ADMIN
Facility address:	350 LAFAYETTE ST NEW YORK, NY 10012
EPA ID:	NYD986984805
Mailing address:	MAIN ST BROOKLYN, NY 11201
Contact:	FELIX BENITEZ
Contact address:	MAIN ST BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	718-260-6510
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	HUMAN ESOURCES ADMIN CITY OF NY
Owner/operator address:	30 MAIN ST BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	716-260-6510
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	HUMAN ESOURCES ADMIN CITY OF NY
Owner/operator address:	30 MAIN ST BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	716-260-6510
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

NEW YORK CITY OF HUMAN RESOURCES ADMIN (Continued) **1004758169**

Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NEW YORK CITY OF HUMAN RESOURCES ADMIN
Classification: Not a generator, verified

Date form received by agency: 01/07/1992
Site name: NEW YORK CITY OF HUMAN RESOURCES ADMIN
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004481917

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NEW YORK CITY OF HUMAN RESOURCES ADMIN (Continued) **1004758169**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004758169
Registry ID:	110004481917
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004481917

NY MANIFEST:

Country:	USA
EPA ID:	NYD986984805
Facility Status:	Not reported
Location Address 1:	350 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986984805
Mailing Name:	HUMAN RESOURCES ADM CITY OF NEW YORK
Mailing Contact:	BERNICE JOHNSON
Mailing Address 1:	30 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182606510

NY MANIFEST:

Document ID:	NJA1301721
Manifest Status:	C
seq:	Not reported
Year:	1992
Trans1 State ID:	MK8837
Trans2 State ID:	NJDEPS727
Generator Ship Date:	03/05/1992
Trans1 Recv Date:	03/05/1992
Trans2 Recv Date:	03/05/1992
TSD Site Recv Date:	03/05/1992
Part A Recv Date:	/ /
Part B Recv Date:	03/24/1992
Generator EPA ID:	NYD986984805
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	NJD986609949
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

NEW YORK CITY OF HUMAN RESOURCES ADMIN (Continued) **1004758169**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C76 **LAFAYETTE WOMEN SHELTER** **NY UST** **U001736601**
WSW **350 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.052 mi.
276 ft. **Site 12 of 28 in cluster C**

Relative: **Lower**
Actual: **41 ft.**

UST:

Id/Status:	2-601685 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	12/15/2018
UTM X:	584920.14867
UTM Y:	4508881.28099
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	23647
Affiliation Type:	Facility Operator
Company Name:	LAFAYETTE WOMEN SHELTER
Contact Type:	Not reported
Contact Name:	THERESA FEHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 420-7750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM

LAFAYETTE WOMEN SHELTER (Continued) **U001736601**

Date Last Modified: 2014-08-18

Site Id: 23647
Affiliation Type: Emergency Contact
Company Name: NYC DEPARTMENT OF HOMELESS SERVICES
Contact Type: Not reported
Contact Name: PETER DEMPSEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 682-8408
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2014-08-18

Site Id: 23647
Affiliation Type: Mail Contact
Company Name: NYC DEPT. OF HOMELESS SERVICES
Contact Type: DIRECTOR OF MAINTENANCE & REPAIR
Contact Name: PETER DEMPSEY
Address1: 101-07 FARRAGUT ROAD
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11236
Country Code: 001
Phone: (718) 688-8520
EMail: PDEMPSEY@DHS.NYC.GOV
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-24

Site Id: 23647
Affiliation Type: Facility Owner
Company Name: NYC DEPARTMENT OF HOMELESS SERVICES
Contact Type: DIRECTOR OF MAINTENENCE & REPAIR
Contact Name: PETER DEMPSEY
Address1: 101-07 FARRAGUT ROAD
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11236
Country Code: 001
Phone: (718) 688-8520
EMail: PDEMPSEY@DHS.NYC.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-12-30

Tank Info:

Tank Number: 001
Tank ID: 47473

LAFAYETTE WOMEN SHELTER (Continued) **U001736601**

Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	01/01/1970
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	07/16/2014
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	BKFALVEY
Last Modified:	02/01/2018

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

C77 **350 LAFAYETTE ST/SHELTER** **NY LTANKS** **S102671811**
WSW **350 LAFAYETTE ST/SHELTER** **N/A**
< 1/8 **NYC, NY**
0.052 mi.
276 ft. **Site 13 of 28 in cluster C**

Relative: **Lower**

Actual: **41 ft.**

LTANKS:

Facility ID:	9110940
Site ID:	83567
Closed Date:	1992-01-22
Spill Number:	9110940
Spill Date:	1992-01-21
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1992-01-22
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1992-01-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

350 LAFAYETTE ST/SHELTER (Continued) **S102671811**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-02-06
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	76890
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"ABSORB - ALL APPLIED PICKED UP & DISPOSED."

All Materials:

Site ID:	83567
Operable Unit ID:	964740
Operable Unit:	01
Material ID:	416014
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C78 **KAMPO CULTURAL CENTER, INC** **NY AST** **U003390143**
SSW **31 BOND STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.054 mi.
284 ft. **Site 14 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-321427
Program Type:	PBS
UTM X:	585005.23556
UTM Y:	4508884.69494
Expiration Date:	N/A
Site Type:	Private Residence

Affiliation Records:

Site Id:	14936
Affiliation Type:	Mail Contact
Company Name:	KAMPO CUTURAL CENTER
Contact Type:	Not reported
Contact Name:	MICK OAKLEAF
Address1:	31 BOND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY

KAMPO CULTURAL CENTER, INC (Continued) **U003390143**

Zip Code:	10012
Country Code:	001
Phone:	(212) 228-1058
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-03

Site Id:	14936
Affiliation Type:	Facility Operator
Company Name:	KAMPO CULTURAL CENTER, INC
Contact Type:	Not reported
Contact Name:	MICK OAKLEAF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 228-1058
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-03

Site Id:	14936
Affiliation Type:	Emergency Contact
Company Name:	HEIAN BUNKA CENTER
Contact Type:	Not reported
Contact Name:	CARMINE D'INTINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 267-0579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-03

Site Id:	14936
Affiliation Type:	Facility Owner
Company Name:	HEIAN BUNKA CENTER
Contact Type:	MANAGER
Contact Name:	MICHEAL OAKLEAF
Address1:	31 BOND ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 228-1058
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS

KAMPO CULTURAL CENTER, INC (Continued) **U003390143**

Date Last Modified: 2009-11-03

Tank Info:

Tank Number: 001
Tank Id: 18432
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1985
Capacity Gallons: 2000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 11/22/2013
Register: True
Modified By: LXZIELIN
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

C79 **CON EDISON SERVICE BOX: 26601** **RCRA NonGen / NLR** **1016450049**
WSW **6 BOND ST** **NY MANIFEST** **NYP004290441**
< 1/8 **NEW YORK, NY 10012**
0.055 mi.
291 ft. **Site 15 of 28 in cluster C**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:
Date form received by agency: 04/01/2013
Facility name: CON EDISON SERVICE BOX: 26601
Facility address: 6 BOND ST
NEW YORK, NY 10012
EPA ID: NYP004290441
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 347-865-5931
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator

CON EDISON SERVICE BOX: 26601 (Continued) **1016450049**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/01/2013
Site name: CON EDISON SERVICE BOX: 26601
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004290441
Facility Status: Not reported
Location Address 1: 6 BOND ST
Code: BP
Location Address 2: SERV BOX 26601
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004290441
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013

CON EDISON SERVICE BOX: 26601 (Continued) **1016450049**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/01/2013
Trans1 Recv Date:	03/01/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004290441
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707153JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

F80 **50 BOND STREET** **NY AST** **A100382381**
SSE **50 BOND STREET** **N/A**
< 1/8 **NEW YORK, NY 10011**
0.056 mi.
296 ft. **Site 2 of 28 in cluster F**

Relative: **Higher**
Actual: **42 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-607147
Program Type:	PBS
UTM X:	584972.05998
UTM Y:	4508873.41588
Expiration Date:	N/A
Site Type:	Storage Terminal/Petroleum Distributor

Tank Info:

Tank Number:	001
Tank Id:	62400
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/2002
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	Not reported

E81 **688 BROADWAY 1 GREAT JONES ALLEY** **RCRA-LQG** **1017780183**
NW **688 BROADWAY** **FINDS** **NYR000217752**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.057 mi.
299 ft. **Site 2 of 23 in cluster E**

Relative: **Lower**
Actual: **41 ft.**

RCRA-LQG:

Date form received by agency:	05/11/2016
Facility name:	688 BROADWAY 1 GREAT JONES ALLEY
Facility address:	688 BROADWAY NEW YORK, NY 10012
EPA ID:	NYR000217752
Mailing address:	3RD AVE 37TH FLOOR NEW YORK, NY 10022
Contact:	JEREMY PLOFKER
Contact address:	3RD AVE MANHATTAN, NY 10022
Contact country:	US
Contact telephone:	646-747-2230
Contact email:	JPLOFKER@MADISONREALTYCAPITAL.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any

688 BROADWAY 1 GREAT JONES ALLEY (Continued) **1017780183**

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	DOWNTOWN RE HOLDINGS LLC
Owner/operator address:	THIRD AVE 37TH FL
	NEW YORK, NY 10022
Owner/operator country:	US
Owner/operator telephone:	646-472-1900
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/10/2008
Owner/Op end date:	Not reported

Owner/operator name:	DOWNTOWN RE HOLDINGS LLC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/10/2008
Owner/Op end date:	Not reported

Owner/operator name:	DOWNTOWN RE HOLDINGS LLC
Owner/operator address:	3RD AVE
	NEW YORK, NY 10022
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/04/2015
Owner/Op end date:	Not reported

Owner/operator name:	DOWNTOWN RE HOLDINGS
Owner/operator address:	3RD AVE 37TH FLOOR
	NEW YORK, NY 10022
Owner/operator country:	US
Owner/operator telephone:	676-747-2230

688 BROADWAY 1 GREAT JONES ALLEY (Continued) **1017780183**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/28/2008
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 03/03/2015
Site name: DOWNTOWN RE HOLDINGS LLC
Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 1058200

Violation Status: No violations found

FINDS:

Registry ID: 110063757215

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

688 BROADWAY 1 GREAT JONES ALLEY (Continued) **1017780183**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1017780183
Registry ID: 110063757215
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110063757215

E82 **DOWNTOWN RE HOLDINGS LLC** **PA MANIFEST** **S118889638**
NW **688 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.057 mi.
299 ft. **Site 3 of 23 in cluster E**

Relative: **Lower**
Actual: **41 ft.**

Manifest Details:

Year:	2015
Manifest Number:	013321416JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/03/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013321422JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield

DOWNTOWN RE HOLDINGS LLC (Continued) **S118889638**

TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321426JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/16/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321428JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/16/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1

DOWNTOWN RE HOLDINGS LLC (Continued) **S118889638**

Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	011811343JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	08/12/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321413JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/05/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1

DOWNTOWN RE HOLDINGS LLC (Continued) **S118889638**

Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321418JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/03/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321427JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/16/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)

DOWNTOWN RE HOLDINGS LLC (Continued) **S118889638**

Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321414JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/03/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013321411JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000217752
Generator Date:	11/03/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	646-442-4212
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22
Unit:	Tons (2000 Pounds)
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

DOWNTOWN RE HOLDINGS LLC (Continued) **S118889638**

Click this hyperlink while viewing on your computer to access
11 additional PA_MANIFEST: record(s) in the EDR Site Report.

E83 **LOT 4,TAXBLOCK 531** **NY E DESIGNATION** **S116624675**
NW **688 BROADWAY** **N/A**
< 1/8 **MANHATTAN, NY**
0.057 mi.
299 ft. **Site 4 of 23 in cluster E**

Relative: **Lower**
Actual: **41 ft.**

E DESIGNATION:

Tax Lot(s):	4
Tax Block:	531
Borough Code:	Not reported
E-No:	E-325
Effective Date:	4/10/2014
Satisfaction Date:	Not reported
Ceqr Number:	13DCP091M
Ulurp Number:	140055ZSM, 140056ZSM
Zoning Map No:	12c
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

E84 **688 BROADWAY** **NY VCP** **S118943493**
NW **688 BROADWAY** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.057 mi.
299 ft. **Site 5 of 23 in cluster E**

Relative: **Lower**
Actual: **41 ft.**

VCP NYC:

Project ID:	15CVCP104M
Project Name:	688 BROADWAY
Project Address:	688 BROADWAY
Borough:	MANHATTAN

VCP NYC:

Project ID:	15CVCP104M
File Name:	2013-04-15.SIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2013-04-15.13DEPTECH034M.doc.688_Broadway.SIR.pdf
Project ID:	15CVCP104M
File Name:	2015-04-10.RIR+RAWP
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-04-10.15CVCP104M.doc.688_Broadway.SIR+RAWP_Draft.pdf
Project ID:	15CVCP104M
File Name:	2015-04-06.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-04-06.15CVCP104M.doc.688_Broadway.Factsheet-1.pdf

688 BROADWAY (Continued) **S118943493**

Project ID: 15CVCP104M
File Name: 2015-04-06.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-04-06.15CVCP104M.doc.688_Broadway.Translated_Factsheet-1.pdf

Project ID: 15CVCP104M
File Name: 2015-04-06.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-04-06.15CVCP104M.doc.688_Broadway.Translated_Community_Protection_Statement.pdf

Project ID: 15CVCP104M
File Name: 2015-06-15.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-06-15.15CVCP104M.doc.688_Broadway.Stipulation_List.pdf

Project ID: 15CVCP104M
File Name: 2015-07-13.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-07-13.15CVCP104M.doc.688_Broadway.Decision_Document.pdf

Project ID: 15CVCP104M
File Name: 2015-07-13.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-07-13.15CVCP104M.doc.688_Broadway.FactSheet-2.pdf

Project ID: 15CVCP104M
File Name: 2015-07-13.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP104M/2015-07-13.15CVCP104M.doc.688_Broadway.Translated_Factsheet-2.pdf

---

E85 **DOWNTOWN RE HOLDINGS LLC/MADISON REALITY CAPITAL** **NY MANIFEST** **S118260191**
NW **688 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.057 mi.
299 ft. **Site 6 of 23 in cluster E**

Relative: **Lower**

Actual: **41 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYR000217752
Facility Status: Not reported
Location Address 1: 688 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000217752
Mailing Name: DOWNTOWN RE HOLDINGS LLC/MADISON REALITY CAPITAL
Mailing Contact: MADISON REALITY CAPITAL

DOWNTOWN RE HOLDINGS LLC/MADISON REALITY CAPITAL (Continued) **S118260191**

Mailing Address 1:	825 3RD AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10012
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6464721900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	11/16/2015
Trans1 Recv Date:	11/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217752
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	013321427JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	43520
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D008
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

DOWNTOWN RE HOLDINGS LLC/MADISON REALITY CAPITAL (Continued) **S118260191**

Click this hyperlink while viewing on your computer to access
33 additional NY_MANIFEST: record(s) in the EDR Site Report.

B86 **BOWERY AND 4TH STREET** **RCRA NonGen / NLR** **1007206808**
East **BOWERY AND 4TH STREET** **NY MANIFEST** **NYP004031068**
< 1/8 **NEW YORK CITY, NY 10003**
0.057 mi.
300 ft. **Site 12 of 14 in cluster B**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/03/2001
Facility name:	BOWERY AND 4TH STREET
Facility address:	BOWERY AND 4TH STREET NEW YORK CITY, NY 10003
EPA ID:	NYP004031068
Mailing address:	CONSOLIDATED EDISON INC. 4 IRVING PLACE -- ROOM 300 NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC. NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/02/2001
Site name:	BOWERY AND 4TH STREET
Classification:	Not a generator, verified
Date form received by agency:	01/01/2001
Site name:	BOWERY AND 4TH STREET
Classification:	Large Quantity Generator
Violation Status:	No violations found

BOWERY AND 4TH STREET (Continued) **1007206808**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004031068
Facility Status:	Not reported
Location Address 1:	BOWERY ST & E 4TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004031068
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NJA2868105
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	S09041
Trans2 State ID:	Not reported
Generator Ship Date:	02/23/1999
Trans1 Recv Date:	02/23/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/23/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004031068
Trans1 EPA ID:	NJD982744260
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP

BOWERY AND 4TH STREET (Continued) **1007206808**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00375
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C87 **SPILL NUMBER 9801771** **NY Spills** **S104646932**
SW **22 BOND ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.057 mi.
300 ft. **Site 16 of 28 in cluster C**

Relative: **Higher**

Actual: **42 ft.**

SPILLS:

Facility ID:	9801771
Facility Type:	ER
Spill Number:	9801771
DER Facility ID:	231289
Site ID:	285235
DEC Region:	2
Closed Date:	1998-05-11
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	4101
Spill Date:	1998-05-11
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1998-05-11
CID:	366
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-11
Spill Record Last Update:	1998-05-13
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT OIL CO. CALL MR. PROPPER : 5/11 12:35 PM 21-21 43RD AVENUE (TRUCK HAS NO COMPANY NAME OR PHONE # BUT LIC DOT PUT DAM OF SAND AROUND TRUCK - SANDING STREET CONSTRUCTION AT 22 BOND STREET OIL

SPILL NUMBER 9801771 (Continued) **S104646932**

GOING DOWN STORM DAMN FAX TO ECS"
Remarks: "NOTIFIER CALLING TO REPORT THAT AN UNKNOWN QUANTITY OF SOME TYPE OF OIL IS ON GROUND NEAR A TANK TRUCK."

All Materials:
Site ID: 285235
Operable Unit ID: 1059682
Operable Unit: 01
Material ID: 323689
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 285235
Operable Unit ID: 1059682
Operable Unit: 01
Material ID: 323690
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Facility ID: 9802317
Facility Type: ER
Spill Number: 9802317
DER Facility ID: 230625
Site ID: 284400
DEC Region: 2
Closed Date: 1998-05-21
Spill Cause: Unknown
Spill Class: C4
SWIS: 3101
Spill Date: 1998-05-14
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1998-05-21
CID: 322
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-05-21
Spill Record Last Update: 1998-05-26

SPILL NUMBER 9801771 (Continued) **S104646932**

Spiller Name:	Not reported
Spiller Company:	UNK CONSTRUCTION COMPANY
Spiller Address:	AT 22 BOND ST
Spiller Company:	001
Contact Name:	KEITH CRANDELL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT CALL SANITATION CALL JULIO CB2"
Remarks:	"contstrction being done at site - spill of haudraulic oil and construction company put down sand but has not cleaned up sand unk what actually caused spill "

All Materials:

Site ID:	284400
Operable Unit ID:	1062847
Operable Unit:	01
Material ID:	320649
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F88 **CON EDISON** **NJ MANIFEST** **S120669280**
SE **342 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10002**
0.057 mi.
301 ft. **Site 3 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004754321
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611103GBF
EPA ID:	NYP004754321
Date Shipped:	3/19/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON (Continued) **S120669280**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

F89 **CON EDISON** **RCRA NonGen / NLR** **1018280545**
SE **342 BOWERY** **FINDS** **NYP004754321**
< 1/8 **NEW YORK, NY 10002** **ECHO**
0.057 mi.
301 ft. **Site 4 of 28 in cluster F**

Relative: **Higher**

Actual: **42 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/19/2015
Facility name:	CON EDISON
Facility address:	342 BOWERY NEW YORK, NY 10002
EPA ID:	NYP004754321
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON (Continued) **1018280545**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 03/19/2015
- Site name: CON EDISON
- Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067708314

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1018280545
- Registry ID: 110067708314
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067708314

F90 **CON EDISON** **NY MANIFEST** **S118087921**
SE **342 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10002**
0.057 mi.
301 ft. **Site 5 of 28 in cluster F**

Relative: **Higher**
Actual: **42 ft.**

NY MANIFEST:
- Country: USA
- EPA ID: NYP004754321
- Facility Status: Not reported
- Location Address 1: 342 BOWERY
- Code: BP

CON EDISON (Continued) **S118087921**

Location Address 2:	SB 26839
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004754321
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2015
Trans1 Recv Date:	03/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004754321
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611103GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500

CON EDISON (Continued) **S118087921**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

G91 **CON EDISON MANHOLE: 35868** **RCRA NonGen / NLR** **1016963008**
SE **GREAT JONES ST & BOWERY** **NY MANIFEST** **NYP004360459**
< 1/8 **NEW YORK, NY 10012**
0.058 mi.
304 ft. **Site 1 of 12 in cluster G**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/15/2013
Facility name:	CON EDISON MANHOLE: 35868
Facility address:	GREAT JONES ST & BOWERY NEW YORK, NY 10012
EPA ID:	NYP004360459
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON MANHOLE: 35868 (Continued) **1016963008**

Historical Generators:
Date form received by agency: 09/15/2013
Site name: CON EDISON MANHOLE: 35868
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004360459
Facility Status: Not reported
Location Address 1: SW COR GREAT JONES & BOWERY
Code: BP
Location Address 2: MH 35868
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004360459
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/15/2013
Trans1 Recv Date: 09/15/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/17/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004360459
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002221189GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON MANHOLE: 35868 (Continued) **1016963008**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

D92 **FISHER REALTY CORP** **NY AST** **U003393527**
NNE **401 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.058 mi.
308 ft. **Site 2 of 7 in cluster D**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-032522
Program Type:	PBS
UTM X:	585117.28875
UTM Y:	4509130.11169
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	221
Affiliation Type:	Facility Owner
Company Name:	FISHER REALTY CORP
Contact Type:	EXEC. VP
Contact Name:	RICHARD J LEAL
Address1:	21 E 4TH STREET SUITE 617
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001

FISHER REALTY CORP (Continued) **U003393527**

Phone:	(973) 809-9426
EMail:	RLEAL@ASTORWINDS.COM
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-09-21

Site Id:	221
Affiliation Type:	Mail Contact
Company Name:	FISHER REALTY CORP
Contact Type:	EXEC. VP
Contact Name:	RICHARD J LEAL
Address1:	21 E 4TH STREET SUITE 617
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(973) 809-9426
EMail:	RLEAL@ASTORWINDS.COM
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-09-21

Site Id:	221
Affiliation Type:	Facility Operator
Company Name:	FISHER REALTY CORP
Contact Type:	Not reported
Contact Name:	MANUEL CAMBEIRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 693-3606
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-09-21

Site Id:	221
Affiliation Type:	Emergency Contact
Company Name:	FISHER REALTY CORP
Contact Type:	Not reported
Contact Name:	MANUEL CAMBEIRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 693-3606
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2010-09-21

FISHER REALTY CORP (Continued) **U003393527**

Tank Info:

Tank Number:	001
Tank Id:	30470
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1960
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/25/2010
Register:	True
Modified By:	BVCAMPBE
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

E93 **CON EDISON SERVICE BOX: 872** **RCRA NonGen / NLR** **1016969684**
NNW **11 E 4TH ST** **NY MANIFEST** **NYP004433637**
< 1/8 **NEW YORK, NY 10003**
0.059 mi.
310 ft. **Site 7 of 23 in cluster E**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/04/2014
Facility name:	CON EDISON SERVICE BOX: 872
Facility address:	11 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004433637
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON SERVICE BOX: 872 (Continued) **1016969684**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/04/2014
Site name: CON EDISON SERVICE BOX: 872
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004433637
Facility Status: Not reported
Location Address 1: 114 E 4TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004433637
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014

CON EDISON SERVICE BOX: 872 (Continued) **1016969684**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004433637
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329885GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

B94 **MARTYS QUICKSTART INC** **EDR Hist Auto** **1020777740**
East **1 COOPER SQUARE** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.060 mi.
315 ft. **Site 13 of 14 in cluster B**

Relative: EDR Hist Auto
Lower

Actual:
41 ft.

Year:	Name:	Type:
1973	MARTYS QUICKSTART	Gasoline Service Stations
1974	MARTYS QUICKSTART INC	Gasoline Service Stations
1975	MARTYS QUICKSTART INC	Gasoline Service Stations
1976	MARTYS QUICKSTART INC	Gasoline Service Stations
1977	MARTYS QUICKSTART INC	Gasoline Service Stations
1978	MARTYS QUICKSTART INC	Gasoline Service Stations

F95 **SUNOCO STATION** **NY Spills** **S103036631**
SE **THE BOWERY AND SECOND ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.061 mi.
320 ft. **Site 6 of 28 in cluster F**

Relative: SPILLS:
Higher

Actual:
42 ft.

Facility ID:	9713749
Facility Type:	ER
Spill Number:	9713749
DER Facility ID:	58231
Site ID:	59489
DEC Region:	2
Closed Date:	1998-04-01
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	3101
Spill Date:	1998-03-11
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-03-11
CID:	322
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-11
Spill Record Last Update:	1998-04-01
Spiller Name:	Not reported
Spiller Company:	MYSTIC OR COASTAL TRUCK
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 3/11/98 spoke to Ken Nochimson : says oil was still spilling when tanker left. Service center is named Absolute service center. got # from information - 212-674-2827. 326 Bowery St. Spoke to Mystic Transport driver Winston Loren who was still on scene. Said only couple if gallons. Washed with water. Notified NYDEP

SUNOCO STATION (Continued) **S103036631**

communications. Trevinio took report."
Remarks: "large tanker truck was making a delivery and hit a post which broke tank or nozzle on truck - causing spill "

All Materials:
Site ID: 59489
Operable Unit ID: 1056612
Operable Unit: 01
Material ID: 324750
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

F96 **GAS STATION** **NY Spills** **S104881349**
SE **BOND ST / BOWERY** **N/A**
< 1/8 **NEW YORK, NY**
0.061 mi.
320 ft. **Site 7 of 28 in cluster F**

Relative: **Higher**
Actual: **42 ft.**

SPILLS:
Facility ID: 0030033
Facility Type: ER
Spill Number: 0030033
DER Facility ID: 240460
Site ID: 297178
DEC Region: 2
Closed Date: 2000-12-22
Spill Cause: Other
Spill Class: C3
SWIS: 3101
Spill Date: 2000-12-21
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 2000-12-22
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-12-22
Spill Record Last Update: 2000-12-22
Spiller Name: Not reported
Spiller Company: GAS STATION CUSTOMER
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

GAS STATION (Continued) **S104881349**

MARTINKAT "
Remarks: "FIRE DEPT ON SCENE. SPEEDIDRI APPLIED AND SWEPT UP."

All Materials:
Site ID: 297178
Operable Unit ID: 836600
Operable Unit: 01
Material ID: 540926
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported

F97 **MANHOLE #26829** **NY Spills** **S107408249**
SE **BOND ST, SWC BOWERY** **N/A**
< 1/8 **MANHATTAN, NY**
0.061 mi.
320 ft. **Site 8 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

SPILLS:
Facility ID: 0506036
Facility Type: ER
Spill Number: 0506036
DER Facility ID: 298435
Site ID: 351166
DEC Region: 2
Closed Date: 2006-01-11
Spill Cause: Unknown
Spill Class: C4
SWIS: 3101
Spill Date: 2005-08-16
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2005-08-16
CID: 444
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-08-16
Spill Record Last Update: 2006-01-11
Spiller Name: Not reported
Spiller Company: UNKNOWN AT THIS TIME:
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ERT DESK'
DEC Memo: "160526. 8-16-05 @ 12:10. E Manning # 03430 reports that while inspecting m26829 swc bond st & bowery, he discovered 5 gallons of

MANHOLE #26829 (Continued) **S107408249**

unknown oil ontop of 30 gallons of water in the structure. There was or is no smoke or fire involved. No sewer or waterway affected. No injuries and weather had no affect. No measuring device was used to determine the amount of the spill. Account # f3444 is being used for this incident. Source and cause of spill are unknown. No private property affected. No oil filled equipment in the structure. Conduit plate 14-j-3 indicates there is a sewer connection. Environmental yellow tag # 46994 was applied. No visual water movement. No substantial cracks observed. The structure has been d-faulted, the d-fault # is 01476. Samples and cleanup are pending safe access. J Moran # 01182. CIG R Elliott # 81653 notified @ 13:16. J Moran # 01182. "

Remarks: "3 GALLONS OF WATER: CONED # 160526"

All Materials:

Site ID:	351166
Operable Unit ID:	1108696
Operable Unit:	01
Material ID:	2098637
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E98 **682 TENANT CORP.** **NY AST** **U003396792**
WNW **682 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.061 mi.
322 ft. **Site 8 of 23 in cluster E**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602716
Program Type:	PBS
UTM X:	584923.84418
UTM Y:	4509029.41916
Expiration Date:	06/20/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24672
Affiliation Type:	Facility Owner
Company Name:	682 TENANT CORP C/O ANDREWS ORG
Contact Type:	MANAGING AGENT
Contact Name:	EDWARD ZIMMERMANN
Address1:	666 BROADWAY, 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688

682 TENANT CORP. (Continued) **U003396792**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	24672
Affiliation Type:	Mail Contact
Company Name:	ANDREWS ORGANIZATION
Contact Type:	Not reported
Contact Name:	EDWARD ZIMMERMAN
Address1:	666 BROADWAY, 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	24672
Affiliation Type:	Facility Operator
Company Name:	682 TENANT CORP.
Contact Type:	Not reported
Contact Name:	FRANK BURAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24672
Affiliation Type:	Emergency Contact
Company Name:	682 TENANT CORP C/O ANDREWS ORG
Contact Type:	Not reported
Contact Name:	ANDREWS ORG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

682 TENANT CORP. (Continued) **U003396792**

Tank Info:

Tank Number:	001
Tank Id:	51249
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/19/1979
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

D99 **PARKING GARAGE** **NY Spills** **S106010294**
NNE **403 LAFAYETTE ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.061 mi.
322 ft. **Site 3 of 7 in cluster D**

Relative:
Higher

Actual:
42 ft.

SPILLS:

Facility ID:	0209806
Facility Type:	ER
Spill Number:	0209806
DER Facility ID:	110906
Site ID:	128572
DEC Region:	2
Closed Date:	2006-01-31
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	2002-12-26
Investigator:	SKCARLSO
Referred To:	NFA (1/31/06)
Reported to Dept:	2002-12-26
CID:	257

PARKING GARAGE (Continued) **S106010294**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	2004-06-21
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-26
Spill Record Last Update:	2006-09-18
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ROMEO SANTOS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 12/27/02 SPOKE WITH ROMEO SANTOS, THE PHASE 2 WITH A PROPOSED REMEDIAL ACTION PLAN WILL BE SENT TO THIS OFFICE WITHIN THE NEXT FEW WEEKS. DURING THE PHONE CONVERSATION WITH MR. SANTOS, I STATED THAT GROUNDWATER SAMPLES WILL BE REQUIRED IN ADDITION TO THE STANDARD CLEAN SOIL REQUIREMENTS. SEE PBS # 2-350575 1/23/2003 reviewed phase 2 , there was no remedial action plan, scaled site plan and lab results dated one day after report date original data not supplied, only transcribrd version. 6/18/03 TIPPLE'S RESPONSE TO SUBMITTAL1. Scaled Site Map -The Site Map must be a scaled plan indicating the location of all tanks and appurtenances. The tank locations, both horizontally and vertically (depth) are required. 2. Tank Registration- The Tanks must be Properly registered as per 6 NYCRR Registration of Petroleum Storage Facilities. Section1.5 of the June 13 submittal refers to the Extraction, transportation and disposal of tanks and related piping if tanks were removed please have this properly reflected on the PBS registration. The site plan indicates that there are 12 tanks total, one 4000gal.tank, and eleven 550gal. tanks, and one hydraulic lift located on this property, the registration indicates that there are 10 closed in place tanks, one 4000gal. gasoline, one 4000gal. diesel, eight 550 gal. gasoline tanks on this property. Please make sure all PBS records are updated and accurate for this facility. 3. Soil Samples -All samples will be analyzed for both VOC's and SVOC's due to the confusion concerning the product formerly contained in the tanks. The Department requires the analytical soil sample results from this tank excavation, the site plan/report must clearly identify the location of these endpoint results both horizontally and vertically, compare the excavation dimensions with the sample locations. Compare these levels to the NYSDEC Recommended Soil Cleanup Objective - TAGM Levels. 4. Groundwater Samples - As per our December 27, 2002 phone discussion, a minimum of one groundwater sample must be analyzed at this former refueling facility 12/03/03 DC env. Danny called//report arrived/no groundwater sample taken and elevated SVOC's in three seperate tank cluster locations. Awaiting recommendations for continued remedial strategies. 2/12/04 TRANSFERRED FROM TIPPLE TO ROMMEL. 03/15/04 Reassigned from Rommel to Sun. 05/04/04 Sun sent a Stipulation Agreement to Fred Spindler of ParK-It Management requiring complete delineation of the contamination, submittal of an Investigation Summary report followed by a submittal of a Remedial Action Plan. The Department also requires a PBS registration to be submitted

PARKING GARAGE (Continued) **S106010294**

immediately reflecting the former tanks and their subsequent decommissioning. The Department set a deadline of May 26, 2004 for signing of the Stipulation Agreement by the Respondent. 10/12/04 Sun sent a letter to Fred Spindler of Part-It Management requiring by 11/19/04 to submit the following: 1) collect one groundwater sample from each of four former tank fields, and groundwater flow direction must be established. All groundwater samples shall be analyzed via EPA 8260/8270. 2)one soil sample shall be taken for each remote fill location. The Department will evaluate the submitted information and determine if additional investigation is warranted. 1/11/06: Case reassigned to Andersen. Called consultant to ask if the excavation was completed on all sides of the tank, and to confirm that groundwater was not encountered during the excavation. He said he would review the file and call me back. 1/18/06: Called Romeo Santos (Consultant), spoke to secretary and she said he will call me back. 1/31/06: NFA issued."

Remarks: "test results from a investigation - there is a old abandoned tank in the ground"

All Materials:

Site ID:	128572
Operable Unit ID:	861042
Operable Unit:	01
Material ID:	513225
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D100 **KALODOP PARK CORP.** **NY UST** **U000409109**
NNE **403 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.061 mi.
322 ft. **Site 4 of 7 in cluster D**

Relative: **Higher**
Actual: **42 ft.**

UST:

Id/Status:	2-350575 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585120.94082
UTM Y:	4509135.70459
Site Type:	Other

Affiliation Records:

Site Id:	17303
Affiliation Type:	Facility Owner
Company Name:	KALODOP PARK CORP % PARK IT MGMT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	250 W. 26TH ST.
Address2:	Not reported
City:	NEW YORK

KALODOP PARK CORP. (Continued) **U000409109**

State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 929-9404
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17303
Affiliation Type:	Mail Contact
Company Name:	KALODOP PARK CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	PARK IT MANAGEMENT
Address2:	250 WEST 26TH STREET
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 929-9404
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17303
Affiliation Type:	Facility Operator
Company Name:	KALODOP PARK CORP.
Contact Type:	Not reported
Contact Name:	MIKE IBRAHIM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-1263
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17303
Affiliation Type:	Emergency Contact
Company Name:	KALODOP PARK CORP % PARK IT MGMT
Contact Type:	Not reported
Contact Name:	GARY SPINDLER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 929-9404
EMail:	Not reported
Fax Number:	Not reported

KALODOP PARK CORP. (Continued) **U000409109**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 33904
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 10/01/1985
Date Tank Closed: 12/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 33905
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 10/01/1985
Date Tank Closed: 12/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

KALODOP PARK CORP. (Continued) **U000409109**

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Tank Number:	03
Tank ID:	64712
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	04
Tank ID:	64713
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

KALODOP PARK CORP. (Continued) **U000409109**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 05
Tank ID: 64714
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 06
Tank ID: 64715
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/2003

KALODOP PARK CORP. (Continued) **U000409109**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 07
Tank ID: 64716
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 08

KALODOP PARK CORP. (Continued) **U000409109**

Tank ID: 64717
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 09
Tank ID: 64718
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

KALODOP PARK CORP. (Continued) **U000409109**

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	10
Tank ID:	64719
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

F101 **CON EDISON** **NY MANIFEST** **S118087922**
SE **340 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10002**
0.061 mi.
323 ft. **Site 9 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004754339
Facility Status:	Not reported
Location Address 1:	340 BOWERY
Code:	BP
Location Address 2:	SB 26838
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004754339
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **S118087922**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2015
Trans1 Recv Date:	03/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004754339
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611460GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S118087922**

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

F102 **CON EDISON** **RCRA NonGen / NLR** **1018280546**
SE **340 BOWERY** **FINDS** **NYP004754339**
< 1/8 **NEW YORK, NY 10002** **ECHO**
0.061 mi.
323 ft. **Site 10 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/19/2015
Facility name:	CON EDISON
Facility address:	340 BOWERY NEW YORK, NY 10002
EPA ID:	NYP004754339
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/19/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110067708323

Environmental Interest/Information System

CON EDISON (Continued) **1018280546**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280546
Registry ID:	110067708323
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067708323

F103 **CON EDISON** **NJ MANIFEST** **S120669281**
SE **340 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10002**
0.061 mi.
323 ft. **Site 11 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004754339
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611460GBF
EPA ID:	NYP004754339
Date Shipped:	3/19/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **S120669281**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

F104 **340 BOWERY** **NY Spills** **S102143041**
SSE **340 BOWERY** **N/A**
< 1/8 **NYC, NY**
0.065 mi.
344 ft. **Site 12 of 28 in cluster F**

Relative: **Higher**
Actual: **42 ft.**

SPILLS:

Facility ID:	9203601
Facility Type:	ER
Spill Number:	9203601
DER Facility ID:	140192
Site ID:	166376
DEC Region:	2
Closed Date:	1992-06-26
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	3101
Spill Date:	1992-06-26
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1992-06-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1992-06-26
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-06-30

340 BOWERY (Continued) **S102143041**

Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"SORBENT APPLIED & PICKED UP."

All Materials:

Site ID:	166376
Operable Unit ID:	970983
Operable Unit:	01
Material ID:	561860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D105 **CON EDISON** **NY MANIFEST** **S117066907**
NNE **402 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.065 mi.
344 ft. **Site 5 of 7 in cluster D**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004596144
Facility Status:	Not reported
Location Address 1:	402 LAFAYETTE ST
Code:	BP
Location Address 2:	SB37928
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004596144
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

CON EDISON (Continued) **S117066907**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/15/2014
Trans1 Recv Date:	07/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004596144
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608363GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C106 **A&P SERVICE STATION** **NY UST** **U001839563**
WSW **8 BOND ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.066 mi.
349 ft. **Site 17 of 28 in cluster C**

Relative:
Lower

Actual:
41 ft.

UST:

Id/Status:	2-346950 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584942.19688
UTM Y:	4508938.81582
Site Type:	Unknown

Affiliation Records:

Site Id:	16985
Affiliation Type:	Facility Owner
Company Name:	POLMAR REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	35 WOODHAVEN DR
Address2:	Not reported
City:	NEW CITY
State:	NY
Zip Code:	10956
Country Code:	001
Phone:	(914) 634-6671
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16985
Affiliation Type:	Mail Contact
Company Name:	POLMAR REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	35 WOODHAVEN DR
Address2:	Not reported
City:	NEW CITY
State:	NY
Zip Code:	10956
Country Code:	001
Phone:	(914) 634-6671
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16985
Affiliation Type:	Facility Operator
Company Name:	A&P SERVICE STATION
Contact Type:	Not reported
Contact Name:	A&P SERVICE STATION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

A&P SERVICE STATION (Continued) **U001839563**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-6420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16985
Affiliation Type:	Emergency Contact
Company Name:	POLMAR REALTY CORP
Contact Type:	Not reported
Contact Name:	ISAK GUTMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 634-6671
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	32965
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	03/01/1942
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

A&P SERVICE STATION (Continued) **U001839563**

Tank Number: 002
Tank ID: 32966
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 03/01/1942
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 32967
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

A&P SERVICE STATION (Continued) **U001839563**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	004
Tank ID:	32968
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	005
Tank ID:	32969
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	03/01/1942
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

A&P SERVICE STATION (Continued) **U001839563**

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

C107 **BASEMENT OF** **NY Spills** **S104503742**
WSW **8 BOND ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.066 mi.
349 ft. **Site 18 of 28 in cluster C**

Relative: **Lower**

Actual: **41 ft.**

SPILLS:

Facility ID:	9707584
Facility Type:	ER
Spill Number:	9707584
DER Facility ID:	127919
Site ID:	150434
DEC Region:	2
Closed Date:	1997-09-26
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	2401
Spill Date:	1997-09-26
Investigator:	KGHALE
Referred To:	Not reported
Reported to Dept:	1997-09-26
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-26
Spill Record Last Update:	2002-03-05
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KEN GOLDEN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HALE refer to 97-07585 & SP 00284."
Remarks:	"STRONG ODER OF GAS IN BASEMENT THINKS IT'S COMING FROM GAS STATION NEXTDOOR"

All Materials:

Site ID:	150434
Operable Unit ID:	1050927
Operable Unit:	01
Material ID:	329599

BASEMENT OF (Continued) **S104503742**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9707585
Facility Type:	ER
Spill Number:	9707585
DER Facility ID:	230570
Site ID:	284299
DEC Region:	2
Closed Date:	1998-02-25
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	3101
Spill Date:	1997-09-25
Investigator:	KGHALE
Referred To:	Not reported
Reported to Dept:	1997-09-26
CID:	323
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-26
Spill Record Last Update:	2002-03-05
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KENNETH GOLDING
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HALE VAPORS ENTERED BUILDING THROUGH LEAKS IN SEWERMAIN. SEWERMAIN WAS SEALED AND VAPORS NO LONGER A PROBLEM. Tank test and subsurface investigation concluded that tanks were not the source of the problem. No subsurface contamination was found. It was concluded that the bay system on the station, that was closed by the DEC, was the vapor pathway into the sewer and subsequently into the building."
Remarks:	"GAS FUMES ARE ENTERING INTO THE BASMENT OF THE CALLERS BUILDING. UNKNOWN HOW, POSS FROM GAS STATION NEXT DOOR."

All Materials:

Site ID:	284299
Operable Unit ID:	1050928
Operable Unit:	01
Material ID:	329600
Material Code:	0066A
Material Name:	unknown petroleum

BASEMENT OF (Continued) **S104503742**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F108 **CON EDISON SERVICE BOX: 26836** **NJ MANIFEST** **S117986770**
SSE **334 BOWERY FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.067 mi.
355 ft. **Site 13 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004274403
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456415JJK
EPA ID:	NYP004274403
Date Shipped:	10/17/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON SERVICE BOX: 26836 (Continued) **S117986770**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,500.00 Pounds

F109 **CON EDISON SERVICE BOX: 26837** **NJ MANIFEST** **S117986769**
SSE **334 BOWERY FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.067 mi.
355 ft. **Site 14 of 28 in cluster F**

Relative: **Higher**

Actual: **42 ft.**

NJ MANIFEST:

EPA Id:	NYP004274395
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456416JJK
EPA ID:	NYP004274395
Date Shipped:	10/17/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

CON EDISON SERVICE BOX: 26837 (Continued) **S117986769**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	2,000.00 Pounds

C110 **PENSKE TRUCK LEASING CO.,L.P.** **NY UST U003074580**
SSW **23 BOND STREET** **NY AST N/A**
< 1/8 **NEW YORK, NY 10012**
0.068 mi.
357 ft. **Site 19 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

UST:

Id/Status:	2-401269 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584988.98806
UTM Y:	4508894.72242
Site Type:	Other

Affiliation Records:

Site Id:	19176

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

Affiliation Type:	Facility Owner
Company Name:	PENSKE TRUCK LEASING CO.,L.P.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	ROUTE 10, GREEN HILLS, PO BOX 563
Address2:	Not reported
City:	READING
State:	PA
Zip Code:	19603-0563
Country Code:	001
Phone:	(610) 775-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19176
Affiliation Type:	Mail Contact
Company Name:	PENSKE TRUCK LEASING CO.,L.P.
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL SERVICES
Address1:	RT 10,GREEN HILLS,PO BOX 563
Address2:	Not reported
City:	READING
State:	PA
Zip Code:	19603
Country Code:	001
Phone:	(215) 775-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19176
Affiliation Type:	Facility Operator
Company Name:	PENSKE TRUCK LEASING CO.,L.P.
Contact Type:	Not reported
Contact Name:	JOHN MAHER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 420-9622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19176
Affiliation Type:	Emergency Contact
Company Name:	PENSKE TRUCK LEASING CO.,L.P.
Contact Type:	Not reported
Contact Name:	MARC E. ALTHEN
Address1:	Not reported
Address2:	Not reported

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(610) 775-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	21779
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1983
Date Tank Closed:	06/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	21780
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1983
Date Tank Closed:	06/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 21781
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1964
Date Tank Closed: 06/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 004
Tank ID: 21782
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1964
Date Tank Closed: 06/01/1994

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 005
Tank ID: 21783
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1964
Date Tank Closed: 06/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None

AST:
Region: STATE

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-401269
Program Type: PBS
UTM X: 584988.98806
UTM Y: 4508894.72242
Expiration Date: N/A
Site Type: Other

Affiliation Records:

Site Id: 19176
Affiliation Type: Facility Owner
Company Name: PENSKE TRUCK LEASING CO.,L.P.
Contact Type: Not reported
Contact Name: Not reported
Address1: ROUTE 10, GREEN HILLS, PO BOX 563
Address2: Not reported
City: READING
State: PA
Zip Code: 19603-0563
Country Code: 001
Phone: (610) 775-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 19176
Affiliation Type: Mail Contact
Company Name: PENSKE TRUCK LEASING CO.,L.P.
Contact Type: Not reported
Contact Name: ENVIRONMENTAL SERVICES
Address1: RT 10,GREEN HILLS,PO BOX 563
Address2: Not reported
City: READING
State: PA
Zip Code: 19603
Country Code: 001
Phone: (215) 775-6000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 19176
Affiliation Type: Facility Operator
Company Name: PENSKE TRUCK LEASING CO.,L.P.
Contact Type: Not reported
Contact Name: JOHN MAHER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 420-9622
EMail: Not reported
Fax Number: Not reported

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	19176
Affiliation Type:	Emergency Contact
Company Name:	PENSKE TRUCK LEASING CO.,L.P.
Contact Type:	Not reported
Contact Name:	MARC E. ALTHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(610) 775-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	00A
Tank Id:	21784
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other
Tank Number:	00B
Tank Id:	21785
Material Code:	9999

PENSKE TRUCK LEASING CO.,L.P. (Continued) **U003074580**

Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other

C111 **CON EDISON SERVICE BOX: 26611** **RCRA NonGen / NLR** **1016148843**
SSW **23 BOND ST FRONT OF** **NY MANIFEST** **NYP004274940**
< 1/8 **NEW YORK, NY 10012**
0.068 mi.
357 ft. **Site 20 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26611
Facility address:	23 BOND ST FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004274940
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON SERVICE BOX: 26611 (Continued) **1016148843**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/19/2012
Site name: CON EDISON SERVICE BOX: 26611
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004274940
Facility Status: Not reported
Location Address 1: F/O 25 BOND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004274940
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/19/2012
Trans1 Recv Date: 10/19/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/19/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CON EDISON SERVICE BOX: 26611 (Continued) **1016148843**

Generator EPA ID:	NYP004274940
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456407JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C112 **CON EDISON SERVICE BOX: 26611** **NJ MANIFEST** **S117986795**
SSW **23 BOND ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.068 mi.
357 ft. **Site 21 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004274940
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON SERVICE BOX: 26611 (Continued) **S117986795**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456401JJK
EPA ID:	NYP004274940
Date Shipped:	10/22/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,500.00 Pounds

Manifest Number:	010456407JJK
EPA ID:	NYP004274940
Date Shipped:	10/19/2012

CON EDISON SERVICE BOX: 26611 (Continued) **S117986795**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	500.00 Pounds

C113 **PENSKE TRUCK LEASING CO L P** **RCRA NonGen / NLR** **1000382745**
SSW **23 BOND ST** **FINDS** **NYD981563455**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.068 mi. **NY MANIFEST**
357 ft. **Site 22 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PENSKE TRUCK LEASING CO L P
Facility address:	23 BOND ST NEW YORK, NY 10012-2474

PENSKE TRUCK LEASING CO L P (Continued) **1000382745**

EPA ID: NYD981563455
Mailing address: W 26TH ST
NEW YORK, NY 10001-9998
Contact: Not reported
Contact address: W 26TH ST
NEW YORK, NY 10001-9998
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PENSKE TRUCK LEASING CO LP
Owner/operator address: RTE 10 GREEN HILLS PO BOX 563
READING, PA 19603
Owner/operator country: US
Owner/operator telephone: 215-775-6380
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PENSKE TRUCK LEASING CO LP
Owner/operator address: RTE 10 GREEN HILLS PO BOX 563
READING, PA 19603
Owner/operator country: US
Owner/operator telephone: 215-775-6380
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

PENSKE TRUCK LEASING CO L P (Continued) **1000382745**

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PENSKE TRUCK LEASING CO L P
Classification: Not a generator, verified

Date form received by agency: 02/27/1995
Site name: PENSKE TRUCK LEASING CO L P
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 08/15/1991
Site name: PENSKE TRUCK LEASING CO L P
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004409916

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PENSKE TRUCK LEASING CO L P (Continued) **1000382745**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000382745
Registry ID:	110004409916
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004409916

NY MANIFEST:

Country:	USA
EPA ID:	NYD981563455
Facility Status:	Not reported
Location Address 1:	23 BOND STREET ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981563455
Mailing Name:	PENSKE TRUCK LEASING CO
Mailing Contact:	JAMES SVAASAND
Mailing Address 1:	536 WEST 26TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127419837

NY MANIFEST:

Document ID:	NYB6610752
Manifest Status:	C
seq:	Not reported
Year:	1994
Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	08/16/1994
Trans1 Recv Date:	08/16/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/16/1994
Part A Recv Date:	10/03/1994
Part B Recv Date:	08/24/1994
Generator EPA ID:	NYD981563455
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

PENSKE TRUCK LEASING CO L P (Continued) **1000382745**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
46 additional NY_MANIFEST: record(s) in the EDR Site Report.

B114 **54 EAST 4 ST** **NY AST** **U003390648**
ESE **54 EAST 4 ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.068 mi.
358 ft. **Site 14 of 14 in cluster B**

Relative: **Lower**
Actual: **41 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-160776
Program Type:	PBS
UTM X:	585212.59411
UTM Y:	4508911.65503
Expiration Date:	12/05/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5506
Affiliation Type:	Facility Operator
Company Name:	54 EAST 4 ST
Contact Type:	Not reported
Contact Name:	LENIN ENAMORADO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 343-1336
EMail:	Not reported
Fax Number:	Not reported

54 EAST 4 ST (Continued) **U003390648**

Modified By:	CGFREEDM
Date Last Modified:	2016-06-16
Site Id:	5506
Affiliation Type:	Emergency Contact
Company Name:	EAST MANHATTAN HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	THOMAS J. CARACCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 343-1337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-06-16
Site Id:	5506
Affiliation Type:	Facility Owner
Company Name:	EAST MANHATTAN HOLDINGS LLC
Contact Type:	MANAGER
Contact Name:	THOMAS J. CARACCIO
Address1:	253-11 80TH AVENUE
Address2:	Not reported
City:	GLEN OAKS
State:	NY
Zip Code:	11004
Country Code:	001
Phone:	(718) 343-1336
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-06-16
Site Id:	5506
Affiliation Type:	Mail Contact
Company Name:	EAST MANHATTAN HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	THOMAS J. CARACCIO
Address1:	PO BOX 3557
Address2:	Not reported
City:	NEW HYDE PARK
State:	NY
Zip Code:	11040
Country Code:	001
Phone:	(718) 343-1337
EMail:	TOMC@VIKMGT.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-06-16

Tank Info:

Tank Number:	001

54 EAST 4 ST (Continued) **U003390648**

Tank Id:	19707
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	1
Tank Type:	Steel Tank in Concrete
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	03/01/1953
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

G115 **HOMELESS SHELTER** **NY Spills** **S110488537**
ESE **I/F/O 8 EAST 3RD ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.068 mi.
359 ft. **Site 2 of 12 in cluster G**

Relative: **Lower**
Actual: **41 ft.**

SPILLS:

Facility ID:	1002106
Facility Type:	ER
Spill Number:	1002106
DER Facility ID:	390101
Site ID:	435205
DEC Region:	2
Closed Date:	2010-05-26
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2010-05-24
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2010-05-24
CID:	Not reported

HOMELESS SHELTER (Continued) **S110488537**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-24
Spill Record Last Update:	2010-05-26
Spiller Name:	FIREFIGHTER HOURIGAN
Spiller Company:	HOMELESS SHELTER
Spiller Address:	I/F/O 8 EAST 3RD ST
Spiller Company:	999
Contact Name:	FIREFIGHTER HOURIGAN
DEC Memo:	"PBS 2-601677 expired. spoke with FF Hurigan. FD recovered oil into two drums and left the drums at the scene.Spill was from the vent on sidewalk. No spill in the building.No soil was impacted.Spill occurred while transferring oil from one tank to other.No delivery was made. 05/26/10 Spoke with Stan, (718)688-8638. Dept of Homeless Services retained a contractor to remove the drums with oil.Mr. Stan confirmed me that there is no soil impact at the site,no odor in the building.Tank tightness testing was done recently.Disposal manifest will be sent to DEC. Case closed as there is no contamination left at the site.(sr)"
Remarks:	"Caller reporting a spill of 75 gallons of #2 fuel oil to street. Clean up in progress."

All Materials:

Site ID:	435205
Operable Unit ID:	1185995
Operable Unit:	01
Material ID:	2180762
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

H116 **39 EAST 4TH ST.** **NY UST** **U001831531**
ENE **39 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.069 mi.
364 ft. **Site 1 of 26 in cluster H**

Relative: **Lower**
Actual: **41 ft.**

UST:

Id/Status:	2-055174 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585139.09685
UTM Y:	4509003.57824

39 EAST 4TH ST. (Continued) **U001831531**

Site Type: Other

Affiliation Records:

Site Id: 813
Affiliation Type: Facility Owner
Company Name: 10-12 COOPER SQUARE INC. % SOLIL MANAGEMENT
Contact Type: Not reported
Contact Name: Not reported
Address1: 640 5TH AVENUE, 3RD FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 265-2280
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-01-24

Site Id: 813
Affiliation Type: Mail Contact
Company Name: SOLIL MANAGEMENT
Contact Type: Not reported
Contact Name: RONALD J. LICHTMAN, DIRECTOR OF OPERATIONS
Address1: 640 FIFTH AVENUE
Address2: 3RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 265-1577
EMail: RLICHTMAN@SOLIL.COMJ
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-01-24

Site Id: 813
Affiliation Type: Facility Operator
Company Name: 39 EAST 4TH ST.
Contact Type: Not reported
Contact Name: GARY GREENE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-2280
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-01-24

Site Id: 813
Affiliation Type: Emergency Contact
Company Name: 10-12 COOPER SQUARE INC. % SOLIL MANAGEMENT
Contact Type: Not reported

39 EAST 4TH ST. (Continued) **U001831531**

Contact Name:	GARY GREENE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 265-2280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-01-24

Tank Info:

Tank Number:	001
Tank ID:	1756
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	1757
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

39 EAST 4TH ST. (Continued) **U001831531**

Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

H117 **FORMER COOPER HOTEL** **NY UST U004122421**
ENE **2 COOPER SQUARE** **NY AST N/A**
< 1/8 **NEW YORK, NY 10018**
0.069 mi.
364 ft. **Site 2 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

UST:
Id/Status: 2-610850 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585151.63102
UTM Y: 4508982.92114
Site Type: Other

Affiliation Records:
Site Id: 398400
Affiliation Type: Facility Owner
Company Name: TO BETTER DAYS, LLC
Contact Type: AGENT
Contact Name: Not reported
Address1: 155 AVENUE OF THE AMERICAS
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10013
Country Code: 001
Phone: (212) 625-0500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-12-29

Site Id: 398400
Affiliation Type: Mail Contact
Company Name: TO BETTER DAYS, LLC
Contact Type: Not reported

FORMER COOPER HOTEL (Continued) **U004122421**

Contact Name:	DANIEL GABAY
Address1:	155 AVENUE OF THE AMERICAS
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(212) 620-0500 253
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-29

Site Id:	398400
Affiliation Type:	Facility Operator
Company Name:	FORMER COOPER HOTEL
Contact Type:	Not reported
Contact Name:	K&K CONSTRUCTION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(999) 999-9999
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-05-29

Site Id:	398400
Affiliation Type:	Emergency Contact
Company Name:	TO BETTER DAYS, LLC
Contact Type:	Not reported
Contact Name:	JEFF SILVERMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 399-3361
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-05-29

Tank Info:

Tank Number:	2
Tank ID:	223316
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	06/02/2008
Registered:	True

FORMER COOPER HOTEL (Continued) **U004122421**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Number: 3
Tank ID: 228311
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: 06/02/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

FORMER COOPER HOTEL (Continued) **U004122421**

L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number:	4
Tank ID:	228312
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	06/02/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610850
Program Type:	PBS
UTM X:	585151.63102
UTM Y:	4508982.92114
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	398400
Affiliation Type:	Facility Owner
Company Name:	TO BETTER DAYS, LLC
Contact Type:	AGENT
Contact Name:	Not reported
Address1:	155 AVENUE OF THE AMERICAS
Address2:	Not reported
City:	NEW YORK

FORMER COOPER HOTEL (Continued) **U004122421**

State: NY
Zip Code: 10013
Country Code: 001
Phone: (212) 625-0500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-12-29

Site Id: 398400
Affiliation Type: Mail Contact
Company Name: TO BETTER DAYS, LLC
Contact Type: Not reported
Contact Name: DANIEL GABAY
Address1: 155 AVENUE OF THE AMERICAS
Address2: 3RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10013
Country Code: 001
Phone: (212) 620-0500 253
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-12-29

Site Id: 398400
Affiliation Type: Facility Operator
Company Name: FORMER COOPER HOTEL
Contact Type: Not reported
Contact Name: K&K CONSTRUCTION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (999) 999-9999
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 2008-05-29

Site Id: 398400
Affiliation Type: Emergency Contact
Company Name: TO BETTER DAYS, LLC
Contact Type: Not reported
Contact Name: JEFF SILVERMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 399-3361
EMail: Not reported
Fax Number: Not reported

FORMER COOPER HOTEL (Continued) **U004122421**

Modified By: dxliving
Date Last Modified: 2008-05-29

Tank Info:

Tank Number: 1
Tank Id: 223314
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/02/2008
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

H118 **FORMER HOTEL** **NY Spills** **S109063115**
ENE **2 COOPER SQUARE** **N/A**
< 1/8 **MANHATTEN, NY**
0.069 mi.
364 ft. **Site 3 of 26 in cluster H**

Relative: **Lower**
Actual: **41 ft.**

SPILLS:
Facility ID: 0802061
Facility Type: ER
Spill Number: 0802061
DER Facility ID: 347507
Site ID: 398133
DEC Region: 2
Closed Date: 2009-05-20
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 3101
Spill Date: 2008-05-22
Investigator: vszhune

FORMER HOTEL (Continued) **S109063115**

Referred To:	Not reported
Reported to Dept:	2008-05-22
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-22
Spill Record Last Update:	2011-12-08
Spiller Name:	JEFF SILVERMAN
Spiller Company:	FORMER HOTEL
Spiller Address:	2 COOPER SQUARE
Spiller Company:	001
Contact Name:	JEFF SILVERMAN
DEC Memo:	"5/22/08 - Raphael Ketani. I spoke to Pete Lakotos of Terms Environmental (908) 464-0028. He said that the construction crew was digging and just uncovered the 1000 gal. tank. It used to contain heating oil. They did a tank test and it failed. The contaminated soil will be put on a plastic tarp and cover with plastic. A soil sample has been sent off for soil characterization. Once the analyticals come back, they will know where to send the soil and the soil will be removed from the site. They also found 3 more tanks. These tanks are encased in and filled with concrete. They will be pulled out and put on the side of the property for disposal. As far as he knows, they didn't leak. He will submit a PBS registration form to Albany DER. The site is owned by To Better Days, LLC, 155 Avenue of the Americas, NY, 10013. 5/27/08 - Raphael Ketani. I sent a CSL to the owners. 5/30/08 - Raphael Ketani. The CSL came back marked Insufficient Address. I called up Mr. Lakotos and asked him what the full address is. He stated that the owners were on the third floor. I changed the date, added 3rd Floor to the address, and resent the letter. 8/19/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The case manager needs to make followup calls to see what progress has been made in the investigation. The owner owes DEC an investigation report, and a new PBS registration. 12/04/08-Zhune spoke to Pete from Term Environmental Service He said tanks were pull out contaminated soil was removed, samples were taken everything is done. The report will be send within two days. 12/04/08-Zhune spoke to Jeff Silverman he said a 15 story rental building will be build in these site. 04/16/09- Terms Environmental Service Inc. sent the July 19,2008 UST Closure and Remedial Action Report. From May 20, to June 4, 2008, respresentatives from Term were present at the subject site to everdee the (4) UST removals. The three (3) abandoned 500 gallon gasoline UST's were observed to have no holes and no evidence of discharge were noted. Four soil samples were collected (S1,S2,S3 and S4) from sidewalls of the pad at depths 13 to 13.5 fbg. Three base samples (S5,S6,S7) were collected at a depth of 13.5 to 14 fbg. The results of these samples revealed that VOC's are well below the RSCO's. Although levels of SVOc's were detected slightly exceeding the RSCO's standard in samples S1, S2, S4, S5(Benzo(a)antracene, Chrysene, Benzo(a)pyrene, Dibenzo(a,h) anthracene), samples

FORMER HOTEL (Continued) **S109063115**

S3-S6(Benzo(a)pyrene) and sample S7(Benzo(a)pyrene, Chrysene). The one (1) 1000 galoon #2 heating oil UST was observed to have holes in the sidewalls and the soil were noted to be stained and odiferous. Six post excavation samples were collected in total. S1,S2,S3,S4 were collected from the sidewalls of the excavation at a depth of 14.5-15 fbg. S5 and S6 were collected at the base of the excavation beneath the invert former UST at depths 15- 15.5 fbg. The analytical test results revealed that all post excavation soil samples were below the RSCO's Standard for VOC's and SVOC's. Water was no ecountered during remedial activities to a depth of 25 ftbg. Engineering core samples collected at the site reported groundwater to be at approximately 33 fbg. Spill Closed. 12/08/11-Vought-Received call from Daniel Gabay (PH: 917-403-4554) representing Atlantic Development Group) developer and he is requesting a formal closure letter as soon as possible. "

Remarks: "TANK HAD HOLES AND CONTAMINATED SOPIL"

All TTF:

Facility ID:	0802061
Spill Number:	0802061
Spill Tank Test:	2486168
Site ID:	398133
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	398133
Operable Unit ID:	1155036
Operable Unit:	01
Material ID:	2145881
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F119 **CON EDISON SERVICE BOX: 26615** **RCRA NonGen / NLR** **1016967422**
South **39 BOND ST** **NY MANIFEST** **NYP004410379**
< 1/8 **NEW YORK, NY 10012**
0.069 mi.
365 ft. **Site 15 of 28 in cluster F**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/23/2014
Facility name:	CON EDISON SERVICE BOX: 26615
Facility address:	39 BOND ST NEW YORK, NY 10012
EPA ID:	NYP004410379
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/23/2013
Site name:	CON EDISON SERVICE BOX: 26615
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004410379
Facility Status:	Not reported
Location Address 1:	F/O 39 BOND ST
Code:	BP
Location Address 2:	SB26615
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012

CON EDISON SERVICE BOX: 26615 (Continued) **1016967422**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004410379
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 12/23/2013
Trans1 Recv Date: 12/23/2013
Trans2 Recv Date: 12/30/2013
TSD Site Recv Date: 12/30/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004410379
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002299878GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 200
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 26615 (Continued) **1016967422**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E120 **700 BROADWAY/MANHATTAN** **NY Spills** **S102141591**
NNW **700 BROADWAY** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.070 mi.
367 ft. **Site 9 of 23 in cluster E**

Relative: **Lower**
Actual: **41 ft.**

SPILLS:

Facility ID:	9003151
Facility Type:	ER
Spill Number:	9003151
DER Facility ID:	235358
Site ID:	290665
DEC Region:	2
Closed Date:	1998-02-04
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3101
Spill Date:	1990-05-30
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1990-06-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-06-27
Spill Record Last Update:	1998-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"NATIONAL SURFACE CLEANING TO CLEAN AS SOON AS POSSIBLE, ASBESTOS IN THE BASEMENT TOO."

All Materials:

Site ID:	290665
Operable Unit ID:	941036
Operable Unit:	01

700 BROADWAY/MANHATTAN (Continued) **S102141591**

Material ID:	437862
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

E121 **NATIONAL AUDUBON SOCIETY** **NY UST** **U001841017**
NNW **700 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.070 mi.
367 ft. **Site 10 of 23 in cluster E**

Relative: UST:
Lower
Actual: Id/Status: 2-481254 / Unregulated/Closed
41 ft. Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584971.35105
UTM Y: 4509136.54186
Site Type: Unknown

Affiliation Records:

Site Id:	21510
Affiliation Type:	Facility Owner
Company Name:	NATIONAL AUDUBON SOCIETY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	700 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21510
Affiliation Type:	Mail Contact
Company Name:	NATIONAL AUDUBON SOCIETY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	700 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	Not reported
EMail:	Not reported

NATIONAL AUDUBON SOCIETY (Continued) **U001841017**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21510
Affiliation Type:	Facility Operator
Company Name:	NATIONAL AUDUBON SOCIETY
Contact Type:	Not reported
Contact Name:	NATIONAL AUDUBON SOCIETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21510
Affiliation Type:	Emergency Contact
Company Name:	NATIONAL AUDUBON SOCIETY
Contact Type:	Not reported
Contact Name:	NATIONAL AUDUBON SOCIETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	41122
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

NATIONAL AUDUBON SOCIETY (Continued) **U001841017**

Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 41123
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 250
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
G99 - Tank Secondary Containment - Other
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None

C122 **CON EDISON SERVICE BOX: 26609** **NJ MANIFEST** **S117986793**
SW **19 BOND ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.071 mi.
374 ft. **Site 23 of 28 in cluster C**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:
EPA Id: NYP004274924
Mail Address: IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: BENJAMIN BAMONTE

CON EDISON SERVICE BOX: 26609 (Continued) **S117986793**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456408JJK
EPA ID:	NYP004274924
Date Shipped:	10/19/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

C123 **CON EDISON SERVICE BOX: 26609** **RCRA NonGen / NLR** **1016148841**
SW **19 BOND ST FRONT OF** **FINDS** **NYP004274924**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.071 mi. **NY MANIFEST**
374 ft. **Site 24 of 28 in cluster C**

Relative: Higher

Actual: 42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26609
Facility address:	19 BOND ST FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004274924
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/19/2012
Site name:	CON EDISON SERVICE BOX: 26609
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055457081

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 26609 (Continued) **1016148841**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016148841
Registry ID:	110055457081
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055457081

NY MANIFEST:

Country:	USA
EPA ID:	NYP004274924
Facility Status:	Not reported
Location Address 1:	F/O 19 BOND ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004274924
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2012
Trans1 Recv Date:	10/19/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004274924
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456408JJK
Import Indicator:	N
Export Indicator:	N

CON EDISON SERVICE BOX: 26609 (Continued) **1016148841**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

F124 **35 BOND STREET CORP.** **NY AST** **U004081817**
South **35 BOND ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.071 mi.
375 ft. **Site 16 of 28 in cluster F**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-329193
Program Type:	PBS
UTM X:	585010.00481
UTM Y:	4508841.89593
Expiration Date:	02/03/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	15451
Affiliation Type:	Facility Operator
Company Name:	35 BOND STREET CORP.
Contact Type:	Not reported
Contact Name:	DENISE MARTIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

35 BOND STREET CORP. (Continued) **U004081817**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-02-13

Site Id: 15451
Affiliation Type: Emergency Contact
Company Name: 35 BOND STREET CORP.
Contact Type: Not reported
Contact Name: ANDREWS ORG.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-02-13

Site Id: 15451
Affiliation Type: Mail Contact
Company Name: ANDREWS ORGANIZATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 666 BROADWAY
Address2: 12TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-02-13

Site Id: 15451
Affiliation Type: Facility Owner
Company Name: 35 BOND STREET CORP.
Contact Type: SENIOR PROPERTY MANAGER
Contact Name: DANA GORDON
Address1: 35 BOND STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported

35 BOND STREET CORP. (Continued) **U004081817**

Modified By: MFLEONAR
Date Last Modified: 2018-02-13

Tank Info:

Tank Number: 001
Tank Id: 25703
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/25/1994
Capacity Gallons: 3000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 02/13/2018
Material Name: #2 fuel oil (on-site consumption)

F125 **SPILL NUMBER 9908485** **NY Spills** **S104649802**
South **35 BOND ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.071 mi.
375 ft. **Site 17 of 28 in cluster F**

Relative: **Higher**

Actual: **43 ft.**

SPILLS:
Facility ID: 9908485
Facility Type: ER
Spill Number: 9908485
DER Facility ID: 218738
Site ID: 268512
DEC Region: 2
Closed Date: 1999-10-13
Spill Cause: Unknown
Spill Class: C4
SWIS: 3101
Spill Date: 1999-10-13
Investigator: JMKRIMGO

SPILL NUMBER 9908485 (Continued) **S104649802**

Referred To:	Not reported
Reported to Dept:	1999-10-13
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-13
Spill Record Last Update:	1999-10-13
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	UNKNOWN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"FIRE DEPT ON SCENE STATED UNKNOWN ACIDIC MATERIAL FOUND ON GROUND. CLEAND-UP BY FIRE DEPT."

All Materials:

Site ID:	268512
Operable Unit ID:	1082764
Operable Unit:	01
Material ID:	297603
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

H126 **CON EDISON** **NY MANIFEST** **S116550208**
East **11 COOPER SQ FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.071 mi.
376 ft. **Site 4 of 26 in cluster H**

Relative: **Lower**

Actual: **41 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004484739
Facility Status:	Not reported
Location Address 1:	F/O 11 COOPER SQ
Code:	BP
Location Address 2:	SB30950
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

CON EDISON (Continued) **S116550208**

NY MANIFEST:

EPAID:	NYP004484739
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2014
Trans1 Recv Date:	03/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004484739
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406213GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S116550208**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H127 **CON EDISON SERVICE BOX: 30950** **RCRA NonGen / NLR** **1017771533**
East **11 COOPER SQ FRONT OF** **NYP004484739**
< 1/8 **NEW YORK, NY 10003**
0.071 mi.
376 ft. **Site 5 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/30/2014
Facility name: CON EDISON SERVICE BOX: 30950
Facility address: 11 COOPER SQ FRONT OF
NEW YORK, NY 10003
EPA ID: NYP004484739
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/31/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 03/31/2014

CON EDISON SERVICE BOX: 30950 (Continued) **1017771533**

Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

C128 **SPILL NUMBER 9813854** **NY Spills** **S104648584**
WSW **1 BOND ST APT #6C** **N/A**
< 1/8 **MANHATTAN, NY**
0.072 mi.
382 ft. **Site 25 of 28 in cluster C**

Relative: **Lower**

Actual: **41 ft.**

SPILLS:

Facility ID:	9813854
Facility Type:	ER
Spill Number:	9813854
DER Facility ID:	104667
Site ID:	120559
DEC Region:	2
Closed Date:	2003-03-04
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-02-15
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1999-02-15
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-15
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	EVANSON STUDIOS
Spiller Address:	1 BOND ST 5TH FLOOR
Spiller Company:	001
Contact Name:	NICK TSANGARIS
DEC Memo:	""
Remarks:	"FUMES COMING INTO CALLERS APARTMENT - 6 STORY BLDG - FDNY HAS BEEN THERE BEFORE FOR AN EXPLOSION - THE STUDIO DOES ANTIQUE RESTORATION AND/OR ASSEMBLY - VERY STRONG ODOR"

All Materials:

Site ID:	120559
Operable Unit ID:	1071396
Operable Unit:	01
Material ID:	310563
Material Code:	0059A
Material Name:	solvents
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G

SPILL NUMBER 9813854 (Continued) **S104648584**

Recovered:	.00
Oxygenate:	Not reported
Site ID:	120559
Operable Unit ID:	1071396
Operable Unit:	01
Material ID:	310562
Material Code:	0056A
Material Name:	paint thinners
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D129 **708 BROADWAY** **NY AST** **U003395285**
NNE **708 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.073 mi.
383 ft. **Site 6 of 7 in cluster D**

Relative: **Higher**
Actual: **42 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-481904
Program Type:	PBS
UTM X:	584992.21626
UTM Y:	4509173.08431
Expiration Date:	10/21/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21570
Affiliation Type:	Facility Operator
Company Name:	708 BROADWAY
Contact Type:	Not reported
Contact Name:	KRZYSZTOF TOMCZAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 998-1001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-12
Site Id:	21570
Affiliation Type:	Mail Contact
Company Name:	STEPHANIE KUNG
Contact Type:	Not reported
Contact Name:	NEW YORK UNIVERSITY
Address1:	10 ASTOR PLACE 6TH FLOOR

708 BROADWAY (Continued) **U003395285**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-12

Site Id:	21570
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	MELISA PUGLISI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 484-0561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Site Id:	21570
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	ASSISTANT DIRECTOR EHS
Contact Name:	STEPHANIE KUNG
Address1:	70 WASHINTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-12

Tank Info:

Tank Number:	001
Tank Id:	39228
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

708 BROADWAY (Continued) **U003395285**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/15/1955
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

I130 **JORDAN REALTY LLC** **NY AST** **U003387012**
West **676 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.074 mi.
392 ft. **Site 1 of 13 in cluster I**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-236411
Program Type:	PBS
UTM X:	584911.32728
UTM Y:	4509008.73726
Expiration Date:	10/12/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8758
Affiliation Type:	Mail Contact
Company Name:	DITMAS MGMT CORP
Contact Type:	Not reported
Contact Name:	AARON T SIRULNICK
Address1:	3333 NEW HYDE PARK RD
Address2:	Not reported
City:	NEW HYDE PARK
State:	NY
Zip Code:	11042
Country Code:	001
Phone:	(516) 374-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-12

Site Id:	8758

JORDAN REALTY LLC (Continued) **U003387012**

Affiliation Type:	Facility Operator
Company Name:	JORDAN REALTY LLC
Contact Type:	Not reported
Contact Name:	LUIS DELACRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 641-2133
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-12

Site Id:	8758
Affiliation Type:	Emergency Contact
Company Name:	JORDAN REALTY LLC
Contact Type:	Not reported
Contact Name:	LUIS DELACRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 562-1216
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-12

Site Id:	8758
Affiliation Type:	Facility Owner
Company Name:	JORDAN REALTY LLC
Contact Type:	MEMBER
Contact Name:	AARON SIRULNICK
Address1:	3333 NEW HYDE PARK RD
Address2:	Not reported
City:	NEW HYDE PARK
State:	NY
Zip Code:	11042
Country Code:	001
Phone:	(516) 374-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-12

Tank Info:

Tank Number:	001
Tank Id:	11113
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

JORDAN REALTY LLC (Continued) **U003387012**

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1970
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

C131 **VAULT 9133** **NY Spills** **S113818685**
WSW **3 BOND ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.074 mi.
393 ft. **Site 26 of 28 in cluster C**

Relative: **Lower**

Actual: **41 ft.**

SPILLS:

Facility ID:	1303593
Facility Type:	ER
Spill Number:	1303593
DER Facility ID:	439269
Site ID:	484086
DEC Region:	2
Closed Date:	2013-08-15
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2013-07-04
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2013-07-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

VAULT 9133 (Continued) **S113818685**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-07-04
Spill Record Last Update:	2013-08-15
Spiller Name:	ERT
Spiller Company:	CONEDISON
Spiller Address:	4 IRVING PL
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"8/15/13 - Austin - 25 gals atop 100 gals of water in transformer vault, leaked from porous transformer unit - Con Ed contained and cleaned up the spill, and removed the transformer - See eDocs files for further information - Spill closed - end"
Remarks:	"25gal of oil on top of 100gal of water contained to the vault. Clean up is pending sample analysis."

All Materials:

Site ID:	484086
Operable Unit ID:	1233773
Operable Unit:	01
Material ID:	2232703
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

I132 **684 BROADWAY OWNERS CORP** **NY AST** **U003396851**
WNW **684 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.076 mi.
399 ft. **Site 2 of 13 in cluster I**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602825
Program Type:	PBS
UTM X:	584910.29866
UTM Y:	4509039.11922
Expiration Date:	11/20/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24780
Affiliation Type:	Facility Owner
Company Name:	684 OWNERS CORPORATION C/O ANDREWS BUILDING CORP
Contact Type:	MANAGING AGENT
Contact Name:	EDWARD ZIMMERMAN
Address1:	666 BROADWAY 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY

684 BROADWAY OWNERS CORP (Continued) **U003396851**

Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	24780
Affiliation Type:	Facility Operator
Company Name:	684 OWNERS CORPORATION
Contact Type:	Not reported
Contact Name:	FRANK BURAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	24780
Affiliation Type:	Emergency Contact
Company Name:	684 OWNERS CORPORATION C/O ANDREWS BUILDING CORP
Contact Type:	Not reported
Contact Name:	ANDREWS ORG.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	24780
Affiliation Type:	Mail Contact
Company Name:	ANDREWS ORGANIZATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR

684 BROADWAY OWNERS CORP (Continued) **U003396851**

Date Last Modified: 2018-02-13

Tank Info:

Tank Number: 001
Tank Id: 16849
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1996
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 001
Tank Id: 51773
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

684 BROADWAY OWNERS CORP (Continued) **U003396851**

Install Date:	04/23/1984
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Affiliation Records:

Site Id:	6457
Affiliation Type:	Facility Owner
Company Name:	684 BROADWAY OWNERS CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	C/O ANDREWS BLDG CORP/382 LAFAYETTE ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6457
Affiliation Type:	Mail Contact
Company Name:	684 BROADWAY OWNERS CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	C/O ANDREWS BLDG CORP
Address2:	382 LAFAYETTE STREET
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 777-2000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6457
Affiliation Type:	Facility Operator
Company Name:	684 BROADWAY OWNERS CORP
Contact Type:	Not reported
Contact Name:	684 BROADWAY OWNERS CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

684 BROADWAY OWNERS CORP (Continued) **U003396851**

Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6457
Affiliation Type:	Emergency Contact
Company Name:	684 BROADWAY OWNERS CORP
Contact Type:	Not reported
Contact Name:	MARGARET GILMARTIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 734-5750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	16849
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B05 - Tank External Protection - Jacketed
	I05 - Overfill - Vent Whistle
	C01 - Pipe Location - Aboveground
	G00 - Tank Secondary Containment - None
	H00 - Tank Leak Detection - None
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	001

684 BROADWAY OWNERS CORP (Continued) **U003396851**

Tank Id: 51773
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/23/1984
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MRBARROW
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

E133 **CON EDISON SERVICE BOX: 28806** **RCRA NonGen / NLR** **1016974182**
WNW **686-88 BROADWAY & GT JONES ST N OF** **NY MANIFEST** **NYP004479952**
< 1/8 **NEW YORK, NY 10012**
0.076 mi.
400 ft. **Site 11 of 23 in cluster E**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:
Date form received by agency: 04/26/2014
Facility name: CON EDISON SERVICE BOX: 28806
Facility address: 686-88 BROADWAY & GT JONES ST N OF
NEW YORK, NY 10012
EPA ID: NYP004479952
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CON EDISON SERVICE BOX: 28806 (Continued) **1016974182**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/26/2014
Site name: CON EDISON SERVICE BOX: 28806
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004479952
Facility Status: Not reported
Location Address 1: 686-88 BROADWAY & JONES ST
Code: BP
Location Address 2: SB28806
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004479952
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported

CON EDISON SERVICE BOX: 28806 (Continued) **1016974182**

Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004479952
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406087GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

D134 **409 LAFAYETTE ST ASSOCIATES** **NY AST** **U004045525**
NNE **409 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10036**
0.076 mi.
401 ft. **Site 7 of 7 in cluster D**

Relative: AST:
Lower

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-335657
Program Type:	PBS

Actual:
41 ft.

409 LAFAYETTE ST ASSOCIATES (Continued) **U004045525**

UTM X: 585131.72427
UTM Y: 4509152.81435
Expiration Date: N/A
Site Type: Other

Affiliation Records:

Site Id: 16016
Affiliation Type: Facility Owner
Company Name: 409 LAFAYETTE ST ASSOCIATES
Contact Type: Not reported
Contact Name: Not reported
Address1: 30 WEST 26TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 308-2154
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16016
Affiliation Type: Mail Contact
Company Name: 409 LAFAYETTE ST ASSOCIATES
Contact Type: Not reported
Contact Name: MERINGOFF PROPERTIES
Address1: 30 WEST 26TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 645-7575
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16016
Affiliation Type: Facility Operator
Company Name: 409 LAFAYETTE ST ASSOCIATES
Contact Type: Not reported
Contact Name: MERIN GOFF PROP.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 505-0377
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16016

409 LAFAYETTE ST ASSOCIATES (Continued) **U004045525**

Affiliation Type:	Emergency Contact
Company Name:	409 LAFAYETTE ST ASSOCIATES
Contact Type:	Not reported
Contact Name:	NICK STEFANOV
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 645-7575
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	20995
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

H135 **SPILL NUMBER 0204004** **NY Spills** **S106005653**
ENE **20 COOPER SQUARE** **N/A**
< 1/8 **MANHATTAN, NY**
0.076 mi.
402 ft. **Site 6 of 26 in cluster H**

Relative: **Lower**

Actual: **41 ft.**

SPILLS:

Facility ID:	0204004
Facility Type:	ER
Spill Number:	0204004
DER Facility ID:	202362
Site ID:	246396
DEC Region:	2
Closed Date:	2003-05-16
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2002-07-16
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-07-17
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-17
Spill Record Last Update:	2004-03-22
Spiller Name:	ALAN STARKMAN
Spiller Company:	Not reported
Spiller Address:	20 COOPER SQ
Spiller Company:	001
Contact Name:	ALAN STARKMAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 5/16/03 TJD Spill summary and disposal manifest in file. No further action required."
Remarks:	"problem with oil tank in a vault further investigation to follow"

All Materials:

Site ID:	246396
Operable Unit ID:	855268
Operable Unit:	01
Material ID:	518264
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H136 **NY UNIV** **NY AST** **S107781589**
ENE **20 COOPER SQ** **NY Spills** **N/A**
< 1/8 **NEW YORK, NY**
0.076 mi.
402 ft. **Site 7 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-234664
Program Type:	PBS
UTM X:	585235.99023
UTM Y:	4509075.74393
Expiration Date:	11/08/2019
Site Type:	School

Affiliation Records:

Site Id:	8604
Affiliation Type:	Facility Operator
Company Name:	20 COOPER SQ
Contact Type:	Not reported
Contact Name:	JOSE R. SILVA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 985-3424
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-03-06

Site Id:	8604
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	STEPHANIE KUNG
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Site Id:	8604
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	MELISA PUGLISI
Address1:	Not reported
Address2:	Not reported
City:	Not reported

NY UNIV (Continued) **S107781589**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 484-0561
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2017-11-16

Site Id: 8604
Affiliation Type: Facility Owner
Company Name: NEW YORK UNIVERSITY
Contact Type: ASSISTANT DIRECTOR
Contact Name: STEPHANIE KUNG
Address1: 70 WASHINGTON SQUARE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 998-1212
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2017-11-16

Tank Info:

Tank Number: 001
Tank Id: 12594
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I05 - Overfill - Vent Whistle
G02 - Tank Secondary Containment - Vault (w/access)
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1964
Capacity Gallons: 8000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported

NY UNIV (Continued) **S107781589**

Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	57168
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/25/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SPILLS:

Facility ID:	1205385
Facility Type:	ER
Spill Number:	1205385
DER Facility ID:	422618
Site ID:	468321
DEC Region:	2
Closed Date:	2013-07-03
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2012-08-28
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2012-08-28
CID:	Not reported
Water Affected:	Not reported

NY UNIV (Continued) **S107781589**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-08-28
Spill Record Last Update:	2013-07-03
Spiller Name:	CELESTE RUFER
Spiller Company:	NY UNIV
Spiller Address:	20 COOPER SQ
Spiller Company:	999
Contact Name:	CELESTE RUFER
DEC Memo:	"Contact: CELESTE RUFER Safety Mgr @ NYU-212-998-1086 celeste.rufer@nyu.edu Hess is the delivery company. Under sidewalk fill line running into the sidewall of the basement. Break in the fill line spilling oil down the basement wall. Ms Rufer had the fill line cemented closed. Triumverite Environmental (Dan Ambrico 516-315-3877) is doing the quick cleanup . She will install a new fill line right away, and then put up for bid a sidewalk dig out of the old fill line to find out how much contamination there is in the soil under the sidewalk. 9/14/12 TJD CSL - line failure letter mailed and emailed to: New York University 740 Broadway 6th Floor New York, NY 10003 Attention: Celeste Rufer celeste.rufer@nyu.edu 7/2/13 TJD File review. Spill was due to a failed fill pipe associated with 8K AST which recently underwent a conversion from #6 to #2 FO. Spill discharge was following initial fill following cleaning of tank - estimated 50 gallons of fuel was reported discharged onto concrete basement floor. Closure report indicates that following cleaning of tank in preperation for coversion the curb fill pipe was tested and passed - leak was from area of fill pipe which penetrated building foundation - no information rearding the tester was provided. Triumvirate Environmental was retained for cleanup - granular absorbents were utilized for cleanup of conrete basement floor - a total of 5,700 lbs of contaminated absorbents & oil soaked debris were recovered, transported and properly disposed of during the remedial process. NYU consultant Langan Engineering retained the services of Nova Environmental Services to perform a GPR survey prior to a geoprobe investigation by Aquifer Drilling and Testing of soils beneath the sidewalk in vicinity of reported failure of underground single wall fill pipe - a total of (4) soil samples were collected for laboratory analysis. All target analytes are within acceptable concentrations. East Coast Mechanical Corp. was then retained to replace the failed fill pipe with new piping in secondary containment - followed by a reported passing test of new piping. A reference to this work is contained on an invoice but no tightness test report was provided. Ilkay Cam-Spanos of Langan Engineering was contacted via telephone today and was directed to provide copies of tightness test reports for (2) testing events which were referenced in Langan closure report. Awaiting requested documentation. 7/3/13 TJD Langan Engineering has provided requested documentation. No further action is required."
Remarks:	"lost from fill port during fill, unk cause or amount greater than five gallons"

NY UNIV (Continued) **S107781589**

All Materials:
Site ID: 468321
Operable Unit ID: 1218247
Operable Unit: 01
Material ID: 2216626
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

I137 **Z. BUILDING CORP.** **NY AST** **U004048827**
WNW **680 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.077 mi.
409 ft. **Site 3 of 13 in cluster I**

Relative:
Lower

Actual:
40 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-251704
Program Type: PBS
UTM X: 584889.47863
UTM Y: 4509003.21517
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 10111
Affiliation Type: Facility Owner
Company Name: Z BUILDING CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 680 BROADWAY
Address2: Not reported
City: NEW YORK CITY
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 420-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10111
Affiliation Type: Mail Contact
Company Name: Z. BUILDING CORP.
Contact Type: Not reported
Contact Name: JERRY ABRAMOWITZ
Address1: 680 BROADWAY
Address2: Not reported
City: NEW YORK CITY

Z. BUILDING CORP. (Continued) **U004048827**

State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 420-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10111
Affiliation Type: Facility Operator
Company Name: Z. BUILDING CORP.
Contact Type: Not reported
Contact Name: MICHAEL COLLINS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 288-0077
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10111
Affiliation Type: Emergency Contact
Company Name: Z BUILDING CORP.
Contact Type: Not reported
Contact Name: MICHAEL COLLINS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 535-4112
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 11787
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Z. BUILDING CORP. (Continued) **U004048827**

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/1998
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

I138 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157529**
WNW **F/O 680 BROADWAY** **N/A**
< 1/8 **MANHATTEN, NY 10012**
0.077 mi.
409 ft. **Site 4 of 13 in cluster I**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP000237164
Facility Status:	Not reported
Location Address 1:	F/O 680 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTEN
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000237164
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

I139
WNW
< 1/8
0.077 mi.
409 ft.

CONSOLIDATED EDISON
F/O 680 BROADWAY
NEW YORK, NY 10012

Site 5 of 13 in cluster I

NY MANIFEST **S111158100**
N/A

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004237164
Facility Status:	Not reported
Location Address 1:	F/O 680 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004237164
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE ROOM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/2011
Trans1 Recv Date:	06/17/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/20/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004237164
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655053JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CONSOLIDATED EDISON (Continued) **S111158100**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

C140 **CONSOLIDATED EDISON** **NY MANIFEST** **S109825485**
SW **346 LAFFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY**
0.078 mi.
414 ft. **Site 27 of 28 in cluster C**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004175022
Facility Status:	Not reported
Location Address 1:	346 LAFFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004175022
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

CONSOLIDATED EDISON (Continued) **S109825485**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/2009
Trans1 Recv Date:	06/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/23/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004175022
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	000961192GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H141 **CON EDISON GAS MAIN GAS~MAIN** **RCRA NonGen / NLR** **1014957452**
ENE **COOPER SQ & E 5TH ST** **NJ MANIFEST** **NYP004237834**
< 1/8 **NEW YORK, NY 10003** **NY MANIFEST**
0.079 mi.
416 ft. **Site 8 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/06/2012
Facility name:	CON EDISON GAS MAIN GAS~MAIN
Site name:	CON EDISON - GAS MAIN GAS MAIN
Facility address:	COOPER SQ & E 5TH ST NEW YORK, NY 10003
EPA ID:	NYP004237834
Mailing address:	IRVING PL NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CON EDISON CO OF NY INC
Owner/operator address:	IRVING PL15TH FL NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/30/2011
Owner/Op end date:	Not reported

Owner/operator name:	CON EDISON CO OF NY INC
Owner/operator address:	IRVING PL 15TH FL NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/30/2011
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014957452**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D025
. Waste name: P-CRESOL

. Waste code: B002
. Waste name: B002

. Waste code: B007
. Waste name: B007

Historical Generators:
Date form received by agency: 07/30/2011
Site name: CON EDISON GAS MAIN GAS~MAIN
Classification: Not a generator, verified

Date form received by agency: 06/30/2011
Site name: CON EDISON GAS MAIN GAS~MAIN
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004237834
Mail Address: 4 IRVING PL," 15TH NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: LOUIS CLARK
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014957452**

Manifest:

Manifest Number:	007655158JJK
EPA ID:	NYP004237834
Date Shipped:	6/30/2011
TSDF EPA ID:	NJD063147797
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	4,000.00 kilograms

Manifest Number:	007655331JJK
EPA ID:	NYP004237834
Date Shipped:	7/20/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014957452**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	696.00 kilograms

Manifest Number:	007655164JJK
EPA ID:	NYP004237834
Date Shipped:	7/6/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014957452**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	4,000.00 kilograms

NY MANIFEST:

Country:	USA
EPA ID:	NYP004237834
Facility Status:	Not reported
Location Address 1:	COOPER SQUARE AND
Code:	BP
Location Address 2:	EAST 5TH STREET
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004237834
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014957452**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2011
Trans1 Recv Date:	07/20/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/29/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004237834
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655331JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1534.4
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	D026
Waste Code 1_3:	B007
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

H142 **CON EDISON EXCAVATION EXCAVATION** **NJ MANIFEST** **S120665880**
ENE **COOPER SQ & E 5TH ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.079 mi.
416 ft. **Site 9 of 26 in cluster H**

Relative: **Lower**

Actual: **41 ft.**

NJ MANIFEST:

EPA Id:	NYP004235941
Mail Address:	IRVING PLAZA RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LOUIS CLARK
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655078JJK
EPA ID:	NYP004235941
Date Shipped:	6/9/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON EXCAVATION EXCAVATION (Continued) **S120665880**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	2,273.00 kilograms

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	2,273.00 kilograms

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	2,273.00 kilograms

Manifest Number:	007655132JJK
EPA ID:	NYP004235941
Date Shipped:	6/21/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON EXCAVATION EXCAVATION (Continued) **S120665880**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	1,927.00 kilograms

Manifest Number:	007655077JJK
EPA ID:	NYP004235941
Date Shipped:	6/8/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141

CON EDISON EXCAVATION EXCAVATION (Continued) **S120665880**

Quantity:	909.00 kilograms
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	909.00 kilograms
Manifest Number:	007655076JJK
EPA ID:	NYP004235941
Date Shipped:	6/8/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	1,364.00 kilograms
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141

CON EDISON EXCAVATION EXCAVATION (Continued) **S120665880**

Quantity: 1,364.00 kilograms

Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 1,364.00 kilograms

H143 **CON EDISON EXCAVATION EXCAVATION** **RCRA NonGen / NLR** **1014919428**
ENE **COOPER SQUARE AND EAST 5TH ST** **NY MANIFEST** **NYP004235941**
< 1/8 **NEW YORK, NY 10003**
0.079 mi.
416 ft. **Site 10 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/06/2012
Facility name: CON EDISON EXCAVATION EXCAVATION
Site name: CON EDISON - EXCAVATION EXCAVATION
Facility address: COOPER SQUARE AND EAST 5TH ST
NEW YORK, NY 10003
EPA ID: NYP004235941
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: DENNIS HUACON
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 212-460-2757
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE, 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/23/2011
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE, 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported

CON EDISON EXCAVATION EXCAVATION (Continued) **1014919428**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/23/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D025
. Waste name: P-CRESOL

. Waste code: B007
. Waste name: B007

Historical Generators:
Date form received by agency: 06/22/2011
Site name: CON EDISON EXCAVATION EXCAVATION
Classification: Not a generator, verified

Date form received by agency: 05/23/2011
Site name: CON EDISON EXCAVATION EXCAVATION
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004235941
Facility Status: Not reported
Location Address 1: COOPER SQUARE AND EAST 5TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

CON EDISON EXCAVATION EXCAVATION (Continued) **1014919428**

Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004235941
Mailing Name: CONED
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE ROOM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/21/2011
Trans1 Recv Date: 06/21/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/23/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004235941
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007655132JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 4500.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 1.0
Container Type: CM - Metal boxes, cases, roll-offs

CON EDISON EXCAVATION EXCAVATION (Continued) **1014919428**

Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	B007
Waste Code 1_2:	D018
Waste Code 1_3:	D026
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

H144 **CON EDISON SERVICE BOX: 972** **RCRA NonGen / NLR** **1017772609**
ENE **237 E 5TH ST & COOPER SQ E OF** **FINDS** **NYP004495693**
< 1/8 **NEW YORK, NY 10003**
0.079 mi.
416 ft. **Site 11 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/09/2014
Facility name:	CON EDISON SERVICE BOX: 972
Facility address:	237 E 5TH ST & COOPER SQ E OF NEW YORK, NY 10003
EPA ID:	NYP004495693
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/09/2014
Site name:	CON EDISON

CON EDISON SERVICE BOX: 972 (Continued) **1017772609**

Classification: Small Quantity Generator

Date form received by agency: 04/09/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063784178

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

F145 **CON EDISON SERVICE BOX: 26837** **RCRA NonGen / NLR** **1016148815**
SSE **334 BOWERY FRONT OF** **NY MANIFEST** **NYP004274395**
< 1/8 **NEW YORK, NY 10012**
0.080 mi.
421 ft. **Site 18 of 28 in cluster F**

Relative: Higher

Actual: 42 ft.

RCRA NonGen / NLR:
Date form received by agency: 07/28/2017
Facility name: CON EDISON SERVICE BOX: 26837
Facility address: 334 BOWERY FRONT OF
NEW YORK, NY 10012
EPA ID: NYP004274395
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: BENJAMIN BAMONTE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-894-9549
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

CON EDISON SERVICE BOX: 26837 (Continued) **1016148815**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/17/2012
Site name: CON EDISON SERVICE BOX: 26837
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004274395
Facility Status: Not reported
Location Address 1: F/O 338 BOWERY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004274395
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/17/2012
Trans1 Recv Date: 10/17/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/19/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004274395
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON SERVICE BOX: 26837 (Continued) **1016148815**

TSDF ID 2:	Not reported
Manifest Tracking Number:	010456416JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

F146 **CON EDISON SERVICE BOX: 26836** **RCRA NonGen / NLR** **1016148816**
SSE **334 BOWERY FRONT OF** **FINDS** **NYP004274403**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.080 mi. **NY MANIFEST**
421 ft. **Site 19 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26836
Facility address:	334 BOWERY FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004274403
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON SERVICE BOX: 26836 (Continued) **1016148816**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/17/2012
Site name:	CON EDISON SERVICE BOX: 26836
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055421477

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016148816
Registry ID:	110055421477
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055421477

NY MANIFEST:

Country:	USA
EPA ID:	NYP004274403
Facility Status:	Not reported
Location Address 1:	F/O 354 BOWERY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK

CON EDISON SERVICE BOX: 26836 (Continued) **1016148816**

Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004274403
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/17/2012
Trans1 Recv Date: 10/17/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/19/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004274403
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010456415JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks

CON EDISON SERVICE BOX: 26836 (Continued) **1016148816**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H147 **SPILL NUMBER 0004644** **NY Spills** **S104787360**
ENE **16-20 COOPER SQ** **N/A**
< 1/8 **MANHATTAN, NY**
0.080 mi.
422 ft. **Site 12 of 26 in cluster H**

Relative: SPILLS:
Lower

Actual:
41 ft.

Facility ID:	0004644
Facility Type:	ER
Spill Number:	0004644
DER Facility ID:	232434
Site ID:	286853
DEC Region:	2
Closed Date:	2002-11-27
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2000-07-18
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-07-18
CID:	382
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-18
Spill Record Last Update:	2002-11-27
Spiller Name:	SERGIO
Spiller Company:	Not reported
Spiller Address:	20-30 COOPER SQ
Spiller Company:	001
Contact Name:	SERGIO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND/SACCACIO 9/5/2002 Transfer spill to Sangesland Sangesland spoke with Jeffery Doss of CEI (Certified Environment) at 212-717-7042. He asked what it would take to close this spill out. There was also some question on the address. Mr. Doss stated that one building is 16-20 Cooper Sq and the next building is 30 Cooper Sq. There does not appear to be a building listed as 20-30 Cooper Sq. Mr.

SPILL NUMBER 0004644 (Continued) **S104787360**

Doss will look into the spill and address questions and will try to close out the case. 10/1/2002 Sangesland spoke with Michael Orlofsky (attorney for property manager). Mr. Orlofsky confirmed that the address of his client's building is 16-20 Cooper Sq and that it was this building which had the spill incident. Sangesland requested Mr. Orlofsky to have either Castle Oil or the building's oil service company to prepare a letter which states the following: 1) Yes there was a spill at the site and it was traced back to a problem with XXXXXXXX line/pipe or valve. The problem was repaired and no longer leaks. All of the lines (street to tank and tank to boiler) were inspected and determined to be in good working condition. 2) This letter (with any back up info) should be forwarded to the DEC along with a request to close out the spill number. If such a letter comes to the DEC, the DEC will close out the spill and forward a copy of the closed spill report to the building owner or manager. 11/27/2002 - Sangesland received a letter from Michael Orlofsky requesting closure on the spill. Attached to this letter was a statement from Jim Carey of Castle Oil (718-579-3400) that: 1) All of the oil lines associated with the tank, boiler (i.e. fill line, vent line, suction and return lines) are all in good working order. 2)The lines running from the fill port to the tank and from the tank to the burner are all visible. 3) There are no visible signs of contamination. Based on this letter from Castle, the spill has been closed out. "

Remarks: "OIL LINE FAILURE CAUSED SPILL ONTO FLOORING. CLEANED UP BY SUPER OF BUILDING."

All Materials:

Site ID:	286853
Operable Unit ID:	825772
Operable Unit:	01
Material ID:	549377
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

I148 **CON EDISON - SERVICE BOX 35856** **RCRA-LQG 1014396492**
WNW **GREAT JONES ST AND BROADWAY** **NY MANIFEST NYP004188025**
< 1/8 **NEW YORK, NY 10012** **NJ MANIFEST**
0.080 mi.
423 ft. **Site 6 of 13 in cluster I**

Relative: **Lower**

Actual: **40 ft.**

RCRA-LQG:

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - SERVICE BOX 35856
Facility address:	GREAT JONES ST AND BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004188025
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY
Contact address:	Not reported Not reported

CON EDISON - SERVICE BOX 35856 (Continued) **1014396492**

Contact country: Not reported
Contact telephone: 212-460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/28/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/28/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

CON EDISON - SERVICE BOX 35856 (Continued) **1014396492**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004188025
Facility Status: Not reported
Location Address 1: GREAT JONES ST AND BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004188025
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 07/28/2009
Trans1 Recv Date: 07/28/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/28/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004188025
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 003532219JJK
Import Indicator: N
Export Indicator: N

CON EDISON - SERVICE BOX 35856 (Continued) **1014396492**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYP004188025
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532219JJK
EPA ID:	NYP004188025
Date Shipped:	07/28/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

CON EDISON - SERVICE BOX 35856 (Continued) **1014396492**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	3000 P

I149 **219641; GREAT JONES ST AND BROADWAY** **NY Spills** **S110307595**
WNW **GREAT JONES ST AND BROADWAY** **N/A**
< 1/8 **NEW YORK, NY**
0.080 mi.
423 ft. **Site 7 of 13 in cluster I**

Relative: **Lower**

Actual: **40 ft.**

SPILLS:

Facility ID:	0914664
Facility Type:	ER
Spill Number:	0914664
DER Facility ID:	386598
Site ID:	433766
DEC Region:	2
Closed Date:	2009-12-31

219641; GREAT JONES ST AND BROADWAY (Continued) **S110307595**

Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	2009-12-18
Investigator:	DMPOKRZY
Referred To:	Not reported
Reported to Dept:	2009-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-27
Spill Record Last Update:	2010-04-27
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	433766
Operable Unit ID:	1184615
Operable Unit:	01
Material ID:	2178889
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

I150 **VERIZON LOG 32884** **RCRA NonGen / NLR** **1014917865**
WNW **BROADWAY & GREAT JONES** **NY MANIFEST** **NYP000963322**
< 1/8 **NEW YORK, NY 10012**
0.080 mi.
423 ft. **Site 8 of 13 in cluster I**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/18/2008
Facility name:	VERIZON LOG 32884
Facility address:	BROADWAY & GREAT JONES NEW YORK, NY 10012
EPA ID:	NYP000963322
Mailing address:	HANSE AVE FREEPORT, NY 11520
Contact:	JOHN QUATRALE
Contact address:	HANSE AVE

VERIZON LOG 32884 (Continued) **1014917865**

FREEPORT, NY 11520
Contact country: US
Contact telephone: 516-292-8166
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP000963322
Facility Status: Not reported
Location Address 1: BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10016
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000963322
Mailing Name: VERIZON NEW YORK INC. MANHOLE
Mailing Contact: JOHN QUATRALE
Mailing Address 1: 199 FULTON AVE ROOM 409
Mailing Address 2: Not reported
Mailing City: HEMPSTEAD
Mailing State: NY
Mailing Zip: 11550
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5162928166

I151 **214191; GREAT JONES ST AND BROADWAY** **NY Spills** **S110306652**
WNW **GREAT JONES ST AND BROADWAY** **N/A**
< 1/8 **NEW YORK, NY**
0.080 mi.
423 ft. **Site 9 of 13 in cluster I**

Relative:
Lower

Actual:
40 ft.

SPILLS:

Facility ID:	0814546
Facility Type:	ER
Spill Number:	0814546
DER Facility ID:	386598
Site ID:	432692
DEC Region:	2
Closed Date:	2008-10-28
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	2008-10-18
Investigator:	DMPOKRZY
Referred To:	Not reported
Reported to Dept:	2008-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-04-16
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	432692
Operable Unit ID:	1183753
Operable Unit:	01
Material ID:	2177941
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

F152 **SERVICE STATION** **RCRA NonGen / NLR** **1000432500**
SSE **326 BOWERY AVE** **FINDS** **NYD085735017**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.080 mi.
424 ft. **Site 20 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	SERVICE STATION
Facility address:	326 BOWERY AVE NEW YORK, NY 10012-2407
EPA ID:	NYD085735017
Mailing address:	BOWERY AVE NEW YORK, NY 10012
Contact:	Not reported
Contact address:	BOWERY AVE NEW YORK, NY 10012
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BOWERY SERVICE STATION INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BOWERY SERVICE STATION INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

SERVICE STATION (Continued) **1000432500**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SERVICE STATION
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: SERVICE STATION
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: SERVICE STATION
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004372884

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110019803257

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000432500
Registry ID: 110004372884

SERVICE STATION (Continued) **1000432500**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004372884

F153 **DOWNTOWN AUTOMOTIVE, INC.** **NY UST** **U001840828**
SSE **326 BOWERY** **NY Spills** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.080 mi.
424 ft. **Site 21 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

UST:

Id/Status:	2-477052 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585096.93094
UTM Y:	4508781.22084
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	21141
Affiliation Type:	Facility Owner
Company Name:	JERRY RADAKOV
Contact Type:	Not reported
Contact Name:	JERRY RADAKOV
Address1:	326 BOWERY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(917) 348-2613
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-20

Site Id:	21141
Affiliation Type:	Mail Contact
Company Name:	DOWNTOWN AUTOMOTIVE, INC.
Contact Type:	Not reported
Contact Name:	JERRY RADAKOV
Address1:	326 BOWERY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(917) 348-2613
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-20

Site Id:	21141
Affiliation Type:	Facility Operator
Company Name:	DOWNTOWN AUTOMOTIVE, INC.
Contact Type:	Not reported
Contact Name:	JERRY RADAKOV

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 674-2827
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-20

Site Id:	21141
Affiliation Type:	Emergency Contact
Company Name:	JERRY RADAKOV
Contact Type:	Not reported
Contact Name:	JERRY RUDAKOV
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 348-2613
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-10-20

Tank Info:

Tank Number:	001
Tank ID:	38155
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	07/01/1979
Date Tank Closed:	09/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 38156
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1975
Date Tank Closed: 09/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 003
Tank ID: 38157
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1975
Date Tank Closed: 09/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	004
Tank ID:	38158
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1975
Date Tank Closed:	09/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	005
Tank ID:	38159
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1975
Date Tank Closed:	09/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number: 006
Tank ID: 38160
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1975
Date Tank Closed: 09/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 007
Tank ID: 38161
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1975
Date Tank Closed: 09/01/1997

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number: 008
Tank ID: 38162
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1975
Date Tank Closed: 09/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 009

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Tank ID:	38163
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1975
Date Tank Closed:	09/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	010
Tank ID:	38164
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1975
Date Tank Closed:	09/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 011
Tank ID: 38165
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1975
Date Tank Closed: 09/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 012
Tank ID: 53007
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1997
Date Tank Closed: 03/01/2002
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	013
Tank ID:	53008
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1997
Date Tank Closed:	03/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	014
Tank ID:	53009
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1997
Date Tank Closed:	03/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

SPILLS:

Facility ID: 9706763
Facility Type: ER
Spill Number: 9706763
DER Facility ID: 207718
Site ID: 253569
DEC Region: 2
Closed Date: 2017-01-18
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3101
Spill Date: 1997-09-06
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 1997-09-06
CID: 369
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1997-09-06
Spill Record Last Update: 2017-01-18
Spiller Name: GARY
Spiller Company: DOWNTOWN AUTOMOTIVE INC
Spiller Address: 326 BOWERY ST
Spiller Company: 001
Contact Name: GARY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 11/26/97 mmm:GOT CALL FROM STEVE, WHO'S FATHER WAS THE OWNER OF THE PROPERTY 12 YEARS AGO, AND WANTED TO KNOW IF DEC GOT ANY KIND

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

OF SITE ASSESSMENT REPORT. CALLED YELLOWSTONE AND LEFT MESSAGE. 4/12/04-Vought-Spill transferred from Mulqueen to Rommel as per Rommel. 1/18/2006 - Haggerty - Unable to reach Todd McIndoo from Yellowstone Industries. I believe his contact # (516-485-0000) is outdated. I also emailed him with no response Todd McIndoo . Keep open-site visit. 7/1/2008 Sangesland spoke to an attorney who represents one of the new owners in the new building that was built at the site. She will investigate what permitting was done with the city to build the building. The site was a gas station, now it is a 6 floor building with commercial condo units on the ground floor and condo apartment units above it. 7-30-2008- DECPiper Spoke to Don Middleton, consultant for bank. 631-321-4300. I Let him know we have no info on spill. He will look into it and report back. 9/22/2008 Sangesland spoke to Marie Precko(?) who is working for the owner trying to close out all open issues on the new building. Since it was once a gas station and the initial comments said there was soil/groundwater contamination, Sangesland said she would probably need: 1- Drawings/photos which show the area was dug out down to bedrock for construction. 2- Since the building is a corner unit (Bond St & Bowery) Sangesland suggested that soil borings (geoprobe) be taken on the sidewalk of each side of the building. 2/22/2010 - Sangesland spoke to Andy Robinson works for William Vitacco Assoc building expiditer for the building. Trying to clean up open violation. 212-791-4578 ext 206 8/16/11 - Austin - Received call from Allen Green (646-599-5869), an expeditor who wanted to know how to get this spill report closed. I explained the basic preliminary findings of the spill report, and the subsequent history showing many inquiries about how to close this spill, with no submissions or additional info provided to the DEC on what has actually been done since 1997. I referred Mr. Green to the current DEC project manager for this spill (Ryan Piper) for more details on how to proceed. - end 1/18/17- DEC Piper received and reviewed Subsurface investigation report. Based on results of soil, groundwater and soil vapor/ indoor air sampling, no further action is warranted. This spill is closed. Report in DEC Docs."

Remarks: "TANK REMOVAL REVEALED CONTAMINATED SOIL AND POSSIBLE GROUNDWATER CONTAMINATION AT AN AUTOMOTIVE STATION-ABOUT 250 YARDS OF SOIL AT THE COMPLETON"

All Materials:

Site ID:	253569
Operable Unit ID:	1050132
Operable Unit:	01
Material ID:	332344
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	253569
Operable Unit ID:	1050132
Operable Unit:	01
Material ID:	332345
Material Code:	0009

DOWNTOWN AUTOMOTIVE, INC. (Continued) **U001840828**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F154 **SPOT SERVICE STATION INC** **EDR Hist Auto** **1021850394**
SSE **326 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.080 mi.
424 ft. **Site 22 of 28 in cluster F**

Relative: EDR Hist Auto
Higher

Actual:
42 ft.

Year:	Name:	Type:
1973	SPOT SERVICE STATION INC	Gasoline Service Stations
1974	SPOT SERVICE STATION INC	Gasoline Service Stations
1975	SPOT SERVICE STATION INC	Gasoline Service Stations
1976	SPOT SERVICE STATION INC	Gasoline Service Stations
1979	SPOT SERVICE STATION INC	Gasoline Service Stations
1980	SPOT SERVICE STATION INC	Gasoline Service Stations
1982	SPOT SERVICE STATION INC	Gasoline Service Stations
1983	SPOT SERVICE STATION INC	Gasoline Service Stations
1985	SPOT SERVICE STATION INC	Gasoline Service Stations
1986	SPOT SERVICE STATION INC	Gasoline Service Stations
1987	BOWERY SERVICE STATION INC	Not reported
1987	SPOT SERVICE STATION INC	Gasoline Service Stations
1988	BOWERY SERVICE STATION INC	Not reported
1988	SPOT SERVICE STATION INC	Gasoline Service Stations
1989	SPOT SERVICE STATION INC	Gasoline Service Stations
1990	SPOT SERVICE STATION INC	Gasoline Service Stations
1991	SPOT SERVICE STATION INC	Gasoline Service Stations
1991	ABSOLUTE AUTO SERVICE	Gasoline Service Stations
1992	ABSOLUTE AUTO SERVICE	Gasoline Service Stations
1992	SPOT SERVICE STATION INC	Gasoline Service Stations
1993	SPOT SERVICE STATION INC	Gasoline Service Stations
1994	SPOT SERVICE STATION INC	Gasoline Service Stations
1995	SPOT SERVICE STATION INC	Gasoline Service Stations
1996	SPOT SERVICE STATION INC	Gasoline Service Stations
1996	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
1997	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
1997	SPOT SERVICE STATION INC	Gasoline Service Stations
1998	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
1999	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
2000	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
2001	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
2002	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
2003	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops
2004	DOWNTOWN AUTOMOTIVE INC	General Automotive Repair Shops

H155 **CON EDISON SERVICE BOX: 30951** **RCRA NonGen / NLR** **1017771534**
ENE **15 COOPER SQ FRONT OF** **NYP004484747**
< 1/8 **NEW YORK, NY 10003**
0.081 mi.
426 ft. **Site 13 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/30/2014
Facility name:	CON EDISON SERVICE BOX: 30951
Facility address:	15 COOPER SQ FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004484747
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/31/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	03/31/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

H156 **CON EDISON** **NY MANIFEST** **S116550209**
ENE **15 COOPER SQ FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.081 mi.
426 ft. **Site 14 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004484747
Facility Status:	Not reported
Location Address 1:	F/O 15 COOPER SQ
Code:	BP
Location Address 2:	SB30951
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004484747
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2014
Trans1 Recv Date:	03/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004484747
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406244GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S116550209**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

I157 **TM 3691** **NY Spills** **S106468946**
WNW **1 WEST 3RD STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.081 mi.
430 ft. **Site 10 of 13 in cluster I**

Relative: **Lower**
Actual: **40 ft.**

SPILLS:

Facility ID:	0401482
Facility Type:	ER
Spill Number:	0401482
DER Facility ID:	88562
Site ID:	99690
DEC Region:	2
Closed Date:	2004-08-20
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-05-12
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2004-05-12
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-12

TM 3691 (Continued) **S106468946**

Spill Record Last Update:	2004-08-20
Spiller Name:	ERT DESK
Spiller Company:	Con Ed
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 153337: cable gang was in process of lifting up a transformer and discover 20 gal of unknown oil in tm 3691. Substance: transformer oil. Source of spill: transformer; cause of spill: unknown Lab Sequence Number: 04-03629-001: PCBs < 1 ppm (from floor) Lab Sequence Number: 04-03629-002: Flash Point, PMCC > 140 deg F Lab Sequence Number: 04-03629-003: PCBs < 1 ppm (from transformer) Lab Sequence Number: 04-03630-001: Analysis indicates the presence of a substance similar to a dielectric fluid. Update May 14, 2004 O.S Cable Dept. E.Hulser reports clean up complete @ 15:35 on May 14,2004. He reports that tanker removed 25 gallons of oil only no water, from unit and vault. Flush truck removed asphalt and soil, and was power washed twice with flush truck using Bio-Gen. Old unit removed, and new one installed."
Remarks:	"NO SEWERS, WATERWAYS, FIRE OR SMOKE: PENDING CLEAN UP: "

All Materials:

Site ID:	99690
Operable Unit ID:	885444
Operable Unit:	01
Material ID:	492691
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E158 **CON EDISON - SERVICE BOX 28802** **NY MANIFEST** **S120957981**
NW **691 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.083 mi.
440 ft. **Site 12 of 23 in cluster E**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004900153
Facility Status:	Not reported
Location Address 1:	691 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004900153
Mailing Name:	CON EDISON - SERVICE BOX 28802

CON EDISON - SERVICE BOX 28802 (Continued) **S120957981**

Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

E159 **CON EDISON GAS DRIP GAS~MAIN** **RCRA NonGen / NLR** **1015746923**
NW **E 4TH ST & BROADWAY** **NY MANIFEST** **NYP004249221**
< 1/8 **NEW YORK, NY 10003**
0.084 mi.
445 ft. **Site 13 of 23 in cluster E**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/05/2012
Facility name:	CON EDISON GAS DRIP GAS~MAIN
Facility address:	E 4TH ST & BROADWAY NEW YORK, NY 10003
EPA ID:	NYP004249221
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	LOUIS CLARK
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-539-6192
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/06/2012
Site name:	CON EDISON GAS DRIP GAS~MAIN
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON GAS DRIP GAS~MAIN (Continued) **1015746923**

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004249221
Facility Status: Not reported
Location Address 1: W 4TH STREET & BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004249221
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NYD006912359
Trans2 State ID: Not reported
Generator Ship Date: 03/08/2012
Trans1 Recv Date: 03/08/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/09/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004249221
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: 003207240FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141

CON EDISON GAS DRIP GAS~MAIN (Continued) **1015746923**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

E160 **CON EDISON GAS MAIN TRENCH** **RCRA NonGen / NLR** **1014919395**
NW **WEST 4TH STREET AND BROADWAY** **NJ MANIFEST** **NYP004235586**
< 1/8 **NEW YORK, NY 10012** **NY MANIFEST**
0.084 mi.
445 ft. **Site 14 of 23 in cluster E**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/06/2012
Facility name:	CON EDISON GAS MAIN TRENCH
Site name:	CON EDISON - GAS MAIN TRENCH
Facility address:	WEST 4TH STREET AND BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004235586
Mailing address:	IRVING PLACE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE, 15TH FL NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

CON EDISON GAS MAIN TRENCH (Continued) **1014919395**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/16/2011
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE, 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/16/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D025
. Waste name: P-CRESOL

. Waste code: B007
. Waste name: B007

Historical Generators:
Date form received by agency: 06/15/2011
Site name: CON EDISON GAS MAIN TRENCH
Classification: Not a generator, verified

Date form received by agency: 05/16/2011
Site name: CON EDISON GAS MAIN TRENCH
Classification: Conditionally Exempt Small Quantity Generator

CON EDISON GAS MAIN TRENCH (Continued) **1014919395**

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004235586
Mail Address:	IRVING PLAZA RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LOUIS CLARK
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007019364JJK
EPA ID:	NYP004235586
Date Shipped:	5/17/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

CON EDISON GAS MAIN TRENCH (Continued) **1014919395**

Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D018
Hand Code: H141
Quantity: 2,823.00 kilograms

NY MANIFEST:
Country: USA
EPA ID: NYP004235586
Facility Status: Not reported
Location Address 1: WEST 4TH STREET AND BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004235586
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 05/17/2011
Trans1 Recv Date: 05/17/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/26/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004235586
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported

CON EDISON GAS MAIN TRENCH (Continued) **1014919395**

Manifest Tracking Number:	007019364JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2823.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	Not reported
Waste Code 1_2:	B007
Waste Code 1_3:	D018
Waste Code 1_4:	D026
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E161 **CON EDISON GAS DRIP GAS~MAIN** **NJ MANIFEST** **S117985195**
NW **E 4TH ST & BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.084 mi.
445 ft. **Site 15 of 23 in cluster E**

Relative: NJ MANIFEST:
Lower

Actual:
40 ft.

EPA Id:	NYP004249221
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LOUIS CLARK
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

CON EDISON GAS DRIP GAS~MAIN (Continued) **S117985195**

Manifest:

Manifest Number:	001128566GBF
EPA ID:	NYP004249221
Date Shipped:	3/7/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	Not reported
Quantity:	100.00 gallons

E162 **CON EDISON - TRANSFORMER MANHOLE TM2576** **NY MANIFEST** **S120958220**
NW **E 4TH ST & BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.084 mi.
445 ft. **Site 16 of 23 in cluster E**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004922876
Facility Status:	Not reported
Location Address 1:	E 4TH ST & BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004922876
Mailing Name:	CON EDISON - TRANSFORMER MANHOLE TM2576
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

E163 **CON EDISON GAS MAIN GAS~MAIN** **RCRA NonGen / NLR** **1014918706**
NW **W 4TH ST & BROADWAY** **NJ MANIFEST** **NYP004223251**
< 1/8 **NEW YORK, NY 10012** **NY MANIFEST**
0.084 mi.
445 ft. **Site 17 of 23 in cluster E**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/04/2011
Facility name:	CON EDISON GAS MAIN GAS~MAIN
Facility address:	W 4TH ST & BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004223251
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	LOUIS CLARK
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-539-6192
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014918706**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/05/2011
Site name:	CON EDISON GAS MAIN GAS~MAIN
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004223251
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LOUIS CLARK
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655875JJK
EPA ID:	NYP004223251
Date Shipped:	1/6/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014918706**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	882.00 kilograms

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	882.00 kilograms

NY MANIFEST:

Country:	USA
EPA ID:	NYP004223251
Facility Status:	Not reported
Location Address 1:	WEST 4TH STREET & BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004223251
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON GAS MAIN GAS~MAIN (Continued) **1014918706**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/2011
Trans1 Recv Date:	01/06/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/12/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004223251
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655875JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	882.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	B007
Waste Code 1_2:	D018
Waste Code 1_3:	D026
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E164
NW
< 1/8
0.084 mi.
445 ft.

214224; E 4 ST AND BROADWAY
E 4 ST AND BROADWAY
NEW YORK, NY

Site 18 of 23 in cluster E

NY Spills **S110306654**
N/A

Relative:
Lower

Actual:
40 ft.

SPILLS:

Facility ID:	0814548
Facility Type:	ER
Spill Number:	0814548
DER Facility ID:	386526
Site ID:	432696
DEC Region:	2
Closed Date:	2008-10-26
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3101
Spill Date:	2008-10-21
Investigator:	DMPOKRZY
Referred To:	Not reported
Reported to Dept:	2008-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2010-04-16
Spill Record Last Update:	2010-04-16
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	432696
Operable Unit ID:	1183757
Operable Unit:	01
Material ID:	2177945
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

E165 **CON EDISON** **RCRA NonGen / NLR** **1014398455**
NW **BROADWAY & E 4TH ST** **NY MANIFEST** **NYP004208084**
< 1/8 **NEW YORK, NY 10029**
0.084 mi.
445 ft. **Site 19 of 23 in cluster E**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/07/2010
Facility name:	CON EDISON
Facility address:	BROADWAY & E 4TH ST NEW YORK, NY 10029
EPA ID:	NYP004208084
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	ANTHONY BUDA
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	917-440-1809
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004208084
Facility Status:	Not reported
Location Address 1:	BROADWAY & EAST 4th STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004208084
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **1014398455**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/07/2010
Trans1 Recv Date:	06/07/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/08/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004208084
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433253FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **1014398455**

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

E166 **4TH ST & B'WAY/NAT'L AUDU** **NY Spills** **S102141346**
NW **4TH ST & BROADWAY** **N/A**
< 1/8 **NYC, NY**
0.084 mi.
445 ft. **Site 20 of 23 in cluster E**

Relative: **Lower**

Actual: **40 ft.**

SPILLS:

Facility ID:	9107147
Facility Type:	ER
Spill Number:	9107147
DER Facility ID:	164187
Site ID:	197267
DEC Region:	2
Closed Date:	1996-10-23
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1991-09-18
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1991-10-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-07
Spill Record Last Update:	1996-11-20
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	""

All Materials:

Site ID:	197267
Operable Unit ID:	957482
Operable Unit:	01
Material ID:	419373
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00

4TH ST & B'WAY/NAT'L AUDU (Continued) **S102141346**

Oxygenate: Not reported

C167 **SERVICE BOX 37911** **NY Spills** **S105058851**
SW **BLEECKER ST/LAFAYETTE ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.085 mi.
448 ft. **Site 28 of 28 in cluster C**

Relative: **Lower**

Actual: **41 ft.**

SPILLS:

Facility ID:	0103876
Facility Type:	ER
Spill Number:	0103876
DER Facility ID:	75001
Site ID:	81004
DEC Region:	2
Closed Date:	2003-07-28
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-07-11
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2001-07-11
CID:	365
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-11
Spill Record Last Update:	2003-07-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #138160: 7/11/01 19:30 hrs. Sean Henihan #16850, Splicer Underground North, reported at 18:46 hrs. that he found at 18:40 hrs. approx. 15 gallons of green fluid and approx. 15 gallons of water in service box SB37911 located at the north west corner of Bleeker Street & Lafayette Street. The green fluid is possibly anti-freeze or the green dye that the water dept. uses to test for leaks in their pipes. Considering the amount of green fluid found (15 gallons) it is possibly the green dye used by the NY City Water Dept. He was at this location at the request of the Manhattan Environmental Desk and the ERT, Sean Mahoney. Stanley Baldwin of the DEP was at this location earlier in the day and reported to the ERT that a green substance was coming from a Con Edison structure. ERT, Sean Mahoney called the Manh. Environ. Desk at 14:45 hrs. and reported that Mr. Baldwin of the DEP is claiming that the green substance or fluid is coming from a Con Edison manhole. The ERT and Mr. Baldwin agreed that the fluid was either anti-freeze or the green dye used by the Water

SERVICE BOX 37911 (Continued) **S105058851**

Dept. and was non-hazardous. The Environ. Desk called Mike Donahue & Dennis Romano of the Underground South to veify if there were any crews working in this area. They both stated that there were no crews working or assigned to this location. Sean Henihan reported that there was a trench approx. 2 feet north of this service biox which had a pipe running through it. The trench is approx. 12 inches deep x 4 feet long x 2 feet wide. The trench contained approx. 7 gallons mixture of the green fluid and water. It appears that the green fluid from the trench migrated into our service box. UPDATE 7/12/2001 @ 01:50 HRS Lab results for Lab Sequence 01-07266-001 Aroclor 1242 < 1.0 ppm 1.0 Aroclor 1254 < 1.0 ppm 1.0 Aroclor 1248 < 1.0 ppm 1.0 Aroclor 1260 < 1.0 ppm 1.0 UPDATE: 8/09/01 Jimmy Rodriguez, Underground South Supervisor, reported at 11:13 hrs. on 7/13/01 that the cleanup of this manhole has been completed. He reported that 20 gallons of fluid was removed on 7/12/01 and 10 gallons of fluid was removed on 7/13/01 for a total of 30 gallons. One drum of PPE (solid waste) was generated. The crew pumped the structure, washed it with one gallon of citrus cleaner and flushed the service box with the Vactor truck. The cleanup was completed at 11:00 hrs. 8/9/01 14:12 Received lab results lab sequence # 01-07267-001 Insufficient amount of sample extracted to perform oil identification. Ethylene Glycol < 10.2 ppm PROPYLENE GLYCOL 6.60 PPM"

Remarks: "15 gallons of a grn material & 5 gallons of water - they tested material & they will clean up late tonight or tomorrow - ref #138160"

All Materials:

Site ID:	81004
Operable Unit ID:	840494
Operable Unit:	01
Material ID:	535952
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E168 **704 BROADWAY** **NY LTANKS** **S104781897**
NNW **704 BROADWAY** **N/A**
< 1/8 **NY, NY 10003**
0.087 mi.
457 ft. **Site 21 of 23 in cluster E**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	0004513
Site ID:	218411
Closed Date:	2013-11-29
Spill Number:	0004513
Spill Date:	2000-07-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	VXBREVDO

704 BROADWAY (Continued) **S104781897**

Referred To:	Not reported
Reported to Dept:	2000-07-14
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-14
Spill Record Last Update:	2013-11-29
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KTR ENVIRONMENTAL
Spiller Phone:	(212) 906-9410
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	10498
DEC Memo:	"06/08/10 - LZ Sent a TTF leter (eDocs) to Mr. Malcolm Simmons 704 Broadway Condominium 704 Broadway Avenue New York, NY 10003 Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 01/26/04 transferredf rom rommel to Austin 02/17/04: Reassigned from AUSTIN to KRIMGOLD. 10/23/06: Reassigned from S. LASDIN (Central Office) to Y. KRIMGOLD. 07/16/13 - Spill Case is transferred from Leszek Zielinski (PBS Unit) to V. Brevdo (Section B) as per DER Region 2 decision - Tank Test Failure Spill Case. VB 11/29/2013 - V. Brevdo No information, data, documents which would confirm tank test failure are available to the Department. No tank test results report from the alleged failed test are available. This is unconfirmed TTF spill case. Furthermore, PBS file 2-256277 for this address does not contain any documents which would confirm tank test failure in 1999, 2000, 2001 or 2002. To that effect, no any documents are in PBS file which would indicate any TTF at any time. The Department determined that there are no sufficient grounds / cause to pursue / enforce this unconfirmed case against site owner. PBS file shows valid PBS certificate dated 01/29/2013 expiring on 09/19/2017. Spill Case is closed effective 11/29/2013. VB"
Remarks:	""

All Materials:

Site ID:	218411
Operable Unit ID:	825709
Operable Unit:	01
Material ID:	566140
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E169 **704 BROADWAY CONDOMINIUM** **NY AST** **A100343909**
NNW **704 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.087 mi.
457 ft. **Site 22 of 23 in cluster E**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-256277
Program Type:	PBS
UTM X:	584981.78432
UTM Y:	4509154.75758
Expiration Date:	09/19/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10513
Affiliation Type:	Facility Owner
Company Name:	704 BROADWAY CONDOMINIUM
Contact Type:	PROPERTY MANAGER
Contact Name:	FIHLO THOMAS
Address1:	666 BROADWAY, 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-10

Site Id:	10513
Affiliation Type:	Mail Contact
Company Name:	ANDREWS ORG.
Contact Type:	Not reported
Contact Name:	PROPERTY MANAGER
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-10

Site Id:	10513
Affiliation Type:	Facility Operator
Company Name:	704 BROADWAY CONDOMINIUM
Contact Type:	Not reported
Contact Name:	MALCOM SIMMONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported

704 BROADWAY CONDOMINIUM (Continued) **A100343909**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 319-8667
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-10

Site Id:	10513
Affiliation Type:	Emergency Contact
Company Name:	704 BROADWAY CONDOMINIUM
Contact Type:	Not reported
Contact Name:	MALCOM SIMMONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 319-8667
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-10

Tank Info:

Tank Number:	001
Tank Id:	13166
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/25/1997
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

704 BROADWAY CONDOMINIUM (Continued) **A100343909**

Register:	True
Modified By:	MFLEONAR
Last Modified:	10/10/2017
Material Name:	#2 fuel oil (on-site consumption)

F170 **CON EDISON SERVICE BOX: 26620** **NJ MANIFEST** **S117986834**
SSE **59 BOND ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.090 mi.
475 ft. **Site 23 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004275384
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456402JJK
EPA ID:	NYP004275384
Date Shipped:	10/22/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON SERVICE BOX: 26620 (Continued) **S117986834**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	2,000.00 Pounds

F171 **CON EDISON SERVICE BOX: 26620** **RCRA NonGen / NLR** **1016148887**
SSE **59 BOND ST FRONT OF** **FINDS** **NYP004275384**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.090 mi. **NY MANIFEST**
475 ft. **Site 24 of 28 in cluster F**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26620
Facility address:	59 BOND ST FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004275384
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON SERVICE BOX: 26620 (Continued) **1016148887**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/22/2012
Site name: CON EDISON SERVICE BOX: 26620
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055458115

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148887
Registry ID: 110055458115
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055458115

NY MANIFEST:
Country: USA
EPA ID: NYP004275384
Facility Status: Not reported
Location Address 1: FO 59 BOND ST
Code: BP
Location Address 2: SERV BOX 26620
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004275384
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON SERVICE BOX: 26620 (Continued) **1016148887**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2012
Trans1 Recv Date:	10/22/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004275384
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456402JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

E172
NW
< 1/8
0.091 mi.
479 ft.

APARTMENT
2-4 ST NICHOLAS PLACE
NEW YORK, NY

Site 23 of 23 in cluster E

NY LTANKS **S106737919**
N/A

Relative:
Lower

Actual:
39 ft.

LTANKS:

Facility ID:	0411548
Site ID:	336772
Closed Date:	2008-01-11
Spill Number:	0411548
Spill Date:	2005-01-27
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2005-01-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-28
Spill Record Last Update:	2008-01-11
Spiller Name:	MARLIN JOSEPH
Spiller Company:	APARTMENT
Spiller Address:	2-4 ST NICHOLOAS PLACE
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(646) 772-7949
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	272111
DEC Memo:	"01/11/08. J.Krimgold reviewed a letter report submitted by PTC and dated 01/01/08. According to the report the release from this tank system most probably did not occur. A hole was found in the vent line. The line was replaced and no contaminated soil was found during excavation. NFA"
Remarks:	"RECOMMEND: REPAIR AND RETEST"

All TTF:

Facility ID:	0411548
Spill Number:	0411548
Spill Tank Test:	1548535
Site ID:	336772
Tank Number:	1
Tank Size:	4000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

APARTMENT (Continued) **S106737919**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 336772
Operable Unit ID: 1098773
Operable Unit: 01
Material ID: 578952
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

H173 **30 COOPER SQ.** **NY UST U003800471**
ENE **30 COOPER SQUARE** **NY AST N/A**
< 1/8 **NEW YORK, NY 10003** **NY Spills**
0.091 mi.
482 ft. **Site 15 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

UST:
Id/Status: 2-607037 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/01/2021
UTM X: 585240.63131
UTM Y: 4509131.95878
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 28892
Affiliation Type: Facility Owner
Company Name: 30 COOPER SQUARE PARTNERSHIP % TRI-STAR EQ.
Contact Type: AGENT
Contact Name: ROD FELDMAN
Address1: 155 EAST 26TH STREET
Address2: Not reported
City: NEW YORK,
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 751-4800
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-07-20

Site Id: 28892
Affiliation Type: Facility Operator
Company Name: 30 COOPER SQ.
Contact Type: Not reported

30 COOPER SQ. (Continued) **U003800471**

Contact Name:	EUGENE TABONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 837-2860
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-10

Site Id:	28892
Affiliation Type:	Emergency Contact
Company Name:	30 COOPER SQUARE PARTNERSHIP % TRI-STAR EQ.
Contact Type:	Not reported
Contact Name:	ROD FELDMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 751-4800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-10

Site Id:	28892
Affiliation Type:	Mail Contact
Company Name:	TRISTAR EQUITIES
Contact Type:	Not reported
Contact Name:	ROD FELDMAN
Address1:	155 EAST 26TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(212) 751-4800
EMail:	RFELDMAN@TRISTAREQ.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-11-01

Tank Info:

Tank Number:	001
Tank ID:	62210
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	01/09/1975
Date Tank Closed:	01/01/2009
Registered:	True

30 COOPER SQ. (Continued) **U003800471**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 04/25/2008
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-457299
Program Type: PBS
UTM X: 590687.55665
UTM Y: 4524631.94672
Expiration Date: 01/18/2019
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 20200
Affiliation Type: Mail Contact
Company Name: BB & BB MANAGEMENT CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 1624 WEBSTER AVENUE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10457
Country Code: 001
Phone: (718) 583-4905
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-01-31

Site Id: 20200
Affiliation Type: Facility Operator
Company Name: 30 COOPER STREET
Contact Type: Not reported

30 COOPER SQ. (Continued) **U003800471**

Contact Name:	EUGENE TAVARES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 569-3610
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	20200
Affiliation Type:	Emergency Contact
Company Name:	1987-93 WASHINGTON REALTY CORP
Contact Type:	Not reported
Contact Name:	AARON BAUER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 731-2383
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	20200
Affiliation Type:	Facility Owner
Company Name:	1987-93 WASHINGTON REALTY CORP
Contact Type:	VP
Contact Name:	AARON BAUER
Address1:	1624 WEBSTER AVENUE
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10457
Country Code:	001
Phone:	(718) 583-4905
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-01-20

Tank Info:

Tank Number:	001
Tank Id:	36797
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None

30 COOPER SQ. (Continued) **U003800471**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1926
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	227632
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2009
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

30 COOPER SQ. (Continued) **U003800471**

Modified By: DMPOKRZY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Affiliation Records:
Site Id: 28892
Affiliation Type: Facility Owner
Company Name: 30 COOPER SQUARE PARTNERSHIP % TRI-STAR EQ.
Contact Type: AGENT
Contact Name: ROD FELDMAN
Address1: 155 EAST 26TH STREET
Address2: Not reported
City: NEW YORK,
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 751-4800
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-07-20

Site Id: 28892
Affiliation Type: Facility Operator
Company Name: 30 COOPER SQ.
Contact Type: Not reported
Contact Name: EUGENE TABONE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 837-2860
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-03-10

Site Id: 28892
Affiliation Type: Emergency Contact
Company Name: 30 COOPER SQUARE PARTNERSHIP % TRI-STAR EQ.
Contact Type: Not reported
Contact Name: ROD FELDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 751-4800
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-03-10

Site Id: 28892

30 COOPER SQ. (Continued) **U003800471**

Affiliation Type:	Mail Contact
Company Name:	TRISTAR EQUITIES
Contact Type:	Not reported
Contact Name:	ROD FELDMAN
Address1:	155 EAST 26TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(212) 751-4800
EMail:	RFELDMAN@TRISTAREQ.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-11-01

Tank Info:

Tank Number:	001
Tank Id:	36797
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1926
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	227632
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

30 COOPER SQ. (Continued) **U003800471**

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2009
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

SPILLS:

Facility ID:	0609172
Facility Type:	ER
Spill Number:	0609172
DER Facility ID:	323033
Site ID:	373313
DEC Region:	2
Closed Date:	2006-11-13
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-11-09
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-11-09
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-11-09
Spill Record Last Update:	2006-11-13

30 COOPER SQ. (Continued) **U003800471**

Spiller Name:	ROB HILL
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE.
Spiller Company:	001
Contact Name:	ROB HILL
DEC Memo:	"street cleanup completed by castle. NYC Sanitation was called to prevent skidding problems on road"
Remarks:	"Material spilled off of the top of the truck onto the street and curb. No sewers or waterways affected. Clean up crew is on route."

All Materials:

Site ID:	373313
Operable Unit ID:	1131024
Operable Unit:	01
Material ID:	2120713
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

J174 **59 EAST 4 STREET** **NY AST** **A100433643**
East **59 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.091 mi.
483 ft. **Site 1 of 20 in cluster J**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-606886
Program Type:	PBS
UTM X:	585199.97053
UTM Y:	4508936.64874
Expiration Date:	10/06/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	28741
Affiliation Type:	Facility Operator
Company Name:	59 EAST 4 STREET
Contact Type:	Not reported
Contact Name:	JOHN ISAZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-14

59 EAST 4 STREET (Continued) **A100433643**

Site Id:	28741
Affiliation Type:	Emergency Contact
Company Name:	ARC ON 4TH STREET, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-14

Site Id:	28741
Affiliation Type:	Facility Owner
Company Name:	ARC ON 4TH STREET, INC.
Contact Type:	BOARD TREASURER/BLDG MANAGER
Contact Name:	DAVID POWELL
Address1:	59 EAST 4TH STREET, #4E
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-14

Site Id:	28741
Affiliation Type:	Mail Contact
Company Name:	COOPER SQUARE MHA
Contact Type:	Not reported
Contact Name:	JOHN ISAZA, DAVID POWELL
Address1:	59 EAST 4TH STREET
Address2:	#4E
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	DPOWELL@SMHA.ORG
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-14

Tank Info:

Tank Number:	01
Tank Id:	61994
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

59 EAST 4 STREET (Continued) **A100433643**

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1965
Capacity Gallons:	2000
Tightness Test Method:	21
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	08/14/2017
Material Name:	#2 fuel oil (on-site consumption)

H175 **CON EDISION** **NY MANIFEST** **S117066498**
ENE **27 COOPER SQ** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.092 mi.
487 ft. **Site 16 of 26 in cluster H**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591533
Facility Status:	Not reported
Location Address 1:	27 COOPER SQ
Code:	BP
Location Address 2:	SB30956
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591533
Mailing Name:	CON EDISION
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISION (Continued) **S117066498**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591533
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423973GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H176 **COOPERS SQUARE HOTEL GROU** **NY Spills** **S108129276**
ENE **27 COOPERS SQUARE** **N/A**
< 1/8 **MANHATTAN, NY**
0.092 mi.
487 ft. **Site 17 of 26 in cluster H**

Relative: **Lower**
Actual: **40 ft.**

SPILLS:

Facility ID:	0604726
Facility Type:	ER
Spill Number:	0604726
DER Facility ID:	317730
Site ID:	367757
DEC Region:	2
Closed Date:	2006-12-12
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-07-26
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2006-07-26
CID:	409
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-26
Spill Record Last Update:	2006-12-12
Spiller Name:	MATTHEW MOSS
Spiller Company:	COOPERS SQUARE HOTEL GROU
Spiller Address:	27 COOPERS SQUARE
Spiller Company:	001
Contact Name:	MATTHEW MOSS
DEC Memo:	"need to send CSL. 08/3/06-Zhune sent CSL to the owner Matthew Moss at: Peck Moss Hotel Group 250 Lafayette Street, Suite 38 New York, NY 10012 11/20/06-Vought-Review of Environmental Investigation and Remediation at 27 Cooper Square (Environmental Building Solutions, LLC. Mike Borello 646-290-5925). The site currently consists of a four (4) residential building surrounded on the north, south and east sides by an open excavation that is associated with the construction of future Cooper Square Hotel. Site formerly occupied by metal works, auto parts store, canal street towing and tire store. Previous soil investigation by Eldon Environmental Management Corporation, dated January 1990, for the propety located at 25 Cooper Square, a former gasoline service station . As per investigation there were six (550-gallon) gasoline USTs and one 275-gallon waste oil tank. Site investigation performed in July 2006 including the collection of two soil samples at depths of 3' and 6' below the basement floor joists. No groundwater was encountered during investigation. Soil analyticals show 1200ppb benzo(a)anthracene, 8200ppb benzo(a)pyrene, 11000ppb benzo(b)fluoranthene and 3900ppb benzo(k)fluoranthene, 12000ppb chrysene all from below floor center sample. no upgradient samples were collected for comparison purposed as the area surrounding the contamination has been excavated approximately 30 feet below ground

COOPERS SQUARE HOTEL GROU (Continued) **S108129276**

surface for the Cooper Square Hotel foundation. All contaminated soil that exceeds TAGM 4046 will be excavated and disposed of... . If excavation reaches the water table before soil contamination guidance values are met, a groundwater investigation will be conducted . Excavation of site performed from 8/06-10/06. ...approximately 250 cubics yards of contaminated soil and construction debris was removed from the basement of the subject property . Four endpoint sidewall samples were collected for analysis. Soil analyticals show relatively low concentrations of PAHs compared to above soil investigation (highest concentration is 2950 benzo(a)anthracene, no VOCs. No additional soil was removed due to construction constraints. ... a finished four inch concrete slab is to be poured to further finish the basement . Report recommends no further action. DEC requires: 1)PBS registration 2)installation of vapor barrier due to SVOC exceedences under 27 Cooper Square. 11/20/06-Vought-Called Borello for above requirements and material was excavated from under existing foundation of 27 Cooper Square. Gasoline tanks were formerly located in outdoor garden portion on site plan. 27 Cooper had former auto repair operations on ground floor and residential above. Outdoor garden is planned not to be excavated. No signs of pipes or dispenser island (are covered by dirt). Samples collected were actually bottom as sidewalls of were composed of brick and final excavation depth of hotel is 25-30' below grade. Hotel will not be located on top of former gasoline UST location or contamination documented to be under 27 Cooper Square(which is to remain in place). NYCDOB surveying 27 Cooper on a daily basis. Vought to send letter with above requirements to: Peck Moss Hotel Group 250 Lafayette Street, Suite 38 New York, NY 10012 Attm: Mathew Moss Vought received copy of Environmental Investigation Report dated January 1990 prepared by Eldon Environmental Management. A total of six (550-gallon) gasoline USTs and one 275-gallon waste oil UST which are located 6 to 8 feet below the surface . Work included installation of five soil borings. The location of the borings was determined by the general vicinity of the six known 550 gallon gasoline tanks and the 250 gallon waste oil tank . PID survey showed no positive readings. Borings ranged in depth from approximately 17 to 27 feet, where groundwater had not yet been encountered . Site underlain by fill material which includes asphalt, ash, pebbles, concrete, slag and wood . Soil analyticals showed no TAGM 4046 Required Soil Cleanup Objective exceedences. Report concludes that it appears that there are no significant environmental concerns present at the subject site . 12/12/06-Vought-Received fax from Environmental Building Solutions (Borello)dated 12/6/06. Additionally the PBS Application was submitted to Nick Lombardo earlier this week . Attached is letter from Sciame Construction Company (Michael Gordon 212-232-2200) that soil bariier will be installed as per DEC and DOH requirements. Spill closed by Vought. Sent NFA as per letter request. "

Remarks: "HEAVY METALS AND SEMI VOLITALS. THIS WAS HISTORIC MATERIAL IN THE BASEMENT. CLEAN UP IS IN PROCESS."

All Materials:

Site ID:	367757
Operable Unit ID:	1125661
Operable Unit:	01
Material ID:	2115186
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported

COOPERS SQUARE HOTEL GROU (Continued) **S108129276**

Material FA: Other
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

F177 **17-19 BLEECKER STREET, LLC.** **NY AST** **A100147122**
South **17-19 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.092 mi.
488 ft. **Site 25 of 28 in cluster F**

Relative:
Higher

Actual:
43 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-604129
Program Type: PBS
UTM X: 585009.95660
UTM Y: 4508835.21484
Expiration Date: 05/31/2016
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 26012
Affiliation Type: Facility Operator
Company Name: 17-19 BLEECKER STREET, LLC.
Contact Type: Not reported
Contact Name: PAUL HERRANDEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 226-6500
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 2004-04-20

Site Id: 26012
Affiliation Type: Emergency Contact
Company Name: 17-19 BLEECKER STREET, LLC.
Contact Type: Not reported
Contact Name: TONY MATOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 217-2331
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 2004-04-20

17-19 BLEECKER STREET, LLC. (Continued) **A100147122**

Site Id:	26012
Affiliation Type:	Facility Owner
Company Name:	CDN REALTY LLC
Contact Type:	PROPERTY MGR
Contact Name:	DANIEL HOCHBERG
Address1:	825 THIRD AVE. 37TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 747-3396
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-07-16

Site Id:	26012
Affiliation Type:	Mail Contact
Company Name:	CDN REALTY LLC
Contact Type:	PROPERTY MGR
Contact Name:	DANIEL HOCHBERG
Address1:	825 THIRD AVE. 37TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 747-3396
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-07-16

Tank Info:

Tank Number:	001
Tank Id:	56768
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

Tank Location: 3

17-19 BLEECKER STREET, LLC. (Continued) **A100147122**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

I178 **V6421** **RCRA NonGen / NLR** **1007206920**
WNW **3 W. 3RD STREET** **NY MANIFEST** **NYP004033858**
< 1/8 **NEW YORK CITY, NY 10012**
0.093 mi.
491 ft. **Site 11 of 13 in cluster I**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/03/2001
Facility name:	V6421
Facility address:	3 W. 3RD STREET NEW YORK CITY, NY 10012
EPA ID:	NYP004033858
Mailing address:	CONSOLIDATED EDISON INC. 4 IRVING PLACE -- ROOM 300 NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC. NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

V6421 (Continued) **1007206920**

Historical Generators:
Date form received by agency: 01/02/2001
Site name: V6421
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V6421
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004033858
Facility Status: Not reported
Location Address 1: V6421-39 W 3RD ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004033858
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0244394
Manifest Status: Not reported
seq: 01
Year: 1999
Trans1 State ID: GX3213
Trans2 State ID: Not reported
Generator Ship Date: 04/05/1999
Trans1 Recv Date: 04/05/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/05/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004033858
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported

V6421 (Continued) **1007206920**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	02071
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H179 **34 COOPER SQUARE** **NY AST** **A100292165**
NE **34 COOPER SQUARE** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.093 mi.
493 ft. **Site 18 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608744
Program Type:	PBS
UTM X:	590669.99829
UTM Y:	4524632.90359
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	30595
Affiliation Type:	Facility Owner
Company Name:	COOPER SQUARE ASS. LIMITED PARTNERSHIP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	667 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 308-3336
EMail:	Not reported

34 COOPER SQUARE (Continued) **A100292165**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	30595
Affiliation Type:	Facility Operator
Company Name:	34 COOPER SQUARE
Contact Type:	Not reported
Contact Name:	JERRY SIMO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-5554
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	30595
Affiliation Type:	Emergency Contact
Company Name:	COOPER SQUARE ASS. LIMITED PARTNERSHIP
Contact Type:	Not reported
Contact Name:	BRIAN CHABRUNN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(201) 272-5717
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-04-08
Site Id:	30595
Affiliation Type:	Mail Contact
Company Name:	HARTZ MOUNTAIN INDUSTRIES
Contact Type:	Not reported
Contact Name:	BRIAN CHABRUNN
Address1:	667 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 308-3336
EMail:	BRIAN.CHABRUNN@HARTZMOUNTAIN.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-04-08

Tank Info:

34 COOPER SQUARE (Continued) **A100292165**

Tank Number: 001
Tank Id: 65591
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1990
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/20/2006
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

H180 **CON EDISON SERVICE BOX: 30936** **RCRA NonGen / NLR** **1017771984**
NE **34 COOPER SQ FRONT OF** **FINDS** **NYP004489316**
< 1/8 **NEW YORK, NY 10003**
0.093 mi.
493 ft. **Site 19 of 26 in cluster H**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:
Date form received by agency: 05/03/2014
Facility name: CON EDISON SERVICE BOX: 30936
Facility address: 34 COOPER SQ FRONT OF
NEW YORK, NY 10003
EPA ID: NYP004489316
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

CON EDISON SERVICE BOX: 30936 (Continued) **1017771984**

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 04/03/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/03/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063806010

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

H181 **CON EDISON** **NY MANIFEST** **S116550540**
NE **34 COOPER SQ FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.093 mi.
493 ft. **Site 20 of 26 in cluster H**

Relative: **Lower**
Actual: **41 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004489316
Facility Status:	Not reported
Location Address 1:	F/O 34 COOPER SQUARE
Code:	BP
Location Address 2:	SB 30936
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

CON EDISON (Continued) **S116550540**

NY MANIFEST:

EPAID:	NYP004489316
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2014
Trans1 Recv Date:	04/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004489316
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406280GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S116550540**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J182 **56 EAST 4TH STREET** **NY AST** **A100178010**
ESE **56 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.093 mi.
493 ft. **Site 2 of 20 in cluster J**

Relative:
Lower

Actual:
40 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605709
Program Type: PBS
UTM X: 585201.28048
UTM Y: 4508950.44835
Expiration Date: 04/18/2021
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 27576
Affiliation Type: Mail Contact
Company Name: COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type: Not reported
Contact Name: VALERIO ORSELLI
Address1: 59-61 EAST 4TH STREET
Address2: 3RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 477-5340
EMail: VORSELL@CSMHA.ORG
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-03-22

Site Id: 27576
Affiliation Type: Emergency Contact
Company Name: COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type: Not reported
Contact Name: EFRAIN CONCEPCION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 246-3870
EMail: Not reported

56 EAST 4TH STREET (Continued) **A100178010**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27576
Affiliation Type:	Facility Owner
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION II HDFC
Contact Type:	EXEC. DIR.
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET, 3RD FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-20

Site Id:	27576
Affiliation Type:	Facility Operator
Company Name:	56 EAST 4TH STREET
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	003
Tank Id:	60264
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle

56 EAST 4TH STREET (Continued) **A100178010**

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/06/1998
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

I183 **670 BROADWAY** **NY AST** **A100293958**
West **670 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.094 mi.
494 ft. **Site 12 of 13 in cluster I**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608613
Program Type:	PBS
UTM X:	584863.86216
UTM Y:	4508976.98095
Expiration Date:	10/29/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30465
Affiliation Type:	Emergency Contact
Company Name:	F.D.R. INDUSTRIES, INC.
Contact Type:	Not reported
Contact Name:	JOHN O'SULLIVAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 607-8446
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-02-14

Site Id:	30465
Affiliation Type:	Facility Operator
Company Name:	670 BROADWAY
Contact Type:	Not reported
Contact Name:	JOHN O'SULLIVAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

670 BROADWAY (Continued) **A100293958**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-2950
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-03-14

Site Id: 30465
Affiliation Type: Facility Owner
Company Name: 670 BROADWAY OWNER LP
Contact Type: PROPERTY MANAGER
Contact Name: DAVID CROCE
Address1: 1633 BROADWAY SUITE 1801
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 246-2950
EMail: DCROCE@PARAMOUNT-GROUP.COM
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-03-14

Site Id: 30465
Affiliation Type: Mail Contact
Company Name: 670 BROADWAY OWNER LP
Contact Type: PROPERTY MANAGER
Contact Name: DAVID CROCE
Address1: 1633 BROADWAY SUITE 1801
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 246-2950
EMail: DCROCE@PARAMOUNT-GROUP.COM
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-03-14

Tank Info:

Tank Number: 001
Tank Id: 65384
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None

670 BROADWAY (Continued) **A100293958**

G03 - Tank Secondary Containment - Vault (w/o access)
A01 - Tank Internal Protection - Epoxy Liner
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/30/1971
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	03/14/2018
Material Name:	#2 fuel oil (on-site consumption)

G184 **WYOMING ARTS, CONDOMINIUM** **NY AST** **A100300314**
ESE **5 EAST 3RD STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.094 mi.
496 ft. **Site 3 of 12 in cluster G**

Relative: **Lower**
Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610364
Program Type:	PBS
UTM X:	585159.61358
UTM Y:	4508869.12820
Expiration Date:	06/26/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	371405
Affiliation Type:	Facility Owner
Company Name:	WYOMING ARTS CONDOMINIUM C/O ANDREWS ORG
Contact Type:	MANAGING AGENT
Contact Name:	GEOFFREY HULL
Address1:	666 BROADWAY 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	371405

WYOMING ARTS, CONDOMINIUM (Continued) **A100300314**

Affiliation Type:	Facility Operator
Company Name:	WYOMING ARTS, CONDOMINIUM
Contact Type:	Not reported
Contact Name:	MARC GILBERT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 423-5098
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	371405
Affiliation Type:	Emergency Contact
Company Name:	WYOMING ARTS CONDOMINIUM C/O ANDREWS ORG
Contact Type:	Not reported
Contact Name:	ANDREWS ORG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-06-03

Site Id:	371405
Affiliation Type:	Mail Contact
Company Name:	ANDREWS ORGANIZATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-13

Tank Info:

Tank Number:	1
Tank Id:	213887
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

WYOMING ARTS, CONDOMINIUM (Continued) **A100300314**

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1982
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

G185 **5 EAST THIRD STREET** **NY AST** **A100183440**
ESE **5 E THIRD STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.094 mi.
496 ft. **Site 4 of 12 in cluster G**

Relative: **Lower**
Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-606868
Program Type:	PBS
UTM X:	585192.85208
UTM Y:	4508857.27595
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	28723
Affiliation Type:	Emergency Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	213/215 MOTT ST. H.D.F.C.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

5 EAST THIRD STREET (Continued) **A100183440**

Phone:	(646) 613-0908
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-03-04

Site Id:	28723
Affiliation Type:	Mail Contact
Company Name:	NYC/HPD/DAMP
Contact Type:	Not reported
Contact Name:	ASST. COMMISSIONER/DAMP
Address1:	100 GOLD STREET # 7Z5
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-7301
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-03

Site Id:	28723
Affiliation Type:	Facility Operator
Company Name:	5 EAST STREET
Contact Type:	Not reported
Contact Name:	ASST. COMM. DAMP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 863-7301
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-07-11

Site Id:	28723
Affiliation Type:	Facility Owner
Company Name:	NYC/HPD/DAMP
Contact Type:	100 GOLD ST # 7Z5
Contact Name:	WILLA H. PADGETT
Address1:	100 GOLD ST # 7Z5
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-7301
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-07-11

5 EAST THIRD STREET (Continued) **A100183440**

Tank Info:

Tank Number:	001
Tank Id:	61966
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/17/2015
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

F186 **CON EDISON SERVICE BOX: 26587** **NJ MANIFEST** **S117987134**
South **23 BLEECKER ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.094 mi.
497 ft. **Site 26 of 28 in cluster F**

Relative: NJ MANIFEST:
Higher

Actual: EPA Id:	NYP004280129
43 ft. Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

CON EDISON SERVICE BOX: 26587 (Continued) **S117987134**

Manifest:

Manifest Number:	010840348JJK
EPA ID:	NYP004280129
Date Shipped:	12/10/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	500.00 Pounds

F187 **CON EDISON SERVICE BOX: 26587** **RCRA NonGen / NLR** **1016149349**
South **23 BLEECKER ST** **FINDS** **NYP004280129**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.094 mi. **NY MANIFEST**
497 ft. **Site 27 of 28 in cluster F**

Relative: Higher

Actual: 43 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26587
Facility address:	23 BLEECKER ST NEW YORK, NY 10012
EPA ID:	NYP004280129
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	JUAN RODRIGUEZ
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-865-5931
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/10/2012
Site name:	CON EDISON SERVICE BOX: 26587
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110055454066

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 26587 (Continued) **1016149349**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149349
Registry ID:	110055454066
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055454066

NY MANIFEST:

Country:	USA
EPA ID:	NYP004280129
Facility Status:	Not reported
Location Address 1:	23 BLEECKER ST
Code:	BP
Location Address 2:	SERV BOX 26587
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004280129
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

K188 **RESIDENTS** **NY Spills** **S105142425**
SSW **33 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.095 mi.
500 ft. **Site 1 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

SPILLS:

Facility ID:	0106638
Facility Type:	ER
Spill Number:	0106638
DER Facility ID:	205044
Site ID:	250155
DEC Region:	2
Closed Date:	2001-09-26
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-09-25
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2001-09-25

RESIDENTS (Continued) **S105142425**

CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-25
Spill Record Last Update:	2001-09-26
Spiller Name:	SAME
Spiller Company:	MYSTIC CARRIERS
Spiller Address:	19-01 STEINWAY STREET
Spiller Company:	001
Contact Name:	PABLO RODRIGUEZ
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 9/25 OIL COMPANY CLEANED, SPILL CONFINED TO SIDEWALK"
Remarks:	"FAULTY GAUGE CAUSED THE SPILL "

All Materials:

Site ID:	250155
Operable Unit ID:	843697
Operable Unit:	01
Material ID:	531484
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K189 **CON EDISON** **NY MANIFEST** **S117564664**
SSW **33 BLEECKER ST FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.095 mi.
500 ft. **Site 2 of 26 in cluster K**

Relative: **Higher**
Actual: **43 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004481255
Facility Status:	Not reported
Location Address 1:	BROADWAY 33 SSC BLEECKER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004481255
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON

CON EDISON (Continued) **S117564664**

Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2014
Trans1 Recv Date:	03/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004481255
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406172GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117564664**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

K190 **33 BLEECKER STREET CORP.** **NY AST** **A100194100**
SSW **33 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.095 mi.
500 ft. **Site 3 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607052
Program Type:	PBS
UTM X:	584985.66769
UTM Y:	4508791.52704
Expiration Date:	10/02/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	28907
Affiliation Type:	Mail Contact
Company Name:	33 BLEECKER STREET CORP.
Contact Type:	Not reported
Contact Name:	CANDICE KUGEL
Address1:	33 BLEECKER STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 473-8800
EMail:	CANDYK@BUZZZCO.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-11-07

Site Id:	28907
Affiliation Type:	Facility Operator
Company Name:	33 BLEECKER STREET CORP.
Contact Type:	Not reported
Contact Name:	KATHERINE TIDDENS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 473-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-11-07

Site Id:	28907
Affiliation Type:	Emergency Contact

33 BLEECKER STREET CORP. (Continued) **A100194100**

Company Name:	33 BLEECKER STREET CORP.
Contact Type:	Not reported
Contact Name:	GLEN COHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 579-0006
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-11-07

Site Id:	28907
Affiliation Type:	Facility Owner
Company Name:	33 BLEECKER STREET CORP.
Contact Type:	TREASURER
Contact Name:	CANDICE KUGAL
Address1:	33 BLEECKER STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 473-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-10-11

Tank Info:

Tank Number:	01
Tank Id:	62234
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
B99 - Tank External Protection - Other
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	4
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

33 BLEECKER STREET CORP. (Continued) **A100194100**

Pipe Model:	Not reported
Install Date:	01/01/1952
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	10/11/2016
Date Tank Closed:	Not reported
Register:	True
Modified By:	msbaptis
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

K191 **CON EDISON MANHOLE: 59188** **RCRA NonGen / NLR** **1016974307**
SSW **33 BLEECKER ST FRONT OF** **NYP004481255**
< 1/8 **NEW YORK, NY 10012**
0.095 mi.
500 ft. **Site 4 of 26 in cluster K**

Relative: **Higher**

Actual: **43 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/27/2014
Facility name:	CON EDISON MANHOLE: 59188
Facility address:	33 BLEECKER ST FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004481255
Mailing address:	IRVG PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/27/2014
Site name:	CON EDISON MANHOLE: 59188
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON MANHOLE: 59188 (Continued) **1016974307**

Violation Status: No violations found

G192 **CON EDISON SERVICE BOX: 26844** **RCRA NonGen / NLR** **1016148840**
SE **331 BOWERY FRONT OF** **FINDS** **NYP004274916**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.095 mi. **NY MANIFEST**
503 ft. **Site 5 of 12 in cluster G**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26844
Facility address:	331 BOWERY FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004274916
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/19/2012
Site name:	CON EDISON SERVICE BOX: 26844
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055421565

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CON EDISON SERVICE BOX: 26844 (Continued) **1016148840**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016148840
Registry ID:	110055421565
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055421565

NY MANIFEST:

Country:	USA
EPA ID:	NYP004274916
Facility Status:	Not reported
Location Address 1:	F/O 33 BOWERY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004274916
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2012
Trans1 Recv Date:	10/19/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004274916
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046

CON EDISON SERVICE BOX: 26844 (Continued) **1016148840**

TSDF ID 2:	Not reported
Manifest Tracking Number:	010456409JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

G193 **CON EDISON SERVICE BOX: 26844** **NJ MANIFEST** **S117986792**
SE **331 BOWERY FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.095 mi.
503 ft. **Site 6 of 12 in cluster G**

Relative: **Lower**

Actual: **41 ft.**

NJ MANIFEST:

EPA Id:	NYP004274916
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON SERVICE BOX: 26844 (Continued) **S117986792**

Date Change:	Not reported
Manifest:	
Manifest Number:	010456409JJK
EPA ID:	NYP004274916
Date Shipped:	10/19/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported
Waste:	
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

L194 **712-714 BROADWAY CORP.** **NY AST** **U004045738**
NNW **714 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.095 mi.
504 ft. **Site 1 of 16 in cluster L**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-328200
Program Type:	PBS
UTM X:	585010.29782
UTM Y:	4509201.93458
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	15361
Affiliation Type:	Facility Owner
Company Name:	712-714 BROADWAY CORP % ANDREWS BUILDING CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	666 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	15361
Affiliation Type:	Mail Contact
Company Name:	ANDREWS BUILDING CORP.
Contact Type:	Not reported
Contact Name:	STUART SMOLAR
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-05-08

Site Id:	15361
Affiliation Type:	Facility Operator
Company Name:	712-714 BROADWAY CORP.
Contact Type:	Not reported
Contact Name:	712-714 BROADWAY CORP.
Address1:	Not reported
Address2:	Not reported
City:	Not reported

712-714 BROADWAY CORP. (Continued) **U004045738**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 260-1751
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	15361
Affiliation Type:	Emergency Contact
Company Name:	712-714 BROADWAY CORP % ANDREWS BUILDING CORP.
Contact Type:	Not reported
Contact Name:	STUART SMOLAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	20628
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1993
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017

712-714 BROADWAY CORP. (Continued) **U004045738**

Material Name: #2 fuel oil (on-site consumption)

M195 **MANHOLE #31124** **NY Spills** **S103827171**
WSW **CROSBY ST/BLEECKER ST** **N/A**
< 1/8 **NEW YORK, NY**
0.095 mi.
504 ft. **Site 1 of 26 in cluster M**

Relative: **Lower**

Actual: **40 ft.**

SPILLS:

Facility ID:	9812624
Facility Type:	ER
Spill Number:	9812624
DER Facility ID:	148915
Site ID:	177195
DEC Region:	2
Closed Date:	2004-01-08
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	1999-01-13
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-01-13
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-13
Spill Record Last Update:	2004-02-06
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MIKE CEASAR
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis no. 122403: APPROXIMATELY 50 GALLONS OF AN UNKNOWN LIQUID ON TOP OF APPROXIMATELY 50 GALLONS OF WATER.... LAB ANALYSIS 99-00352: PCB <1 PPM 1/13/99 clean up complete in MH #31124. Removed 950 gals. Oil/Water. Double washed & rinsed structure."
Remarks:	"CONED EMPLOYEES FOUND UNKNOWN TYPE OIL FLOATING ON TOP OF APPROX 50 GALLONS OF WATER IN THE ABOVE MANHOLE / OIL SAMPLES TAKEN AND CLEAN UP WILL BEGIN AFTER SAMPLES RETURN / CONED SPILL #122403"

All Materials:

Site ID:	177195
Operable Unit ID:	1073126
Operable Unit:	01
Material ID:	312901
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum

MANHOLE #31124 (Continued) **S103827171**

Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

F196 **SPILL NUMBER 0211638** **NY Spills** **S106124860**
South **17-19 BLEECKER ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.097 mi.
511 ft. **Site 28 of 28 in cluster F**

Relative: **Higher**

Actual: **43 ft.**

SPILLS:

Facility ID:	0211638
Facility Type:	ER
Spill Number:	0211638
DER Facility ID:	203031
Site ID:	247263
DEC Region:	2
Closed Date:	2003-11-13
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2003-01-15
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2003-02-24
CID:	205
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-24
Spill Record Last Update:	2003-11-13
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 2/25/2003-Vought-Spoke with Fred Caputo (Bayside Fuel 718-333-8880) and fill goes under sidewalk and into building. Spill caused by leaking fill line. Line was replaced and sidewalk was backfilled. Last delivery made on 2/3/2003. 4/11/2003-Vought-Received message from Tony (212-226-6500) that Miller performed work. Vought called Tony and Miller removed approximnately 10 cubic yards of soil were removed and fill line broke releasing fuel into vault. NYSDEC requires Site Plan, photos, disposal manifest, work invoice. Vought will notify Tony if endpoint samples are necessary once report with above requirements is received. 5/21/2003-Vought-Recieved the following from Tony Poulter: authorization for contractor (miller Environmental) to proceed, Miller invoice (for disposal of ten yards of soil), daily job report and disposal manifest. Vought called Tony

SPILL NUMBER 0211638 (Continued) **S106124860**

and told him that NYSDEC requires endpoint sampling from below depth of excavation and analyticals. 11/13/2003-Vought-Two soil cores performed by Miller on 5/29/03 from under former tank location. Soil analyzed for 8021/8270 analyses and show no TAGM 4046 Soil Cleanup Objectives exceedances. Spill closed by Vought."

Remarks: "CALLER LIVES IN APT HOUSE. SPILL NOT COMPLETELY CLEANED UP."

All Materials:

Site ID:	247263
Operable Unit ID:	862712
Operable Unit:	01
Material ID:	511423
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N197 **IN ROADWAY** **NY Spills** **S110243471**
SSE **BOND/BOWERY INTERSECTION** **N/A**
< 1/8 **MANHATTAN, NY**
0.098 mi.
515 ft. **Site 1 of 8 in cluster N**

Relative: **Higher**

Actual: **42 ft.**

SPILLS:

Facility ID:	0913422
Facility Type:	ER
Spill Number:	0913422
DER Facility ID:	375245
Site ID:	426366
DEC Region:	2
Closed Date:	2010-03-22
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2010-03-20
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2010-03-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-20
Spill Record Last Update:	2010-04-01
Spiller Name:	Not reported
Spiller Company:	unk
Spiller Address:	Not reported

IN ROADWAY (Continued) **S110243471**

Spiller Company: 999
Contact Name: FIRE FIGHTER CHAMBERS
DEC Memo: "03/20/10-Zhune spoke to FF Chambers. He said approximatelly 5 gallons of gasoline on the road. Little went to the drain. DEP was notified. FF put speedy-dry on the the spill. Sanitation will clean it up. Spill Closed. "
Remarks: "traffic accident spilling approx 5 gallons onto road, speedy dry applied. appprox 1 gallon went into sewer."

All Materials:
Site ID: 426366
Operable Unit ID: 1182048
Operable Unit: 01
Material ID: 2176194
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

G198 **335 BOWERY OPERATING CORP** **NY UST** **U001839290**
SE **335 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.098 mi.
516 ft. **Site 7 of 12 in cluster G**

Relative: **Lower**
Actual: **41 ft.**

UST:
Id/Status: 2-340278 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 585170.46003
UTM Y: 4508839.40811
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 16426
Affiliation Type: Facility Owner
Company Name: MERIT OIL OF NEW YORK INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 551 W LANCASTER AVE
Address2: Not reported
City: HAVERFORD
State: PA
Zip Code: 19041
Country Code: 001
Phone: (610) 527-7900
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16426

335 BOWERY OPERATING CORP (Continued) **U001839290**

Affiliation Type:	Mail Contact
Company Name:	MERIT OIL OF NEW YORK INC
Contact Type:	Not reported
Contact Name:	JACK ISRAEL
Address1:	551 W LANCASTER AVE
Address2:	Not reported
City:	HAVERFORD
State:	PA
Zip Code:	19041
Country Code:	001
Phone:	(215) 527-7900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16426
Affiliation Type:	Facility Operator
Company Name:	335 BOWERY OPERATING CORP
Contact Type:	Not reported
Contact Name:	335 BOWERY OPERATING CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-7790
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16426
Affiliation Type:	Emergency Contact
Company Name:	MERIT OIL OF NEW YORK INC
Contact Type:	Not reported
Contact Name:	G STEININGER-DIVISION MGR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 731-4100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47050
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000

335 BOWERY OPERATING CORP (Continued) **U001839290**

Install Date: 09/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 04/24/2002
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F05 - Pipe External Protection - Jacketed
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 001
Tank ID: 31576
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

335 BOWERY OPERATING CORP (Continued) **U001839290**

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	002
Tank ID:	47051
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	04/24/2002
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	002
Tank ID:	31577
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

335 BOWERY OPERATING CORP (Continued) **U001839290**

Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 003
Tank ID: 47052
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 09/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 04/24/2002
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 003
Tank ID: 31578
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 01/01/1994

335 BOWERY OPERATING CORP (Continued) **U001839290**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	004
Tank ID:	31579
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 005

335 BOWERY OPERATING CORP (Continued) **U001839290**

Tank ID:	31580
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	006
Tank ID:	31581
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

335 BOWERY OPERATING CORP (Continued) **U001839290**

I00 - Overfill - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	007
Tank ID:	31582
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	550
Install Date:	12/01/1973
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other
D00 - Pipe Type - No Piping

Tank Number:	1
Tank ID:	64591
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	02/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None

335 BOWERY OPERATING CORP (Continued) **U001839290**

C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	2
Tank ID:	64592
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	02/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	3
Tank ID:	64593
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	02/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT

335 BOWERY OPERATING CORP (Continued) **U001839290**

Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 4
Tank ID: 64594
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 02/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 5
Tank ID: 64595
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1973
Date Tank Closed: 02/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN

335 BOWERY OPERATING CORP (Continued) **U001839290**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 6
Tank ID: 64596
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1973
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 7
Tank ID: 64597
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

335 BOWERY OPERATING CORP (Continued) **U001839290**

Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Affiliation Records:

Site Id: 23550
Affiliation Type: Facility Owner
Company Name: JOHN RUCHA
Contact Type: Not reported
Contact Name: Not reported
Address1: 335 BOWERY ST.
Address2: Not reported
City: NEW YORK CITY
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 533-9173
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23550
Affiliation Type: Mail Contact
Company Name: JOHN RUCHA
Contact Type: Not reported
Contact Name: Not reported
Address1: BOWERY & EAST 3RD CORP.
Address2: 335 BOWERY
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 533-9173
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23550
Affiliation Type: Facility Operator

335 BOWERY OPERATING CORP (Continued) **U001839290**

Company Name:	BOWERY & EAST 3RD CORP.
Contact Type:	Not reported
Contact Name:	JUAN MUNOZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 533-9173
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23550
Affiliation Type:	Emergency Contact
Company Name:	JOHN RUCHA
Contact Type:	Not reported
Contact Name:	JOHN RUCHA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 533-9173
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47050
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	21
Date Test:	04/24/2002
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass

335 BOWERY OPERATING CORP (Continued) **U001839290**

J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F05 - Pipe External Protection - Jacketed
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	001
Tank ID:	31576
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	002
Tank ID:	47051
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

335 BOWERY OPERATING CORP (Continued) **U001839290**

Tightness Test Method: 21
Date Test: 04/24/2002
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 002
Tank ID: 31577
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 003
Tank ID: 47052
Tank Status: Closed - Removed

335 BOWERY OPERATING CORP (Continued) **U001839290**

Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	09/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	21
Date Test:	04/24/2002
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	003
Tank ID:	31578
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

335 BOWERY OPERATING CORP (Continued) **U001839290**

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	004
Tank ID:	31579
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	005
Tank ID:	31580
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	12/01/1973
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

335 BOWERY OPERATING CORP (Continued) **U001839290**

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 31581
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: 12/01/1973
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 007
Tank ID: 31582
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

335 BOWERY OPERATING CORP (Continued) **U001839290**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other
D00 - Pipe Type - No Piping

Tank Number: 1
Tank ID: 64591
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 02/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 2
Tank ID: 64592
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 02/01/1994
Registered: True
Tank Location: Underground

335 BOWERY OPERATING CORP (Continued) **U001839290**

Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 3
Tank ID: 64593
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1973
Date Tank Closed: 02/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 4
Tank ID: 64594
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000

335 BOWERY OPERATING CORP (Continued) **U001839290**

Install Date:	12/01/1973
Date Tank Closed:	02/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	5
Tank ID:	64595
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1973
Date Tank Closed:	02/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 6

335 BOWERY OPERATING CORP (Continued) **U001839290**

Tank ID:	64596
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1973
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	7
Tank ID:	64597
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1973
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

335 BOWERY OPERATING CORP (Continued) **U001839290**

F00 - Pipe External Protection - None

G199 **335 BOWERY OPERATING CORP** **EDR Hist Auto** **1021877782**
SE **335 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.098 mi.
516 ft. **Site 8 of 12 in cluster G**

Relative: EDR Hist Auto
Lower

Actual: **41 ft.**

Year:	Name:	Type:
1994	335 BOWERY OPERATING CORP	Gasoline Service Stations
1995	335 BOWERY OPERATING CORP	Gasoline Service Stations
1996	335 BOWERY OPERATING CORP	Gasoline Service Stations
1997	335 BOWERY OPERATING CORP	Gasoline Service Stations

G200 **CON EDISON** **NY MANIFEST** **S117066082**
SE **335 BOWERY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.098 mi.
516 ft. **Site 9 of 12 in cluster G**

Relative: NY MANIFEST:
Lower

Actual: **41 ft.**

Country:	USA
EPA ID:	NYP004586996
Facility Status:	Not reported
Location Address 1:	335 BOWERY
Code:	BP
Location Address 2:	SB 26846
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586996
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014

CON EDISON (Continued) **S117066082**

Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586996
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423814GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H201 **CON EDISON SERVICE BOX: 30936** **RCRA NonGen / NLR** **1016148952**
ENE **36 COOPER SQ FRONT OF** **FINDS** **NYP004276044**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.098 mi. **NY MANIFEST**
518 ft. **Site 21 of 26 in cluster H**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 30936
Facility address:	36 COOPER SQ FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004276044
Mailing address:	IRVING PL, RM 828

CON EDISON SERVICE BOX: 30936 (Continued) **1016148952**

NEW YORK, NY 10003
Contact: BENJAMIN BAMONTE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-894-9549
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/24/2012
Site name: CON EDISON SERVICE BOX: 30936
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055460291

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148952
Registry ID: 110055460291
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055460291

CON EDISON SERVICE BOX: 30936 (Continued) **1016148952**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004276044
Facility Status:	Not reported
Location Address 1:	F/O 36 COOPER SQ.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004276044
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2012
Trans1 Recv Date:	10/24/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004276044
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456425JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported

CON EDISON SERVICE BOX: 30936 (Continued) **1016148952**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

H202 **CON EDISON SERVICE BOX: 30936** **NJ MANIFEST** **S117986896**
ENE **36 COOPER SQ FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.098 mi.
518 ft. **Site 22 of 26 in cluster H**

Relative: **Lower**

Actual: **41 ft.**

NJ MANIFEST:

EPA Id:	NYP004276044
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456425JJK
EPA ID:	NYP004276044
Date Shipped:	10/24/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON SERVICE BOX: 30936 (Continued) **S117986896**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	2,500.00 Pounds

L203 **VERSAKLEEN DRY CLEANING CORP** **EDR Hist Cleaner** **1018718604**
NW **8 W 4TH ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.098 mi.
519 ft. **Site 2 of 16 in cluster L**

Relative: EDR Hist Cleaner
Lower

Actual: **39 ft.**

Year:	Name:	Type:
1982	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1983	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1985	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1986	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1987	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1988	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1989	KLEEN VERA CLEANERS	Drycleaning Plants, Except Rugs, NEC
1989	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1990	KLEEN VERA CLEANERS	Drycleaning Plants, Except Rugs, NEC
1990	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs

VERSAKLEEN DRY CLEANING CORP (Continued) **1018718604**

1991	KLEEN VERA CLEANERS	Drycleaning Plants, Except Rugs, NEC
1991	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1992	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1993	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1994	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1995	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1996	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1997	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1998	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
1999	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2000	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2001	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2002	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2003	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2004	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2005	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2006	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2007	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2008	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2009	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2010	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2011	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs
2012	VERSAKLEEN DRY CLEANING CORP	Drycleaning Plants, Except Rugs

---

G204 **CITY OF N.Y. DEPT OF H.P.D.** **NY AST** **U003395915**
ESE **7 EAST 3RD STREET** **N/A**
< 1/8 **MANHATTAN, NY 10003**
0.099 mi.
521 ft. **Site 10 of 12 in cluster G**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601040
Program Type:	PBS
UTM X:	585212.33706
UTM Y:	4508870.30856
Expiration Date:	05/13/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23010
Affiliation Type:	Facility Operator
Company Name:	CITY OF N.Y. DEPT OF H.P.D.
Contact Type:	Not reported
Contact Name:	MARK TAMBELLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 353-0385
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-03-18

CITY OF N.Y. DEPT OF H.P.D. (Continued) **U003395915**

Site Id:	23010
Affiliation Type:	Mail Contact
Company Name:	KAMAN MGMT. CORP
Contact Type:	Not reported
Contact Name:	SCOTT KAMEN
Address1:	4 LIBERTY STREET
Address2:	Not reported
City:	OSSINING
State:	NY
Zip Code:	10562
Country Code:	001
Phone:	(212) 979-9282
EMail:	SCOTT@KAMENMGMT.COM
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-03-18

Site Id:	23010
Affiliation Type:	Emergency Contact
Company Name:	7 EAST 3 STREET H.D.F.C
Contact Type:	Not reported
Contact Name:	MARK TAMBELLA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 477-9588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-03-18

Site Id:	23010
Affiliation Type:	Facility Owner
Company Name:	7 EAST 3 STREET H.D.F.C
Contact Type:	MANAGER
Contact Name:	SCOTT KAMEN
Address1:	7 EAST 3RD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 979-9286
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-03-18

Tank Info:

Tank Number:	1
Tank Id:	44739
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

CITY OF N.Y. DEPT OF H.P.D. (Continued) **U003395915**

Equipment Records:

A00 - Tank Internal Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/07/1999
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

I205 **ALCON ENGRAVERS INC** **RCRA NonGen / NLR** **1000336623**
WSW **656 BROADWAY** **FINDS** **NYD001507250**
< 1/8 **NEW YORK, NY 10012** **ECHO**
0.099 mi. **NY MANIFEST**
525 ft. **Site 13 of 13 in cluster I**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ALCON ENGRAVERS INC
Facility address:	656 BROADWAY NEW YORK, NY 10012
EPA ID:	NYD001507250
Mailing address:	BROADWAY NEW YORK, NY 10012
Contact:	ALCON SAME
Contact address:	BROADWAY NEW YORK, NY 10012
Contact country:	US
Contact telephone:	212-777-4040
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	FRAR CALASCIONE PRES
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212

ALCON ENGRAVERS INC (Continued) **1000336623**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FRAR CALASCIONE PRES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ALCON ENGRAVERS INC
Classification: Not a generator, verified

Date form received by agency: 11/25/1980
Site name: ALCON ENGRAVERS INC
Classification: Unverified

. Waste code: D002
. Waste name: CORROSIVE WASTE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/01/1986
Date achieved compliance: 07/10/1986
Violation lead agency: State

ALCON ENGRAVERS INC (Continued) **1000336623**

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/10/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/01/1986
Date achieved compliance: 07/10/1986
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 06/30/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 750
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/01/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/01/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 07/10/1986
Evaluation lead agency: State

FINDS:

Registry ID: 110004335069

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000336623
Registry ID: 110004335069
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004335069

ALCON ENGRAVERS INC (Continued) **1000336623**

NY MANIFEST:

Country:	USA
EPA ID:	NYD001507250
Facility Status:	Not reported
Location Address 1:	656 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001507250
Mailing Name:	ALCON ENGRAVERS INC
Mailing Contact:	ALCON ENGRAVERS INC
Mailing Address 1:	323 WEST 39TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10018
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	NYA3084682
Manifest Status:	C
seq:	Not reported
Year:	1986
Trans1 State ID:	NY8385-RW
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/1986
Trans1 Recv Date:	08/15/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/18/1986
Part A Recv Date:	08/18/1986
Part B Recv Date:	08/22/1986
Generator EPA ID:	NYD001507250
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES

ALCON ENGRAVERS INC (Continued) **1000336623**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	145

Click this hyperlink while viewing on your computer to access
21 additional NY_MANIFEST: record(s) in the EDR Site Report.

L206 **CON EDISON** **NJ MANIFEST** **S120673596**
NNW **699 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.100 mi.
530 ft. **Site 3 of 16 in cluster L**

Relative: **Lower**

Actual: **39 ft.**

NJ MANIFEST:

EPA Id:	NYP004803516
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614591GBF
EPA ID:	NYP004803516
Date Shipped:	7/7/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **S120673596**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L207 **CON EDISON** **NY MANIFEST** **S118257598**
NNW **699 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.100 mi.
530 ft. **Site 4 of 16 in cluster L**

Relative: **Lower**
Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004803516
Facility Status:	Not reported
Location Address 1:	699 BROADWAY
Code:	BP
Location Address 2:	SB 28809
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004803516
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S118257598**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2015
Trans1 Recv Date:	07/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004803516
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614591GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

L208 **CON EDISON** **RCRA NonGen / NLR** **1019904907**
NNW **699 BROADWAY** **NYP004803516**
< 1/8 **NEW YORK, NY 10003**
0.100 mi.
530 ft. **Site 5 of 16 in cluster L**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/07/2015
Facility name:	CON EDISON
Facility address:	699 BROADWAY NEW YORK, NY 10003
EPA ID:	NYP004803516
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/07/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

H209 **CON EDISON SERVICE BOX: 30937** **RCRA NonGen / NLR** **1017772002**
NE **40 COOPER SQ FRONT OF** **FINDS** **NYP004489498**
< 1/8 **NEW YORK, NY 10003**
0.102 mi.
538 ft. **Site 23 of 26 in cluster H**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/04/2014
Facility name:	CON EDISON SERVICE BOX: 30937
Facility address:	40 COOPER SQ FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004489498

CON EDISON SERVICE BOX: 30937 (Continued) **1017772002**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/04/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/04/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063806181

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

H210 **CON EDISON** **NY MANIFEST** **S116550560**
NE **40 COOPER SQ FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.102 mi.
538 ft. **Site 24 of 26 in cluster H**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004489498
Facility Status:	Not reported
Location Address 1:	F/O 40 COOPER SQUARE
Code:	BP
Location Address 2:	SB 30932
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004489498
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2014
Trans1 Recv Date:	04/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004489498
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406278GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S116550560**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

G211 **SPILL NUMBER 9812634** **NY Spills** **S104648449**
SE **8 EAST 3RD ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.102 mi.
538 ft. **Site 11 of 12 in cluster G**

Relative: SPILLS:
Lower

Actual:
40 ft.

Facility ID:	9812634
Facility Type:	ER
Spill Number:	9812634
DER Facility ID:	135823
Site ID:	160868
DEC Region:	2
Closed Date:	1999-01-14
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-01-13
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-01-13
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-13

SPILL NUMBER 9812634 (Continued) **S104648449**

Spill Record Last Update:	2002-05-20
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE BLDG MANAGER MISDIRECTED DRIVER TO FILL WRONG TANK. TANK OVERFILLED INTO GUTTER AND RAN DOWN STREET TO CATCH BASIN ON 2ND AND EAST 3RD. SUPERINTENDANT APPLIED SPEEDI DRI BUT OIL WAS IN CATCH BASIN. SUPERINTENDANT WAS INFORMED TO CLEAN OUT CATCH BASIN. DEP NOTIFIED OF SITUATION."
Remarks:	"CALLER STATES THAT HE SAW A TRUCK DUMP THE OIL AND THEN DRIVE OFF. CALLER SAYS IT IS A LOT OF OIL."

All Materials:

Site ID:	160868
Operable Unit ID:	1073130
Operable Unit:	01
Material ID:	312910
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0601756
Facility Type:	ER
Spill Number:	0601756
DER Facility ID:	314264
Site ID:	364059
DEC Region:	2
Closed Date:	2006-05-23
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-05-17
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-05-17
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-05-17
Spill Record Last Update:	2006-05-23
Spiller Name:	ROBERT TORRES
Spiller Company:	DEPT. OF HOMELESS SERVICE

SPILL NUMBER 9812634 (Continued) **S104648449**

Spiller Address:	8 EAST 3RD STREET
Spiller Company:	001
Contact Name:	ROBERT TORRES
DEC Memo:	"minor spill - gauge problem. Metro repaired the gauge & cleaned the spill from vent pipe."
Remarks:	"VENT PIPE MALFUNCTION- IS CONTAINED AND BEING CLEANED UP AT THIS TIME"

All Materials:

Site ID:	364059
Operable Unit ID:	1122111
Operable Unit:	01
Material ID:	2111596
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G212 **MEN'S SHELTER** **NY AST** **U004079109**
SE **8 EAST 3RD STREET** **N/A**
< 1/8 **MANHATTAN, NY 10003**
0.102 mi.
538 ft. **Site 12 of 12 in cluster G**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601677
Program Type:	PBS
UTM X:	585213.89411
UTM Y:	4508822.77090
Expiration Date:	05/05/2019
Site Type:	Other

Affiliation Records:

Site Id:	23639
Affiliation Type:	Facility Operator
Company Name:	MENS SHELTER
Contact Type:	Not reported
Contact Name:	HARRY ZINK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 688-8941
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-27

Site Id:	23639

MEN'S SHELTER (Continued) **U004079109**

Affiliation Type:	Mail Contact
Company Name:	NYS DEPT. OF HOMELESS SERVICES
Contact Type:	Not reported
Contact Name:	PETE DEMPSEY
Address1:	101-07 FARRAGUT RD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11236
Country Code:	001
Phone:	(718) 688-8520
EMail:	PDEMPSEY@DHS.NYC.GOV
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-27

Site Id:	23639
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPT. OF HOMELESS SERVICES
Contact Type:	Not reported
Contact Name:	PETE DEMPSEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 682-8408
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-18

Site Id:	23639
Affiliation Type:	Facility Owner
Company Name:	NYC DEPT. OF HOMELESS SERVICES
Contact Type:	DIRECTOR
Contact Name:	PETE DEMPSEY
Address1:	101-07 FARRAGUT RD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11236
Country Code:	001
Phone:	(718) 688-8565
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-27

Tank Info:

Tank Number:	001
Tank Id:	47462
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

MEN'S SHELTER (Continued) **U004079109**

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1953
Capacity Gallons: 10000
Tightness Test Method: 21
Date Test: 08/30/2001
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 47463
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1953
Capacity Gallons: 10000
Tightness Test Method: 21
Date Test: 08/30/2001
Next Test Date: Not reported

MEN'S SHELTER (Continued) **U004079109**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	003
Tank Id:	47464
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1980
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	diesel

N213 **CON EDISON SERVICE BOX: 26843** **RCRA NonGen / NLR** **1016148837**
SE **327 BOWERY FRONT OF** **FINDS** **NYP004274882**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.102 mi. **NY MANIFEST**
539 ft. **Site 2 of 8 in cluster N**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26843
Facility address:	327 BOWERY FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004274882
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549

CON EDISON SERVICE BOX: 26843 (Continued) **1016148837**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/19/2012
Site name: CON EDISON SERVICE BOX: 26843
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055421556

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148837
Registry ID: 110055421556
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055421556

NY MANIFEST:
Country: USA
EPA ID: NYP004274882
Facility Status: Not reported
Location Address 1: F/O 327 BOWERY
Code: BP

CON EDISON SERVICE BOX: 26843 (Continued) **1016148837**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004274882
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2012
Trans1 Recv Date:	10/19/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004274882
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456410JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150.0

CON EDISON SERVICE BOX: 26843 (Continued) **1016148837**

Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

N214 **CON EDISON SERVICE BOX: 26843** **NJ MANIFEST** **S117986789**
SE **327 BOWERY FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.102 mi.
539 ft. **Site 3 of 8 in cluster N**

Relative:
Lower

Actual:
41 ft.

NJ MANIFEST:

EPA Id:	NYP004274882
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456410JJK
EPA ID:	NYP004274882
Date Shipped:	10/19/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON SERVICE BOX: 26843 (Continued) **S117986789**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	2,000.00 Pounds

L215 **718 APT INC** **NY AST** **U003389452**
North **718 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.102 mi.
539 ft. **Site 6 of 16 in cluster L**

Relative:
Lower

Actual:
41 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-318833
Program Type:	PBS
UTM X:	585020.25475
UTM Y:	4509217.48043
Expiration Date:	08/28/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14721
Affiliation Type:	Facility Owner
Company Name:	718 APT INC.
Contact Type:	AGENT
Contact Name:	JEFFREY S. WIEN
Address1:	718 BROADWAY
Address2:	Not reported
City:	NEW YORK

718 APT INC (Continued) **U003389452**

State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 307-0500
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-09-19

Site Id: 14721
Affiliation Type: Mail Contact
Company Name: ABC REALTY
Contact Type: Not reported
Contact Name: JEFFREY S.WIEN
Address1: 152 WEST 57TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 307-0500
EMail: JEFFWEIN@ABCMGMT.NET
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-09-19

Site Id: 14721
Affiliation Type: Facility Operator
Company Name: 718 APT INC
Contact Type: Not reported
Contact Name: GERARDO CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 307-0500
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-09-19

Site Id: 14721
Affiliation Type: Emergency Contact
Company Name: 718 APT INC.
Contact Type: Not reported
Contact Name: ABC REALTY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 307-0500
EMail: Not reported
Fax Number: Not reported

718 APT INC (Continued) **U003389452**

Modified By: MFLEONAR
Date Last Modified: 2017-09-19

Tank Info:

Tank Number: 001
Tank Id: 16734
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/21/1980
Capacity Gallons: 5500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 09/19/2017
Material Name: #2 fuel oil (on-site consumption)

K216 **49 BLEECKER ST** **NY AST** **U001832561**
SSW **49 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.102 mi.
539 ft. **Site 5 of 26 in cluster K**

Relative:
Higher

Actual:
42 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-108278
Program Type: PBS
UTM X: 584958.11078
UTM Y: 4508825.20364
Expiration Date: 06/07/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 3189

49 BLEECKER ST (Continued) **U001832561**

Affiliation Type:	Facility Owner
Company Name:	ROGERS INVESTMENTS NV LP
Contact Type:	GENERAL PARTNER
Contact Name:	FRED ROGERS
Address1:	251 ADAMS LN
Address2:	Not reported
City:	HEWLETT
State:	NY
Zip Code:	11557
Country Code:	001
Phone:	(917) 992-4924
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Site Id:	3189
Affiliation Type:	Mail Contact
Company Name:	C/O LINVINGSTION MANAGEMENT
Contact Type:	Not reported
Contact Name:	PATRICK SULLIVAN
Address1:	225 WEST 35TH ST, 15TH FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(646) 214-0366
EMail:	PATRICK@LINVINGSTONCRE.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Site Id:	3189
Affiliation Type:	Facility Operator
Company Name:	49 BLEECKER ST
Contact Type:	Not reported
Contact Name:	MANI MONILAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-9579
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Site Id:	3189
Affiliation Type:	Emergency Contact
Company Name:	ROGERS INVESTMENTS NV LP
Contact Type:	Not reported
Contact Name:	LIVINGSTON MANAGEMENT
Address1:	Not reported
Address2:	Not reported

49 BLEECKER ST (Continued) **U001832561**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 214-0333
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Tank Info:

Tank Number:	001
Tank Id:	4793
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/15/1960
Capacity Gallons:	5000
Tightness Test Method:	21
Date Test:	04/15/2002
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	08/18/2017
Material Name:	#4 fuel oil (on-site consumption)

L217 **PARKING GARAGE** **NY Spills** **S117268314**
NNW **714 BROADWAY** **N/A**
< 1/8 **MANHATTAN, NY**
0.102 mi.
541 ft. **Site 7 of 16 in cluster L**

Relative: **Lower**
Actual: **40 ft.**

SPILLS:

Facility ID:	1403725
Facility Type:	ER
Spill Number:	1403725
DER Facility ID:	452105
Site ID:	497092

PARKING GARAGE (Continued) **S117268314**

DEC Region:	2
Closed Date:	2014-07-08
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	3101
Spill Date:	2014-07-08
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2014-07-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-07-08
Spill Record Last Update:	2014-07-08
Spiller Name:	Not reported
Spiller Company:	ACTION CAR RENTAL CLIENT
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ANDREW KELLY
DEC Memo:	"DEC Piper spoke with DEP. Rental facility will be taking drum. Spill closed."
Remarks:	"SAND WAS PUT DOWN FOR AN ABSORBENT AND FDNY PUMPED IT INTO A 25 GALLON TANK. SPILL WAS ACCIDENTAL WHEN CLIENT WAS TRYING TO RETURN RENTAL CAR. NO IMPACT TO THE SEWER SYSTEM"

All Materials:

Site ID:	497092
Operable Unit ID:	1246564
Operable Unit:	01
Material ID:	2247736
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

J218 **60 EAST 4TH STREET** **NY AST** **A100178012**
ESE **60 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.103 mi.
544 ft. **Site 3 of 20 in cluster J**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605711

60 EAST 4TH STREET (Continued) **A100178012**

Program Type:	PBS
UTM X:	585220.99580
UTM Y:	4508940.01711
Expiration Date:	04/18/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27578
Affiliation Type:	Mail Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	VORSELL@CSMHA.ORG
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-03-22

Site Id:	27578
Affiliation Type:	Emergency Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 246-3870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27578
Affiliation Type:	Facility Operator
Company Name:	60 EAST 4TH STREET
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

60 EAST 4TH STREET (Continued) **A100178012**

Site Id:	27578
Affiliation Type:	Facility Owner
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION II HDFC
Contact Type:	EXEC. DIR.
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET, 3RD FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-20

Tank Info:

Tank Number:	004
Tank Id:	60266
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/08/1993
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

M219 **CON EDISON** **RCRA NonGen / NLR** **1010327716**
SW **65 BLEEKER STREET** **NY MANIFEST** **NYP004148326**
< 1/8 **NEW YORK, NY 10012**
0.105 mi.
554 ft. **Site 2 of 26 in cluster M**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/11/2007
Facility name:	CON EDISON
Facility address:	65 BLEEKER STREET NEW YORK, NY 10012
EPA ID:	NYP004148326
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DANIEL PONTECORVO
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/10/2007
Site name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	04/09/2007
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004148326
Facility Status:	Not reported
Location Address 1:	bleecker st & crosby st
Code:	BP
Location Address 2:	Not reported

CON EDISON (Continued) **1010327716**

Total Tanks:	Not reported
Location City:	manhattan
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004148326
Mailing Name:	consolidated edison
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2007
Trans1 Recv Date:	02/26/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/27/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148326
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001450368FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds

CON EDISON (Continued) **1010327716**

Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

K220 **CON EDISON GAS DRIP: GAS MAIN** **RCRA NonGen / NLR** **1016143959**
South **BLECKER ST & ELIZABETH ST** **NY MANIFEST** **NYP004267464**
< 1/8 **NEW YORK, NY 10012**
0.105 mi.
554 ft. **Site 6 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON GAS DRIP: GAS MAIN
Facility address:	BLECKER ST & ELIZABETH ST NEW YORK, NY 10012
EPA ID:	NYP004267464
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	LOUIS CLARK
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-539-6192
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON GAS DRIP: GAS MAIN (Continued) **1016143959**

Historical Generators:
Date form received by agency: 09/10/2012
Site name: CON EDISON GAS DRIP: GAS MAIN
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004267464
Facility Status: Not reported
Location Address 1: ELIZABETH ST & BLEEKERS ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004267464
Mailing Name: CON EDISON
Mailing Contact: CON EDISON-MANHOLE 58863
Mailing Address 1: 4 IRVING PL 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/10/2012
Trans1 Recv Date: 09/10/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/10/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004267464
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 001674552GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON GAS DRIP: GAS MAIN (Continued) **1016143959**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

K221 **CON EDISON GAS DRIP: GAS~MAIN** **NJ MANIFEST** **S117986180**
South **BLECKER ST & ELIZABETH ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.105 mi.
554 ft. **Site 7 of 26 in cluster K**

Relative: **Higher**
Actual: **43 ft.**

NJ MANIFEST:

EPA Id:	NYP004267464
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LOUIS CLARK
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001674552GBF
EPA ID:	NYP004267464
Date Shipped:	9/10/2012
TSDF EPA ID:	NJD991291105

CON EDISON GAS DRIP: GAS~MAIN (Continued) **S117986180**

Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	Not reported
Quantity:	120.00 gallons

K222 **CON EDISON SERVICE BOX: 33384** **RCRA NonGen / NLR** **1016974081**
South **BLEECKER ST & ELIZABETH ST** **NY MANIFEST** **NYP004478913**
< 1/8 **NEW YORK, NY 10002**
0.105 mi.
554 ft. **Site 8 of 26 in cluster K**

Relative: **Higher**

Actual: **43 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/26/2014
Facility name:	CON EDISON SERVICE BOX: 33384
Facility address:	BLEECKER ST & ELIZABETH ST SW COR NEW YORK, NY 10002

CON EDISON SERVICE BOX: 33384 (Continued) **1016974081**

EPA ID: NYP004478913
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/26/2014
Site name: CON EDISON SERVICE BOX: 33384
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004478913
Facility Status: Not reported
Location Address 1: S/W/C BLEECKER & LAFAYETTE ST
Code: BP
Location Address 2: SB33384
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10002
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004478913
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK

CON EDISON SERVICE BOX: 33384 (Continued) **1016974081**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478913
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002359573GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON SERVICE BOX: 33384 (Continued) **1016974081**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O223 **419 LAFAYETTE STREET** **NY AST** **U003397265**
NNE **419 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.106 mi.
561 ft. **Site 1 of 23 in cluster O**

Relative:
Lower

Actual:
41 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603577
Program Type:	PBS
UTM X:	585149.81045
UTM Y:	4509181.22095
Expiration Date:	07/28/2018
Site Type:	Other

Affiliation Records:

Site Id:	25491
Affiliation Type:	Mail Contact
Company Name:	MICHAEL BAUM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	419 LAFAYETTE STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 989-3939
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25491
Affiliation Type:	Facility Operator
Company Name:	419 LAFAYETTE STREET
Contact Type:	Not reported
Contact Name:	MICHAEL BAUM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 301-5669
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2008-11-17

Site Id:	25491
Affiliation Type:	Emergency Contact

419 LAFAYETTE STREET (Continued) **U003397265**

Company Name:	MICHAEL BAUM
Contact Type:	Not reported
Contact Name:	MICHAEL BAUM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 301-5669
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2008-11-17

Site Id:	25491
Affiliation Type:	Facility Owner
Company Name:	MICHAEL BAUM
Contact Type:	OWNER
Contact Name:	MICHAEL BLUM
Address1:	419 LAFAYETTE STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(917) 301-5669
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2008-11-17

Tank Info:

Tank Number:	001
Tank Id:	54857
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

419 LAFAYETTE STREET (Continued) **U003397265**

Pipe Model:	Not reported
Install Date:	09/01/1980
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

J224 **COOPER SQ MHA** **NY AST** **A100320218**
ESE **59 -61 EAST 4TH ST. 3RD FLOOR** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.107 mi.
563 ft. **Site 4 of 20 in cluster J**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-470511
Program Type:	PBS
UTM X:	585221.17628
UTM Y:	4508865.52532
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	20606
Affiliation Type:	Facility Operator
Company Name:	COOPER SQ MHA
Contact Type:	Not reported
Contact Name:	COOPER SQ MHA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2008-04-29

Site Id:	20606
Affiliation Type:	Emergency Contact
Company Name:	COPPER SQ MHA
Contact Type:	Not reported
Contact Name:	FAUSTO ESPINAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

COOPER SQ MHA (Continued) **A100320218**

Phone:	(212) 396-8927
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2008-04-29

Site Id:	20606
Affiliation Type:	Facility Owner
Company Name:	COPPER SQ MHA
Contact Type:	MAINTENCE SUPT
Contact Name:	JOHN J. ISAZA
Address1:	59-61 EAST 4TH ST 3RD FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2008-04-29

Site Id:	20606
Affiliation Type:	Mail Contact
Company Name:	COOPER SQ MUTUAL HOUSING ASSOC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	59-61 EAST 4TH ST 3RD FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2008-04-29

Tank Info:

Tank Number:	001
Tank Id:	37317
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None

COOPER SQ MHA (Continued) **A100320218**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1997
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	kakyer
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

J225 **216 EAST 5TH ST** **NY AST** **U003383747**
East **216 EAST 5TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.107 mi.
566 ft. **Site 5 of 20 in cluster J**

Relative: **Lower**

Actual: **39 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-061905
Program Type:	PBS
UTM X:	585251.06774
UTM Y:	4509005.86419
Expiration Date:	02/10/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	1129
Affiliation Type:	Mail Contact
Company Name:	TRI-STAR EQUITIES
Contact Type:	Not reported
Contact Name:	DANIEL ATTARD
Address1:	155 EAST 26TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10010
Country Code:	001
Phone:	(646) 556-5447
EMail:	DATTARD@TRISTAREQ.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-03-13

Site Id:	1129
Affiliation Type:	Facility Operator
Company Name:	216 EAST 5TH ST
Contact Type:	Not reported
Contact Name:	ELIZABTH MAZEWSKI
Address1:	Not reported

216 EAST 5TH ST (Continued) **U003383747**

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 621-0609
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-11-04

Site Id: 1129
Affiliation Type: Emergency Contact
Company Name: 216 E 5TH STREET MANAGEMENT LLC
Contact Type: Not reported
Contact Name: ROD FELDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 974-9663
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-03-13

Site Id: 1129
Affiliation Type: Facility Owner
Company Name: 216 E 5TH STREET MANAGEMENT LLC
Contact Type: PROPERTY MANAGER
Contact Name: DANIEL ATTARD
Address1: 155 EAST 26TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 751-4800
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-03-13

Tank Info:

Tank Number: 001
Tank Id: 2165
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

216 EAST 5TH ST (Continued) **U003383747**

K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/26/2001
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	03/13/2018
Material Name:	#2 fuel oil (on-site consumption)

M226 **JOHNS DRY CLEANERS CORP** **EDR Hist Cleaner** **1020014678**
WSW **652 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.107 mi.
566 ft. **Site 3 of 26 in cluster M**

Relative: EDR Hist Cleaner
Lower

Actual: **39 ft.**

Year:	Name:	Type:
2006	JOHNS DRY CLEANERS CORP	Drycleaning Plants, Except Rugs, NEC
2007	JOHNS DRY CLEANERS CORP	Drycleaning Plants, Except Rugs, NEC
2008	JOHNS DRY CLEANERS CORP	Drycleaning Plants, Except Rugs, NEC
2009	JOHNS DRY CLEANERS CORP	Drycleaning Plants, Except Rugs, NEC
2010	JOHNS DRY CLEANERS CORP	Drycleaning Plants, Except Rugs, NEC

J227 **67 EAST 4TH STREET** **NY AST** **A100178013**
ESE **67 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.107 mi.
566 ft. **Site 6 of 20 in cluster J**

Relative: AST:
Lower

Actual: **39 ft.**

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605712
Program Type:	PBS
UTM X:	585242.96016
UTM Y:	4508918.05004
Expiration Date:	04/18/2021
Site Type:	Apartment Building/Office Building

67 EAST 4TH STREET (Continued) **A100178013**

Affiliation Records:

Site Id:	27579
Affiliation Type:	Mail Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	VORSELL@CSMHA.ORG
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-03-22

Site Id:	27579
Affiliation Type:	Emergency Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 246-3870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27579
Affiliation Type:	Facility Operator
Company Name:	67 EAST 4TH STREET
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27579
Affiliation Type:	Facility Owner
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION II HDFC
Contact Type:	EXEC. DIR.
Contact Name:	VALERIO ORSELLI

67 EAST 4TH STREET (Continued) **A100178013**

Address1:	59-61 EAST 4TH STREET, 3RD FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-20

Tank Info:

Tank Number:	005
Tank Id:	60267
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H99 - Tank Leak Detection - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/14/1996
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

L228 **WASHINGTON PLACE APT CORP** **NY AST** **A100296684**
NNW **716 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.108 mi.
568 ft. **Site 8 of 16 in cluster L**

Relative: **Lower**
Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608819
Program Type:	PBS

WASHINGTON PLACE APT CORP (Continued) **A100296684**

UTM X:	584994.53959
UTM Y:	4509181.75789
Expiration Date:	04/10/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30669
Affiliation Type:	Facility Owner
Company Name:	WASHINGTON PLACE APT CORP
Contact Type:	VICE PRESIDENT
Contact Name:	GENE ZARCONE
Address1:	716 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 254-2556
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-31

Site Id:	30669
Affiliation Type:	Mail Contact
Company Name:	MACK EDGE MGMT
Contact Type:	Not reported
Contact Name:	JAY PERILALL
Address1:	12 DESBROSSES ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(917) 445-5376
EMail:	MAIL@MACKEDGE.COM
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-04-26

Site Id:	30669
Affiliation Type:	Facility Operator
Company Name:	WASHINGTON PLACE APT CORP
Contact Type:	Not reported
Contact Name:	GENE ZARGONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 982-0055
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30669

WASHINGTON PLACE APT CORP (Continued) **A100296684**

Affiliation Type:	Emergency Contact
Company Name:	WASHINGTON PLACE APT CORP
Contact Type:	Not reported
Contact Name:	JAY PERILALL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 587-1273
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-04-26

Tank Info:

Tank Number:	001
Tank Id:	65681
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/10/1979
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

L229 **MEYER COMPLEX** **NY AST** **A100295039**
NNW **2-6 WASHINGTON PLACE** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.108 mi.
569 ft. **Site 9 of 16 in cluster L**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607711
Program Type:	PBS
UTM X:	584798.23534
UTM Y:	4509265.10767
Expiration Date:	04/29/2022
Site Type:	School

Affiliation Records:

Site Id:	29563
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	CELESTE RUFER
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-06

Site Id:	29563
Affiliation Type:	Facility Operator
Company Name:	MEYER COMPLEX
Contact Type:	Not reported
Contact Name:	MICHAEL KOSHKIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 998-1001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-06-23

Site Id:	29563
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	NYU PUBLIC SAFTEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported

MEYER COMPLEX (Continued) **A100295039**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 998-2222
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-04-23

Site Id:	29563
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	ASSISTANT DIRECTOR
Contact Name:	STEPHANIE KUNG
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-11-29

Tank Info:

Tank Number:	001
Tank Id:	63406
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
G12 - Tank Secondary Containment - Double-Walled (AG only)
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2002
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

MEYER COMPLEX (Continued) **A100295039**

Register:	True
Modified By:	DMPOKRZY
Last Modified:	06/06/2017
Material Name:	diesel
Tank Number:	002
Tank Id:	229028
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2002
Capacity Gallons:	200
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	06/06/2017
Material Name:	diesel

H230 **207 EAST 5TH ST** **NY AST** **U004045174**
ENE **207 EAST 5TH ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.109 mi.
574 ft. **Site 25 of 26 in cluster H**

Relative: **Lower**
Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-155446
Program Type:	PBS
UTM X:	585236.47111
UTM Y:	4509026.56795
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	5035

207 EAST 5TH ST (Continued) **U004045174**

Affiliation Type:	Facility Owner
Company Name:	ARAMCO INTERNATIONAL TRADING C
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	26 COURT ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11242
Country Code:	001
Phone:	(718) 858-8426
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5035
Affiliation Type:	Mail Contact
Company Name:	ARAMCO INTERNATIONAL TRADING C
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	26 COURT ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11242
Country Code:	001
Phone:	(718) 858-8426
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5035
Affiliation Type:	Facility Operator
Company Name:	207 EAST 5TH ST
Contact Type:	Not reported
Contact Name:	MARK FLETCHER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 674-1719
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5035
Affiliation Type:	Emergency Contact
Company Name:	ARAMCO INTERNATIONAL TRADING C
Contact Type:	Not reported
Contact Name:	BAYSIDE FUEL OIL CORP
Address1:	Not reported
Address2:	Not reported

207 EAST 5TH ST (Continued) **U004045174**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 946-4000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	8407
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/1993
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

H231 **COOPER 25 ASSOCIATES, LLC** **NY UST** **U004067721**
ENE **25 COOPER SQUARE** **NY AST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.110 mi.
583 ft. **Site 26 of 26 in cluster H**

Relative: **Lower**
Actual: **40 ft.**

UST:

Id/Status:	2-610425 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590636.59524
UTM Y:	4524597.00754
Site Type:	Other

COOPER 25 ASSOCIATES, LLC (Continued) **U004067721**

Affiliation Records:

Site Id:	374765
Affiliation Type:	Facility Owner
Company Name:	COOPER 25 ASSOCIATES, LLC
Contact Type:	PRINCITAL
Contact Name:	MATTHEW MOSS
Address1:	250 LAFAYETTE STREET, SUITE 3A
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 253-9601
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-12-12

Site Id:	374765
Affiliation Type:	Mail Contact
Company Name:	THE PECK MOSS HOTEL GROUP
Contact Type:	Not reported
Contact Name:	MATTHEW MOSS
Address1:	250 LAFAYETTE STREET, SUITE 3A
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 253-9601
EMail:	MATTHEW@PECKMOSS.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-12-12

Site Id:	374765
Affiliation Type:	Facility Operator
Company Name:	COOPER 25 ASSOCIATES, LLC
Contact Type:	Not reported
Contact Name:	MATTHEW MOSS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 253-9601
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-12-12

Site Id:	374765
Affiliation Type:	Emergency Contact
Company Name:	COOPER 25 ASSOCIATES, LLC
Contact Type:	Not reported
Contact Name:	MATTHEW MOSS

COOPER 25 ASSOCIATES, LLC (Continued) **U004067721**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 692-5574
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-12-12

Tank Info:

Tank Number:	001
Tank ID:	214932
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Tank Number:	002
Tank ID:	214934
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Tank Number:	003

COOPER 25 ASSOCIATES, LLC (Continued) **U004067721**

Tank ID:	214935
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Tank Number:	004
Tank ID:	214937
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Tank Number:	005
Tank ID:	214938
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

COOPER 25 ASSOCIATES, LLC (Continued) **U004067721**

Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Tank Number:	006
Tank ID:	214940
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	550
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Tank Number:	007
Tank ID:	214941
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	275
Install Date:	08/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-116653
Program Type:	PBS
UTM X:	590677.07753
UTM Y:	4524613.60986
Expiration Date:	04/16/2020
Site Type:	Apartment Building/Office Building

COOPER 25 ASSOCIATES, LLC (Continued) **U004067721**

Affiliation Records:

Site Id:	3937
Affiliation Type:	Facility Operator
Company Name:	25 COOPER ST
Contact Type:	Not reported
Contact Name:	MANUEL RUIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 321-5928
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-02-11

Site Id:	3937
Affiliation Type:	Emergency Contact
Company Name:	25 COOPER LLC
Contact Type:	Not reported
Contact Name:	GARY GREENE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 681-5857
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-19

Site Id:	3937
Affiliation Type:	Facility Owner
Company Name:	25 COOPER LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	GARY GREENE
Address1:	2207 CONEY ISLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11223
Country Code:	001
Phone:	(917) 257-3672
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-19

Site Id:	3937
Affiliation Type:	Mail Contact
Company Name:	EDEL FAMILY MANAGEMENT
Contact Type:	Not reported
Contact Name:	DANIEL EDELSTEIN

COOPER 25 ASSOCIATES, LLC (Continued) **U004067721**

Address1:	469 FORT WASHINGTON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10033
Country Code:	001
Phone:	(212) 928-0888
EMail:	DANIEL@EFMNY.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-03-25

Tank Info:

Tank Number:	001
Tank Id:	4154
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/16/1968
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

J232 **218 EAST 5TH STREET** **NY AST** **U004079008**
East **218 EAST 5TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.111 mi.
588 ft. **Site 7 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610200
Program Type:	PBS
UTM X:	585263.32819
UTM Y:	4508972.05812
Expiration Date:	07/10/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	363745
Affiliation Type:	Facility Owner
Company Name:	218 E 5TH ST ASSOC. LLC
Contact Type:	AGENT
Contact Name:	EDWARD WEINSTEIN
Address1:	547 W. 27ST RM 508
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(917) 796-5467
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-10-03

Site Id:	363745
Affiliation Type:	Mail Contact
Company Name:	EDWARD WEINSTEIN
Contact Type:	Not reported
Contact Name:	EDWARD WEINSTEIN
Address1:	12 EAST 86TH ST SUITE 220
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10028
Country Code:	001
Phone:	(917) 553-2113
EMail:	EDWARD@LEADMEOUT.COM
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-19

Site Id:	363745
Affiliation Type:	Facility Operator
Company Name:	218 EAST 5TH STREET
Contact Type:	Not reported
Contact Name:	GEORGE BOYD
Address1:	Not reported
Address2:	Not reported
City:	Not reported

218 EAST 5TH STREET (Continued) **U004079008**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 796-5467
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-10-03

Site Id:	363745
Affiliation Type:	Emergency Contact
Company Name:	218 E 5TH ST ASSOC. LLC
Contact Type:	Not reported
Contact Name:	GEORGE BOYD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 573-5823
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-10-03

Tank Info:

Tank Number:	001
Tank Id:	211588
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
D02 - Pipe Type - Galvanized Steel
F05 - Pipe External Protection - Jacketed
G05 - Tank Secondary Containment - Synthetic Liner
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
K00 - Spill Prevention - None
I03 - Overfill - Automatic Shut-Off
B03 - Tank External Protection - Original Impressed Current
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
J03 - Dispenser - Gravity
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1996
Capacity Gallons:	1500
Tightness Test Method:	21
Date Test:	03/07/2006
Next Test Date:	Not reported
Date Tank Closed:	Not reported

218 EAST 5TH STREET (Continued) **U004079008**

Register: True
Modified By: MRBARROW
Last Modified: 10/03/2017
Material Name: #2 fuel oil (on-site consumption)

J233 **236 E 5TH ST** **NY AST** **U003389422**
East **236 E 5TH ST** **N/A**
< 1/8 **NY, NY 10003**
0.111 mi.
588 ft. **Site 8 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-296481
Program Type: PBS
UTM X: 585319.92127
UTM Y: 4508941.18208
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 13654
Affiliation Type: Facility Owner
Company Name: RENAISSANCE OF 236 E. 5TH ST. LLC
Contact Type: DIRECTOR OF OPERATIONS
Contact Name: ERIC JOZA
Address1: 632 BROADWAY 7TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 477-3164
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-09-12

Site Id: 13654
Affiliation Type: Mail Contact
Company Name: RENAISSANCE PROPERTIES NY
Contact Type: Not reported
Contact Name: ERIC JOZA
Address1: 632 BROADWAY
Address2: 7TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 477-3164
EMail: EJOZA@RPNY.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-09-12

Site Id: 13654

236 E 5TH ST (Continued) **U003389422**

Affiliation Type:	Facility Operator
Company Name:	236 E 5TH ST
Contact Type:	Not reported
Contact Name:	KENNETH FISHEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-3164
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2008-05-21

Site Id:	13654
Affiliation Type:	Emergency Contact
Company Name:	RENAISSANCE OF 236 E. 5TH ST. LLC
Contact Type:	Not reported
Contact Name:	ERIC JOZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 477-3164
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-09-12

Tank Info:

Tank Number:	001
Tank Id:	16635
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
J05 - Dispenser - On Site Heating System (Supply/Return)
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed

236 E 5TH ST (Continued) **U003389422**

Pipe Model:	Not reported
Install Date:	01/01/1932
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/08/2017
Register:	True
Modified By:	DAFRANCI
Last Modified:	09/12/2017
Material Name:	#2 fuel oil (on-site consumption)

J234 **WHALEDENT INTL** **RCRA NonGen / NLR** **1000279859**
East **236 5TH AVE** **FINDS** **NYD000708289**
< 1/8 **NEW YORK, NY 10001** **ECHO**
0.111 mi. **NY MANIFEST**
588 ft. **Site 9 of 20 in cluster J**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WHALEDENT INTL
Facility address:	236 5TH AVE NEW YORK, NY 10001
EPA ID:	NYD000708289
Mailing address:	5TH AVE NEW YORK, NY 10001
Contact:	Not reported
Contact address:	5TH AVE NEW YORK, NY 10001
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	IPCO CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	IPCO CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported

WHALEDENT INTL (Continued) **1000279859**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHALEDENT INTL
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: WHALEDENT INTL
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: WHALEDENT INTL
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Manifest

WHALEDENT INTL (Continued) **1000279859**

Date violation determined: 01/27/1987
Date achieved compliance: 01/27/1987
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 01/27/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 01/27/1987
Evaluation lead agency: State

FINDS:

Registry ID: 110004331081

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000279859
Registry ID: 110004331081
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004331081

NY MANIFEST:
Country: USA
EPA ID: NYD000708289
Facility Status: Not reported
Location Address 1: 236 FIFTH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD000708289
Mailing Name: WHALEDENT INTERNATIONAL
Mailing Contact: WHALEDENT INTERNATIONAL

WHALEDENT INTL (Continued) **1000279859**

Mailing Address 1:	236 FIFTH AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126968000

NY MANIFEST:

Document ID:	NJA1626513
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	07/02/1993
Trans1 Recv Date:	07/02/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/07/1993
Part A Recv Date:	07/16/1993
Part B Recv Date:	07/19/1993
Generator EPA ID:	NYD000708289
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F001 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00250
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
71 additional NY_MANIFEST: record(s) in the EDR Site Report.

N235 **CON EDISON SERVICE BOX 538** **RCRA NonGen / NLR** **1014917968**
SSE **8 E 2ND ST & BOWERY ST** **NJ MANIFEST** **NYP004215513**
< 1/8 **NEW YORK, NY 10003** **NY MANIFEST**
0.112 mi.
589 ft. **Site 4 of 8 in cluster N**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/13/2010
Facility name:	CON EDISON SERVICE BOX 538
Facility address:	8 E 2ND ST & BOWERY ST NEW YORK, NY 10003
EPA ID:	NYP004215513
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DANIELLE SIERRA
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9472
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/13/2010
Site name:	CON EDISON SERVICE BOX 538
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004215513
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DANIELLE SIERRA
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported

CON EDISON SERVICE BOX 538 (Continued) **1014917968**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007020880JJK
EPA ID:	NYP004215513
Date Shipped:	09/13/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/13/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	50 P

CON EDISON SERVICE BOX 538 (Continued) **1014917968**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004215513
Facility Status:	Not reported
Location Address 1:	F/O 8 EAST 2ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004215513
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/13/2010
Trans1 Recv Date:	09/13/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004215513
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007020880JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported

CON EDISON SERVICE BOX 538 (Continued) **1014917968**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J236 **69 EAST 4TH STREET** **NY AST** **A100178011**
ESE **69 EAST 4TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.112 mi.
590 ft. **Site 10 of 20 in cluster J**

Relative: **Lower**

Actual: **39 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605710
Program Type:	PBS
UTM X:	585280.23841
UTM Y:	4508922.38019
Expiration Date:	04/18/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27577
Affiliation Type:	Mail Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	VORSELL@CSMHA.ORG
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-03-22

Site Id:	27577

69 EAST 4TH STREET (Continued) **A100178011**

Affiliation Type:	Emergency Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 246-3870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27577
Affiliation Type:	Facility Operator
Company Name:	69 EAST 4TH STREET
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27577
Affiliation Type:	Facility Owner
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION II HDFC
Contact Type:	EXEC. DIR.
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET, 3RD FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-20

Tank Info:

Tank Number:	006
Tank Id:	60265
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

69 EAST 4TH STREET (Continued) **A100178011**

Equipment Records:

A99 - Tank Internal Protection - Other
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)
H99 - Tank Leak Detection - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/24/1996
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

K237 **CON EDISON MANHOLE: 59169** **RCRA NonGen / NLR** **1016969460**
SW **341 LAFAYETTE ST FRONT OF** **NY MANIFEST** **NYP004431268**
< 1/8 **NEW YORK, NY 10012**
0.112 mi.
592 ft. **Site 9 of 26 in cluster K**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/01/2014
Facility name:	CON EDISON MANHOLE: 59169
Facility address:	341 LAFAYETTE ST FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004431268
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON MANHOLE: 59169 (Continued) **1016969460**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/01/2014
Site name: CON EDISON MANHOLE: 59169
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004431268
Facility Status: Not reported
Location Address 1: 341 LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004431268
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/01/2014
Trans1 Recv Date: 02/01/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004431268

CON EDISON MANHOLE: 59169 (Continued) **1016969460**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328736GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J238 **LOT 18,TAXBLOCK 459** **NY E DESIGNATION** **S109527648**
ESE **64 EAST 4 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.112 mi.
593 ft. **Site 11 of 20 in cluster J**

Relative: **Lower**
Actual: **40 ft.**

E DESIGNATION:

Tax Lot(s):	18
Tax Block:	459
Borough Code:	Not reported
E-No:	E-216
Effective Date:	11/19/2008
Satisfaction Date:	Not reported
Ceqr Number:	07DCP078M
Ulurp Number:	080397ZMM
Zoning Map No:	12c
Description:	Air Quality - #2 Fuel Oil or Natural Gas Heat and Hot Water
Lot Remediation Date:	Not reported

K239 **CON EDISON SERVICE BOX: 37911** **RCRA NonGen / NLR** **1016974082**
SW **BLEECKER ST & LAFAYETTE ST** **NY MANIFEST** **NYP004478921**
< 1/8 **NEW YORK, NY 10002**
0.113 mi.
597 ft. **Site 10 of 26 in cluster K**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/26/2014
Facility name:	CON EDISON SERVICE BOX: 37911
Facility address:	BLEECKER ST & LAFAYETTE ST NW COR NEW YORK, NY 10002
EPA ID:	NYP004478921
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/26/2014
Site name:	CON EDISON SERVICE BOX: 37911
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004478921
Facility Status:	Not reported
Location Address 1:	N/W/C BLEECKER & LAFAYETTE ST
Code:	BP
Location Address 2:	SB37911
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CON EDISON SERVICE BOX: 37911 (Continued) **1016974082**

Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004478921
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004478921
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360870GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON SERVICE BOX: 37911 (Continued) **1016974082**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

K240 **MTA NYCT BLEECKER STREET STATION 6 LINE** **RCRA NonGen / NLR** **1001128033**
SW **BLEECKER & LAFAYETTE ST** **NJ MANIFEST** **NYR000037051**
< 1/8 **NEW YORK, NY 10012** **NY MANIFEST**
0.113 mi.
597 ft. **Site 11 of 26 in cluster K**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT BLEECKER STREET STATION 6 LINE
Facility address:	BLEECKER & LAFAYETTE ST NEW YORK, NY 10012
EPA ID:	NYR000037051
Mailing address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact:	WILLIAM JEHLE
Contact address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	646-252-3500
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 3RD FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 3RD FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MTA NYCT BLEECKER STREET STATION 6 LINE
Classification: Not a generator, verified

Date form received by agency: 03/30/2000
Site name: MTA NYCT BLEECKER STREET STATION 6 LINE
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

. Waste code: B002
. Waste name: B002

Date form received by agency: 07/08/1999
Site name: MTA NYCT BLEECKER STREET STATION 6 LINE
Classification: Not a generator, verified

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYR000037051
Mail Address: BROADWAY 3RD FLOOR
Mail City/State/Zip: NEW YORK, NY 10004
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: WILLIAM JEHLE
Comments: Not reported
SIC Code: Not reported
County: NY061

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000198583WAS
EPA ID:	NYR000037051
Date Shipped:	08/11/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/11/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/11/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	400 P

Manifest Number:	000199359WAS

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

EPA ID:	NYR000037051
Date Shipped:	07/07/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/07/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/07/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	400 P

Manifest Number:	000457642WAS
EPA ID:	NYR000037051
Date Shipped:	8/8/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	2,510.00 Pounds

Manifest Number:	000199642WAS
EPA ID:	NYR000037051
Date Shipped:	04/06/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/06/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/06/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	600 P

Manifest Number:	000457321WAS
EPA ID:	NYR000037051
Date Shipped:	4/9/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	150.00 Pounds

Manifest Number:	000195162WAS
EPA ID:	NYR000037051
Date Shipped:	10/08/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 2100 P

Manifest Number: 000201705WAS
EPA ID: NYR000037051
Date Shipped: 10/08/2010
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/08/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 10/08/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10004
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 400 P

Manifest Number: 000457870WAS
EPA ID: NYR000037051

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Date Shipped:	11/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	900.00 Pounds

Manifest Number:	000198408WAS
EPA ID:	NYR000037051
Date Shipped:	06/03/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/03/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/03/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

Manifest Number:	000422435WAS
EPA ID:	NYR000037051
Date Shipped:	8/22/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	300.00 Pounds

Manifest Number:	000423389WAS
EPA ID:	NYR000037051
Date Shipped:	5/11/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	300.00 Pounds

Manifest Number:	000457168WAS
EPA ID:	NYR000037051
Date Shipped:	1/6/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	800.00 Pounds

Manifest Number:	000199559WAS
EPA ID:	NYR000037051
Date Shipped:	01/19/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/19/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/19/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

NY MANIFEST:

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Country:	USA
EPA ID:	NYR000037051
Facility Status:	Not reported
Location Address 1:	BLEEKER ST & LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000037051
Mailing Name:	NYCTA -BLEEKER ST STA
Mailing Contact:	N/S
Mailing Address 1:	2 BROADWAY-3RD FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523500

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJR986628162
Trans2 State ID:	Not reported
Generator Ship Date:	11/13/2012
Trans1 Recv Date:	11/13/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/16/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000037051
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000457870WAS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported

MTA NYCT BLEECKER STREET STATION 6 LINE (Continued) **1001128033**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	900.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
14 additional NY_MANIFEST: record(s) in the EDR Site Report.

K241 **CONSOLIDATED EDISON** **NY MANIFEST** **S112140573**
SW **333 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10002**
0.114 mi.
603 ft. **Site 12 of 26 in cluster K**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004253449
Facility Status:	Not reported
Location Address 1:	333 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004253449
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012

CONSOLIDATED EDISON (Continued) **S112140573**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/24/2012
Trans1 Recv Date:	05/24/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/25/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004253449
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009202766JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

K242 **36 BLEECKER ST** **NY AST** **U004046967**
SSW **36 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.115 mi.
605 ft. **Site 13 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-604840
Program Type:	PBS
UTM X:	591040.21884
UTM Y:	4505300.10362
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	26709
Affiliation Type:	Facility Owner
Company Name:	36 BLEECKER OWNER LP
Contact Type:	ENVIRONMENTAL ENGINEER
Contact Name:	MATTHEW CARROLL
Address1:	505 PARK AVE, 17TH FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 686-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	26709
Affiliation Type:	Emergency Contact
Company Name:	36 BLEECKER OWNER LP
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-10-03

Site Id:	26709
Affiliation Type:	Facility Operator
Company Name:	36 BLEECKER ST
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported

36 BLEECKER ST (Continued) **U004046967**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	26709
Affiliation Type:	Mail Contact
Company Name:	36 BLEECKER OWNER LP
Contact Type:	Not reported
Contact Name:	ARMEN BOYAJIAN
Address1:	505 PARK AVENUE
Address2:	17TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 686-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Tank Info:

Tank Number:	GBS 001
Tank Id:	58992
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/05/2001

36 BLEECKER ST (Continued) **U004046967**

Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	used oil (heating, on-site consumption)

J243 **211 EAST 5TH STREET** **NY AST** **U004191937**
East **211 EAST 5TH STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.116 mi.
610 ft. **Site 12 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-374784
Program Type:	PBS
UTM X:	585244.03064
UTM Y:	4509022.88022
Expiration Date:	10/02/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	18867
Affiliation Type:	Facility Owner
Company Name:	MARKSUE REALTY CORP
Contact Type:	MANAGING AGENT
Contact Name:	RUSSELL COOPER
Address1:	801 2ND AVENUE, SUITE 404
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 518-2693
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-26

Site Id:	18867
Affiliation Type:	Facility Operator
Company Name:	211 EAST 5TH STREET
Contact Type:	Not reported
Contact Name:	EVIE JUNIOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 246-1180
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-26

Site Id:	18867

211 EAST 5TH STREET (Continued) **U004191937**

Affiliation Type:	Emergency Contact
Company Name:	MARKSUE REALTY CORP
Contact Type:	Not reported
Contact Name:	EVIE JUNIOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 246-1180
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-26

Site Id:	18867
Affiliation Type:	Mail Contact
Company Name:	RUSSELL COOPER
Contact Type:	Not reported
Contact Name:	NOVUM PROPERTIES, INC.
Address1:	801 2ND AVENUE
Address2:	SUITE 404
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 518-2693
EMail:	RUSSELL@NOVUMPROPERTIESINC.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-26

Tank Info:

Tank Number:	001
Tank Id:	21171
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

211 EAST 5TH STREET (Continued) **U004191937**

Pipe Model:	Not reported
Install Date:	01/01/1910
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/26/2017
Material Name:	#2 fuel oil (on-site consumption)

K244 **SHEEN CENTER** **NY UST** **U004199587**
South **18 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.116 mi.
613 ft. **Site 14 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

UST:

Id/Status:	2-612106 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585033.04040
UTM Y:	4508762.52984
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	488091
Affiliation Type:	Mail Contact
Company Name:	PAL ENVIRONMENTAL SERVICES , INC
Contact Type:	Not reported
Contact Name:	MICHAEL BALDWIN
Address1:	11-02 QUEENS PLAZA SOUTH
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-0900
EMail:	MBALDWIN@PALCORP.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-02-13

Site Id:	488091
Affiliation Type:	Facility Operator
Company Name:	SHEEN CENTER
Contact Type:	Not reported
Contact Name:	ROSEMARIE BRUNO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 794-3479

SHEEN CENTER (Continued) **U004199587**

EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-10-18

Site Id: 488091
Affiliation Type: Emergency Contact
Company Name: CHURCH OF OUR LADY OF LORETTO
Contact Type: Not reported
Contact Name: ROSEMARIE BRUNO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 794-3479
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-10-18

Site Id: 488091
Affiliation Type: Facility Owner
Company Name: CHURCH OF OUR LADY OF LORETTO
Contact Type: Not reported
Contact Name: Not reported
Address1: 1011 FIRST AVENUE
Address2: Not reported
City: NY
State: NY
Zip Code: 10022
Country Code: 001
Phone: (646) 794-3479
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-02-13

Tank Info:

Tank Number: 001
Tank ID: 249968
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 3500
Install Date: 02/12/1986
Date Tank Closed: 01/27/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

SHEEN CENTER (Continued) **U004199587**

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None

J245 **LOT 51,TAXBLOCK 460** **NY E DESIGNATION** **S109528047**
ESE **71 EAST 4 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.116 mi.
614 ft. **Site 13 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

E DESIGNATION:

Tax Lot(s):	51
Tax Block:	460
Borough Code:	Not reported
E-No:	E-216
Effective Date:	11/19/2008
Satisfaction Date:	Not reported
Ceqr Number:	07DCP078M
Ulurp Number:	080397ZMM
Zoning Map No:	12c
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas Heat and Hot Water
Lot Remediation Date:	Not reported

K246 **PLANNED PARENTHOOD OF NEW YORK CITY INC** **NY AST** **U004078646**
South **26 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.116 mi.
615 ft. **Site 15 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608739
Program Type:	PBS
UTM X:	584997.85571
UTM Y:	4508774.56944
Expiration Date:	12/16/2018
Site Type:	Other

Affiliation Records:

Site Id:	30590

PLANNED PARENTHOOD OF NEW YORK CITY INC (Continued) **U004078646**

Affiliation Type:	Mail Contact
Company Name:	PLANNED PARENTHOOD OF NYC INC.
Contact Type:	Not reported
Contact Name:	FEDERICO A. MORROBEL
Address1:	26 BLEECKER STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 274-7207
EMail:	FEDERICO.MORROBEL@PPNYC.ORG
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-12

Site Id:	30590
Affiliation Type:	Facility Operator
Company Name:	PLANNED PARENTHOOD OF NEW YORK CITY INC
Contact Type:	Not reported
Contact Name:	SIRAIDA COLON (SUPER)
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 274-7207
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-12

Site Id:	30590
Affiliation Type:	Emergency Contact
Company Name:	PLANNED PARENTHOOD OF NEW YORK CITY, INC.
Contact Type:	Not reported
Contact Name:	FEDERICO MORROBEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 274-7207
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-12

Site Id:	30590
Affiliation Type:	Facility Owner
Company Name:	PLANNED PARENTHOOD OF NEW YORK CITY, INC.
Contact Type:	CHIEF FINANCIAL AND ADMINISTRATIVE OFFICER
Contact Name:	JONATHAN SEGAL
Address1:	26 BLEEKER STREET
Address2:	Not reported

PLANNED PARENTHOOD OF NEW YORK CITY INC (Continued) **U004078646**

City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 274-7230
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-12

Tank Info:

Tank Number:	001
Tank Id:	65586
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1997
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	06/12/2017
Material Name:	#2 fuel oil (on-site consumption)

M247 **APARTMENT** **NY LTANKS** **S103824394**
WSW **648 BROADWAY** **N/A**
< 1/8 **MANHATTAN, NY**
0.116 mi.
615 ft. **Site 4 of 26 in cluster M**

Relative: **Lower**
Actual: **39 ft.**

LTANKS:

Facility ID:	9813389
Site ID:	234503
Closed Date:	1999-02-10
Spill Number:	9813389
Spill Date:	1999-02-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3

APARTMENT (Continued) **S103824394**

Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-02-02
CID:	297
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-02
Spill Record Last Update:	1999-02-10
Spiller Name:	CHARLES LAHEY
Spiller Company:	WEATHER FUEL
Spiller Address:	802 JAMAICA AV
Spiller County:	001
Spiller Contact:	CHARLES LAHEY
Spiller Phone:	(718) 647-1268
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	193170
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Sewer and sidewalk and street cleaned by Petroleum Tank Cleaners as reported by Anthony of PTC. - 2/2/99, 1142"
Remarks:	"THE APARTMENT MANAGER REQUESTED 2500 GALLONS OF FUEL BUT THE TANK ONLY HELD 2475 GALLONS AND THE OVERFILL ALARM DID NOT WORK - FIRE DEPT DID RESPOND AND PLACED ABSORBANTS ON THE SPILL - A CLEAN UP CREW WILL BE SENT TO THE SITE TO PICK UP THE ABSORBANTS "

All Materials:

Site ID:	234503
Operable Unit ID:	1073837
Operable Unit:	01
Material ID:	310109
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	25.00
Oxygenate:	Not reported

M248 **648 BROADWAY** **NY AST** **A100294083**
WSW **648 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10022**
0.116 mi.
615 ft. **Site 5 of 26 in cluster M**

Relative: **Lower**

Actual: **39 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608614

648 BROADWAY (Continued) **A100294083**

Program Type:	PBS
UTM X:	584817.28297
UTM Y:	4508899.39922
Expiration Date:	03/18/2023
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	30466
Affiliation Type:	Mail Contact
Company Name:	SIERRA REAL ESTATE
Contact Type:	Not reported
Contact Name:	JOHN AMBROSINI
Address1:	600 MADISON AVENUE
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 776-1283
EMail:	JAMBROSINI@SIERRANYC.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-31

Site Id:	30466
Affiliation Type:	Facility Operator
Company Name:	648 BROADWAY
Contact Type:	Not reported
Contact Name:	ARGENY GARCIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 200-3201
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-31

Site Id:	30466
Affiliation Type:	Emergency Contact
Company Name:	FRANMAR INFANTS WEAR INC.
Contact Type:	Not reported
Contact Name:	ARGENY GARCIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 200-3701
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-31

648 BROADWAY (Continued) **A100294083**

Site Id:	30466
Affiliation Type:	Facility Owner
Company Name:	FRANMAR INFANTS WEAR INC.
Contact Type:	EXECUTIVE VICE PRESIDENT
Contact Name:	JOHN AMBROSINI
Address1:	648 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 776-1283
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-31

Tank Info:

Tank Number:	001
Tank Id:	65385
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
J03 - Dispenser - Gravity

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/15/1978
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	01/31/2018
Material Name:	#2 fuel oil (on-site consumption)

J249 **CONSOLIDATED EDISON** **NY MANIFEST** **1009238769**
ESE **V44150-66 E 4TH ST** **N/A**
< 1/8 **NEW YORK, NY 10001**
0.117 mi.
616 ft. **Site 14 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004052742
Facility Status:	Not reported
Location Address 1:	V44150-66 E 4TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004052742
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0669915
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	GX3213
Trans2 State ID:	Not reported
Generator Ship Date:	04/05/2000
Trans1 Recv Date:	04/05/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004052742
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

CONSOLIDATED EDISON (Continued) **1009238769**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00747
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

K250 **36 BLEECKER ST** **NY UST** **U004199583**
SSW **36 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.118 mi.
622 ft. **Site 16 of 26 in cluster K**

Relative: **Higher**
Actual: **43 ft.**

UST:

Id/Status:	2-604840 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	591040.21884
UTM Y:	4505300.10362
Site Type:	Other

Affiliation Records:

Site Id:	26709
Affiliation Type:	Facility Owner
Company Name:	36 BLEECKER OWNER LP
Contact Type:	ENVIRONMENTAL ENGINEER
Contact Name:	MATTHEW CARROLL
Address1:	505 PARK AVE, 17TH FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 686-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	26709
Affiliation Type:	Emergency Contact
Company Name:	36 BLEECKER OWNER LP
Contact Type:	Not reported

36 BLEECKER ST (Continued) **U004199583**

Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-10-03

Site Id:	26709
Affiliation Type:	Facility Operator
Company Name:	36 BLEECKER ST
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Site Id:	26709
Affiliation Type:	Mail Contact
Company Name:	36 BLEECKER OWNER LP
Contact Type:	Not reported
Contact Name:	ARMEN BOYAJIAN
Address1:	505 PARK AVENUE
Address2:	17TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 686-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-11-20

Tank Info:

Tank Number:	UST001
Tank ID:	249834
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/24/1949
Date Tank Closed:	11/26/2013
Registered:	True

36 BLEECKER ST (Continued) **U004199583**

Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

Tank Number:	UST002
Tank ID:	249835
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	06/24/1949
Date Tank Closed:	12/26/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

L251 **NEW YORK UNIVERSITY - MEYER BUILDING** **RCRA-SQG** **1004757909**
NNW **2-4 WASHINGTON PL** **FINDS** **NYD986963205**
< 1/8 **NEW YORK, NY 10003** **ECHO**
0.118 mi. **NY MANIFEST**
624 ft. **Site 10 of 16 in cluster L**

Relative:
Lower

Actual:
39 ft.

RCRA-SQG:

Date form received by agency:	07/29/2013
Facility name:	NEW YORK UNIVERSITY - MEYER BUILDING
Facility address:	2-4 WASHINGTON PL NEW YORK, NY 10003
EPA ID:	NYD986963205
Mailing address:	ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR NEW YORK, NY 10003
Contact:	STEPHANIE M KUNG
Contact address:	ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-998-1450
Contact email:	STEPHANIE.KUNG@NYU.EDU
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1950
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	WASHINGTON SQUARE SOUTH NEW YORK, NY 10012
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1950
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

NEW YORK UNIVERSITY - MEYER BUILDING (Continued) **1004757909**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

NEW YORK UNIVERSITY - MEYER BUILDING (Continued) **1004757909**

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U056
. Waste name: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Historical Generators:
Date form received by agency: 12/01/2009
Site name: NYU - MEYER BUILDING
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

NEW YORK UNIVERSITY - MEYER BUILDING (Continued) **1004757909**

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Date form received by agency: 01/01/2007
Site name: NY UNIV MEYER HALL OF PHYSICS
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: NY UNIV MEYER HALL OF PHYSICS
Classification: Small Quantity Generator

Date form received by agency: 06/28/1991
Site name: NY UNIV MEYER HALL OF PHYSICS
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL

NEW YORK UNIVERSITY - MEYER BUILDING (Continued) **1004757909**

BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U359
. Waste name: ETHANOL, 2-ETHOXY- (OR) ETHYLENE GLYCOL MONOETHYL ETHER

. Waste code: X001
. Waste name: WASTE OILS

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

FINDS:

Registry ID: 110004472810

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004757909
Registry ID: 110004472810
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004472810

NY MANIFEST:
Country: USA
EPA ID: NYD986963205
Facility Status: Not reported
Location Address 1: 2 -4 WASHINGTON PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986963205
Mailing Name: NEW YORK UNIVERSITY - MEYER BLDG
Mailing Contact: STEPHANIE KUNG
Mailing Address 1: 740 BROADWAY - 6th FLOOR

NEW YORK UNIVERSITY - MEYER BUILDING (Continued) **1004757909**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129981439

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	MAC300016672
Trans2 State ID:	OHD980614374
Generator Ship Date:	08/15/2017
Trans1 Recv Date:	08/15/2017
Trans2 Recv Date:	08/17/2017
TSD Site Recv Date:	08/27/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986963205
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	010964483FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NEW YORK UNIVERSITY - MEYER BUILDING (Continued) **1004757909**

Click this hyperlink while viewing on your computer to access
195 additional NY_MANIFEST: record(s) in the EDR Site Report.

K252 **CON EDISON - MANHOLE M26583** **NY MANIFEST** **S120959266**
SSW **40 BLEECKER ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.119 mi.
627 ft. **Site 17 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP005008129
Facility Status:	Not reported
Location Address 1:	40 BLEECKER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005008129
Mailing Name:	CON EDISON - MANHOLE M26583
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

M253 **BLEECKER TOWER TENANTS CORP** **NY AST** **U004077488**
WSW **644 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.119 mi.
627 ft. **Site 6 of 26 in cluster M**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-315397
Program Type:	PBS
UTM X:	584845.51474
UTM Y:	4508892.07989
Expiration Date:	07/10/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14415
Affiliation Type:	Facility Owner

BLEECKER TOWER TENANTS CORP (Continued) **U004077488**

Company Name:	BLEECKER TOWER TENANTS CORP
Contact Type:	PRESIDENT
Contact Name:	JENNY ALMONTE
Address1:	644 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-07-21

Site Id:	14415
Affiliation Type:	Facility Operator
Company Name:	BLEECKER TOWER TENANTS CORP
Contact Type:	Not reported
Contact Name:	FRANK BURAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-3823
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	14415
Affiliation Type:	Emergency Contact
Company Name:	BLEECKER TOWER TENANTS CORP
Contact Type:	Not reported
Contact Name:	ANDREWS ORG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-07-21

Site Id:	14415
Affiliation Type:	Mail Contact
Company Name:	ANDREWS ORGANIZATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK

BLEECKER TOWER TENANTS CORP (Continued) **U004077488**

State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-13

Tank Info:

Tank Number:	001
Tank Id:	12863
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H04 - Tank Leak Detection - Groundwater Well
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/25/1969
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	07/21/2017
Material Name:	#2 fuel oil (on-site consumption)

M254 **COMMERCIAL** **NY Spills** **S121464200**
WSW **644 BROADWAY** **N/A**
< 1/8 **NY, NY**
0.119 mi.
627 ft. **Site 7 of 26 in cluster M**

Relative: SPILLS:
Lower

Facility ID:	1709872
Facility Type:	ER
Spill Number:	1709872
DER Facility ID:	519780
Site ID:	566338
DEC Region:	2

Actual:
40 ft.

COMMERCIAL (Continued) **S121464200**

Closed Date:	Not reported
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2018-01-29
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2018-01-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2018-01-29
Spill Record Last Update:	2018-02-06
Spiller Name:	Not reported
Spiller Company:	644 BROADWAY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JENNY
DEC Memo:	"01/29/18 - Lakhani During Approved Oil's delivery, it was realized that there was a hole in the fill line. Approved Oil Eric Sutphen claims that the oil is contained to the sub-basement where a majority of the oil was absorbed by garbage and debris that is piled on the sub-basement floor. Approved Oil called Easco Neil Tomasetti (347-682-0730, ntomasetti@easco.com) to assist with the cleanup. 5000 gallon 32 fuel oil AST on the property. PBS #2-315397 Site Owner: Bleecker Tower Tenants Corp 644 Broadway New York, NY 10003 Assigned to DEC Zhune as daytime runner. 1/29/18- Veronica visited the site. The site is a residential building with 8 floors and 13 apartments located at 644 Broadway in Manhattan. The tank is a 5000-gallons AST # 2 fuel oil. As per the super Mr. Brewster they had a delivery of 3000 gallons of fuel oil # 2 today at 4 am. A tenant who resides in the 5 th floor complained oil odors in the main hallway at 12:00 am. The super called Approved oil. They came and discovered a big hole in the fill line and approximately 100 gallons of oil spilled on the floor of the basement. Esco is cleaning the spill in the basement. They installed 2 scrubbers in the main hallway. They will install a ventilation system in the basement tomorrow morning. I checked the hallways of all floors and noticed no oil odors in any of the hallways. There is oil odor in the main hallway 1/30/18-Lin-Recieved call from Dave Wilder (Resident of impacted building. APT #5C). Phone number 917-364-1487. According to Mr. Wilder, he still smell odor in his apartment. There are currently 2 senior citizen who resides in his apartment. He mentioned that odor travels into his apartment when he have the windows open. He request immediate clean up of the spill. Relayed message to case manager. 1/31/18-Zhune visited the apartment of Mr. Wilder and noticed slight oil odors at the entrance of the apartment. The PID reading was 2.4 PPM at the entrance. I inspected the rest of the apartment and found no odors. I inspected the hallways of the building and the maximum PID reading was 4.6 ppm at 8th floor, 3.3 ppm at 7th floor, 3.3 ppm at 6th floor, 3.4 ppm at 5th

COMMERCIAL (Continued) **S121464200**

floor, 4.0 ppm at 4th floor, 3.0 ppm at 3rd floor, 2.9 ppm at second floor and 1.4 ppm at the first floor. There was no odors at the entrance of the building. "

Remarks: "spill to inside concrete floor/clean up crew en route"

All Materials:

Site ID:	566338
Operable Unit ID:	1314270
Operable Unit:	01
Material ID:	2321846
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

M255 **SPILL NUMBER 0209371** **NY Spills** **S106010002**
WSW **644 BROADWAY** **N/A**
< 1/8 **MANHATTAN, NY**
0.119 mi.
627 ft. **Site 8 of 26 in cluster M**

Relative: **Lower**

Actual: **40 ft.**

SPILLS:

Facility ID:	0209371
Facility Type:	ER
Spill Number:	0209371
DER Facility ID:	139892
Site ID:	165999
DEC Region:	2
Closed Date:	2002-12-12
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2002-12-12
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2002-12-12
CID:	211
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-12
Spill Record Last Update:	2002-12-12
Spiller Name:	Not reported
Spiller Company:	PETROLEUM SERVICES
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	PHIL SILVERGLATE

SPILL NUMBER 0209371 (Continued) **S106010002**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/12/02 Petroleum Services is the transporter. Phil Cell phone - 201-206-1185 Spoke to Phil from the site at 2:23. Oil delivered to the wrong address. No drains or soil impacted. No spill inside the basement. 2-3 gallons spilled on grating, underneath which has a concrete floor. It has been cleaned. They are currently pumping out the tank (6 oil delivered to a 2 oil tank.)"
Remarks: "driver hooked up to wrong fill line - tri state enroute for clean up"
Not reported

All Materials:
Site ID: 165999
Operable Unit ID: 860741
Operable Unit: 01
Material ID: 516346
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

K256 **CON EDISON** **NY MANIFEST** **S117738106**
SSW **42 BLEECKER ST** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.119 mi.
628 ft. **Site 18 of 26 in cluster K**

Relative: **Higher**
Actual: **43 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004704680
Facility Status: Not reported
Location Address 1: 42 BLEECKER ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004704680
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:

CON EDISON (Continued) **S117738106**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/10/2014
Trans1 Recv Date:	12/10/2014
Trans2 Recv Date:	12/10/2014
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004704680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610128GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M257 **652 BROADWAY** **NY AST** **U003389176**
WSW **652 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10022**
0.119 mi.
630 ft. **Site 9 of 26 in cluster M**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-294667
Program Type:	PBS
UTM X:	584860.48557
UTM Y:	4508919.78395
Expiration Date:	07/14/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	13493
Affiliation Type:	Facility Owner
Company Name:	652 BROADWAY CORP % CORNERSTONE MGMT SYSTEMS
Contact Type:	AGENT
Contact Name:	ALLEN ABBANI
Address1:	271 MADISON AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 661-1150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Site Id:	13493
Affiliation Type:	Mail Contact
Company Name:	652 BROADWAY OWNERS CORP
Contact Type:	Not reported
Contact Name:	GEORGE SOPASAKIS
Address1:	271 MADISON AVENUE
Address2:	SUITE 800
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 661-1150
EMail:	GSOPASAKIS@CORENERSTONE-NY.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Site Id:	13493
Affiliation Type:	Facility Operator
Company Name:	652 BROADWAY
Contact Type:	Not reported
Contact Name:	ALEX KOSTYUKOV
Address1:	Not reported
Address2:	Not reported
City:	Not reported

652 BROADWAY (Continued) **U003389176**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 532-8320
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Site Id:	13493
Affiliation Type:	Emergency Contact
Company Name:	652 BROADWAY CORP % CORNERSTONE MGMT SYSTEMS
Contact Type:	Not reported
Contact Name:	GEORGE SOPASAKIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 661-1150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-03

Tank Info:

Tank Number:	001
Tank Id:	15377
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

652 BROADWAY (Continued) **U003389176**

Register:	True
Modified By:	MFLEONAR
Last Modified:	07/03/2017
Material Name:	#2 fuel oil (on-site consumption)

P258 **GOUVERNEUR & CO** **EDR Hist Cleaner** **1018473945**
South **10 BLEECKER ST APT 4A** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.120 mi.
631 ft. **Site 1 of 12 in cluster P**

Relative: EDR Hist Cleaner
Higher

Actual: **43 ft.**

Year:	Name:	Type:
1992	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1993	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1994	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1995	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1996	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1997	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1998	GOUVERNEUR & CO	Laundry And Drycleaner Agents
1999	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2000	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2001	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2002	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2003	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2004	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2005	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2006	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2007	GOUVERNEUR & CO	Laundry And Drycleaner Agents
2008	GOUVERNEUR & CO	Laundry And Drycleaner Agents

J259 **66 68 E 4TH STREET ENTITY INC** **EDR Hist Auto** **1021207444**
ESE **66 E 4TH ST** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.120 mi.
631 ft. **Site 15 of 20 in cluster J**

Relative: EDR Hist Auto
Lower

Actual: **39 ft.**

Year:	Name:	Type:
2005	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2006	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2007	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2008	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2010	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2011	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2012	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2013	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC
2014	66 68 E 4TH STREET ENTITY INC	Gasoline Service Stations, NEC

K260 **CON EDISON** **RCRA NonGen / NLR** **1014398198**
SSW **48 BLEEKER ST** **NY MANIFEST** **NYP004205498**
< 1/8 **NEW YORK, NY 10029**
0.120 mi.
635 ft. **Site 19 of 26 in cluster K**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/14/2010
Facility name:	CON EDISON
Facility address:	48 BLEEKER ST NEW YORK, NY 10029
EPA ID:	NYP004205498
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	TIMOTHY REGAN
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	917-416-5436
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004205498
Facility Status:	Not reported
Location Address 1:	48 BLEEKER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004205498
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **1014398198**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/2010
Trans1 Recv Date:	04/14/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004205498
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001442195FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **1014398198**

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

J261 **215 E. 5TH ST** **NY Spills** **S102673052**
East **215 E. 5TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.120 mi.
636 ft. **Site 16 of 20 in cluster J**

Relative: **Lower**

Actual: **39 ft.**

SPILLS:

Facility ID:	9510011
Facility Type:	ER
Spill Number:	9510011
DER Facility ID:	117899
Site ID:	137877
DEC Region:	2
Closed Date:	1995-11-14
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	3101
Spill Date:	1995-11-11
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-11-11
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-11
Spill Record Last Update:	1998-01-27
Spiller Name:	UNKNOWN
Spiller Company:	ACROSS FROM
Spiller Address:	215 E 5TH ST
Spiller Company:	001
Contact Name:	UNKNOWN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE HANDLED BY DEP."
Remarks:	"LARGE APT BUILDING REMOVING LAYERS OF LEAD PAINT - PAINT CHIPS ARE GOING INTO SEWER - REMOVAL BEEN GOING ON FOR WEEK"

All Materials:

Site ID:	137877
Operable Unit ID:	1024335
Operable Unit:	01
Material ID:	360937
Material Code:	0055A
Material Name:	paint
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G

215 E. 5TH ST (Continued) **S102673052**

Recovered: .00
Oxygenate: Not reported

M262 **CON EDISON SERVICE BOX: 27235** **RCRA NonGen / NLR** **1016968001**
West **657 BROADWAY** **NY MANIFEST** **NYP004416020**
< 1/8 **NEW YORK, NY 10012**
0.121 mi.
638 ft. **Site 10 of 26 in cluster M**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:
Date form received by agency: 02/10/2014
Facility name: CON EDISON SERVICE BOX: 27235
Facility address: 657 BROADWAY
NEW YORK, NY 10012
EPA ID: NYP004416020
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/10/2014
Site name: CON EDISON SERVICE BOX: 27235
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004416020
Facility Status: Not reported
Location Address 1: 6567 BROADWAY

CON EDISON SERVICE BOX: 27235 (Continued) **1016968001**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004416020
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/2014
Trans1 Recv Date:	01/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004416020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328602GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 27235 (Continued) **1016968001**

Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M263 **CON EDISON SERVICE BOX: 27233** **RCRA NonGen / NLR** **1016972475**
West **657 BROADWAY** **NY MANIFEST** **NYP004462529**
< 1/8 **NEW YORK, NY 10012**
0.121 mi.
638 ft. **Site 11 of 26 in cluster M**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	04/10/2014
Facility name:	CON EDISON SERVICE BOX: 27233
Facility address:	657 BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004462529
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
39 ft.

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON SERVICE BOX: 27233 (Continued) **1016972475**

Historical Generators:
Date form received by agency: 03/10/2014
Site name: CON EDISON SERVICE BOX: 27233
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004462529
Facility Status: Not reported
Location Address 1: F/O 657 BROADWAY
Code: BP
Location Address 2: SB27233
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004462529
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2014
Trans1 Recv Date: 03/10/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/11/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004462529
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002360797GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON SERVICE BOX: 27233 (Continued) **1016972475**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M264 **BROADWAY CLEANERS INC** **EDR Hist Cleaner** **1019943763**
West **657 BROADWAY** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.121 mi.
638 ft. **Site 12 of 26 in cluster M**

Relative: EDR Hist Cleaner
Lower

Actual: **39 ft.**

Year:	Name:	Type:
1991	BROADWAY CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

N265 **321 BOWERY COURT LLC** **NY Spills** **S106699864**
SSE **321 BOWERY STREET** **N/A**
< 1/8 **NEW YORK, NY**
0.121 mi.
638 ft. **Site 5 of 8 in cluster N**

Relative: SPILLS:
Lower

Actual: **41 ft.**

Facility ID:	0107529
Facility Type:	ER
Spill Number:	0107529
DER Facility ID:	178195
Site ID:	215077
DEC Region:	2
Closed Date:	2002-08-30
Spill Cause:	Other
Spill Class:	C3

321 BOWERY COURT LLC (Continued) **S106699864**

SWIS:	3101
Spill Date:	2001-10-23
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2001-10-23
CID:	204
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2001-10-23
Spill Record Last Update:	2002-08-30
Spiller Name:	GILL SCHULMAN
Spiller Company:	321 BOWERY COURT LLC
Spiller Address:	321 BOWERY STREET
Spiller Company:	001
Contact Name:	SHELLY SCIA SCIA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CROSSEN 10/23/01 ROBERT CROSSEN/FILE. TALKED WITH SHELLY SCIA, UST FOUND AT OLD STATION THEY DO NOT SEE ANY IMPACTS FROM JUST UNCOVERING. CROSSEN ADVISED TO CALL BACK IF ANY IMPACTS ARE FOUND, OTHER WISE REMOVE THE UST, SAMPLE, SAMPLE AND FILE REPORT. REMOVAL WILL TAKE PLACE THIS WEEK, REPORT DUE 11/30/01 8/30/02 - received tank closure report on 8/28/02 - reviewed report, and found to be satisfactory except for lack of info on historical tank closure - issued conditional NFA letter on 8/30/02, specifying that tanks needed to be registered/closed with PBS. No Further ACtion required, other than the PBS filing. - R. Austin"
Remarks:	"OLD GAS STATION - TANK FOUND AND MAY BE LEAKING"

All Materials:

Site ID:	215077
Operable Unit ID:	845675
Operable Unit:	01
Material ID:	532345
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O266 **CON EDISON SERVICE BOX 37929** **RCRA NonGen / NLR** **1015747013**
NNE **428 LAFAYETTE ST** **NY MANIFEST** **NYP004250148**
< 1/8 **NEW YORK, NY 10001**
0.123 mi.
648 ft. **Site 2 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/20/2012
Facility name:	CON EDISON SERVICE BOX 37929
Facility address:	428 LAFAYETTE ST NEW YORK, NY 10001
EPA ID:	NYP004250148
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/21/2012
Site name:	CON EDISON SERVICE BOX 37929
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004250148
Facility Status:	Not reported
Location Address 1:	F/O 428 LAFAYETTE ST.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001

CON EDISON SERVICE BOX 37929 (Continued) **1015747013**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004250148
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/21/2012
Trans1 Recv Date: 03/21/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004250148
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 009203842JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

CON EDISON SERVICE BOX 37929 (Continued) **1015747013**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O267 **428-430 LAFAYETTE STREET** **NY AST** **A100407909**
NNE **428-430 LAFAYETTE STREET** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.123 mi.
648 ft. **Site 3 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612347
Program Type:	PBS
UTM X:	585114.75110
UTM Y:	4509203.89000
Expiration Date:	11/09/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	503550
Affiliation Type:	Facility Owner
Company Name:	ROBINSON CALLEN, AS TRUSTEE
Contact Type:	MANAGING AGENT
Contact Name:	JOSHUA SALON
Address1:	5225 CALLINS AVE., APT. 1418
Address2:	Not reported
City:	MIAMI
State:	FL
Zip Code:	33140
Country Code:	001
Phone:	(212) 534-3131
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2015-01-08

Site Id:	503550
Affiliation Type:	Mail Contact
Company Name:	SALON REALTY
Contact Type:	Not reported
Contact Name:	JOSHUA SALON
Address1:	316 EAST 89TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10128
Country Code:	001
Phone:	(212) 534-3131

428-430 LAFAYETTE STREET (Continued) **A100407909**

EMail: JOSHUA@SALONREALTY.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2015-01-08

Site Id: 503550
Affiliation Type: Facility Operator
Company Name: 428-430 LAFAYETTE STREET
Contact Type: Not reported
Contact Name: FERNANDO GALLARDO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 634-6872
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2015-01-08

Site Id: 503550
Affiliation Type: Emergency Contact
Company Name: ROBINSON CALLEN, AS TRUSTEE
Contact Type: Not reported
Contact Name: JOSHUA SALAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 534-3131
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2015-01-08

Tank Info:

Tank Number: 001
Tank Id: 254115

Equipment Records:

E00 - Piping Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

428-430 LAFAYETTE STREET (Continued) **A100407909**

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/09/2009
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

O268 **CON EDISON SERVICE BOX 37929** **NJ MANIFEST** **S117985269**
NNE **428 LAFAYETTE ST** **N/A**
< 1/8 **NEW YORK, NY 10001**
0.123 mi.
648 ft. **Site 4 of 23 in cluster O**

Relative: **Lower**

Actual: **40 ft.**

NJ MANIFEST:

EPA Id:	NYP004250148
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009203842JJK
EPA ID:	NYP004250148
Date Shipped:	3/21/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON SERVICE BOX 37929 (Continued) **S117985269**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

Q269 **CON EDISON BENZENE AND PCB SPILL TO DIRT** **NY Spills** **S111064548**
ENE **COOPER SQ & EAST 6TH ST** **N/A**
< 1/8 **MANHATTAN, NY**
0.123 mi.
648 ft. **Site 1 of 18 in cluster Q**

Relative: **Lower**

Actual: **40 ft.**

SPILLS:

Facility ID:	1102669
Facility Type:	ER
Spill Number:	1102669
DER Facility ID:	404769
Site ID:	450189
DEC Region:	2
Closed Date:	2011-08-09
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2011-06-08
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2011-06-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

CON EDISON BENZENE AND PCB SPILL TO DIRT (Continued) **S111064548**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-06-08
Spill Record Last Update:	2011-08-09
Spiller Name:	ERT
Spiller Company:	CON EDISON
Spiller Address:	COOPER SQ & EAST 6TH ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"6/9/11-Vought-Primary off-hours spill responder. Spill assigned to DEC Feroze as part of minor Con Ed spill portfolio review and possible closure. Initial EMIS #226103 entered into Cross Reference Field, downloaded into E-docs and deleted from proxy. As per EMIS While removing an abandon gas main at the N/S Cooper SQ. 100' S/O E6 ST ConEd equipment leaked one ounce of liquid on dirt containing PCB and benzene according to past lab results. Spill was immediately cleaned and placed in a soil container. Contractor (Clean Ventures) will dispose of content of cleanup. 8/9/11 - Austin - 1 oz. gas main condensate spilled while abandoned line was being removed - Con Ed contained and cleaned up the spill - See eDocs for additional information - Spill closed - end"
Remarks:	"PCB spilled from transformer onto soil. Cleanup is complete."

All Materials:

Site ID:	450189
Operable Unit ID:	1200394
Operable Unit:	01
Material ID:	2196812
Material Code:	0854A
Material Name:	benzene
Case No.:	00071432
Material FA:	Hazardous Material
Quantity:	.01
Units:	G
Recovered:	.01
Oxygenate:	Not reported

J270 **LOT 23,TAXBLOCK 460** **NY E DESIGNATION** **S109527727**
East **224 EAST 5 STREET** **N/A**
< 1/8 **MANHATTAN, NY**
0.124 mi.
655 ft. **Site 17 of 20 in cluster J**

Relative: **Lower**

Actual: **39 ft.**

E DESIGNATION:

Tax Lot(s):	23
Tax Block:	460
Borough Code:	Not reported
E-No:	E-216
Effective Date:	11/19/2008
Satisfaction Date:	Not reported
Ceqr Number:	07DCP078M
Ulurp Number:	080397ZMM
Zoning Map No:	12c

LOT 23,TAXBLOCK 460 (Continued) **S109527727**

Description: Air Quality - #2 Fuel Oil or Natural Gas Heat and Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

M271 **65 BLEECKER STREET** **NY AST** **U003383701**
WSW **65 BLEECKER STREET** **N/A**
< 1/8 **NEW YORK, NY 10012**
0.124 mi.
657 ft. **Site 13 of 26 in cluster M**

Relative: **Lower**

Actual: **40 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-057614
Program Type: PBS
UTM X: 584872.48440
UTM Y: 4508875.06962
Expiration Date: 01/14/2022
Site Type: Other

Affiliation Records:
Site Id: 1027
Affiliation Type: Mail Contact
Company Name: KERWAY REALTY LLC
Contact Type: Not reported
Contact Name: LUCY ARCATI
Address1: 192 LEXINGTON AVE
Address2: 6TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 685-1514
EMail: LARCATI@SPI307.COM
Fax Number: Not reported
Modified By: HDDUPIGN
Date Last Modified: 2015-07-21

Site Id: 1027
Affiliation Type: Facility Operator
Company Name: 65 BLEECKER STREET
Contact Type: Not reported
Contact Name: ERNEST MCFADEAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 677-8784
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2015-07-21

65 BLEECKER STREET (Continued) **U003383701**

Site Id:	1027
Affiliation Type:	Emergency Contact
Company Name:	KERWAY REALTY LLC
Contact Type:	Not reported
Contact Name:	LUCY ARCATI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 685-1514
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-07-21

Site Id:	1027
Affiliation Type:	Facility Owner
Company Name:	KERWAY REALTY LLC
Contact Type:	AGENT
Contact Name:	LARRY ELEENBERG
Address1:	192 LEXINGTON AVE 6TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 685-1514
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-02-13

Tank Info:

Tank Number:	001
Tank Id:	2059
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron

65 BLEECKER STREET (Continued) **U003383701**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1900
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

M272 **CON EDISON SERVICE BOX: 27234** **RCRA NonGen / NLR** **1016967999**
West **653 BROADWAY** **NY MANIFEST** **NYP004416004**
< 1/8 **NEW YORK, NY 10012**
0.125 mi.
658 ft. **Site 14 of 26 in cluster M**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/10/2014
Facility name:	CON EDISON SERVICE BOX: 27234
Facility address:	653 BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004416004
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/10/2014
Site name:	CON EDISON SERVICE BOX: 27234

CON EDISON SERVICE BOX: 27234 (Continued) **1016967999**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004416004
Facility Status: Not reported
Location Address 1: 653 BROADWAY
Code: BP
Location Address 2: SB27234
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004416004
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 01/10/2014
Trans1 Recv Date: 01/10/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/10/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004416004
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002328603GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported

CON EDISON SERVICE BOX: 27234 (Continued) **1016967999**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Q273 **CON EDISON VAULT: 9995** **RCRA NonGen / NLR** **1017775042**
ENE **41 COOPER SQ** **FINDS** **NYP004528667**
< 1/8 **NEW YORK, NY 10009**
0.125 mi.
659 ft. **Site 2 of 18 in cluster Q**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/12/2014
Facility name:	CON EDISON VAULT: 9995
Facility address:	41 COOPER SQ NEW YORK, NY 10009
EPA ID:	NYP004528667
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

CON EDISON VAULT: 9995 (Continued) **1017775042**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/12/2014
Site name:	CON EDISON
Classification:	Large Quantity Generator

Date form received by agency:	05/12/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063804511

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q274 **CON EDISON** **NY MANIFEST** **S117061161**
ENE **41 COOPER SQ VAULT 9991** **N/A**
< 1/8 **NEW YORK, NY 10009**
0.125 mi.
659 ft. **Site 3 of 18 in cluster Q**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004534418
Facility Status:	Not reported
Location Address 1:	41 COOPER SQUARE
Code:	BP
Location Address 2:	VAULT 9991
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004534418
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117061161**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	05/16/2014
Trans1 Recv Date:	05/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004534418
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	007021636FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117061161**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Q275 **CON EDISON VAULT: 9999** **RCRA NonGen / NLR** **1017775055**
ENE **41 COOPER SQ** **FINDS** **NYP004528790**
< 1/8 **NEW YORK, NY 10009**
0.125 mi.
659 ft. **Site 4 of 18 in cluster Q**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/12/2014
Facility name:	CON EDISON VAULT: 9999
Facility address:	41 COOPER SQ NEW YORK, NY 10009
EPA ID:	NYP004528790
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/12/2014
Site name:	CON EDISON
Classification:	Large Quantity Generator

Date form received by agency:	05/12/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

CON EDISON VAULT: 9999 (Continued) **1017775055**

FINDS:

Registry ID: 110063804646

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q276 **CON EDISON VAULT: 9399** **RCRA NonGen / NLR** **1017775599**
ENE **41 COOPER SQ VAULT 9399** **NYP004534400**
< 1/8 **NEW YORK, NY 10009**
0.125 mi.
659 ft. **Site 5 of 18 in cluster Q**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/16/2014
Facility name:	CON EDISON VAULT: 9399
Facility address:	41 COOPER SQ VAULT 9399 NEW YORK, NY 10009
EPA ID:	NYP004534400
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON VAULT: 9399 (Continued) **1017775599**

Historical Generators:
Date form received by agency: 05/16/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 05/16/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

Q277 **CON EDISON** **NY MANIFEST** **S117061160**
ENE **41 COOPER SQ** **N/A**
< 1/8 **NEW YORK, NY 10009**
0.125 mi.
659 ft. **Site 6 of 18 in cluster Q**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004854358
Facility Status: Not reported
Location Address 1: 41 COOPER SQUARE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004854358
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 10/15/2015
Trans1 Recv Date: 10/15/2015
Trans2 Recv Date: 10/16/2015
TSD Site Recv Date: 10/16/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004854358
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S117061160**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612390GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP004854366
Facility Status:	Not reported
Location Address 1:	41 COOPER SQUARE
Code:	BP
Location Address 2:	V 9994
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004854366
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S117061160**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	10/15/2015
Trans1 Recv Date:	10/15/2015
Trans2 Recv Date:	10/16/2015
TSD Site Recv Date:	10/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004854366
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613270GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Q278
ENE
< 1/8
0.125 mi.
659 ft.

CON EDISION
41 COOPER SQ
NEW YORK, NY 10003

Site 7 of 18 in cluster Q

NY MANIFEST **S117066500**
N/A

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591558
Facility Status:	Not reported
Location Address 1:	41 COOPER SQ
Code:	BP
Location Address 2:	SB30964
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591558
Mailing Name:	CON EDISION
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591558
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423974GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISION (Continued) **S117066500**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYR000144261
Facility Status:	Not reported
Location Address 1:	41 COOPER SQ BLOCK 462 LOT 1
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000144261
Mailing Name:	COOPER UNION
Mailing Contact:	DEIDRE KENNEDY
Mailing Address 1:	41 COOPER SQ BLOCK 462 LOT 1
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123534161

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NYR000052373

CON EDISION (Continued) **S117066500**

Trans2 State ID:	NYD049178296
Generator Ship Date:	05/10/2017
Trans1 Recv Date:	05/10/2017
Trans2 Recv Date:	05/10/2017
TSD Site Recv Date:	05/31/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000144261
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX480000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	010516207FLE
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
192 additional NY_MANIFEST: record(s) in the EDR Site Report.

Q279 **COOPER UNION ENGINEERING BLDG** **RCRA-SQG** **1010328652**
ENE **41 COOPER SQ** **FINDS** **NYR000144261**
< 1/8 **NEW YORK, NY 10003**
0.125 mi.
659 ft. **Site 8 of 18 in cluster Q**

Relative: RCRA-SQG:
Lower
Date form received by agency: 01/06/2010
Actual: Facility name: COOPER UNION ENGINEERING BLDG
40 ft. Facility address: 41 COOPER SQ
BLOCK 462 LOT 1

COOPER UNION ENGINEERING BLDG (Continued) **1010328652**

NEW YORK, NY 10003
EPA ID: NYR000144261
Mailing address: COOPER SQ
NEW YORK, NY 10003
Contact: CLARK WIEMAN
Contact address: COOPER SQ
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-353-4100
Contact email: WIEMAN@COOPER.EDU
EPA Region: 02
Land type: Municipal
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: B001
. Waste name: B001

. Waste code: B002
. Waste name: B002

Historical Generators:
Date form received by agency: 02/05/2007
Site name: HEWITT BUILDING THE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

COOPER UNION ENGINEERING BLDG (Continued) **1010328652**

. Waste code: D009
. Waste name: MERCURY

. Waste code: B001
. Waste name: B001

. Waste code: B002
. Waste name: B002

Date form received by agency: 02/04/2007
Site name: HEWITT BUILDING THE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/04/2007
Site name: HEWITT BUILDING THE
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/27/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 12/02/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110042298518

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q280 **CON EDISON SERVICE BOX: 30964** **RCRA NonGen / NLR** **1016148951**
ENE **41-55 COOPER SQ FRONT OF** **NY MANIFEST** **NYP004276036**
< 1/8 **NEW YORK, NY 10003**
0.125 mi.
659 ft. **Site 9 of 18 in cluster Q**

Relative: RCRA NonGen / NLR:
Lower
Actual: Date form received by agency: 07/28/2017
40 ft. Facility name: CON EDISON SERVICE BOX: 30964
Facility address: 41-55 COOPER SQ FRONT OF
NEW YORK, NY 10003
EPA ID: NYP004276036
Mailing address: IRVING PL, RM 828

CON EDISON SERVICE BOX: 30964 (Continued) **1016148951**

NEW YORK, NY 10003
Contact: BENJAMIN BAMONTE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-894-9549
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/24/2012
Site name: CON EDISON SERVICE BOX: 30964
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004276036
Facility Status: Not reported
Location Address 1: FO 41-55 COOPER SQ
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004276036
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON SERVICE BOX: 30964 (Continued) **1016148951**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Q281 **CON EDISON SERVICE BOX: 30964** **NJ MANIFEST** **S117986895**
ENE **41-55 COOPER SQ FRONT OF** **N/A**
< 1/8 **NEW YORK, NY 10003**
0.125 mi.
659 ft. **Site 10 of 18 in cluster Q**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYP004276036
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456424JJK
EPA ID:	NYP004276036
Date Shipped:	10/24/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON SERVICE BOX: 30964 (Continued) **S117986895**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,500.00 Pounds

Q282 **CON EDISON VAULT: 9991** **RCRA NonGen / NLR** **1017775600**
ENE **41 COOPER SQ VAULT 9991** **FINDS** **NYP004534418**
< 1/8 **NEW YORK, NY 10009**
0.125 mi.
659 ft. **Site 11 of 18 in cluster Q**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/16/2014
Facility name:	CON EDISON VAULT: 9991
Facility address:	41 COOPER SQ VAULT 9991 NEW YORK, NY 10009
EPA ID:	NYP004534418
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON VAULT: 9991 (Continued) **1017775600**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/16/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 05/16/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063779647

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

R283 **CON EDISON** **NY MANIFEST** **S117066080**
WNW **250 MERCER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.125 mi.
661 ft. **Site 1 of 6 in cluster R**

Relative:
Lower

Actual:
38 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004586988
Facility Status: Not reported
Location Address 1: 250 MERCER ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004586988
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK

CON EDISON (Continued) **S117066080**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586988
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423813GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117066080**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J284 **75 EAST 4TH STREET** **NY AST** **A100175221**
ESE **75 EAST 4TH STREET** **N/A**
1/8-1/4 **NYC, NY 10003**
0.125 mi.
662 ft. **Site 18 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601046
Program Type:	PBS
UTM X:	585270.07620
UTM Y:	4508904.34002
Expiration Date:	06/07/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23016
Affiliation Type:	Facility Operator
Company Name:	75 EAST 4TH STREET
Contact Type:	Not reported
Contact Name:	JOHN ISAZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Site Id:	23016
Affiliation Type:	Emergency Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASS II
Contact Type:	Not reported
Contact Name:	JOHN ISAZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 671-0554
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Site Id:	23016
Affiliation Type:	Facility Owner

75 EAST 4TH STREET (Continued) **A100175221**

Company Name:	COOPER SQUARE MUTUAL HOUSING ASS II
Contact Type:	EXECUTIVE DIRECTOR
Contact Name:	DAVID POWELL
Address1:	59-61 E. 4TH STREET, 4TH FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Site Id:	23016
Affiliation Type:	Mail Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASS II
Contact Type:	EXECUTIVE DIRECTOR
Contact Name:	DAVID POWELL
Address1:	59-61 E. 4TH STREET, 4TH FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Tank Info:

Tank Number:	007
Tank Id:	44744
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	2
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	C

75 EAST 4TH STREET (Continued) **A100175221**

Install Date:	12/01/2000
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	02/21/2018
Material Name:	#2 fuel oil (on-site consumption)

S285 **THE NOHO STAR BUILDING** **NY AST** **U004048503**
SW **54 BLEECKER STREET (330 LAFAYETTE ST)** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.127 mi.
668 ft. **Site 1 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-342319
Program Type:	PBS
UTM X:	584891.00000
UTM Y:	4508887.00000
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	16606
Affiliation Type:	Facility Owner
Company Name:	THE NOHO STAR BUILDING CONDOMINUIM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	54 BLEECKER STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 925-4242
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16606
Affiliation Type:	Mail Contact
Company Name:	THE NOHO STAR BUILDING CONDOMINUIM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	54 BLEECKER STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 925-4242

THE NOHO STAR BUILDING (Continued) **U004048503**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16606
Affiliation Type:	Facility Operator
Company Name:	THE NOHO STAR BUILDING
Contact Type:	Not reported
Contact Name:	STUYVESANT FUEL SERVICE CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 925-4242
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16606
Affiliation Type:	Emergency Contact
Company Name:	THE NOHO STAR BUILDING CONDOMINUIM
Contact Type:	Not reported
Contact Name:	GEORGE SCHWARZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 925-4242
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	32043
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None

THE NOHO STAR BUILDING (Continued) **U004048503**

H00 - Tank Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/16/2004
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

O286 **V3178** **RCRA NonGen / NLR** **1007207506**
NNE **423 LAFAYETTE STREET** **NY MANIFEST** **NYP004047338**
1/8-1/4 **NEW YORK CITY, NY 10003**
0.127 mi.
670 ft. **Site 5 of 23 in cluster O**

Relative: **Lower**

Actual: **41 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/03/2001
Facility name:	V3178
Facility address:	423 LAFAYETTE STREET NEW YORK CITY, NY 10003
EPA ID:	NYP004047338
Mailing address:	CONSOLIDATED EDISON INC. 4 IRVING PLACE -- ROOM 300 NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC. NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

V3178 (Continued) **1007207506**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/02/2001
Site name: V3178
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V3178
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004047338
Facility Status: Not reported
Location Address 1: V3178-LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004047338
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0439362
Manifest Status: Not reported
seq: 01
Year: 1999
Trans1 State ID: GX3213
Trans2 State ID: Not reported
Generator Ship Date: 12/18/1999
Trans1 Recv Date: 12/18/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/18/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004047338
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636

V3178 (Continued) **1007207506**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01421
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O287 **CON EDISON** **RCRA NonGen / NLR** **1018280931**
NNE **430 LAFAYETTE ST** **FINDS** **NYP004758447**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.128 mi.
674 ft. **Site 6 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/26/2015
Facility name:	CON EDISON
Facility address:	430 LAFAYETTE ST NEW YORK, NY 10012
EPA ID:	NYP004758447
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON (Continued) **1018280931**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/26/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110067684483

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280931
Registry ID:	110067684483
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067684483

O288 **CON EDISON** **NY MANIFEST** **S118088293**
NNE **430 LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.128 mi.
674 ft. **Site 7 of 23 in cluster O**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004758447
Facility Status:	Not reported
Location Address 1:	430 LAFAYETTE ST
Code:	BP
Location Address 2:	MH 37929
Total Tanks:	Not reported
Location City:	MANHATTAN

CON EDISON (Continued) **S118088293**

Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004758447
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/26/2015
Trans1 Recv Date:	03/26/2015
Trans2 Recv Date:	03/31/2015
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004758447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611534GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S118088293**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

O289 **CON EDISON** **NJ MANIFEST** **S120669642**
NNE **430 LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.128 mi.
674 ft. **Site 8 of 23 in cluster O**

Relative: **Lower**

Actual: **40 ft.**

NJ MANIFEST:

EPA Id:	NYP004758447
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611534GBF
EPA ID:	NYP004758447
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120669642**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N290 **BREMEN HOUSE INC.** **NY AST** **A100194202**
South **312 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.128 mi.
676 ft. **Site 6 of 8 in cluster N**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-607171
Program Type:	PBS
UTM X:	585081.92892
UTM Y:	4508723.81275
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	29025
Affiliation Type:	Mail Contact
Company Name:	BILLUR AKIPEK
Contact Type:	Not reported
Contact Name:	EDUARDO SANTOS
Address1:	220 EAST 86 ST
Address2:	4TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10028
Country Code:	001
Phone:	(212) 860-0020
EMail:	BILLURAKIPEK@GMAIL.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-07-17

BREMEN HOUSE INC. (Continued) **A100194202**

Site Id:	29025
Affiliation Type:	Facility Operator
Company Name:	BREMEN HOUSE INC.
Contact Type:	Not reported
Contact Name:	NA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-07-17

Site Id:	29025
Affiliation Type:	Emergency Contact
Company Name:	BREMEN HOUSE INC.
Contact Type:	Not reported
Contact Name:	EDUARDO SANTOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 436-3885
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-07-17

Site Id:	29025
Affiliation Type:	Facility Owner
Company Name:	BREMEN HOUSE INC.
Contact Type:	VICE PRESIDENT
Contact Name:	BILLUR AKIPEK
Address1:	213 BOWERY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10028
Country Code:	001
Phone:	(212) 860-0020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-07-17

Tank Info:

Tank Number:	001
Tank Id:	62451
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

BREMEN HOUSE INC. (Continued) **A100194202**

Equipment Records:

I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/06/2008
Register:	True
Modified By:	MRBARROW
Last Modified:	07/17/2017
Material Name:	#2 fuel oil (on-site consumption)

L291 **NEW YORK UNIVERSITY - 726 BROADWAY** **NY MANIFEST** **S121133054**
North **726 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.128 mi.
676 ft. **Site 11 of 16 in cluster L**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYR000230839
Facility Status:	Not reported
Location Address 1:	726 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000230839
Mailing Name:	NEW YORK UNIVERSITY - 726 BROADWAY
Mailing Contact:	NEW YORK UNIVERSITY -
Mailing Address 1:	10 ASTOR PL 6TH FL ENVIRONMENTAL H&S
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129928276

NEW YORK UNIVERSITY - 726 BROADWAY (Continued) **S121133054**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	10/04/2017
Trans1 Recv Date:	10/04/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/09/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000230839
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	011101980FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	105
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

L292 **NEW YORK UNIVERSITY** **NY AST** **U003387268**
North **726-730 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.128 mi.
676 ft. **Site 12 of 16 in cluster L**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-244384
Program Type:	PBS
UTM X:	585006.26569
UTM Y:	4509272.96162
Expiration Date:	04/08/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9458
Affiliation Type:	Facility Operator
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	SUSAN BOAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 998-1001
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-10-26

Site Id:	9458
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-10-26

Site Id:	9458
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	MELISA PUGLISI
Address1:	Not reported
Address2:	Not reported
City:	Not reported

NEW YORK UNIVERSITY (Continued) **U003387268**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 484-0561
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2017-11-16

Site Id: 9458
Affiliation Type: Mail Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: STEPHANIE KUNG
Address1: 740 BROADWAY
Address2: 6TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 998-1450
EMail: STEPHANIE.KUNG@NYU.EDU
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2016-10-26

Tank Info:

Tank Number: 001
Tank Id: 11546
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 11/01/1992
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

NEW YORK UNIVERSITY (Continued) **U003387268**

Register: True
Modified By: MXLAY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 264585

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J07 - Dispenser - Loading Rack/Transfer Pump
C01 - Pipe Location - Aboveground
H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/2015
Capacity Gallons: 3500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MXLAY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 003
Tank Id: 264586

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
E12 - Piping Secondary Containment - Double-Walled (AG only)
G12 - Tank Secondary Containment - Double-Walled (AG only)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J07 - Dispenser - Loading Rack/Transfer Pump
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

NEW YORK UNIVERSITY (Continued) **U003387268**

Install Date:	06/01/2015
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

L293 **NEW YORK UNIVERSITY - 726 BROADWAY** **RCRA-CESQG** **1023679105**
North **726 BROADWAY** **NYR000230839**
1/8-1/4 **NEW YORK, NY 10003**
0.128 mi.
676 ft. **Site 13 of 16 in cluster L**

Relative: RCRA-CESQG:
Lower

Date form received by agency:	03/07/2017
Facility name:	NEW YORK UNIVERSITY - 726 BROADWAY
Facility address:	726 BROADWAY NEW YORK, NY 10003
EPA ID:	NYR000230839
Mailing address:	ASTOR PL - 6TH FLOOR EH&S NEW YORK, NY 10003
Contact:	ZACK KORENSTEIN
Contact address:	ASTOR PL - 6TH FLOOR EH&S NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-992-8276
Contact email:	ZACK.KORENSTEIN@NYU.EDU
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Actual:
40 ft.

Owner/Operator Summary:

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	WASHINGTON SQ SOUTH NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

NEW YORK UNIVERSITY - 726 BROADWAY (Continued) **1023679105**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: WASHINGTON SQ SOUTH
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008

NEW YORK UNIVERSITY - 726 BROADWAY (Continued) **1023679105**

. Waste name: LEAD

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Q294 **CON EDISON** **NY MANIFEST** **S118090270**
ENE **208 E 6TH ST & 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.128 mi.
677 ft. **Site 12 of 18 in cluster Q**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004778890
Facility Status: Not reported
Location Address 1: 208 E 6TH ST
Code: BP
Location Address 2: SB 1083
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004778890
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 05/05/2015
Trans1 Recv Date: 05/05/2015
Trans2 Recv Date: 05/08/2015
TSD Site Recv Date: 05/08/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004778890
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105

CON EDISON (Continued) **S118090270**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002612042GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

K295 **CON EDISON** **NY MANIFEST** **S117740333**
South **316 MOTT ST & HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.129 mi.
679 ft. **Site 20 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004734976
Facility Status:	Not reported
Location Address 1:	316 MOTT ST
Code:	BP
Location Address 2:	SB 41430
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004734976
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117740333**

Mailing Contact:	TOM TEELING
Mailing Address 1:	44-36 VERNON BLVD
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2015
Trans1 Recv Date:	02/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004734976
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014161571JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117740333**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

K296 **NEW MOTT APARTMENT CORP.** **NY AST** **U003395750**
South **316 MOTT STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.129 mi.
679 ft. **Site 21 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600778
Program Type:	PBS
UTM X:	584996.17888
UTM Y:	4508768.46517
Expiration Date:	07/07/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22755
Affiliation Type:	Facility Owner
Company Name:	NEW MOTT APT CORP
Contact Type:	MANAGING AGENT
Contact Name:	KIETH SCANDOVE
Address1:	316 MOTT STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

Site Id:	22755
Affiliation Type:	Mail Contact
Company Name:	ALL AREA REALTY SERVICES, INC.
Contact Type:	Not reported
Contact Name:	KIETH SCANDOVE
Address1:	99 TULIP AVE
Address2:	SUITE #302
City:	FLORAL PARK
State:	NY
Zip Code:	11001
Country Code:	001
Phone:	(718) 721-0700
EMail:	KS@AARSNY.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

NEW MOTT APARTMENT CORP. (Continued) **U003395750**

Site Id:	22755
Affiliation Type:	Facility Operator
Company Name:	NEW MOTT APARTMENT CORP.
Contact Type:	Not reported
Contact Name:	CHRIS CONKLIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 334-2168
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-05-25

Site Id:	22755
Affiliation Type:	Emergency Contact
Company Name:	NEW MOTT APT CORP % DOWNTOWN PROPERTIES
Contact Type:	Not reported
Contact Name:	CHANNEL OIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 318-7880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-05-25

Tank Info:

Tank Number:	0030816
Tank Id:	43714
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
D00 - Pipe Type - No Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

NEW MOTT APARTMENT CORP. (Continued) **U003395750**

Install Date:	03/01/1980
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

O297 **JOSEPH PAPP PUBLIC THEATRE** **NY UST U004063268**
NNE **425 LAFAYETTE STREET** **NY AST N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.129 mi.
682 ft. **Site 9 of 23 in cluster O**

Relative: **Lower**
Actual: **41 ft.**

UST:

Id/Status:	2-601956 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585160.59376
UTM Y:	4509198.33076
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	23918
Affiliation Type:	Mail Contact
Company Name:	NEW YORK SHAKESPEARE FESTIVAL
Contact Type:	Not reported
Contact Name:	ISHMAEL FIGUEROA
Address1:	425 LAFAYETTE STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 539-8618
EMail:	IZEE@PUBLICTHEATER.ORG
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-11-10

Site Id:	23918
Affiliation Type:	Facility Operator
Company Name:	JOSEPH PAPP PUBLIC THEATRE
Contact Type:	Not reported
Contact Name:	ISHMAEL FIGUEROA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 539-8618
EMail:	Not reported

JOSEPH PAPP PUBLIC THEATRE (Continued) **U004063268**

Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-11-10

Site Id:	23918
Affiliation Type:	Emergency Contact
Company Name:	DEPARTMENT OF CULTURAL AFFAIRS
Contact Type:	Not reported
Contact Name:	ISHMAEL FIGUEROA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 733-7009
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-06-23

Site Id:	23918
Affiliation Type:	Facility Owner
Company Name:	DEPARTMENT OF CULTURAL AFFAIRS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2 COLUMBUS CIRCLE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 841-4100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-05

Tank Info:

Tank Number:	2
Tank ID:	48494
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	500
Install Date:	12/01/1981
Date Tank Closed:	04/16/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

JOSEPH PAPP PUBLIC THEATRE (Continued) **U004063268**

Modified By: MSBAPTIS
Last Modified: 04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

AST:

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-601956
Program Type: PBS
UTM X: 585160.59376
UTM Y: 4509198.33076
Expiration Date: N/A
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id: 23918
Affiliation Type: Mail Contact
Company Name: NEW YORK SHAKESPEARE FESTIVAL
Contact Type: Not reported
Contact Name: ISHMAEL FIGUEROA
Address1: 425 LAFAYETTE STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 539-8618
EMail: IZEE@PUBLICTHEATER.ORG
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-11-10

Site Id: 23918
Affiliation Type: Facility Operator
Company Name: JOSEPH PAPP PUBLIC THEATRE
Contact Type: Not reported
Contact Name: ISHMAEL FIGUEROA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 539-8618

JOSEPH PAPP PUBLIC THEATRE (Continued) **U004063268**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-11-10

Site Id:	23918
Affiliation Type:	Emergency Contact
Company Name:	DEPARTMENT OF CULTURAL AFFAIRS
Contact Type:	Not reported
Contact Name:	ISHMAEL FIGUEROA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 733-7009
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-06-23

Site Id:	23918
Affiliation Type:	Facility Owner
Company Name:	DEPARTMENT OF CULTURAL AFFAIRS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2 COLUMBUS CIRCLE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 841-4100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-01-05

Tank Info:

Tank Number:	1
Tank Id:	48493
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H99 - Tank Leak Detection - Other
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)

JOSEPH PAPP PUBLIC THEATRE (Continued) **U004063268**

I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/21/1966
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/18/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

O298 **CONSOLIDATED EDISON - MH 37937** **NY MANIFEST** **U002034298**
NNE **425 LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.129 mi.
682 ft. **Site 10 of 23 in cluster O**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004250262
Facility Status:	Not reported
Location Address 1:	425 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004250262
Mailing Name:	CONSOLIDATED EDISON - MH 37937
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/22/2012

CONSOLIDATED EDISON - MH 37937 (Continued) **U002034298**

Trans1 Recv Date:	03/22/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/22/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004250262
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009204828JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O299 **CON EDISON MANHOLE 37937** **NJ MANIFEST** **S117984978**
NNE **425 LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.129 mi.
682 ft. **Site 11 of 23 in cluster O**

Relative: **Lower**
Actual: **41 ft.**

NJ MANIFEST:

EPA Id:	NYP004246361
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ

CON EDISON MANHOLE 37937 (Continued) **S117984978**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006903916JJK
EPA ID:	NYP004246361
Date Shipped:	1/13/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

O300 **CON EDISON MANHOLE 37937** **RCRA NonGen / NLR** **1015746643**
NNE **425 LAFAYETTE ST** **NY MANIFEST** **NYP004246361**
1/8-1/4 **NEW YORK, NY 10003**
0.129 mi.
682 ft. **Site 12 of 23 in cluster O**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/12/2012
Facility name:	CON EDISON MANHOLE 37937
Facility address:	425 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004246361
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	JUAN RODRIGUEZ
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-865-5931
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/13/2012
Site name:	CON EDISON MANHOLE 37937
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004246361
Facility Status:	Not reported
Location Address 1:	425 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported

CON EDISON MANHOLE 37937 (Continued) **1015746643**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004246361
Mailing Name: CONED
Mailing Contact: CONED
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FLOOR
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/13/2012
Trans1 Recv Date: 01/13/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/13/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004246361
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 006903916JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

CON EDISON MANHOLE 37937 (Continued) **1015746643**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J301 **CON EDISON SERVICE BOX: 978** **RCRA NonGen / NLR** **1016148911**
East **228 E 5TH ST FRONT OF** **FINDS** **NYP004275624**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.129 mi. **NY MANIFEST**
683 ft. **Site 19 of 20 in cluster J**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 978
Facility address:	228 E 5TH ST FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004275624
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	RICARDO CARTY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-643-3044
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/23/2012
Site name:	CON EDISON SERVICE BOX: 978
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 978 (Continued) **1016148911**

Violation Status: No violations found

FINDS:

Registry ID: 110055459169

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016148911
Registry ID:	110055459169
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055459169

NY MANIFEST:

Country:	USA
EPA ID:	NYP004275624
Facility Status:	Not reported
Location Address 1:	228 E 5TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004275624
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2012

CON EDISON SERVICE BOX: 978 (Continued) **1016148911**

Trans1 Recv Date:	10/23/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004275624
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456548JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

J302 **CON EDISON SERVICE BOX: 978** **NJ MANIFEST** **S117986858**
East **228 E 5TH ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.129 mi.
683 ft. **Site 20 of 20 in cluster J**

Relative: NJ MANIFEST:
Lower

EPA Id:	NYP004275624
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	RICARDO CARTY

Actual:
39 ft.

CON EDISON SERVICE BOX: 978 (Continued) **S117986858**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456548JJK
EPA ID:	NYP004275624
Date Shipped:	10/23/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	100.00 Pounds

N303 **317 BOWERY** **NY UST** **U004045398**
SSE **317 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.131 mi.
694 ft. **Site 7 of 8 in cluster N**

Relative:
Lower

Actual:
41 ft.

UST:

Id/Status:	2-608681 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/27/2018
UTM X:	585129.93099
UTM Y:	4508750.48379
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30533
Affiliation Type:	Mail Contact
Company Name:	BOWERY RESIDENTS COMMITTEE INC
Contact Type:	Not reported
Contact Name:	CLEMENT ARMOGAN
Address1:	127 WEST 25TH STREET 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 803-5708
EMail:	CARMOGAN@BRE.ORG
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-12-05

Site Id:	30533
Affiliation Type:	Facility Operator
Company Name:	317 BOWERY
Contact Type:	Not reported
Contact Name:	BOWERY RESIDENTS COMM, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 533-5656
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ANAUSTIN
Date Last Modified:	2005-08-09

Site Id:	30533
Affiliation Type:	Facility Owner
Company Name:	S.F. ASSOCIATES, L.P./ GF ASSOC LP
Contact Type:	PRES
Contact Name:	S.F. ASSOCIATES LP
Address1:	94 BOWERY
Address2:	Not reported
City:	NEW YORK
State:	NY

317 BOWERY (Continued) **U004045398**

Zip Code:	10013
Country Code:	001
Phone:	(212) 481-1866
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-12-05

Site Id:	30533
Affiliation Type:	Emergency Contact
Company Name:	S.F. ASSOCIATES, L.P./ GF ASSOC LP
Contact Type:	Not reported
Contact Name:	CLEMENT ARMUGAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 309-9924
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-12-05

Tank Info:

Tank Number:	001
Tank ID:	65517
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	01/01/1984
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	10/21/2013
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

B05 - Tank External Protection - Jacketed
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping

317 BOWERY (Continued) **U004045398**

E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)

R304 **250 MERCER SQ OWNER CORP** **NY AST** **U003390463**
WNW **250 MERCER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.132 mi.
695 ft. **Site 2 of 6 in cluster R**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-146439
Program Type:	PBS
UTM X:	584864.85066
UTM Y:	4509099.24069
Expiration Date:	08/26/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4247
Affiliation Type:	Facility Owner
Company Name:	MERCER SQ OWNER CORPORATON
Contact Type:	COMPLIANCE MANAGER
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	250 MERCER STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 473-6288
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-05

Site Id:	4247
Affiliation Type:	Facility Operator
Company Name:	250 MERCER SQ OWNER CORP
Contact Type:	Not reported
Contact Name:	RAYMOND SUAREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-5856
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-05

Site Id:	4247
Affiliation Type:	Emergency Contact

250 MERCER SQ OWNER CORP (Continued) **U003390463**

Company Name:	MERCER SQ OWNER CORPORATON
Contact Type:	Not reported
Contact Name:	BRENDA BALLISON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 254-5856
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-05

Site Id:	4247
Affiliation Type:	Mail Contact
Company Name:	DOULGAS ELLIMAN PROPERTY MGMT
Contact Type:	Not reported
Contact Name:	PATRICIA PETTWAY-BROWN
Address1:	675 THIRD AVENUE
Address2:	5TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-05

Tank Info:

Tank Number:	001
Tank Id:	19197
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1979
Capacity Gallons:	10000

250 MERCER SQ OWNER CORP (Continued) **U003390463**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/05/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	19198
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	07/01/1948
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/05/2017
Material Name:	other

K305 **304 MULBERRY STREET** **NY AST** **A100292061**
SSW **304 MULBERRY STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.132 mi.
695 ft. **Site 22 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-607424
Program Type:	PBS
UTM X:	584893.25887
UTM Y:	4508725.74313
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

304 MULBERRY STREET (Continued) **A100292061**

Affiliation Records:

Site Id:	29276
Affiliation Type:	Facility Operator
Company Name:	304 MULBERRY STREET
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 460-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-02-03

Site Id:	29276
Affiliation Type:	Emergency Contact
Company Name:	304 MULBERRY STREET OPERATING COMPANY LLC
Contact Type:	Not reported
Contact Name:	STEVEN KRAMER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 609-3712
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-02-03

Site Id:	29276
Affiliation Type:	Mail Contact
Company Name:	304 MULBERRY STREET OPERATING COMPANY LLC
Contact Type:	Not reported
Contact Name:	GAYLE KENNEDY
Address1:	C/O BROAD STREET DEVELOPMENT, LLC
Address2:	80 BROAD ST., 2ND FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(212) 460-8000
EMail:	GAYLEK@BSDRE.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-01-04

Site Id:	29276
Affiliation Type:	Facility Owner
Company Name:	304 MULBERRY STREET OPERATING COMPANY LLC
Contact Type:	GENERAL MGR.
Contact Name:	DANIEL BLANCO

304 MULBERRY STREET (Continued) **A100292061**

Address1:	80 BROAD ST., 2ND FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 609-3700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-01-04

Tank Info:

Tank Number:	1
Tank Id:	62941
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A01 - Tank Internal Protection - Epoxy Liner
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/08/1989
Capacity Gallons:	6045
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/05/2017
Register:	True
Modified By:	DAFRANCI
Last Modified:	01/04/2018
Material Name:	#2 fuel oil (on-site consumption)

T306 **H21 EAST 3RD STREET** **NY AST** **A100178009**
ESE **21 EAST 3RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.132 mi.
696 ft. **Site 1 of 15 in cluster T**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605708
Program Type:	PBS
UTM X:	585274.63671
UTM Y:	4508836.60894
Expiration Date:	04/18/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27575
Affiliation Type:	Mail Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET
Address2:	3RD FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	VORSELL@CSMHA.ORG
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-03-22

Site Id:	27575
Affiliation Type:	Facility Operator
Company Name:	21 EAST 3RD STREET
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27575
Affiliation Type:	Emergency Contact
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION
Contact Type:	Not reported
Contact Name:	EFRAIN CONCEPCION
Address1:	Not reported
Address2:	Not reported
City:	Not reported

H21 EAST 3RD STREET (Continued) **A100178009**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 246-3870
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27575
Affiliation Type:	Facility Owner
Company Name:	COOPER SQUARE MUTUAL HOUSING ASSOCIATION II HDFC
Contact Type:	EXEC. DIR.
Contact Name:	VALERIO ORSELLI
Address1:	59-61 EAST 4TH STREET, 3RD FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-5340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-20

Tank Info:

Tank Number:	001
Tank Id:	60263
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H99 - Tank Leak Detection - Other
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/08/1995
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY

H21 EAST 3RD STREET (Continued) **A100178009**

Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Q307 **50 COOPER SQUARE** **NY AST** **A100292457**
NE **50 COOPER SQUARE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.132 mi.
697 ft. **Site 13 of 18 in cluster Q**

Relative:
Lower

Actual:
41 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608743
Program Type: PBS
UTM X: 585182.39207
UTM Y: 4509123.43735
Expiration Date: 04/01/2023
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 30594
Affiliation Type: Facility Operator
Company Name: 50 COOPER SQUARE
Contact Type: Not reported
Contact Name: JERRY SIMO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 995-5554
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-03-12

Site Id: 30594
Affiliation Type: Emergency Contact
Company Name: COOPER SQ. ASSOCIATES, L.P.
Contact Type: Not reported
Contact Name: BRIAN CHABRUNN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 272-5717
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-03-12

Site Id: 30594
Affiliation Type: Mail Contact
Company Name: HARTZ MOUNTAIN INDUSTRIES

50 COOPER SQUARE (Continued) **A100292457**

Contact Type:	Not reported
Contact Name:	NICHOLAS TURKOVIC
Address1:	667 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10065
Country Code:	001
Phone:	(212) 308-3336
EMail:	NICHOLAS.TURKOVIC@HARTZMOUNTAIN.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-12

Site Id:	30594
Affiliation Type:	Facility Owner
Company Name:	COOPER SQ. ASSOCIATES, L.P.
Contact Type:	VICE PRESIDENT / PROPERTY MANAGER
Contact Name:	NICHOLAS J. TURKOVIC
Address1:	400 PLAZA DRIVE
Address2:	Not reported
City:	SECAUCUS
State:	NJ
Zip Code:	07094
Country Code:	001
Phone:	(201) 272-5717
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-12

Tank Info:

Tank Number:	001
Tank Id:	65590
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

50 COOPER SQUARE (Continued) **A100292457**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	03/12/2018
Material Name:	#2 fuel oil (on-site consumption)

M308 **CON EDISON SERVICE BOX: 31119** **RCRA NonGen / NLR** **1016973441**
SW **166-168 CROSBY ST & HOUSTON ST N OF** **NY MANIFEST** **NYP004472445**
1/8-1/4 **NEW YORK, NY 10012**
0.132 mi.
697 ft. **Site 15 of 26 in cluster M**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/19/2014
Facility name:	CON EDISON SERVICE BOX: 31119
Facility address:	166-168 CROSBY ST & HOUSTON ST N OF NEW YORK, NY 10012
EPA ID:	NYP004472445
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/19/2014
Site name:	CON EDISON SERVICE BOX: 31119
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004472445

CON EDISON SERVICE BOX: 31119 (Continued) **1016973441**

Facility Status:	Not reported
Location Address 1:	166 CROSBY ST
Code:	BP
Location Address 2:	SB31119
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004472445
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2014
Trans1 Recv Date:	03/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004472445
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360627GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 31119 (Continued) **1016973441**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYP004854630
Facility Status:	Not reported
Location Address 1:	166 CROSBY ST
Code:	BP
Location Address 2:	SB 31119
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004854630
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/16/2015
Trans1 Recv Date:	10/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON SERVICE BOX: 31119 (Continued) **1016973441**

Generator EPA ID:	NYP004854630
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085570JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

M309 **CON ED** **NY MANIFEST** **S118463627**
SW **164 CROSBY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.132 mi.
698 ft. **Site 16 of 26 in cluster M**

Relative: NY MANIFEST:
Lower

Actual:
41 ft.

Country:	USA
EPA ID:	NYP004854515
Facility Status:	Not reported
Location Address 1:	164 CROSBY ST
Code:	BP
Location Address 2:	SB 31118
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

CON ED (Continued) **S118463627**

NY MANIFEST:

EPAID:	NYP004854515
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/16/2015
Trans1 Recv Date:	10/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004854515
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085569JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON ED (Continued) **S118463627**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

M310 **CON EDISON SERVICE BOX: 27233** **RCRA NonGen / NLR** **1016968002**
WSW **647 BROADWAY** **NY MANIFEST** **NYP004416038**
1/8-1/4 **NEW YORK, NY 10012**
0.132 mi.
699 ft. **Site 17 of 26 in cluster M**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/10/2014
Facility name:	CON EDISON SERVICE BOX: 27233
Facility address:	647 BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004416038
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/10/2014
Site name:	CON EDISON SERVICE BOX: 27233
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

CON EDISON SERVICE BOX: 27233 (Continued) **1016968002**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004416038
Facility Status:	Not reported
Location Address 1:	647 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004416038
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/2014
Trans1 Recv Date:	01/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004416038
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328604GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON SERVICE BOX: 27233 (Continued) **1016968002**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

R311 **NEW YORK UNIVERSITY** **NY Spills** **1007112448**
WNW **251 MERCER ST** **RCRA NonGen / NLR** **NYR000075762**
1/8-1/4 **NEW YORK, NY 10013** **NY MANIFEST**
0.133 mi.
701 ft. **Site 3 of 6 in cluster R**

Relative: **Lower**

Actual: **37 ft.**

SPILLS:

Facility ID:	0802239
Facility Type:	ER
Spill Number:	0802239
DER Facility ID:	21403
Site ID:	398343
DEC Region:	2
Closed Date:	2010-01-19
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2008-05-28
Investigator:	jbvought
Referred To:	Not reported
Reported to Dept:	2008-05-28
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-28
Spill Record Last Update:	2010-01-20
Spiller Name:	CELESTE ROSER
Spiller Company:	NY UNIVERSITY
Spiller Address:	251 MERCER STREET

NEW YORK UNIVERSITY (Continued) **1007112448**

Spiller Company: 001
Contact Name: CELESTE ROSER
DEC Memo: "05/28/08 Contaminated soil was discovered around underground return line. Return line will be replaced, as per Celeste Rufer.Ms. Rufer also indicated that tightness testing will be performed after the line replacement.CSL was sent to(via mail& facsimile@(212)995-4932) New York University 285 Mercer Street New York, NY 10003 Attn: Celeste Rufer (sr) 11/05/08-Vought-Received copy of submission of PBS registration to DEC Lombardo. 8/21/09- Complete file review by Intern EM Ibeh and DEC Vought File being reviewed is SP#0809019, spill date-11/08, at NYU 251 Mercer Street, NY 10003 {see SP# 0802239}. 6/30/08-TRC Solutions Report to DEC Vought stating that on 5/20/08, the diesel fuel pump associated with the southernmost 30,000gal. UST lost suction pressure indicating a clog or obstruction in the fuel oil supply line and the tank system was immediately taken out of service and in order to determine the cause of obstruction, hand excavation was performed to expose the fuel line. On 5/28/08, the fuel oil lines were exposed and petroleum impacted soil was observed adjacent to an elbow on the fuel oil line. The elbow on the fuel oil line was replaced by NYU plumbing staff afterwards, hand excavation was performed to remove the petroleum impacted soil. The sidewalls and bottom of the excavation were screened with a PID and based on observations, petroleum contamination in soil was confined horizontally to the immediate area of the former leaking fuel oil line and extended vertically downward. 3 post-excavation end-point samples were collected- 1 sample from the bottom of the excavation and 2 samples from the bottom of the northern and southern sidewalls. Due to presence of USTs, it was not practical to collect samples from the eastern and western sidewalls. Groundwater was not encountered in the excavation. Samples were analyzed for STARS Memo #1 VOCs and SVOCs. VOCs for the 3 samples were non-detect while SVOCs for south SW- Benzo(a)pyrene 0.18ppm and Benzo(b)fluoroanthene 0.25ppm; north SW- Benzo(a)pyrene 0.16ppm; BE- Benzo(a)pyrene 0.12ppm. A CD of the Spill Closure Letter Report was enclosed with the correspondence. 9/10/08- TRCSolutions Report same as above. 5/18/09- TRCSolutions Report to DEC Vought stating that the Tisch Building at the above-named address utilizes #2 fuel oil generators for the facility s cogeneration plant and that NYU maintains (3) 30,000gal. fuel oil (2 #2 and 1 #6 fuel oil) USTs (PBS #2-043982) to store fuel for the generators. That on 11/08, construction activities were initiated to re-line the northernmost 30,000gal. UST (tank #3) and on this day, during soil excavations to expose the surface of this UST, a historic out-of-service 4 diameter fuel oil line was identified. The line was oriented north-south, ~6 bgs and a hole ~a quarter inch in diameter was observed in the part of the line above the top of the UST and petroleum impacted soil was observed adjacent to the damaged historic fuel oil line thus a spill was reported to the DEC and a SP# was assigned. The line was removed 11/12/08 and after it was done, hand excavation was performed to remove the petroleum impacted soil. The sidewalls and bottom of the excavation were screened with a PID for evidence of petroleum contamination along with inspection for staining and odors. Based on observations, petroleum contamination in soil was confined horizontally to ~3ftx2ft area in the immediate vicinity of the former leaking fuel oil line and extended vertically downward. On 3/27/09, the excavation was inspected and soil in the northern and southern sidewall exhibited no visual or olfactory evidence of contamination. PID readings for soil samples collected

NEW YORK UNIVERSITY (Continued) **1007112448**

from the sidewalls of the excavation were not above background and soil from the bottom of the excavation exhibited no visual evidence of contamination; however, it exhibited a slight fuel oil odor and PID readings ranged from 50-100ppm. 3 post-excavation end-point samples were collected- 1 sample from the bottom of the excavation and 2 samples from the bottom of the northern and southern sidewalls. Due to presence of USTs, it was not practical to collect samples from the eastern and western sidewalls. Groundwater was not encountered in the excavation. VOCs for the 2 sidewall (SW) samples were below the RSCO for fuel oil contaminated soil but 1,2,4-Trimethylbenzene 26ppm, 1,3,5- Trimethylbenzene 13.ppm, m+p Xylenes 11.0ppm, Naphthalene 15.0ppm and o Xylene 9.7ppm were above RSCO for the sample from the bottom of the excavation (BE). SVOC samples from both SWs had Benzo(a)pyrene at 0.081ppm and 0.071ppm respectively while the BE concentrations were below RSCO. Report concluded that the SVOC concentration detected from the samples from the sidewalls were characteristic of the soil found at the site and not as a result of the spill. VOC exceedence was as a result of the residual fuel oil contamination at the bottom of the excavation. TRC requested spill closure as the historic fuel oil line has been removed and groundwater not being encountered in the excavation (borings installed for an adjacent project revealed that it is present at ~38ftbgs and is not potable). 08/26/09-Vought-Reviewed above notes and file with DEC Ibeh and message was left with TRC Guder (212-221-7822) that either groundwater sample at previous bottom endpoint sample location with site plan OR sensitive receptor survey with site plan is required. Letter to be issued upon callback from Guder. See also spill #0809019 at same site. 09/15/09-Vought-Received email from Guder that I did receive your message from a few weeks back and I presented the options (groundwater or sensitive receptor survey) to NYU. I haven't received a firm commitment on which way they are leaning but I am following up with them. As soon as I hear from them I will send you aquick note with the information. 10/04/09-Vought-Received email from TRC Richard Wetherbee that You are correct in that both releases are associated with the same tank system; however, there were two separate small releases from different sets of piping associated with the USTs. The spills were discovered at different times (hence the separate spill cases) and each was remediated separately. At completion, one of the remedial excavations was entirely clean (Spill No. 0802239): no evidence of residual petroleum contamination; no detectable VOCs; and minor exceedances of TAGM RSCOs for benzo(a)pyrene and beno(b)fluoranthene (max concentration 0.25 mg/kg), which are attributed to the fill characteristics. The second remedial excavation (Spill No. 0809019) removed all petroleum impacted soil to a depth of approximately 20 feet below grade; however, field observations and lab results indicated the presence of residual fuel oil contamination at the base of the excavation. Going forward, we are managing the closure of the spill cases as one project - we are currently preparing a sensitive receptor survey report which will address both spill cases and support our petition for no further action. 11/30/09-Vought-Received copy of report dated 11/30/09 from TRC Lindemuth entitled Sensitive Receptor Survey. Tisch Building located 251 Mercer uses #2 fuel oil generators for facilities cogeneration plant. In conjunction with the contstruction of a cogeneration facility, the No. 2 fuel oil USTs were re-fitted and relined. During this work, petroleum impacted soil was observed in the vicinity of former fuel oil supply lines and

NEW YORK UNIVERSITY (Continued) **1007112448**

spills were reported to the NYSDEC (Spill Case numbers 0809019 and 0802239). Hand excavation of soils occurred at both spill locations. Additional excavation could not be performed at both locations due to a retaining wall. Tank area is located in a pedestrian plaza between two buildings. Groundwater at estimated depth of 38'bg. FOR SPILL NUMBER 0802239: Broken fill pipe at 7'bg and soil excavation performed to depth of 15'bg. 27 drums of contaminated soil removed. Field observations indicated that the petroleum impacted soil was limited in extent and that no petroleum contaminated soil remained at the completion of the excavation . Soil analyticals for this spill number are below TAGM 4046 Requirements except for minor PAH's attibutable to fill material. FOR SPILL NUMBER 0809019: This spill found during relining of northern most UST. During excavation activities to top of UST, a out of service 4 diameter fuel oil fill line was identified. A hole approximately one quarter inch in diameter was observed in the part of the fuel line above the top of the UST and petroleum impacted soil was observed. Soil was hand excavated to a depth of 20'bg and 26 drums of contaminated soil removed. Contaminated soil remained at base of excavation. Soil analyticals showed: 26000ppb 1,2,4-trimethylbenzene, 15,000ppb napthalene and 11000ppb xylene. Sensitive receptor includes evaluation of exposure pathways, use of surrounding buildings. The results of the site reconnaissance indicated that the area in the vicinity of the release is paved with impermeable materials (e.g. concrete and asphalt) and that there are no sensitive receptors located on adjacent properties. Request spill closure.
1/19/10-Vought-This spill closed by Vought and above information forwarded to DEC Piper for possible spill closure of Spill #0809019.
SCL sent to: New York University 285 Mercer Street New York, NY 10003 Attn: Celeste Rufer with cc to TRC Lindemuth. "

Remarks: "PBS No: 2-043982 hole in fuel return line and repairing will be started, has been shut down:"

All Materials:

Site ID:	398343
Operable Unit ID:	1155231
Operable Unit:	01
Material ID:	2146095
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NEW YORK UNIVERSITY
Facility address:	251 MERCER ST NEW YORK, NY 10013
EPA ID:	NYR000075762
Mailing address:	MERCER ST NEW YORK, NY 10013
Contact:	SUZANNE CASSIDY

NEW YORK UNIVERSITY (Continued) **1007112448**

Contact address: MERCER ST C-O PERFORMANCE
NEW YORK, NY 10013
Contact country: US
Contact telephone: 718-805-6252
Contact email: Not reported
EPA Region: 02
Land type: State
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: 251 MERCER ST
NEW YORK, NY 10013
Owner/operator country: US
Owner/operator telephone: 212-998-6060
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: 251 MERCER ST
NEW YORK, NY 10013
Owner/operator country: US
Owner/operator telephone: 212-998-6060
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006

NEW YORK UNIVERSITY (Continued) **1007112448**

Site name: NEW YORK UNIVERSITY
Classification: Not a generator, verified

Date form received by agency: 08/27/1999
Site name: NEW YORK UNIVERSITY
Classification: Small Quantity Generator

. Waste code: D007
. Waste name: CHROMIUM

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/24/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

NY MANIFEST:
Country: USA
EPA ID: NYR000075762
Facility Status: Not reported
Location Address 1: 251 MERCER ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10013
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000075762
Mailing Name: NYU SCHOOL OF LAW FOUNDATION
Mailing Contact: CHARLES S VELLA
Mailing Address 1: 251 MERCER ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10013
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129986060

NY MANIFEST:
Document ID: NYG1002105
Manifest Status: Not reported
seq: 01
Year: 1999
Trans1 State ID: NYPD1011
Trans2 State ID: Not reported
Generator Ship Date: 09/10/1999
Trans1 Recv Date: 09/10/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/13/1999
Part A Recv Date: Not reported

NEW YORK UNIVERSITY (Continued) **1007112448**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075762
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	012
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

R312 **NYU CENTRAL PLANT** **NY LTANKS** **1001493678**
WNW **251 MERCER ST** **NY Spills** **N/A**
1/8-1/4 **NEW YORK, NY 10012** **US AIRS**
0.133 mi. **NY AIRS**
701 ft. **Site 4 of 6 in cluster R**

Relative: LTANKS:
Lower

Actual: Facility ID:	0007785
37 ft. Site ID:	141532
Closed Date:	2001-08-21
Spill Number:	0007785
Spill Date:	2000-10-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2000-10-02
CID:	397
Water Affected:	Not reported
Spill Notifier:	Tank Tester

NYU CENTRAL PLANT (Continued) **1001493678**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-02
Spill Record Last Update:	2001-08-21
Spiller Name:	BRIAN COSTELLO
Spiller Company:	NYU
Spiller Address:	251 MERCER ST
Spiller County:	001
Spiller Contact:	BRIAN COSTELLO
Spiller Phone:	(212) 829-0880
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	120835
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SYSTEM FAILED. FILL LINE ISOLATED AND FAILED. NEW FILL INSTALLED. SYSTEM TESTED AND PASSED. BORING PERFORMED NEXT TO FORMER FILL TO 6.5 FEET. ONLY MINOR CONTAMINATION BELOW TAGM ENCOUNTERED."
Remarks:	"TANK TEST FAILURE"

All TTF:

Facility ID:	0007785
Spill Number:	0007785
Spill Tank Test:	1525917
Site ID:	141532
Tank Number:	1
Tank Size:	6000
Material:	0013
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	141532
Operable Unit ID:	828485
Operable Unit:	01
Material ID:	545311
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

SPILLS:

Facility ID:	0101499
Facility Type:	ER
Spill Number:	0101499
DER Facility ID:	213675
Site ID:	261652
DEC Region:	2
Closed Date:	2001-05-18
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	2001-05-08
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2001-05-08
CID:	282
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-08
Spill Record Last Update:	2001-05-18
Spiller Name:	N/A
Spiller Company:	JOSEPH STERN
Spiller Address:	N/A
Spiller Company:	001
Contact Name:	MR SOLECKI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE SITE VISIT REVEALED NO LEAK, VERY SMALL STAIN (+-2) NEAR OIL FILL PORT."
Remarks:	"caller stated there was a underground leak from a oil line the caller was a annonymous caller. "

All Materials:

Site ID:	261652
Operable Unit ID:	840329
Operable Unit:	01
Material ID:	537204
Material Code:	9999
Material Name:	other -
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9507265
Facility Type:	ER
Spill Number:	9507265
DER Facility ID:	213675

NYU CENTRAL PLANT (Continued) **1001493678**

Site ID:	261653
DEC Region:	2
Closed Date:	1995-10-13
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	1995-09-13
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1995-09-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1948-12-27
Spill Record Last Update:	1995-11-06
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	""
Facility ID:	0709032
Facility Type:	ER
Spill Number:	0709032
DER Facility ID:	213675
Site ID:	390044
DEC Region:	2
Closed Date:	2008-03-03
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2007-11-19
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2007-11-19
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-11-19
Spill Record Last Update:	2008-03-03

NYU CENTRAL PLANT (Continued) **1001493678**

Spiller Name: ANTHONY LARA
Spiller Company: NYU CO-GEN PLANT
Spiller Address: 251 MERCER STREET
Spiller Company: 999
Contact Name: ANTHONY LARA
DEC Memo: "Contaminated soil (#2 oil) found under sidewalk between curb fill and basement wall due to leaking remote fill line. NYU Contact Person: Martin Kushner 212-998-1405 PTC will NOT be doing any more work on this project. NYU is planning a major excavation job on this building and will be digging out the sidewalk and underpinning the building foundation wall as part of a large renovation of the building. They do not think it's necessary to dig out the contamination now and refill, if they will be digging the entire area out in the near future. DEC should confirm NYU's work schedule and get followup when the excavation is actually done. **** Also, need to ask NYU about status of new fill line?*** 11/27/07 - Raphael Ketani. I contacted Martin Kushner of NYU. He said that the site is a co-generation plant. NYU is planning to expand the plant. Deeper digging is necessary to expand the plant. He said that the company that will do the expansion construction will do the deep digging with shoring and underpinning. I asked him about the fill line replacement. He said that they have a temporary right now and will put in a new permanent one when the construction is done on that side of the plant. He said he expected the work to start next week. He put me in conference with Celeste Rufer (roo-fer) (212) 998-1086, Environmental Health & Safety (environmental specialist). I spoke to Ms. Rufer and told her that DEC needed a report at the end of the project with manifests for the soil removed, pictures, plans, end point sample results, and a cover letter explaining what took place. I also asked her to keep me updated as to the progress of the project. She said she would send e-mails and voice mails. She asked that I contact her, rather than Mr. Kushner, as she is the project manager. 12/10/07 - Raphael Ketani. Ms. Rufer called to say that they have resumed digging at the site. They plan to go down 15' for the installation of a Con Ed vault. However, upon the continuation of the digging, they hit an unknown tank. They will inspect the tank, clean it out, remove it, and register it. 12/11/07 - Raphael Ketani. Ms. Rufer called to say that the object was not a tank, but a pipe. It has been completely uncovered and will be removed soon. The soil around the pipe will be checked for contamination and end point samples will be taken if contamination is detected. 12/19/07 - Raphael Ketani. Ms. Rufer (212) 998-1086 called me. She said that they were starting the soil excavation in the area of the future Con Ed vault. She added that all of the contaminated soil will be removed. 1/4/08 - Raphael Ketani. I tried to contact Ms. Rufer, but could only leave a message. 1/7/08 - Raphael Ketani. I spoke to Ms. Rufer. She said that everything was dug out on 12/21/07 and end points were taken. She said that she had told the company doing the digging to keep removing soil until everything is clean. She added that Con Ed has already installed their vault. I told her that DEC needed the manifests and the end point results. She said that DEC will get everything in a report when it is ready. 2/7/08 - Raphael Ketani. I spoke to Ms. Rufer. She said she is about to review the completed report regarding the excavation, sampling and remediation work. She said she hopes to get it to me sometime during the next two weeks. I told her that would be fine. 2/28/08 - Raphael Ketani. Today I received the Environmental Soil Excavation and End Point Sampling

NYU CENTRAL PLANT (Continued) **1001493678**

Findings Report dated 2/12/08 (revised 2/22/08) from Ms. Rufer. I am reviewing the report. 3/3/08 - Raphael Ketani. I finished my review of the ESE and EPSFR. There were virtually no VOC analyte hits for the end point samples. Sample EP-1 was the only one with SVOC hits. Only those hits belonging to the benzo series exceeded the TAGM standards. Manifests for the removed soil and pictures of the excavation work were also included. Based upon my review of the soil analyticals in the ESE and EPSFR, and the manifests and the photos, I am closing the spill case. "

Remarks: "WHILE EXCAVAVTING CAME UPON CONTAMINATED SOIL"

All Materials:

Site ID:	390044
Operable Unit ID:	1147160
Operable Unit:	01
Material ID:	2137560
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0809019
Facility Type:	ER
Spill Number:	0809019
DER Facility ID:	120835
Site ID:	406452
DEC Region:	2
Closed Date:	2010-01-27
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2008-11-10
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2008-11-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-11-10
Spill Record Last Update:	2010-01-27
Spiller Name:	CELESTE RUFER
Spiller Company:	NY UNIVERSITY
Spiller Address:	251 MERCER ST
Spiller Company:	999
Contact Name:	CELESTE RUFER
DEC Memo:	"Contaminated soil found under/around 3000 gal tank. Soil being

NYU CENTRAL PLANT (Continued) **1001493678**

removed, end point samples will be taken. Report will be forwarded to DEC Piper. 8/21/09- Complete file review by Intern EM Ibeh and DEC Vought File being reviewed is SP#0809019, spill date- 11/08, at NYU 251 Mercer Street, NY 10003. {See SP# 0802239} 6/30/08- TRCSolutions Report to DEC Vought stating that on 5/20/08, the diesel fuel pump associated with the southernmost 30,000gal. UST lost suction pressure indicating a clog or obstruction in the fuel oil supply line and the tank system was immediately taken out of service and in order to determine the cause of obstruction, hand excavation was performed to expose the fuel line. On 5/28/08, the fuel oil lines were exposed and petroleum impacted soil was observed adjacent to an elbow on the fuel oil line. The elbow on the fuel oil line was replaced by NYU plumbing staff afterwards, hand excavation was performed to remove the petroleum impacted soil. The sidewalls and bottom of the excavation were screened with a PID and based on observations, petroleum contamination in soil was confined horizontally to the immediate area of the former leaking fuel oil line and extended vertically downward. 3 post-excavation end-point samples were collected- 1 sample from the bottom of the excavation and 2 samples from the bottom of the northern and southern sidewalls. Due to presence of USTs, it was not practical to collect samples from the eastern and western sidewalls. Groundwater was not encountered in the excavation. Samples were analyzed for STARS Memo #1 VOCs and SVOCs. VOCs for the 3 samples were non-detect while SVOCs for south SW- Benzo(a)pyrene 0.18ppm and Benzo(b)fluoroanthene 0.25ppm; north SW- Benzo(a)pyrene 0.16ppm; BE- Benzo(a)pyrene 0.12ppm. A CD of the Spill Closure Letter Report was enclosed with the correspondence. 9/10/08- TRCSolutions Report same as above. 5/18/09- TRCSolutions Report to DEC Vought stating that the Tisch Building at the above-named address utilizes #2 fuel oil generators for the facility s cogeneration plant and that NYU maintains (3) 30,000gal. fuel oil (2 #2 and 1 #6 fuel oil) USTs (PBS #2-043982) to store fuel for the generators. That on 11/08, construction activities were initiated to re-line the northernmost 30,000gal. UST (tank #3) and on this day, during soil excavations to expose the surface of this UST, a historic out-of-service 4 diameter fuel oil line was identified. The line was oriented north-south, ~6 bgs and a hole ~a quarter inch in diameter was observed in the part of the line above the top of the UST and petroleum impacted soil was observed adjacent to the damaged historic fuel oil line thus a spill was reported to the DEC and a SP# was assigned. The line was removed 11/12/08 and after it was done, hand excavation was performed to remove the petroleum impacted soil. The sidewalls and bottom of the excavation were screened with a PID for evidence of petroleum contamination along with inspection for staining and odors. Based on observations, petroleum contamination in soil was confined horizontally to ~3ftx2ft area in the immediate vicinity of the former leaking fuel oil line and extended vertically downward. On 3/27/09, the excavation was inspected and soil in the northern and southern sidewall exhibited no visual or olfactory evidence of contamination. PID readings for soil samples collected from the sidewalls of the excavation were not above background and soil from the bottom of the excavation exhibited no visual evidence of contamination; however, it exhibited a slight fuel oil odor and PID readings ranged from 50-100ppm. 3 post-excavation end-point samples were collected- 1 sample from the bottom of the excavation and 2 samples from the bottom of the northern and southern sidewalls. Due to presence of USTs, it was not practical to collect samples from the eastern and

NYU CENTRAL PLANT (Continued) **1001493678**

western sidewalls. Groundwater was not encountered in the excavation. VOCs for the 2 sidewall (SW) samples were below the RSCO for fuel oil contaminated soil but 1,2,4-Trimethylbenzene 26ppm, 1,3,5-Trimethylbenzene 13.ppm, m+p Xylenes 11.0ppm, Naphthalene 15.0ppm and o Xylene 9.7ppm were above RSCO for the sample from the bottom of the excavation (BE). SVOC samples from both SWs had Benzo(a)pyrene at 0.081ppm and 0.071ppm respectively while the BE concentrations were below RSCO. Report concluded that the SVOC concentration detected from the samples from the sidewalls were characteristic of the soil found at the site and not as a result of the spill. VOC exceedence was as a result of the residual fuel oil contamination at the bottom of the excavation. TRC requested spill closure as the historic fuel oil line has been removed and groundwater not being encountered in the excavation (borings installed for an adjacent project revealed that it is present at ~38ftbgs and is not potable).
09/01/09-Vought-After review with DEC Ibeh, Due to bottom endpoint TAGM 4046 RSCO exceedence and multiple tank systems on site DEC may possibly require: 1)collection of a groundwater sample at tank location with submission of scaled site plan OR 1)submission of a sensitive receptor survey with a scaled site plan. Vought left message with TRC Guder to return call to discuss. Vought transferred file to DEC Piper for further action as he is project manager on record. You are correct in that both releases are associated with the same tank system; however, there were two separate small releases from different sets of piping associated with the USTs. The spills were discovered at different times (hence the separate spill cases) and each was remediated separately. At completion, one of the remedial excavations was entirely clean (Spill No. 0802239): no evidence of residual petroleum contamination; no detectable VOCs; and minor exceedances of TAGM RSCOs for benzo(a)pyrene and beno(b)fluoranthene (max concentration 0.25 mg/kg), which are attributed to the fill characteristics. The second remedial excavation (Spill No. 0809019) removed all petroleum impacted soil to a depth of approximately 20 feet below grade; however, field observations and lab results indicated the presence of residual fuel oil contamination at the base of the excavation. Going forward, we are managing the closure of the spill cases as one project - we are currently preparing a sensitive receptor survey report which will address both spill cases and support our petition for no further action. 11/30/09-Vought-Received copy of report dated 11/30/09 from TRC Lindemuth entitled Sensitive Receptor Survey. Tisch Building located 251 Mercer uses #2 fuel oil generators for facilities cogeneration plant. In conjunction with the contstruction of a cogeneration facility, the No. 2 fuel oil USTs were re-fitted and relined. During this work, petroleum impacted soil was observed in the vicinity of former fuel oil supply lines and spills were reported to the NYSDEC (Spill Case numbers 0809019 and 0802239). Hand excavation of soils occurred at both spill locations. Additional excavation could not be performed at both locations due to a retaining wall. Tank area is located in a pedestrian plaza between two buildings. Groundwater at estimated depth of 38’bg. FOR SPILL NUMBER 0802239: Broken fill pipe at 7’bg and soil excavation performed to depth of 15’bg. 27 drums of contaminated soil removed. Field observations indicated that the petroleum impacted soil was limited in extent and that no petroleum contaminated soil remained at the completion of the excavation . Soil analyticals for this spill number are below TAGM 4046 Requirements except for minor PAH’s

NYU CENTRAL PLANT (Continued) **1001493678**

attibutable to fill material. FOR SPILL NUMBER 0809019: This spill found during relining of northern most UST. During excavation activities to top of UST, a out of service 4 diameter fuel oil fill line was identified. A hole approximately one quarter inch in diameter was observed in the part of the fuel line above the top of the UST and petroleum impacted soil was observed. Soil was hand excavated to a depth of 20'bg and 26 drums of contaminated soil removed. Contaminated soil remained at base of excavation. Soil analyticals showed: 26000ppb 1,2,4-trimethylbenzene, 15,000ppb napthalene and 11000ppb xylene. Sensitive receptor includes evaluation of exposure pathways, use of surrounding buildings. The results of the site reconnaissance indicated that the area in the vicinity of the release is paved with impermeable materials (e.g. concrete and asphalt) and that there are no sensitive receptors located on adjacent properties. Request spill closure.
1/19/10-Vought-This spill 0802239 closed by Vought and above information forwarded to DEC Piper for possible spill closure of Spill #0809019. DECPiper reviewed report. Based on work to date, this spill is closed .see e-docs if warranted. "

Remarks: "Caller states contaminated soils were found around above tank. Soil will be removed and further testing done."

All Materials:

Site ID:	406452
Operable Unit ID:	1163040
Operable Unit:	01
Material ID:	2154340
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Facility ID:	0910413
Facility Type:	ER
Spill Number:	0910413
DER Facility ID:	213675
Site ID:	423172
DEC Region:	2
Closed Date:	2013-10-09
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3101
Spill Date:	2009-12-21
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2009-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-21
Spill Record Last Update:	2013-10-09
Spiller Name:	CELESTE RUFER
Spiller Company:	NY UNIVERSITY
Spiller Address:	251 MERCER STREET
Spiller Company:	999
Contact Name:	CELESTE RUFER
DEC Memo:	"12/21/09-Spoke to Celeste of NYU. Some oil is seeping through a foundation wall in the central heating system room. They are guessing the oil is coming from old abandoned pipes. They will meet with the consultant tomorrow to discuss this seepage. Need follow-up. DEC Piper performed site visit, met with Mike Burke and Celeste. SSI recommended as oil seeps were obseved at a number of locations where utilities enter basement. 5/23/2011- from SSIR The objective ofthe investigation was to (1) evaluate the source of petroleum weeps in the basement and (2)determine whether the observed release has impacted groundwater. Due to restrictive field conditions, the proposed scope of services was not completed and the objectives were not met. There are two active 28,0005gallon No. 2 fuel oil underground storage tanks (USTs) and one active 30,0005gallon No. 6 fuel oil UST located at the Site. The USTs containing No. 2 fuel oil formerly contained No. 6 fuel oil, but were converted in 1985. In addition, one 30,0005gallon No. 6 fuel oil and one 5,0005gallon lube oil USTs were closed in place with foam and concrete slurry, respectively, in close proximity to the active USTs. According to NYU Cogeneration Plant personnel who are knowledgeable about the Site history, aboveground piping associated with the lube oil UST was removed in 1985 and underground piping associated with the out5of5 service No. 6 fuel oil tanks were cleaned and decommissioned in place in 1985 in conjunction with the UST upgrades; however, there are no available records that document how they were cleaned or closed. Oil weeps and petroleum5related staining are evident on the southern basement wall adjacent to the fuel oil piping room at the fuel oil supply and return line penetrations. The active and out of service USTs are located on the opposite side of the walls where weeps were identified however, oil weeps are only evident at the piping penetrations. The extent, magnitude and source of the petroleum release is not known. 5/17/2011- Due to refusal, sir was inconclusive. Further investigation warranted. Report in edocs. Langan proposes: " Inspect all USTs associated piping that was closed5in5place in 1985 to verify that they were properly cleaned and closed5in5place; " Steam clean all accessible piping associated with the out5of5service USTs and recover all residual liquid; " After piping has been steam cleaned, pressure grout the remnant underground piping associated with the out5of5service USTs; and " Decommission existing underground piping associated with the active No. 2 fuel oil USTs. Residual fuel oil should be collected, then piping should be steam cleaned and pressure grouted. Underground piping should be replaced with aboveground piping. Upon completion of this task, NYSDEC PBS registration should be updated to reflect the changes. 9/2/2011- Left message for Mike Burke."
Remarks:	"FUEL OIL SEEPING IN FROM ANNULAR SPACE AROUND ABONDONED PIPES, CLEANUP UNDERWAY, ABSORBENT PADS BEING USED AT THIS TIME."

NYU CENTRAL PLANT (Continued) **1001493678**

All Materials:
Site ID: 423172
Operable Unit ID: 1178985
Operable Unit: 01
Material ID: 2172510
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

US AIRS (AFS):
Envid: 1001493678
Region Code: 02
County Code: NY061
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
D and B Number: Not reported
Facility Site Name: NYU CENTRAL PLANT
Primary SIC Code: 8221
NAICS Code: 611310
Default Air Classification Code: MAJ
Facility Type of Ownership Code: Not reported
Air CMS Category Code: TVM
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Federally-Enforceable State Operating Permit - Non Title V
Activity Date: 1990-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-07-24 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246

NYU CENTRAL PLANT (Continued) **1001493678**

Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-10-30 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 14:07:42
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-05-07 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-07-27 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-10-16 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-10-21 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:02:20
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-04-26 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-05-06 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2016-05-11 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-06-15 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-08-31 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2000-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2001-01-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2001-04-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-01-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-02-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-10-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-05-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-04-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-06-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-04-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-04-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-06-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-06-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-10-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-11-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-01-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-05-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2011-08-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-05-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-09-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-10-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-01-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-04-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-10-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2014-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Not defined as federally-reportable
Activity Date: Not reported
Activity Status Date: 2000-09-29 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Not defined as federally-reportable
Activity Date: 2000-09-29 00:00:00
Activity Status Date: 2000-09-29 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Not defined as federally-reportable
Activity Date: 1998-06-03 00:00:00
Activity Status Date: 1998-06-03 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Operating Permits
Activity Date: 2016-06-28 00:00:00
Activity Status Date: 2016-06-29 07:35:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-07-24 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-10-30 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 14:07:42
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-05-07 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-07-27 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-10-16 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-10-21 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:02:20
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2016-04-26 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-05-06 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-05-11 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-06-15 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-08-31 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2000-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2001-01-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2001-04-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-01-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-02-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2003-10-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-05-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-04-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-06-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2007-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2007-04-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2007-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2007-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-04-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-06-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-06-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2009-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2009-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2009-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2009-10-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-11-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2011-01-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2011-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2011-05-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2011-08-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2011-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-05-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-09-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-10-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-01-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-04-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-10-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2014-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: Not reported
Activity Status Date: 2000-09-29 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-07-24 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-10-30 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 14:07:42
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-05-07 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-07-27 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-10-16 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-10-21 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:02:20
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-26 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2016-05-06 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-05-11 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-06-15 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-08-31 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-01-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-04-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-01-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-02-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-10-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-05-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-04-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-06-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-04-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2007-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-04-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-06-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-06-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-10-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-11-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-01-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2011-05-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-08-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-05-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-09-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-10-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-01-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-04-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-10-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2014-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-09-29 00:00:00
Activity Status Date: 2000-09-29 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-06-03 00:00:00
Activity Status Date: 1998-06-03 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-04-27 00:00:00
Activity Status Date: 2001-04-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-07-24 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-10-30 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 14:07:42
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-05-07 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-07-27 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-10-16 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-10-21 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:02:20
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2016-04-26 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-05-06 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-05-11 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-06-15 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-08-31 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2000-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2001-01-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2001-04-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-01-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-02-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2003-10-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-05-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-04-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-06-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-04-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2007-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-04-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-06-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-06-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-10-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-11-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2011-01-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2011-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2011-05-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2011-08-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2011-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-05-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-09-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-10-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-01-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-04-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-10-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2014-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-07-24 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-10-30 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-01-23 00:00:00
Activity Status Date: 2016-05-02 14:07:42
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-05-07 00:00:00
Activity Status Date: 2016-05-02 13:21:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-07-27 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-10-16 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-10-21 00:00:00
Activity Status Date: 2016-05-02 13:21:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-01-29 00:00:00
Activity Status Date: 2016-06-09 07:02:20
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-02-29 00:00:00
Activity Status Date: 2016-06-09 07:01:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-26 00:00:00
Activity Status Date: 2016-06-09 07:01:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-05-06 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2016-05-11 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-06-15 00:00:00
Activity Status Date: 2016-07-09 11:05:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-08-31 00:00:00
Activity Status Date: 2016-09-09 07:16:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1998-03-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1998-12-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2001-01-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2001-04-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-01-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-02-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2003-10-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-05-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-04-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-06-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-04-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2007-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-04-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-06-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-06-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-10-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-11-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-01-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2011-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-05-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-08-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-11-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-05-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453

NYU CENTRAL PLANT (Continued) **1001493678**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-05-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-09-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-10-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-01-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-04-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-10-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-01-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYU CENTRAL PLANT (Continued) **1001493678**

Activity Date: 2014-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-04-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002620500246
Facility Registry ID: 110001603453
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-07-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

AIRS:
Permit Type: ATV
Permit Status: Issued
Issue Date: 09/29/2015
Expiration Date: 09/28/2020
County Fips: Not reported
DEC Id: 2620500246
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: Not reported
Unit: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Auth Type Code: 2
Latitude: 73.995798923
Longitude: 40.729368375

Permit Type: ATV
Permit Status: Issued
Issue Date: 01/23/2018
Expiration Date: 09/28/2020
County Fips: Not reported
DEC Id: 2620500246
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: Not reported
Unit: Not reported
Auth Type Code: 2
Latitude: 73.995798923
Longitude: 40.729368375

Permit Type: ATV
Permit Status: Expired
Issue Date: 01/19/2010
Expiration Date: 01/18/2015
County Fips: Not reported
DEC Id: 2620500246
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: Not reported
Unit: Not reported
Auth Type Code: 7
Latitude: 73.995798923
Longitude: 40.729368375

Permit Type: ATV
Permit Status: Expired
Issue Date: 01/22/2001
Expiration Date: 01/21/2006
County Fips: Not reported
DEC Id: 2620500246
Emission Unit Id: Not reported
Process Id: Not reported
Contaminant Name/cas: Not reported
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: Not reported
Unit: Not reported
Auth Type Code: 7
Latitude: 73.995798923
Longitude: 40.729368375

Permit Type: Not reported
Permit Status: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	PM25-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	1.10562994
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	PM25-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.54812305
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	001FP
Contaminant Name/cas:	PM25-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.71255644
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI

NYU CENTRAL PLANT (Continued) **1001493678**

Contaminant Name/cas:	PM25-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.47728948
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	7440417
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0035
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7440417
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.003
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	PM10-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	1.105625
Unit:	TON
Auth Type Code:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: NH3
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 143.389999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 86737
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0008
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 7782492
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.007
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	218019
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.36000001
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	107028
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	1.87999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	83329
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0005
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	VOC

NYU CENTRAL PLANT (Continued) **1001493678**

Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	9.2744199
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	75070
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	6.01999998
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	CO
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	12.2908349
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	85018
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0033
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	85018
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	9.75
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	50000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	18.8600006
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	PM-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	11.9521796
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	56553
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.14
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	191242
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.12999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	120127
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.28999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	86737
Epa Control Code:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Contol Eff:	Not reported
Emissions:	3.05999994
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	7439921
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.14
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	7440417
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0034
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7440439
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E01EI
Contaminant Name/cas: 7439965
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: 50328
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.05999999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: 108883
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 67.1900024
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246

NYU CENTRAL PLANT (Continued) **1001493678**

Emission Unit Id: 100000
Process Id: E01EI
Contaminant Name/cas: 7440020
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: NOX
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 16.6935
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: 7439976
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E01EI
Contaminant Name/cas: SO2
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 16.5855097

NYU CENTRAL PLANT (Continued) **1001493678**

Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7440484
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	PM10-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	1.47602502
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	50000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	14.75
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	120127
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0007
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7439976
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	7439965
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000

NYU CENTRAL PLANT (Continued) **1001493678**

Process Id: E02EI
Contaminant Name/cas: 191242
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0004
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E01EI
Contaminant Name/cas: 7440360
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: 1330207
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 46.1399993
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: SO2
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 24.1501992
Unit: TON

NYU CENTRAL PLANT (Continued) **1001493678**

Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	91203
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	31.0799999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	71432
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	185.550003
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	CO
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	101.622132
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	207089
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.05
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	205992
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.25999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	200000
Process Id:	003FP
Contaminant Name/cas:	129000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.87999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI

NYU CENTRAL PLANT (Continued) **1001493678**

Contaminant Name/cas: SO2
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.08779
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: NOX
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 22.826
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 91203
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.11999999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: NOX
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 139.427
Unit: TON
Auth Type Code: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: 83329
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1.11000001
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 200000
Process Id: 003FP
Contaminant Name/cas: 206440
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.95999997
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 7439965
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.10999999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7782492
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.02
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	7440360
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	56553
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0004
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	108883

NYU CENTRAL PLANT (Continued) **1001493678**

Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.66000002
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E01EI
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.382945
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 71432
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.40999999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 50328
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0002
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	NH3
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	563.409973
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	CO
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	1.76067004
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	NH3
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	647.020019
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	7440439
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	7440439
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.31999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	7439976
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.07
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	50000
Epa Control Code:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Contol Eff: Not reported
Emissions: 29.9300003
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 7440382
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.05
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 7440020
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.61000001
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 218019
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0004
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 206440
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0009
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E01EI
Contaminant Name/cas: PM10-PRI
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 1.28528002
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 207089
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0004
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246

NYU CENTRAL PLANT (Continued) **1001493678**

Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: CO
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 2.02196496
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: 7782492
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.02999999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: 7440484
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: E02EI
Contaminant Name/cas: 7440484
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.02

NYU CENTRAL PLANT (Continued) **1001493678**

Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	7440473
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.4
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	205992
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0005
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	110543
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	354.070007
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported

NYU CENTRAL PLANT (Continued) **1001493678**

Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7440473
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E01EI
Contaminant Name/cas:	7440382
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	E02EI
Contaminant Name/cas:	129000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0015
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000

NYU CENTRAL PLANT (Continued) **1001493678**

Process Id: E01EI
Contaminant Name/cas: NOX
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 19.283
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: VOC
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.43977499
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: 7440020
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36061
DEC Id: 2620500246
Emission Unit Id: 100000
Process Id: 002FP
Contaminant Name/cas: 50000
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 34.3699989
Unit: LB

NYU CENTRAL PLANT (Continued) **1001493678**

Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	SO2
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	19.0469296
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	7440473
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36061
DEC Id:	2620500246
Emission Unit Id:	100000
Process Id:	002FP
Contaminant Name/cas:	7440382
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

R313 **CENTRAL HEATING PLANT** **NY UST** **U000393713**
WNW **251 MERCER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.133 mi.
701 ft. **Site 5 of 6 in cluster R**

Relative:
Lower

Actual:
37 ft.

UST:

Id/Status:	2-043982 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	12/02/2021
UTM X:	584856.77895
UTM Y:	4509110.80529
Site Type:	School

Affiliation Records:

Site Id:	439
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	MELISA PUGLISIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 484-0561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-09

Site Id:	439
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	ASST DIRECTOR
Contact Name:	STEPAHNE KUNG
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-09

Site Id:	439
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL HEALTH & SAFETY
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY

CENTRAL HEATING PLANT (Continued) **U000393713**

Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-09

Site Id:	439
Affiliation Type:	Facility Operator
Company Name:	CENTRAL HEATING PLANT
Contact Type:	Not reported
Contact Name:	BRIAN MCGULLAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3424
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AYLAGATI
Date Last Modified:	2017-07-28

Tank Info:

Tank Number:	001
Tank ID:	1198
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	06/01/1964
Date Tank Closed:	12/12/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped

CENTRAL HEATING PLANT (Continued) **U000393713**

J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	002
Tank ID:	1199
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	30000
Install Date:	06/01/1964
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	11/19/2015
Next Test Date:	11/19/2016
Pipe Model:	Not reported
Modified By:	TLYE
Last Modified:	02/01/2018

Equipment Records:

B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	003
Tank ID:	1200
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	28500
Install Date:	06/01/1964
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	04/21/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JAAVERSA
Last Modified:	05/16/2017

Equipment Records:

CENTRAL HEATING PLANT (Continued) **U000393713**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
B08 - Tank External Protection - Retrofitted Impressed Current
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
F08 - Pipe External Protection - Retrofitted Impressed Current
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Number: 004
Tank ID: 1201
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 28500
Install Date: 06/01/1964
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 04/22/2014
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JAAVERSA
Last Modified: 05/16/2017

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
B08 - Tank External Protection - Retrofitted Impressed Current
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
F08 - Pipe External Protection - Retrofitted Impressed Current

Tank Number: 005
Tank ID: 58068
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: 01/01/1963
Date Tank Closed: 10/01/2001
Registered: True
Tank Location: Underground

CENTRAL HEATING PLANT (Continued) **U000393713**

Tank Type: Steel/carbon steel
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 007
Tank ID: 63294
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1080
Install Date: 04/01/2002
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TLYE
Last Modified: 04/24/2017

Equipment Records:

H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle

CENTRAL HEATING PLANT (Continued) **U000393713**

Affiliation Records:

Site Id:	21453
Affiliation Type:	Facility Operator
Company Name:	CENTRAL HEATING PLANT
Contact Type:	Not reported
Contact Name:	BRIAN MCGULLAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-02-10

Site Id:	21453
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	STEPHANIE KUNG
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Site Id:	21453
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	ASSISTANT DIRECTOR
Contact Name:	STEPHANIE KUNG
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-11-29

Site Id:	21453
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	MELISA PUGLISI

CENTRAL HEATING PLANT (Continued) **U000393713**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 484-0561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Tank Info:

Tank Number:	001
Tank ID:	1198
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	06/01/1964
Date Tank Closed:	12/12/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	002
Tank ID:	1199
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	30000
Install Date:	06/01/1964
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

CENTRAL HEATING PLANT (Continued) **U000393713**

Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 11/19/2015
Next Test Date: 11/19/2016
Pipe Model: Not reported
Modified By: TLYE
Last Modified: 02/01/2018

Equipment Records:

B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 003
Tank ID: 1200
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 28500
Install Date: 06/01/1964
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 04/21/2014
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JAAVERSA
Last Modified: 05/16/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
B08 - Tank External Protection - Retrofitted Impressed Current
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
F08 - Pipe External Protection - Retrofitted Impressed Current
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

CENTRAL HEATING PLANT (Continued) **U000393713**

Tank Number:	004
Tank ID:	1201
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	28500
Install Date:	06/01/1964
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	04/22/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JAAVERSA
Last Modified:	05/16/2017

Equipment Records:

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
B08 - Tank External Protection - Retrofitted Impressed Current
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
F08 - Pipe External Protection - Retrofitted Impressed Current

Tank Number:	005
Tank ID:	58068
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	01/01/1963
Date Tank Closed:	10/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground

CENTRAL HEATING PLANT (Continued) **U000393713**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	007
Tank ID:	63294
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1080
Install Date:	04/01/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TLYE
Last Modified:	04/24/2017

Equipment Records:

H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle

R314 **CENTRAL HEATING PLANT** **NY AST** **U000411268**
WNW **251 MERCER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.133 mi.
701 ft. **Site 6 of 6 in cluster R**

Relative: **Lower**
Actual: **37 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-480614
Program Type:	PBS
UTM X:	584856.77895
UTM Y:	4509110.80529
Expiration Date:	N/A

CENTRAL HEATING PLANT (Continued) **U000411268**

Site Type: School

Affiliation Records:

Site Id: 21453
Affiliation Type: Facility Operator
Company Name: CENTRAL HEATING PLANT
Contact Type: Not reported
Contact Name: BRIAN MCGULLAM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 995-3434
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-02-10

Site Id: 21453
Affiliation Type: Mail Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: STEPHANIE KUNG
Address1: 10 ASTOR PLACE
Address2: 6TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 998-1450
EMail: STEPHANIE.KUNG@NYU.EDU
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2017-11-16

Site Id: 21453
Affiliation Type: Facility Owner
Company Name: NEW YORK UNIVERSITY
Contact Type: ASSISTANT DIRECTOR
Contact Name: STEPHANIE KUNG
Address1: 70 WASHINGTON SQUARE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 998-1212
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-11-29

Site Id: 21453
Affiliation Type: Emergency Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported

CENTRAL HEATING PLANT (Continued) **U000411268**

Contact Name:	MELISA PUGLISI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 484-0561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Tank Info:

Tank Number:	006
Tank Id:	60668
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2002
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TLYE
Last Modified:	04/24/2017
Material Name:	waste oil/used oil

Tank Number:	008
Tank Id:	64130
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

CENTRAL HEATING PLANT (Continued) **U000411268**

I01 - Overfill - Float Vent Valve
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/2002
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TLYE
Last Modified:	04/24/2017
Material Name:	waste oil/used oil

Tank Number:	009
Tank Id:	64131
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/2002
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TLYE
Last Modified:	04/24/2017
Material Name:	waste oil/used oil

Tank Number:	010
Tank Id:	234475
Material Code:	0013

CENTRAL HEATING PLANT (Continued) **U000411268**

Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2003
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 04/24/2017
Material Name: lube oil

Tank Number: 011
Tank Id: 234476
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
B02 - Tank External Protection - Original Sacrificial Anode
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2002
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported

CENTRAL HEATING PLANT (Continued) **U000411268**

Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 04/24/2017
Material Name: waste oil/used oil

Tank Number: 012
Tank Id: 274717

Equipment Records:
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/2010
Capacity Gallons: 1000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 01/02/2018
Material Name: waste oil/used oil

Tank Number: 012
Tank Id: 266752

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J07 - Dispenser - Loading Rack/Transfer Pump
E00 - Piping Secondary Containment - None
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed

CENTRAL HEATING PLANT (Continued) **U000411268**

Pipe Model: Not reported
Install Date: 06/01/2010
Capacity Gallons: 1000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/06/2017
Register: True
Modified By: TLYE
Last Modified: 01/02/2018
Material Name: waste oil/used oil

Affiliation Records:
Site Id: 439
Affiliation Type: Emergency Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: MELISA PUGLISIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 484-0561
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-01-09

Site Id: 439
Affiliation Type: Facility Owner
Company Name: NEW YORK UNIVERSITY
Contact Type: ASST DIRECTOR
Contact Name: STEPAHNE KUNG
Address1: 70 WASHINGTON SQUARE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 998-1212
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-01-09

Site Id: 439
Affiliation Type: Mail Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: ENVIRONMENTAL HEALTH & SAFETY
Address1: 10 ASTOR PLACE
Address2: 6TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10003

CENTRAL HEATING PLANT (Continued) **U000411268**

Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-09

Site Id:	439
Affiliation Type:	Facility Operator
Company Name:	CENTRAL HEATING PLANT
Contact Type:	Not reported
Contact Name:	BRIAN MCGULLAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3424
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AYLAGATI
Date Last Modified:	2017-07-28

Tank Info:

Tank Number:	006
Tank Id:	60668
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/2002
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TLYE
Last Modified:	04/24/2017

CENTRAL HEATING PLANT (Continued) **U000411268**

Material Name: waste oil/used oil

Tank Number: 008
Tank Id: 64130
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 08/01/2002
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 04/24/2017
Material Name: waste oil/used oil

Tank Number: 009
Tank Id: 64131
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 08/01/2002
Capacity Gallons: 275
Tightness Test Method: -

CENTRAL HEATING PLANT (Continued) **U000411268**

Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 04/24/2017
Material Name: waste oil/used oil

Tank Number: 010
Tank Id: 234475
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2003
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 04/24/2017
Material Name: lube oil

Tank Number: 011
Tank Id: 234476
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
B02 - Tank External Protection - Original Sacrificial Anode
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

CENTRAL HEATING PLANT (Continued) **U000411268**

D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/2002
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 04/24/2017
Material Name: waste oil/used oil

Tank Number: 012
Tank Id: 274717

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/2010
Capacity Gallons: 1000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TLYE
Last Modified: 01/02/2018
Material Name: waste oil/used oil

Tank Number: 012
Tank Id: 266752

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

CENTRAL HEATING PLANT (Continued) **U000411268**

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J07 - Dispenser - Loading Rack/Transfer Pump
E00 - Piping Secondary Containment - None
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/2010
Capacity Gallons:	1000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/06/2017
Register:	True
Modified By:	TLYE
Last Modified:	01/02/2018
Material Name:	waste oil/used oil

O315 **CON EDISON SERVICE BOX: 37938** **RCRA NonGen / NLR** **1016968962**
NNE **429 LAFAYETTE ST** **NY MANIFEST** **NYP004426011**
1/8-1/4 **NEW YORK, NY 10003**
0.133 mi.
702 ft. **Site 13 of 23 in cluster O**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/26/2014
Facility name:	CON EDISON SERVICE BOX: 37938
Facility address:	429 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004426011
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON SERVICE BOX: 37938 (Continued) **1016968962**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/26/2014
Site name: CON EDISON SERVICE BOX: 37938
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004426011
Facility Status: Not reported
Location Address 1: F/O 429 LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004426011
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 01/26/2014
Trans1 Recv Date: 01/26/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/27/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004426011
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON SERVICE BOX: 37938 (Continued) **1016968962**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328759GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

L316 **CON EDISON** **NY MANIFEST** **S118463794**
North **717 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY**
0.134 mi.
706 ft. **Site 14 of 16 in cluster L**

Relative: **Lower**

Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004857199
Facility Status:	Not reported
Location Address 1:	717 BROADWAY
Code:	BP
Location Address 2:	SB 28818
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004857199

CON EDISON (Continued) **S118463794**

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/2015
Trans1 Recv Date:	10/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004857199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085732JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S118463794**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

L317 **NYU WASHINGTON SQUARE CAMPUS** **NY AST** **A100452219**
North **715 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.135 mi.
711 ft. **Site 15 of 16 in cluster L**

Relative:
Lower

Actual:
40 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-611130
Program Type: PBS
UTM X: 584970.96475
UTM Y: 4509184.94244
Expiration Date: N/A
Site Type: School

Affiliation Records:
Site Id: 416649
Affiliation Type: Facility Owner
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: Not reported
Address1: 70 WASHINGTON SQUARE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 998-1450
EMail: Not reported
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2016-05-19

Site Id: 416649
Affiliation Type: Facility Operator
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: NYU PUBLIC SAFETY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 998-2222
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-02-15

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

Site Id:	416649
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	NYU PUBLIC SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 998-2222
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-02-15

Site Id:	416649
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	STEPHANIE KUNG
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Tank Info:

Tank Number:	110 E 14TH
Tank Id:	229531
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	07/02/1998
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	110 W 3RD 1
Tank Id:	229528
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	10/29/2008
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	110 W 3RD 2
Tank Id:	229529
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	10/29/2008
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	140 E 14TH
Tank Id:	229530
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/24/2001
Capacity Gallons:	800
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

Material Name: diesel

Tank Number: 230SULLIVAN
Tank Id: 230257
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 01/01/1998
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/28/2016
Register: True
Modified By: MXLAY
Last Modified: 04/14/2017
Material Name: #4 fuel oil (on-site consumption)

Tank Number: 4 WSN1
Tank Id: 230255
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

Pipe Model: Not reported
Install Date: 02/01/1954
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/28/2016
Register: True
Modified By: MXLAY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 4 WSN2
Tank Id: 230256
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 02/01/1954
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/28/2016
Register: True
Modified By: MXLAY
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 70 WSS 1
Tank Id: 229526
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
I05 - Overfill - Vent Whistle

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/27/1993
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/15/2011
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 70 WSS 2
Tank Id: 229527
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/27/1993
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/15/2011
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

Material Name: diesel

Tank Number: 70WSS3
Tank Id: 238643
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 01/15/2011
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/28/2016
Register: True
Modified By: MXLAY
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 70WSS4
Tank Id: 238644
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

G10 - Tank Secondary Containment - Impervious Underlayment

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/15/2011
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	715 BWY 1
Tank Id:	229524
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/15/1999
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	715 BWY 2
Tank Id:	229525
Material Code:	0008
Common Name of Substance:	Diesel

NYU WASHINGTON SQUARE CAMPUS (Continued) **A100452219**

Equipment Records:

L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/15/1999
Capacity Gallons:	25
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/28/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel

L318 **NYU TISCH SCHOOL OF THE ARTS** **RCRA NonGen / NLR** **1001090301**
North **721-725 BROADWAY** **FINDS** **NYR000021386**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.136 mi. **NY MANIFEST**
718 ft. **Site 16 of 16 in cluster L**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYU TISCH SCHOOL OF THE ARTS
Facility address:	721-725 BROADWAY NEW YORK, NY 10003-6807
EPA ID:	NYR000021386
Mailing address:	FIRST AVE SVCS DEPT C117 C-O NYUMC ENVIRONMENTAL NEW YORK, NY 10016
Contact:	Not reported
Contact address:	FIRST AVE SVCS DEPT C117 NEW YORK, NY 10016
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	70 WASHINGOTN SQ S NEW YORK, NY 10012

NYU TISCH SCHOOL OF THE ARTS (Continued) **1001090301**

Owner/operator country: US
Owner/operator telephone: 212-998-1200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: 70 WASHINGOTN SQ S
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-998-1200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYU TISCH SCHOOL OF THE ARTS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYU TISCH SCHOOL OF THE ARTS
Classification: Not a generator, verified

Date form received by agency: 03/21/1996
Site name: NYU TISCH SCHOOL OF THE ARTS
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

NYU TISCH SCHOOL OF THE ARTS (Continued) **1001090301**

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004523347

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001090301
Registry ID: 110004523347
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004523347

NY MANIFEST:
Country: USA
EPA ID: NYR000021386
Facility Status: Not reported
Location Address 1: 721-725 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000021386
Mailing Name: NYU TISCH SCHOOL OF THE ARTS
Mailing Contact: NEW YORK UNIVERSITY
Mailing Address 1: 10 ASTOR PL 6TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014

NYU TISCH SCHOOL OF THE ARTS (Continued) **1001090301**

Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	09/08/2014
Trans1 Recv Date:	09/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000021386
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	006917140FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	65
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

U319 **SPILL NUMBER 0000672** **NY LTANKS** **U000402147**
West **77 BLEECKER ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.136 mi.
718 ft. **Site 1 of 10 in cluster U**

Relative: **Lower**

Actual: **37 ft.**

LTANKS:

Facility ID:	0000672
Site ID:	86275
Closed Date:	2004-04-26
Spill Number:	0000672
Spill Date:	2000-04-17
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2000-04-17
CID:	233
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-17
Spill Record Last Update:	2004-04-26
Spiller Name:	JIM FLAHERTY
Spiller Company:	Not reported
Spiller Address:	77 BLEECKER ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	79183
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 8/06/2002 TANK IS ABOVE GROUND AS PER CONVERSATION WITH REAL ESTATE PERSON, HE WILL SEND PHOTOS TO SHOW THAT THE TANK AND AUXILLARY PIPING DID NOT LEAK. 4/11/03MT reminder sent to send documentation to DEC 4/12/04 MT UPDATING/// SECOND REMINDER SENT//RETURN RECEIPT REQUEST 4/19/04 will send a copy of correspondance that isn't in DEC file 4/26/04 tank is ast, copies of photos submitted, no further action necessary ."
Remarks:	"tank in basment tank failed test property manager has been advised retest will be done "

All TTF:

Facility ID:	0000672
Spill Number:	0000672
Spill Tank Test:	1525498
Site ID:	86275
Tank Number:	1
Tank Size:	3500
Material:	0001
EPA UST:	Not reported
UST:	Not reported

SPILL NUMBER 0000672 (Continued) **U000402147**

Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	86275
Operable Unit ID:	822342
Operable Unit:	01
Material ID:	288912
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

U320 **CON EDISON** **NY MANIFEST** **S116044253**
West **F/O 377 BLEEKER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.136 mi.
718 ft. **Site 2 of 10 in cluster U**

Relative: **Lower**

Actual: **37 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004406484
Facility Status:	Not reported
Location Address 1:	F/O 377 BLEEKER ST
Code:	BP
Location Address 2:	SB26483
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004406484
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

CON EDISON (Continued) **S116044253**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/16/2013
Trans1 Recv Date:	12/16/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/18/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004406484
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299741GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

U321 **77 BLEECKER ST CORP** **NY AST** **A100292729**
West **77 BLEECKER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.136 mi.
718 ft. **Site 3 of 10 in cluster U**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-202584
Program Type:	PBS
UTM X:	584773.08245
UTM Y:	4508920.01604
Expiration Date:	11/20/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6945
Affiliation Type:	Facility Owner
Company Name:	77 BLEEKER ST CORP
Contact Type:	ASSISTANT SECRETARY
Contact Name:	JACOB SIROTKIN
Address1:	7 PENN PLAZA
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 560-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-09-15

Site Id:	6945
Affiliation Type:	Mail Contact
Company Name:	CENTURY MANAGMENT SERVICES
Contact Type:	Not reported
Contact Name:	JACOB SIROTKIN
Address1:	440 NINTH AVENUE, 15TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 560-6475
EMail:	JSIROTKIN@CENTURYNY.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-09-15

Site Id:	6945
Affiliation Type:	Facility Operator
Company Name:	77 BLEECKER ST CORP
Contact Type:	Not reported
Contact Name:	BENJAMIN DEHART
Address1:	Not reported
Address2:	Not reported
City:	Not reported

77 BLEECKER ST CORP (Continued) **A100292729**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 473-1839
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-09-15

Site Id: 6945
Affiliation Type: Emergency Contact
Company Name: 77 BLEEKER ST CORP
Contact Type: Not reported
Contact Name: JACOB SIROTKIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 560-6475
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-09-15

Tank Info:

Tank Number: 001
Tank Id: 16976
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
J01 - Dispenser - Pressurized Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K02 - Spill Prevention - Transfer Station Containment
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
A02 - Tank Internal Protection - Rubber Liner
F99 - Pipe External Protection - Other
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
B99 - Tank External Protection - Other

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1979
Capacity Gallons: 3500
Tightness Test Method: 21
Date Test: 05/01/2000

77 BLEECKER ST CORP (Continued) **A100292729**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	09/15/2017
Material Name:	#2 fuel oil (on-site consumption)

M322 **640 REALTY & 86 REALTY LLC-TIC** **NY AST** **A100292626**
WSW **640 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.137 mi.
725 ft. **Site 18 of 26 in cluster M**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609725
Program Type:	PBS
UTM X:	584801.61645
UTM Y:	4508873.46309
Expiration Date:	10/06/2014
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	331907
Affiliation Type:	Facility Owner
Company Name:	640 REALTY, LLC C/O 86 REALTY LLC - TIC
Contact Type:	V.P.
Contact Name:	MARK BRUCATO
Address1:	745 5TH AVE. SUITE 1250
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 873-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-08-11

Site Id:	331907
Affiliation Type:	Mail Contact
Company Name:	HELLER REALTY
Contact Type:	Not reported
Contact Name:	MARK BRUCATO
Address1:	745 FIFTH AVENUE
Address2:	SUITE 1250
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 873-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-12-09

640 REALTY & 86 REALTY LLC-TIC (Continued) **A100292626**

Site Id:	331907
Affiliation Type:	Facility Operator
Company Name:	640 REALTY, LLC
Contact Type:	Not reported
Contact Name:	RENATO VASQUEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 240-2463
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2004-10-06

Site Id:	331907
Affiliation Type:	Emergency Contact
Company Name:	640 REALTY, LLC C/O HELLER REALTY
Contact Type:	Not reported
Contact Name:	MARK BRUCATO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 873-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2004-10-06

Tank Info:

Tank Number:	001
Tank Id:	180328
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I01 - Overfill - Float Vent Valve
C01 - Pipe Location - Aboveground
A01 - Tank Internal Protection - Epoxy Liner
E12 - Piping Secondary Containment - Double-Walled (AG only)
J00 - Dispenser - None

Tank Location: 3

640 REALTY & 86 REALTY LLC-TIC (Continued) **A100292626**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1900
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

M323 **CON EDISON SERVICE BOX 26578** **RCRA NonGen / NLR** **1014926574**
WSW **640 BROADWAY FRONT OF** **NJ MANIFEST** **NYP004243499**
1/8-1/4 **NEW YORK, NY 10012** **NY MANIFEST**
0.137 mi.
725 ft. **Site 19 of 26 in cluster M**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:
Date form received by agency: 11/21/2011

Facility name:	CON EDISON SERVICE BOX 26578
Facility address:	640 BROADWAY FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004243499
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:
Date form received by agency: 10/22/2011

CON EDISON SERVICE BOX 26578 (Continued) **1014926574**

Site name: CON EDISON SERVICE BOX 26578
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004243499
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: BENJAMIN BAMONTE
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655422JJK
EPA ID: NYP004243499
Date Shipped: 10/22/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported

CON EDISON SERVICE BOX 26578 (Continued) **1014926574**

Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 250.00 Pounds

NY MANIFEST:
Country: USA
EPA ID: NYP004243499
Facility Status: Not reported
Location Address 1: F/O 690 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MANHATTAN
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004243499
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE ROOM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2011
Trans1 Recv Date: 10/22/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/24/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004243499
Trans1 EPA ID: Not reported

CON EDISON SERVICE BOX 26578 (Continued) **1014926574**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655422JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

N324 **CON EDISON SERVICE BOX: 26823** **RCRA NonGen / NLR** **1016148834**
SSE **307 BOWERY FRONT OF** **FINDS** **NYP004274858**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.138 mi. **NY MANIFEST**
726 ft. **Site 8 of 8 in cluster N**

Relative: **Higher**
Actual: **42 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26823
Facility address:	307 BOWERY FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004274858
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported

CON EDISON SERVICE BOX: 26823 (Continued) **1016148834**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/19/2012
Site name: CON EDISON SERVICE BOX: 26823
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055457045

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148834
Registry ID: 110055457045
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055457045

NY MANIFEST:
Country: USA
EPA ID: NYP004274858
Facility Status: Not reported
Location Address 1: F/O 307 BOWERY
Code: BP
Location Address 2: Not reported

CON EDISON SERVICE BOX: 26823 (Continued) **1016148834**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004274858
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2012
Trans1 Recv Date:	10/19/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004274858
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456411JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds

CON EDISON SERVICE BOX: 26823 (Continued) **1016148834**

Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O325 **APARTMENT COMPLEX** **NY LTANKS** **S102619272**
NNE **434 LAFAYETTE ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.138 mi.
728 ft. **Site 14 of 23 in cluster O**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	9514652
Site ID:	170205
Closed Date:	1996-12-30
Spill Number:	9514652
Spill Date:	1996-02-15
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	252
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	1997-01-06
Spiller Name:	PETER DARGAS
Spiller Company:	APARTMENT COMPLEX
Spiller Address:	434 LAFAYETTE ST
Spiller County:	001
Spiller Contact:	PETER DARGAS
Spiller Phone:	(212) 473-6109
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143216
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY "
Remarks:	"tank failure due to air test-small stain on wall-the whole line will be repaired tomorrow and contaminated soil clean up as well "

APARTMENT COMPLEX (Continued) **S102619272**

All Materials:

Site ID:	170205
Operable Unit ID:	1025759
Operable Unit:	01
Material ID:	354782
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M326 **CON EDISON** **NY MANIFEST** **S117067509**
WSW **BLEEKER ST & BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.138 mi.
729 ft. **Site 20 of 26 in cluster M**

Relative: **Lower**

Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004604450
Facility Status:	Not reported
Location Address 1:	BLEEKER ST & BROADWAY
Code:	BP
Location Address 2:	MH 39188
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004604450
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117067509**

TSD Site Recv Date:	07/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004604450
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504447GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M327 **CON EDISON** **NY MANIFEST** **S117318883**
WSW **BROADWAY & BLEEKER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.138 mi.
729 ft. **Site 21 of 26 in cluster M**

Relative: **Lower**
Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004664751
Facility Status:	Not reported
Location Address 1:	BROADWAY & BLEEKER ST
Code:	BP
Location Address 2:	SB59188
Total Tanks:	Not reported
Location City:	NEW YORK

CON EDISON (Continued) **S117318883**

Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004664751
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/23/2014
Trans1 Recv Date: 09/23/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004664751
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013243767JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117318883**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M328 **CON EDISON MANHOLE 57406** **RCRA NonGen / NLR** **1014918003**
WSW **BROADWAY & BLEEKER ST** **NJ MANIFEST** **NYP004215869**
1/8-1/4 **NEW YORK, NY 10008**
0.138 mi.
729 ft. **Site 22 of 26 in cluster M**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/18/2010
Facility name:	CON EDISON MANHOLE 57406
Facility address:	BROADWAY & BLEEKER ST NEW YORK, NY 10008
EPA ID:	NYP004215869
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	JEAN PIERRE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/18/2010
Site name:	CON EDISON MANHOLE 57406

CON EDISON MANHOLE 57406 (Continued) **1014918003**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004215869
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JEAN PIERRE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007656911JJK
EPA ID:	NYP004215869
Date Shipped:	09/18/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/18/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/20/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON MANHOLE 57406 (Continued) **1014918003**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 100 P

Q329 **C-SQUAREWOOD LLC** **RCRA NonGen / NLR** **1004761418**
NE **52-62 COOPER SQ** **FINDS** **NYR000086678**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.138 mi.
729 ft. **Site 14 of 18 in cluster Q**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: C-SQUAREWOOD LLC
Facility address: 52-62 COOPER SQ
NEW YORK, NY 10012
EPA ID: NYR000086678
Mailing address: WOOSTER ST
NEW YORK, NY 10012
Contact: JOHN CONNELY
Contact address: WOOSTER ST
NEW YORK, NY 10012
Contact country: US
Contact telephone: 646-602-9331
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: C-SQUAREWOOD LLC
Owner/operator address: 111 WOOSTER ST
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-219-1974
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: C-SQUAREWOOD LLC
Owner/operator address: 111 WOOSTER ST
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-219-1974

C-SQUAREWOOD LLC (Continued) **1004761418**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: C-SQUAREWOOD LLC
Classification: Not a generator, verified

Date form received by agency: 06/08/2000
Site name: C-SQUAREWOOD LLC
Classification: Small Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110004562483

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

C-SQUAREWOOD LLC (Continued) **1004761418**

Envid: 1004761418
Registry ID: 110004562483
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004562483

K330 **CON EDISON** **NJ MANIFEST** **S120667607**
SSW **315 MOTT ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.139 mi.
735 ft. **Site 23 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

NJ MANIFEST:
EPA Id: NYP004735361
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002610809GBF
EPA ID: NYP004735361
Date Shipped: 2/22/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported

CON EDISON (Continued) **S120667607**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K331 **CON EDISON** **NY MANIFEST** **S117740371**
SSW **315 MOTT ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.139 mi.
735 ft. **Site 24 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004735361
Facility Status:	Not reported
Location Address 1:	315 MOTT ST
Code:	BP
Location Address 2:	SB 41430
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004735361
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/22/2015
Trans1 Recv Date:	02/22/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	02/26/2015
Part A Recv Date:	Not reported

CON EDISON (Continued) **S117740371**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004735361
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610809GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

K332 **CON EDISON** **RCRA NonGen / NLR** **1018278755**
SSW **315 MOTT ST** **FINDS** **NYP004735361**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.139 mi.
735 ft. **Site 25 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/22/2015
Facility name:	CON EDISON
Facility address:	315 MOTT ST NEW YORK, NY 10012
EPA ID:	NYP004735361
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported

CON EDISON (Continued) **1018278755**

Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/22/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067680860

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278755
Registry ID: 110067680860
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067680860

U333 **CON ED - V 2708** **RCRA NonGen / NLR** **1007206224**
WSW **71 BLEEKER ST** **NY MANIFEST** **NYP004005997**
1/8-1/4 **NEW YORK, NY 10003**
0.141 mi.
743 ft. **Site 4 of 10 in cluster U**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/1998
Facility name:	CON ED - V 2708
Facility address:	71 BLEEKER ST NEW YORK, NY 10003-0000
EPA ID:	NYP004005997
Mailing address:	CONSOLIDATED EDISON INC 4 IRVING PL RM 300 NEW YORK, NY 10003-0000
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC NEW YORK, NY 10003-0000
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/27/1998
Site name:	CON ED - V 2708
Classification:	Not a generator, verified

Date form received by agency:	02/26/1998
Site name:	CON ED - V 2708
Classification:	Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004005997
Facility Status:	Not reported
Location Address 1:	TM 2708 - 71 BLEEKER ST
Code:	BP

CON ED - V 2708 (Continued) **1007206224**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004005997
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYB8468541
Manifest Status:	C
seq:	Not reported
Year:	1997
Trans1 State ID:	80416AB
Trans2 State ID:	Not reported
Generator Ship Date:	02/27/1997
Trans1 Recv Date:	02/27/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/28/1997
Part A Recv Date:	03/13/1997
Part B Recv Date:	03/11/1997
Generator EPA ID:	NYP004005997
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01788

CON ED - V 2708 (Continued) **1007206224**

Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country: USA
EPA ID: NYP004397378
Facility Status: Not reported
Location Address 1: F/O 71 BLEEKER ST
Code: BP
Location Address 2: SB2708
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10013
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004397378
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/24/2013
Trans1 Recv Date: 11/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/25/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004397378
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002237624GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N

CON ED - V 2708 (Continued) **1007206224**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

V334 **CON EDISON SERVICE BOX: 1085** **NJ MANIFEST** **S117986860**
ENE **216 E 6 ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.141 mi.
744 ft. **Site 1 of 15 in cluster V**

Relative: **Lower**

Actual: **39 ft.**

NJ MANIFEST:

EPA Id:	NYP004275640
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	RICARDO CARTY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456551JJK
EPA ID:	NYP004275640

CON EDISON SERVICE BOX: 1085 (Continued) **S117986860**

Date Shipped:	10/23/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

V335 **CON EDISON SERVICE BOX: 1085** **RCRA NonGen / NLR** **1016148913**
ENE **216 E 6 ST FRONT OF** **FINDS** **NYP004275640**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.141 mi. **NY MANIFEST**
744 ft. **Site 2 of 15 in cluster V**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 1085
Facility address:	216 E 6 ST FRONT OF

Actual:
39 ft.

CON EDISON SERVICE BOX: 1085 (Continued) **1016148913**

NEW YORK, NY 10003
EPA ID: NYP004275640
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: RICARDO CARTY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-643-3044
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/23/2012
Site name: CON EDISON SERVICE BOX: 1085
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055459178

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148913

CON EDISON SERVICE BOX: 1085 (Continued) **1016148913**

Registry ID: 110055459178
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055459178

NY MANIFEST:
Country: USA
EPA ID: NYP004275640
Facility Status: Not reported
Location Address 1: FO 216 E 6TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004275640
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/23/2012
Trans1 Recv Date: 10/23/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004275640
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010456551JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported

CON EDISON SERVICE BOX: 1085 (Continued) **1016148913**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

K336 **ELG MOTT STREET LLC** **NY UST** **U004251046**
SSW **LFG MOTT STREET, LLC** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
0.142 mi.
750 ft. **Site 26 of 26 in cluster K**

Relative:
Higher

Actual:
43 ft.

UST:

Id/Status:	2-249173 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/05/2022
UTM X:	584977.23683
UTM Y:	4508748.26460
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9884
Affiliation Type:	Facility Operator
Company Name:	ELG MOTT STREET LLC
Contact Type:	Not reported
Contact Name:	BENJAMIN GOLETIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 860-5081
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-31

ELG MOTT STREET LLC (Continued) **U004251046**

Site Id:	9884
Affiliation Type:	Emergency Contact
Company Name:	ELG MOTT STREET, LLC
Contact Type:	Not reported
Contact Name:	LOUISA LITTLE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 265-2280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-31

Site Id:	9884
Affiliation Type:	Mail Contact
Company Name:	LFG MOTT STREET LLC
Contact Type:	Not reported
Contact Name:	ELG MOTT STREET, LLC
Address1:	1185 SIXTH AVENUE
Address2:	10TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 265-2280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-31

Site Id:	9884
Affiliation Type:	Facility Owner
Company Name:	ELG MOTT STREET, LLC
Contact Type:	VICE PRESIDENT
Contact Name:	LOUISA LITTLE
Address1:	1185 SIXTH AVENUE, 10TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 265-2280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-31

Tank Info:

Tank Number:	001
Tank ID:	274169
Tank Status:	In Service
Material Name:	In Service

ELG MOTT STREET LLC (Continued) **U004251046**

Capacity Gallons:	1500
Install Date:	02/10/1958
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	MFLEONAR
Last Modified:	10/31/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
B05 - Tank External Protection - Jacketed
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

P337 **OUR LADY OF LORETO R.C. CHURCH** **NY UST** **U001834012**
South **309 ELIZABETH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.142 mi.
751 ft. **Site 2 of 12 in cluster P**

Relative: **Higher**

Actual: **43 ft.**

UST:

Id/Status:	2-246395 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	12/14/2012
UTM X:	585036.35125
UTM Y:	4508690.32433
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	9634
Affiliation Type:	Mail Contact
Company Name:	OUR LADY OF LORETO R.C. CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	309 ELIZABETH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-9840
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

OUR LADY OF LORETO R.C. CHURCH (Continued) **U001834012**

Date Last Modified: 2004-03-04

Site Id: 9634
Affiliation Type: Facility Operator
Company Name: OUR LADY OF LORETO R.C. CHURCH
Contact Type: Not reported
Contact Name: OUR LADY OF LORETO R.C. CHURCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 431-9840
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9634
Affiliation Type: Emergency Contact
Company Name: OUR LADY OF LORETO R.C. CHURCH
Contact Type: Not reported
Contact Name: CASTLE COAL & OIL CO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 823-8800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9634
Affiliation Type: Facility Owner
Company Name: OUR LADY OF LORETO R.C. CHURCH
Contact Type: PASTOR
Contact Name: JOHN AHERN
Address1: 309 ELIZABETH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 431-9840
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 2007-08-30

Tank Info:

Tank Number: 001
Tank ID: 10570

OUR LADY OF LORETO R.C. CHURCH (Continued) **U001834012**

Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1985
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	07/06/2007
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	BKFALVEY
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)

O338 **COMMERCIAL BUILDING** **NY LTANKS** **S109064210**
NNE **440 LAFAYETTE AVE** **N/A**
1/8-1/4 **NEW YORK, NY**
0.144 mi.
760 ft. **Site 15 of 23 in cluster O**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	0713774
Site ID:	395591
Closed Date:	2008-10-06
Spill Number:	0713774
Spill Date:	2008-03-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2008-03-28
CID:	404
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-28
Spill Record Last Update:	2008-10-06

COMMERCIAL BUILDING (Continued) **S109064210**

Spiller Name:	ANDERSON SANTOS
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	440 LAFAYETTE AVE
Spiller County:	001
Spiller Contact:	ANDERSON SANTOS
Spiller Phone:	(212) 505-0756
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	345115
DEC Memo:	"4/11/08 bf: Called Ken Bonal (212)431-5751 of Newmark & Company. He no longer works there according to receptionist. She instructed me to call Anderson Santos, Superintendent of the building cell:(917)288-6195 office: (212)505-0756. Left message on machine for him to call me. Sent ttf letter to: Anderson Santos, Superintendent 436 Lafayette Street New York, NY 10003 5/12/08 On 5/8/08, received message from Mike Tartanella, consultant (914)740-1963. Called him back today. Tank is AST in a vault and all piping is exposed. No visible leak was found. Could not determine cause of failure yet. Wanted to know iof second tightness test is required. I told him yes and tank will be retested. He has to inform client of this. Letter on the way to me explaining failure. Received letter from Michael Tatanella of IVI Due Diligence Services, Inc. bf 9/30/08 Received fax from Ray Lara of PTC. Fax was of sampling results. bf 10/1/08 Called Ray Lara. PTC did tank cleaning and had sampling done around tank. Tank was removed. I requested that he send a site plan of sampling. He will send site plan. Called Joe Bortolussi of Newmark Knight Frank (212)431-5751. Told him he needs to send closure application. He told me new tank was installed. I told him he needs to update registration to reflect new changes. He will have contractor (Ace Atlas) contact me regaring this. bf 10/6/08 Received fax from Ray Lara. Letter from John of Ace-Atlas. Tank failed with dry leak. Two dead lines connected to the tank. Tank failed again. Concrete wrapping is removed No oil found on tank in enclosure material or on floor. NFA. bf"
Remarks:	"gross problem"

All TTF:

Facility ID:	0713774
Spill Number:	0713774
Spill Tank Test:	2384925
Site ID:	395591
Tank Number:	Not reported
Tank Size:	12000
Material:	0003
EPA UST:	Not reported
UST:	True
Cause:	99
Source:	99
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	395591

COMMERCIAL BUILDING (Continued) **S109064210**

Operable Unit ID:	1152533
Operable Unit:	01
Material ID:	2143311
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O339 **CON EDISON MANHOLE 37930** **NJ MANIFEST** **S117985277**
NNE **436 LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.144 mi.
760 ft. **Site 16 of 23 in cluster O**

Relative: **Lower**

Actual: **40 ft.**

NJ MANIFEST:

EPA Id:	NYP004802914
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614581GBF
EPA ID:	NYP004802914
Date Shipped:	7/7/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON MANHOLE 37930 (Continued) **S117985277**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

EPA Id:	NYP004250254
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009204827JJK
EPA ID:	NYP004250254
Date Shipped:	3/22/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON MANHOLE 37930 (Continued) **S117985277**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

O340 **LAFAYETTE ASTOR ASSOCS.** **NY AST** **A100322496**
NNE **436-440 LAFAYETTE STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.144 mi.
760 ft. **Site 17 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-242527
Program Type:	PBS
UTM X:	585189.67468
UTM Y:	4509262.16789
Expiration Date:	01/07/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9294
Affiliation Type:	Facility Owner
Company Name:	LAFAYETTE ASTOR ASSOCS.
Contact Type:	OWNER'S REP
Contact Name:	ART D'ESTRADA
Address1:	594 BROADWAY - ROOM 311
Address2:	Not reported
City:	NEW YORK

LAFAYETTE ASTOR ASSOCS. (Continued) **A100322496**

State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 625-6203
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-11-08

Site Id: 9294
Affiliation Type: Facility Operator
Company Name: LAFAYETTE ASTOR ASSOCS.
Contact Type: Not reported
Contact Name: PAUL RUFO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 505-0756
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-11-08

Site Id: 9294
Affiliation Type: Emergency Contact
Company Name: LAFAYETTE ASTOR ASSOCS.
Contact Type: Not reported
Contact Name: PAUL RUFO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 288-6195
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-11-08

Site Id: 9294
Affiliation Type: Mail Contact
Company Name: NEWMARK FAMILY PROPERTIES, LLC
Contact Type: Not reported
Contact Name: ART D'ESTRADA
Address1: 594 BROADWAY
Address2: ROOM 311
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 625-6203
EMail: ADESTRADA@NGKF.COM
Fax Number: Not reported

LAFAYETTE ASTOR ASSOCS. (Continued) **A100322496**

Modified By: DAFRANCI
Date Last Modified: 2017-12-01

Tank Info:

Tank Number: 001
Tank Id: 25330
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A99 - Tank Internal Protection - Other
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1920
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/19/2008
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #6 fuel oil (on-site consumption)

Tank Number: 01A
Tank Id: 225808
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

LAFAYETTE ASTOR ASSOCS. (Continued) **A100322496**

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/15/2008
Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	11/08/2017
Material Name:	#2 fuel oil (on-site consumption)

O341 **CON EDISON** **NY MANIFEST** **S117537282**
NNE **F/O 436 LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.144 mi.
760 ft. **Site 18 of 23 in cluster O**

Relative: **Lower**

Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004698262
Facility Status:	Not reported
Location Address 1:	F/O 436 LAFAYETTE ST
Code:	BP
Location Address 2:	SB37930
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004698262
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/20/2014
Trans1 Recv Date:	11/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/24/2014

CON EDISON (Continued) **S117537282**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004698262
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002563326GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O342 **CON EDISON MANHOLE: 37930** **RCRA NonGen / NLR** **1016142965**
NNE **436 LAFFAYETTE AVE S OF ASTOR PL** **FINDS** **NYP004256947**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.144 mi. **NY MANIFEST**
760 ft. **Site 19 of 23 in cluster O**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	07/28/2017
Facility name:	CON EDISON MANHOLE: 37930
Facility address:	436 LAFFAYETTE AVE S OF ASTOR PL NEW YORK, NY 10012
EPA ID:	NYP004256947
Mailing address:	IRVING PL - ROOM 828 NEW YORK, NY 10003
Contact:	JOSE MONTALVO
Contact address:	Not reported

Actual:
40 ft.

CON EDISON MANHOLE: 37930 (Continued) **1016142965**

Not reported
Contact country: Not reported
Contact telephone: 212-427-1331
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/04/2012
Site name: CON EDISON MANHOLE: 37930
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055463797

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016142965
Registry ID: 110055463797
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055463797

NY MANIFEST:
Country: USA
EPA ID: NYP004256947

CON EDISON MANHOLE: 37930 (Continued) **1016142965**

Facility Status:	Not reported
Location Address 1:	F/O 436 LAFAYETTE ST S/O ASTOR PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004256947
Mailing Name:	CONSOLIDATED EDISON OF NY
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE FLOOR 15
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/04/2012
Trans1 Recv Date:	07/04/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004256947
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	009209637JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON MANHOLE: 37930 (Continued) **1016142965**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

O343 **CON EDISON MANHOLE 37930** **RCRA NonGen / NLR** **1015747024**
NNE **436 LAFAYETTE ST** **NY MANIFEST** **NYP004250254**
1/8-1/4 **NEW YORK, NY 10003**
0.144 mi.
760 ft. **Site 20 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/21/2012
Facility name:	CON EDISON MANHOLE 37930
Facility address:	436 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004250254
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	JUAN RODRIGUEZ
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-865-5931
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

CON EDISON MANHOLE 37930 (Continued) **1015747024**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/22/2012
Site name: CON EDISON MANHOLE 37930
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004250254
Facility Status: Not reported
Location Address 1: 436 LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004250254
Mailing Name: CONSOLIDATED EDISON - MH 37930
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/22/2012
Trans1 Recv Date: 03/22/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/22/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004250254
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 009204827JJK
Import Indicator: N
Export Indicator: N

CON EDISON MANHOLE 37930 (Continued) **1015747024**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYP004802914
Facility Status:	Not reported
Location Address 1:	436 LAFFAYETTE ST
Code:	BP
Location Address 2:	MH 37930
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004802914
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON MANHOLE 37930 (Continued) **1015747024**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2015
Trans1 Recv Date:	07/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004802914
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614581GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

O344 **CON EDISON MANHOLE: 37930** **NJ MANIFEST** **S117985307**
NNE **436 LAFFAYETTE AVE S OF ASTOR PL** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.144 mi.
760 ft. **Site 21 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYP004256947
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOSE MONTALVO
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009209637JJK
EPA ID:	NYP004256947
Date Shipped:	7/4/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON MANHOLE: 37930 (Continued) **S117985307**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 2,000.00 Pounds

O345 **CON EDISON - MANHOLE 37930** **RCRA-LQG** **1014395865**
NNE **436 LAFAYETTE ST AND ASTOR PL** **NY MANIFEST** **NYP004175162**
1/8-1/4 **NEW YORK, NY 10003** **NJ MANIFEST**
0.144 mi.
760 ft. **Site 22 of 23 in cluster O**

Relative:
Lower

Actual:
40 ft.

RCRA-LQG:
Date form received by agency: 03/23/2010
Facility name: CON EDISON - MANHOLE 37930
Facility address: 436 LAFAYETTE ST AND ASTOR PL
NEW YORK, NY 10003
EPA ID: NYP004175162
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported

CON EDISON - MANHOLE 37930 (Continued) **1014395865**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/19/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/19/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004175162
Facility Status: Not reported
Location Address 1: 436 LAFAYETTE ST AND ASTOR PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004175162
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON

CON EDISON - MANHOLE 37930 (Continued) **1014395865**

Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/2009
Trans1 Recv Date:	06/25/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/25/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004175162
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003532165JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	11250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON - MANHOLE 37930 (Continued) **1014395865**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYP004175162
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003532165JJK
EPA ID:	NYP004175162
Date Shipped:	06/25/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/25/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/25/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

CON EDISON - MANHOLE 37930 (Continued) **1014395865**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	11250 P

O346 **CON EDISON** **RCRA NonGen / NLR** **1019904852**
NNE **436 LAFAYETTE ST** **FINDS** **NYP004802914**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.144 mi.
760 ft. **Site 23 of 23 in cluster O**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/07/2015
Facility name:	CON EDISON
Facility address:	436 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004802914
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1019904852**

Historical Generators:
Date form received by agency: 07/07/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069658114

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019904852
Registry ID: 110069658114
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069658114

W347 **THE 62 COOPER SQUARE CONDOMINIUM** **NY AST** **A100301198**
NE **54-62 COOPER SQUARE** **N/A**
1/8-1/4 **NY, NY 10003**
0.144 mi.
760 ft. **Site 1 of 6 in cluster W**

Relative:
Lower

Actual:
41 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-600834
Program Type: PBS
UTM X: 585187.36499
UTM Y: 4509094.99091
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 22806
Affiliation Type: Mail Contact
Company Name: STARWOOD CAPITAL GROUP
Contact Type: Not reported
Contact Name: JEFFERY MORRIS
Address1: 591 WEST PUTNAM AVENUE
Address2: Not reported
City: GREENWICH
State: CT
Zip Code: 06830
Country Code: 001
Phone: (203) 422-7754

THE 62 COOPER SQUARE CONDOMINIUM (Continued) **A100301198**

EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2004-08-12

Site Id: 22806
Affiliation Type: Facility Operator
Company Name: THE 62 COOPER SQUARE CONDOMINIUM
Contact Type: Not reported
Contact Name: MONILAL MANIE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 699-7180
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2004-08-12

Site Id: 22806
Affiliation Type: Emergency Contact
Company Name: C-SQUAREWOOD LLC
Contact Type: Not reported
Contact Name: MICHAEL SCHENKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 529-5688
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2004-08-12

Site Id: 22806
Affiliation Type: Facility Owner
Company Name: C-SQUAREWOOD LLC
Contact Type: SENIOR VICE-PRESIDENT
Contact Name: JEFFERY MORRIS
Address1: 62 COOPER SQUARE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (203) 422-7754
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2004-08-12

THE 62 COOPER SQUARE CONDOMINIUM (Continued) **A100301198**

Tank Info:

Tank Number:	001
Tank Id:	44016
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle

Tank Location:	4
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1960
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/05/2000
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

P348 **303 ELIZABETH ST.** **NY LTANKS** **S100167435**
South **303 ELIZABETH ST.** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.144 mi.
761 ft. **Site 3 of 12 in cluster P**

Relative: **Higher**

Actual: **43 ft.**

LTANKS:

Facility ID:	8704231
Site ID:	270112
Closed Date:	1992-11-19
Spill Number:	8704231
Spill Date:	1987-08-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1992-11-19
SWIS:	3101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1987-08-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

303 ELIZABETH ST. (Continued) **S100167435**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-08-26
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	OUR LADY OF LORETTO
Spiller Address:	303 ELIZABETH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	219971
DEC Memo:	""
Remarks:	"TANK TEST FAILURE OF 3500 GALLON SYSTEM."

All TTF:

Facility ID:	8704231
Spill Number:	8704231
Spill Tank Test:	1531442
Site ID:	270112
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	270112
Operable Unit ID:	910714
Operable Unit:	01
Material ID:	466876
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	8705585
Site ID:	271130
Closed Date:	1992-11-16
Spill Number:	8705585
Spill Date:	1987-10-02

303 ELIZABETH ST. (Continued) **S100167435**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1992-11-16
SWIS:	3101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1987-10-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-05
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	OUR LADY OF LORETTA CHURC
Spiller Address:	303 ELIZABETH ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	220685
DEC Memo:	""
Remarks:	"3500 GAL. TANK SYSTEM FAILED HORNER EZY TEST, UNREADABLE RATES, WILL EXCAVATE AND INVESTIGATE FURTHER, PREVIOUSLY TESTED BY HAZCO."

All TTF:

Facility ID:	8705585
Spill Number:	8705585
Spill Tank Test:	1531804
Site ID:	271130
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	271130
Operable Unit ID:	909413
Operable Unit:	01
Material ID:	468176
Material Code:	0001A
Material Name:	#2 fuel oil

303 ELIZABETH ST. (Continued) **S100167435**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

M349 **OFFICE BUILDING** **NY LTANKS** **S102143793**
WSW **636 BROADWAY** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.145 mi.
766 ft. **Site 23 of 26 in cluster M**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	0413180
Site ID:	339041
Closed Date:	2006-05-04
Spill Number:	0413180
Spill Date:	2005-03-18
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2006-05-04
Spiller Name:	MARK SALAMACK
Spiller Company:	OFFICE BUILDING
Spiller Address:	215 PARK AVE. SOUTH
Spiller County:	001
Spiller Contact:	MARK SALAMACK
Spiller Phone:	(917) 559-5519
Spiller Extention:	CELL
DEC Region:	2
DER Facility ID:	89061
DEC Memo:	"PTC is working on the site 11/18/05- DEC Piper contacted PTC. PTC pressure washed concrete floor. No samples collected. Building manager as per PTC. Victor Treger 212. 254.7701. Placed cal into Victor. Left message. 3/15/06-Placed cal into Victor. Left message w/ secretary requesting callback 3/30/06- DECP iper mailed old csl letter to victor. 5/4/06- DEC Piper reviewed closure report. Small spill to concrete. Concrete exibited no cracks. Cleaned up. Closed."
Remarks:	"INSIDE BUILDING OIL PUMP IS SPITTING OIL:"

All Materials:

Site ID:	339041

OFFICE BUILDING (Continued) **S102143793**

Operable Unit ID:	1100959
Operable Unit:	01
Material ID:	581109
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9701173
Site ID:	100275
Closed Date:	1997-04-28
Spill Number:	9701173
Spill Date:	1997-04-25
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1997-04-26
CID:	201
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-26
Spill Record Last Update:	1997-05-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	VICTOR TRAGER
Spiller Phone:	(212) 254-7701
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	89061
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE ABC TANK TO CLEAN. DEP ON SCENE 30 GALLONS ON SIDEWALK 100 - 150 GALLONS IN TANK. CASTLE MADE A DELIVERY IN MORNING 12 HRS LATER SPILL NOTIFICATION BY FD HAZMAT. IT APPEARS THAT BLDNG WAS TRANSFERRING OIL FROM ONE TANK TO ANOTHER AND OVER FILLED UTANK. CLEANED BY RESPONSIBLE PARTY. UPDATED ON 5-22-97"
Remarks:	"OVER FILL OF FUEL TANK/CLEAN UP HAS NOT BEGUN AT THIS TIME"

All Materials:

Site ID:	100275
Operable Unit ID:	1043824
Operable Unit:	01
Material ID:	569567

OFFICE BUILDING (Continued) **S102143793**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9213082
Facility Type:	ER
Spill Number:	9213082
DER Facility ID:	280637
Site ID:	100274
DEC Region:	2
Closed Date:	1993-02-23
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	1993-02-23
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-02-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-02-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-24
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	GOTHAM PETRO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"BAD GAGE-CAME OUT FILL-CONTAINED ON SIDEWALK-CLEANUP IS DONE"

All Materials:

Site ID:	100274
Operable Unit ID:	980258
Operable Unit:	01
Material ID:	402895
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00

OFFICE BUILDING (Continued) **S102143793**

Oxygenate:	Not reported
Facility ID:	0800020
Facility Type:	ER
Spill Number:	0800020
DER Facility ID:	345227
Site ID:	395705
DEC Region:	2
Closed Date:	2008-04-01
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2008-04-01
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2008-04-01
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-01
Spill Record Last Update:	2008-04-01
Spiller Name:	VICTOR TRAGER- SUPER
Spiller Company:	APART
Spiller Address:	636 BROADWAY
Spiller Company:	001
Contact Name:	VICTOR TRAGER- SUPER
DEC Memo:	"Sangesland spoke to Steve King at Hess. He said 35 gal spilled in front of the building. Approx 5 gal stayed outside on the sidewalk, 30 gal went through a floor grate/door? into the basement floor. Petroleum Tank Cleaners is on site to do cleanup."
Remarks:	"FAULTY GAUGE ON TANK AND IS CONTAINED AND IN PROCESS OF CLEANING"

All Materials:

Site ID:	395705
Operable Unit ID:	1152647
Operable Unit:	01
Material ID:	2143426
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	35.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M350 **636 BROADWAY ASSOCIATES** **NY UST** **U004275634**
WSW **636 BROADWAY, SUITE 1008** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.145 mi.
766 ft. **Site 24 of 26 in cluster M**

Relative:
Lower

Actual:
40 ft.

UST:

Id/Status:	2-609099 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/15/2018
UTM X:	584790.83212
UTM Y:	4508856.35351
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30945
Affiliation Type:	Facility Owner
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	MANAGER
Contact Name:	VICTOR TRAGER
Address1:	636 BROADWAY, SUITE 1008
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 254-7701
EMail:	VICTOR@TRAGERUS.COM
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Site Id:	30945
Affiliation Type:	Mail Contact
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	MANAGER
Contact Name:	VICTOR TRAGER
Address1:	636 BROADWAY, SUITE 1008
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 254-7701
EMail:	VICTOR@TRAGERUS.COM
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Site Id:	30945
Affiliation Type:	Emergency Contact
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	Not reported
Contact Name:	JULIO OCASIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

636 BROADWAY ASSOCIATES (Continued) **U004275634**

Zip Code:	Not reported
Country Code:	999
Phone:	(646) 469-8824
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Site Id:	30945
Affiliation Type:	Facility Operator
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	Not reported
Contact Name:	JULIO OCASIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-7701
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Tank Info:

Tank Number:	001
Tank ID:	66399
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	01/01/1968
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	10/06/2017
Next Test Date:	10/06/2018
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	02/01/2018

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

636 BROADWAY ASSOCIATES (Continued) **U004275634**

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle

M351 **CON EDISON** **NY Spills** **S106722431**
WSW **636 BROADWAY** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.145 mi.
766 ft. **Site 25 of 26 in cluster M**

Relative: **Lower**
Actual: **40 ft.**

SPILLS:

Facility ID:	0408341
Facility Type:	ER
Spill Number:	0408341
DER Facility ID:	268289
Site ID:	333053
DEC Region:	2
Closed Date:	2005-03-17
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2004-10-28
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2004-10-28
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-28
Spill Record Last Update:	2005-03-17
Spiller Name:	VICTOR
Spiller Company:	Not reported
Spiller Address:	836 BROADWAY
Spiller Company:	001
Contact Name:	VICTOR
DEC Memo:	"11/24/2004 Anthony from PTC said there was a leak in the fill line at this address. The fill pipe ran in an old coal chute from the curb into the basement. The leaking line dripped down this chute and into a sidewalk vault. PTC cleaned the vault and replaced the fill line. No soil was impacted, all spilling was confined to the chute and the vault. PTC will send in a package to confirm what was said. 12/24/2005 - PTC submitted a letter & waste manifest outlining the remediation and line repair work done to close out the spill. 03/17/05 - Sawyer - No further action is necessary for this spill. Closed."
Remarks:	"Clean up in progress."

All Materials:

Site ID:	333053
Operable Unit ID:	1095235
Operable Unit:	01

CON EDISON (Continued) **S106722431**

Material ID: 575375
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYP004588554
Facility Status: Not reported
Location Address 1: 636 BROADWAY
Code: BP
Location Address 2: MH 59188
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004588554
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/08/2014
Trans1 Recv Date: 07/08/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004588554
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002423937GBF
Import Indicator: N

CON EDISON (Continued) **S106722431**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

M352 **636 BROADWAY ASSOCIATES** **NY AST** **A100292620**
WSW **636 BROADWAY, SUITE 1008** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.145 mi.
766 ft. **Site 26 of 26 in cluster M**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609099
Program Type:	PBS
UTM X:	584790.83212
UTM Y:	4508856.35351
Expiration Date:	07/15/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30945
Affiliation Type:	Facility Owner
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	MANAGER
Contact Name:	VICTOR TRAGER
Address1:	636 BROADWAY, SUITE 1008
Address2:	Not reported

636 BROADWAY ASSOCIATES (Continued) **A100292620**

City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 254-7701
EMail:	VICTOR@TRAGERUS.COM
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Site Id:	30945
Affiliation Type:	Mail Contact
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	MANAGER
Contact Name:	VICTOR TRAGER
Address1:	636 BROADWAY, SUITE 1008
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 254-7701
EMail:	VICTOR@TRAGERUS.COM
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Site Id:	30945
Affiliation Type:	Emergency Contact
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	Not reported
Contact Name:	JULIO OCASIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 469-8824
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Site Id:	30945
Affiliation Type:	Facility Operator
Company Name:	636 BROADWAY ASSOCIATES
Contact Type:	Not reported
Contact Name:	JULIO OCASIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-7701
EMail:	Not reported

636 BROADWAY ASSOCIATES (Continued) **A100292620**

Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2014-10-20

Tank Info:

Tank Number:	002
Tank Id:	66400
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/28/2013
Register:	True
Modified By:	LSZINOMA
Last Modified:	04/14/2017
Material Name:	empty

Q353 **CON EDISON** **NY MANIFEST** **S117738199**
ENE **14 TARAS SCHEVCHENKO PL.** **N/A**
1/8-1/4 **NEW YORK, NY 10032**
0.145 mi.
768 ft. **Site 15 of 18 in cluster Q**

Relative: **Lower**
Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004711099
Facility Status:	Not reported
Location Address 1:	14 TARAS SCHEVCHENKO PL.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10032
Location Zip 4:	Not reported

CON EDISON (Continued) **S117738199**

NY MANIFEST:

EPAID:	NYP004711099
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2014
Trans1 Recv Date:	12/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004711099
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	007748022FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported

CON EDISON (Continued) **S117738199**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Q354 **CON EDISON** **NY MANIFEST** **S117738195**
ENE **14 TARAS SCHEVCHENKO PL.** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.145 mi.
768 ft. **Site 16 of 18 in cluster Q**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004711032
Facility Status:	Not reported
Location Address 1:	14 TARAS SCHEVCHENKO PL.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004711032
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2014
Trans1 Recv Date:	12/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004711032
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117738195**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	007748029FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Q355 **CON EDISON** **NY MANIFEST** **S117738197**
ENE **14 TARAS SCHEVCHENKO PL.** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.145 mi.
768 ft. **Site 17 of 18 in cluster Q**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004711073
Facility Status:	Not reported
Location Address 1:	14 TARAS SCHEVCHENKO PL.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004711073

CON EDISON (Continued) **S117738197**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2014
Trans1 Recv Date:	12/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004711073
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	007748027FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117738197**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Q356 **CON EDISON** **NY MANIFEST** **S117738196**
ENE **14 TARAS SCHEVCHENKO PL.** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.145 mi.
768 ft. **Site 18 of 18 in cluster Q**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004711057
Facility Status: Not reported
Location Address 1: 14 TARAS SCHEVCHENKO PL.
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004711057
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: MAD039322250
Trans2 State ID: Not reported
Generator Ship Date: 12/30/2014
Trans1 Recv Date: 12/30/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/30/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004711057
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 007748026FLE

CON EDISON (Continued) **S117738196**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

P357 **CON EDISON** **NY MANIFEST** **S117740372**
SSW **306 MOTT ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.146 mi.
770 ft. **Site 4 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004735379
Facility Status:	Not reported
Location Address 1:	306 MOTT ST
Code:	BP
Location Address 2:	SB 41429
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004735379
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR

CON EDISON (Continued) **S117740372**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/22/2015
Trans1 Recv Date:	02/22/2015
Trans2 Recv Date:	02/26/2015
TSD Site Recv Date:	02/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004735379
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610810GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117740372**

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

P358 **CON EDISON** **NJ MANIFEST** **S120667608**
SSW **306 MOTT ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.146 mi.
770 ft. **Site 5 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

NJ MANIFEST:

EPA Id:	NYP004735379
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610810GBF
EPA ID:	NYP004735379
Date Shipped:	2/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON (Continued) **S120667608**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

P359 **CON EDISON** **RCRA NonGen / NLR** **1018278756**
SSW **306 MOTT ST** **FINDS** **NYP004735379**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.146 mi.
770 ft. **Site 6 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/22/2015
Facility name:	CON EDISON
Facility address:	306 MOTT ST NEW YORK, NY 10012
EPA ID:	NYP004735379
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/22/2015

CON EDISON (Continued) **1018278756**

Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067680879

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278756
Registry ID: 110067680879
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067680879

P360 **SOHO COURT** **NY AST** **U003396991**
South **301 ELIZABETH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.146 mi.
770 ft. **Site 7 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-603100
Program Type: PBS
UTM X: 585034.66426
UTM Y: 4508682.75568
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 25052
Affiliation Type: Facility Owner
Company Name: SOHO COURT ASSOCIATES
Contact Type: Not reported
Contact Name: Not reported
Address1: 103 WEST 55TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 977-4813
EMail: Not reported
Fax Number: Not reported

SOHO COURT (Continued) **U003396991**

Modified By:	NRLOMBAR
Date Last Modified:	2014-05-29
Site Id:	25052
Affiliation Type:	Mail Contact
Company Name:	MANHATTAN SKYLINE MANAGEMENT
Contact Type:	Not reported
Contact Name:	THOMAS ESCHMANN
Address1:	103 WEST 55TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 977-4800
EMail:	TESCHMANN @MSKYLINE.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-05-29
Site Id:	25052
Affiliation Type:	Facility Operator
Company Name:	SOHO COURT
Contact Type:	Not reported
Contact Name:	JEFF GJENASHIJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 835-9275
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-05-29
Site Id:	25052
Affiliation Type:	Emergency Contact
Company Name:	SOHO COURT ASSOCIATES
Contact Type:	Not reported
Contact Name:	THOMAS ESCHMANN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 977-4800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-05-29

Tank Info:

Tank Number:	001

SOHO COURT (Continued) **U003396991**

Tank Id: 53065
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1996
Capacity Gallons: 12000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/30/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #6 fuel oil (on-site consumption)

S361 **DEMAIMON CORP** **NY AST** **U003387750**
SW **156 CROSBY STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.146 mi.
771 ft. **Site 2 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-233889
Program Type: PBS
UTM X: 584875.49339
UTM Y: 4508804.05190
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 8533
Affiliation Type: Facility Owner
Company Name: DEMAIMON CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 324 LAFAYETTE ST.
Address2: Not reported

DEMAIMON CORP (Continued) **U003387750**

City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 727-0022
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-12-21

Site Id:	8533
Affiliation Type:	Mail Contact
Company Name:	DEMAIMON CORP
Contact Type:	Not reported
Contact Name:	JEFFREY WEBER
Address1:	236 WEST 26TH STREET SUITE 805
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 727-0022
EMail:	JWEBER@WEBFAR.NET
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2012-05-22

Site Id:	8533
Affiliation Type:	Emergency Contact
Company Name:	DEMAIMON CORP
Contact Type:	Not reported
Contact Name:	JULIUS NEUMANN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 260-1030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8533
Affiliation Type:	Facility Operator
Company Name:	DEMAIMON CORP
Contact Type:	Not reported
Contact Name:	GJIN MARKAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 908-9056
EMail:	Not reported

DEMAIMON CORP (Continued) **U003387750**

Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2012-05-22

Tank Info:

Tank Number:	001
Tank Id:	12512
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)
B99 - Tank External Protection - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1960
Capacity Gallons:	3000
Tightness Test Method:	ZZ
Date Test:	04/01/1992
Next Test Date:	Not reported
Date Tank Closed:	09/17/2016
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

S362 **159-02 CROSS BAY BLVD** **NY LTANKS** **S102671322**
SW **159-02 CROSS BAY BLVD** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.146 mi.
771 ft. **Site 3 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

LTANKS:

Facility ID:	8806752
Site ID:	94717
Closed Date:	1988-11-13
Spill Number:	8806752
Spill Date:	1988-11-13
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1988-11-13
SWIS:	4101

159-02 CROSS BAY BLVD (Continued) **S102671322**

Investigator:	JCGRATHW
Referred To:	Not reported
Reported to Dept:	1988-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-11-18
Spill Record Last Update:	2004-01-06
Spiller Name:	Not reported
Spiller Company:	ISLAND TRANSPORTATION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	282899
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GRATHWOL "
Remarks:	"DEC (GRATHWOL) CALLED NYCFD (ENGINE CO 331) TO FLUSH SPILL AWAY WITH LARGE VOLUME OF WATER."

All Materials:

Site ID:	94717
Operable Unit ID:	923591
Operable Unit:	01
Material ID:	455096
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

W363 **CON EDISON** **NY MANIFEST** **S117066508**
NE **56 COOPER SQ** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.146 mi.
773 ft. **Site 2 of 6 in cluster W**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591651
Facility Status:	Not reported
Location Address 1:	56 COOPER SQ
Code:	BP
Location Address 2:	MH 30942
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY

CON EDISON (Continued) **S117066508**

Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591651
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591651
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423978GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117066508**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

W364 **CON EDISON** **NY MANIFEST** **S117066507**
NE **56 COOPER SQ** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.146 mi.
773 ft. **Site 3 of 6 in cluster W**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591640
Facility Status:	Not reported
Location Address 1:	56 COOPER SQ
Code:	BP
Location Address 2:	SB 30941
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591640
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591640

CON EDISON (Continued) **S117066507**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423977GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

S365 **325 LAFAYETTE TENANTS CORP** **NY AST** **A100292137**
SW **325/331 LAFAYETTE STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.146 mi.
773 ft. **Site 4 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-607479
Program Type:	PBS
UTM X:	584896.19963
UTM Y:	4508796.13886
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29331

325 LAFAYETTE TENANTS CORP (Continued) **A100292137**

Affiliation Type:	Facility Owner
Company Name:	325 LAFAYATTE TENANTS CORP
Contact Type:	MGR
Contact Name:	BEN AGIN
Address1:	325/331 LAFAYETTE ST #6
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11743
Country Code:	001
Phone:	(212) 431-5374
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-08-26

Site Id:	29331
Affiliation Type:	Mail Contact
Company Name:	325/331 LAFAYETTE STREET
Contact Type:	Not reported
Contact Name:	BEN AGIN
Address1:	#6
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-5374
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-07-27

Site Id:	29331
Affiliation Type:	Facility Operator
Company Name:	325 LAFAYETTE TENANTS CORP
Contact Type:	Not reported
Contact Name:	STAR SANDORN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(631) 692-5608
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29331
Affiliation Type:	Emergency Contact
Company Name:	325 LAFAYATTE TENANTS CORP
Contact Type:	Not reported
Contact Name:	MOTI EFOTA
Address1:	Not reported
Address2:	Not reported

325 LAFAYETTE TENANTS CORP (Continued) **A100292137**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 226-6470
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	63048
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/05/2011
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

X366 **736 BROADWAY BUILDING** **NY AST** **U003387319**
North **736 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.146 mi.
773 ft. **Site 1 of 13 in cluster X**

Relative: AST:
Lower

Actual:
39 ft.

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-245879
Program Type:	PBS
UTM X:	585076.24881

736 BROADWAY BUILDING (Continued) **U003387319**

UTM Y: 4509306.05004
Expiration Date: 06/28/2023
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 9588
Affiliation Type: Mail Contact
Company Name: JEONG HOON KIM OF UD 736 BORADWAY LLC
Contact Type: Not reported
Contact Name: ALEX SEO
Address1: C/O UDG MANAGEMENT LLC
Address2: 212 E 49TH STREET
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (212) 643-0927
EMail: ALEX.SEO@SUPPORTMGMT.COM
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-02-21

Site Id: 9588
Affiliation Type: Facility Operator
Company Name: 736 BROADWAY BUILDING
Contact Type: Not reported
Contact Name: STEVE HOWLEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 296-4927
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2012-02-08

Site Id: 9588
Affiliation Type: Emergency Contact
Company Name: UD 736 BROADWAY LLC
Contact Type: Not reported
Contact Name: ALEX SEO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 679-5223
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-02-21

Site Id: 9588
Affiliation Type: Facility Owner

736 BROADWAY BUILDING (Continued) **U003387319**

Company Name:	UD 736 BROADWAY LLC
Contact Type:	DIRECTOR
Contact Name:	ALEX SEO
Address1:	C/O UDG MANAGMENT 212 E. 49TH ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 643-0927
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Tank Info:

Tank Number:	001
Tank Id:	11667
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1970
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BVCAMPBE
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

V367 **CON EDISON** **RCRA NonGen / NLR** **1019907262**
East **229 E 5TH ST** **FINDS** **NYP004832024**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.148 mi.
779 ft. **Site 3 of 15 in cluster V**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/31/2015
Facility name:	CON EDISON
Facility address:	229 E 5TH ST NEW YORK, NY 10003
EPA ID:	NYP004832024
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/31/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069690098

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019907262**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019907262
Registry ID:	110069690098
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069690098

V368 **CON EDISON** **NJ MANIFEST** **S120676113**
East **229 E 5TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.148 mi.
779 ft. **Site 4 of 15 in cluster V**

Relative: **Lower**
Actual: **38 ft.**

NJ MANIFEST:

EPA Id:	NYP004832024
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613053GBF
EPA ID:	NYP004832024
Date Shipped:	8/31/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON (Continued) **S120676113**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

V369 **CON EDISON** **NY MANIFEST** **S119077485**
East **229 E 5TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.148 mi.
779 ft. **Site 5 of 15 in cluster V**

Relative: **Lower**

Actual: **38 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004832024
Facility Status:	Not reported
Location Address 1:	229TH ST & 5TH ST
Code:	BP
Location Address 2:	SB 970
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004832024
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S119077485**

Generator Ship Date:	08/31/2015
Trans1 Recv Date:	08/31/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004832024
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613053GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

S370 **CON EDISON** **RCRA NonGen / NLR** **1014398470**
SW **324 LAFAYETTE ST** **NY MANIFEST** **NYP004208233**
1/8-1/4 **NEW YORK, NY 10012**
0.148 mi.
782 ft. **Site 5 of 10 in cluster S**

Relative: **Higher**
Actual: **42 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/08/2010
Facility name:	CON EDISON
Facility address:	324 LAFAYETTE ST NEW YORK, NY 10012
EPA ID:	NYP004208233

CON EDISON (Continued) **1014398470**

Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DANIEL PONTECORVO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 347-203-2573
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004208233
Facility Status: Not reported
Location Address 1: 324 LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004208233
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: THOMAS TEELING
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON (Continued) **1014398470**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/2010
Trans1 Recv Date:	06/08/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004208233
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001442254FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

X371 **CON EDISON SERVICE BOX: 28829** **RCRA NonGen / NLR** **1016969381**
North **736 BROADWAY** **NY MANIFEST** **NYP004430419**
1/8-1/4 **NEW YORK, NY 10003**
0.148 mi.
782 ft. **Site 2 of 13 in cluster X**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/28/2014
Facility name: CON EDISON SERVICE BOX: 28829
Facility address: 736 BROADWAY
NEW YORK, NY 10003
EPA ID: NYP004430419
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/30/2014
Site name: CON EDISON SERVICE BOX: 28829
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004430419
Facility Status: Not reported
Location Address 1: 736 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003

CON EDISON SERVICE BOX: 28829 (Continued) **1016969381**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004430419
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 01/30/2014
Trans1 Recv Date: 01/30/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/03/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004430419
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002329788GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 28829 (Continued) **1016969381**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

T372 **CON EDISON** **NJ MANIFEST** **S120671283**
ESE **85 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.148 mi.
784 ft. **Site 2 of 15 in cluster T**

Relative: **Lower**
Actual: **38 ft.**

NJ MANIFEST:

EPA Id:	NYP004777074
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002609873GBF
EPA ID:	NYP004777074
Date Shipped:	4/30/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON (Continued) **S120671283**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

T373 **CON EDISON SERVICE BOX: 848** **RCRA NonGen / NLR** **1016974191**
ESE **85 E 4TH ST & COOPER SQ E OF** **FINDS** **NYP004480042**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.148 mi. **NY MANIFEST**
784 ft. **Site 3 of 15 in cluster T**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/26/2014
Facility name:	CON EDISON SERVICE BOX: 848
Facility address:	85 E 4TH ST & COOPER SQ E OF NEW YORK, NY 10003
EPA ID:	NYP004480042
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON SERVICE BOX: 848 (Continued) **1016974191**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/26/2014
Site name: CON EDISON SERVICE BOX: 848
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069694218

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016974191
Registry ID: 110069694218
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069694218

NY MANIFEST:
Country: USA
EPA ID: NYP004777074
Facility Status: Not reported
Location Address 1: 85 E 4 STREET
Code: BP
Location Address 2: SB 848
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004777074
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON SERVICE BOX: 848 (Continued) **1016974191**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/30/2015
Trans1 Recv Date:	04/30/2015
Trans2 Recv Date:	05/06/2015
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004777074
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609873GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP004480042

CON EDISON SERVICE BOX: 848 (Continued) **1016974191**

Facility Status:	Not reported
Location Address 1:	85 4 & COOPER SQ
Code:	BP
Location Address 2:	SB848
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004480042
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480042
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406126GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 848 (Continued) **1016974191**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

T374 **CON EDISON** **RCRA NonGen / NLR** **1019902722**
ESE **85 E 4TH ST** **NYP004777074**
1/8-1/4 **NEW YORK, NY 10003**
0.148 mi.
784 ft. **Site 4 of 15 in cluster T**

Relative: **Lower**

Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/30/2015
Facility name:	CON EDISON
Facility address:	85 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004777074
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

CON EDISON (Continued) **1019902722**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/30/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

P375 **SPILL NUMBER 9411282** **NY LTANKS** **S102149033**
South **ELIZABETH ST & HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.149 mi.
785 ft. **Site 8 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

LTANKS:
Facility ID: 9411282
Site ID: 153267
Closed Date: 2004-01-13
Spill Number: 9411282
Spill Date: 1994-11-23
Spill Cause: Tank Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1994-11-23
CID: Not reported
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-01-05
Spill Record Last Update: 2004-01-13
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 130047
DEC Memo: ""
Remarks: "EVCAV. & RUPTURED A TANK- EXCAV. W/O A PERMIT- NO NAME BY EXCAV. WORK"

All Materials:
Site ID: 153267
Operable Unit ID: 1009164
Operable Unit: 01
Material ID: 377143
Material Code: 0066A

SPILL NUMBER 9411282 (Continued) **S102149033**

Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P376 **CON EDISON SERVICE BOX: 26809** **RCRA NonGen / NLR** **1016973603**
SSE **308 BOWERY & HOUSTON N OF** **NY MANIFEST** **NYP004474078**
1/8-1/4 **NEW YORK, NY 10012**
0.150 mi.
790 ft. **Site 9 of 12 in cluster P**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/21/2014
Facility name:	CON EDISON SERVICE BOX: 26809
Facility address:	308 BOWERY & HOUSTON N OF NEW YORK, NY 10012
EPA ID:	NYP004474078
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/21/2014
Site name:	CON EDISON SERVICE BOX: 26809
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

CON EDISON SERVICE BOX: 26809 (Continued) **1016973603**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004474078
Facility Status:	Not reported
Location Address 1:	308 BOWERY ST
Code:	BP
Location Address 2:	SB26809
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004474078
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/21/2014
Trans1 Recv Date:	03/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004474078
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360632GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON SERVICE BOX: 26809 (Continued) **1016973603**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

T377 **CON EDISON** **NY MANIFEST** **S117066200**
SE **30 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.150 mi.
792 ft. **Site 5 of 15 in cluster T**

Relative: **Lower**

Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004588299
Facility Status:	Not reported
Location Address 1:	30 E 3RD ST
Code:	BP
Location Address 2:	SB 671
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004588299
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON (Continued) **S117066200**

Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004588299
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503411GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

T378 **30 EAST 3RD STREET** **NY LTANKS** **S105135145**
SE **30 EAST 3RD STREET** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.150 mi.
792 ft. **Site 6 of 15 in cluster T**

Relative: **Lower**

Actual: **39 ft.**

LTANKS:

Facility ID:	0106303
Site ID:	70393
Closed Date:	2005-08-04
Spill Number:	0106303
Spill Date:	2001-09-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MDMACCAB
Referred To:	Not reported
Reported to Dept:	2001-09-14
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-14
Spill Record Last Update:	2005-08-04
Spiller Name:	JEAN HUGHES
Spiller Company:	Not reported
Spiller Address:	30 EAST 3RD STREET
Spiller County:	999
Spiller Contact:	JEAN HUGHES
Spiller Phone:	(212) 475-0243
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	66809
DEC Memo:	"An environmental contractor noted that approxomately 100 gallons of heating fuel oil spilled in the basement of this private residence. the oil was removed. Cracks were observed in the concrete floor. Seventeen cubic yards of oil contaminated concrete and debris were removed from the site. Twenety-two cubic yards of contaminated soil were excavated and removed from the site. The excavation was backfilled, a vapor barrier was placed over the soil, a new concrete floor was constructed, and the floor was sealed. Later soil borings found low-level PAH contamination below or just above the recommended soil cleanup objectives in one location. The spill was closed on August 4, 2005."
Remarks:	"September 14, 2001 the resident smelled oil. Service man found AST leaking."

All Materials:

Site ID:	70393
Operable Unit ID:	843218
Operable Unit:	01
Material ID:	531165
Material Code:	0001A
Material Name:	#2 fuel oil

30 EAST 3RD STREET (Continued) **S105135145**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S379 **CONSOLIDATED EDISON-MH 11236** **NY MANIFEST** **S112140720**
SW **323 LAFAYETTE** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.150 mi.
793 ft. **Site 6 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004254975
Facility Status:	Not reported
Location Address 1:	323 LAFAYETTE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004254975
Mailing Name:	CONSOLIDATED EDISON-MH 11236
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2012
Trans1 Recv Date:	06/13/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/14/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004254975
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported

CONSOLIDATED EDISON-MH 11236 (Continued) **S112140720**

Manifest Tracking Number:	004806753FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Y380 **632 BROADWAY** **NY AST** **U003387729**
WSW **632 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.152 mi.
801 ft. **Site 1 of 16 in cluster Y**

Relative: **Lower**

Actual: **39 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-202827
Program Type:	PBS
UTM X:	584818.78072
UTM Y:	4508851.58510
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6967
Affiliation Type:	Facility Owner
Company Name:	RENAISSANCE 632 BROADWAY LLC.
Contact Type:	Not reported
Contact Name:	Not reported

632 BROADWAY (Continued) **U003387729**

Address1:	632 BROADWAY, 7TH FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 477-3165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-05-22

Site Id:	6967
Affiliation Type:	Mail Contact
Company Name:	RENAISSANCE 632 BROADWAY LLC
Contact Type:	Not reported
Contact Name:	KENNETH FISHEL
Address1:	632 BROADWAY, 7TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 477-3165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-05-22

Site Id:	6967
Affiliation Type:	Facility Operator
Company Name:	632 BROADWAY
Contact Type:	Not reported
Contact Name:	KENNETH FISHEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-3165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6967
Affiliation Type:	Emergency Contact
Company Name:	RENAISSANCE 632 BROADWAY LLC.
Contact Type:	Not reported
Contact Name:	ERIC JOZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

632 BROADWAY (Continued) **U003387729**

Phone: (212) 477-3164
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 12480
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1980
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/02/2010
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #6 fuel oil (on-site consumption)

Y381 **CON EDISION - MH 27229** **RCRA NonGen / NLR** **1007207597**
WSW **634 BROADWAY 634 BROADWAY** **NY MANIFEST** **NYP004071627**
1/8-1/4 **NEW YORK, NY 10003**
0.152 mi.
801 ft. **Site 2 of 16 in cluster Y**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/02/2002
Facility name: CON EDISION - MH 27229
Facility address: 634 BROADWAY 634 BROADWAY
NEW YORK, NY 10003
EPA ID: NYP004071627
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: IRVING PLACE

CON EDISION - MH 27229 (Continued) **1007207597**

NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/01/2002
Site name: CON EDISION - MH 27229
Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - MH 27229
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004071627
Facility Status: Not reported
Location Address 1: MH27229-BROADWAY & BLEEKER ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10020
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004071627
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

CON EDISION - MH 27229 (Continued) **1007207597**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	CTF0810486
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	PUL9202
Trans2 State ID:	Not reported
Generator Ship Date:	01/17/2001
Trans1 Recv Date:	01/17/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004071627
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00002
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

P382 **CON EDISON** **NY MANIFEST** **S117066478**
SSE **3 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.152 mi.
802 ft. **Site 10 of 12 in cluster P**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591319
Facility Status:	Not reported
Location Address 1:	3 E 1ST ST
Code:	BP
Location Address 2:	SB 302
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591319
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423976GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117066478**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

X383 **CORINNE OFFSET INC** **RCRA NonGen / NLR** **1001224340**
North **737 BROADWAY** **FINDS** **NYR000055574**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.152 mi. **NY MANIFEST**
803 ft. **Site 3 of 13 in cluster X**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	CORINNE OFFSET INC
Facility address:	737 BROADWAY NEW YORK, NY 10003
EPA ID:	NYR000055574
Mailing address:	BROADWAY NEW YORK, NY 10003
Contact:	ARNOLD EIGEN
Contact address:	BROADWAY NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-777-8083
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ARNOLD EIGEN
Owner/operator address:	765 EAGLE DR NORTH WOODMERE, NY 11581
Owner/operator country:	US
Owner/operator telephone:	516-791-5028
Owner/operator email:	Not reported

CORINNE OFFSET INC (Continued) **1001224340**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ARNOLD EIGEN
Owner/operator address: 765 EAGLE DR
NORTH WOODMERE, NY 11581
Owner/operator country: US
Owner/operator telephone: 516-791-5028
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CORINNE OFFSET INC
Classification: Not a generator, verified

Date form received by agency: 06/02/1998
Site name: CORINNE OFFSET INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004543655

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

CORINNE OFFSET INC (Continued) **1001224340**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001224340
Registry ID:	110004543655
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004543655

NY MANIFEST:

Country:	USA
EPA ID:	NYR000055574
Facility Status:	Not reported
Location Address 1:	737 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000055574
Mailing Name:	CORINNE OFFSET
Mailing Contact:	ARNOLD
Mailing Address 1:	737 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127778083

NY MANIFEST:

Document ID:	NYG0586314
Manifest Status:	Not reported
seq:	01
Year:	1998
Trans1 State ID:	NYPD1010
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/1998
Trans1 Recv Date:	06/03/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/04/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000055574
Trans1 EPA ID:	NYD077444263

CORINNE OFFSET INC (Continued) **1001224340**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

X384 **CON EDISON SERVICE BOX: 28829** **RCRA NonGen / NLR** **1016962593**
North **738 BROADWAY** **NY MANIFEST** **NYP004356457**
1/8-1/4 **NEW YORK, NY 10003**
0.152 mi.
805 ft. **Site 4 of 13 in cluster X**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	10/07/2013
Facility name:	CON EDISON SERVICE BOX: 28829
Facility address:	738 BROADWAY NEW YORK, NY 10003
EPA ID:	NYP004356457
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
39 ft.

Handler Activities Summary:

CON EDISON SERVICE BOX: 28829 (Continued) **1016962593**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/07/2013
Site name: CON EDISON SERVICE BOX: 28829
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004356457
Facility Status: Not reported
Location Address 1: FT OF 738 BROADWAY
Code: BP
Location Address 2: SB 28829
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004356457
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/07/2013

CON EDISON SERVICE BOX: 28829 (Continued) **1016962593**

Trans1 Recv Date:	09/07/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004356457
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002220990GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z385 **CON EDISON - E 2ND** **PA MANIFEST** **S118889034**
SE **26 E 2ND ST** **N/A**
1/8-1/4 **MANHATTAN, NY 10003**
0.153 mi.
807 ft. **Site 1 of 15 in cluster Z**

Relative: **Lower**

Actual: **40 ft.**

Manifest Details:

Year:	2015
Manifest Number:	002659508GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYP004713921
Generator Date:	01/12/2015
Mailing Address:	Not reported

CON EDISON - E 2ND (Continued) **S118889034**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

P386 **CON EDISON SERVICE BOX: 26807** **NJ MANIFEST** **S117985977**
South **302 BOWERY FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.154 mi.
812 ft. **Site 11 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

NJ MANIFEST:

EPA Id:	NYP004265179
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010464334JJK
EPA ID:	NYP004265179
Date Shipped:	8/27/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

CON EDISON SERVICE BOX: 26807 (Continued) **S117985977**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	750.00 Pounds

P387 **CON EDISON SERVICE BOX: 26807** **RCRA NonGen / NLR** **1016143735**
South **302 BOWERY FRONT OF** **FINDS** **NYP004265179**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.154 mi. **NY MANIFEST**
812 ft. **Site 12 of 12 in cluster P**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 26807
Facility address:	302 BOWERY FRONT OF NEW YORK, NY 10012
EPA ID:	NYP004265179
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported

CON EDISON SERVICE BOX: 26807 (Continued) **1016143735**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/27/2012
Site name: CON EDISON SERVICE BOX: 26807
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055467203

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143735
Registry ID: 110055467203
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055467203

NY MANIFEST:
Country: USA
EPA ID: NYP004265179
Facility Status: Not reported
Location Address 1: F/O 302 BOWERY
Code: BP
Location Address 2: Not reported

CON EDISON SERVICE BOX: 26807 (Continued) **1016143735**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004265179
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/27/2012
Trans1 Recv Date:	08/27/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004265179
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010464334JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	750.0
Units:	P - Pounds

CON EDISON SERVICE BOX: 26807 (Continued) **1016143735**

Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

S388 **LAFAYETTE AUTO REPAIR** **RCRA NonGen / NLR** **1000161130**
SW **321 LAFAYETTE ST** **FINDS** **NYD982790214**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.154 mi. **NY MANIFEST**
813 ft. **Site 7 of 10 in cluster S**

Relative: **Higher**

Actual: **42 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	LAFAYETTE AUTO REPAIR
Facility address:	321 LAFAYETTE ST NEW YORK, NY 10012-2727
EPA ID:	NYD982790214
Mailing address:	LAFAYETTE ST NEW YORK, NY 10012
Contact:	Not reported
Contact address:	LAFAYETTE ST NEW YORK, NY 10012
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MUHAMMAD SALEEN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MUHAMMAD SALEEN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US

LAFAYETTE AUTO REPAIR (Continued) **1000161130**

Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: LAFAYETTE AUTO REPAIR
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: LAFAYETTE AUTO REPAIR
Classification: Not a generator, verified

Date form received by agency: 09/25/1989
Site name: LAFAYETTE AUTO REPAIR
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

LAFAYETTE AUTO REPAIR (Continued) **1000161130**

Violation Status: No violations found

FINDS:

Registry ID: 110004433364

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000161130
Registry ID:	110004433364
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004433364

NY MANIFEST:

Country:	USA
EPA ID:	NYD982790214
Facility Status:	Not reported
Location Address 1:	321 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982790214
Mailing Name:	LAFAYETTE AUTO REPAIR
Mailing Contact:	LAFAYETTE AUTO REPAIR
Mailing Address 1:	321 LAFAYETTE ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10012
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129251516

NY MANIFEST:

Document ID:	NJA2704851
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	09/04/1996

LAFAYETTE AUTO REPAIR (Continued) **1000161130**

Trans1 Recv Date:	09/04/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/04/1996
Part A Recv Date:	/ /
Part B Recv Date:	09/24/1996
Generator EPA ID:	NYD982790214
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD000768093
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00013
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
128 additional NY_MANIFEST: record(s) in the EDR Site Report.

AA389 **CVPII LLC CHRYSTIE PLACE II** **NY AST** **U004046480**
SSE **5 EAST 1ST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.154 mi.
814 ft. **Site 1 of 5 in cluster AA**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610027
Program Type:	PBS
UTM X:	585122.67961
UTM Y:	4508687.29515
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	353911

CVPII LLC CHRYSTIE PLACE II (Continued) **U004046480**

Affiliation Type:	Facility Owner
Company Name:	CVP II, LLC
Contact Type:	PROJECT MANAGER
Contact Name:	RICHARD V. TAYLOR
Address1:	535 5TH AVENUE, 17TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 309-1601
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-13

Site Id:	353911
Affiliation Type:	Mail Contact
Company Name:	CVP II, LLC
Contact Type:	Not reported
Contact Name:	ALBERT HROMIN
Address1:	535 5TH AVENUE, 17TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 309-1601
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-13

Site Id:	353911
Affiliation Type:	Facility Operator
Company Name:	CVPII LLC CHRYSTIE PLACE II
Contact Type:	Not reported
Contact Name:	ALBERT HROMIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 387-9646
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-13

Site Id:	353911
Affiliation Type:	Emergency Contact
Company Name:	CVP II, LLC
Contact Type:	Not reported
Contact Name:	ALBERT HROMIN
Address1:	Not reported
Address2:	Not reported

CVPII LLC CHRYSTIE PLACE II (Continued) **U004046480**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 387-9646
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-13

Tank Info:

Tank Number:	1
Tank Id:	208328
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/31/2005
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

AB390 **SCHULMANN PROPERTIES INTERNATIONAL** **NY AST** **U003387035**
SSW **302 MOTT STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.155 mi.
816 ft. **Site 1 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-248630
Program Type:	PBS

SCHULMANN PROPERTIES INTERNATIONAL (Continued) **U003387035**

UTM X:	584960.47273
UTM Y:	4508707.43673
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9834
Affiliation Type:	Facility Owner
Company Name:	SCHILMANN PROPERTIES INTL
Contact Type:	ASST. PROPERTY MANAGER
Contact Name:	ADRIAN AWY
Address1:	88 RIVINGTON STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(212) 475-6660
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-04-28

Site Id:	9834
Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	SION MISRAHI
Address1:	88 RIVINGTON STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(212) 475-6660
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9834
Affiliation Type:	Facility Operator
Company Name:	SCHULMANN PROPERTIES INTERNATIONAL
Contact Type:	Not reported
Contact Name:	SOIN MISRAHI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-6660
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id: 9834

SCHULMANN PROPERTIES INTERNATIONAL (Continued) **U003387035**

Affiliation Type:	Emergency Contact
Company Name:	302 MOTT STREET, C/O MISRAHI REALTY
Contact Type:	Not reported
Contact Name:	SOIN MISRAHI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-6660
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	11150
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/13/1991
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/13/2017
Register:	True
Modified By:	DAFRANCI
Last Modified:	04/28/2017
Material Name:	#2 fuel oil (on-site consumption)

AB391 **CON EDISON SERVICE BOX: 41428** **RCRA NonGen / NLR** **1016450454**
SSW **302 MOTT ST** **FINDS** **NYP004294799**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.155 mi. **NY MANIFEST**
816 ft. **Site 2 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/20/2013
Facility name:	CON EDISON SERVICE BOX: 41428
Facility address:	302 MOTT ST NEW YORK, NY 10012
EPA ID:	NYP004294799
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/20/2013
Site name:	CON EDISON SERVICE BOX: 41428
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110056328433

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 41428 (Continued) **1016450454**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016450454
Registry ID:	110056328433
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056328433

NY MANIFEST:

Country:	USA
EPA ID:	NYP004294799
Facility Status:	Not reported
Location Address 1:	F/O 302 MOTT ST
Code:	BP
Location Address 2:	SERVICE BOX # 41428
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004294799
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2013
Trans1 Recv Date:	03/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004294799
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841173JJK
Import Indicator:	N
Export Indicator:	N

CON EDISON SERVICE BOX: 41428 (Continued) **1016450454**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

W392 **CON EDISON SERVICE BOX: 37939** **RCRA NonGen / NLR** **1016968963**
NNE **439 LAFAYETTE ST** **NY MANIFEST** **NYP004426029**
1/8-1/4 **NEW YORK, NY 10003**
0.155 mi.
821 ft. **Site 4 of 6 in cluster W**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/26/2014
Facility name:	CON EDISON SERVICE BOX: 37939
Facility address:	439 LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004426029
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON SERVICE BOX: 37939 (Continued) **1016968963**

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/26/2014
Site name:	CON EDISON SERVICE BOX: 37939
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004426029
Facility Status:	Not reported
Location Address 1:	F/O 439 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004426029
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/26/2014

CON EDISON SERVICE BOX: 37939 (Continued) **1016968963**

Trans1 Recv Date:	01/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004426029
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328564GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

V393 **CON EDISON SERVICE BOX: 1086** **RCRA NonGen / NLR** **1016148914**
East **222 E 6 ST FRONT OF** **FINDS** **NYP004275657**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.155 mi. **NY MANIFEST**
821 ft. **Site 6 of 15 in cluster V**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 1086
Facility address:	222 E 6 ST FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004275657
Mailing address:	IRVING PL, RM 828

Actual:
38 ft.

CON EDISON SERVICE BOX: 1086 (Continued) **1016148914**

NEW YORK, NY 10003
Contact: RICARDO CARTY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-643-3044
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/23/2012
Site name: CON EDISON SERVICE BOX: 1086
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055459187

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148914
Registry ID: 110055459187
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055459187

CON EDISON SERVICE BOX: 1086 (Continued) **1016148914**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004275657
Facility Status:	Not reported
Location Address 1:	FO 222 E 6TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004275657
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2012
Trans1 Recv Date:	10/23/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004275657
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010456550JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported

CON EDISON SERVICE BOX: 1086 (Continued) **1016148914**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

V394 **CON EDISON SERVICE BOX: 1086** **NJ MANIFEST** **S117986861**
East **222 E 6 ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.155 mi.
821 ft. **Site 7 of 15 in cluster V**

Relative: **Lower**

Actual: **38 ft.**

NJ MANIFEST:

EPA Id:	NYP004275657
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	RICARDO CARTY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010456550JJK
EPA ID:	NYP004275657
Date Shipped:	10/23/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON SERVICE BOX: 1086 (Continued) **S117986861**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	75.00 Pounds

V395 **MORTON TABAK** **NY AST** **U004047637**
East **233 EAST 5TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.156 mi.
822 ft. **Site 8 of 15 in cluster V**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-240079
Program Type:	PBS
UTM X:	585285.39964
UTM Y:	4509002.37340
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9075
Affiliation Type:	Facility Operator

MORTON TABAK (Continued) **U004047637**

Company Name:	MORTON TABAK
Contact Type:	Not reported
Contact Name:	MORTON TABAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 275-3919
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-04-01

Site Id:	9075
Affiliation Type:	Emergency Contact
Company Name:	MORTON TABAK
Contact Type:	Not reported
Contact Name:	BERNARD TABAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 897-5712
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-07-30

Site Id:	9075
Affiliation Type:	Facility Owner
Company Name:	MORTON-TABAK
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	98-41 64TH ROAD
Address2:	Not reported
City:	REGO PARK
State:	NY
Zip Code:	11374
Country Code:	001
Phone:	(718) 275-3919
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9075
Affiliation Type:	Mail Contact
Company Name:	MORTON-TABAK
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	98-41 64TH ROAD
Address2:	Not reported
City:	REGO PARK

MORTON TABAK (Continued) **U004047637**

State:	NY
Zip Code:	11374
Country Code:	001
Phone:	(718) 275-3919
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	10232
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1964
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/17/2002
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AB396 **CON EDISON** **RCRA NonGen / NLR** **1018279127**
SSW **298 MULBERRY ST** **FINDS** **NYP004739264**
1/8-1/4 **NEW YORK, NY 10013** **ECHO**
0.157 mi.
827 ft. **Site 3 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/26/2015
Facility name:	CON EDISON
Facility address:	298 MULBERRY ST NEW YORK, NY 10013
EPA ID:	NYP004739264
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

CON EDISON (Continued) **1018279127**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/26/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067686169

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279127
Registry ID: 110067686169
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067686169

AB397
SSW
1/8-1/4
0.157 mi.
827 ft.

CVS # 10407
298 MULBERRY STREET
MANHATTAN, NY 10012

Site 4 of 12 in cluster AB

PA MANIFEST **S118889327**
N/A

Relative:
Higher

Actual:
43 ft.

Manifest Details:

Year:	2015
Manifest Number:	006299647FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000211128
Generator Date:	03/06/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	13
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396033FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000211128
Generator Date:	05/06/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592

CVS # 10407 (Continued) **S118889327**

Date TSP Sig: Not reported

Year: 2015
Manifest Number: 006299647FLE
Manifest Type: TSD Copy
Generator EPA Id: NYR000211128
Generator Date: 03/06/2015
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: Not reported
TSD Date: Not reported
TSD Facility Name: Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address: 2869 Sandstone Dr
TSD Facility City: Hatfield
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 2
Waste Number: D001
Container Number: 1
Container Type: Fiber or plastic boxes, cartons, cases
Waste Quantity: 27
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD085690592
Date TSP Sig: Not reported

Year: 2015
Manifest Number: 006299647FLE
Manifest Type: TSD Copy
Generator EPA Id: NYR000211128
Generator Date: 03/06/2015
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: Not reported
TSD Date: Not reported
TSD Facility Name: Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address: 2869 Sandstone Dr
TSD Facility City: Hatfield
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 4
Waste Number: D002
Container Number: 1
Container Type: Fiber or plastic boxes, cartons, cases
Waste Quantity: 11
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD085690592
Date TSP Sig: Not reported

Year: 2015

CVS # 10407 (Continued) **S118889327**

Manifest Number:	006299647FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000211128
Generator Date:	03/06/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	U002
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	006299647FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000211128
Generator Date:	03/06/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AB398 **CON EDISON** **NJ MANIFEST** **S120667965**
SSW **298 MULBERRY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.157 mi.
827 ft. **Site 5 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

NJ MANIFEST:

EPA Id:	NYP004739264
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610986GBF
EPA ID:	NYP004739264
Date Shipped:	2/26/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667965**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB399 **CON EDISON** **NY MANIFEST** **S117740745**
SSW **298 MULBERRY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.157 mi.
827 ft. **Site 6 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004739264
Facility Status:	Not reported
Location Address 1:	F/O 298 MULBERRY ST
Code:	BP
Location Address 2:	SB41585
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004739264
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	F/O 298 MULBERRY ST
Mailing Address 2:	SB41585
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10013
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2015
Trans1 Recv Date:	02/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004739264
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117740745**

Manifest Tracking Number:	002610986GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AB400 **CVS PHARMACY #10407** **RCRA-LQG** **1016974653**
SSW **298 MULBERRY ST** **NY MANIFEST** **NYR000211128**
1/8-1/4 **NEW YORK, NY 10012**
0.157 mi.
827 ft. **Site 7 of 12 in cluster AB**

Relative: RCRA-LQG:
Higher

Date form received by agency:	03/18/2016
Facility name:	CVS PHARMACY #10407
Facility address:	298 MULBERRY ST NEW YORK, NY 10012
EPA ID:	NYR000211128
Mailing address:	CVS DR MAIL DROP 23062A WOONSOCKET, RI 02895
Contact:	NICOLE WILKINSON
Contact address:	CVS DR MAIL CODE 2340 WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	401-770-7132
Contact email:	NICOLE.WILKINSON@CVSHEALTH.COM
EPA Region:	02
Classification:	Large Quantity Generator

Actual:
43 ft.

CVS PHARMACY #10407 (Continued) **1016974653**

Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: COLUMBIA 298 MULBERRY LLC
Owner/operator address: HIGH ST 27TH FL HIGH ST TOWER
BOSTON, MA 02110
Owner/operator country: US
Owner/operator telephone: 617-973-9680
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/05/2013
Owner/Op end date: Not reported

Owner/operator name: COLUMBIA 298 MULBERRY LLC
Owner/operator address: HIGH ST HIGH ST TOWER 27TH FLOOR
BOSTON, MA 02110
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/05/2013
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY LLC
Owner/operator address: CVS DR
WOONSOCKET, RI 02895
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/05/2014
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US

CVS PHARMACY #10407 (Continued) **1016974653**

Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/05/2014
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

Historical Generators:
Date form received by agency: 07/28/2015
Site name: CVS PHARMACY #10407

CVS PHARMACY #10407 (Continued) **1016974653**

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

CVS PHARMACY #10407 (Continued) **1016974653**

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

. Waste code: U089
. Waste name: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

CVS PHARMACY #10407 (Continued) **1016974653**

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U151
. Waste name: MERCURY

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL (OR) RESORCINOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U206
. Waste name: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 07/16/2014
Site name: CVS PHARMACY #10407
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D004

CVS PHARMACY #10407 (Continued) **1016974653**

. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

CVS PHARMACY #10407 (Continued) **1016974653**

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

. Waste code: U089
. Waste name: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U151
. Waste name: MERCURY

CVS PHARMACY #10407 (Continued) **1016974653**

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL (OR) RESORCINOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U206
. Waste name: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 217

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN

CVS PHARMACY #10407 (Continued) **1016974653**

THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 47

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 24

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 39

Waste code: D010
Waste name: SELENIUM
Amount (Lbs): 24

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Amount (Lbs): 17

Waste code: P075
Waste name: NICOTINE, & SALTS
Amount (Lbs): 15

Waste code: U002
Waste name: ACETONE (I)
Amount (Lbs): 48

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000211128
Facility Status: Not reported
Location Address 1: 298 MULBERRY ST.
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MANHATTAN
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000211128
Mailing Name: CVS PHARMACY #10407
Mailing Contact: CVS PHARMACY #10407
Mailing Address 1: 298 MULBERRY ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10012
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CVS PHARMACY #10407 (Continued) **1016974653**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJD071629976
Generator Ship Date:	12/07/2017
Trans1 Recv Date:	12/07/2017
Trans2 Recv Date:	12/18/2017
TSD Site Recv Date:	12/18/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000211128
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	011309971FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	29
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
112 additional NY_MANIFEST: record(s) in the EDR Site Report.

T401 **CON EDISON** **RCRA NonGen / NLR** **1019908764**
ESE **82 E 4TH ST** **NYP004877155**
1/8-1/4 **NEW YORK, NY 10002**
0.157 mi.
827 ft. **Site 7 of 15 in cluster T**

Relative: **Lower**
Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/07/2015
Facility name:	CON EDISON
Facility address:	82 E 4TH ST NEW YORK, NY 10002
EPA ID:	NYP004877155
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/07/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

T402 **CON EDISON** **NJ MANIFEST** **S120677985**
ESE **82 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.157 mi.
827 ft. **Site 8 of 15 in cluster T**

Relative: **Lower**
Actual: **38 ft.**

NJ MANIFEST:

EPA Id:	NYP004877155
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

CON EDISON (Continued) **S120677985**

Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613601GBF
EPA ID:	NYP004877155
Date Shipped:	12/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AA403 **CON EDISON SERVICE BOX 501** **RCRA NonGen / NLR** **1015747006**
SSE **6 E 1ST ST** **NY MANIFEST** **NYP004250072**
1/8-1/4 **NEW YORK, NY 10003**
0.157 mi.
829 ft. **Site 2 of 5 in cluster AA**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/19/2012
Facility name:	CON EDISON SERVICE BOX 501
Facility address:	6 E 1ST ST NEW YORK, NY 10003
EPA ID:	NYP004250072
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/20/2012
Site name:	CON EDISON SERVICE BOX 501
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004250072
Facility Status:	Not reported
Location Address 1:	4 IRVING PLACE 15TH FLOOR
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003

CON EDISON SERVICE BOX 501 (Continued) **1015747006**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004250072
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/20/2012
Trans1 Recv Date: 03/20/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004250072
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 009203840JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

CON EDISON SERVICE BOX 501 (Continued) **1015747006**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AA404 **CON EDISON SERVICE BOX 501** **NJ MANIFEST** **S117985264**
SSE **6 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.157 mi.
829 ft. **Site 3 of 5 in cluster AA**

Relative:
Lower

Actual:
41 ft.

NJ MANIFEST:

EPA Id:	NYP004250072
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009203840JJK
EPA ID:	NYP004250072
Date Shipped:	3/20/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON SERVICE BOX 501 (Continued) **S117985264**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	500.00 Pounds

S405 **CON EDISON** **NY MANIFEST** **S117740475**
SW **305 MULBERRY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.157 mi.
830 ft. **Site 8 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004736435
Facility Status:	Not reported
Location Address 1:	305 MULBERRY ST
Code:	BP
Location Address 2:	MH 51586
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004736435
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117740475**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/23/2015
Trans1 Recv Date:	02/23/2015
Trans2 Recv Date:	03/03/2015
TSD Site Recv Date:	03/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004736435
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610677GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

S406 **CON EDISON** **NJ MANIFEST** **S120667709**
SW **305 MULBERRY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.157 mi.
830 ft. **Site 9 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004736435
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610677GBF
EPA ID:	NYP004736435
Date Shipped:	2/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667709**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

S407 **CON EDISON** **RCRA NonGen / NLR** **1018278859**
SW **305 MULBERRY ST** **FINDS** **NYP004736435**
1/8-1/4 **NEW YORK, NY 10013** **ECHO**
0.157 mi.
830 ft. **Site 10 of 10 in cluster S**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/23/2015
Facility name:	CON EDISON
Facility address:	305 MULBERRY ST NEW YORK, NY 10013
EPA ID:	NYP004736435
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/23/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1018278859**

Registry ID: 110067681789

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278859
Registry ID: 110067681789
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067681789

V408 **226 E. 6TH ST.** **NY AST** **A100382377**
East **226 E. 6TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.158 mi.
835 ft. **Site 9 of 15 in cluster V**

Relative:
Lower

Actual:
37 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-605634
Program Type: PBS
UTM X: 585332.23229
UTM Y: 4509022.54520
Expiration Date: N/A
Site Type: Storage Terminal/Petroleum Distributor

Tank Info:

Tank Number: 1
Tank Id: 60143
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/01/2000
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017
Material Name: Not reported

U409 **BAHMAN CLEANERS** **NY Spills** **1000295141**
West **210 MERCER ST** **RCRA NonGen / NLR** **NYD053264925**
1/8-1/4 **NEW YORK, NY 10012** **FINDS**
0.158 mi. **ECHO**
836 ft. **Site 5 of 10 in cluster U** **NY MANIFEST**

Relative:
Lower

Actual:
36 ft.

SPILLS:

Facility ID:	8904302
Facility Type:	ER
Spill Number:	8904302
DER Facility ID:	150515
Site ID:	179343
DEC Region:	2
Closed Date:	1989-07-31
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	1989-07-31
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1989-07-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-07-31
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-01
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BAHMAN CLEANERS
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SPILL ABSORBED WITH OLD RAGS. DEC(TAYLOR) CONDUCTS PHONE INVESTIGATION."

All Materials:

Site ID:	179343
Operable Unit ID:	932002
Operable Unit:	01
Material ID:	448356
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007

BAHMAN CLEANERS (Continued) **1000295141**

Facility name: BAHMAN CLEANERS
Facility address: 210 MERCER ST
NEW YORK, NY 10012-1518
EPA ID: NYD053264925
Mailing address: MERCER ST
NEW YORK, NY 10012
Contact: Not reported
Contact address: MERCER ST
NEW YORK, NY 10012
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MGN DRY CLEANERS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MGN DRY CLEANERS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

BAHMAN CLEANERS (Continued) **1000295141**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: BAHMAN CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BAHMAN CLEANERS
Classification: Not a generator, verified

Date form received by agency: 02/09/1987
Site name: BAHMAN CLEANERS
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004358971

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000295141
Registry ID: 110004358971
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004358971

NY MANIFEST:

BAHMAN CLEANERS (Continued) **1000295141**

Country:	USA
EPA ID:	NYD053264925
Facility Status:	Not reported
Location Address 1:	210 MERCER STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD053264925
Mailing Name:	SAHMAN CLEANERS
Mailing Contact:	SAHMAN CLEANERS
Mailing Address 1:	210 MERCER STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10009
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2120000000

NY MANIFEST:

Document ID:	NJA1924286
Manifest Status:	C
seq:	Not reported
Year:	1994
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	11/23/1994
Trans1 Recv Date:	11/23/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/23/1994
Part A Recv Date:	12/15/1994
Part B Recv Date:	12/08/1994
Generator EPA ID:	NYD053264925
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD000768093
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported

BAHMAN CLEANERS (Continued) **1000295141**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00120
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
81 additional NY_MANIFEST: record(s) in the EDR Site Report.

U410 **BAHMAN CLEANERS** **NY DRYCLEANERS** **S110245977**
West **210 MERCER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.158 mi.
836 ft. **Site 6 of 10 in cluster U**

Relative: DRYCLEANERS:
Lower

Actual:
36 ft.

Facility ID:	2-6205-00920
Phone Number:	212-260-4244
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	03OCT22
Install Date:	Not reported
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Z411 **SLOYER-FORMAN, INC.** **NY AST** **U003387471**
SE **21 EAST 2ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.158 mi.
836 ft. **Site 2 of 15 in cluster Z**

Relative: AST:
Lower

Actual:
40 ft.

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-291803
Program Type:	PBS
UTM X:	585237.19562
UTM Y:	4508750.47159
Expiration Date:	02/03/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	13247
Affiliation Type:	Mail Contact
Company Name:	SLOYER-FORMAN, INC.
Contact Type:	Not reported
Contact Name:	TOM BISAKI
Address1:	185 BROADWAY

SLOYER-FORMAN, INC. (Continued) **U003387471**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-24

Site Id:	13247
Affiliation Type:	Facility Operator
Company Name:	SLOYER-FORMAN,INC.
Contact Type:	Not reported
Contact Name:	WILFREDO COCOM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 716-8631
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-12-10

Site Id:	13247
Affiliation Type:	Emergency Contact
Company Name:	SLOYER-FORMAN, INC.
Contact Type:	Not reported
Contact Name:	TOM BISAKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 734-5865
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-24

Site Id:	13247
Affiliation Type:	Facility Owner
Company Name:	SLOYER-FORMAN, INC.
Contact Type:	PRESIDENT
Contact Name:	AMY RUBENSTIEN
Address1:	185 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-0500

SLOYER-FORMAN, INC. (Continued) **U003387471**

EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-01-24

Tank Info:

Tank Number: 001
Tank Id: 11925
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1942
Capacity Gallons: 3000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 01/24/2018
Material Name: #2 fuel oil (on-site consumption)

U412 **215 MERCER ST** **RCRA-CESQG** **1011863403**
West **215 MERCER ST** **NYN008019879**
1/8-1/4 **NEW YORK, NY 10012**
0.159 mi.
837 ft. **Site 7 of 10 in cluster U**

Relative: **Lower**
Actual: **36 ft.**

RCRA-CESQG:
Date form received by agency: 07/16/2008
Facility name: 215 MERCER ST
Facility address: 215 MERCER ST
NEW YORK, NY 10012-1518
EPA ID: NYN008019879
Mailing address: MERCER ST
NEW YORK, NY 10012-1518
Contact: Not reported
Contact address: MERCER ST
NEW YORK, NY 10012-1518
Contact country: US
Contact telephone: Not reported

215 MERCER ST (Continued) **1011863403**

Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/16/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

V413 **CON EDISON MANHOLE: 9640** **NJ MANIFEST** **S117986426**
East **235 W 5OTH ST FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10036**
0.160 mi.
844 ft. **Site 10 of 15 in cluster V**

Relative: NJ MANIFEST:
Lower
Actual: EPA Id: NYP004270179
37 ft. Mail Address: IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: BENJAMIN BAMONTE

CON EDISON MANHOLE: 9640 (Continued) **S117986426**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010457086JJK
EPA ID:	NYP004270179
Date Shipped:	9/24/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	500.00 Pounds

V414 **235 EAST 5TH STREET** **NY AST** **U003386444**
East **235 EAST 5TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.160 mi.
844 ft. **Site 11 of 15 in cluster V**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-241636
Program Type:	PBS
UTM X:	585332.02629
UTM Y:	4508958.00310
Expiration Date:	09/10/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9214
Affiliation Type:	Emergency Contact
Company Name:	235 EAST 5TH STREET LLC
Contact Type:	Not reported
Contact Name:	MICHAEL BLACK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 771-7117
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-22

Site Id:	9214
Affiliation Type:	Mail Contact
Company Name:	235 EAST 5TH STREET LLC
Contact Type:	Not reported
Contact Name:	MICHAEL BLACK
Address1:	OLD CHELSEA STATION
Address2:	P.O. BOX 1877
City:	NEW YORK
State:	NY
Zip Code:	10113
Country Code:	001
Phone:	(212) 858-9988
EMail:	MICHAEL@BROOKHILLPROP.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-22

Site Id:	9214
Affiliation Type:	Facility Operator
Company Name:	235 EAST 5TH STREET
Contact Type:	Not reported
Contact Name:	ELEDJIN KOVACI
Address1:	Not reported
Address2:	Not reported
City:	Not reported

235 EAST 5TH STREET (Continued) **U003386444**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 858-9988
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-22

Site Id: 9214
Affiliation Type: Facility Owner
Company Name: 235 EAST 5TH STREET LLC
Contact Type: MANAGER
Contact Name: MICHAEL BLACK
Address1: OLD CHELSEA STATION P.O. BOX 1877
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10113
Country Code: 001
Phone: (212) 858-8899
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-22

Tank Info:

Tank Number: 001
Tank Id: 9955
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1924
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

235 EAST 5TH STREET (Continued) **U003386444**

Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

AB415 **298 MULBERRY STREET** **NY AST** **A100292040**
SSW **298 MULBERRY STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.161 mi.
848 ft. **Site 8 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-607425
Program Type: PBS
UTM X: 584881.07704
UTM Y: 4508690.52095
Expiration Date: 12/19/2019
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 29277
Affiliation Type: Facility Operator
Company Name: 298 MULBERRY STREET
Contact Type: Not reported
Contact Name: NA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 460-8000
EMail: Not reported
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2017-01-28

Site Id: 29277
Affiliation Type: Emergency Contact
Company Name: 298 MULBERRY STREET OPERATING COMPLANY, LLC
Contact Type: Not reported
Contact Name: GAYLE KENNEDY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 609-3700 8006
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-01-27

Site Id: 29277

298 MULBERRY STREET (Continued) **A100292040**

Affiliation Type:	Mail Contact
Company Name:	298 MULBERRY STREET OPERATING COMPANY, LLC C/O BR
Contact Type:	Not reported
Contact Name:	GAYLE KENNEDY
Address1:	80 BROAD STREET, 2ND FLOOR
Address2:	Not reported
City:	NEW YORK CITY
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(212) 460-8000
EMail:	GAYLE K @BSDRE.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-01-28

Site Id:	29277
Affiliation Type:	Facility Owner
Company Name:	298 MULBERRY STREET OPERATING COMPANY, LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	GAYLE KENNEDY
Address1:	80 BROAD STREET, 2ND FLOOR
Address2:	Not reported
City:	NEW YORK CITY
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(212) 609-3700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-01-28

Tank Info:

Tank Number:	1
Tank Id:	62942
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A01 - Tank Internal Protection - Epoxy Liner
G99 - Tank Secondary Containment - Other
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

298 MULBERRY STREET (Continued) **A100292040**

Pipe Model:	Not reported
Install Date:	03/24/1988
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

V416 **ORDER OF ST BASIL** **NY AST** **U003385592**
ENE **215 E 6TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.162 mi.
854 ft. **Site 12 of 15 in cluster V**

Relative:
Lower

Actual:
38 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-148814
Program Type:	PBS
UTM X:	585321.10990
UTM Y:	4509077.27821
Expiration Date:	08/24/2017
Site Type:	School

Affiliation Records:

Site Id:	4457
Affiliation Type:	Facility Owner
Company Name:	ORDER OF ST BASIL THE GREAT
Contact Type:	PASTOR
Contact Name:	REV BERNARD PANCZUK
Address1:	30 E 7TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-1615
EMail:	BJPANCZUK@HOTMAIL.COM
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-06-18

Site Id:	4457
Affiliation Type:	Mail Contact
Company Name:	ORDER OF ST BASIL THE GREAT
Contact Type:	PASTOR
Contact Name:	REV BERNARD PANCZUK
Address1:	30 E 7TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001

ORDER OF ST BASIL (Continued) **U003385592**

Phone:	(212) 674-1615
EMail:	BJPANCZUK@HOTMAIL.COM
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-06-18

Site Id:	4457
Affiliation Type:	Facility Operator
Company Name:	ORDER OF ST BASIL
Contact Type:	Not reported
Contact Name:	ORDER OF ST BASIL/ST GEORGE CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 473-3323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-08-28

Site Id:	4457
Affiliation Type:	Emergency Contact
Company Name:	ORDER OF ST BASIL THE GREAT
Contact Type:	Not reported
Contact Name:	212-674-1615
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 231-4981
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-08-28

Tank Info:

Tank Number:	001
Tank Id:	8081
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

ORDER OF ST BASIL (Continued) **U003385592**

D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1958
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DXLIVING
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Z417 **CON EDISON** **RCRA NonGen / NLR** **1018277608**
SE **30 E 2ND ST** **FINDS** **NYP004723425**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.162 mi.
854 ft. **Site 3 of 15 in cluster Z**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/02/2015
Facility name:	CON EDISON
Facility address:	30 E 2ND ST NEW YORK, NY 10003
EPA ID:	NYP004723425
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1018277608**

Historical Generators:
Date form received by agency: 02/02/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067690298

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277608
Registry ID: 110067690298
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067690298

Z418 **CON EDISON** **NJ MANIFEST** **S120666544**
SE **30 E 2ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.162 mi.
854 ft. **Site 4 of 15 in cluster Z**

Relative: **Lower**
Actual: **40 ft.**

NJ MANIFEST:
EPA Id: NYP004723425
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002610299GBF
EPA ID: NYP004723425
Date Shipped: 2/2/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047

CON EDISON (Continued) **S120666544**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Z419 **CON EDISON** **NY MANIFEST** **S117739241**
SE **30 E 2ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.162 mi.
854 ft. **Site 5 of 15 in cluster Z**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004723425
Facility Status:	Not reported
Location Address 1:	30 E 2 ST
Code:	BP
Location Address 2:	SB543
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

CON EDISON (Continued) **S117739241**

EPAID:	NYP004723425
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/02/2015
Trans1 Recv Date:	02/02/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004723425
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610299GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported

CON EDISON (Continued) **S117739241**

Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

V420 **228 EAST 6TH STREET** **NY AST** **U003386459**
East **228 EAST 6TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.162 mi.
854 ft. **Site 13 of 15 in cluster V**

Relative:
Lower

Actual:
37 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-241938
Program Type: PBS
UTM X: 585291.10318
UTM Y: 4509079.26432
Expiration Date: 09/10/2020
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 9241
Affiliation Type: Emergency Contact
Company Name: 228 EAST 6TH STREET LLC
Contact Type: Not reported
Contact Name: MICHAEL BLACK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 771-7117
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-25

Site Id: 9241
Affiliation Type: Facility Operator
Company Name: 228 EAST 6TH STREET
Contact Type: Not reported
Contact Name: MOHAMED MOCTEZUMA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 858-9988
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA

228 EAST 6TH STREET (Continued) **U003386459**

Date Last Modified: 2016-01-25

Site Id: 9241
Affiliation Type: Facility Owner
Company Name: 228 EAST 6TH STREET LLC
Contact Type: MANAGER
Contact Name: MICHAEL BLACK
Address1: OLD CHELSEA STATION P.O. BOX 1877
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10113
Country Code: 001
Phone: (212) 858-9988
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-25

Site Id: 9241
Affiliation Type: Mail Contact
Company Name: 228 EAST 6TH STREET LLC
Contact Type: Not reported
Contact Name: MICHAEL BLACK
Address1: OLD CHELSEA STATION
Address2: P.O. BOX 1877
City: NEW YORK
State: NY
Zip Code: 10113
Country Code: 001
Phone: (212) 858-9988
EMail: MICHAEL@BROOKHILLPROP.COM
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-25

Tank Info:

Tank Number: 001
Tank Id: 10005
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

228 EAST 6TH STREET (Continued) **U003386459**

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1969
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AC421 **CON EDISON** **RCRA NonGen / NLR** **1019907427**
ESE **69 2ND AVE** **FINDS** **NYP004834012**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.162 mi.
855 ft. **Site 1 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/03/2015
Facility name:	CON EDISON
Facility address:	69 2ND AVE NEW YORK, NY 10003
EPA ID:	NYP004834012
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1019907427**

Historical Generators:
Date form received by agency: 09/03/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069693807

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019907427
Registry ID: 110069693807
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069693807

AC422 **CON EDISON** **NJ MANIFEST** **S120676296**
ESE **69 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.162 mi.
855 ft. **Site 2 of 33 in cluster AC**

Relative: **Lower**
Actual: **37 ft.**

NJ MANIFEST:
EPA Id: NYP004834012
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002613124GBF
EPA ID: NYP004834012
Date Shipped: 9/3/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047

CON EDISON (Continued) **S120676296**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Y423 **628 BROADWAY, SUITE 400** **NY AST** **A100292613**
WSW **628 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.162 mi.
856 ft. **Site 3 of 16 in cluster Y**

Relative: **Lower**
Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608650
Program Type:	PBS
UTM X:	584776.39537
UTM Y:	4508833.65113
Expiration Date:	01/01/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30502
Affiliation Type:	Mail Contact

628 BROADWAY, SUITE 400 (Continued) **A100292613**

Company Name:	628 BROADWAY, LLC
Contact Type:	Not reported
Contact Name:	SHARON KAMINER
Address1:	628 BROADWAY #400
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(646) 360-3663
EMail:	MGMT@628BROADWAY.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-12-29

Site Id:	30502
Affiliation Type:	Facility Operator
Company Name:	628 BROADWAY, SUITE 400
Contact Type:	Not reported
Contact Name:	JOFER ARAGON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 360-3663
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-12-29

Site Id:	30502
Affiliation Type:	Emergency Contact
Company Name:	628 BROADWAY , LLC
Contact Type:	Not reported
Contact Name:	SHARON KAMINER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 240-2025
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-14

Site Id:	30502
Affiliation Type:	Facility Owner
Company Name:	628 BROADWAY, LLC
Contact Type:	AGENT
Contact Name:	SHARON KAMINER
Address1:	140 DOGWOOD AVENUE
Address2:	Not reported
City:	ROSLYN HARBOR

628 BROADWAY, SUITE 400 (Continued) **A100292613**

State:	NY
Zip Code:	11576
Country Code:	001
Phone:	(646) 360-3663
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-12-29

Tank Info:

Tank Number:	001
Tank Id:	65441
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1975
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#4 fuel oil (on-site consumption)

AC424 **69 SECOND AVENUE, LLC** **NY AST** **U004045722**
ESE **69 2ND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.163 mi.
859 ft. **Site 3 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602930
Program Type:	PBS
UTM X:	585376.40583

69 SECOND AVENUE, LLC (Continued) **U004045722**

UTM Y: 4508874.19451
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 24885
Affiliation Type: Mail Contact
Company Name: 69 SECOND AVENUE, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 1847
Address2: Not reported
City: PARAMUS
State: NJ
Zip Code: 07653
Country Code: 001
Phone: (201) 363-1448
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-02

Site Id: 24885
Affiliation Type: Facility Operator
Company Name: 69 SECOND AVENUE, LLC
Contact Type: Not reported
Contact Name: HARRY NAZON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: N/A
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-02

Site Id: 24885
Affiliation Type: Emergency Contact
Company Name: 69 SECOND AVENUE, LLC
Contact Type: Not reported
Contact Name: JOHATHAN RUHL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 363-1448
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-02

Site Id: 24885
Affiliation Type: Facility Owner

69 SECOND AVENUE, LLC (Continued) **U004045722**

Company Name:	69 SECOND AVENUE, LLC
Contact Type:	MEMBER
Contact Name:	JONATHAN RUHL
Address1:	P.O. BOX 1847
Address2:	Not reported
City:	PARAMUS
State:	NJ
Zip Code:	07653
Country Code:	001
Phone:	(201) 363-1448
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-02-02

Tank Info:

Tank Number:	001
Tank Id:	52119
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2000
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AC425 **CON ED** **NY Spills** **U003396910**
ESE **69 2ND AVE** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.163 mi.
859 ft. **Site 4 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

SPILLS:

Facility ID:	0609744
Facility Type:	ER
Spill Number:	0609744
DER Facility ID:	323757
Site ID:	374049
DEC Region:	2
Closed Date:	2006-11-28
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2006-11-27
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-11-27
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-11-27
Spill Record Last Update:	2006-11-28
Spiller Name:	MIKE BULLOCK
Spiller Company:	MTA PROJECT
Spiller Address:	69TH AND 2ND AVE
Spiller Company:	001
Contact Name:	MIKE BULLOCK
DEC Memo:	"part of 2nd Ave subway project"
Remarks:	"FOUND DURING DRILLING:"

All Materials:

Site ID:	374049
Operable Unit ID:	1131733
Operable Unit:	01
Material ID:	2121444
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004834012

CON ED (Continued) **U003396910**

Facility Status:	Not reported
Location Address 1:	69 2ND AVE
Code:	BP
Location Address 2:	SB 53955
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004834012
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/03/2015
Trans1 Recv Date:	09/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004834012
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613124GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON ED (Continued) **U003396910**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AD426 **CON EDISON** **NY MANIFEST** **U003396430**
NNW **7 WASHINGTON TERR & 186TH ST S** **N/A**
1/8-1/4 **NEW YORK, NY 10033**
0.163 mi.
860 ft. **Site 1 of 12 in cluster AD**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004563722
Facility Status:	Not reported
Location Address 1:	7 WASHINGTON TERRACE
Code:	BP
Location Address 2:	SB49209
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10033
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004563722
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **U003396430**

Generator Ship Date:	06/13/2014
Trans1 Recv Date:	06/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004563722
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423786GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AD427 **7 WASHINGTON PLACE** **NY AST** **U004045727**
NNW **7 WASHINGTON PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.163 mi.
860 ft. **Site 2 of 12 in cluster AD**

Relative: AST:
Lower

Actual:
39 ft.

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602057
Program Type:	PBS

7 WASHINGTON PLACE (Continued) **U004045727**

UTM X:	584924.03810
UTM Y:	4509233.69650
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

Site Id:	24016
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-02-15

Site Id:	24016
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(732) 499-8051
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Site Id:	24016
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	14 WAVERLY PLACE
Address2:	2ND FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-02-28

Site Id: 24016

7 WASHINGTON PLACE (Continued) **U004045727**

Affiliation Type:	Facility Operator
Company Name:	7 WASHINGTON PLACE
Contact Type:	Not reported
Contact Name:	MICHAEL CALLAGHAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	48973
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/2003
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

T428 **CON EDISON** **NY MANIFEST** **S117066201**
SE **36 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.163 mi.
861 ft. **Site 9 of 15 in cluster T**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004588307
Facility Status:	Not reported
Location Address 1:	36 E 3RD ST
Code:	BP
Location Address 2:	SB 672
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004588307
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004588307
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503370GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117066201**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

U429 **88 BLEECKER ST OWNERS INC** **NY AST** **A100292838**
WSW **88 BLEECKER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.164 mi.
865 ft. **Site 8 of 10 in cluster U**

Relative: **Lower**
Actual: **38 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-267864
Program Type:	PBS
UTM X:	584780.34046
UTM Y:	4508918.86700
Expiration Date:	07/10/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	11135
Affiliation Type:	Facility Owner
Company Name:	88 BLEECKER ST OWNERS INC
Contact Type:	PROPERTY MANAGER
Contact Name:	GERARD PICASO
Address1:	88 BLEECKER ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 807-6969
EMail:	Not reported
Fax Number:	Not reported

88 BLEECKER ST OWNERS INC (Continued) **A100292838**

Modified By:	MFLEONAR
Date Last Modified:	2017-09-07
Site Id:	11135
Affiliation Type:	Mail Contact
Company Name:	GERARD J. PICASO,INC.
Contact Type:	Not reported
Contact Name:	GERARD PICASO
Address1:	770 LEXINGTON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10065
Country Code:	001
Phone:	(212) 807-6969
EMail:	GPICASO@HALSTEAD.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-09-07
Site Id:	11135
Affiliation Type:	Emergency Contact
Company Name:	88 BLEECKER ST OWNERS INC
Contact Type:	Not reported
Contact Name:	GERARD PISCASO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 807-6969
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-09-07
Site Id:	11135
Affiliation Type:	Facility Operator
Company Name:	88 BLEECKER ST OWNERS INC
Contact Type:	Not reported
Contact Name:	ANTONIO BENARRIVATO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 257-8532
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-09-05

Tank Info:

Tank Number:	001

88 BLEECKER ST OWNERS INC (Continued) **A100292838**

Tank Id: 13444
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/25/1995
Capacity Gallons: 7500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 09/07/2017
Material Name: #2 fuel oil (on-site consumption)

T430 **57 2ND AVE** **NY AST** **U003386377**
ESE **57 SECOND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.164 mi.
866 ft. **Site 10 of 15 in cluster T**

Relative:
Lower

Actual:
38 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-213829
Program Type: PBS
UTM X: 585304.18625
UTM Y: 4508817.02689
Expiration Date: 06/30/2017
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 7907
Affiliation Type: Facility Owner
Company Name: LUDMILLA LOZOUY
Contact Type: Not reported
Contact Name: Not reported
Address1: 116 ST MARK'S PL
Address2: Not reported
City: N Y C

57 2ND AVE (Continued) **U003386377**

State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 473-0037
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-12-16

Site Id: 7907
Affiliation Type: Mail Contact
Company Name: 52 SECOND AVENUE
Contact Type: Not reported
Contact Name: SUPER FACILITY MANAGER
Address1: 116 ST. MARKS PLACE
Address2: #2
City: NEW YORK
State: NY
Zip Code: 10009
Country Code: 001
Phone: (212) 473-0037
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-12-16

Site Id: 7907
Affiliation Type: Facility Operator
Company Name: 57 2ND AVE
Contact Type: Not reported
Contact Name: TARAS LOZOWY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 673-9127
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 7907
Affiliation Type: Emergency Contact
Company Name: LUDMILLA LOZOUY
Contact Type: Not reported
Contact Name: TARAS LOZOWY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 673-9121
EMail: Not reported
Fax Number: Not reported

57 2ND AVE (Continued) **U003386377**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 9810
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1980
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUG
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

AE431 **237 EAST REALTY LLC** **NY AST** **A100166527**
East **237 EAST 5TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.164 mi.
868 ft. **Site 1 of 11 in cluster AE**

Relative:
Lower

Actual:
37 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-314439
Program Type: PBS
UTM X: 585292.87477
UTM Y: 4508998.68474
Expiration Date: 06/16/2020
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 14333
Affiliation Type: Facility Owner

237 EAST REALTY LLC (Continued) **A100166527**

Company Name:	237 EAST REALTY LLC
Contact Type:	MANAGING AGENT
Contact Name:	GEORGE LAVIAN
Address1:	377 PARK AVENUE SOUTH, 8TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 213-2500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-07-01

Site Id:	14333
Affiliation Type:	Mail Contact
Company Name:	237 EAST REALTY LLC
Contact Type:	Not reported
Contact Name:	GEORGE LAVION
Address1:	377 PARK AVENUE SOUTH
Address2:	8TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 213-2500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	14333
Affiliation Type:	Emergency Contact
Company Name:	237 EAST REALTY LLC
Contact Type:	Not reported
Contact Name:	HONORIO SALAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 334-4406
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-19

Site Id:	14333
Affiliation Type:	Facility Operator
Company Name:	237 EAST REALTY LLC
Contact Type:	Not reported
Contact Name:	HONORIO SALAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported

237 EAST REALTY LLC (Continued) **A100166527**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-4642
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-19

Tank Info:

Tank Number:	001
Tank Id:	12789
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I01 - Overfill - Float Vent Valve
C01 - Pipe Location - Aboveground
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B05 - Tank External Protection - Jacketed

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1950
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

X432 **740 BROADWAY** **NY UST** **U004194404**
North **740 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.165 mi.
869 ft. **Site 5 of 13 in cluster X**

Relative: **Lower**
Actual: **39 ft.**

UST:

Id/Status:	2-208566 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585086.68412
UTM Y:	4509324.04391
Site Type:	Apartment Building/Office Building

740 BROADWAY (Continued) **U004194404**

Affiliation Records:

Site Id:	7458
Affiliation Type:	Facility Owner
Company Name:	LAFAYETTE ASTOR ASSOCS % NEWMARK GRUBB KNIGHT FRAN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	594 BROADWAY - RM 311
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-5751
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-03-31

Site Id:	7458
Affiliation Type:	Mail Contact
Company Name:	NEWMARK GRUBB KNIGHT FRANK
Contact Type:	Not reported
Contact Name:	ART D'ESTRADA
Address1:	594 BROADWAY
Address2:	ROOM 311
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 431-5751
EMail:	ADESTRATA@NGKF.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-10

Site Id:	7458
Affiliation Type:	Facility Operator
Company Name:	740 BROADWAY
Contact Type:	Not reported
Contact Name:	PAUL RUFO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 982-5734
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-03-31

Site Id:	7458
Affiliation Type:	Emergency Contact
Company Name:	LAFAYETTE ASTOR ASSOCS % NEWMARK GRUBB KNIGHT FRAN
Contact Type:	Not reported
Contact Name:	PAUL RUFO

740 BROADWAY (Continued) **U004194404**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 982-5734
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-03-31

Tank Info:

Tank Number:	001
Tank ID:	9703
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	12/01/1980
Date Tank Closed:	02/11/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

X433 **ABOVE GROUND TANK** **NY LTANKS** **S117364510**
North **740 BROADWAY** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.165 mi.
869 ft. **Site 6 of 13 in cluster X**

Relative: LTANKS:
Lower

Actual: Facility ID:	1406897
39 ft. Site ID:	500389
Closed Date:	2014-12-23
Spill Number:	1406897
Spill Date:	2014-09-30

ABOVE GROUND TANK (Continued) **S117364510**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2014-09-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-09-30
Spill Record Last Update:	2014-12-23
Spiller Name:	MIKE
Spiller Company:	UNKNOWN
Spiller Address:	740 BROADWAY
Spiller County:	999
Spiller Contact:	MIKE
Spiller Phone:	(917) 288-6195
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	455393
DEC Memo:	"10/01/14-Hiralkumar Patel. alternate address: 2-20 Astor Place, 740-744 Broadway, 436-450 Lafayette Street PBS #: 2-208566 for 740 Broadway. as per PBS record, the site has one 10,000 gal #6 oil UST, installed in Dec. 1980. PBS #: 2-242527 for 436-440 Lafayette Street. as per PBS record, site 436 has/had following tanks: - one (1) 7,500 gal #6 oil AST on saddles, removed in Aug. 2008 - one (1) 7,500 gal #2 oil AST on saddles, installed in Sep. 2008 other spills for 436-440 Lafayette St: 0713774, 1005946 spill # 0713774 was reported on 03/28/2008 due to tank test failure of #6 oil tank. test was failed due to two old lines connected to the tank. case closed. spill # 1005946 was reported on 08/30/2010 due to 5 gal of benzene from drip water. case closed. Lafayette-Astor Associates, LLC. **property owner** c/o Newmark Grubb Knight Frank 125 Park Avenue, 11th Floor New York, NY 10017 Attn.: Art Destrada **property manager** PH. (212) 372-2000 (203) 859-7301 email: adestrada@ngkf.com Paul Rufo **building super** Ph. (212) 982-2880 (917) 288-6195 (C) 2:37 PM:- left message for Paul. 10/15/14-Hiralkumar Patel. 10:52 AM:- left message for Mr. Destrada. 11:25 AM:- sent TTF letter to Mr. Destrada, requiring report submission by the end of 11/28/14. letter emailed to Mr. Destrada and James Coffey (jcoffey@ngkf.com). 12/18/14-Hiralkumar Patel. 2:45 PM:- spoke with Mr. Destrada. he mentioned that the leaking tank system is empty since it failed the test. the tank is located in room under the sidewalk. all the piping run aboveground, including fill line which crosses the sidewalk concrete. they have hired Ace Atlas to conduct soil investigation along the tank's bottom as the tank is sitting on surface. he will talk to the contractor and submit work schedule. 3:09 PM:- received call from Rob from Riteway, subcontractor working for Ace Atlas. they tried to drill four holes through tank's bottom, but got to soil underneath the floor in only one hole. there is 5 inches of concrete floor underneath the tank and

ABOVE GROUND TANK (Continued) **S117364510**

no oil stains observed on concrete or soil from the holes. as no petroleum staining noted in concrete underneath the tank (which was holding #6 oil), informed Rob that no further investigation is needed. asked him to send email including site observations. 12/23/14-Hiralkumar Patel. received email from Rob including site summary. based on available information, case closed."

Remarks: "empty tank tank test failure"

All Materials:

Site ID:	500389
Operable Unit ID:	1249797
Operable Unit:	01
Material ID:	2251424
Material Code:	9999
Material Name:	other - tank test fail
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

X434 **CON EDISON** **NY MANIFEST** **S117318173**
North **744 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.165 mi.
869 ft. **Site 7 of 13 in cluster X**

Relative: **Lower**

Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004656757
Facility Status:	Not reported
Location Address 1:	744 BROADWAY
Code:	BP
Location Address 2:	SERVICE BOX # 28830
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004656757
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **S117318173**

seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2014
Trans1 Recv Date:	09/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004656757
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609604GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

W435 **54-62 COOPERS SQUARE** **NY LTANKS** **S103940509**
NE **62 COOPERS SQUARE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.166 mi.
878 ft. **Site 5 of 6 in cluster W**

Relative: **Lower**

Actual: **40 ft.**

LTANKS:

Facility ID:	9811435
Site ID:	314704
Closed Date:	1999-05-10
Spill Number:	9811435
Spill Date:	1998-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1998-12-10
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-10
Spill Record Last Update:	1999-05-10
Spiller Name:	STEVE HORN
Spiller Company:	54-62 COOPERS SQUARE
Spiller Address:	62 COOPERS SQUARE
Spiller County:	001
Spiller Contact:	STEVE HORN
Spiller Phone:	(212) 794-1300
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	253726
DEC Memo:	""
Remarks:	"RECOMMEND TANK BE EMPTIED AND LINES BE ISOLATED AND RE-TESTED."

All TTF:

Facility ID:	9811435
Spill Number:	9811435
Spill Tank Test:	1546628
Site ID:	314704
Tank Number:	00000000000
Tank Size:	5000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

54-62 COOPERS SQUARE (Continued) **S103940509**

All Materials:

Site ID:	314704
Operable Unit ID:	1068827
Operable Unit:	01
Material ID:	311735
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

W436 **CON EDISON** **NY MANIFEST** **S117736386**
NE **62 COOPER SQUARE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.166 mi.
878 ft. **Site 6 of 6 in cluster W**

Relative: **Lower**

Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004504247
Facility Status:	Not reported
Location Address 1:	62 COOPER SQUARE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504247
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/2014
Trans1 Recv Date:	04/17/2014
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117736386**

TSD Site Recv Date:	04/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504247
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416748GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

T437 **CON EDISON** **NY MANIFEST** **S117066510**
ESE **86 E 4 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.167 mi.
881 ft. **Site 11 of 15 in cluster T**

Relative: NY MANIFEST:
Lower

Actual: Country:	USA
37 ft. EPA ID:	NYP004591673
Facility Status:	Not reported
Location Address 1:	86 E 4 ST
Code:	BP
Location Address 2:	MH 865
Total Tanks:	Not reported
Location City:	NEW YORK

CON EDISON (Continued) **S117066510**

Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591673
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591673
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423968GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117066510**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Y438 **CON EDISION - MH27224** **RCRA NonGen / NLR** **1007207680**
WSW **626 BROADWAY AND E.HOUSTON 626** **NY MANIFEST** **NYP004072955**
1/8-1/4 **NEW YORK, NY 10003**
0.167 mi.
881 ft. **Site 4 of 16 in cluster Y**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/02/2002
Facility name:	CON EDISION - MH27224
Facility address:	626 BROADWAY AND E.HOUSTON 626 NEW YORK, NY 10003
EPA ID:	NYP004072955
Mailing address:	IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/01/2002
Site name:	CON EDISION - MH27224

CON EDISION - MH27224 (Continued) **1007207680**

Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - MH27224
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004072955
Facility Status: Not reported
Location Address 1: MH27224-BROADWAY & HOUSTON
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004072955
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PL-RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: CTF0838003
Manifest Status: Not reported
seq: 01
Year: 2001
Trans1 State ID: 13014MA
Trans2 State ID: Not reported
Generator Ship Date: 02/08/2001
Trans1 Recv Date: 02/08/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/08/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004072955
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported
TSDF ID 1: CTD000604488
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

CON EDISION - MH27224 (Continued) **1007207680**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00003
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Y439 **CON EDISON MANHOLE 27227** **RCRA NonGen / NLR** **1010326436**
WSW **626 BROADWAY** **NY MANIFEST** **NYP004141164**
1/8-1/4 **NEW YORK, NY 10002**
0.167 mi.
881 ft. **Site 5 of 16 in cluster Y**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/30/2006
Facility name:	CON EDISON MANHOLE 27227
Facility address:	626 BROADWAY NEW YORK, NY 10002
EPA ID:	NYP004141164
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL D'AGOSTINO
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	917-559-8958
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON MANHOLE 27227 (Continued) **1010326436**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/29/2006
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 08/28/2006
Site name: CON EDISON
Classification: Unverified

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004141164
Facility Status: Not reported
Location Address 1: 626 BROADWAY MH27227
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10031
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004141164
Mailing Name: CONSOLIDAATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE1540935
Manifest Status: Not reported
seq: 01
Year: 2006
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/27/2006
Trans1 Recv Date: 03/27/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/29/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CON EDISON MANHOLE 27227 (Continued) **1010326436**

Generator EPA ID:	NYP004141164
Trans1 EPA ID:	12446JT
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z440 **32-34 E 2 ST** **NY AST** **U003384661**
SE **32-34 EAST 2ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.167 mi.
884 ft. **Site 6 of 15 in cluster Z**

Relative: **Lower**

Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-116742
Program Type:	PBS
UTM X:	585244.61754
UTM Y:	4508778.59008
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3944
Affiliation Type:	Facility Owner
Company Name:	32-34 E 2ND ST HDFC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	32-34 EAST 2ND ST

32-34 E 2 ST (Continued) **U003384661**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 675-3010
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-05-15

Site Id:	3944
Affiliation Type:	Mail Contact
Company Name:	ROBERT R CANCELLARE REALTY INC
Contact Type:	Not reported
Contact Name:	ROBERT R CANCELLARE
Address1:	152 NINTH AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212) 675-3010
EMail:	RCANCE9012@AOL.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-01-25

Site Id:	3944
Affiliation Type:	Facility Operator
Company Name:	32-34 EAST 2ND ST
Contact Type:	Not reported
Contact Name:	RICHARD CHANDLER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-3010
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-01-09

Site Id:	3944
Affiliation Type:	Emergency Contact
Company Name:	32-34 E 2ND ST HDFC
Contact Type:	Not reported
Contact Name:	ROBERT R CANCELLARE RLTY INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 675-3010

32-34 E 2 ST (Continued) **U003384661**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	4161
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1901
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/29/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AC441 **CON EDISON SERVICE BOX: 53956** **NJ MANIFEST** **S120666154**
ESE **73-75 2ND AVE & 4TH ST N OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.168 mi.
885 ft. **Site 5 of 33 in cluster AC**

Relative: **Lower**
Actual: **37 ft.**

NJ MANIFEST:

EPA Id:	NYP004492203
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported

CON EDISON SERVICE BOX: 53956 (Continued) **S120666154**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015318937JJK
EPA ID:	NYP004492203
Date Shipped:	2/26/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	CONSOLIDATED EDISON CO OF NY SB #53956
Transporter-1 EPA Facility Name:	CLEAN VENTURE INC
TSDF EPA Facility Name:	CYCLE CHEM INC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/26/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/26/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

T442 **CON EDISON** **NY MANIFEST** **S117066064**
SE **45 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.168 mi.
886 ft. **Site 12 of 15 in cluster T**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004863706
Facility Status:	Not reported
Location Address 1:	45 2ND AVE
Code:	BP
Location Address 2:	SB 53936
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004863706
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/2015
Trans1 Recv Date:	11/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004863706
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085918JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117066064**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP004586806
Facility Status:	Not reported
Location Address 1:	45 2ND AVE
Code:	BP
Location Address 2:	SB53936
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586806
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S117066064**

Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586806
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503426GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF443 **CON EDISON** **RCRA NonGen / NLR** **1019906442**
NW **29 W 4TH ST** **NYP004821118**
1/8-1/4 **NEW YORK, NY 10012**
0.168 mi.
888 ft. **Site 1 of 14 in cluster AF**

Relative: RCRA NonGen / NLR:
Lower
Date form received by agency: 08/10/2015
Actual: Facility name: CON EDISON
36 ft. Facility address: 29 W 4TH ST
NEW YORK, NY 10012

CON EDISON (Continued) **1019906442**

EPA ID: NYP004821118
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/10/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

AF444 **CON ED** **NY MANIFEST** **S118258780**
NW **29 W 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.168 mi.
888 ft. **Site 2 of 14 in cluster AF**

Relative: **Lower**
Actual: **36 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004821118
Facility Status: Not reported
Location Address 1: 29 WEST 4TH ST
Code: BP
Location Address 2: SB 824
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004821118

CON ED (Continued) **S118258780**

Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2015
Trans1 Recv Date:	08/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004821118
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612097GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON ED (Continued) **S118258780**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AF445 **CON EDISON** **NJ MANIFEST** **S120675210**
NW **29 W 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.168 mi.
888 ft. **Site 3 of 14 in cluster AF**

Relative:
Lower

Actual:
36 ft.

NJ MANIFEST:

EPA Id:	NYP004821118
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612097GBF
EPA ID:	NYP004821118
Date Shipped:	8/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120675210**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

U446 **CON EDISON** **NY MANIFEST** **S118463681**
WSW **96 BLEEKER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.169 mi.
893 ft. **Site 9 of 10 in cluster U**

Relative: **Lower**

Actual: **37 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004855470
Facility Status:	Not reported
Location Address 1:	96 BLEEKER ST
Code:	BP
Location Address 2:	SB 26570
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004855470
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015

CON EDISON (Continued) **S118463681**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855470
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085605JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Z447 **CON EDISON SERVICE BOX: 53935** **RCRA NonGen / NLR** **1016968030**
SE **41 E 2ND AVE** **NY MANIFEST** **NYP004416319**
1/8-1/4 **NEW YORK, NY 10002**
0.170 mi.
896 ft. **Site 7 of 15 in cluster Z**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	02/10/2014
Facility name:	CON EDISON SERVICE BOX: 53935
Facility address:	41 E 2ND AVE NEW YORK, NY 10002
EPA ID:	NYP004416319
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003

Actual:
39 ft.

CON EDISON SERVICE BOX: 53935 (Continued) **1016968030**

Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/10/2014
Site name: CON EDISON SERVICE BOX: 53935
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004416319
Facility Status: Not reported
Location Address 1: 41 2ND AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10002
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004416319
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

CON EDISON SERVICE BOX: 53935 (Continued) **1016968030**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/2014
Trans1 Recv Date:	01/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004416319
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328597GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z448 **CON EDISON** **NY MANIFEST** **S117066063**
SE **41 2 AV** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.170 mi.
896 ft. **Site 8 of 15 in cluster Z**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004586798
Facility Status:	Not reported
Location Address 1:	41 2 AV
Code:	BP
Location Address 2:	SB53953
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586798
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586798
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503427GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117066063**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

V449 **232 EQUITIES CORPORATION** **NY AST** **U003389546**
East **232 EAST 6TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.170 mi.
896 ft. **Site 14 of 15 in cluster V**

Relative: **Lower**
Actual: **37 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-197521
Program Type:	PBS
UTM X:	585295.09533
UTM Y:	4509077.31190
Expiration Date:	07/20/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6499
Affiliation Type:	Facility Operator
Company Name:	232 EQUITIES CORPORATION
Contact Type:	Not reported
Contact Name:	OLIVER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 896-8600
EMail:	Not reported
Fax Number:	Not reported

232 EQUITIES CORPORATION (Continued) **U003389546**

Modified By:	MFLEONAR
Date Last Modified:	2017-08-22
Site Id:	6499
Affiliation Type:	Emergency Contact
Company Name:	232 EQUITIES CORP. C/O THE ARGO CORP.
Contact Type:	Not reported
Contact Name:	JESSICA TUSING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 896-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-22
Site Id:	6499
Affiliation Type:	Facility Owner
Company Name:	232 EQUITIES CORP. C/O THE ARGO CORP.
Contact Type:	AGENT
Contact Name:	FRANK YAN
Address1:	50 W. 17TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 896-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-22
Site Id:	6499
Affiliation Type:	Mail Contact
Company Name:	ARGO REAL ESTATE
Contact Type:	Not reported
Contact Name:	JESSICA TUSING
Address1:	50 W 17TH ST
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10011
Country Code:	001
Phone:	(212)896-8600
EMail:	COMPLIANCE@ARGO.COM
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2018-02-22

Tank Info:

Tank Number:	001

232 EQUITIES CORPORATION (Continued) **U003389546**

Tank Id: 16882
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J05 - Dispenser - On Site Heating System (Supply/Return)
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/15/1985
Capacity Gallons: 3000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 08/22/2017
Material Name: #2 fuel oil (on-site consumption)

U450
West
1/8-1/4
0.172 mi.
908 ft.

CON EDISON SERVICE BOX: 41037 **RCRA NonGen / NLR** **1017771522**
226-28 MERCER ST & BLEECKER ST N OF **FINDS** **NYP004484622**
NEW YORK, NY 10012

Site 10 of 10 in cluster U

Relative:
Lower

Actual:
36 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/30/2014
Facility name: CON EDISON SERVICE BOX: 41037
Facility address: 226-28 MERCER ST & BLEECKER ST N OF
NEW YORK, NY 10012
EPA ID: NYP004484622
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CON EDISON SERVICE BOX: 41037 (Continued) **1017771522**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/31/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 03/31/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063782982

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AD451 **NYU** **NY AST** **U003383306**
NW **14 WASHINGTON PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.172 mi.
910 ft. **Site 3 of 12 in cluster AD**

Relative: **Lower**

Actual: **37 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-034932
Program Type: PBS
UTM X: 584882.16417

NYU (Continued) **U003383306**

UTM Y: 4509246.87224
Expiration Date: N/A
Site Type: School

Affiliation Records:

Site Id: 315
Affiliation Type: Facility Operator
Company Name: N Y U
Contact Type: Not reported
Contact Name: KEVIN HOLSTON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 477-3058
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 315
Affiliation Type: Facility Owner
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: Not reported
Address1: 70 WASHINGTON SQUARE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 998-1212
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-02-15

Site Id: 315
Affiliation Type: Emergency Contact
Company Name: NEW YORK UNIVERSITY
Contact Type: Not reported
Contact Name: NYU PUBLIC SAFETY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 998-222
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-04-24

Site Id: 315
Affiliation Type: Mail Contact

NYU (Continued) **U003383306**

Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL HEALTH & SAFETY
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-09

Tank Info:

Tank Number:	001
Tank Id:	944
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1980
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/13/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	945
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

NYU (Continued) **U003383306**

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1980
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/13/2013
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

Y452 **MOKLAM ENTERPRISES INC** **NY AST** **A100295135**
WSW **622 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.173 mi.
911 ft. **Site 6 of 16 in cluster Y**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607720
Program Type:	PBS
UTM X:	584765.60965
UTM Y:	4508816.65260
Expiration Date:	04/29/2017
Site Type:	Other

Affiliation Records:

Site Id:	29572
Affiliation Type:	Facility Owner
Company Name:	MOKLAM ENTERPRISES INC C/O YUCO MGT INC
Contact Type:	PRESIDENT
Contact Name:	YUCO MANAGEMENT INC.
Address1:	295 MADISON AVE, 34TH FL.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 994-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-03-28

Site Id:	29572
Affiliation Type:	Mail Contact
Company Name:	YUCO MANAGEMENT, INC.

MOKLAM ENTERPRISES INC (Continued) **A100295135**

Contact Type:	Not reported
Contact Name:	RAYMOND YU
Address1:	295 MADISON AVENUE
Address2:	34TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 994-2200
EMail:	INFO@YUCOINC.COM
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-02-07

Site Id:	29572
Affiliation Type:	Facility Operator
Company Name:	MOKLAM ENTERPRISES INC
Contact Type:	Not reported
Contact Name:	MOKLAM ENTERPRISES INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 994-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-03-28

Site Id:	29572
Affiliation Type:	Emergency Contact
Company Name:	MOKLAM ENTERPRISES INC C/O YUCO MGT INC
Contact Type:	Not reported
Contact Name:	RAYMOND YU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 994-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-03-28

Tank Info:

Tank Number:	001
Tank Id:	63415
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

MOKLAM ENTERPRISES INC (Continued) **A100295135**

I05 - Overfill - Vent Whistle
H99 - Tank Leak Detection - Other
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1978
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Y453 **MOKLAM ENTERPRISES INC C/O YUCO MGMT INC** **PA MANIFEST** **S118069766**
WSW **622 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.173 mi.
911 ft. **Site 7 of 16 in cluster Y**

Relative: **Lower**

Actual: **40 ft.**

Manifest Details:

Year:	2014
Manifest Number:	011980561JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000213413
Generator Date:	11/11/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	212-994-2200
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Waste Quantity:	5000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Y454 **MOKLAM BUILDING** **RCRA NonGen / NLR** **1016974880**
WSW **622 BROADWAY** **NY MANIFEST** **NYR000213413**
1/8-1/4 **NEW YORK, NY 10012**
0.173 mi.
911 ft. **Site 8 of 16 in cluster Y**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/09/2015
Facility name:	MOKLAM BUILDING
Facility address:	622 BROADWAY ENTIRE BUILDING NEW YORK, NY 10012
EPA ID:	NYR000213413
Mailing address:	BROADWAY ENTIRE BUILDING NEW YORK, NY 10012
Contact:	ARISMENDY CIPRIAN
Contact address:	MANAGEMENT INC 200 PARK AVE 11TH FL NEW YORK, NY 10166
Contact country:	US
Contact telephone:	212-994-2200
Telephone ext.:	202
Contact email:	INFO@YUCOINC.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MOKLAM ENTERPRISES INC
Owner/operator address:	PARK AVE 11TH FL NEW YORK, NY 10166
Owner/operator country:	US
Owner/operator telephone:	212-994-2200
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	12/13/1982
Owner/Op end date:	Not reported

Owner/operator name:	YUCO MANAGEMENT INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/03/1989
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

MOKLAM BUILDING (Continued) **1016974880**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 10/03/2014
Site name: MOKLAM BUILDING
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000213413
Facility Status: Not reported
Location Address 1: 622 BROADWAY ENTIRE BUILDING
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000213413
Mailing Name: MOKLAM BUILDING
Mailing Contact: MOLDAM ENTERPRISES C/O YUCO MGMT
Mailing Address 1: 200 PARK AVE - FLOOR 11
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10166
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129942000

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014

MOKLAM BUILDING (Continued) **1016974880**

Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	11/11/2014
Trans1 Recv Date:	11/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000213413
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	011980561JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5440
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Y455 **BEST BUY** **RCRA-CESQG** **1014399293**
WSW **622 BROADWAY** **NY MANIFEST** **NYR000173773**
1/8-1/4 **NEW YORK, NY 10012**
0.173 mi.
911 ft. **Site 9 of 16 in cluster Y**

Relative:
Lower

Actual:
40 ft.

RCRA-CESQG:

Date form received by agency:	04/09/2010
Facility name:	BEST BUY
Facility address:	622 BROADWAY NEW YORK, NY 10012
EPA ID:	NYR000173773
Mailing address:	BROADWAY YUCO MANAGEMENT INC NEW YORK, NY 10012
Contact:	NAVINA SABNANI
Contact address:	MADISON AVE - 34TH FLOOR NEW YORK, NY 10017
Contact country:	US
Contact telephone:	212-994-2200
Telephone ext.:	200
Contact email:	NAVINA.SABNANI@YUCOINC.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MOKLAM ENTERPRISES INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/27/1982
Owner/Op end date:	Not reported

Owner/operator name:	MOKLAM ENTERPRISES INC
Owner/operator address:	MADISON AVE - 34TH FLOOR NEW YORK, NY 10017
Owner/operator country:	US
Owner/operator telephone:	212-994-2200
Owner/operator email:	Not reported

BEST BUY (Continued) **1014399293**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/27/1982
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000173773
Facility Status: Not reported
Location Address 1: 622 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000173773
Mailing Name: BEST BUY
Mailing Contact: YUCO MANAGEMENT INC.
Mailing Address 1: 295 MADISON AVENUE 34TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10012
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129942200

NY MANIFEST:
Document ID: Not reported

BEST BUY (Continued) **1014399293**

Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/2010
Trans1 Recv Date:	08/26/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000173773
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	007321684JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC456 **99 E 4 ST** **NY AST** **U003395767**
ESE **99 EAST 4TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.173 mi.
914 ft. **Site 6 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600847
Program Type:	PBS
UTM X:	585427.78243
UTM Y:	4508819.10889
Expiration Date:	07/20/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22819
Affiliation Type:	Mail Contact
Company Name:	% FIRST SERVICE RESIDENTIAL
Contact Type:	Not reported
Contact Name:	99 EAST 4TH ST. CORP.
Address1:	622 THIRD AVENUE
Address2:	14TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 634-8900
EMail:	MATT.RESNICK@FSRESIDENTIAL.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-10-07

Site Id:	22819
Affiliation Type:	Facility Operator
Company Name:	99 E 4 ST
Contact Type:	Not reported
Contact Name:	ELUTERIO GARRIGA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 729-8533
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-10-07

Site Id:	22819
Affiliation Type:	Emergency Contact
Company Name:	99 E. 4TH ST APARTMENT CORP.
Contact Type:	Not reported
Contact Name:	MATT RESNICK
Address1:	Not reported
Address2:	Not reported
City:	Not reported

99 E 4 ST (Continued) **U003395767**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 634-8900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-10-07

Site Id: 22819
Affiliation Type: Facility Owner
Company Name: 99 E. 4TH ST APARTMENT CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 99 EAST 4TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 673-4326
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-10-07

Tank Info:

Tank Number: 1
Tank Id: 44035
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1929
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

99 E 4 ST (Continued) **U003395767**

Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AC457 **CON EDISON** **NY MANIFEST** **S116550801**
ESE **73-75 2ND AVE & 4TH ST N OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.173 mi.
915 ft. **Site 7 of 33 in cluster AC**

Relative: **Lower**

Actual: **37 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004492203
Facility Status:	Not reported
Location Address 1:	73 2ND AVE
Code:	BP
Location Address 2:	SB53956
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004492203
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/2014
Trans1 Recv Date:	04/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004492203
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406236GBF
Import Indicator:	N
Export Indicator:	N

CON EDISON (Continued) **S116550801**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

X458 **CON EDISON SERVICE BOX: 28834** **RCRA NonGen / NLR** **1016966706**
North **749-51 W BROADWAY** **NY MANIFEST** **NYP004395513**
1/8-1/4 **NEW YORK, NY 10009**
0.174 mi.
919 ft. **Site 8 of 13 in cluster X**

Relative: **Lower**

Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 28834
Facility address:	749-51 W BROADWAY NEW YORK, NY 10009
EPA ID:	NYP004395513
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON SERVICE BOX: 28834 (Continued) **1016966706**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 28834
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395513
Facility Status: Not reported
Location Address 1: 749 BROADWAY
Code: BP
Location Address 2: SB28834
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395513
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2013

CON EDISON SERVICE BOX: 28834 (Continued) **1016966706**

Trans1 Recv Date:	11/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395513
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237679GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AB459 **CON EDISON** **RCRA NonGen / NLR** **1018278716**
SSW **316 MOTT ST & HOUSTON ST** **FINDS** **NYP004734976**
1/8-1/4 **NEW YORK, NY 10013** **ECHO**
0.174 mi.
919 ft. **Site 9 of 12 in cluster AB**

Relative: **Higher**
Actual: **43 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/22/2015
Facility name:	CON EDISON
Facility address:	316 MOTT ST & HOUSTON ST NEW YORK, NY 10013
EPA ID:	NYP004734976
Mailing address:	IRVING PL, 15TH FL NE

CON EDISON (Continued) **1018278716**

NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/22/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067709910

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278716
Registry ID: 110067709910
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067709910

AA460 **CON EDISON** **NY MANIFEST** **S117066477**
SSE **9 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.175 mi.
923 ft. **Site 4 of 5 in cluster AA**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591301
Facility Status:	Not reported
Location Address 1:	9 E 1ST ST
Code:	BP
Location Address 2:	SB 503
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591301
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591301
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423975GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117066477**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

T461 **EAST VILLAGE REALTY COMPANY** **NY AST** **A100173687**
SE **53 2ND AVENUE A/K/A** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.175 mi.
925 ft. **Site 13 of 15 in cluster T**

Relative: **Lower**
Actual: **38 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604946
Program Type:	PBS
UTM X:	585339.88259
UTM Y:	4508803.83189
Expiration Date:	01/03/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	26815
Affiliation Type:	Facility Owner
Company Name:	EAST VILLAGE REALTY CO.
Contact Type:	PRESIDENT
Contact Name:	DAVID GATENIO
Address1:	40 WEST 39TH ST, SUITE #1
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 221-1118
EMail:	Not reported
Fax Number:	Not reported

EAST VILLAGE REALTY COMPANY (Continued) **A100173687**

Modified By: NTFREEMA
Date Last Modified: 2015-12-21

Site Id: 26815
Affiliation Type: Mail Contact
Company Name: EAST VILLAGE REALTY CO.
Contact Type: Not reported
Contact Name: DAVID GATENIO
Address1: 40 WEST 39TH ST
Address2: SUITE #1
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 221-1118
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-12-21

Site Id: 26815
Affiliation Type: Facility Operator
Company Name: EAST VILLAGE REALTY COMPANY
Contact Type: Not reported
Contact Name: SUPER ELY FOLCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 351-1415
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2010-10-14

Site Id: 26815
Affiliation Type: Emergency Contact
Company Name: EAST VILLAGE REALTY CO.
Contact Type: Not reported
Contact Name: DAVID GATENIO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 699-7781
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-12-07

Tank Info:

Tank Number: 001

EAST VILLAGE REALTY COMPANY (Continued) **A100173687**

Tank Id:	59219
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/01/1980
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

V462 **ORDER OF ST. BASIL** **NY AST** **U003385824**
ENE **16-22 E 7TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.175 mi.
926 ft. **Site 15 of 15 in cluster V**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-149691
Program Type:	PBS
UTM X:	585325.55584
UTM Y:	4509182.84531
Expiration Date:	06/18/2022
Site Type:	Other

Affiliation Records:

Site Id:	4532
Affiliation Type:	Mail Contact
Company Name:	ORDER OF ST BASIL THE GREAT
Contact Type:	Not reported
Contact Name:	EMILIAN DOROSH
Address1:	30 E 7TH ST
Address2:	Not reported
City:	NEW YORK
State:	NY

ORDER OF ST. BASIL (Continued) **U003385824**

Zip Code:	10003
Country Code:	001
Phone:	(212) 674-1615
EMail:	EMILIANEUROPE@HOTMAIL.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Site Id:	4532
Affiliation Type:	Facility Operator
Company Name:	ORDER OF ST. BASIL
Contact Type:	Not reported
Contact Name:	ORDER OF ST. BASIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 674-1615
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2006-08-28

Site Id:	4532
Affiliation Type:	Emergency Contact
Company Name:	ORDER OF ST BASIL THE GREAT
Contact Type:	Not reported
Contact Name:	EMILIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 650-3615
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-08-18

Site Id:	4532
Affiliation Type:	Facility Owner
Company Name:	ORDER OF ST BASIL THE GREAT
Contact Type:	ADMINISTRATOR
Contact Name:	ORDER OF ST BASIL THE GREAT FATHER EMILIAN DOROSH
Address1:	30 E 7TH ST
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-1615
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY

ORDER OF ST. BASIL (Continued) **U003385824**

Date Last Modified: 2017-08-18

Tank Info:

Tank Number: 001
Tank Id: 8658
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/16/1978
Capacity Gallons: 2000
Tightness Test Method: 21
Date Test: 08/09/2006
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMPOKRZY
Last Modified: 08/18/2017
Material Name: #2 fuel oil (on-site consumption)

AC463 **CON EDISON SERVICE BOX: 53955** **RCRA NonGen / NLR** **1017772263**
ESE **69-71 2ND AVE & 4TH ST N OF** **NYP004492195**
1/8-1/4 **NEW YORK, NY 10003**
0.176 mi.
927 ft. **Site 8 of 33 in cluster AC**

Relative: RCRA NonGen / NLR:
Lower Date form received by agency: 05/07/2014
Facility name: CON EDISON SERVICE BOX: 53955
Actual: Facility address: 69-71 2ND AVE & 4TH ST N OF
37 ft. NEW YORK, NY 10003
EPA ID: NYP004492195
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported

CON EDISON SERVICE BOX: 53955 (Continued) **1017772263**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/07/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/07/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

AC464 **CON EDISON** **NY MANIFEST** **S116550800**
ESE **69-71 2ND AVE & 4TH ST N OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.176 mi.
927 ft. **Site 9 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004492195
Facility Status: Not reported
Location Address 1: 69 2 AVE
Code: BP
Location Address 2: SB53955
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004492195
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK

CON EDISON (Continued) **S116550800**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/2014
Trans1 Recv Date:	04/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004492195
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406237GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S116550800**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AD465 **NEW YORK UNIVERSITY** **NY AST** **U003383307**
NNW **15 WASHINGTON PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.176 mi.
929 ft. **Site 4 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-034940
Program Type:	PBS
UTM X:	584896.29431
UTM Y:	4509252.02992
Expiration Date:	12/30/2021
Site Type:	School

Affiliation Records:

Site Id:	316
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	STEPHANIE KUNG
Address1:	10 ASTOR PLACE
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	STEPHANIE.KUNG@NYU.EDU
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-11-16

Site Id:	316
Affiliation Type:	Facility Operator
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	WALTER BUBNIAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3424
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-03-06

Site Id:	316
Affiliation Type:	Facility Owner

NEW YORK UNIVERSITY (Continued) **U003383307**

Company Name:	NEW YORK UNIVERSITY
Contact Type:	ASSISTANT DIRECTOR
Contact Name:	STEPHANIE KUNG
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-11-29

Site Id:	316
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	MELISA PUGLISI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 454-0561
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-02

Tank Info:

Tank Number:	001
Tank Id:	946
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J05 - Dispenser - On Site Heating System (Supply/Return)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

NEW YORK UNIVERSITY (Continued) **U003383307**

Install Date:	01/01/1976
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Y466 **AMOCO GAS STATION** **NY LTANKS** **S104516686**
SW **620 BROADWAY** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.177 mi.
933 ft. **Site 10 of 16 in cluster Y**

Relative: **Lower**
Actual: **41 ft.**

LTANKS:

Facility ID:	9913713
Site ID:	187139
Closed Date:	2001-07-11
Spill Number:	9913713
Spill Date:	2000-03-06
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-03-06
CID:	323
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-03-06
Spill Record Last Update:	2001-07-11
Spiller Name:	Not reported
Spiller Company:	AMOCO GAS STATION
Spiller Address:	620 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	156376
DEC Memo:	""
Remarks:	"FD ON SCENE. ATTEMPT TO CONTAIN. CLEAN UP CREW, FROM GAS CO, IS RESPONDING."

All Materials:

Site ID:	187139
Operable Unit ID:	1092159
Operable Unit:	01

AMOCO GAS STATION (Continued) **S104516686**

Material ID:	295545
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9913711
Facility Type:	ER
Spill Number:	9913711
DER Facility ID:	156376
Site ID:	187138
DEC Region:	2
Closed Date:	2000-04-03
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2000-03-06
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-03-06
CID:	389
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2000-03-06
Spill Record Last Update:	2000-06-12
Spiller Name:	Not reported
Spiller Company:	AMOCO GAS STATION
Spiller Address:	610 BROADWAY
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"filling tanks and the automatic shut off valve malfunctioned causing the spill of material. Spill being cleaned up at this time. REFER TO 0000928."

All Materials:

Site ID:	187138
Operable Unit ID:	1092157
Operable Unit:	01
Material ID:	295543
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

AMOCO GAS STATION (Continued) **S104516686**

Quantity: 12.00
Units: G
Recovered: 12.00
Oxygenate: Not reported

AC467 **CON EDISON** **NY MANIFEST** **S117065990**
ESE **EAST 4 ST & 2ND AV** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.177 mi.
934 ft. **Site 10 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004585980
Facility Status: Not reported
Location Address 1: EAST 4 ST & 2ND AV
Code: BP
Location Address 2: SB869
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004585980
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/04/2014
Trans1 Recv Date: 07/04/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004585980
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002503244GBF
Import Indicator: N

CON EDISON (Continued) **S117065990**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC468
ESE
1/8-1/4
0.177 mi.
934 ft.

CON EDISON SERVICE BOX: 847
E 4TH ST & 2 ND AVE
NEW YORK, NY 10003

RCRA NonGen / NLR **1016974190**
NY MANIFEST **NYP004480034**

Site 11 of 33 in cluster AC

Relative:
Lower

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/26/2014
Facility name:	CON EDISON SERVICE BOX: 847
Facility address:	E 4TH ST & 2 ND AVE NEW YORK, NY 10003
EPA ID:	NYP004480034
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON SERVICE BOX: 847 (Continued) **1016974190**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/26/2014
Site name: CON EDISON SERVICE BOX: 847
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004480034
Facility Status: Not reported
Location Address 1: E 4 & 2 AVE
Code: BP
Location Address 2: SB847
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004480034
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported

CON EDISON SERVICE BOX: 847 (Continued) **1016974190**

Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480034
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406127GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC469 **CON EDISON SERVICE BOX: 53958** **RCRA NonGen / NLR** **1017772266**
ESE **83-85 2ND AVE & 4TH ST N OF** **FINDS** **NYP004492229**
1/8-1/4 **NEW YORK, NY 10003**
0.177 mi.
934 ft. **Site 12 of 33 in cluster AC**

Relative: RCRA NonGen / NLR:
Lower
Date form received by agency: 05/07/2014
Actual: Facility name: CON EDISON SERVICE BOX: 53958
37 ft. Facility address: 83-85 2ND AVE & 4TH ST N OF
NEW YORK, NY 10003
EPA ID: NYP004492229

CON EDISON SERVICE BOX: 53958 (Continued) **1017772266**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/07/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/07/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063769426

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AC470 **CON EDISON SERVICE BOX: 53957** **RCRA NonGen / NLR** **1017772265**
ESE **79 2ND AVE & 4TH ST N OF** **FINDS** **NYP004492211**
1/8-1/4 **NEW YORK, NY 10003**
0.177 mi.
934 ft. **Site 13 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/07/2014
Facility name:	CON EDISON SERVICE BOX: 53957
Facility address:	79 2ND AVE & 4TH ST N OF NEW YORK, NY 10003
EPA ID:	NYP004492211
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/07/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/07/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063769417

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON SERVICE BOX: 53957 (Continued) **1017772265**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AC471 **CON EDISON SERVICE BOX: 53956** **RCRA NonGen / NLR** **1017772264**
ESE **73-75 2ND AVE & 4TH ST N OF** **FINDS** **NYP004492203**
1/8-1/4 **NEW YORK, NY 10003**
0.177 mi.
934 ft. **Site 14 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/07/2014
Facility name:	CON EDISON SERVICE BOX: 53956
Facility address:	73-75 2ND AVE & 4TH ST N OF NEW YORK, NY 10003
EPA ID:	NYP004492203
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/07/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/07/2014
Site name:	CON EDISON

CON EDISON SERVICE BOX: 53956 (Continued) **1017772264**

Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063769408

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AG472 **CON EDISON SERVICE BOX: 1216** **RCRA NonGen / NLR** **1017771659**
ENE **30 E 7TH ST & HALL PL E OF** **FINDS** **NYP004486007**
1/8-1/4 **NEW YORK, NY 10003**
0.177 mi.
936 ft. **Site 1 of 7 in cluster AG**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/01/2014
Facility name:	CON EDISON SERVICE BOX: 1216
Facility address:	30 E 7TH ST & HALL PL E OF NEW YORK, NY 10003
EPA ID:	NYP004486007
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

CON EDISON SERVICE BOX: 1216 (Continued) **1017771659**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/01/2014
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 04/01/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110063790107

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

T473 **CON EDISON MANHOLE 53942** **RCRA NonGen / NLR** **1014926549**
SE **E 3RD ST & 2ND AVE SE COR** **NJ MANIFEST** **NYP004243226**
1/8-1/4 **NEW YORK, NY 10003** **NY MANIFEST**
0.177 mi.
937 ft. **Site 14 of 15 in cluster T**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:
Date form received by agency: 11/14/2011
Facility name: CON EDISON MANHOLE 53942
Facility address: E 3RD ST & 2ND AVE SE COR
NEW YORK, NY 10003
EPA ID: NYP004243226
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 347-865-5931
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON MANHOLE 53942 (Continued) **1014926549**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/15/2011
Site name:	CON EDISON MANHOLE 53942
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004243226
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655483JJK
EPA ID:	NYP004243226
Date Shipped:	10/15/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON MANHOLE 53942 (Continued) **1014926549**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1,000.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004243226
Facility Status:	Not reported
Location Address 1:	E3RD ST
Code:	BP
Location Address 2:	2ND AVE
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004243226
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON MANHOLE 53942 (Continued) **1014926549**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2011
Trans1 Recv Date:	10/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004243226
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655483JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Y474 **627 BROADWAY** **NY AST** **U003387728**
WSW **627 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.177 mi.
937 ft. **Site 11 of 16 in cluster Y**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-202800
Program Type:	PBS
UTM X:	584754.21242
UTM Y:	4508838.80092
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6965
Affiliation Type:	Facility Owner
Company Name:	RENAISSANCE 627 BROADWAY LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	633 BROADWAY, 7TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 477-3165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-05-31

Site Id:	6965
Affiliation Type:	Mail Contact
Company Name:	RENAISSANCE 627 BROADWAY LLC
Contact Type:	Not reported
Contact Name:	KENNETH FISHEL
Address1:	632 BROADWAY - 7TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 477-3165
EMail:	EJOZA@RPNY.COM
Fax Number:	Not reported
Modified By:	EJCALIFA
Date Last Modified:	2007-05-23

Site Id:	6965
Affiliation Type:	Facility Operator
Company Name:	627 BROADWAY
Contact Type:	Not reported
Contact Name:	KENNETH FISHEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported

627 BROADWAY (Continued) **U003387728**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-3165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	6965
Affiliation Type:	Emergency Contact
Company Name:	RENAISSANCE 627 BROADWAY LLC
Contact Type:	Not reported
Contact Name:	ROBERT FISHEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-3164
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	12478
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E01 - Piping Secondary Containment - Diking (AG only)
D00 - Pipe Type - No Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1995
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/03/2010

627 BROADWAY (Continued) **U003387728**

Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #6 fuel oil (on-site consumption)

Y475 **JIM HENSON CO THE** **RCRA NonGen / NLR** **1008404463**
WSW **627 BROADWAY - 9TH FLOOR** **NY MANIFEST** **NYR000134601**
1/8-1/4 **NEW YORK, NY 10012**
0.177 mi.
937 ft. **Site 12 of 16 in cluster Y**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: JIM HENSON CO THE
Facility address: 627 BROADWAY - 9TH FLOOR
NEW YORK, NY 10012
EPA ID: NYR000134601
Mailing address: BROADWAY - 9TH FLOOR
NEW YORK, NY 10012
Contact: JASON M SECK
Contact address: BROADWAY - 9TH FLOOR
NEW YORK, NY 10012
Contact country: US
Contact telephone: 212-439-7419
Contact email: JSECK@HENSON.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/01/2004
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/01/2004
Owner/Op end date: Not reported

JIM HENSON CO THE (Continued) **1008404463**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: JIM HENSON CO THE
Classification: Not a generator, verified

Date form received by agency: 09/20/2005
Site name: JIM HENSON CO THE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000134601
Facility Status: Not reported
Location Address 1: 627 BROADWAY - 9TH FLOOR
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

JIM HENSON CO THE (Continued) **1008404463**

NY MANIFEST:

EPAID:	NYR000134601
Mailing Name:	JIM HENSON CO THE
Mailing Contact:	JIM HENSON CO THE
Mailing Address 1:	627 BROADWAY - 9TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10012
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124397572

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	03/30/2009
Trans1 Recv Date:	03/30/2009
Trans2 Recv Date:	04/07/2009
TSD Site Recv Date:	04/08/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134601
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	001030927SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001

JIM HENSON CO THE (Continued) **1008404463**

Waste Code 1_2:	D035
Waste Code 1_3:	D005
Waste Code 1_4:	D006
Waste Code 1_5:	D007
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AF476 **CON EDISON** **NY MANIFEST** **S116550378**
NW **WEST 4TH AVE & GREENE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.177 mi.
937 ft. **Site 4 of 14 in cluster AF**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004487526
Facility Status:	Not reported
Location Address 1:	WEST 4TH ST & GREENE
Code:	BP
Location Address 2:	SB 824
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004487526
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/2014
Trans1 Recv Date:	04/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S116550378**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407223GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF477 **CON EDISON SERVICE BOX: 826** **RCRA NonGen / NLR** **1017771808**
NW **WEST 4TH AVE & GREENE ST** **FINDS** **NYP004487534**
1/8-1/4 **NEW YORK, NY 10014**
0.177 mi.
937 ft. **Site 5 of 14 in cluster AF**

Relative: **Lower**

Actual: **35 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/02/2014
Facility name:	CON EDISON SERVICE BOX: 826
Facility address:	WEST 4TH AVE & GREENE ST SB826 NEW YORK, NY 10014
EPA ID:	NYP004487534
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON SERVICE BOX: 826 (Continued) **1017771808**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/02/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/02/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063799199

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AF478 **CON EDISON** **NY MANIFEST** **S116550379**
NW **WEST 4TH AVE & GREENE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.177 mi.
937 ft. **Site 6 of 14 in cluster AF**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004487534
Facility Status:	Not reported
Location Address 1:	WEST 4TH & GREENE ST
Code:	BP
Location Address 2:	SB 826
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004487534
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/2014
Trans1 Recv Date:	04/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487534
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407222GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S116550379**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF479 **CON EDISON SERVICE BOX: 820** **RCRA NonGen / NLR** **1017771806**
NW **WEST 4TH AVE & GREENE ST** **NYP004487518**
1/8-1/4 **NEW YORK, NY 10014**
0.177 mi.
937 ft. **Site 7 of 14 in cluster AF**

Relative: **Lower**

Actual: **35 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/02/2014
Facility name:	CON EDISON SERVICE BOX: 820
Facility address:	WEST 4TH AVE & GREENE ST SB820 NEW YORK, NY 10014
EPA ID:	NYP004487518
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON SERVICE BOX: 820 (Continued) **1017771806**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/02/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/02/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

AF480 **CON EDISON** **NY MANIFEST** **S116550377**
NW **WEST 4TH AVE & GREENE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10014**
0.177 mi.
937 ft. **Site 8 of 14 in cluster AF**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004487518
Facility Status:	Not reported
Location Address 1:	WEST 4TH ST & GREENE
Code:	BP
Location Address 2:	SB 820
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004487518
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON (Continued) **S116550377**

Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/2014
Trans1 Recv Date:	04/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487518
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407224GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF481
NW
1/8-1/4
0.177 mi.
937 ft.

CON EDISON SERVICE BOX: 824
WEST 4TH AVE & GREENE ST
NEW YORK, NY 10014

Site 9 of 14 in cluster AF

RCRA NonGen / NLR | **1017771807** | **NYP004487526**

Relative:
Lower

Actual:
35 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/02/2014
Facility name:	CON EDISON SERVICE BOX: 824
Facility address:	WEST 4TH AVE & GREENE ST SB824 NEW YORK, NY 10014
EPA ID:	NYP004487526
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/02/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/02/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

T482 **CON EDISON** **NY MANIFEST** **S117067289**
SE **E 3 ST & 2 AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.178 mi.
939 ft. **Site 15 of 15 in cluster T**

Relative:
Lower

Actual:
38 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004600508
Facility Status:	Not reported
Location Address 1:	E 3 ST & 2 AVE
Code:	BP
Location Address 2:	SB 53944
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004600508
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/18/2014
Trans1 Recv Date:	07/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004600508
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608388GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117067289**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF483 **CON EDISON SERVICE BOX: 35990** **RCRA NonGen / NLR** **1017771829**
NW **237 GREENE ST & 4TH ST N OF** **FINDS** **NYP004487740**
1/8-1/4 **NEW YORK, NY 10003**
0.178 mi.
939 ft. **Site 10 of 14 in cluster AF**

Relative: **Lower**
Actual: **35 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/03/2014
Facility name:	CON EDISON SERVICE BOX: 35990
Facility address:	237 GREENE ST & 4TH ST N OF NEW YORK, NY 10003
EPA ID:	NYP004487740
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON SERVICE BOX: 35990 (Continued) **1017771829**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/03/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/03/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063799402

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AH484 **COOPER UNION SCHOOL OF ART/FOUNDATION BLDG** **RCRA-SQG** **1001460225**
NNE **50 ASTOR PL** **FINDS** **NYR000066779**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.178 mi.
940 ft. **Site 1 of 23 in cluster AH**

Relative:
Lower

Actual:
39 ft.

RCRA-SQG:

Date form received by agency:	02/03/2010
Facility name:	COOPER UNION SCHOOL OF ART/FOUNDATION BLDG
Facility address:	50 ASTOR PL NEW YORK, NY 10003
EPA ID:	NYR000066779
Mailing address:	COOPER SQ NEW YORK, NY 10003
Contact:	ROGER TOOZE
Contact address:	COOPER SQ NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-353-4161
Contact email:	Not reported
EPA Region:	02

COOPER UNION SCHOOL OF ART/FOUNDATION BLDG (Continued) **1001460225**

Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: THE COOPER UNION
Owner/operator address: 7 E 7TH ST
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-353-4150
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: THE COOPER UNION
Owner/operator address: 7 E 7TH ST
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-353-4150
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Site name: COOPER UNION FOR THE ADVAN THE
Classification: Small Quantity Generator

COOPER UNION SCHOOL OF ART/FOUNDATION BLDG (Continued) **1001460225**

Date form received by agency: 01/01/2006
Site name: COOPER UNION FOR THE ADVAN THE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2001
Site name: COOPER UNION FOR THE ADVANCEMENT
Classification: Large Quantity Generator

Date form received by agency: 02/08/1999
Site name: COOPER UNION FOR THE ADVAN THE
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/27/2017
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004550815

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001460225
Registry ID: 110004550815
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004550815

AH485 **COOPER UNION ADVANCEMENT SCIENCE & ART** **NY MANIFEST** **S119078587**
NNE **50 ASTOR PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.178 mi.
940 ft. **Site 2 of 23 in cluster AH**

Relative: **Lower**
Actual: **39 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYR000066779
Facility Status: Not reported
Location Address 1: FOUNDATION BUILDING
Code: BP

COOPER UNION ADVANCEMENT SCIENCE & ART (Continued) **S119078587**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	N/S
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000066779
Mailing Name:	COOPER UNION ADVANCEMENT SCIENCE & ART
Mailing Contact:	JOHNNIE LYNCH
Mailing Address 1:	50 ASTOR PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123534161

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NYR000052373
Trans2 State ID:	NYD049178296
Generator Ship Date:	11/14/2017
Trans1 Recv Date:	11/14/2017
Trans2 Recv Date:	11/21/2017
TSD Site Recv Date:	12/05/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000066779
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD083377010
TSDF ID 2:	Not reported
Manifest Tracking Number:	010516229FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400

COOPER UNION ADVANCEMENT SCIENCE & ART (Continued) **S119078587**

Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
61 additional NY_MANIFEST: record(s) in the EDR Site Report.

AD486 **285 MERCER STREET** **NY AST** **U004045345**
NNW **285 MERCER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.179 mi.
943 ft. **Site 5 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-601833
Program Type:	PBS
UTM X:	584934.71654
UTM Y:	4509245.25381
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

Site Id:	23795
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-02-15

Site Id:	23795
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	JOSEPH STERN
Address1:	Not reported
Address2:	Not reported

285 MERCER STREET (Continued) **U004045345**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 874-7748
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23795
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY - ENVIR. SERVICES DEPARTMENT
Contact Type:	Not reported
Contact Name:	JOSEPH STERN
Address1:	64 WEST THIRD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1423
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23795
Affiliation Type:	Facility Operator
Company Name:	285 MERCER STREET
Contact Type:	Not reported
Contact Name:	LEE PAGE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	47997
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

285 MERCER STREET (Continued) **U004045345**

F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

X487 **CON EDISON** **NY MANIFEST** **S117314298**
North **292 MERCER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.179 mi.
945 ft. **Site 9 of 13 in cluster X**

Relative: **Lower**

Actual: **37 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004613451
Facility Status:	Not reported
Location Address 1:	292 MERCER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004613451
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S117314298**

Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2014
Trans1 Recv Date:	07/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004613451
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608693GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AD488 **11 WAVERLY ASSOC** **NY LTANKS** **S103238385**
NNW **11 WAVERLY PL** **N/A**
1/8-1/4 **NEW YORK, NY**
0.179 mi.
947 ft. **Site 6 of 12 in cluster AD**

Relative: LTANKS:
Lower

Facility ID:	9801971
Site ID:	178153
Closed Date:	2005-11-21
Spill Number:	9801971

Actual:
37 ft.

11 WAVERLY ASSOC (Continued) **S103238385**

Spill Date:	1998-05-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RPRUTLAN
Referred To:	Not reported
Reported to Dept:	1998-05-15
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-15
Spill Record Last Update:	2005-11-21
Spiller Name:	PETER JACOBSON
Spiller Company:	11 WAVERLY ASSOC
Spiller Address:	11 WAVERLY PL
Spiller County:	001
Spiller Contact:	PETER JACOBSON
Spiller Phone:	(212) 533-1300
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	149634
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/18/04 - AUSTIN - SWITCHED FROM TOMASELLO - END Transferred to Rutland during the Spill Reduction Initiative 9/19/05 Spoke to Protest Enterprises (631) 321-4670. They will look up records and get back to me. - Rutland 9/22/05 Spoke to Jim Leddy from Protest. They had no further involvement in this. -Rutland 11/21/05 Spoke to Frank Nieves (212)533-1300 of Waverly Associates. Region 2 called him about this in Sept. 2004. He told them the tank is above ground and they said they would send someone out to verify but never did. Tank has always been above ground. No product leaked, failure came from cover. Closed. - Rutland"
Remarks:	"appears to be manhole cover"

All TTF:

Facility ID:	9801971
Spill Number:	9801971
Spill Tank Test:	1545901
Site ID:	178153
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

11 WAVERLY ASSOC (Continued) **S103238385**

Last Modified Date: Not reported

All Materials:
Site ID: 178153
Operable Unit ID: 1059876
Operable Unit: 01
Material ID: 323879
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AD489 **ELEVEN WAVERLY ASSOCIATES** **NY AST** **U001834536**
NNW **11 WAVERLY PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.179 mi.
947 ft. **Site 7 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-292222
Program Type: PBS
UTM X: 584965.39508
UTM Y: 4509295.11992
Expiration Date: 07/07/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 13284
Affiliation Type: Facility Owner
Company Name: ELEVEN WAVERLY ASSOC.
Contact Type: SENIOR PROPERTY MANAGER
Contact Name: TAMMY RICE
Address1: 11 WAVERLY PLACE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 533-1300
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-07-31

Site Id: 13284
Affiliation Type: Mail Contact
Company Name: ELEVEN WAVERLY ASSOCIATES
Contact Type: Not reported
Contact Name: PETER JAKOBSON
Address1: 11 WAVERLY PLACE

ELEVEN WAVERLY ASSOCIATES (Continued) **U001834536**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 533-1300
EMail:	PROPERTYMANAGEMENT@JAKOBSON.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-31

Site Id:	13284
Affiliation Type:	Facility Operator
Company Name:	ELEVEN WAVERLY ASSOCIATES
Contact Type:	Not reported
Contact Name:	MIKE MUSKAT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 533-1300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2012-06-06

Site Id:	13284
Affiliation Type:	Emergency Contact
Company Name:	ELEVEN WAVERLY ASSOC.
Contact Type:	Not reported
Contact Name:	MIKE MUSCAT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 533-1300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-31

Tank Info:

Tank Number:	001
Tank Id:	12026
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination

ELEVEN WAVERLY ASSOCIATES (Continued) **U001834536**

G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1928
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	07/31/2017
Material Name:	#2 fuel oil (on-site consumption)

AB490 **CONED** **NY MANIFEST** **S109825136**
SSW **MOTT ST & HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.180 mi.
948 ft. **Site 10 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004174702
Facility Status:	Not reported
Location Address 1:	MOTT ST & HOUSTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004174702
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	ROOM 818
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported

CONED (Continued) **S109825136**

Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/30/2009
Trans1 Recv Date:	06/30/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004174702
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001083992GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AI491 **NYCTA - BROADWAY & LAFAYETTE STATION** **RCRA-SQG** **1001079810**
SW **E HOUSTON & CROSBY ST** **NY MANIFEST** **NYR000015172**
1/8-1/4 **NEW YORK, NY 10002**
0.180 mi.
952 ft. **Site 1 of 23 in cluster AI**

Relative:
Higher

Actual:
42 ft.

RCRA-SQG:

Date form received by agency:	10/16/2017
Facility name:	NYCTA - BROADWAY & LAFAYETTE STATION
Facility address:	E HOUSTON & CROSBY ST NEW YORK, NY 10002
EPA ID:	NYR000015172
Mailing address:	BROADWAY 27TH FLOOR A27.73 NEW YORK, NY 10002
Contact:	DANIEL YU
Contact address:	BROADWAY 27TH FLOOR A27.73 NEW YORK, NY 10002
Contact country:	US
Contact telephone:	646-252-5777
Contact email:	DANIEL.YU@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	BROADWAY NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-5777
Owner/operator email:	DANIEL.YU@NYCT.COM
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1900
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	BROADWAY NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-5777
Owner/operator email:	DANIEL.YU@NYCT.COM
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1900
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address:	370 JAY ST ROOM 809 BROOKLYN, NY 11201
Owner/operator country:	Not reported

NYCTA - BROADWAY & LAFAYETTE STATION (Continued) **1001079810**

Owner/operator telephone: 718-243-4581
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 01/01/2007
Site name: NYCTA - BROADWAY & LAFAYETTE STATION
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: NYCTA - BROADWAY & LAFAYETTE STATION
Classification: Not a generator, verified

Date form received by agency: 10/20/1995
Site name: NYCTA - BROADWAY & LAFAYETTE STATION
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000015172
Facility Status: Not reported
Location Address 1: E HOUSTON & CROSBY STREETS
Code: BP
Location Address 2: Not reported

NYCTA - BROADWAY & LAFAYETTE STATION (Continued) **1001079810**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000015172
Mailing Name:	NYCTA BROADWAY & LAFAYETTE STATION
Mailing Contact:	HOWARD MATZA
Mailing Address 1:	370 JAY STREET/ROOM 809
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182434581

NY MANIFEST:

Document ID:	CTF0901916
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2000
Trans1 Recv Date:	03/28/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000015172
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)

NYCTA - BROADWAY & LAFAYETTE STATION (Continued) **1001079810**

Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AD492 **NEW YORK UNIVERSITY - 12-16 WAVERLY PLACE** **RCRA-SQG** **1011863494**
NNW **12-16 WAVERLY PL** **NY MANIFEST** **NYR000160069**
1/8-1/4 **NEW YORK, NY 10003**
0.181 mi.
954 ft. **Site 8 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

RCRA-SQG:
Date form received by agency: 07/29/2013
Facility name: NEW YORK UNIVERSITY - 12-16 WAVERLY PLACE
Facility address: 12-16 WAVERLY PL
NEW YORK, NY 10003
EPA ID: NYR000160069
Mailing address: ENVIRONMENTAL HEALTH & SAFETY
10 ASTOR PL - 6TH FLOOR
NEW YORK, NY 10003
Contact: STEPHANIE M KUNG
Contact address: ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-998-1450
Contact email: STEPHANIE.KUNG@NYU.EDU
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: WASHINGTON SQUARE SOUTH
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: Not reported

NEW YORK UNIVERSITY - 12-16 WAVERLY PLACE (Continued) **1011863494**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR

NEW YORK UNIVERSITY - 12-16 WAVERLY PLACE (Continued) **1011863494**

MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

. Waste code: U188
. Waste name: PHENOL

Historical Generators:
Date form received by agency: 12/01/2009
Site name: NYU - 12-16 WAVERLY PLACE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 10/01/2008
Site name: NEW YORK UNIVERSITY
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004791612
Facility Status: Not reported
Location Address 1: 12 WAVERLY PL
Code: BP
Location Address 2: MH 49501
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004791612
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NEW YORK UNIVERSITY - 12-16 WAVERLY PLACE (Continued) **1011863494**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/2015
Trans1 Recv Date:	06/08/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004791612
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614383GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

X493 **CONSOLIDATED EDISON - MH 60264** **NY MANIFEST** **S111157737**
North **BROADWAY & ASTOR PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10004**
0.181 mi.
956 ft. **Site 10 of 13 in cluster X**

Relative:
Lower

Actual:
38 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004231072
Facility Status:	Not reported
Location Address 1:	BROADWAY & ASTOR PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10004
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004231072
Mailing Name:	CONSOLIDATED EDISON - MH 60264
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/15/2011
Trans1 Recv Date:	03/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/16/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004231072
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001442385FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CONSOLIDATED EDISON - MH 60264 (Continued) **S111157737**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	45.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	D007
Waste Code 1_3:	D006
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC494 **77 SECOND LLC** **NY AST** **U003392128**
ESE **77 2ND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.181 mi.
957 ft. **Site 15 of 33 in cluster AC**

Relative: **Lower**
Actual: **36 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-214965
Program Type:	PBS
UTM X:	585348.82231
UTM Y:	4508898.48001
Expiration Date:	03/21/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8011
Affiliation Type:	Facility Operator
Company Name:	77 SECOND LLC
Contact Type:	Not reported
Contact Name:	CHARLES CARROLL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 685-3982
EMail:	Not reported
Fax Number:	Not reported

77 SECOND LLC (Continued) **U003392128**

Modified By:	KXTANG
Date Last Modified:	2005-03-21
Site Id:	8011
Affiliation Type:	Emergency Contact
Company Name:	77 SECOND LLC
Contact Type:	Not reported
Contact Name:	CHARLES CARROLL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 685-3982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-21
Site Id:	8011
Affiliation Type:	Facility Owner
Company Name:	77 SECOND LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	BILLY GILROY
Address1:	240 WEST 35TH ST. SUITE 504
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 685-3982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-17
Site Id:	8011
Affiliation Type:	Mail Contact
Company Name:	77 SECOND LLC
Contact Type:	Not reported
Contact Name:	MICHAEL KANE
Address1:	240 WEST 35TH ST. SUITE 504
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 685-3982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-17

Tank Info:

Tank Number:	001

77 SECOND LLC (Continued) **U003392128**

Tank Id: 23603
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1980
Capacity Gallons: 2500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

AA495 **AVALON BOWERY PLACE I** **NY AST** **A100300879**
SSE **11 EAST FIRST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.182 mi.
959 ft. **Site 5 of 5 in cluster AA**

Relative:
Lower

Actual:
41 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610503
Program Type: PBS
UTM X: 585143.50046
UTM Y: 4508676.20999
Expiration Date: 08/23/2020
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 377778
Affiliation Type: Facility Owner
Company Name: CVP II, LLC
Contact Type: MAINTENANCE MANAGER
Contact Name: KAMIL KONOPKA
Address1: 11 EAST 1ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003

AVALON BOWERY PLACE I (Continued) **A100300879**

Country Code:	001
Phone:	(212) 387-7720
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-21

Site Id:	377778
Affiliation Type:	Mail Contact
Company Name:	AVALONBAY COMMUNITIES
Contact Type:	Not reported
Contact Name:	KAMIL KONOPKA
Address1:	11 EAST 1ST STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 387-7720
EMail:	KAMIL_KONOPKA@AVALONBAY.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-21

Site Id:	377778
Affiliation Type:	Facility Operator
Company Name:	AVALON BOWERY PLACE I
Contact Type:	Not reported
Contact Name:	KAMIL KONOPKA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 387-7720 214
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-21

Site Id:	377778
Affiliation Type:	Emergency Contact
Company Name:	CVP II, LLC
Contact Type:	Not reported
Contact Name:	KAMIL KONOPKA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 623-2590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-08-21

AVALON BOWERY PLACE I (Continued) **A100300879**

Tank Info:

Tank Number:	001
Tank Id:	216148
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E12 - Piping Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A01 - Tank Internal Protection - Epoxy Liner
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/23/2005
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AE496 **CON EDISON** **NY MANIFEST** **S117066338**
East **95 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.182 mi.
963 ft. **Site 2 of 11 in cluster AE**

Relative: **Lower**
Actual: **36 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004589800
Facility Status:	Not reported
Location Address 1:	95 2ND AVE
Code:	BP
Location Address 2:	SB 53968
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004589800
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117066338**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004589800
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608181GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117066338**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AG497 **CON EDISON** **NY MANIFEST** **S118463745**
NE **61 COOPER SQ** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.183 mi.
965 ft. **Site 2 of 7 in cluster AG**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856447
Facility Status:	Not reported
Location Address 1:	61 COOPER SQ
Code:	BP
Location Address 2:	SB 30969
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856447
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856447
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087624JJK
Import Indicator:	N

CON EDISON (Continued) **S118463745**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Z498 **PETCO STORE #5816** **RCRA-CESQG 1016451784**
SE **31 2ND AVE** **FINDS NYR000203760**
1/8-1/4 **NEW YORK, NY 10002** **ECHO**
0.183 mi.
965 ft. **Site 9 of 15 in cluster Z**

Relative: RCRA-CESQG:
Lower

Date form received by agency:	05/22/2015
Facility name:	PETCO STORE #5816
Facility address:	31 2ND AVE NEW YORK, NY 10002
EPA ID:	NYR000203760
Mailing address:	RICHLAND HILLS DR SAN ANTONIO, TX 78245
Contact:	AMY EBERSOLE-MARTIN
Contact address:	RICHLAND HILLS DR SAN ANTONIO, TX 78245
Contact country:	US
Contact telephone:	210-201-9217
Contact email:	SAFETY@PETCO.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar

Actual:
40 ft.

PETCO STORE #5816 (Continued) **1016451784**

month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	PETCO STORE #5816
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/01/2015
Owner/Op end date:	Not reported

Owner/operator name:	MAGNUM REAL ESTATE GROUP
Owner/operator address:	BROADWAY SUITE 1010
	NEW YORK, NY 10012
Owner/operator country:	US
Owner/operator telephone:	212-942-9399
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/12/2012
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

PETCO STORE #5816 (Continued) **1016451784**

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Historical Generators:
Date form received by agency: 10/30/2013
Site name: PETCO STORE #5816
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

FINDS:

Registry ID: 110056331376

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

PETCO STORE #5816 (Continued) **1016451784**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016451784
Registry ID:	110056331376
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056331376

AD499 **CON EDISON** **RCRA NonGen / NLR** **1019903926**
NNW **12 WAVERLY PL** **NYP004791612**
1/8-1/4 **NEW YORK, NY 10003**
0.183 mi.
968 ft. **Site 9 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/08/2015
Facility name:	CON EDISON
Facility address:	12 WAVERLY PL NEW YORK, NY 10003
EPA ID:	NYP004791612
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/08/2015

CON EDISON (Continued) **1019903926**

Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

AD500 **CON EDISON** **NJ MANIFEST** **S120672559**
NNW **12 WAVERLY PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.183 mi.
968 ft. **Site 10 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

NJ MANIFEST:

EPA Id:	NYP004791612
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614383GBF
EPA ID:	NYP004791612
Date Shipped:	6/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON (Continued) **S120672559**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AD501 **NEW YORK UNIVERSITY - ENVIRONMENTAL SERVICES** **NY MANIFEST** **S119079029**
NNW **12-16 WAVERLY PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.183 mi.
968 ft. **Site 11 of 12 in cluster AD**

Relative:
Lower

Actual:
37 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYR000160069
Facility Status:	Not reported
Location Address 1:	12 -16 WAVERLY PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000160069
Mailing Name:	NEW YORK UNIVERSITY - ENVIRONMENTAL SERVICES
Mailing Contact:	ZACK KORENSTEIN
Mailing Address 1:	10 ASTOR PLACE 6TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129981439

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	MAC300016672
Trans2 State ID:	OHD980614374
Generator Ship Date:	06/30/2017
Trans1 Recv Date:	06/30/2017
Trans2 Recv Date:	07/06/2017
TSD Site Recv Date:	07/14/2017
Part A Recv Date:	Not reported

NEW YORK UNIVERSITY - ENVIRONMENTAL SERVICES (Continued) **S119079029**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000160069
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	010967418FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
96 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH502 **CON EDISON VAULT: 9653** **RCRA-CESQG** **1000110318**
NNE **51 ASTOR PL** **FINDS** **NYD980766604**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.185 mi. **NY MANIFEST**
979 ft. **Site 3 of 23 in cluster AH**

Relative: RCRA-CESQG:
Lower

Date form received by agency:	01/19/2016
Facility name:	CVS PHARMACY #10828
Facility address:	51 ASTOR PL NEW YORK, NY 10003
EPA ID:	NYD980766604
Mailing address:	CVS DR WOONSOCKET, RI 02895
Contact:	NICOLE WILKINSON
Contact address:	CVS DR MAIL CODE 2340 WOONSOCKET, RI 02895

Actual:
39 ft.

CON EDISON VAULT: 9653 (Continued) **1000110318**

Contact country: US
Contact telephone: 401-770-7132
Contact email: NICOLE.WILKINSON@CVSHEALTH.COM
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: CITY OF NEW YORK
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CVS ALBANY PHARMACY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/19/2015
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW YORK
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator

CON EDISON VAULT: 9653 (Continued) **1000110318**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JSM ASSOCIATES I LLC
Owner/operator address: AVENUE OF THE AMERICAS
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: 212-554-0500
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/21/1958
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

CON EDISON VAULT: 9653 (Continued) **1000110318**

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

. Waste code: U035

CON EDISON VAULT: 9653 (Continued) **1000110318**

. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U059
. Waste name: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

. Waste code: U089
. Waste name: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U151
. Waste name: MERCURY

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL (OR) RESORCINOL

CON EDISON VAULT: 9653 (Continued) **1000110318**

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U206
. Waste name: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Historical Generators:
Date form received by agency: 01/01/2007
Site name: NYC DEPT OF ENVIR PROT-BUR SCI & TECH
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: NYC DEPT OF ENVIR PROT-BUR SCI & TECH
Classification: Not a generator, verified

Date form received by agency: 02/21/1984
Site name: NYC DEPT OF ENVIR PROT-BUR SCI & TECH
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110060174449

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON VAULT: 9653 (Continued) **1000110318**

corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000110318
Registry ID:	110060174449
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110060174449

Envid:	1000110318
Registry ID:	110004390686
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004390686

NY MANIFEST:

Country:	USA
EPA ID:	NYD980766604
Facility Status:	Not reported
Location Address 1:	51 ASTOR PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD980766604
Mailing Name:	NYCDEP
Mailing Contact:	DR EDWARD F FERRAND
Mailing Address 1:	51 ASTOR PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2125668977

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	PAD982661381
Trans2 State ID:	NJD071629976
Generator Ship Date:	09/29/2017
Trans1 Recv Date:	09/29/2017
Trans2 Recv Date:	10/11/2017
TSD Site Recv Date:	10/11/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980766604
Trans1 EPA ID:	Not reported

CON EDISON VAULT: 9653 (Continued) **1000110318**

Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010767772FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D007
Waste Code 1_3:	D010
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
89 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP000778514
Facility Status:	Not reported
Location Address 1:	51 ASTOR PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000778514
Mailing Name:	NYCDEP
Mailing Contact:	S. SIEBENBERG
Mailing Address 1:	37-80 REVIEW AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY

CON EDISON VAULT: 9653 (Continued) **1000110318**

Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2125668977

NY MANIFEST:

Document ID:	NYO3073977
Manifest Status:	C
seq:	Not reported
Year:	1983
Trans1 State ID:	NY2A004
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/1983
Trans1 Recv Date:	08/24/1983
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/24/1983
Part A Recv Date:	09/12/2003
Part B Recv Date:	09/12/2003
Generator EPA ID:	NYP000778514
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049178296
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00054
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported

CON EDISON VAULT: 9653 (Continued) **1000110318**

Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00350
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Waste Code:	D000 - NON-LISTED TOXIC WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100
Waste Code:	D000 - NON-LISTED TOXIC WASTES
Quantity:	00150
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	Not reported
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH503 **NYCDEP - HAZARDOUS MATERIAL LAB** **RCRA NonGen / NLR** **1000187318**
NNE **51 ASTOR PL RM 643** **FINDS** **NYD986896686**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.185 mi. **NY MANIFEST**
979 ft. **Site 4 of 23 in cluster AH**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCDEP - HAZARDOUS MATERIAL LAB
Facility address:	51 ASTOR PL RM 643 NEW YORK, NY 10003-7132
EPA ID:	NYD986896686
Mailing address:	ASTOR PL RM 643 NEW YORK, NY 10003
Contact:	Not reported
Contact address:	ASTOR PL RM 643 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

NYCDEP - HAZARDOUS MATERIAL LAB (Continued) **1000187318**

Owner/Operator Summary:
Owner/operator name: NYCDEP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCDEP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYCDEP - HAZARDOUS MATERIAL LAB
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYCDEP - HAZARDOUS MATERIAL LAB
Classification: Not a generator, verified

Date form received by agency: 04/18/1990
Site name: NYCDEP - HAZARDOUS MATERIAL LAB
Classification: Small Quantity Generator

NYCDEP - HAZARDOUS MATERIAL LAB (Continued) **1000187318**

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F008
. Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Violation Status: No violations found

FINDS:

Registry ID: 110004444799

Environmental Interest/Information System

NYCDEP - HAZARDOUS MATERIAL LAB (Continued) **1000187318**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000187318
Registry ID:	110004444799
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004444799

NY MANIFEST:

Country:	USA
EPA ID:	NYD986896686
Facility Status:	Not reported
Location Address 1:	51 ASTOR PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986896686
Mailing Name:	NYCDEP
Mailing Contact:	JEANNETTE BEST
Mailing Address 1:	51 ASTOR PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2125665913

NY MANIFEST:

Document ID:	NJA0986997
Manifest Status:	K
seq:	Not reported
Year:	1990
Trans1 State ID:	NJDEPS-58
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/1990
Trans1 Recv Date:	06/20/1990
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/20/1990
Part A Recv Date:	09/05/1990
Part B Recv Date:	08/30/1990
Generator EPA ID:	NYD986896686

NYCDEP - HAZARDOUS MATERIAL LAB (Continued) **1000187318**

Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00010
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
4 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH504 **MINSKOFF EQUITY BLDG** **RCRA NonGen / NLR** **1000346045**
NNE **51 ASTOR PL** **FINDS** **NYD982794117**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.185 mi. **NY MANIFEST**
979 ft. **Site 5 of 23 in cluster AH**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/25/2015
Facility name:	MINSKOFF EQUITY BLDG
Facility address:	51 ASTOR PL NEW YORK, NY 10003
EPA ID:	NYD982794117
Mailing address:	ASTOR PL NEW YORK, NY 10003
Contact:	Not reported
Contact address:	ASTOR PL NEW YORK, NY 10003
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/06/2010
Site name:	MINSKOFF EQUITY BLDG
Classification:	Small Quantity Generator
Date form received by agency:	01/01/2007
Site name:	COOPER UNION SCHOOL OF ENG
Classification:	Small Quantity Generator
Date form received by agency:	01/01/2006
Site name:	COOPER UNION SCHOOL OF ENG
Classification:	Small Quantity Generator
Date form received by agency:	04/13/1995
Site name:	COOPER UNION SCHOOL OF ENG
Classification:	Not a generator, verified

MINSKOFF EQUITY BLDG (Continued) **1000346045**

. Waste code: NONE
. Waste name: None

Date form received by agency: 07/24/1989
Site name: COOPER UNION SCHOOL OF ENG
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: U188
. Waste name: PHENOL

MINSKOFF EQUITY BLDG (Continued) **1000346045**

. Waste code: U218
. Waste name: ETHANETHIOAMIDE (OR) THIOACETAMIDE

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 12/02/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110066947166

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110004390686

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000346045
Registry ID: 110066947166
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110066947166

NY MANIFEST:
Country: USA
EPA ID: NYP010001030
Facility Status: Not reported
Location Address 1: 51 ASTOR PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

MINSKOFF EQUITY BLDG (Continued) **1000346045**

Location State: NY
Location Zip: 11368
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP010001030
Mailing Name: NYCDEP
Mailing Contact: COSMO ZINGAROPOLI
Mailing Address 1: 59-17 JUNCTION BLVD
Mailing Address 2: Not reported
Mailing City: FLUSHING
Mailing State: NY
Mailing Zip: 11368
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185954661

NY MANIFEST:
Document ID: NYB2126394
Manifest Status: C
seq: Not reported
Year: 1993
Trans1 State ID: VU4150
Trans2 State ID: Not reported
Generator Ship Date: 06/01/1993
Trans1 Recv Date: 06/01/1993
Trans2 Recv Date: / /
TSD Site Recv Date: 06/01/1993
Part A Recv Date: 06/17/1993
Part B Recv Date: 06/10/1993
Generator EPA ID: NYP010001030
Trans1 EPA ID: NYD986893261
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00025
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels

MINSKOFF EQUITY BLDG (Continued) **1000346045**

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country: USA
EPA ID: NYP000772061
Facility Status: Not reported
Location Address 1: 51 ASTOR PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000772061
Mailing Name: NYCDEP
Mailing Contact: UNKNOWN
Mailing Address 1: 51 ASTOR PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2125668977

NY MANIFEST:
Document ID: NYO1653444
Manifest Status: C
seq: Not reported
Year: 1982
Trans1 State ID: NJJA044
Trans2 State ID: Not reported
Generator Ship Date: 06/07/1982
Trans1 Recv Date: 06/07/1982
Trans2 Recv Date: / /
TSD Site Recv Date: 06/09/1982
Part A Recv Date: / /
Part B Recv Date: / /
Generator EPA ID: NYP000772061
Trans1 EPA ID: NJT000009027
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported

MINSKOFF EQUITY BLDG (Continued) **1000346045**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00006
Units:	T - Tons
Number of Containers:	006
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	Not reported
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH505 **CON EDISON VAULT: 9653** **RCRA NonGen / NLR** **1016965588**
NNE **51 ASTOR PL** **NY MANIFEST** **NYP004384574**
1/8-1/4 **NEW YORK, NY 10003**
0.185 mi.
979 ft. **Site 6 of 23 in cluster AH**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/02/2013
Facility name:	CON EDISON VAULT: 9653
Facility address:	51 ASTOR PL NEW YORK, NY 10003
EPA ID:	NYP004384574
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON VAULT: 9653 (Continued) **1016965588**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/02/2013
Site name: CON EDISON VAULT: 9653
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004384574
Facility Status: Not reported
Location Address 1: FT OF 51 ASTON PL
Code: BP
Location Address 2: VAULT 9653
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004384574
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/02/2013
Trans1 Recv Date: 11/02/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/05/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004384574
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported

CON EDISON VAULT: 9653 (Continued) **1016965588**

Manifest Tracking Number:	002236012GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC506 **91 EAST 4TH ST** **NY LTANKS** **S106124188**
ESE **91 EAST 4TH ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.186 mi.
980 ft. **Site 16 of 33 in cluster AC**

Relative: LTANKS:
Lower

Actual: Facility ID:	0307640
36 ft. Site ID:	82922
Closed Date:	2004-07-27
Spill Number:	0307640
Spill Date:	2003-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2003-10-20
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party

91 EAST 4TH ST (Continued) **S106124188**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-20
Spill Record Last Update:	2004-07-27
Spiller Name:	SCOTT ALCHEH
Spiller Company:	PIONEER MGNT CO.
Spiller Address:	27 WEST 72ND STREET
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	76377
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 10/20/03. TTF LETTER HAS BEEN SENT to: Scott Alcheh C/o Pioneer MGNT Co. 27 West 72nd Street NY, NY 10023 YK. 7/27/04 TJD Spill closed and cross-referenced to spill 0210175. All open spills consolidated into single spill. SITE DOES NOT MEET STANDARDS."
Remarks:	""

All TTF:

Facility ID:	0307640
Spill Number:	0307640
Spill Tank Test:	1528747
Site ID:	82922
Tank Number:	2
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	82922
Operable Unit ID:	874034
Operable Unit:	01
Material ID:	501164
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC507 **LEONARD FRANZBLAU** **NY UST** **U003790784**
ESE **91 EAST 4TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.186 mi.
980 ft. **Site 17 of 33 in cluster AC**

Relative:
Lower

Actual:
36 ft.

UST:

Id/Status:	2-605720 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585386.80494
UTM Y:	4508865.98783
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27587
Affiliation Type:	Facility Owner
Company Name:	LEONARD FRANZBLAU
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	27 WEST 72ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 874-1882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27587
Affiliation Type:	Mail Contact
Company Name:	C/O PIONEER MANAGEMENT CO.
Contact Type:	Not reported
Contact Name:	LEONARD FRANZBLAU
Address1:	27 WEST 72ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 496-7322
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27587
Affiliation Type:	Facility Operator
Company Name:	LEONARD FRANZBLAU
Contact Type:	Not reported
Contact Name:	LEONARD FRANZBLAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

LEONARD FRANZBLAU (Continued) **U003790784**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 874-1882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27587
Affiliation Type:	Emergency Contact
Company Name:	LEONARD FRANZBLAU
Contact Type:	Not reported
Contact Name:	LEONARD FRANZBLAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 874-1882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	60279
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	11/07/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
I99 - Overfill - Other

AC508 **RESIDENTIAL** **NY LTANKS** **S105997847**
ESE **91 EAST 4TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.186 mi.
980 ft. **Site 18 of 33 in cluster AC**

Relative: LTANKS:
Lower

Actual:
36 ft.

Facility ID:	0210175
Site ID:	326541
Closed Date:	2017-02-24
Spill Number:	0210175
Spill Date:	2003-01-08
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2003-01-08
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-08
Spill Record Last Update:	2017-02-24
Spiller Name:	LEONARD FARNVBLAU
Spiller Company:	PIONEER MANAGMENT
Spiller Address:	27 WEST 72ND STREET
Spiller County:	001
Spiller Contact:	RENE LOUIS
Spiller Phone:	(718) 378-7000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	263041
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 0210175-Vought-Spoke with Scott (Pioneer Mangement) who just received, and will approve of proposal to isolate and retest. Faxed and mailed tank test failure letter on 1/9/2003. 7/21/03 TJD Demeo contacted Pioneer Management to determine tank status as letter received from Pioneer (Addressed to Ben Conlon)reveals only tank test failure of 1/8/03. Letter to DEC dated 6/30/03 requests the Department cancel any and all civil penalties concerning this matter. 6/30/03 letter signed by Scott Alcheh. Demeo called Pioneer and asked for Scott Alcheh and was told no such person works for Pioneer and I must have wrong number. Upon further identifying myself and DEC the individual who answered phone (John Stein) now recognized name but states that individual is unavailable. Upon further questioning regarding tank status Mr. Stein states that Pioneer is in the process of obtaining permits to uncover tank. Mr. Stein is unable to provide information regarding tank status but he has stated tank probably still contains product. Demeo directed Mr. Stein to immediately empty tank and proceed with directives of 1/8/03 correspondence from DEC. 7/27/04 TJD Open spills on property being consolidated. Second TTF (0307640) closed and cross-referenced. 6/21/07 Matthew Klaas (Albany

RESIDENTIAL (Continued) **S105997847**

DER) -Drafted a letter to Pioneer management at 27 west 72nd street, New York, NY 10023, informing them they have only sent copies of failed tank tests, requesting further information. 9/29/09 - Austin - Transferred from Albany assignment to Piper, for further investigation. - end 11/2/09- Tank closed 11/03.in place. 2/11/11- DEC piper sent infor request to Mr. Leonard Franzblau Pioneer Management 345 West 35th Street New York, NY 10001-1706 1/3/17- DEC piper sent info request to Mr. Leonard Franzblau 4900 North Ocean Blvd Apt 1213 Ft. Lauderdale, FL 33308-2936 Pioneer Management 289 Columbus Ave New York, NY 10023 2/23/17- DEC Piper received closure documentation. Tank closed in place 11/7/2003. Spill closed. Docs in DEC Docs. 2-605720. See also 0307640"

Remarks: "tank failed the test.unknownb size tank the line runs underneath the sidewalk"

All TTF:

Facility ID:	0210175
Spill Number:	0210175
Spill Tank Test:	1527915
Site ID:	326541
Tank Number:	1
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	326541
Operable Unit ID:	863376
Operable Unit:	01
Material ID:	513570
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI509 **AMOCO** **NY LTANKS** **S105135274**
SW **610 BROADWAY** **NY Spills** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.186 mi.
984 ft. **Site 2 of 23 in cluster AI**

Relative: **Lower**
Actual: **41 ft.**

LTANKS:

Facility ID:	0104555
Site ID:	164986
Closed Date:	2003-12-24
Spill Number:	0104555
Spill Date:	2001-07-28
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2001-07-28
CID:	397
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2001-07-28
Spill Record Last Update:	2004-01-20
Spiller Name:	UNK
Spiller Company:	AMOCO
Spiller Address:	610 BROADWAY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	139089
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 07/28/00 TIPPLE RESPONDED TO THE SPILL AT AN AMOCO STATION LOCATED AT 610 BROADWAY THE STATION HAS 4 UST'S BELOW BASEMENT OF PARKING GARAGE. PIPING FROM THE TANKS TO THE PUMPS ABOVE IS SITUATED IN A SERIES OF SOLID CONCRETE PILASTERS ON THE WALL OF EACH LEVEL OF THE PARKING GARAGE. GASOLINE WAS LEAKING OUT OF THE CONCRETE PILASTER IN THE LOWEST LEVEL OF THE PARKING GARAGE. THE ELECTRICITY TO THE PUMPS WAS TURNED OFF IMMEDIATELY, WHILE MONITORING THE LEL, AUTOS WERE REMOVED FROM THE GARAGE. TYREE ED WALDRON (516-790-2189) WAS ON THE SCENE. BIO-SOLVE WAS APPLIED TO THE GAS TO REDUCE THE VOLATLES, AND SPEEDY DRY WAS USED TO SOAK UP ANY FREE PRODUCT. WORK WOULD CONTINUE THROUGH SUNDAY TO FIND THE SOURCE. THE GAS STATION AND PARKING GARAGE WILL REMAIN OUT OF SERVICE UNTIL THE PROBLEM IS SOLVED. 07/30/01 A HOLE IN THE SUPPLY LINE BETWEEN THE TANKS AND THE PUMPS WAS LOCATED IN THE SECOND LEVEL OF THE PARKING GARAGE. REPAIRS ARE SCHEDULED FOR TUESDAY. 12/24/2003-Vought-Spill transferred from Rommel to Vought. Spill closed by Vought due to open spill #0102242 at same location. 12/31/03 Reassigned from Vought to Foley. 1/2/04 Delta closure request from 6/17/03: Leaking pipe section was repaired in August 2001. Tyree dismantles mid-grade suction piping system to

AMOCO (Continued) **S105135274**

isolate the leaking pipe. Pipes were encased in concrete. Tyree isolated the piping with the pinhole leak which was identified between the first and second levels of the garage. Tyree completed hydraulic integrity testing as directed by FDNY and all lines passed. Tyree reconstructed the concrete-filled pipe chase and restored to serivce. (KMF) 1/20/04 Sent NFA to Amoco for 0209761, 0102242, 0104555. (KMF)"

Remarks: "underground tank undera parking garage failed spilling gasoline. has not been cleaned up yet. "

All Materials:

Site ID:	164986
Operable Unit ID:	841299
Operable Unit:	01
Material ID:	533041
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0209761
Site ID:	164987
Closed Date:	2003-11-06
Spill Number:	0209761
Spill Date:	2002-12-23
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2002-12-23
CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-12-23
Spill Record Last Update:	2004-01-20
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	610 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	139089
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K

AMOCO (Continued) **S105135274**

FOLEY 12/24/02 - Standard to-do letter has been sent to owner's representitive. jz 11/6/2003-Vought-File review by Vought: 12/30/02-Tanknology Report-Tanks were isolated and retested. Failure due to 4 coaxial fill adapter which was replaced. All three USTs passed tightness test. Stage II was not tested . Spill closed by Vought. 12/3/03 Reassigned from Vought to Foley. See spill #s 0104555, 0102242. 1/20/04 Sent NFA to Amoco for 0209761, 0102242, 0104555. (KMF)"

Remarks: "CALLER BELIEVES THAT THE FAILURE IS DUE TO A BAD SUCTION LINE ON THE #7E DISPENSER. DISPENSER TAKEN OUT OF SERVICE. SUCTION LINE TO BE UNCOVERED, ISOLATED AND RETESTED."

All TTF:

Facility ID:	0209761
Spill Number:	0209761
Spill Tank Test:	1527868
Site ID:	164987
Tank Number:	3
Tank Size:	4000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	164987
Operable Unit ID:	862984
Operable Unit:	01
Material ID:	565766
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0000928
Facility Type:	ER
Spill Number:	0000928
DER Facility ID:	139089
Site ID:	164984
DEC Region:	2
Closed Date:	2000-06-12
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	3101

AMOCO (Continued) **S105135274**

Spill Date:	2000-04-23
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2000-04-23
CID:	322
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-23
Spill Record Last Update:	2003-01-06
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL The spill was due to a cab that started to drive away with the nozzle. When he yanked the nozzle, fuel spilled onto the concrete and down into the 1st floor of the garage below. Approx. 12 gallons were spilled. The spill was cleaned up by the Fire Department and Ed Waldron of Tyree. "
Remarks:	"2 SEPERATE SPILLS 10 GAL ON LAND & 10 GAL BELOW GRADE IN A GARAGE FIRE DEPT WAS ON SCENE AND DID CLEAN UP "

All Materials:

Site ID:	164984
Operable Unit ID:	822655
Operable Unit:	01
Material ID:	289161
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0102242
Facility Type:	ER
Spill Number:	0102242
DER Facility ID:	139089
Site ID:	164985
DEC Region:	2
Closed Date:	2004-01-20
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	2001-05-29
Investigator:	KMFOLEY
Referred To:	Not reported

AMOCO (Continued) **S105135274**

Reported to Dept:	2001-05-29
CID:	282
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2001-05-29
Spill Record Last Update:	2004-01-20
Spiller Name:	N/
Spiller Company:	AMOCO
Spiller Address:	610 BROADWAY
Spiller Company:	001
Contact Name:	ZELIA KRANICH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 3/14/03 REASSIGNED FROM ROMMEL TO VOUGHT. 12/24/2003-Vought-See closed spill #0104555 at same location. Spill transferred from Vought to K Foley. 1/2/04 UST closure report reviewed (Delta, 7/23/03). Report summarizes the excavation of four 4000gal fiberglass coated double-walled steel gasoline USTs and associated piping. Service station is above a three-level underground parking garage. USTs were located beneath the concrete floor on the third underground level of the parking garage. The piping extended upwards through the concrete encasement along the interior wall of the garage. Delta submitted a closure request letter for spill #0104555 which summarized maintenance activities performed to repair the failed piping associated with this spill number and passing line test after repairs were made. Tanks were observed to be in good condition. PID readings were generally less than 10ppm with the highest reading at 75ppm. Due to the absence of petroluem-impacted soil, no soil was removed from the site. Four post-ex soil samples were collected from outside the tank excavation vault and did not identify any VOCs above TAGM. Spill #0102242 was called in upon discovery of impacted soil at the location of the off-site former remote fill ports during maintenance work. Four drums of petroleum contaminated soil were generated as a result of the impacted soil discovery. During UST closure, approx 80ft of piping beneath the concrete floor of the third level underground parking garage was removed. Six soil samples were taken from beneath the piping(1.5'). No VOCs were detected above soil cleanup objectives. An additional 30' of piping vertically rose in a concrete encasement along the interior parking garage wall to the remote fill ports and pump islands. Of note, no soil was encountered along the piping and no soil was encountered during removal of the pump islands (above a parking garage). 1/20/04 Sent NFA to Amoco for 0209761, 0102242, 0104555. (KMF)"
Remarks:	"THEY WAS A LEAK IN THE ROMOTE AREA OF THE FILL PUMP. "

All Materials:

Site ID:	164985
Operable Unit ID:	839080
Operable Unit:	01
Material ID:	534358
Material Code:	0009
Material Name:	gasoline

AMOCO (Continued) **S105135274**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI510 **CON EDISON** **NY MANIFEST** **S118088932**
SW **610 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.186 mi.
984 ft. **Site 3 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004765228
Facility Status:	Not reported
Location Address 1:	610 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004765228
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004765228
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S118088932**

Manifest Tracking Number:	002611186GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI511 **AMOCO SERVICE STATION #13410** **NY UST** **U003107147**
SW **610 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.186 mi.
984 ft. **Site 4 of 23 in cluster AI**

Relative: UST:
Lower

Id/Status:	2-204358 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584778.32482
UTM Y:	4508792.28231
Site Type:	Retail Gasoline Sales

Actual:
41 ft.

Affiliation Records:

Site Id:	7098
Affiliation Type:	Facility Owner
Company Name:	BP PRODUCTS NORTH AMERICA INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 CENTERPOINT DRIVE

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Address2:	Not reported
City:	LA PALMA
State:	CA
Zip Code:	90623-1066
Country Code:	001
Phone:	(410) 551-6074
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7098
Affiliation Type:	Mail Contact
Company Name:	BP PRODUCTS NORTH AMERICA INC.
Contact Type:	Not reported
Contact Name:	PAULA SKRYJA
Address1:	7645 FAIRBANKS COURT
Address2:	Not reported
City:	HANOVER
State:	MD
Zip Code:	21076
Country Code:	001
Phone:	(410) 551-6074
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-06-30

Site Id:	7098
Affiliation Type:	Facility Operator
Company Name:	AMOCO SERVICE STATION #13410
Contact Type:	Not reported
Contact Name:	JOE CHOI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 473-5924
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7098
Affiliation Type:	Emergency Contact
Company Name:	BP PRODUCTS NORTH AMERICA INC
Contact Type:	Not reported
Contact Name:	BP AMOCO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(800) 272-4357

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 16992
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 002
Tank ID: 16993
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 16994
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 004
Tank ID: 16995
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 16996
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 006
Tank ID: 16997
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	007
Tank ID:	16998
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 008

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Tank ID:	16999
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	009
Tank ID:	17000
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	010
Tank ID:	17001
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	011
Tank ID:	17002
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 012
Tank ID: 17003
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 101
Tank ID: 44231
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 06/30/2003
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 102
Tank ID: 44232
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 06/30/2003
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 103
Tank ID: 44233
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

Install Date:	11/01/1992
Date Tank Closed:	06/30/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
J01 - Dispenser - Pressurized Dispenser
D02 - Pipe Type - Galvanized Steel
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	104
Tank ID:	45352
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	06/30/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin

AMOCO SERVICE STATION #13410 (Continued) **U003107147**

I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

AI512 **CON EDISON** **RCRA NonGen / NLR** **1019324818**
SW **610 BROADWAY** **NYP004765228**
1/8-1/4 **NEW YORK, NY 10012**
0.186 mi.
984 ft. **Site 5 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON
Site name:	CON EDISON - VAULT 4200
Facility address:	610 BROADWAY NEW YORK, NY 10012
EPA ID:	NYP004765228
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/09/2015
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/09/2015
Owner/Op end date:	Not reported

CON EDISON (Continued) **1019324818**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 04/09/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 04/09/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 3000

Violation Status: No violations found

AI513 **CON EDISON** **NJ MANIFEST** **S120670240**
SW **610 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.186 mi.
984 ft. **Site 6 of 23 in cluster AI**

Relative: **Lower**
Actual: **41 ft.**

NJ MANIFEST:
EPA Id: NYP004765228
Mail Address: IRVING PLACE, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THERESA BURKARD
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported

CON EDISON (Continued) **S120670240**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611186GBF
EPA ID:	NYP004765228
Date Shipped:	4/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AI514 **TRIBECA GAS INC** **RCRA NonGen / NLR** **1000556247**
SW **610 BROADWAY** **FINDS** **NYD986988061**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.186 mi. **NY MANIFEST**
984 ft. **Site 7 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	TRIBECA GAS INC
Facility address:	610 BROADWAY NEW YORK, NY 10012-2601
EPA ID:	NYD986988061
Mailing address:	BROADWAY NEW YORK, NY 10012
Contact:	Not reported
Contact address:	BROADWAY NEW YORK, NY 10012
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	S & E ENTERPRISES
Owner/operator address:	6273 WOODHAVEN REGO PARK, NY 99999
Owner/operator country:	US
Owner/operator telephone:	718-478-6400
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	S & E ENTERPRISES
Owner/operator address:	6273 WOODHAVEN REGO PARK, NY 99999
Owner/operator country:	US
Owner/operator telephone:	718-478-6400
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

TRIBECA GAS INC (Continued) **1000556247**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: TRIBECA GAS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: TRIBECA GAS INC
Classification: Not a generator, verified

Date form received by agency: 12/13/1991
Site name: TRIBECA GAS INC
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110004483700

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000556247
Registry ID: 110004483700

TRIBECA GAS INC (Continued) **1000556247**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004483700

NY MANIFEST:

Country:	USA
EPA ID:	NYD986988061
Facility Status:	Not reported
Location Address 1:	AMOCO S/S 610 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10016
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986988061
Mailing Name:	ARIBELA & GAS
Mailing Contact:	TOM SQUIRES
Mailing Address 1:	610 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009865825
Generator Ship Date:	11/21/2008
Trans1 Recv Date:	11/21/2008
Trans2 Recv Date:	11/29/2008
TSD Site Recv Date:	12/03/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986988061
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	002271671FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

TRIBECA GAS INC (Continued) **1000556247**

MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH515 **CON EDISON SERVICE BOX 37931** **RCRA NonGen / NLR** **1014926460**
NNE **444 LAFAYETTE ST** **NJ MANIFEST** **NYP004242285**
1/8-1/4 **NEW YORK, NY 10013** **NY MANIFEST**
0.187 mi.
989 ft. **Site 7 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/22/2011
Facility name:	CON EDISON SERVICE BOX 37931
Facility address:	444 LAFAYETTE ST NEW YORK, NY 10013
EPA ID:	NYP004242285
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	ROBERT BRUNS
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-780-3756
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON SERVICE BOX 37931 (Continued) **1014926460**

Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/22/2011
Site name:	CON EDISON SERVICE BOX 37931
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004242285
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ROBERT BRUNS
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655400JJK
EPA ID:	NYP004242285
Date Shipped:	9/22/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON SERVICE BOX 37931 (Continued) **1014926460**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	500.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004242285
Facility Status:	Not reported
Location Address 1:	F/O 444 LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004242285
Mailing Name:	CONSOLIDATED EDISON - SERV BOX 37931
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011

CON EDISON SERVICE BOX 37931 (Continued) **1014926460**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/22/2011
Trans1 Recv Date:	09/22/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/23/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004242285
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655400JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z516 **CON EDISON SERVICE BOX 549** **RCRA NonGen / NLR** **1014926398**
SE **44 E 2ND ST & 2ND AVE** **FINDS** **NYP004241550**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.188 mi. **NY MANIFEST**
991 ft. **Site 10 of 15 in cluster Z** **NJ MANIFEST**

Relative: Lower

Actual: 39 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/08/2011
Facility name:	CON EDISON SERVICE BOX 549
Facility address:	44 E 2ND ST & 2ND AVE NEW YORK, NY 10003
EPA ID:	NYP004241550
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	TONI A FRANZONE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9450
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/08/2011
Site name:	CON EDISON SERVICE BOX 549
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110043651027

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX 549 (Continued) **1014926398**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1014926398
Registry ID:	110043651027
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110043651027

NY MANIFEST:

Country:	USA
EPA ID:	NYP004241550
Facility Status:	Not reported
Location Address 1:	44 EAST 2ND STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004241550
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/08/2011
Trans1 Recv Date:	09/08/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/08/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004241550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655392JJK
Import Indicator:	N
Export Indicator:	N

CON EDISON SERVICE BOX 549 (Continued) **1014926398**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYP004241550
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	TONI A FRANZONE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655392JJK
EPA ID:	NYP004241550
Date Shipped:	9/8/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

CON EDISON SERVICE BOX 549 (Continued) **1014926398**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	500.00 Pounds

AH517 **CON EDISON SERVICE BOX: 37941** **RCRA NonGen / NLR** **1016966812**
NNE **LAFAYETTE ST & ASTOR PL** **NY MANIFEST** **NYP004396537**
1/8-1/4 **NEW YORK, NY 10006**
0.188 mi.
991 ft. **Site 8 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 37941
Facility address:	LAFAYETTE ST & ASTOR PL NEW YORK, NY 10006
EPA ID:	NYP004396537
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003

CON EDISON SERVICE BOX: 37941 (Continued) **1016966812**

Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 37941
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004396537
Facility Status: Not reported
Location Address 1: NW LAFAYETTE ST & ASTOR PL
Code: BP
Location Address 2: SB 37941
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004396537
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

CON EDISON SERVICE BOX: 37941 (Continued) **1016966812**

Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2013
Trans1 Recv Date: 11/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/22/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004396537
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002237639GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH518 **MTA NYCT ASTOR PL STA LEX AVE LINE** **NJ MANIFEST** **S117987284**
NNE **ASTOR PL & LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 9 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYR000095208
Mail Address:	BROADWAY 2ND FLOOR
Mail City/State/Zip:	NEW YORK, NY 10004
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	WILLIAM JEHLE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000457300WAS
EPA ID:	NYR000095208
Date Shipped:	3/22/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

MTA NYCT ASTOR PL STA LEX AVE LINE (Continued) **S117987284**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10004
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 2,750.00 Pounds

AH519 **MTA NYCT ASTOR PL STA LEX AVE LINE** **RCRA NonGen / NLR** **1004762266**
NNE **ASTOR PL & LAFAYETTE ST** **NY MANIFEST** **NYR000095208**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 10 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MTA NYCT ASTOR PL STA LEX AVE LINE
Facility address: ASTOR PL & LAFAYETTE ST
NEW YORK, NY 10003
EPA ID: NYR000095208
Mailing address: BROADWAY 2ND FLOOR
NEW YORK, NY 10004
Contact: WILLIAM JEHLE
Contact address: BROADWAY 2ND FLOOR
NEW YORK, NY 10004
Contact country: US
Contact telephone: 646-252-3500
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 2ND FLOOR
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: 646-252-3500
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 2ND FLOOR
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: 646-252-3500

MTA NYCT ASTOR PL STA LEX AVE LINE (Continued) **1004762266**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MTA NYCT ASTOR PL STA LEX AVE LINE
Classification: Not a generator, verified

Date form received by agency: 03/23/2001
Site name: MTA NYCT ASTOR PL STA LEX AVE LINE
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000095208
Facility Status: Not reported
Location Address 1: ASTOR PLACE & LAFAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000095208

MTA NYCT ASTOR PL STA LEX AVE LINE (Continued) **1004762266**

Mailing Name:	NYCTA CPM ENVIRONMENTAL ENGINEERING DIV
Mailing Contact:	NYCTA CPM ENVIRONMENTAL ENGINEERING DIV
Mailing Address 1:	2 BROADWAY 2ND FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523500

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	NJR986628162
Trans2 State ID:	Not reported
Generator Ship Date:	07/28/2016
Trans1 Recv Date:	07/28/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/28/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000095208
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	009140820FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

MTA NYCT ASTOR PL STA LEX AVE LINE (Continued) **1004762266**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH520 **CONSOLIDATED EDISON** **NY MANIFEST** **1009240348**
NNE **LAFAYETTE ST & ASTOR PL** **N/A**
1/8-1/4 **NEW YORK, NY 10020**
0.188 mi.
991 ft. **Site 11 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004075396
Facility Status: Not reported
Location Address 1: LAFAYETTE ST & ASTOR PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10020
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004075396
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0733419
Manifest Status: Not reported
seq: 01
Year: 2001
Trans1 State ID: 60913AX
Trans2 State ID: 60913AX
Generator Ship Date: 02/21/2001
Trans1 Recv Date: 02/21/2001
Trans2 Recv Date: 02/22/2001
TSD Site Recv Date: 02/22/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004075396
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: NYD006982359
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported

CONSOLIDATED EDISON (Continued) **1009240348**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00300
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH521 **CON EDISON MANHOLE: 37940** **RCRA NonGen / NLR** **1016969288**
NNE **E LAFAYETTE ST & ASTOR PL** **NY MANIFEST** **NYP004429452**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 12 of 23 in cluster AH**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/28/2014
Facility name:	CON EDISON MANHOLE: 37940
Facility address:	E LAFAYETTE ST & ASTOR PL SE COR NEW YORK, NY 10003
EPA ID:	NYP004429452
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

CON EDISON MANHOLE: 37940 (Continued) **1016969288**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/29/2014
Site name: CON EDISON MANHOLE: 37940
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004429452
Facility Status: Not reported
Location Address 1: S/E/C LAFAYETTE & ASTOR PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004429452
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 01/29/2014
Trans1 Recv Date: 01/29/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/31/2014

CON EDISON MANHOLE: 37940 (Continued) **1016969288**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004429452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329715GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH522 **CON EDISON** **RCRA NonGen / NLR** **1014399084**
NNE **LAFAYETTE ST & ASTOR PL** **NJ MANIFEST** **NYP004214615**
1/8-1/4 **NEW YORK, NY 10003** **NY MANIFEST**
0.188 mi.
991 ft. **Site 13 of 23 in cluster AH**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	08/31/2010
Facility name:	CON EDISON
Facility address:	LAFAYETTE ST & ASTOR PL NEW YORK, NY 10003
EPA ID:	NYP004214615
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	LOUIS CLARK
Contact address:	Not reported

Actual:
40 ft.

CON EDISON (Continued) **1014399084**

Not reported
Contact country: Not reported
Contact telephone: 347-539-6192
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004214615
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: LOUIS CLARK
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 006874783JJK
EPA ID: NYP004214615
Date Shipped: 09/01/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported

CON EDISON (Continued) **1014399084**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/01/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/01/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	500 G

NY MANIFEST:

Country:	USA
EPA ID:	NYP004214615
Facility Status:	Not reported
Location Address 1:	LAFAYETTE STREET AND ASTOR PLA
Code:	BP
Location Address 2:	CE
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004214615
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **1014399084**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/01/2010
Trans1 Recv Date:	09/01/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/01/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004214615
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	006874783JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **1014399084**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH523 **CON EDISON MANHOLE: 37940** **RCRA NonGen / NLR** **1017775841**
NNE **ASTOR PL & LAFAYETTE ST** **NYP004536868**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 14 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/20/2014
Facility name:	CON EDISON MANHOLE: 37940
Facility address:	ASTOR PL & LAFAYETTE ST NEW YORK, NY 10003
EPA ID:	NYP004536868
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/20/2014
Site name:	CON EDISON
Classification:	Large Quantity Generator

Date form received by agency:	05/20/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

AH524 **CON EDISON GAS DRIP** **RCRA NonGen / NLR** **1014397829**
NNE **ASTOR PL & LAFAYETTE ST** **NY MANIFEST** **NYP004201687**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 15 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/02/2010
Facility name:	CON EDISON GAS DRIP
Facility address:	ASTOR PL & LAFAYETTE ST GAS DRIP NEW YORK, NY 10003
EPA ID:	NYP004201687
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	SCOTT MAROTTA
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-427-1793
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004201687
Facility Status:	Not reported
Location Address 1:	LAFAYETTE ST & ASTOR PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10020
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004201687
Mailing Name:	CONSOLIDATED EDISON

CON EDISON GAS DRIP (Continued) **1014397829**

Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/02/2010
Trans1 Recv Date:	02/02/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/03/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004201687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001442113FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON GAS DRIP (Continued) **1014397829**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH525 **CON EDISON MANHOLE: 37940** **RCRA NonGen / NLR** **1016968882**
NNE **LAFAYETTE ST & ASTOR PL** **NY MANIFEST** **NYP004425187**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 16 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/24/2014
Facility name: CON EDISON MANHOLE: 37940
Facility address: LAFAYETTE ST & ASTOR PL
NEW YORK, NY 10003
EPA ID: NYP004425187
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/24/2014
Site name: CON EDISON MANHOLE: 37940
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004425187

CON EDISON MANHOLE: 37940 (Continued) **1016968882**

Facility Status:	Not reported
Location Address 1:	LAFAYETTE STASTOR PL.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004425187
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/24/2014
Trans1 Recv Date:	01/24/2014
Trans2 Recv Date:	01/27/2014
TSD Site Recv Date:	01/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004425187
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328673GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON MANHOLE: 37940 (Continued) **1016968882**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH526 **CON EDISON** **NY MANIFEST** **S117061383**
NNE **ASTOR PL & LAFAYETTE ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 17 of 23 in cluster AH**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004536868
Facility Status:	Not reported
Location Address 1:	ASTOR PL & LAFAYETTE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004536868
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported

CON EDISON (Continued) **S117061383**

Generator Ship Date:	05/20/2014
Trans1 Recv Date:	05/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004536868
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013246297JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AJ527 **40-42 EAST 3RD STREET** **NY AST** **U004078311**
SE **40-42 EAST 3RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
991 ft. **Site 1 of 9 in cluster AJ**

Relative: AST:
Lower

Actual:
38 ft.

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605748
Program Type:	PBS

40-42 EAST 3RD STREET (Continued) **U004078311**

UTM X: 585315.19918
UTM Y: 4508831.23202
Expiration Date: 12/14/2022
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 27615
Affiliation Type: Facility Operator
Company Name: 40-42 EAST 3RD STREET
Contact Type: Not reported
Contact Name: ROBERT PROTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 739-4002
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-04-18

Site Id: 27615
Affiliation Type: Emergency Contact
Company Name: SECOND AND THIRD LLC
Contact Type: Not reported
Contact Name: ROBERT PROTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 739-4002
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-14

Site Id: 27615
Affiliation Type: Facility Owner
Company Name: SECOND AND THIRD LLC
Contact Type: MANAGING AGENT
Contact Name: ROBERT PROTO
Address1: 50 2ND AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (201) 739-4002
EMail: PROTO93@VERIZON.NET
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-14

Site Id: 27615

40-42 EAST 3RD STREET (Continued) **U004078311**

Affiliation Type:	Mail Contact
Company Name:	SECOND AND THIRD LLC
Contact Type:	MANAGING AGENT
Contact Name:	ROBERT PROTO
Address1:	50 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(201) 739-4002
EMail:	PROTO93@VERIZON.NET
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-14

Tank Info:

Tank Number:	001
Tank Id:	60418
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	G01 - Tank Secondary Containment - Diking (Aboveground)
Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/03/1976
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	11/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Y528 **625 BROADWAY** **NY AST** **U003389218**
WSW **625 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.188 mi.
992 ft. **Site 13 of 16 in cluster Y**

Relative:
Lower

Actual:
38 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-297259
Program Type:	PBS
UTM X:	584795.03161
UTM Y:	4508838.10217
Expiration Date:	10/23/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	13719
Affiliation Type:	Mail Contact
Company Name:	625 BROADWAY VENTURE LLC
Contact Type:	Not reported
Contact Name:	MIKE CARTER
Address1:	9 ENTIN ROAD
Address2:	SUITE 103
City:	PARSIPPANY
State:	NJ
Zip Code:	07054
Country Code:	001
Phone:	(973) 599-0550
EMail:	MCARTER@LPC.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-23

Site Id:	13719
Affiliation Type:	Facility Operator
Company Name:	625 BROADWAY
Contact Type:	Not reported
Contact Name:	MIKE CARTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 206-2323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-09-10

Site Id:	13719
Affiliation Type:	Emergency Contact
Company Name:	625 BROADWAY VENTURE LLC
Contact Type:	Not reported
Contact Name:	DREW MAZURA
Address1:	Not reported
Address2:	Not reported
City:	Not reported

625 BROADWAY (Continued) **U003389218**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(973) 387-5433
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-23

Site Id:	13719
Affiliation Type:	Facility Owner
Company Name:	625 BROADWAY VENTURE LLC
Contact Type:	'PROPERTY MANAGER
Contact Name:	DREW MAZURA
Address1:	9 ENTIN ROAD SUITE 103
Address2:	Not reported
City:	PARSIPPANY
State:	NJ
Zip Code:	07054
Country Code:	001
Phone:	(973) 599-0550
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-23

Tank Info:

Tank Number:	001
Tank Id:	15448
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1962
Capacity Gallons:	8000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

625 BROADWAY (Continued) **U003389218**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/23/2017
Material Name:	#2 fuel oil (on-site consumption)

AI529 **CONSOLIDATED EDISON** **NY MANIFEST** **S108650758**
SW **LAFAYETTE ST & HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10020**
0.188 mi.
992 ft. **Site 8 of 23 in cluster AI**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004150702
Facility Status:	Not reported
Location Address 1:	LAFAYETTE ST & HOUSTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10020
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004150702
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/24/2007
Trans1 Recv Date:	05/24/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/25/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004150702
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001450175FLE
Import Indicator:	N

CONSOLIDATED EDISON (Continued) **S108650758**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D006
Waste Code 1_2:	D007
Waste Code 1_3:	D008
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC530 **CONSOLIDATED EDISON** **NY MANIFEST** **1009238519**
East **E 5TH & 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
993 ft. **Site 19 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004049755
Facility Status:	Not reported
Location Address 1:	E 5TH & 2ND AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004049755
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported

CONSOLIDATED EDISON (Continued) **1009238519**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0673371
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	43056AN
Trans2 State ID:	Not reported
Generator Ship Date:	03/02/2000
Trans1 Recv Date:	03/02/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/03/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004049755
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00127
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC531 **CON EDISON** **NY MANIFEST** **S116550804**
East **2ND AVE & 5TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
993 ft. **Site 20 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004492237
Facility Status:	Not reported
Location Address 1:	2 AVE E 5 ST
Code:	BP
Location Address 2:	SB53966
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004492237
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/2014
Trans1 Recv Date:	04/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004492237
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406233GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S116550804**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC532 **CON EDISON SERVICE BOX: 53966** **RCRA NonGen / NLR** **1017772267**
East **2ND AVE & 5TH ST** **FINDS** **NYP004492237**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
993 ft. **Site 21 of 33 in cluster AC**

Relative: **Lower**

Actual: **35 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/07/2014
Facility name:	CON EDISON SERVICE BOX: 53966
Facility address:	2ND AVE & 5TH ST NEW YORK, NY 10003
EPA ID:	NYP004492237
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON SERVICE BOX: 53966 (Continued) **1017772267**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/07/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/07/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063769435

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AC533 **CON EDISON** **NY MANIFEST** **S117066079**
ESE **66 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
995 ft. **Site 22 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004586962
Facility Status:	Not reported
Location Address 1:	66 2ND AVE
Code:	BP
Location Address 2:	SB 53951
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586962

CON EDISON (Continued) **S117066079**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586962
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423931GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117066079**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country: USA
EPA ID: NYP004855421
Facility Status: Not reported
Location Address 1: 66 2ND AVE
Code: BP
Location Address 2: SB 53951
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004855421
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/18/2015
Trans1 Recv Date: 10/18/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004855421
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013245209JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

CON EDISON (Continued) **S117066079**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AC534 **300 EAST FIFTH STREET** **NY AST** **U003391509**
East **300 EAST 5TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
995 ft. **Site 23 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-399396
Program Type:	PBS
UTM X:	585418.58393
UTM Y:	4508922.86271
Expiration Date:	10/06/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19018
Affiliation Type:	Facility Owner
Company Name:	86 2ND AVE LLC
Contact Type:	AGENT
Contact Name:	FRED FRAGANO
Address1:	250 PARK AVENUE, SUITE 1901
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10177
Country Code:	001
Phone:	(212) 972-5900

300 EAST FIFTH STREET (Continued) **U003391509**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	19018
Affiliation Type:	Facility Operator
Company Name:	300 EAST FIFTH STREET
Contact Type:	Not reported
Contact Name:	BENNY SULIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 691-6966
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	19018
Affiliation Type:	Emergency Contact
Company Name:	86 2ND AVE LLC
Contact Type:	Not reported
Contact Name:	BENNY SULIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 691-6966
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	19018
Affiliation Type:	Mail Contact
Company Name:	R.A. COHEN & ASSOCIATES INC.
Contact Type:	Not reported
Contact Name:	FRED FRAGANO
Address1:	250 PARK AVENUE
Address2:	SUITE 1901
City:	NEW YORK
State:	NY
Zip Code:	10177
Country Code:	001
Phone:	(212) 835-9526
EMail:	FRED@RACOHEN.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

300 EAST FIFTH STREET (Continued) **U003391509**

Tank Info:

Tank Number:	001
Tank Id:	21621
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1955
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/11/2017
Material Name:	#2 fuel oil (on-site consumption)

AC535 **CON EDISON** **NY MANIFEST** **S118259872**
ESE **64 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.188 mi.
995 ft. **Site 24 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004855405
Facility Status:	Not reported
Location Address 1:	64 2ND AVE
Code:	BP
Location Address 2:	SB 53950
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004855405
Mailing Name:	CON EDISON

CON EDISON (Continued) **S118259872**

Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/18/2015
Trans1 Recv Date:	10/18/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855405
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245207JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S118259872**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AC536 **60-SECOND AVE CORP** **NY AST** **U004045682**
ESE **60 SECOND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.189 mi.
996 ft. **Site 25 of 33 in cluster AC**

Relative:
Lower

Actual:
37 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-159190
Program Type: PBS
UTM X: 585361.00132
UTM Y: 4508818.28548
Expiration Date: N/A
Site Type: Unknown

Affiliation Records:
Site Id: 5370
Affiliation Type: Facility Owner
Company Name: 60-SECOND AVE CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 107 FIRST AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 475-2325
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5370
Affiliation Type: Mail Contact
Company Name: 60-SECOND AVE CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 107 FIRST AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 475-2325
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

60-SECOND AVE CORP (Continued) **U004045682**

Site Id:	5370
Affiliation Type:	Facility Operator
Company Name:	60-SECOND AVE CORP
Contact Type:	Not reported
Contact Name:	CLEOFE LOPEZ-SUPT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-2325
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5370
Affiliation Type:	Emergency Contact
Company Name:	60-SECOND AVE CORP
Contact Type:	Not reported
Contact Name:	LEONARD ELS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-2325
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	19635
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported

60-SECOND AVE CORP (Continued) **U004045682**

Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Z537 **CON EDISON** **NY MANIFEST** **S117066198**
SE **48 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.189 mi.
996 ft. **Site 11 of 15 in cluster Z**

Relative:
Lower

Actual:
38 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004588273
Facility Status:	Not reported
Location Address 1:	48 2ND AVE
Code:	BP
Location Address 2:	SB 53941
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004588273
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004588273
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117066198**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423933GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYP004855439
Facility Status:	Not reported
Location Address 1:	48 2ND AVE
Code:	BP
Location Address 2:	SB 53941
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004855439
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117066198**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855439
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245210JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Y538 **CON EDISON SERVICE BOX: 27217** **RCRA NonGen / NLR** **1016969283**
WSW **623 BROADWAY FRONT** **NY MANIFEST** **NYP004429395**
1/8-1/4 **NEW YORK, NY 10012**
0.190 mi.
1003 ft. **Site 14 of 16 in cluster Y**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/2014
Facility name:	CON EDISON SERVICE BOX: 27217
Facility address:	623 BROADWAY FRONT NEW YORK, NY 10012
EPA ID:	NYP004429395
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/29/2014
Site name:	CON EDISON SERVICE BOX: 27217
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004429395
Facility Status:	Not reported
Location Address 1:	623 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012

CON EDISON SERVICE BOX: 27217 (Continued) **1016969283**

Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004429395
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2014
Trans1 Recv Date:	01/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004429395
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329215GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON SERVICE BOX: 27217 (Continued) **1016969283**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Y539 **ISE REALTY GROUP, INC.** **NY AST** **U004077858**
WSW **623 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.190 mi.
1003 ft. **Site 15 of 16 in cluster Y**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-480533
Program Type:	PBS
UTM X:	584790.87750
UTM Y:	4508832.05964
Expiration Date:	08/21/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21446
Affiliation Type:	Mail Contact
Company Name:	EMMES REALTY
Contact Type:	Not reported
Contact Name:	CHRIS PLATH
Address1:	420 LEXINGTON AVE.
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10170
Country Code:	001
Phone:	(212) 293-8900
EMail:	CLAWR3@AOL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-08-12

Site Id:	21446
Affiliation Type:	Facility Operator
Company Name:	ISE REALTY GROUP, INC.
Contact Type:	Not reported
Contact Name:	CHRIS PORTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 293-8900

ISE REALTY GROUP, INC. (Continued) **U004077858**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-08-12

Site Id:	21446
Affiliation Type:	Emergency Contact
Company Name:	NOHO 623 STRATEGIC VENTURE LLC
Contact Type:	Not reported
Contact Name:	CHRIS PLATH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 293-8900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-08-12

Site Id:	21446
Affiliation Type:	Facility Owner
Company Name:	NOHO 623 STRATEGIC VENTURE LLC
Contact Type:	MGR
Contact Name:	CHRIS PLATH
Address1:	420 LEXINGTON AVE.
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10170
Country Code:	001
Phone:	(212) 293-8900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-08-12

Tank Info:

Tank Number:	001
Tank Id:	38997
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

ISE REALTY GROUP, INC. (Continued) **U004077858**

I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/15/1895
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Z540 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S103238331**
SE **44 SECOND AVENUE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.190 mi.
1004 ft. **Site 12 of 15 in cluster Z**

Relative: **Lower**
Actual: **38 ft.**

LTANKS:

Facility ID:	9801146
Site ID:	214063
Closed Date:	2003-03-03
Spill Number:	9801146
Spill Date:	1998-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1998-04-27
CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-27
Spill Record Last Update:	2003-03-05
Spiller Name:	FATHER ANTHONY ARACICH
Spiller Company:	NATIVITY PARISH
Spiller Address:	44 SECOND AVENUE
Spiller County:	001
Spiller Contact:	FATHER ANTHONY ARACICH
Spiller Phone:	(212) 674-8590
Spiller Extention:	20
DEC Region:	2
DER Facility ID:	177348
DEC Memo:	""

CLOSED-LACKOF RECENT INFO (Continued) **S103238331**

Remarks: "FURTHER ACTION TO FOLLOW. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	9801146
Spill Number:	9801146
Spill Tank Test:	1545825
Site ID:	214063
Tank Number:	Not reported
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	214063
Operable Unit ID:	1058617
Operable Unit:	01
Material ID:	556196
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC541 **74 CLEANERS INC** **RCRA-CESQG 1000117332**
ESE **74 SECOND AVE** **NY MANIFEST NYD034343657**
1/8-1/4 **NEW YORK, NY 10003**
0.191 mi.
1009 ft. **Site 26 of 33 in cluster AC**

Relative:
Lower

Actual:
36 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	74 CLEANERS INC
Facility address:	74 SECOND AVE NEW YORK, NY 10003
EPA ID:	NYD034343657
Mailing address:	SECOND AVE NEW YORK, NY 10003
Contact:	MIKE ALTER
Contact address:	SECOND AVE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	718-673-7434
Contact email:	Not reported
EPA Region:	02

74 CLEANERS INC (Continued) **1000117332**

Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: MIKE ALTER
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MIKE ALTER
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

74 CLEANERS INC (Continued) **1000117332**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: 74 CLEANERS INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/16/1985
Site name: 74 CLEANERS INC
Classification: Small Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/21/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
Country: USA
EPA ID: NYD034343657
Facility Status: Not reported
Location Address 1: 74 SECOND AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD034343657
Mailing Name: ONE HOUR MARTINIZING
Mailing Contact: ONE HOUR MARTINIZING
Mailing Address 1: 74 SECOND AVENUE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

74 CLEANERS INC (Continued) **1000117332**

Mailing Country:	USA
Mailing Phone:	2126749609

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814262374
Generator Ship Date:	08/23/2017
Trans1 Recv Date:	08/23/2017
Trans2 Recv Date:	08/29/2017
TSD Site Recv Date:	08/29/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD034343657
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX761010010
TSDF ID 2:	Not reported
Manifest Tracking Number:	016193452JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	390
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
111 additional NY_MANIFEST: record(s) in the EDR Site Report.

AC542 **ALICE/HANNA/74 DRY CLNERS** **NY DRYCLEANERS** **S110245861**
ESE **74 SECOND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.191 mi.
1009 ft. **Site 27 of 33 in cluster AC**

Relative:
Lower

Actual:
36 ft.

DRYCLEANERS:

Facility ID:	2-6206-00504
Phone Number:	212-673-7434
Region:	Not reported
Registration Effective Date:	9/24/2002 10:29:27:603
Inspection Date:	16AUG9
Install Date:	99/16
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	DF2000
Current Business:	Not reported

Z543 **CON EDISON** **NY MANIFEST** **S117066065**
SE **42 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.191 mi.
1009 ft. **Site 13 of 15 in cluster Z**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004586814
Facility Status:	Not reported
Location Address 1:	42 2ND AVE
Code:	BP
Location Address 2:	SB53940
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586814
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117066065**

TSD Site Recv Date:	07/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586814
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503425GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AE544 **CONSOLIDATED EDISON** **NY MANIFEST** **S117564101**
East **255-261 NO. 6TH ST. 255-261 NO** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.191 mi.
1010 ft. **Site 3 of 11 in cluster AE**

Relative: **Lower**
Actual: **36 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004079448
Facility Status:	Not reported
Location Address 1:	V2828 255-261 N 6TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN

CONSOLIDATED EDISON (Continued) **S117564101**

Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004079448
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0053932
Manifest Status: Not reported
seq: 01
Year: 2001
Trans1 State ID: GX3216
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2001
Trans1 Recv Date: 04/11/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/12/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004079448
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 01055
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks

CONSOLIDATED EDISON (Continued) **S117564101**

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AE545 **CON EDISION - TM2828** **RCRA NonGen / NLR** **1007207968**
East **255-261 NO. 6TH ST. 255-261 NO** **NYP004079448**
1/8-1/4 **NEW YORK, NY 10003**
0.191 mi.
1010 ft. **Site 4 of 11 in cluster AE**

Relative:
Lower

Actual:
36 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/02/2002
Facility name: CON EDISION - TM2828
Facility address: 255-261 NO. 6TH ST. 255-261 NO
NEW YORK, NY 10003
EPA ID: NYP004079448
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/01/2002
Site name: CON EDISION - TM2828
Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - TM2828
Classification: Large Quantity Generator

CON EDISION - TM2828 (Continued) **1007207968**

Violation Status: No violations found

Z546 **CON EDISON** **NY MANIFEST** **S117066349**
SE **27 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.191 mi.
1011 ft. **Site 14 of 15 in cluster Z**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004589925
Facility Status:	Not reported
Location Address 1:	27 2ND AVE
Code:	BP
Location Address 2:	SB 53922
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004589925
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004589925
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423993GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

CON EDISON (Continued) **S117066349**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AK547 **CON EDISON - VAULT 8286** **RCRA NonGen / NLR** **1010325531**
WNW **39 W3 ST** **NY MANIFEST** **NYP004128641**
1/8-1/4 **NEW YORK, NY 10012**
0.192 mi.
1015 ft. **Site 1 of 2 in cluster AK**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/23/2006
Facility name:	CON EDISON - VAULT 8286
Facility address:	39 W3 ST NEW YORK, NY 10012
EPA ID:	NYP004128641
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLIN MURRAY
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US

CON EDISON - VAULT 8286 (Continued) **1010325531**

Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/02/2005
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/02/2005
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/22/2006
Site name: CON EDISON - VAULT 8286
Classification: Not a generator, verified

Date form received by agency: 02/21/2006
Site name: CON EDISON - VAULT 8286
Classification: Large Quantity Generator

. Waste code: B002
. Waste name: B002

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004128641
Facility Status: Not reported

CON EDISON - VAULT 8286 (Continued) **1010325531**

Location Address 1:	39 W 3RD ST V8286
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004128641
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0629568
Manifest Status:	Not reported
seq:	Not reported
Year:	2005
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/02/2005
Trans1 Recv Date:	02/02/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004128641
Trans1 EPA ID:	46826JM
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON - VAULT 8286 (Continued) **1010325531**

Waste Code:	Not reported
Quantity:	02736
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH548 **V3554** **RCRA NonGen / NLR** **1007207209**
NNE **75-20 ASTORIA BOULEVARD** **NY MANIFEST** **NYP004040085**
1/8-1/4 **NEW YORK CITY, NY 11105**
0.193 mi.
1018 ft. **Site 18 of 23 in cluster AH**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/03/2001
Facility name:	V3554
Facility address:	75-20 ASTORIA BOULEVARD NEW YORK CITY, NY 11105
EPA ID:	NYP004040085
Mailing address:	CONSOLIDATED EDISON INC. 4 IRVING PLACE -- ROOM 300 NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC. NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/02/2001
Site name:	V3554

V3554 (Continued) **1007207209**

Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V3554
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004040085
Facility Status: Not reported
Location Address 1: V3554-ASTORIA BLVD & 77TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004040085
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0231682
Manifest Status: Not reported
seq: 01
Year: 1999
Trans1 State ID: GX3216
Trans2 State ID: Not reported
Generator Ship Date: 07/10/1999
Trans1 Recv Date: 07/10/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/12/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004040085
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

V3554 (Continued) **1007207209**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	02009
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Z549 **CON EDISON SERVICE BOX: 53939** **RCRA NonGen / NLR** **1016969764**
SE **38 2ND AVE** **NY MANIFEST** **NYP004434460**
1/8-1/4 **NEW YORK, NY 10003**
0.193 mi.
1019 ft. **Site 15 of 15 in cluster Z**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/05/2014
Facility name:	CON EDISON SERVICE BOX: 53939
Facility address:	38 2ND AVE NEW YORK, NY 10003
EPA ID:	NYP004434460
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON SERVICE BOX: 53939 (Continued) **1016969764**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/05/2014
Site name: CON EDISON SERVICE BOX: 53939
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004434460
Facility Status: Not reported
Location Address 1: 38 2 AVE
Code: BP
Location Address 2: SB 53939
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004434460
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/05/2014
Trans1 Recv Date: 02/05/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004434460
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105

CON EDISON SERVICE BOX: 53939 (Continued) **1016969764**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002329975GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AB550 **55 HOUSTON REALTY LLC** **NY AST** **A100318950**
SSW **55 EAST HOUSTON STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.193 mi.
1020 ft. **Site 11 of 12 in cluster AB**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610765
Program Type:	PBS
UTM X:	584933.98246
UTM Y:	4508668.87545
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	393504
Affiliation Type:	Mail Contact
Company Name:	ERIC NELSON
Contact Type:	Not reported

55 HOUSTON REALTY LLC (Continued) **A100318950**

Contact Name:	Not reported
Address1:	381 PARK AVENUE SOUTH, SUITE 1120
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 279-9600
EMail:	ENELSON@VINTROUP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-06-08

Site Id:	393504
Affiliation Type:	Facility Operator
Company Name:	55 HOUSTON REALTY LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 279-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-06-08

Site Id:	393504
Affiliation Type:	Emergency Contact
Company Name:	55 HOUSTON REALTY LLC
Contact Type:	Not reported
Contact Name:	ERIC NELSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 279-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-05-26

Site Id:	393504
Affiliation Type:	Facility Owner
Company Name:	55 HOUSTON REALTY LLC
Contact Type:	MEMBER MANAGER
Contact Name:	ERIC NELSON
Address1:	381 PARK AVENUE SOUTH, SUITE 1120
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016

55 HOUSTON REALTY LLC (Continued) **A100318950**

Country Code:	001
Phone:	(212) 279-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-06-08

Tank Info:

Tank Number:	001
Tank Id:	221597
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1970
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/06/2017
Register:	True
Modified By:	DAFRANCI
Last Modified:	06/08/2017
Material Name:	#2 fuel oil (on-site consumption)

AC551 **CON EDISON** **NY MANIFEST** **S117066340**
ESE **80 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.194 mi.
1024 ft. **Site 28 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004589826
Facility Status:	Not reported
Location Address 1:	80 2ND AVE
Code:	BP
Location Address 2:	SB 53962
Total Tanks:	Not reported
Location City:	NEW YORK

CON EDISON (Continued) **S117066340**

Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004589826
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004589826
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608202GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117066340**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF552 **NEW YORK UNIVERSITY** **RCRA-CESQG** **1019901173**
NW **35 W 4TH ST** **FINDS** **NYN008028714**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.194 mi.
1025 ft. **Site 11 of 14 in cluster AF**

Relative:
Lower

Actual:
34 ft.

RCRA-CESQG:

Date form received by agency:	05/17/2016
Facility name:	NEW YORK UNIVERSITY
Facility address:	35 W 4TH ST NEW YORK, NY 10003
EPA ID:	NYN008028714
Mailing address:	W 4TH ST NEW YORK, NY 10003
Contact:	Not reported
Contact address:	W 4TH ST NEW YORK, NY 10003
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

NEW YORK UNIVERSITY (Continued) **1019901173**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/17/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110069551988

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901173
Registry ID: 110069551988
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069551988

AL553 **CON EDISON** **NY MANIFEST** **S117066348**
SSE **23 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1027 ft. **Site 1 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004589917
Facility Status:	Not reported
Location Address 1:	23 2ND AVE
Code:	BP
Location Address 2:	SB 53921
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004589917
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004589917
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423992GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117066348**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AD554 **NEW YORK UNIVERSITY** **NY AST** **U003396351**
NNW **16 WAVERLY PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1027 ft. **Site 12 of 12 in cluster AD**

Relative: **Lower**
Actual: **36 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-601889
Program Type:	PBS
UTM X:	584934.25466
UTM Y:	4509300.31400
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

Site Id:	23851
Affiliation Type:	Facility Operator
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	PETER WOODS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3273
EMail:	Not reported
Fax Number:	Not reported

NEW YORK UNIVERSITY (Continued) **U003396351**

Modified By:	NRLOMBAR
Date Last Modified:	2007-09-17
Site Id:	23851
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 998-2222
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-09-17
Site Id:	23851
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-19
Site Id:	23851
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	ENVIRONMENTAL HEALTH & SAFETY
Address2:	285 MERCER STREET - 2ND FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1442
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-09-17

Tank Info:

Tank Number:	001

NEW YORK UNIVERSITY (Continued) **U003396351**

Tank Id: 48220
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 11/30/2007
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

X555 **APARTMENT HOUSE** **NY UST** **U000412448**
North **300 MERCER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1029 ft. **Site 11 of 13 in cluster X**

Relative: **Lower**
Actual: **37 ft.**

UST:
Id/Status: 2-214051 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 06/30/2022
UTM X: 584977.97353
UTM Y: 4509288.26990
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 7928
Affiliation Type: Facility Operator
Company Name: APARTMENT HOUSE
Contact Type: Not reported
Contact Name: GEORGE GEORGIO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

APARTMENT HOUSE (Continued) **U000412448**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 677-3404
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-04-09
Site Id:	7928
Affiliation Type:	Emergency Contact
Company Name:	HILARY GARDENS CO., LLC C/O ALGIN MANAGEMENT
Contact Type:	Not reported
Contact Name:	GEORGE GEORGIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 241-6977
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-06
Site Id:	7928
Affiliation Type:	Mail Contact
Company Name:	C/O ALGIN MANAGEMENT CO. LLC
Contact Type:	Not reported
Contact Name:	DAN HOCHSTADT
Address1:	183 MADISON AVE
Address2:	STE. 1602
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 213-9600
EMail:	DH@ALGINNY.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-06
Site Id:	7928
Affiliation Type:	Facility Owner
Company Name:	HILARY GARDENS CO., LLC
Contact Type:	AGENT
Contact Name:	DAN HOCHSTADT
Address1:	183 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(718) 896-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI

APARTMENT HOUSE (Continued) **U000412448**

Date Last Modified: 2017-12-13

Tank Info:

Tank Number: 001
Tank ID: 9843
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 20000
Install Date: 10/01/1976
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 07/11/2013
Next Test Date: 10/11/2016
Pipe Model: Not reported
Modified By: MFLEONAR
Last Modified: 02/01/2018

Equipment Records:

K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
H99 - Tank Leak Detection - Other
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J05 - Dispenser - On Site Heating System (Supply/Return)
I05 - Overfill - Vent Whistle
F07 - Pipe External Protection - Retrofitted Sacrificial Anode

Tank Number: 002
Tank ID: 9844
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 20000
Install Date: 10/01/1976
Date Tank Closed: 02/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported

APARTMENT HOUSE (Continued) **U000412448**

Pipe Model: Not reported
Modified By: MFLEONAR
Last Modified: 07/06/2017

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination

X556 **APHRODITE FRENCH CLEANERS** **NY DRYCLEANERS** **S110245933**
North **300 MERCER ST #1** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1029 ft. **Site 12 of 13 in cluster X**

Relative: **Lower**
Actual: **37 ft.**

DRYCLEANERS:
Facility ID: ---
Phone Number: Not reported
Region: 2
Registration Effective Date: ???
Inspection Date: Not reported
Install Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: ???

X557 **APT BUILDING TTF** **NY LTANKS** **S110490684**
North **300 MERCER ST** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.195 mi.
1029 ft. **Site 13 of 13 in cluster X**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:
Facility ID: 1003940
Site ID: 437192
Closed Date: 2015-02-05
Spill Number: 1003940
Spill Date: 2010-07-08
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2010-07-08
CID: Not reported

APT BUILDING TTF (Continued) **S110490684**

Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-07-08
Spill Record Last Update:	2015-02-05
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DAN HOCHSTABT - MANAGER
Spiller Phone:	(718) 896-9600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	392153
DEC Memo:	"1/20/15 TJD Spill reassigned from Sangesland to DeMeo. Neil Tomassetti from Eastmond submitted a closure letter and has requested a file review. 2/5/15 TJD File review. Two 20K USTs in a basement garage, Tank #1 passed tightness test on July 11, 2013 - Tank #2 failed. Investigation of tightness test failure for Tank #2 revealed several conditions including: a cracked elbow in aboveground fill line, a hidden (open)vent behind a wall and a corroded active vent line. Repairs were made to the tank system and Tank #2 passed a system test on 10/21/14. Following the passing test of Tank #2 the contractor reports the building management determined they had excess capacity as the building has been converted to dual fuel (primary fuel - natural gas). As such, Tank #2 was to be permanently closed - Eastmond then cut three holes in the bottom of Tank #2 along centerline and collected samples - additionally three holes were cut in the sidewall of Tank #2 facing Tank #2 and hand directional borings were advanced below Tank #1 to collect samples to assess the condition of sub-surface soils beneath both tanks. Samples were submitted (6 total)to a NYS ELAP certified laboratory for analysis. All results were non-detect. Based upon above information no further action is required. All documentation has been uploaded to DECDOCS. Spill closed. DeMeo informed Neil from Eastmond that the facility's PBS registration must be updated to reflect change in status."
Remarks:	"2 tanks on property - 1 failed - cleanup in progress"

All Materials:

Site ID:	437192
Operable Unit ID:	1187875
Operable Unit:	01
Material ID:	2182763
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AM558 **CON EDISON SERVICE BOX 37052** **NJ MANIFEST** **S117985007**
SSW **41 E HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.195 mi.
1031 ft. **Site 1 of 10 in cluster AM**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004246726
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	009204629JJK
EPA ID:	NYP004246726
Date Shipped:	1/20/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX 37052 (Continued) **S117985007**

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 500.00 Pounds

AM559 **CON EDISON SERVICE BOX 37052** **RCRA NonGen / NLR** **1015746679**
SSW **41 E HOUSTON ST** **NY MANIFEST** **NYP004246726**
1/8-1/4 **NEW YORK, NY 10012**
0.195 mi.
1031 ft. **Site 2 of 10 in cluster AM**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/19/2012
Facility name: CON EDISON SERVICE BOX 37052
Facility address: 41 E HOUSTON ST
NEW YORK, NY 10012
EPA ID: NYP004246726
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: BENJAMIN BAMONTE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-894-9549
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

CON EDISON SERVICE BOX 37052 (Continued) **1015746679**

Date form received by agency: 01/20/2012
Site name: CON EDISON SERVICE BOX 37052
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004246726
Facility Status: Not reported
Location Address 1: F/O 41 EAST HOUSTON & MULBERY ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004246726
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2012
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/20/2012
Trans1 Recv Date: 01/20/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/20/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004246726
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 009204629JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N

CON EDISON SERVICE BOX 37052 (Continued) **1015746679**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AN560 **LESTER/GLASSNER** **NY AST** **U003388133**
ENE **36 EAST 7TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1031 ft. **Site 1 of 16 in cluster AN**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-404578
Program Type:	PBS
UTM X:	585376.83536
UTM Y:	4509081.44229
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19466
Affiliation Type:	Facility Operator
Company Name:	GARFUNKEL & TAUSTER CORP
Contact Type:	Not reported
Contact Name:	DANNY CARABALLO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 328-4449
EMail:	Not reported

LESTER/GLASSNER (Continued) **U003388133**

Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-02

Site Id:	19466
Affiliation Type:	Emergency Contact
Company Name:	GARFUNKEL & TAUSTER CORP.
Contact Type:	Not reported
Contact Name:	SHANE PATRICK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 328-4449
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-02

Site Id:	19466
Affiliation Type:	Mail Contact
Company Name:	GARFUNKEL & TAUSTER CORP.
Contact Type:	Not reported
Contact Name:	SHANE PATRICK
Address1:	36 EAST 7TH STREET
Address2:	APT. 6W
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(917) 328-4449
EMail:	SHANEPATRICK100@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-02

Site Id:	19466
Affiliation Type:	Facility Owner
Company Name:	GARFUNKEL & TAUSTER CORP.
Contact Type:	OWNER
Contact Name:	SHANE PATRICK
Address1:	36 EAST 7TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(917) 328-4449
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-02-02

Tank Info:

LESTER/GLASSNER (Continued) **U003388133**

Tank Number: 001
Tank Id: 13224
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JMKRIMGO
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 001
Tank Id: 22995
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1984
Capacity Gallons: 1500

LESTER/GLASSNER (Continued) **U003388133**

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/24/2017
Register: True
Modified By: DAFRANCI
Last Modified: 02/02/2018
Material Name: #2 fuel oil (on-site consumption)

Affiliation Records:
Site Id: 10639
Affiliation Type: Facility Owner
Company Name: LESTER/GLASSNER
Contact Type: Not reported
Contact Name: Not reported
Address1: RT 10 BOX 97
Address2: Not reported
City: BLOOMVILLE
State: NY
Zip Code: 13739
Country Code: 001
Phone: (607) 538-9065
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10639
Affiliation Type: Mail Contact
Company Name: CITY & SUBURBAN FEDERAL SAVINGS
Contact Type: Not reported
Contact Name: Not reported
Address1: 3 EXECUTIVE BLVD
Address2: Not reported
City: YONKERS
State: NY
Zip Code: 10701
Country Code: 001
Phone: (607) 538-9065
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 10639
Affiliation Type: Facility Operator
Company Name: LESTER/GLASSNER
Contact Type: Not reported
Contact Name: LESTER/GLASSNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (607) 538-9065
EMail: Not reported

LESTER/GLASSNER (Continued) **U003388133**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	10639
Affiliation Type:	Emergency Contact
Company Name:	LESTER/GLASSNER
Contact Type:	Not reported
Contact Name:	JEROME FEIRMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 228-3370
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	13224
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JMKRIMGO
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	001

LESTER/GLASSNER (Continued) **U003388133**

Tank Id: 22995
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1984
Capacity Gallons: 1500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/24/2017
Register: True
Modified By: DAFRANCI
Last Modified: 02/02/2018
Material Name: #2 fuel oil (on-site consumption)

AI561 **GASETERIA** **NY LTANKS** **S105995059**
SW **21 EAST HOUSTON STREET** **N/A**
1/8-1/4 **NEW YORK, NY**
0.195 mi.
1031 ft. **Site 9 of 23 in cluster AI**

Relative: **Higher**
Actual: **42 ft.**

LTANKS:
Facility ID: 0230042
Site ID: 162605
Closed Date: 2006-03-20
Spill Number: 0230042
Spill Date: 2002-01-30
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: aaobliga
Referred To: Not reported
Reported to Dept: 2002-01-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False

GASETERIA (Continued) **S105995059**

Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-09-27
Spill Record Last Update:	2008-01-04
Spiller Name:	ROBERTO
Spiller Company:	GASETERIA
Spiller Address:	364 MASPETH AVENUE
Spiller County:	001
Spiller Contact:	ROBERTO
Spiller Phone:	(718) 782-4200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	137186
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT SPILL TRANSFERRED FROM VOUGHT OBLIGADO 10/26/05 - Obligado - Site also known as 300 Lafayette Street under spill number 9408102. Close older spill number 9408102 and consolidate with new spill number 0230042. 11/21/05 - Obligado - Spoke with Steve Muller, well installation planned. 12/2/05 - Obligado - Review baseline assessment report, submitted by Delta, 10/02. At time of assessment, site had 3 active 4000 galon USTs, and was an active Gaseteria. Between Jan 01 and Dec 02, three soil borings advanced to 20 to 30 ft. Two more soil boroings advanced in Jan 02 to 48 ft. A total of 9 soil samples collected. Soil results in ppb: SB1 (13-15) - 1250 xylenes SB1 (18-20) - 2060 xylenes SB4 (45-47) - 198 MTBE SB5 (40-42) - 1850 xylenes, 62,350 total VOCs Two of the soil borings turned into wells. Ground water results in ppb: MW4 - 4.92 benzene, 171 ethylbenzene, 868 xylenes, 247 MTBE, 105 arsenic, 461 chromium, 728 lead MW5 - 220 nbutlybenzene, 253 124trimethlybenzene Sensitive receptors include 1 federal public supply well 1.1 miles northwest, church 750 ft southeast, St.Patrick elementary school 800 ft southeast. Depth to water is 41 ft. Ground water flow is westerly-southwesterly to Hudson River. Soil is predominantly sand. 12/7/05 - Obligado - Meeting with DEC, ASR, Gaseteria. Decide to postpone drilling at this locattion to advance other higher priority sites. 1/5/05 - Obligado - Spoke with Steve Muller. Drilling scheduled for 1/12 1/18/05 - Obligado - Spoke with Steve Muller. Drilling postponed. Drilling will occur this week. 3/2/06 - Obligado - Received Final Remedial Action Plan, submitted by ASR, dated 3/1/06. According to report, 3 wells installed by Air Rotary method to 70 ft bgs. Ground water at 45 ft bgs. 1 composite soil sample collected from each well at 40 - 50 ft bgs depth interval. Only one impact (300 ppb napthalene) at one soil boring. Three ground water samples show non detect. Request NFA. Call Steve MUller. Ask why air rotary drilling method was used to drill through silty sand. Also why wells were installed to 70 ft, and screening a 30 ft interval. He said he would have to look at the report and the field notes and he would get back to me. Told him from now on I would like to see workplans for all subsurface investigations before drilling. 3/7/06 - Obligado - Phone conversation with Steve Muller. He said there were some errors in the reporting, and that wells were installed by hollow stem auger to 50 ft. He said he would submit a revised report. 3/20/06 - Obligado - Review revised report, wells drilled to 50 ft with augers. Ground water analyticals show non detect for groundwater. Discuss with Joe Sunn, close spill number based on no ground water impacts. 1/4/08 - Obligado - Received well abandonment report."

GASETERIA (Continued) **S105995059**

Remarks: "Contaminated soil and groundwater found. Data reported to DEC by Delta despite knowledge by Gaseteria since 8/5/2002."

All Materials:

Site ID:	162605
Operable Unit ID:	864452
Operable Unit:	01
Material ID:	568565
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI562 **B P PRODUCTS NORTH AMERICA INC #48384** **RCRA-SQG** **1007571110**
SW **21 E HOUSTON ST** **NY MANIFEST** **NYR000126698**
1/8-1/4 **NEW YORK, NY 10012** **NJ MANIFEST**
0.195 mi.
1031 ft. **Site 10 of 23 in cluster AI**

Relative:
Higher

Actual:
42 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	B P PRODUCTS NORTH AMERICA INC #48384
Facility address:	21 E HOUSTON ST NEW YORK, NY 10012
EPA ID:	NYR000126698
Mailing address:	PO BOX 6038 ARTESIA, NY 90702-6038
Contact:	PAULA SKRYJA
Contact address:	PO BOX 6038 ARTESIA, NY 90702-6038
Contact country:	US
Contact telephone:	410-551-6074
Contact email:	Not reported
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/19/2002

B P PRODUCTS NORTH AMERICA INC #48384 (Continued) **1007571110**

Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/19/2002
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: B P PRODUCTS NORTH AMERICA INC #48384
Classification: Not a generator, verified

Date form received by agency: 07/29/2004
Site name: B P PRODUCTS NORTH AMERICA INC #48384
Classification: Small Quantity Generator

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000126698
Facility Status: Not reported
Location Address 1: 21 E HOUSTON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported

B P PRODUCTS NORTH AMERICA INC #48384 (Continued) **1007571110**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000126698
Mailing Name: BP PRODUCTS NORTH AMERICA AMOCO 48384
Mailing Contact: N/S
Mailing Address 1: PO BOX 80249
Mailing Address 2: Not reported
Mailing City: RANCHO SANTA MARGARITA
Mailing State: CA
Mailing Zip: 92688
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9494605200

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2008
Trans1 State ID: NJR000023036
Trans2 State ID: Not reported
Generator Ship Date: 10/23/2008
Trans1 Recv Date: 10/23/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000126698
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 001274852JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: Y
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 400.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0

B P PRODUCTS NORTH AMERICA INC #48384 (Continued) **1007571110**

Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYR000126698
Mail Address:	P.O. BOX 80249
Mail City/State/Zip:	SANTA MARGARITA 92688
Facility Phone:	9494605200
Emergency Phone:	Not reported
Contact:	FRANK LOBELLO
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5246526
EPA ID:	NYR000126698
Date Shipped:	04/06/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/06/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/07/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

B P PRODUCTS NORTH AMERICA INC #48384 (Continued) **1007571110**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	07110625
Was Load Rejected:	SANTA MARGARITA 92688
Reason Load Was Rejected:	Not reported

Manifest Number:	001274852JJK
EPA ID:	NYR000126698
Date Shipped:	01/23/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/23/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/23/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	SANTA MARGARITA 92688
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018

B P PRODUCTS NORTH AMERICA INC #48384 (Continued) **1007571110**

Hand Code: H141
Quantity: 400 P

Manifest Number: 001274582JJK
EPA ID: NYR000126698
Date Shipped: 01/22/2007
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000023036
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/22/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/22/2007
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: SANTA MARGARITA 92688
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D018
Hand Code: H14
Quantity: 200 P

Manifest Number: NJA5246561
EPA ID: NYR000126698
Date Shipped: 07/07/2006
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000023036
Transporter 2 EPA ID: Not reported

B P PRODUCTS NORTH AMERICA INC #48384 (Continued) **1007571110**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/07/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/10/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08220625
Was Load Rejected:	SANTA MARGARITA 92688
Reason Load Was Rejected:	Not reported

Y563 **CABLE BUILDING** **NY AST** **U003384433**
WSW **611 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.195 mi.
1031 ft. **Site 16 of 16 in cluster Y**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-100455
Program Type:	PBS
UTM X:	584731.36839
UTM Y:	4508798.69986
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	3046
Affiliation Type:	Facility Owner
Company Name:	CABLE BUILDING ASSOCIATES

CABLE BUILDING (Continued) **U003384433**

Contact Type:	ASSET MANAGER
Contact Name:	BEN SLOAH
Address1:	611 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-2254
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-21

Site Id:	3046
Affiliation Type:	Mail Contact
Company Name:	CABLE BUILDING ASSOCIATES
Contact Type:	Not reported
Contact Name:	LANDIN HUTAJ
Address1:	611 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-2254
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-21

Site Id:	3046
Affiliation Type:	Facility Operator
Company Name:	CABLE BUILDING
Contact Type:	Not reported
Contact Name:	LANDIN HUTAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-2254
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-21

Site Id:	3046
Affiliation Type:	Emergency Contact
Company Name:	CABLE BUILDING ASSOCIATES
Contact Type:	Not reported
Contact Name:	M.D. CARLISLE REALTY CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

CABLE BUILDING (Continued) **U003384433**

Zip Code:	Not reported
Country Code:	999
Phone:	(347) 762-7694
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-21

Tank Info:

Tank Number:	001
Tank Id:	3767
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

B05 - Tank External Protection - Jacketed
G02 - Tank Secondary Containment - Vault (w/access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1940
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	06/21/2017
Material Name:	#6 fuel oil (on-site consumption)

AL564 **CON EDISON** **NY MANIFEST** **S117066513**
SSE **15 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.195 mi.
1032 ft. **Site 2 of 24 in cluster AL**

Relative: **Lower**
Actual: **41 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591707
Facility Status:	Not reported
Location Address 1:	15 E 1ST ST
Code:	BP
Location Address 2:	SB 506
Total Tanks:	Not reported

CON EDISON (Continued) **S117066513**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591707
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591707
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423980GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S117066513**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AC565 **CON EDISON** **NY MANIFEST** **S117066341**
ESE **84 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.196 mi.
1036 ft. **Site 29 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004589834
Facility Status:	Not reported
Location Address 1:	84 2ND AVE
Code:	BP
Location Address 2:	SB 53963
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004589834
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2014
Part A Recv Date:	Not reported

CON EDISON (Continued) **S117066341**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004589834
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608203GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AO566 **CON EDISON - SERVICE BOX 26801** **RCRA-LQG** **1014395853**
South **BOWERY AND E HOUSTON ST** **NY MANIFEST** **NYP004174777**
1/8-1/4 **NEW YORK, NY 10002** **NJ MANIFEST**
0.196 mi.
1037 ft. **Site 1 of 13 in cluster AO**

Relative: RCRA-LQG:
Higher

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - SERVICE BOX 26801
Facility address:	BOWERY AND E HOUSTON ST NEW YORK, NY 10002
EPA ID:	NYP004174777
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY
Contact address:	Not reported Not reported

Actual:
43 ft.

CON EDISON - SERVICE BOX 26801 (Continued) **1014395853**

Contact country: Not reported
Contact telephone: 212-460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/19/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/19/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

CON EDISON - SERVICE BOX 26801 (Continued) **1014395853**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004174777
Facility Status: Not reported
Location Address 1: BOWERY AND E HOUSTON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10002
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004174777
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/23/2009
Trans1 Recv Date: 06/23/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/23/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004174777
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 000961216GBF
Import Indicator: N
Export Indicator: N

CON EDISON - SERVICE BOX 26801 (Continued) **1014395853**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYP004174777
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000961216GBF
EPA ID:	NYP004174777
Date Shipped:	06/23/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

CON EDISON - SERVICE BOX 26801 (Continued) **1014395853**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/23/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2500 P

AF567 **CONSOLIDATED EDISON** **NY MANIFEST** **1009239084**
NW **58 W 4OTH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.196 mi.
1037 ft. **Site 12 of 14 in cluster AF**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004056966
Facility Status:	Not reported
Location Address 1:	58 W 4OTH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CONSOLIDATED EDISON (Continued) **1009239084**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004056966
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0668484
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	GX3213
Trans2 State ID:	Not reported
Generator Ship Date:	06/14/2000
Trans1 Recv Date:	06/14/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/14/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004056966
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00659
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001

CONSOLIDATED EDISON (Continued) **1009239084**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF568 **CON ED** **NY MANIFEST** **S118463735**
NW **45 WEST 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.197 mi.
1039 ft. **Site 13 of 14 in cluster AF**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856256
Facility Status:	Not reported
Location Address 1:	45 WEST 4TH ST
Code:	BP
Location Address 2:	SB 820
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856256
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856256
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

CON ED (Continued) **S118463735**

Manifest Tracking Number:	014085727JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AJ569 **CON EDISON** **RCRA NonGen / NLR** **1019905491**
SE **44 E 3RD ST** **FINDS** **NYP004810277**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.197 mi.
1040 ft. **Site 2 of 9 in cluster AJ**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	07/21/2015
Facility name:	CON EDISON
Facility address:	44 E 3RD ST NEW YORK, NY 10003
EPA ID:	NYP004810277
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
38 ft.

CON EDISON (Continued) **1019905491**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 07/21/2015
- Site name: CON EDISON
- Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069682597

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1019905491
- Registry ID: 110069682597
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069682597

AJ570 **CON EDISON** **NY MANIFEST** **S117066213**
SE **44 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.197 mi.
1040 ft. **Site 3 of 9 in cluster AJ**

Relative: **Lower**

Actual: **38 ft.**

NY MANIFEST:
- Country: USA
- EPA ID: NYP004588422
- Facility Status: Not reported
- Location Address 1: 44 E 3RD ST
- Code: BP

CON EDISON (Continued) **S117066213**

Location Address 2:	SB 681
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004588422
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004588422
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002236278GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000

CON EDISON (Continued) **S117066213**

Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country: USA
EPA ID: NYP004810277
Facility Status: Not reported
Location Address 1: 44 E 3RD ST
Code: BP
Location Address 2: SB 681
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004810277
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/21/2015
Trans1 Recv Date: 07/21/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/24/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004810277
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON (Continued) **S117066213**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612111GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AJ571 **CON EDISON** **NJ MANIFEST** **S120674210**
SE **44 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.197 mi.
1040 ft. **Site 4 of 9 in cluster AJ**

Relative: NJ MANIFEST:
Lower

Actual:
38 ft.

EPA Id:	NYP004810277
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported

CON EDISON (Continued) **S120674210**

Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002612111GBF
EPA ID: NYP004810277
Date Shipped: 7/21/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

AO572 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243809**
South **HOUSTON ST & BOWERY ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.198 mi.
1048 ft. **Site 2 of 13 in cluster AO**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004133948
Facility Status: Not reported
Location Address 1: HOUSTON ST & BOWERY ST

CONSOLIDATED EDISON (Continued) **1009243809**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004133948
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE1294632
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/27/2005
Trans1 Recv Date: 07/27/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/28/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004133948
Trans1 EPA ID: 69526JR
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CONSOLIDATED EDISON (Continued) **1009243809**

Quantity:	00400
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AO573 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243823**
South **BOWERY ST & E HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY**
0.198 mi.
1048 ft. **Site 3 of 13 in cluster AO**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004134110
Facility Status:	Not reported
Location Address 1:	BOWERY ST & E HOUSTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004134110
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE1294641
Manifest Status:	Not reported
seq:	Not reported
Year:	2005
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	08/01/2005
Trans1 Recv Date:	08/01/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/02/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004134110
Trans1 EPA ID:	12446JT

CONSOLIDATED EDISON (Continued) **1009243823**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00064
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AP574 **CON EDISON SERVICE BOX: 61134** **RCRA NonGen / NLR** **1017772003**
NE **COOPER SQ & ASTOR PL** **FINDS** **NYP004489506**
1/8-1/4 **NEW YORK, NY 10003**
0.199 mi.
1049 ft. **Site 1 of 29 in cluster AP**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/04/2014
Facility name:	CON EDISON SERVICE BOX: 61134
Facility address:	COOPER SQ & ASTOR PL NEW YORK, NY 10003
EPA ID:	NYP004489506
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON SERVICE BOX: 61134 (Continued) **1017772003**

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 04/04/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/04/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063806190

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AP575 **CON EDISON GAS DRIP: GAS-MAIN** **RCRA NonGen / NLR** **1016143156**
NE **COOPER SQ & W 4TH ST** **FINDS** **NYP004258901**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.199 mi. **NY MANIFEST**
1049 ft. **Site 2 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency: 07/28/2017
Facility name: CON EDISON GAS DRIP: GAS-MAIN
Facility address: COOPER SQ & W 4TH ST
NEW YORK, NY 10003
EPA ID: NYP004258901
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: LOUIS CLARK

CON EDISON GAS DRIP: GAS-MAIN (Continued) **1016143156**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 347-539-6192
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/18/2012
Site name: CON EDISON GAS DRIP: GAS-MAIN
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110064275181

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016143156
Registry ID: 110064275181
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110064275181

NY MANIFEST:
Country: USA

CON EDISON GAS DRIP: GAS-MAIN (Continued) **1016143156**

EPA ID:	NYP004258901
Facility Status:	Not reported
Location Address 1:	COOPER AND EAST 5TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004258901
Mailing Name:	CONSOLIDATED EDISON OF NY
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE FLOOR 15
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/18/2012
Trans1 Recv Date:	07/18/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/18/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004258901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001674549GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON GAS DRIP: GAS-MAIN (Continued) **1016143156**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	35.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH576 **CON EDISON SERVICE BOX: 28838** **RCRA NonGen / NLR** **1016966708**
North **754 E BROADWAY** **NY MANIFEST** **NYP004395539**
1/8-1/4 **NEW YORK, NY 10009**
0.199 mi.
1050 ft. **Site 19 of 23 in cluster AH**

Relative: **Lower**

Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 28838
Facility address:	754 E BROADWAY NEW YORK, NY 10009
EPA ID:	NYP004395539
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON SERVICE BOX: 28838 (Continued) **1016966708**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 28838
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395539
Facility Status: Not reported
Location Address 1: 754 BROADWAY
Code: BP
Location Address 2: SB28838
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395539
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2013
Trans1 Recv Date: 11/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/25/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004395539
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002237677GBF
Import Indicator: N

CON EDISON SERVICE BOX: 28838 (Continued) **1016966708**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AQ577 **N Y U** **NY AST** **U004076080**
West **4 WASHINGTON SQUARE VILLAGE** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.200 mi.
1054 ft. **Site 1 of 3 in cluster AQ**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-034835
Program Type:	PBS
UTM X:	584699.66034
UTM Y:	4508966.77511
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

Site Id:	306
Affiliation Type:	Facility Operator
Company Name:	N Y U
Contact Type:	Not reported
Contact Name:	TONY BARRIS
Address1:	Not reported
Address2:	Not reported

N Y U (Continued) **U004076080**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 598-0680
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	306
Affiliation Type:	Emergency Contact
Company Name:	N Y U
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(732) 499-8051
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	306
Affiliation Type:	Facility Owner
Company Name:	N Y U
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-04-19

Site Id:	306
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL HEALTH & SAFETY
Address1:	740 BROADWAY
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	Not reported

N Y U (Continued) **U004076080**

Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-04-15

Tank Info:

Tank Number:	003
Tank Id:	937
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1958
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/15/2011
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	004
Tank Id:	938
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron

N Y U (Continued) **U004076080**

Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1958
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/04/2011
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AI578 **300 LAFAYETTE STREET** **NY VCP** **S118943339**
SW **300 LAFAYETTE STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.200 mi.
1056 ft. **Site 11 of 23 in cluster AI**

Relative:
Higher

Actual:
42 ft.

VCP NYC:

Project ID:	14CVCP201M
Project Name:	300 LAFAYETTE STREET
Project Address:	300 LAFAYETTE STREET
Borough:	MANHATTAN

VCP NYC:

Project ID:	14CVCP201M
File Name:	2014-01-09.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/14CVCP201M/2014-02-07.14CVCP201M.RIR_Web_Revision_with_Phase_1.pdf

Project ID:	14CVCP201M
File Name:	2014-01-09.RAWP_Final
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/14CVCP201M/2014-04-01.14CVCP201M.300_Lafayette_Street.RAWP_Final.pdf

Project ID:	14CVCP201M
File Name:	2014-01-09.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/14CVCP201M/2014-01-08.14CVCP201M.300-Lafayette_St.Fact_Sheet_final.pdf

Project ID:	14CVCP201M
File Name:	2014-01-09.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/14CVCP201M/2014-01-03.14CVCP201M.Translated_Fact_Sheet.pdf

Project ID:	14CVCP201M
File Name:	2014-01-09.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/14CVCP201M/2014-01-03.14CVCP201M.Translated_Community_Protection_Statement.pdf

AJ579 **50 E 3RD ST** **NY AST** **U000405437**
SE **50 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.200 mi.
1058 ft. **Site 5 of 9 in cluster AJ**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-364762
Program Type:	PBS
UTM X:	585345.90931
UTM Y:	4508751.71879
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	18500
Affiliation Type:	Facility Owner
Company Name:	ABE HARUVI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	22 WEST 75TH ST
Address2:	Not reported
City:	NEW YORK CITY
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 769-4253
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18500
Affiliation Type:	Mail Contact
Company Name:	ABART HOLDING COMPANY
Contact Type:	Not reported
Contact Name:	ABE HARUVI
Address1:	22 WEST 75TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 769-4253
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18500
Affiliation Type:	Facility Operator
Company Name:	50 E 3RD ST
Contact Type:	Not reported
Contact Name:	ROCKWAY FUEL OIL
Address1:	Not reported
Address2:	Not reported
City:	Not reported

50 E 3RD ST (Continued) **U000405437**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 769-4253
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18500
Affiliation Type:	Emergency Contact
Company Name:	ABE HARUVI
Contact Type:	Not reported
Contact Name:	GEORGE AGUILAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 769-4253
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	22637
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AB580 **ALMARK HOLDING** **NY AST** **A100175661**
SSW **284 MOTT STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.201 mi.
1060 ft. **Site 12 of 12 in cluster AB**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605402
Program Type:	PBS
UTM X:	584940.52470
UTM Y:	4508646.05463
Expiration Date:	03/14/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27270
Affiliation Type:	Facility Owner
Company Name:	ALMARK HOLDING CO, LLC
Contact Type:	MAINTENANCE MANAGER
Contact Name:	DAN MCCARTHY
Address1:	950 THIRD AVENUE 27TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 759-5000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-02-25

Site Id:	27270
Affiliation Type:	Mail Contact
Company Name:	ABINGTON HOLDING
Contact Type:	Not reported
Contact Name:	DAN MCCARTHY
Address1:	950 THIRD AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 759-5000
EMail:	DMCCARTHY@ABINGTONHOLDING.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-02-25

Site Id:	27270
Affiliation Type:	Facility Operator
Company Name:	ALMARK HOLDING
Contact Type:	Not reported
Contact Name:	SYLVIO GRIMA
Address1:	Not reported
Address2:	Not reported
City:	Not reported

ALMARK HOLDING (Continued) **A100175661**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 374-1507
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-02-25

Site Id:	27270
Affiliation Type:	Emergency Contact
Company Name:	ALMARK HOLDING CO, LLC
Contact Type:	Not reported
Contact Name:	MELISSA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 931-6687
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-02-25

Tank Info:

Tank Number:	001
Tank Id:	59824
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
I05 - Overfill - Vent Whistle

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/18/1986
Capacity Gallons:	7500
Tightness Test Method:	21
Date Test:	02/07/2017
Next Test Date:	Not reported
Date Tank Closed:	Not reported

ALMARK HOLDING (Continued) **A100175661**

Register: True
Modified By: TLYE
Last Modified: 11/20/2017
Material Name: #2 fuel oil (on-site consumption)

AG581 **CON EDISON SERVICE BOX: 40673** **RCRA NonGen / NLR** **1016966715**
NE **2-4 ST MARKS** **NY MANIFEST** **NYP004395604**
1/8-1/4 **NEW YORK, NY 10009**
0.201 mi.
1063 ft. **Site 3 of 7 in cluster AG**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:
Date form received by agency: 12/21/2013
Facility name: CON EDISON SERVICE BOX: 40673
Facility address: 2-4 ST MARKS
NEW YORK, NY 10009
EPA ID: NYP004395604
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 40673
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395604
Facility Status: Not reported

CON EDISON SERVICE BOX: 40673 (Continued) **1016966715**

Location Address 1:	2-4 ST MARKS PL
Code:	BP
Location Address 2:	SB40673
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004395604
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/21/2013
Trans1 Recv Date:	11/21/2013
Trans2 Recv Date:	11/25/2013
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395604
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237611GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX: 40673 (Continued) **1016966715**

Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AO582 **CON EDISON** **PA MANIFEST** **S118889141**
South **284 BOWERY** **N/A**
1/8-1/4 **MANHATTAN, NY 10002**
0.202 mi.
1065 ft. **Site 4 of 13 in cluster AO**

Relative: **Higher**

Actual: **43 ft.**

Manifest Details:

Year:	2015
Manifest Number:	002659318GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYP004718573
Generator Date:	01/24/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	212-894-9467
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AH583 **CON EDISON GAS MAIN: N/A** **RCRA-CESQG** **1016451365**
North **755 BROADWAY** **FINDS** **NYP004304556**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.202 mi. **NY MANIFEST**
1066 ft. **Site 20 of 23 in cluster AH**

Relative:
Lower

Actual:
37 ft.

RCRA-CESQG:

Date form received by agency:	04/24/2013
Facility name:	CON EDISON GAS MAIN: N/A
Facility address:	755 BROADWAY NEW YORK, NY 10003
EPA ID:	NYP004304556
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	FRANCIS DONOHUE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	917-440-3061
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110056329780

CON EDISON GAS MAIN: N/A (Continued) **1016451365**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016451365
Registry ID:	110056329780
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056329780

NY MANIFEST:

Country:	USA
EPA ID:	NYP004304556
Facility Status:	Not reported
Location Address 1:	755 BROADWAY W 8TH ST & ASTOR
Code:	BP
Location Address 2:	JOB# 02-03050-259
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004304556
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NYD004304556
Generator Ship Date:	04/25/2013
Trans1 Recv Date:	04/25/2013
Trans2 Recv Date:	04/25/2013
TSD Site Recv Date:	04/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON GAS MAIN: N/A (Continued) **1016451365**

Generator EPA ID:	NYP004304556
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001675612GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	191
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AF584 **NEW YORK UNIVERSITY - TISCH HALL** **RCRA-SQG** **1000994483**
NW **40 W 4TH ST** **NY MANIFEST** **NYD986963213**
1/8-1/4 **NEW YORK, NY 10003**
0.203 mi.
1073 ft. **Site 14 of 14 in cluster AF**

Relative: **Lower**
Actual: **33 ft.**

RCRA-SQG:

Date form received by agency:	07/29/2013
Facility name:	NEW YORK UNIVERSITY - TISCH HALL
Facility address:	40 W 4TH ST NEW YORK, NY 10003
EPA ID:	NYD986963213
Mailing address:	ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR NEW YORK, NY 10003
Contact:	STEPHANIE M KUNG
Contact address:	ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR NEW YORK, NY 10003

NEW YORK UNIVERSITY - TISCH HALL (Continued) **1000994483**

Contact country: US
Contact telephone: 212-998-1450
Contact email: STEPHANIE.KUNG@NYU.EDU
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NY UNIVERSITY
Owner/operator address: 70 WASHINGTON SQ S
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-998-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Owner/operator name: NY UNIVERSITY
Owner/operator address: 70 WASHINGTON SQ S
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-998-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK UNIVESRITY
Owner/operator address: WASHINGTON SQUARE SOUTH
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported

NEW YORK UNIVERSITY - TISCH HALL (Continued) **1000994483**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:
Date form received by agency: 03/09/2010
Site name: NEW YORK UNIVERSITY - TISCH HALL
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: U151
. Waste name: MERCURY

Date form received by agency: 12/01/2009
Site name: NYU - TISCH HALL
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

NEW YORK UNIVERSITY - TISCH HALL (Continued) **1000994483**

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: U151
. Waste name: MERCURY

Date form received by agency: 01/01/2007
Site name: NYU - TISCH HALL
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: NYU - TISCH HALL
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/28/2002
Site name: NYU - TISCH HALL
Classification: Large Quantity Generator

Date form received by agency: 04/19/1995
Site name: NY UNIVERSITY TISCH HALL
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 04/28/1991
Site name: NY UNIVERSITY TISCH HALL
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: X001
. Waste name: WASTE OILS

. Waste code: X002

NEW YORK UNIVERSITY - TISCH HALL (Continued) **1000994483**

. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD986963213
Facility Status: Not reported
Location Address 1: 40 WEST FOURTH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986963213
Mailing Name: NEW YORK UNIVERSITY MED CTR
Mailing Contact: ZACK KORENSTEIN
Mailing Address 1: 10 ASTOR PLACE 6TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129928276

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2016
Trans1 State ID: MAC300016672
Trans2 State ID: NYD982792814
Generator Ship Date: 01/13/2016
Trans1 Recv Date: 01/13/2016
Trans2 Recv Date: 01/14/2016
TSD Site Recv Date: 01/29/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986963213
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD048415665
TSDF ID 2: Not reported
Manifest Tracking Number: 007885795FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

NEW YORK UNIVERSITY - TISCH HALL (Continued) **1000994483**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	425
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
41 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI585 **295 LAFAYETTE ST.** **NY LTANKS** **S100494942**
SW **295 LAFAYETTE ST.** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.204 mi.
1076 ft. **Site 12 of 23 in cluster AI**

Relative: **Higher**
Actual: **42 ft.**

LTANKS:

Facility ID:	9214395
Site ID:	167565
Closed Date:	1994-01-21
Spill Number:	9214395
Spill Date:	1993-03-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1994-01-21
SWIS:	3101
Investigator:	MITCHELL
Referred To:	Not reported
Reported to Dept:	1993-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-01

295 LAFAYETTE ST. (Continued) **S100494942**

Spill Record Last Update:	1994-01-21
Spiller Name:	Not reported
Spiller Company:	PARK ASSOCIATES APTS.
Spiller Address:	295 LAFAYETTE ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	141191
DEC Memo:	""
Remarks:	"TANK FAILED. OIL CONTAINED ON CONCRETE FLOOR IN TANK ROOM. 7500 GAL TANK. SPEEDI-DRI APPLIED. VAC-TRUCK ON SITES PUMPING TANK. WILL CHECK FOR REPAIR OR REPLACEMENT. CLOSED ON 1/21/94, SEE HISTOR"

All Materials:

Site ID:	167565
Operable Unit ID:	978472
Operable Unit:	01
Material ID:	400609
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI586 **GIGANTE VAZ & PARTNERS** **RCRA NonGen / NLR** **1000215456**
SW **295 LAFAYETTE ST - 7TH FLOOR** **FINDS** **NYD001360494**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.204 mi. **NY MANIFEST**
1076 ft. **Site 13 of 23 in cluster AI**

Relative: Higher

Actual: 42 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	GIGANTE VAZ & PARTNERS
Facility address:	295 LAFAYETTE ST - 7TH FLOOR NEW YORK, NY 10012
EPA ID:	NYD001360494
Mailing address:	LAFAYETTE ST - 7TH FLOOR NEW YORK, NY 10012
Contact:	Not reported
Contact address:	LAFAYETTE ST - 7TH FLOOR NEW YORK, NY 10012
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PAUL GIGANTE
Owner/operator address:	295 LAFAYETTE ST NEW YORK, NY 10012

GIGANTE VAZ & PARTNERS (Continued) **1000215456**

Owner/operator country: US
Owner/operator telephone: 212-343-0004
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PAUL GIGANTE
Owner/operator address: 295 LAFAYETTE ST
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-343-0004
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: GIGANTE VAZ & PARTNERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: GIGANTE VAZ & PARTNERS
Classification: Not a generator, verified

Date form received by agency: 11/08/1993
Site name: GIGANTE VAZ & PARTNERS
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

GIGANTE VAZ & PARTNERS (Continued) **1000215456**

. Waste code: K086
. Waste name: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

Violation Status: No violations found

FINDS:

Registry ID: 110004334051

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000215456
Registry ID: 110004334051
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004334051

NY MANIFEST:
Country: USA
EPA ID: NYD001360494
Facility Status: Not reported
Location Address 1: 295 LA FAYETTE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001360494
Mailing Name: GIGANTE-VAZ
Mailing Contact: C PERACCHINO
Mailing Address 1: 295 LA FAYETTE ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10012
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123430004

NY MANIFEST:
Document ID: NJA2695775

GIGANTE VAZ & PARTNERS (Continued) **1000215456**

Manifest Status:	K
seq:	Not reported
Year:	1996
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	11/19/1996
Trans1 Recv Date:	11/19/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/21/1996
Part A Recv Date:	/ /
Part B Recv Date:	12/17/1996
Generator EPA ID:	NYD001360494
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00785
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
5 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI587 **PRATT INSTITUTE - PUCK BUILDING** **RCRA NonGen / NLR** **1004762826**
SW **295 LAFAYETTE ST 2ND FL** **ICIS** **NYR000100867**
1/8-1/4 **NEW YORK, NY 10012** **FINDS**
0.204 mi. **ECHO**
1076 ft. **Site 14 of 23 in cluster AI** **NY MANIFEST**
RI MANIFEST

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/22/2015
Facility name:	PRATT INSTITUTE - PUCK BUILDING
Facility address:	295 LAFAYETTE ST 2ND FL NEW YORK, NY 10012
EPA ID:	NYR000100867

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

Mailing address:	WILLOUGHBY AVE
	BROOKLYN, NY 11205
Contact:	RON LECLAIR
Contact address:	WILLOUGHBY AVE
	BROOKLYN, NY 11205
Contact country:	US
Contact telephone:	718-399-4250
Contact email:	EHS@PRATT.EDU
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2007
Site name:	PRATT INSTITUTE - PUCK BUILDING
Classification:	Small Quantity Generator

Date form received by agency:	01/01/2006
Site name:	PRATT INSTITUTE - PUCK BUILDING
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	09/09/2001
Site name:	PRATT INSTITUTE - PUCK BUILDING
Classification:	Conditionally Exempt Small Quantity Generator

. Waste code:	D000
. Waste name:	Not Defined

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

. Waste code:	D002
. Waste name:	CORROSIVE WASTE

. Waste code:	D003
. Waste name:	REACTIVE WASTE

. Waste code:	D006

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/05/2000
Date achieved compliance: 11/05/2003
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/24/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 12/05/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/05/2003
Evaluation lead agency: EPA

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

ICIS:

Enforcement Action ID:	02-2002-7104
FRS ID:	Not reported
Action Name:	PRATT INSTITUTE
Facility Name:	PRATT INSTITUTE - PUCK BUILDING
Facility Address:	295 LAFAYETTE ST 2ND FL NEW YORK, NY 10012
Enforcement Action Type:	RCRA 3008A AO For Comp And/Or Penalty
Facility County:	NEW YORK
Program System Acronym:	RCRAINFO
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	3008A
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.72441
Longitude in Decimal Degrees:	-73.99588
Permit Type Desc:	Not reported
Program System Acronym:	NYR000100867
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

FINDS:

Registry ID: 110066985472

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762826
Registry ID:	110066985472
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110066985472

NY MANIFEST:

Country:	USA
EPA ID:	NYR000100867
Facility Status:	Not reported
Location Address 1:	142 W 14TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

NY MANIFEST:

EPAID:	NYR000100867
Mailing Name:	PRATT INSTITUTE
Mailing Contact:	MATTHEW YEAGER
Mailing Address 1:	142 W 14TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10011
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126477776

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	10/29/2014
Trans1 Recv Date:	10/29/2014
Trans2 Recv Date:	11/05/2014
TSD Site Recv Date:	11/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000100867
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	007884948FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	82
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
34 additional NY_MANIFEST: record(s) in the EDR Site Report.

RI MANIFEST:

EPA Id:	NYR000100867
GEN Cert Date:	4/2/2008
Manifest Document Number:	000066632UIS
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
TSDF Id:	RID084802842
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC
Qty:	15
WT/Vol Units:	G
TSDF Date:	4/9/2008
Transporter 2 Id:	Not reported
Item Number:	a
Transporter 2 Name:	Not reported
Transporter Name 2:	SAFETY-KLEEN SYSTEMS INC
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	4/2/2008
Number Of Containers:	3
Container Type:	DM
Waste Code1:	D001
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	4/2/2008
Number Of Containers:	3
Container Type:	DM
Waste Code1:	D001

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000100867
Manifest Docket Number:	000066632UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	15
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS INC
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/2/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	4/9/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	4/2/2008
Number Of Containers:	3
Container Type:	DM
Waste Code1:	D001
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000100867
Manifest Docket Number:	000066632UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

Transporter Contact Name:	Not reported
Quantity:	15
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS INC
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/2/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	4/9/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	12/6/2007
Number Of Containers:	3
Container Type:	DM
Waste Code1:	D001
Waste Code2:	D039
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000100867
Manifest Docket Number:	000054987UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	15
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/6/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported

PRATT INSTITUTE - PUCK BUILDING (Continued) **1004762826**

Manifest Created Date:	Not reported
TSDF Receipt Date:	12/11/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/6/2007
Number Of Containers:	3
Container Type:	DM
Waste Code1:	D001
Waste Code2:	D039
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000100867
Manifest Docket Number:	000054987UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	15
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/6/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	12/11/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

AI588 **PUCK BUILDING** **NY AST** **U003391608**
SW **295 LAFAYETTE STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.204 mi.
1076 ft. **Site 15 of 23 in cluster AI**

Relative: AST:
Higher

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-402052

Actual:
42 ft.

PUCK BUILDING (Continued) **U003391608**

Program Type:	PBS
UTM X:	584862.18567
UTM Y:	4508712.19787
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19242
Affiliation Type:	Mail Contact
Company Name:	NEW PUCK LP
Contact Type:	Not reported
Contact Name:	PROPERTY MANAGER
Address1:	18 COLUMBIA TURNPIKE
Address2:	Not reported
City:	FLORHAM PARK
State:	NJ
Zip Code:	07932
Country Code:	001
Phone:	(973) 822-0050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-05-12

Site Id:	19242
Affiliation Type:	Facility Operator
Company Name:	PUCK BUILDING
Contact Type:	Not reported
Contact Name:	ANTHONY KOLODZIEJCZYK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 966-0750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19242
Affiliation Type:	Emergency Contact
Company Name:	NEW PUCK LP
Contact Type:	Not reported
Contact Name:	DONNY FURER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(973) 549-4952
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

PUCK BUILDING (Continued) **U003391608**

Site Id:	19242
Affiliation Type:	Facility Owner
Company Name:	NEW PUCK LP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	18 COLUMBIA TURNPIKE
Address2:	Not reported
City:	FLORHAM PARK
State:	NJ
Zip Code:	07932
Country Code:	001
Phone:	(973) 822-0050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-05-12

Tank Info:

Tank Number:	001
Tank Id:	21882
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/08/1984
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AE589 **92 2ND AVENUE** **NY AST** **A100178075**
East **92 SECOND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.204 mi.
1077 ft. **Site 5 of 11 in cluster AE**

Relative:
Lower

Actual:
35 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605806
Program Type:	PBS
UTM X:	585431.35683
UTM Y:	4508950.54267
Expiration Date:	06/10/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27673
Affiliation Type:	Mail Contact
Company Name:	92 SECOND AVE LLC
Contact Type:	Not reported
Contact Name:	LEOR SABET
Address1:	38 WEST 31ST STREET
Address2:	SUITE 3
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 239-8785
EMail:	LEOR@SABETGROUP.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-23

Site Id:	27673
Affiliation Type:	Facility Operator
Company Name:	92 2ND AVENUE
Contact Type:	Not reported
Contact Name:	NA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 239-8785
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-23

Site Id:	27673
Affiliation Type:	Emergency Contact
Company Name:	92 SECOND AVE LLC
Contact Type:	Not reported
Contact Name:	LEOR SABET
Address1:	Not reported
Address2:	Not reported
City:	Not reported

92 2ND AVENUE (Continued) **A100178075**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 582-9978
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-23

Site Id:	27673
Affiliation Type:	Facility Owner
Company Name:	92 SECOND AVE LLC
Contact Type:	MEMBER
Contact Name:	LEOR SABET
Address1:	38 WEST 31ST STREET, SUITE 3
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 239-8785
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-23

Tank Info:

Tank Number:	001
Tank Id:	60501
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1983
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW

92 2ND AVENUE (Continued) **A100178075**

Last Modified: 08/23/2017
Material Name: #2 fuel oil (on-site consumption)

AE590 **RED HOUSE REALTY CORP/LINDA GEISER** **NY AST** **A100178045**
East **317 EAST 5TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.204 mi.
1077 ft. **Site 6 of 11 in cluster AE**

Relative:
Lower

Actual:
35 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605762
Program Type: PBS
UTM X: 585453.54847
UTM Y: 4508891.55100
Expiration Date: 04/25/2021
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 27629
Affiliation Type: Facility Owner
Company Name: RED HOUSE REALTY CORP.
Contact Type: PRESIDENT
Contact Name: LINDA GEISER
Address1: 317 E. 5TH ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 673-5422
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-02-01

Site Id: 27629
Affiliation Type: Mail Contact
Company Name: RED HOUSE REALTY CORP.
Contact Type: Not reported
Contact Name: LINDA GEISER
Address1: 317 EAST 5TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 673-5422
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 27629
Affiliation Type: Facility Operator
Company Name: RED HOUSE REALTY CORP/LINDA GEISER

RED HOUSE REALTY CORP/LINDA GEISER (Continued) **A100178045**

Contact Type:	Not reported
Contact Name:	LINDA GEISER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 673-5422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27629
Affiliation Type:	Emergency Contact
Company Name:	RED HOUSE REALTY CORP.
Contact Type:	Not reported
Contact Name:	JOHN DURGIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 673-5422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-03-28

Tank Info:

Tank Number:	001
Tank Id:	60433
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
D00 - Pipe Type - No Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1953
Capacity Gallons:	1500

RED HOUSE REALTY CORP/LINDA GEISER (Continued) **A100178045**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AR591 **CON EDISON** **NY MANIFEST** **S117066495**
North **297 MERCER ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.204 mi.
1077 ft. **Site 1 of 8 in cluster AR**

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591509
Facility Status:	Not reported
Location Address 1:	297 MERCER ST
Code:	BP
Location Address 2:	SB 41055
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591509
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591509
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105

CON EDISON (Continued) **S117066495**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002608310GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AC592 **CON ED** **NY MANIFEST** **S118463740**
ESE **97 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.204 mi.
1078 ft. **Site 30 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856355
Facility Status:	Not reported
Location Address 1:	97 E 4TH ST
Code:	BP
Location Address 2:	SB 859
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856355
Mailing Name:	CON ED

CON ED (Continued) **S118463740**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856355
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085706JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON ED (Continued) **S118463740**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AC593 **CON EDISON** **RCRA NonGen / NLR** **1019902621**
ESE **97 E 4TH ST** **FINDS** **NYP004775912**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.204 mi.
1078 ft. **Site 31 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/28/2015
Facility name: CON EDISON
Facility address: 97 E 4TH ST
NEW YORK, NY 10003
EPA ID: NYP004775912
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/28/2015
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069691177

CON EDISON (Continued) **1019902621**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019902621
Registry ID: 110069691177
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069691177

AC594 **CON EDISON** **NY MANIFEST** **S118463687**
ESE **97 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.204 mi.
1078 ft. **Site 32 of 33 in cluster AC**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004775912
Facility Status: Not reported
Location Address 1: 2 AVE & E. 4TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004775912
Mailing Name: CON EDISON
Mailing Contact: TOM TELLING
Mailing Address 1: 4 IRVING PLACE-15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/29/2015

CON EDISON (Continued) **S118463687**

Trans1 Recv Date:	04/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004775912
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454361JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	139
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	D018
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP004855546
Facility Status:	Not reported
Location Address 1:	97 E 4TH ST
Code:	BP
Location Address 2:	SB 858
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

CON EDISON (Continued) **S118463687**

NY MANIFEST:

EPAID:	NYP004855546
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855546
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245214JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S118463687**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AC595 **CON EDISON** **NJ MANIFEST** **S120671177**
ESE **97 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.204 mi.
1078 ft. **Site 33 of 33 in cluster AC**

Relative: **Lower**

Actual: **35 ft.**

NJ MANIFEST:

EPA Id:	NYP004775912
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454361JJK
EPA ID:	NYP004775912
Date Shipped:	4/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON (Continued) **S120671177**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AO596 **266 ELIZABETH ST** **NY AST** **A100366135**
South **266 ELIZABETH ST** **N/A**
1/8-1/4 **NY, NY 10012**
0.205 mi.
1080 ft. **Site 5 of 13 in cluster AO**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-611945
Program Type:	PBS
UTM X:	584994.79841
UTM Y:	4508595.06799
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	477649
Affiliation Type:	Facility Owner
Company Name:	ELIZABETH STONE LLC
Contact Type:	MANAGING PRINCIPAL
Contact Name:	JEFFERY KAYE
Address1:	599 LEXINGTON AVE, 36TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 808-2917
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-01-09

Site Id:	477649
Affiliation Type:	Mail Contact
Company Name:	STONE STREET PROPERTIES LLC

266 ELIZABETH ST (Continued) **A100366135**

Contact Type:	Not reported
Contact Name:	BRETT HARRIS
Address1:	599 LEXINGTON AVE, 36TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 808-2921
EMail:	BRETT@SSPNY.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-01-09

Site Id:	477649
Affiliation Type:	Facility Operator
Company Name:	266 ELIZABETH ST
Contact Type:	Not reported
Contact Name:	STONE STREET PROPERTIES LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 808-2917
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-01-09

Site Id:	477649
Affiliation Type:	Emergency Contact
Company Name:	ELIZABETH STONE LLC
Contact Type:	Not reported
Contact Name:	BRETT HARRIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-01-09

Tank Info:

Tank Number:	001
Tank Id:	246901
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tank Location:	3
Tank Type:	ZZ

266 ELIZABETH ST (Continued) **A100366135**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AJ597 **47 EAST 3RD STREET** **NY AST** **U003392129**
ESE **47 EAST 3RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.205 mi.
1084 ft. **Site 6 of 9 in cluster AJ**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-214973
Program Type:	PBS
UTM X:	585380.61706
UTM Y:	4508779.87666
Expiration Date:	08/20/2018
Site Type:	Private Residence

Affiliation Records:

Site Id:	8012
Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	ALISTAIR ECONOMAKIS
Address1:	138 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 625-4114 304
EMail:	ACE@GRANITEMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-09

Site Id:	8012
Affiliation Type:	Facility Operator
Company Name:	47 EAST 3RD STREET
Contact Type:	Not reported
Contact Name:	ALISTAIR ECONOMAKIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

47 EAST 3RD STREET (Continued) **U003392129**

Country Code:	001
Phone:	(718) 625-4114 304
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-09

Site Id:	8012
Affiliation Type:	Emergency Contact
Company Name:	ALISTAIR AND CATHERINE ECONOMAKIS
Contact Type:	Not reported
Contact Name:	ALISTAIR ECONOMAKIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 379-5085
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-09

Site Id:	8012
Affiliation Type:	Facility Owner
Company Name:	ALISTAIR AND CATHERINE ECONOMAKIS
Contact Type:	OWNER
Contact Name:	ALISTAIR ECONOMAKIS
Address1:	138 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(917) 379-5085
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-09

Tank Info:

Tank Number:	001
Tank Id:	23604
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

47 EAST 3RD STREET (Continued) **U003392129**

C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/20/2003
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMMOLOUG
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AP598 **248 NORTH 8TH STREET (SITE B)** **NY VCP** **S118943208**
NE **248 NORTH 8TH STREET (SITE B)** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.205 mi.
1085 ft. **Site 3 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

VCP NYC:

Project ID:	12CVCP069K
Project Name:	248 NORTH 8TH STREET (SITE B)
Project Address:	248 NORTH 8TH STREET (SITE B)
Borough:	BROOKLYN

VCP NYC:

Project ID:	12CVCP069K
File Name:	Please see the list of documents under Site A.
URL:	#VALUE!

AE599 **309 E. 5TH STREET** **NY AST** **A100168951**
East **309 EAST FIFTH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.205 mi.
1085 ft. **Site 7 of 11 in cluster AE**

Relative:
Lower

Actual:
35 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-399361
Program Type:	PBS
UTM X:	585430.07044
UTM Y:	4508904.08402
Expiration Date:	10/06/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19016

309 E. 5TH STREET (Continued) **A100168951**

Affiliation Type:	Facility Owner
Company Name:	309 EAST 5TH STREET LLC
Contact Type:	AGENT
Contact Name:	FRED FRAGANO
Address1:	250 PARK AVENUE, SUITE 1901
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10177
Country Code:	001
Phone:	(212) 972-5900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	19016
Affiliation Type:	Facility Operator
Company Name:	309 E. 5TH STREET
Contact Type:	Not reported
Contact Name:	BENNY SULIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 691-6966
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	19016
Affiliation Type:	Emergency Contact
Company Name:	309 EAST 5TH STREET LLC
Contact Type:	Not reported
Contact Name:	BENNY SULIC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 691-6966
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-11

Site Id:	19016
Affiliation Type:	Mail Contact
Company Name:	R.A. COHEN & ASSOCIATES, INC.
Contact Type:	Not reported
Contact Name:	FRED FRAGANO
Address1:	250 PARK AVENUE
Address2:	SUITE 1901

309 E. 5TH STREET (Continued) **A100168951**

City:	NEW YORK
State:	NY
Zip Code:	10177
Country Code:	001
Phone:	(212) 835-9526
EMail:	FRED@RACOHEN.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-01-10

Tank Info:

Tank Number:	001
Tank Id:	21619
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1955
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	10/11/2017
Material Name:	#2 fuel oil (on-site consumption)

AG600 **CON EDISON SERVICE BOX: 40674** **RCRA NonGen / NLR** **1016966716**
ENE **6-8 ST MARKS** **NY MANIFEST** **NYP004395612**
1/8-1/4 **NEW YORK, NY 10009**
0.206 mi.
1086 ft. **Site 4 of 7 in cluster AG**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 40674
Facility address:	6-8 ST MARKS NEW YORK, NY 10009
EPA ID:	NYP004395612

CON EDISON SERVICE BOX: 40674 (Continued) **1016966716**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 40674
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395612
Facility Status: Not reported
Location Address 1: 6-8 ST MARKS PL
Code: BP
Location Address 2: SB40674
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10009
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395612
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY

CON EDISON SERVICE BOX: 40674 (Continued) **1016966716**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/21/2013
Trans1 Recv Date:	11/21/2013
Trans2 Recv Date:	11/25/2013
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395612
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237086GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AL601 **24 SECOND AVE MOBIL** **NY LTANKS** **S100146663**
SSE **24 SECOND AVE & 1ST ST** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.206 mi.
1087 ft. **Site 3 of 24 in cluster AL**

Relative: **Lower**

Actual: **40 ft.**

LTANKS:

Facility ID:	9010367
Site ID:	91409
Closed Date:	1991-05-02
Spill Number:	9010367
Spill Date:	1990-06-06
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1991-05-02
SWIS:	3101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1990-12-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-01-09
Spill Record Last Update:	2003-12-05
Spiller Name:	Not reported
Spiller Company:	MOBIL OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	82257
DEC Memo:	""
Remarks:	"TESTS WERE NOT DONE ON TANKS, TANKS REPLACED IN 1987,SITE ASSESSMENT WAS DONE, 4 MONITORING WELLS INSTALLED."

All Materials:

Site ID:	91409
Operable Unit ID:	947505
Operable Unit:	01
Material ID:	430527
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AL602 **WESTFIELD SECOND ASSOCIATES** **NY UST** **U001831286**
SSE **24 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.206 mi.
1087 ft. **Site 4 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

UST:

Id/Status:	2-032158 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585230.36914
UTM Y:	4508754.35980
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	190
Affiliation Type:	Facility Owner
Company Name:	WESTFIELD SECOND ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	25 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 533-4580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	190
Affiliation Type:	Mail Contact
Company Name:	WESTFIELD SECOND ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	25 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 533-4580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	190
Affiliation Type:	Facility Operator
Company Name:	WESTFIELD SECOND ASSOCIATES
Contact Type:	Not reported
Contact Name:	SAMUEL GILLETTE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

WESTFIELD SECOND ASSOCIATES (Continued) **U001831286**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 533-4580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	190
Affiliation Type:	Emergency Contact
Company Name:	WESTFIELD SECOND ASSOCIATES
Contact Type:	Not reported
Contact Name:	KEITH M DOUGLAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 979-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	860
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1985
Date Tank Closed:	01/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other

WESTFIELD SECOND ASSOCIATES (Continued) **U001831286**

Tank Number:	002
Tank ID:	861
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1985
Date Tank Closed:	01/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	862
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	3000
Install Date:	12/01/1981
Date Tank Closed:	01/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

WESTFIELD SECOND ASSOCIATES (Continued) **U001831286**

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other

AL603 **CON EDISON** **NY E DESIGNATION** **S109527536**
SSE **24 2 AVE** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.206 mi.
1087 ft. **Site 5 of 24 in cluster AL**

Relative: **Lower**
Actual: **40 ft.**

E DESIGNATION:

Tax Lot(s):	1
Tax Block:	443
Borough Code:	Not reported
E-No:	E-216
Effective Date:	11/19/2008
Satisfaction Date:	Not reported
Ceqr Number:	07DCP078M
Ulurp Number:	080397ZMM
Zoning Map No:	12c
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004586970
Facility Status:	Not reported
Location Address 1:	24 2 AVE
Code:	BP
Location Address 2:	SB53928
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586970
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S109527536**

Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586970
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503421GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AL604 **GAS STATION** **NY LTANKS** **S106703784**
SSE **24 SECOND AVE** **N/A**
1/8-1/4 **NEW YORK, NY**
0.206 mi.
1087 ft. **Site 6 of 24 in cluster AL**

Relative: LTANKS:
Lower

Facility ID:	9603385
Site ID:	295854
Closed Date:	1996-06-11
Spill Number:	9603385

Actual:
40 ft.

GAS STATION (Continued) **S106703784**

Spill Date:	1996-06-10
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1996-06-11
CID:	349
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-06-11
Spill Record Last Update:	2003-12-05
Spiller Name:	MR LAUTH
Spiller Company:	ISLAND TRANPORTATION
Spiller Address:	299 EDISON AV
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(212) 979-7000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	239422
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG CALLED MR LAUTH, HE SAID SPILL HAPPEN LAST NUGHT - OVERFILL CAME OUT FROM THE STICK HOLE, SOME GOT INTO SEWER DRAIN, MOST WAS PICKED UP BY SPEEDY DRY. ALSO CLEANED UP SEWER DRAIN WITH PADS."
Remarks:	"DRIVER OVERFILLED TANK - VERY SMALL AMOUNT WENT INTO DRAIN - DRAIN WAS CLEANED W/ABSORBANT PAD AND SPEEDY-DRY USED FOR CLEAN UP ON PAVEMENT "

All Materials:

Site ID:	295854
Operable Unit ID:	1034675
Operable Unit:	01
Material ID:	349649
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

AL605 **24 SECOND AVENUE OWNER LLC** **NY UST** **U003241868**
SSE **24 SECOND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.206 mi.
1087 ft. **Site 7 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

UST:

Id/Status:	2-603153 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585230.36914
UTM Y:	4508754.35980
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	25105
Affiliation Type:	Facility Owner
Company Name:	24 SECOND AVENUE OWNER LLC
Contact Type:	MEMBER
Contact Name:	YAN QUAKNINE
Address1:	49 BLEEKER STREET, SUITE 301
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 501-0050
EMail:	YAN@AOREH.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-10-05

Site Id:	25105
Affiliation Type:	Mail Contact
Company Name:	24 SECOND AVENUE OWNER LLC
Contact Type:	MEMBER
Contact Name:	YAN QUAKNINE
Address1:	49 BLEEKER STREET, SUITE 301
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 501-0050
EMail:	YAN@AOREH.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-10-05

Site Id:	25105
Affiliation Type:	Facility Operator
Company Name:	24 SECOND AVENUE OWNER LLC
Contact Type:	Not reported
Contact Name:	HILLEL KATZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

24 SECOND AVENUE OWNER LLC (Continued) **U003241868**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 501-0050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-10-05

Site Id:	25105
Affiliation Type:	Emergency Contact
Company Name:	WESTFIELD SECOND ASSOC.
Contact Type:	Not reported
Contact Name:	HILLEL KATZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 519-7361
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-10-05

Tank Info:

Tank Number:	001
Tank ID:	53263
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1985
Date Tank Closed:	01/23/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

Tightness Test Method:	21
Date Test:	02/22/2011
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JAAVERSA
Last Modified:	10/05/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
L99 - Piping Leak Detection - Other
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

24 SECOND AVENUE OWNER LLC (Continued) **U003241868**

B08 - Tank External Protection - Retrofitted Impressed Current
F08 - Pipe External Protection - Retrofitted Impressed Current
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	002
Tank ID:	53264
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	12/01/1985
Date Tank Closed:	01/23/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	02/22/2011
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JAAVERSA
Last Modified:	10/05/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J00 - Dispenser - None
B08 - Tank External Protection - Retrofitted Impressed Current
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
F08 - Pipe External Protection - Retrofitted Impressed Current

Tank Number:	003
Tank ID:	53265
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1985
Date Tank Closed:	01/23/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	02/22/2011
Next Test Date:	Not reported
Pipe Model:	Not reported

24 SECOND AVENUE OWNER LLC (Continued) **U003241868**

Modified By:	JAAVERSA
Last Modified:	10/05/2017

Equipment Records:

A00 - Tank Internal Protection - None
L99 - Piping Leak Detection - Other
B08 - Tank External Protection - Retrofitted Impressed Current
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
F08 - Pipe External Protection - Retrofitted Impressed Current
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	004
Tank ID:	239564
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1985
Date Tank Closed:	01/23/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JAAVERSA
Last Modified:	10/05/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

AG606 **ST MARKS HOTEL** **NY AST** **A100296134**
NE **2 ST. MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.206 mi.
1089 ft. **Site 5 of 7 in cluster AG**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608643
Program Type:	PBS
UTM X:	585301.31754
UTM Y:	4509216.14489
Expiration Date:	03/19/2018
Site Type:	Other

Affiliation Records:

Site Id:	30495
Affiliation Type:	Facility Owner
Company Name:	2 ST MARKS PLACE HOTEL CORP
Contact Type:	OFFICER
Contact Name:	WILLIAM PAPPAS
Address1:	2 ST. MARKS PLACE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-0100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-02-17

Site Id:	30495
Affiliation Type:	Mail Contact
Company Name:	ST MARKS HOTEL CORP
Contact Type:	Not reported
Contact Name:	WILLIAM PAPPAS
Address1:	2 ST. MARKS PLACE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-0100
EMail:	STMARKSHOTEL@AOL.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-02-17

Site Id:	30495
Affiliation Type:	Facility Operator
Company Name:	ST MARKS HOTEL
Contact Type:	Not reported
Contact Name:	WILLIAM PAPPAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported

ST MARKS HOTEL (Continued) **A100296134**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 674-0100
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2017-02-17

Site Id: 30495
Affiliation Type: Emergency Contact
Company Name: 2 ST MARKS PLACE HOTEL CORP
Contact Type: Not reported
Contact Name: WILLIAM PAPPAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 674-0100
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2017-02-17

Tank Info:

Tank Number: 1500
Tank Id: 65431
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
J05 - Dispenser - On Site Heating System (Supply/Return)
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1992
Capacity Gallons: 1500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

ST MARKS HOTEL (Continued) **A100296134**

Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AL607 **CON EDISON** **NY MANIFEST** **S117066078**
SE **28 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.207 mi.
1091 ft. **Site 8 of 24 in cluster AL**

Relative: **Lower**
Actual: **39 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004586954
Facility Status:	Not reported
Location Address 1:	28 2ND AVE
Code:	BP
Location Address 2:	SB53930
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586954
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586954
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503424GBF
Import Indicator:	N
Export Indicator:	N

CON EDISON (Continued) **S117066078**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH608 **CON EDISON VAULT: 1335** **RCRA NonGen / NLR** **1016963790**
NNE **136 E 8TH ST FRONT OF VAULT 1335** **NY MANIFEST** **NYP004367637**
1/8-1/4 **NEW YORK, NY 10010**
0.207 mi.
1092 ft. **Site 21 of 23 in cluster AH**

Relative: **Lower**

Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/29/2013
Facility name:	CON EDISON VAULT: 1335
Facility address:	136 E 8TH ST FRONT OF VAULT 1335 NEW YORK, NY 10010
EPA ID:	NYP004367637
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON VAULT: 1335 (Continued) **1016963790**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/29/2013
Site name: CON EDISON VAULT: 1335
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004367637
Facility Status: Not reported
Location Address 1: E 8TH ST 136 CTR
Code: BP
Location Address 2: V# 1335
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10010
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004367637
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2013

CON EDISON VAULT: 1335 (Continued) **1016963790**

Trans1 Recv Date:	09/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004367637
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002086132GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AH609 **CON EDISON VAULT: 3384** **RCRA NonGen / NLR** **1016963789**
NNE **136 E 8TH ST FRONT OF VAULT 3384** **NY MANIFEST** **NYP004367629**
1/8-1/4 **NEW YORK, NY 10010**
0.207 mi.
1092 ft. **Site 22 of 23 in cluster AH**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/29/2013
Facility name:	CON EDISON VAULT: 3384
Facility address:	136 E 8TH ST FRONT OF VAULT 3384 NEW YORK, NY 10010
EPA ID:	NYP004367629
Mailing address:	IRVING PL, 15TH FL NE

CON EDISON VAULT: 3384 (Continued) **1016963789**

NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/29/2013
Site name: CON EDISON VAULT: 3384
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004367629
Facility Status: Not reported
Location Address 1: E 8TH ST 136 EIY
Code: BP
Location Address 2: V# 3384
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10010
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004367629
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON VAULT: 3384 (Continued) **1016963789**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/29/2013
Trans1 Recv Date:	09/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004367629
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002086130GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AP610 **CON EDISON - MH 24349** **RCRA NonGen / NLR** **1008195548**
NE **2-4 ALBANY STREET** **NY MANIFEST** **NYP004108353**
1/8-1/4 **NEW YORK, NY 10004**
0.207 mi.
1092 ft. **Site 4 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/27/2004
Facility name:	CON EDISON - MH 24349
Facility address:	2-4 ALBANY STREET NEW YORK, NY 10004
EPA ID:	NYP004108353
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/07/2003
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/07/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON - MH 24349 (Continued) **1008195548**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/26/2004
Site name: CON EDISON - MH 24349
Classification: Not a generator, verified

Date form received by agency: 02/25/2004
Site name: CON EDISON - MH 24349
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004108353
Facility Status: Not reported
Location Address 1: MH24349-ALBANY & WASHINGTON
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004108353
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: CTF0836021
Manifest Status: Not reported
seq: 01
Year: 2003
Trans1 State ID: 13266MA
Trans2 State ID: 13266MA

CON EDISON - MH 24349 (Continued) **1008195548**

Generator Ship Date:	03/18/2003
Trans1 Recv Date:	03/18/2003
Trans2 Recv Date:	03/20/2003
TSD Site Recv Date:	03/20/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004108353
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	MAD039322250
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00001
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI611 **BP LAFAYETTE (FORMERLY)** **NY UST U001833038**
SW **21 EAST HOUSTON STREET** **NY Spills N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.207 mi.
1093 ft. **Site 16 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

UST:

Id/Status:	2-191256 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584799.52795
UTM Y:	4508696.53787
Site Type:	Other

Affiliation Records:

Site Id:	5951

BP LAFAYETTE (FORMERLY) (Continued) **U001833038**

Affiliation Type:	Emergency Contact
Company Name:	PACO LAFAYETTE LLC
Contact Type:	Not reported
Contact Name:	ADAM GOOD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 612-7350
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-07-11

Site Id:	5951
Affiliation Type:	Facility Operator
Company Name:	BP LAFAYETTE (FORMERLY)
Contact Type:	Not reported
Contact Name:	HARRIS KALISH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 765-6446
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-07-11

Site Id:	5951
Affiliation Type:	Facility Owner
Company Name:	PACO LAFAYETTE LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	275 MADISON AVE, 37TH FL
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(646) 612-7350
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-07-11

Site Id:	5951
Affiliation Type:	Mail Contact
Company Name:	GASETERIA OIL CORP.
Contact Type:	Not reported
Contact Name:	ADAM GOOD
Address1:	275 MADISON AVE, 37TH FL
Address2:	Not reported

BP LAFAYETTE (FORMERLY) (Continued) **U001833038**

City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(646) 612-7350
EMail:	AGOOD@LARGAVISTA.COM
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-07-11

Tank Info:

Tank Number:	001
Tank ID:	7443
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	02/01/1977
Date Tank Closed:	05/09/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	12/13/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

F08 - Pipe External Protection - Retrofitted Impressed Current
H99 - Tank Leak Detection - Other
B08 - Tank External Protection - Retrofitted Impressed Current
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other
I03 - Overfill - Automatic Shut-Off
D02 - Pipe Type - Galvanized Steel

Tank Number:	002
Tank ID:	7444
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	02/01/1977
Date Tank Closed:	05/09/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009

BP LAFAYETTE (FORMERLY) (Continued) **U001833038**

Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 12/13/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
B08 - Tank External Protection - Retrofitted Impressed Current
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
F08 - Pipe External Protection - Retrofitted Impressed Current

Tank Number: 003
Tank ID: 7445
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 02/01/1977
Date Tank Closed: 05/09/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 12/13/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G99 - Tank Secondary Containment - Other
D02 - Pipe Type - Galvanized Steel
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
B08 - Tank External Protection - Retrofitted Impressed Current

Tank Number: 004

BP LAFAYETTE (FORMERLY) (Continued) **U001833038**

Tank ID:	206243
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	05/20/2005
Date Tank Closed:	05/19/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	E
Modified By:	MXLAY
Last Modified:	04/14/2017

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed

Tank Number:	005
Tank ID:	206244
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	05/20/2005
Date Tank Closed:	05/19/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	E
Modified By:	MXLAY
Last Modified:	04/14/2017

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector

BP LAFAYETTE (FORMERLY) (Continued) **U001833038**

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

SPILLS:

Facility ID:	9408102
Facility Type:	ER
Spill Number:	9408102
DER Facility ID:	163984
Site ID:	197004
DEC Region:	2
Closed Date:	2005-10-26
Spill Cause:	Other
Spill Class:	B3
SWIS:	3101
Spill Date:	1994-09-14
Investigator:	aaobliga
Referred To:	Not reported
Reported to Dept:	1994-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-28
Spill Record Last Update:	2006-01-06
Spiller Name:	Not reported
Spiller Company:	GASETERIA
Spiller Address:	300 LAFAYETTE ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 1/12/2004-Vought-Spill transferred from Rommel to Vought. 9/26/05- OBLIGADO - FILE TRANSFERRED FROM VOUGHT TO OBLIGADO 10/26/05 - Olbigado - Site now listed as 21 East Houston Street. Closed spill number 9408102 and consolidated it with newer spill number 0230042. "
Remarks:	"DISCOVERED IN INVENTORY CHECK TO TEST TANK (TOMASELLO)"

All Materials:

Site ID:	197004
Operable Unit ID:	1002234
Operable Unit:	01

BP LAFAYETTE (FORMERLY) (Continued) **U001833038**

Material ID:	377546
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP612 **CON EDISON MANHOLE: 30947** **NJ MANIFEST** **S117987146**
NE **E COOPER SQ & 4TH AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.208 mi.
1096 ft. **Site 5 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYP004280277
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	RICARDO CARTY
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010840122JJK
EPA ID:	NYP004280277
Date Shipped:	12/11/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON MANHOLE: 30947 (Continued) **S117987146**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,500.00 Pounds

AP613 **CON EDISON** **NJ MANIFEST** **S120677090**
NE **4TH AVE & COOPER SQ** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.208 mi.
1096 ft. **Site 6 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

NJ MANIFEST:

EPA Id:	NYP004842965
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002613302GBF
EPA ID:	NYP004842965
Date Shipped:	9/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported

CON EDISON (Continued) **S120677090**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AP614 **CON EDISON** **NY MANIFEST** **S119077962**
NE **4TH AVE & COOPER SQ** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.208 mi.
1096 ft. **Site 7 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004842965
Facility Status:	Not reported
Location Address 1:	ASTOR PL & COOPER SQ
Code:	BP
Location Address 2:	SB 61134
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004842965

CON EDISON (Continued) **S119077962**

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2015
Trans1 Recv Date:	09/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004842965
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613302GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S119077962**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AP615 **CON EDISON** **RCRA NonGen / NLR** **1019908189**
NE **4TH AVE & COOPER SQ** **FINDS** **NYP004842965**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.208 mi.
1096 ft. **Site 8 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/23/2015
Facility name: CON EDISON
Facility address: 4TH AVE & COOPER SQ
NEW YORK, NY 10003
EPA ID: NYP004842965
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/23/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019908189**

Registry ID: 110069660138

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019908189
Registry ID: 110069660138
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069660138

AP616 **MTA NYCT ASTOR PLACE STATION** **RCRA NonGen / NLR** **1001128032**
NE **ASTOR PL & 4TH AVE** **NYR000037044**
1/8-1/4 **NEW YORK, NY 10013**
0.208 mi.
1096 ft. **Site 9 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MTA NYCT ASTOR PLACE STATION
Facility address: ASTOR PL & 4TH AVE
NEW YORK, NY 10013
EPA ID: NYR000037044
Mailing address: COLUMBUS CIR 25TH FLOOR
NEW YORK, NY 10019
Contact: Not reported
Contact address: COLUMBUS CIR 25TH FLOOR
NEW YORK, NY 10019
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 10 COLUMBUS CIR 25TH FLOOR
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: 212-307-5589
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

MTA NYCT ASTOR PLACE STATION (Continued) **1001128032**

Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 10 COLUMBUS CIR 25TH FLOOR
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: 212-307-5589
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MTA NYCT ASTOR PLACE STATION
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MTA NYCT ASTOR PLACE STATION
Classification: Not a generator, verified

Date form received by agency: 03/27/1997
Site name: MTA NYCT ASTOR PLACE STATION
Classification: Small Quantity Generator

. Waste code: B002
. Waste name: B002

Violation Status: No violations found

AP617 **CON EDISON MANHOLE: 30947** **RCRA NonGen / NLR** **1016149364**
NE **E COOPER SQ & 4TH AVE** **NYP004280277**
1/8-1/4 **NEW YORK, NY 10003**
0.208 mi.
1096 ft. **Site 10 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON MANHOLE: 30947
Facility address:	E COOPER SQ & 4TH AVE NEW YORK, NY 10003
EPA ID:	NYP004280277
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	RICARDO CARTY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	646-772-3407
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/11/2012
Site name:	CON EDISON MANHOLE: 30947
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

AO618 **268 ELIZABETH ST PROPERTY** **NY AST** **U003391638**
South **268 ELIZABETH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.208 mi.
1097 ft. **Site 6 of 13 in cluster AO**

Relative: **Higher**
Actual: **43 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-403261
Program Type:	PBS

268 ELIZABETH ST PROPERTY (Continued) **U003391638**

UTM X: 585003.37180
UTM Y: 4508619.90159
Expiration Date: 03/11/2020
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 19350
Affiliation Type: Facility Operator
Company Name: 268 ELIZABETH ST PROPERTY
Contact Type: Not reported
Contact Name: CHAD JEWELL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 540-4612
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-27

Site Id: 19350
Affiliation Type: Emergency Contact
Company Name: 260 ELIZABETH STREET OWNER LLC
Contact Type: Not reported
Contact Name: JOEL GOLDSTEIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 434-9440
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-27

Site Id: 19350
Affiliation Type: Facility Owner
Company Name: 260 ELIZABETH STREET OWNER LLC
Contact Type: MANAGER
Contact Name: JOEL GOLDSTEIN
Address1: 1465A FLATBUSH AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11210
Country Code: 001
Phone: (718) 434-9440
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-27

Site Id: 19350

268 ELIZABETH ST PROPERTY (Continued) **U003391638**

Affiliation Type:	Mail Contact
Company Name:	GALIL MANAGEMENT LLC
Contact Type:	Not reported
Contact Name:	JOEL GOLDSTEIN
Address1:	1465A FLATBUSH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11210
Country Code:	001
Phone:	(718) 434-9440
EMail:	JGOLDSTEIN@GALILMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-27

Tank Info:

Tank Number:	001
Tank Id:	21957
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1920
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AM619 **GOTTLIEB W REAL ESTATE** **RCRA NonGen / NLR** **1004759226**
SSW **284 MULBERRY ST** **FINDS** **NYR000002188**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.208 mi. **NY MANIFEST**
1099 ft. **Site 3 of 10 in cluster AM**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	GOTTLIEB W REAL ESTATE
Facility address:	284 MULBERRY ST NEW YORK, NY 10012
EPA ID:	NYR000002188
Mailing address:	HUDSON ST NEW YORK, NY 10014
Contact:	WILLIAM GOTTLIEB
Contact address:	HUDSON ST NEW YORK, NY 10014
Contact country:	US
Contact telephone:	212-989-3100
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	W GOTTLIEB REAL ESTATE
Owner/operator address:	544 HUDSON ST NEW YORK, NY 10014
Owner/operator country:	US
Owner/operator telephone:	212-989-3100
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	W GOTTLIEB REAL ESTATE
Owner/operator address:	544 HUDSON ST NEW YORK, NY 10014
Owner/operator country:	US
Owner/operator telephone:	212-989-3100
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

GOTTLIEB W REAL ESTATE (Continued) **1004759226**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: GOTTLIEB W REAL ESTATE
Classification: Not a generator, verified

Date form received by agency: 03/23/1995
Site name: GOTTLIEB W REAL ESTATE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110004512126

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759226
Registry ID: 110004512126
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004512126

NY MANIFEST:
Country: USA
EPA ID: NYR000002188
Facility Status: Not reported
Location Address 1: 544 HUDSON STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

GOTTLIEB W REAL ESTATE (Continued) **1004759226**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000002188
Mailing Name:	GOTTLIEB W REAL ESTATE
Mailing Contact:	ALBERTO GOMEZ
Mailing Address 1:	544 HUDSON STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	8002250256

NY MANIFEST:

Document ID:	NYB6880482
Manifest Status:	K
seq:	Not reported
Year:	1995
Trans1 State ID:	NYPD1011
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/1995
Trans1 Recv Date:	04/07/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/07/1995
Part A Recv Date:	/ /
Part B Recv Date:	05/09/1995
Generator EPA ID:	NYR000002188
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

GOTTLIEB W REAL ESTATE (Continued) **1004759226**

Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AM620 **285 MOTT ST** **NY AST** **U003387817**
SSW **285 MOTT ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.208 mi.
1100 ft. **Site 4 of 10 in cluster AM**

Relative:
Higher

Actual:
42 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-235261
Program Type: PBS
UTM X: 584950.98772
UTM Y: 4508650.71113
Expiration Date: 07/10/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 8659
Affiliation Type: Mail Contact
Company Name: 285 MOTT DEVELOPMENT, LLC.
Contact Type: Not reported
Contact Name: CAROLINE PALMIERI
Address1: 23 BARROW ST
Address2: SUITE 1D
City: NEW YORK
State: NY
Zip Code: 10014
Country Code: 001
Phone: (212) 924-5924
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-06-26

Site Id: 8659
Affiliation Type: Facility Operator
Company Name: 285 MOTT ST
Contact Type: Not reported
Contact Name: LESZEK BIELA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 924-5924
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR

285 MOTT ST (Continued) **U003387817**

Date Last Modified: 2017-06-26

Site Id: 8659
Affiliation Type: Emergency Contact
Company Name: 285 MOTT DEVELOPMENT LLC
Contact Type: Not reported
Contact Name: CAROLINE PALMIERI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 924-5924
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-06-26

Site Id: 8659
Affiliation Type: Facility Owner
Company Name: 285 MOTT DEVELOPMENT LLC
Contact Type: MANAGING AGENT
Contact Name: CAROLINE PALMIERI
Address1: 23 BARROW ST, SUITE 1D
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10014
Country Code: 001
Phone: (212) 924-5924
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-06-26

Tank Info:

Tank Number: 001
Tank Id: 12631
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

285 MOTT ST (Continued) **U003387817**

	I05 - Overfill - Vent Whistle
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/02/1986
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	06/26/2017
Material Name:	#2 fuel oil (on-site consumption)

AP621 **1-4 MILLIGAN PLACE** **NY LTANKS** **S102673373**
NE **1-4 MILLIGAN PLACE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.209 mi.
1102 ft. **Site 11 of 29 in cluster AP**

Relative: **Lower**

Actual: **40 ft.**

LTANKS:

Facility ID:	9601200
Site ID:	171104
Closed Date:	1996-04-24
Spill Number:	9601200
Spill Date:	1996-04-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1996-04-24
CID:	204
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-24
Spill Record Last Update:	1996-05-06
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	JIM CAREY
Spiller Phone:	(917) 375-5494
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143987
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"SIMPLE TANK OVERFILL"

1-4 MILLIGAN PLACE (Continued) **S102673373**

All Materials:

Site ID:	171104
Operable Unit ID:	1032759
Operable Unit:	01
Material ID:	351017
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

AQ622 **NEW YORK UNIVERSITY - 1-4 WASHINGTON SQUARE VILLAG** **RCRA-SQG** **1011863495**
West **1-4 WASHINGTON SQUARE VILLAGE** **NY MANIFEST** **NYR000160077**
1/8-1/4 **NEW YORK, NY 10013**
0.209 mi.
1103 ft. **Site 2 of 3 in cluster AQ**

Relative:
Lower

Actual:
33 ft.

RCRA-SQG:

Date form received by agency:	07/29/2013
Facility name:	NEW YORK UNIVERSITY - 1-4 WASHINGTON SQUARE VILLAGE
Facility address:	1-4 WASHINGTON SQUARE VILLAGE NEW YORK, NY 10013
EPA ID:	NYR000160077
Mailing address:	ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR NEW YORK, NY 10003
Contact:	STEPHANIE M KUNG
Contact address:	ENVIRONMENTAL HEALTH & SAFETY 10 ASTOR PL - 6TH FLOOR NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-998-1450
Contact email:	STEPHANIE.KUNG@NYU.EDU
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1950
Owner/Op end date:	Not reported

NEW YORK UNIVERSITY - 1-4 WASHINGTON SQUARE VILLAGE (Continued) **1011863495**

Owner/operator name: NEW YORK UNIVERSITY
Owner/operator address: WASHINGTON SQUARE SOUTH
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:
Date form received by agency: 12/01/2009
Site name: NYU - 1-4 WASHINGTON SQUARE VILLAGE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 10/01/2008
Site name: NEW YORK UNIVERSITY
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000160077
Facility Status: Not reported

NEW YORK UNIVERSITY - 1-4 WASHINGTON SQUARE VILLAGE (Continued) **1011863495**

Location Address 1:	1-4 WASHINGTON SQUARE VILLAGE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000160077
Mailing Name:	NEW YORK UNIVERSITY
Mailing Contact:	ZACK KORENSTEIN
Mailing Address 1:	10 ASTOR PLACE 6TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129928276

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	09/24/2014
Trans1 Recv Date:	09/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000160077
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	006917404FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

NEW YORK UNIVERSITY - 1-4 WASHINGTON SQUARE VILLAGE (Continued) **1011863495**

Waste Code:	Not reported
Quantity:	37
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
8 additional NY_MANIFEST: record(s) in the EDR Site Report.

AP623 **286-292 NORTH 8TH STREET** **NY VCP** **S118943626**
NE **286-292 NORTH 8TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.209 mi.
1105 ft. **Site 12 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

VCP NYC:

Project ID:	17CVCP005K
Project Name:	286-292 NORTH 8TH STREET
Project Address:	286-292 NORTH 8TH STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	17CVCP005K
File Name:	2016-06-14.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP005K/2016-06-14.16CVCP005K.report.286-292_N_8th_Street_RIR_Final.EBC.pdf

Project ID:	17CVCP005K
File Name:	2016-07-22.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP005K/2016-07-22.16CVCP005K.report.286-292_N_8th_Street_RAWP_Draft.EBC.pdf

Project ID:	17CVCP005K
File Name:	2016-07-26.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP005K/2016-07-26.17CVCP005K.288-292_N_8th_Street_Factsheet-1.pdf

Project ID:	17CVCP005K
File Name:	2016-07-26.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP005K/2016-07-26.17CVCP005K.288-292_N_8th_Street_Translated_Factsheet-1.pdf

Project ID:	17CVCP005K
File Name:	2016-07-26.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP005K/2016-07-26.17CVCP005K.288-292_N_8th_Street_Community_Protect

286-292 NORTH 8TH STREET (Continued) **S118943626**

ion_Statement.pdf

AL624 **CON EDISON** **NY MANIFEST** **S117538541**
SSE **EAST 1ST ST & 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.209 mi.
1106 ft. **Site 9 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004714853
Facility Status:	Not reported
Location Address 1:	EAST 1ST ST & 2ND AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004714853
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/13/2015
Trans1 Recv Date:	01/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004714853
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	002659406GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON (Continued) **S117538541**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AL625 **CON EDISON - 1ST** **PA MANIFEST** **S118888927**
SSE **E 1ST & 2ND AVE** **N/A**
1/8-1/4 **MANHATTAN, NY 10009**
0.209 mi.
1106 ft. **Site 10 of 24 in cluster AL**

Relative: **Lower**

Actual: **40 ft.**

Manifest Details:

Year:	2015
Manifest Number:	002659406GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYP004714853
Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)

CON EDISON - 1ST (Continued) **S118888927**

Waste Quantity: 1000
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD085690592
Date TSP Sig: Not reported

AL626 **CON EDISON SERVICE BOX 53914** **RCRA NonGen / NLR** **1014926233**
SSE **9 2ND AVE FRONT OF** **NJ MANIFEST** **NYP004239602**
1/8-1/4 **NEW YORK, NY 10003** **NY MANIFEST**
0.210 mi.
1107 ft. **Site 11 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/07/2011
Facility name: CON EDISON SERVICE BOX 53914
Facility address: 9 2ND AVE FRONT OF
NEW YORK, NY 10003
EPA ID: NYP004239602
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: ROBERT BRUNS
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-780-3756
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/08/2011
Site name: CON EDISON SERVICE BOX 53914
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004239602
Mail Address: 4 IRVING PL, RM 828

CON EDISON SERVICE BOX 53914 (Continued) **1014926233**

Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ROBERT BRUNS
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007660431JJK
EPA ID:	NYP004239602
Date Shipped:	8/8/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

CON EDISON SERVICE BOX 53914 (Continued) **1014926233**

Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 2,000.00 Pounds

NY MANIFEST:
Country: USA
EPA ID: NYP004239602
Facility Status: Not reported
Location Address 1: F/O 9 2ND AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MANHATTAN
Location State: NY
Location Zip: 10020
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004239602
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602757

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 08/08/2011
Trans1 Recv Date: 08/08/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/10/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004239602
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007660431JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX 53914 (Continued) **1014926233**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AE627 **CON EDISON** **RCRA NonGen / NLR** **1019902880**
East **208 E 6TH ST & 2ND AVE** **FINDS** **NYP004778890**
1/8-1/4 **NEW YORK, NY 10009** **ECHO**
0.210 mi.
1109 ft. **Site 8 of 11 in cluster AE**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/05/2015
Facility name:	CON EDISON
Facility address:	208 E 6TH ST & 2ND AVE NEW YORK, NY 10009
EPA ID:	NYP004778890
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON (Continued) **1019902880**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:
Date form received by agency: 05/05/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069697732

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019902880
Registry ID: 110069697732
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069697732

AP628 **207 NORTH 8TH STREET** **NY VCP** **S118943402**
NE **207 NORTH 8TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.211 mi.
1113 ft. **Site 13 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

VCP NYC:
Project ID: 15CVCP008K
Project Name: 207 NORTH 8TH STREET
Project Address: 207 NORTH 8TH STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP008K
File Name: 2014-06-13.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/1

207 NORTH 8TH STREET (Continued) **S118943402**

5CVCP008K/2014-06-13.14EHAZ095K.report.RIR_V2.pdf

Project ID: 15CVCP008K
File Name: 2014-07-23.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP008K/2014-12-30.15CVCP008K.report.RAWP_COMBINED_FINAL.pdf

Project ID: 15CVCP008K
File Name: 2014-07-23.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP008K/2014-07-14.15CVCP008K.doc.FactSheet-1.FINAL.pdf

Project ID: 15CVCP008K
File Name: 2014-07-23.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP008K/2014-07-24.15CVCP008K.Factsheet-1_translated.pdf

Project ID: 15CVCP008K
File Name: 2014-07-23.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP008K/2014-07-24.15CVCP008K.translated_CPS.pdf

---

AE629 **CON EDISON MANHOLE** **RCRA NonGen / NLR** **1014397672**
East **E 6 ST & 2ND AVE** **NY MANIFEST** **NYP004200051**
1/8-1/4 **NEW YORK, NY 10003**
0.211 mi.
1114 ft. **Site 9 of 11 in cluster AE**

Relative: **Lower**
Actual: **34 ft.**

RCRA NonGen / NLR:
Date form received by agency: 07/28/2017
Facility name: CON EDISON MANHOLE
Facility address: E 6 ST & 2ND AVE
NEW YORK, NY 10003
EPA ID: NYP004200051
Mailing address: 4 IRVING PL - ROOM 828
NEW YORK, NY 10003
Contact: PAUL WALSH
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 347-203-0646
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

CON EDISON MANHOLE (Continued) **1014397672**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/30/2009
Site name: CON EDISON MANHOLE
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004200051
Facility Status: Not reported
Location Address 1: 107 2nd AVE - MH 53978
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10020
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004200051
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/30/2009
Trans1 Recv Date: 11/30/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/01/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004200051
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON MANHOLE (Continued) **1014397672**

TSDF ID 2:	Not reported
Manifest Tracking Number:	001085577GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AE630 **CON EDISON SERVICE BOX: 1091** **RCRA NonGen / NLR** **1017771667**
East **E 6TH ST & 2ND AVE** **FINDS** **NYP004486080**
1/8-1/4 **NEW YORK, NY 10003**
0.211 mi.
1114 ft. **Site 10 of 11 in cluster AE**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	05/02/2014
Facility name:	CON EDISON SERVICE BOX: 1091
Facility address:	E 6TH ST & 2ND AVE
	NEW YORK, NY 10003
EPA ID:	NYP004486080
Mailing address:	IRVING PL, 15TH FL NE
	NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported
	Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

Actual:
34 ft.

CON EDISON SERVICE BOX: 1091 (Continued) **1017771667**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 04/02/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/02/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063790189

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AE631 **CON EDISON** **NY MANIFEST** **S116550278**
East **E 6TH ST & 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.211 mi.
1114 ft. **Site 11 of 11 in cluster AE**

Relative: NY MANIFEST:
Lower

Country:	USA
EPA ID:	NYP004486080
Facility Status:	Not reported
Location Address 1:	2 AVE & E 6 ST

Actual:
34 ft.

CON EDISON (Continued) **S116550278**

Code: BP
Location Address 2: SB1091
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004486080
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/02/2014
Trans1 Recv Date: 04/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/03/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004486080
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002407203GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S116550278**

Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AG632 **8 ST. MARKS PLACE** **NY AST** **A100292757**
ENE **8 ST. MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.211 mi.
1116 ft. **Site 6 of 7 in cluster AG**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609552
Program Type:	PBS
UTM X:	585332.76841
UTM Y:	4509198.63232
Expiration Date:	05/13/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	55599
Affiliation Type:	Facility Owner
Company Name:	TARGET REALTY LLC
Contact Type:	ASST PROPERTY MGR
Contact Name:	MELISSA ARAGON
Address1:	226 EAST 54 STREET, SUITE 402
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 759-1300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-03-13

Site Id:	55599
Affiliation Type:	Mail Contact
Company Name:	TARGET REALTY LLC % SKY MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	JON SHALOM / JOEL CULOTTA
Address1:	226 EAST 54 STREET

8 ST. MARKS PLACE (Continued) **A100292757**

Address2:	SUITE 402
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 759-1300
EMail:	JOEL@SKYMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-03-13

Site Id:	55599
Affiliation Type:	Facility Operator
Company Name:	8 ST. MARKS PLACE
Contact Type:	Not reported
Contact Name:	ED
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 257-4053
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-03-13

Site Id:	55599
Affiliation Type:	Emergency Contact
Company Name:	TARGET REALTY LLC
Contact Type:	Not reported
Contact Name:	JOEL CULOTTA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 612-2758
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-03-13

Tank Info:

Tank Number:	001
Tank Id:	178778
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None

8 ST. MARKS PLACE (Continued) **A100292757**

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	1
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/16/1971
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AP633 **219-223 NORTH 8TH STREET** **NY VCP** **S118943304**
NE **219-223 NORTH 8TH STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.211 mi.
1116 ft. **Site 14 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

VCP NYC:

Project ID:	14CVCP165K
Project Name:	219-223 NORTH 8TH STREET
Project Address:	219-223 NORTH 8TH STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	14CVCP165K
File Name:	2013-09-13.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-13.14CVCP165K.219-223_North_8th_Street.RIR.pdf

Project ID:	14CVCP165K
File Name:	2013-09-13.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-13.14CVCP165K.219-223_North_8th_Street.RAWP_Draft.pdf

Project ID:	14CVCP165K
File Name:	2013-09-09.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-09.14CVCP165K.219-223_North_8th_Street.FactSheet-1.pdf

Project ID:	14CVCP165K
File Name:	2013-09-09.Translated_FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-09.14CVCP165K.219-223_North_8th_Street.Translated_Fa

219-223 NORTH 8TH STREET (Continued) **S118943304**

ctSheet-1.pdf

Project ID: 14CVCP165K
File Name: 2013-09-09.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-09.14CVCP165K.219-223_North_8th_Street.Translated_Community_Protection_Statement.pdf

Project ID: 14CVCP165K
File Name: 2013-10-16.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-10-16.14CVCP165K.219-223_North_8th_Street.Stipulation_List.pdf

Project ID: 14CVCP165K
File Name: 2013-09-23.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-23.14CVCP165K.219-223_North_8th_Street.FactSheet-2.pdf

Project ID: 14CVCP165K
File Name: 2013-09-29.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2013-09-29.14CVCP165K.219-223_North_8th_Street.Translated_FactSheet-2.pdf

Project ID: 14CVCP165K
File Name: 2014-05-14.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2014-05-14.14CVCP165K.219-223_North_8th_Street.Decision_Document.pdf

Project ID: 14CVCP165K
File Name: 2015-09-11.RAR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2015-09-11.14CVCP165K.219-223_North_8th_Street.RAR.pdf

Project ID: 14CVCP165K
File Name: 2015-09-17.Notice_of_Completion
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2015-09-17.14CVCP165K.219-223_North_8th_Street.NOC.pdf

Project ID: 14CVCP165K
File Name: 2015-09-18.FactSheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2015-09-18.14CVCP165K.219-223_North_8th_Street.FactSheet-3.pdf

Project ID: 14CVCP165K
File Name: 2015-09-17.Translated_FactSheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP165K/2015-09-17.14CVCP165K.219-223_North_8th_Street.Translated_FactSheet-3.pdf

AS634 **FILLMORE EAST APARTMENTS** **NY AST** **U003065831**
East **105 2ND AVENUE (223-237 EAST 6TH STREET)** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1123 ft. **Site 1 of 8 in cluster AS**

Relative:
Lower

Actual:
34 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-209503
Program Type:	PBS
UTM X:	585407.96560
UTM Y:	4509046.00088
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	7534
Affiliation Type:	Facility Owner
Company Name:	FILLMORE EAST VILLAGE ASSOCIATES, LIMITED PARTNERS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	155 THIRD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11231
Country Code:	001
Phone:	(718) 875-8500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7534
Affiliation Type:	Mail Contact
Company Name:	FILLMORE EAST VILLAGE ASSOCIATES, LIMITED PARTNERS
Contact Type:	Not reported
Contact Name:	MR. DAVID KRAMER
Address1:	155 THIRD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11231
Country Code:	001
Phone:	(718) 875-8500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7534
Affiliation Type:	Facility Operator
Company Name:	FILLMORE EAST APARTMENTS
Contact Type:	Not reported
Contact Name:	FILLMORE E. VILLAGE, L.P. ASSC
Address1:	Not reported
Address2:	Not reported
City:	Not reported

FILLMORE EAST APARTMENTS (Continued) **U003065831**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 875-8500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 7534
Affiliation Type: Emergency Contact
Company Name: FILLMORE EAST VILLAGE ASSOCIATES, LIMITED PARTNERS
Contact Type: Not reported
Contact Name: DAVID KRAMER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 875-8500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 18641
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/01/1996
Register: True
Modified By: TRANSLAT
Last Modified: 04/14/2017

FILLMORE EAST APARTMENTS (Continued) **U003065831**

Material Name: #2 fuel oil (on-site consumption)

AL635 **CON ED** **NY MANIFEST** **S118463746**
SSE **20 EAST 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1125 ft. **Site 12 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856454
Facility Status:	Not reported
Location Address 1:	20 EAST 1ST ST
Code:	BP
Location Address 2:	SB 516
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856454
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856454
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085728JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118463746**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AK636 **CON EDISON - MANHOLE M48377** **NY MANIFEST** **S120958662**
NW **100 W 4 ST** **N/A**
1/8-1/4 **MANHATTAN, NY 10012**
0.213 mi.
1125 ft. **Site 2 of 2 in cluster AK**

Relative:
Lower

Actual:
33 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004955090
Facility Status:	Not reported
Location Address 1:	100 W 4 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004955090
Mailing Name:	CON EDISON - MANHOLE M48377
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON - MANHOLE M48377 (Continued) **S120958662**

Mailing Country: USA
Mailing Phone: Not reported

AG637 **10 ST MARKS PL** **NY AST** **U003385797**
ENE **10 ST MARKS PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1126 ft. **Site 7 of 7 in cluster AG**

Relative:
Lower

Actual:
39 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-117447
Program Type: PBS
UTM X: 585348.52632
UTM Y: 4509182.88544
Expiration Date: 06/18/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 4004
Affiliation Type: Mail Contact
Company Name: JEANETTE SPATZ
Contact Type: Not reported
Contact Name: Not reported
Address1: 136 ASBURY AVE
Address2: Not reported
City: CARLE PL
State: NY
Zip Code: 11514
Country Code: 001
Phone: (516) 334-2217
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-28

Site Id: 4004
Affiliation Type: Facility Operator
Company Name: 10 ST MARKS PL
Contact Type: Not reported
Contact Name: EDWARD DROBINSKI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 387-8388
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-28

Site Id: 4004
Affiliation Type: Emergency Contact

10 ST MARKS PL (Continued) **U003385797**

Company Name:	JEANETTE SPATZ
Contact Type:	Not reported
Contact Name:	JEANETTE SPATZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 334-2217
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-28

Site Id:	4004
Affiliation Type:	Facility Owner
Company Name:	JEANETTE SPATZ
Contact Type:	OWNER
Contact Name:	JEANETTE SPATZ
Address1:	136 ASBURY AVE
Address2:	Not reported
City:	CARLE PL
State:	NY
Zip Code:	11514
Country Code:	001
Phone:	(516) 334-2217
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-28

Tank Info:

Tank Number:	001
Tank Id:	8577
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

10 ST MARKS PL (Continued) **U003385797**

Install Date:	06/01/1964
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	08/28/2017
Material Name:	#2 fuel oil (on-site consumption)

AP638 **1 ASTOR PLACE** **NY AST** **A100414547**
NE **1 ASTOR PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1126 ft. **Site 15 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612516
Program Type:	PBS
UTM X:	585092.79993
UTM Y:	4509284.89659
Expiration Date:	10/17/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	520801
Affiliation Type:	Facility Owner
Company Name:	ADMAR COMPANY LLC
Contact Type:	MANAGING MEMBER
Contact Name:	JEFFREY MANOCHERIAN
Address1:	150 EAST 58TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10155
Country Code:	001
Phone:	(212) 355-4900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-01-12

Site Id:	520801
Affiliation Type:	Mail Contact
Company Name:	MANOCHERIAN BROTHERS
Contact Type:	Not reported
Contact Name:	LISA BLUTTAL
Address1:	150 EAST 58TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10155
Country Code:	001
Phone:	(212) 355-4900

1 ASTOR PLACE (Continued) **A100414547**

EMail: LBLUTTAL@MANOCHERIANBROTHERS.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2016-01-12

Site Id: 520801
Affiliation Type: Facility Operator
Company Name: 1 ASTOR PLACE
Contact Type: Not reported
Contact Name: JOE DE BONO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 420-0556
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2016-01-12

Site Id: 520801
Affiliation Type: Emergency Contact
Company Name: ADMAR COMPANY LLC
Contact Type: Not reported
Contact Name: LISA BLUTTAL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 355-4900
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2016-01-12

Tank Info:

Tank Number: 001
Tank Id: 260242

Equipment Records:

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
H05 - Tank Leak Detection - In-Tank System (ATG)
G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None

1 ASTOR PLACE (Continued) **A100414547**

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/17/2011
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AP639 **CON EDISON** **NY MANIFEST** **S117066769**
NE **2-3 GREENWICH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10004**
0.213 mi.
1126 ft. **Site 16 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004594610
Facility Status:	Not reported
Location Address 1:	2-3 GREENWICH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10004
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004594610
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/13/2014
Trans1 Recv Date:	07/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2014

CON EDISON (Continued) **S117066769**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004594610
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002422713GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	9000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AP640 **CON EDISON SERVICE BOX: 30971** **RCRA NonGen / NLR** **1016966713**
NE **COOPER SQ & ST MARK PL** **NY MANIFEST** **NYP004395588**
1/8-1/4 **NEW YORK, NY 10009**
0.213 mi.
1127 ft. **Site 17 of 29 in cluster AP**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date form received by agency: 12/21/2013
40 ft.

Facility name:	CON EDISON SERVICE BOX: 30971
Facility address:	COOPER SQ & ST MARK PL NEW YORK, NY 10009
EPA ID:	NYP004395588
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

CON EDISON SERVICE BOX: 30971 (Continued) **1016966713**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 30971
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395588
Facility Status: Not reported
Location Address 1: S/E COOPER SQ & ST MARKS PL
Code: BP
Location Address 2: SB30971
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395588
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON SERVICE BOX: 30971 (Continued) **1016966713**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/21/2013
Trans1 Recv Date:	11/21/2013
Trans2 Recv Date:	11/25/2013
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395588
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237641GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AP641 **CON EDISON** **NY MANIFEST** **S118256561**
NE **ASTOR PL & 3RD AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 18 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004784393
Facility Status:	Not reported
Location Address 1:	ASTOR PL & 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004784393
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	05/19/2015
Trans1 Recv Date:	05/19/2015
Trans2 Recv Date:	05/20/2015
TSD Site Recv Date:	05/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004784393
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611874GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S118256561**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	7000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AP642 **CON EDISON TRENCH: OPEN~EXCAVATION** **RCRA NonGen / NLR** **1017772507**
NE **3RD AVE & ASTOR PL** **FINDS** **NYP004494662**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 19 of 29 in cluster AP**

Relative: **Lower**

Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/09/2014
Facility name:	CON EDISON TRENCH: OPEN~EXCAVATION
Facility address:	3RD AVE & ASTOR PL NEW YORK, NY 10003
EPA ID:	NYP004494662
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON TRENCH: OPEN~EXCAVATION (Continued) **1017772507**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/09/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/09/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063780859

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AP643 **CON ED** **NY MANIFEST** **S119077335**
NE **3RD AVE & SAINT MARKS PL SE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 20 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004827663
Facility Status: Not reported
Location Address 1: SEC SAINT MARKS AND 3RD AVE
Code: BP
Location Address 2: SB 30971
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004827663

CON ED (Continued) **S119077335**

Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/20/2015
Trans1 Recv Date:	08/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/25/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004827663
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612923GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON ED (Continued) **S119077335**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AP644 **CON EDISON** **NJ MANIFEST** **S120675705**
NE **3RD AVE & SAINT MARKS PL SE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 21 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYP004827663
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612923GBF
EPA ID:	NYP004827663
Date Shipped:	8/20/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120675705**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AP645 **CON EDISON - MANHOLE 30968** **RCRA-LQG** **1019324983**
NE **ASTOR PL & 3RD AVE** **NYP004784393**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 22 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

RCRA-LQG:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON - MANHOLE 30968
Facility address:	ASTOR PL & 3RD AVE NEW YORK, NY 10003
EPA ID:	NYP004784393
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US

CON EDISON - MANHOLE 30968 (Continued) **1019324983**

Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/19/2015
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/19/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 7000

Violation Status: No violations found

AP646 **CON EDISON** **RCRA NonGen / NLR** **1019906889**
NE **3RD AVE & SAINT MARKS PL SE** **NYP004827663**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 23 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:
Date form received by agency: 08/20/2015
Facility name: CON EDISON
Facility address: 3RD AVE & SAINT MARKS PL SE
COR
NEW YORK, NY 10003
EPA ID: NYP004827663
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/20/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

AP647 **CON EDISON SERVICE BOX 40680** **RCRA NonGen / NLR** **1014918978**
NE **ST MARKS PL & COOPER SQ** **NJ MANIFEST** **NYP004225975**
1/8-1/4 **NEW YORK, NY 10003** **NY MANIFEST**
0.213 mi.
1127 ft. **Site 24 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:
Date form received by agency: 02/28/2011
Facility name: CON EDISON SERVICE BOX 40680
Facility address: ST MARKS PL & COOPER SQ
NEW YORK, NY 10003

CON EDISON SERVICE BOX 40680 (Continued) **1014918978**

EPA ID: NYP004225975
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: SEAN FERNANDEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-780-3756
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/29/2011
Site name: CON EDISON SERVICE BOX 40680
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004225975
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: SEAN FERNANDEZ
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655944JJK

CON EDISON SERVICE BOX 40680 (Continued) **1014918978**

EPA ID:	NYP004225975
Date Shipped:	1/29/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004225975
Facility Status:	Not reported
Location Address 1:	F/O 30-32 ST MARKS PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CON EDISON SERVICE BOX 40680 (Continued) **1014918978**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004225975
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7186788126

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2011
Trans1 Recv Date:	01/29/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/01/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004225975
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655944JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0

CON EDISON SERVICE BOX 40680 (Continued) **1014918978**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AP648 **CON EDISON** **NY MANIFEST** **S117737282**
NE **ASTOR PLACE AND 3RD AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 25 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004629523
Facility Status:	Not reported
Location Address 1:	ASTOR PLACE AND 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004629523
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	137 W 74 ST
Mailing Address 2:	SB 13351
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/2014
Trans1 Recv Date:	08/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/26/2014
Part A Recv Date:	Not reported

CON EDISON (Continued) **S117737282**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004629523
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013243692JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	D018
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AP649 **CON EDISON** **RCRA NonGen / NLR** **1019903283**
NE **ASTOR PL & 3RD AVE** **NYP004783643**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 26 of 29 in cluster AP**

Relative: **Lower**
Actual: **40 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/18/2015
Facility name:	CON EDISON
Facility address:	ASTOR PL & 3RD AVE NEW YORK, NY 10003
EPA ID:	NYP004783643
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported

CON EDISON (Continued) **1019903283**

Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/18/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

AP650 **CON EDISON** **NY MANIFEST** **S116551032**
NE **3RD AVE & ASTOR PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.213 mi.
1127 ft. **Site 27 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004494662
Facility Status:	Not reported
Location Address 1:	30 COOPER SQCOOPER SQUARE AND AST
Code:	BP
Location Address 2:	OR PLACE
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004494662
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S116551032**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	PAD146714878
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	09/16/2014
TSD Site Recv Date:	09/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004494662
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD000622464
TSDF ID 2:	Not reported
Manifest Tracking Number:	013255528JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3189
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	D003
Waste Code 1_4:	D018
Waste Code 1_5:	D026
Waste Code 1_6:	B007

Click this hyperlink while viewing on your computer to access
6 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI651 **MOBIL S/S** **NY LTANKS** **S102141711**
SW **137-02 CROSS BAY BLVD** **NY Spills** **N/A**
1/8-1/4 **QUEENS, NY**
0.214 mi.
1128 ft. **Site 17 of 23 in cluster AI**

Relative: **Lower**

Actual: **41 ft.**

LTANKS:

Facility ID:	8706157
Site ID:	298849
Closed Date:	2017-05-12
Spill Number:	8706157
Spill Date:	1987-10-21
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SXAHMED
Referred To:	NEED TO INITIATE REMEDIAL PROCESS
Reported to Dept:	1987-10-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-22
Spill Record Last Update:	2017-05-12
Spiller Name:	MIKE MEOLA
Spiller Company:	EXXONMOBIL CORPORATION
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	241778
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 02/10/2004. Reassigned from O'Dowd to Sigona on 10/25/00. Bureau B, unassigned, due to low priority. Transferred from R-2 on April 27, 2005. Formerly R-2, unassigned. 04/06/2006: Per report dated Dec 20, 1990 by GW Tech. This location is presently inactive. All UST system have been removed in Feb 1990. There were 12 nos 550 gal gasoline and 1 no 550 gal waste oil tank. The closest hydrocarbon storage facility, a Texaco S/S is located 300 ft to the west and independently owned gas S/S, Fighting oil co, is located 350 ft to the south west. There were no public well supply wells within 0.5 miles of the property. 3 MW s have installed during Oct 1990. GW flowing towards south. Depth of GW is 18 fbg, Analytical results for the samples collected on Nov 5, 1990 showed very high level of BTEX and MTBE in all 3 wells. BTEX 17200 to 122700 ppb and MTBE 11000 to 27000 ppb. Per last available data as of 11/28/05, highest BTEX concentration was 9632 ppb and MTBE was 2.8 ppb out of 7 nos. MW s. 4 more MW s installed during April 1991. GSC is currently monitoring and sampling quarterly of these 7 wells. Per PBS record, there were only 2 nos 550 gal and 1 no 4000 gal gasoline UST s were registered.

MOBIL S/S (Continued) **S102141711**

Registration should expire on 10/29/92. Did not find any other PBS record for this particular address during search. Talked to Jennifer Martin of GSC who is the project Hydro geologist for this site, she informed presently there is a running convenient store and no gas S/S. They are monitoring quarterly and last sampled on 02/28/06. Report expecting soon. Also talked to Mr. Rick Kaputo of GSC, he informed they are now preparing remediation working plan (ORC). (Sadique) 04/21/2006: Quarterly monitoring of gw for 7 MW s performed by GSC-Kleinfelder on 02/28/06. Site Status Update Report dated April 14, 2006 showed gradual attenuation but still presence of very high concentration of BTEX near MW-1 (8,670 ug/l). Total BTEX and MTBE concentrations for 7 MW's (MW's-1 through 7)were as follows: BTEX-8670, 5160, 3311, BRL, BRL, 451, 1326 and MTBE- less than 10, less than 5.0, 1.5J, 1.0, less than 5.0, 0.58J, less than 2.0 ug/l respectively. (Sadique) 07/07/2006: SSUR dated June 20, 2006 received on 6/23/06. Seven MW's sampled on 05/04/2006. Concentrations of BTEX and MTBE were found in MW-1 through 7 as 10912, 7058, 2416, BRL, BRL, 1354, 3162 ppb and less than 10, less than 5, less than 2.5, less than 1, less than 1, less than 2.5, less than 5 ppb respectively. (Sadique) 10/13/2006: Electronic copy of SSUR dated Oct 12, 2006 received and reviewed. Seven MW's were sampled on 08/30/2006. BTEX and MTBE concentrations for 7 MWs were 12422, 5022, 1214, BRL, BRL, 2920, 1964 ppb and less than 10, less than 2, less than 1, 0.52j, less than 1, less than 2, less than 1 ppb respectively. Though overall level of concentrations for both BTEX and MTBE decreaesd from last quarter, still present BTEX concentration is a concern. Need to issue letter for taking aggressive measure for remediation. (Sadique) 12/12/2006: Based on the review of latest SSUR, issued a letter requesting to submit RWP by Feb 28, 2007. (Sadique) 01/03/2007: SSUR dated December 29, 2006 received on 01/02/2007. Seven MW's sampled on 11/10/2006. Concentrations of BTEX and MTBE were found in MW-1 through 7 as 8176, 5513, 1347, BRL, BRL, 1223, 1828 ppb and less than 20, less than 10, less than 2, less than 1, less than 1, less than 2, less than 2.5 ppb respectively. Overall BTEX concentrations decreased from previous sampling event due to natural attenuation. (Sadique) 02/26/2007: Soil Vapor Extraction / Air Sparge Feasibility Study Work Plan dated 2/21/2007 received and now under review. (Sadique) 3/14/2007: Reviewed the WP. The SVE/AS feasibility study will be conducted to assess the integrity of the existing infrastructure at the site and to determine the effectiveness of the technology. Based on the review, I find the Work Plan to be acceptable as written. Approval letter issued. (Sadique) 04/05/2007: SSUR dated March 30, 2007 reviewed. Seven MW's sampled on 2/13/2007. BTEX and MTBE concentrations were found in MW-1 through 7 as 7228, 15534, 652, BRL, BRL, 3181, 5490 ppb and less than 5, less than 25, less than 1, 0.40j, less than 1, less than 2, less than 2 ppb respectively. SVE/AS feasibility study to assess the integrity of the existing infrastructure at the site will be conducted very soon. (Sadique) 07/06/2007: SSUR dated June 27, 2007 reviewed. Seven MW's sampled on 5/15/2007. Highest on-site BTEX concentration detected as 3425 ppb (MW-7). MTBE was not detected in any wells. SSUR is acceptable. The commencement of field work for SVE/AS feasibility study to assess the integrity of the existing infrastructure yet not started.(Sadique) 07/16/2007: SSUR June 07 approval email sent out today. Also requested provide update status for the commencement of SVE/AS feasibility study feild work by June 23rd, 2007. (Sadique) 07/17/2007: Per Jennifer's (Kleinfelder)email, field work for

MOBIL S/S (Continued) **S102141711**

feasibility study of SVE/AS will commence from August 06, 2007. (Sadique) 08/17/2007: Per Jennifer's email dated 8/10/07, site activities for feasibility study of SVE/AS have been rescheduled for September 11, 2007. (Sadique) 10/15/2007: Site Status Update Report dated 10/12/2007 is under review. (Sadique) 10/29/2007: Reviewed the October 12, 2007 Site Status Update Report . On August 27, 2007, kleinfelder gauged and sampled seven groundwater monitoring wells. On-site highest BTEX concentration was 10,127 ppb in MW-7. Last quarter, BTEX concentration in the sample from the same well was 3,425 ppb. Concentrations of MTBE were detected at below limits for all wells. As per approved SVE/AS Feasibility Study Work Plan, field activities were completed in early October, 2007 and the report is under preparation. I found the report to be acceptable. Approval email sent today. (Sadique) 01/29/2008: Reviewed the December 28, 2007 Site Status Update Report . On November 16, 2007, kleinfelder gauged and sampled seven groundwater monitoring wells. On-site highest BTEX concentration was 11,729 ppb in MW-7. Concentrations of MTBE were detected at below limits. Dissolved Oxygen content also measured from all samples. There appears to be an increasing level of contamination in MW-7. Please analyze and discuss in the next SSUR. Based on the review, I find the report to be acceptable as written. Also Talked to Jennifer M. Martin from Kleinfelder, she told report of the SVE/AS Feasibility Study is ready to review by Exxon and will be submitted to the Department very soon. I am looking forward to receive the Report. Based on the next SSUR, may ask to submit SSIWP. (Sadique) 02/29/2008: Reviewed the February 12, 2008 SVE/AS Feasibility Study Report for the above referenced site. During October 2007, Kleinfelder conducted a SVE/AS feasibility test using the existing SVE/AS infrastructure at the above site. An SVE pilot test was conducted on extraction wells VP-1 and VP-3. In addition, SVE/AS tests were conducted using extraction well VP-1 and sparge point AS-1. Test results confirm that application of SVE/AS is conducive at the site. The minimal mass recovery observed from the existing SVE wells during the test suggest that either the current SVE/AS wells need to be relocated to remediate residual adsorbed mass, or that there may be insufficient residual hydrocarbon mass remaining in the vadose zone. Investigation activities are proposed to characterize and delineate the horizontal and vertical extent of residual adsorbed phase hydrocarbons in soil beneath the site. Based on the review, I find the SVE/AS Feasibility Study Report to be acceptable as written. I am looking forward to receiving a work plan for horizontal and vertical delineation of residual adsorbed phase hydrocarbons. Approval letter issued today. (Sadique) 05/05/2008: Reviewed the April 23, 2008 Site Status Update Report. On February 29, 2008, kleinfelder gauged and sampled seven groundwater monitoring wells. LPH was not detected in any monitoring wells. Highest BTEX concentration of 7,979 ppb was detected in MW-7. Like the previous quarter, concentrations of MTBE were detected at below limits from all samples. Dissolved Oxygen content was also recorded from all samples. Based on the review, I find the report to be acceptable. Approval email sent today. (Sadique) 05/05/2008: Reviewed the April 28, 2008 Soil Assessment Work Plan (SAWP). The investigation activities are proposed to characterize and delineate the horizontal and vertical extent of residual adsorbed phase hydrocarbons in soils beneath the Site. Results will be used to aid in selecting a remedial strategy that will reduce subsurface hydrocarbon concentrations, volume, and mobility. Kleinfelder proposes a geophysical

MOBIL S/S (Continued) **S102141711**

investigation and advancement of six soil borings on and off-site (on the side walk). The geophysical investigation is proposed in the vicinity of the proposed soil boring locations. Soil borings will be advanced to a minimum of five feet into the saturated zone (approximately 24 fbg). A minimum of one soil sample will be collected from each soil boring for laboratory analysis. Based on the review, I find the Soil Assessment Work Plan to be acceptable contingent upon the inclusion of the following: 1.Per Petroleum Bulk Storage (PBS) report, two 500 gals and one 4000-gal UST s were previously closed. In the Figure 2, please, show their locations, if known. 2.Consider completing the geophysical investigation for the entire site, instead of only at the vicinity of the proposed soil boring locations, to check for any undocumented tanks or piping. 3.The designed depth of MW-4, 5 and 7 were 30 feet, with the screen extended down to the bottom. Consider advancing soil borings down to 30 feet instead of a minimum of five feet into the saturated zone (approximately 24 fbg). Approval letter issued today. (Sadique) 06/10/2008: Per email dated 6/9/08 from Kleinfelder, a letter is issued to obtain NYCDOT road opening permit for upcoming off-site investigation work. (Sadique) 07/16/2008: Reviewed the June 27, 2008 Site Status Update Report. On May 16, 2008, kleinfelder gauged and sampled seven groundwater monitoring wells. LPH was not detected in any monitoring wells. Highest BTEX concentration of 6,543 ppb was detected in MW-1. Concentrations of MTBE were below detection limits for all samples. Dissolved Oxygen content ranged from 0.57 to 1.75 g/L within the on-site wells. Kleinfelder will be conducting additional on-site delineation activities during the second quarter of 2008. Findings of the investigation will be included in a Subsurface Investigation Report and submitted to the Department. Based on the review, I find the report to be acceptable as written. Approval email sent on 7/16/2008. (Sadique) 11/17/2008: Cotacted Mr. Richard Caputo of Klienfelder today. Per his email (Dated 11/17/08), the Site Status Update Report dated June 27, 2008 is the most recent report. Consultant completed the additional assessment and repeated the feasibility testing at the site along with the groundwater sampling in August and the draft report is seding to the client tomorrow. Final copy of the next report will be submitted to the Department within about 2 weeks time. (Sadique) 12/29/2008: Reviewed the November 25, 2008 SIR/SSUR. The SI activities were initiated on June 16, 2008. The investigation included a geophysical survey throughout the entire site and advancement of seven soil borings to characterize and delineate the horizontal and vertical extent of residual adsorbed phase hydrocarbons in the soils beneath the Site. Soil boring depths ranged from 30 to 35 fbg. Three soil borings (SB-2, SB-4, and SB-7) were completed as air sparge wells (AS-7, AS-5, and AS-6). 18 soil samples were collected and analyzed for VOC s. 3 samples exhibited VOC concentrations above NYSDEC RSCOs for nine VOCs. These samples were collected from 20-25 fbg. GW samples were collected from all network monitoring wells, except MW-3 (inaccessible), on August 15, 2008. LPH was not detected in any wells. Highest BTEX concentration was detected as 1,564 ppb in MW-1 and MTBE concentrations were detected below NYSDEC guidance values from all samples. Additionally, during July 29 through 31, 2008, a SVE/AS feasibility test was conducted utilizing the recently installed air sparge wells to assess the feasibility of SVE/AS technology as a means to remediate the remaining residual hydrocarbons. The test indicated favorable VOC recovery in the vapor

MOBIL S/S (Continued) **S102141711**

samples collected and a marked decrease in dissolved hydrocarbons in groundwater, except in one well (MW-6). Due to the relatively low levels of dissolved concentrations of hydrocarbons observed in groundwater, instead of installation of permanent SVE/AS system, Kleinfelder proposes to manifold air sparge wells (AS-7, AS-5, and AS-6) to the existing subsurface system piping. Following connection of three new air sparge points, one SVE/AS event will be conducted per month for three consecutive months, in order to remediate adsorbed and dissolved phase impacts. Quarterly groundwater monitoring and sampling will continue for two additional quarters in order to monitor for rebound prior to requesting closure of this spill. Based on my review, I find the Subsurface Investigation Report / Site Status Update Report to be acceptable contingent upon the inclusion of the following: 1.During monthly SVE/AS events (less than 8.00 hrs), air sampling needs to be done at the extraction wells to demonstrate that the system is actually removing contamination. PID readings should be acceptable for the first run. 2.Monitoring of DO in groundwater both before and after the events, to demonstrate that the system is having an effect. 3.After completion of all three SVE/AS events, quarterly groundwater monitoring and sampling should continue for four additional quarters due to the impacts of seasonal variation of groundwater depths. Approval letter issued today. (Sadique) 02/02/2009: Reviewed the January 09, 2009 Quarterly sampling and report reduction request. Kleinfelder requested a reduction in the groundwater monitoring and sampling network and reporting frequency for the above spill site. They proposed to reduce the current quarterly monitoring and sampling program by eliminating up gradient monitoring well MW-4 and side gradient monitoring well MW-5. These two wells historically exhibited concentrations below NYSDEC water quality standards. Quarterly groundwater sampling will continue. However, a reporting frequency change to biannual was requested. Based on the review, MW-4 and MW-5 can be eliminated from the sampling program. However, quarterly reporting should continue, so I can assess the affect of the upcoming monthly SVE/AS events. Comments letter issued today. (Sadique) 02/10/2009: Reviewed the Site Status Update Report dated January 09, 2009 for the period of September through November 2008. On November 25, 2008, kleinfelder gauged and sampled six groundwater monitoring wells. LPH was not detected in any monitoring wells. Highest BTEX concentration of 3,255 ppb was detected in MW-2. Concentrations of MTBE were below detection limits for all samples. Dissolved Oxygen content ranged from 0.50 to 1.68 mg/L within the on-site wells. MW-3 was inaccessible and was not sampled. Based on my review, I find the report to be acceptable contingent up on the following: 1. Monitoring and reporting of network monitoring wells except MW-4 and 5 should continue on a quarterly basis. 2. MW-4 and 5 will not be abandoned now. 3. In the future reports, please, provide clarification and/or reasons if any well(s) is found inaccessible during groundwater sampling events Email issued today. (Sadique) 06/25/2009: Reviewed the SSUR dated April 13, 2009. On February 27, 2009, Kleinfelder gauged and sampled five groundwater monitoring wells. LPH was not detected in any monitoring wells. Highest BTEX concentration of 10,024 ppb was detected in MW-1. Concentrations of MTBE were below detection limits for all samples. Dissolved Oxygen content ranged from 0.64 to 0.96 mg/L within the on-site wells. The process has been initiated to conduct a series of mobile AS/SVE events as a remedial alternative at the site. I find the report to be acceptable as written. Email sent

MOBIL S/S (Continued) **S102141711**

out today. (Sadique) 07/23/2009: Reviewed the SSUR dated June 29, 2009. On May 22, 2009, Kleinfelder gauged 7 and sampled 5groundwater monitoring wells. LPH was not detected in any monitoring wells. Highest BTEX concentration of 6,038 ppb was detected in MW-7. Concentrations of MTBE were below detection limits for all samples. Dissolved Oxygen content ranged from 0.47 to 0.63 mg/L within the on-site wells. Decreasing BTEX and DO concentrations are noticed in all groundwater samples. Mobile air sparge and soil venting remedial events are scheduled for three consecutive months beginning in June 2009 to remediate adsorbed and dissolved phase impacts. As of today, June and July 2009 events, each lasting three days, were completed. Based on my review, I find the report to be acceptable as written. Approval email sent out today. (Sadique) 12/23/2009: Reviewed the SSSUR dated 10/30/09.Three separate SVE/AS mobile remediation events (MRE) conducted during June, July and August, 2009. GW analytical results showed BTEX concentration decreased in all samples except from MW-2. Decrease in DO concentrations are also noticed in all groundwater samples. Kleinfelder proposed to continue to monitor to determine if additional MREs should be proposed. I find the report to be acceptable as written. Approval email sent out today. (Sadique) 4/26/2010: Current status: Reviewed the report dated 1/25/10. LPH was not detected in any wells. 3 separate SVE/AS mobile remediation monthly events (MRE) conducted during June, July and August 09. Consultant will continue monitoring to determine if additional MRE events should be proposed. S.Ahmed 6/28/2010: Current status: Reviewed the report dated 4/30/10. LPH was not detected in any wells. 3 separate SVE/AS mobile remediation monthly events (MRE) conducted during June, July and August 09. Consultant proposed to schedule 3 more MRE s for the fourth quarter of 2010. S.Ahmed 7/28/2010: Current status: Reviewed the report dated 4/30/10. LPH was not detected in any wells. 3 separate SVE/AS mobile remediation monthly events (MRE) conducted during June, July and August 09. Based May 2010 gw data, consultant proposed to halt additional MRE s. S.Ahmed 8/26/2010: Current status: Reviewed the report dated 7/29/10. LPH was not detected in any wells. 3 separate SVE/AS mobile remediation monthly events (MRE) conducted during June, July and August 09. Based May 2010 gw data, consultant proposed to halt additional MRE s. S.Ahmed 11/23/2010: Current status: Reviewed the report dated 10/22/10. LPH was not detected in any wells. 3 separate SVE/AS mobile remediation monthly events (MRE) conducted during June, July and August 09. Need for additinal MRE will be determined after evaluation of Aug and Nov'10 results. S.Ahmed 01/19/2011: Current status: Reviewed the SSUR dated 1/3/11. LPH was not detected in any wells. Requested to analyze for DO and also consider other remedial options if during next gw monitoring (Feb 2011) the concentration remains at ppm level in any well sample. S.Ahmed 03/28/2011: Current status: Reviewed the 3/22/11 SSUR. LPH was not detected in any wells. Highest BTEX concentration detected as 1077 ppb. Overall concentration of dissolved phase hydrocarbon decreased. MTBE is BDL for all wells. DO ranged from 1.15 to 4.67 mg/L. S.Ahmed 06/23/2011: Current status: Reviewed the 6/17/11 SSUR. LPH was not detected in any wells. Highest BTEX concentration detected as 4,567 ppb. Overall concentration of BTEX decreased. Requested to evaluate the implementation of an appropriate remedial technology to expedite remediation. S.Ahmed 08/03/2011: Current status: Reviewed the 7/29/11 ORC socks pilot test WP. Proposed for installation of five nos 4 dia and one foot long ORC socks in three on-site well. The WP is approved contingent upon.

MOBIL S/S (Continued) **S102141711**

Based on the earlier SIR, requested ORC socks installation in MW-2 & 7. S.Ahmed 10/04/2011: Current status: Reviewed the SSUR dated 10/3/11. Per approved pilot test work plan, during September of 2011, ORC socks were installed in seven monitoring wells. Quarterly monitoring will continue. S.Ahmed 12/27/2011: Current status: Reviewed the SSUR dated 12/9/11. During September 2011 ORC socks were installed in 5 on-site monitoring wells. Remarkably increased concentrations of dissolved Oxygen contents in all monitored wells were evident. Quarterly monitoring will continue. S.Ahmed 03/20/2012: Current status: Reviewed the SSUR and Regenox injection WP dated 3/16/2012. To remediate the dissolved phase hydrocarbon consulatnt proposed to inject Regenox in the subsurface through six injection points. UIC notification required. Approval letter sent out. S.Ahmed 06/17/2012: Current status: Reviewed the SSUR dated 5/25/2012. Dissolved phase hydrocarbon concentration increased in one MW. RegenOx injection point installation expected to begin this month. UIC notification to EPA has been performed by the consultanrt. S.Ahmed 09/17/2012: Current status: Reviewed the SSUR dated 8/27/2012. Regenox was injected through 4 IP's during July 2012. LPH was not detected in MW's. The need for additional chemical injection events will be evaluated based on the quarterly monitoring results. S.Ahmed 11/16/2012: Current status: Reviewed the SSUR dated 11/13/2012. Regenox was injected through 4 IP's during July 2012. LPH was not detected in MW's. Overall BTEX concentrations are appeared to be declining. Quarterly gauging of 7 MW's and sampling of 4 MW's will continue. S. Ahmed. 03/18/2013: Current status: Reviewed the SSUR dated 3/7/13. LPH was not detected in MW's. Dissolved oxigen content have increased remarkably in all MW's after chemical oxidation injection event was completed in July 2012. S. Ahmed. 06/14/2013: Current status: Reviewed the SSUR dated 6/14/13. LPH was not detected in any MW's. A Regenox injection event was completed between April 30 and May 1, 2013. Dissolved oxigen content have increased remarkably in most MW's. BTEX concentration shows a decreasing trend. S. Ahmed. 09/13/2013: Current status: SSUR dated 9/14/13 reviewed. LPH was not detected in any MW's. Regenox injection conducted on April 30 and May 1, 2013. Per Jul25 2013 monitoring data the BTEX concentrations increased in most wells since last quarter. Quarterly monitoring will continue. S. Ahmed. 11/08/2013: SSUR dated 11/7/13 reviewed. LPH was not detected in any MW's. Regenox injection conducted on April 30 and May 1, 2013. Per Oct2, 2013 monitoring data the BTEX concentrations ranged from 1.94 to 2378 ppb. Elevated concentrations of DO on-site. Monitoring will continue. S. Ahmed. 03/12/2014: SSUR dated 3/5/14 reviewed. After Regenox injection in 2013 the dissolved oxygen (DO) content in all wells increased significantly and natural attenuation process has enhanced. Now the DO levels went down. Requested to installed ORC socks in MW-2. S. Ahmed. 06/19/2014: SSUR dated 6/4/14 reviewed. Groundwater samples from most sitewide monitoring wells detected very low concentrations of BTEX. Only MW-2 still have over 2 ppm of BTEX. Dissolv oxygen is only 0.52 mg/L at MW-2. Consultant will submit a work plan proposing injection to enhance DO concentrations. S. Ahmed. 12/18/2014: SSUR dated 12/18/14 reviewed. MW-2 still detected high BTEX concentrations (4,775) ppb. Dissolved oxygen concentration is very low in all MW's (less than 0.5 mg/L) lacking aerobic nutural attenuation. Requested to install ORC socks in 2 on-site MW's S. Ahmed. 02/04/2015: SSUR dated 2/4/15 reviewed. BTEX concentrations increased in MW-2 during last quarter (6,151 ppb). Moderate increase of dissolved oxygen observed in most wells.

MOBIL S/S (Continued) **S102141711**

Application of oxygen releasing compound (ORC) this quarter. Quarterly monitoring will continue. S. Ahmed. 06/08/2015: SSUR dated 5/12/15 reviewed. BTEX concentrations are below 1 ppm in all on-site monitoring wells. LPH was not detected in any wells. Quarterly monitoring will continue atleast for 3 consecutive quarters to observe the BTEX concentrations trend. S. Ahmed. 08/12/2015: SSUR dated 7/30/15 reviewed. BTEX concentrations are below 1 ppm in all on-site monitoring wells (highest 300 ppb). LPH was not detected in any wells. Quarterly monitoring will continue at least for 3 consecutive quarters to observe the BTEX concentrations trend. S. Ahmed. 02/08/2016: SSUR dated 10/27/15 reviewed. BTEX concentrations increases in MW-2 (2,946 ppb). LPH was not detected in any wells. Quarterly monitoring will continue at least for 2 consecutive quarters to observe the BTEX concentrations trend. S. Ahmed. 03/02/2016: SSUR and No Further Action Request dated 2/17/16 reviewed. BTEX concentrations increased in MW-2 (3,791 ppb). No LPH in any wells. Rebound of BTEX in MW-2 is evident. NFA request is not acceptable. Requested to conduct an additional RegenOx inject event and semiannual monitoring. S. Ahmed. 06/23/2016: Regenox Part A/B injection around the MW-2 will be conducted in July 2016 following submittal of the EPA UIC letter and obtaining the FDNY permit. Next semi annual groundwater monitoring would be conducted during September 2016. S. Ahmed. 09/21/2016: Regenox Part A/B injection around the MW-2 completed during July 2016. Details of the injection activities will be summarized in the next site status report which is due in September 2016. S. Ahmed. 10/26/2016: SSUR dated 10/19/16 reviewed. BTEX concentrations in MW-2 decreased from 3,791 to 656 ppb after RegenOx application. Dissolve oxygen concentrations also increased in all monitored wells. A year of rebound effect monitoring warrants. Email sent to consultant. S. Ahmed. 05/12/2017: The Department has reviewed the April 12, 2017 Site Status Update Report (SSUR) as well as request for No Further Action (NFA) submitted by Groundwater & Environmental Services, Inc. (GES) of New York, Inc. on behalf of the ExxonMobil Environmental Services Company (EMESC) regarding the above referenced spill site. Based on the documentation provided to date, no further investigation or response will be required concerning this site. Decision made based on followings: " Twelve 550-gallon gasoline USTs, and one 550-gallon used oil UST were removed in February and one 550-gallon fuel oil UST was removed in December of 1990. " Conducted three separate SVE/AS mobile remediation events in June, July, and August of 2009. " Chemical oxidation injection events utilizing RegenOx conducted three times during 2012, 2013 and 2016. " Overall, concentrations of BTEX and MTBE continue to decline and/or remain stable with exception of only MW-2. " Benzene and MTBE concentrations in MW-2 have remained below the laboratory reporting limits for four consecutive quarters. " The remaining residual impacts are localized to the central portion of the site (MW-2) with historical sampling of down-gradient monitoring wells (MW-3, MW-6, and MW-7) indicating decreasing and/or stable concentrations of VOCs. " Human exposure to remaining impacts is not likely or possible as a result of the presence of concrete/asphalt at grade which precludes the ability for direct contact; and the overall depth at which remaining impacts remain (greater than 18 feet below grade). Spill inactivation letter mailed on May 12, 2017. S. Ahmed "

Remarks: "(4) 550 GAL. TANKS, NO LEAK RATE AVAILABLE, WILL INVESTIGATE, EXCAVATE, AND RETEST. CONTACT: STEVE TRIFILITTI (516) 371-0739."

MOBIL S/S (Continued) **S102141711**

All TTF:

Facility ID:	8706157
Spill Number:	8706157
Spill Tank Test:	1531984
Site ID:	298849
Tank Number:	Not reported
Tank Size:	0
Material:	1213A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	298849
Operable Unit ID:	912194
Operable Unit:	01
Material ID:	465181
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	298849
Operable Unit ID:	912194
Operable Unit:	01
Material ID:	2096466
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	9007642
Facility Type:	ER
Spill Number:	9007642
DER Facility ID:	228030
Site ID:	280810
DEC Region:	2
Closed Date:	1995-02-28
Spill Cause:	Unknown

MOBIL S/S (Continued) **S102141711**

Spill Class:	A4
SWIS:	4101
Spill Date:	1990-10-12
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1990-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-02-28
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-31
Spill Record Last Update:	2003-05-27
Spiller Name:	MIKE MEOLA
Spiller Company:	EXXONMOBIL CORPORATION
Spiller Address:	464 DOUGHTY BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TANK REMOVED 3/90, ENCASED IN CONCRETE."

All Materials:

Site ID:	280810
Operable Unit ID:	944980
Operable Unit:	01
Material ID:	431488
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP652 **CON EDISION - V9216** **RCRA NonGen / NLR** **1007208300**
NE **ST.MARKS PL. AND 3RD AVE. ST.M** **NY MANIFEST** **NYP004086062**
1/8-1/4 **NEW YORK, NY 10003**
0.214 mi.
1131 ft. **Site 28 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/02/2002
Facility name:	CON EDISION - V9216
Facility address:	ST.MARKS PL. AND 3RD AVE. ST.M NEW YORK, NY 10003
EPA ID:	NYP004086062
Mailing address:	IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	IRVING PLACE NEW YORK, NY 10003

CON EDISION - V9216 (Continued) **1007208300**

Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/01/2002
Site name: CON EDISION - V9216
Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - V9216
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004086062
Facility Status: Not reported
Location Address 1: V9216-ST MARKS PL 341'E/O 3 AV
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004086062
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISION - V9216 (Continued) **1007208300**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0500265
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	31877AJ
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2001
Trans1 Recv Date:	07/10/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/10/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004086062
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01340
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AR653 **CON EDISON SERVICE BOX: 49502** **RCRA NonGen / NLR** **1017771535**
NNW **18 WAVERLY PL & GREENE ST E OF** **FINDS** **NYP004484754**
1/8-1/4 **NEW YORK, NY 10003**
0.214 mi.
1131 ft. **Site 2 of 8 in cluster AR**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/30/2014
Facility name:	CON EDISON SERVICE BOX: 49502
Facility address:	18 WAVERLY PL & GREENE ST E OF NEW YORK, NY 10003
EPA ID:	NYP004484754
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/31/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	03/31/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063783115

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON SERVICE BOX: 49502 (Continued) **1017771535**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AR654 **CON EDISON SERVICE BOX: 36001** **RCRA NonGen / NLR** **1017771542**
NNW **261-63 GREENE ST & WAVERLY PL N OF** **FINDS** **NYP004484820**
1/8-1/4 **NEW YORK, NY 10003**
0.214 mi.
1131 ft. **Site 3 of 8 in cluster AR**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/01/2014
Facility name:	CON EDISON SERVICE BOX: 36001
Facility address:	261-63 GREENE ST & WAVERLY PL N OF NEW YORK, NY 10003
EPA ID:	NYP004484820
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/01/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/01/2014
Site name:	CON EDISON

CON EDISON SERVICE BOX: 36001 (Continued) **1017771542**

Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063783188

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AL655 **24 SECOND AVENUE OWNER LLC** **RCRA NonGen / NLR** **1018281155**
SE **24 2ND AVE** **FINDS** **NYR000225318**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.214 mi.
1132 ft. **Site 13 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/18/2017
Facility name:	24 SECOND AVENUE OWNER LLC
Facility address:	24 2ND AVE NEW YORK, NY 10003
EPA ID:	NYR000225318
Mailing address:	BLEECKER ST NEW YORK, NY 10012
Contact:	THOMAS N CIANCARELLI
Contact address:	BLEECKER ST NEW YORK, NY 10012
Contact country:	US
Contact telephone:	212-501-0050
Contact email:	TOM@AOREH.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	24 SECOND AVENUE OWNER LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/07/2014
Owner/Op end date:	Not reported

24 SECOND AVENUE OWNER LLC (Continued) **1018281155**

Owner/operator name: 24 SECOND AVENUE OWNER LLC
Owner/operator address: BLEECKER ST
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-501-0050
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/07/2014
Owner/Op end date: Not reported

Owner/operator name: 24 SECOND AVENUE OWNER LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/07/2014
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:
Date form received by agency: 12/23/2015
Site name: 24 SECOND AVENUE OWNER LLC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

24 SECOND AVENUE OWNER LLC (Continued) **1018281155**

FINDS:

Registry ID: 110067204395

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281155
Registry ID:	110067204395
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067204395

AL656 **24 SECOND AVENUE OWNER LLC** **NY Spills** **S117394134**
SE **24 2ND AVE** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.214 mi.
1132 ft. **Site 14 of 24 in cluster AL**

Relative: **Lower**
Actual: **40 ft.**

SPILLS:

Facility ID:	1409689
Facility Type:	ER
Spill Number:	1409689
DER Facility ID:	458258
Site ID:	503330
DEC Region:	2
Closed Date:	2017-05-01
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2014-12-29
Investigator:	RVKETANI
Referred To:	050117 RVWD CLSR RPT AND CLOSED CASE
Reported to Dept:	2014-12-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-12-29
Spill Record Last Update:	2017-05-01
Spiller Name:	Not reported
Spiller Company:	AORE HOLDINGS, LLC
Spiller Address:	49 BLEEKER STREET, SUITE 301

24 SECOND AVENUE OWNER LLC (Continued) **S117394134**

Spiller Company: 999
Contact Name: BRIAN FENLEY
DEC Memo: "12/29/14-Zhune spoke to Brian Fenley from Island Pump Tank. They are working on a tank removal project. They are in the process to remove four tanks two (4000) gallons, one (3000) gallons and one (275) gallon. They removed one of the two (4000) gallons and encountered soil contaminated underneath the bottom of the tank. They will continue removing the other three tanks. Brian Fenley Business Development Island Pump & Tank Corp. 40 Doyle Court East Northport, NY 11731 O 631.462.2226 X12 F 631.462.1301 C 516.446.2816 www.islandpumpandtank.com 12/31/14-Brian sent the following email. Hope you are well -- We are currently excavating the tanks and stockpiling any contaminated soil. If possible please have the case manager call me so we can determine what he wants. Most likely we will over excavate the soil 12/31/14: Mahat t/c: DEC Mahat contacted Mr. Fenly inquiring about the progress on the spill case. All the tank from the site has been removed and end point samples has been taken from the site. Further excavation will be performed on the site in order to achive clean end point. A clean sample collection is schedule on 1/5/15. A site visit will be organized depending on the time of the day. 1/5/15 : Mahat e/c: DEC Mahat received an email from Mr. Fenly mentioning that bottom slab is taking off today and sample for classification of the waste for proper disposal. Santosh, I will keep you updated. Today they are working on the bottom slabs and grabbing a waste classification for disposal. 02/11/15-Hiralkumar Patel. 11:53 AM:- received call from Paul from Island Pump and Tank. they excavated contaminated soil to 14 ft bg and collected endpoint sample prior to backfilling the hole as further excavation is not possible without shoring. Paul mentioned that there is more contamination beneath 14 ft depth, which will be removed during site development as developer is planning to excavate the entire site to 17 ft bg for new foundation. asked Paul to submit endpoint sample results for review. 5/28/15: Mahat T/c: Brian mentionded that the building is waiting on demolistion permits. Tanks are removed from the site. Samples and site map is due. Brian will provide upto date reprot as sson as he can. DEC is waiting for a report. 8/24/15: Mahat DEC Mahat sent an email inquiring about the progress on the spill case. 4/6/16: Mahat DEC Mahat received an email update on the spill case. Eamil: Good Morning Santosh, It was nice speaking to you this morning. As discussed, Impact Environmental has been contracted by the owner of 24 Second Avenue, Manhattan (Spill 14-09689) to remediate and attempt closure of the open spill case during site redevelopment activities. Currently, all existing buildings have been demolished and SOE/underpinning is underway. Redevelopment proposes the entire site to be excavated to approximately 18 -20 below grade for the construction of a residential building. We will prepare and submit a Spill Remedial Action Work Plan for this site within the next two weeks. In the meantime please contact me with any questions. Below please find my contact information. Thank You, Ben Hernandez Salazar Project Manager O: 631-269-8800 Ext. 142 C: 631-334-2354 IMPACT ENVIRONMENTAL A WRAP will submitted to the Department for a review. 7/27/16: Mahat A RAP on the spill case has been submitted to the Department. It has been uploaded on D2 for reference. The RAP is under review. 9/12/2016 - V. Brevdo Spill Case is transferred from Spill Prevention and Response to Remediation Section B due to project manager Santosh Mahat departure to the other DEC Program, as per 9/9/16 discussion between Randall Austin and Vadim Brevdo. VB 9/12/16

24 SECOND AVENUE OWNER LLC (Continued) **S117394134**

- Raphael Ketani. The spill case was transferred to me during a caseload realignment. 9/23/16 - Raphael Ketani. Alternative property location addresses are 20 to 24 2nd Avenue and 30 to 32 East 1st Street. According to ACRIS, the block and lot are 443 and 1. There is a deed dated 7/7/14. The address of the buyer is listed as 24 Second Avenue Owner, LLC, c/o Arthure J. Israel, Esq. A later owner address is AORE Second Avenue Partners, LLC, 53 Greene Street, 3rd Floor, NY, 10013. There is an additional Party 1 consisting of Porytko Porperties, LLC, 337 East 5th Street, NY, 10003. The latest address for the owner is 24 Second Avenue Owner, LLC, c/o AORE Holdings, LLC, 49 Bleeker Street, Ste. 301, NY, 10012. The earlier PBS registration is #2-032158. Three USTs were listed. These were two 4000 gal. tanks which were installed on 12/1/85 and one 3000 gal. tank which was installed on 12/1/81. All had gasoline. All 3 were closed on 1/1/98. A later PBS registration number #2-603153 was found. It listed the same three large gasoline USTs and a 240 gallon waste oil UST. The owner is the same, Westfield Second Associates. The RAP could not be found. Therefore, I sent Ben Hernandez Salazar (631-269-8800 Ext. 142/cell 631-334-2354/bhernandez@impactenvironmental.com) an email requesting the document. Mr. Hernandez-Salazar sent me a response email. He stated that the SOE and underpinning operations have been completed and deep excavation is under way. Excavation has not yet reached the spill area depth of 13 feet below grade but we anticipate this depth to be reached within the next week or two. He included a link to the 6/20/16 Impact Environmental Spill Remedial Action Plan. On the title page of the RAP, the Impact Environmental client is listed as AORE Holdings, LLC at the 49 Bleeker Street address. I reviewed the RAP. The first part of the document was the RAP itself. It included the Island Pump and Tank 6/25/14 Subsurface Investigation Report and the Island Pump and Tank March 2015 Tank Excavation Assessment Report. I reviewed all 3 documents. It was stated in the RAP that excavation will take place site wide down to 20 feet. After this, endpoint soil samples will be taken. A 20 MIL vapor barrier will be installed beneath all foundation slabs and behind all subgrade foundation walls. An engineered composite cover will be installed over the entire site and will consist of a 5 inch thick reinforced concrete foundation slab and 12 inch thick reinforced foundation walls. The site was a gas station and a car repair shop from the 1960s to 2014. It became a BP station sometime during this period. There were 4 pumps, 3 large gasoline USTs and 1 small waste oil UST. Gasoline impacted soil was discovered on 12/29/14 during the removal of a UST. The 4 USTs and the pumps were removed by Island Pump and Tank. Impacted soil was found at 13 feet below grade as a result of a series of exploratory borings. The soil was excavated down to 13 feet, but the pit was later backfilled with clean soil. Groundwater was found at 35 to 40 feet below grade. Impact Environmental does not expect it to be affected by the spill. The proposed site development will be mixed use with a commercial facility on the first floor and 9 residential levels above. A basement is included as part of the development. The Subsurface Investigation Report demonstrated that very elevated soil contamination was found at an outside drain. However, boring samples from 25 feet or below showed little or no VOC contamination. Also, groundwater impacts were very low. A review of the Tank Excavation Assessment Report showed that very high (N1, BE1, BE2, BW2) to extremely high (E1) total VOC contamination was present at a number of locations. The contamination was found in soil samples that were

24 SECOND AVENUE OWNER LLC (Continued) **S117394134**

taken from 8 to 12 feet below grade. All of these locations were situated within the footprint of excavation area #1. I found the documents to be acceptable and sent an approval email to Mr. Hernandez-Salazar. 2/21/17 - Raphael Ketani. As no information has been forthcoming in many months regarding progress at the site, I sent Mr. Hernandez-Salazar (bhernandez@impactenvironmental.com) an email requesting an update and the closer report. 4/14/17 - Raphael Ketani. As no information has been forthcoming in many months regarding progress at the site, I sent Mr. Hernandez-Salazar (bhernandez@impactenvironmental.com) an email requesting an update and the closer report by 4/28/17. I added that since we have no documentation that the spill had been remediated, the site is still in violation of the Department's environmental laws and can and may be subject to legal action and fines. 4/28/17 - Raphael Ketani. Today I received the Impact Environment Spill Closure Report dated 4/28/17. The report was prepared for AORE Holdings, LLC, 49 Bleecker Street, Ste 301, NY, NY, 10012. The areal extent of the site is about 7,715 square feet. Site elevation is 40 feet above mean sea level. Boring took place down to 35 feet bgs. Bedrock was not encountered during the investigation or the development of the site. Previous investigations found the soil to consist of historical fill (from 5 to 19 feet thick according to the boring logs) over, in general, light to dark brown fine to medium grained sand with gravel. The previous investigations also encountered groundwater at 35 to 40 feet bgs. Groundwater flow is from west to east to the East River. The site operated as a filling station and auto repair shop from the 1960s to 2014. The NYS DEC PBS database indicates that three 4000 gallon gasoline USTs and one 240 gallon waste oil UST were below the site. The current spill case was opened when grossly contaminated soil was discovered below the site. The proposed use is mixed residential/retail commercial. A ten story building with a footprint that occupies the entire property is presently being constructed. The building will have a subgrade cellar with 2483 square feet of commercial space, tenant recreational space, tenant storage facilities and building utility rooms. The cellar foundation extends down to 18.5 feet bgs throughout the site. The excavation generated 9246.72 tons of soil and fill. The grossly contaminated soil was excavated to 13 feet bgs within the area of the former pump island. The total amount consisted was 36.78 tons. Some of the material was shipped to Bayshore Recycling Corp. in Keasbey, NJ. A total of 1346.58 tons of soil and fill was shipped as non-hazardous material to Impact Recovery & Reuse Center in Lyndhurst, NJ. Another 7863.36 tons of non-hazardous soil and fill was removed to the Former NJ Zinc site in Palmerton, PA. The Palmerton facility also received much of the soil from the spill area. All of the facilities were licensed and/or regulated to receive the material. A Stego Wrap brand 20mm thick vapor barrier system was installed below the entire foundation slab and behind sub-grade foundation walls. A composite cover system consisting of a 5 inch thick concrete foundation slab underlain by 12 inch to 55 inch thick concrete mat slabs and a 6 inch thick layer of clean 3/4 inch gravel and 12 inch thick concrete foundation walls were installed throughout the building footprint. Six post excavation bottom endpoint samples (EP-1 to EP-6) and seven sidewall samples (SW-1 to SW-7) were collected from the soil within the spill area excavation on 9/30/16 and on 10/5/16. One bottom endpoint sample was collected for every 900 square feet of area at a depth of 19 to 19.5 feet bgs (from 6 to 12 inches below the excavation floor). One

24 SECOND AVENUE OWNER LLC (Continued) **S117394134**

sidewall sample was collected for every 30 linear feet of sidewall at a depth of 13 to 15 feet bgs. The results for all of the bottom and sidewall samples were almost entirely non-detect for VOCs, with the exception of some very low naphthalene hits. Soil sampling results were included for total metals and TCLP lead. However, both sets of data were low in concentration. Sampling results were also included for the drains from the former service station and were very high. However, as the facility had been removed and deep excavating had taken place to remove the soil down to the design grade, this information had no affect on the safe development of the site and was only historical. Tickets and manifests were included in the report. I had no comment about them. I found the Spill Closure Report to be acceptable. As the entire volume of contaminated soil had been removed and the end point sample results were almost entirely non-detect and as groundwater was unaffected, I determined that the spill had been remediated and that the incident no longer posed a threat to the public or the environment. I sent a Spill Closure Letter to 24 Second Avenue Owner, LLC, c/o AORE Holdings, LLC at the 49 Bleecker Street address. I closed the spill case effective today."

Remarks: "4 tanks pending removal, loss found under tank, c/u pending"

All TTF:

Facility ID:	1409689
Spill Number:	1409689
Spill Tank Test:	2498487
Site ID:	503330
Tank Number:	1
Tank Size:	0
Material:	0009
EPA UST:	True
UST:	True
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	RVKETANI
Last Modified Date:	Not reported

All Materials:

Site ID:	503330
Operable Unit ID:	1252686
Operable Unit:	01
Material ID:	2254812
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA

24 SECOND AVENUE OWNER LLC (Continued) **S117394134**

EPA ID:	NYR000225318
Facility Status:	Not reported
Location Address 1:	24 2ND AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000225318
Mailing Name:	24 SECOND AVENUE OWNER LLC
Mailing Contact:	24 SECOND AVENUE OWNER LLC
Mailing Address 1:	49 BLEECKER STREET
Mailing Address 2:	SUITE 301
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10012
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	NYR000191726
Trans2 State ID:	NJR000063677
Generator Ship Date:	01/22/2016
Trans1 Recv Date:	01/22/2016
Trans2 Recv Date:	01/28/2016
TSD Site Recv Date:	02/02/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000225318
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	006612847FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

24 SECOND AVENUE OWNER LLC (Continued) **S117394134**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3500
Units:	P - Pounds
Number of Containers:	6
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D018
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AR657 **SNUG HARBOR OWNERS INC** **NY AST** **U003384669**
North **303 MERCER STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.215 mi.
1134 ft. **Site 4 of 8 in cluster AR**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-092193
Program Type:	PBS
UTM X:	584972.08375
UTM Y:	4509327.36766
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2360
Affiliation Type:	Facility Owner
Company Name:	SNUG HARBOR OWNERS INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	303 MERCER ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 228-0349
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-06-03

Site Id:	2360
Affiliation Type:	Mail Contact
Company Name:	JOHN J GROGAN & ASSOCIATES

SNUG HARBOR OWNERS INC (Continued) **U003384669**

Contact Type:	Not reported
Contact Name:	TIMOTHY C. GROGAN
Address1:	360 LEXINGTON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 370-1480
EMail:	TCGROGAN@GROGANASSOC.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-06-11

Site Id:	2360
Affiliation Type:	Facility Operator
Company Name:	SNUG HARBOR OWNERS INC
Contact Type:	Not reported
Contact Name:	GROGAN ASSOCIATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 228-0349
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2360
Affiliation Type:	Emergency Contact
Company Name:	SNUG HARBOR OWNERS INC
Contact Type:	Not reported
Contact Name:	GROGAN ASSOCIATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 228-0349
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	4176
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

SNUG HARBOR OWNERS INC (Continued) **U003384669**

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1978
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/04/2011
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AT658 **CON EDISON** **NY MANIFEST** **S117066360**
ESE **302 E 5TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.215 mi.
1135 ft. **Site 1 of 11 in cluster AT**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004590048
Facility Status:	Not reported
Location Address 1:	302 E 5TH ST
Code:	BP
Location Address 2:	SB 990
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004590048
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117066360**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004590048
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608197GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AI659 **CON EDISON** **RCRA NonGen / NLR** **1019904418**
SW **19 E HOUSTON ST** **NYP004797775**
1/8-1/4 **NEW YORK, NY 10012**
0.215 mi.
1136 ft. **Site 18 of 23 in cluster AI**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:
Date form received by agency: 06/23/2015
Facility name: CON EDISON
Facility address: 19 E HOUSTON ST
NEW YORK, NY 10012
EPA ID: NYP004797775
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/23/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

AI660 **MC 19 EAST HOUSTON LLC** **RCRA NonGen / NLR** **1019326142**
SW **19 E HOUSTON ST** **NYR000227553**
1/8-1/4 **NEW YORK, NY 10012**
0.215 mi.
1136 ft. **Site 19 of 23 in cluster AI**

Relative: **Lower**
Actual: **41 ft.**

RCRA NonGen / NLR:
Date form received by agency: 12/23/2016
Facility name: MC 19 EAST HOUSTON LLC
Facility address: 19 E HOUSTON ST
NEW YORK, NY 10012
EPA ID: NYR000227553

MC 19 EAST HOUSTON LLC (Continued) **1019326142**

Mailing address: E 59TH ST - 17TH FL
NEW YORK, NY 10022
Contact: ANDREW RODGERS
Contact address: W 37TH ST - 11TH FL
NEW YORK, NY 10018
Contact country: US
Contact telephone: 646-568-4057
Contact email: ANDREW.RODGERS@CIKKUERS.CIN
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MC 19 EAST HOUSTON LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/08/2016
Owner/Op end date: Not reported

Owner/operator name: MC 19 EAST HOUSTON LLC
Owner/operator address: E 59TH ST - 17TH FL
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/08/2016
Owner/Op end date: Not reported

Owner/operator name: MC 19 EAST HOUSTON LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/08/2016
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

MC 19 EAST HOUSTON LLC (Continued) **1019326142**

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D008
. Waste name: LEAD

Historical Generators:

Date form received by agency:	07/05/2016
Site name:	MC 19 EAST HOUSTON LLC
Classification:	Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

AI661 **19 EAST HOUSTON STREET** **US BROWNFIELDS** **1018119725**
SW **19 EAST HOUSTON STREET** **N/A**
1/8-1/4 **MANHATTAN, NY 10012**
0.215 mi.
1136 ft. **Site 20 of 23 in cluster AI**

Relative: **Lower**
Actual: **41 ft.**

US BROWNFIELDS:

Property Name:	19 EAST HOUSTON STREET
Recipient Name:	New York, City of
Grant Type:	Assessment
Property Number:	Block 511, Lot 19
Parcel size:	.14
Latitude:	40.725102
Longitude:	-73.99641500000001
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	151024
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4500
Assessment Funding Source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

19 EAST HOUSTON STREET (Continued) **1018119725**

Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	97257906
Start Date:	03/07/2012 00:00:00
Ownership Entity:	Government
Completion Date:	04/27/2012 00:00:00
Current Owner:	City of New York
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported

19 EAST HOUSTON STREET (Continued) **1018119725**

Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Residential, commercial, auto repair/sales
Below Poverty Number:	8718
Below Poverty Percent:	14.5%
Meidan Income:	29885
Meidan Income Number:	15750
Meidan Income Percent:	26.1%
Vacant Housing Number:	4532
Vacant Housing Percent:	12.8%
Unemployed Number:	2570
Unemployed Percent:	4.3%

AI662 **MC 19 EAST HOUSTON LLC** **NY MANIFEST** **S119079262**
SW **19 E HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.215 mi.
1136 ft. **Site 21 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYR000227553
Facility Status:	Not reported
Location Address 1:	19 EAST HOUSTON STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000227553
Mailing Name:	MC 19 EAST HOUSTON LLC
Mailing Contact:	MC 19 EAST HOUSTON LLC
Mailing Address 1:	55 E HOUSTON ST 17TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10022
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6465684057

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	09/29/2016
Trans1 Recv Date:	09/29/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/29/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000227553
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	013321551JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

MC 19 EAST HOUSTON LLC (Continued) **S119079262**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	56360
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D008
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI663 **CON EDISON** **NY MANIFEST** **S119076049**
SW **19 E HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.215 mi.
1136 ft. **Site 22 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004797775
Facility Status:	Not reported
Location Address 1:	E HOUSTON & BROADWAY
Code:	BP
Location Address 2:	MH 37036
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004797775
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S119076049**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/2015
Trans1 Recv Date:	06/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004797775
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614449GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AI664 **CON EDISON** **NJ MANIFEST** **S120673086**
SW **19 E HOUSTON ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.215 mi.
1136 ft. **Site 23 of 23 in cluster AI**

Relative:
Lower

Actual:
41 ft.

NJ MANIFEST:

EPA Id:	NYP004797775
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614449GBF
EPA ID:	NYP004797775
Date Shipped:	6/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120673086**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AT665 **108 EAST FOURTH LLC** **NY AST** **U003392125**
ESE **108 EAST 4TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.215 mi.
1136 ft. **Site 2 of 11 in cluster AT**

Relative:
Lower

Actual:
35 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-214930
Program Type:	PBS
UTM X:	585460.99031
UTM Y:	4508812.44318
Expiration Date:	03/21/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8008
Affiliation Type:	Facility Operator
Company Name:	108 EAST FOURTH LLC
Contact Type:	Not reported
Contact Name:	CHARLES CARROLL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 685-3982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-21

Site Id:	8008
Affiliation Type:	Emergency Contact
Company Name:	108 EAST FOURTH LLC
Contact Type:	Not reported
Contact Name:	CHARLES CARROLL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 685-3982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG

108 EAST FOURTH LLC (Continued) **U003392125**

Date Last Modified: 2005-03-21

Site Id: 8008
Affiliation Type: Mail Contact
Company Name: 108 EAST FOURTH LLC
Contact Type: MANAGER
Contact Name: MICHAEL KANE
Address1: 240 WEST 35TH ST. SUITE 504
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 685-3982
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-03-21

Site Id: 8008
Affiliation Type: Facility Owner
Company Name: 108 EAST FOURTH LLC
Contact Type: PROPERTY MANAGER
Contact Name: BILLY GILROY
Address1: 240 WEST 35TH ST. SUITE 504
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 685-3982
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-17

Tank Info:

Tank Number: 001
Tank Id: 23600
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron

108 EAST FOURTH LLC (Continued) **U003392125**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AT666 **CON ED** **NY MANIFEST** **S118463739**
ESE **88 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.215 mi.
1136 ft. **Site 3 of 11 in cluster AT**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856348
Facility Status:	Not reported
Location Address 1:	88 E 4TH ST
Code:	BP
Location Address 2:	SB 866
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856348
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON ED (Continued) **S118463739**

Generator EPA ID:	NYP004856348
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085705JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AP667 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S104275493**
NE **275 NORTH 8TH ST.** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.215 mi.
1137 ft. **Site 29 of 29 in cluster AP**

Relative:
Lower

Actual:
40 ft.

LTANKS:

Facility ID:	8706710
Site ID:	176330
Closed Date:	2003-03-04
Spill Number:	8706710
Spill Date:	1987-11-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED

CLOSED-LACKOF RECENT INFO (Continued) **S104275493**

Referred To:	Not reported
Reported to Dept:	1987-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-16
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	OUR LADY OF MT. CARMEL
Spiller Address:	275 NORTH 8TH ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	148202
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/04/2003-Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"5K TANK FAILED WITH A HIGH VOLUME LEAK, WILL EXCAVATE, ISOLATE, AND RETEST. CONTACT: FR. CASSARO (718) 384-0223. CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	8706710
Spill Number:	8706710
Spill Tank Test:	1532195
Site ID:	176330
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	176330
Operable Unit ID:	910418
Operable Unit:	01
Material ID:	465713
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00

CLOSED-LACKOF RECENT INFO (Continued) **S104275493**

Units: L
Recovered: .00
Oxygenate: Not reported

AT668 **CON EDISON SERVICE BOX: 866** **RCRA NonGen / NLR** **1016450361**
ESE **94 E 4TH ST** **NY MANIFEST** **NYP004293858**
1/8-1/4 **NEW YORK, NY 10003**
0.216 mi.
1139 ft. **Site 4 of 11 in cluster AT**

Relative:
Lower

Actual:
35 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/15/2013
Facility name: CON EDISON SERVICE BOX: 866
Facility address: 94 E 4TH ST
NEW YORK, NY 10003
EPA ID: NYP004293858
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 347-865-5931
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/15/2013
Site name: CON EDISON SERVICE BOX: 866
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004293858
Facility Status: Not reported
Location Address 1: 94 E 4TH ST
Code: BP

CON EDISON SERVICE BOX: 866 (Continued) **1016450361**

Location Address 2:	SERVICE BOX # 866
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004293858
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/15/2013
Trans1 Recv Date:	03/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004293858
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841236JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500

CON EDISON SERVICE BOX: 866 (Continued) **1016450361**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AT669 **94 E. 4TH ST** **NY AST** **A100292883**
ESE **94 EAST 4TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.216 mi.
1139 ft. **Site 5 of 11 in cluster AT**

Relative:
Lower

Actual:
35 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609268
Program Type:	PBS
UTM X:	585357.10921
UTM Y:	4508837.64840
Expiration Date:	09/29/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	31113
Affiliation Type:	Facility Owner
Company Name:	EAST 4TH PROPERTIES, LLC
Contact Type:	OWNER
Contact Name:	BENNY A. CAIOLA
Address1:	230 E. 85TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10028
Country Code:	001
Phone:	(212) 772-8830
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2008-07-11

Site Id:	31113
Affiliation Type:	Mail Contact
Company Name:	EAST 4TH PROPERTIES, LLC
Contact Type:	Not reported
Contact Name:	BENNY A. CAIOLA
Address1:	230 EAST 85TH STREET
Address2:	Not reported

94 E. 4TH ST (Continued) **A100292883**

City:	NEW YORK
State:	NY
Zip Code:	10028
Country Code:	001
Phone:	(212) 772-8830
EMail:	BCAIOLA#BETTINAEQUITIES.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-10-31

Site Id:	31113
Affiliation Type:	Facility Operator
Company Name:	94 E. 4TH ST
Contact Type:	Not reported
Contact Name:	EAST 4TH PROPERTIES, LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 772-8830
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-10-31

Site Id:	31113
Affiliation Type:	Emergency Contact
Company Name:	EAST 4TH PROPERTIES, LLC
Contact Type:	Not reported
Contact Name:	BETTINA EQUITIES COMPANY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 772-8830
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	66982
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None

94 E. 4TH ST (Continued) **A100292883**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
G05 - Tank Secondary Containment - Synthetic Liner
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1998
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AJ670 **CHURCH OF THE NATIVITY** **NY UST** **U000404919**
SE **44 2ND AVENUE** **NY AST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.216 mi.
1142 ft. **Site 7 of 9 in cluster AJ**

Relative: **Lower**
Actual: **38 ft.**

UST:

Id/Status:	2-401110 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585296.32724
UTM Y:	4508732.76676
Site Type:	Other

Affiliation Records:

Site Id:	19167
Affiliation Type:	Facility Owner
Company Name:	CHURCH OF THE NATIVITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	44 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-8590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

CHURCH OF THE NATIVITY (Continued) **U000404919**

Site Id:	19167
Affiliation Type:	Mail Contact
Company Name:	CHURCH OF THE NATIVITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	44 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 674-8590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19167
Affiliation Type:	Facility Operator
Company Name:	CHURCH OF THE NATIVITY
Contact Type:	Not reported
Contact Name:	RAMON COLLADO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 674-8590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19167
Affiliation Type:	Emergency Contact
Company Name:	CHURCH OF THE NATIVITY
Contact Type:	Not reported
Contact Name:	RAMON COLLADO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 674-8590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	21769
Tank Status:	Closed - In Place
Material Name:	Closed - In Place

CHURCH OF THE NATIVITY (Continued) **U000404919**

Capacity Gallons:	1500
Install Date:	01/01/1999
Date Tank Closed:	02/23/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	11/01/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-080896
Program Type:	PBS
UTM X:	585307.91425
UTM Y:	4508702.47472
Expiration Date:	01/14/2022
Site Type:	School

Affiliation Records:

Site Id:	1654
Affiliation Type:	Mail Contact
Company Name:	BROTHERS OF THE CHRISTIAN SCHOOL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	800 NEWMAN SPRINGS ROAD
Address2:	Not reported
City:	LINCROFT
State:	NJ
Zip Code:	07738
Country Code:	001
Phone:	(732) 842-7420
EMail:	CBNY@CBNEWYORK.ORG
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-11-21
Site Id:	1654

CHURCH OF THE NATIVITY (Continued) **U000404919**

Affiliation Type:	Facility Operator
Company Name:	LA SALLE ACADEMY
Contact Type:	Not reported
Contact Name:	BROTHER JAMES MARTINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-8940
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1654
Affiliation Type:	Emergency Contact
Company Name:	BROTHERS OF THE CHRISTIAN SCHOOL
Contact Type:	Not reported
Contact Name:	JORGE ZAVALA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 851-3141
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1654
Affiliation Type:	Facility Owner
Company Name:	BROTHERS OF THE CHRISTIAN SCHOOL
Contact Type:	PRESIDENT
Contact Name:	BRO. MICHAEL FARRELL
Address1:	800 NEWMAN SPRINGS ROAD
Address2:	Not reported
City:	LINCROFT
State:	NJ
Zip Code:	07738
Country Code:	001
Phone:	(732) 842-7420
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-11-21

Tank Info:

Tank Number:	001
Tank Id:	2715
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

CHURCH OF THE NATIVITY (Continued) **U000404919**

Equipment Records:

H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1936
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	06/23/2017
Material Name:	#2 fuel oil (on-site consumption)

AL671 **126TH DEPOT** **NY LTANKS** **S106971660**
SE **24-60 2ND AVE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.217 mi.
1147 ft. **Site 15 of 24 in cluster AL**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	0409201
Site ID:	334066
Closed Date:	2005-02-22
Spill Number:	0409201
Spill Date:	2004-11-17
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-11-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-19

126TH DEPOT (Continued) **S106971660**

Spill Record Last Update:	2005-02-22
Spiller Name:	PASCOE CAMAJ
Spiller Company:	126TH DEPOT
Spiller Address:	24-60 2ND AVE
Spiller County:	001
Spiller Contact:	PASCOE CAMAJ
Spiller Phone:	(718) 243-4581
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	269270
DEC Memo:	"02-22-05: Product found in sump of diesel tanks 5&6. Primary suction line failed, secondary passed. Flex connector was replaced. Primary, secondary and sump passed testing."
Remarks:	"SUNCTION LINE FOR TANKS 5 & 6 FAILED: TANK HAS BEEN LOCKED OUT AND WILL REPAIR, AND RESTEST"

AU672 **CON EDISON** **RCRA NonGen / NLR 1012185524**
SW **HOUSTON ST & BROADWAY** **NY MANIFEST NYP004163325**
1/8-1/4 **NEW YORK, NY 10008**
0.217 mi.
1148 ft. **Site 1 of 11 in cluster AU**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	HOUSTON ST & BROADWAY NEW YORK, NY 10008
EPA ID:	NYP004163325
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL BETO
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	917-337-5519
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1012185524**

Historical Generators:
Date form received by agency: 01/13/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004163325
Facility Status: Not reported
Location Address 1: BROADWAY & HOUSTON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004163325
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 01/23/2009
Trans1 Recv Date: 01/23/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/27/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004163325
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: 001433921FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON (Continued) **1012185524**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	D007
Waste Code 1_3:	D006
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AJ673 **59-61 E 3 ST ASSOC** **NY AST** **U003384283**
ESE **59-61 EAST 3RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.218 mi.
1149 ft. **Site 8 of 9 in cluster AJ**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-090174
Program Type:	PBS
UTM X:	585364.06554
UTM Y:	4508802.32334
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2180
Affiliation Type:	Facility Owner
Company Name:	59-61 E 3 ST ASSOC
Contact Type:	PARTNER
Contact Name:	JEFFREY BROWN
Address1:	45 WHITE ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001

59-61 E 3 ST ASSOC (Continued) **U003384283**

Phone:	(212) 219-3944
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-03-12

Site Id:	2180
Affiliation Type:	Mail Contact
Company Name:	EJ REALTY
Contact Type:	Not reported
Contact Name:	SUPERINTENDENT
Address1:	45 WHITE STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(212) 219-3944
EMail:	EJR10013@YAHOO.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-03-12

Site Id:	2180
Affiliation Type:	Facility Operator
Company Name:	59-61 E 3 ST ASSOC
Contact Type:	Not reported
Contact Name:	ANDY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-2269
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-02-17

Site Id:	2180
Affiliation Type:	Emergency Contact
Company Name:	59-61 E 3 ST ASSOC
Contact Type:	Not reported
Contact Name:	CRISTINA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-2269
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

59-61 E 3 ST ASSOC (Continued) **U003384283**

Tank Info:

Tank Number:	001
Tank Id:	3462
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/26/1950
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/28/2012
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AT674 **CON ED** **NY MANIFEST** **S118463686**
ESE **90 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.218 mi.
1150 ft. **Site 6 of 11 in cluster AT**

Relative: **Lower**

Actual: **35 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004855538
Facility Status:	Not reported
Location Address 1:	90 E 4TH ST
Code:	BP
Location Address 2:	SB 857
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004855538
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR

CON ED (Continued) **S118463686**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855538
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245213JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON ED (Continued) **S118463686**

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AV675 **GEORGETOWN PLAZA** **NY AST** **U004076153**
North **60 EAST 8TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.218 mi.
1150 ft. **Site 1 of 15 in cluster AV**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-055069
Program Type:	PBS
UTM X:	585053.33987
UTM Y:	4509344.31168
Expiration Date:	12/02/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	803
Affiliation Type:	Facility Owner
Company Name:	THE 60 EAST 8TH ST. CONDOMINIUM % ROSE ASSOCIATES
Contact Type:	PROPERTY MANAGER
Contact Name:	DAVID VON HOLLWEG
Address1:	200 MADISON AVENUE, 5TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 210-6666
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-12-06

Site Id:	803
Affiliation Type:	Facility Operator
Company Name:	GEORGETOWN PLAZA
Contact Type:	Not reported
Contact Name:	VALDET BELLCISITIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 533-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-10-18

Site Id:	803
Affiliation Type:	Emergency Contact

GEORGETOWN PLAZA (Continued) **U004076153**

Company Name:	THE 60 EAST 8TH ST. CONDOMINIUM % ROSE ASSOCIATES
Contact Type:	Not reported
Contact Name:	DAVID VON HOLLWEG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 210-6686
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-10-13

Site Id:	803
Affiliation Type:	Mail Contact
Company Name:	ROSETERRA MANAGEMENT
Contact Type:	Not reported
Contact Name:	COMPLIANCE DEPT.
Address1:	770 LEXINGTON AVENUE, 9TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10065
Country Code:	001
Phone:	(212) 317-3613
EMail:	SNICHOLSON@ROSETERRA.COM
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2017-09-07

Tank Info:

Tank Number:	001
Tank Id:	1741
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

GEORGETOWN PLAZA (Continued) **U004076153**

Install Date:	11/17/1948
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

AL676 **CON EDISON** **NY MANIFEST** **S117066090**
SE **47 E 2ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.219 mi.
1157 ft. **Site 16 of 24 in cluster AL**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004587119
Facility Status:	Not reported
Location Address 1:	47 E 2ND ST
Code:	BP
Location Address 2:	SB 522
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004587119
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2014
Trans1 Recv Date:	07/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004587119
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117066090**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423882GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AT677 **304 EAST 5TH STREET** **NY AST** **U003385611**
ESE **304 EAST 5TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1160 ft. **Site 7 of 11 in cluster AT**

Relative: **Lower**
Actual: **34 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-149179
Program Type:	PBS
UTM X:	585426.06432
UTM Y:	4508918.73017
Expiration Date:	06/05/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4486
Affiliation Type:	Facility Owner

304 EAST 5TH STREET (Continued) **U003385611**

Company Name:	302-4 SWA LLC C/O STEFAN SLYWOTZKY
Contact Type:	OWNER
Contact Name:	WOLDODYMYRA SLYWOTZKY
Address1:	241 EAST 18TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 777-0184
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-26

Site Id:	4486
Affiliation Type:	Mail Contact
Company Name:	C/O WOLDODYMYRA SLYWOTZKY
Contact Type:	Not reported
Contact Name:	302-4 SWA LLC
Address1:	241 EAST 18TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 777-0184
EMail:	SWACSLY@GMAIL.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-26

Site Id:	4486
Affiliation Type:	Facility Operator
Company Name:	304 EAST 5TH STREET
Contact Type:	Not reported
Contact Name:	BOHDAN PACHASHYNSKYY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-0184
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4486
Affiliation Type:	Emergency Contact
Company Name:	302-4 SWA LLC C/O STEFAN SLYWOTZKY
Contact Type:	Not reported
Contact Name:	BOHDAN PACHASHYNSKYY
Address1:	Not reported
Address2:	Not reported
City:	Not reported

304 EAST 5TH STREET (Continued) **U003385611**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 677-3256
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	8116
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1940
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	06/26/2017
Material Name:	#4 fuel oil (on-site consumption)

AV678 **CON EDISON - SERVICE BOX 28835** **NJ MANIFEST** **S120677743**
North **BROADWAY & E 8 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1160 ft. **Site 2 of 15 in cluster AV**

Relative: **Lower**
Actual: **38 ft.**

NJ MANIFEST:

EPA Id:	NYP004858124
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD

CON EDISON - SERVICE BOX 28835 (Continued) **S120677743**

Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014087504JJK
EPA ID:	NYP004858124
Date Shipped:	10/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AV679 **CON EDISON** **RCRA NonGen / NLR** **1012185394**
North **BROADWAY & E 8TH ST** **NY MANIFEST** **NYP004161998**
1/8-1/4 **NEW YORK, NY 10009**
0.220 mi.
1160 ft. **Site 3 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	BROADWAY & E 8TH ST NEW YORK, NY 10009
EPA ID:	NYP004161998
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL D'AGOSTINO
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	917-559-8958
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/22/2008
Site name:	CON EDISON
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004161998
Facility Status:	Not reported
Location Address 1:	BROADWAY & E 8th ST
Code:	BP
Location Address 2:	MH28844
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10020

CON EDISON (Continued) **1012185394**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004161998
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2008
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2008
Trans1 Recv Date: 10/22/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004161998
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: 001432761FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 25.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0

CON EDISON (Continued) **1012185394**

Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AV680 **NYCT - 8TH ST STA N&R LINE** **RCRA NonGen / NLR** **1004762204**
North **E 8TH ST & BROADWAY CORNER** **NY MANIFEST** **NYR000094573**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1160 ft. **Site 4 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCT - 8TH ST STA N&R LINE
Facility address:	E 8TH ST & BROADWAY CORNER NEW YORK, NY 10003
EPA ID:	NYR000094573
Mailing address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact:	JAMES CRANDALL
Contact address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	718-243-4581
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	718-243-4581
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	718-243-4581
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

NYCT - 8TH ST STA N&R LINE (Continued) **1004762204**

Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYCT - 8TH ST STA N&R LINE
Classification: Not a generator, verified

Date form received by agency: 02/27/2001
Site name: NYCT - 8TH ST STA N&R LINE
Classification: Not a generator, verified

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000094573
Facility Status: Not reported
Location Address 1: E 8TH ST & BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000094573
Mailing Name: NYCTA
Mailing Contact: N/S
Mailing Address 1: 370 JAY ST RM 819

NYCT - 8TH ST STA N&R LINE (Continued) **1004762204**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182434227

NY MANIFEST:

Document ID:	NJA4070458
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	H10376
Trans2 State ID:	H10376
Generator Ship Date:	06/20/2002
Trans1 Recv Date:	06/20/2002
Trans2 Recv Date:	06/21/2002
TSD Site Recv Date:	06/21/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000094573
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	NJD003812047
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00240
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
3 additional NY_MANIFEST: record(s) in the EDR Site Report.

AV681 **CON EDISON** **NY MANIFEST** **S118463859**
North **BROADWAY & E 8 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1160 ft. **Site 5 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004858124
Facility Status:	Not reported
Location Address 1:	BROADWAY & E 8 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004858124
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858124
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087504JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S118463859**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AV682 **CON EDISON - SERVICE BOX 28835** **RCRA-LQG** **1019325783**
North **BROADWAY & E 8 ST** **NYP004858124**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1160 ft. **Site 6 of 15 in cluster AV**

Relative: RCRA-LQG:
Lower

Date form received by agency:	02/05/2016
Facility name:	CON EDISON - SERVICE BOX 28835
Facility address:	BROADWAY & E 8 ST NEW YORK, NY 10003
EPA ID:	NYP004858124
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

Actual:
38 ft.

CON EDISON - SERVICE BOX 28835 (Continued) **1019325783**

hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/22/2015
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/22/2015
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D008
. Waste name:	LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code:	D008
Waste name:	LEAD

CON EDISON - SERVICE BOX 28835 (Continued) **1019325783**

Amount (Lbs): 2500

Violation Status: No violations found

AU683 **CONSOLIDATED EDISON** **NY MANIFEST** **1009242479**
SW **V5990-W 88TH ST & BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY**
0.220 mi.
1163 ft. **Site 2 of 11 in cluster AU**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004115689
Facility Status:	Not reported
Location Address 1:	V5990-W 88TH ST & BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004115689
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE1273932
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	46233JM
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2003
Trans1 Recv Date:	10/10/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/10/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004115689
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported

CONSOLIDATED EDISON (Continued) **1009242479**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00909
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AN684 **TISCH SCHOOL OF THE ARTS** **NY UST** **U000399849**
East **111 SECOND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1163 ft. **Site 2 of 16 in cluster AN**

Relative: **Lower**

Actual: **34 ft.**

UST:

Id/Status:	2-314927 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585465.73644
UTM Y:	4509038.20009
Site Type:	School

Affiliation Records:

Site Id:	14377
Affiliation Type:	Facility Owner
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	70 WASHINGTON SQUARE SOUTH
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 998-1212
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-02-15

TISCH SCHOOL OF THE ARTS (Continued) **U000399849**

Site Id:	14377
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(732) 499-8051
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Site Id:	14377
Affiliation Type:	Mail Contact
Company Name:	NEW YORK UNIVERSITY
Contact Type:	Not reported
Contact Name:	LOUIS ORTIZ
Address1:	14 WAVERLY PLACE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 998-1450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Site Id:	14377
Affiliation Type:	Facility Operator
Company Name:	TISCH SCHOOL OF THE ARTS
Contact Type:	Not reported
Contact Name:	KEITH FREDER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-3338
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Tank Info:

Tank Number:	001
Tank ID:	12831
Tank Status:	Closed - In Place
Material Name:	Closed - In Place

TISCH SCHOOL OF THE ARTS (Continued) **U000399849**

Capacity Gallons:	4000
Install Date:	12/01/1977
Date Tank Closed:	11/10/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	04/22/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

AN685 **NYU - TTF** **NY LTANKS** **S109583768**
East **111 2ND AVE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.220 mi.
1163 ft. **Site 3 of 16 in cluster AN**

Relative: **Lower**
Actual: **34 ft.**

LTANKS:

Facility ID:	0900252
Site ID:	412176
Closed Date:	2010-07-06
Spill Number:	0900252
Spill Date:	2009-04-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	2009-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

NYU - TTF (Continued) **S109583768**

Date Entered In Computer:	2009-04-07
Spill Record Last Update:	2010-07-06
Spiller Name:	Not reported
Spiller Company:	NYU
Spiller Address:	111 2ND AVE
Spiller County:	999
Spiller Contact:	MARLYN JOSEPH
Spiller Phone:	(646) 772-7949
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	361359
DEC Memo:	"4/24/2009 TTF letter sent to: Mr. Louis Ortiz New York University 14 Waverly Place New York, NY 10003 5/7/2009 - Sangesland received a call from John Leddy to discuss the work schedule for this site. Apparently the city DOT office of sidewalk permits is moving and can not issue a sidewalk opening permit soon enough to meet the May 22nd deadline given in the TTF letter. Sangesland sent the following e-mail back to Mr. Leddy. ********** Mr. Leddy - The DEC has made a notation on this spill file that a 30 day extension has been approved due to the NYC DOT sidewalk permit issue. Please have the tank repair/retest work done at this site by June 22, 2009 ********** Protest requested another extension to July 22nd. Steve, We have experienced delays in getting sidewalk opening permits for the EIR of the 5000 gal. No. 2 fuel oil tank at that location. Our customer is understandably concerned with the present deadline of 6/22/09, which looks like it won t be met. We would greatly appreciate one last extension of 30 days to July 22. Thank you. John Leddy - Pro Test ********** 10/16/09. Pro Test Environmental emailed: The tank was excavated and tests of tank alone and lines were done. The tank, remote fill line and vent line failed. Contamination was seen. EIR of tank under city sidewalk on hold pending NYU getting bids for the job and complication of having to replace entire sidewalk before holiday moratorium starting on 11/17. Will keep you advised. JK. 7/6/10 received closure report dated 12/21/09 prepared by pro Test Environmental. Tank failed because of vent line. Soil samples taken. Most contaminants were non-detectable. Two exccedances found from Boring #2: benzo(a)pyrene [200 ppb vs. 60 ppb] and Boring #5: benzo(a)anthracene [270 ppb vs. 224 ppb]. Tank was closed in place. NFA. bf "
Remarks:	"TANK TEST FAILURE ON A 5000 GALLON TANK UNK IF ANY PRODUCT SPILLED."

All Materials:

Site ID:	412176
Operable Unit ID:	1168663
Operable Unit:	01
Material ID:	2160271
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AN686 **NYU** **NY LTANKS** **S106471773**
East **111 2ND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.220 mi.
1163 ft. **Site 4 of 16 in cluster AN**

Relative: **Lower**

Actual: **34 ft.**

LTANKS:

Facility ID:	0402181
Site ID:	157657
Closed Date:	2005-07-27
Spill Number:	0402181
Spill Date:	2004-05-20
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2004-05-27
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-27
Spill Record Last Update:	2011-02-15
Spiller Name:	STEPHANE KUNG
Spiller Company:	NYU
Spiller Address:	111 2ND AVE
Spiller County:	001
Spiller Contact:	STEPHANE KUNG
Spiller Phone:	(212) 998-1450
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	14358
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 5/28/2004 Sangesland spoke with Adam Smyth of Triumvirate Envir. He says NYU has a 4,000 gal UST under the sidewalk in front of it's building at 111 2nd Ave. Piping from this tank enters the basement of the building and runs an oil fired backup heating system when their interruptible natural gas gets cut off during extreme cold weather. NYU Maintenance people noticed staining on the wall around these pipes. The wall was opened and it was determined that the pipes were rotten. All pipes were replaced and the tank/pipes passed a pressure test. NYU would like to keep this tank in operation. Additional horizontal borings were taken through the bottom of the basement wall into the area under the buried tank. These soil samples came back quote hot unquote. Triumvirate Environmental is in the process of completing a delineation of the site. They will either propose some form of remediation in place, or they will propose excavating the tank, contamination & then replacing the tank. This report will be sent directly to Jake Krimgold. Contaminated soil letter sent to Louis Ortiz NYU 14 Waverly Place New York, NY 10003 6/24/2004 Sangesland called Stephanie Kung at NYU to ask for a status update. She said she has a draft copy of a work plan from Triumvirate

NYU (Continued) **S106471773**

Environmental. A hard copy of this plan should be submitted to the DEC within the next week or so. The plan outlines additional delineation and proposed remediation options. A decision has NOT yet been made if the tank needs to be pulled. 7/26/04. J.Krimgold talked to Justin Williams (Triumvirate Env.). He stated that drilling will be commenced on 7/30/04. 10/21/04. J.Krimgold has reviewed the Site Investigation Report submitted in August 2004 by Triumvirate Env. The report was not accepted for the following reasons: Boring logs with soil screening results are not included in the report. The drawing in the report is not up to scale and lacks compass orientation. Soil sampling results performed by ACE-ATLAS Corp. are not included in the report. Also , the location of this sample is not shown on the drawing. Even though it is stated that this sample was taken roughly 12 inches off the floor the floor elevation is not defined in the report. If, as stated in the report, no evidence of an oil leak was found during tank top excavation, than it is unclear what is the source of the oil on the basement wall and elevated levels of contaminants found in the ACE-ATLAS sample. Contaminant levels in boring number 1 seems to be increasing with depth, however, no explanations were given to this fact. Lateral and vertical delineation of a petroleum release has not been completed. The Summary statement that samples fall well under the cleanup objectives is incorrect. All soil samples presented in the report exhibit contaminant concentrations above NYS TAGM levels. Requested to correct these deficiencies and resubmit the report for Departmental review. 3/1/5/05. J.Krimgold reviewed the Site Investigation Report Addendum submitted by Triumvirate Env. on February 18, 2005. The report concludes that soil in the vicinity of UST and piping had been impacted. However, no recommendations were giving regarding remediation or further actions at this site. J.Krimgold contacted Triumvirate (Adam Smyth). He will submit recommendations in a week. 7/27/05. J.Krimgold reviewed a letter submitted by NYU dated May 27, 2005. In the letter NYU concludes that contamination found in soil borings GP-6 , GP-7 and GP-2 was not from UST's corroded fill line, but rather show a background contamination in the urban fill. NFA letter."

Remarks: "Spill has not been cleaned up. "

All Materials:

Site ID:	157657
Operable Unit ID:	883914
Operable Unit:	01
Material ID:	489818
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AW687 **CON ED** **NY MANIFEST** **1009242107**
NW **80 WASHINGTON SQ E SB55746** **N/A**
1/8-1/4 **NEW YORK, NY 10027**
0.221 mi.
1168 ft. **Site 1 of 7 in cluster AW**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004107793
Facility Status:	Not reported
Location Address 1:	80 WASHINGTON SQ E SB55746
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10027
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004107793
Mailing Name:	CON ED
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NJA4135757
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	H10376
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2003
Trans1 Recv Date:	02/22/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/25/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004107793
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

CON ED (Continued) **1009242107**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AW688 **CON EDISON** **NJ MANIFEST** **S120675431**
NW **85 WASHINGTON SQ W** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.221 mi.
1168 ft. **Site 2 of 7 in cluster AW**

Relative: **Lower**
Actual: **32 ft.**

NJ MANIFEST:

EPA Id:	NYP004824591
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612853GBF
EPA ID:	NYP004824591
Date Shipped:	8/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CON EDISON (Continued) **S120675431**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AW689 **CON EDISON** **NY MANIFEST** **S119077221**
NW **85 WASHINGTON SQ W** **N/A**
1/8-1/4 **NEW YORK, NY 10011**
0.221 mi.
1168 ft. **Site 3 of 7 in cluster AW**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004824591
Facility Status:	Not reported
Location Address 1:	85 WASHINGTON PL
Code:	BP
Location Address 2:	SB 47793
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10011
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004824591
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S119077221**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2015
Trans1 Recv Date:	08/15/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004824591
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612853GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AW690 **CON EDISON** **RCRA NonGen / NLR** **1019906635**
NW **85 WASHINGTON SQ W** **FINDS** **NYP004824591**
1/8-1/4 **NEW YORK, NY 10011** **ECHO**
0.221 mi.
1168 ft. **Site 4 of 7 in cluster AW**

Relative:
Lower

Actual:
32 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/15/2015
Facility name:	CON EDISON
Facility address:	85 WASHINGTON SQ W NEW YORK, NY 10011
EPA ID:	NYP004824591
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/15/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069667998

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019906635**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906635
Registry ID: 110069667998
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069667998

AN691 **CON EDISON** **NY MANIFEST** **S118091265**
East **115 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.221 mi.
1169 ft. **Site 5 of 16 in cluster AN**

Relative: **Lower**
Actual: **34 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004789509
Facility Status: Not reported
Location Address 1: 115 2ND AVE
Code: BP
Location Address 2: SB 53809
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004789509
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 06/03/2015
Trans1 Recv Date: 06/03/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/04/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004789509
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON (Continued) **S118091265**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614239GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AN692 **CON EDISON** **NY MANIFEST** **S117066339**
East **115 2 AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.221 mi.
1169 ft. **Site 6 of 16 in cluster AN**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004589818
Facility Status:	Not reported
Location Address 1:	115 2 AVE
Code:	BP
Location Address 2:	SB 53980
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004589818

CON EDISON (Continued) **S117066339**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004589818
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423997GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117066339**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AN693 **CON EDISON** **NJ MANIFEST** **S120672370**
East **115 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.221 mi.
1169 ft. **Site 7 of 16 in cluster AN**

Relative: **Lower**
Actual: **34 ft.**

NJ MANIFEST:

EPA Id:	NYP004789509
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614239GBF
EPA ID:	NYP004789509
Date Shipped:	6/3/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120672370**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AN694 **CON EDISON** **RCRA NonGen / NLR** **1019903755**
East **115 2ND AVE** **NYP004789509**
1/8-1/4 **NEW YORK, NY 10003**
0.221 mi.
1169 ft. **Site 8 of 16 in cluster AN**

Relative: **Lower**

Actual: **34 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/03/2015
Facility name:	CON EDISON
Facility address:	115 2ND AVE NEW YORK, NY 10003
EPA ID:	NYP004789509
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1019903755**

Historical Generators:
Date form received by agency: 06/03/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

AL695 **CON ED** **NY MANIFEST** **S118463747**
SE **26 EAST 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.222 mi.
1170 ft. **Site 17 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004856470
Facility Status: Not reported
Location Address 1: 26 EAST 1ST ST
Code: BP
Location Address 2: SB 517
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004856470
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/20/2015
Trans1 Recv Date: 10/20/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004856470
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014085729JJK

CON ED (Continued) **S118463747**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AH696 **CON EDISON SERVICE BOX: 1362** **RCRA NonGen / NLR** **1016966723**
NNE **69 E 8 ST** **NY MANIFEST** **NYP004395687**
1/8-1/4 **NEW YORK, NY 10009**
0.222 mi.
1170 ft. **Site 23 of 23 in cluster AH**

Relative: **Lower**

Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 1362
Facility address:	69 E 8 ST NEW YORK, NY 10009
EPA ID:	NYP004395687
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON SERVICE BOX: 1362 (Continued) **1016966723**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 1362
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395687
Facility Status: Not reported
Location Address 1: 69 E 8TH ST
Code: BP
Location Address 2: SB1362
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10009
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395687
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported

CON EDISON SERVICE BOX: 1362 (Continued) **1016966723**

Generator Ship Date:	11/21/2013
Trans1 Recv Date:	11/21/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237612GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AL697 **34 EAST 1ST STREET** **NY LTANKS** **S102619285**
SSE **34 E. 1 ST BTWN 1ST & 2ND** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.223 mi.
1178 ft. **Site 18 of 24 in cluster AL**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	9701768
Site ID:	237521
Closed Date:	2003-03-03
Spill Number:	9701768
Spill Date:	1997-05-09

34 EAST 1ST STREET (Continued) **S102619285**

Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-05-09
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-05-09
Spill Record Last Update:	2004-05-14
Spiller Name:	SAME
Spiller Company:	MOBIL GAS STATION
Spiller Address:	EAST 34 AND 1ST AVE
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195629
DEC Memo:	""
Remarks:	"THEY SUSPECT THERE IS GAS LEAKING OUT OF THE TANKS AT THE MOBIL.THERE ARE STRONG FUMES IN THE ADDRESS AT 34 EAST 1ST STREET FD NOT ON THE SCENE.THEY SUSPECT IT IS COMING FROM THE MOBIL. "

All Materials:

Site ID:	237521
Operable Unit ID:	1047789
Operable Unit:	01
Material ID:	338312
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM698 **CON EDISON SERVICE BOX: 41582** **RCRA NonGen / NLR** **1016968763**
SSW **276 MULBERRY ST** **NYP004423919**
1/8-1/4 **NEW YORK, NY 10012**
0.223 mi.
1179 ft. **Site 5 of 10 in cluster AM**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/22/2014
Facility name:	CON EDISON SERVICE BOX: 41582
Facility address:	276 MULBERRY ST NEW YORK, NY 10012

CON EDISON SERVICE BOX: 41582 (Continued) **1016968763**

EPA ID: NYP004423919
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/22/2014
Site name: CON EDISON SERVICE BOX: 41582
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

AM699 **CON EDISON SERVICE BOX: 41582** **RCRA NonGen / NLR** **1016968764**
SSW **276 MULBERRY ST** **NYP004423927**
1/8-1/4 **NEW YORK, NY 10012**
0.223 mi.
1179 ft. **Site 6 of 10 in cluster AM**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/22/2014
Facility name: CON EDISON SERVICE BOX: 41582
Facility address: 276 MULBERRY ST
NEW YORK, NY 10012
EPA ID: NYP004423927
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02

CON EDISON SERVICE BOX: 41582 (Continued) **1016968764**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/22/2014
Site name: CON EDISON SERVICE BOX: 41582
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

AM700 **CON EDISON** **NY MANIFEST** **S116291339**
SSW **276 MULBERRY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.223 mi.
1179 ft. **Site 7 of 10 in cluster AM**

Relative: **Lower**
Actual: **41 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004423935
Facility Status: Not reported
Location Address 1: 276 MULBERRY ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004423935
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON (Continued) **S116291339**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/2014
Trans1 Recv Date:	01/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004423935
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692984JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AX701 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S104275487**
SE **49 SOUTH 2ND STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.224 mi.
1184 ft. **Site 1 of 9 in cluster AX**

Relative:
Lower

Actual:
39 ft.

LTANKS:

Facility ID:	8807845
Site ID:	73688
Closed Date:	2003-03-14
Spill Number:	8807845
Spill Date:	1988-12-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1988-12-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-12-30
Spill Record Last Update:	2003-03-14
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	69330
DEC Memo:	""
Remarks:	"3K TANK FAILED TEST WITH A LEAK RATE OF -.593GPH, WILL REPAIR AND RETEST. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	8807845
Spill Number:	8807845
Spill Tank Test:	1535041
Site ID:	73688
Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S104275487**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 73688
Operable Unit ID: 923322
Operable Unit: 01
Material ID: 452621
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

Facility ID: 8706162
Site ID: 265300
Closed Date: 2003-03-13
Spill Number: 8706162
Spill Date: 1987-10-21
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 1987-10-21
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1987-10-26
Spill Record Last Update: 2003-03-18
Spiller Name: Not reported
Spiller Company: AMSTAR
Spiller Address: 49 SOUTH 2ND ST.
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 216185
DEC Memo: ""
Remarks: "(2) 5.5K TANKS FAILED TEST WITH A LEAK RATE OF -.1863G/HR. WILL EXCAVATE, ISOLATE, AND RETEST. CONTACT: JOE LUCCES (718) 387-6800. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

CLOSED-LACKOF RECENT INFO (Continued) **S104275487**

Facility ID:	8706162
Spill Number:	8706162
Spill Tank Test:	1531985
Site ID:	265300
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	265300
Operable Unit ID:	912204
Operable Unit:	01
Material ID:	465187
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AX702 **TATE & LYLE NORTH AMERICAN SUGAR INC.-BR** **NY MOSF AST** **S104491021**
SE **49 SOUTH SECOND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 11211**
0.224 mi.
1184 ft. **Site 2 of 9 in cluster AX**

Relative: **Lower**
Actual: **39 ft.**

MOSF AST:

MOSF Number:	2-2440
SWIS Code:	61
Facility Town:	BROOKLYN
Facility Phone:	(718) 387-6800
Emergency Contact Name:	LAEL J. PAULSON
Emergency Contact Phone:	(718) 387-6800
Total Tanks:	6
Total Capacity:	402608
Daily Throughput:	0
License Status:	1
Facility Type:	APARTMENT BUILDING
Product Transfer Operation:	Tank Truck
Facility Status:	IN SERVICE
Operator Name:	MICHAEL TODD
Owner Name:	TATE & LYLE NORTH AMERICAN SUGARS INC.
Owner Address:	49 SOUTH 2ND STREET
Owner City,St,Zip:	BROOKLYN, NY 11211-

TATE & LYLE NORTH AMERICAN SUGAR INC.-BR (Continued) **S104491021**

Owner Phone:	(718) 387-6800
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner
Mailing Name:	TATE & LYLE NORTH AMERICAN SUGARS INC.
Mailing Address:	49 SOUTH 2 STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11211-5187
Mailing Contact:	MICHAEL TODD
Mailing Phone:	(718) 387-6800
Legal Agent Name:	C.T. CORPORATION SYSTEM
Legal Agent Address:	1633 BROADWAY
Legal Agent City,St,Zip:	NEW YORK, NY 10017-
LIC Expires:	03/31/2006

Tank ID:	006
Tank Location:	ABOVEGROUND
Install Date:	01/79
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	40|42|52 / 73|58|07
Federal ID:	Not reported
Inspected Date:	03/09/1998
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000194
Pollution Discharge Elimination System Num:	0-008443
Date Legal Agent Filed with Secretary of State:	08/87

Tank ID:	003
Tank Location:	ABOVEGROUND
Install Date:	05/87
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel

TATE & LYLE NORTH AMERICAN SUGAR INC.-BR (Continued) **S104491021**

Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	None
Pipe Type:	0
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	40|42|52 / 73|58|07
Federal ID:	Not reported
Inspected Date:	03/09/1998
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000194
Pollution Discharge Elimination System Num:	0-008443
Date Legal Agent Filed with Secretary of State:	08/87

Tank ID:	004
Tank Location:	ABOVEGROUND
Install Date:	02/87
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	None
Pipe Type:	0
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	40|42|52 / 73|58|07
Federal ID:	Not reported
Inspected Date:	03/09/1998
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported

TATE & LYLE NORTH AMERICAN SUGAR INC.-BR (Continued) **S104491021**

Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000194
Pollution Discharge Elimination System Num:	0-008443
Date Legal Agent Filed with Secretary of State:	08/87

Tank ID:	005
Tank Location:	ABOVEGROUND
Install Date:	02/87
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	None
Pipe Type:	0
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	40|42|52 / 73|58|07
Federal ID:	Not reported
Inspected Date:	03/09/1998
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000194
Pollution Discharge Elimination System Num:	0-008443
Date Legal Agent Filed with Secretary of State:	08/87

AX703 **TATE & LYLE NORTH AMERICAN SUGAR INC.-BR** **NY MOSF UST** **1003881565**
SE **49 SOUTH SECOND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 11211**
0.224 mi.
1184 ft. **Site 3 of 9 in cluster AX**

Relative:
Lower

Actual:
39 ft.

MOSF UST:

Id/Status:	2-2440 / ACTIVE FACILITY
SWIS Code:	61
Facility Town:	BROOKLYN
Contact Phone:	(718) 387-6800
Emergency Contact:	LAEL J. PAULSON
Emergency Telephone:	(718) 387-6800
CBS Number:	2-000194
SPDES Num:	0-008443
Total Tanks:	6
Total Capacity:	402608
Avg Throughput:	0
License Stat:	1
Facility Type:	APARTMENT BUILDING
Prod Xfer Options:	Tank Truck
Expiration Date:	03/31/2006
Applic Rcvd:	01/05/2001
Operator:	MICHAEL TODD
Owner Name:	TATE & LYLE NORTH AMERICAN SUGARS INC.
Owner Address:	49 SOUTH 2ND STREET
Owner City,St,Zip:	BROOKLYN, NY 11211-
Owner Telephone:	(718) 387-6800
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner
Mail To Name:	TATE & LYLE NORTH AMERICAN SUGARS INC.
Mail To Address:	49 SOUTH 2 STREET
Mail To Address 2:	Not reported
Mail City,St,Zip:	BROOKLYN, NY 11211-5187
Mail To Contact:	MICHAEL TODD
Mail To Telephone:	(718) 387-6800
Legal Agent Name:	C.T. CORPORATION SYSTEM
Legal Agent Address:	1633 BROADWAY
Legal Agent City,St,Zip:	NEW YORK, NY 10017-
Date Filed:	08/87
Latitude:	40|42|52
Longitude:	73|58|07

Tank ID:	001
Tank Location:	UNDERGROUND
Install Date:	01/50
Capacity (Gal):	200754
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Other

TATE & LYLE NORTH AMERICAN SUGAR INC.-BR (Continued) **1003881565**

Overfill Protection:	None
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	03/09/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	002
Tank Location:	UNDERGROUND
Install Date:	01/50
Capacity (Gal):	200754
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Other
Overfill Protection:	None
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	03/09/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	D003
Tank Location:	UNDERGROUND
Install Date:	01/50
Capacity (Gal):	2888
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None

TATE & LYLE NORTH AMERICAN SUGAR INC.-BR (Continued) **1003881565**

Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Other
Overfill Protection:	None
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	UNKWN
Status of Data:	Complete
Inspected Date:	03/09/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

AN704 **41-43 EAST 7TH STREET** **NY AST** **A100178035**
ENE **41-43 EAST 7TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.224 mi.
1184 ft. **Site 9 of 16 in cluster AN**

Relative: **Lower**

Actual: **35 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605752
Program Type:	PBS
UTM X:	585402.90278
UTM Y:	4509125.12450
Expiration Date:	07/29/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27619
Affiliation Type:	Mail Contact
Company Name:	EAST 7TH STREET ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	THOMAS J CARACCIO
Address1:	PO BOX 3557
Address2:	Not reported
City:	NEW HYDE PARK
State:	NY
Zip Code:	11040
Country Code:	001
Phone:	(718) 343-1337
EMail:	TOMC@VIKMGT.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-19

41-43 EAST 7TH STREET (Continued) **A100178035**

Site Id:	27619
Affiliation Type:	Facility Operator
Company Name:	41-43 EAST 7TH STREET
Contact Type:	Not reported
Contact Name:	LENIN ENAMORADO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-1614
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-19

Site Id:	27619
Affiliation Type:	Emergency Contact
Company Name:	EAST 7TH STREET ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	THOMAS MASTRANGELO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 343-1337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-12-12

Site Id:	27619
Affiliation Type:	Facility Owner
Company Name:	EAST 7TH STREET ASSOCIATES LLC
Contact Type:	MANAGER
Contact Name:	THOMAS J CARACCIO
Address1:	PO BOX 3557
Address2:	Not reported
City:	NEW HYDE PARK
State:	NY
Zip Code:	11040
Country Code:	001
Phone:	(718) 343-1336
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-19

Tank Info:

Tank Number:	001
Tank Id:	60422
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

41-43 EAST 7TH STREET (Continued) **A100178035**

Equipment Records:

B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/18/1956
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AS705 **CON EDISON** **NY MANIFEST** **S118464190**
East **302 E 6TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.224 mi.
1185 ft. **Site 2 of 8 in cluster AS**

Relative: **Lower**
Actual: **33 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004863680
Facility Status:	Not reported
Location Address 1:	302 E 6TH ST
Code:	BP
Location Address 2:	SB 1102
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004863680
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S118464190**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/2015
Trans1 Recv Date:	11/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004863680
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085917JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AW706 **CON EDISON** **RCRA NonGen / NLR** **1019909034**
NW **W 4TH ST & WASHINGTON SQ E** **FINDS** **NYP004880288**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.225 mi.
1187 ft. **Site 5 of 7 in cluster AW**

Relative:
Lower

Actual:
32 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/16/2015
Facility name:	CON EDISON
Facility address:	W 4TH ST & WASHINGTON SQ E COR OF NEW YORK, NY 10012
EPA ID:	NYP004880288
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/16/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069645281

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

CON EDISON (Continued) **1019909034**

corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909034
Registry ID: 110069645281
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069645281

AM707 **CON EDISON - MATT ST** **PA MANIFEST** **S118889053**
SSW **279 MATT ST** **N/A**
1/8-1/4 **NY, NY 10012**
0.225 mi.
1189 ft. **Site 8 of 10 in cluster AM**

Relative: Higher
Actual: 42 ft.

Manifest Details:
Year: 2015
Manifest Number: 002659223GBF
Manifest Type: TSD Copy
Generator EPA Id: NYP004721700
Generator Date: 01/30/2015
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: Not reported
TSD Date: Not reported
TSD Facility Name: Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address: 2869 Sandstone Dr
TSD Facility City: Hatfield
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 1
Container Type: Cargo tanks (tank trucks)
Waste Quantity: 600
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD085690592
Date TSP Sig: Not reported

AM708 **CON EDISON** **NY MANIFEST** **S117739078**
SSW **279 MOTT ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.225 mi.
1189 ft. **Site 9 of 10 in cluster AM**

Relative: Higher
Actual: 42 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004721700
Facility Status: Not reported
Location Address 1: 279 MOTT ST

CON EDISON (Continued) **S117739078**

Code:	BP
Location Address 2:	SB41416
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004721700
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/30/2015
Trans1 Recv Date:	01/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004721700
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	002659223GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117739078**

Quantity:	1190
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AU709 **CON EDISON MANHOLE: 36981** **RCRA-CESQG** **1016149719**
SW **1 W HOUSTON ST FRONT OF** **FINDS** **NYP004283859**
1/8-1/4 **NEW YORK, NY 10014** **ECHO**
0.226 mi. **NY MANIFEST**
1192 ft. **Site 3 of 11 in cluster AU**

Relative: **Lower**
Actual: **40 ft.**

RCRA-CESQG:

Date form received by agency:	01/17/2013
Facility name:	CON EDISON MANHOLE: 36981
Facility address:	1 W HOUSTON ST FRONT OF NEW YORK, NY 10014
EPA ID:	NYP004283859
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	RICARDO CARTY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	646-772-3407
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON MANHOLE: 36981 (Continued) **1016149719**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110055463662

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149719
Registry ID:	110055463662
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055463662

NY MANIFEST:

Country:	USA
EPA ID:	NYP004283859
Facility Status:	Not reported
Location Address 1:	1 W HOUSTON ST
Code:	BP
Location Address 2:	MH 36981
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10014
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004283859
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON MANHOLE: 36981 (Continued) **1016149719**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/17/2013
Trans1 Recv Date:	01/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004283859
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707329JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON MANHOLE: 36981 (Continued) **1016149719**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AY710 **22 ST MARKS PLACE LP** **NY AST** **U003384912**
ENE **22 ST MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.226 mi.
1194 ft. **Site 1 of 9 in cluster AY**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-099538
Program Type:	PBS
UTM X:	585440.22881
UTM Y:	4509170.13005
Expiration Date:	06/03/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2967
Affiliation Type:	Facility Owner
Company Name:	22 ST. MARKS PLACE LP
Contact Type:	MANAGING AGENT
Contact Name:	S. BLANAROVICH
Address1:	182 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-1612
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-25

Site Id:	2967
Affiliation Type:	Mail Contact
Company Name:	NBKN REALTY MGMT CORP
Contact Type:	Not reported
Contact Name:	S. BLANAROVICH
Address1:	182 2ND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 477-1612
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-25

Site Id:	2967
Affiliation Type:	Facility Operator

22 ST MARKS PLACE LP (Continued) **U003384912**

Company Name:	22 ST MARKS PLACE LP
Contact Type:	Not reported
Contact Name:	I. KHOMENETS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 462-7158
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-25

Site Id:	2967
Affiliation Type:	Emergency Contact
Company Name:	22 ST. MARKS PLACE LP
Contact Type:	Not reported
Contact Name:	S. BLANAROVICH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 477-1612
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-08-25

Tank Info:

Tank Number:	001
Tank Id:	4721
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1987
Capacity Gallons:	2000
Tightness Test Method:	NN

22 ST MARKS PLACE LP (Continued) **U003384912**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	06/20/2017
Material Name:	gasoline

AW711 **CONSOLIDATED EDISON** **NY MANIFEST** **1009242114**
NW **WASH SQ E & W 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.227 mi.
1196 ft. **Site 6 of 7 in cluster AW**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004107892
Facility Status:	Not reported
Location Address 1:	WASH SQ E & W 4TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004107892
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NJA4138514
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	H10376
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2003
Trans1 Recv Date:	02/22/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/25/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004107892
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CONSOLIDATED EDISON (Continued) **1009242114**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AS712 **104 SECOND AVE** **NY AST** **A100320166**
East **104 SECOND AVE** **N/A**
1/8-1/4 **NEW YORK CITY, NY 10003**
0.227 mi.
1196 ft. **Site 3 of 8 in cluster AS**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610848
Program Type:	PBS
UTM X:	585421.99435
UTM Y:	4508987.66808
Expiration Date:	10/12/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	398336
Affiliation Type:	Mail Contact
Company Name:	104 SECOND REALTY,LLC
Contact Type:	Not reported
Contact Name:	GEORGE LAVIAN
Address1:	377 PARK AVE SOUTH
Address2:	3RD FLR
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001

104 SECOND AVE (Continued) **A100320166**

Phone:	(212) 213-2500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-09-11

Site Id:	398336
Affiliation Type:	Facility Operator
Company Name:	104 SECOND AVE
Contact Type:	Not reported
Contact Name:	HONDRIS SALAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-4642
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2008-05-28

Site Id:	398336
Affiliation Type:	Emergency Contact
Company Name:	104 SECOND REALTY,LLC
Contact Type:	Not reported
Contact Name:	HONDRIS SALAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 334-4406
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2008-05-28

Site Id:	398336
Affiliation Type:	Facility Owner
Company Name:	104 SECOND REALTY,LLC
Contact Type:	MANAGING AGENT
Contact Name:	GEORGE LAVIAN
Address1:	377 PARK AVE SOUTH, 3RD FLR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 213-2500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-09-11

104 SECOND AVE (Continued) **A100320166**

Tank Info:

Tank Number:	001
Tank Id:	223273
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
B05 - Tank External Protection - Jacketed
G02 - Tank Secondary Containment - Vault (w/access)
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None

Tank Location:	2
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/12/1999
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AT713 **CON ED** **NY MANIFEST** **S118463741**
ESE **98 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.228 mi.
1202 ft. **Site 8 of 11 in cluster AT**

Relative: **Lower**
Actual: **34 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856363
Facility Status:	Not reported
Location Address 1:	98 E 4TH ST
Code:	BP
Location Address 2:	SB 867
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856363
Mailing Name:	CON ED

CON ED (Continued) **S118463741**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856363
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085707JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON ED (Continued) **S118463741**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AT714 **9TH PCT** **NY AST** **U003393747**
ESE **321 EAST 5TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.228 mi.
1203 ft. **Site 9 of 11 in cluster AT**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-342823
Program Type:	PBS
UTM X:	585460.83690
UTM Y:	4508913.69098
Expiration Date:	12/14/2022
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	16652
Affiliation Type:	Facility Owner
Company Name:	NYC PD / ASD
Contact Type:	SUPERVISOR
Contact Name:	NICHOLAS GISONDA
Address1:	1 POLICE PLAZA - ROOM 800
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 374-7650
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-12-20

Site Id:	16652
Affiliation Type:	Facility Operator
Company Name:	9TH PCT
Contact Type:	Not reported
Contact Name:	NYC PD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 477-7811
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

9TH PCT (Continued) **U003393747**

Site Id:	16652
Affiliation Type:	Emergency Contact
Company Name:	NYC PD / ASD
Contact Type:	Not reported
Contact Name:	NYC PD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 476-7524
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-12-20

Site Id:	16652
Affiliation Type:	Mail Contact
Company Name:	NYC POLICE DEPARTMENT
Contact Type:	Not reported
Contact Name:	COMMANDING OFFICER
Address1:	BUILDING MAINTENANCE SECTION
Address2:	59-06 BROOKLYN-QUEENS EXPY
City:	WOODSIDE
State:	NY
Zip Code:	11377
Country Code:	001
Phone:	(718) 476-7576
EMail:	NICHOLAS.GISONDA@NYPD.ORG
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-12-20

Tank Info:

Tank Number:	001
Tank Id:	32277
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron

9TH PCT (Continued) **U003393747**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/1961
Capacity Gallons:	2500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/08/2004
Register:	True
Modified By:	MFLEONAR
Last Modified:	12/20/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	179418
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2004
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	12/20/2017
Material Name:	#2 fuel oil (on-site consumption)

AJ715 **TOMAR EQUITIES, LLC** **NY AST** **U003392124**
SE **60 EAST 3RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.228 mi.
1205 ft. **Site 9 of 9 in cluster AJ**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-214922
Program Type:	PBS
UTM X:	585410.43285
UTM Y:	4508750.57795
Expiration Date:	11/20/2017
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8007
Affiliation Type:	Mail Contact
Company Name:	TOMAR EQUITIES, LLC
Contact Type:	Not reported
Contact Name:	KOSTAS ZACHARIADIS
Address1:	346 EAST 59TH ST,, SUITE 1
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 750-2209
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-11-15

Site Id:	8007
Affiliation Type:	Facility Operator
Company Name:	TOMAR EQUITIES, LLC
Contact Type:	Not reported
Contact Name:	EVAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 902-4418
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-12-13

Site Id:	8007
Affiliation Type:	Emergency Contact
Company Name:	TOMAR EQUITIES, LLC
Contact Type:	Not reported
Contact Name:	KOSTAS ZACHARIADIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported

TOMAR EQUITIES, LLC (Continued) **U003392124**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 410-9234
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 2012-12-13

Site Id: 8007
Affiliation Type: Facility Owner
Company Name: TOMAR EQUITIES, LLC
Contact Type: AGENT
Contact Name: TOMAR EQUITIES, LLC
Address1: 346 EAST 59TH ST,, SUITE 1
Address2: Not reported
City: NY
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 750-2209
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2011-11-15

Tank Info:

Tank Number: 001
Tank Id: 23599
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/26/1999
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True

TOMAR EQUITIES, LLC (Continued) **U003392124**

Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AU716 **600 BROADWAY** **NY AST** **A100292577**
SW **600 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.228 mi.
1206 ft. **Site 4 of 11 in cluster AU**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608888
Program Type:	PBS
UTM X:	584711.12086
UTM Y:	4508728.87826
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30736
Affiliation Type:	Facility Operator
Company Name:	600 BROADWAY
Contact Type:	Not reported
Contact Name:	ACHS CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 398-3970
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-03-11

Site Id:	30736
Affiliation Type:	Emergency Contact
Company Name:	600 BROADWAY PARTNERS,LLC
Contact Type:	Not reported
Contact Name:	JIM MILLER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 483-6454
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-03-11

Site Id:	30736
Affiliation Type:	Facility Owner

600 BROADWAY (Continued) **A100292577**

Company Name:	600 BROADWAY PARTNERS, LLC
Contact Type:	DIRECTOR
Contact Name:	JIM MILLER
Address1:	1412 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 398-3970
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2012-12-18

Site Id:	30736
Affiliation Type:	Mail Contact
Company Name:	ACHS MGMT
Contact Type:	Not reported
Contact Name:	JIM MILLER
Address1:	1412 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 398-3970
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2012-12-18

Tank Info:

Tank Number:	001
Tank Id:	65920
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1972
Capacity Gallons:	3000

600 BROADWAY (Continued) **A100292577**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/16/2008
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AN717 **24 ST. MARK'S PLACE OWNERS, LLC** **NY AST** **U003388808**
ENE **24 ST MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.229 mi.
1207 ft. **Site 10 of 16 in cluster AN**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-281085
Program Type:	PBS
UTM X:	585450.68390
UTM Y:	4509164.36654
Expiration Date:	01/05/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	12308
Affiliation Type:	Facility Operator
Company Name:	24 ST. MARKS PLACE OWNERS, LLC
Contact Type:	Not reported
Contact Name:	NA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-08-01

Site Id:	12308
Affiliation Type:	Emergency Contact
Company Name:	24 ST MARKS TL LLC
Contact Type:	Not reported
Contact Name:	LAURENCE BEAME
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 770-8882
EMail:	Not reported
Fax Number:	Not reported

24 ST. MARK'S PLACE OWNERS, LLC (Continued) **U003388808**

Modified By: MRBARROW
Date Last Modified: 2017-08-01

Site Id: 12308
Affiliation Type: Mail Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: LAURENCE BEAME
Address1: PO BOX 61
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (516) 770-8882
EMail: LAURENCEBEAME@GMAIL.COM
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2017-08-01

Site Id: 12308
Affiliation Type: Facility Owner
Company Name: 24 ST MARKS TL LLC
Contact Type: OWNER
Contact Name: LAURENCE BEAME
Address1: PO BOX 61
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (516) 770-8882
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2017-08-01

Tank Info:

Tank Number: 001
Tank Id: 14672
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle

Tank Location: 1

24 ST. MARK'S PLACE OWNERS, LLC (Continued) **U003388808**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1900
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	08/01/2017
Material Name:	#2 fuel oil (on-site consumption)

AN718 **TANK TEST FAILURE - TTF** **NY LTANKS** **S110762260**
ENE **24 ST MARK'S PLACE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.229 mi.
1207 ft. **Site 11 of 16 in cluster AN**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:

Facility ID:	1010402
Site ID:	444005
Closed Date:	Not reported
Spill Number:	1010402
Spill Date:	2011-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2011-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2011-01-05
Spill Record Last Update:	2015-03-31
Spiller Name:	CHRISTOPHER
Spiller Company:	UNKNOWN
Spiller Address:	24 ST MARX PLACE
Spiller County:	999
Spiller Contact:	CHRISTOPHER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	398920
DEC Memo:	"8/15/2012 TTF Spill Case transferred to DEC Tim DeMeo. 03-31-2015 - V. Brevdo As per discussion with Chief of Spill Response Section, this Tank Test Failure Spill Case is transferred to Remediation Section B for management of the project. Spill Case is further assigned to Jonathan Kolleeny. VB"

TANK TEST FAILURE - TTF (Continued) **S110762260**

Remarks: "5000g tank. Unknown why failed"

All Materials:
Site ID: 444005
Operable Unit ID: 1194449
Operable Unit: 01
Material ID: 2190276
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AN719 **24 ST MARKS PLACE** **NY LTANKS** **S104877385**
ENE **24 ST MARKS PLACE** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.229 mi.
1207 ft. **Site 12 of 16 in cluster AN**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:
Facility ID: 0010130
Site ID: 143501
Closed Date: 2003-06-13
Spill Number: 0010130
Spill Date: 2000-12-08
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2000-12-08
CID: 389
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-12-08
Spill Record Last Update: 2003-06-13
Spiller Name: CALLER
Spiller Company: CASTLE OIL
Spiller Address: 290 LOCUST AVE
Spiller County: 001
Spiller Contact: JIM CAREY
Spiller Phone: (718) 579-3414
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 122386
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE E2MIS NOTES: 12/8/00 11:10: APPROX. 1 GALLON UNKNOWN OIL ON

24 ST MARKS PLACE (Continued) **S104877385**

APPROX. 150 GALLONS OF WATER. SPILL APPEARS TO BE CONTAINED. 1 LIQUID SAMPLE TAKEN. LAB RESULT RECEIVED 12/8/00 - 2345 HOURS: <1.00 PPM 12/13/00 - 1430 HOURS: CLEANUP COMPLETED BY DOUBLE WASHING THE STRUCTURE WITH SLIX. LIQUIDS WERE REMOVED BY TANKER, AND SOLIDS WERE REMOVED BY VACTOR. NO LEAKING COMPANY EQUIPMENT. INCIDENT IS CLOSED."

Remarks: "caller reporting a spill of material from a tank overfill clean up in the process and no callback necessary"

All Materials:

Site ID:	143501
Operable Unit ID:	831095
Operable Unit:	01
Material ID:	544047
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

AV720 **CON EDISON SERVICE BOX: 28841** **RCRA NonGen / NLR 1016966709**
North **759 W BROADWAY** **NY MANIFEST NYP004395547**
1/8-1/4 **NEW YORK, NY 10009**
0.229 mi.
1207 ft. **Site 7 of 15 in cluster AV**

Relative: **Lower**

Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 28841
Facility address:	759 W BROADWAY NEW YORK, NY 10009
EPA ID:	NYP004395547
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON SERVICE BOX: 28841 (Continued) **1016966709**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 28841
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395547
Facility Status: Not reported
Location Address 1: 759 BROADWAY
Code: BP
Location Address 2: SB28841
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395547
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2013
Trans1 Recv Date: 11/21/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/25/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004395547
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported

CON EDISON SERVICE BOX: 28841 (Continued) **1016966709**

Manifest Tracking Number:	002237676GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AV721 **CON EDISON MANHOLE 57389** **RCRA NonGen / NLR** **1014926674**
North **759 BROADWAY** **NJ MANIFEST** **NYP004244539**
1/8-1/4 **NEW YORK, NY 10003** **NY MANIFEST**
0.229 mi.
1207 ft. **Site 8 of 15 in cluster AV**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	12/20/2011
Facility name:	CON EDISON MANHOLE 57389
Facility address:	759 BROADWAY NEW YORK, NY 10003
EPA ID:	NYP004244539
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	JOSE MONTALVO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-427-1331
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
38 ft.

CON EDISON MANHOLE 57389 (Continued) **1014926674**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 11/20/2011
- Site name: CON EDISON MANHOLE 57389
- Classification: Conditionally Exempt Small Quantity Generator

- Violation Status: No violations found

NJ MANIFEST:
- EPA Id: NYP004244539
- Mail Address: 4 IRVING PL, RM 828
- Mail City/State/Zip: NEW YORK, NY 10003
- Facility Phone: Not reported
- Emergency Phone: Not reported
- Contact: JOSE MONTALVO
- Comments: Not reported
- SIC Code: Not reported
- County: NY061
- Municipal: Not reported
- Previous EPA Id: Not reported
- Gen Flag: Not reported
- Trans Flag: Not reported
- TSDF Flag: Not reported
- Name Change: Not reported
- Date Change: Not reported

Manifest:
- Manifest Number: 003634414JJK
- EPA ID: NYP004244539
- Date Shipped: 11/20/2011
- TSDF EPA ID: NJD002200046
- Transporter EPA ID: NJ0000027193
- Transporter 2 EPA ID: Not reported
- Transporter 3 EPA ID: Not reported
- Transporter 4 EPA ID: Not reported
- Transporter 5 EPA ID: Not reported
- Transporter 6 EPA ID: Not reported
- Transporter 7 EPA ID: Not reported
- Transporter 8 EPA ID: Not reported
- Transporter 9 EPA ID: Not reported
- Transporter 10 EPA ID: Not reported

CON EDISON MANHOLE 57389 (Continued) **1014926674**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2,000.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004244539
Facility Status:	Not reported
Location Address 1:	759 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004244539
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004

CON EDISON MANHOLE 57389 (Continued) **1014926674**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/20/2011
Trans1 Recv Date:	11/20/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/21/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004244539
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003634414JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AV722 **CON EDISON MANHOLE 51407** **RCRA NonGen / NLR** **1010326744**
North **759 BROADWAY & 8TH ST** **NY MANIFEST** **NYP004142832**
1/8-1/4 **NEW YORK, NY 10001**
0.229 mi.
1207 ft. **Site 9 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/17/2006
Facility name:	CON EDISON MANHOLE 51407
Facility address:	759 BROADWAY & 8TH ST E OF 8TH ST NEW YORK, NY 10001
EPA ID:	NYP004142832
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	ANDREW FIORE
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/16/2006
Site name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	11/15/2006
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004142832
Facility Status:	Not reported
Location Address 1:	MH57389 - 759 BROADWAY
Code:	BP

CON EDISON MANHOLE 51407 (Continued) **1010326744**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004142832
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE1319985
Manifest Status:	Not reported
seq:	01
Year:	2006
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/2006
Trans1 Recv Date:	06/12/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004142832
Trans1 EPA ID:	69526JR
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150

CON EDISON MANHOLE 51407 (Continued) **1010326744**

Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AV723 **CON EDISON SERVICE BOX: 28841** **NJ MANIFEST** **S120666037**
North **759 W BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.229 mi.
1207 ft. **Site 10 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

NJ MANIFEST:

EPA Id:	NYP004395547
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015318563JJK
EPA ID:	NYP004395547
Date Shipped:	2/18/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON SERVICE BOX: 28841 (Continued) **S120666037**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	CONSOLIDATED EDISON CO OF NY SB #28841
Transporter-1 EPA Facility Name:	CLEAN VENTURE INC
TSDF EPA Facility Name:	CYCLE CHEM INC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/18/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/19/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AZ724 **CON EDISON** **RCRA NonGen / NLR** **1018280499**
NE **27 3RD AVE** **FINDS** **NYP004753836**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.229 mi.
1211 ft. **Site 1 of 8 in cluster AZ**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/19/2015
Facility name:	CON EDISON
Facility address:	27 3RD AVE NEW YORK, NY 10003
EPA ID:	NYP004753836
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON (Continued) **1018280499**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/19/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067707020

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018280499
Registry ID: 110067707020
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067707020

AZ725 **CON EDISON** **NJ MANIFEST** **S120669237**
NE **27 3RD AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.229 mi.
1211 ft. **Site 2 of 8 in cluster AZ**

Relative: **Lower**
Actual: **40 ft.**

NJ MANIFEST:
EPA Id: NYP004753836
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

CON EDISON (Continued) **S120669237**

Manifest:

Manifest Number:	002611412GBF
EPA ID:	NYP004753836
Date Shipped:	3/19/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AZ726 **CON EDISON** **NY MANIFEST** **S118088446**
NE **27 3RD AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.229 mi.
1211 ft. **Site 3 of 8 in cluster AZ**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004753836
Facility Status:	Not reported
Location Address 1:	27 3 AV
Code:	BP
Location Address 2:	SB30956

CON EDISON (Continued) **S118088446**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004753836
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/19/2015
Trans1 Recv Date:	03/19/2015
Trans2 Recv Date:	03/20/2015
TSD Site Recv Date:	03/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004753836
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611412GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds

CON EDISON (Continued) **S118088446**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP004760104
Facility Status:	Not reported
Location Address 1:	27 3RD AVE
Code:	BP
Location Address 2:	SB 30956
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004760104
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/30/2015
Trans1 Recv Date:	03/30/2015
Trans2 Recv Date:	04/01/2015
TSD Site Recv Date:	04/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760104
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105

CON EDISON (Continued) **S118088446**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002611433GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AM727 **ST PATRICKS YOUTH CENTER** **NY UST** **U000401194**
SSW **268 MULBERRY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.229 mi.
1211 ft. **Site 10 of 10 in cluster AM**

Relative:
Lower

Actual:
41 ft.

UST:

Id/Status:	2-283436 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584871.50163
UTM Y:	4508591.95994
Site Type:	Unknown

Affiliation Records:

Site Id:	12513
Affiliation Type:	Facility Owner
Company Name:	ST PATRICKS OLD CATHEDRAL
Contact Type:	Not reported
Contact Name:	Not reported

ST PATRICKS YOUTH CENTER (Continued) **U000401194**

Address1:	263 MULBERRY ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 226-8075
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12513
Affiliation Type:	Mail Contact
Company Name:	ST PATRICKS OLD CATHEDRAL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	263 MULBERRY ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 226-8075
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12513
Affiliation Type:	Facility Operator
Company Name:	ST PATRICKS YOUTH CENTER
Contact Type:	Not reported
Contact Name:	RAMON TAVAREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 925-7111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12513
Affiliation Type:	Emergency Contact
Company Name:	ST PATRICKS OLD CATHEDRAL
Contact Type:	Not reported
Contact Name:	REV GUY VINCI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

ST PATRICKS YOUTH CENTER (Continued) **U000401194**

Phone:	(212) 226-8075
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	14899
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	01/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None

AO728 **CON EDISON** **NJ MANIFEST** **S120673599**
South **279 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.230 mi.
1212 ft. **Site 7 of 13 in cluster AO**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004803540
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported

CON EDISON (Continued) **S120673599**

Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002614592GBF
EPA ID:	NYP004803540
Date Shipped:	7/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AO729 **CON EDISON** **RCRA NonGen / NLR** **1019904910**
South **279 BOWERY** **NYP004803540**
1/8-1/4 **NEW YORK, NY 10002**
0.230 mi.
1212 ft. **Site 8 of 13 in cluster AO**

Relative:
Higher

Actual:
42 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/08/2015
Facility name:	CON EDISON
Facility address:	279 BOWERY NEW YORK, NY 10002
EPA ID:	NYP004803540
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/08/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

AO730 **CON ED** **NY MANIFEST** **S119076343**
South **279 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.230 mi.
1212 ft. **Site 9 of 13 in cluster AO**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004803540
Facility Status:	Not reported
Location Address 1:	SEC OF E HOUSTON ST AND BOWERY
Code:	BP

CON ED (Continued) **S119076343**

Location Address 2: SB 26880
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004803540
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/08/2015
Trans1 Recv Date: 07/08/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004803540
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002614592GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500

CON ED (Continued) **S119076343**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

BA731 **CON EDISON SERVICE BOX: 868** **RCRA NonGen / NLR** **1016969199**
ESE **100 E 4TH ST** **NY MANIFEST** **NYP004428504**
1/8-1/4 **NEW YORK, NY 10003**
0.230 mi.
1214 ft. **Site 1 of 16 in cluster BA**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/2014
Facility name:	CON EDISON SERVICE BOX: 868
Facility address:	100 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004428504
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON SERVICE BOX: 868 (Continued) **1016969199**

Historical Generators:
Date form received by agency: 01/28/2014
Site name: CON EDISON SERVICE BOX: 868
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004428504
Facility Status: Not reported
Location Address 1: F/O 100 EAST 4TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004428504
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/28/2014
Trans1 Recv Date: 01/28/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/30/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004428504
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011692922JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON SERVICE BOX: 868 (Continued) **1016969199**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AN732 **CON ED** **NY Spills** **S117851663**
ENE **119 2ND AVE & 7TH ST** **NY MANIFEST** **N/A**
1/8-1/4 **NEW YORK, NY 10035**
0.230 mi.
1216 ft. **Site 13 of 16 in cluster AN**

Relative: **Lower**
Actual: **34 ft.**

SPILLS:

Facility ID:	1412247
Facility Type:	ER
Spill Number:	1412247
DER Facility ID:	460862
Site ID:	506061
DEC Region:	2
Closed Date:	2015-04-03
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2015-03-26
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2015-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

CON ED (Continued) **S117851663**

UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2015-03-30
Spill Record Last Update:	2015-04-08
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	NOT APPLICABLE
DEC Memo:	"3/30/15-Vought-Created spill number as need to maintain record of response to NYCEM EOC at the request of Regional Director. Spill notes best summarized by Vought's summary emails from NYC EM EOC to all supervisors as follows: Initial Update from 3/27/15: There have been a total of three building collapses associated with the explosion at the addresses of 119, 121 and 123 Second Avenue. There is also 8 other building vacate orders issued by NYCDOB. NYPD, FDNY and EM are currently determining if whether any seconday human remains searches are or may be necessary so that it may be determined whether the debris is staged or directly loaded and hauled to a disposal facility. EM has requested that DEC, DEP and themselves inspect the two possible staging locations, Randalls Island DPR lot being the primary, and the North end of the EDC South Brooklyn Marine Terminal being the secondary location. Staff has reached out to DEC Water Unit (Southwell) as per the Regional Director to facilitate the possible inspections with DEP and EM, if necessary. The debris will be hauled by private (and not city) contractors and there is currently no estimated time for when debris removal will start. Ongoing discussions of filter fabric use at the site for water filtration and hay bale use for water filtration at the disposal facilities are being held as well. Intial information is that the hay bales may be supplied by DEP and/or DPR. Another Debris Task Force meeting is scheduled for 4pm today. With respect to air monitoring, DEP will be performing monitoring at disposal facilities (if needed) and DEP and DOH have been conducting air monitoring (including asbestos) at the explosion site since yesterday. A thorough search of the PBS and Spills database of the site has been performed and no active tanks were registered at any of the collapse sites. PBS Registrations were however noted for both 125 Second Avenue and 41-43 7th Street and these buildings have been heavily impacted with smoke and water. PBS inspections and or tank tightness testing of these buildings may be necessary (pending discussion with RSE or RD) to ensure that the collapse did not compromise the integrity of the adjacent tank systems. Final Update from 3/27/15: There have been a total of three building collapses at the addresses of 119, 121 and 123 Second Avenue associated with the explosion. There are also 8 other building vacate orders issued by NYCDOB. NYPD, FDNY and EM continue to determine if any seconday human remains searches are or may be necessary which will determine whether the debris is staged at a transfer location for human remain searches or directly loaded/hauled to a disposal facility after being searched for human remains at the site. To ensure an effective waste stream, numerous agencies including DEC, DEP, EM and HPD are working together to plan for both direct load and haul of debris to a disposal facility (Cooper Tank and/or 110 Sand) and also taking the site to a transfer location (Randalls island and/or South Brooklyn Marine Terminal). With respect to the direct load and haul, DEC is reaching out to HPD's contractors disposal facility (Cooper Tank in Brooklyn) to walk

CON ED (Continued) **S117851663**

them through the approval process and determine if whether they are seeking an increase in storage capacity or an increase in throughput capacity. The secondary direct load and haul location (110 Sand in Long Island) that closes at 3pm was requested to contact DEC Region 1 (Syed Rahman) to request an increase in operational hours. As the debris containers have begun to be loaded and loading is expected to continue through the night, HPD will reach out to 110 Sand to have them contact Syed Rahman directly to ask if they can take debris to 110 Sand also through the night. With respect to possibly staging the debris at a transfer location for secondary inspection, NYEM noted that an inspection of the Randall's Island DPR facility was not necessary due to its prior use and approval by all agencies during the Park Avenue building collapse. Staff faciliated a site inpsection to the secondary transfer location at South Brooklyn Marine Terminal that included DEP, EM and DEC Division of Water Unit and it was agreed by all parties that this location would be acceptable as well. With respect to air monitoring, DEP will be performing monitoring at disposal facilities (if needed) and DEP and DOH have been conducting air monitoring (including asbestos) at the explosion site since yesterday. Staff has sent an email request to DEP for more information on the air monitoring including results, methods used and agencies that reviewed and approved the results (eg-NYCDOH). A thorough search of the PBS and Spills database of the site has been performed and no active tanks were registered at any of the collapse sites. PBS Registrations were however noted for both 125 Second Avenue and 41-43 7th Street and these buildings have been heavily impacted with smoke and water. After further discussion with the Regional Engineer and Regional Spill Engineeer it was determined that PBS inspections of these adjacent facilities are not warranted at this time. Daily Update from 3/28/15: On 3/27/15, debris removal and transport operations continued overnight including the transport of a reported nine containers to Allocco Recycling located in Brooklyn and one reported container taken to Cooper Tank also in Brooklyn. Cooper Tank reached capacity with the one additional container and could not accept more debris. On 3/27/15, The Site Management Plan (SMP) for the South Brooklyn Marine Terminal (SBMT) was submitted to, and approved by, the Regional Director as this site was still being considered as an option for waste transfer, if needed. Allocco Recycling was no longer able to accept debris due to the type of waste (eg. debris mixed with household hazardous waste and putrescibles) and the fact that they closed at 2pm on Saturday. On 3/28/15, upon learning that the disposal locations were no longer viable, the Regional Director reached out to Waste Management and Action Environmental for their possible assistance and facilitated a call between HPD and Gateway (agency and their contractor performing the debris removal). Action Environmental after additional facilitation by both the Regional Director and EOC DEC Staff was the selected disposal facility due to: proximal location in the south Bronx, ability to accept all types of waste associated with the collapse, 24 hour/7day a week capabilities, and available capacity to receive the waste. It was a later learned that Action Environmental closes every Saturday at 6pm and reopens every Sunday at 12pm and as such the 12-16 trucks that will be loaded over the night will be stored at either Gateway or the truck rental facility until they can be brought to Action tomorrow at 12pm for disposal (which was approved by the Regional Director during the 4:30 Debris Task Force teleconference). Human remains searches are being performed at the

CON ED (Continued) **S117851663**

site via removal of approximately 10 cubic yards of soil at a time, spreading it on Second Avenue and then placement into the container/trailer. It has been confirmed that for the majority of the debris, this will be the sole method of searching for remains. As the debris removal is expected to encounter the first floor and basement of 121 Second Avenue tomorrow where two missing persons were last seen, OCME, PD and FDNY requested that a separate area be used to store these materials for secondary human remain searches at a later date. EM, DEC, EDC and DEP agreed that SBMT was the best location due to increased security, privacy, capacity and having an approved SMP. The expected amount of debris taken to this location is 25 twenty cubic yard containers and it will be stored for up to a month. DEP is mobilizing a crew tonight to SDMT to vacuum, clear and protect the basins in expectation this debris will begin to arrive tomorrow. NYCOEM is also working on acquiring additional bales of hay for additional basin protection at the site. As of 4pm today, 250 cubic yards have been removed from the site. Removal and search operations will continue throughout the night. DEC EOC Staff has sent an email request to DEP for more information on the air monitoring including results, methods used and agencies that reviewed and approved the results (eg-NYCDOH) and had not yet received a response and will pursue the issue further. The next Debris Task Force teleconference will be tomorrow, Sunday at 10:30am. Regional Director attended Debris Task Force teleconference(s) on Sunday 3/29/15.
3/30/15-Vought-Participated in the 10:30am and 4:30pm teleconferences by EM and with all agencies. Two additional bodies were recovered overnight and one has been identified and the second is in the process of being identified. Second Avenue will be now open to bus traffic and steps are being taken (including the installation of jersey barriers and construction fences) to faciliate pedestrian traffic on the east side of Second Avenue. Four buildings still have vacate orders and two of these orders lifted resulting in recoccupation as soon as today. To date 46 trailers and 10 containers have been removed from the site for a total of 3,515 cubic yards. Approximately half of the total debris has been removed to date and debris removal operations will be supervised by HPD and will continue throughout tonight. Since 3/28/15, all debris has been taken to Action Carting in the Bronx and no debris has been taken to South Brooklyn Marine Terminal. An insurance company for one of the property owners has requested to inspect the debris and as some of it has already been taken to Action Carting, the request is being reviewed by the NYC Law Department. NYCDOH is posting additional information regarding concerns to air quality on their website. To date no response has been received from the request to DEP placed by the DEC at the EOC on 3/27/15 regarding methods, parameters and reviewing agencies of air sampling. Debris removal operations may shut down tomorrow at 7pm and restart the next day due to union constraints associated with the FDNY Bureau of Fire Investigation and this will be further evaluated by EM. DEC Spills Staff will attend the 10:30am and 4:30pm calls tomrrow as per the Regional Director.
3/31/15-Vought-Participated in the 10:30am teleconference held by NYC EM and with all agencies. NYCT buses have been now allowed on Second Avenue and debris removal continued throughout the night. Debris removal today, however, has been slowed as the removal operations are reaching the point where the suspect gas line was located and as such NYPD and FDNY Fire Marshall are performing additional investigation. To date 75 trailers and 20 containers have been removed from the site

CON ED (Continued) **S117851663**

for a total of 4,000 cubic yards. DEP will also soon cut water service to the collapse sites as all remaining debris is at or below street level. Debris removal operations may be suspended this coming weekend due to a holiday weekend (Easter) and known services associated with a nearby church. As the bodies of the two missing persons were located, the focus is changing from a search and recovery mode to an evidence collection and investigation mode . Spotters are, however, still on-site examining debris as it is being removed for any evidence of further unknown human remains. Two vacate orders remain for adjacent buildings and one partial vacate order in in place for an adjacent commercial location. DEC Spills staff will participate in the 4:30 conference call from the field and include in tomorrow's daily update. 3/31/15-Vought-Vought and Regional Director called in and due to limited number of parties, NYC EM cancelled call. 4/1/15-Vought-Missed call at 10am and 4:30 interagency was cancelled. Received forwarded Debris Task Force call at 10:30am notes from RD that noted Debris Task Force Call Notes April 1, 2015 10:30 AM. FDNY and PD are still conducting investigations. 180 cubic yards of debris has been removed from the site as of 0900. 4095 cubic yards have been removed from the site to the transfer facility. Approximately 45 to 55 percent remains. Debris operations: Friday operations will be suspended at 1600. Saturday operations will be from 0700 to 1600. Sunday operations for the day will be suspended. HPD is still looking into service schedules of nearby houses of worship which may change operation times. There will be no 4:30 debris call this afternoon. 4/2/14-Vought-Participated in 10am inter-agency call. Debris removal continues at a slower rate as the site is being considered a crime scene and they are also reaching the basement levels of the building where the gas connections lead into the former buildings. Another lane has been opened for vehicle traffic on Second Avenue for a total of two open lanes so far (other lane is for NYCT buses). Reception Center is being moved from Tompkins Square Library to Community Board 3. Six businesses remain closed and only one more missing pet is being looked for. Two complete vacate orders are still in place (for 125 Second Avenue and 41 East 7th Street). To date approximately 4,400 cubic yards of debris have been removed and taken to Action Carting in the Bronx. Excavations of debris are now at basement levels in all three collapse sites and approximately 66% of the total debris has been removed. Vought sent an email request on 3/27 to DEP at the EOC for methods, parameters and reviewing agencies for air monitoring data and received no reply. Vought sent a request for an update today to DEP and received a reply from DEP (with cc to DEP Commissioner Licata) that all results are negative . Vought will follow up with Regional Director on whether more specific information is necessary with respect to the East Village air monitoring or whether the request can be used as an example during the next EM-DEC meeting to discuss general response planning and communcations. The frequency of the twice per day inter-agency calls has been decreasing due to scaling back of operations and restoration of services. Vought discussed daily updates with Regional Director and she noted that they were no longer necessary and as such Vought to send this update as last update to all. Vought will continue to participate in inter-agency calls as requested by Regional Director, who may also be continuing to participate in Debris Task Force calls. 4/2/15-Vought-Sent email to DEP Thomas Votta that Tom, Any updates on the below email regarding the air monitoring at the East Village

CON ED (Continued) **S117851663**

Building collapse? The DEC is eagerly awaiting the information as there was a recent high level discussion between our Regional Director and EM Commissioner Esposito regarding air monitoring (including methods, parameters measured and agencies involved) during large scale events in New York City.Thanks. DEP Votta replied that effrey, I'm not sure I'm on vacation, but let me see what I can find out..Ryan find out for Jeffrey what's going on with the air samples. See below. DEP Votta forwarded email to DEC Fanklyn Crowley who sent email to DEP Commissioner Licata and DEC Carlstein Lutchmedial that Any updates on air quality . DEC Lutchmedial replied that All results are negative . Vought sent email to Regional Director with cc to DEC Austin, DEC Lieblich and DEC Flint that Venetia, As you can see our request for an update on the methods, parameters and reviewing agencies for the air monitoring data resulted in a reply from DEP below solely that All results are negative with a copy to DEP Commissioner Licata. As per our last meeting with EM Commissioner Esposito we noted that we would like to enhance our communication with all agencies regarding these measurements during large scale events in NYC. Two questions for you: Should I follow up to get more specific details for the air monitoring for the East Village building collapse, or is all results are negative acceptable for this incident? Should we use this as an example of difficulties associated with this topic during our next EM/DEC meeting? Thanks. The Regional Director then sent an email to Commissioner Licata that Reaching out to you as I don't recognize your staff members' names below. We're looking to understand what parameters DEP measured at the collapse site and if there is data you could share with us. Our interest is purely 'academic' and we wouldn't distribute it any further. Response from DEP staff is that all results are negative, which is of course good news, but we'd appreciate the detail! Thanks. Regional Director then received reply from DEP Commissioner Licata that Monitoring for asbestos since day one. We also monitored for CO and VOCs on first night. We monitored during firefighting and debris handling. We just cut back yesterday to (I think 5 from 10) monitoring sites. See attached, but also trying to post daily to website. Vought added air monitoring data to D2. 4/3/15-Vought-Forwarded air monitoring data to DEC Austin, DEC John, DEC Lieblich and DEC Flint with cc to RD. Spoke with DEC Austin and this spill closed as non-petroleum spill and no involvement of Spills Unit besides Vought on debris issues. 4/6/15-Vought-Continued to participate in 10am inter-agency calls. During call today following was noted: investigation by FDNY Fire Marshall and NYPD has begun as excavation has reached location of suspect gas line that caused explosin and collapse. Two lanes are still open on Second Avenue and site work will continue till 4pm. Electric service being restored to 125 Second Avenue and residents are being escorted for discrete time periods into 125 Second Avenue and 41 East 7th street so that they may have access to their personal possessions. Reception Center will be open at noon, 7 households are still in hotels and to date 93 tractor trailers of debris have been removed for a total of 4800 cubic yards. 4/7/15-Vought-10am inter-agency call. FNDY Fire Marshalls doing pressure check on gas lines with Con Edison which must occur before any further debris removal due to proximity of debris removal operations to gas lines. No other site activity occurred as such other than door repair to 125 Second Avenue and 41 East 7th Street. Reception Center will be scaled down after approval of Mayor's Office is provided and 5 households still in hotels. 4/8/15-Vought-Sent email request to RD that due to

CON ED (Continued) **S117851663**

upcoming vacation and reducing scope of work related to investigation and reducing debris, that Vought no longer participate in 10am calls and RD replied with approval to no longer participate and also to send email to EM Planning Section that DEC will no longer be on 10am inter-agency calls and they could reach out to her for any additional information."

Remarks: "DEC Regional Director and RSE received notification as part of an All Call from NYC Emergency Management(EM) that three buildings collapsed due to an explosion and fire. DEC Staff (Vought) requested to attend EM EOC as per Regional Director to faciliate debris disposal indoor air concerns and any potential petroleum issues."

All Materials:

Site ID:	506061
Operable Unit ID:	1255374
Operable Unit:	01
Material ID:	2258108
Material Code:	0047A
Material Name:	debris
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004761243
Facility Status:	Not reported
Location Address 1:	119 2ND AVE & 7TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10035
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004761243
Mailing Name:	CON ED
Mailing Contact:	THERESA BURKARD
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602262

AS733 **SELF RELIANCE NY FEDL CR UN** **NY AST** **U004048262**
East **108 SECOND AVENUE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.231 mi.
1218 ft. **Site 4 of 8 in cluster AS**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-090182
Program Type:	PBS
UTM X:	585469.16695
UTM Y:	4509019.03330
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	2181
Affiliation Type:	Facility Owner
Company Name:	SELF RELIANCE NY FEDL CR UN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	108 SECOND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 473-7310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2181
Affiliation Type:	Mail Contact
Company Name:	SELF RELIANCE NY FEDL CR UN
Contact Type:	Not reported
Contact Name:	SUPER FACILITY MANAGER
Address1:	108 SECOND AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 473-7310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2181
Affiliation Type:	Facility Operator
Company Name:	SELF RELIANCE NY FEDL CR UN
Contact Type:	Not reported
Contact Name:	SELF RELIANCE NY FEDL CR UN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

SELF RELIANCE NY FEDL CR UN (Continued) **U004048262**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 473-7310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2181
Affiliation Type:	Emergency Contact
Company Name:	SELF RELIANCE NY FEDL CR UN
Contact Type:	Not reported
Contact Name:	COASTAL PETROLEUM TANK CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-4263
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	3463
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B05 - Tank External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AW734 **NEW YORK UNIVERSITY - BROWN BUILDING** **RCRA-LQG** **1000136879**
NW **100 WASHINGTON SQUARE EAST** **ICIS** **NYD981566607**
1/8-1/4 **NEW YORK, NY 10012** **FINDS**
0.231 mi. **ECHO**
1219 ft. **Site 7 of 7 in cluster AW** **NJ MANIFEST**
NY MANIFEST

Relative:
Lower

Actual:
32 ft.

RCRA-LQG:

Date form received by agency:	02/25/2016
Facility name:	NEW YORK UNIVERSITY - BROWN BUILDING
Facility address:	100 WASHINGTON SQUARE EAST NEW YORK, NY 10012
EPA ID:	NYD981566607
Mailing address:	ASTOR PLACE 6TH FLOOR, EH&S NEW YORK, NY 10003
Contact:	ZACK KORENSTEIN
Contact address:	ASTOR PLACE 6TH FLOOR, EH&S NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-992-8276
Contact email:	ZACK.KORENSTEIN@NYU.EDU
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	WASHINGTON SQUARE SOUTH NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1950
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK UNIVERSITY
Owner/operator address:	WASHINGTON SQUARE SOUTH NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE,

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P003
. Waste name: 2-PROPENAL (OR) ACROLEIN

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U170
. Waste name: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

Historical Generators:
Date form received by agency: 03/06/2014
Site name: NEW YORK UNIVERSITY - BROWN BUILDING
Classification: Large Quantity Generator

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P010
. Waste name: ARSENIC ACID H3ASO4

. Waste code: P014
. Waste name: BENZENETHIOL (OR) THIOPHENOL

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P048
. Waste name: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

. Waste code: P077
. Waste name: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Date form received by agency: 07/29/2013
Site name: NEW YORK UNIVERSITY - BROWN BUILDING
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P005
. Waste name: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

. Waste code: P008
. Waste name: 4-AMINOPYRIDINE (OR) 4-PYRIDINAMINE

. Waste code: P010
. Waste name: ARSENIC ACID H3ASO4

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P077
. Waste name: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U004
. Waste name: ACETOPHENONE (OR) ETHANONE, 1-PHENYL-

. Waste code: U007
. Waste name: 2-PROPENAMIDE (OR) ACRYLAMIDE

. Waste code: U012
. Waste name: ANILINE (I,T) (OR) BENZENAMINE (I,T)

. Waste code: U019
. Waste name: BENZENE (I,T)

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U056
. Waste name: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

. Waste code: U067
. Waste name: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U133
. Waste name: HYDRAZINE (R,T)

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U151
. Waste name: MERCURY

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

. Waste code: U404
. Waste name: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Date form received by agency: 02/14/2012
Site name: NEW YORK UNIVERSITY - BROWN BUILDING
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: LABP
. Waste name: LAB PACK

. Waste code: P005
. Waste name: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

. Waste code: P010
. Waste name: ARSENIC ACID H3ASO4

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Date form received by agency: 02/11/2010
Site name: NEW YORK UNIVERSITY - BROWN BUILDING
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D026
. Waste name: CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P014
. Waste name: BENZENETHIOL (OR) THIOPHENOL

. Waste code: P015

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste name: BERYLLIUM

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Date form received by agency: 12/01/2009
Site name: NYU - BROWN BUILDING
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D037
. Waste name: PENTACHLOROPHENOL

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F022
. Waste name: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENES UNDER ALKALINE CONDITIONS.

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

Date form received by agency: 02/22/2008
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D013
. Waste name: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: B004
. Waste name: B004

Date form received by agency: 01/01/2007
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 02/01/2006
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D026
. Waste name: CRESOL

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE,

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P005
. Waste name: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: P029
. Waste name: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P077
. Waste name: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P104
. Waste name: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: P107
. Waste name: STRONTIUM SULFIDE SRS

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: U007
. Waste name: 2-PROPENAMIDE (OR) ACRYLAMIDE

. Waste code: U009
. Waste name: 2-PROPENENITRILE (OR) ACRYLONITRILE

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U067
. Waste name: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

. Waste code: U076
. Waste name: ETHANE, 1,1-DICHLORO- (OR) ETHYLIDENE DICHLORIDE

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U103
. Waste name: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

. Waste code: U108
. Waste name: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

. Waste code: U117
. Waste name: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U133
. Waste name: HYDRAZINE (R,T)

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

. Waste code: U144
. Waste name: ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE

. Waste code: U169
. Waste name: BENZENE, NITRO- (OR) NITROBENZENE (I,T)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U196
. Waste name: PYRIDINE

. Waste code: U209
. Waste name: 1,1,2,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,2,2-TETRACHLORO-

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: U211
. Waste name: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

. Waste code: U213
. Waste name: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

. Waste code: U218
. Waste name: ETHANETHIOAMIDE (OR) THIOACETAMIDE

Date form received by agency: 01/31/2006
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 02/11/2004
Site name: NEW YORK UNIVERSITY- BROWN BUILDING
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste name: METHYL ETHYL KETONE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P087
. Waste name: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

. Waste code: P093
. Waste name: PHENYLTHIOUREA (OR) THIOUREA, PHENYL-

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U007
. Waste name: 2-PROPENAMIDE (OR) ACRYLAMIDE

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U133
. Waste name: HYDRAZINE (R,T)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U189
. Waste name: PHOSPHORUS SULFIDE (R) (OR) SULFUR PHOSPHIDE (R)

. Waste code: U211
. Waste name: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

. Waste code: U219
. Waste name: THIOUREA

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U236
. Waste name: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO -4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

. Waste code: B004
. Waste name: B004

Date form received by agency: 02/28/2002
Site name: NEW YORK UNIVERSITY - BROWN BUILDING
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 02/26/1998
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 02/28/1996
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 03/18/1994
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 02/27/1992
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

Date form received by agency: 11/19/1986
Site name: NEW YORK UNIVERSITY
Classification: Large Quantity Generator

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Amount (Lbs): 25752

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 10543

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.
Amount (Lbs): 64

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 2856

Waste code: D008
Waste name: LEAD
Amount (Lbs): 3425

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 2876

Waste code: D011
Waste name: SILVER
Amount (Lbs): 2905

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 13971

Waste code: D022
Waste name: CHLOROFORM
Amount (Lbs): 14020

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 13971

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

SPENT SOLVENT MIXTURES.
Amount (Lbs): 14020

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 16145

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 14487

Waste code: LABP
Waste name: LAB PACK
Amount (Lbs): 2905

Waste code: P003
Waste name: ACROLEIN
Amount (Lbs): 15

Waste code: P075
Waste name: NICOTINE, & SALTS
Amount (Lbs): 15

Waste code: P087
Waste name: OSMIUM OXIDE OSO4, (T-4)-
Amount (Lbs): 15

Waste code: U002
Waste name: ACETONE (I)
Amount (Lbs): 13971

Waste code: U019
Waste name: BENZENE (I,T)
Amount (Lbs): 13971

Waste code: U031
Waste name: 1-BUTANOL (I)
Amount (Lbs): 13971

Waste code: U170
Waste name: P-NITROPHENOL
Amount (Lbs): 49

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: TSD IS-Container Use and Management
- Date violation determined: 03/20/2014
- Date achieved compliance: 03/20/2014
- Violation lead agency: EPA
  - Enforcement action: VERBAL INFORMAL
  - Enforcement action date: 03/20/2014
  - Enf. disposition status: Action Satisfied (Case Closed)
  - Enf. disp. status date: 03/20/2014
  - Enforcement lead agency: EPA
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 03/20/2014
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: TSD IS-Container Use and Management
- Date achieved compliance: 03/20/2014
- Evaluation lead agency: EPA

- Evaluation date: 09/24/2009
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: EPA

- Evaluation date: 05/21/2001
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: EPA

- Evaluation date: 11/09/1993
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: EPA Contractor/Grantee

ICIS:
- Enforcement Action ID: 02-2006-0882
- FRS ID: 110000882493
- Action Name: NYU Phase V
- Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
- Facility Address: 100 WASHINGTON SQUARE
  NEW YORK, NY 10012
- Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
- Facility County: NEW YORK
- Program System Acronym: RCRAINFO
- Enforcement Action Forum Desc: Administrative - Formal
- EA Type Code: 3008A
- Facility SIC Code: Not reported
- Federal Facility ID: Not reported
- Latitude in Decimal Degrees: 40.73021
- Longitude in Decimal Degrees: -73.996003
- Permit Type Desc: Not reported

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Program System Acronym: NYD981566607
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-2006-0856
FRS ID: 110000882493
Action Name: New York University
Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Facility Address: 100 WASHINGTON SQUARE
NEW YORK, NY 10012
Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
Facility County: NEW YORK
Program System Acronym: RCRAINFO
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 3008A
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.73021
Longitude in Decimal Degrees: -73.996003
Permit Type Desc: Not reported
Program System Acronym: NYD981566607
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Address: 100 WASHINGTON SQUARE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Address: 100 WASHINGTON SQUARE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Address: 100 WASHINGTON SQUARE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Address: 100 WASHINGTON SQUARE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Address: 100 WASHINGTON SQUARE
Tribal Indicator: N
Fed Facility: No

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NEW YORK UNIVERSITY - BROWN BUILDING
Address: 100 WASHINGTON SQUARE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

FINDS:

Registry ID: 110000882493

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000136879
Registry ID: 110000882493
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000882493

NJ MANIFEST:
EPA Id: NYD981566607
Mail Address: Not reported
Mail City/State/Zip: Not reported
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: 000000

Manifest:
Manifest Number: 003756468JJK
EPA ID: NYD981566607
Date Shipped: 03/07/2008
TSDF EPA ID: NJD002200046

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/07/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/17/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D037
Hand Code:	H141
Quantity:	1 P

Manifest Number:	003756046JJK
EPA ID:	NYD981566607
Date Shipped:	02/13/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Date Trans1 Transported Waste:	02/13/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/19/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F027
Hand Code:	H141
Quantity:	91 P

Manifest Number:	NJA4083353
EPA ID:	NYD981566607
Date Shipped:	06/25/2004
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/25/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Date TSDF Received Waste:	07/09/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08230425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	003756447JJK
EPA ID:	NYD981566607
Date Shipped:	04/30/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/30/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/02/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 20 P

NY MANIFEST:
Country: USA
EPA ID: NYD981566607
Facility Status: Not reported
Location Address 1: 100 WASHINGTON SQUARE EAST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD981566607
Mailing Name: NEW YORK UNIVERSITY - BROWN BLDG
Mailing Contact: STEPHANIE KUNG
Mailing Address 1: 740 BROADWAY - 6th FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2129981439

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2017
Trans1 State ID: MAC300016672
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2017
Trans1 Recv Date: 11/29/2017
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/01/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981566607
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: 011104877FLE
Import Indicator: N
Export Indicator: N

NEW YORK UNIVERSITY - BROWN BUILDING (Continued) **1000136879**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	85
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
4386 additional NY_MANIFEST: record(s) in the EDR Site Report.

AN735 **A.B. IBIBASSI REALTY CO** **NY AST** **A100359428**
ENE **26 ST MARKS PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.231 mi.
1220 ft. **Site 14 of 16 in cluster AN**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611722
Program Type:	PBS
UTM X:	585408.27251
UTM Y:	4509162.11105
Expiration Date:	07/24/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	458947
Affiliation Type:	Facility Owner
Company Name:	A.B. ILIBASSI REALTY CO.
Contact Type:	MANAGER
Contact Name:	THOMAS J CARACCIO
Address1:	P.O. BOX 3557
Address2:	Not reported
City:	NEW HYDE PARK

A.B. IBIBASSI REALTY CO (Continued) **A100359428**

State: NY
Zip Code: 11040
Country Code: 001
Phone: (718) 343-1336
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-06-15

Site Id: 458947
Affiliation Type: Mail Contact
Company Name: A.B. ILIBASSI REALTY CO.
Contact Type: Not reported
Contact Name: THOMAS J CARACCIO
Address1: PO BOX 3557
Address2: Not reported
City: NEW HYDE PARK
State: NY
Zip Code: 11040
Country Code: 001
Phone: (718) 343-1337
EMail: TOMC@VIKMGT.COM
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-12-13

Site Id: 458947
Affiliation Type: Facility Operator
Company Name: A.B. IBIBASSI REALTY CO
Contact Type: Not reported
Contact Name: LENIN ENAMORADO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 529-1614
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2011-12-13

Site Id: 458947
Affiliation Type: Emergency Contact
Company Name: A.B. ILIBASSI REALTY CO.
Contact Type: Not reported
Contact Name: LENIN ENAMORADO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 529-1614
EMail: Not reported
Fax Number: Not reported

A.B. IBIBASSI REALTY CO (Continued) **A100359428**

Modified By: MRBARROW
Date Last Modified: 2016-06-15

Tank Info:

Tank Number: 001
Tank Id: 241969
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
B05 - Tank External Protection - Jacketed
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1953
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MRBARROW
Last Modified: 04/14/2017
Material Name: #2 fuel oil (on-site consumption)

AQ736 **ROADWAY/PARKING LOT** **NY LTANKS** **S107523245**
West **110 BLEECKER ST** **N/A**
1/8-1/4 **MANHATTAN, NY**
0.231 mi.
1221 ft. **Site 3 of 3 in cluster AQ**

Relative:
Lower

Actual:
31 ft.

LTANKS:
Facility ID: 0511206
Site ID: 357309
Closed Date: 2006-01-24
Spill Number: 0511206
Spill Date: 2005-12-26
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: D3

ROADWAY/PARKING LOT (Continued) **S107523245**

Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-12-26
CID:	409
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-26
Spill Record Last Update:	2006-01-24
Spiller Name:	EDISON TORRES
Spiller Company:	WASHINGTON SOUTH APARTMEN
Spiller Address:	110 BLEECKER ST
Spiller County:	001
Spiller Contact:	SCOTT SARNELL
Spiller Phone:	(347) 203-6886
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	307336
DEC Memo:	"Rahman responded to the site. Duplicate to spill #0511209 12/27/05-Sharif// I responded to the site around 5:00 PM yesterday.There is a mobile boiler unit operated by Easco,(718)378-3000.The tank is AST,4000 gallons.The gauge on the oil line that goes to boiler broke and spilled unidentified amt. of #2 oil on the street that went to two Con Edison manhole.NYC FD responded to the site and put speedy dry on the street and side walk. Easco crews were at the site to do the residual clean up."
Remarks:	"OUTDOOR MOBILE TANK. SHUT DOWN TANK. SOME LEAKED INTO CON ED TRANSFORMER. 80 GAL SPILLED OUTSIDE. CLEAN UP IN PROCESS AND PUMPING INTO DRUMS WITR SPEEDY DRY."

All Materials:

Site ID:	357309
Operable Unit ID:	1114586
Operable Unit:	01
Material ID:	2104653
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	80.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BB737 **NYCT - 2ND AVE STATION F LINE** **RCRA NonGen / NLR** **1004761882**
SSE **2ND AVE & HOUSTON ST COR** **NY MANIFEST** **NYR000091355**
1/8-1/4 **NEW YORK, NY 10002**
0.231 mi.
1222 ft. **Site 1 of 2 in cluster BB**

Relative:
Lower

Actual:
41 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCT - 2ND AVE STATION F LINE
Facility address:	2ND AVE & HOUSTON ST COR NEW YORK, NY 10002
EPA ID:	NYR000091355
Mailing address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact:	JAMES CRANDALL
Contact address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	718-243-4581
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	718-243-4581
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	718-243-4581
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

NYCT - 2ND AVE STATION F LINE (Continued) **1004761882**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYCT - 2ND AVE STATION F LINE
Classification: Not a generator, verified

Date form received by agency: 11/15/2000
Site name: NYCT - 2ND AVE STATION F LINE
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000091355
Facility Status: Not reported
Location Address 1: 2ND AVE 7 HUDSON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000091355
Mailing Name: NYCTA
Mailing Contact: HECTOR NIEVES
Mailing Address 1: 370 JAY ST RM 819
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7182434227

NY MANIFEST:
Document ID: NJA3179090
Manifest Status: Not reported
seq: 01

NYCT - 2ND AVE STATION F LINE (Continued) **1004761882**

Year:	2000
Trans1 State ID:	H10376
Trans2 State ID:	H10376
Generator Ship Date:	11/27/2000
Trans1 Recv Date:	11/27/2000
Trans2 Recv Date:	11/28/2000
TSD Site Recv Date:	11/28/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000091355
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	NJD003812047
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00237
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AV738 **CON EDISON SERVICE BOX: 1361** **RCRA NonGen / NLR** **1016966823**
North **61 E 8TH ST** **NY MANIFEST** **NYP004396644**
1/8-1/4 **NEW YORK, NY 10003**
0.232 mi.
1224 ft. **Site 11 of 15 in cluster AV**

Relative: **Lower**
Actual: **37 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/22/2013
Facility name:	CON EDISON SERVICE BOX: 1361
Facility address:	61 E 8TH ST NEW YORK, NY 10003
EPA ID:	NYP004396644
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING

CON EDISON SERVICE BOX: 1361 (Continued) **1016966823**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/22/2013
Site name: CON EDISON SERVICE BOX: 1361
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004396644
Facility Status: Not reported
Location Address 1: 61 E 8TH ST
Code: BP
Location Address 2: SB1361
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004396644
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON SERVICE BOX: 1361 (Continued) **1016966823**

Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/22/2013
Trans1 Recv Date:	11/22/2013
Trans2 Recv Date:	11/25/2013
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004396644
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237694GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AL739 **CON EDISON** **RCRA NonGen / NLR** **1019902502**
SE **34 E 1ST ST** **FINDS** **NYP004774543**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.232 mi.
1225 ft. **Site 19 of 24 in cluster AL**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/27/2015
Facility name:	CON EDISON
Facility address:	34 E 1ST ST NEW YORK, NY 10003
EPA ID:	NYP004774543
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/27/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069688056

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019902502**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019902502
Registry ID:	110069688056
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069688056

AL740 **CON EDISON** **NJ MANIFEST** **S120671052**
SE **34 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.232 mi.
1225 ft. **Site 20 of 24 in cluster AL**

Relative: **Lower**
Actual: **39 ft.**

NJ MANIFEST:

EPA Id:	NYP004774543
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611022GBF
EPA ID:	NYP004774543
Date Shipped:	4/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON (Continued) **S120671052**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL741 **CON EDISON** **NY MANIFEST** **S119074824**
SE **34 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.232 mi.
1225 ft. **Site 21 of 24 in cluster AL**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004774543
Facility Status:	Not reported
Location Address 1:	F/O 36 E 1ST ST
Code:	BP
Location Address 2:	SB 508
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004774543
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047

CON EDISON (Continued) **S119074824**

Generator Ship Date:	04/27/2015
Trans1 Recv Date:	04/27/2015
Trans2 Recv Date:	04/28/2015
TSD Site Recv Date:	04/28/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004774543
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611022GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AU742 **598 BROADWAY REALTY** **NY AST** **A100433661**
SW **598 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.233 mi.
1229 ft. **Site 5 of 11 in cluster AU**

Relative:
Lower

Actual:
40 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612666
Program Type:	PBS

598 BROADWAY REALTY (Continued) **A100433661**

UTM X: 584714.23436
UTM Y: 4508725.36875
Expiration Date: 04/01/2021
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 538559
Affiliation Type: Facility Owner
Company Name: 598 BROADWAY REALTY ASSOC. INC.
Contact Type: VICE PRESIDENT
Contact Name: ZVI MOSERY
Address1: P.O. BOX 514
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 334-0139
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-03-19

Site Id: 538559
Affiliation Type: Emergency Contact
Company Name: 598 BROADWAY REALTY ASSOC. INC.
Contact Type: Not reported
Contact Name: ZVI MOSERY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 334-0139
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-03-19

Site Id: 538559
Affiliation Type: Mail Contact
Company Name: 598 BROADWAY REALTY ASSOC. INC.
Contact Type: Not reported
Contact Name: ZVI MOSERY
Address1: PO BOX 514
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 334-0139
EMail: 598BROADWAYREALTY@GMAIL.COM
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-03-19

Site Id: 538559

598 BROADWAY REALTY (Continued) **A100433661**

Affiliation Type:	Facility Operator
Company Name:	598 BROADWAY REALTY
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 334-0139
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-19

Tank Info:

Tank Number:	001
Tank Id:	266595

Equipment Records:

F00 - Pipe External Protection - None
H08 - Tank Leak Detection - Weep holes in Vaults with no access for inspection
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
E00 - Piping Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
K00 - Spill Prevention - None
A02 - Tank Internal Protection - Rubber Liner
I05 - Overfill - Vent Whistle
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/2001
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	03/19/2018
Material Name:	#2 fuel oil (on-site consumption)

AL743 **CON EDISON SERVICE BOX: 516** **RCRA NonGen / NLR** **1016969410**
SSE **29 E 1ST ST** **NY MANIFEST** **NYP004430732**
1/8-1/4 **NEW YORK, NY 10003**
0.233 mi.
1232 ft. **Site 22 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/28/2014
Facility name: CON EDISON SERVICE BOX: 516
Facility address: 29 E 1ST ST
NEW YORK, NY 10003
EPA ID: NYP004430732
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/31/2014
Site name: CON EDISON SERVICE BOX: 516
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004430732
Facility Status: Not reported
Location Address 1: 29 E 1ST ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003

CON EDISON SERVICE BOX: 516 (Continued) **1016969410**

Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004430732
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2014
Trans1 Recv Date:	01/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004430732
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329235GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON SERVICE BOX: 516 (Continued) **1016969410**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BA744 **CON EDISON SERVICE BOX: 869** **RCRA NonGen / NLR** **1016969142**
ESE **102 E 4TH ST** **NY MANIFEST** **NYP004427910**
1/8-1/4 **NEW YORK, NY 10003**
0.234 mi.
1233 ft. **Site 2 of 16 in cluster BA**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/2014
Facility name:	CON EDISON SERVICE BOX: 869
Facility address:	102 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004427910
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/28/2014
Site name:	CON EDISON SERVICE BOX: 869
Classification:	Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 869 (Continued) **1016969142**

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004856371
Facility Status: Not reported
Location Address 1: 102 E 4TH ST
Code: BP
Location Address 2: SB 869
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004856371
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/19/2015
Trans1 Recv Date: 10/19/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004856371
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014085708JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110

CON EDISON SERVICE BOX: 869 (Continued) **1016969142**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

Country:	USA
EPA ID:	NYP004427910
Facility Status:	Not reported
Location Address 1:	102 E 4TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004427910
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/28/2014
Trans1 Recv Date:	01/28/2014

CON EDISON SERVICE BOX: 869 (Continued) **1016969142**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004427910
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329388GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AX745 **CON EDISON** **NY MANIFEST** **S117537669**
SE **53 E 2ND ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.234 mi.
1233 ft. **Site 4 of 9 in cluster AX**

Relative: NY MANIFEST:
Lower

Actual: Country:	USA
38 ft. EPA ID:	NYP004702536
Facility Status:	Not reported
Location Address 1:	53 E 2ND ST
Code:	BP
Location Address 2:	SB 553
Total Tanks:	Not reported

CON EDISON (Continued) **S117537669**

Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004702536
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/04/2014
Trans1 Recv Date:	12/04/2014
Trans2 Recv Date:	12/04/2014
TSD Site Recv Date:	12/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004702536
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002609957GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S117537669**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BC746 **KMART CORPORATION #7777** **RCRA-SQG** **1001124863**
NNE **770 BROADWAY** **NY MANIFEST** **NYR000031930**
1/8-1/4 **NEW YORK, NY 10003**
0.234 mi.
1236 ft. **Site 1 of 5 in cluster BC**

Relative:
Lower

Actual:
39 ft.

RCRA-SQG:

Date form received by agency:	03/25/2008
Facility name:	KMART CORPORATION #7777
Facility address:	770 BROADWAY NEW YORK, NY 10003
EPA ID:	NYR000031930
Mailing address:	BEVERLY RD - B5 348A HOFFMAN ESTATES, IL 60179
Contact:	DAWN A JESS
Contact address:	BEVERLY RD - B5 348A HOFFMAN ESTATES, IL 60179
Contact country:	US
Contact telephone:	847-286-8616
Contact email:	DJESS1@SEARSHC.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	770 BROADWAY CO LLC
Owner/operator address:	7TH AVE NEW YORK, NY 10019
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/03/1995
Owner/Op end date:	Not reported
Owner/operator name:	KMART CORPORATION

KMART CORPORATION #7777 (Continued) **1001124863**

Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/03/1995
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Historical Generators:
Date form received by agency: 03/24/2008
Site name: KMART CORPORATION #7777
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: CUSHMAN & WAKEFIELD CO
Classification: Not a generator, verified

Date form received by agency: 12/13/1996
Site name: CUSHMAN & WAKEFIELD CO
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 11/13/1996
Site name: CUSHMAN & WAKEFIELD CO
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D002

KMART CORPORATION #7777 (Continued) **1001124863**

. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000031930
Facility Status: Not reported
Location Address 1: 770 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000031930
Mailing Name: KMART CORPORATION #7777
Mailing Contact: TOM COSTELLO
Mailing Address 1: 770 BROADWAY
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10285
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2126403911

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2017
Trans1 State ID: PAD982661381
Trans2 State ID: NJD071629976
Generator Ship Date: 09/14/2017
Trans1 Recv Date: 09/14/2017
Trans2 Recv Date: 09/18/2017
TSD Site Recv Date: 09/19/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000031930
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: RID040098352
TSDF ID 2: Not reported
Manifest Tracking Number: 010767733FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

KMART CORPORATION #7777 (Continued) **1001124863**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	24
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
215 additional NY_MANIFEST: record(s) in the EDR Site Report.

BC747 **AOL, INC.** **NY AST** **A100349549**
NNE **770 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.234 mi.
1236 ft. **Site 2 of 5 in cluster BC**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610143
Program Type:	PBS
UTM X:	585127.35167
UTM Y:	4509391.22480
Expiration Date:	07/03/2018
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	360733
Affiliation Type:	Facility Owner
Company Name:	770 BROADWAY OWNER LLC
Contact Type:	V.P OPERATIONS
Contact Name:	RICHARD B WALLACE
Address1:	770 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 894-7000

AOL, INC. (Continued) **A100349549**

EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-19

Site Id: 360733
Affiliation Type: Mail Contact
Company Name: VORNADO OFFICE MGMT. LLC
Contact Type: Not reported
Contact Name: DANIEL RUANOVA
Address1: 770 BROADWAY
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 982-8240
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-19

Site Id: 360733
Affiliation Type: Facility Operator
Company Name: 770 BROADWAY
Contact Type: Not reported
Contact Name: BRIAN KOCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 982-8240
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-19

Site Id: 360733
Affiliation Type: Emergency Contact
Company Name: 770 BROADWAY OWNER LLC
Contact Type: Not reported
Contact Name: DANIEL RUANOVA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 982-8240
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-19

AOL, INC. (Continued) **A100349549**

Tank Info:

Tank Number:	001
Tank Id:	210398
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/15/1975
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	T1
Tank Id:	233264
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E12 - Piping Secondary Containment - Double-Walled (AG only)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I05 - Overfill - Vent Whistle
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron

AOL, INC. (Continued) **A100349549**

Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/2009
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: diesel

Affiliation Records:
Site Id: 425676
Affiliation Type: Mail Contact
Company Name: AOL , INC
Contact Type: Not reported
Contact Name: LARRY SADLER
Address1: 770 BROADWAY
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 206-4452
EMail: LARRY.SADLER@TEAMAOL.COM
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-13

Site Id: 425676
Affiliation Type: Facility Operator
Company Name: AOL, INC.
Contact Type: Not reported
Contact Name: LARRY SADLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 206-4452
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2010-03-09

Site Id: 425676
Affiliation Type: Emergency Contact
Company Name: AOL , INC
Contact Type: Not reported
Contact Name: SECURITY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

AOL, INC. (Continued) **A100349549**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 982-8240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-03-09

Site Id:	425676
Affiliation Type:	Facility Owner
Company Name:	AOL , INC
Contact Type:	VP, CORPORATE SERVICES
Contact Name:	ALAN NIELSON
Address1:	22000 AOL WAY
Address2:	Not reported
City:	DULLES
State:	VA
Zip Code:	20166
Country Code:	001
Phone:	(703) 265-3845
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-13

Tank Info:

Tank Number:	001
Tank Id:	210398
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location:	6
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/15/1975
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

AOL, INC. (Continued) **A100349549**

Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: T1
Tank Id: 233264
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E12 - Piping Secondary Containment - Double-Walled (AG only)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I05 - Overfill - Vent Whistle
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/2009
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: diesel

BC748 **770 BROADWAY COMPANY LLC** **RCRA NonGen / NLR** **1001485600**
NNE **770 BROADWAY** **FINDS** **NYR000070060**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.234 mi.
1236 ft. **Site 3 of 5 in cluster BC**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/18/2017
Facility name: 770 BROADWAY COMPANY LLC
Facility address: 770 BROADWAY
NEW YORK, NY 10003
EPA ID: NYR000070060
Mailing address: BROADWAY
NEW YORK, NY 10003
Contact: DANIEL RUANOVA
Contact address: BROADWAY
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-982-8240

770 BROADWAY COMPANY LLC (Continued) **1001485600**

Contact email: DRUANOVA@VNO.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: 770 BROADWAY COMPANY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/23/1998
Owner/Op end date: Not reported

Owner/operator name: 770 BROADWAY COMPANY LLC
Owner/operator address: BROADWAY
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-228-9861
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/23/1998
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 12/02/2015
Site name: 770 BROADWAY COMPANY LLC
Classification: Conditionally Exempt Small Quantity Generator

770 BROADWAY COMPANY LLC (Continued) **1001485600**

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 01/01/2007
Site name: 770 BROADWAY CO LLC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: 770 BROADWAY CO LLC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/12/1999
Site name: 770 BROADWAY CO LLC
Classification: Small Quantity Generator

. Waste code: X001
. Waste name: WASTE OILS

Violation Status: No violations found

FINDS:

Registry ID: 110004530053

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001485600
Registry ID: 110004530053
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004530053

AT749 **CON EDISON** **NY MANIFEST** **S118463742**
ESE **106 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.235 mi.
1239 ft. **Site 10 of 11 in cluster AT**

Relative: **Lower**
Actual: **34 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004856389
Facility Status: Not reported
Location Address 1: 106 E 4TH ST
Code: BP
Location Address 2: SB 890
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003

CON EDISON (Continued) **S118463742**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004856389
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/20/2015
Trans1 Recv Date: 10/20/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004856389
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014085709JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S118463742**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AT750 **CON EDISON** **NY MANIFEST** **S117066511**
ESE **106 E 4 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.235 mi.
1239 ft. **Site 11 of 11 in cluster AT**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591681
Facility Status:	Not reported
Location Address 1:	106 E 4 ST
Code:	BP
Location Address 2:	SB 870
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591681
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591681
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117066511**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423967GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AO751 **CON EDISON** **RCRA NonGen / NLR** **1018277780**
South **269 BOWERY** **FINDS** **NYP004725180**
1/8-1/4 **NEW YORK, NY 10002** **ECHO**
0.235 mi.
1241 ft. **Site 10 of 13 in cluster AO**

Relative: **Higher**
Actual: **42 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/04/2015
Facility name:	CON EDISON
Facility address:	269 BOWERY NEW YORK, NY 10002
EPA ID:	NYP004725180
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON (Continued) **1018277780**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/04/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067693954

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277780
Registry ID: 110067693954
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067693954

AO752 **CON EDISON** **NJ MANIFEST** **S120666702**
South **269 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.235 mi.
1241 ft. **Site 11 of 13 in cluster AO**

Relative:
Higher

Actual:
42 ft.

NJ MANIFEST:

EPA Id:	NYP004725180
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610344GBF
EPA ID:	NYP004725180
Date Shipped:	2/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120666702**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AO753 **CON EDISON** **NY MANIFEST** **S117739404**
South **269 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.235 mi.
1241 ft. **Site 12 of 13 in cluster AO**

Relative:
Higher

Actual:
42 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004725180
Facility Status:	Not reported
Location Address 1:	269 BOWERY
Code:	BP
Location Address 2:	SB26796
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004725180
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2015
Trans1 Recv Date:	02/04/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004725180
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117739404**

Manifest Tracking Number:	002610344GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AR754 **CON ED** **NY MANIFEST** **S118463706**
North **58 E 8TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.236 mi.
1244 ft. **Site 5 of 8 in cluster AR**

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004855843
Facility Status:	Not reported
Location Address 1:	58 E 8TH ST
Code:	BP
Location Address 2:	SB 1364
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004855843
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING

CON ED (Continued) **S118463706**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855843
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612635GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON ED (Continued) **S118463706**

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AN755 **30 ST MARKS PLACE** **NY AST** **U003384351**
ENE **30 ST MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.236 mi.
1248 ft. **Site 15 of 16 in cluster AN**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-091456
Program Type:	PBS
UTM X:	585482.13115
UTM Y:	4509147.29907
Expiration Date:	03/24/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2296
Affiliation Type:	Facility Owner
Company Name:	ST MARKS ASSETS C/O AJ CLARKE MGMT
Contact Type:	AGENT
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-01-04

Site Id:	2296
Affiliation Type:	Mail Contact
Company Name:	ST MARKS ASSETS C/O AJ CLARKE MGMT R.E. CORP
Contact Type:	Not reported
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	SDENARDO@AJCLARKENYC.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-05-01

Site Id:	2296
Affiliation Type:	Facility Operator

30 ST MARKS PLACE (Continued) **U003384351**

Company Name:	30 ST MARKS PLACE
Contact Type:	Not reported
Contact Name:	VICTOR IVEZAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 903-9630
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-05-01

Site Id:	2296
Affiliation Type:	Emergency Contact
Company Name:	ST MARKS ASSETS C/O AJ CLARKE MGMT
Contact Type:	Not reported
Contact Name:	VICTOR IVEZAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 951-6433
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-05-01

Tank Info:

Tank Number:	001
Tank Id:	3621
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

30 ST MARKS PLACE (Continued) **U003384351**

Install Date:	01/01/1958
Capacity Gallons:	3000
Tightness Test Method:	21
Date Test:	02/18/2010
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	05/01/2017
Material Name:	#2 fuel oil (on-site consumption)

AL756 **CON EDISON SERVICE BOX: 546** **RCRA-CESQG** **1016451422**
SSE **14 E 2ND ST OPPOSITE** **FINDS** **NYP004305124**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.237 mi. **NY MANIFEST**
1249 ft. **Site 23 of 24 in cluster AL**

Relative: **Lower**
Actual: **40 ft.**

RCRA-CESQG:

Date form received by agency:	04/26/2013
Facility name:	CON EDISON SERVICE BOX: 546
Facility address:	14 E 2ND ST OPPOSITE NEW YORK, NY 10003
EPA ID:	NYP004305124
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	RICARDO CARTY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	646-772-3407
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON SERVICE BOX: 546 (Continued) **1016451422**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110056325828

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016451422
Registry ID: 110056325828
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056325828

NY MANIFEST:
Country: USA
EPA ID: NYP004305124
Facility Status: Not reported
Location Address 1: OPP 14 E 2ND ST
Code: BP
Location Address 2: SERV BOX 546
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004305124
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON SERVICE BOX: 546 (Continued) **1016451422**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/26/2013
Trans1 Recv Date:	04/26/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004305124
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010707942JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BD757 **CON EDISON MANHOLE 31112** **RCRA NonGen / NLR** **1010327480**
SW **JERSEY ST & CROSBY ST** **NYP004146874**
1/8-1/4 **NEW YORK, NY 10022**
0.237 mi.
1252 ft. **Site 1 of 4 in cluster BD**

Relative:
Lower

Actual:
40 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/11/2007
Facility name:	CON EDISON MANHOLE 31112
Facility address:	JERSEY ST & CROSBY ST E INT OF JERSEY ST NEW YORK, NY 10022
EPA ID:	NYP004146874
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	PATRICK HANLEY
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	718-204-4234
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/10/2007
Site name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	01/09/2007
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

BD758 **CONED** **NY MANIFEST** **S119072855**
SW **E INT JERSEY ST & CROSBY ST** **N/A**
1/8-1/4 **NEW YORK, NY 10022**
0.237 mi.
1252 ft. **Site 2 of 4 in cluster BD**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004146874
Facility Status:	Not reported
Location Address 1:	JERSEY & CROSBY ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004146874
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

BA759 **CON EDISON** **NY MANIFEST** **S117066211**
ESE **65 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.238 mi.
1257 ft. **Site 3 of 16 in cluster BA**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004588406
Facility Status:	Not reported
Location Address 1:	65 E 3RD ST
Code:	BP
Location Address 2:	SB 675
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004588406
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117066211**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004588406
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503329GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

CON EDISON (Continued) **S117066211**

Country:	USA
EPA ID:	NYP004862092
Facility Status:	Not reported
Location Address 1:	65 E 3RD ST
Code:	BP
Location Address 2:	SB 675
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004862092
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004862092
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612493GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117066211**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

BA760 **66-68 EAST 3RD STREET** **NY AST** **U003835974**
SE **66-68 EAST 3RD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.238 mi.
1258 ft. **Site 4 of 16 in cluster BA**

Relative:
Lower

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-606758
Program Type:	PBS
UTM X:	585394.58367
UTM Y:	4508729.94490
Expiration Date:	08/21/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	28615
Affiliation Type:	Facility Operator
Company Name:	66-68 EAST 3RD STREET
Contact Type:	Not reported
Contact Name:	EVELYN CABRERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 863-7444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-09-15

Site Id:	28615
Affiliation Type:	Emergency Contact

66-68 EAST 3RD STREET (Continued) **U003835974**

Company Name:	NYC DEP OF HOUSING PRESERVATION DEVELOPMENT
Contact Type:	Not reported
Contact Name:	DEREK PARSONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 559-4337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-10-14

Site Id:	28615
Affiliation Type:	Facility Owner
Company Name:	NYC DEP OF HOUSING PRESERVATION DEVELOPMENT
Contact Type:	DIRECTOR OF FIELD OPERATIONS & ENVIRONMENTAL COMPL
Contact Name:	DEREK PARSONS
Address1:	100 GOLD ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-7444
EMail:	ALEXANDJ@HPD.NYC.GOV
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-10-14

Site Id:	28615
Affiliation Type:	Mail Contact
Company Name:	NYC HPD
Contact Type:	Not reported
Contact Name:	ASST. COMMISSIONER DIV OF PROPERTY DISPOSITION
Address1:	100 GOLD STREET
Address2:	7T-3
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-8590
EMail:	ALEXANDJ@HPD.NYC.GOV
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2016-09-15

Tank Info:

Tank Number:	001
Tank Id:	61849
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

66-68 EAST 3RD STREET (Continued) **U003835974**

Equipment Records:

F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1970
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BA761 **CON EDISON** **NY MANIFEST** **S117066214**
SE **66 E 3RD ST** **N/A**
1/8-1/4 **NEW YORK, NY 10013**
0.238 mi.
1258 ft. **Site 5 of 16 in cluster BA**

Relative: **Lower**

Actual: **36 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004588430
Facility Status:	Not reported
Location Address 1:	66 E 3RD ST
Code:	BP
Location Address 2:	SB 685
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10013
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004588430
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON (Continued) **S117066214**

Mailing Phone: Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2014
Trans1 Recv Date:	07/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004588430
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002291692GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BE762 **CON EDISON** **RCRA NonGen / NLR** **1019901828**
South **268 BOWERY** **FINDS** **NYP004766481**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.238 mi.
1259 ft. **Site 1 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/10/2015
Facility name:	CON EDISON
Facility address:	268 BOWERY NEW YORK, NY 10012
EPA ID:	NYP004766481
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/10/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069661887

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019901828**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901828
Registry ID: 110069661887
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069661887

BE763 **CON ED** **NY MANIFEST** **S119077551**
South **268 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.238 mi.
1259 ft. **Site 2 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004833501
Facility Status: Not reported
Location Address 1: FRONT OF 268 AND BOWERY ST
Code: BP
Location Address 2: SB 26781
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004833501
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/02/2015
Trans1 Recv Date: 09/02/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/04/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004833501
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON ED (Continued) **S119077551**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612974GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

BE764 **CON EDISON** **NY MANIFEST** **S119074359**
South **268 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.238 mi.
1259 ft. **Site 3 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004766481
Facility Status:	Not reported
Location Address 1:	F/O 268 BOWERY
Code:	BP
Location Address 2:	SB 26781
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004766481

CON EDISON (Continued) **S119074359**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/10/2015
Trans1 Recv Date:	04/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004766481
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611737GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S119074359**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

BE765 **CON EDISON** **RCRA NonGen / NLR** **1019907386**
South **268 BOWERY** **NYP004833501**
1/8-1/4 **NEW YORK, NY 10012**
0.238 mi.
1259 ft. **Site 4 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/02/2015
Facility name: CON EDISON
Facility address: 268 BOWERY
NEW YORK, NY 10012
EPA ID: NYP004833501
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/02/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

BE766 **CON EDISON** **NJ MANIFEST** **S120676253**
South **268 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.238 mi.
1259 ft. **Site 5 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

NJ MANIFEST:

EPA Id:	NYP004833501
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612974GBF
EPA ID:	NYP004833501
Date Shipped:	9/2/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120676253**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BE767 **CON EDISON** **NJ MANIFEST** **S120670356**
South **268 BOWERY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.238 mi.
1259 ft. **Site 6 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

NJ MANIFEST:

EPA Id:	NYP004766481
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611737GBF
EPA ID:	NYP004766481
Date Shipped:	4/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON (Continued) **S120670356**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AS768 **CON EDISON** **NJ MANIFEST** **S120675783**
East **E 7TH ST & 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.239 mi.
1260 ft. **Site 5 of 8 in cluster AS**

Relative: **Lower**

Actual: **33 ft.**

NJ MANIFEST:

EPA Id:	NYP004828507
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612777GBF
EPA ID:	NYP004828507
Date Shipped:	8/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported

CON EDISON (Continued) **S120675783**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AS769 **CON EDISON** **RCRA NonGen / NLR** **1019325459**
East **EAST 7TH ST & 2ND AVE** **NYP004828507**
1/8-1/4 **NEW YORK, NY 10001**
0.239 mi.
1260 ft. **Site 6 of 8 in cluster AS**

Relative:
Lower

Actual:
33 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/26/2016
Facility name:	CON EDISON
Site name:	CON EDISON - MANHOLE 53987
Facility address:	EAST 7TH ST & 2ND AVE NEW YORK, NY 10001
EPA ID:	NYP004828507
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003

CON EDISON (Continued) **1019325459**

Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/23/2015
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/23/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 08/23/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 08/23/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2017

CON EDISON (Continued) **1019325459**

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 6000

Violation Status: No violations found

AS770 **CON ED** **NY MANIFEST** **S118563477**
East **EAST 7TH ST & 2ND AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10001**
0.239 mi.
1260 ft. **Site 7 of 8 in cluster AS**

Relative:
Lower

Actual:
33 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004828507
Facility Status: Not reported
Location Address 1: EAST 7TH ST & 2ND AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10001
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004828507
Mailing Name: CON ED
Mailing Contact: THERESA BURKARD
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602262

AS771 **CON EDISON SERVICE BOX 53992** **RCRA NonGen / NLR** **1014926448**
East **E 7TH ST & 2ND AVE NE COR** **FINDS** **NYP004242160**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.239 mi. **NY MANIFEST**
1260 ft. **Site 8 of 8 in cluster AS** **NJ MANIFEST**

Relative:
Lower

Actual:
33 ft.

RCRA NonGen / NLR:
Date form received by agency: 10/19/2011
Facility name: CON EDISON SERVICE BOX 53992
Facility address: E 7TH ST & 2ND AVE NE COR
NEW YORK, NY 10003
EPA ID: NYP004242160
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: KELVIN NELSON
Contact address: Not reported

CON EDISON SERVICE BOX 53992 (Continued) **1014926448**

Not reported
Contact country: Not reported
Contact telephone: 212-780-3756
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/19/2011
Site name: CON EDISON SERVICE BOX 53992
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069383697

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1014926448
Registry ID: 110069383697
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069383697

NY MANIFEST:
Country: USA
EPA ID: NYP004242160

CON EDISON SERVICE BOX 53992 (Continued) **1014926448**

Facility Status:	Not reported
Location Address 1:	E7TH ST
Code:	BP
Location Address 2:	2ND AVE
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004242160
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/19/2011
Trans1 Recv Date:	09/19/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/20/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004242160
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007660369JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON SERVICE BOX 53992 (Continued) **1014926448**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	750.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

NJ MANIFEST:

EPA Id:	NYP004242160
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	KELVIN NELSON
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007660369JJK
EPA ID:	NYP004242160
Date Shipped:	9/19/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

CON EDISON SERVICE BOX 53992 (Continued) **1014926448**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	750.00 Pounds

BE772 **250 ELIZABETH STREET** **NY AST** **A100291932**
South **250 ELIZABETH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.239 mi.
1260 ft. **Site 7 of 7 in cluster BE**

Relative:
Higher

Actual:
43 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607344
Program Type:	PBS
UTM X:	584960.43324
UTM Y:	4508480.15615
Expiration Date:	07/21/2019
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29197
Affiliation Type:	Mail Contact
Company Name:	C/O AJ CLARKE REALTY CORP.
Contact Type:	Not reported
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023

250 ELIZABETH STREET (Continued) **A100291932**

Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-19

Site Id:	29197
Affiliation Type:	Facility Operator
Company Name:	250 ELIZABETH STREET
Contact Type:	Not reported
Contact Name:	SAMANTHA ATTARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 256-5658
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-19

Site Id:	29197
Affiliation Type:	Emergency Contact
Company Name:	250-252 ELIZABETH S. PARTNERS C/O AJ CLARKE
Contact Type:	Not reported
Contact Name:	SAMANTHA ATTARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 256-5658
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-19

Site Id:	29197
Affiliation Type:	Facility Owner
Company Name:	250-252 ELIZABETH S. PARTNERS C/O AJ CLARKE
Contact Type:	AGENT
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-05-12

250 ELIZABETH STREET (Continued) **A100291932**

Tank Info:

Tank Number:	001
Tank Id:	62795
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/29/1993
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BA773 **CON EDISON** **RCRA NonGen / NLR** **1019908113**
ESE **104 E 4TH ST** **FINDS** **NYP004842114**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.239 mi.
1261 ft. **Site 6 of 16 in cluster BA**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/22/2015
Facility name:	CON EDISON
Facility address:	104 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004842114
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON (Continued) **1019908113**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/22/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069654804

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908113
Registry ID:	110069654804
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069654804

BA774 **CON EDISON SERVICE BOX: 870** **RCRA NonGen / NLR** **1016969146**
ESE **104 E 4TH ST** **NY MANIFEST** **NYP004427951**
1/8-1/4 **NEW YORK, NY 10003**
0.239 mi.
1261 ft. **Site 7 of 16 in cluster BA**

Relative:
Lower

Actual:
34 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/2014
Facility name:	CON EDISON SERVICE BOX: 870
Facility address:	104 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004427951
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/28/2014
Site name:	CON EDISON SERVICE BOX: 870
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004427951
Facility Status:	Not reported
Location Address 1:	104 E 4TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003

CON EDISON SERVICE BOX: 870 (Continued) **1016969146**

Location Zip 4: Not reported

NY MANIFEST:

EPAID:	NYP004427951
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/28/2014
Trans1 Recv Date:	01/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004427951
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002330031GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON SERVICE BOX: 870 (Continued) **1016969146**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

Country:	USA
EPA ID:	NYP004842114
Facility Status:	Not reported
Location Address 1:	104 E 4TH ST
Code:	BP
Location Address 2:	SB 870
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10009
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004842114
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/22/2015
Trans1 Recv Date:	09/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/22/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004842114
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002613280GBF
Import Indicator:	N
Export Indicator:	N

CON EDISON SERVICE BOX: 870 (Continued) **1016969146**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

BA775 **104 E 4TH ST REALTY CO** **NY AST** **U003390583**
ESE **104 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.239 mi.
1261 ft. **Site 8 of 16 in cluster BA**

Relative:
Lower

Actual:
34 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-153281
Program Type:	PBS
UTM X:	585441.27174
UTM Y:	4508823.09579
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4845
Affiliation Type:	Facility Operator
Company Name:	104 E 4TH ST REALTY CO
Contact Type:	Not reported
Contact Name:	104 E 4TH ST REALTY CO
Address1:	Not reported
Address2:	Not reported
City:	Not reported

104 E 4TH ST REALTY CO (Continued) **U003390583**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 606-2082
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4845
Affiliation Type:	Emergency Contact
Company Name:	104 E 4TH ST REALTY CO
Contact Type:	Not reported
Contact Name:	104 E 4TH ST REALTY CO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 606-2082
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4845
Affiliation Type:	Facility Owner
Company Name:	NPA HOLDINGS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1373 3RD AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(917) 848-1854
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-11-30

Site Id:	4845
Affiliation Type:	Mail Contact
Company Name:	MPA HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	MORRIS PLATT
Address1:	241 WEST 37TH ST
Address2:	3RD FLOOR
City:	NY
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(917) 848-1854
EMail:	YESNEWYORK@GMAIL.COM
Fax Number:	Not reported

104 E 4TH ST REALTY CO (Continued) **U003390583**

Modified By: DMPOKRZY
Date Last Modified: 2016-11-30

Tank Info:

Tank Number: 001
Tank Id: 19591
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1947
Capacity Gallons: 2000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/26/2016
Register: True
Modified By: MXLAY
Last Modified: 11/28/2017
Material Name: #2 fuel oil (on-site consumption)

BA776 **CON EDISON** **NJ MANIFEST** **S120677019**
ESE **104 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.239 mi.
1261 ft. **Site 9 of 16 in cluster BA**

Relative: NJ MANIFEST:
Lower
Actual: EPA Id: NYP004842114
34 ft. Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

CON EDISON (Continued) **S120677019**

Manifest:

Manifest Number:	002613280GBF
EPA ID:	NYP004842114
Date Shipped:	9/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

BC777 **M R C MGMT** **NY MANIFEST** **S119078611**
NNE **770 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.239 mi.
1262 ft. **Site 4 of 5 in cluster BC**

Relative:
Lower

Actual:
39 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYR000070060
Facility Status:	Not reported
Location Address 1:	770 BROADWAY
Code:	BP
Location Address 2:	Not reported

M R C MGMT (Continued) **S119078611**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000070060
Mailing Name:	M R C MGMT
Mailing Contact:	CI FAMULARO
Mailing Address 1:	770 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129828240

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	NYR000081661
Trans2 State ID:	NJD080631369
Generator Ship Date:	06/01/2016
Trans1 Recv Date:	06/01/2016
Trans2 Recv Date:	06/06/2016
TSD Site Recv Date:	06/09/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000070060
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000097352JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds

M R C MGMT (Continued) **S119078611**

Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
9 additional NY_MANIFEST: record(s) in the EDR Site Report.

BC778 **KMART # 7777** **PA MANIFEST** **S118890240**
NNE **770 BROADWAY** **N/A**
1/8-1/4 **NY, NY 10003**
0.239 mi.
1262 ft. **Site 5 of 5 in cluster BC**

Relative: **Lower**

Actual: **39 ft.**

Manifest Details:

Year:	2015
Manifest Number:	006298746FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	02/19/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396046FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

KMART # 7777 (Continued) **S118890240**

TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D006
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396046FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396047FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC

KMART # 7777 (Continued) **S118890240**

TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	11
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396047FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	007396046FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA

KMART # 7777 (Continued) **S118890240**

Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D005
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007396046FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D007
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007396047FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1

KMART # 7777 (Continued) **S118890240**

Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	55
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007396047FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	21
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007396046FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000031930
Generator Date:	05/11/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D008
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases

KMART # 7777 (Continued) **S118890240**

Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access additional PA_MANIFEST: detail in the EDR Site Report.

AN779 **32 ST MARKS PLACE** **NY AST** **U003384350**
ENE **32 ST MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.239 mi.
1263 ft. **Site 16 of 16 in cluster AN**

Relative:
Lower

Actual:
35 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-091448
Program Type:	PBS
UTM X:	585425.10843
UTM Y:	4509141.00638
Expiration Date:	05/07/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2295
Affiliation Type:	Facility Owner
Company Name:	ST.MARKS ASSETS % A.J. CLARKE R.E. CORP.
Contact Type:	AGENT
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-08

Site Id:	2295
Affiliation Type:	Mail Contact
Company Name:	A.J. CLARKE REAL ESTATE CORP.
Contact Type:	Not reported
Contact Name:	STEPHEN DENARDO
Address1:	1881 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10023
Country Code:	001
Phone:	(212) 541-4477
EMail:	SDENARDO@AJCLARKENYC.COM
Fax Number:	Not reported

32 ST MARKS PLACE (Continued) **U003384350**

Modified By:	MFLEONAR
Date Last Modified:	2017-06-08

Site Id:	2295
Affiliation Type:	Facility Operator
Company Name:	32 ST MARKS PLACE
Contact Type:	Not reported
Contact Name:	VICTOR IVEZAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 903-9630
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-08

Site Id:	2295
Affiliation Type:	Emergency Contact
Company Name:	ST.MARKS ASSETS % A.J. CLARKE R.E. CORP.
Contact Type:	Not reported
Contact Name:	ST MARKS ASSTS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 541-4477
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-08

Tank Info:

Tank Number:	001
Tank Id:	3620
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None

32 ST MARKS PLACE (Continued) **U003384350**

K00 - Spill Prevention - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/19/1973
Capacity Gallons:	5000
Tightness Test Method:	21
Date Test:	10/26/2016
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	06/08/2017
Material Name:	#2 fuel oil (on-site consumption)

AL780 **CON EDISON** **NY MANIFEST** **S117066514**
SSE **33 E 1ST ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.241 mi.
1270 ft. **Site 24 of 24 in cluster AL**

Relative:
Lower

Actual:
40 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591723
Facility Status:	Not reported
Location Address 1:	33 E 1ST ST
Code:	BP
Location Address 2:	SB 517
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591723
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117066514**

TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004591723
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608162GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AU781 **CON EDISON SERVICE BOX: 27209** **RCRA NonGen / NLR** **1016973322**
WSW **599-601 BROADWAY & PRINCE ST N OF** **NY MANIFEST** **NYP004471199**
1/8-1/4 **NEW YORK, NY 10012**
0.241 mi.
1274 ft. **Site 6 of 11 in cluster AU**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/19/2014
Facility name:	CON EDISON SERVICE BOX: 27209
Facility address:	599-601 BROADWAY & PRINCE ST N OF NEW YORK, NY 10012
EPA ID:	NYP004471199
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING

CON EDISON SERVICE BOX: 27209 (Continued) **1016973322**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/19/2014
Site name: CON EDISON SERVICE BOX: 27209
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004471199
Facility Status: Not reported
Location Address 1: 599 BROADWAY
Code: BP
Location Address 2: SERVICE BOX # 27209
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004471199
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON SERVICE BOX: 27209 (Continued) **1016973322**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/21/2014
Trans1 Recv Date:	03/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004471199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360884GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AU782 **C F A CORP OF ILLINOIS** **RCRA NonGen / NLR** **1001203142**
WSW **599 BROADWAY** **FINDS** **NYR000045047**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.241 mi. **NY MANIFEST**
1274 ft. **Site 7 of 11 in cluster AU**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	C F A CORP OF ILLINOIS
Facility address:	599 BROADWAY CO THE GRABSCHEID GROUP LTD NEW YORK, NY 10012
EPA ID:	NYR000045047
Mailing address:	W MADISON SUITE 2250 CHICAGO, NY 60606
Contact:	MARY THOMAS
Contact address:	W MADISON SUITE 2250 CHICAGO, NY 60606
Contact country:	US
Contact telephone:	212-757-1035
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CFA CORP OF ILLINOIS - GRABSCHEID GROUP
Owner/operator address:	200 W MADISON SUITE 2250 CHICAGO, IL 60606
Owner/operator country:	US
Owner/operator telephone:	312-407-6440
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	CFA CORP OF ILLINOIS - GRABSCHEID GROUP
Owner/operator address:	200 W MADISON SUITE 2250 CHICAGO, IL 60606
Owner/operator country:	US
Owner/operator telephone:	312-407-6440
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

C F A CORP OF ILLINOIS (Continued) **1001203142**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: C F A CORP OF ILLINOIS
Classification: Not a generator, verified

Date form received by agency: 09/22/1997
Site name: C F A CORP OF ILLINOIS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110009486252

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001203142
Registry ID: 110009486252
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009486252

NY MANIFEST:
Country: USA
EPA ID: NYR000045047
Facility Status: Not reported
Location Address 1: 599 BROADWAY
Code: BP
Location Address 2: Not reported

C F A CORP OF ILLINOIS (Continued) **1001203142**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000045047
Mailing Name:	CFA CORP OF ILLINOIS
Mailing Contact:	CFA CORP OF ILLINOIS
Mailing Address 1:	200 WEST MADISON - SUITE 2250
Mailing Address 2:	Not reported
Mailing City:	CHICAGO
Mailing State:	IL
Mailing Zip:	60606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	NJA2578750
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	S50059
Trans2 State ID:	50059
Generator Ship Date:	09/26/1997
Trans1 Recv Date:	09/26/1997
Trans2 Recv Date:	10/14/1997
TSD Site Recv Date:	10/14/1997
Part A Recv Date:	/ /
Part B Recv Date:	11/21/1997
Generator EPA ID:	NYR000045047
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150
Units:	P - Pounds

C F A CORP OF ILLINOIS (Continued) **1001203142**

Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00250
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00250
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00250
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AU783 **599 BROADWAY** **NY AST** **A100366080**
WSW **599 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.241 mi.
1274 ft. **Site 8 of 11 in cluster AU**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-201804
Program Type:	PBS
UTM X:	584733.83421
UTM Y:	4508738.59562
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6876
Affiliation Type:	Facility Owner
Company Name:	SOHO INTERNTL ARTS CONDOMINIUM
Contact Type:	MANAGING AGENT
Contact Name:	PETER T. MURRAY
Address1:	599 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 995-5140
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-12-28

Site Id:	6876
Affiliation Type:	Facility Operator
Company Name:	599 BROADWAY
Contact Type:	Not reported
Contact Name:	NICK GURAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 966-5046
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTang
Date Last Modified:	2004-07-19

Site Id:	6876
Affiliation Type:	Emergency Contact
Company Name:	SOHO INTERNTL ARTS CONDOMINIUM
Contact Type:	Not reported
Contact Name:	PETER MURRAY
Address1:	Not reported
Address2:	Not reported
City:	Not reported

599 BROADWAY (Continued) **A100366080**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 307-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTang
Date Last Modified:	2004-07-19

Site Id:	6876
Affiliation Type:	Mail Contact
Company Name:	ABC REALTY
Contact Type:	Not reported
Contact Name:	PETER MURRAY
Address1:	152 WEST 57TH STREET
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10019
Country Code:	001
Phone:	(212) 307-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-06-02

Tank Info:

Tank Number:	001
Tank Id:	11494
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	06/01/1989
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/06/2014

599 BROADWAY (Continued) **A100366080**

Register:	True
Modified By:	DAFRANCI
Last Modified:	12/28/2017
Material Name:	#6 fuel oil (on-site consumption)

AU784 **TANK TEST FAIL** **NY LTANKS** **S116295860**
WSW **599 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY**
0.241 mi.
1274 ft. **Site 9 of 11 in cluster AU**

Relative: **Lower**
Actual: **39 ft.**

LTANKS:

Facility ID:	1404020
Site ID:	497400
Closed Date:	2014-09-25
Spill Number:	1404020
Spill Date:	2014-07-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2014-07-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-07-14
Spill Record Last Update:	2014-09-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DIANE PARKER
Spiller Phone:	(718) 383-9800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	452396
DEC Memo:	"7/7/14-Zhune spoke to Ray Lara from PTC. Ray said they emptied the tank and cleaned it and after they cleaned the tank they performed the tank system test and the test failed. They will do the isolation test. 9/25/14-Rene lewis from Alliance Mechanical Division sent the spill closure Report dated 9/23/14. The report stated that the board decides to go full gas instead of dual fuel, leading to decision to abandon the tank in place. Four hole were drilled in the bottom of the tank. Four soil samples were collected fromthe four holes and composite in two samples S1 and S2. The soil analytical results of the two samples indicate no VOCCs and no SVOCs detected. On 9/16/14-Rene Luis sent an email the email stated that the suction line and return line were complety aboveground lines and all but 4' of fill line is accesible. Entire vent line can be removed. Suction and Return has been removed and fill line filled with cement. Spill

TANK TEST FAIL (Continued) **S116295860**

Closed."
Remarks: "Tank test failure"

All Materials:
Site ID: 497400
Operable Unit ID: 1246865
Operable Unit: 01
Material ID: 2248067
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AR785 **CON EDISON** **NY MANIFEST** **S118463860**
North **50 E 8TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.242 mi.
1277 ft. **Site 6 of 8 in cluster AR**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004858140
Facility Status: Not reported
Location Address 1: 50 E 8TH ST
Code: BP
Location Address 2: SB 57217
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004858140
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2015

CON EDISON (Continued) **S118463860**

Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004858140
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087543JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AR786 **8TH ST OWNERS CORP** **NY AST** **U003387485**
North **50-54 E 8TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.242 mi.
1277 ft. **Site 7 of 8 in cluster AR**

Relative: AST:
Lower

Actual:
35 ft.

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-292206
Program Type:	PBS
UTM X:	584978.69240

8TH ST OWNERS CORP (Continued) **U003387485**

UTM Y: 4509461.15802
Expiration Date: 07/07/2022
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 13282
Affiliation Type: Facility Owner
Company Name: 8TH STREET OWNERS CORP
Contact Type: DIRECTOR OF MANAGEMENT ADMINISTRATION
Contact Name: VALERY LIPARI
Address1: C/O MGRE 1981 MARCUS AVENUE, SUITE C131
Address2: Not reported
City: LAKE SUCCESS
State: NY
Zip Code: 11042
Country Code: 001
Phone: (516) 944-5000
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-08-15

Site Id: 13282
Affiliation Type: Mail Contact
Company Name: % MARK GREENBERG REAL ESTATE
Contact Type: Not reported
Contact Name: VALERY LIPARI
Address1: 30-30 NORTHERN BOULEVARD, SUITE 400
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (516) 944-5000
EMail: VALERY@MGRE.COM
Fax Number: Not reported
Modified By: TLYE
Date Last Modified: 2017-10-13

Site Id: 13282
Affiliation Type: Facility Operator
Company Name: 8TH ST OWNERS CORP
Contact Type: Not reported
Contact Name: RODNEY SALADIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 358-1287
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 2007-04-03

Site Id: 13282
Affiliation Type: Emergency Contact

8TH ST OWNERS CORP (Continued) **U003387485**

Company Name:	8TH STREET OWNERS CORP
Contact Type:	Not reported
Contact Name:	RODNEY SALADIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 944-5000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-08-15

Tank Info:

Tank Number:	001
Tank Id:	12025
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
E02 - Piping Secondary Containment - Vault (with Access)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1951
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	08/15/2017
Material Name:	#2 fuel oil (on-site consumption)

AY787 **CON EDISON SERVICE BOX: 40681** **RCRA NonGen / NLR** **1016966600**
ENE **34 ST MARKS PL** **NY MANIFEST** **NYP004394482**
1/8-1/4 **NEW YORK, NY 10003**
0.242 mi.
1278 ft. **Site 2 of 9 in cluster AY**

Relative:
Lower

Actual:
35 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/19/2013
Facility name:	CON EDISON SERVICE BOX: 40681
Facility address:	34 ST MARKS PL NEW YORK, NY 10003
EPA ID:	NYP004394482
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/19/2013
Site name:	CON EDISON SERVICE BOX: 40681
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004394482
Facility Status:	Not reported
Location Address 1:	34 ST MARKS PL
Code:	BP
Location Address 2:	SB40681
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003

CON EDISON SERVICE BOX: 40681 (Continued) **1016966600**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004394482
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/20/2013
Trans1 Recv Date: 11/20/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/20/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004394482
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002237683GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 40681 (Continued) **1016966600**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BB788 **CON EDISON - MANHOLE M37067** **NY MANIFEST** **S120959085**
SSE **109-11 E HOUSTON ST** **N/A**
1/8-1/4 **MANHATTAN, NY 10002**
0.242 mi.
1279 ft. **Site 2 of 2 in cluster BB**

Relative: **Lower**
Actual: **41 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004990642
Facility Status:	Not reported
Location Address 1:	109-11 E HOUSTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MANHATTAN
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004990642
Mailing Name:	CON EDISON - MANHOLE M37067
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

BF789 **CON EDISON MANHOLE 384** **RCRA NonGen / NLR** **1014926580**
WSW **W HOUSTON ST & MERCER ST 52** **NY MANIFEST** **NYP004243556**
1/8-1/4 **NEW YORK, NY 10003**
0.242 mi.
1280 ft. **Site 1 of 4 in cluster BF**

Relative: **Lower**
Actual: **35 ft.**

RCRA NonGen / NLR:

Date form received by agency:	11/23/2011
Facility name:	CON EDISON MANHOLE 384
Facility address:	W HOUSTON ST & MERCER ST 52 FEET E OF NEW YORK, NY 10003
EPA ID:	NYP004243556

CON EDISON MANHOLE 384 (Continued) **1014926580**

Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MICHAEL ECKARDT
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 917-417-1998
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/24/2011
Site name: CON EDISON MANHOLE 384
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004243556
Facility Status: Not reported
Location Address 1: MERCER & HOUSTON
Code: BP
Location Address 2: MH #384
Total Tanks: Not reported
Location City: MANHATTAN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004243556
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE ROOM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

CON EDISON MANHOLE 384 (Continued) **1014926580**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2011
Trans1 Recv Date:	10/24/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004243556
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	003203791FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	D007
Waste Code 1_3:	D006
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AX790 **FIRS GARDEN CORPORATION** **NY AST** **U004046743**
SE **38 EAST FIRST STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.243 mi.
1281 ft. **Site 5 of 9 in cluster AX**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-237000
Program Type:	PBS
UTM X:	585286.89505
UTM Y:	4508630.03225
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8811
Affiliation Type:	Facility Owner
Company Name:	FIRST GARDEN CORP % ANDREWS BUILDING CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	666 BROADWAY 12TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8811
Affiliation Type:	Mail Contact
Company Name:	ANDREWS BUILDING CORP.
Contact Type:	Not reported
Contact Name:	LEONARD VOGT
Address1:	666 BROADWAY
Address2:	12TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8811
Affiliation Type:	Facility Operator
Company Name:	FIRS GARDEN CORPORATION
Contact Type:	Not reported
Contact Name:	IZHAR PATKIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

FIRS GARDEN CORPORATION (Continued) **U004046743**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 254-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8811
Affiliation Type:	Emergency Contact
Company Name:	FIRST GARDEN CORP % ANDREWS BUILDING CORP
Contact Type:	Not reported
Contact Name:	LEONARD VOGT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 529-5688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	17238
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	03/01/1999
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017

FIRS GARDEN CORPORATION (Continued) **U004046743**

Material Name: #2 fuel oil (on-site consumption)

AV791 **CON EDISON SERVICE BOX: 1366** **RCRA NonGen / NLR** **1016966824**
North **59 E 8 ST FRONT OF** **NY MANIFEST** **NYP004396651**
1/8-1/4 **NEW YORK, NY 10003**
0.243 mi.
1284 ft. **Site 12 of 15 in cluster AV**

Relative:
Lower

Actual:
36 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/22/2013
Facility name:	CON EDISON SERVICE BOX: 1366
Facility address:	59 E 8 ST FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004396651
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/22/2013
Site name:	CON EDISON SERVICE BOX: 1366
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004396651
Facility Status:	Not reported
Location Address 1:	OP 59 E 8TH ST
Code:	BP
Location Address 2:	SB1366

CON EDISON SERVICE BOX: 1366 (Continued) **1016966824**

Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004396651
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/22/2013
Trans1 Recv Date:	11/22/2013
Trans2 Recv Date:	11/25/2013
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004396651
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237695GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds

CON EDISON SERVICE BOX: 1366 (Continued) **1016966824**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AU792 **594 BROADWAY BROADWAY ASSOCIATES, LLC** **NY AST** **A100364455**
SW **594 BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10012**
0.244 mi.
1286 ft. **Site 10 of 11 in cluster AU**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-082694
Program Type:	PBS
UTM X:	584711.01736
UTM Y:	4508720.25775
Expiration Date:	11/07/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	1807
Affiliation Type:	Facility Operator
Company Name:	594 BROADWAY
Contact Type:	Not reported
Contact Name:	JOE VILLAFANE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 625-6205
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-10-09

Site Id:	1807
Affiliation Type:	Emergency Contact
Company Name:	594 BROADWAY BROADWAY ASSOCIATES, LLC
Contact Type:	Not reported
Contact Name:	ART D'ESTRADA
Address1:	Not reported
Address2:	Not reported
City:	Not reported

594 BROADWAY BROADWAY ASSOCIATES, LLC (Continued) **A100364455**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 625-6203
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-08-10

Site Id: 1807
Affiliation Type: Mail Contact
Company Name: NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: ART D'ESTRADA
Address1: 594 BROADWAY
Address2: ROOM 311
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 431-5751
EMail: ADESTRATA@NGKF.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-08-10

Site Id: 1807
Affiliation Type: Facility Owner
Company Name: 594 BROADWAY BROADWAY ASSOCIATES, LLC
Contact Type: AGENT FOR 594 BROADWAY BROADWAY ASSOCIATES, LLC
Contact Name: ART D'ESTRADA
Address1: 594 BROADWAY
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10012
Country Code: 001
Phone: (212) 431-5751
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-08-10

Tank Info:

Tank Number: 001
Tank Id: 3022
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating

594 BROADWAY BROADWAY ASSOCIATES, LLC (Continued) **A100364455**

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A02 - Tank Internal Protection - Rubber Liner
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1955
Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	08/10/2017
Material Name:	#2 fuel oil (on-site consumption)

AU793 **PORTOFOTO INC** **RCRA NonGen / NLR** **1000872784**
SW **596 BROADWAY 1ST FLOOR** **FINDS** **NYD987040029**
1/8-1/4 **NEW YORK, NY 10012** **ECHO**
0.244 mi.
1286 ft. **Site 11 of 11 in cluster AU**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PORTOFOTO INC
Facility address:	596 BROADWAY 1ST FLOOR NEW YORK, NY 10012-3210
EPA ID:	NYD987040029
Mailing address:	BROADWAY 1ST FLOOR NEW YORK, NY 10012
Contact:	Not reported
Contact address:	BROADWAY 1ST FLOOR NEW YORK, NY 10012
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PORTOFOTO INC
Owner/operator address:	596 BROADWAY 1ST FLOOR NEW YORK, NY 10012
Owner/operator country:	US
Owner/operator telephone:	212-226-9788
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

PORTOFOTO INC (Continued) **1000872784**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PORTOFOTO INC
Owner/operator address: 596 BROADWAY 1ST FLOOR
NEW YORK, NY 10012
Owner/operator country: US
Owner/operator telephone: 212-226-9788
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PORTOFOTO INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PORTOFOTO INC
Classification: Not a generator, verified

Date form received by agency: 08/26/1993
Site name: PORTOFOTO INC
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

PORTOFOTO INC (Continued) **1000872784**

Registry ID: 110004508319

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000872784
Registry ID: 110004508319
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004508319

AO794 **CON EDISON SERVICE BOX 26795** **RCRA NonGen / NLR** **1014397788**
South **265 BOWERY STANTON ST FO SB 26795** **NJ MANIFEST** **NYP004201273**
1/8-1/4 **NEW YORK, NY 10002** **NY MANIFEST**
0.244 mi.
1287 ft. **Site 13 of 13 in cluster AO**

Relative: **Higher**

Actual: **42 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/20/2010
Facility name: CON EDISON SERVICE BOX 26795
Facility address: 265 BOWERY STANTON ST FO SB 26795
NEW YORK, NY 10002
EPA ID: NYP004201273
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: TIMOTHY REGAN
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 917-416-5436
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

CON EDISON SERVICE BOX 26795 (Continued) **1014397788**

Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004201273
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: TIMOTHY REGAN
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 001085261GBF
EPA ID: NYP004201273
Date Shipped: 01/20/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/20/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/20/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported

CON EDISON SERVICE BOX 26795 (Continued) **1014397788**

Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 500 P

NY MANIFEST:
Country: USA
EPA ID: NYP004201273
Facility Status: Not reported
Location Address 1: F/O 263 BOWERY ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10002
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004201273
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2010
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 01/20/2010
Trans1 Recv Date: 01/20/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/20/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004201273
Trans1 EPA ID: Not reported

CON EDISON SERVICE BOX 26795 (Continued) **1014397788**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001085261GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AY795 **GIOIA PROPERTIES** **NY AST** **A100318881**
ENE **17 ST MARKS PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.244 mi.
1287 ft. **Site 3 of 9 in cluster AY**

Relative:
Lower

Actual:
37 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-160490
Program Type:	PBS
UTM X:	585419.33028
UTM Y:	4509195.31263
Expiration Date:	06/30/2020
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5481
Affiliation Type:	Mail Contact

GIOIA PROPERTIES (Continued) **A100318881**

Company Name:	GIOIA PROPERTIES, INC.
Contact Type:	Not reported
Contact Name:	ANTHONY GIOIA
Address1:	17 ST MARKS PLACE
Address2:	SUITE 1
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 420-1246
EMail:	REGINA@GIOIAREALTY.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-05-19

Site Id:	5481
Affiliation Type:	Facility Operator
Company Name:	GIOIA PROPERTIES
Contact Type:	Not reported
Contact Name:	RICHARD GIOIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 420-1246
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-14

Site Id:	5481
Affiliation Type:	Emergency Contact
Company Name:	GIOIA PROPERTIES, INC.
Contact Type:	Not reported
Contact Name:	RICHARD GIOIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(631) 766-9691
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-01-14

Site Id:	5481
Affiliation Type:	Facility Owner
Company Name:	GIOIA PROPERTIES, INC.
Contact Type:	OWNER
Contact Name:	RICHARD GIOIA
Address1:	12 ALLEY POND COURT
Address2:	Not reported
City:	DIX HILLS

GIOIA PROPERTIES (Continued) **A100318881**

State:	NY
Zip Code:	11746
Country Code:	001
Phone:	(631) 766-9691
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-05-19

Tank Info:

Tank Number:	001
Tank Id:	8804
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1948
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AX796 **CON EDISON** **RCRA NonGen / NLR** **1014397873**
SE **61 2ND AVE & E 3RD ST** **NJ MANIFEST** **NYP004202156**
1/8-1/4 **NEW YORK, NY 10002** **NY MANIFEST**
0.245 mi.
1291 ft. **Site 6 of 9 in cluster AX**

Relative: **Lower**
Actual: **37 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/12/2010
Facility name:	CON EDISON
Facility address:	61 2ND AVE & E 3RD ST NEW YORK, NY 10002
EPA ID:	NYP004202156
Mailing address:	4 IRVING PL, RM 828

CON EDISON (Continued) **1014397873**

NEW YORK, NY 10003
Contact: MICHAEL BETO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 917-337-5519
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004202156
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: MICHAEL BETO
Comments: Not reported
SIC Code: Not reported
County: NY061
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 001085279GBF
EPA ID: NYP004202156
Date Shipped: 02/12/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

CON EDISON (Continued) **1014397873**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/12/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/16/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	250 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004202156
Facility Status:	Not reported
Location Address 1:	F/O 61 2ND AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004202156
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	THOMAS TEELING

CON EDISON (Continued) **1014397873**

Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/12/2010
Trans1 Recv Date:	02/12/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/16/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004202156
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001085279GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **1014397873**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AZ797 **CON EDISON SERVICE BOX: 43505** **RCRA NonGen / NLR** **1016148992**
NE **29 3RD AVE FRONT OF** **FINDS** **NYP004276481**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.245 mi. **NY MANIFEST**
1296 ft. **Site 4 of 8 in cluster AZ**

Relative:
Lower

Actual:
39 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 43505
Facility address:	29 3RD AVE FRONT OF NEW YORK, NY 10003
EPA ID:	NYP004276481
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	BENJAMIN BAMONTE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-894-9549
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/27/2012
Site name:	CON EDISON SERVICE BOX: 43505
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110055436577

Environmental Interest/Information System

CON EDISON SERVICE BOX: 43505 (Continued) **1016148992**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016148992
Registry ID:	110055436577
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055436577

NY MANIFEST:

Country:	USA
EPA ID:	NYP004276481
Facility Status:	Not reported
Location Address 1:	FO 29 3RD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004276481
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

AZ798 **29 THIRD AVE CORP** **NY AST** **U004045348**
NE **29 THIRD AVE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.245 mi.
1296 ft. **Site 5 of 8 in cluster AZ**

Relative:
Lower

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-338516
Program Type:	PBS
UTM X:	585368.55192
UTM Y:	4509292.20263

29 THIRD AVE CORP (Continued) **U004045348**

Expiration Date: N/A
Site Type: Unknown

Affiliation Records:

Site Id: 16271
Affiliation Type: Facility Owner
Company Name: 29 THIRD AVE CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 29 THIRD AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 777-7170
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16271
Affiliation Type: Mail Contact
Company Name: 29 THIRD AVE CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 29 THIRD AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 777-7170
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16271
Affiliation Type: Facility Operator
Company Name: 29 THIRD AVE CORP
Contact Type: Not reported
Contact Name: 29 THIRD AVE CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 777-7170
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16271
Affiliation Type: Emergency Contact
Company Name: 29 THIRD AVE CORP

29 THIRD AVE CORP (Continued) **U004045348**

Contact Type:	Not reported
Contact Name:	MILFORD BALICK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 777-7170
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	27786
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/1991
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AZ799 **CON EDISON SERVICE BOX: 43505** **RCRA NonGen / NLR** **1016966721**
NE **29 3RD AVE** **NY MANIFEST** **NYP004395661**
1/8-1/4 **NEW YORK, NY 10009**
0.245 mi.
1296 ft. **Site 6 of 8 in cluster AZ**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 43505
Facility address:	29 3RD AVE NEW YORK, NY 10009

CON EDISON SERVICE BOX: 43505 (Continued) **1016966721**

EPA ID: NYP004395661
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 43505
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395661
Facility Status: Not reported
Location Address 1: 28 3RD AVE
Code: BP
Location Address 2: SB43505
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395661
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK

CON EDISON SERVICE BOX: 43505 (Continued) **1016966721**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/22/2013
Trans1 Recv Date:	11/22/2013
Trans2 Recv Date:	11/25/2013
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395661
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237601GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON SERVICE BOX: 43505 (Continued) **1016966721**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AZ800 **CON EDISON SERVICE BOX: 43505** **NJ MANIFEST** **S117986935**
NE **29 3RD AVE FRONT OF** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.245 mi.
1296 ft. **Site 7 of 8 in cluster AZ**

Relative:
Lower

Actual:
39 ft.

NJ MANIFEST:

EPA Id:	NYP004276481
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	BENJAMIN BAMONTE
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010408768JJK
EPA ID:	NYP004276481
Date Shipped:	10/27/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON SERVICE BOX: 43505 (Continued) **S117986935**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	1,000.00 Pounds

AR801 **FAUST BROS INC** **RCRA NonGen / NLR** **1000387016**
North **48 E 8TH ST** **FINDS** **NYD078873320**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.246 mi. **NY MANIFEST**
1297 ft. **Site 8 of 8 in cluster AR**

Relative:
Lower

Actual:
35 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	FAUST BROS INC
Facility address:	48 E 8TH ST NEW YORK, NY 10003-6520
EPA ID:	NYD078873320
Mailing address:	E 8TH ST NEW YORK, NY 10003
Contact:	Not reported
Contact address:	E 8TH ST NEW YORK, NY 10003
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KIM CHONG OUK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported

FAUST BROS INC (Continued) **1000387016**

Owner/Op end date: Not reported

Owner/operator name: KIM CHONG OUK
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: FAUST BROS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: FAUST BROS INC
Classification: Not a generator, verified

Date form received by agency: 03/11/1986
Site name: FAUST BROS INC
Classification: Large Quantity Generator

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

FAUST BROS INC (Continued) **1000387016**

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/04/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004370494

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000387016
Registry ID: 110004370494
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004370494

NY MANIFEST:
Country: USA
EPA ID: NYD078873320
Facility Status: Not reported
Location Address 1: 48 EAST 8TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10017
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD078873320
Mailing Name: FAUST BROTHERS
Mailing Contact: FAUST BROTHERS
Mailing Address 1: 48 EAST 8TH STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10017
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2122543737

FAUST BROS INC (Continued) **1000387016**

NY MANIFEST:

Document ID:	NYB7191981
Manifest Status:	C
seq:	Not reported
Year:	1996
Trans1 State ID:	XZ90GR501
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1996
Trans1 Recv Date:	12/30/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/06/1997
Part A Recv Date:	01/22/1997
Part B Recv Date:	01/21/1997
Generator EPA ID:	NYD078873320
Trans1 EPA ID:	NJD000564906
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00135
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
61 additional NY_MANIFEST: record(s) in the EDR Site Report.

802
ENE
1/8-1/4
0.246 mi.
1298 ft.

125 SECOND AVE
125 SECOND AVENUE
NEW YORK, NY 10003

NY AST **U003384689**
N/A

Relative:
Lower

Actual:
34 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active

125 SECOND AVE (Continued) **U003384689**

Facility Id: 2-092649
Program Type: PBS
UTM X: 585499.30410
UTM Y: 4509100.98001
Expiration Date: 07/06/2021
Site Type: Other

Affiliation Records:

Site Id: 2401
Affiliation Type: Facility Operator
Company Name: 125 SECOND AVE
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-05-19

Site Id: 2401
Affiliation Type: Emergency Contact
Company Name: 125 SECOND AVE REALTY CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-05-19

Site Id: 2401
Affiliation Type: Facility Owner
Company Name: 125 SECOND AVE REALTY CORP
Contact Type: PRESIDENT
Contact Name: ROMAN BOHNDANOWYCZ
Address1: 40-60 ELBERTSON ST. APT 4E
Address2: Not reported
City: ELMHURST
State: NY
Zip Code: 11373
Country Code: 001
Phone: (718) 507-08049
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-05-19

125 SECOND AVE (Continued) **U003384689**

Site Id:	2401
Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	ROMAN BOHDANOWYCZ
Address1:	40-60 ELBERTSON ST APT 4E
Address2:	Not reported
City:	ELMHURST
State:	NY
Zip Code:	11373
Country Code:	001
Phone:	(718) 507-0849
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-19

Tank Info:

Tank Number:	001
Tank Id:	4241
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1952
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MRBARROW
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AY803 **CON EDISON** **RCRA NonGen / NLR** **1019905266**
ENE **21 SAINT MARKS PL** **FINDS** **NYP004807723**
1/8-1/4 **NEW YORK, NY 10009** **ECHO**
0.247 mi.
1302 ft. **Site 4 of 9 in cluster AY**

Relative:
Lower

Actual:
36 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/15/2015
Facility name:	CON EDISON
Facility address:	21 SAINT MARKS PL NEW YORK, NY 10009
EPA ID:	NYP004807723
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/15/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069674338

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019905266**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019905266
Registry ID:	110069674338
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069674338

AY804 **CON EDISON** **NJ MANIFEST** **S120673974**
ENE **21 SAINT MARKS PL** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.247 mi.
1302 ft. **Site 5 of 9 in cluster AY**

Relative:
Lower

Actual:
36 ft.

NJ MANIFEST:

EPA Id:	NYP004807723
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612077GBF
EPA ID:	NYP004807723
Date Shipped:	7/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON (Continued) **S120673974**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AV805 **CON EDISON SERVICE BOX: 28842** **NJ MANIFEST** **S120666038**
NNE **765 W BROADWAY** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.247 mi.
1302 ft. **Site 13 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

NJ MANIFEST:

EPA Id:	NYP004395554
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015318564JJK
EPA ID:	NYP004395554
Date Shipped:	2/18/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON SERVICE BOX: 28842 (Continued) **S120666038**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	CONSOLIDATED EDISON CO OF NY SB #28842
Transporter-1 EPA Facility Name:	CLEAN VENTURE INC
TSDF EPA Facility Name:	CYCLE CHEM INC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	2/18/2016
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/19/2016
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AV806 **CON EDISON SERVICE BOX: 28842** **RCRA NonGen / NLR** **1016966710**
NNE **765 W BROADWAY** **NY MANIFEST** **NYP004395554**
1/8-1/4 **NEW YORK, NY 10009**
0.247 mi.
1302 ft. **Site 14 of 15 in cluster AV**

Relative:
Lower

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/21/2013
Facility name:	CON EDISON SERVICE BOX: 28842
Facility address:	765 W BROADWAY NEW YORK, NY 10009
EPA ID:	NYP004395554
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No

CON EDISON SERVICE BOX: 28842 (Continued) **1016966710**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/21/2013
Site name: CON EDISON SERVICE BOX: 28842
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004395554
Facility Status: Not reported
Location Address 1: 765 BROADWAY
Code: BP
Location Address 2: MH28843
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395554
Mailing Name: CON EDISON
Mailing Contact: IHOB TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2013
Trans1 Recv Date: 11/21/2013

CON EDISON SERVICE BOX: 28842 (Continued) **1016966710**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395554
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237145GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BA807 **70 EAST THIRD STREET** **NY AST** **U003396467**
SE **70 EAST THIRD STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10002**
0.247 mi.
1303 ft. **Site 10 of 16 in cluster BA**

Relative: **Lower**

Actual: **36 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602139
Program Type:	PBS
UTM X:	585397.75339
UTM Y:	4508723.93675

70 EAST THIRD STREET (Continued) **U003396467**

Expiration Date: 03/16/2020
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 24098
Affiliation Type: Facility Owner
Company Name: PSA LESAGE LLC
Contact Type: MANAGER
Contact Name: PETER MARCIANO
Address1: P.O. BOX 4536
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10163
Country Code: 001
Phone: (212) 514-2471
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-04-21

Site Id: 24098
Affiliation Type: Facility Operator
Company Name: 70 EAST THIRD STREET
Contact Type: Not reported
Contact Name: FABIAN RODRIGUEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 567-4326
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-03-08

Site Id: 24098
Affiliation Type: Emergency Contact
Company Name: PSA LESAGE LLC
Contact Type: Not reported
Contact Name: PETER MARCIANO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 407-4045
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-04-21

Site Id: 24098
Affiliation Type: Mail Contact
Company Name: PARK SQUARE ASSOCIATES INC.

70 EAST THIRD STREET (Continued) **U003396467**

Contact Type:	Not reported
Contact Name:	PETER MARCIANO
Address1:	P.O. BOX 4536
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10163
Country Code:	001
Phone:	(212) 514-2477
EMail:	PETERMARCIANO@GMAIL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-01-19

Tank Info:

Tank Number:	001
Tank Id:	49287
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BA808
ESE
1/8-1/4
0.247 mi.
1304 ft.

CON EDISON
OPP 108 E 4TH ST
NEW YORK, NY 10003

Site 11 of 16 in cluster BA

NY MANIFEST **S118463743**
N/A

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004856397
Facility Status:	Not reported
Location Address 1:	OPP 108 E 4TH ST
Code:	BP
Location Address 2:	SB 861
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004856397
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2015
Trans1 Recv Date:	10/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004856397
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014085710JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S118463743**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

AV809 **CON EDISON SERVICE BOX: 1360** **RCRA NonGen / NLR** **1016966822**
North **55 E 8TH ST** **NY MANIFEST** **NYP004396636**
1/8-1/4 **NEW YORK, NY 10003**
0.248 mi.
1307 ft. **Site 15 of 15 in cluster AV**

Relative: **Lower**

Actual: **36 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/22/2013
Facility name:	CON EDISON SERVICE BOX: 1360
Facility address:	55 E 8TH ST NEW YORK, NY 10003
EPA ID:	NYP004396636
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON SERVICE BOX: 1360 (Continued) **1016966822**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/22/2013
Site name: CON EDISON SERVICE BOX: 1360
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004396636
Facility Status: Not reported
Location Address 1: 55 E 8TH ST
Code: BP
Location Address 2: SB1360
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004396636
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 11/22/2013
Trans1 Recv Date: 11/22/2013
Trans2 Recv Date: 11/25/2013
TSD Site Recv Date: 11/25/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004396636

CON EDISON SERVICE BOX: 1360 (Continued) **1016966822**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237693GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AX810 **NEW AMSTERDAM THEATER** **RCRA NonGen / NLR** **1001113438**
SE **40 1ST ST** **FINDS** **NYR000024281**
1/8-1/4 **NEW YORK, NY 10013** **ECHO**
0.248 mi.
1307 ft. **Site 7 of 9 in cluster AX**

Relative: **Lower**
Actual: **39 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NEW AMSTERDAM THEATER
Facility address:	40 1ST ST NEW YORK, NY 10013
EPA ID:	NYR000024281
Mailing address:	SEAMAN AVE BETHPAGE, NY 11714
Contact:	Not reported
Contact address:	SEAMAN AVE BETHPAGE, NY 11714
Contact country:	US
Contact telephone:	Not reported

NEW AMSTERDAM THEATER (Continued) **1001113438**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EMPIRE STATE DEVELOPMENT CORP
Owner/operator address: 11 W 42ND ST 21ST FLOOR
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: 212-790-2575
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EMPIRE STATE DEVELOPMENT CORP
Owner/operator address: 11 W 42ND ST 21ST FLOOR
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: 212-790-2575
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NEW AMSTERDAM THEATER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NEW AMSTERDAM THEATER

NEW AMSTERDAM THEATER (Continued) **1001113438**

Classification: Not a generator, verified

Date form received by agency: 05/21/1996
Site name: NEW AMSTERDAM THEATER
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110004525247

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001113438
Registry ID: 110004525247
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004525247

AY811 **CON EDISON** **NY MANIFEST** **S117066649**
ENE **19 ST MARKS PL** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.248 mi.
1309 ft. **Site 6 of 9 in cluster AY**

Relative:
Lower

Actual:
37 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004593265
Facility Status: Not reported
Location Address 1: 19 ST MARKS PL
Code: BP
Location Address 2: SB 40668
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004593265
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK

CON EDISON (Continued) **S117066649**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/11/2014
Trans1 Recv Date:	07/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004593265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002503381GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117066649**

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

812
East
1/8-1/4
0.248 mi.
1309 ft.

314 EAST 6TH STREET
314 EAST 6TH STREET
NEW YORK, NY 10003

NY AST **U003383736**
N/A

Relative:
Lower

Actual:
32 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-061697
Program Type:	PBS
UTM X:	585482.33503
UTM Y:	4508975.77658
Expiration Date:	02/05/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	1110
Affiliation Type:	Facility Owner
Company Name:	D KARNOFSKY INC ALBREN REALTY MANAGEMENT
Contact Type:	TREASURER
Contact Name:	D. KARNOFSKY INC. BY NEAL KURZNER
Address1:	25-31 30TH RD
Address2:	Not reported
City:	ASTORIA
State:	NY
Zip Code:	11102
Country Code:	001
Phone:	(718) 545-5755
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-15

Site Id:	1110
Affiliation Type:	Mail Contact
Company Name:	ALBREN REALTY MANAGEMENT
Contact Type:	Not reported
Contact Name:	NEAL KURZNER
Address1:	25-31 30TH RD
Address2:	1E
City:	ASTORIA
State:	NY
Zip Code:	11102
Country Code:	001
Phone:	(718) 545-5755
EMail:	NKURZNER@ALLBREN.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-15

Site Id:	1110
Affiliation Type:	Facility Operator

314 EAST 6TH STREET (Continued) **U003383736**

Company Name:	314 EAST 6TH STREET
Contact Type:	Not reported
Contact Name:	TYRONE GORDON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 952-4733
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-11-18

Site Id:	1110
Affiliation Type:	Emergency Contact
Company Name:	D KARNOFSKY INC ALBREN REALTY MANAGEMENT
Contact Type:	Not reported
Contact Name:	NEAL KURZNER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 924-2114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-06-15

Tank Info:

Tank Number:	001
Tank Id:	2147
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
K99 - Spill Prevention - Other
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

314 EAST 6TH STREET (Continued) **U003383736**

Install Date:	01/01/1955
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	06/15/2017
Material Name:	#2 fuel oil (on-site consumption)

AY813 **CON EDISON** **RCRA NonGen / NLR** **1019906267**
ENE **23 SAINT MARKS PL** **FINDS** **NYP004819169**
1/8-1/4 **NEW YORK, NY 10009** **ECHO**
0.248 mi.
1310 ft. **Site 7 of 9 in cluster AY**

Relative:
Lower

Actual:
36 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/05/2015
Facility name:	CON EDISON
Facility address:	23 SAINT MARKS PL NEW YORK, NY 10009
EPA ID:	NYP004819169
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/05/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

CON EDISON (Continued) **1019906267**

Violation Status: No violations found

FINDS:

Registry ID: 110069644068

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906267
Registry ID: 110069644068
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069644068

AY814 **CON EDISON** **NY MANIFEST** **S119077035**
ENE **23 SAINT MARKS PL** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.248 mi.
1310 ft. **Site 8 of 9 in cluster AY**

Relative: **Lower**
Actual: **36 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYP004819169
Facility Status: Not reported
Location Address 1: 14 ST MARKS PL
Code: BP
Location Address 2: SB 40666
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10012
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004819169
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON (Continued) **S119077035**

seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2015
Trans1 Recv Date:	08/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004819169
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612730GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

AY815 **CON EDISON** **NJ MANIFEST** **S120675029**
ENE **23 SAINT MARKS PL** **N/A**
1/8-1/4 **NEW YORK, NY 10009**
0.248 mi.
1310 ft. **Site 9 of 9 in cluster AY**

Relative:
Lower

Actual:
36 ft.

NJ MANIFEST:

EPA Id:	NYP004819169
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY061
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612730GBF
EPA ID:	NYP004819169
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675029**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

816
WNW
1/8-1/4
0.248 mi.
1311 ft.

CON EDISON **NY MANIFEST** **S117738107**
52 WEST 3RD STREET **N/A**
NEW YORK, NY 10012

Relative:
Lower

Actual:
31 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004704698
Facility Status:	Not reported
Location Address 1:	52 WEST 3RD STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10012
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004704698
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/10/2014
Trans1 Recv Date:	12/10/2014
Trans2 Recv Date:	12/10/2014
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004704698
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117738107**

Manifest Tracking Number:	002610125GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

AX817 **RUSSIAN ORTHODOX CATHEDRAL OF THE HOLY VIRGIN PROT** **NY AST** **A100295878**
SE **59 EAST 2ND STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.248 mi.
1311 ft. **Site 8 of 9 in cluster AX**

Relative: **Lower**
Actual: **38 ft.**

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608199
Program Type:	PBS
UTM X:	585343.85490
UTM Y:	4508660.97167
Expiration Date:	01/28/2023
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	30051
Affiliation Type:	Facility Owner
Company Name:	RUSSIAN ORTHODOX CATHEDRAL OF THE HOLY VIRGIN PROT
Contact Type:	PARISH ADMINISTRATOR
Contact Name:	FR MICHAEL SUVAK

RUSSIAN ORTHODOX CATHEDRAL OF THE HOLY VIRGIN PROT (Continued) **A100295878**

Address1:	59 E. 2ND ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 677-4664
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-12-26

Site Id:	30051
Affiliation Type:	Mail Contact
Company Name:	RUSSIAN ORTHODOX CATHEDRAL OF
Contact Type:	Not reported
Contact Name:	FR. CHRISTOPHER CALIN
Address1:	THE HOLY VIRGIN PROTECTION
Address2:	59 EAST 2ND STREET
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 677-4664
EMail:	CCALIN@NYC.RR.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-11-08

Site Id:	30051
Affiliation Type:	Facility Operator
Company Name:	RUSSIAN ORTHODOX CATHEDRAL OF THE HOLY VIRGIN PROT
Contact Type:	Not reported
Contact Name:	FR. MICHAEL SUVAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 677-4664
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-11-08

Site Id:	30051
Affiliation Type:	Emergency Contact
Company Name:	RUSSIAN ORTHODOX CATHEDRAL OF THE HOLY VIRGIN PROT
Contact Type:	Not reported
Contact Name:	FR MICHAEL SUVAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

RUSSIAN ORTHODOX CATHEDRAL OF THE HOLY VIRGIN PROT (Continued) **A100295878**

Phone:	(212) 677-4664
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-12-26

Tank Info:

Tank Number:	001
Tank Id:	64879
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1985
Capacity Gallons:	2000
Tightness Test Method:	21
Date Test:	01/28/2003
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	12/26/2017
Material Name:	#2 fuel oil (on-site consumption)

AX818 **CON EDISON SERVICE BOX: 554** **RCRA NonGen / NLR** **1016969830**
SE **59 E 2ND ST** **NY MANIFEST** **NYP004435194**
1/8-1/4 **NEW YORK, NY 10003**
0.248 mi.
1311 ft. **Site 9 of 9 in cluster AX**

Relative: **Lower**
Actual: **38 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/06/2014
Facility name:	CON EDISON SERVICE BOX: 554
Facility address:	59 E 2ND ST NEW YORK, NY 10003
EPA ID:	NYP004435194
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported

CON EDISON SERVICE BOX: 554 (Continued) **1016969830**

Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/06/2014
Site name: CON EDISON SERVICE BOX: 554
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004435194
Facility Status: Not reported
Location Address 1: F/O 59 EAST 2ND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004435194
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON SERVICE BOX: 554 (Continued) **1016969830**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/06/2014
Trans1 Recv Date:	02/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004435194
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329306GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

819 SSW 1/8-1/4 0.249 mi. 1317 ft. | **ST PATRICK'S CHURCH**
264 MULBERRY ST
NY, NY 10012 | **NY UST** | **U000400982**
N/A

Relative: Lower

Actual: 40 ft.

UST:

Id/Status:	2-280232 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584869.06009
UTM Y:	4508576.50035
Site Type:	Unknown

Affiliation Records:

Site Id:	12233
Affiliation Type:	Facility Owner
Company Name:	ST PATRICKS RECTORY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	EW YORK263 MULBERRY STREET
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10012
Country Code:	001
Phone:	(212) 226-8075
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12233
Affiliation Type:	Mail Contact
Company Name:	CASTLE SERVICE CO.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	500 MAMARONECK AVENUE
Address2:	Not reported
City:	ARRISON
State:	NY
Zip Code:	10528-1600
Country Code:	001
Phone:	(914) 723-2620
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12233
Affiliation Type:	Facility Operator
Company Name:	ST PATRICKS CHURCH
Contact Type:	Not reported
Contact Name:	RICARDO TAVAREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

ST PATRICK'S CHURCH (Continued) **U000400982**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 226-8075
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12233
Affiliation Type:	Emergency Contact
Company Name:	ST PATRICKS RECTORY
Contact Type:	Not reported
Contact Name:	REV. KAITH FENNESSY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 226-8075
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	14564
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	12/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

BA820 **NYC DEPT OF EDUCATION - PS 751M** **RCRA-SQG** **1018159339**
ESE **113 E 4TH ST** **FINDS** **NYR000224444**
1/8-1/4 **NEW YORK, NY 10003** **ECHO**
0.249 mi.
1317 ft. **Site 12 of 16 in cluster BA**

Relative:
Lower

Actual:
33 ft.

RCRA-SQG:

Date form received by agency:	10/20/2015
Facility name:	NYC DEPT OF EDUCATION - PS 751M
Facility address:	113 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYR000224444
Mailing address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact:	ALEXANDER LEMPERT
Contact address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	718-472-8501
Contact email:	ALEMPERT@NYCSCA.ORG
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NYC DEPT OF EDUCATION
Owner/operator address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	718-472-8501
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	02/15/1894
Owner/Op end date:	Not reported
Owner/operator name:	NYC DEPT OF SCHOOL FACILITIES
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	02/15/1894
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

NYC DEPT OF EDUCATION - PS 751M (Continued) **1018159339**

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: B004
. Waste name: B004

. Waste code: B007
. Waste name: B007

Violation Status: No violations found

FINDS:

Registry ID: 110067044772

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018159339
Registry ID: 110067044772
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067044772

BA821 **NYC DEPT OF EDUCATION - PS 751M** **NY MANIFEST** **S118708585**
ESE **113 E 4TH ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.249 mi.
1317 ft. **Site 13 of 16 in cluster BA**

Relative: **Lower**
Actual: **33 ft.**

NY MANIFEST:
Country: USA
EPA ID: NYR000224444
Facility Status: Not reported
Location Address 1: 113 EAST 4TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK

NYC DEPT OF EDUCATION - PS 751M (Continued) **S118708585**

Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000224444
Mailing Name:	NYC DEPT OF EDUCATION - PS 751M
Mailing Contact:	NYC DEPT OF EDUCATION - PS 751M
Mailing Address 1:	113 E 4TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9733320411

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2016
Trans1 Recv Date:	06/11/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000224444
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	015625756JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels

NYC DEPT OF EDUCATION - PS 751M (Continued) **S118708585**

Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

BA822 **CON EDISON** **NY MANIFEST** **S117066479**
ESE **113 E 4 ST** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.249 mi.
1317 ft. **Site 14 of 16 in cluster BA**

Relative:
Lower

Actual:
33 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004591327
Facility Status:	Not reported
Location Address 1:	113 E 4 ST
Code:	BP
Location Address 2:	SB 863
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10003
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004591327
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2014
Trans1 Recv Date:	07/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON (Continued) **S117066479**

Generator EPA ID:	NYP004591327
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423985GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BA823 **CON EDISON SERVICE BOX: 862** **RCRA NonGen / NLR** **1016451009**
ESE **113 E 4TH ST** **NY MANIFEST** **NYP004300430**
1/8-1/4 **NEW YORK, NY 10003**
0.249 mi.
1317 ft. **Site 15 of 16 in cluster BA**

Relative: **Lower**
Actual: **33 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/26/2014
Facility name:	CON EDISON SERVICE BOX: 862
Facility address:	113 E 4TH ST NEW YORK, NY 10003
EPA ID:	NYP004300430
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported

CON EDISON SERVICE BOX: 862 (Continued) **1016451009**

Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/26/2014
Site name: CON EDISON SERVICE BOX: 862
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004300430
Facility Status: Not reported
Location Address 1: 113 E 4TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10003
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004300430
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON SERVICE BOX: 862 (Continued) **1016451009**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/10/2013
Trans1 Recv Date:	04/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004300430
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841413JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BA824 **P.S. 751 (CAR/DEV/OLD 25)-M M751** **NY AST** **A100173598**
ESE **113 EAST 4TH STREET** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.249 mi.
1317 ft. **Site 16 of 16 in cluster BA**

Relative:
Lower

Actual:
33 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604838
Program Type:	PBS
UTM X:	585489.72753
UTM Y:	4508810.77615
Expiration Date:	04/17/2022
Site Type:	School

Affiliation Records:

Site Id:	26707
Affiliation Type:	Facility Operator
Company Name:	P.S. 751 (CAR.DEV/OLD 25) - M751
Contact Type:	Not reported
Contact Name:	WILLIAM HERNANDEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 475-4589
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-07-18

Site Id:	26707
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	44-36 VERNON BLVD.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-10-13

Site Id:	26707
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BLVD.
City:	LONG ISLAND CITY

P.S. 751 (CAR/DEV/OLD 25)-M M751 (Continued) **A100173598**

State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	MSHARMA@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-12-19

Site Id:	26707
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-10-13

Tank Info:

Tank Number:	001
Tank Id:	63317
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2001
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported

P.S. 751 (CAR/DEV/OLD 25)-M M751 (Continued) **A100173598**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	TWO
Tank Id:	58990
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/2001
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BG825 **1 UNIVERSITY PLACE** **NY AST** **U003383432**
NNW **1 UNIVERSITY PLACE** **N/A**
1/8-1/4 **NEW YORK, NY 10003**
0.250 mi.
1320 ft. **Site 1 of 2 in cluster BG**

Relative:
Lower

Actual:
32 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-045705
Program Type:	PBS
UTM X:	584859.72679
UTM Y:	4509362.40826
Expiration Date:	12/02/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	592
Affiliation Type:	Facility Owner

1 UNIVERSITY PLACE (Continued) **U003383432**

Company Name:	PIK RECORDS CO C/O THE ALPERT GROUP
Contact Type:	AGENT
Contact Name:	ORI ALPERT
Address1:	271 MADISON AVE-22ND FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 532-0816
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-02-08

Site Id:	592
Affiliation Type:	Facility Operator
Company Name:	1 UNIVERSITY PLACE
Contact Type:	Not reported
Contact Name:	CIRILLO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 532-0816
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-02-08

Site Id:	592
Affiliation Type:	Emergency Contact
Company Name:	PIK RECORDS CO C/O THE ALPERT GROUP
Contact Type:	Not reported
Contact Name:	FRANK YAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 532-0816
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-02-08

Site Id:	592
Affiliation Type:	Mail Contact
Company Name:	ABILENE INC.
Contact Type:	Not reported
Contact Name:	FRANK YAN
Address1:	2402 NEPTUNE AVENUE
Address2:	Not reported
City:	BROOKLYN

1 UNIVERSITY PLACE (Continued) **U003383432**

State:	NY
Zip Code:	11224
Country Code:	001
Phone:	(718) 372-4210
EMail:	FRANK@ABILENEINC.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-02-09

Tank Info:

Tank Number:	031
Tank Id:	1448
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/07/1930
Capacity Gallons:	6500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

---

826 **ABOVE GROUND TTF** **NY LTANKS** **S112231298**
SSE **39 EAST FIRST STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.255 mi.
1346 ft.

Relative: **Lower**
Actual: **39 ft.**

LTANKS:

Facility ID:	1210187
Site ID:	473262
Closed Date:	2015-11-17
Spill Number:	1210187
Spill Date:	2012-11-12
Spill Cause:	Tank Test Failure

ABOVE GROUND TTF (Continued) **S112231298**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2012-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-12
Spill Record Last Update:	2015-11-17
Spiller Name:	SHAWN BUSTIAEZO
Spiller Company:	UNKNOWN
Spiller Address:	39 EAST FIRST STREET
Spiller County:	999
Spiller Contact:	SHAWN BUSTIAEZO
Spiller Phone:	(856) 813-3000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	427500
DEC Memo:	"09/17/15-Hiralkumar Patel. DEC Austin assigned this case on 06/24/15. alternate address: 39A E 1st Street no PBS record found. other spill # 9412743 was reported 12/22/1994 as 2 gal #2 fuel oil was spilled. case closed. 39 East 1 Realty LLC. **property owner** c/o Icon Realty Management 419 Lafayette Street, 5th Floor New York, NY 10003 Attn.: Terrence Lowenberg Ph. (212) 661-2700 email: terrence@iconrealtymgmt.com 09/18/15-Hiralkumar Patel. 10:05 AM:- visited site and met Arnold. site has one AST completely wrapped in cinder block/concrete. no signs of oil seepage noted from the weep holes in tank wrap. all lines run aboveground within building basement. the fill and vent line cross the concrete floor and run aboveground near northwest corner of the building. the active fill port is aboveground near the building wall. during visit, noted an abandoned fill port by the curb in northwest area of the site. Frank **building super** PH. (718) 913-1188 10:11 AM:- spoke with representative at ATS. as per their record, on-site building has 1,000 gal tank. there was no further work done at the site by ATS after initial test failure in Nov. 2012. 11:12 AM:- received message from Brett Gartenberg (646-362-8851). 11:47 AM:- spoke with Brett. informed him about the open spill case. he asked to send correspondence to Mr. Lowenberg. Brett Gartenberg JM Zoning 299 Broadway, Suite 1100 New York, NY 10007 Ph. (646) 362-8851 Fax (775) 628-3726 email: bgartenberg@jmzoning.com 12:08 PM:- sent letter to Mr. Lowenberg requiring submission of documents related to tank test failure investigation/cleanup by the end of 10/16/15. letter emailed to Mr. Lowenberg. 09/24/15-Hiralkumar Patel. 8:51 AM:- received call from Mr. Lowenberg. he has some documents related to the site and will email it. 9:27 AM:- received email from Brett including copy of tank test result dated 05/24/2013. PTC tested the tank system on 05/24/13 and it passed. no documents received regarding cause of the failure and actions taken. 1:44 PM:- left message for Mr. Lowenberg.

ABOVE GROUND TTF (Continued) **S112231298**

1:48 PM:- spoke with representative at PTC who confirmed that they only did tank system test on 05/24/13 and no other work was performed by PTC at the site. 1:58 PM:- sent email to Mr. Lowenberg and informed him to submit required documents as per letter dated 09/18/15. email copied to Brett. 3:17 PM:- received call from Mr. Lowenberg. he mentioned that the initial test on 11/12/2012 was conducted by a contractor working for potential buyer at that time. Mr. Lowneberg stated that the test in Nov. 2012 was inconclusive possibly due to vent pipe. he claimed that no repair work was performed on the tank system after failure report in Nov. 2012 and tank system was retested in 2013 when it passed. asked him when was the fill port at the curb was closed. he was not aware of the closed fill port at the curb. he will review files and call back. 11/03/15-Hiralkumar Patel. 2:38 PM:- sent email to Mr. Lowenberg and asked him to submit required report immediately. email copied to Brett and Melissa DiGiacomo (melissa@iconrealtymgmt.com). 11/17/15-Hiralkumar Patel. received email from Ms. DiGiacomo (at 12:36 PM on 11/09/15) including a letter with result of tank system test dated 05/24/13. in the letter, Mr. Lowenberg mentioned that Approved Oil inspected the tank system in Jan. 2013 and found leak in the tank system due to a failed vent port. Approved Oil replaced the vent and fill port on, or around 01/25/2013. after that, the tank system was retested on 05/24/13 and it was found tight. case closed based on available information. as per the tank system test result, the site has 1,500 gallon tank which requires to be registered. 2:37 PM:- sent email to Mr. Lowenberg including copy of PBS application and instructions. asked him to immediately register the 1,500 gallon tank system at the site. email copied to Melissa, Brett, Joey Goldzal (joey@jmzoning.com) and DEC Leszek. 2:44 PM:- sent spill closure letter to Mr. Lowenberg. letter emailed to Mr. Lowenberg, Melissa, Brett and Joey Goldzal. 2:45 PM:- received email from Mr. Lowneberg including copy of PBS certificate (# 2-329487)."

Remarks: "apartment building - failed tank test repair and retest"

All Materials:

Site ID:	473262
Operable Unit ID:	1223111
Operable Unit:	01
Material ID:	2221864
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AZ827 **212-218 NORTH 9TH STREET** **NY VCP** **S118943259**
NE **212-218 NORTH 9TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.259 mi.
1369 ft. **Site 8 of 8 in cluster AZ**

Relative:
Lower

Actual:
38 ft.

VCP NYC:
Project ID: 13CVCP122K
Project Name: 212-218 NORTH 9TH STREET
Project Address: 212-218 NORTH 9TH STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 13CVCP122K
File Name: 2013-04-10.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP122K/2013-04-10.13CVCP122K.212-218_North_9th_Street.Remedial_Investigation_Report.pdf

Project ID: 13CVCP122K
File Name: 2013-04-10.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP122K/2013-04-10.13CVCP122K.212-218_North_9th_Street.Remedial_Action_Plan_draft.pdf

Project ID: 13CVCP122K
File Name: 2013-04-10.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP122K/2013-04-10.13CVCP122K.212-218_North_9th_Street.FactSheet-1.link

Project ID: 13CVCP122K
File Name: 2013-04-11.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP122K/2013-04-11.13CVCP122K.212-218 North 9th Street.FactSheet1-translated.pdf

Project ID: 13CVCP122K
File Name: 2013-04-11.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP122K/2013-04-11.13CVCP122K.212-218 North 9th Street.Community_Protection_Statement-translated.pdf

---

BD828 **OLMSTEAD PROPERTIES, LLC.** **NY LTANKS** **S107783925**
SW **584 BROADWAY** **N/A**
1/4-1/2 **NEW YORK, NY**
0.263 mi.
1387 ft. **Site 3 of 4 in cluster BD**

Relative:
Lower

Actual:
37 ft.

LTANKS:
Facility ID: 1306357
Site ID: 486965
Closed Date: 2013-12-17
Spill Number: 1306357
Spill Date: 2013-09-17
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: Not reported

OLMSTEAD PROPERTIES, LLC. (Continued) **S107783925**

SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2013-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-17
Spill Record Last Update:	2013-12-17
Spiller Name:	Not reported
Spiller Company:	OLMSTEAT PROPERTIES
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	OLMSTEAD PROPERTIES, LLC.
Spiller Phone:	(212) 334-8400
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	442066
DEC Memo:	"09/23/13-Hiralkumar Patel. alternate address: 584-590 Broadway, 116-122 Crosby Street PBS #: 2-605044. as per PBS record, the site has two 7,500 gal #6 oil ASTs in contact with soil. the tanks were installed in Feb. 1953. other spill # 0012623 was reported on 02/27/2001 due to 2 pint of unknown petroleum found in ConEd manhole at the site. case closed. 584 Broadway LLC. **property owner** c/o Olmstead Propoerties, Inc. 575 8th Avenue, Suite 2400 New York, NY 10018 Attn.: Cesar Vasquez **property manager** PH. (212) 334-8400 Ext. 12 NYC DOB permit approved on 08/22/13 for grade change from #6 to #2 oil. 10:40 AM:- spoke with Mark at PTC. they are working as sub-contractor. Mark mentioned that the tanks are aboveground and possibly sitting on floor. PTC will pump out tanks on 10/04/13. 12:27 PM:- received call from Tom, building super. informed him that the department requires isolation test of the system. Tom mentioned that both tanks are covered with cinder blocks. Tom Krasniqi **building super** Ph. (212) 334-8400 Ext. 23 Fax (212)925-4353 email: tkrasniqi@olmsteadinc.com 10/10/13-Hiralkumar Patel. 4:00 PM:- visited site. its 12 story commercial building, with two level basement. met Tom, building super. inspected tanks located in sub-basement of the site. PTC crew was on-site, cleaning tank's interior. the two 7,500 gal tanks are located aboveground, completely wrapped in cinder blocks. no petroleum odors were noted in building, other than tank room where crew was working. Tom mentioned that isolation test will be done. 4:26 PM:- spoke with Mr. Vasquez. as tanks were installed in 1953 and not visible for inspection, strongly suggested him to remove these tanks and install a new tank completely aboveground. 10/15/13-Hiralkumar Patel. 10:35 AM:- received email from Tom. he mentioned that both tanks were tested and found tight. a small leak was found on the vent line for Tank #1 and a coupling needs to be replaced on the oil line. repair work has been scheduled for tomorrow. 12:39 PM:- sent email to Tom. informed him that both tank systems mus be retested after repairs and results must be submitted for review. email copied to Mr. Vasquez. 12/11/13-Hiralkumar Patel. 4:05 PM:- left message for Tom. 4:06 PM:-

OLMSTEAD PROPERTIES, LLC. (Continued) **S107783925**

sent email to Tom inquiring about tank system test results. email copied to Mr. Vasquez. 12/12/13-Hiralkumar Patel. 10:04 AM:- spoke with PTC desk person. she mentioned that after tanks cleaning, both tank only passed. during retesting of tank systems, they found issue with vent and fill line on tank 1 and fill line on tank 2. building management did required repair and both tank systems were tested on 10/23/13, when it passed. tank test results will be submitted for review. 10:11 AM:- spoke with Mr. Vasquez. he mentioned that corrsion found on fill and vent line. they changed both fill and vent lines under the sidewalk and installed new lines in same location. he confirmed that no contamination was found. asked him to submit a report confirming this. he will talk to contractor who performed line work. 10:15 AM:- received email from PTC including tank system test results. both tank systems were tested on 10/23/13 and passed. 12/13/13-Hiralkumar Patel. 3:07 PM:- received email from Anthony Fischetti or Champion Combustion including a letter report. Anthony mentioned that they replaced both fill and vent lines and tested. 12/16/13-Hiralkumar Patel. 11:01 AM:- sent email to Anthony and asked to submit document confirming condition of subsurface soil where fill and vent lines were located. 12/17/13-Hiralkumar Patel. received email from Anthony (at 5:42 PM on 12/16/13). he stated that the sidewalk where the fill and vent are located is vaulted and the underside of the sidewalk is the basement of the building. he confirmed that all piping are visible from beneath. based on available information and documents, case closed."

Remarks: "two failures/7500 gal tanks"

All Materials:

Site ID:	486965
Operable Unit ID:	1236607
Operable Unit:	01
Material ID:	2236032
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BF829 **181 MERCER STREET** **NY VCP** **S121133126**
WSW **181 MERCER STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.264 mi.
1395 ft. **Site 2 of 4 in cluster BF**

Relative: **Lower**
Actual: **32 ft.**

VCP NYC:

Project ID:	17CVCP040M
Project Name:	181 MERCER STREET
Project Address:	181 MERCER STREET
Borough:	MANHATTAN

VCP NYC:

Project ID:	17CVCP040M
File Name:	2017-01-27.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/17CVCP040M/2017-02-01.15TMP0111M.RIR Phase II Report.Draft Final

181 MERCER STREET (Continued) **S121133126**

RIR.pdf

Project ID: 17CVCP040M
File Name: 2017-01-27.Draft_RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/17CVCP040M/2017-02-01.15TMP0111M.RAPRAWP.Draft RAWP.pdf

Project ID: 17CVCP040M
File Name: 2017-01-27.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/17CVCP040M/2017-01-27.17CVCP040M.Doc.181_Mercer_Street.Factsheet-1.OER.pdf

Project ID: 17CVCP040M
File Name: 2017-01-27.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/17CVCP040M/2017-01-27.17CVCP040M.Doc.181_Mercer_Street.Translated_Factsheet-1.OER.pdf

Project ID: 17CVCP040M
File Name: 2017-01-27.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/17CVCP040M/2017-01-27.17CVCP040M.Doc.181_Mercer_Street.Translated_CPS.OER.pdf

---

BG830 **NEW YORK UNIVERSITY** **NY LTANKS** **S102672923**
NNW **1ST AVE/30TH-33RD STS.** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.264 mi.
1396 ft. **Site 2 of 2 in cluster BG**

Relative: **Lower**
Actual: **31 ft.**

LTANKS:

Facility ID:	9501895
Site ID:	110229
Closed Date:	1995-05-15
Spill Number:	9501895
Spill Date:	1995-05-15
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1995-05-15
SWIS:	3101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1995-05-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-26
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	MYSTIC OIL CO

NEW YORK UNIVERSITY (Continued) **S102672923**

Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96640
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"DELIVERY TRUCK OVERFILLED TANK CAUSING 4-5 GAL TO SPILL ONTO GROUND (PAVEMENT) - ALL RECOVERED WITH PADS."

All Materials:

Site ID:	110229
Operable Unit ID:	1013033
Operable Unit:	01
Material ID:	366970
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

BH831 **72 SOUTH SECOND STREET** **NY VCP** **S121796996**
SE **72 SOUTH SECOND STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.270 mi.
1428 ft. **Site 1 of 3 in cluster BH**

Relative:
Lower

Actual:
36 ft.

VCP NYC:

Project ID:	18CVCP030K
Project Name:	72 SOUTH SECOND STREET
Project Address:	72 SOUTH SECOND STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	18CVCP030K
File Name:	2017-11-03.RIR_Final
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP030K/2017-11-03.18TMP0135K.72 South Second Street.RIR.pdf

Project ID:	18CVCP030K
File Name:	2017-12-27.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP030K/2017-12-27.18TMP0135K.72 South Second Street.RAWP_Draft.pdf

Project ID:	18CVCP030K
File Name:	2017-12-22.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP030K/2017-12-22.18TMP0135K.72 South Second Street.Fact Sheet-1.pdf

Project ID:	18CVCP030K
File Name:	2017-12-22.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/1

72 SOUTH SECOND STREET (Continued) **S121796996**

8CVCP030K/2017-12-22.18TMP0135K.72 South Second Street.Fact Sheet-1_translated.pdf

Project ID: 18CVCP030K
File Name: 2017-12-22.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP030K/2017-12-22.18TMP0135K.72 South Second Street.Community Protection Statement.pdf

---

832 North 1/4-1/2 0.271 mi. 1429 ft.

BASEMENT
60 EAST 9TH ST
MANHATTAN, NY

NY LTANKS **S102560153**
NY Spills **N/A**

Relative: Lower

Actual: 36 ft.

LTANKS:

Facility ID:	1401198
Site ID:	494471
Closed Date:	2015-09-17
Spill Number:	1401198
Spill Date:	2014-05-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2014-05-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-05-05
Spill Record Last Update:	2015-09-17
Spiller Name:	GEORGE
Spiller Company:	EFFICIENT COMBUSTION
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CHRIS STEELE
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	132094
DEC Memo:	"proposal is out for repairs and retest . PTC will notify dept if they are not contracted . TTF letter on hold. 05/12/14-Hiralkumar Patel. alternate addresses: 757-769 Broadway, 63-75 East 8th Street, 54-68 East 9th Street other spill # 9612434 was reported on 01/17/1997 due to leak from cracked fill line. case closed. PBS #: 2-289779. as per PBS record, the site has one 10,000 gal #6 oil AST in subterranean vault with access. the tank was installed in Oct. 1960. 60 East 9th Street Owners Corp. **property owner** c/o Rose Associates, Inc. 200 Madison Avenue, 5th Floor New York, NY 10016

BASEMENT (Continued) **S102560153**

Attn.: Matthew Providente Ph. (212) 328-5539 email: mprovidente@rosenyc.com 12:36 PM:- left message for Matthew Providente, authorized representative listed in PBS. 09/02/14-Hiralkumar Patel. 1:30 PM:- spoke with Ray at PTC. he mentioned that no further work done by PTC at the site. he asked to contact George at Efficient Combustion. 1:33 PM:- spoke with Geore at Efficient Combustion. he mentioned that leak was found in vent line. asked him to submit documents including cause of failure, cleanup of any petroleum release and result of system retest. George Efficient Combustion PH. (516) 795-5828 09/29/14-Hiralkumar Patel. 2:29 PM:- left message for George. 11/12/14-Hiralkumar Patel. 1:46 PM:- left message for Mr. Hollweg, property manager. 60 East 9th Street Owners Corp. **property owner** c/o Rose Associates, Inc. 200 Madison Avenue, 5th Floor New York, NY 10016 Attn.: David Von Hollweg **property manager** Ph. (212) 210-6666/6686 email: dvonhollweg@rosenyc.com 1:55 PM:- sent TTF letter to Mr. Hollweg requiring report submission by the end of 12/31/14. letter emailed to Mr. Hollweg. 11/14/14 - Austin - Received call from Jennifer Armstrong of Langon Engineering (212-479-5537). She indicated that Langon has been retained by the building owners to investigate the soil contamination from this tank test failure, and she wanted to know the process for getting our assistance in getting street and subway access permits for the boringsings (work would adjoin a subway, and one of the points wouldbe in a tree well, which would need NYC Parks approval...?). Referred her to NYCT and NYCDOT. I told her she needs to speak with the tank tester to get a better idea as to what the tank test showed, to assure this was not a dry leak . She replied that she was told that there is some evidence of oil seepage, no further info given. Informed her that any such investigatory work would need the approval from DEC before proceeding. Gave her the DEC project manager's name (Kumar Patel) and his direct phone #. - end 12/01/14-Hiralkumar Patel. 3:25 PM:- received message from Mike Burke from Langan Engineering. Mike Burke Langan Engineering Ph. (212) 479-5413 Jennifer Armstrong Langan Engineering PH. (212) 479-5537 12/02/14-Hiralkumar Patel. 8:16 AM:- left message for Jennifer at Langan. 8:43 AM:- received call from Mike and Jennifer from Langan. after grade conversion from #6 to #4 oil, an oil seepage was noted from area where the remote fill line enters the basement. currently, the leaking remote fill line is out of service. Langan is planning to open the sidewalk for removal of leaking fill line and any associated contamination. besides NYC DOT, they need permit from MTA (a subway line within 100 ft) and NYC Parks (remote fill port near a tree well). Mike will send email with work plan and schedule. 12/04/14-Hiralkumar Patel. received message from Jennifer (at 5:05 PM on 12/03/14). 9:44 AM:- spoke with Jennifer. she mentioned that the building needs an oil delivery and they are planning to install a new fill line near the building foundation wall, in area where the existing leaking fill line is located. owner is planning to remove sidewalk flags near the building wall for fill line installation. informed Jennifer that the Department requires a document, from the contractor, confirming condition of subsurface soil in the proposed excavation area, including color photographs of the excavation. informed her that any contamination must be removed/remediated. she mentioned that a permit package will be submitted to MTA today and to NYCDOT in near future. 12/12/14-Hiralkumar Patel. 2:58 PM:- received email from Jennifer including remediation work plan. Langan proposed to excavate and remove the leaking fill line and associated

BASEMENT (Continued) **S102560153**

contamination, and to collect endpoint samples. they have submitted plans to MTA on 12/10/14 and waiting for response. 12/22/14-Hiralkumar Patel. received email from Jennifer (at 4:44 PM on 12/19/14) requesting deadline extension for report submission as approvals needed from various agencies. 12/26/14-Hiralkumar Patel. 1:28 PM:- left message for (and sent email to) Jennifer and asked her to call back to discuss deadline extension. 12/29/14-Hiralkumar Patel. 1:44 PM:- received call from Jennifer. they are waiting for approval from MTA and then submit permit application to NYC DOT. she believes that field work can begin in Feb. 2015. as the leaking line is not in use and requires approval from multiple agencies, approved Jennifer's request to submit report by the end of 03/13/15. 01/21/15-Hiralkumar Patel. 11:55 AM:- received email from Jennifer. they got OK from MTA and DOT. now they will apply permit application to NYC Parks. 02/04/15-Hiralkumar Patel. 1:28 PM:- received email from Jennifer. contractor has submitted permit application to NYC Parks. 03/26/15-Hiralkumar Patel. 12:09 PM:- received email from Jennifer. they received permit from parks dept. they are planning to start excavation on 04/06/15. Jennifer requested time extention to end of April for report submission. 04/10/15-Hiralkumar Patel. 3:02 PM:- spoke with Jennifer. she mentioned that contractor has set up temporary pedestrian walkway today and will start soil excavation on 04/13/15. 04/14/15-Hiralkumar Patel. 10:36 AM:- received message from Jennifer. they finished excavation yesterday and has collected endpoint samples. she mentioned that the excavation was about 4 ft deep. 09/08/15-Hiralkumar Patel. 12:13 PM:- received email from Jennifer including link to cleanup report. - the leaking fill line was replaced - petroleum impacted soil was first observed approx. 18 inches below sidewalk grade adjacent to the building wall - impacts visibly extended to a depth of about 44 inches bg and upto approx. 24 inches away from the building - 0.9 tons of impacted soil was removed - four endpoint samples were collected: three from sidewalls (east, west and south) and one from bottom - north sidewall of the excavation was the building wall - no contamination noted in endpoint samples 09/10/15-Hiralkumar Patel. 1:30 PM:- sent email to Mr. Hollweg and asked him to submit immediately a letter confirming cause of initial test failure and result of tank system retest. email copied to Jennifer and Mike at Langan. 09/15/15-Hiralkumar Patel. received email from Jennifer (at 12:47 PM on 09/14/15) including result of tightness test of the newly installed fill line. the line was found tight during test on 04/14/15. 09/16/15-Hiralkumar Patel. 10:22 AM:- received message from Mike. 10:28 AM:- spoke with Mike. he mentioned that the tank system is aboveground, except portion of fill line and vent line. he inspected the site and had not observed any leak from tank bottom or supply/return/vent lines. the fill line was recently replaced and tested tight. he will submit revised report. 09/17/15-Hiralkumar Patel. 8:08 AM:- received email from Jennifer including link to revised report. case closed based on available information. 11:12 AM:- sent spill closure letter to Mr. Hollweg. letter emailed to Mr. Hollweg and Jennifer."

Remarks: "7500gal tank"

All Materials:
Site ID: 494471
Operable Unit ID: 1243987
Operable Unit: 01
Material ID: 2244733
Material Code: 0002A

BASEMENT (Continued) **S102560153**

Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	9612434
Facility Type:	ER
Spill Number:	9612434
DER Facility ID:	132094
Site ID:	156059
DEC Region:	2
Closed Date:	1997-01-21
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3101
Spill Date:	1997-01-17
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1997-01-17
CID:	369
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-17
Spill Record Last Update:	1997-04-17
Spiller Name:	JOHN SANTARIA
Spiller Company:	CENTURY OPERATING
Spiller Address:	60 EAST 9TH ST
Spiller Company:	001
Contact Name:	JOHN SANTARIA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE APT EXCAVATION 5500 GLS ORDERED. SIDEWALK WAS DUG UP. LINE NOT REPAIRED. CUSTOMER COORDINATING A CLEAN UP CREW AND SOMEONE TO FIX IT TO THEM. EXCAVATION COVERED W/PLYWOOD. 71 EAST 8TH ST. IS WHERE THE FILL LINE IS.DIGGING UP FILL LINE TO FIX AND THE TOLD THE OIL CO TO MAKE A DROP. CONTROL COMBUSTION TO REPAIR LINE.STEVE KING 908-750-6707. CLEANED BY RP"
Remarks:	"CRACKED FILL LINE AT GAS STATION LEAKED INTO PADS"

All Materials:

Site ID:	156059
Operable Unit ID:	1043948
Operable Unit:	01
Material ID:	341079
Material Code:	0003A
Material Name:	#6 fuel oil

BASEMENT (Continued) **S102560153**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

833 **NYU FACILITY** **NY LTANKS** **S102672866**
NW **7-13 WASHINGTON SQUARE** **N/A**
1/4-1/2 **NEW YORK, NY**
0.274 mi.
1449 ft.

Relative: **Lower**

Actual: **30 ft.**

LTANKS:

Facility ID:	9416113
Site ID:	99990
Closed Date:	2003-08-11
Spill Number:	9416113
Spill Date:	1995-03-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1995-03-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-04-27
Spill Record Last Update:	2003-08-11
Spiller Name:	Not reported
Spiller Company:	EMPIRE STATE FUEL OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	88825
DEC Memo:	""
Remarks:	"LEAK IN PIPE FROM TANK; SPILL CONTAINED; CLEAN UP CREW ON THE WAY. NEW TANK - OIL COMPANY STUCK TANK - STILL OVERFILLED ANYWAY - TONY CALLED OIL COMP. - THEY SHOULD BE BACK."

All Materials:

Site ID:	99990
Operable Unit ID:	1013383
Operable Unit:	01
Material ID:	371278
Material Code:	0003A

NYU FACILITY (Continued) **S102672866**

Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF834 **165 MERCER ST** **NY LTANKS** **S102232679**
WSW **165 MERCER ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.275 mi.
1454 ft. **Site 3 of 4 in cluster BF**

Relative: **Lower**
Actual: **31 ft.**

LTANKS:

Facility ID:	9601951
Site ID:	89426
Closed Date:	1996-05-28
Spill Number:	9601951
Spill Date:	1996-05-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1996-05-09
CID:	351
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-09
Spill Record Last Update:	1996-05-28
Spiller Name:	JAY EVETTE
Spiller Company:	MERCER PARKING GARAGE
Spiller Address:	165 MERCER ST
Spiller County:	001
Spiller Contact:	JAY EVETTE
Spiller Phone:	(212) 226-5578
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	81674
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 2 x 550 UST's IN UNDERGROUND PARKING GARAGE WITH ONE DISPENSER. RP HIRE TONE PUMP & TANK TO EIR. TONE FOUND LEAK IN DISPENSER UNIT AND REPAIRED. NO IMPACT TO SUBSURFACE."
Remarks:	"caller was testing a discharge line and found that it could not hold ther required pressure"

All TTF:

Facility ID:	9601951
Spill Number:	9601951

165 MERCER ST (Continued) **S102232679**

Spill Tank Test:	1544533
Site ID:	89426
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	89426
Operable Unit ID:	1033513
Operable Unit:	01
Material ID:	351746
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI835 **RESIDENCE** **NY LTANKS** **S104516638**
East **51 E 7TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.277 mi.
1460 ft. **Site 1 of 3 in cluster BI**

Relative: **Lower**
Actual: **31 ft.**

LTANKS:

Facility ID:	9913497
Site ID:	295238
Closed Date:	2003-08-22
Spill Number:	9913497
Spill Date:	2000-02-29
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2000-02-29
CID:	371
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

RESIDENCE (Continued) **S104516638**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-29
Spill Record Last Update:	2003-08-22
Spiller Name:	CALLER
Spiller Company:	MYSTIC OIL
Spiller Address:	19-01 STEINWAY ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	238906
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 8/22/03 - MINOR SURF SPILL - CLOSE IN DATABASE - ORIG. ASSIGNED TO ROMMEL - END"
Remarks:	"driver missed fill alarm due to passing vehicle -- clean up in progress and expected to be complete."

All Materials:

Site ID:	295238
Operable Unit ID:	1088021
Operable Unit:	01
Material ID:	295344
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI836 **SPILL NUMBER 9913513** **NY LTANKS** **S104620879**
East **51 EAST 7TH ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.277 mi.
1460 ft. **Site 2 of 3 in cluster BI**

Relative: **Lower**
Actual: **31 ft.**

LTANKS:

Facility ID:	9913513
Site ID:	77298
Closed Date:	2000-02-29
Spill Number:	9913513
Spill Date:	2000-02-29
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2000-02-29
CID:	281
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported

SPILL NUMBER 9913513 (Continued) **S104620879**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-29
Spill Record Last Update:	2000-02-29
Spiller Name:	Not reported
Spiller Company:	MYSTIC OIL
Spiller Address:	19-01 STEINWAY ST
Spiller County:	001
Spiller Contact:	DEBORAH GAVITO
Spiller Phone:	(212) 982-6364
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	72152
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL closed cross referenced to 9913497."
Remarks:	"CALLER STATES THAT DURING DELIVERY TO BUILDING NEXT TO HERS ABOVE MATERIAL DISCOVERED SPILLED. MATERAIL IS ON SIDEWALK AND BASEMENT OF CALLERS BUILDING. MYSTIC ON SCENE AND CLEANUP IS IN PROGRESS. CALLER STATES ON GOING PROBLEM. CALLER REQUEST CALL BACK FROM DEC REP."

All Materials:

Site ID:	77298
Operable Unit ID:	1092057
Operable Unit:	01
Material ID:	295356
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH837 **APARTMENT BLDG** **NY LTANKS** **S117853874**
ESE **86 E 3RD ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.285 mi.
1503 ft. **Site 2 of 3 in cluster BH**

Relative: **Lower**
Actual: **34 ft.**

LTANKS:

Facility ID:	1501578
Site ID:	507803
Closed Date:	2015-12-18
Spill Number:	1501578
Spill Date:	2015-05-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2015-05-12
CID:	Not reported

APARTMENT BLDG (Continued) **S117853874**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-05-12
Spill Record Last Update:	2015-12-18
Spiller Name:	DON HESSEMER
Spiller Company:	APARTMENT BLDG
Spiller Address:	86 E 3RD ST
Spiller County:	999
Spiller Contact:	DON HESSEMER
Spiller Phone:	(732) 417-0999
Spiller Extention:	220
DEC Region:	2
DER Facility ID:	462526
DEC Memo:	"7/13/15 TJD File review. Spill reassigned from AH Primary (Ahmed) to AH Secondary (DeMeo). 12/18/15 TJD File review. ABC Tank has submitted closure report stating: " A tank tightness test was performed by others on (1) 1080 gallon aboveground vaulted fuel oil storage tank. The tank did not PASS the test and NYSDEC Spill Case #1501578 was assigned to this site. " ABC Tank observed a precut on top of the tank that would cause the tank to fail a test. ABC Tank pumped out & cleaned the interior of the tank. All lines were disconnected from the top of the tank. Upon completion of the job, ABC Tank welded the pre-existing precut closed " ABC Tank performed a pressure test on the isolated (1) I 080 gallon tank. The tank was able to hold the pressure for more than 24 hours. " ABC Tank performed a pressure test on each lines. All lines, except the vent line, were able to hold the pressure. " ABC Tank tightened the vent line and performed a second pressure test on the line. The vent line was able to hold the pressure. " ABC Tank reconnected all the lines back to the top of the tank. A tightness test was performed on (I) 1080 gallon tank & tank system. The tank & system were deemed a PASS. A copy of the tightness test is attached for your review. Based upon above, initial tightness test failure was a dry leak. Repairs were made and system passed a subsequent test (report included with closure documentation). No further action is required. All documentation uploaded to DECDOCS. Spill closed."
Remarks:	"Basement contained tank failed test. Investigate, repair and retest being planned."

All Materials:

Site ID:	507803
Operable Unit ID:	1257128
Operable Unit:	01
Material ID:	2260117
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BD838 **BROAD PRINT REALITY CORP** **NY LTANKS** **S107523563**
SW **112 CROSBY ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.287 mi.
1514 ft. **Site 4 of 4 in cluster BD**

Relative: **Lower**

Actual: **37 ft.**

LTANKS:

Facility ID:	0512792
Site ID:	359169
Closed Date:	2006-02-06
Spill Number:	0512792
Spill Date:	2006-02-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2006-02-03
CID:	27
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-02-04
Spill Record Last Update:	2006-02-06
Spiller Name:	Not reported
Spiller Company:	PETRO OILCO
Spiller Address:	55-60 58TH ST
Spiller County:	001
Spiller Contact:	BOLIVO
Spiller Phone:	(212) 334-5589
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	309170
DEC Memo:	"02/06/06 Sharif// I called Broad Print Realty Corp. and left a messege for the building manager, Nicholas to follow up about the clean up. The super does n't have any cell phone. Later on today, Building Manager,DiMaiuta,(212)334-5589 returned my call verifying the oil clean up was good. No soil/drain was impacted.NFA required. "
Remarks:	"Caller reports spill onto pavement and into the basement. Driver took the supers word for the amount in the tank and overfilled it. Petro is doing the cleanup."

All Materials:

Site ID:	359169
Operable Unit ID:	1116394
Operable Unit:	01
Material ID:	2106773
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	.00

BROAD PRINT REALITY CORP (Continued) **S107523563**

Oxygenate: Not reported

BJ839 **FORMER MOBIL S/S#17-KHB** **NY LTANKS** **S104513528**
WSW **37 WEST HOUSTON ST** **NY Spills** **N/A**
1/4-1/2 **NEW YORK, NY**
0.288 mi.
1523 ft. **Site 1 of 2 in cluster BJ**

Relative:
Lower

Actual:
28 ft.

LTANKS:

Facility ID:	8803871
Site ID:	306206
Closed Date:	2015-06-01
Spill Number:	8803871
Spill Date:	1988-08-02
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	1988-08-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-08-03
Spill Record Last Update:	2015-06-02
Spiller Name:	FRANK MESSINA
Spiller Company:	EXXONMOBIL CORPORATION
Spiller Address:	1545 ROUTE 22 EAST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	247332
DEC Memo:	"Site remediation for this spill has been consolidated under spill no. 88-03871. See also spill nos. 81-01485, 88-09786, 00-00286, 02-06308, 02-06369, and 04-08460. SEE PIN FILE SP1596.701 for additional information. 3/13/2000: DEC sent Stipulation Agreement for cleanup. Spill Reassigned from O'Dowd to Sigona in March 2000. (Sigona) 2/11/2003: Order On Consent No. D2-5001-02-12 is executed - Spill Nos. 81-01485, 88-03871, 88-09786, 00-00286, 02-06308 & 02-06369 & State Funded Project Identification No. 01596 - Former ExxonMobil S/S, 37-61 West Houston Street, New York, N.Y. Petroleum Bulk Storage (PBS) facility No. 02-157945 (the Site). (Sigona) 3/31/2003: DEC received Geologic Services Corporation (GSC) Supplemental Community Air Monitoring Plan (SCAMP) to address potential petroleum vapors and dust from impacting the adjoining properties, including, but not limited to, Via Verde Art School for Children, located at 143 Greene Street #3, New York, N.Y. (Sigona) 4/1/2003: The DEC along with the New York State Department of

FORMER MOBIL S/S#17-KHB (Continued) **S104513528**

Health's Bureau of Toxic Substance Assessment (NYS DOH) have determined that the SCAMP provided by GSC is acceptable provided that conditions, which were outlined in a letter to ExxonMobil dated April 1, 2003, are met. (Sigona) 4/23/2004: Site was transferred from Rommel (Region 2) to Harrington (Central Office) for management. (Harrington) 5/25/2004: PM conducted a site visit. Construction of on-site building continues. (Harrington) 2/4/2005: Sent letter to Exxon Mobil requesting indoor air sampling in the basement of 152 Wooster Street. (Harrington) 7/14/2005: PM conducted a site visit with Exxon Mobil personnel and their consultant (GSC). Additional investigation along Greene Street and in the parking lot @ 146 Wooster Street to be completed before remedy selection. (Harrington) 9/27/2005: Access is granted to the 146 Wooster Street parking lot. GSC will be installing an additional monitoring well in the eastern end of this parking lot before the end of the year. (Harrington) 11/16/2005: The location for the proposed monitoring well in the 146 Wooster Street parking lot has been approved. (Harrington) 1/31/2006: The chemical inventory and preliminary interview for 152 Wooster Street has been scheduled with the building's president (board of directors, 152 Wooster Street Corp.) for February 1, 2006 @ 6PM. Indoor air sampling will be conducted primarily in the basement, and will be conducted on February 1, 2006 @ 9AM. (Harrington) 2/6/2006: Sent letter to Exxon Mobil approving request to discontinue bi-weekly LPH gauging and bailing at monitoring well GMW-15 located in the basement of 152 Wooster Street (bldg. immediately south of site). Free product in well GMW-15 has not been observed since March 16, 2005. Well will continue to be gauged and sampled as part of bi-monthly groundwater sampling events for the site. Accordingly, spill no. 04-08460 has been closed. (Harrington) 2/26/2006: Approved off-site SI report and supplemental off-site SI work plan. Two (2) additional wells will be installed in northwest corner of site. Monthly EFR events to commence in order to reduce dissolved levels of BTEX in groundwater. Sent letter for NYCDOT road-opening permits. (Harrington) 5/16/2006: Approved Indoor Air Quality Investigation Report for the work done at 152 Wooster Street. No further investigatory work regarding indoor air quality will be required at this location. (Harrington) 8/16/2006: Approved the revised RAP. RAP calls for the usage of chem-ox technology in order to address the dissolved BTEX beneath the on-site buildings. (Harrington) 8/31/2006: Sent an e-mail to Exxon Mobil approving the sensitive receptor survey report. (Harrington) 2/6/2007: Project transferred from Harrington to Smith (central office) for management. (Smith) 4/18/2007: Performed site visit. One round of chemical oxidation injection was performed. However, due to exhaust fumes from the equipment a tenant of the 152 Wooster Street requested that work be stopped. These concerns will need to be addressed before work will be allowed to continue. (Smith) 7/20/2007: Second round of chemical oxidation performed. Tenents concerns addressed by moving truck and equipment as far away from building as possible (onto West Houston Street). No complaints from residents during this work. (Smith) 7/24/2007: Project transferred from Smith to Harrington (central office) for management. (Harrington) 8/3/2007: PM visited the site with Kleinfelder personnel (Mooney, Meyerhoefer). Follow-up groundwater sampling for the 2nd round of chem-ox injections will be conducted shortly. Work was delayed due to road-opening permit issues with NYCDOT. (Harrington) 3/25/2008: PM sent e-mail to Exxon Mobil approving the Supplemental Off-Site SI Report, the Remedial Activity Summary Report documenting

FORMER MOBIL S/S#17-KHB (Continued) **S104513528**

the results of the 3rd round of chem-ox injections, and the latest quarterly report (October - December 2007). Access issues between Exxon Mobil and the residents of 152 Wooster Street have been brought to the attention of DEC legal counsel. (Harrington) 7/17/2008: PM sent e-mail to Exxon Mobil approving quarterly report for January - March 2008. E-mail required an update regarding negotiations between Exxon Mobil and 152 Wooster Street Corporation, as the 4th round of chem-ox injections has been delayed since June 24th due to another round of access issues. (Harrington) 12/4/08 - Haggerty: Assumed management from Dave Harrington 3/27/09 - Haggerty: approved Remedial Activities Summary Report prepared by Groundwater & Environmental Services (GES). GES provides technical services for Kleinfelder with ChemOx. This was Phase IV out of V phases detailed in the RAP and Consent Order. 11/11/08 - 11/13/08 Hydrogen Peroxide and Sodium Persulfate were injected. High BTEX concentrations (greater than 40ppm) remain in groundwater. It appears the ChemOx is remediating the groundwater but not the adsorbed contamination preventing the dissolved BTEX concentrations from decreasing. The last Phase of ChemOx is scheduled for June. After the last round, we will re-evaluate the technology and try to come up with a more effective remedy. Possibly surfactant enhanced ChemOx June 2009 - Phase V of chemOx injection completed in June September 2009 - Groundwater still heavily contaminated after 5 injection events. Up to 40ppm of BTEX in groundwater. PM sent email to Charles Kolb, Exxon PM, to have a conference call. Consent Order called for 5 injection events which are now exhausted. It appears the groundwater surrounding the injection wells is being remediated, but contaminants adsorbed to the soil particles remain. Drilling is this area is very difficult downtown Manhattan. April 2010 - PM met with Kevin Hale to discuss project. Kevin Hale, PM, EM, Kleinfelder had a conference call on 2/18/10. EM will be submitting a work plan by the end of April 10. EM requested a month extension. Due date May 19 May 2010 - Revised RAP under review July 2010 - Approved RRAP with some modifications. Site conditions limit what is possible. Site is now 7 story building so we have to design a remedial approach based on the current wells, Injection points under the building. We will extract groundwater at the site in conjunction with vapor extraction. Based on the contruction of all wells, vapor extraction of the unsaturated zone is possible and while the grondwater is depressed the heavily contaminated smear zone will be exposed allowing for vapor extraction of the saturated zone February 2011 - Feasability Report due next month March 2011 - Permitting issues delayed HIT events and gw sampling so Feasibility Report has been pushed back May 2011 - Feasibility Report due in end of June June - Feabibility Report under review July 2011 - Approved Feasibility Report. Based on the results, PM required a 5 consecutive day HIT event. Based on that result, future HIT events will be scheduled accordingly August 2011 - 5 day HIT event completed December 2011 - Feasibility Study Report of review January 2012 - VTE events successful in reducing contaminant mass in the unsaturated zone to a point where GES is going to begin additional rounds of ChemOx, most likely persulfate February 2012 - GES now EM's consultant. RAP for sodium persulfate injections due 3/31/12 April 2012 - Approved RAP, already has a CO December 2012 - GES planning an additional injection once the holiday embargo is over May 2013 - Waiting on groundwater data to determine the success of the additional injection October 2013 - a spike in dissolved concentration in one well at 27,000ppb total BTEX. Agreed to wait

FORMER MOBIL S/S#17-KHB (Continued) **S104513528**

until the next groundwater data set comes in before making a decision as to whether additional injections are required June 18-19, 2014 - additional hydrogen peroxide/ sodium persulfate/ air sparge/ SVE event conducted. ISCO injected directly into monitoring wells, rather than only into inject wells, to address areas of the groundwater impact. June 1, 2015 - Spill closed. ExxonMobil remediated contamination to the extent feasible. A multi-story residential building was built across the entire property in the early 2000's which limited ExxonMobil's consultant GES to fully remediate impact to the site. Under a consent order, the remedy included SVE events and 8 separate ISCO (hydrogen peroxide and sodium persulfate with chelated iron) injection events from 2006-2014. All on-site injection wells and monitoring wells (used for SVE) were installed before the building foundation and piped to a vault in the adjacent sidewalk. As of the last SVE data collected in June 2014, very little to no vapor mass was collected from the unsaturated zone confirming the remaining soil contamination resided in the smear zone. The Department beleives that further injections would have a minimal impact on the remaining groundwater contamination at this point. It appears that adsorbed contamination in the smear zone is the source of the remaining groundwater contamination and given the physical constraints of the property, the inability to access these limited pockets of remaining soil contamination makes further remediation unfeasible."

Remarks: "LINE TEST FAILURE, LINE WAS CAPPED OFF; GAS SERVICE MAINTENANCE DID TEST."

All TTF:

Facility ID:	8803871
Spill Number:	8803871
Spill Tank Test:	1534388
Site ID:	306206
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	306206
Operable Unit ID:	919007
Operable Unit:	01
Material ID:	459400
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

FORMER MOBIL S/S#17-KHB (Continued) **S104513528**

Oxygenate: True

Site ID: 306206
Operable Unit ID: 919007
Operable Unit: 01
Material ID: 2260883
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

SPILLS:
Facility ID: 0206308
Facility Type: ER
Spill Number: 0206308
DER Facility ID: 247332
Site ID: 306204
DEC Region: 2
Closed Date: 2003-05-27
Spill Cause: Housekeeping
Spill Class: A3
SWIS: 3101
Spill Date: 2002-09-18
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2002-09-18
CID: 205
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-09-18
Spill Record Last Update: 2003-05-27
Spiller Name: JOANNE WALLACK
Spiller Company: EXXONMOBIL
Spiller Address: 3225 GALLOWS ROAD
Spiller Company: 001
Contact Name: CALLER
DEC Memo: ""
Remarks: "Product found in temporary observation wells."

All Materials:
Site ID: 306204
Operable Unit ID: 858964
Operable Unit: 01
Material ID: 516921
Material Code: 0009

FORMER MOBIL S/S#17-KHB (Continued) **S104513528**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	0206369
Facility Type:	ER
Spill Number:	0206369
DER Facility ID:	247332
Site ID:	306205
DEC Region:	2
Closed Date:	2003-05-27
Spill Cause:	Housekeeping
Spill Class:	A3
SWIS:	3101
Spill Date:	2002-09-19
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2002-09-19
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2002-09-19
Spill Record Last Update:	2003-05-27
Spiller Name:	JOANNE WALLACH
Spiller Company:	EXXONMOBIL
Spiller Address:	1900 E. LINDEN AVENUE
Spiller Company:	001
Contact Name:	JOANN WALLACH
DEC Memo:	""
Remarks:	"While performing test borings product was discovered in grounwater "

All Materials:

Site ID:	306205
Operable Unit ID:	859027
Operable Unit:	01
Material ID:	516981
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF840 **APARTMENT** **NY LTANKS** **S108298537**
WSW **142-44 GREENE STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.291 mi.
1536 ft. **Site 4 of 4 in cluster BF**

Relative: **Lower**

Actual: **28 ft.**

LTANKS:

Facility ID:	0607628
Site ID:	371408
Closed Date:	2006-10-13
Spill Number:	0607628
Spill Date:	2006-10-04
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-10-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-10-04
Spill Record Last Update:	2006-10-13
Spiller Name:	ANTHONY LARA
Spiller Company:	APARTMENT
Spiller Address:	142-44 GREENE STREET
Spiller County:	001
Spiller Contact:	ANTHONY LARA
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	321187
DEC Memo:	"tank had a fiberglass patch on it and during an overfill approx 1 cup of oil spilled. PTC removed the cement wrap around the tank, removed the fiberglass patch and welded a metal patch into place. The tank is now being re-wrapped in cement. Minor spill was cleaned up. There was a stain on the floor and PTC said the owner wanted over kill so part of the floor was pulled up."
Remarks:	"2500 GALLON TANK- WAS FIBERGLASSED CLOSED ON TOP AND IS LEAKING: IT IS CEMENTED : THEY HAVE REMOVED CEMENT AND ONLY 1 55 GALLON DRUM WAS TAKEN FULL OF CONTAMINATED SOIL AND IS ALL CLEANED U P"

All Materials:

Site ID:	371408
Operable Unit ID:	1129171
Operable Unit:	01
Material ID:	2118831
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G

APARTMENT (Continued) **S108298537**

Recovered: .00
Oxygenate: Not reported

BK841 **BASEMENT - TTF** **NY LTANKS** **S110762261**
ENE **141 2ND AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.295 mi.
1558 ft. **Site 1 of 4 in cluster BK**

Relative: **Lower**
Actual: **32 ft.**

LTANKS:
Facility ID: 1010403
Site ID: 444006
Closed Date: Not reported
Spill Number: 1010403
Spill Date: 2011-01-05
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 2011-01-05
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 1
Date Entered In Computer: 2011-01-05
Spill Record Last Update: 2015-03-31
Spiller Name: CHRISTOPHER
Spiller Company: UNKNOWN
Spiller Address: 141 2ND AVE
Spiller County: 999
Spiller Contact: CHRISTOPHER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 398921
DEC Memo: "8/15/2012 TTF Spill Case transferred to DEC Tim DeMeo. 03-31-2015 - V. Brevdo As per discussion with Chief of Spill Response Section, this Tank Test Failure Spill Case is transferred to Remediation Section B for management of the project. Spill Case is further assigned to Jonathan Kolleeny. VB"
Remarks: "4500g tank test failure"

All Materials:
Site ID: 444006
Operable Unit ID: 1194450
Operable Unit: 01
Material ID: 2190277
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported

BASEMENT - TTF (Continued) **S110762261**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BI842 **61 EAST 7TH ST** **NY LTANKS** **S104503153**
East **61 EAST 7TH ST** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.295 mi.
1560 ft. **Site 3 of 3 in cluster BI**

Relative: **Lower**
Actual: **29 ft.**

LTANKS:

Facility ID:	0500005
Site ID:	342871
Closed Date:	2006-01-09
Spill Number:	0500005
Spill Date:	2005-04-01
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-04-01
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-01
Spill Record Last Update:	2006-01-09
Spiller Name:	MIKE
Spiller Company:	BRIDGE TRANSPORTATION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MIKE
Spiller Phone:	(718) 369-6016
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	289236
DEC Memo:	"4/4/05 Sawyer noted on fax report that PTC responded, 2 bags of speedy dry, 1 gallon///Tipple updating database//// Tipple called property owner Mike at 908-355-9270, his supers are currently on vacation, he has had no complaints of odors, the Supers will contact DEC once they return from vacation.... 10/27/05 - Raphael Ketani. I wanted to close out the case, but there were no notes indicating that the spill had been cleaned up - despite 1 gal. being listed above. I called up Diana Parker at PTC ((718) 624-4842) and she told me that the total cost of the spill cleanup was $15,000. She said oil spilled onto the floor of the building and 30 drums of material were taken away. She said Bridge Transportation did the removal of the drummed material and PTC did the cleanup and took end point samples. I asked

61 EAST 7TH ST (Continued) **S104503153**

Ms. Parker for the documents verifying the cleanup. She said she would FAX them to me by next week. 1/5/06 - Raphael Ketani. I called up Ms. Parker again and told her to send me the cleanup documentation as I had previously requested. She said she would FAX it. I received the FAXed documentation regarding soil removal and site cleanup. Based upon the documentation, I am closing the case."

Remarks: "TANK OVERFILL CAUSED BY BRIDGE TRANSPORTATION"

All Materials:

Site ID:	342871
Operable Unit ID:	1101563
Operable Unit:	01
Material ID:	581766
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	9701858
Facility Type:	ER
Spill Number:	9701858
DER Facility ID:	104062
Site ID:	119812
DEC Region:	2
Closed Date:	2003-02-25
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1997-05-13
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-05-13
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-13
Spill Record Last Update:	2003-02-25
Spiller Name:	MIKE HELFONT
Spiller Company:	MYSTIC TRANSPORTATION
Spiller Address:	1901 STEINWAY ST
Spiller Company:	001
Contact Name:	MIKE HELFONT
DEC Memo:	""
Remarks:	"DRIVER WAS DELIVERING OIL TO THE ABOVE APARTMENT BUILDING AND THE

61 EAST 7TH ST (Continued) **S104503153**

NOZZLE CAME LOOSE FROM THE FILL PIPE AND SPILLED ONTO THE GROUND - THEY ARE CLEANING THE SPILL NOW"

All Materials:

Site ID:	119812
Operable Unit ID:	1044461
Operable Unit:	01
Material ID:	334796
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

843
ESE
1/4-1/2
0.298 mi.
1572 ft.

SPILL NUMBER 0004317 **NY LTANKS** **S104781859**
91 EAST 3RD ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
33 ft.

LTANKS:

Facility ID:	0004317
Site ID:	61149
Closed Date:	2004-01-23
Spill Number:	0004317
Spill Date:	2000-07-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-07-11
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-11
Spill Record Last Update:	2004-01-23
Spiller Name:	JANICE MCDOWELL
Spiller Company:	Not reported
Spiller Address:	91 EAST 3RD ST
Spiller County:	001
Spiller Contact:	JANICE MCDOWELL
Spiller Phone:	(212) 673-7333
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	59606
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

SPILL NUMBER 0004317 (Continued) **S104781859**

SANGESLAND 7/29/2003 Sent out old TTF ltr 1/23/2004 Sangesland received a copy of a letter from ProTest (John Leddy) dated Aug 20, 2003. Letter states that the tank failed because of a non-tight manhole cover and pinholes at the top of the tank. According to Protest the tank was in a vault, PTC pumped out the tank and then the tank was cut up by Cardinal Tank. No sign of contamination was found. A new 3,000 gal tank was installed in the vault. There was no contaminated soil for disposal. Unfortunately there are no records of the PTC cleaning or the scrap disposal records. Spill Closed"

Remarks: "pinholes at top of tank - wrapped tank in basement"

All TTF:

Facility ID:	0004317
Spill Number:	0004317
Spill Tank Test:	1525757
Site ID:	61149
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	61149
Operable Unit ID:	826701
Operable Unit:	01
Material ID:	549056
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BK844 **235-263 NORTH 9TH STREET** **NY VCP** **S118943224**
ENE **235-263 NORTH 9TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.301 mi.
1588 ft. **Site 2 of 4 in cluster BK**

Relative: **Lower**
Actual: **34 ft.**

VCP NYC:

Project ID:	13CVCP086K
Project Name:	235-263 NORTH 9TH STREET
Project Address:	235-263 NORTH 9TH STREET
Borough:	BROOKLYN

VCP NYC:

235-263 NORTH 9TH STREET (Continued) **S118943224**

Project ID: 13CVCP086K
File Name: 2012-09-19.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-09-19.13CVCP086K.RIR.pdf

Project ID: 13CVCP086K
File Name: 2012-09-20.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-09-20.13CVCP086K.FactSheet1.pdf

Project ID: 13CVCP086K
File Name: 2012-09-20.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-09-20.13CVCP086K.Translated_FactSheet1.pdf

Project ID: 13CVCP086K
File Name: 2012-09-20.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-09-20.13CVCP086K.Translated_CPS.pdf

Project ID: 13CVCP086K
File Name: 2012-11-15.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-11-15.13CVCP086K.report.Remedial_Action_Work_Plan.pdf

Project ID: 13CVCP086K
File Name: 2012-11-20.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-11-20.13CVCP086K.Stipulation_List.pdf

Project ID: 13CVCP086K
File Name: 2012-11-26.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-11-26.13CVCP086K.FactSheet_2.pdf

Project ID: 13CVCP086K
File Name: 2012-11-26.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP086K/2012-11-26.13CVCP086K.Translated_FactSheet2.pdf

---

845 SW 1/4-1/2 0.310 mi. 1639 ft.

AMOCO
62 PRINCE STREET
MANHATTAN, NY

NY LTANKS **S100167501**
NY Spills **N/A**

Relative: Lower
Actual: 36 ft.

LTANKS:
Facility ID: 8709385
Site ID: 143437
Closed Date: 2004-04-28
Spill Number: 8709385
Spill Date: 1988-02-03
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: a3
Cleanup Ceased: Not reported
SWIS: 3101

AMOCO (Continued) **S100167501**

Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1988-02-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-02-09
Spill Record Last Update:	2004-04-29
Spiller Name:	MIKE REGINA
Spiller Company:	AMOCO
Spiller Address:	62 PRINCE STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	307049
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 12/6/2001 See spill #0108884 contaminated soil samples found. 3/14/03 REASSIGNED FROM SULLVAN TO VOUGHT. 1/8/04 Reassigned from Vought to K Foley. (KMF) 4/28/04 See notes for closed spill #0108884. No BTEX found above TAGM cleanup guidance in 10 soil borings completed. Minor exceedances for PAHs."
Remarks:	"EIGHT 550-GAL TANKS DROPPED PRESSURE. ACTION UNKNOWN/ EXCAVATE--ISOLATE--RETEST "

All TTF:

Facility ID:	8709385
Spill Number:	8709385
Spill Tank Test:	1533175
Site ID:	143437
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	143437
Operable Unit ID:	914645
Operable Unit:	01
Material ID:	464709
Material Code:	0009
Material Name:	gasoline

AMOCO (Continued) **S100167501**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	-1.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0510954
Facility Type:	ER
Spill Number:	0510954
DER Facility ID:	307049
Site ID:	357011
DEC Region:	2
Closed Date:	2008-06-26
Spill Cause:	Other
Spill Class:	C4
SWIS:	3101
Spill Date:	2005-12-18
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2005-12-19
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-12-19
Spill Record Last Update:	2008-06-26
Spiller Name:	ANDREW KELLY
Spiller Company:	CONSTRUCTION SITE
Spiller Address:	62 PRINCE STREET
Spiller Company:	001
Contact Name:	ANDREW KELLY
DEC Memo:	"Left 2 messages for Andrew Kelly of DEP - No additional information. Site was a gas station (Spill #0108884 Closed by Vought) This was a surface spill - cleaned and closed."
Remarks:	"NO INFO FURTHER INVESTIGATION"

All Materials:

Site ID:	357011
Operable Unit ID:	1114299
Operable Unit:	01
Material ID:	2104378
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

AMOCO (Continued) **S100167501**

Oxygenate: Not reported

BK846 **SPILL NUMBER 0302699** **NY LTANKS** **S106123802**
ENE **291 EAST 9TH STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.312 mi.
1645 ft. **Site 3 of 4 in cluster BK**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Facility ID:	0302699
Site ID:	107141
Closed Date:	2003-12-15
Spill Number:	0302699
Spill Date:	2003-06-13
Spill Cause:	Tank Overfill
Spill Source:	Unknown
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2003-06-13
CID:	297
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-13
Spill Record Last Update:	2003-12-15
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ANNA ROLDAN
Spiller Phone:	(212) 504-4207
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	94242
DEC Memo:	""
Remarks:	"CITIZEN CALLED NYC DEP AND STATED THERE WAS OIL COMING OUT OF A CAP IN THE STREET AND WAS FLOWING INTO A CATCH BASIN"

All Materials:

Site ID:	107141
Operable Unit ID:	870436
Operable Unit:	01
Material ID:	507159
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SPILL NUMBER 0302699 (Continued) **S106123802**

Oxygenate: Not reported

BK847 **BASEMENT - TTF** **NY LTANKS** **S110762262**
ENE **145 2ND AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.312 mi.
1649 ft. **Site 4 of 4 in cluster BK**

Relative: **Lower**

Actual: **31 ft.**

LTANKS:

Facility ID:	1010404
Site ID:	444007
Closed Date:	Not reported
Spill Number:	1010404
Spill Date:	2011-01-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2011-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2011-01-05
Spill Record Last Update:	2015-03-31
Spiller Name:	CHRISTOPHER
Spiller Company:	UNKNOWN
Spiller Address:	145 2ND AVE
Spiller County:	999
Spiller Contact:	CHRISTOPHER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	398922
DEC Memo:	"8/15/2012 TTF Spill Case transferred to DEC Tim DeMeo. 03-31-2015 - V. Brevdo As per discussion with Chief of Spill Response Section, this Tank Test Failure Spill Case is transferred to Remediation Section B for management of the project. Spill Case is further assigned to Jonathan Kolleeny. VB"
Remarks:	"4500g tank test failure"

All Materials:

Site ID:	444007
Operable Unit ID:	1194451
Operable Unit:	01
Material ID:	2190278
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

BASEMENT - TTF (Continued) **S110762262**

Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

BH848 **HITCHINGS RES** **NY LTANKS S103559049**
SE **87 EAST 2ND ST** **NY Spills N/A**
1/4-1/2 **MANHATTAN, NY**
0.314 mi.
1656 ft. **Site 3 of 3 in cluster BH**

Relative: **Lower**
Actual: **35 ft.**

LTANKS:

Facility ID:	9812332
Site ID:	79235
Closed Date:	1999-05-20
Spill Number:	9812332
Spill Date:	1999-01-05
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1999-01-05
CID:	233
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-05
Spill Record Last Update:	1999-05-20
Spiller Name:	KATHREN HITCHINGS
Spiller Company:	HITCHINGS RES
Spiller Address:	87 EAST 2ND ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	73660
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND OIL IN BASEMENT FLOOR AREA WAS CLEANED. TANK TEST RUN 1/11/99 - SYSTEM FAILED - AUDIBLE LEAK DETECTED COMING FROM FILL & VENT LINE. 1/21/99 - NEW YORK HEATING CORP. (718-782-3894) INSTALLED NEW VENT & FILL LINES. SYSTEM RETESTED AND PASSED. ORIGINAL CALL CAME FROM TENANT IN BUILDING DIRECTLY OVER THE BASEMENT BOILER ROOM AREA"
Remarks:	"tank in basement cracked spill to concrete floor spill contained in basement res request call"

All Materials:

Site ID:	79235
Operable Unit ID:	1072936
Operable Unit:	01

HITCHINGS RES (Continued) **S103559049**

Material ID:	312609
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	1204476
Facility Type:	ER
Spill Number:	1204476
DER Facility ID:	421681
Site ID:	467363
DEC Region:	2
Closed Date:	2012-08-09
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	2012-08-04
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2012-08-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-08-04
Spill Record Last Update:	2012-08-09
Spiller Name:	LT. JONES
Spiller Company:	COMMERICAL TRUCK
Spiller Address:	87TH ST
Spiller Company:	999
Contact Name:	LT. JONES
DEC Memo:	"8/9/12-Vought-Spill caused by leaking saddle tank on truck and spill to concrete and asphalt with no sewers or drains affected as per caller remarks. Spill cleaned using absorbent material as per FDNY protocal and spill closed by Vought as no effect to soil or groundwater."
Remarks:	"Truck lost saddle tank spilling in street. No sewers affected. Cleanup is underway."

All Materials:

Site ID:	467363
Operable Unit ID:	1217320
Operable Unit:	01
Material ID:	2215588
Material Code:	0008

HITCHINGS RES (Continued) **S103559049**

Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	35.00
Units:	G
Recovered:	35.00
Oxygenate:	Not reported

849
North
1/4-1/2
0.314 mi.
1657 ft.

SPILL NUMBER 9814449 **NY LTANKS** **S104620009**
30 EAST 9TH ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
33 ft.

LTANKS:

Facility ID:	9814449
Site ID:	163694
Closed Date:	1999-03-23
Spill Number:	9814449
Spill Date:	1999-03-03
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-03-03
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-03
Spill Record Last Update:	2002-05-20
Spiller Name:	MIKE WEXLER
Spiller Company:	NEW BEDFORD
Spiller Address:	30 EAST 9TH ST
Spiller County:	001
Spiller Contact:	MIKE WEXLER
Spiller Phone:	(212) 674-6123
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	138062
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SPOKE WITH JOE OF NY HEATING, APPROX 10 GLS. SPILLED ONTO THE TANK ROOM. CONTAINED. 2:15. 3/4/1999 APPEARS TO BE DIRT FLOOR. TANK CLEANED. ROOM BEING CLEANED. TANK TO BE REMOVED AND REPLACE ACCORDING TO SUPERINTENDANT. 3/17/1999 REINSPECTED. NOT DIRT FLOOR. COMNCRETE FLOOR. FLOOR WILL BE CLEANED BETTER. "
Remarks:	"while making a delivery the tank developed a leak . clean up crew on the way"

All Materials:

SPILL NUMBER 9814449 (Continued) **S104620009**

Site ID:	163694
Operable Unit ID:	1075491
Operable Unit:	01
Material ID:	311136
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL850 **APARTMENT BUILDING** **NY LTANKS** **S108131252**
NNE **85 4TH AVE** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.315 mi.
1661 ft. **Site 1 of 4 in cluster BL**

Relative: LTANKS:
Lower

Actual: Facility ID:	0605695
40 ft. Site ID:	368911
Closed Date:	2011-07-11
Spill Number:	0605695
Spill Date:	2006-08-16
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	2006-08-16
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-16
Spill Record Last Update:	2011-07-11
Spiller Name:	ROBERT WEISS
Spiller Company:	85 FOURTH PARTNERSHIP
Spiller Address:	85 4TH AVE
Spiller County:	999
Spiller Contact:	ED TOWNSEND
Spiller Phone:	(914) 762-6333
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	318796
DEC Memo:	"08/17/2006-Vought-Spill assigned to DEC Vought due to previous involvement with case (see spill #0604292). Vought received call from Ed Townsend(Environmental Management Solutions) (914-762-6333) that tank and fill line failed test and that isolate and retest will be performed possibly by 5/25/06. 08/29/06-Vought. Received message from

APARTMENT BUILDING (Continued) **S108131252**

Townsend that fill pipe failed test and that he will be replacing fill line. Vought returned call and Townsend will be faxing in failed tank test results and will be removing fill line and taking soil endpoints. 09/06/06-Vought-Received fax from Townsend. Tank Test Results (Advanced Testing Services-Mark Ricciardi)-8/15/06. Tank test showing failing of one (10000-gallon) #4 fuel oil UST tested via EZY3 Locator Plus test. Test results show dry portion leak (ullage).
Letter from ATS Ricciardi to Ed Townsend-8/16/06. The evaluation showed that a leak exists in the underground storage tank system that exceeds EPA and NYDEC standards for leak detection... We recommend that the responsible party isolate the tank from the piping by uncovering the top of the tank and removing the vent and product lines from the system . 09/06/06-Vought-Called Townsend and required that he contact DEC for site visit during excavation of fill line.
Tank Test Results (Advanced Testing Services-Mark Ricciardi)-8/25/06. Tank test showing tight tank. Letter from ATS Ricciardi to Ed Townsend-8/28/06. Advanced Tank Services Co. certifies that the 10,000 gallon underground #4 oil storage tank and distribution lines located at 85 4th Avenue did not contain any detectable leaks .
Letter from Ed Townsend to DEC Vought-8/3/06. This letter serves as an update to the activities surrounding the 10000-gallon #4 fuel oil tank... Subsequently the tank and fill pipe were tested separately on 8/25/06 at which point it was determined that it was the fill pipe that caused the tank failure on 8/16/06. Oil deliveries were ceased based on the tank failure . ...we have informed Jardan Property Management) that the fill pipe will have to be replaced as soon as possible. During replacement of the fill pipe, located under the sidewalk on 85th Street, soils directly adjacent to the fill pipe will be screened with a PID and soil samples will be taken and analyzed... 09/06/06-Vought-Called Townsend and required that he contact DEC for site visit during excavation of fill line. Townsend mentioned that they were looking for plumber to replace fill line and he will contact Vought as soon as date is set up.
12/12/06-Vought-Called Townsend for update and he is no longer working for realty. 12/13/06-Received call from Bob Friedl (Environmental Management Solutions 914-762-6333x16) and his cell is 914-906-4157. Vought called Friedl and left message to return call. Vought spoke to Friedl and sidewalked was opened and fill line was removed and quater size hole in fittings. Three drums of soil were excavated and fill pipe was replaced. New system passed tightness test. Unsure if endpoint samples were collected. Contamination did extend to a depth of 4 below grade at building. DEC will receive report by 12/22. Vought requested site plan with point of intrusion into NYCTA exit and fill port on same plan. 8/06/10 - Raphael Ketani. The PBS is #2-292192. There is one 10,000 gal. tank with #6 oil. The mail goes to Jardan Management Corp., 670 White Plains Road, #305, Scarsdale, NY, 10583. The contact is Robert Weiss at (914) 722-4400. The owner is 85 Fourth Partnership, c/o Jardan Management. I found only a FAX of the tank testing documentation package in the file and put it in the E-docs. I spoke to Mr. Friedl. He said that the spill was cleaned up in 2006. He said that the only problem was the leaking fill pipe. He added that they removed the old fill pipe and a bunch of soil, backfilled with fresh soil, and replaced the fill pipe. I asked him whether the oil had made its way into the NYCTA exit. He said that this was a report by the NYCTA that they had oil in their system, but the location of the oil was over 100 feet away. He added that the soil contamination below the fill pipe went down no more

APARTMENT BUILDING (Continued) **S108131252**

than a foot. I asked Mr. Friedo to send me the cleanup report for the site. He said that he will. 11/22/10 - Raphael Ketani. I spoke to Bob Friedl of Environmental Management Solutions (914)762-6333, ext 16/ cell (914) 906-4157 about the cleanup report. He said that he forgot to send it. However, he took my e-mail address and he said that he would send it shortly. 2/22/11 - Raphael Ketani. I tried to contact Mr. Friedl (914)762-6333, ext 16/ cell (914) 906-4157, but I could only leave voice mail messages requesting the cleanup report. 2/24/11 - Raphael Ketani. I made contact with Mr. Friedl. I asked him where the cleanup report was. He said that it was in the archives in the basement. I asked him whether there was a problem getting the report. He said No, but that he just hadn't gotten around to it. I told him that if the DEC doesn't receive the report, then the spill will remain open. Then, if his client wants to do a refinance of the mortgage or get a loan, they will have trouble. Mr. Friedl said that he will get me the document. 5/25/11 - Raphael Ketani. I contacted Mr. Friedl regarding sending the DEC the cleanup report. I told him that we last talked in the latter part of March of this year about the need for the report. I told him that last March was the fourth time I had asked for it. Mr. Friedl sounded surprised. He apologized and said that he will dig it out and send it to me, but that he was extremely busy at work. So he needed me to remind him this wednesday. I said that I will call him. 6/1/11 - Raphael Ketani. I tried to reach Mr. Friedl (914)762-6333, ext 16/ cell (914) 906-4157, but he was out in the field. I did contact him via his cell phone. He said that Mr. Pedone - one of the owners of Environmental Management Solutions - had contacted him regarding the cleanup report. Mr. Friedl said that he will be back in his office in an hour and will call me today. Mr. Friedl called me back. We discussed the spill, the fill pipe replacement and the soil excavation that took place on 12/13/06. Mr. Friedl commented that now that he knew when the work had been completed, he had a better idea of where to look in the hard files for the cleanup report. He said that I should call him tomorrow to see whether he found the report. 6/10/11 - Raphael Ketani. I spoke to Mr. Friedl about whether he had found the missing reports. He said that he had found several reports for the site from 2006 and 2009. They were behind a filing cabinet. The cabinet will be moved and the reports retrieved. He asked that I call him monday regarding the reports. I told him that I will and to have someone scan the reports and send them to the DEC. He said that this will be done. 6/14/11 - Raphael Ketani. I talked to Mr. Friedl (914)762-6333, ext 16/ cell (914) 906-4157. He said that he was downstairs going through the file cabinets and the reports for the site. I told him to send me the documents as soon as possible. 6/21/11 - Raphael Ketani. I contacted Mr. Friedl (914)762-6333, ext 16/ cell (914) 906-4157. He said that he was still pulling files. I asked him when the DEC will receive the cleanup report. He said to give him more time. He added that he wanted to resolve this case, too. As the cleanup report has not been forthcoming, I sent a strongly worded letter to the property manager Rabina Properties, 670 White Plains Road, Scarsdale, NY, 10583, and to 85 Fourth Avenue Corp., itself. The latest name for the property is 85 Fourth Avenue Corporation and the block and lot are 556 and 1. I set a deadline of July 8 for receipt of the cleanup report. 6/22/11 - Raphael Ketani. Mr. Friedl tried to return my call, but I was out of the office. 6/27/11 - Raphael Ketani. Rob Weiss and Oein (Owen) Fitzgerald (914) 722-4400/cell (914) 649-7764 called on a conference call. They were responding to the DEC 6/21/11 letter. They said that

APARTMENT BUILDING (Continued) **S108131252**

they were surprised that the DEC has been trying to obtain the cleanup report for so long. They had no idea that the spill case was still open. They said that they will contact Mr. Friedl and either get the report from him or arrange to have a new investigation performed. Mr. Weiss added that if they find out that the report doesn't exist, then they will ask for an extension of the deadline so that they have enough time to do the investigation and submit a new report. I told them that sounded reasonable. Later, Mr. Weiss sent me an e-mail that the report can not be located. So, a new investigation will be conducted this week. The report will be submitted to the DEC in 2 or 3 weeks. I wrote back that this sounded reasonable. 7/1/11 - Raphael Ketani. Mr. Friedl of Environmental Management Solutions (914)762-6333, ext 16/ cell (914) 906-4157 called today. He said that soil samples were taken today and were sent off to the laboratory for analysis. He expected to receive the results sometime next week. 7/11/11 - Raphael Ketani. Mr. Weiss sent me the 7/7/11 Enviornmental Management Solutions soil sampling data report. I reviewed it and found that the results were almost entirely non-detect. The few analytes that had hits were very close to non-detect. Mr. Weiss requested an NFA letter and I sent him one. As the results in the 7/7/11 report indicated that there was almost no contamination in the vicinity of the fill pipe, I determined that there was no threat to the public or the environment. Therefore, I closed the spill case."

Remarks: ""

All TTF:

Facility ID:	0605695
Spill Number:	0605695
Spill Tank Test:	1550201
Site ID:	368911
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	False
UST:	False
Cause:	03
Source:	02
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	RVKETANI
Last Modified Date:	Not reported

All Materials:

Site ID:	368911
Operable Unit ID:	1126766
Operable Unit:	01
Material ID:	2116332
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

851
ESE
1/4-1/2
0.318 mi.
1680 ft.

85-09 1ST AVENUE
85-09 1ST AVENUE
NEW YORK CITY, NY

NY LTANKS **S100145146**
N/A

Relative:
Lower

Actual:
28 ft.

LTANKS:

Facility ID:	8802622
Site ID:	170432
Closed Date:	1992-09-30
Spill Number:	8802622
Spill Date:	1988-06-22
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	1992-09-30
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-06-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-06-27
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143404
DEC Memo:	""
Remarks:	"COULDN'T STABILIZE IN STAND PIPE."

All TTF:

Facility ID:	8802622
Spill Number:	8802622
Spill Tank Test:	1534171
Site ID:	170432
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

85-09 1ST AVENUE (Continued) **S100145146**

All Materials:

Site ID:	170432
Operable Unit ID:	917954
Operable Unit:	01
Material ID:	458190
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BM852 **107 EAST 10TH STREET** **NY LTANKS** **S105230175**
NE **107 EAST 10TH ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.321 mi.
1695 ft. **Site 1 of 4 in cluster BM**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:

Facility ID:	9704339
Site ID:	191695
Closed Date:	2003-11-17
Spill Number:	9704339
Spill Date:	1997-07-11
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1997-07-11
CID:	282
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-11
Spill Record Last Update:	2006-06-20
Spiller Name:	ROGER
Spiller Company:	FERRENTINO OIL COMPANY
Spiller Address:	17 CLEVLAND PLACE
Spiller County:	001
Spiller Contact:	CHARLES WISER
Spiller Phone:	(718) 786-2253
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159878
DEC Memo:	"06/20/06-Vought-File review by Vought. See also spill numbers: 9511157 (105 E10th St-closed 03/17/03) 9611309 (105-107 E10th St-OPEN PIN WITH NOTES FOR ALL SITES ON BLOCK) 9702485 (116 E10th St-closed

107 EAST 10TH STREET (Continued) **S105230175**

05/28/97) 9704339 (107 E10th St-closed 11/17/03) 9807065 (103 E10th St-closed 03/14/05) 9905975 (103 E10th St-closed 02/26/03) 9913474 (103 E10th St-open) 0006640 (107 E10th St-closed 05/20/03) 0101346 (114 E10th St-closed 07/22/03) 0104789 (107 E10th St-closed 10/20/03) 0111670 (107 E10th St-closed 03/13/02) 0203371 (107 E10th St-closed 07/01/02) 0208470 (105 E10th St-closed 01/08/04) 0511701 (101 E10th St-open) "

Remarks: "DRIVER OVERFILLED TEMPORARY TANK SPILLED ON TO SIDEWALK NOTIFIER CLAIMS IT HAPPENED 3 TIMES DEC ON SCENE "

All Materials:

Site ID:	191695
Operable Unit ID:	1047563
Operable Unit:	01
Material ID:	333599
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

BJ853 **150 WOOSTER STREET** **NY VCP** **S118943599**
WSW **150 WOOSTER STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.322 mi.
1698 ft. **Site 2 of 2 in cluster BJ**

Relative: **Lower**

Actual: **25 ft.**

VCP NYC:

Project ID:	16CVCP060M
Project Name:	150 WOOSTER STREET
Project Address:	150 WOOSTER STREET
Borough:	MANHATTAN

VCP NYC:

Project ID:	16CVCP060M
File Name:	2016-02-01.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/16CVCP060M/2016-02-02.150_Wooster.SupRIR.pdf

Project ID:	16CVCP060M
File Name:	2016-01-19.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/16CVCP060M/2016-03-30 150WOOSTER RAWP_REV1.pdf

Project ID:	16CVCP060M
File Name:	2016-01-19.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/16CVCP060M/2016-03-31.16CVCP060M.doc.150_Wooster_Factsheet-1.pdf

Project ID:	16CVCP060M
File Name:	2016-01-19.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/16CVCP060M/2016-03-31.16TEMP046M.doc.translated_150_Wooster_FS1.OER..pdf

150 WOOSTER STREET (Continued) **S118943599**

Project ID: 16CVCP060M
File Name: 2016-01-19.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/16CVCP060M/2016-03-31.16TEMP046M.doc.translated_CPS.OER..pdf

---

BM854 **103 EAST 10TH ST** **NY LTANKS** **S104619679**
NE **103 EAST 10TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.322 mi.
1698 ft. **Site 2 of 4 in cluster BM**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:

Facility ID:	9807065
Site ID:	155770
Closed Date:	2005-03-14
Spill Number:	9807065
Spill Date:	1998-09-09
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1998-09-09
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-09
Spill Record Last Update:	2006-06-20
Spiller Name:	ANDY HASTER
Spiller Company:	Not reported
Spiller Address:	103 EAST 10TH ST
Spiller County:	001
Spiller Contact:	ANDY HASTER
Spiller Phone:	(212) 477-5345
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	131884
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/18/04 - AUSTIN - TRANSFERRED FROM TOMASELLO FOR REASSIGNMENT - END 3/14/05 - Austinclosed this spill record out and consolidated this tank test failure with spill #9913474. end 06/20/06-Vought-File review by Vought. See also spill numbers: 9511157 (105 E10th St-closed 03/17/03) 9611309 (105-107 E10th St-OPEN PIN WITH NOTES FOR ALL SITES ON BLOCK) 9702485 (116 E10th St-closed 05/28/97) 9704339 (107 E10th St-closed 11/17/03) 9807065 (103 E10th St-closed 03/14/05) 9905975 (103 E10th St-closed 02/26/03) 9913474 (103 E10th St-open) 0006640 (107 E10th St-closed 05/20/03) 0101346 (114 E10th St-closed 07/22/03) 0104789 (107 E10th St-closed 10/20/03) 0111670 (107 E10th St-closed 03/13/02) 0203371 (107 E10th St-closed 07/01/02) 0208470 (105 E10th St-closed 01/08/04) 0511701 (101 E10th St-open) "

103 EAST 10TH ST (Continued) **S104619679**

Remarks: "TANK TEST FAILURE AT APT. BUILDING "

All TTF:

Facility ID:	9807065
Spill Number:	9807065
Spill Tank Test:	1546233
Site ID:	155770
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	155770
Operable Unit ID:	1068126
Operable Unit:	01
Material ID:	318187
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BM855 **103 EAST 10TH STREET** **NY LTANKS** **S104620874**
NE **103 E.10TH ST** **NY LIENS** **N/A**
1/4-1/2 **NEW YORK, NY** **NY Spills**
0.322 mi.
1698 ft. **Site 3 of 4 in cluster BM**

Relative: **Lower**

Actual: **37 ft.**

LTANKS:

Facility ID:	9913474
Site ID:	117758
Closed Date:	2015-12-23
Spill Number:	9913474
Spill Date:	2000-02-28
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RVKETANI
Referred To:	122315 REVIEWED122115 PROGRESS SUMMARY
Reported to Dept:	2000-02-28
CID:	207
Water Affected:	Not reported

103 EAST 10TH STREET (Continued) **S104620874**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-02-28
Spill Record Last Update:	2015-12-23
Spiller Name:	Not reported
Spiller Company:	3/10 TENANTS CORP
Spiller Address:	103 EAST 10TH STREET
Spiller County:	999
Spiller Contact:	HEATHER
Spiller Phone:	(212) 971-8315
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102397
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN SEE ALSO SPILL NUMBERS 9611157 AND 9611309. PIN JOB. tOMASELLO 5/9/2000 9/02 DEC/AG's office settled the case and have gotten a stip signed and costs recovered for this spill as well as 96-11309. The responsible parties have contracted with environmental firms to complete the remedial activities. 5/18/04 - AUSTIN -TRANSFERRED FROM TOMASELLO - CONSOLIDATED WITH SPILL # 9611309, WHICH IS A STATE FUNDED CLEANUP - END 1/12/05 Tipple reopened in Tipple's name///stipulation and cleanup ongoing with RP at 103 East 10th Street See also spill #9807065 9/16/05 - Raphael Ketani. The May 11, 2005 to August 24, 2005 Project Status Report was received on September 14, 2005 and is under review. I finished my review of the Project Status Report and I will send a letter to John Iannnone at Day Engineering ((212) 986-8645) and to 3/10 Tenants Housing Corporation instructing them to proceed with the manual monitoring and product collection for the present monitoring period. Then, if warranated, they can change their methodolgy for the foreseeable future to using absorbent socks in the two wells, MW-23 and MW-29. 10/20/05 - Raphael Ketani. I called John Iannone (i-a-known) at Day Engineering, but I could not reach him. I left a voice message regarding the submission of a report about the use of the absorbent socks in W23 and W29. 10/21/05 - Raphael Ketani. I received a call from John Iannone regarding the site. He said that W23 is in the sidewalk next to the building and is a 4 inch diameter screened well. He said that is has maybe 1/4 inch of product which is being removed manually. W29, he said, is in the back of a basement and was pounded into rubble below the basement. He said that product is present sporadically in this well. Mr. Iannone added that you can have nothing in the well one month, and two months later you will find 2 inches of product. He thinks the rain has something to do with the appearance of the oil. He has an environmental specialist from a consulting company coming over every so often to recover the product. She spends a couple of hours each time. He thinks that, at this time, manual recovery is the way to go. I told him to send me a letter regarding what had been spilled, what has been recovered so far, and what he would like to do (some sort of plan) regarding manual collection and the use of absorbent socks. He said he would get the letter out to me soon. 11/21/05 - Raphael Ketani. I received Mr. Iannone's letter dated 11/18/05, stating that he will request a closure of the spill case in 3 or 4 months if measureable amounts of

103 EAST 10TH STREET (Continued) **S104620874**

product are not seen in the wells. 4/25/06 - Raphael Ketani. I received a progress report from John Iannone of Day Engineering. The report stated that the product thickness jumped up to as much as 2.82' after several months of product thickness measurements which were below 0.1'. He said that he will keep monitoring and collecting the oil. 4/28/06 - Raphael Ketani. I received a letter dated April 21, 2006 from Stephen DeNardo of AJClarke Real Estate Corp. ((212) 541-4477). Mr. DeNardo stated that he received a violation from the NYFD for the site for having unregistered holding tanks. He asked that DEC inform the NYFD that registration is not necessary. I left a message for Mr. DeNardo that he has to discuss the issue with the NYC Dept. of Buildings. 5/15/06 - Raphael Ketani. Mr. Koon Tang of the Div. of Environmental Remediation, Region 2, came over to me today and asked whether I can straighten out the issue of Mr. DeNardo getting repeated violations for tanks on his property at 107 E. 10 Street that are really for the building next door at 103 E. 10 Street. I talked to Mr. DeNardo and he said there are 2 tanks with DEC emblems on them and an oil water separator tank on his property. He said that he had already been to court once to fight the last violation and had received another violation. (At the top of the notes for this case it is indicated that there was a PIN job - which appears to have been reimbursed by the R.P.) I will send a letter to A.J. Clarke stating that the tanks were installed by DEC and that they are needed in order to contain fluids recovered from next door. 06/20/06-Vought-This spill transferred to DEC Vought due to exisiting PIN for spill #9611309. 06/20/06-Vought-File review by Vought. See also spill numbers: 9511157 (105 E10th St-closed 03/17/03) 9611309 (105-107 E10th St-OPEN PIN WITH NOTES FOR ALL SITES ON BLOCK) 9702485 (116 E10th St-closed 05/28/97) 9704339 (107 E10th St-closed 11/17/03) 9807065 (103 E10th St-closed 03/14/05) 9905975 (103 E10th St-closed 02/26/03) 9913474 (103 E10th St-open) 0006640 (107 E10th St-closed 05/20/03) 0101346 (114 E10th St-closed 07/22/03) 0104789 (107 E10th St-closed 10/20/03) 0111670 (107 E10th St-closed 03/13/02) 0203371 (107 E10th St-closed 07/01/02) 0208470 (105 E10th St-closed 01/08/04) 0511701 (101 E10th St-open) 09/13/03-Vought-Received call and spoke to John Iannone (212-986-8645) and Vought will return call once review is completed. 10/15/07-Vought-File Review by Vought. See also spill #9611309 for PIN at adjacent site 105-107 E 10th St. Letter from AG Riggi to 3/10THC. Demand letter for $422529.45 for cleanup costs. Letter from DEC Tipple to John Iannone (103E10th Street)-2/22/01. DEC ... continues to require the following work to be conducted if the owners of 103 East 10th Street intend to takeover the investigation/remediation efforts... . Requirements include installation of two upgradient delineation wells inside basement of 103E10th St. 2)installation of a 3rd Avenue delineation well 3)installation of downgradient (south-side) delineation wells 4)installation of an enhanced remediation system usch as automated EFR system. The Department is currently having a Multi-Phase Extraction System Pilot Test conducted on this site . Currently the Department's contractor is preparing to install the additional wells needed to fully delineate the plume resulting from the 103 East 10th Street release . Please inform the Department by March 31, 2001 as to your clients intention... . Letter from Ianone to DEC Tipple-04/30/01. Letter from Cody Ehlers Group(CEG)-(Iannone) consultant for 103E10th St. CEG hired Apex Envioronmental to perform additional well installation, perform baildown tests, initiate weekly multi-phase extraction (MPX) program for wells with free product for

103 EAST 10TH STREET (Continued) **S104620874**

one year. Request DEC assistance to obtain sidewalk permits. Letter from DEC Tipple to CEG Ianone-5/1/01. DEC agrees with proposal for sequential installation of wells, reasons for well installation in basement of 103E10th, deadline for installation of additional wells is by 5/18/01, submission of baildown results for wells by 5/7/01, submission of RAP by 6/15/01 for installation of a permanent recovery system. Letter from AG Riggi to Debra Rothberg-5/1/01. ...Mr. Iannone continues to selectively eliminate certain portions of the work considered by DEC to be essential in investigation and remediation of this site. AG will proceed with litigation by end of month if settlement is not reached. Letter from AG Riggi to Debra Rothberg-5/2/01. DEC will facilitate the performance of this work by your clients only if they agree to perform the entire scope of work detailed previously in meetings and correspondence... . Letter from CEG Iannone to DEC Tipple-5/2/01. CEG is prepared to do delineation work and request DEC assistance in obtaining permits. Letter from Rothberg to AG Riggi-5/2/01. Your statement that NYSDEC requires all or nothing is deeply troubling . Rothberg asserts that past DEC expenditures were improper . Letter from AG Riggi to Rothberg-5/4/01. ...I share in your disappointment . Letter reiterates failure to delineate plume expeditiously. Due to the discovery of vapors in the building across the street, DEC has determined it cannot wait until later this month for wells to be installed, and it will proceed with the work needed early next week. Letter from DEC Tipple to CEG Iannone-7/5/01. Justification for rationale for installation of well in basement of 103E10th St. Letter from CEG Iannone to DEC Tipple-7/12/01. Request for monitoring data and well logs and quarterly progress reports. I must continue to confirm that 3/10 Tenants Housing Corporation, the owner of the cooperative building at 103 East 10th Street does not consent to the installation of this well . Affadavit (DEC Tipple)-8/23/01. Order to Permit Entry Upon Land. Letter from AG Riggi to Carole Ule (Esq.)-10/3/01. The stipulation looks fine to me. If you execute two originals, I will sign both and return one to you for filing with the Court . Ule represents 103E10th St. 103E10th St will hook up to remediation system in basement of 105E10th due to lack of space in 103E10th for system. Quarterly Project Status Report (EAR) Jan 2002 to March 2002-9/20/01. Groundwater flow direction shifted from east-southeast to a more northerly then a north/northwest direction. Tanks in 107E10th St have recovered 416 gallons to date. Installation of a well in the northwest corner of 103E10th occurred. Baildown/recharge test of well in basement of 103E10th was performed but was inconclusive. Recovery system consists of four submersible pumps, 3 portable centrifugal well pumps for basement wells and 5 SpillBuster automatically adjusting pumps. Vapor extraction wells also occur in basement of 109E10th. Report recommends continuation of monitoring, cleaning oil water separators, investigate use of biorem beneath the buildings at 109 and 113E10th, delineate and recovery of product found in 1032E10th St. Meeting List-4/22/02. At meeting was EAR, DEC, CEG, John Crane, AG Riggi. Site Plan-7/21/02. Northwest-southeast oriented line separates responsibilities of 103E10th and 105-107E10th Street. Corrective Action Plan (CEG Iannone)-7/21/02. 3/10 THC intends to contract with EAR to continue work and maintenance. The prospective owners of the building at 105-107 East 10th Street and the current owners of the building at 103E10th Street (i.e, 3/10 Tenants Housing Corporation) have agreed on a division of work currently required by the NYSDEC to address these two spill sites .

103 EAST 10TH STREET (Continued) **S104620874**

Document describes in detail reponsibilities of each party. CAP includes weekly well monitoring of wells (W1, W3, W8, W9, W11, W12, W13, W18, W19, W20, W24, W25, W27, W28, W29. Product recovery includes existing wells and recovery systems installed by DEC and collection of effluent samples. Vapor abatement system will be operated by 105-107E10th Street. 3/10 Tenants Housing Corporation would continue to operate the vapor abatement system until Spill #9913474 has been closed by the NYSDEC. Reports will be submitted to the Department quarterly. 10/16/07-Vought-File review continued by Vought: Corrective Action Plan (CEG Iannone)-8/5/02. New CAP submitted including DEC Tipple's requirements after review. 3/10 THC will perform the following tasks: 1)Weekly well monitoring and if product is encountered, bailing 2)Product recovery via use of previously installed submersible pumps, spill busters and MPX events 3)Biweekly maintenance of submersible pumps and sumbission of status reports 4)Biweekly maintenance of dual phase portable pumps and submission of stautus reports 5)Biweekly maintenance and adjustment of oil/water separator 6)Biweekly collection and analyses of groundwater treatment system effluent 7)Weekly maintenance of holding tanks 8)Operation of vapor abatement sytem if spill 9611309 is closed and DEC continues to require operation. 9)Submission of quarterly status reports. 10)Possible use of Bio-rem in Closure Plan upon no more free product. 11)Sampling of groundwater for dissolved parameters. Closure may be considered upon four rounds of asymptotic groundwater levels. Letter from DEC Tipple to CEG Iannone-8/5/02. DEC reviewed the CAP and required title to be changed to Remediation Plan and after ALL product is removed from wells the remediation of any other soil and or dissolved petroleum contamination will be addressed. STIPULATION AGREEMENT with due date of 8/20/02 sent by DEC Tipple to: Ms. Heather Verran Ramo 3/10 Tenants Housing Corporation 103E10 Street New York, NY 10003 Remediation Plan and Signed STIPULATION AGREEMENT (CEG Iannone)-8/16/02. Copy of remediation plan and signed Stip. 10/17/07-Vought-Continued File Review by Vought: Email from CEG Iannone to DEC Tipple-10/1/02. This is to let you know that the EAR contract has been signed and they will be starting work tomorrow... Memorandum (CEG Iannone) to DEC Tipple-4/22/03. Attached please find the draft product thickness tables and maps for 103E10th Street... Project Status Report April-December 2002 (CEG Iannone)-6/19/03. ...only 17 gallons of product have been removed from the 5 sidewalk product recovery wells and an additional 9.5 gallons was removed from basement well. However, groundwater flow during this period has reversed direction due to last year's drought and some product has now probably moved to the subsurface soil beneath the building at 103 East 10th Street . Report recommends reduction to monthly monitoring and increase in frequency of manaul bailing as opposed to operation of product recovery system. EAR report shows groundwater flow to the north/northwest. Trace free product in W12 and W13 and .33'FP (W20), .46'FP(W28). Product levels of 1 to 3 feet have consistently accumulated in W29 which is bailed weekly. Operation of portable recovery pumps in basements of 109 and 111 E10th discontinued due to lack of free product (FP) and product now removed via and absorbent socks and no effluent samples being collected and system not on and no discharge. Spill Buster pumps still in operation and maintained biweekly and removed 17 gallons referred to above during this period. Report recommends reduction to biweekly well monitoring, temporary discontinuation of operation of pumps in W7, W21, W22, W23 and W26, manual recovery of product and

103 EAST 10TH STREET (Continued) **S104620874**

more frequent manual recovery of product in W29. Email from CEG Iannone to DEC Tipple-7/30/03. Iannone no longer working for CEG and is working for Day Engineering. 10/18/07-Vought-File Review continued by Vought: Project Status Report (Day Engineering and EAR) Jan 2003 thru June2003. Groundwater flow direction reversed and assumed previous direction of south-southeast. Report recommend change to monthly well monitoring, discontinuation of product recovery system using portable wells, removal of product from recovery wells and W29 via peristaltic pump which was approved by DEC on 9/5/03. 8 week test program of manual product removal from wells via peristaltic pump will be initiated and report will be submitted to DEC. Proposed Revision to the Remediation Plan (DAY Iannone)-8/26/03. Report proposed use of manual bailing and discontinued use of the troubled automated product recovery system . Revisions include weekly product recovery, monthly monitoring for a period of three months, Letter from DEC Tipple to Iannone-9/5/03. DEC reviewed Proposed Revision and will allow a two month pilot study with a subsequent analysis of the effectiveness provided that product is removed from W29 and the recovery wells three times per week for the first four weeks of the study, removal of product from wells W7, W21, W22, W23 and W26 using peristaltic pump. Report to be submitted to DEC within ten days of the 8 week pilot study. If DEC does not recevie report within that time, product recovery system will be completely rehabiliated and reinstalled. Email from DAY Iannone to DEC Tipple-9/5/03. Iannone received 9/5/03 letter from DEC Tipple and all looks good to me . Email from DEC Tiplle DAY Iannone-10/15/03. DEC requires submission of bailing schedule with specific dates. Email from DAY Iannone to DEC Tipple-10/17/03. Product pumping will begin on 10/21/03 and subsequent specific schedule attached. Email from DAY Iannnone to DEC Tipple-10/29/03. Proposal to install socks in four recovery wells due to the absence of product that will be maintained weekly, discontinuation of three times bailing per week for these four wells. Socks to be placed in wells W7, W21, W22 and W26 this week. Email from DEC Tipple to DAY Iannone-10/29/03. Request for amount of product recovered from wells, rate of recovery, proposal to check socks. Email from DAY Iannone to DEC Tipple-11/3/03. Only appreciable amounts of product recovered are from wells W23 and W29, recovery rates for W29 are between 1-1.5' of product every one to two days, and no need to check socks as no product in these wells for over one year. Proposed Changes to Revised Remediation Plan (DAY Iannone)-11/5/03. Four of five product recovery wells in sidewalk have no free product and proposal to install socks and monitor weekly. Revised Remediation Plan (DAY Iannone)-12/22/03. During 8 week program a total of 11.69 gallons of product removed from W23 and W29. Proposal for manual bailing of product 1 to 3 times per week for next 2-3 months, monthly monitoring of socks in former product recovery wells, quartertly monitoring of wells without free product. Letter from DEC Tipple to DAY Iannone-12/23/03. ...there was never an approved revision to the August 16, 2002 NYSDEC Stipulation . DEC allowed a two month pilot study with subsequent analysis. Complete report summarizing findings must be submitted to DEC Tipple within ten days. DEC awaits monthly groundwater elevations, status of all wells, and site map with groundwater flow direction. There is no revised remediation plan approved by the NYSDEC for the site, there is currently a two month pilot study being conducted . Letter from John J Grogan to DEC Tipple-2/13/04. We are writing to obtain a follow-up on the status of the above mentioned spill and the impact

103 EAST 10TH STREET (Continued) **S104620874**

it has has on our property (109-119 East 10th Street). Request for definitive date when wells will be removed as well as all other monitoring equipment. Project Status Report (CEG Iannone) July 2003-March 2004. ...little or no product has been observed in 18 of the 20 Site monitoring wells during this reporting period. Two wells, W23 and W29 still have accumulating product. ...manual product removal methods equal and, for some periods, exceed the removal rate acheived by the automated product removal system . Groundwater flow to the north. Two wells with product are W23 and W29. 13.77 gallons of product removed from W23, 6.18 gallons removed from W29 and .16 gallons removed from other wells. Current product recovery methods will continue until no more measureable product in wells. Letter from DEC Tipple to 3/10 THC (Verran Ramo)-4/9/04. Please be advised that you are in violation of the Stipulation . DEC currently awaiting completed study of proposed future remedial strategies at the site. As per Section 3.3 of the August 7, 2002 Remediation Plan, the vapor abatement system will be the responsibility of the 3/10 Tenants Housing Corporation after spill 9611309 has been closed . I am currently awaiting the March 2004 Quarterly Report . Letter from DEC Tipple to 3/10THC Verran-Romano-8/19/04. Spill 9611309 has been closed. Operation and maintenance of vapor abatement system will be turned over to 3/10 THC. Email from DEC Tipple to DAY Iannone-12/28/04. I am awaiting acknowledgement that 103 is now responsible for both the remediation systm as well as the vapor abatement system... . Request for past due Nov 2004 report. Residents of 105-107 E10th complained about noise from vapor abatement system. 10/22/07-Vought-Continued File Review by Vought: Email from DAY Iannone to DEC Tipple-12/28/04. 3/10 THC has assumed responsibility for operation of the vapor abatement system related to this spill . The vapor abatement system is now operating and in good condition and is being maintained by EAR. Rubber isolation material installed to address noise complaints. Product still occasionally noted in W23 and W29 and ERM hired to perform groundwater monitoring and manual product recovery and if present is 1 to 3 in thickness. Project Status Report (DAY Iannone) April 2004-Dec 2004. As discussed in the report, no product has been observed in 18 of the 20 site monitoring wells during this reporting period . 8 gallons of product removed from W23 and W29. Socks have no product. Average product thickness is .02'(W23) and .06'(W29). Groundwater flow to the north. Removal of product fromw wells W23 and W29 2 to 3 times per week via portable peristaltic pump. THC has assumed responsibility for that system since that time (vapor abatement system). Vapor abatement system is currently in operation. Exhaust fans installed in basements of 109 and 113 East 10th Street to remove stray petroleum odors and intake grills were installed. Vapor extraction blower is also in place in sump of 109 E10th to remove vapors and two dedicated SVE wells in same basement. Vapor phase treated using carbon canister. Report recommends manual bailing till product no longer present at which socks will be installed and groundwater sampling be proposed. Email from DAY Iannone to DEC Tipple-1/4/05. W29 had two feet of product. Project Status Report (DAY Iannone) Jan 2005 to May 2005-5/19/05. 2.4 gallons of product removed from W23 and W29. Enclosed email request to perform short-duration test of vapor abatement system (ie shut down system for 2 to 4 days). Groundwater flow to the north. OM&M includes semi-annual monitoring of all wells, monthly monitoring of recovery wells and weekly monitoring and recovery of W23 and W29. 2.35 gallons of product removed during period. Recommendation for

103 EAST 10TH STREET (Continued) **S104620874**

further monitoring. Project Status Report (DAY Iannone) May 2005 to Aug 2005-5/19/05. One gallon of product total removed from W23 ane W29 during period. Groundwater flow to the north. Product recovery from W23 and W29 1 to 2 times per month. Recommendation for further monitoring. Letter from John G. Grogan to DEC Tipple-9/13/05. Letter requesting status and request to provide definitive date that wells will be removed from property as well as removal of all other monitoring equipment. Letter from DEC Ketani to Verran-Ramo and DAY Iannone-9/16/05. DEC agrees with current groundwater monitoring schedule. Written request must be submitted to use socks in place of manual product recovery. Letter from DAY Iannone to DEC Ketani-11/18/05. Approximately 407 gallons of product was removed from August 1999 through September 2003 using the automated product removal system... and 32 gallons have been removed manually. Absorbent socks will be placed and monitored in each of these wells . (W23 and W29). Spill #0511701 101E10th Street-1/10/06. Spill reported by Eric Telemaque (Emteque 212-631-9000) that tank was uncovered during excavation and discolored soil was noted from 14' to 20'bg. See this spill for continued file. Progress Report (DAY Iannone)-4/19/06. Only W29 still has product. As you can see, product levels in well W29 rose unexpectedly in February 2005 . Product levels up to 1'. No product or petroleum release was reported to the NYSDEC when the adjacent building including the basement of that building, was demolished and removed . Proposal to continue monitoring and removal until product no longer present for 3 months and upon then NFA will be proposed. Letter from AJ Clarke Real Estate Corp (Stephen DeNardo) to DEC Ketani-4/21/06. Letter from DAY Iannone to AJ Clarke Real Estate. Letter providing status of two ASTs at 105-107E10th St. Tanks still inservice. Included was copy of FDNY violation for fuel oil storage with out FDNY permit. Letter from DEC Ketani to Walden Pond Realty-5/16/06. I am writing to explain the status of the tanks which are of concern . The tanks and the oil/water separator will have to remain at 107 East 10th Street for the forseeable future . Progress Report (April to August 2006) and Closure Request (Day Iannone)-9/6/06. W29 still contains product. Product levels in well W29 have diminished to low levels but occasionally there are still measurable levels of product accumulating in that well. We continue to remove this product during each of the Site visits but believe that we have no removed the petroleum related to this spill to the extent practicable . One half gallon of product removed since last report. With regards to adjacent excavation at 101E10th St, Photographs of that excavation demonstrate that the soil remaining at the bottom of the excavated area and the soil staged for off-site removal appears to be clean and does not appear to be impacted from petroluem from the adjacent building, i.e 103 East 10th Street . No Further Action requested on basis of absence of product. Letter from John J Grogan to DEC Vought-9/22/06. Request for status of spill and definitive date upon which all monitoring wells can be removed. Grogan received notice for cracks in sidewalk. Letter from DEC Vought to Michael Brandt (John G Grogan)-11/21/06. Continued monitoring is required... and as such request to remove monitoring wells is denied. 10/22/07-Vought-After complete file review DEC requires: 1)call to AG for status of PIN-PIN closure for 9611309 due to 8/19/04 NFA? or keep open due to ongoing cleanup by 103E10th? 2)recent round of groundwater monitoring data for all wells and adjustment of OM&M schedule to quarterly monitoring of all wells and monthly monitoring of wells with free product.

103 EAST 10TH STREET (Continued) **S104620874**

3)Boring to the north (downgradient) 4)cc or call to John G Grogan 5)dissolved groundwater sampling of all wells, confirmatory SUMMA sampling in 105/107/109/113 east 10th St,closure of monitoring wells, vapor abatement system, product recovery tanks, vapor extraction system upon request for spill closure as per STIP RAP
01/16/08-Vought-Called AG Riggi for status of PIN and discuss further scope of work. PIN was settled and RP did execute STIP and nothing further was billed to fund. AG Riggi requested to be cc'd on letter and informed if RP did not meet obligations and Spill Funds were needed. AG Riggi suggested that PIN remain open until RP meets DEC's current obligations and requirements above. DEC sent letter with cc to AG Riggi and M. Brandt and TWO MONTH DEADLINE requiring: 1)Increase in well monitoring frequency in wells with free product to a biweekly basis 2)quarterly groundwater monitoring and sampling for EPA Methods 8260/8270 3)Delineation of groundwater contamination via installation of downgradient well to the north 4)PID survey of adjacent residences of possible consideration of vapor abatement system removal. Vought called Iannone (Ph:212-986-8645 Fax:212-986-8657) to discuss scope of work. Vought spoke to Iannone regarding biweekly monitoring and above scope of work and Iannone suggested performing another round of groundwater monitoring to confirm groundwater flow prior to delineation.
04/16/08-Vought-Received call and email from John Iannone (212-986-8645 Fax:212-986-8657) and called Iannone and left message to return call to cell phone. 04/24/08-Vought-Received message from Iannone. Vought returned call and left message to return call. Vought received call and spoke to Iannone and he is working with co-op and he has been authorized scope of work. Iannone will send in well monitoring records that show less than 1 -1.7 inches in sidewalk and such he requested biweekly product recovery that was approved by DEC. Baseline groundwater monitoring will performed on all wells. Groundwater elevations will be surveyed and groundwater flow direction. Once groundwater flow direction is determined then downgradient wells will be monitored and sampled. PID survey will be performed including ambient sample. Iannone will send in workplan.
5/9/08 - Raphael Ketani. Today I received a letter with NYFD violation attached from Stephen DeNardo of A J Clarke Real Estate Corp. The letter requested that I send an updated letter regarding the need for the holding tanks that were installed by DEC to aid in the recovery of product. The violation was issued because the building didn't have a permit from the NYC Dept. of Buildings for the holding tanks. A copy of the first letter from DEC dated 5/16/2006 explaining the need for the tanks was attached. Since I am not the case manager, I forwarded the letter to Mr. Vought.
06/4/08-Vought-DEC Ketani received fax from AJ Clarke dated 4/17/08 asking for return call for status of site. Fax included copy of letter from DEC Ketani to Walden Pond Realty stating that there were two 275-gallon tanks at 107 East 10th Street as a part of state funded cleanup. As per DEC Ketani one well at site was still being monitored as part of cleanup and that tanks have to remain at property for forseeable future . Vought also received letter dated 5/6/08 from AJ Clarke including copy of FDNY violation for third time due to tanks in the basement of 107 E10th st. Vought called Iannone and he is still using product holding tanks and no basement in 103E10th Street. Less than 2 of product in wells and during one week almost one foot of product. Iannone pays rent to 107E10th Street for tanks and Iannone will be submitting workplan. Vought called AJ

103 EAST 10TH STREET (Continued) **S104620874**

Clarke (Stephen DeNardo 212-541-4477) and left message to return call to DEC. Vought discussed site with DEC Austin who said that no letter will be issued by DEC requesting tank does not have to be registered or no violations should be issued as tank is now privately owned and must conform with all applicable regulations. Vought called Iannone and summarized that DEC would not negotiate FDNY violations. Letter submitted to DEC Austin for approval and addressed to: Walden Pond Realty, LLC c/o Stephen Kaplan AJ Clarke Real Estate Co. 1881 Broadway New York, NY 10023 Fax:(212)541-4872 06/06/08-Vought-Vought forwarded copy of draft letter to AG Riggi for approval and AG provided edited draft and Vought sent and faxed out letter to Walden pond with cc to Iannone and DEC Austin. 04/20/2009-Vought-File review to date: Project Status Report (Day Engineering)-7/31/08. Report covers period from 9/07 thru 7/08. Groundwater flow to the North. Product only present in wells W23, W29 and W26. Product in well W29 can only be manually recovered from this well since building codes and space limitations preclude the use of an automated product recovery system for this well . Approximately five gallons of product have been removed in the past ten months with 48 gallons removed to date since manual product recovery began in 2003. In response to DEC request, recovery frequency was increased from 6/08 to 7/08 from biweekly to twice per week. ....manual product recovery has had little, if any effect on the relatively low levels of product remaining at the Site . Because of the physical constraints and limited product removal options at this site and on the inability of the existing product recovery methods to reduce the relatively low product levels in well W29, other approaches, such as monitoring, should be considered for this site . Product currently being removed twice per month. Final Investigation and Remdial Work Plan (ERM)-August 2008. Scope of work includes monitoring and sampling of all wells, possible downgradient well installation, determination of groundwater flow direction. Up to ten monitoring wells will be sampled for laboratory analysis , proposal for PID survey in buildings including possible collection of draeger tubes and building inventories. Project Status Report (Day Engineering)-11/6/08. Site visit suggested by Iannone. BWeekly NAPL Removal Test Program (Day Engineering)-11/06/08. ...(Day) recommends that NAPL removal actions be discontinued at this Site and that future work at the Site be related to the presence of NAPL be limited to quarterly monitoring of NAPL thickness in affected wells . DAY recommends that these ineffective manual NAPL removal efforts be discontinued and replaced with a program to monitor the two affected Site wells 04/20/09-Vought-Called John Iannone and left message to return call to arrange site visit. DEC requires: 1)sock installation? 2)excavation of abandoned tank? 3)disapproval of proposed quarterly monitoring only method in Work Plan. 4)dissapproval of up to ten wells being sampled and inclusion of all wells to be sampled in Work Plan. 5)disapproval of necessity of draeger tubes and PID background surveys unless desire of consultant to perform in Work Plan and arrangement of NYCDOH site visit if PID surveys show no petroleum impact. 6)Approval of determination of groundwater flow and possible installation of downgradient well as per ERM report. 06/03/09-Vought-Received email reply from Iannone on 5/11/09 that ERM representative (Tiernan Smith) available for site visit. Vought also received a call from and spoke to Tim Grogan who requested that sidewalk structures be abandoned in front of 113 E10th as well as removal of PVC piping from rear of property. DEC requires: 1)call to

103 EAST 10TH STREET (Continued) **S104620874**

AG for status of PIN-PIN closure for 9611309? or keep open due to ongoing cleanup by 103E10th? 2)close spill/PIN for 9611309 due to 8/19/04 Tipple NFA? 3)quarterly groundwater sampling from all wells. 4)Site inspection of 103W10th to determine feasibility of alternative recovery methods such as trenching or excavation of abandoned UST as free product still onsite after seven years. 5)Requirement letter after site visit with cc to Iannone, Grogan and Riggi and review of letter prior to transmission by NYSOAG Riggi. 06/03/09-Vought sent email to Iannone, Tim Grogan (tcgrogan@groganassoc.com) and John Grogan (john@groganassoc.com) providing free times for site visit to determine alternative remedial action (free product still present) and also that dissolved groundwater sampling needed prior to well abandonment as requested by Grogan. Vought called and spoke to Riggi and PIN/Spill will be left open for 9611309 in case RP (Iannone) fails to meet DEC requirements and NYSOAG assistance is needed. Riggi requested she be cc'd on all correspondence to Iannone. Vought called Iannone (212-986-8645) to discuss site visit and need of quarterly groundwater sampling and left message. 06/17/09-Vought-Site visit by Vought with: Marilyn Appleberg (111 E10th St Bd of Directors) Tim Grogan John Grogan John Ianone (Day Engineering) Tiernan Smith(ERM) Mario Sciacca (ETNA Contracting 718-858-4668 will replace sidewalk concrete for 111 E 10th St). Well W9 depth to water is 11.92' with sheen and no product and no product in MW8 with depth to water of 12.52'. Grogan and Appleberg and tenants of 111 E10th st want to replace sidewalk due to cosmetic reasons and inquiring if structures in sidewalk in front of their property can be abandoned (structures in sidewalk include monitoring well MW8 and well MW9 that is in square concrete pit with steel trap door with out of service remediation wiring. Vought required Ianone and Smith to perform dissolved groundwater sampling from wells before determination of abandonment or replacement in new sidewalk can be made. Iannone to perform dissolved groundwater sampling next week so that results will be back by Vought's return from vacation. Appleberg expressed concerns over historical petroleum vapors Product recovery ongoing via peristaltic pump. Vought also received table of groundwater monitoring results and most recent monitoring from 5/28/09 shows .27'FP*W23), .01'FP(W26), .48'FP(W29). Next onsite meeting set for 7/1/09 at 10am. Ianone will also begin on obtaining estimate to remove aboveground SVE piping from 111E10th St. Vought inspected 103 E 10th St and abandoned UST is directly under basement apartment. Iannone currently using storage tanks in 107E10th st for oil however access and payment of rental for space is making recovery operations not feasible and Iannone will switch to using onsite storage tank at 103 E10th St. Vought sent email to all parties at meeting today and NYSDOH Hughes and NYCDOH Stallbohm requesting site visit at 111 East 10th ST by NYCDOH for vapor survey. Next meeting scheduled for 7/1. 7/03/09-Vought-7/1 meeting cancelled as groundwater results expected from Iannone on 7/6 and no product found in wells W8 amd W9.. NYCDOH site visit results received on 7/1/09 from NYCDOH Allan Friedman(212-442-3372). At the time of the visit, John Grogan was present. No odors of oil, no volatile organic compounds detected and no visible oil contamination noted at time of site visit. 07/06/09-Vought-As per CAP dated 8/5/02 and RAP dated 8/7/02, The closure plan will be prepared and submitted to the NYSDEC for approval when all product related to spill 9913474 has been removed from the wells associated with this spill. If necessary, closure activities may include the addition of nutrients and other NYSDEC

103 EAST 10TH STREET (Continued) **S104620874**

approved agents to monitoring wells with limited amounts of product (e.g. a sheen or less than 0.01 feet of product) to enhance the natural biodegradation and removal of this material from the affected wells. In addition, closure activities will address the remediation of any soil and/or dissolved petroleum constituents in groundwater related to spill #9913474. Work to confirm that closure criteria is satisfied includes collection of dissolved groundwater samples. DEC prior approved product recovery method of handbailing being used for past five years with minimal reduction in product thickness. As such product levels are relatively stable and closure criteria have not been approached in past seven years. RAP included continual operation of automated and manual product recovery systems however due to relatively low product thickness, operations of these systems are not feasible and as such alternative remedial methods must be considered. Note that source excavation not possible as abandoned UST located directly under residential apartment at 103E10th St. Vought sent email to NYSOAG Riggi inquiring if RAP approval can be withdrawn so that dissolved groundwater samples may be collected and alternative remedial methods (such as injection of agents) may be considered to reduce free product thicknesses as they have remained relatively constant with hand bailing for past five years. Vought also to inquire of NYSOAG Riggi as to who is RP for SVE system removal along with monitoring well and recovery equipment. (Note that as per CAP and RAP, 3/10THC is responsible to operate and maintain system but no mention made of systems decommissioning. Site visit scheduled for 7/8/09. 7/8/09-Vought-Site visit by Vought with Iannone and John Grogan. Vought inspected basement of 107 E 10th St with super (John-cell(917)577-7341, fax:212-533-9538) and three 275-gallon ASTs still in place (two used for recovery tanks for hand bailed product) and one for out of service oil/water separator for old recovery system. Iannone using product recovery for hand bailed product however due to low recovery amounts he will place drum in basement of 103 E10th St to store recovered oil. Vought inspected AST in 107 E10th and noted 5000-gallon AST with weepholes and no sign of leakage. Vought also noted remnants of vapor recovery system also in boiler room of 107 E10th St that also needs to be removed by Iannone. No vapors or signs of oil seepage into basement of 107 E10th St. Owner rep for 107 E10th St is Steve Kaplan (Ph:212-541-4477x22 fax:212-541-4881). Iannone will send email with schedule of well decommissioning and SVE/Ejector piping removal. Vought sent email to Iannone, Grogan, Appleberg, Kaplan with requirement of removal of ejector piping and SVE piping and decomissioning of wells from buildings 105 E10th St thru 111 East 10th St. Email from Grogan to Iannone that super onsite and will accomodate whatever is needed (super is Juan Balandra 917-496-1602). Well abandonment scheduled for Friday of MW8 and MW9. 7/10/09-Vought-Received email from Iannone. As per the Stipulation and the NYSDEC approved Remediation Plan for 103 East 10th Street..... only wells W11, W12 (at 109 East 10th Street) and W13 (in 111 East 10th Street) had product recovery equipment and have been assigned to 103 East 10th Street. The responsibility for the remaining wells and associated product recovery equipment in 109 and 111 East 10th Street and all of the wells and associated product recovery equipment in 113 and 115 east 10th Street were assigned to the owners of 105-107 East 10th Street. Iannone will ask contractor for proposal to remove the vapor abatement equipment in 107, 109, 111 and 113 East 10th Street and the product recovery system equipment from wells W11 and W12 in 109 East 10th Street. Attached is a list of

103 EAST 10TH STREET (Continued) **S104620874**

vapor abatement and product recovery equipment for which he is obtaining cost proposal to remove. Vought received call from and spoke to Riggi and will send Riggi copy of CAP and RAP and will also return call to her with DEC Tibbe who was involved in negotiation of CAP and RAP. Vought sent copy of RAP to NYSOAG Riggi. Vought later received email from Iannone that he thought that the wells and product removal systems that were assigned to 105-107 East 10th Street and that were in the basements of 109-113 have already been closed and/or removed. I think that John Grogan and I just need to meet at the site some time and go through it again. Vought copied on email from Grogan to Iannone requesting site walkthrough with Appelberg and Iannone will get back to Grogan with date. Vought received another email from Iannone that wells in front of 111 East 10th St (W8 and W9) was completed by Metro Environmental Contracting Corp. Vought also received email from Iannone with copy of DEC Tipples letter dated 8/19/04. Ianonne felt that letter explains that wells and remedial systems in 109-113 E 10th were 105-107's responsibility and that the systems had been removed and the wells closed. Letter stated system was removed and granted NFA with no mention of responsibility. 07/13/09-Vought-Received email from Grogan that The buildings 109,111,113,115,117&119 which are all one property were the innocent victims here. We had no spill this was all around us, all that is being asked is that what ever was put in wells, pumps or measuring devices be removed and things be put back to there original state. Your cooperation and understanding in this matter is greatly appreciated. 07/14/09-Vought-Called and spoke to Iannone and asked for clarification on emails of 7/10 as to whether remnants of the recovery system were still at 111 East 10th St. As per Iannone the only remaining piping is that for the venting system at 109-111 East 10th St and that product recovery system still present at 105-107 E 10th St and that he will have estimate to have both systems removed in two weeks and contractor will be selected within three weeks. Vought sent email to all parties with above information. Vought also called John Grogan to explain update.
08/04/09-Vought-Received email scope of work from Iannone from Metro Environmental that included removal of only the two 275-gallon oil storage tanks, one 275 gallon oil/water separator and all associated piping and equipment. Carol Ule cc'd on email. Vought replied with cc to all and NYSOAG Riggi and DEC Austin that department approved scope of work pending inclusion of the removal of the vapor extraction equipment as well. 09/10/09-Vought-Received call from Grogan expressing fustration that the vapor extraction system and product recovery system have not been removed to date. Vought drafted drop dead letter to remove systems and requirement letter for submission of new RAP and sent to NYSOAG Riggi for approval prior to transmission to RP. Vought informed DEC Austin of same.
09/11/09-Vought-Spoke with NYSOAG and she will use 9/10 letter as template letter to send requirements directly to Carole Ule.
09/14/09-Vought-Reviewed Riggi template and editted.
09/16/09-Vought-Received email from Riggi that she was contacted by Ule. Vought called Riggi and Riggi to arrange either teleconference with Ule and Vought and/or meeting at Region 2 offices with participation of Riggi in person or via phone from Albany. Letter issued by NYSOAG Riggi to Carol Ule, Esq dated 9/16/09. Work notes that Department requires additional work including removal of vapor extraction equipment and product recovery equipment. 'It's DEC's position that failure to timely remove this equipment is a breach of

103 EAST 10TH STREET (Continued) **S104620874**

the Stipulation Agreement from August 2002 and the associated Corrective Action Plan (CAP) and Remedial Action Plan(RAP)... . If you wish to discuss this matter, please call me . 9/17/09-Vought-NYSOAG Riggi discussion with Ule and Ule noted possible additional source of contamination to 103 E 10th St as from 101 East 10th Street (see closed spill notes 0511701 for updates). 09/18/09-Vought-Received email fro NYSOAG Riggi with additional inquires regarding spill notes and Ule will be approaching owners of 107 to work out agreement on equipment removal. Request to return call when reviewed spill 0511701. 9/22/09-Vought-Letter from Ule to NYSOAG Riggi-9/22/09. Response to NYSOAG letter dated 9/16/09. Request for a meeting. This letter id onthe subject of the removal of the product. I will be writing you separately on the subject of the removal of the vapor abatement and storage tank equipment in the buildings east of 3/10. ....our belief that the remediation of our spill sustained a setback when our neighbor immediately to the west, 101 East 10th Street, demolished its existing building and excavated its property preparatory to building a new, bigger building... . Attached is product recovery showing a steady progression of dimunition until March 2006 when there was a big spike up from the prior reading of December 2005. This anamolous spike coincided with the excavation which unearthed Spill #05-11701 on the property immediately to our west, 101 East 10th Street, as set forth above. As you will see, although the amount of product recovered starting after December 2005 spiked, it has now been brought under control. See chart . In the opinion of our engineer, no additional recovery installations wouild serve any purpose . Request for meeting. VOUGHT PERSONAL NOTES on product spike in letter dated 9/22/09:The big product thickness spike that is after December 2005 shows an increase of 1.40'. A similar spike of 1.40' increase is observed in July 2006, a 1.0' spike is observed in Sept 2004 and a 1.20' increase is also observed in December 2006. The large number of additional spikes shows that the December event is not satistically significant as a major event. Furthermore if 101 E 10th construction was source and 103 was succesfully remediated close to closure we should see STEADILY decreasing thicknesses from October 2003 thru Dec 2005 and constant high thicknesses after Dec 2005 not the fluctuating thicknesses which are observed. Note we see a decrease to almost 0' in 2006 after construction of the building and if the building construction caused an increase of product to 103 then this O' reading would not be there. Furthermore, product thicknesses alone cannot be used for source determination, they MUST be combined with hydrographs and groundwater contour maps with flow direction as product thicknesses are known to fluctuate with rising and lowering water table. Department feels the fluctuations in thickness are soley due to fluctuating groundwater levels caused by possible adjacent sump pits and or geology. Fluctuating groundwater conditions were also observed at spill 0511701. Futhermore to use product thicknesses only as a determination of source is not adequate, the pathway from the potential source to receptor MUST BE DEFINED via sampling (note no free product in groundwater at 101E 10th Street) and groundwater flow direction monitoring. Department also notes three steady monitoring events close to 0' in December 2007 (this is the same as observed prior to the big spike in December 2005) again suggesting that the three events close to 0' product thickness is not a one time event and is a function of groundwater fluctuations. ALSO to suggest that product thickness increases are a due to product migrating

103 EAST 10TH STREET (Continued) **S104620874**

onsite also implies that product decreases are due to product flowing off-site and hence during the product decrease events in the same graph, 103 E 10th St THC was impacting 101 East 10th Street. Ule states in letter that product recovered has now been brought under control however note that the last two monitoring events had the same magnitude and fluctuation of product thickness as March 2005 indicating that product recovery via manual bailing is having no effect on product thickness and hence cleanup of the site. 9/22/09-Vought-Letter from Ule to Riggi dated 9/22/09. Letter regarding removal of vapor extraction and product recovery systems. To the extent that 3/10 is legally obligated to pay for the removal of any of this equipment, it is prepared to do so, but 3/10 believes that it is not obligated to pay for all that work, as is set forth below. We await only confirmation from our neighbor that it is satisfied with the insurance certificates which have been provided and to schedule the work for a date certain. .....since we query who has the obligation to pay for the removal. We did not install the two vapor abatement systems and we did not agree to pay for their removal. The DEC's present request that 3/10 Tenants Housing Corp pay for the removal of the two vapor abatement systems in the neighboring buildings is an attempt to rewrite the remediation plans which were accepted by the DEC and the property years ago and the DEC should not be able to rewrite those agreements, especially by imposing new obligations on neighboring properties. ...we have reached out to our neighbors at 105-107 East 10th Street to come to a resolution of the matter and are preapred to bring the issue to a fair and neighborly resolution. Request for a meeting. Request for extension of 9/23/09 until 10/2. Letter from Day Engineering (Iannone) to Ule-9/21/09. Enclosed is product recovery chart same as that with 9/22/09 letter. I was not aware of the presence of an underground storage tank or the petroleum contaminated soil at 101 East 10th Street before receiving the attached information on Spill 0511701 from NYSDEC in July 2009. It is my opinion, based on information recently provided by the NYSDEC regarding Spill 05-11701 and on the attached product thickness chart for well W29, that the petroleum identified in subsurface soil and groundwater at 101 East 10th Street has probably contributed to some or most of the increased product thickness levels observed in well W29 since January 2006. VOUGHTS PERSONAL NOTES on Day Engineering letter-As per Progress Report submitted by Day Engineering and written by John Iannone dated 9/6/06 In addition, the recent demolition and construction project on the adjacent property (i.e. western) property discussed above included the excavation of soil on that property to depths near the water table (i.e. approximately 10 feet below street level). This property is located directly west of and abuts the building at 103 East 10th Street. Photographs of the excavation demonstrate that the soil remaining at the bottom of the excavated area and the soil staged for offsite removal appears clean and does not appear to have been impacted by petroleum from the adjacent building, i.e 103 East 10th Street. John Iannone himself saw the excavation to depths near the water table and observed the soil remaining at the bottom of the excavated area and the soil staged for offsite removal appears clean and does not appear to have been impacted by petroleum. If 101 East 10th st was the source of free product to 103 East 10th than Iannone should have obseved grossly impacted soil and free product onsite. Futhermore, the Department had no obligation to report the spill to Iannone. See personal notes above as well for letter dated 9/22/09.

103 EAST 10TH STREET (Continued) **S104620874**

10/22/09-Vought-See closed spill 9611309 and open spill 9913474. Letter received from consultant for 103 East 10th St (spill 9913474) who states in letter that it is my opinion that based on the information recently provided by the NYSDEC regarding spill 0511701 and on the attached product thickness chart for well W29, that the petroleum indentified in subsurface soil and groundwater at 101 East 10th Street has probably contributed to some or most of the increased product thickness levels observed in well W29 since January 2006. Vought reviewed soil and groundwater data from the file and noted the following: Limited Subsurface Investigation Report (Emteque)-1/11/06. Six test pits were installed to a maximum depth of 23'bg; the whole property was previously excavated to approximately 13'bgs with collection of fourteen test pit soil samples. An approximately 6ft layer of discolored soil with old petroleum odors was encountered 14 feet bgs and extending to approximately 20 feet bgs throughout the site. In the entire six(6) test pits excavated, petroleum odors and several VOCs were identified from approximately 14 to 20 feet bgs... However no petroleum odors or VOCs identified in the sample collected from 23 feet bgs. At the time of the investigation, scattered ponds of standing water were observed in the excavation bed. The UST was partially filled with seepage water and its invert was at 14 feet bgs . Moist and wet soils were encountered in all six test pits near termination depth. Perched water was observed at various elevations above water table. Soil analyticals show:33000ppb 1,2,4-trimethylbenzene(TP3), 9900ppb 1,3,5-trimethylbenzene(TP3), 22000ppb napthalene(TP3), 12000ppb xylene(TP3), 40000ppb methylnapthalene(TP3), 3800ppb xylene(TP4 18'), 27000ppb 2-methylbenzene(TP4 18'bg), 15000ppb 1,2,4-trimethylbenzene(TP4 18'bg), 14000ppb napthalene(TP5), 5400ppb xylene(TP5), 53000ppb methylnapthalene(TP5), 1500ppb xylene(TP6), 23000ppb 2-methylnapthalene(TP6). SUGGESTION: Groundwater fluctuates between 14-20'bgs evidenced by the product staining and VOC's at same interval. Also suggests that no discolored soil encountered shallower than 14'bgs indicating no onsite source to groundwater and as such offsite source combined with fluctuating groundwater table. No VOCs found in 23' soil sample suggesting that groundwater usually present above this level and as such it remains below water table at most times. Note also that depth to groundwater is from 13-15'bg in Well W23 as per spill #9913474 from 10/03-10/09. Ponds of standing water in excavation bed either due to fluctuating groundwater table and/or rain contributions to open excavation. Seepage in water in UST at 14'bgs from highpoint of fluctuating water table. Soil sample collected at 23'bgs suggests that groundwater at time of sample collection was greater than 23'bg. Perched water observed at various elevations suggests fluctuating water table and/or high infiltration from rain at excavation. Test pit analyticals show higher petroleum concentrations on north and east side of site and not adjacent to UST (which one would expect if UST was the source of contamination). Note that contamination exist from 14'-20'bg which is directly below invert. This contamination may be due to a leaking onsite UST and/or the spill from 103 East 10th Street but this cannot be proven due to removal of UST, fluctuating water table and construction of residential building over former tank location. Groundwater Sample Analyticals (Emteque)-2/8/06. Groundwater samples collected from the excavation at 101 East 10th Street and from two monitoring wells on the south and west side of the site. Groundwater samples collected from excavation and samples collected from monitoring wells on

103 EAST 10TH STREET (Continued) **S104620874**

adjacent sidewalks. Groundwater analyticals show: 87ppb 1,2,4-trimethylbenzene(GW2), 190ppb napthalene(GW2), 250ppb napthalene(GW1), 32ppb n-butylbenzene(GW1), 74ppb sec-butylbenzene(GW1). No site plan included. SUGGESTION: Groundwater analyticals collected from excavation show no free product and hence site is most likely not a source of contamination to 103 E 10th St. Contaminated Soil Excavation Report (Emteque)-October 2006. Groundwater was encountered at a depth of 14'-16' below grade. Prior to the completion of excavation work, a NYSDEC site visit confirmed the location of groundwater at 14-16' depth. Six endpoint samples were collected from excavation. As viewed onsite, it appears that contamination extends below the depth of groundwater and further cleanup is not feasible at this time . Soil endpoint analyticals show no TAGM 4046 Required Soil Cleanup Objective exceedences. 10/29/09-Vought-Called Emteque (Telemaque 212-631-9000) and left message to return call. 11/3/09-Vought-Received and reviewed Project Status Report from Day Engineering dated 10/27/09. In response, the Remediation Plan for Spill #99-13474 (Cody Ehlers Group; August 7,2002) was submitted and approved by the NYSDEC. The NYSDEC approved this remedial approach based on the December 22, 2003 report and on additional information that was provided to the agency in January 2004 . VOUGHT PERSONAL NOTE:DEC never approved this approach as per notes from Tipple dated 4/9/04. Groundwater at depth of 12'bg. Free product in wells W7, W23, W26 and W29 and product being recovered using portable pump. Product in well W29 can only be manually recovered from this well since building codes and space limitations preculde the use of an automated product recovery system for this well. Approximately 4.3 gallons of product have been removed from all site wells in the last 13 months since the last progress report was submitted... . A total of 52 gallons of product have been removed since manual recovery began on 10/23/03. ...the excavation work conducted on the property adjacent to 103 E 10th Street (i.e. 101 East 10th Street) and the presence of an underground oil storage tank (UST) and an 8-foot thick layer of petroleum contaminated soil at the property is probably the cause of the temporary increase in product thickness levels in these two wells that occurred over the past few years. VOUGHT PERSONAL NOTES: see 9/21 notes above. This indicates that petroleum contamination was present in the soil above the water tablee and that additional petroleum might still be present at that site . VOUGHT PERSONAL NOTES: See Iannone 9/6/06 letter where he states he saw no soil contamination onsite and furthermore Iannone states here groundwater is at 12'bg and hence soil contamination observed at 14-20'bg at 101 East 10th St is below the groundwater not above suggesting off-site source. Biweekly recovery was implemented as per DEC request in January 2008 and was compared against bi-monthly and overall the biweekly NAPL removal test program showed that this remedial approach provided little to no benefits but would significantly increase costs. NAPL recovery is performed bi-monthly now. VOUGHT PERSONAL NOTES: DEC still has not approved bi-monthly recovery. Note also that Remediation Plan does not identify the parties responsible for the removal of this vapor abatement system equipment. Dissolved groundwater samples collected from W8 and W9 and show no VOCs and wells were abandoned. Section also included on review of spill 0511701. Iannone notes that high VOC concentrations compared to SVOCs and this is an indication that petroleum release occurred relative recently since VOCs generally volatilize and are metablolized by natural microorganisms at a rate that is faster than

103 EAST 10TH STREET (Continued) **S104620874**

SVOCs. VOUGHT PERSONAL NOTE: This cannot be determined without VOC soil samples from 103 East 10th to compare, furthermore VOCS are only subject to active metabolism in groundwater as water necessary for enhanced aerobic degradation. Iannone also notes that VOCs detected in groundwater samples from excavation at 101 East 10th Street. VOUGHT PERSONAL NOTE: If 101 E 10th was source of free product to 101 then we would see free product at this site and not dissolved VOCs only. DAY believes based on a a review of the information obtained from the NYSDEC regarding the petroleum release at 101 East 10th Street that the petroleum contaminated soil at 101 East 10th Street is the source of most if not all the product that has been accumulating in wells W23 and W29 since January 2006. Overall, most if not all the product related to Spill 9913474 that was released in 1999 has been removed and is no longer present.... VOUGHT PERSONAL NOTE: Without downgradient delineation over the years one cannot state that product was removed. Furthermore manual bailing is not a plume wide remedial method. That is, continued use of these product recovery methods are expected to remove product from the spill 9913474 wells (W23 and W29) to the extent practicalbe as required by the Remediation Plan... VOUGHT PERSONAL NOTE: DEC requires removal of all free product (not to the extent practicable) and the Remediation Plan was never approved by DEC. 11/13/09-Vought-Called Telemaque after receiving his message and discussed letter from Iannone. Telemaque sent pictures to vought of large test pit in center of property that is not impacted with free product. Telemaque also noted that water was observed seeping into test pits at 23'bg suggesting tight soils and low recharge rates. Telemaque will research his report further and get back to Vought with file search results for additional information. Telemaque also open to attending meeting between 3/10 THC and DEC. Received email from Grogan that had attached document from Appleberg that listed groundwater monitoring well abandonment procedures, remediation equipment removal procedures. Document however does not state who should perform procedures. Vought sent reply asking for additional documentation as to responsibility. 11/24/09-Vought-Left message for Telemaque to see if he any any results of file research for additional information. Received email from Telemaque Prior photographs have also been forwarded to you subsequent to foundation installation and some of those photos document the infiltration of groundwater into the elevator pit under construction. This will provide an estimate as to the depth of groundwater encountered during the excavation. I had been at the site on several occasions and and never encountered free product in the standing water or the groundwater at the site. Our standard operating procedures on site of this nature, once free product is discovered, is to arrange for the recovery of free product and associated liquids and provide for the manifested disposal. These are services we normally subcontract and include as charges to our client. The absence of any liquid manifests would suggest that free product was not present. 12/14/09-Vought-Called and spoke to NYSOAG Riggi and Vought to send out letter in response noting that removal of remedial system past due as per Riggi letter dated 9/16/09 and also responding to Ule letters dated 9/22/09. Vought to address letter to Ule, owners of 103 and owners of 105 East 10th Street. Vought called and spoke to Kaplan and informed him of letter and current status. Vought drafted deadline letter requiring immediate meeting and submitted to NYSOAG Riggi for review. 12/16/09-Vought-Riggi and DEC Austin approved letter and Vought sent

103 EAST 10TH STREET (Continued) **S104620874**

letter to 3/10 THC and Steve Kaplan. 12/17/09-Vought-Received call from and spoke to NYSOAG Riggi who received call from and spoke to Ule. Ule noted that money in escrow by the building and that 3/10 THC will be removing both systems via Metropolitan Heating and Plumbing. Metropolitan key staff however has had a heart problem. Vought to call Riggi on 1/3/10 for update on work. Tentative meeting date scheduled at DEC offices for 1/6/09 to discuss current remedial status and future work. 12/31/09-Vought-Received email from Grogan that he received email from Ule that stated As discussed, we are targeting the vent removal job for mid January. Please provide me with any insurance requirements so that we can get them in place as a part of the contract with Metro. I will be in touch re access, scheduling, etc. Thank you Carol Ule . Vought also receieved email from Grogan as well that stated I received the below message from Carol Ule and it appears that this issue will finally be addressed. I have provided Ms. Ule with the necessary insurance and building guidelines regarding access to the building and the building work rules. 2) I have not, maybe you have them but we have not received any description of exactly what will be removed and who will be supervising the removal and who will be signing off on the completion of the work. 3) I received the following message from Marilyn Appleberg and I want to make sure that her concerns are addressed: John - there are vents - literally vents -in the front garden area that are vents and they are not to go. The pvc piping in the back was never referred to as vents - I just want to make sure we are all talking about the same thing - I don't think there will be a second shot at this and we should never assume. Could you please get a list of what is going and if there will be any odors associated with the removal. Thank you. Marilyn 4) I have informed Juan the Part Time Superintendent of the building of the up coming work and when the schedule is set he will be available to provide access to the necessary areas of the buildings that the removal team will need access to. Your attention and follow up to the above issues will be greatly appreciated. Thank you and have a Happy New Year! JJG . Vought also may require PID monitoring during piping removal due to odor concerns by Appleberg. Vought replied to Grogan and all parties requesting a site visit to determine which pipes will be removed. Site visit tentatively scheduled for second week of January and Vought awaiting replies on availability. 1/11/10-Vought-Meeting at DEC including NYSOAG Riggi (via telephone), DEC Austin, DEC Vought, Ule, Iannone and: Andrew Hafter 3/10 THC Ph: (212)477-5345. Topics for dicussion included status of system removal from 111 East 10th and system removal to begin tomorrow. Ule indicated that she spoke to Grogan who indicated that PID monitoring was not necessary. DEC required that a PID be onsite during removal in case odors should arise. Also covered was site status and current monitoring/recovery schedule including that product recovery occuring placement of pump to water surface (not depressing water table). Vought also noted requirements of dissolved groundwater sample collection from all wells without free product as well as need for determination of groundwater flow direction and possibly additional delineation. Vought and Austin agreed to VOCs only for monitoring parameters. Vought sent email to EAR Edward Werner with cc to Ule, Austin and Riggi requesting well survey information. Iannone noted that no sump pits were present in the basement of 103 E 10th Street. 1/13/10-Vought-Site visit and meeting with Iannone and contractor to remove vapor abatement and groundwater extraction piping (Mathew

103 EAST 10TH STREET (Continued) **S104620874**

Copeland-Metro Environmental-cell:516-216-0616). Also onsite was Marilyn Appleberg who noted piping to be removed, reviewed replacement of plywood, odor concerns. Method of piping removal will be mechanical only with no combustion or vapor generation. Vought however noted that windows should be kept open during removal of piping. Vought ensured that Appleberg, Copeland, Iannnone and super had eachothers contact information in case questions or concerns should arise during piping removal. Piping removal expected to occur for at least a minimum of two days. 1/14/10-Vought-Received EAR survey data for well elevation and forwarded to Iannone and Ule for review and determination of flow direction. Vought drafted review letter of Final Investigation and Remedial WorkPlan dated August 2010 and 10/27/09 Progress Report approving determination and installation of a downgradient (if necessary), not approving up to ten wells being sampled and requirement of all wells to be sampled, requirements of quarterly groundwater monitoring noting that Department would consider closure of individual pending submission of results, noting no further requirements of indoor air sampling, and no approval of manual NAPL removal as PERMANENT remedial method and as temporary only, and requiring implementation schedule. Vought submitted letter to Austin who reviewed and approved letter. Vought sent letter with deadline to submit revised Work Plan by 3/15/10 as per CAP. 5/20/10-Vought-Reviewed Revised Investigation and Remedial Work Plan (ERM unknown author) dated March 2010 and received on 3/18/10. Hand bailing of product in wells W29 and W23. Low NAPL thickness measurements are also occasionally recorded for wells W7 and W26 during these visits. One full round of groundwater elevation measurements will be collected for all 12 site wells to be used in flow determination. If it is determined that the direction of groundwater flow beneath the Site is north, then a new monitoring well MIGHT be installed on East 11th Street. If groundwater flow is determined to be to the north, a new 2-inch diameter monitoring well WILL be installed downgradient of the 3/10 THC property in the sidewalk along East 11th Street. The new monitoring well will be installed to 20 feet below grade or to bedrock, whichever is shallower . Wells W8, W9, W3, W1, W11, W12 and W13 abandoned as they were in basement of 105-107 or showed recent low levels of dissolved groundwater contaminants comparable to TOGS Standards. The monitoring will be done quarterly for up to two years unless an alternate schedule is approved by NYSDEC. Report also proposes VEFR on a monthly basis for a period of six months. After six months its effectiveness will be evaluated and a determination will be made whether or not to continue the program . Report also proposes possible use of ORC socks but does not note groundwater monitoring parameters for monitoed natural attenuation. Work Plan also includes proposed implementation schedule with water level measurements in March, groundwater sampling in June, well installation in June, VEFR from June to Nov, installation of ORC socks in June. Quarterly groundwater sampling also proposed in schedule. VEFT removal of NAPL will commence within 2 to 3 weeks of NYSDEC approval of the use of this NAPL removal methods..... . Vought sent email to John Grogan to confirm satisfaction with with SVE and product recovery system removal. Vought drafted Work Plan review letter for editting and approval by DEC Austin and Riggi. Vought received email from Grogan that Jeffery, The best of luck too you in your next assignment. Haz-Mat sounds dangerous so please be careful. To the best of my knowledge we are finished I cannot speak for Marilyn I trust she will

103 EAST 10TH STREET (Continued) **S104620874**

reply. Thank you again for all of your help. JJG 5/25/10-Vought-Sent letter to 3/10 THC requiring resubmission of Revised Investigation and Remedial Action Plan by 6/28/10. Plan to include clarification as to whether downgradient well MIGHT or WILL be installed if groundwater flow to the north, installation of monitoring well if groundwater to the north, to WATER and not 20'bg or bedrock, inclusion collection of deepest dry and highest PID soil sample collection if new well needed, Inclusion of sample collection from W21, performance of quarterly monitoring until spill is closed as opposed to for a period of up to two years , submission of a RAP upon completion of investigation and no ORC application without Department approval. Letter also approved implementation of VEFR and determination of groundwater flow direction. DEC requires: 1)cc to Iannone, Ule and Riggi. 2)Remediation Plan must contain an implementation schedule. 3)Replacement of historical flagstone sidewalk (flags may be stored in buildings as per DEC Tibbe)when wells are abandoned. 4)Resubmission of Work Plan by 6/28/10 including clarification as to whether downgradient well MIGHT or WILL be installed if groundwater flow to the north, installation of monitoring well if groundwater to the north, to WATER and not 20'bg or bedrock, inclusion collection of deepest dry and highest PID soil sample collection if new well needed, Inclusion of sample collection from W21, performance of quarterly monitoring until spill is closed as opposed to for a period of up to two years , submission of a RAP upon completion of investigation and no ORC application without Department approval. 6/11/10-Vought-Spill transferred from DEC Vought to DEC Ketani as per DEC Austin and Vought transfer to Section A. 6/29/10 - Raphael Ketani. Today, I received the Second Revised Investigation & Remedial Work Plan dated June 2010 from ERM. I reviewed the SRI & RWP and composed a letter with the following comments: 1) purge water is to be disposed of in drums and not returned to the respective wells. 2) all environmental samples are to be analyzed via methods 8260 and 8270. 3) VEFRing is acceptable. 4) ORC is not to be used until all of the free product is recovered. 5) Socks are not to be used until the product thickness has reached such a limit that VEFRing is no longer effective. 6) All future groundwater monitoring reports are to contain groundwater flow maps and product thickness maps to the nearest hundredth of a foot. 7) New well development must not take place less than 24 hours after well construction in order to allow the grout time to cure, and care must be taken regarding the air pressure used for development. 8) New well sampling must not take place earlier than two weeks from the date of development. 9) The location of the proposed well (MW-30) is acceptable. 10) An additional new well (MW-31) must be installed along East 11th Street directly opposite 103 East 10th Street. The letter was sent to Randall Austin, Chief of the Spills Unit, for his approval. Interested party addresses: 3/10 Tenants Housing Corporation, 25 8th Avenue, Brooklyn, NY, 11217 Carol Ule, Esq., Hartman Ule Rose & Ratner, LLP, 305 Broadway, NY, 10007, (212) 437-9110 John Iannone, PE, Day Engineering, 60 East 42 Street, Ste 1641, NY, 10165, (212) 986-8645 Bonnie Riggi, Esq., Assistant Attorney General, Oil Spill Unit, State of New York, The Capitol, Albany, NY, 12224 7/1/10 - Raphael Ketani. The letter was approved by Mr. Austin and was sent out today to 3/10 Tenants Housing Corp., Mr. Iannone, Ms. Ule, and Ms. Riggi. 7/9/10 - Raphael Ketani. The letter to Mr. Iannone came back Not Deliverable As Addressed. I contacted Mr. Iannone (212) 986-8645 and obtained the correct address for Day

103 EAST 10TH STREET (Continued) **S104620874**

Engineering. It is 274 Madison Avenue, Ste 1104, NY, 10016. I will send out a letter with the correct address. 7/12/10 - Raphael Ketani. The letter to Mr. Iannone was resent to Madison Avenue. 7/21/10 - Raphael Ketani. I met John Iannone, PE of Day Engineering (212) 986-8645 at 103 East 10th Street for a scheduled meeting. He showed me some of the wells that were still active. We discussed the site and what should happen next. He said that there was between 0.2 feet and 0.4 feet of oil in the well in the basement of 103 East 10th Street. Mr. Iannone commented that the oil was thickest at this well. He said that they have been doing vacuum events to collect the oil. He mentioned that groundwater had lately been determined to flow north, instead of south as it had been during most of the project. I told Mr. Iannone that wells should be installed along 11th Street (to the north) in order to see whether the groundwater and the oil are migrating in that direction. Mr. Iannone suggested doing geoprobe drilling first. He added that if the soil sampling shows that the oil is indeed moving north, then he will install a well or two. I told him to submit a proposal to DEC and I will take a look at it. He said that he will. Next, we discussed the handling of the purge water from the wells. Mr. Iannone said that it was expensive to get rid of it, and the co-op association at 103 East 10th Street was paying for everything out of their pockets. He asked whether he can reinject the purge water back into each respective well. I told him that once the water is out of the ground, then its chemistry changes and that reinjecting the water changes the chemistry of the groundwater. I added that we would never know the true groundwater chemistry after the injections. I suggested to Mr. Iannone that he should either have a drum on a truck which can be used to contain the purge water, or he can put a drum at the corner of 101 East 10th Street where it meets 103 East 10th Street, and put the purge water in there. I added that he should put the drum in an overpack drum so that it can be opened easily and to chain the drum to the railing of the garden area. Mr. Iannone said that this was a possibility. I asked Mr. Iannone for regular progress reports for the site. He said that he will send them to me. After this, the conversation ended. Mr. Iannone handed me the July 2010 Project Status Report. I reviewed the report for spill case #9913474. Groundwater is contained within the overburden material that covers the bedrock. The water table is at 12 feet below grade. Oil and gas contaminated soil was found at 101 East 10th Street (the new building at the corner where a gas station used to be) at up to 20 feet below grade. Spill case #0511701 was initiated. The soil was excavated to about 22 feet below grade and removed. Digging could not continue further. Perched groundwater was encountered in the excavation at various levels. There was very little contamination in the groundwater. Soil end point samples came up at about TAGM. A passive venting system and vapor barrier were installed. The spill case was closed on 10/23/07. Product is still being recovered from W23 and W29, with sheen observed in W7 and W26 (product thickness below 0.01 feet). W29 is in a basement store room at 103 East 10th Street. During the reporting period, a total of 3.12 gals. of oil were removed from all of the active wells. Over the past 6 years, the product thickness has generally decreased to as low as 0.1 feet in W29. A total of 55 gals. of oil have been recovered since manual bailing began on October 23, 2003. The venting system was removed on 7/8/09 from 105 to 111 East 10th Street after a NYCDOH inspection failed to detect any vapors in the homes. 11/18/10 - Raphael Ketani. I spoke to Mr. Iannone (212) 986-8645. I told him that the DEC was

103 EAST 10TH STREET (Continued) **S104620874**

missing the August, September, and October update reports. Mr Iannone explained that he will send the DEC an update report very soon. He added that they have been collecting oil with peristaltic pumps since they can't get a guzzler truck down the street (no one is obeying the alternate side of the street parking rules). He said that the oil in the one well is consistent at 2 to 4 inches. I asked him about the well that was supposed to be installed on 11th Street. Mr. Iannone said that they are still working on getting the permits for drilling through the sidewalk. I ended the conversation by telling Mr.Iannone that he must send the DEC an update report. 12/8/10 - Raphael Ketani. I received the December 2010 Project Status Report from Mr. Iannone. I reviewed the report. It gave a history of the oil recovery efforts from July 16, 2009 to November 23, 2010. only 3 wells have continued to collect oil. These wells are W-7, W-23, and W-29. Due to the difficulty of parking the guzzler truck on the street, a peristaltic pump has been used to recover the oil from the affected wells. A total of 0.57 gals. of oil was recovered during the past 5 months since July 2010. Another well will be installed to the north of the spill site on 11th Avenue. However, bid proposals are still being received. 1/28/11 - Raphael Ketani. I spoke to Mr. Iannone (212) 986-8645. He said that his workers conducted three oil recoveries since 12/8/10. They collected about 1 pint of oil from the 2 inch well at W-29. Sometimes it takes a few weeks until any oil appears in the well. The other two wells have had only occasional sheens. Mr. Iannone said that the co-op doesn't understand why another well is being requested by the DEC. He said that they are very strapped for money and are having a hard time understanding what the plan is. He asked for a meeting between the co-op board, himself and the DEC. I told him that I was willing to have a meeting and I asked him to set it up. 2/3/11 - Raphael Ketani. A site meeting took place today between Mr. Iannone, Andy Hafter - co-op treasurer, Carol Ule - co-op attorney (212) 437-9110, and myself. Previously, Mr. Iannone had indicated that this was going to be a meeting with the co-op board, him and myself. So the presence of Ms. Ule was a surprise. However, the meeting took place anyway. Both Ms. Ule and Mr. Hafter took active roles in the discussion. Mr. Hafter stated that the co-op was just about out of money and couldn't do more work. He said that some co-op owners were not paying their maintenance and that 1 dollar out of every three was going to the environmental work. Ms. Ule stated that the co-op had cooperated with the DEC and had paid back over $600,000 dollars of the State's money as part of the agreement. She said that she had talked to Bonnie Riggi, the State attorney general, and had worked out the settlement. Ms. Ule also stated that the special mortgage that was being used to pay for the present environmental work was going to run out soon. She added that the co-op couldn't get another special mortgage until after some time. I told both of them that the money issues were not the State's concern. I told them (Iannone, Ule, Hafter) the the DEC was insisting on having wells installed along East 11th Street as the groundwater was now flowing in that direction. I told them that it needed to be seen whether oil is flowing off site and whether there is more oil under East 11th Street from the spill. Both Ms. Ule and Mr. Hafter said that the oil may be from the 101 East 10th Street site where there used to be a commercial facility - a site that now has a high rise condominium building. Mr. Hafter said that there was a tremedous amount of contamination in the site. He said that he saw truck after truck taking out contaminated soil. Ms. Ule said that there was oil

103 EAST 10TH STREET (Continued) **S104620874**

in the site and she said that I had closed the site anyway. I told her that I vaguely remembered the site and that I wouldn't have closed the spill case if oil contamination was present. Ms. Ule said that there may be oil under the sidewalks. I told her that I had inspected the site and I had seen oil floating on water in the bottom of the excavation pit. I had told the site manager to collect the oil. Mr. Hafter then said that the pit wreaked strongly of oil and everyone in the neighborhood was aware of this contaminated site. I told him that the contaminated soil was being taken away by the construction company. Mr. Hafter stated that he saw many trucks leaving the site with soil. I added that I had looked at the sidewalls of the site - under the sidewalks along East 11th Street and along East 10th Street and along the foundation of 103 East 10th Street - and I didn't see any seeping oil or oil staining. Ms. Ule asked Mr. Iannone whether there were any signs of oil in the wells along Third Avenue (the cross street to East 10th Street). Mr. Iannone said that there was nothing. I insisted that a series of wells be installed along East 11th Street. Ms. Ule stated that there just wasn't any money to do this. She added that the State wouldn't want to see another co-op go bankrupt. I again told her and Mr. Hafter that the groundwater had changed direction and that the DEC needed to know what was going on. Ms. Ule stated that we don't know that oil is there or heading in that direction. I responded by stating that we don't know that it isn't heading north and off-site. Ms. Ule countered that they could put in the wells and discover oil and it would be from a site along East 11th Street or from the new condominium. She added that any oil found would be pinned on 103 East 10th Street. I told her that, with a series of wells, the DEC would be able to determine who owns the spill along East 11th Street. Ms. Ule then asked Mr. Iannone (who had said almost nothing through the meeting) why the groundwater flow direction had changed from south to north. Mr. Iannone said that he had no idea. Mr. Hafter asked whether the installation of the high rise condo had changed the flow direction. Mr. Iannone said that he didn't know. Ms. Ule asked whether the agreed upon plan to install one well along East 11th Street could be implemented. She added that if oil would be found there, then more wells could be put in. I told her that the DEC wanted a series of wells put in, not just one. Ms. Ule said that they didn't have the money. At this point in time, I tried to contact Jeff Vought, the previous case manager by cell phone in order to have him join the discussion. However, he informed Randy Austin, Chief of the Spills Unit, about my meeting and Mr. Austin told me to stop talking to the group. After this, I stopped talking to them. Ms. Ule ended the discussion by stating that nothing was agreed upon here and so this could still be discussed further. I told her that she needed to talk to the DEC counsel, John Urda, in order to arrange an investigation plan. I added that I couldn't talk to her anymore. With that, I left. 2/10/11 - Raphael Ketani. At the suggestion of Mr. Austin, I put together a Case Initiation package for legal action. The basis of the case is the violation of the STIP and a failure to perform further investigative action and remedial action. Mr. Austin and I signed the Case Initiation cover form and it was delivered by hand to the regional Office of General Counsel. 2/14/11 - Raphael Ketani. James Periconi (212) 213-5500, attorney for 3/10 Tenants, sent an e-mail to John Urda of the Region 2 Office of General Counsel. In the e-mail he protested the alleged change in the agreed upon work plan from one well on 11th Street to a series of wells

103 EAST 10TH STREET (Continued) **S104620874**

along 11th Street. He also requested a meeting between staff from the Department and himself. 2/28/11 - Raphael Ketani. Mr. Periconi sent Mr. Urda an e-mail stating that they didn't understand where the DEC wanted the two wells. Mr. Urda asked me to talk to Mr. Iannone. I talked to Mr. Iannone and explained that one well should go in the backyard of 103 East 10th Street. He said that it's not a backyard, but a front yard to a church property. As this was the situation, I told Mr. Iannone that the well should be in the sidewalk in front of the church property. I added that the second well should be 30 feet to the east to possibly catch additional oil flow. Mr. Iannone said that the co-op doesn't have the money to install two wells. He stated that the DEC should ask for just the one well because the co-op is struggling. They can't even get the money to repair the roof. I told Mr. Iannone that I was calling just to clarify where the wells should go, not the issue of how many wells will be agreed upon. I added that the agreement is between Mr. Urda and Mr. Periconi. With that, the conversation ended. 3/11/11 - Raphael Ketani. I received an e-mail containing a letter Mr. Iannone had sent to Mr. Periconi. The letter was titled Evaluation of the NYS DEC Request for Additional Wells. I read the letter. Mr. Iannone seemed to understand the change in groundwater flow direction. he indicated that one well due north of the site would tell everyone whether oil was migrating towards 11th Street. However, he indicated that no more than this one well should be installed. Attached to the letter were flow direction maps showing the change in flow direction over the course of a number of years. 3/17/11 - Raphael Ketani. John Urda of Region 2 Office of General Counsel sent an e-mail to Jim Periconi, the attorney for 103 East 10th Street. In the the e-mail, Mr. Urda stated that Day Engineering needed to submit a work plan to the DEC for installing two groundwater monitoring wells and for doing weekly product recovery. If oil is found in the wells, then further groundwater contamination delineation would be required. The plan is due on March 25, 2011. Mr. Urda added that an investigation report would need to be submitted after the work is done and then a remedial action work plan. The deadlines for submission of these plans would be agreed upon between Mr. Iannone and Mr. Ketani. Both work plans and the investigation report will become part of the STIP agreement. 3/23/11 - Raphael Ketani. Mr. Iannone (212) 986-8645 sent me an air photo showing the proposed locations of MW-31 and MW-30. I reviewed the photo and told him that the locations were acceptable and to start the work. 3/24/11 - Raphael Ketani. Mr. Iannone sent me an e-mail requesting permission to use the STARS methods for VOCs and the SVOCs. I told him that he can use these simpler methods. 3/25/11 - Raphael Ketani. Chuck Merritt (631) 617-6200 of Merritt Environmental called regarding what was taking place at 103 East 10th Street and why the associated spill (#9611309) for 105-107 East 10th Street was still open. I explained the issue to him, how 103 is related to 105 and 107, and that investigation work was proceeding with Day Engineering. Mr. Merritt said that his client was trying to refinance his mortgage for 105 East 10th Street and that the bank was asking what was the environmental situation. I told Mr. Merritt that he can talk to Mr. Iannone and get some information and then maybe he can put together a report for the bank that will explain everything. Mr. Merritt said that he had been to the site himself (105 East 10th Street) and he didn't find any problems. I added that until the situation at 103 East 10th Street is resolved, the spill case for 105-107 East 10th Street can not be closed. Mr. Merritt said that he understood. Later,

103 EAST 10TH STREET (Continued) **S104620874**

Eric Weinstock of C A Rich Consultants called me. He asked why the spill case had been reopened when Michelle Tipple had closed it in 2004. I told him that I did see a case note indicating that Ms. Tipple had written an NFA letter dated 8/19/04. However, from reviewing the notes, I could not determine why the case had been reopened or when. I told him that there still was an ongoing spill case with 103 East 10th Street and that the cases for both sites were associated with a State PIN case, which was still open. I added that, maybe, the open PIN case was the reason, but I just wasn't sure and I couldn't find anything in the notes to clarify the matter. I told him to talk to Mr. Vought when he comes back from vacation order to find out the answer as to why the case is still open. Later, Miriam Villani of Sahn Ward Coschignano & Baker, PLLC (516) 228-1300 sent an e-mail to Jeff Vought (the former case manager) and John Urda, Assistant Regional Attorney for DEC, requesting that the spill case for 105-107 East 10th Street (#9611309) be closed. The reason for the request is that her client, Walden Pond Realty, LLC, is trying to refinance its mortgage. However, Mr. Vought wont return until 3/31/11, the day of the closing. 3/28/11 - Raphael Ketani. I received the Day Engineering Remedial Investigation and Remedial Action Work Plan dated 3/25/11. I reviewed the plan and found it to be acceptable. I sent a draft letter to Mr. Austin for his approval. In the letter I added that Day Engineering should: (1) perform two rounds of groundwater sampling, not just one, for MW-30 and MW-31; (2) that if the groundwater does not meet the State standards, then it should be VEFRed; (3) that the wells should be left in a useable condition for determing the groundwater flow direction, even if no oil is found; (4) when access to 10th Street for the VEFR truck is prevented by parked cars, Day Engineering should contact the local precinct; (5) product collection should be performed with an alternative mechanical means when use of the VEFR truck is prevented The letter was approved and sent out today. 3/29/11 - Raphael Ketani. Mr. Iannone (212) 986-8645 sent a letter in which he responded to the DEC's 5 comments above. 103 East 10th Street and Day Engineering agreed to abide by the comments. 3/31/11 - Raphael Ketani. The associated spill case, #9611309, was closed today as the spill had been remediated. The Final ISR was signed by Mr. Austin and Mr. Oliva and sent to Albany DER today. 5/10/11 - Raphael Ketani. Mr. Iannone (212) 986-8645 sent me an e-mail stating that wells MW-30 and MW-31 would be installed on either May 24th or the 25th. He attached an air photo showing where the wells would be installed. This was the same photo as in the 3/25/11 work plan. I responded back by e-mail that the locations looked fine and that he should proceed as he had planned. 5/20/11 - Raphael Ketani. Mr. Iannone sent me the May 2011 status report dated 5/20/11. I reviewed the report. Wells W7, W21, W22, W23, W26, W29 were used as the monitoring array. Wells W7, W23, W26, and W29 are the wells that have product. Manual product recovery started on October 21, 2003. Product thickness varies from 0.001' to 0.005'. About 1.12 gals. of product were recovered during this reporting period. About 56 gals. of product have been recovered from October 21, 2003 to May 19, 2011. Two new monitoring wells, M30 and M31, will be installed on May 24, 2011 along 11th Avenue in a downgradient position. 5/24/11 - Raphael Ketani. I spoke to Mr. Iannone about the well installations. He said that they were at the locations all day and that he had just returned. He said that they hit refusal at the original locations for MW-30 and MW-31. The driller told him that they were constrained by NYC DOT regulations

103 EAST 10TH STREET (Continued) **S104620874**

regarding how close to the street side of the sidewalk they could drill. So they didn't have much room to try and install the wells. They hits boulders at about 1 feet and 4 feet below grade. Finally, they were able to install MW-30 in front of the church and between the two original locations. They drilled with augers to 15 feet and then punched down to 18 feet. A one inch diameter well was installed. There was about 3 or 4 feet of water. The soil samples had PID hits of 9 ppm to 11 ppm. Mr. Iannone said that they will let MW-30 sit for awhile (about several weeks) and then sample it along with the other monitoring wells. I asked Mr. Iannone to send the DEC a full report regarding the well installation and sampling. He said that he will. Later, Mr. Iannone sent me a picture showing the drilling and a picture showing the final location of MW-30. 7/11/11 - Raphael Ketani. I spoke to Mr. Iannone (212) 986-8645. He said that he had received the data for the latest round of groundwater sampling just last week. He is in the process of putting the report together and will send it to the DEC by July 22. I told him that sounded fine. 8/2/11 - Raphael Ketani. Mr. Iannone sent me the 2011 Remedial Investigation and Remedial Action Results Report dated 7/29/11. I reviewed the report. They hired ADT to install MW-30 and MW-31. However, ADT hit refusal at the locations for installing the two wells. So, only MW-30 was installed between these locations as a one inch diameter well. Soil samples were taken on 5/24/11 from MW-30 at 6.0 to 6.5 feet down, 9.0 to 9.5 feet down and at 15.0 to 15.5 feet down. The results showed toluene at less than 1 ppb and one hit of ethylbenzene at less than 1 ppb. The SVOCs were virtually all non-detect. Groundwater samples were taken on 6/9/11 from MW-18 to MW-21, MW-24 to MW-30. The VOCs were almost entirely non-detect, except for a few very low hits (typically below 17 ppb) in MW-24, MW-26, MW-28 and MW-30. The SVOCs were almost entirely non-detect. On 6/2/11, groundwater flow was to the northeast. In the Conclusions section, Mr. Iannone mentions that only 0.4 gals. of oil were collected in the past 6 months. Also, there was no product at MW-7, MW-22 and MW-26 during the past year and product was less than 0.1 feet in MW-23 and MW-29. Product was usually a sheen in these wells. Considering the information in the Conclusions section, Mr. Iannone recommended closing wells MW-18 to MW-21, MW-24, MW-25 and MW-27 due to low product recovery. He also recommended quarterly monitoring and groundwater sampling at MW-7, MW-22, MW-23, MW-26, MW-28 to MW-30. Lastly, he recommended product monitoring and removal from MW-7, MW-22, MW-23, MW-28 to MW-30. I sent an e-mail to Mr. Iannone approving the RIRAR Report. I also stated that none of the wells should be plugged and abandoned as they have value for determining the groundwater flow direction. So those 7 wells should just be used for groundwater elevation measurements. I added that groundwater sampling should take place as recommended and that product recovery should take place as recommended. Lastly, I suggested that some more efficient means of product recovery should be used to collect oil from MW-23 and MW-29. Later, Mr. Iannone sent a response e-mail stating that MW-23 had 0.07 feet of oil and MW-29 had 0.03 feet of oil. 9/9/11 - Raphael Ketani. I spoke to Mr. Iannone (212) 986-8645. He said that the next (second) round of groundwater sampling is scheduled to take place next week. He also mentioned that an oil sheen was occasionally seen in the new well, MW-30. I asked him whether Day Engineering had come up with an effective alternate means of collecting the oil. He said that they hadn't. However, he said, it was an easy task to have his staff come down to the site to collect

103 EAST 10TH STREET (Continued) **S104620874**

the oil and do other work as their office is nearby. 10/18/11 - Raphael Ketani. I spoke to Mr. Iannone (212) 986-8645. He said that he had the groundwater results. He will put them together with the product collection data and submit a status report to the DEC sometime this week or next week. 10/31/11 - Raphael Ketani. Mr. Iannone called to say that the groundwater report will be sent to the DEC by wednesday. I told him that would be alright. 11/15/11 - Raphael Ketani. Mr. Iannone sent me the 11/15/11 September/October 2011 Day Engineering Groundwater Monitoring and Project Status Report. On 9/16/11, wells W7, W22, W23, W26 and W28 to W30 were sampled. Wells 7, 22, 23, 29 and 30 had oil from a sheen to 0.73 feet in W30. Well W30 has had product from 0' to 1.2' since installation in May 2011. Wells W29 and W30 which had the most oil also had the highest contamination. Analytes 1,2,4-trimethylbenzene, total xylenes and ethylbenzene were in the high double digits to the low triple digits. A total of 1.43 gals. of oil has been recovered from the wells in the past 14 months. I responded to Mr. Iannone's e-mail and told him not to sample the groundwater in wells that had even a sheen of product. 7/6/12 - Raphael Ketani. I reviewed the June 2012 Groundwater Monitoring and Project Status Report dated 6/6/12 and submitted by Day Engineering. Groundwater gauging and sampling took place at W7, W22, W23, W26, W28 to W30 on 2/7/12. Product or sheen was present in all of the wells except W22. W22 had two VOC exceedences of the groundwater standards in the low triple digits (no higher than 180 ppb), but the rest of the exceedences were much lower. About 1.47 gals. of product were collected during the past 13 months. Groundwater flow was to the north to W30. Mr. Iannone recommends curtailing groundwater sampling for the time being and instead injecting ORC into the wells with sheen or product in order to reduce the amount of oil in the subsurface. I approved the June 2012 report and wrote a draft letter stating the Department was approving the recommendation to end groundwater sampling. However, we were not going to approve the use of ORC in the affected wells until Day Engineering submits a work plan describing the treatment program. I set a deadline of August 3, 2012 for receipt of the work plan. The draft letter was submitted to Hassan Hussein for his review. Mr. Iannone wrote that Day Engineering closed their New York office. All correspondences should go to John Iannone, P.E., Day Engineering, P.C., 2711 Henry Hudson Parkway, 7C, Bronx, NY, 10463. Mr. Hussein approved the letter and it was sent out today. 8/3/12 - Raphael Ketani. Mr. Iannone (347) 204-7852 sent me the 8/3/12 Oxygen Release Compound Treatment Work Plan. I reviewed the work plan. Treatment socks will be installed in wells W7, 22, 23 and 26. All of these wells have exhibited sheen. Product thickness will be monitored and product will be collected and the thickness will be included in a quarterly report. The great majority of the report consisted of appendices with the standard manufacturer literature. I drafted a letter for Mr. Hussein approving the work plan with the comments that Day Engineering must adhere to the service limits of 12 months for the ORC filter socks and 3 to 6 months for the EHC-O canisters. The letter was approved and was sent out. 3/14/2013 - Raphael Ketani. I sent Mr. Iannone an e-mail requesting an update regarding progress at the site. 3/21/13 - Raphael Ketani. I received and reviewed the March 2013 Project Status Report dated March 20, 2013. Product is still appearing and averages about 0.1 feet in W7, W23, W26 and W29. Well W30 has averaged 0.55 feet of product since its construction during May 2011. Recently, the product in the well has averaged 0.45 feet in

103 EAST 10TH STREET (Continued) **S104620874**

thickness. Groundwater flow has continued to the north. On 9/7/12, ORC socks were installed in W7, W22, W23 and W26. On 2/23/13, the oil was 0.61 feet thick in W30. On this same day, the oil was 0.39 feet thick in W23 and 0.02 feet thick in W29. 12/13/13 - Raphael Ketani. I spoke to Mr. Iannone (347) 204-7852 regarding progress at the site and the lack of monthly reports. Mr. Iannone stated that he is presently working on the next progress report and that it will have all of the data from the past 9 months. He also said that more ORC had been put in the wells and that the thickness of the product is now down to a matter of a few inches at most. I commented that well W30 had a persistent thickness of product of half a foot. I asked him whether the oil was being removed from this well. He said that it was, but, sometimes, it has no water. Mr. Iannone said that I should expect the next report to be delivered next week. 1/21/14 - Raphael Ketani. I reviewed the December 2013 Project Status Report dated 12/31/13 and submitted by Day Engineering. Measureable amounts of product have not been accumulating in wells W7, W21, W22 and W26 during the past 9 months (April to December 2013). Product was found in W23, W29 and W30. The product thickness in averaged 0.1 feet in W23, only a sheen in W29 and 0.5 feet in W30. A total of 4.20 gals. of product were collected during the past 9 months. Groundwater flow is to the north towards W30. From April 6 to October, and on November 16, 2013 and during December, only product monitoring and removal took place. On November 1, 2013, the ORC socks were replaced on wells W7, W22, W23 and W26 and product monitoring and removal. I drafted a letter approving the December 2013 report and requesting that 3/10 Tenants Housing Corp. find a more efficient method for collecting the oil from well W30. The letter had a deadline of February 21, 2014 for submitting the alternative method work plan. The letter was submitted to Mr. Hussein for his approval. 1/22/14 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out. 2/17/14 - Raphael Ketani. Mr. Iannone sent me an e-mail requesting an extension of the deadline for submitting the alternative recovery work plan for W-30 (as was requested in the DEC 1/22/14 letter). The reason for the request was that Mr. Iannone is retiring and the new consultant will need to be transitioned once the new contract is in place. I granted the request for extending the submission deadline to 3/28/14. 4/1/14 - Raphael Ketani. Sean Clifford of Brockerhoff Environmental Services, LLC (908) 689-4300/seanc@brockerhoffllc.com called and left a message stating that he is the project manager for the spill. 4/3/14 - Raphael Ketani. I reviewed the Light Non-Aqueous Phase Liquid Interim Response Action Workplan dated 3/27/14 and submitted by Brockerhoff Environmental Services, LLC. The objective is to enhance LNAPL recovery through mass removal with subsequent monitoring. Product removal will take place 3 times per month for 6 months. Each removal event will last 3 hours, instead of the 1 hour that was previously spent. BES will measure the depth to water and the depth to product. A perstaltic pump will be used to remove the product. Product recovery will be done until the product thickness is 0.1 . ORC treatment will take place in the wells that have NAPL. Filter socks will be installed with ORC in wells W7, W22, W28 and W29. During each site visit, the socks will be inspected and their depth will be adjusted. At the end of 6 months BES will submit a report to the DEC. I found the work plan to be acceptable and sent an e-mail to Mr. Clifford stating so. 6/24/14 - Raphael Ketani. I sent an e-mail to Mr. Clifford (908) 689-4300/seanc@brockerhoffllc.com requesting a progress update. Later, I received and e-mail from Mr.

103 EAST 10TH STREET (Continued) **S104620874**

Clifford. He stated that they have implemented the activities in accordance with the workplan (Light Non-aqueous Phase Liquid Interim Response Action Workplan dated March 27, 2014) which was approved in April 2014. A progress report will be submitted six months following implementation of the workplan which will summarize the groundwater and product level measurements and include a discussion of site observations and activities. They anticipate submitting this report in November 2014. 11/7/14 - Raphael Ketani. Mr. Clifford left me a voice message. He stated that they plan to pursue a more aggressive means of NAPL recovery. He will contact me later regarding the details of their plans. 11/25/14 - Raphael Ketani. I reviewed the Brockerhoff Environmental Services Progress Report: Remediation and Monitoring of LNAPL dated 11/14/14. From April to October 2014, 6 site visits took place to monitor the groundwater and collect product. Product was detected in only 3 wells during this period. These wells were W23, W29 and W30. A total of 0.36 gals. of product was recovered during this period. Since October 2013, a total of 61.5 gals. of product has been recovered. ORC socks were put into wells W7, W22, W23 and W29. The LNAPL thickness showed a decreasing trend and had reduced to a thickness of 0.02 feet in the respective wells. Brockerhoff recommends: reducing LNAPL monitoring and recovery to once a month; continue using ORC socks in W7, W22, W23 and W29 and inspect the socks monthly and replace them semi-annually; provide a summary report to the DEC at 3 months, 6 months and 9 months. The report did not include a plan for sampling the groundwater in the wells which didn't have product and didn't include monitoring W30. Also, I determined that reporting every 3 months for 3 quarters was not informative enough. Groundwater sampling for STARS VOCs and SVOCs must take place at wells W21, W24 and W26 to W28 twice a year. The reporting must be quarterly. I sent an e-mail to Mr. Clifford (908) 689-4300/ seanc@brockerhoffllc.com approving the report, but stating the above comments. 12/19/14 - Raphael Ketani. Mr. Clifford sent me the following email: Last night I spoke with the attorney representing the association and she indicated that they are willing to move forward with the plan outlined in the approved workplan and the additional conditions noted below. There has been a little bit of a delay in authorizing the work however because they just had a re-shuffling of the association board so that has added a little bit of an administrative related delay. Based on my discussion, I expect the authorization to be wrapped up soon and that the new scope of work will be implemented starting in January. In the meantime, the association is committed to addressing the remaining impacts and have authorized the three recovery/monitoring events per month to continue. 12/24/14 - Raphael Ketani. Mr. Clifford (908) 689-4300 sent me the following email: The 3/10 Tennant Housing Corporation is ready to move forward with the scope of work detailed in the Progress Report dated 11/14/2014 and the additional comments summarized below. This scope of work will be initiated in January 2015 and will include the following: -Monthly LNAPL monitoring and recovery events at W23, W29, and W30. -Quarterly updates to NYSDEC regarding findings of investigation and progress made. These updates will be scheduled for March, June, September, and December 2015. -Semi-annual installation/replacement of ORC socks within W7, W22, W23, and W29. This work will be scheduled for January and June 2015. -Semi-annual ground water sampling at W21, W24 and W26 to W28 for NYSDEC STARS list VOCs and SVOCs. This work will be scheduled for February and August 2015. I found the proposed schedule/work plan to be acceptable

103 EAST 10TH STREET (Continued) **S104620874**

and sent a response email to Mr. Clifford stating this. 2/11/15 - Raphael Ketani. Mr. Clifford sent me an email stating that groundwater sampling took place on 2/10/15. However, upgradient well MW-27 could not be accessed. He asked whether Brockerhoff should go back and try again to get to the well. I responded that they could skip the well this time and sample the well during the next round. 3/31/15 - Raphael Ketani. I reviewed the Brockerhoff Environmental Services, LLC 3/31/15 Progress Summary. The period covered was from January to March of 2015. The services performed were gauging, ORC sock installation and groundwater sampling. The wells were inspected during January, February and March. During the 1/20/15 inspection, product was found in W23 (0.03'), W29 (0.02') and W30 (0.01'). NAPL was not seen in the wells on 2/10/15 or 3/20/15. However, due to the thinness of the product there was no NAPL collection. ORC socks were installed in W7, 22, 23 and 29 on 1/29/15. Wells W21, 24, 26 and 28 were sampled on 2/10/15. The VOC results were either entirely non-detect or had non-detects with many hits either below the TOGS standards or just above. The SVOC results were either entirely non-detect or mostly non-detect with a small number of hits below the TOGS standards. 7/8/15 - Raphael Ketani. I reviewed the Brockerhoff Environmental Services, LLC 6/30/15 Progress Summary. The period covered was from April to June of 2015. The services performed were gauging and ORC sock replacement. During the 6/11/15 inspection, product was found in W7, W22, W23 and W29. The thickness of the product in each well was no greater than 0.01'. Due to the thinness of the product there was no NAPL collection. ORC socks were reinstalled in W7, 22, 23 and 29. Groundwater sampling will take place during August 2015 at W21, 24, 26, 27 and 28. While I found the report to be acceptable, there was no mention of MW-30. I sent an email requesting an update regarding its status (i.e. presence of oil and how thick). Mr. Clifford responded by email and stated that well MW-30 was gauged for product at the same time as the other wells, but nothing was found. 10/1/15 - Raphael Ketani. I reviewed the Brockerhoff Environmental Services 10/1/15 Progress Summary - Remediation and Monitoring of LNAPL. The monitoring period was July to September 2015. During this time, monthly groundwater monitoring and semi-annual groundwater sampling took place. The wells were inspected for LNAPL during July, August and September. The LNAPL thickness was less than or equal to 0.02 feet at all of the wells during July and August. During September, W-29 was found to have 0.41 feet of product. A total of 0.08 gallons of oil was collected. The appearance of the thicker layer of product may have been due to the 0.98 feet drop in the water table during August. W-29 was revisited on 9/16/15 and only 0.11 feet of product was found. On this date, none of the wells had LNAPL. W-30 wasn't sampled because it had been cemented over when the sidewalk was refurbished. Brockerhoff will try to reopen the well. Groundwater sampling took place on 8/4/15 at W-21, 24, 26 and 28. There was insufficient water for sampling at W-27. The VOC results for all of the samples were mostly non-detects with a few low hits in each sample. One sample had a few low VOC exceedences. The SVOC results for all of the samples were mostly non-detect with several low hits in each sample and one sample with a few exceedences. I approved the report without comments. 12/15/15 - Raphael Ketani. I received an email from Mr. Clifford today. He stated that groundwater sampling was conducted during February and September 2015. He added that the residual NAPL is not affecting the groundwater quality. The spike in product thickness at well W-29 on

103 EAST 10TH STREET (Continued) **S104620874**

9/9/15 was just an anomaly, according to Mr. Clifford. Product thickness was measured in W-29 on 9/16/15, 10/5/15, 11/9/15 and on 12/2/15. The measured thickness on those dates was 0.11 feet, not measureable, 0.03 feet and not measureable, respectively. He stated that on these dates, product was not seen in any of the other wells. Mr. Clifford attached a figure showing the cumulative NAPL recovery amount from gauging round to gauging round. A higher synoptic plateau was depicted. He stated that he will write the fourth monitoring memo if the Department believes that the case is closeable. I responded that, given the product thickness results stated, the Department believes that the spill case is closeable. 12/23/15 - Raphael Ketani. Mr. Clifford sent me the Brockerhoff Environmental Services, LLC 12/21/15 Progress Summary Report: Remediation and Monitoring of LNAPL. I reviewed the report and found it to contain the same information as in his 12/15/15 email. He stated that Brockerhoff was requesting that the spill case be closed. Based upon the data in the case record, I determined that the residual contamination would not be a threat to the public or the environment. I sent a Spill Closure Letter to Heather Verran, Coop Board Treasurer, 3/10 Tenants Housing Corp., 25 8th Avenue, Brooklyn, NY, 11217. The spill case was closed effective today. "

Remarks: "tank contained #2"

All TTF:

Facility ID:	9913474
Spill Number:	9913474
Spill Tank Test:	1548078
Site ID:	117758
Tank Number:	1
Tank Size:	2000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

LIENS:

Region:	2
Spill No:	96-11309
Tax Map Id:	466-56
Lien Request Received:	07/16/2001
Request Sent To APA Or Vendor:	08/24/2001
Draft Lien Received From Vendor:	10/01/2001
Approved Lien To Administrator:	Not reported
Signed By Administrator:	Not reported
Received From Administrator:	Not reported
Sent For Filing:	Not reported
Resent For Filing:	Not reported
Proof Of Service Received:	Not reported
Sent To OAG:	10/01/2001

103 EAST 10TH STREET (Continued) **S104620874**

Amount:	$370,678.85
Release Required:	05/20/2002
Sent To Administrator:	Not reported
Signed By Adminstrator:	Not reported
Received From Adminsitrator:	Not reported
Release Sent To OAG:	06/02/2002
Complete:	True
Release:	True
Withdrawn:	False

SPILLS:

Facility ID:	9905975
Facility Type:	ER
Spill Number:	9905975
DER Facility ID:	117189
Site ID:	136983
DEC Region:	2
Closed Date:	2003-02-26
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	3101
Spill Date:	1999-08-16
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1999-08-18
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-18
Spill Record Last Update:	2006-06-20
Spiller Name:	Not reported
Spiller Company:	UNKNOWN FOR NOW
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	BONNIE ROSENSTOCK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND CALLER SAYS BUILDING ACROSS THE STREET HAD A BAD SPILL 2 DAYS AGO (8/16/99) SHE DOESN'T KNOW THE ADDRESS OR THE SPILLER. HER OWN BUILDING ALSO HAS SPILL PROBLEMS. SHE WILL CALL BACK WITH THE NAME AND PHONE NUMBER OF BOTH BUILDING MANAGING AGENTS AND BOTH OIL COMPANIES. 107 E 10th Street: Ferrentino Fuel 212-226-4191 Landlord - John Crane 212-753-5933 06/20/06-Vought-File review by Vought. See also spill numbers: 9511157 (105 E10th St-closed 03/17/03) 9611309 (105-107 E10th St-OPEN PIN WITH NOTES FOR ALL SITES ON BLOCK) 9702485 (116 E10th St-closed 05/28/97) 9704339 (107 E10th St-closed 11/17/03) 9807065 (103 E10th St-closed 03/14/05) 9905975 (103 E10th St-closed 02/26/03) 9913474 (103 E10th St-open) 0006640 (107 E10th St-closed 05/20/03) 0101346 (114 E10th St-closed 07/22/03) 0104789 (107 E10th St-closed 10/20/03) 0111670 (107 E10th St-closed 03/13/02) 0203371 (107 E10th St-closed 07/01/02) 0208470 (105 E10th St-closed 01/08/04)

103 EAST 10TH STREET (Continued) **S104620874**

0511701 (101 E10th St-open) "
Remarks: "CALLER STATES THE FUEL OIL COMPANY IS MAKING DELIVERIES TO THE APTS SHE STATES THIER HOUSEKEEPING IS VERY SLOPPY. THEY LEAVE OIL IN THE FRONT OF THE BUILDING AND ON THE PREMISES. SHE CAN GET THE NAME OF THE COMPANY FROM THE LANDLORD."

All Materials:
Site ID: 136983
Operable Unit ID: 1080411
Operable Unit: 01
Material ID: 302252
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BL856 **85-89 4TH AVENUE** **NY VCP** **S118943270**
NNE **85-89 4TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.323 mi.
1705 ft. **Site 2 of 4 in cluster BL**

Relative:
Lower

Actual:
40 ft.

VCP NYC:
Project ID: 13CVCP133K
Project Name: 85-89 4TH AVENUE
Project Address: 85-89 4TH AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 13CVCP133K
File Name: 2013-05-14.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP133K/2013-05-14.13CVCP133K.85-89_4th_Avenue.RIR.pdf

Project ID: 13CVCP133K
File Name: 2013-05-14.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP133K/2013-05-14.13CVCP133K.85-89_4th_Avenue.RAWP.draft.pdf

Project ID: 13CVCP133K
File Name: 2013-05-13.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP133K/2013-05-13.13CVCP133K.85-89_4th_Avenue.FactSheet-1.pdf

Project ID: 13CVCP133K
File Name: 2013-05-14.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP133K/2013-05-14.13CVCP133K.85-89_4th_Avenue.Translated_Factsheet1.pdf

Project ID: 13CVCP133K
File Name: 2013-05-14.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP133K/2013-05-14.13CVCP133K.85-89_4th_Avenue.Translated_CPS.pdf

85-89 4TH AVENUE (Continued) **S118943270**

Project ID:	13CVCP133K
File Name:	2013-06-10.Stipulation_List
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP133K/2013-06-14.13CVCP133K.85-89_4th_Avenue.Stip_List.pdf

---

BM857 **SPILL NUMBER 0208470** **NY LTANKS** **S106009305**
NE **105 E 10TH ST** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.323 mi.
1707 ft. **Site 4 of 4 in cluster BM**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:

Facility ID:	9611157
Site ID:	331436
Closed Date:	2003-03-17
Spill Number:	9611157
Spill Date:	1996-12-10
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1996-12-10
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-10
Spill Record Last Update:	2006-06-20
Spiller Name:	HENRY LEE
Spiller Company:	HENRY LEE
Spiller Address:	105 E 10TH ST
Spiller County:	001
Spiller Contact:	HENRY LEE
Spiller Phone:	(917) 832-5865
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266569
DEC Memo:	"06/20/06-Vought-File review by Vought. See also spill numbers: 9511157 (105 E10th St-closed 03/17/03) 9611309 (105-107 E10th St-OPEN PIN WITH NOTES FOR ALL SITES ON BLOCK) 9702485 (116 E10th St-closed 05/28/97) 9704339 (107 E10th St-closed 11/17/03) 9807065 (103 E10th St-closed 03/14/05) 9905975 (103 E10th St-closed 02/26/03) 9913474 (103 E10th St-open) 0006640 (107 E10th St-closed 05/20/03) 0101346 (114 E10th St-closed 07/22/03) 0104789 (107 E10th St-closed 10/20/03) 0111670 (107 E10th St-closed 03/13/02) 0203371 (107 E10th St-closed 07/01/02) 0208470 (105 E10th St-closed 01/08/04) 0511701 (101 E10th St-open) "
Remarks:	"MGR NOTICED OIL COMING OUT OF VAULTED TANK - VAULT OPENED AND TANK HAS A HOLE IN - TANK WILL BE REPAIRED - MOST OIL WAS CLEANED UP"

SPILL NUMBER 0208470 (Continued) **S106009305**

All Materials:

Site ID:	331436
Operable Unit ID:	1042701
Operable Unit:	01
Material ID:	343358
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0208470
Facility Type:	ER
Spill Number:	0208470
DER Facility ID:	274963
Site ID:	331435
DEC Region:	2
Closed Date:	2004-01-08
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3101
Spill Date:	2002-11-15
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2002-11-15
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-15
Spill Record Last Update:	2006-06-20
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 10/15/2002: called mr. robertsoon at 718-325-1144. No response. Called at 3:44 pm. Left message on voice mail to call us back. ARS. 1/08/2003-Vought-Spill alarm went off after truck left. Non spill event. Closed by Vought. 06/20/06-Vought-File review by Vought. See also spill numbers: 9511157 (105 E10th St-closed 03/17/03) 9611309 (105-107 E10th St-OPEN PIN WITH NOTES FOR ALL SITES ON BLOCK) 9702485 (116 E10th St-closed 05/28/97) 9704339 (107 E10th St-closed 11/17/03) 9807065 (103 E10th St-closed 03/14/05) 9905975

SPILL NUMBER 0208470 (Continued) **S106009305**

(103 E10th St-closed 02/26/03) 9913474 (103 E10th St-open) 0006640 (107 E10th St-closed 05/20/03) 0101346 (114 E10th St-closed 07/22/03) 0104789 (107 E10th St-closed 10/20/03) 0111670 (107 E10th St-closed 03/13/02) 0203371 (107 E10th St-closed 07/01/02) 0208470 (105 E10th St-closed 01/08/04) 0511701 (101 E10th St-open) "

Remarks: "caller went to leave his apt & heard an alarm going off - he did see a delivery truck leave - unk if there is a spill - he called the local office to inquire about the alarm but they referred him to the spill hotline."

All Materials:

Site ID:	331435
Operable Unit ID:	861466
Operable Unit:	01
Material ID:	515474
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

858
NW
1/4-1/2
0.334 mi.
1763 ft.

NY UNIVERSITY **NY LTANKS** **S105994966**
WEST 3RD ST/THOMPSON ST **N/A**
NEW YORK, NY

Relative:
Lower

Actual:
26 ft.

LTANKS:

Facility ID:	0110099
Site ID:	251943
Closed Date:	2002-05-20
Spill Number:	0110099
Spill Date:	2002-01-21
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2002-01-21
CID:	405
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-21
Spill Record Last Update:	2002-05-20
Spiller Name:	TONY KLOSS
Spiller Company:	NY UNIVERSITY
Spiller Address:	WEST 3RD ST/THOMPSON ST

NY UNIVERSITY (Continued) **S105994966**

Spiller County:	001
Spiller Contact:	TONY KLOSS
Spiller Phone:	(908) 453-2790
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	206449
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 50 cu yards of contaminated soil were removed and properly disposed off. Post excavation samples does not show soil contamination. (see file for more info.). "
Remarks:	"caller states he was removing a 1000 gallon tank and found holes in the tank and approx 20 yards of contaminated soil"

All Materials:

Site ID:	251943
Operable Unit ID:	847219
Operable Unit:	01
Material ID:	527729
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL859 **116 E 11TH ST** **NY LTANKS** **S102671758**
NE **116 E 11TH ST** **N/A**
1/4-1/2 **NYC, NY**
0.339 mi.
1790 ft. **Site 3 of 4 in cluster BL**

Relative: **Lower**
Actual: **39 ft.**

LTANKS:

Facility ID:	9108578
Site ID:	319633
Closed Date:	1991-11-12
Spill Number:	9108578
Spill Date:	1991-11-11
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1991-11-12
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1991-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-11-21
Spill Record Last Update:	1991-12-06

116 E 11TH ST (Continued) **S102671758**

Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	257524
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"CONTAINED IN ALLEYWAY IN FRONT OF BUILDING BELOW GROUND LEVEL. WHALE-CO CLEANUP CREW ENROUTE."

All Materials:

Site ID:	319633
Operable Unit ID:	962626
Operable Unit:	01
Material ID:	420717
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

860 **109 PRINCE ST** **NY LTANKS** **S106703636**
WSW **109 PRINCE ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.343 mi.
1809 ft.

Relative: **Lower**

Actual: **25 ft.**

LTANKS:

Facility ID:	9205530
Site ID:	246381
Closed Date:	2002-12-27
Spill Number:	9205530
Spill Date:	1992-08-13
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SJMILLER
Referred To:	Not reported
Reported to Dept:	1992-08-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-21

109 PRINCE ST (Continued) **S106703636**

Spill Record Last Update:	2002-12-27
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	202350
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER "
Remarks:	"CONTAMINATED SOIL TO BE PICKED UP & DISPOSED BY HAZARDOUS ELIMINATION CORP."

All Materials:

Site ID:	246381
Operable Unit ID:	969142
Operable Unit:	01
Material ID:	409735
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

861
ENE
1/4-1/2
0.347 mi.
1833 ft.

UNDERGROUND
156 2ND AVE
NEW YORK, NY

NY LTANKS **S110769534**
NY Spills **N/A**

Relative:
Lower

Actual:
30 ft.

LTANKS:

Facility ID:	0611420
Site ID:	376114
Closed Date:	2011-04-12
Spill Number:	0611420
Spill Date:	2007-01-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2007-01-15
CID:	76
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

UNDERGROUND (Continued) **S110769534**

Date Entered In Computer:	2007-01-16
Spill Record Last Update:	2011-04-12
Spiller Name:	MARLIN JOSEPH
Spiller Company:	CITY URBAN MNGT
Spiller Address:	156 2ND AVE
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	109
DEC Region:	2
DER Facility ID:	325708
DEC Memo:	"1/22/07 notified that this was referred to me from V. Zhune. Called James Seiler of Sterling Equiies (516)773-3800. Left message to call me back. bf 2/1/07 bf: sent ttf letter to: James Seiler Clearwater Associates c/o Sterling Equities 111 Great Neck Road Great Neck, NY 11021 4/16/07 received tank test results on 3/13/07. Tank passed test on 1/18/07. bf 6/14/07 Left message for J. Seiler and requested a call back and a letter from 3rd party regarding repairs made to the tank. bf 6/22/07 Called Mr. Seiler. He told me the building was sold and they have not operated it since 2005. City Urban Management is now management company (516)466-3333. They told me they sent report and letter to me by certified mail in January 2007. I never received it. They will fax it to me today. bf 4/7/08 Site was issued a NOV on 1/30/07 as a result of a PBS inspection. DLA has been in contact with the attorney for the site, Jim Rigano. J. Urda and I called Mr. Rigano today and left a message with his sectertary for him to return the call. Staff called him to discuss violations found during the inspection and for closure of this spill both of which are part of a draft consent order. bf 04/12/11-Hiralkumar Patel. 10:00 AM:- visited site as part of investigation of spill #: 1013012. met building manager and super. inspected tank room. found some stained concrete, but tank room floor found in good condition and does not need any subsurface investigation. the old lines were running aboveground which were removed. manager mentioned that they started managing building in Aug. 2005 and since then they were using the fill port by the foundation wall and they never used fill line that was running under the sidewalk. saw old cut out fill line under the sidewalk. no sign of oil spill found by area where old fill line enters into building. based on observations during the site visit, case closed. refer to spill #:1013012 for more details."
Remarks:	"CALLER REPORTS TANK FAILURE TEST WITH NO LEAK. "

All TTF:

Facility ID:	0611420
Spill Number:	0611420
Spill Tank Test:	1550561
Site ID:	376114
Tank Number:	1
Tank Size:	5000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

UNDERGROUND (Continued) **S110769534**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 376114
Operable Unit ID: 1133719
Operable Unit: 01
Material ID: 2123540
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 1013012
Facility Type: ER
Spill Number: 1013012
DER Facility ID: 325708
Site ID: 447313
DEC Region: 2
Closed Date: 2011-04-12
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 3101
Spill Date: 2011-03-27
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2011-03-30
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-03-30
Spill Record Last Update: 2011-04-12
Spiller Name: Not reported
Spiller Company: CITI URBAN MANAGEMENT CORP
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JOE MOHAN
DEC Memo: "03/30/11-Hiralkumar Patel. alternate address: 196-204 E 10th Street Other spill #: 0611420 PBS #: 2-240346. as per PBS, site has one 5,000 gal #2 oil AST in contact with soil. tank was installed in Jan. 1920. site had two 275 gal #2 oil ASTs on legs which were removed in Aug. 2010. spill 0611420 was reported on 01/15/07 due to tank test failure. TTF was sent on 02/01/07, but no response. a NOV was issued

UNDERGROUND (Continued) **S110769534**

on 01/30/07 and a consent order was signed by RP. as per the compliance schedule in the consent order, a closure report for the spill #: 0611420 was due on 06/21/08, but the spill case is still open. as per ACRIS: Second Avenue Village Partners LLC. **property owner** Nathan Halegua **property partner** c/o Citi Urban Management Corp. 6 Grace Avenue, Suite 400 Great Neck, NY 11021 Attn.: Joe Mohan **property manager** Ph. (516) 466-3333 (O) (917) 335-4728 (C) email: jmohan@citiurban.com Joseph Debono **super** Ph. (516) 903-9630 4:49 PM:- sent email to DEC Urda informing that spill #: 0611420 is still open and possible violation of the consent order. 4:58 PM:- spoke with Mr. Debono, building super. he mentioned that they are converting from oil to gas. he mentioned that there is no spill. he is not at the building and asked to call property manager for access in building for inspection. 5:02 PM:- spoke with Mr. Mohna, property manager. asked him to arrange access for site inspection. 03/31/11-Hiralkumar Patel. received email from Mr. Mohan (at 5:34 PM on 03/30/11) including a passing tank system test result from Jan. 2007 (result on PBS e-docs). but no indication about type of work/repair done after initial failure. 9:36 AM:- spoke with Mark at PTC regarding tank test failure reported on 01/15/07. Mark mentioned that they tested tank system on 01/15/07 and it failed. they went back on 01/18/07 and system passed. Mark will look for documents to see if any repair done by PTC after test failure on 01/15/07. tank system was tested on 01/25/11 for refinance purpose and it passed. during conversation Mark mentioned that they cleaned out tank on 03/25/11 and they pumped out #4 oil from tank. after cleaning tank, property manager/super filled tank with #2 oil and observed oil leaked from tank. the tank is aboveground wrapped with cinder blocks. Mark doesn't know if there is any spill inside the cinder blocks. Mr. Mohan submitted passing tank test result dated 01/15/07, but as per Mark they tested system again on 01/18/07 when it passed. also, as per PBS record, site is using #2 oil, but as per PTC, they pumped out #4 oil from tank. 9:44 AM:- received fax from Mark including two invoice copy for tank test work. invoices doesn't include any information about repair work. invoices stored on e-doc for spill #: 0611420. 9:53 AM:- left message for Joe, property manager. 9:55 AM:- left message for Joe at NYC DOH. 12:09 PM:- received call from Joe from DOH. he found about 57 ppm in tank room, about 12 ppm in basement outside of tank room and 0 ppm in common area on first floor. he also found some loose oil and some speedy dry on tank room floor. 12:13 PM:- left message for Joe, building super. 12:14 PM:- left message for Joe, property manager. 12:39 PM:- received call from Joe, super. he will meet at the site at 4:30 PM today. 4:15 PM:- visited site. met building super. inspected tank room. site has one 5,000 gal aboveground tank sitting on floor. found oil stain on floor along the side of the tank. could inspect only one side of the tank as other three sides were close to tank room walls. found sign of recent leak (little wet) on side of the tank. super mentioned that they were using #4 oil. the tank was cleaned on 03/25/11 and then they put about 1200-1500 gal #2 oil in it. soon after they found oil leaking from side of the tank. super tried to clean spill with water/soap that cause larger stain on floor. found solid floor in visible areas. during inspection, found two concrete patches on E 10th street sidewalk. also found about 1 ft wide concrete patch from sidewalk to sidewalk entrance to basement. super doesn't know anything about these patches as working for only 2.5 years. the most recent fill port was loacted on building foundation wall, close to

UNDERGROUND (Continued) **S110769534**

garbage conainer area. 4:51 PM:- spoke with Joe, building manager. he mentioned that tank will be removed tomorrow and PTC will remove the tank. informed Joe that as the department never got any documents regarding the cause of tank test failure in Jan. 2007, the department requires investigation. so asked him to call for re-inspection once the tank is removed as need to inspect floor condition underneath the tank. informed him that the department may require further investigation based on inspection. 5:28 PM:- received call from Mark from PTC. they will submit a proposal for tank removal and will start tank removal once get approval. 04/05/11-Hiralkumar Patel. 9:08 AM:- spoke with Joe, building manager. he has sent signed proposal to PTC and tank will be removed this week. Joe will meet at 10 AM, at the site, on 04/12/11. 04/07/11-Hiralkumar Patel. 12:43 PM:- received call from Mark from PTC. they removed the tank. 04/12/11-Hiralkumar Patel. 10:00 AM:- visited site. met building manager and super. inspected tank room. found some stained concrete, but tank room floor found in good condition and does not need any subsurface investigation. the old lines were running aboveground which were removed. manager mentioned that they started managing building in Aug. 2005 and since then they were using the fill port by the foundation wall and they never used fill line that was running under the sidewalk. saw old cut out fill line under the sidewalk. no sign of oil spill found by area where old fill line enters into building. based on observations during the site visit, case closed."

Remarks: "Caller advised received a call advised of a smell of oil coming from the building he advised he has readings of 57.3 ppm. Caller advised that the building is possibly going through a conversion to natural gas. Caller advised that the building houses commercial and residential. Oil is spilled onto the oil tank room floor."

All Materials:

Site ID:	447313
Operable Unit ID:	1197457
Operable Unit:	01
Material ID:	2193775
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

862
ENE
1/4-1/2
0.348 mi.
1837 ft.

APARTMENT- TTF **NY LTANKS** **S106869301**
332 E 9TH ST **N/A**
NEW YORK CITY, NY 10003

Relative: Lower
Actual: 27 ft.

LTANKS:

Facility ID:	0501168
Site ID:	344329
Closed Date:	2006-04-27
Spill Number:	0501168
Spill Date:	2005-04-28
Spill Cause:	Tank Test Failure

APARTMENT- TTF (Continued) **S106869301**

Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-04-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-28
Spill Record Last Update:	2006-05-19
Spiller Name:	ALLEN TABAK
Spiller Company:	APARTMENT
Spiller Address:	332 EAST 9TH STREET
Spiller County:	001
Spiller Contact:	ALLEN TABAK
Spiller Phone:	(908) 273-7726
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	314408
DEC Memo:	"ttf ltr sent to: Alan Tabak P.O. Box 1384 Summit, NJ 07902-1384 07/25/05-Sharif Rahman// Left a message for Alan to follow up about the tank. 10.14.05 Sharif Rahman//Sharif sent another violation letter to above address and faxed it to 908-273-5613. 02/23/06 Sharif Rahman- I left a messege and also sent another ttf letter to Tabak Family Realty Company 332 East 9th Street New York, NY 10003 03/17/06 Sharif Rahman- I called Alan Tabak,(908)273-7726 several times and he never picked up the phone. I left messege and never got any return call.TTF was sent to Tyron Hendix(212-228-9420) 329 East 6th Street New York, NY 10003 as per her suggestion. 03/24/06 Sharif Rahman- Mr. Mario from Petro Oil,(718)-333-8882 called to say the old tank was removed and 2 275 tanks were placed instead.There was a crack on top of the tank but there was no spill and no contamination observed. A report will be sent to DEC in a week. 04/27/06 Sharif Rahman- The 1500 gallon tank has been removed and two 275 ASTs have been installed.The 1500 gallon tank failed the test because of a crack at the manhole and no oil spill was observed out side of the tank area.Invoice of work was provided.NFA required."
Remarks:	"RECOMMEND, NOTHING AT THIS TIME;"

All TTF:

Facility ID:	0501168
Spill Number:	0501168
Spill Tank Test:	1548855
Site ID:	344329
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

APARTMENT- TTF (Continued) **S106869301**

Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 344329
Operable Unit ID: 1102974
Operable Unit: 01
Material ID: 583186
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

BL863 **SUBSTATION** **NY LTANKS** **S105995570**
NNE **4TH AVE & 11TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.349 mi.
1842 ft. **Site 4 of 4 in cluster BL**

Relative:
Lower

Actual:
40 ft.

LTANKS:
Facility ID: 0200225
Site ID: 157318
Closed Date: 2002-08-05
Spill Number: 0200225
Spill Date: 2002-04-07
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 2002-04-07
CID: 322
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-04-07
Spill Record Last Update: 2002-08-05
Spiller Name: Not reported
Spiller Company: WARD ELECTRIC
Spiller Address: (CONTRACTOR)
Spiller County: 001
Spiller Contact: JAMES CRANDALL

SUBSTATION (Continued) **S105995570**

Spiller Phone: (718) 243-4581
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 133052
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CONTAINED AND CLEANED BY NYCT."
Remarks: "employee of nyc transit noticed that a contractors barrel was leaking - spill to floor of building - spill contained with speedy dry "

All Materials:
Site ID: 157318
Operable Unit ID: 853648
Operable Unit: 01
Material ID: 525222
Material Code: 1680A
Material Name: silicone oil
Case No.: Not reported
Material FA: Other
Quantity: 30.00
Units: G
Recovered: .00
Oxygenate: Not reported

864
NE
1/4-1/2
0.351 mi.
1852 ft.

SPILL NUMBER 0301866 **NY LTANKS** **S105999023**
200 E 11TH ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
38 ft.

LTANKS:
Facility ID: 0301866
Site ID: 137439
Closed Date: 2003-08-07
Spill Number: 0301866
Spill Date: 2003-05-21
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2003-05-21
CID: 207
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-05-21
Spill Record Last Update: 2003-08-07
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported

SPILL NUMBER 0301866 (Continued) **S105999023**

Spiller County:	001
Spiller Contact:	JIM FLARRERTY
Spiller Phone:	(212) 560-6423
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	117584
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 5/22/03 - ROSSAN, DDO - Called Jim Flarrerty, who confirmed tank failure and advised that tank test failure letter sent to: Mr. Mitchell Barry, c/o Jim Flarrerty 200 East 11th St. Associates c/o Century Operating Corp. 7 Penn Plaza Suite 1400 New York, NY 10001 08/07/03 ttf due to corroded air vent line// vent repaired as per mr flaherty"
Remarks:	"uncover - retest"

All TTF:

Facility ID:	0301866
Spill Number:	0301866
Spill Tank Test:	1528398
Site ID:	137439
Tank Number:	1
Tank Size:	7500
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

BN865 **SPILL NUMBER 0212755** **NY LTANKS** **S105998497**
North **80 EAST 11TH STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.356 mi.
1882 ft. **Site 1 of 3 in cluster BN**

Relative: **Lower**

Actual: **39 ft.**

LTANKS:

Facility ID:	0212755
Site ID:	292802
Closed Date:	2004-01-07
Spill Number:	0212755
Spill Date:	2003-03-25
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2003-03-25
CID:	195
Water Affected:	Not reported
Spill Notifier:	Affected Persons

SPILL NUMBER 0212755 (Continued) **S105998497**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-25
Spill Record Last Update:	2004-01-07
Spiller Name:	CAMBRIDGE ASSOCIATES
Spiller Company:	ST DENIS OFFICE BLDG
Spiller Address:	80 EAST 11TH ST
Spiller County:	001
Spiller Contact:	MARK SALAMACK
Spiller Phone:	(917) 559-5519
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	236997
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT CALLED MARK SALAMACK,(PETROLEUM TANK CLEANERS), WHO CONFIRMED THAT SPILL IS ON CONCRETE FLOOR OF AN OFFICE BUILDING. SPILL IS CONTAINED AND CLEAN-UP IN PROGRESS. NO WATER OR SOIL WAS IMPACTED. E.R. 3/27/2003-Vought-spill transferred from Tipple to Vought. Site visit by Vought. Spill on brick with schist cobble wall containment area. Minor staining between bricks (brick removal not needed due to thorough grouting and hence lack of infiltration). Tank emptied by PTC. No sewers or drains affected. Spill cleaned using speedy dry. For spill closure NYSDEC requires copy of invoice of sealing of containment walls. 1/7/04-Vought-Received copy of invoice of sealing of containment walls. Spill closed by Vought."
Remarks:	"TANK HAD BEEN CLEANED OUT EARLIER. OIL WAS BEING PUMPED INTO TANK AND TANK FAILED. CLEAN UP IN PROGRESS. "

All Materials:

Site ID:	292802
Operable Unit ID:	866213
Operable Unit:	01
Material ID:	512479
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BO866 **183 CHRYSTIE STREET** **NY LTANKS** **S106703765**
South **183 CHRYSTIE STREET** **N/A**
1/4-1/2 **NEW YORK, NY**
0.362 mi.
1913 ft. **Site 1 of 3 in cluster BO**

Relative: **Higher**

Actual: **42 ft.**

LTANKS:

Facility ID:	9512158
Site ID:	219443
Closed Date:	1996-11-22
Spill Number:	9512158
Spill Date:	1995-12-28

183 CHRYSTIE STREET (Continued) **S106703765**

Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-12-28
CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-28
Spill Record Last Update:	2002-04-24
Spiller Name:	FRANK ODONNEL
Spiller Company:	BAERENKLAU
Spiller Address:	740 JAMAICA AVENUE
Spiller County:	001
Spiller Contact:	STANDARD TINSMITH SUPPLY
Spiller Phone:	(212) 674-2240
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	280598
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 30 OR 40 GALLONS - FD ON SCENE - SPOKE TO ERIK AT TINSMITH SUPPLY, SPILL IN DRIVEWAY, ON C0ONCRETE, THRU VENT - OIL CO HAD ONLY 8 BAGS O FSPEEDY DRY - FD CLOSED STREET, WILL NOT LET THEM LEAVE UNTIL CLEAN - LEFT # IF THEY NEED TO CALL. CLEANED BY RP. HANDLED BY FD."
Remarks:	"SMALL SPILL AT A SMALL APARTMENT BUILDING AREA WAS CLEANED UP BY CALLERS COMPANY "

All Materials:

Site ID:	219443
Operable Unit ID:	1026375
Operable Unit:	01
Material ID:	359471
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

BO867 **LOT 35,TAXBLOCK 426** **NY LTANKS** **S103239018**
South **183 CHRYSTIE STREET** **NY E DESIGNATION** **N/A**
1/4-1/2 **MANHATTAN, NY 10002**
0.362 mi.
1913 ft. **Site 2 of 3 in cluster BO**

Relative:
Higher

Actual:
42 ft.

LTANKS:

Facility ID:	9510876
Site ID:	219442
Closed Date:	1995-11-29
Spill Number:	9510876
Spill Date:	1995-11-29
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1995-11-29
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-29
Spill Record Last Update:	2002-04-24
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU FUEL OIL
Spiller Address:	740 JAMAICA AVE
Spiller County:	001
Spiller Contact:	STANDARD TIN SMITHS
Spiller Phone:	(212) 674-2240
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	181475
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"CUSTOMER ORDERED 400 GALS AND STARTED TO SPILL AFTER 360 GALS."

All Materials:

Site ID:	219442
Operable Unit ID:	1021411
Operable Unit:	01
Material ID:	358229
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

E DESIGNATION:

LOT 35,TAXBLOCK 426 (Continued) **S103239018**

Tax Lot(s):	35
Tax Block:	426
Borough Code:	MN
E-No:	E-216
Effective Date:	11/19/2008
Satisfaction Date:	Not reported
Ceqr Number:	07DCP078M
Ulurp Number:	080397ZMM
Zoning Map No:	12c
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

BP868 **TTF** **NY LTANKS** **S117853746**
SW **547 BROADWAY** **N/A**
1/4-1/2 **NEW YORK, NY**
0.367 mi.
1937 ft. **Site 1 of 3 in cluster BP**

Relative: **Lower**

Actual: **30 ft.**

LTANKS:

Facility ID:	1411718
Site ID:	505512
Closed Date:	2016-02-03
Spill Number:	1411718
Spill Date:	2015-03-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2015-03-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-16
Spill Record Last Update:	2016-02-03
Spiller Name:	Not reported
Spiller Company:	SHAWN INNIS
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	SHAWN INNIS
Spiller Phone:	212 529 5688
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	460332
DEC Memo:	"3/16/15- 2-327425 DEC piper spoke with call jeff mcKenzie. AS per conversation, the 2K aboveground contact with soil tank failed a tightness test in the wet portion of the tank. I spoke with Andrew Bldg Corp Eric Martinez. I insturcted him to empty tank and set up temp tanks. Bldg is a residential bldg. He is in talks with Oil provider and will contqct Dept if needed. DEC Zhune's contact info

TTF (Continued) **S117853746**

provided. TTF Letter to be sent to 547 Browadway Realty Inc C/o Andrews Building Corp 666 Broadway, 12th FLoor New York, NY 10012 Assigned to DEC Zhune for followup and closure. 2/3/16-David Chan from Riteway sent the spill closure report. The letter stated that on November 23, 2015 Riteway Tank Maintenance Corp. was contracted by Andrews Building Corp. to address a tank test failure. The tank test failed with an ullage dry portion leak. There was no contamination neither found nor observe. The existing 2000 gallon AST was pumped out, cleaned, scraped and washed. Lines were isolated, tested ant the vent was found to be faulty. In addition, and old cut was found on the tank. Rite way proceeded to install a new vent and re-welded the old cut. Afterwards, another tank test was performed on the entire system which passed. Based on this information the spill is closed."

Remarks: "tank test fail"

All Materials:

Site ID:	505512
Operable Unit ID:	1254822
Operable Unit:	01
Material ID:	2257447
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BN869 **SPILL NUMBER 0109418** **NY LTANKS** **S105230146**
North **58 E. 11TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.367 mi.
1939 ft. **Site 2 of 3 in cluster BN**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:

Facility ID:	0109418
Site ID:	97042
Closed Date:	2003-03-10
Spill Number:	0109418
Spill Date:	2001-12-24
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	EXROSSAN
Referred To:	Not reported
Reported to Dept:	2001-12-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

SPILL NUMBER 0109418 (Continued) **S105230146**

Date Entered In Computer:	2001-12-24
Spill Record Last Update:	2003-03-10
Spiller Name:	Not reported
Spiller Company:	BIJAN REALTY INC
Spiller Address:	58 E. 11TH ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(212) 533-0604
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	86509
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROSSAN Called Carl, Petro, On 12/24/01, At 1540 Hrs. Who Confirmed That Clean-Up Crew Is On The Way. No Soil Or Water Is Impacted. Called Bijan Realty, Who Confirmed That Clean Is In Progress.03/10/2003- Closed Due To The Nature / Extent Of The Spill Report."
Remarks:	"owner of building call to report the oil spill - there is a leak in the tank - repairman on site at this time "

All Materials:

Site ID:	97042
Operable Unit ID:	847775
Operable Unit:	01
Material ID:	530626
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

870 **MELTZER-HERNANDEZ (GOMPERS)** **NY LTANKS** **U000410814**
SSE **189 ALLEN STREET (HERNANDEZ)** **NY UST** **N/A**
1/4-1/2 **NEW YORK, NY 10002**
0.378 mi.
1997 ft.

Relative:
Lower

Actual:
37 ft.

LTANKS:

Facility ID:	9001939
Site ID:	200757
Closed Date:	1995-04-20
Spill Number:	9001939
Spill Date:	1990-05-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-04-20
SWIS:	3101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-05-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

MELTZER-HERNANDEZ (GOMPERS) (Continued) **U000410814**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-22
Spill Record Last Update:	1995-05-09
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	167048
DEC Memo:	""
Remarks:	"15K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK. SEE SPILL # 9100612"

All TTF:

Facility ID:	9001939
Spill Number:	9001939
Spill Tank Test:	1537096
Site ID:	200757
Tank Number:	001
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	200757
Operable Unit ID:	941801
Operable Unit:	01
Material ID:	554555
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9007076
Site ID:	200758
Closed Date:	1995-04-20

MELTZER-HERNANDEZ (GOMPERS) (Continued) **U000410814**

Spill Number:	9007076
Spill Date:	1990-09-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-04-20
SWIS:	3101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-09-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-10
Spill Record Last Update:	1995-04-20
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	167048
DEC Memo:	""
Remarks:	"VISUAL LEAK AT PETROMETER, 15K TANK FAILED HORNER EZY CHECK, WILL EXCAVATE, ISOLATE & RETEST. SEE SPILL # 9100612"

All TTF:

Facility ID:	9007076
Spill Number:	9007076
Spill Tank Test:	1537609
Site ID:	200758
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	200758
Operable Unit ID:	944516
Operable Unit:	01
Material ID:	434502

MELTZER-HERNANDEZ (GOMPERS) (Continued) **U000410814**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9100612
Site ID:	200759
Closed Date:	1995-06-21
Spill Number:	9100612
Spill Date:	1991-04-16
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-06-21
SWIS:	3101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1991-04-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-17
Spill Record Last Update:	2004-04-01
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	167048
DEC Memo:	""
Remarks:	"15K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK. TANK REPAIRED AND RETESTED 7/9/91 AND PASSED. See 9001939 and 9007076."

All TTF:

Facility ID:	9100612
Spill Number:	9100612
Spill Tank Test:	1538458
Site ID:	200759
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

MELTZER-HERNANDEZ (GOMPERS) (Continued) **U000410814**

Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 200759
Operable Unit ID: 951749
Operable Unit: 01
Material ID: 426802
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

UST:
Id/Status: 2-475289 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/28/2019
UTM X: 585409.35855
UTM Y: 4508418.50716
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 20988
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-10-03

Site Id: 20988
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR

MELTZER-HERNANDEZ (GOMPERS) (Continued) **U000410814**

City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	YELENA.TKACH@NYCHA.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-08-14

Site Id:	20988
Affiliation Type:	Facility Operator
Company Name:	MELTZER-HERNANDEZ (GOMPERS)
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-01-30

Site Id:	20988
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-01-17

Tank Info:

Tank Number:	1
Tank ID:	37780
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	15000
Install Date:	08/01/1971
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001

MELTZER-HERNANDEZ (GOMPERS) (Continued) **U000410814**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 03/23/2017
Next Test Date: 03/23/2018
Pipe Model: Not reported
Modified By: TLYE
Last Modified: 10/16/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None

BQ871 **MELZER-HERNANDEZ (GOMPERS)** **NY LTANKS** **U001840737**
SE **94 EAST 1ST STREET (MELZER)** **NY UST** **N/A**
1/4-1/2 **NEW YORK, NY 10002** **NY Spills**
0.378 mi.
1997 ft. **Site 1 of 2 in cluster BQ**

Relative: LTANKS:
Lower
Actual: Facility ID: 0104813
33 ft. Site ID: 328653
Closed Date: 2009-07-07
Spill Number: 0104813
Spill Date: 2001-08-03
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: jkkann
Referred To: Not reported
Reported to Dept: 2001-08-03
CID: 282
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-08-03
Spill Record Last Update: 2009-07-07
Spiller Name: SEBASTIAN LOREFICE
Spiller Company: NEW YORK CITY HOUSING
Spiller Address: 250 BROADWAY
Spiller County: 001
Spiller Contact: SEBASTIAN LOREFICE

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Spiller Phone:	(718) 649-7017
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	264491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY 4/30/04 TJD As per direction of RSE, site transferred Demeo >>> Kolleeny as spill location is at NYCHA owned facility. 11/07/05: This spill transferred from J.Kolleeny to S.Kraszewski. 12/27/05: Several tank failures since 1989. Passed subsequent tightness test in 2002. - SK 01/27/06: THis spill transferred from S.Kraszewaski to Q.Abidi. 03/31/06: This spill transferred from Q. Abidi to Koon Tang. 07/07/09: J.Kann - spill transferred to J.Kann. Based on information provided by NYCHA indicating TT failure was due to a leaking piezometer, the spill was closed. Piezometer was repaired and tank passed subsequent tests. Tank Tightness testing information provided (edocs)."
Remarks:	"tank failed the test.isolation and retesting"

All TTF:

Facility ID:	0104813
Spill Number:	0104813
Spill Tank Test:	1526504
Site ID:	328653
Tank Number:	1
Tank Size:	15000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	328653
Operable Unit ID:	843331
Operable Unit:	01
Material ID:	533290
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	9001822
Site ID:	290409
Closed Date:	2004-04-09
Spill Number:	9001822
Spill Date:	1990-05-16

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1990-05-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-17
Spill Record Last Update:	2005-12-27
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTH
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	264491
DEC Memo:	""
Remarks:	"15K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL PUMP TEST, RETEST LINE, UNTRA SONIC INSPECTION OF TANK. See 8911775. Tank passed tightness testing subsequently, specifically on 4/22/02. Breen."

All TTF:

Facility ID:	9001822
Spill Number:	9001822
Spill Tank Test:	1537082
Site ID:	290409
Tank Number:	001
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	290409
Operable Unit ID:	940072
Operable Unit:	01
Material ID:	436603
Material Code:	0002A

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	8911775
Site ID:	235062
Closed Date:	1997-04-07
Spill Number:	8911775
Spill Date:	1990-03-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-03-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-15
Spill Record Last Update:	2005-12-27
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	264491
DEC Memo:	""
Remarks:	"15K TK FAILS HORNER-EZY @ L R =-0.311. EXCAV & ISOL. See 9001822."

All TTF:

Facility ID:	8911775
Spill Number:	8911775
Spill Tank Test:	1536853
Site ID:	235062
Tank Number:	001
Tank Size:	15000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 235062
Operable Unit ID: 937599
Operable Unit: 01
Material ID: 441280
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

UST:
Id/Status: 2-475270 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/28/2019
UTM X: 585493.82282
UTM Y: 4508521.50722
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 20987
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: 718-707-5900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-12-31

Site Id: 20987
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	YELENA.TKACH@NYCHA.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-08-14

Site Id:	20987
Affiliation Type:	Facility Operator
Company Name:	MELZER-HERNANDEZ (GOMPERS)
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-02-03

Site Id:	20987
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-01-17

Tank Info:

Tank Number:	1
Tank ID:	37779
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	15000
Install Date:	08/01/1971
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Tightness Test Method: 21
Date Test: 03/22/2017
Next Test Date: 03/22/2018
Pipe Model: Not reported
Modified By: TLYE
Last Modified: 09/11/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None

SPILLS:

Facility ID: 9901157
Facility Type: ER
Spill Number: 9901157
DER Facility ID: 131883
Site ID: 155769
DEC Region: 2
Closed Date: 1999-09-28
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 3101
Spill Date: 1999-04-29
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-04-29
CID: 216
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-04-29
Spill Record Last Update: 2000-06-14
Spiller Name: RICHARD ROACH
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: RICHARD ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes: 1/2 pint of dielectric fluid from seal cap leaking on feeder cable ends in man hole. Contained. PLIC in structure. absorb pads placed. Cleanup pending test results and crew.

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

AROCLOR 1254 pcb count <1.00 ppm cleanup complete in mh - 53648 on 4/30/99 @ 23:00 hrs. <1ppm AROCLOR 1254 Removed 150 gals oil/water to <50 tanker. Generated 1 drum PPE Used flush truck to clean and rinse structure. Removed spill tag upon completion. "

Remarks: "leaking distribution feeder spill is being sampled before cleanup their spill number is con edison "

All Materials:

Site ID:	155769
Operable Unit ID:	1079906
Operable Unit:	01
Material ID:	304706
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Facility ID:	8911347
Facility Type:	ER
Spill Number:	8911347
DER Facility ID:	264491
Site ID:	302936
DEC Region:	2
Closed Date:	1993-11-30
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3101
Spill Date:	1990-03-01
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-03-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-11-30
Cleanup Meets Std:	True
Last Inspection:	1993-08-10
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-05
Spill Record Last Update:	2005-12-27
Spiller Name:	Not reported
Spiller Company:	N.Y.C.H.A.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SEEPAGE INTO SUMP PIT 35 GALS REMOVED SO FAR. OIL IS RESULT OF CLEANING BOILER ROOM FLOOR. NO ADDITIONAL SEEPAGE DISCOVERED."

All TTF:

MELZER-HERNANDEZ (GOMPERS) (Continued) **U001840737**

Facility ID:	8911347
Spill Number:	8911347
Spill Tank Test:	1536811
Site ID:	302936
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	302936
Operable Unit ID:	937022
Operable Unit:	01
Material ID:	440871
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BP872 **114 MERCER STREET** **NY LTANKS** **S102671953**
SW **114 MERCER STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.380 mi.
2008 ft. **Site 2 of 3 in cluster BP**

Relative: **Lower**
Actual: **27 ft.**

LTANKS:

Facility ID:	0409192
Site ID:	334057
Closed Date:	2004-11-22
Spill Number:	0409192
Spill Date:	2004-11-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-11-17
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

114 MERCER STREET (Continued) **S102671953**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-19
Spill Record Last Update:	2004-11-22
Spiller Name:	MARK SALAMACK
Spiller Company:	COMM/RES BUILDING
Spiller Address:	114 MERCER ST
Spiller County:	001
Spiller Contact:	MARK SALAMACK
Spiller Phone:	(917) 559-5519
Spiller Extention:	CELL
DEC Region:	2
DER Facility ID:	269263
DEC Memo:	"Sangesland spoke to Mark at PTC. He said PTC pulled out an AST and found about 1/2 drum of contaminated soil. Area was dug out, site appeared clean. OK to close case"
Remarks:	"Tank size:3000 Gallon."
Facility ID:	9208021
Site ID:	165107
Closed Date:	1992-10-12
Spill Number:	9208021
Spill Date:	1992-10-08
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-12
SWIS:	3101
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1992-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-10-15
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	139183
DEC Memo:	""
Remarks:	"OVERFILLED AND SPILLED INTO ALLEY MARK RYAN CLEANED IT UP."

All Materials:

Site ID:	165107
Operable Unit ID:	971670

114 MERCER STREET (Continued) **S102671953**

Operable Unit:	01
Material ID:	408629
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BR873 **231 EAST 11TH ST** **NY LTANKS S109207713**
NE **231 EAST 11TH ST** **NY Spills N/A**
1/4-1/2 **MANHATTAN, NY**
0.381 mi.
2011 ft. **Site 1 of 3 in cluster BR**

Relative: **Lower**

Actual: **33 ft.**

LTANKS:

Facility ID:	0807005
Site ID:	404317
Closed Date:	2008-12-04
Spill Number:	0807005
Spill Date:	2008-09-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2008-09-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-22
Spill Record Last Update:	2008-12-08
Spiller Name:	DON PALUMBO
Spiller Company:	UNKNOWN
Spiller Address:	231 EAST 11TH ST
Spiller County:	999
Spiller Contact:	DON PALUMBO
Spiller Phone:	(212) 254-9177
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	352757
DEC Memo:	"case closed. refer to spill #: 0806258."
Remarks:	"Callers company states the had a failure at above address. No product spill is known at this time."

All Materials:

Site ID:	404317
Operable Unit ID:	1160982

231 EAST 11TH ST (Continued) **S109207713**

Operable Unit:	01
Material ID:	2152171
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Facility ID:	0806258
Facility Type:	ER
Spill Number:	0806258
DER Facility ID:	352757
Site ID:	403529
DEC Region:	2
Closed Date:	2008-12-08
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2008-09-03
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2008-09-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-04
Spill Record Last Update:	2009-02-26
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MAX ISAACS
DEC Memo:	"09/04/08-Hiralkumar Patel. visited site. met Mr. Isaacs, property owner. site has one 550 gal tank in square concrete box. found minor leak on top of tank. found some oil stains on floor around tank. no petroleum odors inside basement. all lines runs aboveground and no sign of leak under visible portion of line location. asked Mr. Isaacs to test tank to confirm no leak from it. left message for Mr. Palumbo at Petro. 09/11/08-Hiralkumar Patel. spoke with Don at Petro. he mentioned that they never did any tank test. spoke with Mr. Isaacs. asked him to do tank test. Max Isaacs 231 East 11th Street New York, NY 10003 PH. (212) 254-9177 sent TTF letter to Mr. Isaacs. 09/23/08-Hiralkumar Patel. received call from Mr. Palumbo from Petro. they performed tank test last week but due to some difficulty they could not reach to final result. will go back on 09/30/08 for tank

231 EAST 11TH ST (Continued) **S109207713**

only test. 12/03/08-Hiralkumar Patel. spoke with Mr. Isaacs. he mentioned that Petro has installed two new tanks in Oct. 2008 as they were suspecting leak from tank. Mr. Isaacs asked to contact Don at petro. Mr. Isaacs's account #: 2551790 Don Palumbo Petro Oil Ph. (718) 628-3324 Fax (718) 628-3325 email: dpalumbo@petroheat.com left message for Don at Petro. 12/04/08-Hiralkumar Patel. received call from Don from Petro. he mentioned that home owner hired Advanced Tank Services for tank test and tank failed the test. then owner hired Petro to install new tanks. Petro hired Milro for tank installation. Milro abandoned old tank. Don doesn't have any report regarding abandonment method of old tank. Advanced tank services company Ph. (800) 440-8265 left message at ATS for tank test result. received call from Cathy from ATS. she mentioned that they were hired by Petro. during tank test they found dry leak in system. asked Kathy to submit tank test result. tank test failure reported by ATS. spill #: 0807005. received email from Laura Capilli from Advanced Tank Services with tank test result. according to the result, tank was empty during tank test and found tank system leaking. ATS recommends for isolation test, but no isolation test performed. Laura Capilli Advanced Tank Services Ph. (800) 440-8265 Fax (800) 303-5323 email: lcapilli@atsenvironmental.com Cathy Burke ATS email: cathy@atsenvironmental.com spoke with Anthony at Milro regarding abandonment of old tank. Anthony will call back with more information. spoke with Mr. Isaacs. explained him that based on tank test result, the Department requires isolation test and possible soil investigation, according to earlier letter dated 09/11/08. Mr. Isaacs will contact previous tank testing company and ask them to call back. spoke with Don at Petro regarding tank test result. white talking to Don, he mentioned that tank had about 40 inches of product in it and they transferred oil from tank into new tanks after installed. they installed tanks after findings failure. received call from Cathy from ATS. she mentioned that tank had oil in it when they tested it, but not empty. but due to configuration of pipe, they could not measure via stick and they didn't know whether petrometer was working or not. Cathy also mentioned that after installing new tanks, Milro abandoned old tank with sand without isolation test. 12/08/08-Hiralkumar Patel. received email from Cathy Burke from ATS. Cathy mentioned that they tested tank twice. at first time they tested tank system and tank system failed. then they tested tank only and found leak in tank. could not decide whether dry or wet leak. after first test, petro cut remote fill line and converted to direct fill. during second test, ATS measured product level via a direct fill port and measured about 40 inches of product (about 500 gal) in it. summary: - spill reported as found stain on concrete box on top (could be overfill) - tank system tested and found leaking - amount of product was not measured during first tank test due to no access for that - remote fill line removed and Petro installed new direct fill on tank - ATS tested tank only second time and found dry leak - ATS measures 40 inches of product (about 500 gal in 550 gal tank) - tank was in concrete box and has been abandoned based on available information and absence of any visible spill in basement during site visit, case closed."

Remarks: "The owner of the building, Max Isaacs told caller he thought he had an overfill on his 550 gallon tank. Caller saw old residue from a possible overfill or minor equipment failure. Caller will contact a tank co. for further testing. Any dry residue is contained in the tank vault."

231 EAST 11TH ST (Continued) **S109207713**

All Materials:

Site ID:	403529
Operable Unit ID:	1160225
Operable Unit:	01
Material ID:	2151370
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	403529
Operable Unit ID:	1160225
Operable Unit:	01
Material ID:	2151369
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BP874 **JOANNA / RESIDENTIAL TANK** **NY LTANKS** **S111836509**
SW **110 MERCER ST** **N/A**
1/4-1/2 **NEW YORK (MANHATTAN), NY**
0.387 mi.
2043 ft. **Site 3 of 3 in cluster BP**

Relative:
Lower

Actual:
30 ft.

LTANKS:

Facility ID:	1200725
Site ID:	463379
Closed Date:	2013-05-22
Spill Number:	1200725
Spill Date:	2012-04-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2012-04-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-23

JOANNA / RESIDENTIAL TANK (Continued) **S111836509**

Spill Record Last Update:	2013-05-22
Spiller Name:	Not reported
Spiller Company:	JOANNA
Spiller Address:	110 MURPHY ST
Spiller County:	999
Spiller Contact:	JOANNA
Spiller Phone:	212614-9717
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	417779
DEC Memo:	"called Bob(PTC)to get more information. Demar Plumbing repaired the Tank and it passed the test.Call:212-614-9717"
Remarks:	"test failure, retest planned"

All Materials:

Site ID:	463379
Operable Unit ID:	1213474
Operable Unit:	01
Material ID:	2211434
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BN875 **TTF** **NY LTANKS** **S121120195**
North **61 EAST 11TH STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.388 mi.
2051 ft. **Site 3 of 3 in cluster BN**

Relative: **Lower**
Actual: **38 ft.**

LTANKS:

Facility ID:	1706536
Site ID:	560854
Closed Date:	Not reported
Spill Number:	1706536
Spill Date:	2017-10-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2017-10-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2017-10-04

TTF (Continued) **S121120195**

Spill Record Last Update:	2018-01-12
Spiller Name:	BUCKWINDER AND WARREN
Spiller Company:	OWNERS
Spiller Address:	61 EAST 11TH STREET
Spiller County:	999
Spiller Contact:	NEIL TOMASETTI
Spiller Phone:	(718) 378-3000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	514469
DEC Memo:	"10/05/17-Hiralkumar Patel. alternate address: none no other spills found. PBS #: 2-064890. as per PBS record, the site has one (1) 2,000 gal #2 oil AST on saddles, in-service, installed in Dec. 1979. 2:50 PM:- spoke with Karen Reoch at property management office. she mentioned that the 2,000 gal tank is aboveground and encased in cement with weep holes. she stated that the tank has failed in a dry portion and there are no signs of release around the tank. the last oil delivery was in May 2017. asked Ms. Reoch to secure fill port to prevent further oil deliveries to the tank. Ms. Reoch mentioned that property owner has decided to replace the tank. 61 East 11 Street Corp. **property owner** c/o Buchbinder & Warren LLC. 1 Union Square West, 4th Floor New York, NY 10003 Attn.: Eric Ehrenhaus **property manager** Ph. (212) 243-6722 Ext. 284 email: eehrenhaus@buchbinderwarren.com Karen Reoch Ph. (646) 637-9019 email: kreoch@buchbinderwarren.com 3:06 PM:- sent TTF letter to Mr. Ehrenhaus requiring report submission by the end of 12/22/17. letter emailed to Mr. Ehrenhaus, Ms. Reoch and DEC Piper. case assigned to DEC Piper."
Remarks:	"2000 Gallon tank. Failed Tank test."

All Materials:

Site ID:	560854
Operable Unit ID:	1308843
Operable Unit:	01
Material ID:	2315862
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

876
West
1/4-1/2
0.392 mi.
2072 ft.

171 SULLIVAN ST
171 SULLIVAN ST
MANHATTAN, NY

NY LTANKS **S104877273**
NY Spills **N/A**

Relative:
Lower

Actual:
24 ft.

LTANKS:

Facility ID:	0009608
Site ID:	209542
Closed Date:	2002-04-09
Spill Number:	0009608
Spill Date:	2000-11-21
Spill Cause:	Tank Overfill

171 SULLIVAN ST (Continued) **S104877273**

Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-11-21
CID:	396
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-21
Spill Record Last Update:	2002-04-09
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	173742
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Con Ed e2mis #134483: GDS MECHANIC A SORRANO 11084 WAS CALLED TO LOCATION FOR A UNLOCATED 51. UPON ARRIVAL HE FOUND FUEL OIL ALL OVER THE BASEMENT FLOOR. OIL HAD ALREADY SEEPED INTO THE DRAIN. THE SUPER WAS HOSING SAME DOWN THE DRAIN. AT 1611 THE FD WAS CALLED TO LOCATION. THEY SHUT DOWN WATER TO THE BUILDING.CON ED LEAK TICKET NUMBER IS ML00012929.THERE IS APPROXIMATELY 5 GALLONS ON OIL ON THE FLOOR WHEN THE FD ARRIVED.THIS IS A THIRD PARTY SPILL. CON ED NOT INVOLVED IN SPILL.NOTIFIED CIG NATALE 16:58 BY LYLE SEAGRIFF #50868 INPUT BY LYLE SEAGRIFF. UPDATE - November 27, 2000 THIS IS NOT A CON EDISON INCIDENT. This spill was turned over to the New York City Fire Department for action. Changed Incident Type to Spill - Fuel Oil from Spill - Drip Water . Added 3P to the Short Description. Added Stop Date. Changed OPN STATUS to Closed . Added Resolved Date. Logger Gary Windman, Env. Coordinator, 75989. Logger Kenneth Heyman #96534 3/8/02 14:40 Update: I spoke to Lou Faro today and he advised me to submit to DEC for approval. I changed the Opn Staus to CLODE and removed the resolved time."
Remarks:	"con ed was doing an inspect. and saw the build super washing fuel oil down the drain...con ed called the fd and they responded. nfd. "

All Materials:

Site ID:	209542
Operable Unit ID:	831897
Operable Unit:	01
Material ID:	543545
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

171 SULLIVAN ST (Continued) **S104877273**

Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 0212366
Facility Type: ER
Spill Number: 0212366
DER Facility ID: 173742
Site ID: 209543
DEC Region: 2
Closed Date: 2006-10-16
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 3101
Spill Date: 2003-03-16
Investigator: qxabidi
Referred To: Not reported
Reported to Dept: 2003-03-16
CID: 297
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-03-16
Spill Record Last Update: 2006-10-16
Spiller Name: Not reported
Spiller Company: FERRANTINO OIL CO.
Spiller Address: Not reported
Spiller Company: 001
Contact Name: RICHARD SAUNDERS
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 3/17/2003-Vought-Called Ferrantino Oil and spoke with Roger Loughlin and crew is on-site who is cleaning spill with drysol. Spill came out top of tank. No sewers or drains affected and spill on concrete. Vought called Richard Saunders who is not at site today. Vought explained to Saunders that NYSDEC requires confirmation of cleanup from owner or manager. Saunders stated that he will call Tipple tommorrow with confirmation of cleanup. 05/18/06: This spill is transferred from Mr. Koon Tang to Q.Abidi. Called to Richard Saunders at (212)253-2530 left message to call me back. Also talked to Mr. Danis (Ferrantino oil co.) at (718)832-6700. He said that site is already cleaned. He will fax me confirmation of cleanup letter. -QA 06/21/06: Called Mr. Danis (Ferantino oil Company)at(718)832-6700 reminded him to send confirmation of clean up letter. -QA 06/23/06: Called to Mr. Danis and talked to Mr. Mike Taylor (Service Manager), Ferrantino Oil Company regarding spill. He said that he will find out the spill record and he will fax it to me. -QA 07/06/06: Called Danis and talked to Mike he said that he will send report to me in a week. -QA 07/20/06: Called to Mr. Danis and talked to Ms. Ethel She said she will convey my message to Mr. Danis and Mr. Mike regarding clean up confirmation letter. -QA 07/24/06: Mr. Anthony Lara (718)624-4824

171 SULLIVAN ST (Continued) **S104877273**

called me back and said spill is cleaned up. He will fax me confirmation of closing letter for the spill. -QA 09/11/06: Called Mike, Service Manager (Ferrantino Oil Company) at (718)832-6700 he said he will send report and a closing confirmation letter to close the spill as soon as possible. -QA 09/18/06: Called Mr. Mike he said as soon as hewill received papers . He will send it to me. -QA 10/11/06: Called Mr. Danis at (718)832-6700 he said he will find out from his Service Manager and he will call me back regarding spill. -QA 10/16/06: Called to Mr. Richard Saunders at (212)253-2530 and talked to owner Mrs. Maruska Saunders she said this spill is cleaned and she sold this property in February 2006. Received a closing confirmation letter from Mr. Mark Salamack (Petroleum Tank Cleaner)they emptied the tank and welded this opening closed. The oil dripped down the outside painted concrete surface of the tank jacket and onto the painted floor. This was cleaned up by the oil company (Ferrantino). The amount of resulting oil absorbent was a small amount and discarded with the household trash from the building.According to the information of Mr. Mark Salamack spill is cleaned. DEC staff closed the spill. -QA"

Remarks: "CALLER STATED A FILL PIPE LEAKED GOING INTO THE BUILDING, COMP SPOKE TO THE DRIVER, AND THE DRIVER REFUSED TO GIVE HIS NAME, BUT STATED THAT HE HAD CALLED FOR SOMEONE TO COME CLEAN UP THE SPILL, AND THEN TOOK OFF DOWN THE ROAD TO HIS NEXT STOP"

All Materials:

Site ID:	209543
Operable Unit ID:	863369
Operable Unit:	01
Material ID:	512106
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BO877 **ON PROPERTY** **NY LTANKS** **S120702926**
South **7 RIVINGTON ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.396 mi.
2089 ft. **Site 3 of 3 in cluster BO**

Relative: **Lower**
Actual: **41 ft.**

LTANKS:

Facility ID:	1700746
Site ID:	545768
Closed Date:	2017-05-24
Spill Number:	1700746
Spill Date:	2017-04-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	vszhune
Referred To:	Not reported

ON PROPERTY (Continued) **S120702926**

Reported to Dept:	2017-04-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2017-04-24
Spill Record Last Update:	2017-05-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DOUG
Spiller Phone:	(631) 727-2700
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	221800
DEC Memo:	"04/24/17-Hiralkumar Patel. alternate address: none no PBS record found. other spill # 9811442 was reported on 12/11/1998 due to 40 gal #2 fuel oil spill. case closed. 2:55 PM:- spoke with TJ. he mentioned that they attempted to test a 1,500 gal AST encased in concrete, but could not build pressure. 2:56 PM:- spoke with Doug at Eastern Env. he mentioned that as per the owner's representative, site has 1,000 gal tank, but FDNY record shows 1,500 gal tank. he mentioned that leak is suspected in vent or remote fill line. informed Doug that isolation test must be conducted immediately to confirm tank's integrity for continuous use of remaining oil (no further deliveries until system is fixed and tested tight), otherwise tank system must be pumped out immediately. 3:06 PM:- left message for Joshua Martin, property manager. 7 Rivington LLC. **property manager** c/o Veracity Real Estate Management 199 Lafayette Street, Suite # 5D New York, NY 10012 Attn.: Joshua Martin PH. (212) 966-6811 (646) 267-4065 email: Joshua@veracityrem.com 3:27 PM:- received message from Mr. Martin. 3:31 PM:- spoke with Mr. Martin. asked him not to deliver any more oil to the leaking tank system until it is fixed and tested tight. also asked him to pump out tank by the end of tomorrow unless dry leak in the system. 3:44 PM:- sent TTF letter to Mr. Martin and asked him to submit report by the end of 05/31/17. letter emailed to Mr. Martin and Doug. case assigned to DEC Zhune. 04/25/17-Hiralkumar Patel. 12:38 PM:- received call from Doug. he mentioned that the isolation test will be conducted tomorrow morning. 5/24/17-Louis J. Baselli from Eastern Environmental emailed the report. The letter stated that On behalf of GRS/Corteq, Eastern Environmental Solutions, Inc., (Eastern)has performed tank tightness testing in conformance with USEPA and 6NYCRR test criteria for 1,100 gallon capacity #2 fuel oil storage tank. On April 24, 2017, the New Yor State Department of Environmental Conservation (NYSDEC) was contacted regarding a tank tightness testing failure occurring at 7 Rivington Street, The testing was performed in order to determine a cause for the reported tank equipment failure. On April 24, 2017 a tank tightness test was performed on the fuel oil and oil delivery system. A tank testing failure was recorded. On April 26, 2017 a second tank tightness test was performed after a determination was made that leakage was coming from the tank vent line. The second test was perfomed with the oil

ON PROPERTY (Continued) **S120702926**

tank isolated from the vent line. The tank passed the tank testing criteria. On May 3, 2017, a third tank test was performend for the entire tank delivey sytem including all lines after the leaking vent line was repaired by Eastern Technicians. The tank system passed the tank tightness test. Spill Closed."

Remarks: "tank test failure"

All Materials:

Site ID:	545768
Operable Unit ID:	1293928
Operable Unit:	01
Material ID:	2299904
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BQ878 **96 NORTH 1ST STREET** **NY VCP** **S118943407**
SE **96 NORTH 1ST STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.398 mi.
2103 ft. **Site 2 of 2 in cluster BQ**

Relative:
Lower

Actual:
32 ft.

VCP NYC:

Project ID:	15CVCP013K
Project Name:	96 NORTH 1ST STREET
Project Address:	96 NORTH 1ST STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	15CVCP013K
File Name:	2014-08-15.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP013K/2014-08-15.15CVCP013K.report.RIR_Revised.Hydrotech.pdf

Project ID:	15CVCP013K
File Name:	2016-06-13.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP013K/2016-06-13.15CVCP013K.report.96_N_1st_RAWP_DRAFT.pdf

Project ID:	15CVCP013K
File Name:	2016-06-14.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP013K/2016-06-14.15CVCP013K.96_North_1st_Street_Factsheet-1.pdf

Project ID:	15CVCP013K
File Name:	2016-06-14.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP013K/2016-06-14.15CVCP013K.96_North_1st_Street_Translated_Factsheet-1.pdf

Project ID:	15CVCP013K
File Name:	2016-06-14.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/1

96 NORTH 1ST STREET (Continued) **S118943407**

5CVCP013K/2016-06-14.15CVCP013K.96_North_1st_Street_Translated_CPS.pdf

---

BR879 **APT. BUILDING TTF** **NY LTANKS** **S109829603**
NE **222 EAST 12TH ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.400 mi.
2110 ft. **Site 2 of 3 in cluster BR**

Relative: **Lower**
Actual: **34 ft.**

LTANKS:

Facility ID:	0905974
Site ID:	418269
Closed Date:	2009-08-27
Spill Number:	0905974
Spill Date:	2009-08-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	2009-08-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-08-21
Spill Record Last Update:	2009-09-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	WONG
Spiller Phone:	(212) 966-6699
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	367385
DEC Memo:	"08/21/09- Zhune spoke to TJ from Dry as Bone. He said the tank failed the test with a dry leak. Probably the line that goes to the side walk is leaking he will come back next week to check it. He did not see any spill when test was done. 8/27/2009 Sangesland spoke to property manager Alana Barran - She has a hearing with John Urda on Friday Aug 28th. ***Is this a PBS Site?*** Dry As aBone says it's a 1080 gal tank??? TTF letter sent to: Alana Barran 109 Lafayette St - Suite 302 New York, NY 10013 8/27/09 - Raphael Ketani. This case is associated with the earlier spill case #0813565. The earlier case involved a fill box and fill pipe leak that was supposedly repaired. However, during an inspection made by me months ago with a PID meter, elevated total VOC detections were found at the bottom of the tank vault and at the top of a covered sump. This prompted a request by me to the owners to investigate the tank. They didn't respond for along time and so John Urda of the Office of General Counsel was asked to become involved. He sent correspondences to the owners. The owners

APT. BUILDING TTF (Continued) **S109829603**

hired Dry AS A Bone to test the tank system and that is when the leak was found. I am closing the spill case and referring it to the earlier one for the site, spill #0813565. "

Remarks: "1080 gal vaulted tank"

All Materials:

Site ID:	418269
Operable Unit ID:	1174455
Operable Unit:	01
Material ID:	2166812
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

---

880 WNW 1/4-1/2 0.401 mi. 2115 ft. **APARTMENT** **NY LTANKS** **S109829738**
126 MACDOUGAL ST **N/A**
MANHATTAN, NY

Relative: Lower

Actual: 22 ft.

LTANKS:

Facility ID:	0904868
Site ID:	417080
Closed Date:	2011-05-25
Spill Number:	0904868
Spill Date:	2009-07-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2009-07-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-07-27
Spill Record Last Update:	2011-05-25
Spiller Name:	Not reported
Spiller Company:	unk
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MARLIN JOESPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2

APARTMENT (Continued) **S109829738**

DER Facility ID: 366154
DEC Memo: "07/30/09 PTC working on the tank removal.UST #2 oil, 550 gallon, not in use, as of now.(sr) 09/10/09 CSL sent out to 126 Macdougal Holdings LLC 126 Macdougal Street New York, NY 10012(sr) 10/26/09 Letter returned undelivered.Letter resent to 126 Macdougal Holdings LLC 100 Cedarhurst Avenue Cedarhurst, NY 11511 Attn: Andrew Kleiman(sr) 11/13/09 Rec'd response letter from Barberry Rose Mgmt. Co. Inc., waiting DOB permit to replace the tank.(sr) 04/09/10 PTC performed tightness testing.Tank failed the test.Left messege for Mordy Oberstein at BRM to follow up on the investigation around the tank.(sr) 09/08/10 Spoke with Mordy Oberstein of BRM.He could not tell me whether soil testing around the tank was performed or not.I explained it to him that subsurface investigation is required since the tank was underground and it failed the test.Unsure if the tank passed the subsequent tightness test. Letter was sent out again to(requiirng subsurface investigation) Barberry Rose Management Company, Inc 100 Cedarhurst Avenue, Suite 202 Cedarhurst, NY 11516 Attn: Mordy Oberstein, Chief Operations Officer CERTIFIED MAIL-70090820000086871293 05/25/11 Rec'd soil analytical data.Results are within acceptable range.Soil samples were taken through the bottom of the tank. Letter from PTC in edocs.Tank was closed in place.Case closed.(sr)"
Remarks: "disconected tank did tank only test the tank failed, tank is 550 gallons, tank will be pumped and retested."

All Materials:
Site ID: 417080
Operable Unit ID: 1173334
Operable Unit: 01
Material ID: 2165235
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

881
North
1/4-1/2
0.401 mi.
2116 ft.

APARTMENT COMPLEX - TTF **NY LTANKS** **S102555800**
11 EAST 10 TH STREET **N/A**
NEW YORK, NY

Relative:
Lower

Actual:
32 ft.

LTANKS:
Facility ID: 9612302
Site ID: 161486
Closed Date: 2015-02-19
Spill Number: 9612302
Spill Date: 1997-01-14
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: HRPATEL

APARTMENT COMPLEX - TTF (Continued) **S102555800**

Referred To:	Not reported
Reported to Dept:	1997-01-14
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-14
Spill Record Last Update:	2015-04-09
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	JERRY SHEA
Spiller Phone:	(212) 673-0964
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	136350
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE Transferred from Engelhardt to Tibbe on 1/15/97. Transferred for closeout review to M Johnson 7/29/05. 6/15/06 Transferred for closure review to T Knizek. 08/13/12 - LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo 1/3/13 AFrischeisen intern Previous TTF letter sent December 13, 2012 was returned as undeliverable. Sent new TTF letter with revised address and upped to eDocs. 10/10/14-Hiralkumar Patel. reviewed available information for DEC DeMeo. alternate address: none no PBS or other spill record found. the subject spill was reported as 5,000 gal tank failed the test. but no PBS record found. its a three story building, with possible basement, at the site. 11 East 10th Street, LLC. **property owner** 2/12/15 TJD Spill reassigned from DeMeo to Patel 02/19/15-Hiralkumar Patel. went to site for inspection, but no access available. its three story building with basement. no fill or vent pipe observed. searched NYC DOB database. as per NYC DOB, a permit was approved on 08/04/1997 for alteration and enlargement of a single family mixed use building. as per NYC ACRIS, current owner purchased the subject site in May 2005. 11 East 10th Street LLC. **property owner** 11 East 10th Street New York, NY 10003 Attn.: Hilary Rubenstein Hatch PH. (212) 529-7906 9:39 AM:- left message for Ms. Hatch, who is listed as property owner in last DOB permit application. 1:22 PM:- received call from Ms. Hatch. informed her about open spill case. she confirmed that there is no oil tank in the building and they never noted any petroleum odors or signs of petroleum release in the building. in accordance with R2 TTF closure protocol, this spill is being closed due to no indication of a current release, no information indicating that there may have been a historical release, and no information that this tank test failure will be an issue in the future."
Remarks:	"TANK FAILED THE TEST"

All TTF:

Facility ID:	9612302
Spill Number:	9612302
Spill Tank Test:	1544963
Site ID:	161486

APARTMENT COMPLEX - TTF (Continued) **S102555800**

Tank Number:	1
Tank Size:	5000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BS882 **77 EAST 12 OWNERS INC** **NY LTANKS** **U003241818**
NNE **77 EAST 12TH STREET** **NY UST** **N/A**
1/4-1/2 **NEW YORK, NY 10003**
0.406 mi.
2142 ft. **Site 1 of 3 in cluster BS**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	1411008
Site ID:	504752
Closed Date:	2015-05-19
Spill Number:	1411008
Spill Date:	2015-02-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2015-02-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-02-19
Spill Record Last Update:	2015-10-28
Spiller Name:	Not reported
Spiller Company:	LISA MORETTI
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	LISA MORETTI
Spiller Phone:	(212) 473-3813
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	459609
DEC Memo:	"02/20/15-Hiralkumar Patel. alternate address: 65-77 East 12th Street, 120-130 4th Avenue PBS #: 2-320722. as per PBS record, the site has one (1) 12,000 gal #6 oil UST, in-service, installed in May 1964. no other spills found. 12:25 PM:- spoke with John at AARCO.

77 EAST 12 OWNERS INC (Continued) **U003241818**

they tested 15,000 gal out-of-service UST. at the time of the test, the tank had about 3,000 gal #6 oil in it. John mentioned that they could not confirm type of leak (dry or wet) as the system did not hold any pressure. 12:30 PM:- spoke with John, building super. he mentioned that a new gas boiler was installed about three years ago and the oil tank is out-of-service since then. the tank is located under the basement floor. now, as part of refinance process, building owner has decided to close the tank in-place. asked John to seal the fill port to prevent any misdelivery to the leaking tank system. John mentioned that AARCO Env. will do tank abandonment. 77 E. 12 Owners, Inc. **property owner** c/o Douglas Elliman Property Management 675 3rd Avenue, 5th Floor New York, NY 10017 Attn.: Lisa Moretti Ph. (212) 473-3813 (212) 370-9200 email: lisa.moretti@ellimanpm.com John **building super** PH. (914) 625-0994 Douglas Elliman after discussion, case assigned to DEC Mahat prior to issuing any letter. 3/9/15: Mahat DEC Mahat received a call from Ms. Hegginson (Project Manager - ARCO Environmental) mentioning that they will be taking three samples along the line of the tank for the process of abandonment. A complete closure reprot will be provided to the Department as it is ready. Lab reprot was provided, and based on the GW Lab analysis, no contmaination above the Guidance value was observed. Tank will be aboandon in place. 5/19/15: Mahat DEC Mahat received a closure report and it has been uploaded on D2 for reference. Based on the laboratory results and report, the Department does not warrant any further investiagation. Hence, the spillcase will be closed in DEC Spill Database. "

Remarks: "tank test fail"

All Materials:

Site ID:	504752
Operable Unit ID:	1254089
Operable Unit:	01
Material ID:	2256491
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

UST:

Id/Status:	2-320722 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	585265.77804
UTM Y:	4509628.85144
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14873
Affiliation Type:	Facility Owner
Company Name:	77 EAST 12TH OWNERS INC
Contact Type:	Not reported

77 EAST 12 OWNERS INC (Continued) **U003241818**

Contact Name:	Not reported
Address1:	77 EAST 12TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 370-9200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-04-23

Site Id:	14873
Affiliation Type:	Mail Contact
Company Name:	77 EAST 12 OWNERS CORPORATION
Contact Type:	Not reported
Contact Name:	PAT PETTWAY-BROWN
Address1:	DOUGLAS ELLIMAN PROPERTY MGMT.
Address2:	675 THIRD AVENUE, 5TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 350-2846
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-06-29

Site Id:	14873
Affiliation Type:	Facility Operator
Company Name:	77 EAST 12 OWNERS INC
Contact Type:	Not reported
Contact Name:	FRANK FIGUEROA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 673-6024
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	14873
Affiliation Type:	Emergency Contact
Company Name:	77 EAST 12TH OWNERS INC
Contact Type:	Not reported
Contact Name:	GJON GJELAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

77 EAST 12 OWNERS INC (Continued) **U003241818**

Country Code:	999
Phone:	(212) 673-6024
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-09-12

Tank Info:

Tank Number:	072
Tank ID:	19768
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	12000
Install Date:	05/17/1964
Date Tank Closed:	03/16/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
H99 - Tank Leak Detection - Other

BS883 **X** **NY LTANKS** **S105998660**
NNE **112 4TH AVE** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.407 mi.
2149 ft. **Site 2 of 3 in cluster BS**

Relative: **Lower**
Actual: **40 ft.**

LTANKS:

Facility ID:	0300357
Site ID:	107845
Closed Date:	2004-10-18
Spill Number:	0300357
Spill Date:	2003-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3

X (Continued) **S105998660**

Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2003-04-10
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-10
Spill Record Last Update:	2004-10-18
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	HOWARD LANDMAN MGT CO
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	94812
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER Tank test failure letter was prepared and sent 4/10/03. PBS # 2-602443. 11/14/2003-Vought-Siren Management Corp (Howard Landman 212-483-0700) review of passing tank and system test results after the needed repairs were made . Vought called Landman to find out extent of repairs and for written no contamination statement as per tank test failure letter and left message to return call to DEC. 1/7/04-Vought-Spill transferred from Vought to Austin. 1/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 10/18/04 - Sawyer - Received a detailed description of the repairs done to the tank by ABC Tank Repair & Lining. Howard Landman of Siren Management provide the documentation. No further action required. Closed."
Remarks:	""

All TTF:

Facility ID:	0300357
Spill Number:	0300357
Spill Tank Test:	1528251
Site ID:	107845
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

X (Continued) **S105998660**

All Materials:

Site ID:	107845
Operable Unit ID:	868654
Operable Unit:	01
Material ID:	508438
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

884 **THE DERMOT COMPANY** **NY LTANKS** **U003383742**
NE **229 EAST 12TH STREET** **NY AST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.408 mi.
2154 ft.

Relative: **Lower**

Actual: **35 ft.**

LTANKS:

Facility ID:	0801496
Site ID:	397432
Closed Date:	2009-01-20
Spill Number:	0801496
Spill Date:	2008-05-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2008-05-07
CID:	404
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-07
Spill Record Last Update:	2009-01-20
Spiller Name:	CARMON SANTIAGO
Spiller Company:	APPT BUILDING
Spiller Address:	229 EAST 12TH STREET
Spiller County:	001
Spiller Contact:	CARMON SANTIAGO
Spiller Phone:	(646) 673-6714
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	346847
DEC Memo:	"6/16/08 bf: sent ttf to: Carmen Santiago The Dermot group, Inc. 320 West 57th Street, 5th Floor New York, NY 10019 1/20/09 Steve braun of Approved Oil hand delivered letter. Manhole cover was regasketed. No

THE DERMOT COMPANY (Continued) **U003383742**

evidence of oil relaese was found. Tank passed retest on 1/14/09. NFA. bf"
Remarks: "PBS No: 2-061832 dry portion leak"

All TTF:
Facility ID: 0801496
Spill Number: 0801496
Spill Tank Test: 2486049
Site ID: 397432
Tank Number: 1
Tank Size: 4000
Material: 0001
EPA UST: Not reported
UST: False
Cause: 99
Source: 99
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 397432
Operable Unit ID: 1154396
Operable Unit: 01
Material ID: 2145191
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-061832
Program Type: PBS
UTM X: 585547.02665
UTM Y: 4509474.11161
Expiration Date: 12/13/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 1122
Affiliation Type: Facility Operator
Company Name: 229 E 12TH ST
Contact Type: Not reported
Contact Name: ELVIR PALIC
Address1: Not reported
Address2: Not reported

THE DERMOT COMPANY (Continued) **U003383742**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 583-6551
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2017-04-20

Site Id:	1122
Affiliation Type:	Emergency Contact
Company Name:	229-231 EAST 12TH ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	MICKEY NAPOLITANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 624-4300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-01-05

Site Id:	1122
Affiliation Type:	Mail Contact
Company Name:	BLDG MANAGEMENT CO., INC.
Contact Type:	Not reported
Contact Name:	ABBY MENACHEM
Address1:	417 FIFTH AVENUE
Address2:	4TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 624-4300
EMail:	ABBY@BLDG.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-14

Site Id:	1122
Affiliation Type:	Facility Owner
Company Name:	229-231 EAST 12TH ASSOCIATES LLC
Contact Type:	SENIOR VICE PRESIDENT
Contact Name:	MICKEY NAPOLITANO
Address1:	417 5TH AVE, 4TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 624-4300
EMail:	Not reported

THE DERMOT COMPANY (Continued) **U003383742**

Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-14

Tank Info:

Tank Number:	001
Tank Id:	2158
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
J05 - Dispenser - On Site Heating System (Supply/Return)

Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	11/14/2017
Material Name:	#2 fuel oil (on-site consumption)

BT885 **68-70 SPRING STREET** **NY VCP** **S121796995**
SW **68-70 SPRING STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.409 mi.
2160 ft. **Site 1 of 2 in cluster BT**

Relative:
Lower

Actual:
33 ft.

VCP NYC:

Project ID:	18CVCP029M
Project Name:	68-70 SPRING STREET
Project Address:	68-70 SPRING STREET
Borough:	MANHATTAN

VCP NYC:

Project ID:	18CVCP029M
File Name:	2017-11-03.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/18CVCP029M/2017-10-02.18TMP0146M.RIR Phase II Report.RIRPhase II

68-70 SPRING STREET (Continued) **S121796995**

Report.pdf

Project ID: 18CVCP029M
File Name: 2017-11-03.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/18CVCP029M/2017-10-27.18TMP0146M.RAPRAWP.Draft Text Figures and Appendices.pdf

Project ID: 18CVCP029M
File Name: 2017-11-03.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/18CVCP029M/2017-10-30.18TMP0146M.68-70_Spring_Street_Fact Sheet-1.pdf

Project ID: 18CVCP029M
File Name: 2017-11-03.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/18CVCP029M/2017-11-03.18TMP0146M.68-70_Spring_Street_Fact Sheet-1_Translation.pdf

Project ID: 18CVCP029M
File Name: 2017-11-03.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/18CVCP029M/2017-11-03.18TMP0146M.68-70_Spring_Street_CPS_Translation.pdf

---

BU886 **SPILL NUMBER 0106344** **NY LTANKS** **S105135148**
NNW **20 5TH AV** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.409 mi.
2162 ft. **Site 1 of 3 in cluster BU**

Relative: **Lower**
Actual: **27 ft.**

LTANKS:

Facility ID:	0106344
Site ID:	78648
Closed Date:	2002-05-15
Spill Number:	0106344
Spill Date:	2001-09-17
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2001-09-17
CID:	201
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-17
Spill Record Last Update:	2002-05-15
Spiller Name:	CALLER
Spiller Company:	HESS

SPILL NUMBER 0106344 (Continued) **S105135148**

Spiller Address:	420 HOOK RD
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	73169
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD Home owner hired Eastmond to do the cleaaup."
Remarks:	"CUSTOMER GAVE THE DRIVER THE WRONG AMOUNT IN THE TANK. APPROX 50 GLS OG OIL SPILLED IN AN ALLEYWAY. CONTAINED. CLEAN UP WILL BE TAKEN CARE OF BY HOMEOWNER."

All Materials:

Site ID:	78648
Operable Unit ID:	843258
Operable Unit:	01
Material ID:	531208
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BT887 **66 CROSBY ST/MANHATTAN** **NY LTANKS** **S102671356**
SW **66 CROSBY STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.410 mi.
2164 ft. **Site 2 of 2 in cluster BT**

Relative: **Lower**
Actual: **31 ft.**

LTANKS:

Facility ID:	8809170
Site ID:	114804
Closed Date:	1989-02-27
Spill Number:	8809170
Spill Date:	1989-02-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-02-27
SWIS:	3101
Investigator:	JCGRATHW
Referred To:	Not reported
Reported to Dept:	1989-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-02-28
Spill Record Last Update:	2004-09-30

66 CROSBY ST/MANHATTAN (Continued) **S102671356**

Spiller Name:	Not reported
Spiller Company:	SIGRAM MARMIS OIL CO
Spiller Address:	290 LOCUST AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	100107
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GRATHWOL "
Remarks:	"NYC EMERGENCY MANAGEMENT OFFICE NOTIFIED, CLEAN UP CREW ON SCENE."

All Materials:

Site ID:	114804
Operable Unit ID:	925071
Operable Unit:	01
Material ID:	453931
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BR888 **CAPRI APARTMENTS** **NY LTANKS** **S105997410**
NE **232 EAST 12TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.410 mi.
2166 ft. **Site 3 of 3 in cluster BR**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Facility ID:	0208805
Site ID:	115105
Closed Date:	2004-07-22
Spill Number:	0208805
Spill Date:	2002-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2004-07-22

CAPRI APARTMENTS (Continued) **S105997410**

Spiller Name:	PETER DAVIS
Spiller Company:	CAPRI APARTMENTS
Spiller Address:	232 EAST 12ST ST
Spiller County:	001
Spiller Contact:	PETER DAVIS
Spiller Phone:	(516) 767-7252
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	100313
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 11/25/02 - Austin - TTF letter sent to Peter Davis 1/7/04-Vought-Spills transferred from Vought to Austin. 1/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 7/22/04 - Sawyer - Called Peter Davis of Capri management and he will forward repair documentation to the Department. Received information from Mr. Davis concerning PTC repairs. Air leak was above the Product line. Closed."
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION. TANK TO BE UNCOVERED/EVALUATED AND RETESTED."

All TTF:

Facility ID:	0208805
Spill Number:	0208805
Spill Tank Test:	1527757
Site ID:	115105
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	115105
Operable Unit ID:	861996
Operable Unit:	01
Material ID:	515800
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BU889 **24 FIFTH AVE** **NY LTANKS** **S105135133**
NNW **24 5TH AVE** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.411 mi.
2172 ft. **Site 2 of 3 in cluster BU**

Relative: **Lower**

Actual: **28 ft.**

LTANKS:

Facility ID:	0106144
Site ID:	193832
Closed Date:	2003-04-28
Spill Number:	0106144
Spill Date:	2001-09-10
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-09-10
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-10
Spill Record Last Update:	2003-04-28
Spiller Name:	OWNER
Spiller Company:	NY URBAN PROPERTY MGMT
Spiller Address:	24 5TH AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	161562
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO DEC Duty Officer Sigona received a call from Peter Peracio on April 4, 2003 regarding the status of the cleanup. He said the contractor performed the cleanup and wanted to know how to close the spill case. DEC Sigona requested that the documentation be submitted to DEC Demeo for review for possible NFA letter. 4/28/03 TJD Disposal manifest submitted. No further action required."
Remarks:	"SPILL TO CONCRETE FLOOR. CLEANUP STARTED."

All Materials:

Site ID:	193832
Operable Unit ID:	844511
Operable Unit:	01
Material ID:	568801
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	G
Recovered:	.00

24 FIFTH AVE (Continued) **S105135133**

Oxygenate: Not reported

SPILLS:

Facility ID:	0205706
Facility Type:	ER
Spill Number:	0205706
DER Facility ID:	349957
Site ID:	70507
DEC Region:	2
Closed Date:	2002-09-03
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	2002-09-01
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-09-02
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-02
Spill Record Last Update:	2008-07-03
Spiller Name:	CALLER
Spiller Company:	Not reported
Spiller Address:	24 5TH AVE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 9/3/02 TJD Demeo spoke with Mr. Shaw who indicated spill was from an old personal thermometer. All mercury was reported to have been recovered. Spill closed"
Remarks:	"mercury from a thermometer - caller attempted to clean the best he could - req callback to number above or below 718 3433586"

All Materials:

Site ID:	70507
Operable Unit ID:	858264
Operable Unit:	01
Material ID:	519904
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

24 FIFTH AVE (Continued) **S105135133**

Facility ID:	9514312
Facility Type:	ER
Spill Number:	9514312
DER Facility ID:	66899
Site ID:	70508
DEC Region:	2
Closed Date:	1996-01-09
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	3101
Spill Date:	1996-02-09
Investigator:	LUCE
Referred To:	Not reported
Reported to Dept:	1996-02-09
CID:	311
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-09
Spill Record Last Update:	1996-02-21
Spiller Name:	UNK
Spiller Company:	OWNERS INCORP
Spiller Address:	24 5TH AVE
Spiller Company:	001
Contact Name:	UNK
DEC Memo:	""
Remarks:	"caller states driver was directed to the wrong tank by super of the building. started to fill tank and observed overflow. "

All Materials:

Site ID:	70508
Operable Unit ID:	1028862
Operable Unit:	01
Material ID:	354441
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	1212649
Facility Type:	ER
Spill Number:	1212649
DER Facility ID:	66899
Site ID:	475801
DEC Region:	2
Closed Date:	2013-01-23
Spill Cause:	Equipment Failure

24 FIFTH AVE (Continued) **S105135133**

Spill Class:	Not reported
SWIS:	3101
Spill Date:	2012-11-27
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2012-11-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-27
Spill Record Last Update:	2013-01-29
Spiller Name:	Not reported
Spiller Company:	24 5TH AVE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MARC SALAMACK
DEC Memo:	"11/28/12-Hiralkumar Patel. the spill report received yesterday afternoon. DEC Steve spoke with property manager yesterday evening and asked to hire contractor for cleanup. this morning, Steve received email from Mark (PTC) including pics of impacted basement floor. Mark mentioned in email that PTC was hired to pump out leaking tank and to set up temporary tanks, but has not got authorization for cleanup. so Steve asked to inspect the site. 10:06 AM:- spoke with Mark. he mentioned that PTC was hired to pump out tank and install temporary tanks, but were not authorized to do spill cleanup in basement. PTC crew at site right now. he will talk to his crew member and will call back with update. 10:09 AM:- received call from Mark. he confirmed with his crew that no cleanup in progress. after that he spoke with building super who was under the impression that PTC was going to cleanup the spill also. as Mark did not got signed authorization, he asked super to signed work proposal. Mark will call back with update. 10:31 AM:- spoke with Mark. he just got fax authorizing cleanup. PTC crew will do cleanup. alternate addresses: 26 5th Ave, 1-9 West 9th Street other spills: 9514312, 0106144, 0205706, 0610334 PBS #: 2-359041. as per PBS record, the site has one 10,000 gal #6 oil AST and one 15,000 gal #6 oil AST. both tanks are in-service and are located in subterranean vault with access. both tanks were installed in Jan. 1982. 24 Fifth Onwers Inc. **property owner** c/o Douglas Elliman Property Management **management office** 675 3rd Avenue New York, NY 10017 Attn.: Joanna Soto **property manager** Ph. (212) 473-6877 Robert Rodriguez **building super** Ph. (212) 473-6877 (O) (917) 518-2272 (C) 10:55 AM:- spoke with Robert Rodriguez, building super. he mentioned that the site has two tanks (one 10,000 gal and one 15,000 gal), but only 10,000 gal was in-service. the 15,000 gal tank is not in use for some time as something wrong (oil freezes inside) with the tank. Mr. Rodriguez does not know when was the last delivery to 15,000 gal tank. currently, the 10,000 gal tank is leaking from bottom. bottom of 10,000 gal tank touches the floor. he is not sure about location of 15,000 gal tank (either on floor or saddles). 3:35 PM:- visited site.

24 FIFTH AVE (Continued) **S105135133**

met Mr. Rodriguez. PTC crew was on-site installing temporary #2 oil tank on street. vac truck also at the site. inspected boiler/tank room in basement. the site has two tanks: one 10,000 gal (east-side tank) and one 15,000 gal (west-side tank). both tanks are aboveground in separate vaults with access, located in the boiler room. the tank vaults are located under the sidewalk. Mr. Rodriguez mentioned that the 15,000 gal tank is not in service for at least last 7 years since he is working and it only contains sludge. there are separate fill ports/vent pipes for both tanks. the fill ports are covered in fill boxes. fill box for 15,000 gal tank is covered with dirt and the fill port was not visible. Mr. Rodriguez mentioned that they check tank vault everyday. during inspection yesterday, they noticed oil on tank room floor. so they opened a small hole at the bottom of tank vault, in boiler room and oil started flowing in boiler room. the 10,000 gal tank will be removed and a new #4 oil tank will be installed. also, building engineers are working on natural gas heating system design. there are total 420 residential units in building. Mr. Rodriguez mentioned that there is no odor complaint from any resident. asked Mr. Rodriguez to secure both fill boxes to prevent any misdelivery. 11/29/12-Hiralkumar Patel. 11:44 AM:- left message for Mr.Rodriguez and asked him to call for site inspection, once leaking tank removed from site. 11:46 AM:- spoke with Mark. asked him about tank removal schedule. he mentioned that owner is working on inspecting tank for possible repair. asked him to call for inspection, once tank room floor is cleaned. 11/30/12-Hiralkumar Patel. 9:45 AM:- received message from Mark. they cleaned tank room. 12/04/12-Hiralkumar Patel. 10:00 AM:- visited site. met Mr. Rodriguez. could not inspect tank room due to limited access. Mr. Rodriguez mentioned that the 10,000 gal tank will be removed and property manager/owner are currently reviewing cost estimate. asked him to call for site inspection, once tank removed. 12/12/12-Hiralkumar Patel. 2:20 PM:- received message from Mark. PTC got approval and currently they are removing the tank. they will do further cleanup once tank steel is out of the room. DEC Sharif will visit site on 12/14/12, if possible. 12/19/12 I stopped by the site as per a request from Kumar Patel on 12/14/2012 PM.The 10,000 gallon tank has been taken out, contaminated debris, metal plate left in the tank room. Further clean up will be performed as the management told me.(sr) 12/27/12-Hiralkumar Patel. 11:53 AM:- spoke with Mr. Rodriguez. tank is completely removed. scheduled a site inspection tomorrow morning. 12/28/12-Hiralkumar Patel. 9:15 AM:- went to site for tank room inspection, but tank room is not completely cleaned. 01/07/13-Hiralkumar Patel. 11:20 AM:- left message for Mart at PTC. 11:22 AM:- left message for Mr. Rodriguez. 11:23 AM:- left message for Ms. Soto. 11:24 AM:- received call from Mr. Rodriguez. he mentioned that PTC crew has removed remaining stuff from tank room floor. 1:56 PM:- received call from Mark from site. he mentioned that all the debris have been removed from the tank room floor and floor was found in good condition. he also mentioned that portion of tank room floor, where the tank was located, is about 4 inches higher than remaining floor. Mark confirmed some stains on the floor which will be powerwashed in couple of days. Mark will call back once floor is powerwashed. 01/16/13-Hiralkumar Patel. 4:10 PM:- visited site. inspected tank room. tank room floor found in good condition. found oil stains on floor that will be powerwashed. 01/23/13-Hiralkumar Patel. 2:30 PM:- visited site. inspected tank room floor which found in good condition. some oil stains on floor. based on available

24 FIFTH AVE (Continued) **S105135133**

information, case closed."
Remarks: "cleanup pending"

All Materials:
Site ID: 475801
Operable Unit ID: 1225642
Operable Unit: 01
Material ID: 2222926
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

---

890 **SPILL NUMBER 0307474** **NY LTANKS** **S106000190**
ENE **305 EAST 11TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.412 mi.
2178 ft.

Relative: LTANKS:
Lower
Actual: Facility ID: 0307474
28 ft. Site ID: 131118
Closed Date: 2004-01-09
Spill Number: 0307474
Spill Date: 2003-10-15
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2003-10-15
CID: 207
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-10-15
Spill Record Last Update: 2004-01-09
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: REX HARRIS
Spiller Phone: (212) 727-8208
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 112965
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

SPILL NUMBER 0307474 (Continued) **S106000190**

SANGESLAND TTF LETTER SENT TO: Highmount Associates 305A West 19th St NY, NY 10011 1/9/2004 Sangesland received a letter from Emor Management Inc. stating that the faulty gasket was replaced and a second tank test was performed in which the tank passed. Receipt for the tank repair and a copy of the passing tank test. Spill Closed"

Remarks: "tank contained #4 oil "

All TTF:

Facility ID:	0307474
Spill Number:	0307474
Spill Tank Test:	1528738
Site ID:	131118
Tank Number:	1
Tank Size:	3500
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

---

891 WSW 1/4-1/2 0.414 mi. 2184 ft. **APARTMENT BUILDING 159 PRINCE STREET NEW YORK, NY** **NY LTANKS** **S107410739 N/A**

Relative: Lower

Actual: 19 ft.

LTANKS:

Facility ID:	0507990
Site ID:	353498
Closed Date:	2006-09-25
Spill Number:	0507990
Spill Date:	2005-10-03
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-10-04
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-04
Spill Record Last Update:	2006-09-25
Spiller Name:	CHRIS LEAHY

APARTMENT BUILDING (Continued) **S107410739**

Spiller Company:	APARTMENT BUILDING
Spiller Address:	159 PRINCE STREET
Spiller County:	001
Spiller Contact:	CHRIS LEAHY
Spiller Phone:	(212) 777-8838
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	300837
DEC Memo:	"10/05/04-Vought-Spoke with Jim Melnick and owner was not sure if he wanted to abandon, remove tank or leave it in place. If tank passes test he will leave it in place for possible future use. ProTest will reseal manhole, plug vent and retest. Vought sent out TTF letter to owner on PBS also requiring submission of updated PBS registration. 10/13/05-Vought-Received both copies of TTF returned to sender as attempted -not known unable to forward. Addresses on letters were: Noel Torsi 114 Waverly Place New York, NY 10011 and Chris Leahy 159 Prince Street New York, NY 10012. Vought called Leahy for correct address and received address from secretary and sent out new TTF letter to: Christopher Leahy 636 11th Avenue New York, NY 10036 10/21/05-Vought-Received message from Chris Leahy that source of failure was broken air release valve that will be replaced and tank will be retested. Report will be submitted to DEC. 05/17/06-Vought-Spill transferred from DEC Vought to DEC Ketani as per DEC Austin. 6/14/06 - Raphael Ketani. I tried to reach Mr. Leahy (lay-hee) at (212) 777-8838, but could only leave a voice message. There are 2 tanks on the property, but I could not find a PBS case. Mr. Melnick of Protest (631) 321-4670 had done the first tank test. 6/15/06 - Raphael Ketani. Mr. Leahy called me back. He said the PBS case is 2-339059. I checked the number and found both a 1500 and 2000 gallon tank listed. I told Mr. Leahy that I needed a revised PBS application, the successful test results for the 2000 gal. tank, a letter describing the removal of the 1500 gal. tank, and a cover letter from Protest stating that there was no oil spill, no impact to drains or the environment. He said he would get me these documents. 7/28/06 - Raphael Ketani. I spoke to Mr. Leahy and asked him for the revised PBS and the cover letter describing the incident, repairs, and that no drains or the environment were impacted. He said that he thought these documents were sent, but he will see to it that they are sent very shortly. 7/31/06 - Raphael Ketani. I received the FAXed 2000 gal. tank test report from Pro Test. The tank passed. However, I have not received the revised PBS. I left a message for Mr. Leddy of Pro Test and Mr. Leahy, the landlord. Mr. Leahy told me that a 1100 gal. tank was removed by Petroleum Tank Cleaners and that there is only a 2000 gal. on site, NOT a manifolded 2000/2200 gal. system. He said that even the Fire Department had the wrong tank size a while ago. He said the PBS form hasn't come back from the expediter, yet. He said he will send the revised PBS AND the report regarding the end point samples that were taken in the vicinity of the removed 1000 gal. tank. He said the end point samples were clean. 8/17/06 - Raphael Ketani. I tried to reach Mr. Leahy, but could only leave a message. 8/30/06 - Raphael Ketani. I tried to reach Mr. Leahy, but could only leave a message. 8/31/06 - Raphael Ketani. I received a call from Jessinia of Edgemont Realty (212) 228-6757 - the expeditor. She said that she had an affadavit for the removed tank (1080 gals.) and a check for renewal of the registration of the 2000 gal. tank. She asked who she should send it to. I told her to send it to me and I will walk it over to Nick Lombardo in the PBS Unit. She said she

APARTMENT BUILDING (Continued) **S107410739**

spoke to Mr. Lombardo and she said that he told her just to send the affadavit and the check for the renewal. I spoke to Mr. Lombardo and he said he recalled the conversation with Jessinia and he showed me a FAXed PBS registration form with the removal of the 1080 gal. tank and renewal of the 2000 gal. tank. He said he is just waiting for the originial PBS form, the affadavit and the check. 9/25/06 - Raphael Ketani. I received a call from Jessina inquiring whether the DEC had received all of the paperwork for the site. I told her I had the cover letter explaining what triggered the spill case. I told her I had to check with Mr. Lombardo of the PBS Unit to see whether he had received all of the necessary paperwork and the check. Mr. Lombardo told me that he must have received everything as Albany DER issued a certificate for the tank registration. I told her that the DEC had received all of the necessary paperwork. Based upon receipt of the revised PBS registration, the affadavit, the check, and the passing tank test results, I am closing the spill case. "

Remarks: ""

All TTF:

Facility ID:	0507990
Spill Number:	0507990
Spill Tank Test:	1549358
Site ID:	353498
Tank Number:	1
Tank Size:	2200
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

Facility ID:	0507990
Spill Number:	0507990
Spill Tank Test:	1549359
Site ID:	353498
Tank Number:	2
Tank Size:	1000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	353498

APARTMENT BUILDING (Continued) **S107410739**

Operable Unit ID:	1110958
Operable Unit:	01
Material ID:	2100997
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

892
East
1/4-1/2
0.421 mi.
2224 ft.

IFO 111 E7TH ST **NY LTANKS** **S105230178**
IFO 111 E.7TH ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
22 ft.

LTANKS:

Facility ID:	9912647
Site ID:	129838
Closed Date:	2000-02-17
Spill Number:	9912647
Spill Date:	2000-02-05
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2000-02-05
CID:	323
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-05
Spill Record Last Update:	2004-07-21
Spiller Name:	CALLER
Spiller Company:	MYSTIC
Spiller Address:	1901 STEINWAY ST
Spiller County:	001
Spiller Contact:	CASEY CHAMPION
Spiller Phone:	(919) 942-2156
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	111904
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE CLEANED BY RP."
Remarks:	"ON SIDEWALK ONLY. CONTAINED BEING CLEANED UP NOW. EASTMAN RESPONDING FOR CLEAN UP."

All Materials:

IFO 111 E7TH ST (Continued) **S105230178**

Site ID:	129838
Operable Unit ID:	1091350
Operable Unit:	01
Material ID:	569084
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

893
SSW
1/4-1/2
0.423 mi.
2234 ft.

UNKNOWN RESIDENCE
173 ELIZABETH ST
MANHATTAN, NY

NY LTANKS **S108131277**
N/A

Relative:
Lower

Actual:
39 ft.

LTANKS:

Facility ID:	0605862
Site ID:	369117
Closed Date:	2007-06-11
Spill Number:	0605862
Spill Date:	2006-08-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	2006-08-21
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-21
Spill Record Last Update:	2007-06-11
Spiller Name:	MARLIN JOESPH
Spiller Company:	UNKNOWN RESIDENCE
Spiller Address:	173 ELIZABETH ST
Spiller County:	001
Spiller Contact:	MARLIN JOESPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	318996
DEC Memo:	"Need to trace the owner and send a TTF letter. 09/13/06 a TTF letter was sent to: 14 Spring realty LLC 251 Mulberry Street New York, NY 10012 10/17/06- I got the tank tightness test results which showed that the ullage (dry) portion failed the test and a letter from Ferrantino fuel corporation saying that a temporary 275-gallon tank

UNKNOWN RESIDENCE (Continued) **S108131277**

was placed to supply the building with oil. The 1500 gallons above ground tank will be closed-removed. A new 1080-gallon above ground oil tank will be put in the basement by January. They said that there is no any visible sign of oil in the basement by the tank. They also said they will have a better look to determine if there is an spill when the cemented vault of the tank is broken up to removed the old tank. June 8,2007 I got a letter from Ferrantino Fuel Corporation saying upon removing the vault of the tank, we found no contamination on bricks on the ground. This case is closed "

Remarks: "THE OIL HAS BEEN PUMPED OUT."

All TTF:

Facility ID:	0605862
Spill Number:	0605862
Spill Tank Test:	1550210
Site ID:	369117
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	369117
Operable Unit ID:	1126965
Operable Unit:	01
Material ID:	2116533
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

894
WSW
1/4-1/2
0.425 mi.
2243 ft.

ABOVE GROUND TANK **NY LTANKS** **S120702915**
121 SPRING ST **N/A**
NEW YORK, NY

Relative:
Lower

Actual:
23 ft.

LTANKS:

Facility ID:	1700092
Site ID:	544687
Closed Date:	2017-06-21
Spill Number:	1700092
Spill Date:	2017-04-04
Spill Cause:	Tank Test Failure

ABOVE GROUND TANK (Continued) **S120702915**

Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2017-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2017-04-04
Spill Record Last Update:	2017-06-21
Spiller Name:	RICK
Spiller Company:	UNKNOWN
Spiller Address:	119 SPRING ST
Spiller County:	999
Spiller Contact:	RICK
Spiller Phone:	(718) 714-6898
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	498366
DEC Memo:	"04/04/17 - Lakhani Spoke to Ricky (9175932154) from Empire Environmental. He informed that a system test was performed on the AST tank system and failing results were obtained. There is no spill. They are unaware of where the system failed. The property is a commercial building using a 1080 gallon #2 fuel oil AST. TTF letter sent to owner: Tar Beach Club Inc. 119 Spring Street New York, NY 10012 and uploaded to D2. 04/12/17-Hiralkumar Patel. alternate address: none no PBS or other spills found. 04/27/17-Hiralkumar Patel. 11:33 AM:- received message from Soraya (917-445-5376), owner of building 119 Spring St. 12:06 PM:- spoke with Soraya. she mentioned that building 119 uses gas heating system and tank test failure may be related to neighboring property 121 Spring St. 12:09 PM:- spoke with Empire Env. who received site address from their client. after initial system test failure, Empire Env. conducted an isolation test and found leak in vent line. Empire has submitted work proposal to their client and waiting for approval. 12:11 PM:- spoke with Bryan Shaw at EBI Consulting. during phase I investigation, EBI Consulting noted the oil tank system at the site and recommended system test. Bryan confirmed site address as 121 Spring St. based on available information, changed site address in spill report from 119 Spring St. to 121 Spring St. . alternate address: 90 Greene St {block #: 499 / lot #: 43 (or 7503 as per NYC DOB)} no PBS or other spills found. as per NYC DOB records, a permit application was approved on 12/12/2003 for replacement of boiler and oil burner, and installation of 1,080 gal oil tank wrapped in jacket. 1:34 PM:- spoke with Jaime Espinales at Milan/Quatrone Property Management and received property manager and building super's contact info. 1:41 PM:- left message for Worley, building super. 121 Spring Street Associates **property owner** c/o Milan/Quatrone Property Management 52A West 8th Street New York, NY 10011 Attn.: Robert Milan Ph. (212) 598-4888 Ext. 201 email: bob@mqmgt.com Worley **building super** Ph. (917) 327-8440

ABOVE GROUND TANK (Continued) **S120702915**

Bryan Shaw EBI Consulting Ph. (845) 893-1245 email: bshaw@ebiconsulting.com 1:55 PM:- spoke with Soraya and informed her about change in site address. asked her to disregard the letter from the Department dated 04/04/2017. 2:20 PM:- sent TTF letter to Mr. Milan and asked him to submit report by the end of 05/31/17. letter emailed to Mr. Milan, Bryan and Michael (Empire Env.). 06/20/17-Hiralkumar Patel. 2:03 PM:- spoke with Carol at management office. informed her about overdue report. she requested copy of letter dated 04/27/17 as Mr. Milan is out of office. 2:29 PM:- sent email to Carol (info@mqmgt.com) including letter dated 04/27/17. asked her to submit required report immediately to avoid enforcement. email copied to Mr. Milan, Bryan and Michael. 3:16 PM:- received email from Jennifer Perez from Empire Env. including tightness test results dated 04/04/17 and 05/03/17. as per tester, the vent riser piping was leaking. the faulty vent riser pipe was replaced and the tank system was tested tight on 05/03/17. 06/21/17-Hiralkumar Patel. 8:51 AM:- sent email to Jennifer inquiring about any contamination noted during repairs. 9:32 AM:- received email from Jennifer stating that no evidence of contamination noted during repairs. case closed. 9:49 AM:- sent spill closure letter to Mr. Milan. letter emailed to Mr. Milan, Carol and Jennifer."

Remarks: "no spill tank test failure only"

All Materials:

Site ID:	544687
Operable Unit ID:	1293233
Operable Unit:	01
Material ID:	2299150
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

895
NW
1/4-1/2
0.426 mi.
2250 ft.

APT COMPLEX TTF
37 WASHINGTON SQ WEST
MANHATTAN, NY

NY LTANKS **S113494276**
N/A

Relative:
Lower

Actual:
19 ft.

LTANKS:

Facility ID:	1300635
Site ID:	480970
Closed Date:	2016-03-30
Spill Number:	1300635
Spill Date:	2013-04-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2013-04-19

APT COMPLEX TTF (Continued) **S113494276**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-04-19
Spill Record Last Update:	2016-03-30
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MARK SALAMACK
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	436256
DEC Memo:	"Sangesland sent an e-mail to Mark at PTC asking for status update on repairs/retest. 11/6/13-Vought-Found email in paperstack noting response from PTC Salamack (Ph:718-624-4842)that It's an above ground tank...#6 to other grade(not sure if it's #2 or #4)....vent line problem, been fixed, retested and passed, no contamination. 3/29/16-Vought-During routine portfolio review, Vought closed spill as above email from PTC indicated that the spill was from a vent line problem (does not contain oil unless overfill), note of repair, as well as report of no contamination)."
Remarks:	"REPAIR/RETEST PENDING"

All Materials:

Site ID:	480970
Operable Unit ID:	1230752
Operable Unit:	01
Material ID:	2229442
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BS896 **830 BROADWAY/PRETIUM ASSO** **NY LTANKS** **S100166620**
NNE **830 BROADWAY** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.429 mi.
2267 ft. **Site 3 of 3 in cluster BS**

Relative: LTANKS:
Lower

Facility ID:	8806438
Site ID:	196674
Closed Date:	1988-11-15
Spill Number:	8806438
Spill Date:	1988-11-01
Spill Cause:	Tank Failure

Actual:
40 ft.

830 BROADWAY/PRETIUM ASSO (Continued) **S100166620**

Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1988-11-15
SWIS:	3101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1988-11-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-11-03
Spill Record Last Update:	1988-12-08
Spiller Name:	Not reported
Spiller Company:	PRETISM ASSOC
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	163720
DEC Memo:	""
Remarks:	"#2 FO DELIVERED LAST WEEK, NOTICED 500 GALLONS MISSING WHEN TAKING INVENTORY, NO VISIBLE OIL BUT SUSPECT LEAKING TANK, STRONG ODOR."

All Materials:

Site ID:	196674
Operable Unit ID:	923263
Operable Unit:	01
Material ID:	454777
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2500.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Facility ID:	8807426
Site ID:	196675
Closed Date:	2001-11-06
Spill Number:	8807426
Spill Date:	1988-10-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	2001-11-06
SWIS:	3101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1988-12-08

830 BROADWAY/PRETIUM ASSO (Continued) **S100166620**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-12-09
Spill Record Last Update:	2001-11-06
Spiller Name:	Not reported
Spiller Company:	PRETIUM ASSOCIATES
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	163720
DEC Memo:	""
Remarks:	"TANK IN BASEMENT, CONVERTED FROM #6 FUEL OIL TO #2, CLEANED TANK, OIL SEEPED THROUGH BOTTOM OF TANK, FOUND BOTTOM OF TANK WAS CORRODED, REFER TO SPILL # 8806438."

All TTF:

Facility ID:	8807426
Spill Number:	8807426
Spill Tank Test:	1534986
Site ID:	196675
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	196675
Operable Unit ID:	924091
Operable Unit:	01
Material ID:	455769
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1500.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BV897 **105 WOOSTER STREET** **NY LTANKS** **S102660635**
WSW **105 WOOSTER STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.431 mi.
2274 ft. **Site 1 of 3 in cluster BV**

Relative: **Lower**

Actual: **18 ft.**

LTANKS:

Facility ID:	9212937
Site ID:	217084
Closed Date:	2003-02-10
Spill Number:	9212937
Spill Date:	1993-02-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1993-02-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-18
Spill Record Last Update:	2003-02-10
Spiller Name:	Not reported
Spiller Company:	SINVIN REALTY CO.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	179736
DEC Memo:	""
Remarks:	"DURING TANK PULL CONTAMINATED SOIL DISCOVERED BENEATH TANK-LOCATED IN TANK ROOM-3 SOIL WAS PUT DOWN FOR TANK TO REST ON -WILL EXCAV P/U & DRUM-NO NAME CONTR TO HAUL AND DISPOSE"

All Materials:

Site ID:	217084
Operable Unit ID:	979948
Operable Unit:	01
Material ID:	402757
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

898
ENE
1/4-1/2
0.438 mi.
2314 ft.

APARTMENT BLDG - TTF
340 E 11TH ST
MANHATTAN, NY

NY LTANKS **S112810140**
N/A

Relative:
Lower

Actual:
24 ft.

LTANKS:

Facility ID:	1212854
Site ID:	476012
Closed Date:	2015-03-06
Spill Number:	1212854
Spill Date:	2012-11-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2012-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-30
Spill Record Last Update:	2015-03-06
Spiller Name:	JOSH
Spiller Company:	APARTMENT BLDG
Spiller Address:	340 E 11TH ST
Spiller County:	999
Spiller Contact:	JOSH OR ALEX
Spiller Phone:	(718) 360-1893
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	431332
DEC Memo:	"11/30/12- Zhune spoke to Jeff Mckenzey from Advanced Tank. He said the tank failed the test. He does not know who is goimg to do the repair and retest the tank. 3/6/15-David Vega from Eastmond & Son Boiler & Welding Services, Inc. emailed the spill closure report dated March, 6 2015. The letter stated: This is to inform you of the work that was done at 340 East 11th St. Magnum Mgmt. informed us of a failed tank test reported by another company. On January 3, 2013 we isolated oil lines, tested & passed tank tightness test (attached test report)at that time we found the oil vent line leaking at grade. On January 8, 2013 we replaced a 4' section of the vent line at grade. There was no discharge of oil from the vent line. At this time we are requesting that you close the spill. Spill Closed."
Remarks:	"test failure. Repair & retest being scheduled."

All Materials:

Site ID:	476012
Operable Unit ID:	1225851
Operable Unit:	01
Material ID:	2223176
Material Code:	0001A
Material Name:	#2 fuel oil

APARTMENT BLDG - TTF (Continued) **S112810140**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

899
ESE
1/4-1/2
0.440 mi.
2322 ft.

APARTMENT BLDG **NY LTANKS** **S104782306**
141 EAST 3RD ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
27 ft.

LTANKS:

Facility ID:	0007066
Site ID:	154414
Closed Date:	2002-10-23
Spill Number:	0007066
Spill Date:	2000-09-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-09-15
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-09-15
Spill Record Last Update:	2002-10-23
Spiller Name:	RON HERMAN - REALTOR
Spiller Company:	HERMAN REALTY
Spiller Address:	720 WEST 181ST STREET
Spiller County:	001
Spiller Contact:	PEPE
Spiller Phone:	(917) 424-3973
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	130924
DEC Memo:	""
Remarks:	"10,000 GAL UST HAS HOLES IN IT - CONTAMINATED SOIL"

All Materials:

Site ID:	154414
Operable Unit ID:	827920
Operable Unit:	01
Material ID:	548168
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported

APARTMENT BLDG (Continued) **S104782306**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BW900 **COMMERCIAL SASSAN SAAOUNI** **NY LTANKS** **S119030008**
East **158 FIRST AVE** **N/A**
1/4-1/2 **NEW YORK, NY**
0.441 mi.
2326 ft. **Site 1 of 2 in cluster BW**

Relative: LTANKS:
Lower

Facility ID:	1609563
Site ID:	538353
Closed Date:	2017-04-06
Spill Number:	1609563
Spill Date:	2017-01-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2017-01-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2017-01-16
Spill Record Last Update:	2017-04-06
Spiller Name:	Not reported
Spiller Company:	COMMERCIAL SASSAN SAAOUNI
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BROOKIE MIELCKI
Spiller Phone:	(718) 253-2020
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	492175
DEC Memo:	"2-483036 1/16/2017- DEC Piper spoke with Protest. Leak was a gross dry leak at vent where it entered building. Protest has sent proposal to repair and retest system. Contact information for building is Brookie@skylinecapitalgrp.com DEC Piper sent TTF and PBS registration renewal to Representative. Assigned to DEC Patel for follow up and closure. 02/03/17-Hiralkumar Patel. alternate address: none PBS #: 2-483036. as per PBS record, the site has one (1) 1,500 gal #2 oil AST in contact with soil, in-service, installed in Jan. 1978. PBS expired on 11/16/2015. no other spills found. DEC Piper sent TTF letter to N & S Sassouni on 01/17/17 based on owner's information in PBS record, but property has been sold to 158 First Ave NYC LLC. on 01/22/16. on 01/17/17, DEC Piper emailed letter and PBS application

Actual:
22 ft.

COMMERCIAL SASSAN SAAOUNI (Continued) **S119030008**

to Ms. Milecki and asked her to renew PBS registration. Brookie Milecki Skyline Capital Group 1404 Coney Island Avenue Brooklyn, NY 11230 Ph. (718) 253-2020 Ext. 210 email: Brookie@skylinecapitalgrp.com 2:22 PM:- left message for Ms. Milecki. 02/06/17-Hiralkumar Patel. 2:55 PM:- received message from Sassan Sassouni. 02/07/17-Hiralkumar Patel. 12:47 PM:- spoke with Mr. Sassouni, property owner. he asked to send correspondences to below address. 158 First Ave NYC LLC. **property owner** c/o Sassan Sassouni 1 Sinclair Drive Great Neck, NY 11024 PH. (516) 662-4632 email: sassansassouni@gmail.com 12:51 PM:- spoke with Ms. Milecki. she mentioned that Skyline Capital Group is mortgage broker for the property. she asked to contact Mr. Sassouni regarding tank test failure investigation. 1:47 PM:- sent TTF letter to Mr. Sassouni with correct property owner's name and address. also included copy of PBS application requiring renewal of PBS registration. asked Mr. Sassouni to immediately renew PBS registration and submit tank test failure investigation/spill cleanup report by the end of 03/24/17. letter emailed to Mr. Sassouni. 02/16/17-Hiralkumar Patel. 7:26 AM:- received email from Mr. Sassouni including tank system test result. the tank system was tested tight on 02/15/17 by Rene Lewis. 9:05 AM:- sent email to Mr. Sassouni and asked him to submit complete report as per the letter dated 02/06/17. 03/06/17-Hiralkumar Patel. 9:17 AM:- sent email to Mr. Sassouni and asked him to submit required report. also asked him to provide update on renewal of tank registration. email copied to Rene Lewis. 9:23 AM:- received email from Mr. Sassouni stating that documents were submitted a while ago. 9:24 AM:- spoke with Mr. Sassouni and informed him that documents have not received yet. he will talk to Rene. 04/04/17-Hiralkumar Patel. 11:17 AM:- spoke with Mr. Sassouni and informed him that the department has not received required report yet. asked him to submit report by the end of 04/07/17. 11:22 AM:- left message for Rene. 11:25 AM:- sent email to Mr. Sassouni including copy of letter dated 02/07/17. informed him that the report must be submitted by the end of 04/07/17 or else case will be referred for enforcement. email copied to Rene. 04/06/17-Hiralkumar Patel. 6:34 AM:- received email from Rene including spill closure letter. Rene mentioned that both fill and vent lines were found corroded, but leak was noted in vent line only. he replaced entire vent line and portion of fill line. after repairs, the tank system was tested tight on 02/15/17. case closed based on available information. 11:32 AM:- sent spill closure letter to Mr. Sassouni. letter emailed to Mr. Sassouni, including note to renew PBS registration immediately. email copied to Rene and DEC Leszek."

Remarks: "test failure, dry leak"

All Materials:

Site ID:	538353
Operable Unit ID:	1286956
Operable Unit:	01
Material ID:	2292609
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BX901 **31 E 12TH ST** **NY LTANKS** **S104620865**
North **31 E 12TH ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.444 mi.
2345 ft. **Site 1 of 2 in cluster BX**

Relative: LTANKS:
Lower

Actual:
37 ft.

Facility ID:	9913336
Site ID:	74731
Closed Date:	2005-11-01
Spill Number:	9913336
Spill Date:	2000-02-24
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TLGIBBON
Referred To:	Not reported
Reported to Dept:	2000-02-24
CID:	207
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-24
Spill Record Last Update:	2005-11-01
Spiller Name:	ROB HALABOV
Spiller Company:	Not reported
Spiller Address:	31 E 12TH ST
Spiller County:	001
Spiller Contact:	ROB HALABOV
Spiller Phone:	(212) 243-6722
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	70066
DEC Memo:	"6/8/05 - Project transferred to TLGibbons in Central Office, Albany 9/9/05 - Called Buchbinder & Warren Realty Group, Inc., 212-243-6722. Mr Halabov, contact on spill report, no longer with company. Left message. 9/12/05 - Received call from Neil Hellegers, 646-637-9033, who works for Jennifer , managing agent for 31 East 12th St. He will track down paperwork on spill. 10/26/05 - Tried to contact Mr. Hellegers but no longer with company. Julia Fergeson is new manager of building. She wanted copy of spill report so e-mailed her today. 10/31/05 - Received fax from Buchbinder & Warren which includes invoice (dated 5/18/00) from A.L. Eastmond for removal of old 5,000 gal fuel oil tank and replace with new 7,500 gal fuel oil tank, including certification from the NY Department of Buildings, dated 6/7/00. Close spill."
Remarks:	"spill at this residence last week - spill taken care of then but tank was found today to have a hole in it - no further spilled product - tank was empty - air was introduced into tank to determine location of leak"

BX902 **31 EAST 12TH STREET** **NY LTANKS** **S104516539**
North **31 EAST 12TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.444 mi.
2345 ft. **Site 2 of 2 in cluster BX**

Relative: **Lower**

Actual: **37 ft.**

LTANKS:

Facility ID:	9913000
Site ID:	118045
Closed Date:	2000-03-07
Spill Number:	9913000
Spill Date:	2000-02-15
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-02-15
CID:	281
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-15
Spill Record Last Update:	2000-03-07
Spiller Name:	ROBERT HALABOV
Spiller Company:	BUCHBINDER & WARREN,LLC
Spiller Address:	1 UNION SQUARE WEST
Spiller County:	001
Spiller Contact:	NYC FIRE
Spiller Phone:	(212) 570-4230
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102612
DEC Memo:	""
Remarks:	"NYC FIRE PREVENTION ON SITE WITH A LEAKING TANK. UNKNONW AT TIME OF CALL WHO OWNS PROPERTY. BUILDING SUPERINDENDANT ON SITE AND STATES MANAGMENT AWARE OF PROBLEM. CALLER REQUESTING CALL BACK FROM DEC IN REFERENCE TO PROBLEM."

All Materials:

Site ID:	118045
Operable Unit ID:	1087525
Operable Unit:	01
Material ID:	294864
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BY903 **512 BROADWAY** **NY LTANKS** **S101103332**
SW **512 BROADWAY** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.448 mi.
2365 ft. **Site 1 of 4 in cluster BY**

Relative: **Lower**

Actual: **28 ft.**

LTANKS:

Facility ID:	9315173
Site ID:	103353
Closed Date:	1994-03-25
Spill Number:	9315173
Spill Date:	1994-03-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	1994-03-25
SWIS:	3101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1994-03-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-28
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	ABC
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	91405
DEC Memo:	""
Remarks:	"GAGE MALFUNCTION CONTAINED ON SIDEWALK - ABC CREW ENROUTE FOR CLEAN UP."

All Materials:

Site ID:	103353
Operable Unit ID:	997099
Operable Unit:	01
Material ID:	386940
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

512 BROADWAY (Continued) **S101103332**

Facility ID:	9315188
Facility Type:	ER
Spill Number:	9315188
DER Facility ID:	91405
Site ID:	103354
DEC Region:	2
Closed Date:	1995-09-05
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3101
Spill Date:	1994-03-25
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1994-03-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	1995-09-05
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-26
Spill Record Last Update:	2003-09-25
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN "
Remarks:	"TANK OVERFILL WENT ON SIDEWALK"

All Materials:

Site ID:	103354
Operable Unit ID:	993430
Operable Unit:	01
Material ID:	386954
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BU904 **10 WEST 10TH ST** **NY LTANKS** **S104790598**
NNW **10 WEST 10TH ST** **NY Spills** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.448 mi.
2367 ft. **Site 3 of 3 in cluster BU**

Relative:
Lower

Actual:
28 ft.

LTANKS:

Facility ID:	0205121
Site ID:	99707
Closed Date:	2005-08-24
Spill Number:	0205121
Spill Date:	2002-08-15
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	jdjarrat
Referred To:	Not reported
Reported to Dept:	2002-08-15
CID:	207
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-15
Spill Record Last Update:	2005-08-24
Spiller Name:	N/A
Spiller Company:	ATLANTIC AND PACIFIC OIL
Spiller Address:	CONEY ISLAND AVE
Spiller County:	001
Spiller Contact:	RAY LARA
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	88573
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 8/15/02 TJD Misdelivery causing discharge into basement of apartment building with offices on ground floor. PTC retained by delivery company for cleanup. Instructed to remove all petroleum impacted items and provide manifests from disposal. Concrete floor beneath carpeting and rubber matting in hallways. Strong petroleum vapors noted inside of building, occupants were displaced as a result of spill. file transferred to CO July 2005, assigned to jarratt. Received copy of invoice of cleanup by PTC (invoice date 8/20/2002) Spill closed 8/24/05 "
Remarks:	"poss up to 100 gals involved"

All Materials:

Site ID:	99707
Operable Unit ID:	857894
Operable Unit:	01
Material ID:	519332
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

10 WEST 10TH ST (Continued) **S104790598**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Facility ID:	0008247
Facility Type:	ER
Spill Number:	0008247
DER Facility ID:	197893
Site ID:	240627
DEC Region:	2
Closed Date:	2003-12-12
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	2000-10-13
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-10-14
CID:	204
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-14
Spill Record Last Update:	2003-12-12
Spiller Name:	UNKNOWN
Spiller Company:	5TH AVENUE CENTER FOR CON
Spiller Address:	10 WEST 10TH STREET
Spiller Company:	001
Contact Name:	MARINA TOMARCHIO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/12/03 Tjdold Odor Complaint. Closed Due To The Nature / Extent Of The Spill Report."
Remarks:	"CALLER STATES SHE HAD AN APPOINTMENT TODAY - AND WHEN SHE GOT THERE SHE SMELLED AN UNKNOWN PETROLEUM-HER CONSELLOR ALSO SMELLED IT - HE SAID THEY WERE HAVING A PROBLEM WITH THE OIL TANK. THE CALLER BEGAN TO GET SICK AND HER HEART STARTED RACING WHILE SHE WAS THERE. CALLER DOES WANT TO REMAIN ANNOYMOUS."

All Materials:

Site ID:	240627
Operable Unit ID:	828855
Operable Unit:	01
Material ID:	545763
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

10 WEST 10TH ST (Continued) **S104790598**

Units: G
Recovered: .00
Oxygenate: Not reported

BZ905 **39 5TH AVENUE** **NY LTANKS** **S102672414**
NNW **39 5TH AVENUE** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.449 mi.
2371 ft. **Site 1 of 2 in cluster BZ**

Relative: **Lower**
Actual: **31 ft.**

LTANKS:
Facility ID: 9313956
Site ID: 295304
Closed Date: 1994-03-08
Spill Number: 9313956
Spill Date: 1994-02-26
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: 1994-03-08
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1994-02-26
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-03-10
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: MYSTIC TRANSP.
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 238964
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks: "DRIVER OVERFILLED TANK DUE TO FAULTY GAUGE - DRIVER CLEANED - NYC DEP NOTIFIED."

All Materials:
Site ID: 295304
Operable Unit ID: 992385
Operable Unit: 01
Material ID: 389305
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum

39 5TH AVENUE (Continued) **S102672414**

Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

BV906 **COMMERCIAL BUILDING** **NY LTANKS** **S111319271**
WSW **145 SPRING ST** **N/A**
1/4-1/2 **NEW YORK, NY**
0.454 mi.
2399 ft. **Site 2 of 3 in cluster BV**

Relative: **Lower**

Actual: **17 ft.**

LTANKS:

Facility ID:	1110287
Site ID:	458099
Closed Date:	2011-12-20
Spill Number:	1110287
Spill Date:	2011-11-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	2011-11-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-11-18
Spill Record Last Update:	2011-12-20
Spiller Name:	Not reported
Spiller Company:	RBH /LINDA MONTANEZ
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	RBH /LINDA MONTANEZ
Spiller Phone:	(212) 685-7833
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	412595
DEC Memo:	"Dry leak-TTF was sent out to RBH Management 16 W 36th Street New York, NY 10018(sr) 12/20/11 Yesterday, received letter from Pro Test requesting closure of this case. Vent line, fill line, and petrometer line were replaced. After lines were replaced, tank passed ttt on 12/9/11. No contamination found. No PBS Number for this site, may be because tank is 1080 gal. and used for consumption on-site. NFA. bf "
Remarks:	"1080 gal agt"

All Materials:

Site ID:	458099
Operable Unit ID:	1208209
Operable Unit:	01
Material ID:	2205540

COMMERCIAL BUILDING (Continued) **S111319271**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

907
NE
1/4-1/2
0.462 mi.
2437 ft.

ON SIDEWALK
240 E 13TH ST
MANHATTAN, NY

NY LTANKS **S104950861**
NY Spills **N/A**

Relative:
Lower

Actual:
32 ft.

LTANKS:

Facility ID:	0011558
Site ID:	84167
Closed Date:	2001-02-06
Spill Number:	0011558
Spill Date:	2001-01-25
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2001-01-25
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-25
Spill Record Last Update:	2001-02-06
Spiller Name:	PAT TURTURRO
Spiller Company:	CLASSIC FUEL
Spiller Address:	9 WYTHE AVENUE
Spiller County:	001
Spiller Contact:	UNNOWN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	77419
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD CLEANED UP BY CLASSIC FUELS."
Remarks:	"CLASSIC FUELS IS IN THE PROCESS OF CLEANING UP SPILL NOW WITH ABSORBANT"

All Materials:

Site ID:	84167
Operable Unit ID:	833032
Operable Unit:	01

ON SIDEWALK (Continued) **S104950861**

Material ID: 541866
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Facility ID: 9914290
Facility Type: ER
Spill Number: 9914290
DER Facility ID: 77419
Site ID: 84168
DEC Region: 2
Closed Date: 2000-03-20
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 3101
Spill Date: 2000-03-19
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 2000-03-19
CID: 257
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-03-19
Spill Record Last Update: 2000-03-20
Spiller Name: Not reported
Spiller Company: MYSTIC TRANPORTATION
Spiller Address: Not reported
Spiller Company: 001
Contact Name: UNNOWN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY SPILLER"
Remarks: "cleanup crew is on the way spilli son the sidewalk"

All Materials:
Site ID: 84168
Operable Unit ID: 1092445
Operable Unit: 01
Material ID: 292573
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00

ON SIDEWALK (Continued) **S104950861**

Units: G
Recovered: .00
Oxygenate: Not reported

BV908 **PROPERTIES SOLUTIONS** **NY LTANKS** **S107658769**
WSW **155 SPRING STREET** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.463 mi.
2445 ft. **Site 3 of 3 in cluster BV**

Relative: LTANKS:
Lower
Actual:
16 ft.

Facility ID:	0514284
Site ID:	360975
Closed Date:	2007-11-23
Spill Number:	0514284
Spill Date:	2006-03-14
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2006-03-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-14
Spill Record Last Update:	2008-03-05
Spiller Name:	CRAIG
Spiller Company:	PROPERTIES SOLUTIONS
Spiller Address:	155 SPRING STREET
Spiller County:	001
Spiller Contact:	CRAIG
Spiller Phone:	(732) 417-0999
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	311156
DEC Memo:	"mailed ttf to Mrs. Emile Mercier Charles Jourdan USA Inc. 2 Caesar Place Moonachie, NY 07074 and Charles Jourdan USA Inc. 136 West 11th Street New York, NY 10011 No PBS records on property. Spoke w/ craig norris of Properties solutions. He is a contractor representing potential buyer. He will also look into current ownership. 3/30/6- faxed pbs application to donna.The tightness test failure eas due to a line leak, tank passed. 5/8/06- DEC Piper left message for Donna (Rep for prop.)201-974-1286 cell-201-906-7995 Repairs have been made though a PBS application needs to be submitted. 2/28/07- DEC Piper left message for donna requesting callback and info. 3/5/07- DEC Piper psoke w. Donna, The building has been sold and she will get back to me with contact. 11/23/07- DECP iperreviewed case. Spill closed though PBS violations exist. Referred to PBS for enforcement. 3/5/08 PBS inspection yesterday. NOV issued for failing to register,

PROPERTIES SOLUTIONS (Continued) **S107658769**

failing to color code fill port, and failure to label AST.
Administrative settlement conference scheduled for 3/27/08. bf"

Remarks: ""

All TTF:

Facility ID:	0514284
Spill Number:	0514284
Spill Tank Test:	1549798
Site ID:	360975
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	360975
Operable Unit ID:	1118076
Operable Unit:	01
Material ID:	2108589
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BW909 **260 EAST 10TH ST** **NY LTANKS** **S102660663**
East **260 EAST 10TH ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.464 mi.
2449 ft. **Site 2 of 2 in cluster BW**

Relative:
Lower

Actual:
21 ft.

LTANKS:

Facility ID:	9416858
Site ID:	145786
Closed Date:	1995-03-31
Spill Number:	9416858
Spill Date:	1995-03-29
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-03-31
SWIS:	3101
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1995-03-29

260 EAST 10TH ST (Continued) **S102660663**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-02
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	124185
DEC Memo:	""
Remarks:	"VAULTED TANK - INTERIOR TANK IS SPLIT - VIJAX IS ON THE WAY TO REPAIR TANK. 03/31/95 SPOKE TO RONALD, DID CLEANUP ACTIVITIES. PRODUCT OUT OF TANK. WILL EPOXY IN NEW SHELL & THEN PUT PRODUCT IN."

All Materials:

Site ID:	145786
Operable Unit ID:	1010661
Operable Unit:	01
Material ID:	368486
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

BY910 **HSR CORP** **NY LTANKS** **S118263544**
SW **503-511 BROADWAY** **N/A**
1/4-1/2 **NEW YORK, NY**
0.469 mi.
2477 ft. **Site 2 of 4 in cluster BY**

Relative: **Lower**
Actual: **27 ft.**

LTANKS:

Facility ID:	1507638
Site ID:	515135
Closed Date:	2015-11-17
Spill Number:	1507638
Spill Date:	2015-10-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMOMAR
Referred To:	Not reported

HSR CORP (Continued) **S118263544**

Reported to Dept:	2015-10-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-10-21
Spill Record Last Update:	2015-11-17
Spiller Name:	Not reported
Spiller Company:	HSR CORP
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	PRO TEST
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	469562
DEC Memo:	"10/21/2015: Rashad Duty Desk Called pro test and spoke to Victoria, she said it was a dry leak and no product was lost. The owner will be fixing tank and have it retested, she will be emailing me tank reports. 503-511 Broadway has alternate addresses of 503 Broadway and 74-82 Mercer Street. According to PBS# 2-611955 there is a 5,000 gallon #2 fuel oil AST with no last test date or next test date. There is a previous spill#9914496 at 511 Broadway that was closed in 2004 under Jane O'Connell, it was a con Ed spill that has 2.5 gallons of unknown oil into 20 gallons of water in service box in front of 511 Broadway, lab results indicated PCBs at less than 1 ppm. 10/30/2015: Rashad Victoria emailed tank test failure document: As per your request, I am attaching a copy of the failing test report for 503-511 Broadway. The customer will make arrangements for the repairs and then plans to have us conduct the retest. It has been uploaded to D2. Tightness test indicates a 5000 gallon tank with a dry leak (specifies gross dry leak in vent pipe). I responded: Thank you for the update. 11/17/2015: Rashad Received Email from Harvey Fung (hfung@hsrcorp.com) on 11/16: Please find close out letter and report attached for PBS#2-611955 #001, Spill#1507638. If you have any question please feel free to contact me& .Thanks! Attached in email was passing tightness test on tank and system conducted on 11/10/2015 by Pro Test Environmental. Also attached in email is request for closure letter which included repairs made: installed 50 LF of 2 inch vent lines and installed a 2x2 vent alarm. Both documents have been uploaded to D2. Emailed Harvey: Attached is a standardized letter closing out spill# 1507638 for 503-511 Broadway. Please let me know if you have any questions. Closure letter has been uploaded to D2. Case will be closed due to repairs made on tank, passing tightness test, and aboveground tank."
Remarks:	"5000 gal ast"

All Materials:

Site ID:	515135
Operable Unit ID:	1264302
Operable Unit:	01
Material ID:	2268065
Material Code:	0001A
Material Name:	#2 fuel oil

HSR CORP (Continued) **S118263544**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

911
SSW
1/4-1/2
0.473 mi.
2496 ft.

179 MULBERRY ST **NY LTANKS** **S102672928**
179 MULBERRY ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
33 ft.

LTANKS:

Facility ID:	9502099
Site ID:	325857
Closed Date:	1995-06-19
Spill Number:	9502099
Spill Date:	1995-05-01
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-06-19
SWIS:	3101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1995-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-06-23
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	PARK LANE MANAGEMENT
Spiller Address:	117-18 QUEENS BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	262490
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"POSSIBLE TANK OVERFILL - ALSO PROBLEM WITH OIL LINE - BASEMENT FILLED WITH WATER - OIL FLOATING ON THE TOP - CASTLE OIL WILL SEDN A CREW TO PUMP OUT CONTAMINATED WATER"

All Materials:

Site ID:	325857
Operable Unit ID:	1016521
Operable Unit:	01
Material ID:	367167

179 MULBERRY ST (Continued) **S102672928**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

912
SSW
1/4-1/2
0.475 mi.
2509 ft.

LAFAYETTE STREET SCHOOL YARD
205 LAFAYETTE STREET
NEW YORK, NY 10013

US BROWNFIELDS **1022830845**
N/A

Relative:
Lower

Actual:
31 ft.

US BROWNFIELDS:

Property Name:	LAFAYETTE STREET SCHOOL YARD
Recipient Name:	R2 TBA (STAG Funded)
Grant Type:	TBA
Property Number:	Block 186, Lot 35
Parcel size:	.5
Latitude:	40.7215328
Longitude:	-73.9977639
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	224321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	14769
Assessment Funding Source:	US EPA - TBA Funding
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	1
Cooperative Agreement Number:	n/a
Start Date:	02/17/2016 00:00:00
Ownership Entity:	Government
Completion Date:	04/29/2016 00:00:00
Current Owner:	Newark Public Schools
Did Owner Change:	N
Cleanup Required:	U
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U

LAFAYETTE STREET SCHOOL YARD (Continued) **1022830845**

IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	.5
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported

LAFAYETTE STREET SCHOOL YARD (Continued) **1022830845**

Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	The property has been used as a schoolyard for the adjacent Lafayette Street School at least since the 1930s; prior to that the site was occupied by residential properties.
Below Poverty Number:	10676
Below Poverty Percent:	19.2%
Meidan Income:	21491
Meidan Income Number:	19693
Meidan Income Percent:	35.4%
Vacant Housing Number:	4077
Vacant Housing Percent:	14.2%
Unemployed Number:	2357
Unemployed Percent:	4.2%

BZ913 **47-27 5TH STREET** **NY VCP** **S118943275**
North **47-27 5TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.476 mi.
2512 ft. **Site 2 of 2 in cluster BZ**

Relative:
Lower

Actual:
33 ft.

VCP NYC:

Project ID:	13CVCP138Q
Project Name:	47-27 5TH STREET
Project Address:	47-27 5TH STREET
Borough:	QUEENS

VCP NYC:

Project ID:	13CVCP138Q
File Name:	2013-05-29.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-05-29.13CVCP138Q.47-27_5th_Street.RIR.pdf

47-27 5TH STREET (Continued) **S118943275**

Project ID: 13CVCP138Q
File Name: 2013-05-31.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-05-31.13CVCP138Q.47-27_5th_Street.RAWP_Draft.pdf

Project ID: 13CVCP138Q
File Name: 2013-05-28.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-05-28.13CVCP138Q.47-27_5th_Street.FactSheet_1.pdf

Project ID: 13CVCP138Q
File Name: 2013-05-29.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-05-29.13CVCP138Q.47-27_5th_Street.Translated_FactSheet_1.pdf

Project ID: 13CVCP138Q
File Name: 2013-05-29.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-05-29.13CVCP138Q.47-27_5th_Street.Translated_CPS.pdf

Project ID: 13CVCP138Q
File Name: 2013-06-03.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-06-03.13CVCP138Q.47-27_5th_Street.Stipulation_List.pdf

Project ID: 13CVCP138Q
File Name: 2013-07-18.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-07-18.13CVCP138Q.47-27_5th_Street.FactSheet-2.pdf

Project ID: 13CVCP138Q
File Name: 2013-07-29.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Queens/13CVCP138Q/2013-05-29.13CVCP138Q.47-27_5th_Street.Translated_FactSheet-2.tj.pdf

---

BY914 **TTF** **NY LTANKS** **S113916412**
SW **496 BROADWAY** **N/A**
1/4-1/2 **NEW YORK, NY**
0.481 mi.
2541 ft. **Site 3 of 4 in cluster BY**

Relative: LTANKS:
Lower
Actual:
27 ft.

Facility ID: 1305781
Site ID: 486362
Closed Date: Not reported
Spill Number: 1305781
Spill Date: 2013-08-30
Spill Cause: Tank Test Failure
Spill Source: Unknown
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 3101
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2013-08-30

TTF (Continued) **S113916412**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2013-08-30
Spill Record Last Update:	2014-10-09
Spiller Name:	TJ O'CONNOR
Spiller Company:	TANK TEST FAIL
Spiller Address:	496 BROADWAY
Spiller County:	999
Spiller Contact:	TJ O'CONNOR
Spiller Phone:	(516) 678-5115
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	441477
DEC Memo:	"DEC called contact. number busy. 9/6/13- Number still busy. MAy be bad. No PBS number for address. Furhter info needed from Dry as a Bone."
Remarks:	"TANK TEST FAIL"

All Materials:

Site ID:	486362
Operable Unit ID:	1236008
Operable Unit:	01
Material ID:	2235307
Material Code:	9999
Material Name:	other - TANK TEST FAIL
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

915
North
1/4-1/2
0.481 mi.
2542 ft.

13 E. 12TH STREET **NY LTANKS** **S102671939**
13 E. 12TH STREET **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
36 ft.

LTANKS:

Facility ID:	9206642
Site ID:	220273
Closed Date:	1992-09-08
Spill Number:	9206642
Spill Date:	1992-09-08
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1992-09-08
SWIS:	3101
Investigator:	KSTANG
Referred To:	Not reported

13 E. 12TH STREET (Continued) **S102671939**

Reported to Dept:	1992-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-09
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	182192
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"CONTAINED IN SIDEWALK WHALECO DID CLEANUP"

All Materials:

Site ID:	220273
Operable Unit ID:	973810
Operable Unit:	01
Material ID:	407341
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BY916 **42 CROSBY STREET** **NY VCP** **S118943405**
SW **42 CROSBY STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.482 mi.
2543 ft. **Site 4 of 4 in cluster BY**

Relative:
Lower

Actual:
27 ft.

VCP NYC:

Project ID:	15CVCP011M
Project Name:	42 CROSBY STREET
Project Address:	42 CROSBY STREET
Borough:	MANHATTAN

VCP NYC:

Project ID:	15CVCP011M
File Name:	2014-07-21.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-07-23.15CVCP011M.42_Crosby_Street.report.RIR.V2_Langan.pdf

Project ID:	15CVCP011M

42 CROSBY STREET (Continued) **S118943405**

File Name: 2014-07-21.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-07-2317.15CVCP011M.42_Crosby_Street.report.RAWP.V2_Langan.pdf

Project ID: 15CVCP011M
File Name: 2014-07-21.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-07-21.15CVCP011M.42_Crosby.document.FactSheet-1.pdf

Project ID: 15CVCP011M
File Name: 2014-07-21.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-07-21.15CVCP011M.42_Crosby.Translated_FS1.pdf

Project ID: 15CVCP011M
File Name: 2014-07-21.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-07-21.15CVCP011M.42_Crosby.Translated_CPS.pdf

Project ID: 15CVCP011M
File Name: 2014-08-25.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-08-25.15CVCP011M.doc.42_Crosby_Street.Factsheet-2.pdf

Project ID: 15CVCP011M
File Name: 2014-08-25.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Manhattan/15CVCP011M/2014-08-25.15CVCP011M.doc.42_Crosby_Street.Translated_Factsheet-2.pdf

---

917 South 1/4-1/2 0.482 mi. 2543 ft. **DELANCEY ST AND 2ND AVE TRACK 3 F LINE MANHATTAN, NY** **NY LTANKS** **S104191978 N/A**

Relative: Lower
Actual: 40 ft.

LTANKS:

Facility ID:	9906932
Site ID:	300893
Closed Date:	2003-11-12
Spill Number:	9906932
Spill Date:	1999-09-10
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-09-10
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

DELANCEY ST AND (Continued) **S104191978**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-09-10
Spill Record Last Update:	2003-11-12
Spiller Name:	CALLER
Spiller Company:	NYC TRANSIT
Spiller Address:	370 JAY ST
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	243347
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Spill to tracks. No sewer impacted. Contained and cleaned by NYCT."
Remarks:	"file line overfilled all cleaned up"

All Materials:

Site ID:	300893
Operable Unit ID:	1085363
Operable Unit:	01
Material ID:	299644
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

CA918 **LITTLE RED SCHOOL HOUSE** **NY LTANKS** **S105997591**
WNW **272 6TH AVENUE** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.486 mi.
2564 ft. **Site 1 of 2 in cluster CA**

Relative: **Lower**
Actual: **20 ft.**

LTANKS:

Facility ID:	0209396
Site ID:	147642
Closed Date:	2006-06-30
Spill Number:	0209396
Spill Date:	2002-12-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2002-12-12
CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

LITTLE RED SCHOOL HOUSE (Continued) **S105997591**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-12
Spill Record Last Update:	2006-06-30
Spiller Name:	MICHELLE
Spiller Company:	LITTLE RED SCHOOL HOUSE
Spiller Address:	272 6TH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	125688
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 7/24/2003-Vought-Conroy Environmental Consultants-631-423-1240 received NFA Request results dated April 30, 2003. Tank repair work included pumping existing fuel from tank, cleaning the tank interior and resealing tank manway. The tank ONLY passed the tightness test after repairs were made (tighness test results provided). Vent and fill line did not pass the test and as a result the fill line was immediately sealed an are scheduled to be replaced. FOr spill closure NYSDEC requires 1)Site Plan 2)borings or endpoints to investigate possiblity of fill pipe impact to subsurface. 1/7/04-Vought-Spill transferred from Vought to Austin. 01/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 11/28/05- DEC Piper sent out another ttf letter in regards to fill and vent line failure to Michele Dekonkoly Thege at 272 6th Ave, NY, NY. Daphne no longer w/ little red school house. 12/28/05- DEC Piper has spoke w/ Steve Russo, rep for Little Red School house. regarding borings. He will look into it. 5/5/06- DEC Piper has left message w/ Steve Russo, rep for Little Red School house. regarding borings, requesting callback and info. 5/11/06- DEC Piper spoke w. Steve. A visit is scheduled for 5/15 at 3:30pm. 5/15/06- DEC Piper responded to site to determine additional work. The 2 x 2 vault to the manway of an UST contained contaminated soil. Once opened the vault eminated vapors. Trap door was sealed with duct tape to prevent vapors intruding into basement classrooms. There is no such evidence that any soil was removed when the fill line was replaced (manifests, analytical , not mentioned in report. DEC instructed LRSH to remediate top of tank and perform borings along fill line. CSL letter sent. 6/6/06- DEC Piper left maessage for John at langan requesting callback. Returning his call. 6/30/06- DEC Piper met w/ John Garvis of Langan and Hydrotech technicians. Contaminated Soil was excavated around manway with a shop vac approx, five gallons. Soil was clean under surface oil staining. Top of tank exposed w/ no indication of overfill to subsurface. Some concrete existed. Hydro tech to epoxy seal manway (2 coats) and concrete around manway. Fill and vent were replaced. No oil staining observed on old fill line entering basement. Closed. See e-docs if warranted. "
Remarks:	"TANK TO BE INSPECTED AND RETESTED."

All TTF:

Facility ID:	0209396
Spill Number:	0209396
Spill Tank Test:	1527824
Site ID:	147642
Tank Number:	1

LITTLE RED SCHOOL HOUSE (Continued) **S105997591**

Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	147642
Operable Unit ID:	862512
Operable Unit:	01
Material ID:	516371
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CA919 **LITTLE RED SCHOOL HOUSE** **NY LTANKS** **S108765810**
WNW **272 6TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.486 mi.
2564 ft. **Site 2 of 2 in cluster CA**

Relative:
Lower

Actual:
20 ft.

LTANKS:

Facility ID:	0706903
Site ID:	387510
Closed Date:	2008-05-29
Spill Number:	0706903
Spill Date:	2007-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Unknown
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2007-09-21
CID:	404
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-09-21

LITTLE RED SCHOOL HOUSE (Continued) **S108765810**

Spill Record Last Update:	2008-05-29
Spiller Name:	MARLON JOSEPH
Spiller Company:	PETROLIUM TANK CLEANERS
Spiller Address:	236 BUTLER ST
Spiller County:	001
Spiller Contact:	MARLON JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	336940
DEC Memo:	"9/25/07 bf: Called Michel de Konkoly Thege 212-477-5316. Left message to return my call. Sent ttf letter to: Michel de Konkoly Little Red School House 40 Charlton St. New York, NY 10014 9/28/07 Received message from Mr. Thege on 9/25/07. They have apptointment with contractor to have tank emtied and find source of failure on 10/5/07. He left his number which is same as above. His extension is 319. bf 11/16/07- Piper spoke w. Jason at Langan to perform borings through tank and undersidewalk. The will keep Dept in Loop. The school plans on converting to gas. 3/15/08- DEC Piper met contractors onsite to complete remainder of tank cleaning and sampling. odors were not present in hallways untill adjacent to work area. The school will be closed for the week and sampling will be performed and then the tank will be slurried. 5/29/08- DECPiper- I recieved and reviewed ust and spill closure report. Tank was cleaned and two enpoints were taken through tank bottom. No visible evidence of cont was discovered and laba analytical showed no exceedances. Tank was then slurried. Based on work to date, NFA granted. closed. See e-docs if warranted."
Remarks:	"it was a dry portion leak;"

All TTF:

Facility ID:	0706903
Spill Number:	0706903
Spill Tank Test:	1764127
Site ID:	387510
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	387510
Operable Unit ID:	1144710
Operable Unit:	01
Material ID:	2135018
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

LITTLE RED SCHOOL HOUSE (Continued) **S108765810**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

920 East 1/4-1/2 0.486 mi. 2567 ft. **J. PALULIW** **NY LTANKS** **S102672817**
433 EAST 9TH STREET **N/A**
NEW YORK, NY

Relative: Lower
Actual: 19 ft.

LTANKS:
Facility ID: 9414756
Site ID: 145111
Closed Date: 1995-02-09
Spill Number: 9414756
Spill Date: 1995-02-09
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: 1995-02-09
SWIS: 4101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1995-02-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-02-09
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: PETRO
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 123664
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks: "TANK WAS FULL BEFORE DELIVERY."

All Materials:
Site ID: 145111
Operable Unit ID: 1008255
Operable Unit: 01
Material ID: 373481
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum

J. PALULIW (Continued) **S102672817**

Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

CB921 **TTF** **NY LTANKS** **S112148820**
SW **65 GREENE STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.488 mi.
2576 ft. **Site 1 of 2 in cluster CB**

Relative: **Lower**

Actual: **19 ft.**

LTANKS:

Facility ID:	1203271
Site ID:	466068
Closed Date:	2015-12-17
Spill Number:	1203271
Spill Date:	2012-07-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMOMAR
Referred To:	Not reported
Reported to Dept:	2012-07-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-03
Spill Record Last Update:	2015-12-17
Spiller Name:	BILL MAKKOS EQUITIES
Spiller Company:	UNKNOWN
Spiller Address:	65 GREENE STREET
Spiller County:	999
Spiller Contact:	BILL MAKKOS EQUITIES
Spiller Phone:	2127368700
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	420413
DEC Memo:	"8/04/2015: Rashad Spill transferred from Sangesland to Rashad as per RSE. As per NYC building records 65 Greene Street has alternate address of 65-65 Greene Street. Searched PBS and spills database, no other records found for property. 8/06/2015: Rashad No documents found in D2. Owners information: 67-65 Greene Street, LLC 349 West 37th Street New York, NY 10018 8/10/2015: Rashad Spoke to Marisol at Petroleum Tank Cleaners she indicated that she will send us any relevant documentation that she can find. Also spoke to Mark Salamack, he indiacted he would look into this site. Email to Mark: I am currently reviewing spill reports under Jeff s temporary supervision for 1712 Second Avenue, Manhattan NY spill #1203598 as well as 65 Greene Street, Manhattan NY spill#1203271. I would like to request the following information if possible for each site: Copy of

TTF (Continued) **S112148820**

failed tank test report. Supply/return and vent/fill test results. Current property owner and contact information. 8/11/2015: Rashad Mark replied to email: I have been in touch with Petroleum's office ..I know they have the information on the 65 Greene Street job...we tested a 1080 gallon tank and it failed...they never authorized us to continue with any other work...I can get the owner's contact information for you when I get back from vacation. On the 2nd Avenue job, they are having trouble finding the information on the job...do you have a date for it?. I responded The 1712 Second Ave spill was recorded on 7/13/2012. I appreciate your help. Marisol has indicated she will fax relevant information. 8/13/2015: Rashad Marisol faxed documents on 8/11/2015 - 3:08 pm. Failed tank test report indicates ullage (dry) portion leak. Document uploaded to D2. 8/17/2015: Rashad Mark Salamck emailed: Omar...the owner's contact info for 65 Greene Street: Makkos Equities 349 West 37th Street NY, NY10018 Ph# 212 736-8700 Thomas Makkos is owner per DOB job filling records email is thomasmakkos@aol.com 9/4/2015: Rashad Sent TTF letter to Makkos Equities. Letter uploaded to D2. 9/17/2015: Rashad Received letter from William Castoro, property manager for 65 Greene Street with Tank Abandonment Affidavit. Letter and affidavit have been uploaded to D2. 12/17/2015: Rashad Based on discussion with Tim due to tank closure affidavit and dry leak specified by ttf report which also indicates that tank was almost full, having 800 gallons in 1080 gallon tank case will be closed."

Remarks: "failed tank - leaking - clean up pending"

All Materials:

Site ID:	466068
Operable Unit ID:	1216078
Operable Unit:	01
Material ID:	2214240
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

922
ENE
1/4-1/2
0.489 mi.
2583 ft.

PS 19-M **NY LTANKS** **S104782074**
185 1ST AVE **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
23 ft.

LTANKS:

Facility ID:	0005678
Site ID:	168156
Closed Date:	2005-12-19
Spill Number:	0005678
Spill Date:	2000-08-11
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3101

PS 19-M (Continued) **S104782074**

Investigator:	AJWHITE
Referred To:	Not reported
Reported to Dept:	2000-08-11
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-11
Spill Record Last Update:	2005-12-19
Spiller Name:	CALLER
Spiller Company:	PS 19-M
Spiller Address:	185 1ST AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	141654
DEC Memo:	" 11/15/2005: Lead transferred to Joe White as part of the Spill Initiative Project. 12/08/2005: Mr. James Merlo, the coordinator for NYC School spills, called Joe White to indicate that the tank has been retested and passed. These passing results will be sent to the DEC for closure of failed tank test. 12/19/2005: Joe White received information from James Merlo documenting a subsequent tank test passing on 7/13/2005 and a certification printed on 12/9/2005. Tank number 2 at this location has been administratively closed. The PBS # associated with this location is 2-478318. This documentation is sufficient for closing the spill."
Remarks:	"tank failed test"

All TTF:

Facility ID:	0005678
Spill Number:	0005678
Spill Tank Test:	1525830
Site ID:	168156
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	168156
Operable Unit ID:	828247
Operable Unit:	01

PS 19-M (Continued) **S104782074**

Material ID:	546830
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CB923 **APT BUILDING** **NY LTANKS** **S114561765**
SW **62 GREENE ST** **N/A**
1/4-1/2 **MANHATTAN, NY**
0.490 mi.
2587 ft. **Site 2 of 2 in cluster CB**

Relative: **Lower**
Actual: **19 ft.**

LTANKS:

Facility ID:	1306972
Site ID:	487621
Closed Date:	2014-04-11
Spill Number:	1306972
Spill Date:	2013-10-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2013-10-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-10-03
Spill Record Last Update:	2014-04-11
Spiller Name:	Not reported
Spiller Company:	APT BUILDING
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROB JOHNSON
Spiller Phone:	(631) 942-9747
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	442736
DEC Memo:	"10/03/13-Zhune spoke to Donna from ABC tank. She indicated they performed a tightness test to the tank and failed the test with a dry leak. They can not say if there is oil spill because the tank is vaulted and they can not see the bottom of the tank. She sent the proposal to the owner to do the isolation test. " A tightness test was performed on (1) 2,000 gallon tank located at the above referenced address. The tank did not pass the test. Spill # 1306972 was assigned. " ABC Tank pumped out all product from the interior of

APT BUILDING (Continued) **S114561765**

the tank. The interior of the tank was cleaned. All lines were disconnected from the top of the tank to isolate the tank from the system. " A pressure test was performed on the isolated tank. The tank did not hold the pressure. A visual inspection was performed on the interior of the tank. The top of the tank had numerous holes and the steel on top of the tank was in poor condition. " ABC Tank obtained (3) soil samples along the bottom of the tank. Resluts indicated low level VOCs below CP-51 standards. SVOCs were observed slightly above. Possible due to fill material. 4//11/14- DEC Piper reviewed documentaiton of tank removal done by Don Carlo Env. Based on samples and removal of 2K AST, this spill is closed. Will notify ABC Tank to u[pdate status in PBS program. "

Remarks: "2000 gal tank in vault/dry leak"

All Materials:

Site ID:	487621
Operable Unit ID:	1237254
Operable Unit:	01
Material ID:	2236878
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

924
SW
1/4-1/2
0.492 mi.
2600 ft.

BUILDING **NY LTANKS** **S106124120**
38 CROSBY ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
27 ft.

LTANKS:

Facility ID:	0312394
Site ID:	139377
Closed Date:	2005-02-08
Spill Number:	0312394
Spill Date:	2004-02-07
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2004-02-07
CID:	41
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-07

BUILDING (Continued) **S106124120**

Spill Record Last Update:	2005-02-08
Spiller Name:	FRANK AMATO
Spiller Company:	BLT TRANSPORT
Spiller Address:	50 COMMERCE ST
Spiller County:	001
Spiller Contact:	JOE RAMIREZ
Spiller Phone:	(917) 444-8678
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	119064
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 2/8/05 TJD All product spilled to concrete. Cleaned by spiller. No further action required. Spill closed. "
Remarks:	"BEING CLEANED UP BY BLT TRANSPORT. DISPOSING OF MATERIAL AT PETROLEUM TANK CLEANERS. NOTE: ORIGINAL CALL CAME IN FROM RAYMOND SEVERINO (CONCIERGE OF BLDG) REPORTING SPILL ON SIDEWALK AND THAT CASTLE OIL WAS OUTSIDE THE BUILDING. DUE TO A SLIGHT LANGUAGE BARRIER, I CONTACTED CASTLE OIL DIRECTLY. THEY ADVISED ME THAT BLT TRANSPORT WAS THE CARRIER AND THAT THEY WOULD HAVE BLT CALL ME DIRECTLY. THEY DID AND THE CONCIERGE WAS NOTIFIED OF SAME - SPILL NUMBER PROVIDED FOR HIS RECORDS."

All Materials:

Site ID:	139377
Operable Unit ID:	877631
Operable Unit:	01
Material ID:	562766
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

925
West
1/4-1/2
0.497 mi.
2624 ft.

SPILL NUMBER 0112067 **NY LTANKS** **S105995445**
2 KING ST **N/A**
MANHATTAN, NY

Relative:
Lower

Actual:
22 ft.

LTANKS:

Facility ID:	0112067
Site ID:	236703
Closed Date:	2002-07-22
Spill Number:	0112067
Spill Date:	2002-03-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	3101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2002-03-22
CID:	199

SPILL NUMBER 0112067 (Continued) **S105995445**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-22
Spill Record Last Update:	2002-07-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	NICK MARINOV
Spiller Phone:	(212) 661-1150
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	194999
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND/VOUGHT 7/22/2002-VOUGHT-Spoke with Dave Fazin on 6/13: PTC replaced lines 8 years ago. Tank was cut open and old suction/return lines were not plugged causing tank failure. Lines were plugged and tank passed test (passing test results and invoice by PTC provided to NYSDEC). Spill closed by Vought."
Remarks:	"tank top will be excavated and tank only test will be done"

All TTF:

Facility ID:	0112067
Spill Number:	0112067
Spill Tank Test:	1526959
Site ID:	236703
Tank Number:	1
Tank Size:	6000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	236703
Operable Unit ID:	849004
Operable Unit:	01
Material ID:	526081
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SPILL NUMBER 0112067 (Continued) **S105995445**

Oxygenate: Not reported

926
NW
1/2-1
0.577 mi.
3048 ft.

MARKITE CO.
155 WAVERLY PLACE
NEW YORK, NY

FUSRAP **1016603386**
N/A

Relative:
Lower

Actual:
19 ft.

FUSRAP:

Site Name:	MARKITE CO.
Site Id:	NY.49
Site Status:	Eliminated from consideration under FUSRAP
Designated Name:	Not Designated
Alternate Name:	None
Location Street Address:	155 WAVERLY PLACE
Location City:	NEW YORK
Location State:	NY
Location County:	Not reported
Evaluation Year:	1987
Site Oprerations:	Conducted experiments with very small amounts of uranium and thorium.
Site Disposition:	Eliminated - Handled limited amounts of radioactive materials - Potential for contamination remote
Radioactice Materials Handled:	Yes
Primary Radioactivce Materials Handled:	Uranium, Thorium
Radiological Survey(S):	None Indicated
Long Term Care Requirements:	Not reported
Historical Operations:	Not reported
Website URL:	http://www.lm.doe.gov/Considered_Sites/Markite_Co_-_NY_49.aspx

---

927
WSW
1/2-1
0.608 mi.
3212 ft.

LEDOUX AND CO.
155 AVENUE OF THE AMERICAS
NEW YORK, NY

FUSRAP **1016603379**
N/A

Relative:
Lower

Actual:
18 ft.

FUSRAP:

Site Name:	LEDOUX AND CO.
Site Id:	NY.37
Site Status:	Eliminated from further consideration under FUSRAP
Designated Name:	Not Designated
Alternate Name:	None
Location Street Address:	155 AVENUE OF THE AMERICAS
Location City:	NEW YORK
Location State:	NY
Location County:	Not reported
Evaluation Year:	1987
Site Oprerations:	Prime contractor to AEC, African Metals. LeDoux handled radioactive materials under this contract at other locations; records indicate that radioactive materials were not sent to the New York office.
Site Disposition:	Eliminated - Potential for contamination considered remote - Radioactive materials were not handled
Radioactice Materials Handled:	No
Primary Radioactivce Materials Handled:	None
Radiological Survey(S):	None Indicated
Long Term Care Requirements:	Not reported

LEDOUX AND CO. (Continued) **1016603379**

Historical Operations: Not reported
Website URL: http://www.lm.doe.gov/Considered_Sites/Ledoux_and_Co_-_NY_37.aspx

---

928
SSW
1/2-1
0.667 mi.
3522 ft.

CON EDISON - HESTER ST. GAS WORKS MGP **EDR MGP** **1008407991**
HESTER STREET **N/A**
NEW YORK, NY 10002

Relative:
Lower

Actual:
37 ft.

Manufactured Gas Plants:
No additional information available

929
SSW
1/2-1
0.697 mi.
3679 ft.

CON EDISON - CANAL ST. WORKS MGP **EDR MGP** **1008408208**
CANAL STREET **N/A**
NEW YORK, NY 10013

Relative:
Lower

Actual:
14 ft.

Manufactured Gas Plants:
No additional information available

930
WNW
1/2-1
0.743 mi.
3925 ft.

HUDSON DRY CLEANERS **NY SHWS** **S110246833**
462 HUDSON STREET **NY DRYCLEANERS** **N/A**
MANHATTAN, NY 10014

Relative:
Lower

Actual:
16 ft.

SHWS:
Program: HW
Site Code: 486480
Classification: P
Region: 2
Acres: 0.57
HW Code: 231085
Record Add: 09/04/2013
Record Upd: 10/02/2017
Updated By: TJKILLEE
Site Description: Location: The 25,000 square foot (0.57 acre) site is located at 462 Hudson Street in the Borough of Manhattan in an urban area. The site is bordered by Hudson Street to the west, Barrow Street to the north, one and two-family brownstones to the east, and by Morton Street to the south. Site Features: The site is occupied by a two 6-story apartment buildings with commercial uses on the first floor along Hudson St. The dry cleaner occupies the northwest corner of the first floor of the northern building. Current Zoning/Use(s): The site is zoned as C1-6/R6 for commercial and residential uses. Historical Use(s): The on-site building was constructed in 1925. A dry cleaner has operated at the site since at least 1986. The site is a RCRA large quantity generator (EPA ID # NYD981141948) of spent solvent, waste code F002. Site Topography, Geology and Hydrogeology: The Site is generally level and is at an elevation of approximately 36 feet

HUDSON DRY CLEANERS (Continued) **S110246833**

above mean sea level. The geology of New York County consists of unconsolidated glacial deposits overlying crystalline bedrock. Soil cores collected during investigation on a nearby site generally consisted of historic fill material containing brown sand and silt with fine gravel and brick fragments to a depth of 8 to 15 feet bgs. The Site is located 1300 feet east of the Hudson River. Groundwater in the vicinity of the site was encountered at approximately 27 feet bgs and is expected to flow to the west towards the Hudson River.

Env Problem: Nature and Extent of Contamination: Information is based on the results of a site characterization investigation performed at the nearby property at 75 Morton Street by the NYC School Construction Authority. That investigation was triggered by the discovery of elevated levels of cVOCs in groundwater on that site. The subsequent Supplemental Site Investigation (SSI) indicated that elevated concentrations of cVOCs (namely PCE) existed along the adjacent sidewalk on the eastern side of Hudson Street. The SSI ascertained that the 75 Morton Street site was not a source of the contamination. Eleven temporary groundwater wells were installed on and upgradient from the Morton Street property and samples were collected for lab analysis. One well was installed immediately in front of and downgradient from the Hudson Cleaners site. Groundwater: Tetrachloroethylene (PCE) was detected at elevated concentrations in groundwater samples taken immediately in front of the Hudson Cleaners site. PCE was detected at a concentration of 2900 ppb at that location, with concentrations decreasing in the downgradient direction consistent with the inferred contaminant plume. The groundwater flow direction was confirmed to be from east to west based on surveyed groundwater elevation measurements collected during the 75 Morton St. SSI. Building owners' contractor completed Phase II scope of work at and around Hudson Dry Cleaners in the fall of 2016. The groundwater sample taken in front of this site had only 2.1 ppb PCE, versus 2900 ppb in May 2013. Another round of sampling concentrating on VI evaluation is being done (spring 2017) at DOH's request. Significant Threat: Evaluation of significant threat will be made following completion of the Site Characterization.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: E
Owner Name: Michael Sass
Owner Company: Z H Control Co., LLC
Owner Address: c/o ABS Partners Real Estate
Owner Addr2: 200 Park Avenue South, 10th Floor
Owner City,St,Zip: New York, NY 10003

HUDSON DRY CLEANERS (Continued) **S110246833**

Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Byung Woo Kim
Owner Company:	Hudson Kim Cleaners, Inc.
Owner Address:	462 Hudson Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10014
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

DRYCLEANERS:

Facility ID:	2-6205-00290
Phone Number:	212-242-4518
Region:	Not reported
Registration Effective Date:	9/8/2003 11:12:38:006
Inspection Date:	17JAN23
Install Date:	90/02/17
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

931
ENE
1/2-1
0.842 mi.
4448 ft.

CON EDISON - EAST 17TH ST. WORKS MGP **EDR MGP** **1008407985**
EAST 17TH - EAST 18TH STS. **N/A**
NEW YORK, NY 10009

Relative:
Lower

Actual:
9 ft.

Manufactured Gas Plants:
No additional information available

932
ENE
1/2-1
0.947 mi.
5000 ft.

CON EDISON - EAST 21ST ST. WORKS MGP **EDR MGP** **1008407987**
EAST 20TH - EAST 22ND STS. **N/A**
NEW YORK, NY 10009

Relative:
Lower

Actual:
9 ft.

Manufactured Gas Plants:
No additional information available

933
SSW
1/2-1
0.981 mi.
5180 ft.

CON EDISON - CROSS/LITTLE WATER STS. MGP
60 CENTRE ST
NEW YORK, NY 10007

EDR MGP **1008407979**
N/A

Relative:
Lower

Actual:
17 ft.

Manufactured Gas Plants:
No additional information available

Count: 6 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
MANHATTAN	S113922053	PROPOSED FEDERAL EXPRESS DISTRIBUT	BETWEEN 17TH & 18TH STREETS &	10011	NY VCP
MANHATTAN	S108147123	WILLIAMSBURGE	DELANCEY STREET	10002	NY HSWDS
NEW YORK	S102672058	76TH ST BET. BROADWAY	76TH ST BET BROADWAY		NY LTANKS
NEW YORK	S113916762	WEST 9TH STREET GW	WEST 9TH STREET	10011	NY SHWS
NEW YORK	S112231289	DERMONT CO - TTF	75-79 AND 81-83 ORCHARD ST		NY LTANKS
ROCKAWAY	S118950574	EDGEMERE LANDFILL	BEACH CHANNEL DRIVE AND BEACH	10013	NY SHWS, NY VAPOR REOPENED

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/22/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/06/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 66

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 66

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 02/16/2018
Date Data Arrived at EDR: 02/22/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 78

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/09/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/13/2018
Date Data Arrived at EDR: 02/27/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/29/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/13/2018
Date Data Arrived at EDR: 02/27/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/29/2018
Next Scheduled EDR Contact: 09/10/2018
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 01/16/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 63

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/08/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/16/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/24/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/12/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/12/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 01/06/2018
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/16/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/27/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/27/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/12/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 01/13/2018
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/24/2017
Date Data Arrived at EDR: 07/27/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 134

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/14/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/16/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/24/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 80

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 04/30/2018
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/23/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 06/27/2017
Date Data Arrived at EDR: 09/21/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 1

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/21/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Semi-Annually

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/29/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 46

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/15/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 01/19/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/21/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 12/12/2017
Date Data Arrived at EDR: 12/14/2017
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/08/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/30/2018
Next Scheduled EDR Contact: 05/14/2018
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 05/04/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 02/22/2018
Date Data Arrived at EDR: 03/01/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/27/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/22/2018
Date Data Arrived at EDR: 03/01/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/27/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 02/13/2018
Date Data Arrived at EDR: 02/16/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 39
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 94
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 01/19/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 63
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/12/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/16/2018
Number of Days to Update: 30
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/16/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/11/2017
Date Data Arrived at EDR: 12/26/2017
Date Made Active in Reports: 02/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/28/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/25/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/11/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/15/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 01/11/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/27/2018
Next Scheduled EDR Contact: 07/09/2018
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/07/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/08/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/23/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/25/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/09/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 94

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 11/02/2017
Date Data Arrived at EDR: 11/17/2017
Date Made Active in Reports: 12/08/2017
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/20/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2017
Date Data Arrived at EDR: 06/09/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 126

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 04/09/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 03/09/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/06/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/03/2018
Date Data Arrived at EDR: 01/04/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 99

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/05/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 79

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 04/06/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/25/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/11/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 12/23/2016
Date Data Arrived at EDR: 12/27/2016
Date Made Active in Reports: 02/17/2017
Number of Days to Update: 52

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/07/2018
Next Scheduled EDR Contact: 08/20/2018
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/09/2018
Date Data Arrived at EDR: 02/06/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 24

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 04/27/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 01/25/2018
Date Data Arrived at EDR: 02/28/2018
Date Made Active in Reports: 05/11/2018
Number of Days to Update: 72

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/28/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/02/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/02/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/20/2017
Date Data Arrived at EDR: 12/21/2017
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 92

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/21/2018
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 28

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 02/23/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 01/04/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 04/13/2018
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 03/02/2018
Next Scheduled EDR Contact: 06/11/2018
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 01/13/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 03/02/2018
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2016
Date Data Arrived at EDR: 10/31/2017
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 73

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 04/13/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/20/2018
Date Data Arrived at EDR: 02/21/2018
Date Made Active in Reports: 03/23/2018
Number of Days to Update: 30

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/23/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 02/07/2018
Date Data Arrived at EDR: 02/13/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/20/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 09/25/2017
Date Data Arrived at EDR: 09/26/2017
Date Made Active in Reports: 10/12/2017
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 11/22/2017
Date Data Arrived at EDR: 12/14/2017
Date Made Active in Reports: 01/29/2018
Number of Days to Update: 46

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 02/14/2018
Date Data Arrived at EDR: 03/23/2018
Date Made Active in Reports: 05/14/2018
Number of Days to Update: 52

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/19/2018
Next Scheduled EDR Contact: 07/02/2018
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 12/01/2017
Date Data Arrived at EDR: 01/02/2018
Date Made Active in Reports: 01/31/2018
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/02/2018
Next Scheduled EDR Contact: 07/16/2018
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 03/09/2017
Date Data Arrived at EDR: 04/12/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 184

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 03/07/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/31/2018
Date Made Active in Reports: 03/09/2018
Number of Days to Update: 37

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/03/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/25/2017
Date Data Arrived at EDR: 10/27/2017
Date Made Active in Reports: 11/28/2017
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/06/2018
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2018
Date Data Arrived at EDR: 02/15/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 40

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/04/2018
Date Data Arrived at EDR: 03/08/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/08/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 01/02/2018
Date Data Arrived at EDR: 03/05/2018
Date Made Active in Reports: 03/29/2018
Number of Days to Update: 24

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 01/02/2018
Date Data Arrived at EDR: 03/05/2018
Date Made Active in Reports: 03/29/2018
Number of Days to Update: 24

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/01/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/01/2018
Next Scheduled EDR Contact: 06/18/2018
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 01/05/2018
Date Data Arrived at EDR: 02/20/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 35
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Semi-Annually

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 01/05/2018
Date Data Arrived at EDR: 02/20/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 35

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/30/2018
Next Scheduled EDR Contact: 08/13/2018
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 01/03/2018
Date Data Arrived at EDR: 02/14/2018
Date Made Active in Reports: 03/22/2018
Number of Days to Update: 36

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/18/2018
Next Scheduled EDR Contact: 08/27/2018
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 04/11/2017
Date Made Active in Reports: 07/27/2017
Number of Days to Update: 107

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/23/2018
Next Scheduled EDR Contact: 07/23/2018
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 07/25/2017
Date Made Active in Reports: 09/25/2017
Number of Days to Update: 62

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/12/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/21/2018
Next Scheduled EDR Contact: 09/03/2018
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 01/12/2018
Date Data Arrived at EDR: 01/19/2018
Date Made Active in Reports: 02/13/2018
Number of Days to Update: 25

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/16/2018
Next Scheduled EDR Contact: 07/30/2018
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 04/13/2017
Date Made Active in Reports: 07/14/2017
Number of Days to Update: 92

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/08/2018
Next Scheduled EDR Contact: 06/25/2018
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

375 LAFAYETTE STREET
375 LAFAYETTE STREET
NEW YORK, NY 10003

TARGET PROPERTY COORDINATES

Latitude (North):	40.727296 - 40° 43' 38.27''
Longitude (West):	73.993162 - 73° 59' 35.38''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	585027.6
UTM Y (Meters):	4508761.0
Elevation:	42 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940597 BROOKLYN, NY
Version Date:	2013
Southwest Map:	6048959 JERSEY CITY, NJ
Version Date:	2014

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 42 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970201F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970182F	FEMA FIRM Flood data
3604970184F	FEMA FIRM Flood data
3604970203F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/2 - 1 Mile North
Site Name:	AMERICAN RADIUM INDUSTRIES
Site EPA ID Number:	NYD987001476
Groundwater Flow Direction:	NOT AVAILABLE.
Inferred Depth to Water:	not available. Saturated layers impacted by salt water intrusion are present in the overburden. It is generally inferred that the depth to the uppermost 'aquifer' is greater than 70 feet at the surface of the bedrock/sediment interface.
Hydraulic Connection:	Detailed hydraulic connection information is not available. Glacial till and outwash deposit sediments overlie the Manhattan Schist, the uppermost bedrock unit at the site. The surface elevation of bedrock decreases to the southwest of the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT **GEOLOGIC AGE IDENTIFICATION**

Era:	Paleozoic	Category:	Stratified Sequence
System:	Ordovician		
Series:	Middle Ordovician (Mohawkian)		
Code:	O2 *(decoded above as Era, System & Series)*		

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000830175	0 - 1/8 Mile ENE
2	USGS40000830096	0 - 1/8 Mile South
A3	USGS40000829989	1/4 - 1/2 Mile SSW
4	USGS40000830007	1/4 - 1/2 Mile SE
A5	USGS40000829948	1/4 - 1/2 Mile SSW
6	USGS40000829893	1/4 - 1/2 Mile South
7	USGS40000829894	1/4 - 1/2 Mile SW
B8	USGS40000830447	1/4 - 1/2 Mile NE
9	USGS40000829947	1/4 - 1/2 Mile SE
B10	USGS40000830462	1/4 - 1/2 Mile NE
11	USGS40000829884	1/4 - 1/2 Mile SE
C12	USGS40000829780	1/2 - 1 Mile SSW
D13	USGS40000829748	1/2 - 1 Mile South
C14	USGS40000829749	1/2 - 1 Mile South
D15	USGS40000829747	1/2 - 1 Mile South
D16	USGS40000829746	1/2 - 1 Mile South
17	USGS40000829835	1/2 - 1 Mile SE
E18	USGS40000829781	1/2 - 1 Mile SW
E19	USGS40000829782	1/2 - 1 Mile SW
20	USGS40000829733	1/2 - 1 Mile SSW
F21	USGS40000829869	1/2 - 1 Mile SW
F22	USGS40000829870	1/2 - 1 Mile SW
23	USGS40000830200	1/2 - 1 Mile West
F24	USGS40000829885	1/2 - 1 Mile SW
F25	USGS40000829886	1/2 - 1 Mile SW
26	USGS40000829937	1/2 - 1 Mile WSW
27	USGS40000829657	1/2 - 1 Mile South
G28	USGS40000829683	1/2 - 1 Mile SSW
29	USGS40000830018	1/2 - 1 Mile WSW
H30	USGS40000829825	1/2 - 1 Mile SW
H31	USGS40000829846	1/2 - 1 Mile WSW
G32	USGS40000829658	1/2 - 1 Mile SSW
I33	USGS40000830201	1/2 - 1 Mile West
I34	USGS40000830224	1/2 - 1 Mile West
I35	USGS40000830230	1/2 - 1 Mile West
36	USGS40000829824	1/2 - 1 Mile SE
I37	USGS40000830231	1/2 - 1 Mile West
38	USGS40000830321	1/2 - 1 Mile WNW
39	USGS40000829723	1/2 - 1 Mile SW
J40	USGS40000830493	1/2 - 1 Mile WNW
K42	USGS40000830097	1/2 - 1 Mile West
K43	USGS40000830099	1/2 - 1 Mile West
K44	USGS40000830098	1/2 - 1 Mile West
L45	USGS40000829562	1/2 - 1 Mile South
M46	USGS40000830392	1/2 - 1 Mile WNW
M47	USGS40000830393	1/2 - 1 Mile WNW
M48	USGS40000830394	1/2 - 1 Mile WNW
49	USGS40000829656	1/2 - 1 Mile SE
L50	USGS40000829530	1/2 - 1 Mile South
51	USGS40000829539	1/2 - 1 Mile SSE
52	USGS40000829599	1/2 - 1 Mile SW
53	USGS40000829836	1/2 - 1 Mile WSW

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
54	USGS40000829598	1/2 - 1 Mile SE
N55	USGS40000830914	1/2 - 1 Mile NNE
N56	USGS40000830913	1/2 - 1 Mile NNE
O57	USGS40000829499	1/2 - 1 Mile South
58	USGS40000829507	1/2 - 1 Mile South
59	USGS40000829684	1/2 - 1 Mile SW
P60	USGS40000829897	1/2 - 1 Mile WSW
P61	USGS40000829896	1/2 - 1 Mile WSW
P62	USGS40000829895	1/2 - 1 Mile WSW
Q63	USGS40000829783	1/2 - 1 Mile WSW
Q64	USGS40000829795	1/2 - 1 Mile WSW
Q65	USGS40000829794	1/2 - 1 Mile WSW
Q66	USGS40000829793	1/2 - 1 Mile WSW
Q67	USGS40000829796	1/2 - 1 Mile WSW
Q68	USGS40000829799	1/2 - 1 Mile WSW
Q69	USGS40000829798	1/2 - 1 Mile WSW
Q70	USGS40000829797	1/2 - 1 Mile WSW
71	USGS40000830929	1/2 - 1 Mile NNW
P72	USGS40000829847	1/2 - 1 Mile WSW
73	USGS40000829635	1/2 - 1 Mile SW
O74	USGS40000829461	1/2 - 1 Mile South
R75	USGS40000829459	1/2 - 1 Mile South
R76	USGS40000829460	1/2 - 1 Mile South
77	USGS40000829579	1/2 - 1 Mile SW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG80000035708	0 - 1/8 Mile South
A3	NYOG80000035707	0 - 1/8 Mile East
A2	NYOG80000035687	0 - 1/8 Mile East
4	NYOG80000035722	0 - 1/8 Mile NNW
B6	NYOG80000035802	1/4 - 1/2 Mile South
B5	NYOG80000035803	1/4 - 1/2 Mile South
C7	NYOG80000035660	1/4 - 1/2 Mile WNW

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
B9	NYOG80000035805	1/4 - 1/2 Mile South
B8	NYOG80000035804	1/4 - 1/2 Mile South
C10	NYOG80000035661	1/4 - 1/2 Mile WNW
B12	NYOG80000035799	1/4 - 1/2 Mile South
B11	NYOG80000035798	1/4 - 1/2 Mile South
B14	NYOG80000035801	1/4 - 1/2 Mile South
B13	NYOG80000035800	1/4 - 1/2 Mile South
15	NYOG80000035682	1/4 - 1/2 Mile SSW
16	NYOG80000035667	1/4 - 1/2 Mile SE
17	NYOG80000035806	1/4 - 1/2 Mile NE
18	NYOG80000035680	1/4 - 1/2 Mile SW
D19	NYOG80000035731	1/2 - 1 Mile SSW
D20	NYOG80000035728	1/2 - 1 Mile South
E21	NYOG80000035671	1/2 - 1 Mile SSW
E22	NYOG80000035677	1/2 - 1 Mile SSW
23	NYOG80000035732	1/2 - 1 Mile SSW
F24	NYOG80000035672	1/2 - 1 Mile SSW
25	NYOG80000035713	1/2 - 1 Mile South
G26	NYOG80000035696	1/2 - 1 Mile West
G27	NYOG80000035697	1/2 - 1 Mile West
F28	NYOG80000035662	1/2 - 1 Mile SSW
29	NYOG80000035845	1/2 - 1 Mile NW
30	NYOG80000035683	1/2 - 1 Mile SW
31	NYOG80000035698	1/2 - 1 Mile WNW
32	NYOG80000035819	1/2 - 1 Mile WSW
33	NYOG80000035712	1/2 - 1 Mile South
H34	NYOG80000035847	1/2 - 1 Mile NNE
H36	NYOG80000035848	1/2 - 1 Mile NNE
H35	NYOG80000035846	1/2 - 1 Mile NNE
I37	NYOG80000035797	1/2 - 1 Mile NNW
I38	NYOG80000035796	1/2 - 1 Mile NNW
39	NYOG80000035820	1/2 - 1 Mile NW
40	NYOG80000035663	1/2 - 1 Mile SW
41	NYOG80000035710	1/2 - 1 Mile South
J42	NYOG80000035825	1/2 - 1 Mile WSW
J43	NYOG80000035824	1/2 - 1 Mile WSW
K45	NYOG80000035832	1/2 - 1 Mile West
K44	NYOG80000035831	1/2 - 1 Mile West
K46	NYOG80000035827	1/2 - 1 Mile WSW
47	NYOG80000035725	1/2 - 1 Mile NNE
K49	NYOG80000035830	1/2 - 1 Mile West
K48	NYOG80000035829	1/2 - 1 Mile West
K50	NYOG80000035828	1/2 - 1 Mile WSW
51	NYOG80000035714	1/2 - 1 Mile South
52	NYOG80000035681	1/2 - 1 Mile SW
53	NYOG80000035730	1/2 - 1 Mile South
54	NYOG80000035664	1/2 - 1 Mile WSW
55	NYOG80000035808	1/2 - 1 Mile NW
56	NYOG80000035715	1/2 - 1 Mile South

PHYSICAL SETTING SOURCE MAP - 5314975.2s



County Boundary
Major Roads
Contour Lines
Airports
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
GI Indeterminate Groundwater Flow at Location
GV Groundwater Flow Varies at Location
HD Closest Hydrogeological Data
Oil, gas or related wells

N

SITE NAME:	375 Lafayette Street	CLIENT:	Langan Engineering
ADDRESS:	375 Lafayette Street New York NY 10003	CONTACT:	Amanda Forsburg
		INQUIRY #:	5314975.2s
LAT/LONG:	40.727296 / 73.993162	DATE:	May 30, 2018 7:42 am

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
ENE **FED USGS** **USGS40000830175**
0 - 1/8 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404339073593301		
Monloc name:	NY 185		
Monloc type:	Well		
Monloc desc:	EAST 4TH STREET & BOWERY		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7276022
Longitude:	-73.9920836	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	minutes
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	44.19
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	653.68
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-07-26		5.42	2004-04-21		6.12
2004-02-18		6.60	2003-09-15		6.78
2003-08-27		6.75	2003-06-24		6.48
2002-10-09		5.34	2002-06-25		5.24
2002-04-03		5.37	2002-01-09		5.57

2
South **FED USGS** **USGS40000830096**
0 - 1/8 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404334073593601		
Monloc name:	NY 202		
Monloc type:	Well		
Monloc desc:	BOND ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7262411
Longitude:	-73.9931392	Sourcemap scale:	24000

Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	47.37
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	604
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A3
SSW **FED USGS** **USGS40000829989**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404326073594501		
Monloc name:	NY 119		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7239911
Longitude:	-73.995417	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	45
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	65
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

4
SE **FED USGS** **USGS40000830007**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404327073592501		
Monloc name:	NY 70		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7242689
Longitude:	-73.9898614	Sourcemap scale:	24000

Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	75
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A5
SSW **FED USGS** **USGS40000829948**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404324073594501		
Monloc name:	NY 231		
Monloc type:	Well		
Monloc desc:	MULBERRY ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7234633
Longitude:	-73.9956115	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	42.07
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	570
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-04-19		3.56	2004-04-05		3.65
2004-02-18		3.98			

6
South **FED USGS** **USGS40000829893**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404321073594101		
Monloc name:	NY 192. 1		
Monloc type:	Well		
Monloc desc:	PRINCE & ELIZABETH STREETS-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7227245
Longitude:	-73.9943031	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	46.87
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20010410	Welldepth:	665
Welldepth units:	ft	Wellholedepth:	665
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 19

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		2.32	2004-11-10		4.52
2004-07-26		4.68	2004-06-28		4.56
2004-04-19		4.32	2004-02-18		4.47
2004-01-07		4.51	2003-11-21		4.40
2003-10-08		4.21	2003-10-01		4.28
2003-10-01		4.25	2003-09-29		4.28
2003-09-17		4.42	2003-08-27		4.63
2003-06-24		4.75	2002-10-09		3.83
2002-06-25		3.71	2002-04-03		3.67
2002-01-09		3.72			

7
SW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000829894**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404321073595301		
Monloc name:	NY 232		
Monloc type:	Well		
Monloc desc:	CROSBY ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7228522
Longitude:	-73.9978894	Sourcemap scale:	24000

Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	33.47
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	578
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-04-19		2.44	2004-04-05		2.43
2004-02-18		2.76			

B8
NE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000830447**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404354073591901		
Monloc name:	NY 205		
Monloc type:	Well		
Monloc desc:	EAST 12 ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7318799
Longitude:	-73.9883891	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	38.65
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	538
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

9
SE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000829947**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404324073591601		
Monloc name:	NY 67		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7234356
Longitude:	-73.9873613	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	22
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

B10
NE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000830462**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404355073592001		
Monloc name:	NY 171		
Monloc type:	Well		
Monloc desc:	EAST 12TH STREET-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7320465
Longitude:	-73.9884724	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	minutes
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	38.65
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	538
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

11
SE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000829884**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404320073591901		
Monloc name:	NY 18		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7223245
Longitude:	-73.9881946	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	46
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

C12
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829780**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404312073594401		
Monloc name:	NY 178. 1		
Monloc type:	Well		
Monloc desc:	ELIZABETH ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7201329
Longitude:	-73.9952337	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	37.88
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		

Aquifer type:	Not Reported		
Construction date:	20020718	Welldepth:	600
Welldepth units:	ft	Wellholedepth:	600
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 9

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		2.18	2004-11-10		4.24
2004-07-26		4.57	2004-04-19		4.30
2004-02-18		4.08	2003-09-24		4.02
2003-08-27		4.23	2003-06-24		4.24
2002-10-09		3.77			

D13
South
1/2 - 1 Mile
Lower

FED USGS **USGS40000829748**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404310073593701		
Monloc name:	NY 175		
Monloc type:	Well		
Monloc desc:	FORSYTH ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7198245
Longitude:	-73.9934726	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	40.31
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	600.87
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2002-10-09		3.24	2002-07-09		3.11
2002-06-25		3.08			

C14
South
1/2 - 1 Mile
Lower

FED USGS **USGS40000829749**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404310073594201		
Monloc name:	NY 169. 1		
Monloc type:	Well		
Monloc desc:	BROOME STREET-B		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7197245
Longitude:	-73.9947087	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	38.57
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20010405	Welldepth:	664.82
Welldepth units:	ft	Wellholedepth:	664.82
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		4.15	2004-11-10		5.67
2004-07-26		6.06	2004-04-19		5.71
2004-02-18		5.50	2003-09-24		5.99
2003-08-27		6.19	2003-06-24		6.15
2002-10-09		5.81	2002-06-25		6.09
2002-04-03		6.03	2002-01-09		5.90

D15
South
1/2 - 1 Mile
Lower

FED USGS **USGS40000829747**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404310073593402		
Monloc name:	NY 109		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7195468
Longitude:	-73.9923614	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	45
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	177
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

D16
South **FED USGS** **USGS40000829746**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404310073593401		
Monloc name:	NY 108		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7195468
Longitude:	-73.9923614	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	45
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	402
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

17
SE **FED USGS** **USGS40000829835**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404317073591001		
Monloc name:	NY 20		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7214912
Longitude:	-73.9856946	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	30
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	43
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

E18
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829781**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404312073595901		
Monloc name:	NY 216		
Monloc type:	Well		
Monloc desc:	GRAND ST-B		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.720269
Longitude:	-73.9993894	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	25.61
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	547.4
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-07-26		1.20	2004-04-21		1.22
2004-02-18		1.26	2003-11-24		1.31

E19
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829782**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404312073595902		
Monloc name:	NY 244. 1		
Monloc type:	Well		
Monloc desc:	GRAND ST-W		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.720269
Longitude:	-73.9993894	Sourcemap scale:	24000

Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	25.63
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	66.6
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

20
SSW **FED USGS** **USGS40000829733**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404309073595101		
Monloc name:	NY 215. 1		
Monloc type:	Well		
Monloc desc:	GRAND ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7193162
Longitude:	-73.9971143	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	28.25
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20021030	Welldepth:	599.7
Welldepth units:	ft	Wellholedepth:	599.7
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		0.23	2004-11-10		3.06
2004-07-26		3.44	2004-04-19		3.18
2004-02-18		2.90	2004-02-18		2.90

F21
SW **FED USGS** **USGS40000829869**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404319074000901		
Monloc name:	NY 11		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7220467
Longitude:	-74.0020839	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	52
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

F22
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829870**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404319074000902		
Monloc name:	NY 12		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7220467
Longitude:	-74.0020839	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	52
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

23
West
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000830200**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404341074001801		
Monloc name:	NY 57		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7281577
Longitude:	-74.004584	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	65
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

F24
SW
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000829885**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404320074001201		
Monloc name:	NY 64		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7223245
Longitude:	-74.0029173	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	31
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

F25
SW **FED USGS** **USGS40000829886**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404320074001202		
Monloc name:	NY 65		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7223245
Longitude:	-74.0029173	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	31
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

26
WSW **FED USGS** **USGS40000829937**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404323074001701		
Monloc name:	NY 74		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7231578
Longitude:	-74.0043062	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	160
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

27
South **FED USGS** **USGS40000829657**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404304073594101		
Monloc name:	NY 148		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7178801
Longitude:	-73.9943059	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	35
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

G28
SSW **FED USGS** **USGS40000829683**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404306073595801		
Monloc name:	NY 229		
Monloc type:	Well		
Monloc desc:	HESTER ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7185746
Longitude:	-73.9992505	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	19.08
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	548
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2004-11-10		1.11	2004-07-26		1.49
2004-04-19		1.36	2004-04-02		1.31
2004-02-18		1.21			

29
WSW **FED USGS** **USGS40000830018**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404328074002201		
Monloc name:	NY 143		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7245466
Longitude:	-74.0056951	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	40
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

H30
SW **FED USGS** **USGS40000829825**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404316074001501		
Monloc name:	NY 95		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7212134
Longitude:	-74.0037506	Sourcemap scale:	24000

Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand and Gravel		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	55
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

H31
WSW **FED USGS** **USGS40000829846**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404318074001701		
Monloc name:	NY 13		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7217689
Longitude:	-74.0043062	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	55
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

G32
SSW **FED USGS** **USGS40000829658**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404304073595701		
Monloc name:	NY 230		
Monloc type:	Well		
Monloc desc:	BAXTER ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7181023
Longitude:	-73.9988894	Sourcemap scale:	24000

Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	21.48
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	528.8
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

I33
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000830201**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404341074002501		
Monloc name:	NY 184. 1		
Monloc type:	Well		
Monloc desc:	HOUSTON ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7287854
Longitude:	-74.0065924	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	16.57
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20020412	Welldepth:	663.84
Welldepth units:	ft	Wellholedepth:	663.84
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

I34
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000830224**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404343074002601		
Monloc name:	NY 172		
Monloc type:	Well		
Monloc desc:	HUDSON & HOUSTON STREETS-B		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7287132
Longitude:	-74.0068063	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	minutes
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	17.32
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	640.7
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

I35
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000830230**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404344074002601		
Monloc name:	NY 248. 1		
Monloc type:	Well		
Monloc desc:	28B-GEO-02/W		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7291854
Longitude:	-74.0068896	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	17.82
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	100
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

36
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829824**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404316073585501		
Monloc name:	NY 77		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7212134
Longitude:	-73.9815278	Sourcemap scale:	24000

Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	60
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

I37
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000830231**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404344074002801		
Monloc name:	NY 32		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.728991
Longitude:	-74.0073619	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	15
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand and Gravel		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	70
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

38
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830321**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404349074002701		
Monloc name:	NY 40		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7303798
Longitude:	-74.0070841	Sourcemap scale:	24000

Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	52
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

39
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829723**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404308074001201		
Monloc name:	NY 149		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7189912
Longitude:	-74.0029173	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	38
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

J40
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830493**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404356074002401		
Monloc name:	NY 199		
Monloc type:	Well		
Monloc desc:	GROVE STREET-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7323242
Longitude:	-74.0062507	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	minutes
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	20.87
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	644.77
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

J41
WNW
1/2 - 1 Mile
Lower

		AQUIFLOW	**4531**
Site ID:	16311		
Groundwater Flow:	NOT REPORTED		
Water Table Depth:	4.96-5.92		
Date:	10/01/92		

K42
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000830097**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404334074003001		
Monloc name:	NY 26		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7262133
Longitude:	-74.0079174	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	80
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

K43
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000830099**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404334074003003		
Monloc name:	NY 28		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7262133
Longitude:	-74.0079174	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

K44
West **FED USGS** **USGS40000830098**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404334074003002		
Monloc name:	NY 27		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7262133
Longitude:	-74.0079174	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	80
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

L45
South
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000829562**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404256073593701		
Monloc name:	NY 189		
Monloc type:	Well		
Monloc desc:	ELDRIDGE ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7158802
Longitude:	-73.9932225	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	43.54
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	600.41
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 11

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		2.64	2004-11-10		3.38
2004-10-17		3.40	2004-07-26		3.75
2004-04-19		3.83	2004-02-18		3.42
2003-08-27		3.56	2003-06-24		3.56
2002-10-09		3.18	2002-07-10		2.96
2002-06-25		2.92			

M46
WNW
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000830392**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404352074003101		
Monloc name:	NY 130		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7312131
Longitude:	-74.0081952	Sourcemap scale:	24000

Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	35
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

M47
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830393**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404352074003102		
Monloc name:	NY 131		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7312131
Longitude:	-74.0081952	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	35
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

M48
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000830394**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404352074003103		
Monloc name:	NY 132		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7312131
Longitude:	-74.0081952	Sourcemap scale:	24000

Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	35
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

49
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829656**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404304073585901		
Monloc name:	NY 141		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7178801
Longitude:	-73.9826389	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	25
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	61
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

L50
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000829530**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404253073593601		
Monloc name:	NY 201		
Monloc type:	Well		
Monloc desc:	ALLEN ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7148524
Longitude:	-73.9931392	Sourcemap scale:	24000

Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	42.26
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	600
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 7

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		3.15	2004-11-10		2.65
2004-10-14		2.25	2004-10-07		4.25
2004-07-26		4.31	2004-04-19		4.17
2004-02-18		4.05			

51
SSE **FED USGS** **USGS40000829539**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404254073592501		
Monloc name:	NY 19		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7151024
Longitude:	-73.9898613	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	40
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	32
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

52
SW **FED USGS** **USGS40000829599**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404300074001001		
Monloc name:	NY 214. 1		
Monloc type:	Well		
Monloc desc:	FRANKLIN ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7170107
Longitude:	-74.0025339	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	19.88
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20030911	Welldepth:	545
Welldepth units:	ft	Wellholedepth:	545
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		-4.29	2004-11-10		-0.32
2004-07-26		3.17	2004-04-19		-0.17
2004-02-18		-0.29	2003-11-12		-0.01

53
WSW **FED USGS** **USGS40000829836**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404317074003001		
Monloc name:	NY 237. 1		
Monloc type:	Well		
Monloc desc:	29B-GEO-03/W		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7215189
Longitude:	-74.0081952	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	16.85
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	96
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

54
SE **FED USGS** **USGS40000829598**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404300073590201		
Monloc name:	NY 159		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7167691
Longitude:	-73.9834723	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	60
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

N55
NNE **FED USGS** **USGS40000830914**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404419073590801		
Monloc name:	NY 253. 1		
Monloc type:	Well		
Monloc desc:	E. 22ND STREET AND LEXINGTON AVE, NEW YORK		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.738713
Longitude:	-73.985139	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	26.74
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		

Aquifer type:	Not Reported		
Construction date:	20050630	Welldepth:	45
Welldepth units:	ft	Wellholedepth:	45
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

N56
NNE **FED USGS** **USGS40000830913**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404419073590701		
Monloc name:	NY 241. 1		
Monloc type:	Well		
Monloc desc:	E22ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7387325
Longitude:	-73.9851029	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	26.68
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20021114	Welldepth:	600.1
Welldepth units:	ft	Wellholedepth:	600.1
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

O57
South **FED USGS** **USGS40000829499**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404250073593901		
Monloc name:	NY 182		
Monloc type:	Well		
Monloc desc:	FORSYTH ST-B		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.714158
Longitude:	-73.9939726	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	38.50
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	600
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 11

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		-0.02	2004-11-10		1.27
2004-10-13		2.25	2004-07-26		2.37
2004-04-19		2.45	2004-02-18		2.07
2003-08-27		1.58	2003-06-24		2.69
2002-10-09		2.61	2002-07-10		2.27
2002-06-25		2.19			

58
South **FED USGS** **USGS40000829507**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404251073594801		
Monloc name:	NY 203. 1		
Monloc type:	Well		
Monloc desc:	DIVISION ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7142858
Longitude:	-73.9962949	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	42.32
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		
Aquifer type:	Not Reported		
Construction date:	20020927	Welldepth:	604.3
Welldepth units:	ft	Wellholedepth:	604.3
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-14		0.60	2004-11-10		1.61
2004-10-13		1.92	2004-07-26		2.06
2004-04-19		2.11	2004-02-18		1.72

59
SW **FED USGS** **USGS40000829684**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404306074002501		
Monloc name:	NY 228		
Monloc type:	Well		
Monloc desc:	FRANKLIN ST-B		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7186856
Longitude:	-74.006584	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	11.40
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

P60
WSW **FED USGS** **USGS40000829897**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404321074003703		
Monloc name:	NY 37		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7226022
Longitude:	-74.0098619	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	61
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P61
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829896**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404321074003702		
Monloc name:	NY 36		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7226022
Longitude:	-74.0098619	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand and Gravel		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	38
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

P62
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829895**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404321074003701		
Monloc name:	NY 35		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7226022
Longitude:	-74.0098619	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand and Gravel		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	39
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q63
WSW **FED USGS** **USGS40000829783**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404312074003101		
Monloc name:	NY 213		
Monloc type:	Well		
Monloc desc:	ERICSSON ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7202967
Longitude:	-74.0084452	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	18.49
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	525
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q64
WSW **FED USGS** **USGS40000829795**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003303		
Monloc name:	NY 5		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	40
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q65
WSW **FED USGS** **USGS40000829794**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003302		
Monloc name:	NY 4		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	46
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q66
WSW **FED USGS** **USGS40000829793**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003301		
Monloc name:	NY 3		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	47
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q67
WSW **FED USGS** **USGS40000829796**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003304		
Monloc name:	NY 6		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	49
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q68
WSW **FED USGS** **USGS40000829799**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003307		
Monloc name:	NY 9		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	40
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q69
WSW **FED USGS** **USGS40000829798**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003306		
Monloc name:	NY 8		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	38
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q70
WSW **FED USGS** **USGS40000829797**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404313074003305		
Monloc name:	NY 7		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.72038
Longitude:	-74.0087508	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	44
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

71
NNW **FED USGS** **USGS40000830929**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404421074000901		
Monloc name:	NY 117		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7392686
Longitude:	-74.0020839	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	25
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	39
Welldepth units:	ft	Wellholedepth:	40
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

P72
WSW **FED USGS** **USGS40000829847**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404318074003801		
Monloc name:	NY 23		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7217689
Longitude:	-74.0101397	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand and Gravel		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	35
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

73
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829635**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404302074002401		
Monloc name:	NY 16		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7173246
Longitude:	-74.0062507	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	56
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

O74
South
1/2 - 1 Mile
Lower

FED USGS **USGS40000829461**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404246073594001		
Monloc name:	NY 200		
Monloc type:	Well		
Monloc desc:	HENRY ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7131302
Longitude:	-73.9941392	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	36.09
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	604.65
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2002-10-09		2.44	2002-07-09		2.07
2002-06-25		1.96	2002-04-03		2.17

R75
South **FED USGS** **USGS40000829459**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404246073593501		
Monloc name:	NY 187		
Monloc type:	Well		
Monloc desc:	PIKE ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7130191
Longitude:	-73.9927503	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Unknown		
Horiz coord refsys:	NAD83	Vert measure val:	35.10
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Unknown		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	603.07
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-09		1.32	2004-11-10		1.45
2004-07-26		1.54	2004-04-19		4.68
2004-02-18		4.13			
2003-10-22		4.44			
Note: Water level was affected by tide stage.					
2003-10-22		4.43			
Note: Water level was affected by tide stage.					
2003-09-15		4.70			
Note: Water level was affected by tide stage.					
2003-08-27		4.56			
Note: Water level was affected by tide stage.					
2003-06-24		4.80			
Note: Water level was affected by tide stage.					
2002-10-09		4.84	2002-06-25		4.57

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

R76
South
1/2 - 1 Mile
Lower

FED USGS **USGS40000829460**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404246073593502		
Monloc name:	NY 238. 1		
Monloc type:	Well		
Monloc desc:	PIKE-W		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7130191
Longitude:	-73.9927503	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	35.10
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	34.92
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

77
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000829579**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404258074002101		
Monloc name:	NY 101		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7162135
Longitude:	-74.0054173	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	35
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	51
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

1G
WNW
1/2 - 1 Mile
Lower

Site ID:	16311
Groundwater Flow:	NOT REPORTED
Water Table Depth:	4.96-5.92
Date:	10/01/92

AQUIFLOW **4531**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
South
0 - 1/8 Mile

OIL_GAS **NYOG80000035708**

Api wellno:	31061210900000	Cnty:	61
Hole:	21090	Sidetrck:	0
Completion:	0	Well name:	Bond St - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-07-29 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-10-18 00:00:00	Date total:	2002-11-13 00:00:00
Date well :	2002-11-13 00:00:00	Date wel00:	2004-07-29 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Not Reported
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-73.993119		
Surface la:	40.72623		
Bottom hol:	BH		
Bottom h00:	-73.993119		
Bottom h01:	40.72623		
True verti:	604	Measured d:	604
Kickoff:	0	Drilleddep:	604
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-01-24 13:01:44.590000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210900000		
Site id:	NYOG80000035708		

A3
East
0 - 1/8 Mile

OIL_GAS **NYOG80000035707**

Api wellno:	31061210890000	Cnty:	61
Hole:	21089	Sidetrck:	0
Completion:	0	Well name:	31 B-1
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-07-27 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2001-02-27 00:00:00	Date total:	2001-03-15 00:00:00
Date well :	2002-01-31 00:00:00	Date wel00:	2004-07-27 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-73.99156		
Surface la:	40.72737		
Bottom hol:	BH		
Bottom h00:	-73.99156		

Bottom h01:	40.72737		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-26 11:52:30.890000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210890000		
Site id:	NYOG80000035707		

A2
East **OIL_GAS** **NYOG80000035687**
0 - 1/8 Mile

Api wellno:	31061210670000	Cnty:	61
Hole:	21067	Sidetrck:	0
Completion:	0	Well name:	31 B-2
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	O
Well statu:	CA	Date statu:	2003-10-14 00:00:00
Date permi:	2003-10-14 00:00:00	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	500	Surface lo:	SURF
Surface 00:	-73.99156		
Surface la:	40.72737		
Bottom hol:	BH		
Bottom h00:	-73.99156		
Bottom h01:	40.72737		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-12-11 11:18:35.703000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210670000		
Site id:	NYOG80000035687		

4
NNW **OIL_GAS** **NYOG80000035722**
0 - 1/8 Mile

Api wellno:	31061236050000	Cnty:	61
Hole:	23605	Sidetrck:	0
Completion:	0	Well name:	Prince St. - A
Company na:	U.S. Geological Survey	Operator n:	2370
Well type:	SG	Map symbol:	O
Well statu:	AC	Date statu:	2011-12-31 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2001-03-21 00:00:00	Date total:	2001-04-10 00:00:00
Date well :	2001-04-10 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	550	Surface lo:	SURF
Surface 00:	-73.99397		
Surface la:	40.72871		
Bottom hol:	BH		
Bottom h00:	-73.99397		
Bottom h01:	40.72871		
True verti:	665	Measured d:	665
Kickoff:	0	Drilleddep:	665
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Manhattan Schist
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-07-20 13:00:18.737000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061236050000		
Site id:	NYOG80000035722		

B6
South **OIL_GAS** **NYOG80000035802**
1/4 - 1/2 Mile

Api wellno:	31061237300000	Cnty:	61
Hole:	23730	Sidetrck:	0
Completion:	0	Well name:	Geothermal 3
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2008-03-22 00:00:00
Date permi:	2006-12-14 00:00:00	Permit iss:	2007-08-20 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.993697		
Surface la:	40.723203		
Bottom hol:	BH		
Bottom h00:	-73.993697		

Bottom h01:	40.723203		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt from Title 5; complies with 6 NYCRR 553.1(a)
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2008-04-24 11:53:48.100000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237300000		
Site id:	NYOG80000035802		

B5
South
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035803**

Api wellno:	31061237300001	Cnty:	61
Hole:	23730	Sidetrck:	0
Completion:	1	Well name:	Geothermal 3
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	CA	Date statu:	2008-04-24 00:00:00
Date permi:	2008-04-15 00:00:00	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Not Reported
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.993697		
Surface la:	40.723203		
Bottom hol:	BH		
Bottom h00:	-73.993697		
Bottom h01:	40.723203		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2008-07-23 12:27:59.427000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237300001		
Site id:	NYOG80000035803		

C7
WNW
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035660**

Api wellno:	31061210400000	Cnty:	61
Hole:	21040	Sidetrck:	0
Completion:	0	Well name:	534 LaGuardia Place AIA 1
Company na:	Amer. Institute of Architects NY	Operator n:	2154
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-12-31 00:00:00
Date permi:	2003-03-18 00:00:00	Permit iss:	2003-04-08 00:00:00
Date spudd:	2003-04-23 00:00:00	Date total:	2003-05-02 00:00:00
Date well :	2003-05-16 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1250	Surface lo:	SURF
Surface 00:	-73.99833		
Surface la:	40.72879		
Bottom hol:	BH		
Bottom h00:	-73.99833		
Bottom h01:	40.72879		
True verti:	1250	Measured d:	1250
Kickoff:	0	Drilleddep:	1250
Elevation:	36	Original w:	TH
Permit fee:	475	Objective :	NA - Geoexchange
Depth fee:	375	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2009-07-08 11:34:23.053000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210400000		
Site id:	NYOG80000035660		

B9
South
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035805**

Api wellno:	31061237310001	Cnty:	61
Hole:	23731	Sidetrck:	0
Completion:	1	Well name:	Geothermal 4
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	CA	Date statu:	2008-04-24 00:00:00
Date permi:	2008-04-15 00:00:00	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Not Reported
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.993628		
Surface la:	40.723083		
Bottom hol:	BH		
Bottom h00:	-73.993628		

Bottom h01:	40.723083		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2008-07-23 12:28:34.007000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237310001		
Site id:	NYOG80000035805		

B8
South
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035804**

Api wellno:	31061237310000	Cnty:	61
Hole:	23731	Sidetrck:	0
Completion:	0	Well name:	Geothermal 4
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2008-03-22 00:00:00
Date permi:	2006-12-14 00:00:00	Permit iss:	2007-08-20 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.993628		
Surface la:	40.723083		
Bottom hol:	BH		
Bottom h00:	-73.993628		
Bottom h01:	40.723083		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2008-04-24 11:54:10.427000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237310000		
Site id:	NYOG80000035804		

C10
WNW
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035661**

Api wellno:	31061210410000	Cnty:	61
Hole:	21041	Sidetrck:	0
Completion:	0	Well name:	534 LaGuardia Place AIA 2
Company na:	Amer. Institute of Architects NY	Operator n:	2154
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2008-12-31 00:00:00
Date permi:	2003-03-18 00:00:00	Permit iss:	2003-04-09 00:00:00
Date spudd:	2003-05-05 00:00:00	Date total:	2003-05-14 00:00:00
Date well :	2003-05-05 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1250	Surface lo:	SURF
Surface 00:	-73.99843		
Surface la:	40.72866		
Bottom hol:	BH		
Bottom h00:	-73.99843		
Bottom h01:	40.72866		
True verti:	1250	Measured d:	1250
Kickoff:	0	Drilleddep:	1250
Elevation:	36	Original w:	TH
Permit fee:	475	Objective :	NA - Geoexchange
Depth fee:	375	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2009-07-08 11:34:29.600000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210410000		
Site id:	NYOG80000035661		

B12
South
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035799**

Api wellno:	31061237280001	Cnty:	61
Hole:	23728	Sidetrck:	0
Completion:	1	Well name:	Geothermal 1
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	CA	Date statu:	2008-04-24 00:00:00
Date permi:	2008-04-15 00:00:00	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Not Reported
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.993944		
Surface la:	40.723014		
Bottom hol:	BH		
Bottom h00:	-73.993944		

Bottom h01:	40.723014		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2008-07-23 12:26:39.943000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237280001		
Site id:	NYOG80000035799		

B11
South **OIL_GAS** **NYOG80000035798**
1/4 - 1/2 Mile

Api wellno:	31061237280000	Cnty:	61
Hole:	23728	Sidetrck:	0
Completion:	0	Well name:	Geothermal 1
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2008-03-22 00:00:00
Date permi:	2006-12-14 00:00:00	Permit iss:	2007-08-20 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.993944		
Surface la:	40.723014		
Bottom hol:	BH		
Bottom h00:	-73.993944		
Bottom h01:	40.723014		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt from Title 5; complies with 6 NYCRR 553.1(a)
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2008-04-24 11:53:03.880000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237280000		
Site id:	NYOG80000035798		

B14
South **OIL_GAS** **NYOG80000035801**
1/4 - 1/2 Mile

Api wellno:	31061237290001	Cnty:	61
Hole:	23729	Sidetrck:	0
Completion:	1	Well name:	Geothermal 2
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	CA	Date statu:	2008-04-24 00:00:00
Date permi:	2008-04-15 00:00:00	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Not Reported
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.99365		
Surface la:	40.722944		
Bottom hol:	BH		
Bottom h00:	-73.99365		
Bottom h01:	40.722944		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2008-07-23 12:27:29.193000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237290001		
Site id:	NYOG80000035801		

B13
South
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035800**

Api wellno:	31061237290000	Cnty:	61
Hole:	23729	Sidetrck:	0
Completion:	0	Well name:	Geothermal 2
Company na:	250 Bowery Project, LLC	Operator n:	2350
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2008-03-22 00:00:00
Date permi:	2006-12-14 00:00:00	Permit iss:	2007-08-20 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.99365		
Surface la:	40.722944		
Bottom hol:	BH		
Bottom h00:	-73.99365		

Bottom h01:	40.722944		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	42	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt from Title 5; complies with 6 NYCRR 553.1(a)
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2008-04-24 11:53:26.350000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237290000		
Site id:	NYOG80000035800		

15
SSW **OIL_GAS** **NYOG80000035682**
1/4 - 1/2 Mile

Api wellno:	31061210620000	Cnty:	61
Hole:	21062	Sidetrck:	0
Completion:	0	Well name:	Mulberry St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-06-01 00:00:00
Date permi:	2003-09-22 00:00:00	Permit iss:	2003-12-31 00:00:00
Date spudd:	2004-01-26 00:00:00	Date total:	2004-02-10 00:00:00
Date well :	2004-02-10 00:00:00	Date wel00:	2004-06-01 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	525	Surface lo:	SURF
Surface 00:	-73.99553		
Surface la:	40.72327		
Bottom hol:	BH		
Bottom h00:	-73.99553		
Bottom h01:	40.72327		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	40	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-24 10:05:12.713000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210620000		
Site id:	NYOG80000035682		

16
SE **OIL_GAS** **NYOG80000035667**
1/4 - 1/2 Mile

Api wellno:	31061210470000	Cnty:	61
Hole:	21047	Sidetrck:	0
Completion:	0	Well name:	SCA-1
Company na:	A&F Commercial Builders, LLC	Operator n:	2169
Well type:	TH	Map symbol:	OP
Well statu:	PA	Date statu:	2004-11-02 00:00:00
Date permi:	2003-07-09 00:00:00	Permit iss:	2003-08-28 00:00:00
Date spudd:	2003-09-07 00:00:00	Date total:	2003-09-25 00:00:00
Date well :	Not Reported	Date wel00:	2004-07-29 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-73.98906		
Surface la:	40.72329		
Bottom hol:	BH		
Bottom h00:	-73.98906		
Bottom h01:	40.72329		
True verti:	350	Measured d:	350
Kickoff:	0	Drilleddep:	350
Elevation:	36	Original w:	TH
Permit fee:	475	Objective :	Fordham Gneiss
Depth fee:	375	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2006-04-11 12:55:21.493000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210470000		
Site id:	NYOG80000035667		

17
NE
1/4 - 1/2 Mile

OIL_GAS **NYOG80000035806**

Api wellno:	31061237350000	Cnty:	61
Hole:	23735	Sidetrck:	0
Completion:	0	Well name:	E12 St - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2007-10-11 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	1999-09-02 00:00:00	Date total:	1999-09-29 00:00:00
Date well :	1999-09-29 00:00:00	Date wel00:	2007-10-11 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Unknown	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-73.988388		
Surface la:	40.731888		
Bottom hol:	BH		
Bottom h00:	-73.988388		

Bottom h01:	40.731888		
True verti:	0	Measured d:	538
Kickoff:	0	Drilleddep:	538
Elevation:	38	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2008-12-23 14:23:33.750000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237350000		
Site id:	NYOG80000035806		

18
SW **OIL_GAS** **NYOG80000035680**
1/4 - 1/2 Mile

Api wellno:	31061210600000	Cnty:	61
Hole:	21060	Sidetrck:	0
Completion:	0	Well name:	Crosby St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-05-25 00:00:00
Date permi:	2003-09-22 00:00:00	Permit iss:	2003-12-10 00:00:00
Date spudd:	2004-01-26 00:00:00	Date total:	2004-02-10 00:00:00
Date well :	2004-02-06 00:00:00	Date wel00:	2004-05-25 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	578	Surface lo:	SURF
Surface 00:	-73.99776		
Surface la:	40.72256		
Bottom hol:	BH		
Bottom h00:	-73.99776		
Bottom h01:	40.72256		
True verti:	578	Measured d:	578
Kickoff:	0	Drilleddep:	578
Elevation:	35	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-24 10:43:13.873000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210600000		
Site id:	NYOG80000035680		

D19
SSW **OIL_GAS** **NYOG80000035731**
1/2 - 1 Mile

Api wellno:	31061236180000	Cnty:	61
Hole:	23618	Sidetrck:	0
Completion:	0	Well name:	Elizabeth St. - A
Company na:	U.S. Geological Survey	Operator n:	2370
Well type:	SG	Map symbol:	O
Well statu:	AC	Date statu:	2011-12-31 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-06-20 00:00:00	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99512		
Surface la:	40.71996		
Bottom hol:	BH		
Bottom h00:	-73.99512		
Bottom h01:	40.71996		
True verti:	600	Measured d:	600
Kickoff:	0	Drilleddep:	600
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Unknown
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-07-20 13:02:05.080000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061236180000		
Site id:	NYOG80000035731		

D20
South
1/2 - 1 Mile

OIL_GAS **NYOG80000035728**

Api wellno:	31061236150000	Cnty:	61
Hole:	23615	Sidetrck:	0
Completion:	0	Well name:	Broome - 2
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2007-10-10 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2001-03-06 00:00:00	Date total:	2001-04-05 00:00:00
Date well :	2001-04-05 00:00:00	Date wel00:	2007-01-31 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Inwood Marble	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.994709		
Surface la:	40.719726		
Bottom hol:	BH		
Bottom h00:	-73.994709		

Bottom h01:	40.719726		
True verti:	665	Measured d:	665
Kickoff:	0	Drilleddep:	665
Elevation:	39	Original w:	SG
Permit fee:	0	Objective :	Unknown
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-10-30 13:41:54.330000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061236150000		
Site id:	NYOG80000035728		

E21
SSW
1/2 - 1 Mile

OIL_GAS **NYOG80000035671**

Api wellno:	31061210510000	Cnty:	61
Hole:	21051	Sidetrck:	0
Completion:	0	Well name:	Grand St. - B
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2003-12-09 00:00:00
Date permi:	2003-07-23 00:00:00	Permit iss:	2003-09-18 00:00:00
Date spudd:	2003-10-06 00:00:00	Date total:	2003-10-17 00:00:00
Date well :	2003-10-17 00:00:00	Date wel00:	2004-06-04 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99919		
Surface la:	40.72017		
Bottom hol:	BH		
Bottom h00:	-73.99919		
Bottom h01:	40.72017		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	25	Original w:	SG
Permit fee:	0	Objective :	Fordham Gneiss
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-20 10:04:02.570000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210510000		
Site id:	NYOG80000035671		

E22
SSW
1/2 - 1 Mile

OIL_GAS **NYOG80000035677**

Api wellno:	31061210570000	Cnty:	61
Hole:	21057	Sidetrck:	0
Completion:	0	Well name:	Grand St. - C
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	O
Well statu:	EX	Date statu:	2004-06-07 00:00:00
Date permi:	2003-09-18 00:00:00	Permit iss:	2003-12-10 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99926		
Surface la:	40.72008		
Bottom hol:	BH		
Bottom h00:	-73.99926		
Bottom h01:	40.72008		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	25	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2005-10-26 09:51:22.797000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210570000		
Site id:	NYOG80000035677		

23
SSW **OIL_GAS** **NYOG80000035732**
1/2 - 1 Mile

Api wellno:	31061236190000	Cnty:	61
Hole:	23619	Sidetrck:	0
Completion:	0	Well name:	Grand St. - A
Company na:	U.S. Geological Survey	Operator n:	2370
Well type:	SG	Map symbol:	O
Well statu:	AC	Date statu:	2011-12-31 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-06-27 00:00:00	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.997		
Surface la:	40.71913		
Bottom hol:	BH		
Bottom h00:	-73.997		

Bottom h01:	40.71913		
True verti:	600	Measured d:	600
Kickoff:	0	Drilleddep:	600
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Unknown
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-07-20 13:04:55.407000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061236190000		
Site id:	NYOG80000035732		

F24
SSW **OIL_GAS** **NYOG80000035672**
1/2 - 1 Mile

Api wellno:	31061210520000	Cnty:	61
Hole:	21052	Sidetrck:	0
Completion:	0	Well name:	Hester St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2005-02-01 00:00:00
Date permi:	2003-07-23 00:00:00	Permit iss:	2003-09-18 00:00:00
Date spudd:	2003-10-01 00:00:00	Date total:	2003-10-17 00:00:00
Date well :	2003-10-17 00:00:00	Date wel00:	2005-02-01 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99913		
Surface la:	40.71827		
Bottom hol:	BH		
Bottom h00:	-73.99913		
Bottom h01:	40.71827		
True verti:	548	Measured d:	548
Kickoff:	0	Drilleddep:	548
Elevation:	19	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-20 10:03:44.320000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210520000		
Site id:	NYOG80000035672		

25
South **OIL_GAS** **NYOG80000035713**
1/2 - 1 Mile

Api wellno:	31061210950000	Cnty:	61
Hole:	21095	Sidetrck:	0
Completion:	0	Well name:	Forsyth - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2005-02-18 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-03-11 00:00:00	Date total:	2002-04-17 00:00:00
Date well :	2002-04-17 00:00:00	Date wel00:	2005-02-18 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	550	Surface lo:	SURF
Surface 00:	-73.99332		
Surface la:	40.71714		
Bottom hol:	BH		
Bottom h00:	-73.99332		
Bottom h01:	40.71714		
True verti:	601	Measured d:	601
Kickoff:	0	Drilleddep:	601
Elevation:	40	Original w:	SG
Permit fee:	0	Objective :	Manhattan Schist
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2014-12-01 09:15:56.813000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210950000		
Site id:	NYOG80000035713		

G26
West
1/2 - 1 Mile

OIL_GAS **NYOG80000035696**

Api wellno:	31061210780000	Cnty:	61
Hole:	21078	Sidetrck:	0
Completion:	0	Well name:	Houston St. - A
Company na:	U.S. Geological Survey	Operator n:	2370
Well type:	SG	Map symbol:	O
Well statu:	AC	Date statu:	2011-12-31 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-03-06 00:00:00	Date total:	2002-04-12 00:00:00
Date well :	2002-04-12 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	664	Surface lo:	SURF
Surface 00:	-74.0064903004		
Surface la:	40.7287601522		
Bottom hol:	BH		
Bottom h00:	-74.0064903004		

Bottom h01:	40.7287601522		
True verti:	664	Measured d:	664
Kickoff:	0	Drilleddep:	664
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2014-12-01 09:15:27.110000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210780000		
Site id:	NYOG80000035696		

G27
West
1/2 - 1 Mile

OIL_GAS **NYOG80000035697**

Api wellno:	31061210790000	Cnty:	61
Hole:	21079	Sidetrck:	0
Completion:	0	Well name:	Hudson St. - B
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-05-19 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2004-01-14 00:00:00	Date total:	2004-02-06 00:00:00
Date well :	2004-02-06 00:00:00	Date wel00:	2004-04-27 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Newark
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	651	Surface lo:	SURF
Surface 00:	-74.006826		
Surface la:	40.728875		
Bottom hol:	BH		
Bottom h00:	-74.006826		
Bottom h01:	40.728875		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-02-14 07:58:07.493000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210790000		
Site id:	NYOG80000035697		

F28
SSW
1/2 - 1 Mile

OIL_GAS **NYOG80000035662**

Api wellno:	31061210420000	Cnty:	61
Hole:	21042	Sidetrck:	0
Completion:	0	Well name:	Baxter St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2003-06-20 00:00:00
Date permi:	2003-03-14 00:00:00	Permit iss:	2003-04-16 00:00:00
Date spudd:	2003-05-16 00:00:00	Date total:	2003-06-10 00:00:00
Date well :	2003-06-20 00:00:00	Date wel00:	2003-06-20 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99907		
Surface la:	40.71774		
Bottom hol:	BH		
Bottom h00:	-73.99907		
Bottom h01:	40.71774		
True verti:	529	Measured d:	529
Kickoff:	0	Drilleddep:	529
Elevation:	40	Original w:	SG
Permit fee:	0	Objective :	None Specified
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-07-19 15:48:53.280000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210420000		
Site id:	NYOG80000035662		

29
NW
1/2 - 1 Mile

OIL_GAS **NYOG80000035845**

Api wellno:	31061237870000	Cnty:	61
Hole:	23787	Sidetrck:	0
Completion:	0	Well name:	1
Company na:	Perry Street Associates, LLC	Operator n:	2459
Well type:	NL	Map symbol:	O
Well statu:	CA	Date statu:	2008-07-03 00:00:00
Date permi:	2008-06-27 00:00:00	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.00241		
Surface la:	40.735666		
Bottom hol:	BH		
Bottom h00:	-74.00241		

Bottom h01:	40.735666		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	15	Original w:	TH
Permit fee:	670	Objective :	Not Applicable
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2011-07-14 09:52:18.723000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237870000		
Site id:	NYOG80000035845		

30
SW
1/2 - 1 Mile

OIL_GAS **NYOG80000035683**

Api wellno:	31061210630000	Cnty:	61
Hole:	21063	Sidetrck:	0
Completion:	0	Well name:	Walker St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	O
Well statu:	EX	Date statu:	2004-06-28 00:00:00
Date permi:	2003-09-22 00:00:00	Permit iss:	2003-12-31 00:00:00
Date spudd:	2004-01-20 00:00:00	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	570	Surface lo:	SURF
Surface 00:	-74.00196		
Surface la:	40.71842		
Bottom hol:	BH		
Bottom h00:	-74.00196		
Bottom h01:	40.71842		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	20	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-07-19 11:29:33.223000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210630000		
Site id:	NYOG80000035683		

31
WNW
1/2 - 1 Mile

OIL_GAS **NYOG80000035698**

Api wellno:	31061210800000	Cnty:	61
Hole:	21080	Sidetrck:	0
Completion:	0	Well name:	Grove St - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-05-19 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	Not Reported	Date total:	2001-05-03 00:00:00
Date well :	2001-05-19 00:00:00	Date wel00:	2004-04-23 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	645	Surface lo:	SURF
Surface 00:	-74.00632		
Surface la:	40.73223		
Bottom hol:	BH		
Bottom h00:	-74.00632		
Bottom h01:	40.73223		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	18	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2005-12-28 10:03:57.093000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210800000		
Site id:	NYOG80000035698		

32
WSW **OIL_GAS** **NYOG80000035819**
1/2 - 1 Mile

Api wellno:	31061237480000	Cnty:	61
Hole:	23748	Sidetrck:	0
Completion:	0	Well name:	Broome - 1
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	1997-08-26 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	1997-08-12 00:00:00	Date total:	Not Reported
Date well :	1997-08-26 00:00:00	Date wel00:	1997-08-26 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-74.007835		
Surface la:	40.724942		
Bottom hol:	BH		
Bottom h00:	-74.007835		

Bottom h01:	40.724942		
True verti:	567	Measured d:	567
Kickoff:	0	Drilleddep:	567
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-07-20 09:50:42.717000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237480000		
Site id:	NYOG80000035819		

33
South
1/2 - 1 Mile

OIL_GAS **NYOG80000035712**

Api wellno:	31061210940000	Cnty:	61
Hole:	21094	Sidetrck:	0
Completion:	0	Well name:	Eldridge - 1
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2005-02-24 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-03-19 00:00:00	Date total:	2002-05-06 00:00:00
Date well :	Not Reported	Date wel00:	2005-02-24 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99306		
Surface la:	40.71571		
Bottom hol:	BH		
Bottom h00:	-73.99306		
Bottom h01:	40.71571		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	44	Original w:	SG
Permit fee:	0	Objective :	Manhattan Schist
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-26 11:52:30.890000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210940000		
Site id:	NYOG80000035712		

H34
NNE
1/2 - 1 Mile

OIL_GAS **NYOG80000035847**

Api wellno:	31061270190001	Cnty:	61
Hole:	27019	Sidetrck:	0
Completion:	1	Well name:	Geothermal Well W-1
Company na:	Bond 23 LLC	Operator n:	2600
Well type:	TH	Map symbol:	O
Well statu:	EX	Date statu:	2014-01-18 00:00:00
Date permi:	2013-06-07 00:00:00	Permit iss:	2013-07-22 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Not Reported
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.985754		
Surface la:	40.737474		
Bottom hol:	BH		
Bottom h00:	0		
Bottom h01:	0		
True verti:	1500	Measured d:	1500
Kickoff:	0	Drilleddep:	1500
Elevation:	31	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt from Title 5; complies with 6 NYCRR 553.1(a)
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2014-01-21 08:43:52.310000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061270190001		
Site id:	NYOG80000035847		

H36
NNE **OIL_GAS** **NYOG80000035848**
1/2 - 1 Mile

Api wellno:	31061270190002	Cnty:	61
Hole:	27019	Sidetrck:	0
Completion:	2	Well name:	Geothermal Well W-1
Company na:	Bond 23 LLC	Operator n:	2600
Well type:	TH	Map symbol:	O
Well statu:	AC	Date statu:	2014-08-28 00:00:00
Date permi:	2014-02-14 00:00:00	Permit iss:	2014-03-27 00:00:00
Date spudd:	2014-08-28 00:00:00	Date total:	2014-11-13 00:00:00
Date well :	2014-11-13 00:00:00	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Applicati
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.985754		
Surface la:	40.737475		
Bottom hol:	BH		
Bottom h00:	-73.985754		

Bottom h01:	40.737475		
True verti:	1215	Measured d:	1259
Kickoff:	0	Drilleddep:	1259
Elevation:	31	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Not Reported
Spacing ac:	Not Reported	Integratio:	Not Reported
Dt hearing:	Not Reported	Dt mod:	2015-03-17 10:10:34.710000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061270190002		
Site id:	NYOG80000035848		

H35
NNE **OIL_GAS** **NYOG80000035846**
1/2 - 1 Mile

Api wellno:	31061270190000	Cnty:	61
Hole:	27019	Sidetrck:	0
Completion:	0	Well name:	Geothermal Well W-1
Company na:	Bond 23 LLC	Operator n:	2600
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2012-03-20 00:00:00
Date permi:	2011-03-11 00:00:00	Permit iss:	2011-09-22 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-73.985754		
Surface la:	40.737475		
Bottom hol:	BH		
Bottom h00:	-73.985754		
Bottom h01:	40.737475		
True verti:	1500	Measured d:	1500
Kickoff:	0	Drilleddep:	1500
Elevation:	31	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-03-26 08:01:52.800000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061270190000		
Site id:	NYOG80000035846		

I37
NNW **OIL_GAS** **NYOG80000035797**
1/2 - 1 Mile

Api wellno:	31061237270000	Cnty:	61
Hole:	23727	Sidetrck:	0
Completion:	0	Well name:	Valhalla 2
Company na:	Terrapin Industries, LLC	Operator n:	2356
Well type:	TH	Map symbol:	O
Well statu:	IN	Date statu:	2008-12-31 00:00:00
Date permi:	2006-10-19 00:00:00	Permit iss:	2007-01-11 00:00:00
Date spudd:	2007-03-12 00:00:00	Date total:	2007-03-16 00:00:00
Date well :	2007-03-16 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Unknown	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	800	Surface lo:	SURF
Surface 00:	-73.997446		
Surface la:	40.738488		
Bottom hol:	BH		
Bottom h00:	-73.997446		
Bottom h01:	40.738488		
True verti:	960	Measured d:	960
Kickoff:	0	Drilleddep:	960
Elevation:	18	Original w:	TH
Permit fee:	480	Objective :	Manhattan Schist
Depth fee:	380	Spacing:	Exempt from Title 5; complies with 6 NYCRR 553.1(a)
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-07-06 15:04:14.830000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237270000		
Site id:	NYOG80000035797		

I38
NNW
1/2 - 1 Mile

OIL_GAS **NYOG80000035796**

Api wellno:	31061237260000	Cnty:	61
Hole:	23726	Sidetrck:	0
Completion:	0	Well name:	Valhalla 1
Company na:	Terrapin Industries, LLC	Operator n:	2356
Well type:	TH	Map symbol:	O
Well statu:	IN	Date statu:	2008-12-31 00:00:00
Date permi:	2006-10-19 00:00:00	Permit iss:	2007-01-11 00:00:00
Date spudd:	2007-02-27 00:00:00	Date total:	2007-03-12 00:00:00
Date well :	2007-03-12 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Unknown	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	800	Surface lo:	SURF
Surface 00:	-73.997507		
Surface la:	40.738516		
Bottom hol:	BH		
Bottom h00:	-73.997507		

Bottom h01:	40.738516		
True verti:	640	Measured d:	640
Kickoff:	0	Drilleddep:	640
Elevation:	18	Original w:	TH
Permit fee:	480	Objective :	Manhattan Schist
Depth fee:	380	Spacing:	Exempt from Title 5; complies with 6 NYCRR 553.1(a)
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2009-07-06 15:04:12.313000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237260000		
Site id:	NYOG80000035796		

39
NW
1/2 - 1 Mile

OIL_GAS **NYOG80000035820**

Api wellno:	31061237490000	Cnty:	61
Hole:	23749	Sidetrck:	0
Completion:	0	Well name:	Charles - 1
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	1997-08-11 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	1997-07-27 00:00:00	Date total:	Not Reported
Date well :	1997-08-11 00:00:00	Date wel00:	1997-08-11 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-74.006019		
Surface la:	40.734546		
Bottom hol:	BH		
Bottom h00:	-74.006019		
Bottom h01:	40.734546		
True verti:	576	Measured d:	576
Kickoff:	0	Drilleddep:	576
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-07-20 09:55:08.233000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237490000		
Site id:	NYOG80000035820		

40
SW
1/2 - 1 Mile

OIL_GAS **NYOG80000035663**

Api wellno:	31061210430000	Cnty:	61
Hole:	21043	Sidetrck:	0
Completion:	0	Well name:	Franklin St. - A
Company na:	U.S. Geological Survey	Operator n:	2370
Well type:	SG	Map symbol:	O
Well statu:	AC	Date statu:	2011-12-31 00:00:00
Date permi:	2003-03-14 00:00:00	Permit iss:	2003-04-16 00:00:00
Date spudd:	2003-08-26 00:00:00	Date total:	2003-09-11 00:00:00
Date well :	2003-09-11 00:00:00	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-74.00235		
Surface la:	40.71709		
Bottom hol:	BH		
Bottom h00:	-74.00235		
Bottom h01:	40.71709		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	25	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-07-20 13:04:09.530000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210430000		
Site id:	NYOG80000035663		

41
South
1/2 - 1 Mile

OIL_GAS **NYOG80000035710**

Api wellno:	31061210920000	Cnty:	61
Hole:	21092	Sidetrck:	0
Completion:	0	Well name:	Allen St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-01-18 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-08-05 00:00:00	Date total:	2002-09-19 00:00:00
Date well :	Not Reported	Date wel00:	2005-02-17 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Central Park
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-73.99225		
Surface la:	40.71467		
Bottom hol:	BH		
Bottom h00:	-73.99225		

Bottom h01:	40.71467		
True verti:	600	Measured d:	600
Kickoff:	0	Drilleddep:	600
Elevation:	42	Original w:	SG
Permit fee:	0	Objective :	None Specified
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-26 11:52:30.890000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210920000		
Site id:	NYOG80000035710		

J42
WSW **OIL_GAS** **NYOG80000035825**
1/2 - 1 Mile

Api wellno:	31061237540000	Cnty:	61
Hole:	23754	Sidetrck:	0
Completion:	0	Well name:	Holland - 2
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	1996-07-30 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	1996-07-15 00:00:00	Date total:	Not Reported
Date well :	1996-07-29 00:00:00	Date wel00:	1996-07-30 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-74.00808		
Surface la:	40.721705		
Bottom hol:	BH		
Bottom h00:	-74.00808		
Bottom h01:	40.721705		
True verti:	541	Measured d:	541
Kickoff:	0	Drilleddep:	541
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-07-20 10:17:32.250000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237540000		
Site id:	NYOG80000035825		

J43
WSW **OIL_GAS** **NYOG80000035824**
1/2 - 1 Mile

Api wellno:	31061237530000	Cnty:	61
Hole:	23753	Sidetrck:	0
Completion:	0	Well name:	Holland - 1
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	1996-07-12 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	1996-06-24 00:00:00	Date total:	Not Reported
Date well :	1996-07-11 00:00:00	Date wel00:	1996-07-12 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-74.008071		
Surface la:	40.721608		
Bottom hol:	BH		
Bottom h00:	-74.008071		
Bottom h01:	40.721608		
True verti:	542	Measured d:	542
Kickoff:	0	Drilleddep:	542
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-07-20 10:13:37.560000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237530000		
Site id:	NYOG80000035824		

K45
West
1/2 - 1 Mile

OIL_GAS **NYOG80000035832**

Api wellno:	31061237580001	Cnty:	61
Hole:	23758	Sidetrck:	0
Completion:	1	Well name:	W-3
Company na:	471 VE LLC	Operator n:	2565
Well type:	TH	Map symbol:	OP
Well statu:	PA	Date statu:	2010-12-22 00:00:00
Date permi:	2007-12-06 00:00:00	Permit iss:	2008-01-16 00:00:00
Date spudd:	2008-03-10 00:00:00	Date total:	2008-05-20 00:00:00
Date well :	2008-05-20 00:00:00	Date wel00:	2010-12-22 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.009883		
Surface la:	40.725033		
Bottom hol:	BH		
Bottom h00:	-74.009883		

Bottom h01:	40.725033		
True verti:	1530	Measured d:	1530
Kickoff:	0	Drilleddep:	1530
Elevation:	10	Original w:	TH
Permit fee:	860	Objective :	NA - Geoexchange
Depth fee:	760	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-03-19 07:27:32.173000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237580001		
Site id:	NYOG80000035832		

K44
West
1/2 - 1 Mile

OIL_GAS **NYOG80000035831**

Api wellno:	31061237580000	Cnty:	61
Hole:	23758	Sidetrck:	0
Completion:	0	Well name:	W-3
Company na:	471 Washington Street Partners	Operator n:	2371
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2007-09-08 00:00:00
Date permi:	2007-01-30 00:00:00	Permit iss:	2007-03-12 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.009883		
Surface la:	40.725033		
Bottom hol:	BH		
Bottom h00:	-74.009883		
Bottom h01:	40.725033		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	10	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-12-06 09:15:43.993000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237580000		
Site id:	NYOG80000035831		

K46
WSW
1/2 - 1 Mile

OIL_GAS **NYOG80000035827**

Api wellno:	31061237560000	Cnty:	61
Hole:	23756	Sidetrck:	0
Completion:	0	Well name:	W-1
Company na:	471 Washington Street Partners	Operator n:	2371
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2007-09-08 00:00:00
Date permi:	2007-01-30 00:00:00	Permit iss:	2007-03-12 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.00985		
Surface la:	40.724717		
Bottom hol:	BH		
Bottom h00:	-74.00985		
Bottom h01:	40.724717		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	10	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-12-06 09:14:55.917000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237560000		
Site id:	NYOG80000035827		

47
NNE **OIL_GAS** **NYOG80000035725**
1/2 - 1 Mile

Api wellno:	31061236120000	Cnty:	61
Hole:	23612	Sidetrck:	0
Completion:	0	Well name:	E. 22 St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2007-10-10 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-10-31 00:00:00	Date total:	2002-11-14 00:00:00
Date well :	2002-11-14 00:00:00	Date wel00:	2007-02-02 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-73.985104		
Surface la:	40.738732		
Bottom hol:	BH		
Bottom h00:	-73.985104		

Bottom h01:	40.738732		
True verti:	600	Measured d:	600
Kickoff:	0	Drilleddep:	600
Elevation:	27	Original w:	SG
Permit fee:	0	Objective :	Manhattan Schist
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-10-30 13:36:08.867000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061236120000		
Site id:	NYOG80000035725		

K49
West
1/2 - 1 Mile

OIL_GAS **NYOG80000035830**

Api wellno:	31061237570001	Cnty:	61
Hole:	23757	Sidetrck:	0
Completion:	1	Well name:	W-2
Company na:	471 VE LLC	Operator n:	2565
Well type:	TH	Map symbol:	OP
Well statu:	PA	Date statu:	2010-12-21 00:00:00
Date permi:	2007-12-06 00:00:00	Permit iss:	2008-01-16 00:00:00
Date spudd:	2008-02-13 00:00:00	Date total:	2008-04-23 00:00:00
Date well :	2008-04-23 00:00:00	Date wel00:	2010-12-21 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.00995		
Surface la:	40.724917		
Bottom hol:	BH		
Bottom h00:	-74.00995		
Bottom h01:	40.724917		
True verti:	1530	Measured d:	1530
Kickoff:	0	Drilleddep:	1530
Elevation:	10	Original w:	TH
Permit fee:	860	Objective :	NA - Geoexchange
Depth fee:	760	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-03-19 07:27:25.003000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237570001		
Site id:	NYOG80000035830		

K48
West
1/2 - 1 Mile

OIL_GAS **NYOG80000035829**

Api wellno:	31061237570000	Cnty:	61
Hole:	23757	Sidetrck:	0
Completion:	0	Well name:	W-2
Company na:	471 Washington Street Partners	Operator n:	2371
Well type:	NL	Map symbol:	O
Well statu:	EX	Date statu:	2007-09-08 00:00:00
Date permi:	2007-01-30 00:00:00	Permit iss:	2007-03-12 00:00:00
Date spudd:	Not Reported	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	Not Reported	Confid:	No
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.00995		
Surface la:	40.724917		
Bottom hol:	BH		
Bottom h00:	-74.00995		
Bottom h01:	40.724917		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	10	Original w:	TH
Permit fee:	670	Objective :	NA - Geoexchange
Depth fee:	570	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2007-12-06 09:15:16.320000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237570000		
Site id:	NYOG80000035829		

K50
WSW **OIL_GAS** **NYOG80000035828**
1/2 - 1 Mile

Api wellno:	31061237560001	Cnty:	61
Hole:	23756	Sidetrck:	0
Completion:	1	Well name:	W-1
Company na:	471 VE LLC	Operator n:	2565
Well type:	TH	Map symbol:	OP
Well statu:	PA	Date statu:	2011-08-05 00:00:00
Date permi:	2007-12-06 00:00:00	Permit iss:	2008-01-16 00:00:00
Date spudd:	2008-02-28 00:00:00	Date total:	2008-05-06 00:00:00
Date well :	2008-05-06 00:00:00	Date wel00:	2011-08-05 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	True
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	1500	Surface lo:	SURF
Surface 00:	-74.009972		
Surface la:	40.72475		
Bottom hol:	BH		
Bottom h00:	-74.009972		

Bottom h01:	40.72475		
True verti:	1525	Measured d:	1525
Kickoff:	0	Drilleddep:	1525
Elevation:	10	Original w:	TH
Permit fee:	860	Objective :	NA - Geoexchange
Depth fee:	760	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2013-04-09 10:01:41.220000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237560001		
Site id:	NYOG80000035828		

51
South
1/2 - 1 Mile

OIL_GAS **NYOG80000035714**

Api wellno:	31061210960000	Cnty:	61
Hole:	21096	Sidetrck:	0
Completion:	0	Well name:	Forsyth St. - B
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2005-03-01 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-05-08 00:00:00	Date total:	2002-06-18 00:00:00
Date well :	Not Reported	Date wel00:	2005-03-01 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	606	Surface lo:	SURF
Surface 00:	-73.99382		
Surface la:	40.71399		
Bottom hol:	BH		
Bottom h00:	-73.99382		
Bottom h01:	40.71399		
True verti:	0	Measured d:	0
Kickoff:	0	Drilleddep:	0
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Manhattan Schist
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-08-31 13:03:31.380000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210960000		
Site id:	NYOG80000035714		

52
SW
1/2 - 1 Mile

OIL_GAS **NYOG80000035681**

Api wellno:	31061210610000	Cnty:	61
Hole:	21061	Sidetrck:	0
Completion:	0	Well name:	Franklin St. - B
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-02-20 00:00:00
Date permi:	2003-10-10 00:00:00	Permit iss:	2003-12-31 00:00:00
Date spudd:	2004-01-19 00:00:00	Date total:	2004-02-20 00:00:00
Date well :	2004-02-20 00:00:00	Date wel00:	2004-05-27 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	Not Reported	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	575	Surface lo:	SURF
Surface 00:	-74.00644		
Surface la:	40.71861		
Bottom hol:	BH		
Bottom h00:	-74.00644		
Bottom h01:	40.71861		
True verti:	555	Measured d:	555
Kickoff:	0	Drilleddep:	555
Elevation:	30	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-24 10:04:54.480000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210610000		
Site id:	NYOG80000035681		

53
South
1/2 - 1 Mile

OIL_GAS **NYOG80000035730**

Api wellno:	31061236170000	Cnty:	61
Hole:	23617	Sidetrck:	0
Completion:	0	Well name:	Division St. - A
Company na:	U.S. Geological Survey	Operator n:	2370
Well type:	SG	Map symbol:	O
Well statu:	AC	Date statu:	2011-12-31 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-08-27 00:00:00	Date total:	Not Reported
Date well :	Not Reported	Date wel00:	Not Reported
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-73.99615		
Surface la:	40.7141		
Bottom hol:	BH		
Bottom h00:	-73.99615		

Bottom h01:	40.7141		
True verti:	604	Measured d:	604
Kickoff:	0	Drilleddep:	604
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Unknown
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2012-07-20 13:02:28.050000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061236170000		
Site id:	NYOG80000035730		

54
WSW **OIL_GAS** **NYOG80000035664**
1/2 - 1 Mile

Api wellno:	31061210440000	Cnty:	61
Hole:	21044	Sidetrck:	0
Completion:	0	Well name:	Ericsson A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2004-05-03 00:00:00
Date permi:	2003-03-14 00:00:00	Permit iss:	2003-04-16 00:00:00
Date spudd:	2003-05-29 00:00:00	Date total:	2003-06-25 00:00:00
Date well :	2003-06-25 00:00:00	Date wel00:	2004-05-04 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	600	Surface lo:	SURF
Surface 00:	-74.00825		
Surface la:	40.72018		
Bottom hol:	BH		
Bottom h00:	-74.00825		
Bottom h01:	40.72018		
True verti:	529	Measured d:	529
Kickoff:	0	Drilleddep:	529
Elevation:	15	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-18 15:58:21.303000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210440000		
Site id:	NYOG80000035664		

55
NW **OIL_GAS** **NYOG80000035808**
1/2 - 1 Mile

Api wellno:	31061237370000	Cnty:	61
Hole:	23737	Sidetrck:	0
Completion:	0	Well name:	W12 St - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	1997-07-21 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	1997-06-25 00:00:00	Date total:	1997-07-16 00:00:00
Date well :	1997-07-16 00:00:00	Date wel00:	1997-07-21 00:00:00
Date wel01:	Not Reported	Confid:	Released
Town:	Manhattan	Quad:	Jersey City
Quadsec:	C	Producing :	Not Applicable
Producin00:	Manhattan Schist	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	0	Surface lo:	SURF
Surface 00:	-74.005586		
Surface la:	40.737292		
Bottom hol:	BH		
Bottom h00:	-74.005586		
Bottom h01:	40.737292		
True verti:	576	Measured d:	576
Kickoff:	0	Drilleddep:	576
Elevation:	0	Original w:	SG
Permit fee:	0	Objective :	Not Applicable
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2014-05-01 11:19:57.547000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061237370000		
Site id:	NYOG80000035808		

56
South
1/2 - 1 Mile

OIL_GAS **NYOG80000035715**

Api wellno:	31061210970000	Cnty:	61
Hole:	21097	Sidetrck:	0
Completion:	0	Well name:	Henry St. - A
Company na:	New York City Dept. of Environme	Operator n:	2127
Well type:	SG	Map symbol:	OP
Well statu:	PA	Date statu:	2002-12-30 00:00:00
Date permi:	Not Reported	Permit iss:	Not Reported
Date spudd:	2002-02-12 00:00:00	Date total:	2002-03-19 00:00:00
Date well :	2002-03-19 00:00:00	Date wel00:	2002-12-30 00:00:00
Date wel01:	2	Confid:	Released
Town:	Manhattan	Quad:	Brooklyn
Quadsec:	A	Producing :	Not Applicable
Producin00:	Not Applicable	Financial :	False
Slant:	Vertical	County:	New York
Region:	2	State leas:	NA
Proposed d:	550	Surface lo:	SURF
Surface 00:	-73.99396		
Surface la:	40.71294		
Bottom hol:	BH		
Bottom h00:	-73.99396		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Bottom h01:	40.71294		
True verti:	605	Measured d:	605
Kickoff:	0	Drilleddep:	605
Elevation:	36	Original w:	SG
Permit fee:	0	Objective :	None Specified
Depth fee:	-100	Spacing:	Exempt - not an oil or gas well
Spacing ac:	Not Reported	Integratio:	N
Dt hearing:	Not Reported	Dt mod:	2006-04-26 11:52:30.907000000
Link:	http://www.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31061210970000		
Site id:	NYOG80000035715		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
NEW YORK	NYC (BRONX)	91	1.59	0.85	16
NEW YORK	NYC (KINGS)	416	1.93	1.19	28.2
NEW YORK	NYC (NEW YORK)	108	2.15	0.98	49.5
NEW YORK	NYC (QUEENS)	501	1.24	0.77	23.8
NEW YORK	NYC (RICHMOND)	225	1.44	0.76	14.1

Federal EPA Radon Zone for NEW YORK County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for NEW YORK COUNTY, NY

Number of sites tested: 31

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.690 pCi/L	90%	10%	0%
Basement	1.490 pCi/L	81%	19%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX F

GOVERNMENT CORRESPONDENCE AND RECORDS

Mayor's Office of Environmental Coordination

CEQR Access Log In

CEQR Project Search

Keyword

CEQR Number

Project Name

Community District --Select--

Borough / Block / Lot Manhattan / 531 / 17

Lead Agency --Select--

Search for Review Clear Search

Search Result [0 record(s) found]

No result found.

Disclaimer and Notes:

The database contains records of CEQR projects, which were filed with the Mayor's Office of Environmental Coordination from January 1, 2005 to the present. While some older records are available in the database, records that cannot be found on CEQR Access should be requested from the agency that was responsible for preparing it (the "Lead Agency"). If any errors are found in the database, please notify the Mayor's Office of Environmental Coordination (ceqraccess@cityhall.nyc.gov). The Mayor's Office of Environmental Coordination makes no representation as to the accuracy of the information in the database or its suitability for any purpose, and disclaims any liability for errors that may be contained therein.

Copyright 2013 The City of New York

Mayor's Office of Environmental Coordination

CEQR Access Log In

CEQR Project Search

Keyword			
CEQR Number		**Project Name**	
Community District	--Select--	**Borough / Block / Lot**	Manhattan / 531 / 52
Lead Agency	--Select--		

Search for Review Clear Search

Search Result [0 record(s) found]

No result found.

Disclaimer and Notes:

The database contains records of CEQR projects, which were filed with the Mayor's Office of Environmental Coordination from January 1, 2005 to the present. While some older records are available in the database, records that cannot be found on CEQR Access should be requested from the agency that was responsible for preparing it (the "Lead Agency"). If any errors are found in the database, please notify the Mayor's Office of Environmental Coordination (ceqraccess@cityhall.nyc.gov). The Mayor's Office of Environmental Coordination makes no representation as to the accuracy of the information in the database or its suitability for any purpose, and disclaims any liability for errors that may be contained therein.

Copyright 2013 The City of New York

CEQR Project Search

Keyword			
CEQR Number		**Project Name**	
Community District	--Select--	**Borough / Block / Lot**	Manhattan / 531 / 56
Lead Agency	--Select--		

Search for Review Clear Search

Search Result [0 record(s) found]

No result found.

Disclaimer and Notes:

The database contains records of CEQR projects, which were filed with the Mayor's Office of Environmental Coordination from January 1, 2005 to the present. While some older records are available in the database, records that cannot be found on CEQR Access should be requested from the agency that was responsible for preparing it (the "Lead Agency"). If any errors are found in the database, please notify the Mayor's Office of Environmental Coordination (ceqraccess@cityhall.nyc.gov). The Mayor's Office of Environmental Coordination makes no representation as to the accuracy of the information in the database or its suitability for any purpose, and disclaims any liability for errors that may be contained therein.

Copyright 2013 The City of New York

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

4 June 2018

Leslie Ifill
Fire Department of New York City
FDNY Bureau of Legal Affairs
Public Records Unit
9 MetroTech Center, IS-8C
Brooklyn, New York 11201

Re: Request for Review of Information
375 Lafayette Street
New York, New York
Block 531, Lots 17, 52, and 56
Langan Project No.: 100732801

Dear Ms. Ifill:

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) is currently conducting a Phase I Environmental Assessment of the above-referenced property. As part of the assessment, we are requesting a general records search for the above-referenced property. Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, ground water sampling, asbestos abatement, radon, hazardous materials, and any other documents that your department may have regarding the above-referenced property.


The site is an approximately 19,741-square-foot property located at the southeastern portion of Block 531 on Lafayette Street between Great Jones Street and East 4th Street Street in New York, New York. The site is currently occupied by an asphalt-paved parking lot at sidewalk grade and was historically occupied by a gasoline filling station with auto repair facilities between 1950 and 1972. This site is bound to the north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by mixed-use commercial and residential buildings and an active construction development site, and to the west by Lafayette Street followed by a six-story mixed-use commercial and office building. The property is zoned for manufacturing use (M1-5B) and is within the NoHo Historic District Extension (LP-02287).

If possible, please email moleske@langan.com or fax a response to (973) 560-4901 and/or send a hard-copy response to my attention. Please contact me at (973) 560-4273 if there are any questions regarding this request. Thank you in advance for your assistance.

Sincerely,
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.

Matthew Oleske
Senior Staff Engineer

Enclosure(s): Site Location Map, Record Search Request Forms, Check
\\langan.com\data\PAR\data8\100732801\Project Data\Correspondence\FOILS\FDNY.docx



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK

Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A CUSTOMER INFORMATION

Please print the required information below.

Langan - Matthew Oleske
Name

300 Kimball Drive, Parsippany
Address

NJ — State
07054 — Zip Code

973-560-4900
Telephone Number

OFFICE USE ONLY

_____
Cashier / Search No.

PRU Staff
Accepted By/Initials:_____

Searched By:_____

Total Amount:_____

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the NYC Fire Department and a stamped self-addressed envelope (with postage). Mail checks or money orders directly to the address and unit listed above. DO NOT MAIL CASH.

SECTION B FUEL TANK REPORT - FEE $10.00 / PER REPORT

375	Lafayette Street	Manhattan
House Number	Street Name	Borough

- [X] **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- [X] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- [X] **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- [X] **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- [X] **MOST RECENT TANK / PIPING TEST RESULTS**
- [X] **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Fire Records Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2681 or 2682

Violation Special Report Request Form

SECTION A CUSTOMER INFORMATION

Please print the required information below.

OFFICE USE ONLY

_____
Cashier / Search No.

PRU Staff
Accepted By/Initials:_____

Searched By:_____

Total Amount:_____

2/26/2018
Date

Langan - Matthew Oleske
Name

300 Kimball Drive
Address

Parsippany, NJ 07054
Borough, State Zip Code

973-560-4900
Telephone Number

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the NYC Fire Department and a stamped self-addressed envelope (with postage). Mail checks or money orders directly to the address and unit listed above. DO NOT MAIL CASH.

SECTION B REQUEST VIOLATION REPORT FEE $10.00 / PER REPORT

Please print the required information below.

375	Lafayette Street	Manhattan
House No	Street Name	Borough

☒ **EXISTING- ALL NOTICES OF VIOLATION AND VIOLATION ORDERS ISSUED BY THE FIRE PREVENTION**

☐ **EXISTING- ALL SUMMONSES**

Note: This search is limited to outstanding Summonses, Notices of Violation and Violation Orders (VOs) that are reported to be related to a specific address. With respect to VOs this search is limited to VOs issued on January 1, 2008 or thereafter. This search does not contain information on VOs issued by fire companies, unless they were forwarded to the Bureau of Fire Prevention. A requested report will only list the violation numbers. After you have received the Report, you can obtain a copy of any record available for an additional fee of $0.25 (cents) / per page by filling out the copy of violation request form.

Note: Requests will be responded to within 10 business days.

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

4 June 2018

Via Email (recordsaccess@health.nyc.gov)

Rene Bryant
Records Access Officer
Department of Health and Mental Hygiene
Gotham Center
42-09 28th St., Floor 14th, CN31
Long Island City, NY 11101

Re: Request for Review of Information
375 Lafayette Street
New York, New York
Block 531, Lots 17, 52, and 56
Langan Project No.: 100732801

Dear Ms. Bryant:

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) is currently conducting a Phase I Environmental Assessment of the above-referenced property. As part of the assessment, we are requesting a general records search for the above-referenced property. Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, ground water sampling, asbestos abatement, radon, hazardous materials, and any other documents that your department may have regarding the above-referenced property.

The site is an approximately 19,741-square-foot property located at the southeastern portion of Block 531 on Lafayette Street between Great Jones Street and East 4th Street Street in New York, New York. The site is currently occupied by an asphalt-paved parking lot at sidewalk grade and was historically occupied by a gasoline filling station with auto repair facilities between 1950 and 1972. This site is bound to the north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by mixed-use commercial and residential buildings and an active construction development site, and to the west by Lafayette Street followed by a six-story mixed-use commercial and office building. The property is zoned for manufacturing use (M1-5B) and is within the NoHo Historic District Extension (LP-02287).


If possible, please email moleske@langan.com or fax a response to (973) 560-4901 and/or send a hard-copy response to my attention. Please contact me at (973) 560-4273 if there are any questions regarding this request. Thank you in advance for your assistance.

Sincerely,
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.

Matthew Oleske
Senior Staff Engineer

Enclosure(s): Site Map, Records Request Form

\\langan.com\data\PAR\data8\100732801\Project Data\Correspondence\FOILS\NYC DOHMH.docx



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK

Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM

(/)

Your request has been submitted!

You can expect an acknowledgment from the City of New York within 5 business days. The agency will use the contact information you provided.

All messages from the City of New York and/or the information and documents you requested will be posted to this page.

FOIL-2018-826-00850

Title:
Environmental Records for 375 Lafayette Street, New York, NY. Block 531, Lots 17, 52, 56.

Open

Department of Environmental Protection (DEP)

Acknowledgment
Due Date: 06/21/2018

Contact the Agency

Responses

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov)

Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page).
Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

4 June 2018

Submitted On-Line (https://a860-openrecords.nyc.gov)

New York City Department of Environmental Protection (NYCDEP)

Re: Request for Review of Information
375 Lafayette Street
New York, New York
Block 531, Lots 17, 52, and 56
Langan Project No.: 100732801

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) is currently conducting a Phase I Environmental Assessment of the above-referenced property. As part of the assessment, we are requesting a general records search for the above-referenced property. Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, ground water sampling, asbestos abatement, radon, hazardous materials, and any other documents that your department may have regarding the above-referenced property.

The site is an approximately 19,741-square-foot property located at the southeastern portion of Block 531 on Lafayette Street between Great Jones Street and East 4th Street Street in New York, New York. The site is currently occupied by an asphalt-paved parking lot at sidewalk grade and was historically occupied by a gasoline filling station with auto repair facilities between 1950 and 1972. This site is bound to the north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by mixed-use commercial and residential buildings and an active construction development site, and to the west by Lafayette Street followed by a six-story mixed-use commercial and office building. The property is zoned for manufacturing use (M1-5B) and is within the NoHo Historic District Extension (LP-02287).


If possible, please email moleske@langan.com or fax a response to (973) 560-4901 and/or send a hard-copy response to my attention. Please contact me at (973) 560-4273 if there are any questions regarding this request. Thank you in advance for your assistance.

Sincerely,
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.

Matthew Oleske
Senior Staff Engineer

Enclosure(s): Site Map

\\langan.com\data\PAR\data8\100732801\Project Data\Correspondence\FOILS\NYCDEP.docx



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK

Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

4 June 2018

Submitted On-Line (https://a860-openrecords.nyc.gov)

New York City Department of Environmental Protection (NYCDEP)

Re: Request for Review of Information
375 Lafayette Street
New York, New York
Block 531, Lots 17, 52, and 56
Langan Project No.: 100732801

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) is currently conducting a Phase I Environmental Assessment of the above-referenced property. As part of the assessment, we are requesting a general records search for the above-referenced property. Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, ground water sampling, asbestos abatement, radon, hazardous materials, and any other documents that your department may have regarding the above-referenced property.

The site is an approximately 19,741-square-foot property located at the southeastern portion of Block 531 on Lafayette Street between Great Jones Street and East 4th Street Street in New York, New York. The site is currently occupied by an asphalt-paved parking lot at sidewalk grade and was historically occupied by a gasoline filling station with auto repair facilities between 1950 and 1972. This site is bound to the north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by mixed-use commercial and residential buildings and an active construction development site, and to the west by Lafayette Street followed by a six-story mixed-use commercial and office building. The property is zoned for manufacturing use (M1-5B) and is within the NoHo Historic District Extension (LP-02287).


If possible, please email moleske@langan.com or fax a response to (973) 560-4901 and/or send a hard-copy response to my attention. Please contact me at (973) 560-4273 if there are any questions regarding this request. Thank you in advance for your assistance.

Sincerely,
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.

Matthew Oleske
Senior Staff Engineer

Enclosure(s): Site Map

\\langan.com\data\PAR\data8\100732801\Project Data\Correspondence\FOILS\NYCDEP.docx



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK

Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM

(/)

Request a Record

Please make your request specific so you receive the fastest service. After you submit a FOIL request you will receive a confirmation number so you can track the status of the response. The agency will notify you about how much time is required to respond to your request.

Category (optional)

Environment

Agency (required)

Department of Environmental Protection (DEP)

Request Title (required)

Note: The agency, category, and title of your request will be visible to the public. Do not enter personal information here.

Environmental Records for 375 Lafayette Street, New York, NY. Block 531, Lots 17, 52, 5

1 character remaining

Request Description (required)

Note: The request details you write here will not be visible to the public. However, the agency may post a description of the records provided.

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the above-referenced property. The Subject Property is defined as 375 Lafayette Street in Manhattan, New York (Block 531, Lots 17, 52, and 56, and was formerly occupied by a gasoline filling station and repair facility between 1950 and 1972.

4436 characters remaining

Upload File (Must be less than 20 Mb)

Choose File Clear File

NYCDEP Sumbission.pdf

Personal Information

This information will not be publicly viewable on this site. You must provide contact information so that the agency can respond to your request for records.

First Name (required)

Matthew

25 characters remaining

Last Name (required)

Oleske

58 characters remaining

Email

moleske@langan.com

Alternate Contact Information

No information entered in this section will be visible to the public.

Title

Senior Staff Engineer

43 characters remaining

Organization

Langan Engineering & Environmental Services

85 characters remaining

Phone

(973) 560-4273

Fax

(973) 560-4901

Address

Address Line 1

300 Kimball Drive, 4th Floor

Address Line 2

Apartment 3D

City

Parsippany

State

New Jersey

Zip

07054

Submit Request

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov)

Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page).
Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

4 June 2018

Via Email (r2foil.foil@dec.ny.gov)

Dr. Fawzy I. Abdelsadek
NYSDEC – Region II
1 Hunter's Point Plaza
47-40 21st Street
Long Island City, NY 11101-5407

Re: Request for Review of Information
375 Lafayette Street
New York, New York
Block 531, Lots 17, 52, and 56
Langan Project No.: 100732801

Dear Mr. Abdelsadek:

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) is currently conducting a Phase I Environmental Assessment of the above-referenced property. As part of the assessment, we are requesting a general records search for the above-referenced property. Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, ground water sampling, asbestos abatement, radon, hazardous materials, and any other documents that your department may have regarding the above-referenced property.


The site is an approximately 19,741-square-foot property located at the southeastern portion of Block 531 on Lafayette Street between Great Jones Street and East 4th Street in New York, New York. The site is currently occupied by an asphalt-paved parking lot at sidewalk grade and was historically occupied by a gasoline filling station with auto repair facilities between 1950 and 1972. This site is bound to the north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by mixed-use commercial and residential buildings and an active construction development site, and to the west by Lafayette Street followed by a six-story mixed-use commercial and office building. The property is zoned for manufacturing use (M1-5B) and is within the NoHo Historic District Extension (LP-02287).

If possible, please email moleske@langan.com or fax a response to (973) 560-4901 and/or send a hard-copy response to my attention. Please contact me at (973) 560-4273 if there are any questions regarding this request. Thank you in advance for your assistance.

Sincerely,
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.

Matthew Oleske
Senior Staff Engineer

Enclosure(s): Site Location Map, Application for Access to Records Form



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK

Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

4 June 2018

Via Email (foil@health.ny.gov)

Records Access Office
New York State Department of Health
Corning Tower, Room 2364
Albany, New York 12237-0044

Re: Request for Review of Information
375 Lafayette Street
New York, New York
Block 531, Lots 17, 52, and 56
Langan Project No.: 100732801

To Whom It May Concern,

Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C. (Langan) is currently conducting a Phase I Environmental Assessment of the above-referenced property. As part of the assessment, we are requesting a general records search for the above-referenced property. Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, ground water sampling, asbestos abatement, radon, hazardous materials, and any other documents that your department may have regarding the above-referenced property.


The site is an approximately 19,741-square-foot property located at the southeastern portion of Block 531 on Lafayette Street between Great Jones Street and East 4th Street in New York, New York. The site is currently occupied by an asphalt-paved parking lot at sidewalk grade and was historically occupied by a gasoline filling station with auto repair facilities between 1950 and 1972. This site is bound to the north by a five-story mixed-use commercial and office building, a four-story mixed-use commercial building affiliated with New York University, and an eight-story residential apartment building. The subject property is bound to the east by a seven-story residential building, to the south by Great Jones Street followed by mixed-use commercial and residential buildings and an active construction development site, and to the west by Lafayette Street followed by a six-story mixed-use commercial and office building. The property is zoned for manufacturing use (M1-5B) and is within the NoHo Historic District Extension (LP-02287).

If possible, please email moleske@langan.com or fax a response to (973) 560-4901 and/or send a hard-copy response to my attention. Please contact me at (973) 560-4273 if there are any questions regarding this request. Thank you in advance for your assistance.

Sincerely,
Langan Engineering, Environmental, Surveying and Landscape Architecture, D

Matthew Oleske
Senior Staff Engineer

Enclosure(s): Site Location Map, FOIL Request Form
\\langan.com\data\PAR\data8\100732801\Project Data\Correspondence\FOILS\NYS DOH.docx



Notes:
Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online © 2011 National Geographic Society, i-cubed.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project
375 LAFAYETTE STREET

BLOCK No. 531, LOT No. 17, 52, & 56

MANHATTAN NEW YORK

Drawing Title
SITE LOCATION MAP

Project No.	100732801
Date	6/6/2018
Scale	1"=2,000'
Drawn By	ATR
Last Revised	6/12/2018

Figure 1

© 2013 Langan

Path: \\langan.com\data\PAR\data8\100732801\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd Date: 6/12/2018 User: ARUANE Time: 9:56:35 AM

Matthew Oleske

From: New York DEC Support <newyorkdec@mycusthelp.net>
Sent: Monday, June 04, 2018 10:46 AM
To: Matthew Oleske
Subject: FOIL Request :: W037717-061118

Dear Matthew:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 6/11/2018 and given the reference number FOIL #W037717-061118 for tracking purposes. You may expect the Department's response to your request no later than **7/10/2018**.

Record Requested: **Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property with address ranging from 28-38 Great Jones Street, 375-379 Lafayette Street. Subject property identified as Block 531, Lots 17, 56, and 52).**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://mycusthelp.com/NEWYORKDEC//_rs/RequestEdit.aspx?rid=37717

Preview Request

Agency Selection

Agency : Environmental Protection Agency
Sub-Agency : Region 2

Request Type Selection

Request Type : FOIA

Contact Information

Prefix : Mr.
First Name : Matthew
Middle Initial : L
Last Name : Oleske
Organization : Langan Engineering & Environmental Services
Email Address : moleske@langan.com
Phone Number : 973-560-4273
Fax Number : 973-560-4901

Mailing Address Location : United States/U.S. Territories
Address Line 1 : 300 Kimball Drive, 4th Floor
Address Line 2 :
City : Parsippany
State/Province : New Jersey
Zip Code/Postal Code : 07054

Processing Fees

Will Pay Up To : $ 25.00

Description :

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the above-referenced property. The subject property is located at 375 Lafayette Street (Block 531, Lots 17, 52, and 56) in Manhattan, NY and was historically occupied by a gasoline filling station and auto repair facility between 1950 and 1972.

Request a Fee Waiver

Make Request ? No

Request Expedited Handling

Make Request ? No

Attach Supporting Files

Attached File	Type	Size (MB)
Figure 1 - Site Location Map.pdf	PDF	1.48

☐ Agree to Privacy Act Statement. I have read the Privacy Act Statement and agree to the terms set forth.

☐ Affirmation. Pursuant to 28 USC § 1746, I declare and affirm that under penalty of perjury under the laws of the United States of America that all of the foregoing information, statements, and signatures submitted in connection with this request and in any supporting documents are true and correct to the best of my knowledge.

Request Confirmation

Request Information

Tracking Number : *EPA-R2-2018-008667*

Requester Name : Mr. Matthew L. Oleske

Date Submitted : 06/4/2018

Request Status : Submitted

Description :

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the above-referenced property. The subject property is located at 375 Lafayette Street (Block 531, Lots 17, 52, and 56) in Manhattan, NY and was historically occupied by a gasoline filling station and auto repair facility between 1950 and 1972.

APPENDIX G

SITE PHOTOGRAPHS

LANGAN

APPENDIX G
Photographic Log
375 Lafayette Street
New York, New York



Photo 1: Subject Property, facing west.



Photo 2: Subject property, facing east.



Photo 3: Car parking racks, hydraulic pistons visible on rear, facing east.




Photo 4: Hydraulic compressor box on concrete pad, facing west.



Photo 5: Minor staining on hydraulic oil compressor, facing east.



Photo 6: Typical above-grade hydraulic oil distribution lines, facing northwest.





Photo 7: Minor staining on hydraulic pistons and asphalt pavement below, facing north.



Photo 8: Sheen on accumulated rain water on southeast portion of site.



Photo 9: Concrete lined pit with disconnected hydraulic lines entering subsurface, facing north.



Photo 10: Debris obstructing view, hydraulic disconnected hydraulic lines enterering subsurface, facing north.



Photo 11: Adjacent properties to the south, across Great Jones Street, facing south.



Photo 12: Adjacent property to the west across Lafayette Street, facing northwest.



Photo 13: Adjacent property to the north on Lafayette Street, facing northeast.



Photo 14: Adjacent property to the north on East 4th Street, facing south.



Photo 15: Adjacent properties to the east on Great Jones Street, facing northwest.



Photo 16: Fill port and vent pipe adjacent to the north of the subject property, facing east.



Photo 17: Fill port and vent pipe in front of 28-30 East 4th Street, facing south.



Photo 18: Fill port and vent pipe in front of fire house at 42 Great Jones Street, facing west.



Photo 19: Fill port and vent pipe adjacent to the south across Great Jones Street at 35 Great Jones Street, facing south.

APPENDIX H

LANGAN RESUMES

Matthew Oleske

Senior Staff Engineer

Environmental Oversight, Environmental Site Assessment, Remedial Investigation, Remedial Action



7 years in the industry ~ 2 year with Langan

Mr. Oleske has over 7 years of experience that includes working on environmental projects, particularly investigation and remediation of environmental contamination. He has assisted in remedial investigations and has been involved in the collection of field data and assisted in the preparation of reports and other environmental regulatory documents for projects in the New York area.

Mr. Oleske's experience includes collection of soil, groundwater, soil-vapor, sub-slab vapor and indoor air samples for environmental analysis, supervision of remedial excavation activities, and air monitoring to ensure compliance with Occupational Safety and Health Standards. Mr. Oleske has also provided oversight for sub-slab depressurization system, soil-vapor extraction system, and composite cover system installations as well as follow up operations and maintenance.

Selected Projects

250 South Street Development, New York, NY
101-111 Murray Street Development, New York, NY
225 East 39th Street Development, New York, NY
525 West 52nd Street Development, New York, NY
2350 Fifth Avenue, New York, NY
Sky View Parc Development, Flushing, NY
Carroll Gardens Development, Brooklyn, NY

Publications

"Effects of Lime Amendment on the pH of Engineered Soil Mix for the Purposes of Bioretention", (2008), ASCE Journal of Irrigation and Drainage Engineering, Vol. 134, Issue No. 5, pages 675-679

Education

B.S., Bioresource Engineering
Rutgers University

Professional Registration

40 Hour, Hazardous Waste Handler

OSHA 10-Hour Training in Construction

LANGAN

Amanda Forsburg, CHMM

Project Scientist

Environmental Oversight, Remedial Investigation, Remedial Action



9 years in the industry ~ 9 years with Langan

Ms. Forsburg has over nine years of experience that includes working on environmental projects, particularly investigation and remediation of environmental contamination. She has assisted in remedial investigations and has been involved in the collection of field data and assisted in the preparation of reports and other environmental regulatory documents for projects in New Jersey and New York.

Ms. Forsburg's field experience includes investigation and remediation of contaminated sites including the collection of soil, groundwater, and air samples for environmental analysis, supervision of injections and remedial excavations, and the completion of air monitoring to ensure OSHA compliance on HAZWOPER sites. Office experience includes management of field investigation and remediation as well as completion of proposals, Phase I Environmental Site Assessments, remedial investigation reports, and remedial closure reports in support of these activities. Ms. Forsburg has worked on projects under regulatory oversight of the New Jersey Department of Environmental Protection (NJDEP), New York State Department of Environmental Conservation (NYSDEC), and New York City Office of Environmental Remediation (NYCOER).

Selected Projects

NYSDEC Brownfield Redevelopment, Remedial Investigation and Remediation Action – 363 and 365 Bond Street, Brooklyn, NY
NYSDEC Brownfield Redevelopment, Remedial Investigation – Fashion Outlets of Niagara Falls, NY
NYSDEC Spills Redevelopment, Remedial Action – 540 West 26th Street, New York, NY
NYSDEC Spills Redevelopment, Remedial Investigation and Remedial Action – 101 Murray Street, New York, NY
NYSDEC Spills Redevelopment, Remedial Investigation and Remedial Action – 110 University Place, New York, NY
NYSDEC Spills Redevelopment, Remedial Action, Lowe's Home Centers, Kings Plaza Site Redevelopment – Brooklyn, NY
NYSDEC Spills Remediation, Con Edison Soil Remediation - Bronx, NY
NYSDEC Spills Remediation, Con Edison NAPL Monitoring and Removal, Various Sites – Manhattan, NY
NYCOER E-Designation Remediation and Volunteer Cleanup Program Redevelopment, Remedial Investigation and Remedial Action – 400 Park Avenue South, New York, NY
NYCOER E-Designation Remediation and Volunteer Cleanup Program Redevelopment, Remedial Investigation and Remedial Action – 540 West 53rd Street, New York, NY
Remedial Action – 508 West 24th Street, New York, NY

Education

B.A., Environmental Studies
Bucknell University

B.A., Environmental Geology
Bucknell University

Professional Registration

Certified Hazardous Materials Manager (CHMM)

OSHA 29 CFR 1910.120 Certification (HAZWOPER)

Professional Affiliations

New Jersey Society of Women Environmental Professionals (NJSWEP)

Association of Environmental and Engineering Geologists – *New York-Philadelphia Chapter Secretary*

Professional Women in Construction - *New York Chapter Program Committee*

Alliance of Hazardous Materials Professionals New Jersey Chapter (AHMPNJ)

LANGAN

NYCOER E-Designation Remediation, Remedial Investigation and Remedial Action – 505 W 19th Street, New York, NY
NYCOER E-Designation Remediation, Remedial Investigation and Remedial Action – 53 West 53rd Street (MoMA Expansion), New York, NY
NYCOER E-Designation Remediation, Remedial Investigation and Remedial Action – 525 West 52nd Street, New York, NY
NYCOER E-Designation Remediation, Remedial Investigation and Remedial Action – 412 Greenwich Street, New York, NY
NYCOER E-Designation Remediation, Remedial Investigation and Remedial Action – 508 West 24th Street, New York, NY
NYCOER E-Designation Remediation, Remedial Investigation and Remedial Action – 68 Charlton Street, New York, NY
NYCDEP Remediation, Remedial Investigation and Remedial Action – 225 East 39th Street, New York, NY
Sky View Parc Mixed-Use Construction, Sub-Slab Vapor Ventilation System Construction – Flushing, NY
Liberty Plaza Redevelopment Site, Remedial Investigation and Remedial Action – Randallstown, MD
Former Penick Corporation Facility RCRA Site, Remedial Investigation and Remedial Action – Montville, NJ
Former Pan Graphics Facility, Soil and Groundwater Remediation – Garfield, NJ
Former Pan Graphics Facility, Sediment Investigation and Cap Construction – Lodi, NJ
Former Flintkote Facility, Soil and Groundwater Investigation – East Rutherford, NJ
Interport Site, Impacted Soils Delineation and Remediation – Newark, NJ
Lowe's Home Center Store, Sub-Slab Vapor Ventilation System O&M – Eatontown, NJ
Lowe's Home Center Store, Sub-Slab Methane Gas Ventilation System O&M – Woodbridge, NJ
Lowe's Home Center Store, Sub-Slab Vapor Barrier Construction – Rosedale, NY
Stop & Shop, Groundwater and Indoor Air Monitoring – Emerson, NJ
Stop & Shop, Methane Gas Ventilation System O&M – Raritan, NJ
Stop & Shop, Sub-Slab Vapor Ventilation System O&M – New Paltz, NY
Former First Aviation Services Facility, Groundwater Monitoring and Remediation, Teterboro, NJ
Phase I Environmental Site Assessments and Due Diligence Investigations, Various Sites – NJ and NY

Steven Ciambruschini, PG, LEP

Principal/Vice President
Environmental Site Assessments/Investigations, Brownfield Remediation, UST Management



32 years in the industry ~ 27 years with Langan

Mr. Ciambruschini has over 30 years of experience in hydrogeologic and environmental investigations including management of environmental and geotechnical investigations relating to petroleum and chlorinated solvent spill sites, underground storage tank sites, manufactured gas plant sites, landfills, wastewater treatment facilities and industrial/commercial sites. His experience includes managing environmental compliance audits, remedial investigation, pre-acquisition due diligence and permitting assessment, feasibility studies and design, construction and operation of complex innovative remediation systems to treat, contain and recover contaminated soil and groundwater. These projects are managed under various NJDEP, PADEP, NYDEC, NYCDEP and CTDEP programs. Mr. Ciambruschini provides consultation to a diverse group of clients including private developers, utilities, retail and industrial facilities and is expert in assessing remediation options and funding options under various state and federal grant, loan and tax reimbursement programs including Brownfield programs.

Selected Projects

- Brodson Property, Montville NJ, (RCRA, NJDEP ACO Cleanup)
- Carroll Gardens, Brooklyn, NY (NY Brownfield, EPA Superfund, OER E-designated Site)
- Con Edison Appendix B Spill Sites - Various Locations, NY
- Former MGP Site, Brooklyn, NY (VCP Site)
- Extell Development, Hudson Yards, New York, NY (NYC E-designated, NYS Brownfield Site)
- Pan Graphics, Bergen County, NJ (ISRA, LSRP)
- New Jersey Turnpike General Environmental Services Contract, Various Sites, NJ
- Liberty Science Center, Jersey City, NJ (EO 215)
- Blue Back Square, West Hartford, CT (UST, Transfer Act, Brownfield)
- Hershey, Act II Investigation (PA VCP)
- Hershey, Naugatuck, CT (CT Transfer Act)
- Halby Chemical Sites, Various Sites, DE (CERCLA)
- Unisys, Middletown CT, (CT Transfer Act, Brownfield)
- Ryder Rental, Various Sites in CT (CT Transfer Act)
- St. Marks Avenue, Brooklyn, NY (Vapor Mitigation)
- Pan Graphics, Lodi, NJ (Eco Risk Assessment, LSRP)

Education

M.S., Geology
Montclair State University

M.A., Environmental Science
Montclair University

B.S., Environmental Science
Cook College, Rutgers University

Professional Registration

Professional Geologist (PG) in NY, DE, and KY

Licensed Environmental Professional (LEP) in CT

Underground Storage Tank License in NJ

Affiliations

National Ground Water Association

Association of Ground Water Scientists and Engineers

American Association of Petroleum Geologists

Environmental Professionals of Connecticut

American Bar Association (ABA)

LANGAN